Phase I Environmental Site Assessment

2014 - 2042 Fulton Street
Brooklyn, New York

October 25, 2023

Prepared for:

Steps at Saratoga Housing Development Fund Corporation

Prepared by:

Roux Environmental Engineering and Geology, D.P.C.
209 Shafter Street
Islandia, New York 11749

3805.0002Y101/CV

Environmental Consulting
& Management
+1.800.322.ROUX
rouxinc.com

Table of Contents

Executive Summary iii

1. Introduction 1

2. Methods of Investigation 3
   - 2.1 General 3
   - 2.2 Review of Readily Available Information 3
   - 2.3 Subject Property and Surrounding Area Reconnaissance 4
   - 2.4 Interview with Key Subject Property Manager 4
   - 2.5 User Provided Information 5

3. Subject Property Description 6
   - 3.1 Subject Property Location and Description 6
   - 3.2 Current Surrounding Property Usage 6
   - 3.3 Topographic and Hydrogeologic Setting 6

4. Subject Property History 7
   - 4.1 Historical Subject Property and Surrounding Property Usage 7
   - 4.2 Historical Sanborn Maps 7
   - 4.3 Historical Aerial Photographs 8
   - 4.4 Historical Topographic Maps 9
   - 4.5 City Directory Abstract 9

5. Records Review 12
   - 5.1 Environmental Database Review 12
   - 5.2 Freedom of Information Act Letter Responses 13

6. Subject Property Reconnaissance 16
   - 6.1 Utilities 16
   - 6.2 Hazardous Substances 16
   - 6.3 Storage Tanks 16
   - 6.4 Polychlorinated Biphenyls 16
   - 6.5 Staining and Stressed Vegetation 16
   - 6.6 Interior Drains and Sumps 16
   - 6.7 Solid Waste 16
   - 6.8 Wastewater and Stormwater 16
   - 6.9 Wells 16
   - 6.10 Equipment 16

7. Interviews and User Provided Information 17
   - 7.1 Interviews 17
   - 7.2 User Questionnaire 17

8. Summary of Findings 18

9. Report Assumptions and Limitations 19

Figures

1. Subject Property Location Map
2. Subject Property Plan

Appendices

A. Professional Profiles
B. Federal and State Environmental Databases
C. Freedom of Information Law Letters and Responses
D. Historical Sanborn Maps
E. Historical Aerial Maps
F. Historical Topographic Maps
G. City Directory Abstract
H. Subject Property Photographs
I. User Provided Information

Executive Summary

At the request of the Steps at Saratoga Housing Development Fund Corporation (Steps at Saratoga HDFC or User), Roux Environmental Engineering and Geology, D.P.C. (Roux) performed a Phase I Environmental Site Assessment (ESA) of the real properties located at 2014-2042 Fulton Street in the Bedford Stuyvesant neighborhood of Brooklyn, New York (Subject Property) (Figure 1). The Subject Property is comprised of seventeen contiguous parcels, consisting of Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map. A Subject Property Plan showing relevant features is provided as Figure 2. The Phase I ESA is intended to define the historical uses of the Subject Property and identify any potential Recognized Environmental Conditions (RECs) that could warrant further consideration, in accordance with ASTM International Standard Practice E1527-21 (Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process).

A review of historical sources, including historical aerial photographs, historical topographic maps, historical certified Sanborn Fire Insurance maps, and a City Directory Abstract indicate that the western portion of the Subject Property was first developed with mixed use buildings. The rest of the Subject Property was developed with mixed use buildings by 1911. By the 1930s, the Subject Property was occupied by multiple commercial operations, including a machine shop, dry goods store, and upholsterer. By the 1960s, a portion of the Subject Property was operated as a blind manufacturer, tin smith, and sheet metal and roofing company. By 1993, the western portion of the Subject Property was utilized as truck parking. The Subject Property was depicted as completely vacant on the Sanborn Map dated 2001, with the exception of the truck parking area in the western portion of the Subject Property. During the September 27, 2023 Subject Property reconnaissance, the Subject Property was observed to be a completely vacant, vegetated lot. The layout of the surrounding area was also confirmed during the September 27, 2023 Subject Property reconnaissance.

Based on the information gathered during the Phase I ESA process, Roux identified the following RECs in connection with the Subject Property:

- Historical Use of the Subject Property: According to the EDR City Directory Abstract, the Subject Property was occupied by multiple commercial operations, including a tinsmith and sheet metal and roofing facility. The western portion of the Subject Property was also depicted in Sanborn Maps dated from 1993 to 2007 as a truck parking lot. No records of any releases or waste generation were identified in the EDR environmental database report. However, the potential for a historical petroleum or chemical release from these historical uses that negatively impacts the environmental quality of the Subject Property cannot be ruled out, and is considered a REC.

Roux did not identify any Controlled RECs (CRECs) or Historical RECs (HRECs) in connection with the Subject Property.

Roux identified the following Business Environmental Risks (BERs) in connection with the Subject Property:

- Suspected Presence of Fill Material: The Subject Property has had buildings associated with former buildings that have been demolished and there is potential to encounter former foundations, historical fill, and concrete in the Subject Property subsurface.
- E-Designations: The Subject Property is associated with a hazardous materials and noise E-Designation (E-185) associated with City Environmental Quality Review (CEQR# 07DCP070K) placed by the Department of City Planning. Any remediation of the Subject Property will need to be coordinated with the New York City Office of Environmental Remediation (NYCOER) concurrently with development.

Roux has identified the following significant data gap in connection with the Phase I ESA:

- Awaiting responses to FOIA requests from the New York State Department of Environmental Conservation (NYSDEC), New York State Department of Health (NYSDOH), Fire Department of New York (FDNY), and New York City Department of Environmental Protection (NYCDEP). Based on the information and records obtained and reviewed from other sources during the Phase I ESA, this data gap is not considered a significant data gap. If any pertinent information is obtained from responses to outstanding FOIA requests regarding the Subject Property, Roux will prepare a letter addendum summarizing these findings.

1. Introduction

At the request of the Steps at Saratoga Housing Development Fund Corporation (Steps at Saratoga HDFC or User), Roux Environmental Engineering and Geology, D.P.C. (Roux) performed a Phase I Environmental Site Assessment (ESA) of the real properties located at 2014-2042 Fulton Street in the Bedford Stuyvesant neighborhood of Brooklyn, New York (Subject Property) (Figure 1). The Subject Property is comprised of seventeen contiguous parcels, consisting of Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map. A Subject Property Plan showing relevant features is provided as Figure 2. The Phase I ESA is intended to define the historical uses of the Subject Property and identify any potential Recognized Environmental Conditions (RECs) that could warrant further consideration, in accordance with ASTM International Standard Practice E1527-21 (Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process).

The Phase I ESA was conducted in accordance with the scope of work presented in the original contract between the Steps at Saratoga HDFC and Roux, dated July 18, 2023, and in general accordance with the ASTM International Standard Practice E1527-21 (Standard Practice for Environmental Site Assessments), consistent with the USEPA Standards and Practices for All Appropriate Inquiries (AAI) Rule (40 CFR Part 312, Standards and Practices for All Appropriate Inquiries; Final Rule[1]). The preamble for the AAI Rule states:

> *In today's final rule, EPA is referencing the standards and practices developed by ASTM International and known as Standard E1527-05 (entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process") and recognizing the E1527-05 standard as consistent with today's final rule. The Agency determined that this voluntary consensus standard is consistent with today's final rule and is compliant with the statutory criteria for all appropriate inquiries. Persons conducting all appropriate inquiries may use the procedures included in the ASTM E1527-05 standard to comply with today's final rule.*[2]

This AAI Rule was subsequently amended in 2013, as indicated in the following "Background":

> *With today's action, EPA is establishing that parties seeking liability relief under CERCLA's landowner liability protections, as well as recipients of brownfields grants for conducting site assessments, will be considered to have met the standards and practices for all appropriate inquiries, as set forth in the Brownfields Amendments to CERCLA and 40 CFR Part 312, if such parties follow the procedures provided in the ASTM E1527-13 "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process." EPA made this determination based upon the Agency's finding that the ASTM E1527-13 standard is compliant with the All Appropriate Inquiries Rule. Therefore, parties conducting all appropriate inquiries may use the procedures in the newly issued ASTM E1527-13 standard when conducting all appropriate inquiries.*[3]

As of February 13, 2023, the EPA indicated that the updated standard ASTM E1527-21 is now AAI compliant. While ASTM E1527-21 is now the current standard, the previous standard (ASTM E1527-13) is still AAI compliant until February 13, 2024. The purpose of the Phase I ESA was to identify, to the extent feasible, RECs in connection with the Subject Property. ASTM Standard Practice E1527-21 defines RECs as:

> *The presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on or at the Subject Property due to a release or likely release to the environment; or*

[1] Final Rule and information available at www.epa.gov/swerosps/bf/regneg.htm#final_rule, and https://federalregister.gov/a/2013-31112.
[2] Federal Register: November 1, 2005 (Volume 70, Number 210), page 66081.
[3] Federal Register: December 30, 2013 (Volume 78, Number 250).

(3) the presence of hazardous substances or petroleum products in, on or at the Subject Property under conditions that pose a material threat of a future release to the environment.

ASTM Standard Practice E1527-21 provides that identified RECs can be evaluated and classified into Controlled Recognized Environmental Conditions (CRECs) or Historical Recognized Environmental Conditions (HRECs) based on the following definitions. ASTM Standard Practice E1527-21 defines a CREC as:

A recognized environmental condition affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls.

ASTM Standard Practice E1527-21 defines a HREC as:

A previous release of hazardous substances or petroleum products affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the Subject Property to any controls.

To assess the potential for RECs associated with the Subject Property, Roux utilized a variety of informational sources to perform the Phase I ESA, including a radial information search from federal, state, and local regulatory agency databases; Freedom of Information Act (FOIA)/public records responses from federal, state, and local regulatory agencies; and readily available information from the following sources: historical aerial photographs, historical topographic maps and a City Directory Abstract. The historical research and interviews were conducted to develop an understanding of the following:

- Current and past uses of the Subject Property;
- Current and past uses of hazardous substances and/or petroleum at the Subject Property and surrounding properties, if any;
- Waste management and disposal practices that might have potentially caused releases or threatened releases of hazardous substances and/or petroleum products at the Subject Property, and to the extent feasible the surrounding properties;
- Current and past corrective actions and response activities undertaken to address past and ongoing releases of hazardous substances and/or petroleum products at the Subject Property and surrounding properties, if any;
- The existence of any engineering and/or institutional controls recorded for the Subject Property and surrounding properties; and
- Current and past uses of adjoining properties that could have resulted in releases or threatened releases of hazardous substances and/or petroleum products to the Subject Property.

Ms. Jessica Taylor and Mr. Stephen Loonie served as the Environmental Professionals who conducted this Phase I ESA. As the Environmental Professionals, Ms. Taylor and Mr. Loonie possess sufficient specific education, training, and experience necessary to exercise professional judgment to develop opinions and conclusions regarding conditions indicative of releases or threatened releases (as defined in §312.1(c) on, at, in, or to a Site, sufficient to meet the objectives and performance factors in §312.20(e) and (f)). Ms. Taylor and Mr. Loonie's professional profiles are provided in Appendix A.

2. Methods of Investigation

The methods of investigation used to conduct this Phase I ESA are outlined in the following sections.

2.1 General

The activities performed in conjunction with the Phase I ESA of the Subject Property include:

- Review of federal, state, and local environmental regulatory agency databases provided by Environmental Data Resources (EDR), Inc. of Shelton, Connecticut indicating locations of environmental concern within specified radii from the Subject Property (Appendix B);
- Submission of FOIA/public records requests and inquiries to federal, state, and local regulatory agencies for the Subject Property (Appendix C);
- Review of historical information for the Subject Property and surrounding area, including aerial photographs, topographic maps, and other relevant historical information sources;
- Reconnaissance of the Subject Property and surrounding area; and
- Conducted an interview with a Key Subject Property Representative.

2.2 Review of Readily Available Information

The resources compiled and reviewed by Roux to date include the following:

- EDR Radius Map with GeoCheck, dated September 7, 2023 (EDR report) (Appendix B);
- Historical Certified Sanborn Fire Insurance Maps dated 1888, 1908, 1932, 1951, 1962, 1963, 1965, 1976, 1978, 1979, 1980, 1982, 1987, 1988, 1989, 1991 through 1995, and 2001 through 2007 (Appendix D);
- Historical Aerial Photographs 1924, 1951, 1954, 1961, 1966, 1976, 1984, 1994, 2006, 2011, 2015 and 2019 (Appendix E);
- United States Geological Survey (USGS) 15-Minute Topographic Maps, Brooklyn, New York Quadrangle dated 1897, 1898, and 1900; 7.5-Minute Topographic Maps, Brooklyn, New York Quadrangle dated 1947, 1956, 1967, 1979, 1995, 2013, 2016, and 2019 (Appendix F); and
- A search of the City Directory Abstract conducted by EDR (Appendix G).

Pursuant to ASTM E1527-21, Roux contacted and reviewed additional environmental records provided by the following agencies:

Agency	Status
United States Environmental Protection Agency (USEPA)	Online database reviewed; no records available.
New York State Department of Environmental Conservation (NYSDEC)	Records provided and discussed in Section 5.2. Records accessed online.
New York State Department of Health (NYSDOH)	Acknowledgement received; response pending.
New York City Department of Environmental Protection (NYCDEP)	Acknowledgement received; response pending.
New York Fire Department (FDNY)	Records requested; response pending.

Agency	Status
New York City Department of Finance (NYCDOF)	Records accessed online.
New York City Department of Buildings (NYCDOB)	Records accessed online.
New York City Office of Environmental Remediation (NYCOER)	Records accessed online.

2.3 Subject Property and Surrounding Area Reconnaissance

Pursuant to ASTM Standard Practice E1527-21, Roux conducted a reconnaissance of the Subject Property and surrounding area on September 27, 2023, to identify, investigate, and assess potential RECs and other potential environmental concerns. The reconnaissance included observation of the Subject Property, including structures and buildings, and the surrounding area to determine the current use and condition of the Subject Property, indications of past uses of the Subject Property, and current uses of adjacent and adjoining properties and the surrounding area. During the Subject Property reconnaissance, Roux placed particular emphasis on identifying the following features, if present, in accordance with ASTM E1527-21:

- Hazardous substances and petroleum products in connection with identified uses;
- Storage tanks;
- Odors;
- Pools of liquid;
- Drums;
- Hazardous substances and petroleum products containers;
- Unidentified substance containers;
- Polychlorinated biphenyls (PCBs);
- Heating and cooling systems;
- Stains or corrosion;
- Drains and sumps;
- Pits, ponds, or lagoons;
- Stained soil or pavement;
- Stressed vegetation;
- Solid waste;
- Wastewater;
- Wells; and
- Septic systems.

In addition, observation of the general topographic setting of the Subject Property was made, and inquiry was made into the source of potable water for the Subject Property and other utilities, as presented in Section 6. Photographs from the Subject Property reconnaissance are presented in Appendix H.

2.4 Interview with Key Subject Property Manager

As of the date of this report, a Key Subject Property Manager has not been identified by the User. Since the Subject Property has been vacant and owned by New York City Department of Housing Preservation and

Development (NYC HPD) for many years, there is not significant historical information known to any specific property manager or representative. Based on information gathered from other sources, this is not considered a significant data gap.

2.5 User Provided Information

As of the date of this report, Roux has not been provided with any historical documentation pertaining to the Subject Property by the User.

3. Subject Property Description

Descriptions of the Subject Property and surrounding properties are included in the following sections. The location of the Subject Property is presented in Figure 1. The Subject Property and surrounding properties are presented in Figure 2.

3.1 Subject Property Location and Description

The Subject Property is comprised of seventeen contiguous parcels, consisting of Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map. The Subject Property address is also listed as 2014 through 2042 Fulton Street. The Subject Property is a vacant, rectangular lot. The entire lot is vegetated, and no structures were identified during the September 2023 Subject Property reconnaissance. The Subject Property encompasses an area of approximately 0.85 acres, and the current owner is listed in the New York City Automatic City Register Information System (ACRIS) database as NYC HPD. The Subject Property is bounded to the west by a church; to the south by a multi-family residential building; to the east by a school, and to the north by mixed use buildings.

The Subject Property and surrounding area were inspected during the Subject Property reconnaissance. The findings of the reconnaissance are summarized in Section 6.

3.2 Current Surrounding Property Usage

The areas surrounding the Subject Property are developed with residential and commercial properties. Table 3.2 below provides details on adjoining and adjacent properties.

Table 3.2 Surrounding Property Uses

North	Mixed-Use Building (Deli, Hardware Store, Barber)
South	Multi-Family Residential Building
East	School
West	Church

3.3 Topographic and Hydrogeologic Setting

The grade of the Subject Property is generally flat. The average elevation of the Subject Property is approximately 80 feet above mean sea level (ft amsl) as shown in the USGS 7.5 Minute Series (Appendix F). According to the EDR report, the Subject Property is not located in, or adjacent to, regulated wetlands. The Subject Property is not located in the 100-year or 500-year flood zones.

A formal groundwater flow direction study has not been conducted as part of this Phase I ESA. For purposes of investigating potential migration of off-Site groundwater impacts during this Phase I ESA, the regional direction of groundwater flow in the area of the Subject Property is assumed to flow to the north-northwest in the direction of the East River. This estimation was based on regional hydrogeological and topographical features.

4. Subject Property History

The historical uses of the Subject Property are discussed below.

4.1 Historical Subject Property and Surrounding Property Usage

The historical uses of the Subject Property and surrounding properties were researched by examining Certified Sanborn Fire Insurance Maps (Appendix D); historical aerial photographs (Appendix E); historical USGS topographic maps (Appendix F); and the City Directory Abstract (Appendix G).

4.2 Historical Sanborn Maps

Roux reviewed historical Certified Sanborn Fire Insurance maps for the Subject Property. Table 4.2 provides a summary of the Subject Property and surrounding area from 1888 to 2007, as determined from the Certified Sanborn Fire Insurance maps, which are included as Appendix D.

Table 4.2
Certified Sanborn Fire Insurance Maps

Date	Description
1888	**Subject Property:** The western portion of the Subject Property is developed with mixed use buildings. The rest of the Subject Property is undeveloped. **Surrounding Area:** The surrounding area generally consists of residential and commercial properties.
1911	**Subject Property:** The rest of the Subject Property is developed with mixed use buildings. **Surrounding Area:** The surrounding area continues to be developed with residential and commercial properties. An elevated subway train is depicted running along Fulton Street.
1932	**Subject Property:** Lot 26 is developed with a machine shop and bus register storage. **Surrounding Area:** A filling station with three gasoline tanks is located to the south of the Subject Property on the northeastern corner of Atlantic Avenue and Saratoga Avenue. An auto repair facility is depicted on Atlantic Avenue to the south of the Subject Property. A 60-car garage with two gasoline tanks is developed to the north of the Subject Property on the southwestern corner of Saratoga Avenue and Hull Street. The rest of the surrounding area remains generally the same.
1951	**Subject Property:** Lots 26 through 29 are developed with a noodle manufacturing and packaging facility. **Surrounding Area:** Generally the same as the 1932 Sanborn Map.
1962 - 1980	**Subject Property:** Lot 26 is developed with an upholstery facility and Lost 28 and 29 are developed with a tin supply wholesaler. **Surrounding Area:** Generally the same as the 1951 Sanborn Map. The garage to the north of the Subject Property is also labeled as an auto body repair shop.

Table 4.2 Certified Sanborn Fire Insurance Maps	
Date	**Description**
1982 -1992	**Subject Property:** The eastern portion of the Subject Property is depicted as a vacant lot. The warehouse on Lot 26 is labeled as vacant. **Surrounding Area:** Generally the same as the 1980 Sanborn Map. By 1989, the gasoline station to the southeast of the Subject Property was relabeled as a commercial building.
1993, 1994	**Subject Property:** The western portion of the Subject Property is labeled as truck parking. **Surrounding Area:** Generally the same as the 1992 Sanborn Map.
2001 – 2007	**Subject Property:** The entire Subject Property is depicted as vacant with the exception of Lots 18 through 21, which is labeled as truck parking. **Surrounding Area:** Generally the same as the 1994 Sanborn Map. The garage and auto body repair shop to the north of the subject property was redeveloped into residential buildings.

The western portion of the Subject Property was labeled as truck parking from 1993 through 2007. No reports of releases or waste generation was identified in the EDR database report. However, the use of the Subject Property as truck parking had the potential for a release of petroleum products into the subsurface, which is considered a REC.

Additionally, multiple buildings were demolished since the Subject Property was developed prior to 1888. There is a potential for historical building materials to be present in fill material at the Subject Property, which is considered a Business Environmental Risk (BER).

A gasoline station was identified to the southeast of the Subject Property from 1932 to 1988. No records of any release or waste generation was identified in the EDR database report. Based on the distance from the Subject Property and the lack of any spill or waste generation records, this property is not expected to negatively impact the Subject Property.

4.3 Historical Aerial Photographs

Historical aerial photographs were obtained from EDR, and are provided in Appendix E. Historical aerials may indicate past activities at a property that may not have been documented by other means or observed during a reconnaissance visit. According to a review of the historical aerial photographs, the Subject Property appears to have been developed with multiple buildings as early as 1924. The quality of the aerial photographs are not clear enough to clearly identify individual buildings. By 2006, the Subject Property appears to be completely vacant and vegetated. The general layout of the Subject Property was consistent through the latest aerial photograph dated 2019.

According to the 1924 aerial photograph, the surrounding area appears to be developed with a mix of residential and commercial properties. The general composition of the surrounding area has remained approximately the same through the 2019 aerial photograph.

4.4 Historical Topographic Maps

Historical topographic maps of the Subject Property were obtained from EDR, and they are provided in Appendix F. Elevation of the Subject Property was consistent in topographic maps reviewed from 1897 to 2019. No significant elevation changes that would suggest backfilling operations were identified.

4.5 City Directory Abstract

A City Directory Abstract of the Subject Property was obtained from EDR and is presented in Appendix G. Records reviewed from 1928 to 2020 were sourced from Cole Information Services, Hill-Donnelly Information Services, NYNEX Information Resource Company, New York Telephone, R.L. Polk and Company, and Manhattan and Bronx Directory. Notable listings for the Subject Property are provided in the table below.

Table 4.5
City Directory Listings for 2014 Fulton Street

Date	Description
1960	Individual Apartments
1949	Individual Apartments
1945	Individual Apartments
1940	Individual Apartments
1934	Individual Apartments
1928	Individual Apartments

Table 4.5
City Directory Listings for 2016 Fulton Street

Date	Description
1976	Individual Apartments
1960	Individual Apartments
1934	Individual Apartments
1928	Individual Apartments

Table 4.5
City Directory Listings for 2018 Fulton Street

Date	Description
1960	Individual Apartments
1934	EVANS FRES JANITOR BKN PUB LIBRARY, KESSELMAN ANTHONY DRY GDS H DO, TOMPSON PETER A SLSMN H
1928	Individual Apartments

Table 4.5 City Directory Listings for 2020 Fulton Street	
Date	**Description**
1992	Individual Apartments
1960	Individual Apartments
1949	KESSELMAN ANTHONY, LINCOLN TRADING CO
1945	KESSELMAN ANTHONY
1940	KESSELMAN ANTHONY
1934	KESSELMAN HANNAH MRS DOM R, KESSELMAN MAY SLSWN R
1928	KESSELMAN ANTHONY DRY GOODS

Table 4.5 City Directory Listings for 2022 Fulton Street	
Date	**Description**
1976	Individual Apartments
1960	Cohen D & Sons RFSG & Sheet Metal, Fulton Sheet Metal and Roofing, Smith Adele M, Smith Mary H
1949	Cohen D & Sons Tnsmths
1940	Fulton Etching Co, Schnaars David R ins, Wuttke Chas Inc Carpntry & Contr
1934	Evinson Carrie H
1928	Muller Henry RL Est

Table 4.5 City Directory Listings for 2024 Fulton Street	
Date	**Description**
1934	Bethell Fanne H, Gelles Max Necktie Mfr, Green F Uphol R, Hamlin John Elev Opr H
1928	Bailey B W Mrs R, Newman S & Son Pnts

Table 4.5 City Directory Listings for 2026 Fulton Street	
Date	**Description**
1992	Daniels Church of God in Christ
1976	Dean Whol Dstrbtrs
1960	Nockowitz Meyer Uphlstry
1934	Berlow Abr Retail Cigars, Chambers Leathe H, Chambers Linwood Jr Clk R
1928	Gelman Saml Cigars

Table 4.5 City Directory Listings for 2028 Fulton Street	
Date	**Description**
1949	Acme Venetian Blind Mfg Co
1945	Perey Turnstiles The
1940	Perey Turnstiles The
1934	Scheafer Edw J Turbin Opr H
1928	Perey Mfg Co Turnstls

Table 4.5 City Directory Listings for 2030 Fulton Street	
Date	**Description**
1965	Sussman Benj Sheet Metal Co Inc.
1949	Chasin Noodle Co, Pure Home Made Food Prods Co.

The Subject Property was historically occupied by multiple commercial operations, including a tinsmith and sheet metal and roofing facility. No records of any releases or waste generation were identified in the EDR environmental database report. However, the potential for a historical petroleum or chemical release that negatively impacts the environmental quality of the Subject Property cannot be ruled out, and is considered a REC.

Listings for the surrounding area surrounding the Subject Property consist of retail stores, offices, churches, contractors, restaurants, individual residences.

5. Records Review

This section summarizes the information regarding the Subject Property and potential environmental sites of concern that are contained in the standard and additional environmental record sources reviewed by Roux in accordance with ASTM Standard Practice E1527-21.

5.1 Environmental Database Review

Roux used a computerized environmental database and radius map report prepared by EDR to conduct a government records database search of properties of potential environmental concern within a maximum of one-mile radius of the Subject Property. Appendix B contains a complete copy of the EDR Radius Map Report with GeoCheck.

Each lot of the Subject Property is listed in the E-DESIGNATION database for hazardous materials and noise. The Subject Property is not listed in any other environmental database.

Off-Site properties that meet the criteria presented below are discussed in this report:

- Facilities adjoining and adjacent to the Subject Property are examined due to their proximity and the potential for surface water discharges (e.g., stormwater runoff, surface water effluent discharges) to enter the Subject Property or through the migration of groundwater or soil vapor.
- Facilities located topographically or hydraulically upgradient of the Subject Property.

Groundwater flow direction is presumed north-northwest across the Subject Property, toward the East River. Facilities that are located downgradient or cross gradient to the Subject Property—but not adjoining the Subject Property—are not discussed in this report because these facilities are considered to pose a low potential environmental concern to the Subject Property.

Adjoining Properties

1095 Herkimer Street (adjoins to the south)

The above-referenced property is listed in the NY SPILLS database for NYSDEC Spill Case Number 9700115 which was reported on April 2, 1997, when a heating oil leak and fumes were observed coming through the basement floor of an apartment building. The spill was closed on April 17, 2003.

Based on the status of these spill cases (closed), this facility is not expected to negatively impact upon the environmental quality of the Subject Property.

1093 Herkimer Street (adjoins to the south)

The above-referenced property is listed in the NY SPILLS database for NYSDEC Spill Case Number 9311226 and was reported on December 18, 1993, when a #2 fuel oil spill was reported in the basement of an apartment building. The spill was cleaned up and the case was closed to the satisfaction of the NYSDEC on September 17, 2001.

Based on the status of these spill cases (closed), this facility is not expected to negatively impact upon the environmental quality of the Subject Property.

1115 Herkimer Street (adjoins to the south)

The above-referenced property is listed in the NY SPILLS database for NYSDEC Spill Case Number 0913454 and was reported on March 21, 2010, when a leaking fuel line from a 275-gallon aboveground storage tank (AST) led to a release of five gallons of heating oil onto the ground. The spill was cleaned up and the case was closed to the satisfaction of the NYSDEC on December 8, 2011.

Based on the status of these spill cases (closed), this facility is not expected to negatively impact upon the environmental quality of the Subject Property.

Upgradient Properties

Upgradient listings primarily consist of closed spill cases for releases of small quantities of petroleum, and RCRA listings for properties associated with utilities maintained by Con Edison. The below facilities are listed in other databases in the EDR report.

1993 Atlantic Avenue (approximately 492 feet to the south)

The above-referenced property is listed in the EDR HIST AUTO database under the name W&M Service Station between 1974 and 1988 as a former gasoline station. No reported spills or waste generation were identified in the database listing.

Based on the lack of reported releases, as well as the distance from the Subject Property, this facility is not expected to negatively impact upon the environmental quality of the Subject Property.

2043 Atlantic Avenue (approximately 1,000 feet to the southeast)

The above-referenced property is listed in the DRYCLEANERS database under the name Bill's Dry Cleaners and Facility ID 2-6104-01318 from 2003 through 2016. The type of solvent used by the facility is not identified in the database listing. No releases or evidence of waste generation were identified in the EDR report. The property is currently operated as a funeral merchandise boutique.

Based on the lack of reported releases and waste generation, as well as the distance from the Subject Property, this facility is not expected to negatively impact upon the environmental quality of the Subject Property.

5.2 Freedom of Information Act Letter Responses

FOIA requests were submitted to the NYSDEC, NYSDOH, NYCDEP and the FDNY. Online USEPA, NYCDOF and NYCDOB resources and databases were searched for records related to the Subject Property. If any additional pertinent environmental information is received from the outstanding FOIA requests following the issuance of this report, Roux will provide a letter addendum to this report detailing this information. Information obtained from the Internet Databases and FOIA responses is included as Appendix C.

USEPA

The Subject Property was not identified in any of the online USEPA environmental databases.

NYSDEC

As of the date of this report, the NYSDEC has acknowledged our FOIA request. The NYSDEC has not identified whether any records exist for the Subject Property. Any additional information provided by the NYSDEC will be provided as soon as it has been received and evaluated.

The online DECinfo Locator tool was also searched for any state records pertaining to the Subject Property or surrounding properties. No records pertaining to the Subject Property were identified, and no nearby sites were identified in the DECinfo Locator tool.

NYSDOH

As of the date of this report, the NYSDOH has acknowledged our FOIA request. The NYSDOH has not identified whether any records exist for the Subject Property. Any additional information provided by the NYSDOH will be provided as soon as it has been received and evaluated.

NYCDEP

As of the date of this report, the NYCDEP has acknowledged our FOIA request. The NYCDEP has not identified whether any records exist for the Subject Property. Any additional information provided by the NYCDEP will be provided as soon as it has been received and evaluated.

FDNY

As of the date of this report, the FDNY has not yet responded to our initial FOIA request. Any additional information provided by the FDNY will be provided as soon as it has been received and evaluated.

NYCDOF

The NYCDOF Automated City Register Information System (ACRIS) was searched for each lot of the Subject Property. The ACRIS files generally contained mortgage agreements, lease agreements and deed. According to the most recent satisfaction of mortgage, each lot of the Subject Property is owned by the HPD.

The NYCDOF Building Classification for each lot of the Subject Property is V1 – Vacant Land.

NYCDOB

The NYCDOB online database was searched for the Subject Property. The following complaints, DOB violations, and Environmental Control Board (ECB) violations were identified in the NYCDOB database:

- Lot 19 is associated with one open ECB violation for construction safety.
- Lot 22 is associated with three DOB violations for building safety.
- Lot 23 is associated with one unknown DOB violation.

The following Certificates of Occupancy (COs) were identified in the NYCDOB online database:

- A CO in poor quality from the 1920s was addressed to Lot 34.
- A CO dated June 19, 1930, identified Lot 32 as a mixed use building.
- A CO dated January 18, 1962, identified Lot 25 as a three-story mixed use building occupied by a doctor’s office.
- A CO dated April 11, 1951, identified Lot 26 as an upholstery and showroom building.
- A CO dated November 7, 1972, identified Lot 26 as a one story wholesale establishment with a basement. The CO indicates that the building was heated with fuel oil.
- A CO dated August 30, 1977, identified Lot 31 as a four-story store building, with the second, third, and fourth floors listed as vacant.

NYCOER

The NYCOER's SPEED was searched for the Subject Property. The Subject Property was listed in the SPEED database for multiple E-designations (E-185) under CEQR# 07DCP070K. Any remediation of the Subject Property will need to be coordinated with the NYCOER concurrently with development.

6. Subject Property Reconnaissance

The findings of the Subject Property reconnaissance, conducted on September 27, 2023, are discussed below. At the time of the Subject Property reconnaissance, the Subject Property consisted of a vacant lot. The temperature during the Subject Property reconnaissance was 65 degrees Fahrenheit and the conditions were overcast.

6.1 Utilities

No utilities were observed to be connected to the Subject Property. Several natural gas lines were observed on the northern adjoining sidewalk on Fulton Street.

6.2 Hazardous Substances

No evidence of hazardous substances was observed at the Subject Property.

6.3 Storage Tanks

No evidence of storage tanks was identified on the Subject Property.

6.4 Polychlorinated Biphenyls

No evidence of equipment containing PCBs was identified on the Subject Property.

6.5 Staining and Stressed Vegetation

No evidence of staining was observed at the Subject Property. The Subject Property was overgrown with weeds and grasses; however, no stressed vegetation was observed at the Subject Property.

6.6 Interior Drains and Sumps

No interior drains or sumps were observed at the Subject Property, as the Subject Property is completely vacant.

6.7 Solid Waste

Solid waste at the Subject Property is limited to typical urban litter, including paper products and recyclables.

6.8 Wastewater and Stormwater

Stormwater is expected to directly infiltrate into vegetated areas of the Subject Property or run off into catch basins located in the street.

6.9 Wells

No groundwater or potable water wells were identified at the Subject Property.

6.10 Equipment

No equipment was observed at the Subject Property.

7. Interviews and User Provided Information

Roux incorporated interviews provided by the User to complete this Phase I ESA. Information obtained from these sources was detailed throughout this report in various sections, as appropriate. Pertinent findings from these sources are summarized in the following sections.

7.1 Interviews

NYC HPD was contacted to provide any information regarding the historical use and environmental conditions of the Subject Property. As of the date of this report, the HPD indicated that they have no specialized knowledge of the Subject Property.

7.2 User Questionnaire

As of the date of this report, Roux has not been provided with a completed User Questionnaire. A copy of the blank questionnaire is provided in Appendix I.

8. Summary of Findings

Based on the information gathered during the Phase I ESA process, Roux identified the following RECs in connection with the Subject Property:

- Historical Use of the Subject Property: According to the EDR City Directory Abstract, the Subject Property was occupied by multiple commercial operations, including a tinsmith and sheet metal and roofing facility. The western portion of the Subject Property was also depicted in Sanborn Maps dated from 1993 to 2007 as a truck parking lot. No records of any releases or waste generation were identified in the EDR environmental database report. However, the potential for a historical petroleum or chemical release from these historical uses that negatively impacts the environmental quality of the Subject Property cannot be ruled out, and is considered a REC.

Roux did not identify any CRECs or HRECs in connection with the Subject Property.

Roux identified the following BERs in connection with the Subject Property:

- Suspected Presence of Fill Material: The Subject Property has had buildings associated with former buildings that have been demolished and there is potential to encounter former foundations, historical fill, and concrete in the Subject Property subsurface.
- E-Designations: The Subject Property is associated with a hazardous materials and noise E-Designation (E-185) associated with City Environmental Quality Review (CEQR# 07DCP070K) placed by the Department of City Planning. Any remediation of the Subject Property will need to be coordinated with the New York City Office of Environmental Remediation (NYCOER) concurrently with development.

Roux has identified the following significant data gap in connection with the Phase I ESA:

- Awaiting responses to FOIA requests from the NYSDEC, NYSDOH, NYCDEP, and FDNY pertaining to the Subject Property. Based on the information and records obtained and reviewed from other sources during the Phase I ESA, this data gap is not considered a significant data gap. If any pertinent information is obtained from responses to outstanding FOIA requests regarding the Subject Property, Roux will prepare a letter addendum summarizing these findings.

9. Report Assumptions and Limitations

This Phase I ESA Report, including the exhibits attached hereto, describes the results of Roux's initial investigation to identify the potential presence of RECs involving or affecting the Subject Property in accordance with ASTM Standard Practice E1527-21. This Phase I ESA was conducted by Roux in accordance with the regulatory requirements for conducting AAI as set forth in the USEPA AAI Rule, at 40 CFR Part 312. Use of ASTM E1527-21 is consistent with the USEPA AAI Rule (40 CFR Part 312, Amendment to Standards and Practices for All Appropriate Inquiries Under CERCLA; Final Rule), as amended effective February 13, 2023.

One of the requirements that a person acquiring real property must meet in order to qualify for either the innocent landowner, contiguous owner, or bona fide prospective purchaser (collectively hereinafter "Prospective Purchaser") defense to liability under the federal Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), is that person must conduct all appropriate inquiry in conformance with the AAI Rule (or the ASTM E1527-21) prior to acquisition of the property. The User understands that, under the AAI Rule, Roux's performance of the Phase I ESA in accordance with ASTM E1527-21 will not alone result in the User satisfying all requirements of the AAI Rule and provide a defense to CERCLA liability.

The User understands that the AAI Rule also requires that the Prospective Purchaser undertake certain additional inquiries and post-acquisition activities to satisfy the CERCLA AAI requirements. **ACCORDINGLY, ROUX MAKES NO GUARANTEES OR WARRANTIES, EXPRESSED OR IMPLIED, REGARDING THIS PHASE I ESA, INCLUDING WITHOUT LIMITATION, ANY WARRANTY THAT THIS PHASE I ESA WILL IN FACT QUALIFY THE CLIENT FOR A DEFENSE TO CERCLA LIABILITY.**

Roux has performed this Phase I ESA in a professional manner using the degree of skill and care exercised for similar projects under similar conditions by reputable and competent environmental consultants. Professional judgments expressed herein are based on the facts currently available to Roux.

The AAI Rule requires, and the conclusions and recommendations stated herein, represent the application of a variety of engineering and technical disciplines to material facts and conditions associated with the Subject Property. As such, these conclusions and recommendations are based on subjective interpretations and the exercise of discretion. Many of these facts and conditions are subject to change over time. Accordingly, the conclusions and recommendations must be considered within this context.

The User understands that Roux will not be responsible for conditions or consequences arising from relevant facts that were concealed, withheld, or not fully disclosed at the time the Phase I ESA was performed. To the extent practicable, Roux has identified data gaps and has evaluated the potential significance of such data gaps. Recommendations to address those data gaps are presented herein and are based on the data available at the time of the performance of the Phase I ESA. Implementation of the recommendations may not fully address the data gaps as the information obtained from execution of those recommendations may alter or modify the interpretation of the Subject Property conditions and conclusions regarding the data gaps.

It should be noted that Roux has not conducted any intrusive activities on the Subject Property and is relying on information presented by others, often in preliminary, draft, or verbal form. By referencing this information, Roux does not accept responsibility for the accuracy of the underlying data, sampling methods, laboratory analysis, or documentation.

This Phase I ESA Report should not be considered a legal interpretation of existing environmental laws and regulations. The Phase I ESA was conducted with a reasonable degree of inquiry to identify significant RECs, but uncertainty is not eliminated. No Phase I ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. The Phase I ESA process is intended to reduce, but not eliminate, the uncertainty involved with identifying RECs.

This Phase I ESA Report is not an appraisal or value judgment of the Subject Property. The User understands that Roux shall not be liable for any use of the Phase I ESA Report as an appraisal or value judgment of the Subject Property.

The Phase I ESA Report has been prepared for the User for specific application to the Subject Property covered by the Phase I ESA Report. The User understands that any third-party use of this Phase I ESA Report is the sole responsibility and at the sole liability of the User.

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in §312.10 of 40 CFR 312; and

We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth on 40 CFR 312.

Respectfully Submitted,


ROUX ENVIRONMENTAL ENGINEERING AND GEOLOGY, D.P.C.

Stephen Loonie
Project Geologist

Jessica Taylor, PG
Principal Hydrogeologist

FIGURES

1. Subject Property Location Map
2. Subject Property Plan



QUADRANGLE LOCATION



N

1,000 0 1,000'

Title:

SUBJECT PROPERTY LOCATION MAP

2014 - 2042 FULTON STREET, BROOKLYN, NEW YORK

Prepared for:

STEPS AT SARATOGA
HOUSING DEVELOPMENT FUND CORPORATION

ROUX

Compiled by: S.L.	Date: 10/18/23
Prepared by: M.S.R.	Scale: AS SHOWN
Project Mgr: J.T.	Project: 3805.0002Y000
File: 3805.0002Y101.1.mxd	

FIGURE 1

V:\GIS\PROJECTS\3805\0002Y\101\3805.0002Y101.1.MXD



N

LEGEND

- PARCELS ONSITE
- SITE BOUNDARY (BLOCK 1549)

NOTES

1. AERIAL SOURCE: NYS OFFICE OF INFORMATION TECHNOLOGY SERVICES GIS PROGRAM OFFICE (GPO)

50 0 50'

Title:

SUBJECT PROPERTY PLAN

2014 - 2042 FULTON STREET, BROOKLYN, NEW YORK

Prepared for:
STEPS AT SARATOGA
HOUSING DEVELOPMENT FUND CORPORATION

ROUX

Compiled by: S.L.	Date: 10/18/23	FIGURE
Prepared by: M.S.R.	Scale: AS SHOWN	2
Project Mgr: J.T.	Project: 3805.0002Y000	
File: 3805.0002Y101.2.mxd		

V:\GIS\PROJECTS\3805\0002Y\101\3805.0002Y101.2.MXD

APPENDICES

A. Professional Profiles
B. Federal and State Environmental Databases
C. Freedom of Information Law Letters and Responses
D. Historical Sanborn Maps
E. Historical Aerial Maps
F. Historical Topographic Maps
G. City Directory Abstract
H. Subject Property Photographs
I. User Provided Information

APPENDIX A

Professional Profiles

PROFESSIONAL PROFILE



CONTACT INFORMATION

Main: (631) 232-2600
Direct: (631) 630-2395
Email: jtaylor@rouxinc.com
Website: www.rouxinc.com

209 Shafter Street
Islandia, NY 11749

EDUCATION

BS, Geology, Binghamton University, 2005

PROFESSIONAL LICENSES

Professional Geologist, New York, 2017

Jessica L. Taylor, PG

Principal Hydrogeologist

EXPERIENCE SUMMARY

Seventeen years of experience: Principal, Senior, Project, and Staff Hydrogeologist, Roux, Islandia, New York; Staff Hydrogeologist and Intern at GSC | Kleinfelder.

TECHNICAL SPECIALTIES

Project Management and Field Management for large-scale soil excavation and remediation projects, including site assessment, remediation implementation, and construction activities. Negotiation with NYSDEC Brownfield Clean-up Program (BCP) and NYCOER E-Designation/Voluntary Clean-up Program. Coordination and management of large-scale demolition and renovation support. Performance of sampling and direction of field sampling teams for the following media: soil, groundwater, surface water, soil vapor, sludge, and sediment. Soil characterization, coordination with construction management teams, disposal brokers, and facilities for cost-effective disposal of contaminated and clean soils from complex, large-scale projects.

REPRESENTATIVE PROJECTS

- Project Principal for a large ongoing redevelopment project in Brooklyn, New York, including four buildings with NYCOER E-Designations for Hazardous Materials. The project encompasses 22 acres including the Barclays Center. Project responsibilities include coordination and oversight of in situ waste characterization sampling, excavation, and proper disposal of 500,000 CY of soil. Included sampling, classification, and coordination with construction managers and soil disposal facilities for disposal of soil impacted by petroleum contamination and TCLP hazardous levels of lead and corrosivity. Designed soil delineation sampling programs to limit boundaries of more contaminated soils to reduce disposal costs. Responsible for implementing and managing remediation work at several NYSDEC spill sites within the project footprint, including in situ chemical oxidation, UST removal, and soil excavation. Agency support for NYSDEC, NYCDEP, NYCOER, MTA (LIRR/NYCT), and ESDC.
- Project Principal providing technical guidance to construction management team during the excavation of NYSDEC Brownfield Cleanup Program project in Yonkers, New York. Coordinated with development team, their consultant, soil brokers, and disposal facilities to determine appropriate facilities and manage costs during disposal of approximately 30,000 tons of soil contaminated with TCSA-level PCBs, hazardous lead, and elevated VOCs triggering UHCs.
- Project Principal for remediation of two parcels in Hunter's Point South, Queens, New York, as part of the NYSDEC Brownfield Cleanup Program. This project included due diligence environmental assessment and investigation, development of NYSDEC-approved Remedial Investigation Work Plan and Remedial Action Work Plan, and remediation during construction of two mixed-use, affordable housing developments. Acted on behalf of developer to provide soil classification data and vet disposal facilities, and eventual evaluation of Change Order Request by contractor for disposal of soil with elevated PAHs and hazardous levels of lead. Designed delineation sampling program to limit costs associated with disposal of contaminated soil.
- Project Principal for remediation of a 0.66-acre parcel in Brooklyn, New York, as part of a NYSDEC Brownfield Cleanup Program. This project included due diligence environmental assessment and investigation, development of NYSDEC-approved RIWP and RAWP including an active sub-slab depressurization system, and remediation during construction of mixed-use affordable housing developments including full cellar. Also required coordination with NYCHPD and NYCDEP to meet regulatory requirements for funding.

- Project Principal for management of NYCOER E-Designation for Hazardous Materials during excavation and construction of a hotel/residential building in Manhattanville. Responsibilities included negotiation with NYCOER to limit additional sampling required for Remedial Investigation, and soil management including performing *in situ* waste characterization, coordination with soil brokers, and oversight of disposal of 16,000 CY of soil.
- Project Principal for real estate acquisition due diligence for industrial properties across Queens and the Bronx. Prepared Phase I ESAs and designed and implemented Phase II ESAs to meet financing requirements while coordinating with selling parties. Provided technical and strategic support, including remedial cost estimates during short due diligence periods.
- Project Principal for redevelopment of four properties for a supportive housing development in Brooklyn, New York, with NYCOER to address NYCDEP E-Designations. Coordination with NYCOER to implement remedial investigation and develop RAP as part of the NYC VCP.
- Senior Project Manager for the environmental management of asbestos remediation during the renovation of Nassau Coliseum, Uniondale, New York. Responsible for coordinating inspections and delineation of ACM, preparing budgetary estimates, and bid support for full abatement. Also includes management of decommissioning and replacement of existing emergency generator UST.
- Project Manager for commercial redevelopment site in the Bronx, including in situ waste characterization, management and coordination of excavation, community air monitoring, and development of NYCDEP-approved RAP.
- Client liaison and full-time on-site construction manager at redevelopment site in Rego Park, New York. Collection of 500 *in situ* waste characterization soil samples, oversight of 250,000 cubic yards of soil excavation and remediation, development of post-remediation sampling plan, and organization of waste manifests and hazardous waste documents to ensure proper disposal. Coordination of daily site activities with multiple construction contractors and other involved parties on behalf of client. Oversight and confirmatory soil sampling for on-site treatment of 75,000 cubic yards of hazardous lead-contaminated soil.
- Project and Field Manager for Phase I and Phase II ESAs on a portfolio of retail gasoline stations in New York and New Jersey. Responsibilities included drilling and sampling oversight and health and safety management, as well as writing Phase II ESA reports for over 40 sites.
- Field Manager for remediation system installation in Brooklyn, New York. Responsibilities included daily oversight of contractors excavating soil and installing piping within streets and sidewalks. Ensured compliance with client-specific Health and Safety Completed daily health and safety meeting and reports and attended weekly construction progress meetings.
- Field manager for quarterly groundwater sampling rounds at a former pesticides manufacturing facility in Dayton, New Jersey. Responsibilities include direction of multiple sampling teams and coordination with subcontractors.
- Field manager for site investigation activities at a redevelopment site in Staten Island. Responsible for oversight of subcontractor performing soil borings and soil and groundwater sampling.
- Field manager during groundwater monitoring rounds at former oil and fuel distribution terminals in Staten Island, Westchester, Glen Cove, and Oceanside, New York. Activities include system operations and maintenance, supervision of multiple field personnel, performing water levels gauging, and collection of groundwater samples from site monitoring wells using a variety of equipment.
- Field manager during a site investigation at a former chemical manufacturer in Brooklyn, New York. Responsibilities included oversight of subcontractor installation of monitoring wells, collection of soil and groundwater samples, and logging soil lithology.
- Field manager for annual groundwater sampling at a chemical manufacturing Superfund site in Delaware. Involves the oversight and supervision of multiple teams of personnel for a weeklong gauging and sampling round.
- Field manager at an underground storage tank closure in Queens, New York. Provided health and safety supervision, collection of soil and groundwater samples, and oversight of subcontractor closure activities on behalf of client.
- Field manager for a long-term remediation project for the City of New York. Includes quarterly groundwater sampling and soil vapor sampling as part of an NYSDEC-approved work plan, as well as oversight of soil sampling as part of subsurface investigations. Creation of tables and figures based on investigation results and as part of periodic reports submitted to NYSDEC.
- Field manager during off-site investigation at a former chemical production facility in Rensselaer, New York. Investigation included the installation of piezometers, monitoring wells, and soil gas and environmental health and safety oversight.
- Project and Field Manager for implementation of a Phase II ESA at one of the largest on-going redevelopment projects in New York. Responsibilities included coordination and oversight of drilling, sampling, and excavation of soil. Drilling methods included sonic rotary, Geoprobe, hollow-stem auger, and air hammer/split spoon sampling. Includes oversight of Phase II ESA and waste characterization activities, coordination with laboratory contacts, as well as synthesis of lithology logs for over 100 soil borings. Project includes completion of Phase II ESAs (sampling of soil, groundwater, and soil gas) for over 50 properties.

- Project and field manager responsible for implementing and managing remediation work at several NYSDEC spill sites within the footprint of a large redevelopment project in Brooklyn, New York. Responsibilities included management and oversight of *in situ* chemical oxidation for treatment of petroleum-impacted groundwater.
- Field manager for redevelopment site in New Jersey. Collection of waste characterization soil samples, post excavation confirmatory sampling, and groundwater off-site discharge sampling.

PROFESSIONAL TRAININGS

OSHA 40-Hour HAZWOPER Training, 2005

OSHA 10-Hour Construction Safety Training, 2008

ROUX

PROFESSIONAL PROFILE

Stephen S. Loonie
Project Geologist

TECHNICAL EXPERIENCE

Phase I and II environmental site assessments, remedial construction oversight, Petroleum Bulk Storage regulations, drywell and storm drain investigation and remediation, regulatory coordination, Underground Storage Tank (UST) investigations and removal, SPDES permit compliance and management

EXPERIENCE SUMMARY:

Four years of experience: Project Geologist at Roux Environmental Engineering and Geology, D.P.C.; Environmental Scientist at TRC Companies, Inc.; Hydrogeologist at RNC Environmental Geology, P.G.

CREDENTIALS:

B.S. Environmental Geology, SUNY Binghamton 2017

OSHA 40-Hour HAZWOPER and OSHA 8-Hour Annual Refreshers

OSHA 30-Hour Construction Safety, 2020

OSHA 10-Hour Construction Safety, 2020

KEY PROJECTS

- Authored and assisted on over 100 Phase I Environmental Site Assessments for properties in the greater New York City area and Long Island. These assessments ranged from small residential properties to large scale industrial, commercial and manufacturing businesses. Responsible for maintaining report integrity and compliance with ASTM E1527-13 standards. Maintained client expectations and delivered accurate results in a timely manner to satisfy tight due diligence deadlines. Provided recommendations and cost estimates to clients if Phase II investigations were warranted.
- Performed a Phase I and IAQ survey portfolio of over 30 sites in service of the New York City School Construction Authority (NYCSCA) and New York City Economic Development Corporation (NYCEDC) for the Learning Bridges program. Responsible for maintaining report integrity and compliance with ASTM E1527-13 standards. Maintained client expectations and delivered accurate results in a timely manner to satisfy tight due diligence deadlines.
- Managed the monitoring and compliance activities for the SPDES permit registered for the Astoria Park Pool wastewater discharge system in Queens, New York. Responsible for field work scheduling, report preparation, subcontractor oversight. Maintained client expectations and delivered accurate results in a timely manner to satisfy tight deadlines.
- Performed oversight of foundation and general contractors installing various engineering controls including: concrete covers, vapor barriers and SSD systems to ensure appropriate installation methods. Audited and corrected installation methods to ensure strict adherence to engineering design. Performed yearly inspections of these systems for SMP compliance on OER projects and generated SMP inspection reports. Maintained client expectations and delivered accurate results in a timely manner to satisfy tight deadlines.
- Served as environmental scientist in connection with the construction and reconstruction of park buildings and facilities throughout New York City. Responsibilities include collection of soil and groundwater samples in connection with subsurface investigations and groundwater sampling events, landfill gas monitoring, waste characterization sampling, and particulate monitoring in accordance with CAMPs. Maintained client expectations and delivered accurate results in a timely manner to satisfy tight deadlines.
- Implemented and monitored remedial measures at John F. Kennedy Airport in New York, including oversight of engineering controls over select LNAPL plumes. Performed biennial site-wide groundwater monitoring investigations and prepared biennial progress reports based on the investigation findings. Maintained client expectations and delivered accurate results in a timely manner to satisfy tight deadlines.
- Performed in-situ chemical oxidation injections and subsequent groundwater monitoring at several properties owned by the Port Authority of New York and New Jersey (PANYNJ). Maintained client expectations and delivered accurate results in a timely manner to satisfy tight deadlines.
- Served as a Project Scientist during a Supplemental Site Investigation for the assessment of current soil and groundwater conditions at a former spill Site in Long Island City, New York. Screened soil for indications of contamination, recorded geologic descriptions of soil, collected soil samples at collocated soil/groundwater monitoring well locations, and performed oversight during installation of groundwater monitoring wells.
- Served as environmental scientist in connection with a radiological survey performed for the New Jersey Department of Environmental Protection (NJDEP) at a Site in Middlesex, New Jersey, under licensed site remediation professional (LSRP) supervision. Field activities included soil sample collection, soil characterization, subcontractor oversight, and collection of in-situ radiological data.

209 Shafter Street | Islandia, NY 11749
Main: (631) 232-2600 | Direct: (631) 630-2379
Email: sloonie@rouxinc.com | Website: www.rouxinc.com

APPENDIX B

Federal and State Environmental Databases

2014 Fulton Street
2014 Fulton Street
Brooklyn, NY 11233

Inquiry Number: 7438000.2s
September 07, 2023

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	871
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

2014 FULTON STREET
BROOKLYN, NY 11233

COORDINATES

Latitude (North):	40.6784070 - 40° 40' 42.26''
Longitude (West):	73.9176170 - 73° 55' 3.42''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	591474.4
UTM Y (Meters):	4503410.0
Elevation:	80 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20190830
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	LOT 19,TAXBLOCK 1549	2014 FULTON STREET	NY E DESIGNATION		TP
A2	LOT 20,TAXBLOCK 1549	2016 FULTON STREET	NY E DESIGNATION	Lower	1 ft.
A3	LOT 23,TAXBLOCK 1549	2020A FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A4	LOT 21,TAXBLOCK 1549	2018 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A5	LOT 25,TAXBLOCK 1549	2024 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A6	LOT 31,TAXBLOCK 1549	2036 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
B7	LOT 34,TAXBLOCK 1549	2042 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
B8	LOT 33,TAXBLOCK 1549	2040 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A9	LOT 24,TAXBLOCK 1549	2022 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A10	LOT 28,TAXBLOCK 1549	FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A11	LOT 18,TAXBLOCK 1549	FULTON STREET	NY E DESIGNATION	Lower	1 ft.
A12	LOT 30,TAXBLOCK 1549	2034 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
B13	LOT 35,TAXBLOCK 1549	224 SARATOGA AVENUE	NY E DESIGNATION	Higher	1 ft.
A14	LOT 22,TAXBLOCK 1549	2020 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
B15	LOT 32,TAXBLOCK 1549	2038 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A16	LOT 29,TAXBLOCK 1549	FULTON STREET	NY E DESIGNATION	Higher	1 ft.
A17	LOT 26,TAXBLOCK 1549	2026 FULTON STREET	NY E DESIGNATION	Higher	1 ft.
B18	MTA NYCT - SARATOGA	FULTON ST & SARATOGA	RCRA-SQG, NY MANIFEST	Higher	38, 0.007, East
B19	NYCTA ESSEX ST FIELD	2046 FULTON STREET	NJ MANIFEST	Higher	41, 0.008, East
A20	PRIVATE RESIDENCE	1095 HERKIMER ST	NY Spills	Higher	45, 0.009, SE
A21	1093 HERKIMER ST.	1093 HERKIMER ST	NY Spills	Higher	46, 0.009, SE
A22	CON EDISON	1091 HERKIMER ST	NY MANIFEST	Higher	46, 0.009, SE
A23	CON EDISON SERVICE B	1091 HERKIMER ST	RCRA NonGen / NLR	Higher	46, 0.009, SE
A24	CON EDISON SERVICE B	1103 HERKIMER ST	RCRA NonGen / NLR, NY MANIFEST	Higher	66, 0.013, SE
B25	MULTI FAMILY	1115 HERKIMER ST	NY Spills	Higher	67, 0.013, ESE
A26	2006 A FULTON STREET	2006 A FULTON STREET	NY LTANKS	Lower	75, 0.014, West
A27	2006A FULTON STREET	2006A FULTON STREET	NY UST	Lower	96, 0.018, WNW
A28	LOT 13,TAXBLOCK 1549	2006A FULTON STREET	NY E DESIGNATION	Lower	96, 0.018, WNW
A29	PRESCOTT AUTMTC TRAN	2004 FULTON ST	EDR Hist Auto	Lower	108, 0.020, WNW
A30	LOT 12,TAXBLOCK 1549	2004 FULTON STREET	NY E DESIGNATION	Lower	108, 0.020, WNW
A31	CON EDISON	1063 HERKIMER ST	NY MANIFEST	Higher	122, 0.023, WSW
A32	CON EDISON	1063 HERKIMER ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	122, 0.023, WSW
A33	CON EDISON	1063 HERKIMER ST	NJ MANIFEST	Higher	122, 0.023, WSW
B34	VAULT # 3800	HERKIMER ST NEAR SAR	NY Spills	Higher	131, 0.025, ESE
B35	CONSOLIDATED EDISON	HERKIMER ST & SARATO	NY MANIFEST	Higher	134, 0.025, ESE
B36	VAULT VS 3704	SARTOGA AVE AND HERK	NY Spills	Higher	135, 0.026, ESE
B37	VAULT 3295	HERKIMER ST/SARATOGA	NY Spills	Higher	135, 0.026, ESE
B38	MANHOLE 14355	HULL ST / SARATOGA A	NY Spills	Lower	149, 0.028, ENE
A39	LENNY GOODWIN RESIDE	17 HULL ST	NY Spills	Lower	156, 0.030, North

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A40	H.P.D. HOUSING	21 HULL ST	NY Spills	Lower	164, 0.031, NNE
A41	CON EDISON	HERKIMER ST & DEWEY	RCRA NonGen / NLR, FINDS, ECHO	Higher	179, 0.034, SW
A42	CON EDISON	HERKIMER ST & DEWEY	NY MANIFEST	Higher	179, 0.034, SW
A43	CON EDISON	HERKIMER ST & DEWEY	NJ MANIFEST	Higher	179, 0.034, SW
A44	1064 HERKIMER STREET	1064 HERKIMER STREET	NY LTANKS	Higher	187, 0.035, SSW
A45	LOT 7,TAXBLOCK 1549	FULTON STREET	NY E DESIGNATION	Lower	209, 0.040, West
C46		1088 HERKIMER STREET	NY LTANKS, NY LEAD	Higher	212, 0.040, South
A47	LOT 6,TAXBLOCK 1549	1994 FULTON STREET	NY E DESIGNATION	Lower	230, 0.044, West
D48	BACK YARD	1049 HERKIMER ST	NY Spills	Lower	231, 0.044, WSW
E49	I.S. 271 JOHN M. COL	1137 HERKIMER ST	RCRA-SQG, FINDS, ECHO, NY LEAD, NY MANIFEST	Higher	233, 0.044, ESE
E50	I.S. 271 - BROOKLYN	1137 HERKIMER STREET	NY AST	Higher	233, 0.044, ESE
D51	LOT 5,TAXBLOCK 1549	1992 FULTON STREET	NY E DESIGNATION	Lower	249, 0.047, West
E52	CON EDISON SERVICE B	1132 HERKIMER ST	RCRA NonGen / NLR, NY MANIFEST	Higher	251, 0.048, ESE
D53	LOT 4,TAXBLOCK 1549	FULTON STREET	NY E DESIGNATION	Lower	269, 0.051, West
C54	SPILL NUMBER 9905790	11 LOUIS PLACE	NY Spills	Higher	273, 0.052, SSE
F55	CON EDISON SERVICE B	84 MACDOUGAL	RCRA NonGen / NLR, NY MANIFEST	Lower	275, 0.052, North
F56	CON EDISON	86 MACDOUGAL ST	NY MANIFEST	Lower	278, 0.053, North
F57	CON EDISON	86 MACDOUGAL ST	NJ MANIFEST	Lower	278, 0.053, North
F58	CON EDISON	86 MACDOUGAL ST	RCRA NonGen / NLR	Lower	278, 0.053, North
G59	CON ED	47 HULL ST	NY MANIFEST	Lower	279, 0.053, ENE
G60	CON EDISON	47 HULL ST	RCRA NonGen / NLR	Lower	279, 0.053, ENE
G61	CON EDISON	47 HULL ST	NJ MANIFEST	Lower	279, 0.053, ENE
D62	LOT 3,TAXBLOCK 1549	1988A FULTON STREET	NY E DESIGNATION	Lower	309, 0.059, West
C63	SPILL NUMBER 0200021	248 SARATOGA AVE	NY Spills	Higher	310, 0.059, SE
D64	LOT 1,TAXBLOCK 1549	1986 FULTON STREET	NY E DESIGNATION	Lower	339, 0.064, West
H65	PLEASANT GROVE BAPTI	1927 FULTON STREET	NY AST	Lower	350, 0.066, WNW
D66	MANHOLE 66326	1042 HERKIMER ST	NY Spills	Higher	359, 0.068, WSW
D67	CON EDISON - MANHOLE	1036 HERKIMER ST	NY MANIFEST	Higher	374, 0.071, WSW
D68	CON EDISON - MANHOLE	1036 HERKIMER ST	RCRA-LQG	Higher	374, 0.071, WSW
C69	CON ED	21 LOUIS PL	NY MANIFEST	Higher	404, 0.077, SSE
C70	CON EDISON	21 LOUIS PL	RCRA NonGen / NLR	Higher	404, 0.077, SSE
C71	CON EDISON	21 LOUIS PL	NJ MANIFEST	Higher	404, 0.077, SSE
F72	CON EDISON	105 MACDOUGAL ST	NY MANIFEST	Lower	408, 0.077, North
F73	CON EDISON SERVICE B	105 MCDOUGAL ST	RCRA NonGen / NLR	Lower	408, 0.077, North
G74	MACDOUGAL ST/SARATOG	MACDOUGAL ST/SARATOG	NY Spills	Lower	409, 0.077, NNE
D75	LOT 33,TAXBLOCK 1548	1984 FULTON STREET	NY E DESIGNATION	Lower	415, 0.079, West
F76	CON EDISON	117 MACDOUGAL ST	NJ MANIFEST	Lower	435, 0.082, North
F77	CON EDISON	117 MACDOUGAL ST	NY MANIFEST	Lower	435, 0.082, North
F78	CON EDISON SERVICE B	117 MCDOUGAL STREET	RCRA NonGen / NLR, NY MANIFEST	Lower	435, 0.082, North

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
F79	CON EDISON	117 MACDOUGAL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	435, 0.082, North
D80	LOT 32,TAXBLOCK 1548	1982 FULTON STREET	NY E DESIGNATION	Lower	442, 0.084, West
F81	CON EDISON SERVICE B	123 MCDOUGAL ST	RCRA NonGen / NLR, NY MANIFEST	Lower	451, 0.085, NNE
I82	NEXT TO 85 MACDOUGAL	BY HOWARD AVE & MACD	NY Spills	Lower	465, 0.088, NW
J83	CON EDISON	1967 ATLANTIC AVE	RCRA NonGen / NLR	Higher	467, 0.088, South
H84	VACANT LOT NEXT TO H	83 MACDOUGAL ST	NY Spills	Lower	472, 0.089, NW
K85	W & M ESSO SERVICE S	1993 ATLANTIC AVE	EDR Hist Auto	Higher	492, 0.093, SSE
H86	77 MACDOUGAL ST	77 MACDOUGAL ST	NY Spills	Lower	494, 0.094, NW
L87	CON ED	52 HULL ST	NY MANIFEST	Higher	506, 0.096, ENE
L88	CON EDISON	52 HULL ST	NJ MANIFEST	Higher	506, 0.096, ENE
L89	CON EDISON	52 HULL ST	RCRA NonGen / NLR	Higher	506, 0.096, ENE
H90	LOT 29,TAXBLOCK 1548	1970 FULTON STREET	NY E DESIGNATION	Lower	517, 0.098, West
K91	CON EDISON	2001 ATLANTIC AVE FR	NY MANIFEST	Higher	525, 0.099, SE
K92	CON EDISON SERVICE B	2001 ATLANTIC AVE	RCRA NonGen / NLR, FINDS	Higher	525, 0.099, SE
K93	CON EDISON SERVICE B	2001 ATLANTIC AVE FR	RCRA NonGen / NLR	Higher	525, 0.099, SE
K94	CON EDISON	2001 ATLANTIC AVE	NY MANIFEST	Higher	525, 0.099, SE
J95	ROMANELLI ANTHONY	1943 ATLANTIC AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	533, 0.101, SSW
J96	CON EDISON	1943 ATLANTIC AV	NY MANIFEST	Higher	533, 0.101, SSW
J97	CON EDISON	1943 ATLANTIC AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	533, 0.101, SSW
M98	CON EDISON SERVICE B	298 HOWARD AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	535, 0.101, SW
J99	CON EDISON	ATLANTIC AVE & LOUIS	RCRA NonGen / NLR, FINDS, ECHO	Higher	535, 0.101, South
H100	CON EDISON	1921 FULTON ST	NJ MANIFEST	Lower	535, 0.101, WNW
H101	CON ED	1921 FULTON ST	NY MANIFEST	Lower	535, 0.101, WNW
H102	CON EDISON	1921 FULTON ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	535, 0.101, WNW
H103	LOT 128,TAXBLOCK 154	1968 FULTON STREET	NY E DESIGNATION	Lower	535, 0.101, West
J104	CON ED	ATLANTIC AVE & DEWEY	NY MANIFEST	Higher	542, 0.103, SSW
J105	CON EDISON	ATLANTIC AVE & DEWEY	NJ MANIFEST	Higher	542, 0.103, SSW
J106	CON EDISON	ATLANTIC AVE & DEWEY	RCRA NonGen / NLR	Higher	542, 0.103, SSW
I107	CON EDISON	166 SUMPTER ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	548, 0.104, NNW
I108	CON EDISON	166 SUMPTER ST	NY MANIFEST	Lower	548, 0.104, NNW
H109	LOT 28,TAXBLOCK 1548	1966 FULTON STREET	NY E DESIGNATION	Lower	555, 0.105, West
M110	315 HOWARD AVE	315 HOWARD AVE	NY Spills	Higher	566, 0.107, SW
N111	LOT 27,TAXBLOCK 1548	1964 FULTON STREET	NY E DESIGNATION	Lower	576, 0.109, West
L112	CON EDISON	77 HULL ST	NJ MANIFEST	Higher	578, 0.109, ENE
L113	CON EDISON	77 HULL ST	NY MANIFEST	Higher	578, 0.109, ENE
L114	CON EDISON	77 HULL ST	RCRA NonGen / NLR	Higher	578, 0.109, ENE
O115	CON EDISON	190 SUMPTER ST	NY MANIFEST	Lower	580, 0.110, North
O116	CON EDISON SERVICE B	190 SUMPTER ST	RCRA NonGen / NLR	Lower	580, 0.110, North
P117	CON EDISON	148 MACDOUGAL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	583, 0.110, ENE

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P118	CON EDISON	148 MACDOUGAL ST	NJ MANIFEST	Lower	583, 0.110, ENE
P119	CON ED	148 MACDOUGAL ST	NY MANIFEST	Lower	583, 0.110, ENE
I120	NEW CONSTRUCTION	150 SUMPTER ST	NY Spills	Lower	593, 0.112, NNW
N121	LOT 26,TAXBLOCK 1548	1962 FULTON STREET	NY E DESIGNATION	Lower	597, 0.113, West
K122	COMMERICAL	2120 ATLANTIC AVE	NY Spills	Higher	606, 0.115, SSE
K123	PARK AVE BLDG & ROOF	2120 ATLANTIC AVE	RCRA NonGen / NLR	Higher	606, 0.115, SSE
J124	CON EDISON	2112 ATLANTIC AVE FR	NY MANIFEST	Higher	606, 0.115, South
J125	CON EDISON SERVICE B	2112 ATLANTIC AVE FR	RCRA NonGen / NLR, FINDS	Higher	606, 0.115, South
J126	CON EDISON SERVICE B	2100 ATLANTIC AVE FR	RCRA NonGen / NLR, FINDS	Higher	607, 0.115, South
J127	CON EDISON	2100 ATLANTIC AVE FR	NY MANIFEST	Higher	607, 0.115, South
P128	CON EDISON	155 MACDOUGAL ST	NY MANIFEST	Lower	607, 0.115, NE
P129	CON EDISON	155 MACDOUGAL ST	NJ MANIFEST	Lower	607, 0.115, NE
P130	CON EDISON	155 MACDOUGAL ST	RCRA NonGen / NLR	Lower	607, 0.115, NE
I131	233 HOWARD AVENUE	233 HOWARD AVENUE	NY Spills	Lower	608, 0.115, NW
I132	CON EDISON	250 HOWARD ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	610, 0.116, NW
I133	CON EDISON	250 HOWARD ST	NJ MANIFEST	Lower	610, 0.116, NW
I134	CON EDISON	250 HOWARD ST	NY MANIFEST	Lower	610, 0.116, NW
J135	CON EDISON	2090 ATLANTIC AVE FR	NY MANIFEST	Higher	617, 0.117, SSW
J136	CON EDISON MANHOLE:	2090 ATLANTIC AVE FR	RCRA NonGen / NLR, FINDS	Higher	617, 0.117, SSW
O137	CON EDISON	F/O 204 SUMPTER ST	NY MANIFEST	Lower	630, 0.119, NNE
P138	CON EDISON SERVICE B	159 MACDOUGAL ST	RCRA NonGen / NLR	Lower	631, 0.120, NE
P139	CON EDISON	159 MACDOUGAL ST	NY MANIFEST	Lower	631, 0.120, NE
O140	AUSTIN RES	201 SUMTER ST	NY Spills	Lower	636, 0.120, North
N141	USPS - STUYVESANT ST	1915 FULTON ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	657, 0.124, WNW
N142	US POSTAL SERVICE -	1915 FULTON STREET	NY AST	Lower	657, 0.124, WNW
K143	CLOSED S/S	2130 ATLANTIC AVENUE	NY UST, NY AST	Higher	661, 0.125, SSE
Q144	CON EDISON	61 MACDOUGAL	NJ MANIFEST	Lower	664, 0.126, WNW
Q145	CON EDISON	61 MACDOUGAL	RCRA NonGen / NLR, FINDS, ECHO	Lower	664, 0.126, WNW
Q146	CON EDISON	61 MACDOUGAL	NY MANIFEST	Lower	664, 0.126, WNW
J147	CON EDISON	2074 ATLANTIC AVE FR	NY MANIFEST	Higher	673, 0.127, South
J148	CON EDISON SERVICE B	2074 ATLANTIC AVE FR	RCRA NonGen / NLR, FINDS	Higher	673, 0.127, South
P149	CON EDISON	156 MACDOUGAL ST	NY MANIFEST	Lower	676, 0.128, ENE
P150	CON EDISON SERVICE B	156 MACDOUGAL ST	RCRA NonGen / NLR, FINDS	Lower	676, 0.128, ENE
Q151	CON EDISON	59 MACDOUGAL ST	NY MANIFEST	Lower	679, 0.129, WNW
Q152	CON EDISON SERVICE B	59 MCDOUGAL ST	RCRA NonGen / NLR, FINDS	Lower	679, 0.129, WNW
Q153	CON EDISON	59 MCDOUGAL ST	NY MANIFEST	Lower	679, 0.129, WNW
R154	CON ED	179 SUMPTER ST	NY MANIFEST	Lower	690, 0.131, NNW
Q155	NYC DEP	55 MACDOUGAL PLACE	RCRA NonGen / NLR, FINDS, ECHO	Lower	703, 0.133, WNW
Q156	NYC DEP	55 MACDOUGAL PLACE	NY MANIFEST	Lower	703, 0.133, WNW

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
O157	CON EDISON SERVICE B	209 SUMPTER ST	RCRA NonGen / NLR, NY MANIFEST	Lower	710, 0.134, North
L158	CON EDISON	87 HULL ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	710, 0.134, ENE
L159	CON EDISON	87 HULL ST	NJ MANIFEST	Higher	710, 0.134, ENE
L160	CON EDISON	87 HULL ST	NY MANIFEST	Higher	710, 0.134, ENE
N161	P.S. 28 THE WARREN	1001 HERKIMER ST	RCRA-SQG, FINDS, NY MANIFEST	Lower	727, 0.138, West
N162	P.S. 28 - BROOKLYN (	1001 HERKIMER STREET	NY AST	Lower	727, 0.138, West
Q163	53 MACDOUGAL STREET	53 MACDOUGAL ST	NY VCP	Lower	732, 0.139, WNW
S164	CON EDISON SERVICE B	170 HOPKINSON AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	767, 0.145, East
T165	CON ED	229 SUMPTER ST	NY MANIFEST	Lower	775, 0.147, NNE
U166	SHARIFA MANAGEMENT C	2125 PACIFIC STREET	NY AST	Higher	793, 0.150, SSE
V167	TRI STATE TRUCK & TR	1927 ATLANTIC AVENUE	NY AST	Higher	799, 0.151, SW
T168	CON EDISON SERVICE B	237 SUMPTER ST	RCRA NonGen / NLR, NY MANIFEST	Lower	800, 0.152, NNE
S169	CON EDISON MANHOLE 6	HERKIMER ST & HOPKIN	RCRA NonGen / NLR, NY MANIFEST	Higher	805, 0.152, ESE
S170	CON EDISON	171 HOPKINSON	NY MANIFEST	Higher	807, 0.153, East
S171	CON EDISON SERVICE B	171 HOPKINSON	RCRA NonGen / NLR, FINDS	Higher	807, 0.153, East
S172	CON EDISON	171 THOMAS S BOYLAND	NY MANIFEST	Higher	807, 0.153, East
R173	CON EDISON	FO 284 MARION ST	NY MANIFEST	Lower	815, 0.154, North
R174	CON EDISON	282 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	816, 0.155, NNW
R175	CON EDISON	282 MARION ST	NJ MANIFEST	Lower	816, 0.155, NNW
R176	CON EDISON	282 MARION ST	NY MANIFEST	Lower	816, 0.155, NNW
W177	TOWER ISLES FROZEN F	2025 ATLANTIC AVE	NY UST	Higher	816, 0.155, ESE
V178	CON EDISON	ATLANTIC AVE & BANCR	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	817, 0.155, SW
R179	CON EDISON	280 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	818, 0.155, NNW
R180	CON EDISON	280 MARION ST	NJ MANIFEST	Lower	818, 0.155, NNW
R181	CON ED	280 MARION ST	NY MANIFEST	Lower	818, 0.155, NNW
R182	CON EDISON	292 MARION ST	NY MANIFEST	Lower	819, 0.155, North
R183	CON EDISON	292 MARION ST	NJ MANIFEST	Lower	819, 0.155, North
R184	CON EDISON	292 MARION ST	NJ MANIFEST	Lower	819, 0.155, North
R185	CON EDISON	292 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	819, 0.155, North
R186	CON EDISON	292 MARION ST	RCRA NonGen / NLR	Lower	819, 0.155, North
R187	CON EDISON	276 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	823, 0.156, NNW
R188	CON EDISON	276 MARION ST	NY MANIFEST	Lower	823, 0.156, NNW
R189	CON EDISON	276 MARION ST	NJ MANIFEST	Lower	823, 0.156, NNW
O190	CON EDISON	304 MARION ST & SARA	NY MANIFEST	Lower	830, 0.157, North
X191	CON EDISON SERVICE B	298 MARION ST	RCRA NonGen / NLR, FINDS	Lower	830, 0.157, North
X192	CON EDISON	298 MARION ST	NY MANIFEST	Lower	830, 0.157, North
R193	CON EDISON	FRONT OF 270 MARION	NY MANIFEST	Lower	837, 0.159, NNW
Y194	CON EDISON	985 HERKIMER ST	NY MANIFEST	Lower	839, 0.159, West
Y195	CON EDISON	F/O 985 HERKIMER ST	NY MANIFEST	Lower	839, 0.159, West

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Y196	CON EDISON	985 HERKIMER ST	NY MANIFEST	Lower	839, 0.159, West
V197	1921 LIHTC LLC - 192	1921 ATLANTIC AVE	RCRA NonGen / NLR	Lower	840, 0.159, WSW
Z198	CON EDISON	F/O 153 SUMPTER ST	NY MANIFEST	Lower	840, 0.159, NW
Z199	CON EDISON	153 SUMPTER ST	NJ MANIFEST	Lower	840, 0.159, NW
Z200	CON EDISON	153 SUMPTER ST	NY MANIFEST	Lower	840, 0.159, NW
Z201	CON EDISON	153 SUMPTER ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	840, 0.159, NW
W202	2170 ATLANTIC AVE	2170 ATLANTIC AVENUE	NY AST	Higher	845, 0.160, SE
R203	CON EDISON	266 MARION ST	NJ MANIFEST	Lower	849, 0.161, NNW
R204	CON EDISON	266 MARION ST	NY MANIFEST	Lower	849, 0.161, NNW
R205	CON EDISON	266 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	849, 0.161, NNW
AA206	138 HOPKINSON ASSOCI	138 HOPKINSON AVENUE	NY AST	Lower	853, 0.162, ENE
U207	VERIZON	SARATOGA AVE & PACIF	RCRA NonGen / NLR	Higher	853, 0.162, SSE
U208	CON EDISON	SARATOGA AVE & PACIF	RCRA NonGen / NLR	Higher	853, 0.162, SSE
U209	CON EDISON	SARATOGA AVE & PACIF	NJ MANIFEST	Higher	853, 0.162, SSE
U210	CON EDISON	SARATOGA AVE & PACIF	NY MANIFEST	Higher	853, 0.162, SSE
U211	BELL ATLANTIC-NY	SARATOGA AVE/PACIFIC	RCRA NonGen / NLR, NY MANIFEST	Higher	857, 0.162, SSE
V212	CON EDISON	2038 ATLANTIC AVE FR	NY MANIFEST	Higher	863, 0.163, SW
V213	CON EDISON SERVICE B	2038 ATLANTIC AVE FR	RCRA NonGen / NLR	Higher	863, 0.163, SW
Q214	CON EDISON	OPP 116 SUMPTER ST	NY MANIFEST	Lower	872, 0.165, WNW
W215	CON EDISON SERVICE B	217 HOPKINSON AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	879, 0.166, ESE
AB216	CON EDISON	2151 PACIFIC ST	NY MANIFEST	Higher	891, 0.169, SE
AB217	CON EDISON	2151 PACIFIC ST	NJ MANIFEST	Higher	891, 0.169, SE
AB218	CON EDISON	2151 PACIFIC ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	891, 0.169, SE
T219	CON EDISON SERVICE B	322 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	903, 0.171, NNE
AC220	CON EDISON - SERVICE	255 SUMPTER ST	NY MANIFEST	Lower	905, 0.171, NE
AD221	CON EDISON	2042A PACIFIC ST	NY MANIFEST	Higher	918, 0.174, South
AD222	CON EDISON	2042A PACIFIC ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	918, 0.174, South
AD223	CON EDISON	2042A PACIFIC ST	NJ MANIFEST	Higher	918, 0.174, South
U224	AFRO CARTING CO.	286 SARATOGA AVE	NY SWF/LF	Higher	929, 0.176, SSE
AE225	CON EDISON	84 HULL ST	NJ MANIFEST	Higher	930, 0.176, ENE
AE226	CON EDISON	84 HULL ST	NY MANIFEST	Higher	930, 0.176, ENE
AE227	CON EDISON	84 HULL ST	RCRA NonGen / NLR	Higher	930, 0.176, ENE
AF228	REGIONAL MGMT & CONS	HOWARD AVE & PACIFIC	RCRA NonGen / NLR	Higher	932, 0.177, SSW
V229	1921 ATLANTIC AVENUE	1911 ATLANTIC AVENUE	NY BROWNFIELDS, NY E DESIGNATION	Lower	935, 0.177, WSW
Y230	CON EDISON SERVICE B	24 MACDOUGAL ST	RCRA NonGen / NLR, NY MANIFEST	Lower	936, 0.177, WNW
T231	CON EDISON SERVICE B	336 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	937, 0.177, NNE
AE232	CON EDISON SERVICE B	86 HULL ST	RCRA NonGen / NLR, FINDS	Higher	948, 0.180, ENE
AE233	CON EDISON	86 HULL ST	NY MANIFEST	Higher	948, 0.180, ENE
AE234	CON EDISON	105 HULL ST	NY MANIFEST	Higher	956, 0.181, ENE

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AE235	CON EDISON SERVICE B	105 HULL ST	RCRA NonGen / NLR	Higher	956, 0.181, ENE
V236	CON EDISON - MANHOLE	2034 ATLANTIC AVE	RCRA-LQG	Higher	981, 0.186, SW
V237	CON EDISON - MANHOLE	2034 ATLANTIC AVE	NY MANIFEST	Higher	981, 0.186, SW
AG238	ACCUTECH FOREIN CAR	22 PRESCOTT PLACE	NY AST	Lower	983, 0.186, WSW
S239	15 SOMERS STREET	15 SOMERS STREET	NY UST	Higher	983, 0.186, East
S240	CON EDISON	15 SOMER ST	NY MANIFEST	Higher	983, 0.186, East
AH241	CON EDISON	253 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	988, 0.187, NNW
AH242	CON EDISON	253 MARION ST	NJ MANIFEST	Lower	988, 0.187, NNW
AH243	CON EDISON	253 MARION ST	NY MANIFEST	Lower	988, 0.187, NNW
AA244	CON EDISON SERVICE B	129 HOPKINSON	RCRA NonGen / NLR, NY MANIFEST	Lower	988, 0.187, NE
AC245	CON EDISON	348 MARION ST	NY MANIFEST	Lower	988, 0.187, NNE
AC246	CON EDISON SERVICE B	348 MARION ST	RCRA NonGen / NLR	Lower	988, 0.187, NNE
AG247	20 PRESCOTT PLACE	20 PRESCOTT PLACE	NY VCP	Lower	997, 0.189, WSW
AI248	CON EDISON SERVICE B	29-29A MCDOUGAL ST	RCRA NonGen / NLR	Lower	997, 0.189, WNW
AI249	CON EDISON SERVICE B	29 MCDOUGAL ST	NJ MANIFEST	Lower	997, 0.189, WNW
AI250	CON EDISON	29-29A MCDOUGAL ST	NY MANIFEST	Lower	997, 0.189, WNW
AI251	CON EDISON SERVICE B	29 MCDOUGAL ST	RCRA NonGen / NLR, FINDS	Lower	997, 0.189, WNW
AI252	CON EDISON	29 MCDOUGAL ST	NY MANIFEST	Lower	997, 0.189, WNW
W253	BILL'S DRY CLEANERS	2043 ATLANTIC AVE	RCRA NonGen / NLR, ICIS, US AIRS, FINDS, ECHO	Higher	1002, 0.190, ESE
W254	BILL'S DRY CLEANERS	2043 ATLANTIC AVE	NY DRYCLEANERS	Higher	1002, 0.190, ESE
AF255	343 HOWARD AVENUE	343 HOWARD AVENUE	NY AST	Higher	1018, 0.193, SSW
AJ256	CON EDISON - MANHOLE	THOMAS S BOYLAND ST	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Lower	1031, 0.195, NE
Z257	CON EDISON SERVICE B	236 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1032, 0.195, NW
AK258	CON EDISON SERVICE B	317 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1037, 0.196, NNE
AI259	RITE AID #04893	1950 FULTON ST	RCRA-VSQG, NY MANIFEST	Lower	1064, 0.202, West
AI260	RITE AID # 04893	1950 FULTON ST	PA MANIFEST	Lower	1064, 0.202, West
V261	MTA LIRR - ATLANTIC	2010 ATLANTIC AVE	RCRA-SQG, NY MANIFEST, NJ MANIFEST	Higher	1064, 0.202, SW
V262	FAMILY DOLLAR STORE	2010 ATLANTIC AVE SU	RCRA-VSQG	Higher	1064, 0.202, SW
V263	CON EDISON SERVICE B	2010 ATLANTIC AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1064, 0.202, SW
AL264	DEAN STREET TRANSITO	2155 DEAN STREET	NY AST	Higher	1065, 0.202, SSE
AF265	351 HOWARD AVE	351 HOWARD AVENUE	NY AST	Higher	1072, 0.203, SSW
AM266	2027 PACIFIC STREET	2027 PACIFIC STREET	NY AST	Higher	1074, 0.203, SW
AK267	GRANT RESIDENCE	335 MARION ST	NY LTANKS	Lower	1078, 0.204, NNE
AN268	2185 PACIFIC STREET	2185 PACIFIC STREET	NY AST	Higher	1082, 0.205, SE
AO269	CON EDISON	F/O 348 CHAUNCEY ST	NY MANIFEST	Lower	1084, 0.205, NNW
AP270	CON EDISON SERVICE B	1235 HERKIMER ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1090, 0.206, East
AG271	335 RALPH AVENUE	335 RALPH AVENUE	NY VCP	Lower	1090, 0.206, WSW
AQ272	CON EDISON	30 MARCONI PL	NJ MANIFEST	Higher	1092, 0.207, ESE
AQ273	CON EDISON	30 MARCONI PL	RCRA NonGen / NLR, FINDS, ECHO	Higher	1092, 0.207, ESE

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AQ274	CON EDISON	30 MARCONI PL	NY MANIFEST	Higher	1092, 0.207, ESE
AH275	CON EDISON SERVICE B	237 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1092, 0.207, NW
AR276	CON ED - MH 65388	HERKIMER ST AND RALP	RCRA NonGen / NLR, NY MANIFEST	Lower	1101, 0.209, West
AR277	CONSOLIDATED EDISON	HERKIMER ST & RALPH	NY MANIFEST	Lower	1101, 0.209, West
AS278	CON EDISON	FRONT OF 235 MARION	NY MANIFEST	Lower	1102, 0.209, NW
AG279	CON EDISON SERVICE B	343 RALPH AVE FRONT	RCRA NonGen / NLR, NY MANIFEST	Lower	1102, 0.209, WSW
AP280	CON EDISON SERVICE B	2118 FULTON ST	RCRA NonGen / NLR, FINDS	Higher	1103, 0.209, East
AP281	CON EDISON	2118 FULTON ST	NY MANIFEST	Higher	1103, 0.209, East
AA282	CON EDISON SERVICE B	203 MCDOUGAL ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1106, 0.209, ENE
AI283	MTA NYCT - RALPH AVE	RALPH AVE & FULTON S	RCRA NonGen / NLR, NY MANIFEST	Lower	1113, 0.211, West
AI284	VERIZON	RALPH AVE & FULTON S	RCRA NonGen / NLR	Lower	1113, 0.211, West
AI285	NYNEX	RALPH AVE & FULTON S	NY MANIFEST	Lower	1113, 0.211, West
AL286	PUBLIC SCHOOL 178-BR	2163 DEAN STREET	NY AST	Higher	1113, 0.211, SSE
AL287	NYC DEPT OF EDUCATIO	2163 DEAN ST	NY LEAD, NY MANIFEST	Higher	1113, 0.211, SSE
AL288	NYC DEPT OF EDUCATIO	2163 DEAN ST	RCRA-LQG	Higher	1113, 0.211, SSE
289	OCEAN HILL-BROWNSVIL	2065 DEAN STREET	NY AST	Higher	1119, 0.212, SSW
AT290	CON EDISON	196 MACDOUGAL ST	NJ MANIFEST	Higher	1122, 0.213, ENE
AT291	CON EDISON	196 MACDOUGAL ST	RCRA NonGen / NLR	Higher	1122, 0.213, ENE
AU292	CON EDISON SERVICE B	349 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1127, 0.213, NNE
AG293	CON EDISON SERVICE B	347 RALPH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1130, 0.214, WSW
AL294	CON EDISON	DEAN ST & SARATOGA A	RCRA NonGen / NLR, FINDS, ECHO	Higher	1136, 0.215, SSE
AL295	CON EDISON	DEAN ST & SARATOGA A	NJ MANIFEST	Higher	1136, 0.215, SSE
AL296	CON EDISON	DEAN ST & SARATOGA A	NY MANIFEST	Higher	1136, 0.215, SSE
AI297	MTA NYCT - RALPH AVE	302 RALPH AVE	RCRA-SQG, NY MANIFEST, NJ MANIFEST	Lower	1143, 0.216, West
AJ298	CON EDISON SERVICE B	106 HOPKINSON AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1146, 0.217, NE
AM299	SHIRLEY CHISHOLM DAY	2023 PACIFIC STREET	NY AST	Higher	1159, 0.220, SW
AN300	CON EDISON - MANHOLE	PACIFIC ST & HOPKINS	NY MANIFEST	Higher	1170, 0.222, SE
AT301	CON EDISON	200 MCDOUGAL ST	NY MANIFEST	Higher	1170, 0.222, ENE
AT302	CON EDISON SERVICE B	209 MCDOUGAL ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1173, 0.222, ENE
AI303	GREAT DEALS DRY CLNG	291 RALPH AVENUE	NY DRYCLEANERS	Lower	1177, 0.223, WNW
AI304	B & G CLEANERS	291 RALPH AVE	RCRA NonGen / NLR, US AIRS, NY MANIFEST	Lower	1177, 0.223, WNW
AI305	CON EDISON	289 RALPH AVE	NY MANIFEST	Lower	1186, 0.225, WNW
AI306	CON EDISON	F/O 289 RALPH AV	NY MANIFEST	Lower	1186, 0.225, WNW
AI307	CON EDISON SERVICE B	289 RALPH AVE	RCRA NonGen / NLR, FINDS	Lower	1186, 0.225, WNW
AN308	ATLANTIC PLAZA TOWER	249 THOMAS S. BOYLAN	NY LTANKS, NY UST	Higher	1190, 0.225, SE
AK309	CON EDISON SERVICE B	402 CHAUNCEY ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1197, 0.227, NNE
AG310	LIRR ATLANTIC AVENUE	S35-S34 ON ATLANTIC	RCRA NonGen / NLR, NY MANIFEST	Lower	1198, 0.227, WSW
AK311	CON EDISON - MANHOLE	CHAUNCEY ST & SARATO	NJ MANIFEST	Lower	1205, 0.228, North
AK312	CON EDISON	CHAUNCEY ST & SARATO	NY MANIFEST	Lower	1205, 0.228, North

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AK313	CON EDISON - MANHOLE	CHAUNCEY ST & SARATO	RCRA-LQG	Lower	1205, 0.228, North
AV314	GP PETRO	1998 ATLANTIC AVENUE	NY LTANKS	Lower	1208, 0.229, WSW
AV315	NORTH ATLANTIC SERVI	1998 ATLANTIC AVENUE	NY UST	Lower	1208, 0.229, WSW
AV316	PETROLEUM COMPLIANCE	1998 ATLANTIC AVE	NY LTANKS	Lower	1208, 0.229, WSW
AT317	CON EDISON SERVICE B	213 MCDOUGAL ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1216, 0.230, ENE
AG318	LIRR ATLANTIC AVENUE	ATLANTIC AVE BETW RA	RCRA NonGen / NLR	Lower	1219, 0.231, WSW
AN319	ATA HOUSING CORP	249 BOYLAND BD	NY LTANKS	Higher	1225, 0.232, SE
AO320	CON EDISON	383 CHAUNCEY ST	NY MANIFEST	Lower	1228, 0.233, NNW
AO321	CON EDISON	383 CHAUNCEY ST	NY MANIFEST	Lower	1228, 0.233, NNW
AO322	CON EDISON SERVICE B	383 CHAUNCEY ST	RCRA NonGen / NLR	Lower	1228, 0.233, NNW
AO323	CON EDISON SERVICE B	383 CHAUNCEY ST	RCRA NonGen / NLR	Lower	1228, 0.233, NNW
AI324	NYCHA - BREVOORT HOU	296 RALPH AVE	RCRA-SQG	Lower	1233, 0.234, WNW
AO325	CON EDISON	375 CHAUNCEY ST	NJ MANIFEST	Lower	1242, 0.235, NNW
AO326	CON EDISON	375 CHAUNCEY ST	RCRA NonGen / NLR	Lower	1242, 0.235, NNW
AO327	CON EDISON	375 CHAUNCEY ST	NY MANIFEST	Lower	1242, 0.235, NNW
AO328	CON EDISON	375 CHAUNCEY ST	NY MANIFEST	Lower	1242, 0.235, NNW
AS329	CON EDISON	215 MARION ST	NJ MANIFEST	Lower	1246, 0.236, NW
AS330	CON EDISON	215 MARION ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1246, 0.236, NW
AS331	CON EDISON	215 MARION ST	NY MANIFEST	Lower	1246, 0.236, NW
AW332	CON EDISON	138 SARATOGA AVE	NJ MANIFEST	Lower	1259, 0.238, North
AW333	CON EDISON	138 SARATOGA AVE	NY MANIFEST	Lower	1259, 0.238, North
AW334	CON EDISON	138 SARATOGA AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1259, 0.238, North
AX335	CON EDISON	12 GUNTHER PL	RCRA NonGen / NLR, FINDS, ECHO	Higher	1272, 0.241, ESE
AX336	CON EDISON	12 GUNTHER PL	NJ MANIFEST	Higher	1272, 0.241, ESE
AX337	CON ED	12 GUNTHER PL	NY MANIFEST	Higher	1272, 0.241, ESE
AV338	CON EDISON	1885 ATLANTIC AVE	RCRA NonGen / NLR	Lower	1273, 0.241, WSW
AV339	CON EDISON	1885 ATLANTIC AVE	NJ MANIFEST	Lower	1273, 0.241, WSW
AV340	1885 ATLANTIC AVENUE	1885 ATLANTIC AVENUE	NY LTANKS, NY BROWNFIELDS, NY Spills	Lower	1273, 0.241, WSW
AV341	SPEEDWAY 7833	1885 ATLANTIC AVE	RCRA-VSQG, NY UST, US AIRS, FINDS, ECHO, NY...	Lower	1273, 0.241, WSW
AU342	CON EDISON - MANHOLE	428 CHAUNCEY ST	NY MANIFEST	Lower	1279, 0.242, NNE
AU343	CON EDISON - MANHOLE	428 CHAUNCEY ST	RCRA-LQG	Lower	1279, 0.242, NNE
AJ344	CON EDISON SERVICE B	392 MARION ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1288, 0.244, NE
AY345	CON EDISON	FRONT OF 297 SUMPTER	NY MANIFEST	Lower	1289, 0.244, NE
AX346	CON EDISON SERVICE B	20 GUNTHER PL	RCRA NonGen / NLR, FINDS	Higher	1292, 0.245, ESE
AY347	CON EDISON	FRONT OF 290 SUMPTER	NY MANIFEST	Lower	1303, 0.247, ENE
AP348	CON EDISON SERVICE B	1261 HERKIMER ST	RCRA NonGen / NLR	Higher	1306, 0.247, East
AP349	CON EDISON	1261 HERKIMER ST	NY MANIFEST	Higher	1306, 0.247, East
AV350	SPILL NUMBER 9907632	1994 ATLANTIC AVE	NY LTANKS	Lower	1340, 0.254, WSW
351	444 BAINBRIDGE ST	444 BAINBRIDGE ST	NY LTANKS	Lower	1362, 0.258, NNW

MAPPED SITES SUMMARY

Target Property Address:
2014 FULTON STREET
BROOKLYN, NY 11233

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AV352	1997 PACIFIC STREET	1997 PACIFIC STREET	NY LTANKS, NY LEAD	Higher	1453, 0.275, WSW
353	1875 ATLANTIC AVENUE	1875 ATLANTIC AVENUE	NY VCP	Lower	1468, 0.278, WSW
354	BROOKLYN CHILDREN CE	1819 BERGEN STREET	NY LTANKS	Higher	1524, 0.289, SSW
355	417 RALPH AVENUE	417 RALPH AVENUE	NY LTANKS	Higher	1657, 0.314, SW
356	615 DECATUR ST	615 DECATUR ST	NY LTANKS	Lower	1754, 0.332, North
357	COMMERCIAL LOT	1855 ATLANTIC AVE	NY LTANKS	Lower	1776, 0.336, WSW
358	598 BAINBRIDGE ST	598 BAINBRIDGE ST	NY LTANKS	Lower	1833, 0.347, NE
359	BACKYARD OF HOUSE	632 MACDONOWGH STREE	NY LTANKS	Lower	1840, 0.348, NNW
360	1819 PROSPECT PLACE	1819 PROSPECT PL	NY LTANKS	Higher	2019, 0.382, South
AZ361	ENGINE CO. 233/LADD.	25 ROCKAWAY AVENUE	NY LTANKS, NY Spills	Lower	2043, 0.387, NE
362	1634 SAINT MARKS PLA	1634 SAINT MARKS PLA	NY LTANKS, NY Spills	Lower	2116, 0.401, SE
363	PROSPECT PLAZA -NYCH	1776 PROSPECT PLACE	NY LTANKS, NY AST	Higher	2122, 0.402, South
BA364	BREVOORT HOUSES	329 PATCHEN AVE	NY LTANKS, NY Spills	Lower	2124, 0.402, West
BA365	329 PATCHEN AVE/BKLY	329 PATCHEN AVE	NY LTANKS	Lower	2176, 0.412, WNW
366	KINGSBOROUGH HOUSES	1880 PACIFIC STREET	NY LTANKS	Lower	2179, 0.413, WSW
AZ367	HENRY APARTMENTS SIT	8 ROCKAWAY AVENUE	NY VCP	Lower	2193, 0.415, NE
BB368	192 RALPH AVE OFF-SI	192 RALPH AVE	NY DEL SHWS	Lower	2199, 0.416, NW
BB369	192 RALPH AVENUE	192 RALPH AVE	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY VCP	Lower	2199, 0.416, NW
370	AKA 31-33 MONACO PLA	2121 MONACO PLACE	NY LTANKS	Higher	2200, 0.417, ESE
371	RESIDENCE	842 MACON ST	NY LTANKS	Lower	2227, 0.422, North
372	HENRY APARTMENTS - S	1676 BROADWAY	NY VCP	Lower	2260, 0.428, NNE
373	TORES HOME	211 HULL STREET	NY LTANKS, NY Spills	Higher	2341, 0.443, ENE
374	OCEAN HILL -NYCHA	24 STONE AVENUE	NY LTANKS, NY Spills	Higher	2346, 0.444, ENE
375	1625 PROSPECT PLACE	1625 PROSPECT PL	NY VCP	Higher	2379, 0.451, SW
376	NYCHA TRIBOROUGH PRE	930 HALSEY STREET (A	NY LTANKS, NY UST, NY Spills	Lower	2479, 0.470, North
377	GAS STATION	1850 PARK PLACE	NY LTANKS	Lower	2480, 0.470, South
378	MILLER HOME	154 BUFFALO AVE	NY LTANKS, NY Spills	Higher	2520, 0.477, SW
379	1860 EASTERN PARKWAY	1860 EASTERN PARKWAY	NY VCP	Lower	2542, 0.481, ESE
380	DCA 1 APARTMENTS	495 HOWARD AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Higher	2583, 0.489, SSW
381	PROSPECT PLAZA -NYCH	430 SARATOGA AVE	NY LTANKS, NY Spills	Lower	2588, 0.490, South

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
LOT 19,TAXBLOCK 1549 2014 FULTON STREET BROOKLYN, NY 11233	NY E DESIGNATION	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System

US ENG CONTROLS ..... Engineering Controls Sites List
US INST CONTROLS ..... Institutional Controls Sites List

Federal ERNS list

ERNS ..... Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ..... Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ..... Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ..... Underground Storage Tank Listing
NY CBS UST ..... Chemical Bulk Storage Database
NY MOSF UST ..... Major Oil Storage Facilities Database
NY CBS ..... Chemical Bulk Storage Site Listing
NY MOSF ..... Major Oil Storage Facility Site Listing
NY CBS AST ..... Chemical Bulk Storage Database
NY MOSF AST ..... Major Oil Storage Facilities Database
INDIAN UST ..... Underground Storage Tanks on Indian Land
NY TANKS ..... Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ..... Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ..... Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ..... Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ..... Registered Waste Tire Storage & Facility List
NY SWRCY ..... Registered Recycling Facility List
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
ODI ..... Open Dump Inventory
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register

US CDL ..... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ..... Historical Petroleum Bulk Storage Database
NY HIST AST ..... Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ..... Spill Liens Information
LIENS 2 ..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ..... Hazardous Materials Information Reporting System
NY Hist Spills ..... SPILLS Database
NY SPILLS 90 ..... SPILLS 90 data from FirstSearch
NY SPILLS 80 ..... SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ..... Formerly Used Defense Sites
DOD ..... Department of Defense Sites
SCRD DRYCLEANERS ..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ..... Financial Assurance Information
EPA WATCH LIST ..... EPA WATCH LIST
2020 COR ACTION ..... 2020 Corrective Action Program List
TSCA ..... Toxic Substances Control Act
TRIS ..... Toxic Chemical Release Inventory System
SSTS ..... Section 7 Tracking Systems
ROD ..... Records Of Decision
RMP ..... Risk Management Plans
RAATS ..... RCRA Administrative Action Tracking System
PRP ..... Potentially Responsible Parties
PADS ..... PCB Activity Database System
FTTS ..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ..... Material Licensing Tracking System
COAL ASH DOE ..... Steam-Electric Plant Operation Data
COAL ASH EPA ..... Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ..... PCB Transformer Registration Database
RADINFO ..... Radiation Information Database
HIST FTTS ..... FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ..... Incident and Accident Data
CONSENT ..... Superfund (CERCLA) Consent Decrees
INDIAN RESERV ..... Indian Reservations
FUSRAP ..... Formerly Utilized Sites Remedial Action Program
UMTRA ..... Uranium Mill Tailings Sites
LEAD SMELTERS ..... Lead Smelter Sites
US MINES ..... Mines Master Index File
ABANDONED MINES ..... Abandoned Mines
UXO ..... Unexploded Ordnance Sites
DOCKET HWC ..... Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ..... EPA Fuels Program Registered Listing
PFAS NPL ..... Superfund Sites with PFAS Detections Information

EXECUTIVE SUMMARY

PFAS FEDERAL SITES Federal Sites PFAS Information
PFAS TSCA PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR PFAS Contamination Site Location Listing
PFAS WQP Ambient Environmental Sampling for PFAS
PFAS NPDES Clean Water Act Discharge Monitoring Information
PFAS ECHO Facilities in Industries that May Be Handling PFAS Listing
PFAS ECHO FIRE TRAINING Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC Aqueous Foam Related Incidents Listing
NY PFAS PFAS Contamination Site Location Listing
NY AIRS Air Emissions Data
NY COAL ASH Coal Ash Disposal Site Listing
NY Financial Assurance Financial Assurance Information Listing
NY HSWDS Hazardous Substance Waste Disposal Site Inventory
NY SPDES State Pollutant Discharge Elimination System
NY VAPOR REOPENED Vapor Intrusion Legacy Site List
NY UIC Underground Injection Control Wells
NY COOLING TOWERS Registered Cooling Towers
MINES MRDS Mineral Resources Data System
BIOSOLIDS ICIS-NPDES Biosolids Facility Data
PFAS TRIS List of PFAS Added to the TRI

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants
EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 6 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP005150511	1036 HERKIMER ST	WSW 0 - 1/8 (0.071 mi.)	D68	98
CON EDISON - MANHOLE EPA ID:: NYP005150495	2034 ATLANTIC AVE	SW 1/8 - 1/4 (0.186 mi.)	V236	430
NYC DEPT OF EDUCATIO EPA ID:: NYR000213983	2163 DEAN ST	SSE 1/8 - 1/4 (0.211 mi.)	AL288	575

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004185351	***THOMAS S BOYLAND ST***	***NE 1/8 - 1/4 (0.195 mi.)***	***AJ256***	***473***
CON EDISON - MANHOLE EPA ID:: NYP004734406	CHAUNCEY ST & SARATO	N 1/8 - 1/4 (0.228 mi.)	AK313	637
CON EDISON - MANHOLE EPA ID:: NYP005050356	428 CHAUNCEY ST	NNE 1/8 - 1/4 (0.242 mi.)	AU343	715

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 6 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - SARATOGA EPA ID:: NYR000196386	***FULTON ST & SARATOGA***	***E 0 - 1/8 (0.007 mi.)***	***B18***	***15***
I.S. 271 JOHN M. COL EPA ID:: NYR000056812	***1137 HERKIMER ST***	***ESE 0 - 1/8 (0.044 mi.)***	***E49***	***63***
MTA LIRR - ATLANTIC EPA ID:: NYR000160986	***2010 ATLANTIC AVE***	***SW 1/8 - 1/4 (0.202 mi.)***	***V261***	***497***

Lower Elevation	Address	Direction / Distance	Map ID	Page
P.S. 28 THE WARREN	***1001 HERKIMER ST***	***W 1/8 - 1/4 (0.138 mi.)***	***N161***	***274***

EPA ID:: NYR000012039				
MTA NYCT - RALPH AVE	***302 RALPH AVE***	***W 1/8 - 1/4 (0.216 mi.)***	***AI297***	***596***
EPA ID:: NYR000156133				
NYCHA - BREVOORT HOU	296 RALPH AVE	WNW 1/8 - 1/4 (0.234 mi.)	AI324	663
EPA ID:: NYR000238931				

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 07/24/2023 has revealed that there are 3 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FAMILY DOLLAR STORE	2010 ATLANTIC AVE SU	SW 1/8 - 1/4 (0.202 mi.)	V262	517
EPA ID:: NYR000215681				

Lower Elevation	Address	Direction / Distance	Map ID	Page
RITE AID #04893	***1950 FULTON ST***	***W 1/8 - 1/4 (0.202 mi.)***	***AI259***	***485***
EPA ID:: NYR000186445				
SPEEDWAY 7833	***1885 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AV341***	***699***
EPA ID:: NYD982185530				

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/05/2023 has revealed that there is 1 NY SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
192 RALPH AVENUE	***192 RALPH AVE***	***NW 1/4 - 1/2 (0.416 mi.)***	***BB369***	***772***
Site Code: 58281				
Class Code: Site is properly closed - requires continued management.				

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 03/31/2023 has revealed that there is 1 NY SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AFRO CARTING CO.	286 SARATOGA AVE	SSE 1/8 - 1/4 (0.176 mi.)	U224	401

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/05/2023 has revealed that there are 33 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
1064 HERKIMER STREET Spill Number/Closed Date: 8910306 / 2003-07-29 Site ID: 221931 Spill Date: 1990-01-26	1064 HERKIMER STREET	SSW 0 - 1/8 (0.035 mi.)	A44	57
Not reported Spill Number/Closed Date: 1811489 / 2021-02-12 Site ID: 582432 Spill Date: 2019-02-15	***1088 HERKIMER STREET***	***S 0 - 1/8 (0.040 mi.)***	***C46***	***58***
ATLANTIC PLAZA TOWER Spill Number/Closed Date: 0506302 / 2005-11-28 Site ID: 351493 Spill Date: 2005-08-22	***249 THOMAS S. BOYLAN***	***SE 1/8 - 1/4 (0.225 mi.)***	***AN308***	***623***
ATA HOUSING CORP Spill Number/Closed Date: 0506553 / 2005-08-29 Site ID: 351786 Spill Date: 2005-08-27	249 BOYLAND BD	SE 1/8 - 1/4 (0.232 mi.)	AN319	654
1997 PACIFIC STREET Spill Number/Closed Date: 9309613 / 1993-11-09 Site ID: 214838 Spill Date: 1993-11-09	***1997 PACIFIC STREET***	***WSW 1/4 - 1/2 (0.275 mi.)***	***AV352***	***733***
BROOKLYN CHILDREN CE Spill Number/Closed Date: 0106070 / 2003-07-21 Spill Number/Closed Date: 0411485 / 2005-12-07 Site ID: 315011 Site ID: 336696 Spill Date: 2001-09-07 Spill Date: 2005-01-25	1819 BERGEN STREET	SSW 1/4 - 1/2 (0.289 mi.)	354	735
417 RALPH AVENUE	417 RALPH AVENUE	SW 1/4 - 1/2 (0.314 mi.)	355	737

Spill Number/Closed Date: 9314183 / 2003-02-12
Site ID: 231437
Spill Date: 1994-03-04

1819 PROSPECT PLACE — 1819 PROSPECT PL — S 1/4 - 1/2 (0.382 mi.) — 360 — 743
Spill Number/Closed Date: 8910858 / 1995-06-20
Site ID: 307716
Spill Date: 1990-02-14

PROSPECT PLAZA -NYCH — ***1776 PROSPECT PLACE*** — ***S 1/4 - 1/2 (0.402 mi.)*** — ***363*** — ***751***
Spill Number/Closed Date: 9107711 / 2006-01-06
Spill Number/Closed Date: 9315474 / 2006-12-08
Spill Number/Closed Date: 0605275 / 2006-09-28
Site ID: 248079
Site ID: 151127
Site ID: 368407
Spill Date: 1991-10-18
Spill Date: 1993-10-27
Spill Date: 2006-08-06

AKA 31-33 MONACO PLA — 2121 MONACO PLACE — ESE 1/4 - 1/2 (0.417 mi.) — 370 — 820
Spill Number/Closed Date: 0408751 / Not Reported
Site ID: 333492
Spill Date: 2004-11-08

TORES HOME — ***211 HULL STREET*** — ***ENE 1/4 - 1/2 (0.443 mi.)*** — ***373*** — ***827***
Spill Number/Closed Date: 0612788 / 2007-09-17
Site ID: 377715
Spill Date: 2007-02-26

OCEAN HILL -NYCHA — ***24 STONE AVENUE*** — ***ENE 1/4 - 1/2 (0.444 mi.)*** — ***374*** — ***833***
Spill Number/Closed Date: 9010234 / 2019-01-14
Site ID: 171459
Spill Date: 1990-12-20

MILLER HOME — ***154 BUFFALO AVE*** — ***SW 1/4 - 1/2 (0.477 mi.)*** — ***378*** — ***846***
Spill Number/Closed Date: 0501857 / 2005-09-28
Site ID: 346085
Spill Date: 2005-05-16

Lower Elevation	Address	Direction / Distance	Map ID	Page
2006 A FULTON STREET Spill Number/Closed Date: 0600324 / 2006-05-17 Site ID: 362303 Spill Date: 2006-04-10	2006 A FULTON STREET	W 0 - 1/8 (0.014 mi.)	A26	33
GRANT RESIDENCE Spill Number/Closed Date: 9912025 / 2000-01-26 Site ID: 237080 Spill Date: 2000-01-18	335 MARION ST	NNE 1/8 - 1/4 (0.204 mi.)	AK267	530
GP PETRO Spill Number/Closed Date: 9712517 / 2006-05-17 Site ID: 129283 Spill Date: 1998-02-09	1998 ATLANTIC AVENUE	WSW 1/8 - 1/4 (0.229 mi.)	AV314	640
PETROLEUM COMPLIANCE Spill Number/Closed Date: 1804629 / 2018-08-30 Site ID: 574315 Spill Date: 2018-07-30	1998 ATLANTIC AVE	WSW 1/8 - 1/4 (0.229 mi.)	AV316	645
1885 ATLANTIC AVENUE	***1885 ATLANTIC AVENUE***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AV340***	***689***

Spill Number/Closed Date: 9209626 / 1994-07-22
Site ID: 132469
Spill Date: 1992-11-18

SPILL NUMBER 9907632 | 1994 ATLANTIC AVE | WSW 1/4 - 1/2 (0.254 mi.) | AV350 | 730
Spill Number/Closed Date: 9907632 / 2004-01-09
Site ID: 314056
Spill Date: 1999-09-24

444 BAINBRIDGE ST | 444 BAINBRIDGE ST | NNW 1/4 - 1/2 (0.258 mi.) | 351 | 732
Spill Number/Closed Date: 9106421 / 1991-09-07
Site ID: 265729
Spill Date: 1991-09-14

615 DECATUR ST | 615 DECATUR ST | N 1/4 - 1/2 (0.332 mi.) | 356 | 738
Spill Number/Closed Date: 0006043 / 2005-11-22
Site ID: 180048
Spill Date: 2000-08-21

COMMERCIAL LOT | 1855 ATLANTIC AVE | WSW 1/4 - 1/2 (0.336 mi.) | 357 | 739
Spill Number/Closed Date: 0401074 / 2004-05-24
Site ID: 328893
Spill Date: 2004-04-30

598 BAINBRIDGE ST | 598 BAINBRIDGE ST | NE 1/4 - 1/2 (0.347 mi.) | 358 | 740
Spill Number/Closed Date: 9512828 / 1996-01-16
Site ID: 150243
Spill Date: 1996-01-15

BACKYARD OF HOUSE | 632 MACDONOWGH STREE | NNW 1/4 - 1/2 (0.348 mi.) | 359 | 742
Spill Number/Closed Date: 0604106 / 2006-07-13
Site ID: 367002
Spill Date: 2006-07-13

ENGINE CO. 233/LADD. | ***25 ROCKAWAY AVENUE*** | ***NE 1/4 - 1/2 (0.387 mi.)*** | ***AZ361*** | ***744***
Spill Number/Closed Date: 9709795 / 1999-04-01
Spill Number/Closed Date: 0102559 / 2009-10-07
Site ID: 89083
Site ID: 313650
Spill Date: 1997-11-15
Spill Date: 2001-06-07

1634 SAINT MARKS PLA | ***1634 SAINT MARKS PLA*** | ***SE 1/4 - 1/2 (0.401 mi.)*** | ***362*** | ***749***
Spill Number/Closed Date: 0104652 / 2008-09-23
Site ID: 144327
Spill Date: 2001-07-31

BREVOORT HOUSES | ***329 PATCHEN AVE*** | ***W 1/4 - 1/2 (0.402 mi.)*** | ***BA364*** | ***759***
Spill Number/Closed Date: 9808684 / 2007-11-19
Site ID: 314864
Spill Date: 1998-10-13

329 PATCHEN AVE/BKLY | 329 PATCHEN AVE | WNW 1/4 - 1/2 (0.412 mi.) | BA365 | 765
Spill Number/Closed Date: 8710502 / 1988-03-16
Site ID: 176361
Spill Date: 1988-03-15

KINGSBOROUGH HOUSES | 1880 PACIFIC STREET | WSW 1/4 - 1/2 (0.413 mi.) | 366 | 766
Spill Number/Closed Date: 9410866 / 2009-07-07
Spill Number/Closed Date: 9010149 / 1995-04-26
Site ID: 290629
Site ID: 276215

Spill Date: 1994-11-14
Spill Date: 1990-12-18

RESIDENCE — 842 MACON ST — N 1/4 - 1/2 (0.422 mi.) — 371 — 826
Spill Number/Closed Date: 0500513 / 2005-04-13
Site ID: 343503
Spill Date: 2005-04-12

NYCHA TRIBOROUGH PRE — 930 HALSEY STREET (A — N 1/4 - 1/2 (0.470 mi.) — 376 — 839
Spill Number/Closed Date: 9801627 / 2002-08-16
Site ID: 181894
Spill Date: 1998-05-08

GAS STATION — 1850 PARK PLACE — S 1/4 - 1/2 (0.470 mi.) — 377 — 845
Spill Number/Closed Date: 0507177 / 2006-02-14
Site ID: 352527
Spill Date: 2005-09-07

PROSPECT PLAZA -NYCH — 430 SARATOGA AVE — S 1/4 - 1/2 (0.490 mi.) — 381 — 866
Spill Number/Closed Date: 9010192 / 2005-12-14
Site ID: 253502
Spill Date: 1990-12-19

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 7 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CLOSED S/S	***2130 ATLANTIC AVENUE***	***SSE 1/8 - 1/4 (0.125 mi.)***	***K143***	***231***
Database: UST, Date of Government Version: 02/14/2023				
TOWER ISLES FROZEN F	2025 ATLANTIC AVE	ESE 1/8 - 1/4 (0.155 mi.)	W177	311
Database: UST, Date of Government Version: 02/14/2023				
15 SOMERS STREET	15 SOMERS STREET	E 1/8 - 1/4 (0.186 mi.)	S239	435
Database: UST, Date of Government Version: 02/14/2023				
ATLANTIC PLAZA TOWER	***249 THOMAS S. BOYLAN***	***SE 1/8 - 1/4 (0.225 mi.)***	***AN308***	***623***
Database: UST, Date of Government Version: 02/14/2023				

Lower Elevation	Address	Direction / Distance	Map ID	Page
2006A FULTON STREET	2006A FULTON STREET	WNW 0 - 1/8 (0.018 mi.)	A27	34
Database: UST, Date of Government Version: 02/14/2023				
NORTH ATLANTIC SERVI	1998 ATLANTIC AVENUE	WSW 1/8 - 1/4 (0.229 mi.)	AV315	641
Database: UST, Date of Government Version: 02/14/2023				
SPEEDWAY 7833	***1885 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AV341***	***699***
Database: UST, Date of Government Version: 02/14/2023				

EXECUTIVE SUMMARY

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 18 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
I.S. 271 - BROOKLYN Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-354384	1137 HERKIMER STREET	ESE 0 - 1/8 (0.044 mi.)	E50	69
CLOSED S/S Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-608672	***2130 ATLANTIC AVENUE***	***SSE 1/8 - 1/4 (0.125 mi.)***	***K143***	***231***
SHARIFA MANAGEMENT C Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-258792	2125 PACIFIC STREET	SSE 1/8 - 1/4 (0.150 mi.)	U166	287
TRI STATE TRUCK & TR Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-612675	1927 ATLANTIC AVENUE	SW 1/8 - 1/4 (0.151 mi.)	V167	289
2170 ATLANTIC AVE Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609714	2170 ATLANTIC AVENUE	SE 1/8 - 1/4 (0.160 mi.)	W202	360
343 HOWARD AVENUE Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-479691	343 HOWARD AVENUE	SSW 1/8 - 1/4 (0.193 mi.)	AF255	471
DEAN STREET TRANSITO Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-601687	2155 DEAN STREET	SSE 1/8 - 1/4 (0.202 mi.)	AL264	523
351 HOWARD AVE Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-608446	351 HOWARD AVENUE	SSW 1/8 - 1/4 (0.203 mi.)	AF265	525
2027 PACIFIC STREET Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609971	2027 PACIFIC STREET	SW 1/8 - 1/4 (0.203 mi.)	AM266	528
2185 PACIFIC STREET Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609501	2185 PACIFIC STREET	SE 1/8 - 1/4 (0.205 mi.)	AN268	531
PUBLIC SCHOOL 178-BR Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-606299	2163 DEAN STREET	SSE 1/8 - 1/4 (0.211 mi.)	AL286	569
OCEAN HILL-BROWNSVIL Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-612300	2065 DEAN STREET	SSW 1/8 - 1/4 (0.212 mi.)	289	579
SHIRLEY CHISHOLM DAY Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-606194	2023 PACIFIC STREET	SW 1/8 - 1/4 (0.220 mi.)	AM299	605

Lower Elevation	Address	Direction / Distance	Map ID	Page
PLEASANT GROVE BAPTI Database: AST, Date of Government Version: 02/14/2023	1927 FULTON STREET	WNW 0 - 1/8 (0.066 mi.)	H65	94

Facility Id: 2-611986

US POSTAL SERVICE - 1915 FULTON STREET WNW 0 - 1/8 (0.124 mi.) N142 229
Database: AST, Date of Government Version: 02/14/2023
Facility Id: 2-453145

P.S. 28 - BROOKLYN (1001 HERKIMER STREET W 1/8 - 1/4 (0.138 mi.) N162 279
Database: AST, Date of Government Version: 02/14/2023
Facility Id: 2-604477

138 HOPKINSON ASSOCI 138 HOPKINSON AVENUE ENE 1/8 - 1/4 (0.162 mi.) AA206 367
Database: AST, Date of Government Version: 02/14/2023
Facility Id: 2-608581

ACCUTECH FOREIN CAR 22 PRESCOTT PLACE WSW 1/8 - 1/4 (0.186 mi.) AG238 433
Database: AST, Date of Government Version: 02/14/2023
Facility Id: 2-609603

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 05/05/2023 has revealed that there are 2 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DCA 1 APARTMENTS Site Code: 466073	***495 HOWARD AVENUE***	***SSW 1/4 - 1/2 (0.489 mi.)***	***380***	***849***

Lower Elevation	Address	Direction / Distance	Map ID	Page
192 RALPH AVENUE Site Code: 58281	***192 RALPH AVE***	***NW 1/4 - 1/2 (0.416 mi.)***	***BB369***	***772***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 05/05/2023 has revealed that there are 2 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DCA 1 APARTMENTS Site Code: 466073	***495 HOWARD AVENUE***	***SSW 1/4 - 1/2 (0.489 mi.)***	***380***	***849***

Lower Elevation	Address	Direction / Distance	Map ID	Page
192 RALPH AVENUE Site Code: 58281	***192 RALPH AVE***	***NW 1/4 - 1/2 (0.416 mi.)***	***BB369***	***772***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 9 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
1625 PROSPECT PLACE Database: VCP NYC, Date of Government Version: 06/04/2023	1625 PROSPECT PL	SW 1/4 - 1/2 (0.451 mi.)	375	838

Lower Elevation	Address	Direction / Distance	Map ID	Page
53 MACDOUGAL STREET Database: VCP NYC, Date of Government Version: 06/04/2023	53 MACDOUGAL ST	WNW 1/8 - 1/4 (0.139 mi.)	Q163	282
20 PRESCOTT PLACE Database: VCP NYC, Date of Government Version: 06/04/2023	20 PRESCOTT PLACE	WSW 1/8 - 1/4 (0.189 mi.)	AG247	451
335 RALPH AVENUE Database: VCP NYC, Date of Government Version: 06/04/2023	335 RALPH AVENUE	WSW 1/8 - 1/4 (0.206 mi.)	AG271	538
1875 ATLANTIC AVENUE Database: VCP NYC, Date of Government Version: 06/04/2023	1875 ATLANTIC AVENUE	WSW 1/4 - 1/2 (0.278 mi.)	353	734
HENRY APARTMENTS SIT Database: VCP NYC, Date of Government Version: 06/04/2023	8 ROCKAWAY AVENUE	NE 1/4 - 1/2 (0.415 mi.)	AZ367	769
192 RALPH AVENUE Database: VCP, Date of Government Version: 05/05/2023 Site Code: 58001	***192 RALPH AVE***	***NW 1/4 - 1/2 (0.416 mi.)***	***BB369***	***772***
HENRY APARTMENTS - S Database: VCP NYC, Date of Government Version: 06/04/2023	1676 BROADWAY	NNE 1/4 - 1/2 (0.428 mi.)	372	827
1860 EASTERN PARKWAY Database: VCP NYC, Date of Government Version: 06/04/2023	1860 EASTERN PARKWAY	ESE 1/4 - 1/2 (0.481 mi.)	379	848

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 05/05/2023 has revealed that there are 3 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DCA 1 APARTMENTS Site Code: 466073	***495 HOWARD AVENUE***	***SSW 1/4 - 1/2 (0.489 mi.)***	***380***	***849***

Lower Elevation	Address	Direction / Distance	Map ID	Page
1921 ATLANTIC AVENUE Site Code: 571794	***1911 ATLANTIC AVENUE***	***WSW 1/8 - 1/4 (0.177 mi.)***	***V229***	***411***
1885 ATLANTIC AVENUE	***1885 ATLANTIC AVENUE***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AV340***	***689***

EXECUTIVE SUMMARY

Site Code: 628592

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the NY DEL SHWS list, as provided by EDR, and dated 05/05/2023 has revealed that there is 1 NY DEL SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
192 RALPH AVE OFF-SI	192 RALPH AVE	NW 1/4 - 1/2 (0.416 mi.)	BB368	769

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/05/2023 has revealed that there are 22 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PRIVATE RESIDENCE Spill Number/Closed Date: 9700115 / 2003-04-17 Site ID: 248100 Spill Date: 1997-04-02	1095 HERKIMER ST	SE 0 - 1/8 (0.009 mi.)	A20	22
1093 HERKIMER ST. Spill Number/Closed Date: 9311226 / 2001-09-17 Site ID: 59490 Spill Date: 1993-12-18	1093 HERKIMER ST	SE 0 - 1/8 (0.009 mi.)	A21	23
MULTI FAMILY Spill Number/Closed Date: 0913454 / 2011-12-09 Site ID: 426398 Spill Date: 2010-03-21	1115 HERKIMER ST	ESE 0 - 1/8 (0.013 mi.)	B25	31
VAULT # 3800 Spill Number/Closed Date: 0506914 / 2005-10-26 Site ID: 352214 Spill Date: 2005-09-06	HERKIMER ST NEAR SAR	ESE 0 - 1/8 (0.025 mi.)	B34	42
VAULT VS 3704 Spill Number/Closed Date: 0410920 / 2005-06-03 Site ID: 336005 Spill Date: 2005-01-06	SARTOGA AVE AND HERK	ESE 0 - 1/8 (0.026 mi.)	B36	45
VAULT 3295	HERKIMER ST/SARATOGA	ESE 0 - 1/8 (0.026 mi.)	B37	47

Spill Number/Closed Date: 0207788 / 2003-02-10
Site ID: 226839
Spill Date: 2002-10-28

SPILL NUMBER 9905790 — 11 LOUIS PLACE — SSE 0 - 1/8 (0.052 mi.) — C54 — 77
Spill Number/Closed Date: 9905790 / 1999-08-13
Site ID: 82967
Spill Date: 1999-08-13

SPILL NUMBER 0200021 — 248 SARATOGA AVE — SE 0 - 1/8 (0.059 mi.) — C63 — 92
Spill Number/Closed Date: 0200021 / 2002-05-06
Site ID: 77213
Spill Date: 2002-04-01

MANHOLE 66326 — 1042 HERKIMER ST — WSW 0 - 1/8 (0.068 mi.) — D66 — 96
Spill Number/Closed Date: 9914670 / 2002-03-27
Site ID: 327614
Spill Date: 2000-03-28

315 HOWARD AVE — 315 HOWARD AVE — SW 0 - 1/8 (0.107 mi.) — M110 — 173
Spill Number/Closed Date: 9607315 / 1996-09-10
Site ID: 127201
Spill Date: 1996-09-09

COMMERICAL — 2120 ATLANTIC AVE — SSE 0 - 1/8 (0.115 mi.) — K122 — 190
Spill Number/Closed Date: 2009595 / 2021-03-02
Site ID: 616600
Spill Date: 2021-02-24

Lower Elevation	Address	Direction / Distance	Map ID	Page

MANHOLE 14355 — HULL ST / SARATOGA A — ENE 0 - 1/8 (0.028 mi.) — B38 — 48
Spill Number/Closed Date: 0010761 / 2001-04-19
Site ID: 233586
Spill Date: 2000-12-28

LENNY GOODWIN RESIDE — 17 HULL ST — N 0 - 1/8 (0.030 mi.) — A39 — 49
Spill Number/Closed Date: 1110327 / 2012-06-18
Site ID: 458140
Spill Date: 2011-11-20

H.P.D. HOUSING — 21 HULL ST — NNE 0 - 1/8 (0.031 mi.) — A40 — 50
Spill Number/Closed Date: 9611846 / 1996-12-31
Site ID: 134622
Spill Date: 1996-12-31

BACK YARD — 1049 HERKIMER ST — WSW 0 - 1/8 (0.044 mi.) — D48 — 62
Spill Number/Closed Date: 1902540 / 2019-06-18
Site ID: 590467
Spill Date: 2019-06-11

MACDOUGAL ST/SARATOG — MACDOUGAL ST/SARATOG — NNE 0 - 1/8 (0.077 mi.) — G74 — 109
Spill Number/Closed Date: 9003612 / 1990-09-13
Site ID: 330568
Spill Date: 1990-06-28

NEXT TO 85 MACDOUGAL — BY HOWARD AVE & MACD — NW 0 - 1/8 (0.088 mi.) — I82 — 123
Spill Number/Closed Date: 9708059 / 1997-11-14
Site ID: 326413
Spill Date: 1997-10-02

VACANT LOT NEXT TO H — 83 MACDOUGAL ST — NW 0 - 1/8 (0.089 mi.) — H84 — 126

Spill Number/Closed Date: 9515842 / 2005-07-15 Site ID: 230070 Spill Date: 1996-03-11				
77 MACDOUGAL ST Spill Number/Closed Date: 9707862 / 2008-09-30 Site ID: 139045 Spill Date: 1997-10-03	77 MACDOUGAL ST	NW 0 - 1/8 (0.094 mi.)	H86	128
NEW CONSTRUCTION Spill Number/Closed Date: 9712516 / 1998-02-09 Site ID: 214012 Spill Date: 1998-02-09	150 SUMPTER ST	NNW 0 - 1/8 (0.112 mi.)	I120	188
233 HOWARD AVENUE Spill Number/Closed Date: 0105366 / 2001-09-28 Spill Number/Closed Date: 9401030 / 1994-04-22 Site ID: 154485 Site ID: 239554 Spill Date: 2001-08-17 Spill Date: 1994-04-21	233 HOWARD AVENUE	NW 0 - 1/8 (0.115 mi.)	I131	206
AUSTIN RES Spill Number/Closed Date: 9515677 / 2003-04-15 Site ID: 92440 Spill Date: 1996-03-06	201 SUMTER ST	N 0 - 1/8 (0.120 mi.)	O140	223

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 07/24/2023 has revealed that there are 110 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID:: NYP004491106	1091 HERKIMER ST	SE 0 - 1/8 (0.009 mi.)	A23	26
CON EDISON SERVICE B EPA ID:: NYP004459616	***1103 HERKIMER ST***	***SE 0 - 1/8 (0.013 mi.)***	***A24***	***28***
CON EDISON EPA ID:: NYP004746053	***1063 HERKIMER ST***	***WSW 0 - 1/8 (0.023 mi.)***	***A32***	***39***
CON EDISON EPA ID:: NYP004746061	***HERKIMER ST & DEWEY***	***SW 0 - 1/8 (0.034 mi.)***	***A41***	***51***
CON EDISON SERVICE B EPA ID:: NYP004458386	***1132 HERKIMER ST***	***ESE 0 - 1/8 (0.048 mi.)***	***E52***	***73***
CON EDISON EPA ID:: NYP004847232	21 LOUIS PL	SSE 0 - 1/8 (0.077 mi.)	C70	102
CON EDISON	1967 ATLANTIC AVE	S 0 - 1/8 (0.088 mi.)	J83	124

EPA ID:: NYP004847224				
CON EDISON EPA ID:: NYP004842247	52 HULL ST	ENE 0 - 1/8 (0.096 mi.)	L89	132
CON EDISON SERVICE B EPA ID:: NYP004483426	***2001 ATLANTIC AVE***	***SE 0 - 1/8 (0.099 mi.)***	***K92***	***136***
CON EDISON SERVICE B EPA ID:: NYP004483418	2001 ATLANTIC AVE FR	SE 0 - 1/8 (0.099 mi.)	K93	139
ROMANELLI ANTHONY EPA ID:: NYD982532640	***1943 ATLANTIC AVE***	***SSW 0 - 1/8 (0.101 mi.)***	***J95***	***142***
CON EDISON EPA ID:: NYP004472155	***1943 ATLANTIC AVE***	***SSW 0 - 1/8 (0.101 mi.)***	***J97***	***148***
CON EDISON SERVICE B EPA ID:: NYP004458402	***298 HOWARD AVE***	***SW 0 - 1/8 (0.101 mi.)***	***M98***	***151***
CON EDISON EPA ID:: NYP004845877	***ATLANTIC AVE & LOUIS***	***S 0 - 1/8 (0.101 mi.)***	***J99***	***155***
CON EDISON EPA ID:: NYP004845893	ATLANTIC AVE & DEWEY	SSW 0 - 1/8 (0.103 mi.)	J106	165
CON EDISON EPA ID:: NYP004837993	77 HULL ST	ENE 0 - 1/8 (0.109 mi.)	L114	177
PARK AVE BLDG & ROOF EPA ID:: NYR000252783	2120 ATLANTIC AVE	SSE 0 - 1/8 (0.115 mi.)	K123	191
CON EDISON SERVICE B EPA ID:: NYP004487922	***2112 ATLANTIC AVE FR***	***S 0 - 1/8 (0.115 mi.)***	***J125***	***195***
CON EDISON SERVICE B EPA ID:: NYP004487955	***2100 ATLANTIC AVE FR***	***S 0 - 1/8 (0.115 mi.)***	***J126***	***198***
CON EDISON MANHOLE: EPA ID:: NYP004487914	***2090 ATLANTIC AVE FR***	***SSW 0 - 1/8 (0.117 mi.)***	***J136***	***215***
CON EDISON SERVICE B EPA ID:: NYP004487948	***2074 ATLANTIC AVE FR***	***S 1/8 - 1/4 (0.127 mi.)***	***J148***	***248***
CON EDISON EPA ID:: NYP004838035	***87 HULL ST***	***ENE 1/8 - 1/4 (0.134 mi.)***	***L158***	***268***
CON EDISON SERVICE B EPA ID:: NYP004426847	***170 HOPKINSON AVE***	***E 1/8 - 1/4 (0.145 mi.)***	***S164***	***282***
CON EDISON MANHOLE 6 EPA ID:: NYP004148367	***HERKIMER ST & HOPKIN***	***ESE 1/8 - 1/4 (0.152 mi.)***	***S169***	***295***
CON EDISON SERVICE B EPA ID:: NYP004577516	***171 HOPKINSON***	***E 1/8 - 1/4 (0.153 mi.)***	***S171***	***300***
CON EDISON EPA ID:: NYP004194452	***ATLANTIC AVE & BANCR***	***SW 1/8 - 1/4 (0.155 mi.)***	***V178***	***313***
VERIZON EPA ID:: NYP000964486	SARATOGA AVE & PACIF	SSE 1/8 - 1/4 (0.162 mi.)	U207	369
CON EDISON EPA ID:: NYP004778452	SARATOGA AVE & PACIF	SSE 1/8 - 1/4 (0.162 mi.)	U208	371
BELL ATLANTIC-NY EPA ID:: NYP000935304	***SARATOGA AVE/PACIFIC***	***SSE 1/8 - 1/4 (0.162 mi.)***	***U211***	***376***
CON EDISON SERVICE B	2038 ATLANTIC AVE FR	SW 1/8 - 1/4 (0.163 mi.)	V213	380

EPA ID:: NYP004487930				
CON EDISON SERVICE B	***217 HOPKINSON AVE***	***ESE 1/8 - 1/4 (0.166 mi.)***	***W215***	***384***
EPA ID:: NYP004458394				
CON EDISON	***2151 PACIFIC ST***	***SE 1/8 - 1/4 (0.169 mi.)***	***AB218***	***390***
EPA ID:: NYP004749131				
CON EDISON	***2042A PACIFIC ST***	***S 1/8 - 1/4 (0.174 mi.)***	***AD222***	***398***
EPA ID:: NYP004813909				
CON EDISON	84 HULL ST	ENE 1/8 - 1/4 (0.176 mi.)	AE227	405
EPA ID:: NYP004838068				
REGIONAL MGMT & CONS	HOWARD AVE & PACIFIC	SSW 1/8 - 1/4 (0.177 mi.)	AF228	407
EPA ID:: NYR000120360				
CON EDISON SERVICE B	***86 HULL ST***	***ENE 1/8 - 1/4 (0.180 mi.)***	***AE232***	***422***
EPA ID:: NYP004556072				
CON EDISON SERVICE B	105 HULL ST	ENE 1/8 - 1/4 (0.181 mi.)	AE235	428
EPA ID:: NYP004483954				
BILL'S DRY CLEANERS	***2043 ATLANTIC AVE***	***ESE 1/8 - 1/4 (0.190 mi.)***	***W253***	***460***
EPA ID:: NYR000035881				
CON EDISON SERVICE B	***2010 ATLANTIC AVE***	***SW 1/8 - 1/4 (0.202 mi.)***	***V263***	***520***
EPA ID:: NYP004464954				
CON EDISON SERVICE B	***1235 HERKIMER ST***	***E 1/8 - 1/4 (0.206 mi.)***	***AP270***	***535***
EPA ID:: NYP004364410				
CON EDISON	***30 MARCONI PL***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AQ273***	***540***
EPA ID:: NYP004765376				
CON EDISON SERVICE B	***2118 FULTON ST***	***E 1/8 - 1/4 (0.209 mi.)***	***AP280***	***555***
EPA ID:: NYP004548988				
CON EDISON	196 MACDOUGAL ST	ENE 1/8 - 1/4 (0.213 mi.)	AT291	582
EPA ID:: NYP004760807				
CON EDISON	***DEAN ST & SARATOGA A***	***SSE 1/8 - 1/4 (0.215 mi.)***	***AL294***	***591***
EPA ID:: NYP004781290				
CON EDISON SERVICE B	***209 MCDOUGAL ST***	***ENE 1/8 - 1/4 (0.222 mi.)***	***AT302***	***609***
EPA ID:: NYP004480711				
CON EDISON SERVICE B	***213 MCDOUGAL ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AT317***	***646***
EPA ID:: NYP004476792				
CON EDISON	***12 GUNTHER PL***	***ESE 1/8 - 1/4 (0.241 mi.)***	***AX335***	***681***
EPA ID:: NYP004821209				
CON EDISON SERVICE B	***20 GUNTHER PL***	***ESE 1/8 - 1/4 (0.245 mi.)***	***AX346***	***723***
EPA ID:: NYP004497194				
CON EDISON SERVICE B	1261 HERKIMER ST	E 1/8 - 1/4 (0.247 mi.)	AP348	727
EPA ID:: NYP004497160				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CON EDISON SERVICE B	***84 MACDOUGAL***	***N 0 - 1/8 (0.052 mi.)***	***F55***	***78***
EPA ID:: NYP004463436				
CON EDISON	86 MACDOUGAL ST	N 0 - 1/8 (0.053 mi.)	F58	84
EPA ID:: NYP004766416				
CON EDISON	47 HULL ST	ENE 0 - 1/8 (0.053 mi.)	G60	88

EPA ID:: NYP004836688				
CON EDISON SERVICE B EPA ID:: NYP004510160	105 MCDOUGAL ST	N 0 - 1/8 (0.077 mi.)	F73	107
CON EDISON SERVICE B EPA ID:: NYP004480729	***117 MCDOUGAL STREET***	***N 0 - 1/8 (0.082 mi.)***	***F78***	***113***
CON EDISON EPA ID:: NYP004783528	***117 MACDOUGAL ST***	***N 0 - 1/8 (0.082 mi.)***	***F79***	***117***
CON EDISON SERVICE B EPA ID:: NYP004480653	***123 MCDOUGAL ST***	***NNE 0 - 1/8 (0.085 mi.)***	***F81***	***120***
CON EDISON EPA ID:: NYP004836506	***1921 FULTON ST***	***WNW 0 - 1/8 (0.101 mi.)***	***H102***	***160***
CON EDISON EPA ID:: NYP004399010	***166 SUMPTER ST***	***NNW 0 - 1/8 (0.104 mi.)***	***I107***	***168***
CON EDISON SERVICE B EPA ID:: NYP004556304	190 SUMPTER ST	N 0 - 1/8 (0.110 mi.)	O116	181
CON EDISON EPA ID:: NYP004825382	***148 MACDOUGAL ST***	***ENE 0 - 1/8 (0.110 mi.)***	***P117***	***183***
CON EDISON EPA ID:: NYP004774733	155 MACDOUGAL ST	NE 0 - 1/8 (0.115 mi.)	P130	204
CON EDISON EPA ID:: NYP004722484	***250 HOWARD ST***	***NW 0 - 1/8 (0.116 mi.)***	***I132***	***209***
CON EDISON SERVICE B EPA ID:: NYP004497210	159 MACDOUGAL ST	NE 0 - 1/8 (0.120 mi.)	P138	219
USPS - STUYVESANT ST EPA ID:: NY8180011233	***1915 FULTON ST***	***WNW 0 - 1/8 (0.124 mi.)***	***N141***	***224***
CON EDISON EPA ID:: NYP004770780	***61 MACDOUGAL***	***WNW 1/8 - 1/4 (0.126 mi.)***	***Q145***	***242***
CON EDISON SERVICE B EPA ID:: NYP004489852	***156 MACDOUGAL ST***	***ENE 1/8 - 1/4 (0.128 mi.)***	***P150***	***252***
CON EDISON SERVICE B EPA ID:: NYP004510152	***59 MCDOUGAL ST***	***WNW 1/8 - 1/4 (0.129 mi.)***	***Q152***	***256***
NYC DEP EPA ID:: NYP003669819	***55 MACDOUGAL PLACE***	***WNW 1/8 - 1/4 (0.133 mi.)***	***Q155***	***261***
CON EDISON SERVICE B EPA ID:: NYP004472874	***209 SUMPTER ST***	***N 1/8 - 1/4 (0.134 mi.)***	***O157***	***265***
CON EDISON SERVICE B EPA ID:: NYP004430153	***237 SUMPTER ST***	***NNE 1/8 - 1/4 (0.152 mi.)***	***T168***	***292***
CON EDISON EPA ID:: NYP004737466	***282 MARION ST***	***NNW 1/8 - 1/4 (0.155 mi.)***	***R174***	***306***
CON EDISON EPA ID:: NYP004832917	***280 MARION ST***	***NNW 1/8 - 1/4 (0.155 mi.)***	***R179***	***318***
CON EDISON EPA ID:: NYP004745386	***292 MARION ST***	***N 1/8 - 1/4 (0.155 mi.)***	***R185***	***329***
CON EDISON EPA ID:: NYP004725370	292 MARION ST	N 1/8 - 1/4 (0.155 mi.)	R186	331
CON EDISON	***276 MARION ST***	***NNW 1/8 - 1/4 (0.156 mi.)***	***R187***	***333***

EPA ID:: NYP004737458				
CON EDISON SERVICE B EPA ID:: NYP004520474	***298 MARION ST***	***N 1/8 - 1/4 (0.157 mi.)***	***X191***	***340***
1921 LIHTC LLC - 192 EPA ID:: NYR000247809	1921 ATLANTIC AVE	WSW 1/8 - 1/4 (0.159 mi.)	V197	350
CON EDISON EPA ID:: NYP004745857	***153 SUMPTER ST***	***NW 1/8 - 1/4 (0.159 mi.)***	***Z201***	***357***
CON EDISON EPA ID:: NYP004737433	***266 MARION ST***	***NNW 1/8 - 1/4 (0.161 mi.)***	***R205***	***365***
CON EDISON SERVICE B EPA ID:: NYP004470209	***322 MARION ST***	***NNE 1/8 - 1/4 (0.171 mi.)***	***T219***	***392***
CON EDISON SERVICE B EPA ID:: NYP004363206	***24 MACDOUGAL ST***	***WNW 1/8 - 1/4 (0.177 mi.)***	***Y230***	***416***
CON EDISON SERVICE B EPA ID:: NYP004470191	***336 MARION ST***	***NNE 1/8 - 1/4 (0.177 mi.)***	***T231***	***419***
CON EDISON EPA ID:: NYP004737441	***253 MARION ST***	***NNW 1/8 - 1/4 (0.187 mi.)***	***AH241***	***439***
CON EDISON SERVICE B EPA ID:: NYP004480976	***129 HOPKINSON***	***NE 1/8 - 1/4 (0.187 mi.)***	***AA244***	***444***
CON EDISON SERVICE B EPA ID:: NYP004515763	348 MARION ST	NNE 1/8 - 1/4 (0.187 mi.)	AC246	449
CON EDISON SERVICE B EPA ID:: NYP004518601	29-29A MCDOUGAL ST	WNW 1/8 - 1/4 (0.189 mi.)	AI248	451
CON EDISON SERVICE B EPA ID:: NYP004520821	***29 MCDOUGAL ST***	***WNW 1/8 - 1/4 (0.189 mi.)***	***AI251***	***456***
CON EDISON SERVICE B EPA ID:: NYP004364535	***236 MARION ST***	***NW 1/8 - 1/4 (0.195 mi.)***	***Z257***	***479***
CON EDISON SERVICE B EPA ID:: NYP004468377	***317 MARION ST***	***NNE 1/8 - 1/4 (0.196 mi.)***	***AK258***	***482***
CON EDISON SERVICE B EPA ID:: NYP004467130	***237 MARION ST***	***NW 1/8 - 1/4 (0.207 mi.)***	***AH275***	***544***
CON ED - MH 65388 EPA ID:: NYP004010914	***HERKIMER ST AND RALP***	***W 1/8 - 1/4 (0.209 mi.)***	***AR276***	***547***
CON EDISON SERVICE B EPA ID:: NYP004438586	***343 RALPH AVE FRONT***	***WSW 1/8 - 1/4 (0.209 mi.)***	***AG279***	***552***
CON EDISON SERVICE B EPA ID:: NYP004480679	***203 MCDOUGAL ST***	***ENE 1/8 - 1/4 (0.209 mi.)***	***AA282***	***559***
MTA NYCT - RALPH AVE EPA ID:: NYR000106682	***RALPH AVE & FULTON S***	***W 1/8 - 1/4 (0.211 mi.)***	***AI283***	***563***
VERIZON EPA ID:: NYP000966861	RALPH AVE & FULTON S	W 1/8 - 1/4 (0.211 mi.)	AI284	566
CON EDISON SERVICE B EPA ID:: NYP004468385	***349 MARION ST***	***NNE 1/8 - 1/4 (0.213 mi.)***	***AU292***	***584***
CON EDISON SERVICE B EPA ID:: NYP004433967	***347 RALPH AVE***	***WSW 1/8 - 1/4 (0.214 mi.)***	***AG293***	***588***
CON EDISON SERVICE B	***106 HOPKINSON AVE***	***NE 1/8 - 1/4 (0.217 mi.)***	***AJ298***	***602***

EPA ID:: NYP004426854				
B & G CLEANERS EPA ID:: NYD986868560	***291 RALPH AVE***	***WNW 1/8 - 1/4 (0.223 mi.)***	***AI304***	***613***
CON EDISON SERVICE B EPA ID:: NYP004555694	***289 RALPH AVE***	***WNW 1/8 - 1/4 (0.225 mi.)***	***AI307***	***621***
CON EDISON SERVICE B EPA ID:: NYP004410692	***402 CHAUNCEY ST***	***NNE 1/8 - 1/4 (0.227 mi.)***	***AK309***	***627***
LIRR ATLANTIC AVENUE EPA ID:: NY0000078774	***S35-S34 ON ATLANTIC***	***WSW 1/8 - 1/4 (0.227 mi.)***	***AG310***	***631***
LIRR ATLANTIC AVENUE EPA ID:: NYD987037488	ATLANTIC AVE BETW RA	WSW 1/8 - 1/4 (0.231 mi.)	AG318	651
CON EDISON SERVICE B EPA ID:: NYP004558862	383 CHAUNCEY ST	NNW 1/8 - 1/4 (0.233 mi.)	AO322	658
CON EDISON SERVICE B EPA ID:: NYP004558649	383 CHAUNCEY ST	NNW 1/8 - 1/4 (0.233 mi.)	AO323	660
CON EDISON EPA ID:: NYP004804811	375 CHAUNCEY ST	NNW 1/8 - 1/4 (0.235 mi.)	AO326	666
CON EDISON EPA ID:: NYP004754073	***215 MARION ST***	***NW 1/8 - 1/4 (0.236 mi.)***	***AS330***	***672***
CON EDISON EPA ID:: NYP004742177	***138 SARATOGA AVE***	***N 1/8 - 1/4 (0.238 mi.)***	***AW334***	***679***
CON EDISON EPA ID:: NYP004881427	1885 ATLANTIC AVE	WSW 1/8 - 1/4 (0.241 mi.)	AV338	686
CON EDISON SERVICE B EPA ID:: NYP004470217	***392 MARION ST***	***NE 1/8 - 1/4 (0.244 mi.)***	***AJ344***	***718***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 06/08/2023 has revealed that there are 2 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BILL'S DRY CLEANERS Facility Id: 2-6104-01318	2043 ATLANTIC AVE	ESE 1/8 - 1/4 (0.190 mi.)	W254	468

Lower Elevation	Address	Direction / Distance	Map ID	Page
GREAT DEALS DRY CLNG Facility Id: 2-6104-00394	291 RALPH AVENUE	WNW 1/8 - 1/4 (0.223 mi.)	AI303	613

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 06/05/2023 has revealed that there are 31 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 23,TAXBLOCK 1549	2020A FULTON STREET	0 - 1/8 (0.000 mi.)	A3	8

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 21,TAXBLOCK 1549	2018 FULTON STREET	0 - 1/8 (0.000 mi.)	A4	9
LOT 25,TAXBLOCK 1549	2024 FULTON STREET	0 - 1/8 (0.000 mi.)	A5	9
LOT 31,TAXBLOCK 1549	2036 FULTON STREET	0 - 1/8 (0.000 mi.)	A6	10
LOT 34,TAXBLOCK 1549	2042 FULTON STREET	0 - 1/8 (0.000 mi.)	B7	10
LOT 33,TAXBLOCK 1549	2040 FULTON STREET	0 - 1/8 (0.000 mi.)	B8	11
LOT 24,TAXBLOCK 1549	2022 FULTON STREET	0 - 1/8 (0.000 mi.)	A9	11
LOT 28,TAXBLOCK 1549	FULTON STREET	0 - 1/8 (0.000 mi.)	A10	11
LOT 30,TAXBLOCK 1549	2034 FULTON STREET	0 - 1/8 (0.000 mi.)	A12	12
LOT 35,TAXBLOCK 1549	224 SARATOGA AVENUE	0 - 1/8 (0.000 mi.)	B13	13
LOT 22,TAXBLOCK 1549	2020 FULTON STREET	0 - 1/8 (0.000 mi.)	A14	13
LOT 32,TAXBLOCK 1549	2038 FULTON STREET	0 - 1/8 (0.000 mi.)	B15	14
LOT 29,TAXBLOCK 1549	FULTON STREET	0 - 1/8 (0.000 mi.)	A16	14
LOT 26,TAXBLOCK 1549	2026 FULTON STREET	0 - 1/8 (0.000 mi.)	A17	14

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 20,TAXBLOCK 1549	2016 FULTON STREET	0 - 1/8 (0.000 mi.)	A2	8
LOT 18,TAXBLOCK 1549	FULTON STREET	0 - 1/8 (0.000 mi.)	A11	12
LOT 13,TAXBLOCK 1549	2006A FULTON STREET	WNW 0 - 1/8 (0.018 mi.)	A28	36
LOT 12,TAXBLOCK 1549	2004 FULTON STREET	WNW 0 - 1/8 (0.020 mi.)	A30	37
LOT 7,TAXBLOCK 1549	FULTON STREET	W 0 - 1/8 (0.040 mi.)	A45	58
LOT 6,TAXBLOCK 1549	1994 FULTON STREET	W 0 - 1/8 (0.044 mi.)	A47	61
LOT 5,TAXBLOCK 1549	1992 FULTON STREET	W 0 - 1/8 (0.047 mi.)	D51	73
LOT 4,TAXBLOCK 1549	FULTON STREET	W 0 - 1/8 (0.051 mi.)	D53	77
LOT 3,TAXBLOCK 1549	1988A FULTON STREET	W 0 - 1/8 (0.059 mi.)	D62	92
LOT 1,TAXBLOCK 1549	1986 FULTON STREET	W 0 - 1/8 (0.064 mi.)	D64	93
LOT 33,TAXBLOCK 1548	1984 FULTON STREET	W 0 - 1/8 (0.079 mi.)	D75	110
LOT 32,TAXBLOCK 1548	1982 FULTON STREET	W 0 - 1/8 (0.084 mi.)	D80	119
LOT 29,TAXBLOCK 1548	1970 FULTON STREET	W 0 - 1/8 (0.098 mi.)	H90	134
LOT 128,TAXBLOCK 154	1968 FULTON STREET	W 0 - 1/8 (0.101 mi.)	H103	162
LOT 28,TAXBLOCK 1548	1966 FULTON STREET	W 0 - 1/8 (0.105 mi.)	H109	172
LOT 27,TAXBLOCK 1548	1964 FULTON STREET	W 0 - 1/8 (0.109 mi.)	N111	174
LOT 26,TAXBLOCK 1548	1962 FULTON STREET	W 0 - 1/8 (0.113 mi.)	N121	189

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 135 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - SARATOGA EPA ID: NYR000196386	***FULTON ST & SARATOGA***	***E 0 - 1/8 (0.007 mi.)***	***B18***	***15***
CON EDISON EPA ID: NYP004491106	1091 HERKIMER ST	SE 0 - 1/8 (0.009 mi.)	A22	24
CON EDISON SERVICE B EPA ID: NYP004459616	***1103 HERKIMER ST***	***SE 0 - 1/8 (0.013 mi.)***	***A24***	***28***
CON EDISON EPA ID: NYP004746053	1063 HERKIMER ST	WSW 0 - 1/8 (0.023 mi.)	A31	37
CONSOLIDATED EDISON	HERKIMER ST & SARATO	ESE 0 - 1/8 (0.025 mi.)	B35	44

EPA ID: NYP004069993				
CON EDISON EPA ID: NYP004746061	HERKIMER ST & DEWEY	SW 0 - 1/8 (0.034 mi.)	A42	54
I.S. 271 JOHN M. COL EPA ID: NYR000056812	***1137 HERKIMER ST***	***ESE 0 - 1/8 (0.044 mi.)***	***E49***	***63***
CON EDISON SERVICE B EPA ID: NYP004458386	***1132 HERKIMER ST***	***ESE 0 - 1/8 (0.048 mi.)***	***E52***	***73***
CON EDISON - MANHOLE EPA ID: NYP005150511	1036 HERKIMER ST	WSW 0 - 1/8 (0.071 mi.)	D67	97
CON ED EPA ID: NYP004847232	21 LOUIS PL	SSE 0 - 1/8 (0.077 mi.)	C69	100
CON ED EPA ID: NYP004842247	52 HULL ST	ENE 0 - 1/8 (0.096 mi.)	L87	130
CON EDISON EPA ID: NYP004483418	2001 ATLANTIC AVE FR	SE 0 - 1/8 (0.099 mi.)	K91	135
CON EDISON EPA ID: NYP004483426	2001 ATLANTIC AVE	SE 0 - 1/8 (0.099 mi.)	K94	141
CON EDISON EPA ID: NYP004738548	1943 ATLANTIC AV	SSW 0 - 1/8 (0.101 mi.)	J96	146
CON EDISON EPA ID: NYP004472155	***1943 ATLANTIC AVE***	***SSW 0 - 1/8 (0.101 mi.)***	***J97***	***148***
CON EDISON SERVICE B EPA ID: NYP004458402	***298 HOWARD AVE***	***SW 0 - 1/8 (0.101 mi.)***	***M98***	***151***
CON ED EPA ID: NYP004845893	ATLANTIC AVE & DEWEY	SSW 0 - 1/8 (0.103 mi.)	J104	163
CON EDISON EPA ID: NYP004837993	77 HULL ST	ENE 0 - 1/8 (0.109 mi.)	L113	175
CON EDISON EPA ID: NYP004487922	2112 ATLANTIC AVE FR	S 0 - 1/8 (0.115 mi.)	J124	194
CON EDISON EPA ID: NYP004487955	2100 ATLANTIC AVE FR	S 0 - 1/8 (0.115 mi.)	J127	200
CON EDISON EPA ID: NYP004487914	2090 ATLANTIC AVE FR	SSW 0 - 1/8 (0.117 mi.)	J135	214
CON EDISON EPA ID: NYP004487948	2074 ATLANTIC AVE FR	S 1/8 - 1/4 (0.127 mi.)	J147	246
CON EDISON EPA ID: NYP004838035	87 HULL ST	ENE 1/8 - 1/4 (0.134 mi.)	L160	272
CON EDISON SERVICE B EPA ID: NYP004426847	***170 HOPKINSON AVE***	***E 1/8 - 1/4 (0.145 mi.)***	***S164***	***282***
CON EDISON MANHOLE 6 EPA ID: NYP004148367	***HERKIMER ST & HOPKIN***	***ESE 1/8 - 1/4 (0.152 mi.)***	***S169***	***295***
CON EDISON EPA ID: NYP004577516	171 HOPKINSON	E 1/8 - 1/4 (0.153 mi.)	S170	299
CON EDISON EPA ID: NYP004609715	171 THOMAS S BOYLAND	E 1/8 - 1/4 (0.153 mi.)	S172	303
CON EDISON	***ATLANTIC AVE & BANCR***	***SW 1/8 - 1/4 (0.155 mi.)***	***V178***	***313***

EPA ID: NYP004194452				
CON EDISON EPA ID: NYP004778452	SARATOGA AVE & PACIF	SSE 1/8 - 1/4 (0.162 mi.)	U210	374
BELL ATLANTIC-NY EPA ID: NYP000935304	***SARATOGA AVE/PACIFIC***	***SSE 1/8 - 1/4 (0.162 mi.)***	***U211***	***376***
CON EDISON EPA ID: NYP004487930	2038 ATLANTIC AVE FR	SW 1/8 - 1/4 (0.163 mi.)	V212	378
CON EDISON SERVICE B EPA ID: NYP004458394	***217 HOPKINSON AVE***	***ESE 1/8 - 1/4 (0.166 mi.)***	***W215***	***384***
CON EDISON EPA ID: NYP004749131	2151 PACIFIC ST	SE 1/8 - 1/4 (0.169 mi.)	AB216	387
CON EDISON EPA ID: NYP004813909	2042A PACIFIC ST	S 1/8 - 1/4 (0.174 mi.)	AD221	396
CON EDISON EPA ID: NYP004838068	84 HULL ST	ENE 1/8 - 1/4 (0.176 mi.)	AE226	403
CON EDISON EPA ID: NYP004556072	86 HULL ST	ENE 1/8 - 1/4 (0.180 mi.)	AE233	425
CON EDISON EPA ID: NYP004483954	105 HULL ST	ENE 1/8 - 1/4 (0.181 mi.)	AE234	426
CON EDISON - MANHOLE EPA ID: NYP005150495	2034 ATLANTIC AVE	SW 1/8 - 1/4 (0.186 mi.)	V237	432
CON EDISON EPA ID: NYP004709440	15 SOMER ST	E 1/8 - 1/4 (0.186 mi.)	S240	437
MTA LIRR - ATLANTIC EPA ID: NYR000160986	***2010 ATLANTIC AVE***	***SW 1/8 - 1/4 (0.202 mi.)***	***V261***	***497***
CON EDISON SERVICE B EPA ID: NYP004464954	***2010 ATLANTIC AVE***	***SW 1/8 - 1/4 (0.202 mi.)***	***V263***	***520***
CON EDISON SERVICE B EPA ID: NYP004364410	***1235 HERKIMER ST***	***E 1/8 - 1/4 (0.206 mi.)***	***AP270***	***535***
CON EDISON EPA ID: NYP004765376	30 MARCONI PL	ESE 1/8 - 1/4 (0.207 mi.)	AQ274	542
CON EDISON EPA ID: NYP004548988	2118 FULTON ST	E 1/8 - 1/4 (0.209 mi.)	AP281	558
NYC DEPT OF EDUCATIO EPA ID: NYR000213983	***2163 DEAN ST***	***SSE 1/8 - 1/4 (0.211 mi.)***	***AL287***	***571***
CON EDISON EPA ID: NYP004781290	DEAN ST & SARATOGA A	SSE 1/8 - 1/4 (0.215 mi.)	AL296	595
CON EDISON - MANHOLE EPA ID: NYP004934681	PACIFIC ST & HOPKINS	SE 1/8 - 1/4 (0.222 mi.)	AN300	607
CON EDISON EPA ID: NYP004715298	200 MCDOUGAL ST	ENE 1/8 - 1/4 (0.222 mi.)	AT301	608
CON EDISON SERVICE B EPA ID: NYP004480711	***209 MCDOUGAL ST***	***ENE 1/8 - 1/4 (0.222 mi.)***	***AT302***	***609***
CON EDISON SERVICE B EPA ID: NYP004476792 EPA ID: NYP004715280	***213 MCDOUGAL ST***	***ENE 1/8 - 1/4 (0.230 mi.)***	***AT317***	***646***
CON ED	12 GUNTHER PL	ESE 1/8 - 1/4 (0.241 mi.)	AX337	685

EPA ID: NYP004821209				
CON EDISON EPA ID: NYP004497160	1261 HERKIMER ST	E 1/8 - 1/4 (0.247 mi.)	AP349	729

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID: NYP004463436	***84 MACDOUGAL***	***N 0 - 1/8 (0.052 mi.)***	***F55***	***78***
CON EDISON EPA ID: NYP004766416	86 MACDOUGAL ST	N 0 - 1/8 (0.053 mi.)	F56	81
CON ED EPA ID: NYP004836688	47 HULL ST	ENE 0 - 1/8 (0.053 mi.)	G59	86
CON EDISON EPA ID: NYP004510161	105 MACDOUGAL ST	N 0 - 1/8 (0.077 mi.)	F72	106
CON EDISON EPA ID: NYP004783528	117 MACDOUGAL ST	N 0 - 1/8 (0.082 mi.)	F77	112
CON EDISON SERVICE B EPA ID: NYP004480729	***117 MCDOUGAL STREET***	***N 0 - 1/8 (0.082 mi.)***	***F78***	***113***
CON EDISON SERVICE B EPA ID: NYP004480653	***123 MCDOUGAL ST***	***NNE 0 - 1/8 (0.085 mi.)***	***F81***	***120***
CON ED EPA ID: NYP004836506	1921 FULTON ST	WNW 0 - 1/8 (0.101 mi.)	H101	158
CON EDISON EPA ID: NYP004399010	166 SUMPTER ST	NNW 0 - 1/8 (0.104 mi.)	I108	171
CON EDISON EPA ID: NYP004556304	190 SUMPTER ST	N 0 - 1/8 (0.110 mi.)	O115	179
CON ED EPA ID: NYP004825382	148 MACDOUGAL ST	ENE 0 - 1/8 (0.110 mi.)	P119	187
CON EDISON EPA ID: NYP004774733	155 MACDOUGAL ST	NE 0 - 1/8 (0.115 mi.)	P128	202
CON EDISON EPA ID: NYP004722484	250 HOWARD ST	NW 0 - 1/8 (0.116 mi.)	I134	212
CON EDISON EPA ID: NYP004718722	F/O 204 SUMPTER ST	NNE 0 - 1/8 (0.119 mi.)	O137	218
CON EDISON EPA ID: NYP004497210	159 MACDOUGAL ST	NE 0 - 1/8 (0.120 mi.)	P139	221
CON EDISON EPA ID: NYP004770780	61 MACDOUGAL	WNW 1/8 - 1/4 (0.126 mi.)	Q146	245
CON EDISON EPA ID: NYP004489852	156 MACDOUGAL ST	ENE 1/8 - 1/4 (0.128 mi.)	P149	250
CON EDISON EPA ID: NYP004697934	59 MACDOUGAL ST	WNW 1/8 - 1/4 (0.129 mi.)	Q151	254
CON EDISON EPA ID: NYP004510152	59 MCDOUGAL ST	WNW 1/8 - 1/4 (0.129 mi.)	Q153	258
CON ED EPA ID: NYP004862062	179 SUMPTER ST	NNW 1/8 - 1/4 (0.131 mi.)	R154	260
NYC DEP	55 MACDOUGAL PLACE	WNW 1/8 - 1/4 (0.133 mi.)	Q156	264

EPA ID: NYP003669819				
CON EDISON SERVICE B EPA ID: NYP004472874	***209 SUMPTER ST***	***N 1/8 - 1/4 (0.134 mi.)***	***O157***	***265***
P.S. 28 THE WARREN EPA ID: NYR000012039	***1001 HERKIMER ST***	***W 1/8 - 1/4 (0.138 mi.)***	***N161***	***274***
CON ED EPA ID: NYP004862237	229 SUMPTER ST	NNE 1/8 - 1/4 (0.147 mi.)	T165	286
CON EDISON SERVICE B EPA ID: NYP004430153	***237 SUMPTER ST***	***NNE 1/8 - 1/4 (0.152 mi.)***	***T168***	***292***
CON EDISON EPA ID: NYP004627030	FO 284 MARION ST	N 1/8 - 1/4 (0.154 mi.)	R173	304
CON EDISON EPA ID: NYP004737466	282 MARION ST	NNW 1/8 - 1/4 (0.155 mi.)	R176	309
CON ED EPA ID: NYP004832917	280 MARION ST	NNW 1/8 - 1/4 (0.155 mi.)	R181	321
CON EDISON EPA ID: NYP004725370 EPA ID: NYP004745386	292 MARION ST	N 1/8 - 1/4 (0.155 mi.)	R182	323
CON EDISON EPA ID: NYP004737458	276 MARION ST	NNW 1/8 - 1/4 (0.156 mi.)	R188	335
CON EDISON EPA ID: NYP004831430	304 MARION ST & SARA	N 1/8 - 1/4 (0.157 mi.)	O190	338
CON EDISON EPA ID: NYP004520474	298 MARION ST	N 1/8 - 1/4 (0.157 mi.)	X192	342
CON EDISON EPA ID: NYP004664389	FRONT OF 270 MARION	NNW 1/8 - 1/4 (0.159 mi.)	R193	344
CON EDISON EPA ID: NYP004648226	985 HERKIMER ST	W 1/8 - 1/4 (0.159 mi.)	Y194	345
CON EDISON EPA ID: NYP004602181	F/O 985 HERKIMER ST	W 1/8 - 1/4 (0.159 mi.)	Y195	347
CON EDISON EPA ID: NYP004670741	985 HERKIMER ST	W 1/8 - 1/4 (0.159 mi.)	Y196	348
CON EDISON EPA ID: NYP004499745	F/O 153 SUMPTER ST	NW 1/8 - 1/4 (0.159 mi.)	Z198	353
CON EDISON EPA ID: NYP004745857	153 SUMPTER ST	NW 1/8 - 1/4 (0.159 mi.)	Z200	356
CON EDISON EPA ID: NYP004737433	266 MARION ST	NNW 1/8 - 1/4 (0.161 mi.)	R204	363
CON EDISON EPA ID: NYP004499752	OPP 116 SUMPTER ST	WNW 1/8 - 1/4 (0.165 mi.)	Q214	382
CON EDISON SERVICE B EPA ID: NYP004470209	***322 MARION ST***	***NNE 1/8 - 1/4 (0.171 mi.)***	***T219***	***392***
CON EDISON - SERVICE EPA ID: NYP004936118	255 SUMPTER ST	NE 1/8 - 1/4 (0.171 mi.)	AC220	396
CON EDISON SERVICE B EPA ID: NYP004363206	***24 MACDOUGAL ST***	***WNW 1/8 - 1/4 (0.177 mi.)***	***Y230***	***416***
CON EDISON SERVICE B	***336 MARION ST***	***NNE 1/8 - 1/4 (0.177 mi.)***	***T231***	***419***

EPA ID: NYP004470191				
CON EDISON EPA ID: NYP004737441	253 MARION ST	NNW 1/8 - 1/4 (0.187 mi.)	AH243	442
CON EDISON SERVICE B EPA ID: NYP004480976	***129 HOPKINSON***	***NE 1/8 - 1/4 (0.187 mi.)***	***AA244***	***444***
CON EDISON EPA ID: NYP004515763	348 MARION ST	NNE 1/8 - 1/4 (0.187 mi.)	AC245	447
CON EDISON EPA ID: NYP004518601	29-29A MCDOUGAL ST	WNW 1/8 - 1/4 (0.189 mi.)	AI250	455
CON EDISON EPA ID: NYP004520821	29 MCDOUGAL ST	WNW 1/8 - 1/4 (0.189 mi.)	AI252	459
CON EDISON - MANHOLE EPA ID: NYP004185351	***THOMAS S BOYLAND ST***	***NE 1/8 - 1/4 (0.195 mi.)***	***AJ256***	***473***
CON EDISON SERVICE B EPA ID: NYP004364535	***236 MARION ST***	***NW 1/8 - 1/4 (0.195 mi.)***	***Z257***	***479***
CON EDISON SERVICE B EPA ID: NYP004468377	***317 MARION ST***	***NNE 1/8 - 1/4 (0.196 mi.)***	***AK258***	***482***
RITE AID #04893 EPA ID: NYR000186445	***1950 FULTON ST***	***W 1/8 - 1/4 (0.202 mi.)***	***AI259***	***485***
CON EDISON EPA ID: NYP004599346	F/O 348 CHAUNCEY ST	NNW 1/8 - 1/4 (0.205 mi.)	AO269	533
CON EDISON SERVICE B EPA ID: NYP004467130	***237 MARION ST***	***NW 1/8 - 1/4 (0.207 mi.)***	***AH275***	***544***
CON ED - MH 65388 EPA ID: NYP004010914	***HERKIMER ST AND RALP***	***W 1/8 - 1/4 (0.209 mi.)***	***AR276***	***547***
CONSOLIDATED EDISON EPA ID: NYP004010003	HERKIMER ST & RALPH	W 1/8 - 1/4 (0.209 mi.)	AR277	550
CON EDISON EPA ID: NYP004720561	FRONT OF 235 MARION	NW 1/8 - 1/4 (0.209 mi.)	AS278	551
CON EDISON SERVICE B EPA ID: NYP004438586	***343 RALPH AVE FRONT***	***WSW 1/8 - 1/4 (0.209 mi.)***	***AG279***	***552***
CON EDISON SERVICE B EPA ID: NYP004480679	***203 MCDOUGAL ST***	***ENE 1/8 - 1/4 (0.209 mi.)***	***AA282***	***559***
MTA NYCT - RALPH AVE EPA ID: NYR000106682	***RALPH AVE & FULTON S***	***W 1/8 - 1/4 (0.211 mi.)***	***AI283***	***563***
NYNEX EPA ID: NYP000926766	RALPH AVE & FULTON S	W 1/8 - 1/4 (0.211 mi.)	AI285	568
CON EDISON SERVICE B EPA ID: NYP004468385	***349 MARION ST***	***NNE 1/8 - 1/4 (0.213 mi.)***	***AU292***	***584***
CON EDISON SERVICE B EPA ID: NYP004433967	***347 RALPH AVE***	***WSW 1/8 - 1/4 (0.214 mi.)***	***AG293***	***588***
MTA NYCT - RALPH AVE EPA ID: NYR000156133	***302 RALPH AVE***	***W 1/8 - 1/4 (0.216 mi.)***	***AI297***	***596***
CON EDISON SERVICE B EPA ID: NYP004426854	***106 HOPKINSON AVE***	***NE 1/8 - 1/4 (0.217 mi.)***	***AJ298***	***602***
B & G CLEANERS	***291 RALPH AVE***	***WNW 1/8 - 1/4 (0.223 mi.)***	***AI304***	***613***

EPA ID: NYD986868560				
CON EDISON EPA ID: NYP004555694	289 RALPH AVE	WNW 1/8 - 1/4 (0.225 mi.)	AI305	618
CON EDISON EPA ID: NYP004652236	F/O 289 RALPH AV	WNW 1/8 - 1/4 (0.225 mi.)	AI306	619
CON EDISON SERVICE B EPA ID: NYP004410692	***402 CHAUNCEY ST***	***NNE 1/8 - 1/4 (0.227 mi.)***	***AK309***	***627***
LIRR ATLANTIC AVENUE EPA ID: NY0000078774	***S35-S34 ON ATLANTIC***	***WSW 1/8 - 1/4 (0.227 mi.)***	***AG310***	***631***
CON EDISON EPA ID: NYP004734406	CHAUNCEY ST & SARATO	N 1/8 - 1/4 (0.228 mi.)	AK312	636
CON EDISON EPA ID: NYP004558649	383 CHAUNCEY ST	NNW 1/8 - 1/4 (0.233 mi.)	AO320	655
CON EDISON EPA ID: NYP004558862	383 CHAUNCEY ST	NNW 1/8 - 1/4 (0.233 mi.)	AO321	657
CON EDISON EPA ID: NYP004817003	375 CHAUNCEY ST	NNW 1/8 - 1/4 (0.235 mi.)	AO327	668
CON EDISON EPA ID: NYP004804811	375 CHAUNCEY ST	NNW 1/8 - 1/4 (0.235 mi.)	AO328	670
CON EDISON EPA ID: NYP004754073	215 MARION ST	NW 1/8 - 1/4 (0.236 mi.)	AS331	675
CON EDISON EPA ID: NYP004742177	138 SARATOGA AVE	N 1/8 - 1/4 (0.238 mi.)	AW333	677
SPEEDWAY 7833 EPA ID: NYD982185530	***1885 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.241 mi.)***	***AV341***	***699***
CON EDISON - MANHOLE EPA ID: NYP005050356	428 CHAUNCEY ST	NNE 1/8 - 1/4 (0.242 mi.)	AU342	715
CON EDISON SERVICE B EPA ID: NYP004470217	***392 MARION ST***	***NE 1/8 - 1/4 (0.244 mi.)***	***AJ344***	***718***
CON EDISON EPA ID: NYP004680195	FRONT OF 297 SUMPTER	NE 1/8 - 1/4 (0.244 mi.)	AY345	721
CON EDISON EPA ID: NYP004623138	FRONT OF 290 SUMPTER	ENE 1/8 - 1/4 (0.247 mi.)	AY347	725

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RITE AID # 04893 Generator EPA Id: NYR000186445	1950 FULTON ST	W 1/8 - 1/4 (0.202 mi.)	AI260	495

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 42 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYCTA ESSEX ST FIELD EPA Id: NYR000102608	2046 FULTON STREET	E 0 - 1/8 (0.008 mi.)	B19	19
CON EDISON EPA Id: NYP004746053	1063 HERKIMER ST	WSW 0 - 1/8 (0.023 mi.)	A33	41
CON EDISON EPA Id: NYP004746061	HERKIMER ST & DEWEY	SW 0 - 1/8 (0.034 mi.)	A43	55
CON EDISON EPA Id: NYP004847232	21 LOUIS PL	SSE 0 - 1/8 (0.077 mi.)	C71	104
CON EDISON EPA Id: NYP004842247	52 HULL ST	ENE 0 - 1/8 (0.096 mi.)	L88	131
CON EDISON EPA Id: NYP004845893	ATLANTIC AVE & DEWEY	SSW 0 - 1/8 (0.103 mi.)	J105	164
CON EDISON EPA Id: NYP004837993	77 HULL ST	ENE 0 - 1/8 (0.109 mi.)	L112	174
CON EDISON EPA Id: NYP004838035	87 HULL ST	ENE 1/8 - 1/4 (0.134 mi.)	L159	271
CON EDISON EPA Id: NYP004194452	***ATLANTIC AVE & BANCR***	***SW 1/8 - 1/4 (0.155 mi.)***	***V178***	***313***
CON EDISON EPA Id: NYP004778452	SARATOGA AVE & PACIF	SSE 1/8 - 1/4 (0.162 mi.)	U209	373
CON EDISON EPA Id: NYP004749131	2151 PACIFIC ST	SE 1/8 - 1/4 (0.169 mi.)	AB217	389
CON EDISON EPA Id: NYP004813909	2042A PACIFIC ST	S 1/8 - 1/4 (0.174 mi.)	AD223	400
CON EDISON EPA Id: NYP004838068	84 HULL ST	ENE 1/8 - 1/4 (0.176 mi.)	AE225	402
MTA LIRR - ATLANTIC EPA Id: NYR000160986	***2010 ATLANTIC AVE***	***SW 1/8 - 1/4 (0.202 mi.)***	***V261***	***497***
CON EDISON EPA Id: NYP004765376	30 MARCONI PL	ESE 1/8 - 1/4 (0.207 mi.)	AQ272	538
CON EDISON EPA Id: NYP004760807	196 MACDOUGAL ST	ENE 1/8 - 1/4 (0.213 mi.)	AT290	581
CON EDISON EPA Id: NYP004781290	DEAN ST & SARATOGA A	SSE 1/8 - 1/4 (0.215 mi.)	AL295	593
CON EDISON EPA Id: NYP004821209	12 GUNTHER PL	ESE 1/8 - 1/4 (0.241 mi.)	AX336	684

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004766416	86 MACDOUGAL ST	N 0 - 1/8 (0.053 mi.)	F57	83
CON EDISON	47 HULL ST	ENE 0 - 1/8 (0.053 mi.)	G61	90

EPA Id: NYP004836688				
CON EDISON EPA Id: NYP004783528	117 MACDOUGAL ST	N 0 - 1/8 (0.082 mi.)	F76	111
CON EDISON EPA Id: NYP004836506	1921 FULTON ST	WNW 0 - 1/8 (0.101 mi.)	H100	157
CON EDISON EPA Id: NYP004825382	148 MACDOUGAL ST	ENE 0 - 1/8 (0.110 mi.)	P118	186
CON EDISON EPA Id: NYP004774733	155 MACDOUGAL ST	NE 0 - 1/8 (0.115 mi.)	P129	203
CON EDISON EPA Id: NYP004722484	250 HOWARD ST	NW 0 - 1/8 (0.116 mi.)	I133	211
CON EDISON EPA Id: NYP004770780	61 MACDOUGAL	WNW 1/8 - 1/4 (0.126 mi.)	Q144	241
CON EDISON EPA Id: NYP004737466	282 MARION ST	NNW 1/8 - 1/4 (0.155 mi.)	R175	308
CON EDISON EPA Id: NYP004832917	280 MARION ST	NNW 1/8 - 1/4 (0.155 mi.)	R180	320
CON EDISON EPA Id: NYP004745386	292 MARION ST	N 1/8 - 1/4 (0.155 mi.)	R183	326
CON EDISON EPA Id: NYP004725370	292 MARION ST	N 1/8 - 1/4 (0.155 mi.)	R184	327
CON EDISON EPA Id: NYP004737458	276 MARION ST	NNW 1/8 - 1/4 (0.156 mi.)	R189	337
CON EDISON EPA Id: NYP004745857	153 SUMPTER ST	NW 1/8 - 1/4 (0.159 mi.)	Z199	355
CON EDISON EPA Id: NYP004737433	266 MARION ST	NNW 1/8 - 1/4 (0.161 mi.)	R203	362
CON EDISON EPA Id: NYP004737441	253 MARION ST	NNW 1/8 - 1/4 (0.187 mi.)	AH242	441
CON EDISON SERVICE B EPA Id: NYP004520821	29 MCDOUGAL ST	WNW 1/8 - 1/4 (0.189 mi.)	AI249	454
CON EDISON - MANHOLE EPA Id: NYP004185351	***THOMAS S BOYLAND ST***	***NE 1/8 - 1/4 (0.195 mi.)***	***AJ256***	***473***
MTA NYCT - RALPH AVE EPA Id: NYR000156133	***302 RALPH AVE***	***W 1/8 - 1/4 (0.216 mi.)***	***AI297***	***596***
CON EDISON - MANHOLE EPA Id: NYP004734406	CHAUNCEY ST & SARATO	N 1/8 - 1/4 (0.228 mi.)	AK311	635
CON EDISON EPA Id: NYP004804811	375 CHAUNCEY ST	NNW 1/8 - 1/4 (0.235 mi.)	AO325	665
CON EDISON EPA Id: NYP004754073	215 MARION ST	NW 1/8 - 1/4 (0.236 mi.)	AS329	671
CON EDISON EPA Id: NYP004742177	138 SARATOGA AVE	N 1/8 - 1/4 (0.238 mi.)	AW332	676
CON EDISON EPA Id: NYP004881427	1885 ATLANTIC AVE	WSW 1/8 - 1/4 (0.241 mi.)	AV339	688

EXECUTIVE SUMMARY

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
W & M ESSO SERVICE S	1993 ATLANTIC AVE	SSE 0 - 1/8 (0.093 mi.)	K85	128


Lower Elevation	Address	Direction / Distance	Map ID	Page
PRESCOTT AUTMTC TRAN	2004 FULTON ST	WNW 0 - 1/8 (0.020 mi.)	A29	37

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name	Database(s)
ATLANTIC AVE. AND UTICA AVENUE (CR	NY INST CONTROL, NY VCP
SARATOGA AVE AND BERGEN STREET	NY SWF/LF
MARINE PARK	NY SWF/LF
UNION STATION (CITIZENS BRANCH)	NY VCP

OVERVIEW MAP - 7438000.2S




This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 2014 Fulton Street	CLIENT: Roux Associates
ADDRESS: 2014 Fulton Street Brooklyn NY 11233	CONTACT: Stephen Loonie
LAT/LONG: 40.678407 / 73.917617	INQUIRY #: 7438000.2s DATE: September 07, 2023 1:25 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7438000.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 2014 Fulton Street	CLIENT: Roux Associates
ADDRESS: 2014 Fulton Street Brooklyn NY 11233	CONTACT: Stephen Loonie
LAT/LONG: 40.678407 / 73.917617	INQUIRY #: 7438000.2s DATE: September 07, 2023 1:27 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		1	5	NR	NR	NR	6
RCRA-SQG	0.250		2	4	NR	NR	NR	6
RCRA-VSQG	0.250		0	3	NR	NR	NR	3
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	0	1	0	NR	1
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	1	0	NR	NR	1
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		3	6	24	NR	NR	33
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		1	6	NR	NR	NR	7
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	0	NR	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY AST	0.250		3	15	NR	NR	NR	18
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	2	NR	NR	2
NY INST CONTROL	0.500		0	0	2	NR	NR	2
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	3	6	NR	NR	9
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		0	2	1	NR	NR	3
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	1	0	NR	1
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125		22	NR	NR	NR	NR	22
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		35	75	NR	NR	NR	110
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	2	NR	NR	NR	2
NY E DESIGNATION	0.125	1	31	NR	NR	NR	NR	32
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY LEAD	0.001		0	NR	NR	NR	NR	0
NY MANIFEST	0.250		36	99	NR	NR	NR	135
PA MANIFEST	0.250		0	1	NR	NR	NR	1
NJ MANIFEST	0.250		14	28	NR	NR	NR	42
NY SPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	0.001		0	NR	NR	NR	NR	0
NY COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	0.001		0	NR	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0
NY RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		1	150	250	37	0	0	438

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target Property

LOT 19,TAXBLOCK 1549
2014 FULTON STREET
BROOKLYN, NY 11233

NY E DESIGNATION

S108984179
N/A

Site 1 of 34 in cluster A

Actual:
80 ft.

E DESIGNATION:

Name:	LOT 19,TAXBLOCK 1549
Address:	2014 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	19
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A2

< 1/8
1 ft.

LOT 20,TAXBLOCK 1549
2016 FULTON STREET
BROOKLYN, NY

NY E DESIGNATION

S108984180
N/A

Site 2 of 34 in cluster A

Relative:
Lower

Actual:
79 ft.

E DESIGNATION:

Name:	LOT 20,TAXBLOCK 1549
Address:	2016 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	20
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A3

< 1/8
1 ft.

LOT 23,TAXBLOCK 1549
2020A FULTON STREET
BROOKLYN, NY

NY E DESIGNATION

S108984187
N/A

Site 3 of 34 in cluster A

Relative:
Higher

Actual:
81 ft.

E DESIGNATION:

Name:	LOT 23,TAXBLOCK 1549
Address:	2020A FULTON STREET
City,State,Zip:	BROOKLYN, NY

LOT 23,TAXBLOCK 1549 (Continued) **S108984187**

Tax Lot(s):	23
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A4 **LOT 21,TAXBLOCK 1549** **NY E DESIGNATION** **S108984182**
2018 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 4 of 34 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 21,TAXBLOCK 1549
Address:	2018 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	21
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Actual:
80 ft.

A5 **LOT 25,TAXBLOCK 1549** **NY E DESIGNATION** **S108984194**
2024 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 5 of 34 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 25,TAXBLOCK 1549
Address:	2024 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	25
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK

Actual:
83 ft.

LOT 25,TAXBLOCK 1549 (Continued) **S108984194**

Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

A6 **LOT 31,TAXBLOCK 1549** **NY E DESIGNATION** **S108984227**
2036 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 6 of 34 in cluster A

Relative: E DESIGNATION:
Higher
Name: LOT 31,TAXBLOCK 1549
Actual: Address: 2036 FULTON STREET
83 ft. City,State,Zip: BROOKLYN, NY
Tax Lot(s): 31
Tax Block: 1549
Borough Code: Not reported
E-No: E-185
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 07DCP070K
Ulurp Number: 070447ZMK
Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

B7 **LOT 34,TAXBLOCK 1549** **NY E DESIGNATION** **S108984237**
2042 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 1 of 12 in cluster B

Relative: E DESIGNATION:
Higher
Name: LOT 34,TAXBLOCK 1549
Actual: Address: 2042 FULTON STREET
85 ft. City,State,Zip: BROOKLYN, NY
Tax Lot(s): 34
Tax Block: 1549
Borough Code: Not reported
E-No: E-185
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 07DCP070K
Ulurp Number: 070447ZMK
Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

B8 **LOT 33,TAXBLOCK 1549** **NY E DESIGNATION** **S108984234**
2040 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 2 of 12 in cluster B

Relative: E DESIGNATION:
Higher

Name:	LOT 33,TAXBLOCK 1549
Address:	2040 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	33
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Actual:
84 ft.

A9 **LOT 24,TAXBLOCK 1549** **NY E DESIGNATION** **S108984191**
2022 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 7 of 34 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 24,TAXBLOCK 1549
Address:	2022 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	24
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Actual:
82 ft.

A10 **LOT 28,TAXBLOCK 1549** **NY E DESIGNATION** **S108984207**
FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 8 of 34 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 28,TAXBLOCK 1549
Address:	FULTON STREET
City,State,Zip:	BROOKLYN, NY

Actual:
84 ft.

LOT 28,TAXBLOCK 1549 (Continued) **S108984207**

Tax Lot(s):	28
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A11 **LOT 18,TAXBLOCK 1549** **NY E DESIGNATION** **S108984177**
FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 9 of 34 in cluster A

Relative: **Lower**
Actual: **79 ft.**

E DESIGNATION:

Name:	LOT 18,TAXBLOCK 1549
Address:	FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	18
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A12 **LOT 30,TAXBLOCK 1549** **NY E DESIGNATION** **S108984221**
2034 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 10 of 34 in cluster A

Relative: **Higher**
Actual: **83 ft.**

E DESIGNATION:

Name:	LOT 30,TAXBLOCK 1549
Address:	2034 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	30
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK

LOT 30,TAXBLOCK 1549 (Continued) **S108984221**

Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

B13 **LOT 35,TAXBLOCK 1549** **NY E DESIGNATION** **S108984242**
224 SARATOGA AVENUE **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 3 of 12 in cluster B

Relative: E DESIGNATION:
Higher
Name: LOT 35,TAXBLOCK 1549
Actual: Address: 224 SARATOGA AVENUE
87 ft. City,State,Zip: BROOKLYN, NY
Tax Lot(s): 35
Tax Block: 1549
Borough Code: Not reported
E-No: E-185
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 07DCP070K
Ulurp Number: 070447ZMK
Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

A14 **LOT 22,TAXBLOCK 1549** **NY E DESIGNATION** **S108984185**
2020 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY 11233**
1 ft.

Site 11 of 34 in cluster A

Relative: E DESIGNATION:
Higher
Name: LOT 22,TAXBLOCK 1549
Actual: Address: 2020 FULTON STREET
81 ft. City,State,Zip: BROOKLYN, NY 11233
Tax Lot(s): 22
Tax Block: 1549
Borough Code: BK
E-No: E-185
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 07DCP070K
Ulurp Number: 070447ZMK
Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

B15 **LOT 32,TAXBLOCK 1549** **NY E DESIGNATION** **S108984229**
2038 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 4 of 12 in cluster B

Relative: E DESIGNATION:
Higher

Name:	LOT 32,TAXBLOCK 1549
Address:	2038 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	32
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Actual:
84 ft.

A16 **LOT 29,TAXBLOCK 1549** **NY E DESIGNATION** **S108984214**
FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 12 of 34 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 29,TAXBLOCK 1549
Address:	FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	29
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Actual:
84 ft.

A17 **LOT 26,TAXBLOCK 1549** **NY E DESIGNATION** **S108984198**
2026 FULTON STREET **N/A**
< 1/8 **BROOKLYN, NY 11233**
1 ft.

Site 13 of 34 in cluster A

Relative: E DESIGNATION:
Higher

Name:	LOT 26,TAXBLOCK 1549
Address:	2026 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233

Actual:
83 ft.

LOT 26,TAXBLOCK 1549 (Continued) **S108984198**

Tax Lot(s):	26
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

B18 **MTA NYCT - SARATOGA STREET SUBSTATION** **RCRA-SQG** **1014958386**
East **FULTON ST & SARATOGA AVE** **NY MANIFEST** **NYR000196386**
< 1/8 **BROOKLYN, NY 11233**
0.007 mi.
38 ft. **Site 5 of 12 in cluster B**

Relative: **Higher**
Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20120813
Handler Name:	Mta Nyct - Saratoga Street Substation
Handler Address:	FULTON ST & SARATOGA AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000196386
Contact Name:	GERALD LEZEAU
Contact Address:	BROADWAY 5TH FLOOR 503
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-3535
Contact Fax:	646-252-3509
Contact Email:	GERALD.LEZEAU@NYCT.COM
Contact Title:	ELECTRICAL ENGINEER 2
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 5TH FLOOR 503
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	Mta Nyct
Owner Type:	State
Operator Name:	Mta Nyct
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

MTA NYCT - SARATOGA STREET SUBSTATION (Continued) **1014958386**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 5TH FLOOR 503
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3535
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

MTA NYCT - SARATOGA STREET SUBSTATION (Continued) **1014958386**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20120813
Handler Name: MTA NYCT - SARATOGA STREET SUBSTATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: MTA NYCT - SARATOGA STREET SUBSTATION
Address: FULTON ST & SARATOGA AVE
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYR000196386
Facility Status: Not reported
Location Address 1: FULTON ST & SARATOGA AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000196386
Mailing Name: MTA NYCT - SARATOGA STREET SUBSTATION
Mailing Contact: MTA NYCT - SARATOGA STREET SUBSTATION
Mailing Address 1: 2 BROADWAY - D2.53
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004

MTA NYCT - SARATOGA STREET SUBSTATION (Continued) **1014958386**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2013
Trans1 Recv Date:	09/09/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196386
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010913646JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B19 **NYCTA ESSEX ST FIELD OFFICE** **NJ MANIFEST** **S111074859**
East **2046 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.008 mi.
41 ft. **Site 6 of 12 in cluster B**

Relative:
Higher

Actual:
83 ft.

NJ MANIFEST:

EPA Id:	NYR000102608
Mail Address:	370 JAY STREET
Mail City/State/Zip:	BROOKLYN 11201
Facility Phone:	7182435366
Emergency Phone:	Not reported
Contact:	THOMAS MURPHY
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001057477GBF
EPA ID:	NYR000102608
Date Shipped:	12/15/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/15/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

NYCTA ESSEX ST FIELD OFFICE (Continued) **S111074859**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	U151
Hand Code:	H141
Quantity:	30 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	25 G
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	50 P
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	70 P

Manifest Number:	006874351JJK
EPA ID:	NYR000102608
Date Shipped:	8/23/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

NYCTA ESSEX ST FIELD OFFICE (Continued) **S111074859**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	40.00 Pounds

Manifest Number:	008921448JJK
EPA ID:	NYR000102608
Date Shipped:	10/16/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

NYCTA ESSEX ST FIELD OFFICE (Continued) **S111074859**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	BROOKLYN 11201
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	80.00 Pounds
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	70.00 Pounds
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	90.00 Pounds

A20 **PRIVATE RESIDENCE** **NY Spills** **S102560530**
SE **1095 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
45 ft. **Site 14 of 34 in cluster A**

Relative: **Higher**
Actual: **87 ft.**

SPILLS:

Name:	PRIVATE RESIDENCE
Address:	1095 HERKIMER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9700115 / 2003-04-17
Facility ID:	9700115
Facility Type:	ER
DER Facility ID:	203680
Site ID:	248100
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-04-02
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1997-04-02
CID:	252
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

PRIVATE RESIDENCE (Continued) **S102560530**

Date Entered In Computer:	1997-04-02
Spill Record Last Update:	2003-04-17
Spiller Name:	DENISE ROBERTS
Spiller Company:	PRIVATE RESIDENCE
Spiller Address:	1095 HERKIMER ST
Spiller Company:	001
Contact Name:	DENISE ROBERTS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE REFER TO 9311226 & SP93511."
Remarks:	"CALLER STATES THAT BLDG NEXT TO THEM IS VACANT AND UP FOR AUCTION OIL BURNER LEAKING CAUSING SPILL ONTO BASEMENT FLOOR-THE FUMES ARE STRONG AND CALLER HAS SMALL CHILDREN-SHE WOULD LIKE A CALL BACK FROM A DEC REP**********"

All Materials:

Site ID:	248100
Operable Unit ID:	1046556
Operable Unit:	01
Material ID:	336729
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A21 **1093 HERKIMER ST.** **NY Spills** **S102147441**
SE **1093 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
46 ft. **Site 15 of 34 in cluster A**

Relative:
Higher

Actual:
86 ft.

SPILLS:

Name:	1093 HERKIMER ST.
Address:	1093 HERKIMER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9311226 / 2001-09-17
Facility ID:	9311226
Facility Type:	ER
DER Facility ID:	58232
Site ID:	59490
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1993-12-18
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1993-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons

1093 HERKIMER ST. (Continued) **S102147441**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-12-28
Spill Record Last Update:	2002-11-14
Spiller Name:	Not reported
Spiller Company:	NEIGHBOR-ARON WALKER
Spiller Address:	1095 HERKIMER ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TOMASELLO/ZITO 10/10/95: This is additional information about material spilled from the translation of the old spill file: ODOR. Spill transfered from Tang/Tibbe to Tomasello. 09/17/01: Cleanup mitigated and meets standards to close the spill."
Remarks:	"NEIGHBOR CONVERTED TO OIL ON 12/04/93 SINCE THEN, ODOR PERSIST, SPOKE TO ALEX ZITOMISKEY BEFORE. REFER TO ALEX & CHRIS IN THE FIELD OFFICE. OIL COMING THROUGH WALL FROM NEXT DOOR NEIGHBOR."

All Materials:

Site ID:	59490
Operable Unit ID:	993101
Operable Unit:	01
Material ID:	390270
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A22 **CON EDISON** **NY MANIFEST** **S116550701**
SE **1091 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.009 mi.
46 ft. **Site 16 of 34 in cluster A**

Relative:
Higher

Actual:
86 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	1091 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004491106
Facility Status:	Not reported
Location Address 1:	1091 HERKIMER ST
Code:	BP
Location Address 2:	SB22000
Total Tanks:	Not reported
Location City:	BROOKLYN

CON EDISON (Continued) **S116550701**

Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004491106
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/2014
Trans1 Recv Date:	04/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004491106
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407000GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S116550701**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A23 **CON EDISON SERVICE BOX: 22000** **RCRA NonGen / NLR** **1017772161**
SE **1091 HERKIMER ST** **NYP004491106**
< 1/8 **BROOKLYN, NY 11233**
0.009 mi.
46 ft. **Site 17 of 34 in cluster A**

Relative: **Higher**

Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:	20140507
Handler Name:	Con Edison Service Box: 22000
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004491106
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

CON EDISON SERVICE BOX: 22000 (Continued) **1017772161**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140407
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140407
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140507
Handler Name: CON EDISON SERVICE BOX: 22000	

CON EDISON SERVICE BOX: 22000 (Continued) **1017772161**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A24 **CON EDISON SERVICE BOX: 22001** **RCRA NonGen / NLR** **1016972198**
SE **1103 HERKIMER ST** **NY MANIFEST** **NYP004459616**
< 1/8 **BROOKLYN, NY 11233**
0.013 mi.
66 ft. **Site 18 of 34 in cluster A**

Relative: Higher
Actual: 89 ft.

RCRA Listings:

Date Form Received by Agency:	20140406
Handler Name:	Con Edison Service Box: 22001
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004459616
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No

CON EDISON SERVICE BOX: 22001 (Continued) **1016972198**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140306
Handler Name: CON EDISON SERVICE BOX:	22001
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140406
Handler Name: CON EDISON SERVICE BOX:	22001

CON EDISON SERVICE BOX: 22001 (Continued) **1016972198**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	1103 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004459616
Facility Status:	Not reported
Location Address 1:	1103 HERKIMER ST
Code:	BP
Location Address 2:	SB22001
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004459616
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON SERVICE BOX: 22001 (Continued) **1016972198**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2014
Trans1 Recv Date:	03/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004459616
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360385GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B25 **MULTI FAMILY** **NY Spills** **S110243502**
ESE **1115 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.013 mi.
67 ft. **Site 7 of 12 in cluster B**

Relative: **Higher**

Actual: **90 ft.**

SPILLS:

Name:	MULTI FAMILY
Address:	1115 HERKIMER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0913454 / 2011-12-09
Facility ID:	0913454
Facility Type:	ER

MULTI FAMILY (Continued) **S110243502**

DER Facility ID:	375277
Site ID:	426398
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-03-21
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2010-03-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-21
Spill Record Last Update:	2011-12-09
Spiller Name:	PERNON DUNSTON
Spiller Company:	UNKNOWN
Spiller Address:	1115 HERKIMER ST
Spiller Company:	999
Contact Name:	PERNON DUNSTON
DEC Memo:	"03/21/10- Zhune spoke to Pernon Dunston Owner 516-315-3197. He could not give much information out of town. Spoke to Petro. Said they have a AST 275 gallons. The fill line was leaking. Fill line was replaced. Fill line is underground on concrete cemented. Aproximately 5 gallons on concrete. Petro put speedy-dry. Owner has to remove it. No vapors in the house. Only little in the basement. 12/09/11- Zhune visited the site. The owner converted the heating system to gas. As per owner a contractor removed the above ground fill line and no contamination was found. Spill closed "
Remarks:	"Caller reporting a spill of unknown quantities of an unknown oil (he belives regular household heating oil) to basement floor. Caller states Petro is on scene to do clean up."

All Materials:

Site ID:	426398
Operable Unit ID:	1182080
Operable Unit:	01
Material ID:	2176233
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

A26
West
< 1/8
0.014 mi.
75 ft.

2006 A FULTON STREET
2006 A FULTON STREET
BROOKLYN, NY

Site 19 of 34 in cluster A

NY LTANKS **S107789119**
N/A

Relative:
Lower

Actual:
78 ft.

LTANKS:

Name:	2006 A FULTON STREET
Address:	2006 A FULTON STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0600324 / 2006-05-17
Facility ID:	0600324
Site ID:	362303
Spill Date:	2006-04-10
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2006-04-10
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-10
Spill Record Last Update:	2006-05-19
Spiller Name:	MR RUDOLPHSKI
Spiller Company:	Not reported
Spiller Address:	2006 A FULTON STREET
Spiller County:	001
Spiller Contact:	MR RUDOLPHSKI
Spiller Phone:	(718) 703-2700
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	312548
DEC Memo:	"Find owner & send CSL 4/18/06 - Raphael Ketani. I finally found the owner of the property. It is: LPL Properties, Inc., 249 Empire Blvd., Brklyn, NY, 11225 ((718) 703-2700; cell (718) 504-7124). I spoke to Jonas Rudofsky at this phone number, but he said this number is not LPL, just him. He said he is the prospective buyer of the property and owns the property next door. He said he will get me the address and phone number of the actual owner. 4/20/06 - Raphael Ketani. Ted Yen (cell 917-584-6299) of Ted Yen Associates called today. He said that his company is involved in the cleanup at the site and work is in progress. He said that Eastmond & Sons pumped out 1,000 gals. of mostly water with a little oil from the tank. Then they lifted the tank and the bottom didn't come with it. So they dug up 55 drums of oil soaked soil and debris. He said he represents the tank removal contractor. Mr. Yen added that they took clean end point samples and all of the information will be sent to me in a report. He said that Mr. Rudofsky is the owner of LPL Properties. I will send Mr. Rudofsky a CSL today. 5/17/06 - Raphael Ketani. I reviewed the 5/10/06 Tank Closure and Remediation Report produced by Don Carlo Environmental

2006 A FULTON STREET (Continued) **S107789119**

Services, Inc. I found the analytical results and the report to be acceptable. I will send a letter to the owners of the property stating that the report is acceptable and that the case has been closed. Based upon this report, I am closing the case."

Remarks: "WHILE EXCAVATING FOUND OIL IN GROUND;"

All Materials:

Site ID:	362303
Operable Unit ID:	1120405
Operable Unit:	01
Material ID:	2109902
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A27 **2006A FULTON STREET** **NY UST** **U004045159**
WNW **2006A FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.018 mi.
96 ft. **Site 20 of 34 in cluster A**

Relative: **Lower**

Actual: **77 ft.**

UST:

Name:	2006A FULTON STREET
Address:	2006A FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-610189 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	591459.07224
UTM Y:	4503643.62509
Site Type:	Other

Affiliation Records:

Site Id:	363123
Affiliation Type:	Facility Owner
Company Name:	LPL PROPERTIES INC
Contact Type:	VICE PRESIDENT
Contact Name:	LEONARD PICCOLO
Address1:	2006A FULTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 703-2700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-04-26

2006A FULTON STREET (Continued) **U004045159**

Site Id:	363123
Affiliation Type:	Mail Contact
Company Name:	MISHTY MAP
Contact Type:	Not reported
Contact Name:	JONAS RUDOFSKY
Address1:	249 EMPIRE BLVD.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11225
Country Code:	001
Phone:	(718) 703-2700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-04-27

Site Id:	363123
Affiliation Type:	Facility Operator
Company Name:	2006A FULTON STREET
Contact Type:	Not reported
Contact Name:	JONAS RUDOFSKY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 703-2700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-04-26

Site Id:	363123
Affiliation Type:	Emergency Contact
Company Name:	LPL PROPERTIES INC
Contact Type:	Not reported
Contact Name:	JONAS RUDOFSKY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 288-6122
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-04-26

Tank Info:

Tank Number:	1
Tank ID:	211383
Tank Status:	Closed - Removed
Material Name:	Closed - Removed

2006A FULTON STREET (Continued) **U004045159**

Capacity Gallons:	1500
Install Date:	04/15/2006
Date Tank Closed:	04/15/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0012
Common Name of Substance:	Kerosene [#1 Fuel Oil] (On-Site Consumption)
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

A28 **LOT 13,TAXBLOCK 1549** **NY E DESIGNATION** **S108984163**
WNW **2006A FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.018 mi.
96 ft. **Site 21 of 34 in cluster A**

Relative:
Lower

Actual:
77 ft.

E DESIGNATION:

Name:	LOT 13,TAXBLOCK 1549
Address:	2006A FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	13
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A29 **PRESCOTT AUTMTC TRANSMISSIONS** **EDR Hist Auto** **1022015968**
WNW **2004 FULTON ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.020 mi.
108 ft. **Site 22 of 34 in cluster A**

Relative: EDR Hist Auto
Lower

Actual: **77 ft.**

Year:	Name:	Type:
1991	PRESCOTT AUTMTC TRANSMISSIONS	Automotive Transmission Repair Shops
1992	PRESCOTT AUTMTC TRANSMISSIONS	Automotive Transmission Repair Shops
1993	PRESCOTT AUTMTC TRANSMISSIONS	Automotive Transmission Repair Shops
1994	PRESCOTT AUTMTC TRANSMISSIONS	Automotive Transmission Repair Shops

---

A30 **LOT 12,TAXBLOCK 1549** **NY E DESIGNATION** **S108984156**
WNW **2004 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.020 mi.
108 ft. **Site 23 of 34 in cluster A**

Relative: E DESIGNATION:
Lower

Actual: **77 ft.**

Name:	LOT 12,TAXBLOCK 1549
Address:	2004 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	12
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A31 **CON EDISON** **NY MANIFEST** **S117741380**
WSW **1063 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.023 mi.
122 ft. **Site 24 of 34 in cluster A**

Relative: NY MANIFEST:
Higher

Actual: **81 ft.**

Name:	CON EDISON
Address:	1063 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004746053
Facility Status:	Not reported
Location Address 1:	1063 HERKIMER ST
Code:	BP
Location Address 2:	SB20994
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233

CON EDISON (Continued) **S117741380**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004746053
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 03/08/2015
Trans1 Recv Date: 03/08/2015
Trans2 Recv Date: 03/09/2015
TSD Site Recv Date: 03/09/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004746053
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002610962GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1000
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117741380**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A32 **CON EDISON** **RCRA NonGen / NLR** **1018279759**
WSW **1063 HERKIMER ST** **FINDS** **NYP004746053**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.023 mi.
122 ft. **Site 25 of 34 in cluster A**

Relative: **Higher**
Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20150308
Handler Name:	Con Edison
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004746053
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON (Continued) **1018279759**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150308
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150308
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1018279759**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067695532

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279759
Registry ID:	110067695532
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067695532
Name:	CON EDISON
Address:	1063 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233

A33 **CON EDISON** **NJ MANIFEST** **S120668557**
WSW **1063 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.023 mi.
122 ft. **Site 26 of 34 in cluster A**

Relative: Higher
Actual: 81 ft.

NJ MANIFEST:

EPA Id:	NYP004746053
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610962GBF
EPA ID:	NYP004746053

CON EDISON (Continued) **S120668557**

Date Shipped:	3/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

B34 **VAULT # 3800** **NY Spills** **S107408762**
ESE **HERKIMER ST NEAR SARATOGA AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.025 mi.
131 ft. **Site 8 of 12 in cluster B**

Relative:
Higher

Actual:
91 ft.

SPILLS:

Name:	VAULT # 3800
Address:	HERKIMER ST NEAR SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0506914 / 2005-10-26
Facility ID:	0506914
Facility Type:	ER
DER Facility ID:	299513
Site ID:	352214
DEC Region:	2
Spill Cause:	Unknown

VAULT # 3800 (Continued) **S107408762**

Spill Class:	C4
SWIS:	2401
Spill Date:	2005-09-06
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-09-07
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-07
Spill Record Last Update:	2005-10-26
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	HERKIMER ST /SARATOGA AVE
Spiller Company:	999
Contact Name:	ERT DESK'
DEC Memo:	"160901. 06-SEP-2005 1955HRS. DISTRIBUTION A MECHANIC CRAIG MURDAUGH, EMPLOYEE NO 18627. WHILE ON LOCATION TO PERFOM NWP WORK, ON ACCT NO. C3482, IN VS3800, LOCATED ON THE N/S OF HERKIMER ST, 236' E/O SARATOGA AVENUE, REPORTS FINDING APPX 10 OZ OF DIELECTRIC FLUID ON SOIL IN THE STRUCTURE. NO FIRE OR SMOKE INVOLVED, NO INJURIES RELATED TO THE SPILL, NO SEWERS, WATERWAYS OR PRIVATE PROPERTY AFFECTED. SPILL APPEARS TO BE CONTAINED TO THE STRUCTURE. MR. MURDAUGH REPORTS THE SPILL APPEARS TO BE LEAKING FOM THE THROAT OF THE UNIT ONTO THE NEUTRAL, INTO THE STRUCTURE. THERE IS NO WATER, NOR CAN HE VERIFY THE EXISTENCE OF ANY SEWER CONNECTIONS OR SUMPS IN THE STRUCTURE AT THIS TIME. A SOIL SAMPLE WAS TAKEN, AND ENVIORONMENTAL STOP TAG NO. 45439 WAS PLACED IN THE STRUCTURE. THIS SAMPLE WILL BE TRANSPORTED TO ASTORIA LAB FOR ANALYSIS BY SUPV. BRENSEKE, ON CC NO. EE20979. UNIT IS SLATED TO BE TAKEN OFF-CATAGORY 2, AT WHICH TIME THEY WILL SAMPLE THE UNT. SUPV. BRENSEKE WILL KEEP THIS DESK INFORMED OF FURTHER PROGRESS. UPDATE 06-SEP-2005 2010HRS. Lab Seq Serial Number No E450611 11/29/2004 11/30/2004 11/30/2004 5 04-09910-006. Analysis indicates the presence of a substance similar to a dielectric fluid. UPDATE 07-SEP-2005 12:26 HRS. LSN-05-09344-001 MATRIX : OIL GRAB. 1 PPM UPDATE: 9/7/05 - 1320. AS PER R. COSENTINO OF E,H & S, WE ARE NOT TO USE THE RESULTS POSTED ABOVE TO CLEAN THIS STRUCTURE. A LIQUID SAMPLE MUST BE TAKEN FROM THE UNIT. TJ - 50495 UPDATE: 9/7/05 - 1400. AS PER SHIFT MANAGER KEN SUDOL, FDR 3B96 (WHICH THIS UNIT IS ON) WILL NOT BE TAKEN OFF IN THE NEAR FUTURE TO SAMPLE & REPLACE THIS UNIT. THIS INCIDENT, THERFORE, IS NOW

VAULT # 3800 (Continued) **S107408762**

OFF THE 72 HR CLOCK. TJ - 50495 UPDATE: 9/7/05 - 1410. AS PER CONVERSATION BTWN DENNIS HEARNS - OGS
- ENV. OPS, & SEAN MCKEEVER - O.S. - BQE, A SAMPLE WILL BE TAKEN FROM THE UNIT WHEN THE FDR IS
TAKEN OFF THE SYSTEM. THERE IS NO MAGNETIC OIL GAUGE ON THE UNIT. TJ - 50495. Closed. 10-26-05. see
eDocs. GB "

Remarks: "COMING OFF 24 HOUR CLOCK: NEED TO DEENERGIZE UNIT: CONED # 160901"

All Materials:

Site ID:	352214
Operable Unit ID:	1109724
Operable Unit:	01
Material ID:	2099742
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B35 **CONSOLIDATED EDISON** **NY MANIFEST** **1009240150**
ESE **HERKIMER ST & SARATOGA** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.025 mi.
134 ft. **Site 9 of 12 in cluster B**

Relative: **Higher**

Actual: **91 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	HERKIMER ST & SARATOGA
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004069993
Facility Status:	Not reported
Location Address 1:	HERKIMER ST & SARATOGA
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004069993
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

B36 **VAULT VS 3704** **NY Spills** **S106736632**
ESE **SARTOGA AVE AND HERKIMER** **N/A**
< 1/8 **BROOKLYN, NY**
0.026 mi.
135 ft. **Site 10 of 12 in cluster B**

Relative: **Higher**

Actual: **91 ft.**

SPILLS:

Name:	VAULT VS 3704
Address:	SARTOGA AVE AND HERKIMER
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0410920 / 2005-06-03
Facility ID:	0410920
Facility Type:	ER
DER Facility ID:	271328
Site ID:	336005
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-01-06
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2005-01-06
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-07
Spill Record Last Update:	2005-06-03
Spiller Name:	ERT DESK
Spiller Company:	VAULT VS 3704
Spiller Address:	SARTOGA AVE AND HERKIMER
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis 156795 1/6/05 - 1505 A. DELEON - 15756 - BQE, REPORTS FINDING APPROX 5 GALS OF DIEL FLUID MIXED WITH APPROX 4 OF SOIL ON THE CONCRETE FLOOR OF VS3704 (3B83). UNIT IS BELOW MIN. HISTORICAL PCB COUNT IS 1 PPM DTD 7/20/01. TRANSFORMER HAS BEEN CONDEMNED. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES. NO PRIVATE PROPERTY AFFECTED. NO SEWER CONNECTIONS. CANNOT VERIFY THE EXISTENCE OF ANY SUMPS. TAG # 45361 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. CLEANUP PENDING LAB RESULT AND FDR OUTAGE. UPDATE 06-JAN-2005 1900 HRS CHEM LAB TECHNICIAN SANTOS CONTACTED THE C/C. HE CAN EXTRACT AN OIL SAMPLE FROM THE SOIL, HOWEVER, THERE WILL BE A SMALL AMOUNT OF ADDED TIME TO DO SO. E. VESCE, ENVIRONMENTAL OPS SUPV. WAS NOTIFIED. UPDATE 06-JAN-2005 BROOKLYN EQUIP GROUP SUPV THERESA HAERING REPORTS. UNIT DEENERGIZED, FAILED PRESSURE TEST. UNIT DIPPED, APPX 5-8 GALS BELOW MIN. REQUESTING TANKER FOR AM

VAULT VS 3704 (Continued) **S106736632**

DRAINING OF THE UNIT.PENDING
TEST RESULTS. SHE HAS ALSO NOTIFIED SHIFT MANAGER B. FRIER. Lab Sequence Number: 05-00158-001 TOTAL
PCB 15 ppm 1/07/2005 19:35 -- R. VEGA OF BROOKLYN ENV OPS REPORTS THAT HE & D. CARSON DOUBLE WASHED
STRUCTURE WITH BIOGEN 760. SUMP WAS FOUND ALREADY CEMENTED. ENV STOP TAG REMAINS IN PLACE PENDING
TRANSFORMER REMOVAL AND FINAL CLEANUP. 1/07/2005 23:05 HRS. -- G. HICKEY #06547, SPLICER WITH
EQUIPMENT GROUP, REPORTS TANKER REMOVED APPROX. 270 GAL. OF OIL FROM THE TRANSFORMER. PLATE ON
TRANSFORMER INDICATES OIL CAPACITY IS 370 GAL, THEREFORE APPROX. 100 GAL. OF OIL IS UNACCOUNTED FOR
. 23:13 HRS. -- NOTIFIED BROOKLYN ENV OPS O/S B. BAMONTE WHO REPORTS ENV OPS CREW HAS COMPLETED
INITIAL CLEANUP AND THERE IS NOTHING MORE THEY CAN DO UNTIL THE TRANSFORMER IS REMOVED. 23:18 HRS.
-- DID NOT NOTIFY BROOKLYN/QUEENS EH&S SINCE AS OF 8/23/04 THEY NO LONGER RESPOND TO SPILLS OVER 10
GAL IN UNDERGROUND STRUCTURES UNLESS NOT CONTAINED, SEWERS/WATERWAYS AFFECTED, OR FIRE INVOLVED (AS
PER EMAIL FROM EH&S MANAGER K. BAROUCH). 23:26 HRS. -- NOTIFIED R. ELLIOT OF C.I.G. (DUE TO
ORIGINAL SPILL AMOUNT REPORTED AS 5 GAL OIL AND NOW HAVING AN ADDITIONAL 95 GAL OIL UNACCOUNTED FOR
). 23:33 HRS. -- AS PER M. EVERS OF E.R.T., THIS LOCATION DOES NOT NEED TO BE MANNED AND C.I.G.
WILL LET AGENCIES KNOW THE TRANSFORMER WAS DRAINED, THE STRUCTURE WAS DOUBLE-WASHED, THE SUMP WAS
FOUND CEMENTED, AND FINAL CLEANUP TO BE DONE AFTER TRANSFORMER IS REMOVED.. 1/08/2005 00:55 HRS. --
RECEIVED CALL FROM ERT M.EVERS WHO REPORTS THAT K.LEITCH OF N.Y.C. D.E.P. WAS ON LOCATION AND ASKED
WHEN TRANSFORMER WILL BE REMOVED. AS PER FEEDER CONTROL REP. C.MONTANA, TRANSFORMER IS SCHEDULED TO
BE REMOVED ON MONDAY 1/10/2005. I NOTIFIED M.EVERS AND SHE REPORTED THAT ERT WOULD NOT BE
RESPONDING TO LOCATION 1/17/05 1530HRS S.RAFT ENVIR OPPD REPORTS CLEANUP COMPLETED DOULBED WASHED
STRUCTURE USING BIO-GEN 760 .FOUND SUMP SEALED .REMOVED ENVIR TAG#45361. NETWORKS REMOVED
TRANSFOMER."

Remarks: "TRANSFORMER IS CONTAINED. LAB RESULTS PENDING CLEAN UP."

All Materials:

Site ID:	336005
Operable Unit ID:	1098053
Operable Unit:	01
Material ID:	578243
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B37 **VAULT 3295** **NY Spills** **S106008805**
ESE **HERKIMER ST/SARATOGA AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.026 mi.
135 ft. **Site 11 of 12 in cluster B**

Relative: **Higher**
Actual: **91 ft.**

SPILLS:

Name:	VAULT 3295
Address:	HERKIMER ST/SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0207788 / 2003-02-10
Facility ID:	0207788
Facility Type:	ER
DER Facility ID:	187225
Site ID:	226839
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-10-28
Investigator:	AERODRIG
Referred To:	Not reported
Reported to Dept:	2002-10-28
CID:	396
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-28
Spill Record Last Update:	2003-02-10
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	SEAN MCKEEVER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RODRIGUEZ RECEIVED UPDATE SPILL REPORT AT 10.45 HRS. THE AMOUNT OF SPILL MATERIAL WAS INCREASED FROM 2 GALS. TO 20 GALS. E.R. E2MIS NOTES 145780 10-28-02 0905 HRS N. FRUSTACI # 14757 MECH A NETWORK REPORTS WHILE MAKING INSPECTION IN VS3295 S/S HERKIMER ST 24' W/O SARATOGA AVE (FDR 3B93) HE FOUND APPROX 2 GALLONS DIELECTRIC FLUID ON DIRT NO WATER THAT HE VISUALLY SEE OIL STAIN MARKS WERE THE OIL LEAKED FROM. UNIT IS ALSO BELOW MIN. HE PRESSURE TESTED UNIT , FAIL TEST (DID NOT HOLD PRESSURE) HISTORICAL RECORD OF TRANSF IS 17 PPM AND WAS LAST TESTED 10-15-92 . THERE WAS NO FIRE OR SMOKE AT THIS LOCATION. NO PRIVATE PROPERTY AFFECTED. NO INJURIES. HE DOES NOT SEE A SEWER CONNECTION OR SUMP AT THIS TIME. LIQUID SEEMS CONTAINED NO SEWERS OR WATERWAYS AFFECTED. ONLY OIL FILLED EQUIPMENT IN STRUCTURE IS TRANSF, HE WAS UNABLE TO TAKE A SAMPLE AT THIS TIME DUE TO UNIT BEING BELOW

VAULT 3295 (Continued) **S106008805**

MIN. SUPV GOING TO LOCATION TO
REQUEST FDR OOE. THEY WILL THEN TAKE A SAMPLE AND REQUEST EMERG PRIORITY FOR PCB SAMPLE RESULT.
CLEANUP PENDING SAMPLE RESULT AND THE SAFETY OF THE STRUCTURE AT THIS TIME. CHAIN OF CUSTODY #
CC05306. HE PLACED E.S.TAG # 30062. THIS WILL NOT GO ON THE 24 HRS DEMINIMIS PROGRAM DUE TO THE
LEAKING TRANSF STILL BE ON LINE (FDR IN SERV) NO PARKING TUES & THURSDAY 0800 HRS TO 1100 HRS CIG
S. MCKEEVER NOTIFIED 1002 HRS UPDATE 10-28-02 1020 HRS FDR,3B93 CUT OUT ON EMERG PRIORITY # 1. ALSO
OS NETWORK G . PALADINO MADE ANOTHER INSPECTION AND FOUND APPROX 20 GALLONS OIL LEAKED. NOTIFIED
CIG MURPHY 1025 HRS AND ENVIR REP R. UPDATE 10-28-02 1025 HRS ENGINEERING PLATES SHOW A SUMP IN
STRUCTURE ORDERED OVER 50 PPM TANKER AND EPA # NYP004104071 ALSO DISPATCHED FLUSH CREW AND SPILL
VAN TO LOCATION LAZ # 04425"

Remarks: "2 quart spill due to a problem w a transformer. ref #145780."

All Materials:

Site ID:	226839
Operable Unit ID:	859374
Operable Unit:	01
Material ID:	514797
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B38 **MANHOLE 14355** **NY Spills** **S104881305**
ENE **HULL ST / SARATOGA AV** **N/A**
< 1/8 **BROOKLYN, NY**
0.028 mi.
149 ft. **Site 12 of 12 in cluster B**

Relative: **Lower**
Actual: **77 ft.**

SPILLS:

Name:	MANHOLE 14355
Address:	HULL ST / SARATOGA AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0010761 / 2001-04-19
Facility ID:	0010761
Facility Type:	ER
DER Facility ID:	192458
Site ID:	233586
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-12-28
Investigator:	OKWUOHA
Referred To:	Not reported

MANHOLE 14355 (Continued) **S104881305**

Reported to Dept:	2000-12-28
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-28
Spill Record Last Update:	2001-06-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"1 PINT UNK OIL IN MANHOLE - CONTAINED - CASE #134908"

All Materials:

Site ID:	233586
Operable Unit ID:	831900
Operable Unit:	01
Material ID:	544648
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A39 **LENNY GOODWIN RESIDENCE** **NY Spills** **S111319129**
North **17 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.030 mi.
156 ft. **Site 27 of 34 in cluster A**

Relative: **Lower**
Actual: **73 ft.**

SPILLS:

Name:	LENNY GOODWIN RESIDENCE
Address:	17 HULL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1110327 / 2012-06-18
Facility ID:	1110327
Facility Type:	ER
DER Facility ID:	412630
Site ID:	458140
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-11-20
Investigator:	SFRAHMAN

LENNY GOODWIN RESIDENCE (Continued) **S111319129**

Referred To:	Not reported
Reported to Dept:	2011-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-11-20
Spill Record Last Update:	2012-06-18
Spiller Name:	LENNY GOODWIN RESIDENCE
Spiller Company:	LENNY GOODWIN RESIDENCE
Spiller Address:	17 HOULL ST
Spiller Company:	999
Contact Name:	LENNY GOODWIN RESIDENCE
DEC Memo:	"Spoke with Petro-Tony.Tank sitting on rocks.Evidence of spill on the dirt.Petro suspended delivering. Need to send letter.(sr) ** Letter was sent out to Spiritual Israel Church and Its Army 17 Hull Street Brooklyn, NY 11233-2605 Attn: Elder C. Goodwin 05/16/12 Roy Singh,917-226-2873 performed tank removal.(sr)"
Remarks:	"onto soil in basement, c/u pending"

All Materials:

Site ID:	458140
Operable Unit ID:	1208249
Operable Unit:	01
Material ID:	2205582
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

A40 **H.P.D. HOUSING** **NY Spills** **S102446810**
NNE **21 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
164 ft. **Site 28 of 34 in cluster A**

Relative: SPILLS:
Lower

Name:	H.P.D. HOUSING
Address:	21 HULL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9611846 / 1996-12-31
Facility ID:	9611846
Facility Type:	ER
DER Facility ID:	115668

Actual:
74 ft.

H.P.D. HOUSING (Continued) **S102446810**

Site ID:	134622
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-12-31
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1996-12-31
CID:	297
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-31
Spill Record Last Update:	1997-04-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BOB DECK
DEC Memo:	""
Remarks:	"CALLERS COMPANY HIRED TO CLEAN UP AN HISTORICAL SPILL AT THE ABOVE LOCATION - ALL MATERIALS HAVE BEEN DRUMMED FOR DISPOSAL"

All Materials:

Site ID:	134622
Operable Unit ID:	1043185
Operable Unit:	01
Material ID:	556392
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A41 **CON EDISON** **RCRA NonGen / NLR** **1018279760**
SW **HERKIMER ST & DEWEY PL** **FINDS** **NYP004746061**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.034 mi.
179 ft. **Site 29 of 34 in cluster A**

Relative: **Higher**
Actual: **83 ft.**

RCRA Listings:

Date Form Received by Agency:	20150308
Handler Name:	Con Edison
Handler Address:	HERKIMER ST & DEWEY PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004746061

CON EDISON (Continued) **1018279760**

Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON (Continued) **1018279760**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150308
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150308
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067695541

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters,

CON EDISON (Continued) **1018279760**

storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279760
Registry ID:	110067695541
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067695541
Name:	CON EDISON
Address:	HERKIMER ST & DEWEY PL
City,State,Zip:	BROOKLYN, NY 11233

A42 **CON EDISON** **NY MANIFEST** **S117741381**
SW **HERKIMER ST & DEWEY PL** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.034 mi.
179 ft. **Site 30 of 34 in cluster A**

Relative:
Higher

Actual:
83 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	HERKIMER ST & DEWEY PL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004746061
Facility Status:	Not reported
Location Address 1:	SWC HERKIMER ST
Code:	BP
Location Address 2:	SB 20999
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004746061
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/08/2015
Trans1 Recv Date:	03/08/2015
Trans2 Recv Date:	Not reported

CON EDISON (Continued) **S117741381**

TSD Site Recv Date:	03/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004746061
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610963GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A43 **CON EDISON** **NJ MANIFEST** **S120668558**
SW **HERKIMER ST & DEWEY PL** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.034 mi.
179 ft. **Site 31 of 34 in cluster A**

Relative:
Higher

Actual:
83 ft.

NJ MANIFEST:

EPA Id:	NYP004746061
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON (Continued) **S120668558**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610963GBF
EPA ID:	NYP004746061
Date Shipped:	3/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

A44 **1064 HERKIMER STREET** **NY LTANKS** **S102671481**
SSW **1064 HERKIMER STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.035 mi.
187 ft. **Site 32 of 34 in cluster A**

Relative:
Higher

Actual:
86 ft.

LTANKS:

Name:	1064 HERKIMER STREET
Address:	1064 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8910306 / 2003-07-29
Facility ID:	8910306
Site ID:	221931
Spill Date:	1990-01-26
Spill Cause:	Tank Overfill
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1990-01-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-01-31
Spill Record Last Update:	2003-07-29
Spiller Name:	Not reported
Spiller Company:	1064 HERKIMER STREET
Spiller Address:	1064 HERKIMER STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	183556
DEC Memo:	""
Remarks:	"NYCFD HAZ MAT & NYCFD ON SCENE, BROKEN PIPE ON OIL TANK, LEAK INTO DRAIN, POSSIBLE VANDALISM."

All Materials:

Site ID:	221931
Operable Unit ID:	937324
Operable Unit:	01
Material ID:	443411
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A45
West
< 1/8
0.040 mi.
209 ft.

LOT 7,TAXBLOCK 1549
FULTON STREET
BROOKLYN, NY 11233

Site 33 of 34 in cluster A

NY E DESIGNATION **S108984339**
N/A

Relative:
Lower

Actual:
76 ft.

E DESIGNATION:

Name:	LOT 7,TAXBLOCK 1549
Address:	FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	7
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

C46
South
< 1/8
0.040 mi.
212 ft.

1088 HERKIMER STREET
BROOKLYN, NY 11233

Site 1 of 6 in cluster C

NY LTANKS **S123663784**
NY LEAD **N/A**

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	HOME
Address:	1088 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1811489 / 2021-02-12
Facility ID:	1811489
Site ID:	582432
Spill Date:	2019-02-15
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HSSEKHON
Referred To:	Not reported
Reported to Dept:	2019-02-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2019-02-15
Spill Record Last Update:	2021-02-12
Spiller Name:	Not reported
Spiller Company:	PROPERTY OWNER
Spiller Address:	1088 HERKIMER STREET
Spiller County:	999

(Continued) **S123663784**

Spiller Contact:	FRANK CASTELLANO
Spiller Phone:	(631) 482-1818
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	534921
DEC Memo:	"02/15/19-Hiralkumar Patel. alternate address: 2 Louis Place no PBS or other spills found. 12:30 PM:- spoke with John at AARCO. he mentioned that a 550 gal UST beneath the basement floor was tested as part of property transaction. the tank failed in a dry portion. currently, the tank has approx. 300 gal of oil in it. 12:32 PM:- spoke with Frank at Castleton Env. Frank mentioned that prior to property transfer, buyer's bank asked for Phase II investigation. so tank system test was conducted as part of bank's phase II requirement. next week, they will conduct a tank only test after removing personal items belong to a tenant living in the basement. asked Frank to provide property owner's contact info. 1:04 PM:- received email from Frank including property owner's contact info. Herkimer Holding Corp. **property owner** c/o Thomas Roberts / Dorian Campbell Roberts 1350 North Street Elmont, NY 11003 Ph. (516) 872-1281 **# from last DOB permit** 1:13 PM:- sent TTF letter to Mr./Ms. Roberts. letter emailed to Frank. case assigned to DEC Sekhon. 3/5 - Sekhon frankc@castletonenv.com - email send to Frank to get updates. 4/4 /19 - Sekhon VM left at above ph. number to get updates. Cell number for Mr. Roberts is 917.324.5609 dori50@aol.com 4/8/19 - Sekhon 3:30 pm -DEC Sekhon met Mr. Robert on site. Dry portion failed 550 gal UST beneath the basement floor was out of order. RP getting quotes from different companies to close this tank. They installed new tank for home heating purpose. Tank area observed to be clean, free from any stains. Mr. Robert advised to update DEC as soon he hires contractor to close leaked tank. 5/8 - Sekhon On 5/7 @ 330pm, site inspected, tank closed in place, and property owner asked to submit report & paperwork associated with this spill. TTF report DECDOCs. 6/10/19 - Sekhon Work done to date - *excavate dirt to reach top of tank * cut open top of tank * Pump out any clean #2 oil from 1080 gal oil tank and dispose of in accordance with the applicable city, state and federal requirements to a facility certified to accept it. * remove all sludge waste from the tank and dispose of in accordance with the applicable city, state and federal requirements to a facility certified to accept it. * Clean & render tank free of any combustion vapors. * Fill tank with sand and replace top of tank that was cut open. * Backfill dirt that was excavated and bring to grade * Cut out and remove from property the oil tank fill and vent pipes. On 6/7/19, Dept. received a invoice with work done description from property owner, same discussed with DEC Kumar, RP asked to submit soil sample results taken from side/ bottom of tank and investigate the fill line. DECDOCs 11/1/19 - Sekhon On 9/23/19- request send to RP to submit sample results and closure report. 2/6/20 - Sekhon dori50@aol.com- Robert JessicaF@castletonenv.com - Jessica Ferngren frankc@castletonenv.com - Frank Castellano email send to above persons to submit required documentation. 3/5/20 - Sekhon Got VM from El Gulam (Soil mechanics - 516-2217500), he was contacted by RP to get his services to close this case, 2/3/21 - Sekhon Closure report received for departmental review. DECDOCS. 2/12/21 - Sekhon Submitted report reviewed & acceptable. Case closed."
	Not reported
Remarks:	"550 gal ust"

(Continued) **S123663784**

All Materials:

Site ID:	582432
Operable Unit ID:	1330113
Operable Unit:	01
Material ID:	2339259
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	1088 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	12337668
Building ID:	311145
Registration ID:	329295
Apartment:	2R
Story:	2
Class:	Most Serious
Inspection Date:	04/15/2018
Approved Date:	04/15/2018
Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6066023
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE KITCHEN LOCATED AT APT 2R, 2nd STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	04/16/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	07/10/2018

Name:	Not reported
Address:	1088 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	12337669
Building ID:	311145
Registration ID:	329295
Apartment:	2R
Story:	2
Class:	Most Serious
Inspection Date:	04/15/2018
Approved Date:	04/15/2018

(Continued) **S123663784**

Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6066023
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE 3rd ROOM FROM NORTH AT WEST LOCATED AT APT 2R, 2nd STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	04/16/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	07/10/2018
Name:	Not reported
Address:	1088 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	12337670
Building ID:	311145
Registration ID:	329295
Apartment:	2R
Story:	2
Class:	Most Serious
Inspection Date:	04/15/2018
Approved Date:	04/15/2018
Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6066023
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st WINDOW FRAME FROM WEST AT NORTH WALL, 2nd WINDOW FRAME FROM WEST AT NORTH WALL IN THE 1st ROOM FROM NORTH AT WEST LOCATED AT APT 2R, 2nd STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	04/16/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	07/10/2018

A47 **LOT 6,TAXBLOCK 1549** **NY E DESIGNATION** **S108984328**
West **1994 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.044 mi.
230 ft. **Site 34 of 34 in cluster A**

Relative: E DESIGNATION:
Lower

Name:	LOT 6,TAXBLOCK 1549
Address:	1994 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	6
Tax Block:	1549

Actual:
75 ft.

LOT 6,TAXBLOCK 1549 (Continued) **S108984328**

Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

D48 **BACK YARD** **NY Spills** **S124517804**
WSW **1049 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.044 mi.
231 ft. **Site 1 of 10 in cluster D**

Relative: **Lower**

Actual: **79 ft.**

SPILLS:

Name:	BACK YARD
Address:	1049 HERKIMER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1902540 / 2019-06-18
Facility ID:	1902540
Facility Type:	ER
DER Facility ID:	540681
Site ID:	590467
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	2401
Spill Date:	2019-06-11
Investigator:	PXLAKHAN
Referred To:	Not reported
Reported to Dept:	2019-06-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-06-11
Spill Record Last Update:	2019-06-18
Spiller Name:	RONAM DEPAZ
Spiller Company:	NEIGHBOR
Spiller Address:	1049 HERKIMER ST
Spiller Company:	999
Contact Name:	RONAM DEPAZ
DEC Memo:	"6/11/19-Lin-According to complainant, saw workers at 1049 Herkimer st dumping oil from a heating oil tank into a vacant lot behind the house. The complainant lives next door in an attached townhouse. NYPD was called and he has a video of the incident. DEC Lakhani responded. 06/11/19 -

BACK YARD (Continued) **S124517804**

Lakhani DEC Lakhani responded and observed a petroleum odor behind the neighboring property. DEC
Lakhani discovered oil contaminated soil dumped in the empty NYCHPD lot behind the property. The
oil originated from a tank that was left in the backyard of the property. While the tank was being
cut for scrap metal, the sludge leaked out of the tank and was most probably absorbed using the
soil dumped in the vacant lot. The owner of the property is Ezekiel (631-384-5624). Ezekiel had his
construction crews cleanup the contamination. DEC Lakhani will perform an inspection to confirm
closure. 06/17/19 - Lakhani Ezekiel had his construction crew remove the contaminated soil from the
lot and dispose of it. The concrete pad in the backyard was also cleared and cleaned. Ezekiel sent
pictures of the cleanup. DEC Lin performed an inspection and indicated that the site was
appropriately cleaned. No odors were present during inspection. Spill is closed. "

Remarks: "neighbor tried to remove a oil tank - cut lines and oil emptied out into back yard they are trying to cover it up now with sand. clean up is pending further investigation"

All Materials:

Site ID:	590467
Operable Unit ID:	1338102
Operable Unit:	01
Material ID:	2347553
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

E49 **I.S. 271 JOHN M. COLEMAN SCHOOL** **RCRA-SQG** **1001224464**
ESE **1137 HERKIMER ST** **FINDS** **NYR000056812**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.044 mi. **NY LEAD**
233 ft. **Site 1 of 3 in cluster E** **NY MANIFEST**

Relative: **Higher**
Actual: **92 ft.**

RCRA Listings:

Date Form Received by Agency:	20130423
Handler Name:	Nyc Dept Of Education - I S 271k
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000056812
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	Not reported
Contact Email:	ALEMPERT@NYCSCA.ORG

I.S. 271 JOHN M. COLEMAN SCHOOL (Continued) **1001224464**

Contact Title:	DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of School Facilities
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20130620
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

I.S. 271 JOHN M. COLEMAN SCHOOL (Continued) **1001224464**

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6832
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19670601
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-472-8501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6832
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES
Legal Status: Municipal

I.S. 271 JOHN M. COLEMAN SCHOOL (Continued) **1001224464**

Date Became Current: 19670601
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6832
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - INTERMEDIATE SCHOOL 271
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - INTERMEDIATE SCHOOL 271
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980618
Handler Name: NYC BD OF ED - INTERMEDIATE SCHOOL 271
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

I.S. 271 JOHN M. COLEMAN SCHOOL (Continued) **1001224464**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130423
Handler Name: NYC DEPT OF EDUCATION - I S 271K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004544351

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001224464
Registry ID: 110004544351
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004544351
Name: I.S. 271 JOHN M. COLEMAN SCHOOL
Address: 1137 HERKIMER ST
City,State,Zip: BROOKLYN, NY 11233

NYC LEAD 2:
Name: I.S. 271 - BROOKLYN
Address: 1137 HERKIMER STREET
City,State,Zip: BROOKLYN, NY

I.S. 271 JOHN M. COLEMAN SCHOOL (Continued) **1001224464**

Geographical District:	23
Building Code:	K271
Room:	GYMNASIUM
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	I.S. 271 - BROOKLYN
Address:	1137 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K271
Room:	AUDITORIUM
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

NY MANIFEST:

Name:	NYC BD OF ED - INTERMEDIATE SCHOOL 271
Address:	1137 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233-3109
Country:	USA
EPA ID:	NYR000056812
Facility Status:	Not reported
Location Address 1:	1137 HERKIMER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000056812
Mailing Name:	NYC BD OF ED - INTERMEDIATE SCHOOL 271
Mailing Contact:	NYC BD OF ED (INTERMEDIATE SCHOOL 271)
Mailing Address 1:	44-36 VERNON BLVD
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184953412

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	09/19/2012
Trans1 Recv Date:	09/19/2012

I.S. 271 JOHN M. COLEMAN SCHOOL (Continued) **1001224464**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000056812
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	005731577FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E50 **I.S. 271 - BROOKLYN K271** **NY AST** **U003394215**
ESE **1137 HERKIMER STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.044 mi.
233 ft. **Site 2 of 3 in cluster E**

Relative: AST:
Higher

Actual:
92 ft.

Name:	I.S. 271 - BROOKLYN K271
Address:	1137 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-354384
Program Type:	PBS
UTM X:	591631.88283
UTM Y:	4503570.56542

I.S. 271 - BROOKLYN K271 (Continued) **U003394215**

Expiration Date: 06/28/2023
Site Type: School

Affiliation Records:
Site Id: 17618
Affiliation Type: Facility Operator
Company Name: I.S. 271 - BROOKLYN K271
Contact Type: Not reported
Contact Name: DAGOBERTO DIAZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 495-0863
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-11-14

Site Id: 17618
Affiliation Type: Mail Contact
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: JOSEPH YOUNGHESE
Address1: FIELD OPERATIONS - FUEL DIVISION
Address2: 44-36 VERNON BOULEVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5779
EMail: JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-01-25

Site Id: 17618
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: JOSEPH YOUNGHESE
Address1: 44-36 VERNON BOULEVARD
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5751
EMail: JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2020-12-17

Site Id: 17618
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION

I.S. 271 - BROOKLYN K271 (Continued) **U003394215**

Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Tank Info:

Tank Number:	001
Tank Id:	34494
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating D01 - Pipe Type - Steel/Carbon Steel/Iron F01 - Pipe External Protection - Painted/Asphalt Coating H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G) L00 - Piping Leak Detection - None E00 - Piping Secondary Containment - None K01 - Spill Prevention - Catch Basin C03 - Pipe Location - Aboveground/Underground Combination J02 - Dispenser - Suction Dispenser G02 - Tank Secondary Containment - Vault (w/access) I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/12/1962
Capacity Gallons:	15000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/10/2019
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34495
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

I.S. 271 - BROOKLYN K271 (Continued) **U003394215**

Equipment Records:
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/12/1962
Capacity Gallons: 15000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/10/2019
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #4 fuel oil (on-site consumption)

Tank Number: 003
Tank Id: 278382

Equipment Records:
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
A01 - Tank Internal Protection - Epoxy Liner
C01 - Pipe Location - Aboveground

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/10/2018
Capacity Gallons: 8000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

I.S. 271 - BROOKLYN K271 (Continued) **U003394215**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

D51 **LOT 5,TAXBLOCK 1549** **NY E DESIGNATION** **S108984297**
West **1992 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.047 mi.
249 ft. **Site 2 of 10 in cluster D**

Relative: **Lower**
Actual: **74 ft.**

E DESIGNATION:

Name:	LOT 5,TAXBLOCK 1549
Address:	1992 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	5
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

E52 **CON EDISON SERVICE BOX: 22002** **RCRA NonGen / NLR** **1016972078**
ESE **1132 HERKIMER ST** **NY MANIFEST** **NYP004458386**
< 1/8 **BROOKLYN, NY 11212**
0.048 mi.
251 ft. **Site 3 of 3 in cluster E**

Relative: **Higher**
Actual: **93 ft.**

RCRA Listings:

Date Form Received by Agency:	20140405
Handler Name:	Con Edison Service Box: 22002
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11212
EPA ID:	NYP004458386
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

CON EDISON SERVICE BOX: 22002 (Continued) **1016972078**

State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140305
Handler Name: CON EDISON SERVICE BOX:	22002
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 22002 (Continued) **1016972078**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140405
Handler Name: CON EDISON SERVICE BOX:	22002
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON ED
Address:	1132 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11212
Country:	USA
EPA ID:	NYP004458386
Facility Status:	Not reported
Location Address 1:	OPP 1132 HERKIMER ST
Code:	BP
Location Address 2:	SB 22002
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004458386
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON SERVICE BOX: 22002 (Continued) **1016972078**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2014
Trans1 Recv Date:	03/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004458386
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360344GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D53 **LOT 4,TAXBLOCK 1549** **NY E DESIGNATION** **S108984262**
West **FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.051 mi.
269 ft. **Site 3 of 10 in cluster D**

Relative: **Lower**
Actual: **75 ft.**

E DESIGNATION:

Name:	LOT 4,TAXBLOCK 1549
Address:	FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	4
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

C54 **SPILL NUMBER 9905790** **NY Spills** **S104649507**
SSE **11 LOUIS PLACE** **N/A**
< 1/8 **BROOKLYN, NY**
0.052 mi.
273 ft. **Site 2 of 6 in cluster C**

Relative: **Higher**
Actual: **91 ft.**

SPILLS:

Name:	SPILL NUMBER 9905790
Address:	11 LOUIS PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9905790 / 1999-08-13
Facility ID:	9905790
Facility Type:	ER
DER Facility ID:	76410
Site ID:	82967
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-08-13
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	1999-08-13
CID:	281
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-13
Spill Record Last Update:	1999-08-16
Spiller Name:	Not reported

SPILL NUMBER 9905790 (Continued) **S104649507**

Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ARRON JOHNSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO "
Remarks:	"UNKNOWN MATERIAL DISCOVERED ON SIDE OF ROADWAY IN 2 FIVE GALLON BUCKETS. MATERIAL TO BE REMOVED BY DEP HAZMAT UNIT. NO CALL BACK REQUESTED."

All Materials:

Site ID:	82967
Operable Unit ID:	1080243
Operable Unit:	01
Material ID:	302075
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

F55 **CON EDISON SERVICE BOX: 28564** **RCRA NonGen / NLR 1016972566**
North **84 MACDOUGAL** **NY MANIFEST NYP004463436**
< 1/8 **BROOKLYN, NY 11233**
0.052 mi.
275 ft. **Site 1 of 11 in cluster F**

Relative: **Lower**

Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20140411
Handler Name:	Con Edison Service Box: 28564
Handler Address:	MACDOUGAL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004463436
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 28564 (Continued) **1016972566**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140311
Handler Name: CON EDISON SERVICE BOX:	28564
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28564 (Continued) **1016972566**

Receive Date:	20140411
Handler Name: CON EDISON SERVICE BOX:	28564
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	84 MACDOUGAL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004463436
Facility Status:	Not reported
Location Address 1:	FRONT OF 84 MACDOUGAS
Code:	BP
Location Address 2:	SB28564
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004463436
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 28564 (Continued) **1016972566**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2014
Trans1 Recv Date:	03/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004463436
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360337GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F56 **CON EDISON** **NY MANIFEST** **S118089054**
North **86 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.053 mi.
278 ft. **Site 2 of 11 in cluster F**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	86 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA

Actual:
68 ft.

CON EDISON (Continued) **S118089054**

EPA ID:	NYP004766416
Facility Status:	Not reported
Location Address 1:	86 MACDOUGAL ST
Code:	BP
Location Address 2:	SB 28564
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004766416
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	04/10/2015
Trans1 Recv Date:	04/10/2015
Trans2 Recv Date:	04/14/2015
TSD Site Recv Date:	04/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004766416
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619216GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S118089054**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F57 **CON EDISON** **NJ MANIFEST** **S120670349**
North **86 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.053 mi.
278 ft. **Site 3 of 11 in cluster F**

Relative: **Lower**
Actual: **68 ft.**

NJ MANIFEST:

EPA Id:	NYP004766416
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619216GBF
EPA ID:	NYP004766416
Date Shipped:	4/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CON EDISON (Continued) **S120670349**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

F58 **CON EDISON** **RCRA NonGen / NLR** **1019901821**
North **86 MACDOUGAL ST** **NYP004766416**
< 1/8 **BROOKLYN, NY 11233**
0.053 mi.
278 ft. **Site 4 of 11 in cluster F**

Relative: **Lower**
Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20150410
Handler Name:	Con Edison
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004766416
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported

CON EDISON (Continued) **1019901821**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019901821**

Electronic Manifest Broker: Not reported

Receive Date: 20150410
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G59 **CON ED** **NY MANIFEST** **S118259735**
ENE **47 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.053 mi.
279 ft. **Site 1 of 4 in cluster G**

Relative: **Lower**

Actual: **78 ft.**

NY MANIFEST:
Name: CON ED
Address: 47 HULL ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004836688
Facility Status: Not reported
Location Address 1: 47 HULL ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004836688
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported

CON ED (Continued) **S118259735**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/10/2015
Trans1 Recv Date:	09/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004836688
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460105JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G60 **CON EDISON** **RCRA NonGen / NLR** **1019325545**
ENE **47 HULL ST** **NYP004836688**
< 1/8 **BROOKLYN, NY 11233**
0.053 mi.
279 ft. **Site 2 of 4 in cluster G**

Relative: **Lower**
Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:	20150910
Handler Name:	Con Edison
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004836688
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019325545**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150910
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150910
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160205
Handler Name:	CON EDISON - SERVICE BOX 21213
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON (Continued) **1019325545**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150910
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150910
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

G61 **CON EDISON** **NJ MANIFEST** **S120676535**
ENE **47 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.053 mi.
279 ft. **Site 3 of 4 in cluster G**

Relative: NJ MANIFEST:
Lower

EPA Id:	NYP004836688
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003

Actual:
78 ft.

CON EDISON (Continued) **S120676535**

Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014460105JJK
EPA ID:	NYP004836688
Date Shipped:	9/10/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D62 **LOT 3,TAXBLOCK 1549** **NY E DESIGNATION** **S108984219**
West **1988A FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.059 mi.
309 ft. **Site 4 of 10 in cluster D**

Relative: **Lower**
Actual: **72 ft.**

E DESIGNATION:

Name:	LOT 3,TAXBLOCK 1549
Address:	1988A FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	3
Tax Block:	1549
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

C63 **SPILL NUMBER 0200021** **NY Spills** **S106002294**
SE **248 SARATOGA AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.059 mi.
310 ft. **Site 3 of 6 in cluster C**

Relative: **Higher**
Actual: **93 ft.**

SPILLS:

Name:	SPILL NUMBER 0200021
Address:	248 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0200021 / 2002-05-06
Facility ID:	0200021
Facility Type:	ER
DER Facility ID:	72076
Site ID:	77213
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-04-01
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2002-04-01
CID:	281
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-01
Spill Record Last Update:	2002-05-09
Spiller Name:	Not reported

SPILL NUMBER 0200021 (Continued) **S106002294**

Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHRIS HAAS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Drum Emptied REF#9930008 PIN#01036"
Remarks:	"55 GALLON DRUM DISCOVERED ABANDONED AT ABOVE LOCATION. DRUM IS LEAKING AND FIRE DEPT IS RESPONDING TO OVERPACK IT. "

All Materials:

Site ID:	77213
Operable Unit ID:	853450
Operable Unit:	01
Material ID:	525018
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D64 **LOT 1,TAXBLOCK 1549** **NY E DESIGNATION** **S108984142**
West **1986 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.064 mi.
339 ft. **Site 5 of 10 in cluster D**

Relative: **Lower**

Actual: **72 ft.**

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 1549
Address:	1986 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	1549
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

H65 **PLEASANT GROVE BAPTIST CHURCH** **NY AST** **A100366166**
WNW **1927 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.066 mi.
350 ft. **Site 1 of 9 in cluster H**

Relative:
Lower

Actual:
68 ft.

AST:

Name:	PLEASANT GROVE BAPTIST CHURCH
Address:	1927 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611986
Program Type:	PBS
UTM X:	591363.26956
UTM Y:	4503669.49057
Expiration Date:	12/27/2021
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	479670
Affiliation Type:	Facility Operator
Company Name:	PLEASANT GROVE BAPTIST CHURCH
Contact Type:	Not reported
Contact Name:	SEGRUN WALKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 773-8049
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Site Id:	479670
Affiliation Type:	Emergency Contact
Company Name:	PLEASANT GROVE BAPTIST CHURCH
Contact Type:	Not reported
Contact Name:	SEGRUN WALKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 773-8049
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Site Id:	479670
Affiliation Type:	Facility Owner
Company Name:	PLEASANT GROVE BAPTIST CHURCH
Contact Type:	CHIEF FINANCIAL OFFICER
Contact Name:	SEGRUN WALKER

PLEASANT GROVE BAPTIST CHURCH (Continued) **A100366166**

Address1:	1927 FULTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 773-8049
EMail:	PGTABERNACLE@AOL.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Site Id:	479670
Affiliation Type:	Mail Contact
Company Name:	PLEASANT GROVE BAPTIST CHURCH
Contact Type:	CHIEF FINANCIAL OFFICER
Contact Name:	SEGRUN WALKER
Address1:	1927 FULTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 773-8049
EMail:	PGTABERNACLE@AOL.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-21

Tank Info:

Tank Number:	001
Tank Id:	247452
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E01 - Piping Secondary Containment - Diking (AG only)
J02 - Dispenser - Suction Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
K01 - Spill Prevention - Catch Basin
A01 - Tank Internal Protection - Epoxy Liner
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1960

PLEASANT GROVE BAPTIST CHURCH (Continued) **A100366166**

Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

D66 **MANHOLE 66326** **NY Spills** **S104511287**
WSW **1042 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.068 mi.
359 ft. **Site 6 of 10 in cluster D**

Relative: **Higher**

Actual: **82 ft.**

SPILLS:

Name:	MANHOLE 66326
Address:	1042 HERKIMER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9914670 / 2002-03-27
Facility ID:	9914670
Facility Type:	ER
DER Facility ID:	263732
Site ID:	327614
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-03-28
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-03-28
CID:	371
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-03-28
Spill Record Last Update:	2002-03-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks:	"1 qt on 200 gals water -- sample taken - clean up pending results con ed 130592."

All Materials:

Site ID:	327614
Operable Unit ID:	1089182

MANHOLE 66326 (Continued) **S104511287**

Operable Unit:	01
Material ID:	292963
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D67 **CON EDISON - MANHOLE 66327** **NY MANIFEST** **S121968741**
WSW **1036 HERKIMER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.071 mi.
374 ft. **Site 7 of 10 in cluster D**

Relative:
Higher

Actual:
81 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 66327
Address:	1036 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP005150511
Facility Status:	Not reported
Location Address 1:	1036 HERKIMER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005150511
Mailing Name:	CON EDISON - MANHOLE 66327
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

D68 **CON EDISON - MANHOLE 66327** **RCRA-LQG** **1024891808**
WSW **1036 HERKIMER ST** **NYP005150511**
< 1/8 **BROOKLYN, NY 11233**
0.071 mi.
374 ft. **Site 8 of 10 in cluster D**

Relative: **Higher**

Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Manhole 66327
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP005150511
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - MANHOLE 66327 (Continued) **1024891808**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20171012
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20171012
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - MANHOLE 66327
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON - MANHOLE 66327 (Continued) **1024891808**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

C69 **CON ED** **NY MANIFEST** **S119078160**
SSE **21 LOUIS PL** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.077 mi.
404 ft. **Site 4 of 6 in cluster C**

Relative:
Higher

Actual:
93 ft.

NY MANIFEST:

Name:	CON ED
Address:	21 LOUIS PL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004847232
Facility Status:	Not reported
Location Address 1:	ATLANTIC AVE & LEWIS BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004847232
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

CON ED (Continued) **S119078160**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/01/2015
Trans1 Recv Date:	10/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004847232
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619451GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C70 **CON EDISON** **RCRA NonGen / NLR** **1019325677**
SSE **21 LOUIS PL** **NYP004847232**
< 1/8 **BROOKLYN, NY 11233**
0.077 mi.
404 ft. **Site 5 of 6 in cluster C**

Relative: **Higher**

Actual: **93 ft.**

RCRA Listings:

Date Form Received by Agency:	20151002
Handler Name:	Con Edison
Handler Address:	LOUIS PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004847232
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019325677**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151002
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20151002
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160205
Handler Name:	CON EDISON - SERVICE BOX 72411
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON (Continued) **1019325677**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151002
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151002
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

C71 **CON EDISON** **NJ MANIFEST** **S120677479**
SSE **21 LOUIS PL** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.077 mi.
404 ft. **Site 6 of 6 in cluster C**

Relative: Higher

Actual: 93 ft.

NJ MANIFEST:

EPA Id:	NYP004847232
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **S120677479**

Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619451GBF
EPA ID:	NYP004847232
Date Shipped:	10/1/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

F72 **CON EDISON** **NY MANIFEST** **S117058879**
North **105 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.077 mi.
408 ft. **Site 5 of 11 in cluster F**

Relative:
Lower

Actual:
63 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	105 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004510161
Facility Status:	Not reported
Location Address 1:	105 MACDOUGAL ST
Code:	BP
Location Address 2:	SB28561
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004510161
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2014
Trans1 Recv Date:	04/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004510161
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406725GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117058879**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F73 **CON EDISON SERVICE BOX: 28561** **RCRA NonGen / NLR** **1017773236**
North **105 MCDOUGAL ST** **NYP004510160**
< 1/8 **BROOKLYN, NY 11233**
0.077 mi.
408 ft. **Site 6 of 11 in cluster F**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20140524
Handler Name:	Con Edison Service Box: 28561
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004510160
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

Actual:
63 ft.

CON EDISON SERVICE BOX: 28561 (Continued) **1017773236**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28561 (Continued) **1017773236**

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140524
Handler Name: CON EDISON SERVICE BOX:	28561
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G74 **MACDOUGAL ST/SARATOGA AVE** **NY Spills** **S102145855**
NNE **MACDOUGAL ST/SARATOGA AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.077 mi.
409 ft. **Site 4 of 4 in cluster G**

Relative: **Lower**
Actual: **66 ft.**

SPILLS:

Name:	MACDOUGAL ST/SARATOGA AVE
Address:	MACDOUGAL ST/SARATOGA AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9003612 / 1990-09-13
Facility ID:	9003612
Facility Type:	ER
DER Facility ID:	265894
Site ID:	330568
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	Not reported
SWIS:	2401
Spill Date:	1990-06-28

MACDOUGAL ST/SARATOGA AVE (Continued) **S102145855**

Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1990-06-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	1990-09-13
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-02
Spill Record Last Update:	1991-05-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"CAPT WHITE NYCFD FOUND ABANDONED UNDERGROUND STORAGE TANK IN LOT AT MACDOUGAL ST BETWEEN SARATOGA & HOPKINSON AVES, APPROXIMATELY 180 GALSOF PRODUCT (WASTE OIL) IN TANK."

All Materials:

Site ID:	330568
Operable Unit ID:	941490
Operable Unit:	01
Material ID:	438299
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

D75 **LOT 33,TAXBLOCK 1548** **NY E DESIGNATION** **S108984233**
West **1984 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.079 mi.
415 ft. **Site 9 of 10 in cluster D**

Relative: **Lower**

Actual: **71 ft.**

E DESIGNATION:

Name:	LOT 33,TAXBLOCK 1548
Address:	1984 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	33
Tax Block:	1548
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K

LOT 33,TAXBLOCK 1548 (Continued) **S108984233**

Ulurp Number: 070447ZMK
Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

F76 **CON EDISON** **NJ MANIFEST** **S120671860**
North **117 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.082 mi.
435 ft. **Site 7 of 11 in cluster F**

Relative: **Lower**

Actual: **63 ft.**

NJ MANIFEST:
EPA Id: NYP004783528
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 002624388GBF
EPA ID: NYP004783528
Date Shipped: 5/18/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported

CON EDISON (Continued) **S120671860**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

F77 **CON EDISON** **NY MANIFEST** **S119075347**
North **117 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.082 mi.
435 ft. **Site 8 of 11 in cluster F**

Relative: **Lower**
Actual: **63 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	117 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004783528
Facility Status:	Not reported
Location Address 1:	117 MACDOUGLAS ST
Code:	BP
Location Address 2:	SB 28565
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004783528
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S119075347**

Trans2 State ID:	Not reported
Generator Ship Date:	05/18/2015
Trans1 Recv Date:	05/18/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004783528
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624388GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F78 **CON EDISON SERVICE BOX: 28565** **RCRA NonGen / NLR** **1016974255**
North **117 MCDOUGAL STREET** **NY MANIFEST** **NYP004480729**
< 1/8 **BROOKLYN, NY 11233**
0.082 mi.
435 ft. **Site 9 of 11 in cluster F**

Relative: **Lower**
Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:	20140427
Handler Name:	Con Edison Service Box: 28565
Handler Address:	MCDOUGAL STREET
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004480729
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON SERVICE BOX: 28565 (Continued) **1016974255**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON SERVICE BOX: 28565 (Continued) **1016974255**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON SERVICE BOX: 28565
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140427
Handler Name: CON EDISON SERVICE BOX: 28565
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 117 MCDOUGAL STREET
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004480729
Facility Status: Not reported
Location Address 1: 117 MCDOUGAL ST
Code: BP
Location Address 2: SB28565
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY

CON EDISON SERVICE BOX: 28565 (Continued) **1016974255**

Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004480729
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2014
Trans1 Recv Date:	03/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480729
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406969GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON SERVICE BOX: 28565 (Continued) **1016974255**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F79 **CON EDISON** **RCRA NonGen / NLR** **1019903272**
North **117 MACDOUGAL ST** **FINDS** **NYP004783528**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.082 mi.
435 ft. **Site 10 of 11 in cluster F**

Relative: **Lower**

Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:	20150518
Handler Name:	Con Edison
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004783528
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

CON EDISON (Continued) **1019903272**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150518
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150518
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1019903272**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069652842

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903272
Registry ID:	110069652842
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069652842
Name:	CON EDISON
Address:	117 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233

D80 **LOT 32,TAXBLOCK 1548** **NY E DESIGNATION** **S108984228**
West **1982 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.084 mi.
442 ft. **Site 10 of 10 in cluster D**

Relative:
Lower

Actual:
70 ft.

E DESIGNATION:

Name:	LOT 32,TAXBLOCK 1548
Address:	1982 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	32
Tax Block:	1548
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

F81 **CON EDISON SERVICE BOX: 28566** **RCRA NonGen / NLR** **1016974248**
NNE **123 MCDOUGAL ST** **NY MANIFEST** **NYP004480653**
< 1/8 **BROOKLYN, NY 11233**
0.085 mi.
451 ft. **Site 11 of 11 in cluster F**

Relative: **Lower**
Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:	20140427
Handler Name:	Con Edison Service Box: 28566
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004480653
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 28566 (Continued) **1016974248**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140327
Handler Name: CON EDISON SERVICE BOX:	28566
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140427
Handler Name: CON EDISON SERVICE BOX:	28566
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 28566 (Continued) **1016974248**

NY MANIFEST:

Name:	CON EDISON
Address:	123 MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004480653
Facility Status:	Not reported
Location Address 1:	123 MCDOUGAL ST
Code:	BP
Location Address 2:	SB28566
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004480653
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2014
Trans1 Recv Date:	03/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480653
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406970GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 28566 (Continued) **1016974248**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I82 **NEXT TO 85 MACDOUGAL ST** **NY Spills** **S103571242**
NW **BY HOWARD AVE & MACDOUGAL** **N/A**
< 1/8 **BROOKLYN, NY**
0.088 mi.
465 ft. **Site 1 of 8 in cluster I**

Relative: **Lower**

Actual: **60 ft.**

SPILLS:

Name:	NEXT TO 85 MACDOUGAL ST
Address:	BY HOWARD AVE & MACDOUGAL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9708059 / 1997-11-14
Facility ID:	9708059
Facility Type:	ER
DER Facility ID:	262963
Site ID:	326413
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-10-02
Investigator:	MMMULQUE
Referred To:	Not reported
Reported to Dept:	1997-10-08
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	1997-10-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-08
Spill Record Last Update:	2002-10-23
Spiller Name:	JOE SCARPULO

NEXT TO 85 MACDOUGAL ST (Continued) **S103571242**

Spiller Company:	HPD
Spiller Address:	100 GOLD STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN CALLED HPD ON 10/9/97 GOT REPONSE ON 10/10/97 FROM JOE SCARPULO. HPD INVESTIGATION INDICATES THAT THE OIL TANK WAS RUPTURE BY URBAN RENEWAL CONTRACTOR - HUDSON COMPANY WHO IS INVOLVED IN THE SARATOGA STREET COMPLEX. HUDSON COMPANY WAS USING VACANT LOT TO GAIN ACCESS TO THE CURRENT CONSTRUCTION SITE AND IN THE PROCESS THEY RUPTURED A TANK. AN UNKOWN CONTRACTOR REMOVED THE TANK. THE CASE HAS GONE TO FELINE REVOLUS OF HPD - PHONE (212) 863-6404. UNABLE TO REACH FELINE. SPILL IS ACTIVE UNDER SPILL # 97-07862 AND IS A PIN CLEANUP."
Remarks:	"CALLER REPORTS CONSTRUCTION WORKERS WERE EXCAVATING SITE NEXT TO HIS BUILDING WHEN THEY RUPTURED TANK - CALLER REPORTED THIS INCIDENT TO EPA - CALLER'S COMPLAINT TODAY IS FUMES FROM OIL ARE ENTERING HIS BUILDING"

All Materials:

Site ID:	326413
Operable Unit ID:	1051288
Operable Unit:	01
Material ID:	560987
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

J83 **CON EDISON** **RCRA NonGen / NLR** **1019908556**
South **1967 ATLANTIC AVE** **NYP004847224**
< 1/8 **BROOKLYN, NY 11233**
0.088 mi.
467 ft. **Site 1 of 16 in cluster J**

Relative:
Higher

Actual:
92 ft.

RCRA Listings:

Date Form Received by Agency:	20151002
Handler Name:	Con Edison
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004847224
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02

CON EDISON (Continued) **1019908556**

Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1019908556**

Historic Generators:
- Receive Date: 20151002
- Handler Name: CON EDISON
- Federal Waste Generator Description: Small Quantity Generator
- State District Owner: Ny
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: No
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

- Receive Date: 20151002
- Handler Name: CON EDISON
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Ny
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

H84 **VACANT LOT NEXT TO HER** **NY Spills** **S102239382**
NW **83 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.089 mi.
472 ft. **Site 2 of 9 in cluster H**

Relative: **Lower**
Actual: **59 ft.**

SPILLS:
- Name: VACANT LOT NEXT TO HER
- Address: 83 MACDOUGAL ST
- City,State,Zip: BROOKLYN, NY
- Spill Number/Closed Date: 9515842 / 2005-07-15
- Facility ID: 9515842
- Facility Type: ER
- DER Facility ID: 189631
- Site ID: 230070
- DEC Region: 2
- Spill Cause: Unknown
- Spill Class: C3
- SWIS: 2401

VACANT LOT NEXT TO HER (Continued) **S102239382**

Spill Date:	1996-03-11
Investigator:	TLDiaz
Referred To:	Not reported
Reported to Dept:	1996-03-11
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-03-11
Spill Record Last Update:	2005-08-22
Spiller Name:	Not reported
Spiller Company:	NYC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"7/15/05 Site inspection conducted. There is no vacant lot next to #83 however there is a vacant lot next to #93. This lot was fenced off with chain link and access could not be obtained, however, there was a large item under a new looking tarp, but it was not in the shape of a tank. No neighbors were available to verify what this item was. All listed phone numbers on spill report are no longer valid."
Remarks:	"nyc tore bldg down 10 or 11 years ago and left the tank - now tank is exposed and open"

All Materials:

Site ID:	230070
Operable Unit ID:	1030496
Operable Unit:	01
Material ID:	355956
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K85 **W & M ESSO SERVICE STATION** **EDR Hist Auto** **1020343311**
SSE **1993 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.093 mi.
492 ft. **Site 1 of 8 in cluster K**

Relative: EDR Hist Auto
Higher

Actual: **96 ft.**

Year:	Name:	Type:
1974	W & M ESSO SERVICE STATION	Gasoline Service Stations
1975	W & M ESSO SERVICE STATION	Gasoline Service Stations
1976	W & M ESSO SERVICE STATION	Gasoline Service Stations
1977	W & M ESSO SERVICE STATION	Gasoline Service Stations
1978	W & M ESSO SERVICE STATION	Gasoline Service Stations
1979	W & M ESSO SERVICE STATION	Gasoline Service Stations
1980	RONNIES SERVICE STATION	Gasoline Service Stations
1980	W & M ESSO SERVICE STATION	Gasoline Service Stations
1982	W & M ESSO SERVICE STATION	Gasoline Service Stations
1982	RONNIES SERVICE STATION	Gasoline Service Stations
1983	W & M ESSO SERVICE STATION	Gasoline Service Stations
1985	W & M ESSO SERVICE STATION	Gasoline Service Stations
1986	W & M ESSO SERVICE STATION	Gasoline Service Stations
1987	W & M ESSO SERVICE STATION	Gasoline Service Stations
1988	W & M ESSO SERVICE STATION	Gasoline Service Stations

H86 **77 MACDOUGAL ST** **NY Spills** **S103571226**
NW **77 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.094 mi.
494 ft. **Site 3 of 9 in cluster H**

Relative: SPILLS:
Lower

Actual: **59 ft.**

Name:	77 MACDOUGAL ST
Address:	77 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9707862 / 2008-09-30
Facility ID:	9707862
Facility Type:	ER
DER Facility ID:	118843
Site ID:	139045
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-10-03
Investigator:	SRPAIGE
Referred To:	Not reported
Reported to Dept:	1997-10-03
CID:	369
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-03
Spill Record Last Update:	2008-12-02

77 MACDOUGAL ST (Continued) **S103571226**

Spiller Name:	FELINE REVOLOUS
Spiller Company:	CITY OF NEW YORK(HPD)
Spiller Address:	100 GOLD STREET
Spiller Company:	001
Contact Name:	MR SCAUSO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 11/14/97 mmm: HUDSON COMPANY WORKING ON THE SARATOGA STREET URBAN RENEWAL PROJECT WAS UTILIZING THE VACANT HPD LOT AS ACCESS TO SARATOGA STREET CONSTRUCTION. THE LOT IS OWNED BY HPD, AND NO ACCESS PERMISSION WAS GRANTED. HUDSON COMPANY ALLEGEDLY RUPTURED THE TANK WHEN THEY WERE MOVING HEAVY EQUIPMENT AND SOIL AROUND THE LOT, CAUSING RELEASE. DEC INVESTIGATION REVEALED HPD TO OWN PROPERTY AND HPD, FELINE REVOULOS WAS SUPPOSED TO BE WORKING WITH THE HUDSON COMPANY TO RECTIFY THE SITUATION. THE SPILL WAS ALSO INVESTIGATED UNDER DEC SPILL # 97-08059 WHICH WAS CLOSED AND REFERED TO THIS ACTIVE SPILL NUMBER. 5/10/04 - AUSTIN - TRANSFERRED FROM TOMASELO TO TIPPLE - END 8/23/05 - Raphael Ketani. Case transferred to Jeff Vought. 07/25/08-Vought-Spill reassigned from DEC Vought to DEC Ketani as per DEC Austin. 9/30/08 - S. Paige conducted Technical Review of project file. An abandoned 1000 gallon UST that had been resting on ground surface for many years was punctured during construction activities. C. Tomasello (DEC) called out Winston Contracting Corporation on 10/3/1997 to clean up the surface spill. Winston Contracting cleaned and removed the abandoned tank and excavated three (3) tons of contaminated soil. The Attorney General’s Office (OAG) sent demand letters in August and December of 2001 to potential responsible parties (City of New York (HPD), Monadnock Construction, Inc. and P. Guppy & A.H. Mercede). The costs expended by the Spill Fund were recovered and the case was closed by OAG on 3/6/2002. A search of the spills database showed that there are no open spills in close proximity to this site as of 10/8/08. Given readily available documentation, the completed cleanup activities and the closed cost recovery case, no further action is required at this time. "
Remarks:	"VACANT LOT DE3MOLITION REVEALED AN 1000 GALLON TANK WHICH WAS PULLED-SPILL WHEN PULLING TANK"

All Materials:

Site ID:	139045
Operable Unit ID:	1054369
Operable Unit:	01
Material ID:	329849
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

77 MACDOUGAL ST (Continued) **S103571226**

Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

L87 **CON ED** **NY MANIFEST** **S118462844**
ENE **52 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.096 mi.
506 ft. **Site 1 of 9 in cluster L**

Relative: **Higher**
Actual: **88 ft.**

NY MANIFEST:
Name: CON ED
Address: 52 HULL ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004842247
Facility Status: Not reported
Location Address 1: 52 HULL ST
Code: BP
Location Address 2: SB 21218
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004842247
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 09/22/2015
Trans1 Recv Date: 09/22/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/23/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004842247
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported

CON ED (Continued) **S118462844**

Manifest Tracking Number:	014086201JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L88 **CON EDISON** **NJ MANIFEST** **S120677031**
ENE **52 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.096 mi.
506 ft. **Site 2 of 9 in cluster L**

Relative:
Higher

Actual:
88 ft.

NJ MANIFEST:

EPA Id:	NYP004842247
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014086201JJK

CON EDISON (Continued) **S120677031**

EPA ID:	NYP004842247
Date Shipped:	9/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L89 **CON EDISON** **RCRA NonGen / NLR** **1019908125**
ENE **52 HULL ST** **NYP004842247**
< 1/8 **BROOKLYN, NY 11233**
0.096 mi.
506 ft. **Site 3 of 9 in cluster L**

Relative: **Higher**

Actual: **88 ft.**

RCRA Listings:

Date Form Received by Agency:	20150922
Handler Name:	Con Edison
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004842247
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770

CON EDISON (Continued) **1019908125**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON (Continued) **1019908125**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20150922
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150922
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H90 **LOT 29,TAXBLOCK 1548** **NY E DESIGNATION** **S108984213**
West **1970 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.098 mi.
517 ft. **Site 4 of 9 in cluster H**

Relative: **Lower**
Actual: **69 ft.**

E DESIGNATION:

Name:	LOT 29,TAXBLOCK 1548
Address:	1970 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	29
Tax Block:	1548
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported

LOT 29,TAXBLOCK 1548 (Continued) **S108984213**

Ceqr Number: 07DCP070K
Ulurp Number: 070447ZMK
Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

K91 **CON EDISON** **NY MANIFEST** **S116296944**
SE **2001 ATLANTIC AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.099 mi.
525 ft. **Site 2 of 8 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:
Name: CON EDISON
Address: 2001 ATLANTIC AVE FRONT OF
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004483418
Facility Status: Not reported
Location Address 1: 2001 ATLANTIC AVE
Code: BP
Location Address 2: SB69920
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004483418
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/30/2014
Trans1 Recv Date: 03/30/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/31/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004483418
Trans1 EPA ID: Not reported

CON EDISON (Continued) **S116296944**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407050GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

K92 **CON EDISON SERVICE BOX: 18001** **RCRA NonGen / NLR** **1017771405**
SE **2001 ATLANTIC AVE** **FINDS** **NYP004483426**
< 1/8 **BROOKLYN, NY 11233**
0.099 mi.
525 ft. **Site 3 of 8 in cluster K**

Relative: RCRA Listings:
Higher

Actual: Date Form Received by Agency:	20140430
96 ft. Handler Name:	Con Edison Service Box: 18001
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004483426
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON SERVICE BOX: 18001 (Continued) **1017771405**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator

CON EDISON SERVICE BOX: 18001 (Continued) **1017771405**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140331
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140430
Handler Name: CON EDISON SERVICE BOX: 18001
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063776720

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

CON EDISON SERVICE BOX: 18001 (Continued) **1017771405**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

K93 **CON EDISON SERVICE BOX: 69920** **RCRA NonGen / NLR** **1017771404**
SE **2001 ATLANTIC AVE FRONT OF** **NYP004483418**
< 1/8 **BROOKLYN, NY 11233**
0.099 mi.
525 ft. **Site 4 of 8 in cluster K**

Relative: **Higher**
Actual: **96 ft.**

RCRA Listings:

Date Form Received by Agency:	20140430
Handler Name:	Con Edison Service Box: 69920
Handler Address:	ATLANTIC AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004483418
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

CON EDISON SERVICE BOX: 69920 (Continued) **1017771404**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140430
Handler Name: CON EDISON SERVICE BOX:	69920
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 69920 (Continued) **1017771404**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K94 **CON EDISON** **NY MANIFEST** **S116296945**
SE **2001 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.099 mi.
525 ft. **Site 5 of 8 in cluster K**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:
Name: CON EDISON
Address: 2001 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004483426
Facility Status: Not reported
Location Address 1: OPP 2001 ATLANTIC AV
Code: BP
Location Address 2: SB18001
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004483426
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018

CON EDISON (Continued) **S116296945**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/2014
Trans1 Recv Date:	03/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004483426
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407057GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J95 **ROMANELLI ANTHONY** **RCRA NonGen / NLR** **1000243605**
SSW **1943 ATLANTIC AVE** **FINDS** **NYD982532640**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.101 mi.
533 ft. **Site 2 of 16 in cluster J**

Relative:
Higher

Actual:
88 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Romanelli Anthony
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233-3158
EPA ID:	NYD982532640
Contact Name:	Not reported

ROMANELLI ANTHONY (Continued) **1000243605**

Contact Address:	PO BOX 124 GRAVESEND ST
Contact City,State,Zip:	BROOKLYN, NY 11223
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	PO BOX 124 GRAVESEND ST
Mailing City,State,Zip:	BROOKLYN, NY 11223
Owner Name:	Anthony Romanelli
Owner Type:	Private
Operator Name:	Anthony Romanelli
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

ROMANELLI ANTHONY (Continued) **1000243605**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: X003
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: ANTHONY ROMANELLI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANTHONY ROMANELLI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANTHONY ROMANELLI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: ROMANELLI ANTHONY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

ROMANELLI ANTHONY (Continued) **1000243605**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: ROMANELLI ANTHONY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: ROMANELLI ANTHONY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19880308
Handler Name: ROMANELLI ANTHONY	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ROMANELLI ANTHONY (Continued) **1000243605**

FINDS:
Registry ID: 110004421901

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000243605
Registry ID:	110004421901
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004421901
Name:	ROMANELLI ANTHONY
Address:	1943 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233

J96 **CON EDISON** **NY MANIFEST** **S117740677**
SSW **1943 ATLANTIC AV** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.101 mi.
533 ft. **Site 3 of 16 in cluster J**

Relative:
Higher

Actual:
88 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	1943 ATLANTIC AV
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004738548
Facility Status:	Not reported
Location Address 1:	1943 ATLANTIC AV
Code:	BP
Location Address 2:	SB14989
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738548
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117740677**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	03/05/2015
TSD Site Recv Date:	03/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738548
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610838GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J97 **CON EDISON** **RCRA NonGen / NLR** **1016973413**
SSW **1943 ATLANTIC AVE** **NY MANIFEST** **NYP004472155**
< 1/8 **BROOKLYN, NY 11233**
0.101 mi.
533 ft. **Site 4 of 16 in cluster J**

Relative: **Higher**

Actual: **88 ft.**

RCRA Listings:

Date Form Received by Agency:	20150225
Handler Name:	Con Edison
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004472155
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1016973413**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140419
Handler Name: CON EDISON SERVICE BOX:	14989
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1016973413**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	1943 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004472155
Facility Status:	Not reported
Location Address 1:	F/O 1943 & ATLANTIC AVE
Code:	BP
Location Address 2:	SERVICE BOX # 14989
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11210
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004472155
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2014
Trans1 Recv Date:	03/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004472155
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **1016973413**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002359186GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M98 **CON EDISON SERVICE BOX: 28234** **RCRA NonGen / NLR** **1016972080**
SW **298 HOWARD AVE** **NY MANIFEST** **NYP004458402**
< 1/8 **BROOKLYN, NY 11233**
0.101 mi.
535 ft. **Site 1 of 2 in cluster M**

Relative: **Higher**

Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20140405
Handler Name:	Con Edison Service Box: 28234
Handler Address:	HOWARD AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004458402
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON EDISON SERVICE BOX: 28234 (Continued) **1016972080**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140305
Handler Name: CON EDISON SERVICE BOX:	28234
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny

CON EDISON SERVICE BOX: 28234 (Continued) **1016972080**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140405
Handler Name: CON EDISON SERVICE BOX:	28234
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON ED
Address:	298 HOWARD AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004458402
Facility Status:	Not reported
Location Address 1:	298 HOWARD AVE
Code:	BP
Location Address 2:	SB 28234
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004458402
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON SERVICE BOX: 28234 (Continued) **1016972080**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2014
Trans1 Recv Date:	03/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004458402
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360330GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J99 **CON EDISON** **RCRA NonGen / NLR** **1019908435**
South **ATLANTIC AVE & LOUIS ST SB1493** **FINDS** **NYP004845877**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.101 mi.
535 ft. **Site 5 of 16 in cluster J**

Relative: **Higher**
Actual: **95 ft.**

RCRA Listings:

Date Form Received by Agency:	20150930
Handler Name:	Con Edison
Handler Address:	ATLANTIC AVE & LOUIS ST SB1493
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004845877
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019908435**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150930
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150930
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019908435**

FINDS:
Registry ID: 110069672571

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908435
Registry ID:	110069672571
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069672571
Name:	CON EDISON
Address:	ATLANTIC AVE & LOUIS ST SB1499
City,State,Zip:	BROOKLYN, NY 11233

H100 **CON EDISON** **NJ MANIFEST** **S120676520**
WNW **1921 FULTON ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.101 mi.
535 ft. **Site 5 of 9 in cluster H**

Relative: **Lower**

Actual: **67 ft.**

NJ MANIFEST:

EPA Id:	NYP004836506
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014460102JJK
EPA ID:	NYP004836506
Date Shipped:	9/10/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120676520**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

H101 **CON ED** **NY MANIFEST** **S118259720**
WNW **1921 FULTON ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.101 mi.
535 ft. **Site 6 of 9 in cluster H**

Relative:
Lower

Actual:
67 ft.

NY MANIFEST:

Name:	CON ED
Address:	1921 FULTON ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004836506
Facility Status:	Not reported
Location Address 1:	1921 FULTON ST
Code:	BP
Location Address 2:	SB 19960
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004836506
Mailing Name:	CON ED

CON ED (Continued) **S118259720**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/10/2015
Trans1 Recv Date:	09/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004836506
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460102JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON ED (Continued) **S118259720**

Waste Code 1_6: Not reported

H102 **CON EDISON** **RCRA NonGen / NLR** **1019907652**
WNW **1921 FULTON ST** **FINDS** **NYP004836506**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.101 mi.
535 ft. **Site 7 of 9 in cluster H**

Relative: **Lower**

Actual: **67 ft.**

RCRA Listings:

Date Form Received by Agency:	20150910
Handler Name:	Con Edison
Handler Address:	FULTON ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004836506
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CON EDISON (Continued) **1019907652**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150910
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150910
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON (Continued) **1019907652**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069704644

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019907652
Registry ID:	110069704644
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069704644
Name:	CON EDISON
Address:	1921 FULTON ST
City,State,Zip:	BROOKLYN, NY 11233

H103 **LOT 128,TAXBLOCK 1548** **NY E DESIGNATION** **S108984162**
West **1968 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.101 mi.
535 ft. **Site 8 of 9 in cluster H**

Relative:
Lower

Actual:
69 ft.

E DESIGNATION:

Name:	LOT 128,TAXBLOCK 1548
Address:	1968 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	128
Tax Block:	1548
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

J104 **CON ED** **NY MANIFEST** **S118463051**
SSW **ATLANTIC AVE & DEWEY PL** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.103 mi.
542 ft. **Site 6 of 16 in cluster J**

Relative:
Higher

Actual:
91 ft.

NY MANIFEST:

Name:	CON ED
Address:	ATLANTIC AVE & DEWEY PL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004845893
Facility Status:	Not reported
Location Address 1:	ATLANTIC AVE & DEWEY PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004845893
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/2015
Trans1 Recv Date:	09/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/01/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004845893
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002832378GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118463051**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J105 **CON EDISON** **NJ MANIFEST** **S120677351**
SSW **ATLANTIC AVE & DEWEY PL** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.103 mi.
542 ft. **Site 7 of 16 in cluster J**

Relative: **Higher**
Actual: **91 ft.**

NJ MANIFEST:

EPA Id:	NYP004845893
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002832378GBF
EPA ID:	NYP004845893
Date Shipped:	9/30/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120677351**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J106 **CON EDISON** **RCRA NonGen / NLR** **1019325665**
SSW **ATLANTIC AVE & DEWEY PL** **NYP004845893**
< 1/8 **BROOKLYN, NY 11233**
0.103 mi.
542 ft. **Site 8 of 16 in cluster J**

Relative:
Higher

Actual:
91 ft.

RCRA Listings:

Date Form Received by Agency:	20150930
Handler Name:	Con Edison
Handler Address:	ATLANTIC AVE & DEWEY PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004845893
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019325665**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years

Year:	2015

CON EDISON (Continued) **1019325665**

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150930
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150930
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - SERVICE BOX 14992
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150930
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

CON EDISON (Continued) **1019325665**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150930
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I107 **CON EDISON** **RCRA NonGen / NLR** **1018277461**
NNW **166 SUMPTER ST** **FINDS** **NYP004399010**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.104 mi.
548 ft. **Site 2 of 8 in cluster I**

Relative: **Lower**
Actual: **57 ft.**

RCRA Listings:
Date Form Received by Agency: 20131203
Handler Name: Con Edison
Handler Address: SUMPTER ST
Handler City,State,Zip: BROOKLYN, NY 11233
EPA ID: NYP004399010
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL, 15TH FL NE

CON EDISON (Continued) **1018277461**

Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131203
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON (Continued) **1018277461**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131203
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067680343

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277461
Registry ID: 110067680343
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067680343
Name: CON EDISON
Address: 166 SUMPTER ST
City,State,Zip: BROOKLYN, NY 11233

I108 **CON EDISON** **NY MANIFEST** **S116043540**
NNW **166 SUMPTER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.104 mi.
548 ft. **Site 3 of 8 in cluster I**

Relative:
Lower

Actual:
57 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	166 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004399010
Facility Status:	Not reported
Location Address 1:	166 SUMPTER AVE
Code:	BP
Location Address 2:	SB42252
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004399010
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2013
Trans1 Recv Date:	12/03/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004399010
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299989GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116043540**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H109 **LOT 28,TAXBLOCK 1548** **NY E DESIGNATION** **S108984206**
West **1966 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.105 mi.
555 ft. **Site 9 of 9 in cluster H**

Relative: **Lower**
Actual: **68 ft.**

E DESIGNATION:

Name:	LOT 28,TAXBLOCK 1548
Address:	1966 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	28
Tax Block:	1548
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

M110 **315 HOWARD AVE** **NY Spills** **S102402011**
SW **315 HOWARD AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.107 mi.
566 ft. **Site 2 of 2 in cluster M**

Relative:
Higher

Actual:
86 ft.

SPILLS:

Name:	315 HOWARD AVE
Address:	315 HOWARD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9607315 / 1996-09-10
Facility ID:	9607315
Facility Type:	ER
DER Facility ID:	109885
Site ID:	127201
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-09-09
Investigator:	NIEVES
Referred To:	Not reported
Reported to Dept:	1996-09-10
CID:	349
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-09-10
Spill Record Last Update:	1997-10-16
Spiller Name:	HOOKER RESIDENCE
Spiller Company:	Not reported
Spiller Address:	315 HOWARD AV
Spiller Company:	001
Contact Name:	HOOKER RESIDENCE
DEC Memo:	""
Remarks:	"OWNER CONVERTED TO GAS HOT WATER AND DID NOT NOTIFY OIL COMPANY - OIL CO DID CLEAN UP SPILL - SPILL OCCURRED ON CONCRETE ONLY"

All Materials:

Site ID:	127201
Operable Unit ID:	1035268
Operable Unit:	01
Material ID:	561169
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	18.00
Units:	G
Recovered:	18.00
Resource Affected:	Soil
Oxygenate:	Not reported

N111 **LOT 27,TAXBLOCK 1548** **NY E DESIGNATION** **S108984203**
West **1964 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.109 mi.
576 ft. **Site 1 of 6 in cluster N**

Relative: **Lower**
Actual: **68 ft.**

E DESIGNATION:

Name:	LOT 27,TAXBLOCK 1548
Address:	1964 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	27
Tax Block:	1548
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK
Zoning Map No:	16c 17a
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

L112 **CON EDISON** **NJ MANIFEST** **S120676646**
ENE **77 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.109 mi.
578 ft. **Site 4 of 9 in cluster L**

Relative: **Higher**
Actual: **83 ft.**

NJ MANIFEST:

EPA Id:	NYP004837993
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014460112JJK
EPA ID:	NYP004837993
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON (Continued) **S120676646**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L113 **CON EDISON** **NY MANIFEST** **S118259820**
ENE **77 HULL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.109 mi.
578 ft. **Site 5 of 9 in cluster L**

Relative:
Higher

Actual:
83 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	77 HULL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004837993
Facility Status:	Not reported
Location Address 1:	77 HULL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004837993
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON

CON EDISON (Continued) **S118259820**

Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004837993
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460112JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L114 **CON EDISON** **RCRA NonGen / NLR** **1019325566**
ENE **77 HULL ST** **NYP004837993**
< 1/8 **BROOKLYN, NY 11233**
0.109 mi.
578 ft. **Site 6 of 9 in cluster L**

Relative: **Higher**
Actual: **83 ft.**

RCRA Listings:

Date Form Received by Agency:	20150914
Handler Name:	Con Edison
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004837993
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019325566**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150914
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150914
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160205
Handler Name:	CON EDISON - SERVICE BOX 21216
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON (Continued) **1019325566**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

O115 **CON EDISON** **NY MANIFEST** **S117063223**
North **190 SUMPTER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.110 mi.
580 ft. **Site 1 of 6 in cluster O**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	190 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233

Actual:
58 ft.

CON EDISON (Continued) **S117063223**

Country: USA
EPA ID: NYP004556304
Facility Status: Not reported
Location Address 1: 190 SUMPTER ST
Code: BP
Location Address 2: SB 42254
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004556304
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/06/2014
Trans1 Recv Date: 06/06/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004556304
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013245730JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S117063223**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O116 **CON EDISON SERVICE BOX: 42254** **RCRA NonGen / NLR** **1017777728**
North **190 SUMPTER ST** **NYP004556304**
< 1/8 **BROOKLYN, NY 11233**
0.110 mi.
580 ft. **Site 2 of 6 in cluster O**

Relative: **Lower**

Actual: **58 ft.**

RCRA Listings:

Date Form Received by Agency:	20140706
Handler Name:	Con Edison Service Box: 42254
Handler Address:	SUMPTER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004556304
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

CON EDISON SERVICE BOX: 42254 (Continued) **1017777728**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140606
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140606
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 42254 (Continued) **1017777728**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140706
Handler Name: CON EDISON SERVICE BOX:	42254
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

P117 **CON EDISON** **RCRA NonGen / NLR** **1019906704**
ENE **148 MACDOUGAL ST** **FINDS** **NYP004825382**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.110 mi.
583 ft. **Site 1 of 10 in cluster P**

Relative: **Lower**
Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20150818
Handler Name:	Con Edison
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004825382
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

CON EDISON (Continued) **1019906704**

State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150818
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON (Continued) **1019906704**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150818
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069668602

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906704
Registry ID: 110069668602
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069668602
Name: CON EDISON
Address: 148 MACDOUGAL ST
City,State,Zip: BROOKLYN, NY 11233

P118
ENE
< 1/8
0.110 mi.
583 ft.

CON EDISON
148 MACDOUGAL ST
BROOKLYN, NY 11233

Site 2 of 10 in cluster P

NJ MANIFEST **S120675503**
N/A

Relative:
Lower

Actual:
77 ft.

NJ MANIFEST:

EPA Id:	NYP004825382
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624871GBF
EPA ID:	NYP004825382
Date Shipped:	8/18/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675503**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

P119 **CON ED** **NY MANIFEST** **S118259052**
ENE **148 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.110 mi.
583 ft. **Site 3 of 10 in cluster P**

Relative:
Lower

Actual:
77 ft.

NY MANIFEST:

Name:	CON ED
Address:	148 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004825382
Facility Status:	Not reported
Location Address 1:	148 MACDOUGAL ST
Code:	BP
Location Address 2:	SB 28571
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004825382
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/18/2015
Trans1 Recv Date:	08/18/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004825382
Trans1 EPA ID:	Not reported

CON ED (Continued) **S118259052**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624871GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I120 **NEW CONSTRUCTION** **NY Spills** **S103571696**
NNW **150 SUMPTER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.112 mi.
593 ft. **Site 4 of 8 in cluster I**

Relative: SPILLS:
Lower

Actual: Name:	NEW CONSTRUCTION
56 ft. Address:	150 SUMPTER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712516 / 1998-02-09
Facility ID:	9712516
Facility Type:	ER
DER Facility ID:	177310
Site ID:	214012
DEC Region:	2
Spill Cause:	Other
Spill Class:	E5
SWIS:	2401
Spill Date:	1998-02-09
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1998-02-09

NEW CONSTRUCTION (Continued) **S103571696**

CID:	323
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-09
Spill Record Last Update:	1998-02-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KEITH PETTEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT ADVISE: 1. NOTIFIY OWNER. 2. FIND SIZE. 3. PUMP OUT TANK. 4.REGISTRATION IF NECESSARY. 5. CLOSURE OF TANK."
Remarks:	"DURING GRADING OF DIRT, A TANK WAS FOUND. UNKNOWN SIZE, UNKNOWN PRODUCT INSIDE. APPEARS TO HAVE BEEN NO LEAKAGE."

All Materials:

Site ID:	214012
Operable Unit ID:	1055378
Operable Unit:	01
Material ID:	327119
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

N121 **LOT 26,TAXBLOCK 1548** **NY E DESIGNATION** **S108984197**
West **1962 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.113 mi.
597 ft. **Site 2 of 6 in cluster N**

Relative: **Lower**
Actual: **68 ft.**

E DESIGNATION:

Name:	LOT 26,TAXBLOCK 1548
Address:	1962 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	26
Tax Block:	1548
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	070447ZMK

LOT 26,TAXBLOCK 1548 (Continued) **S108984197**

Zoning Map No: 16c 17a

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation

Lot Remediation Date: Not reported

K122 **COMMERICAL** **NY Spills** **S127480159**
SSE **2120 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.115 mi.
606 ft. **Site 6 of 8 in cluster K**

Relative: **Higher**

Actual: **97 ft.**

SPILLS:

Name:	COMMERICAL
Address:	2120 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2009595 / 2021-03-02
Facility ID:	2009595
Facility Type:	ER
DER Facility ID:	564434
Site ID:	616600
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2021-02-24
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2021-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-02-24
Spill Record Last Update:	2021-03-02
Spiller Name:	Not reported
Spiller Company:	PARK AVE CO
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PARK AVE CO
DEC Memo:	"2/24/21-Lin-Truck from 2120 Atlantic ave was park outside their building when the saddle tank started leaking. The leak is stopped and they estimate about 15 gallon came out onto the road. No drains were impacted. The RP put down speedy dry and is handling the cleanup. Park Ave Night Supervisor: Francisco 718-403-0100 (General Company Number)"
Remarks:	"clean up on going"

All Materials:

Site ID:	616600
Operable Unit ID:	1363719

COMMERICAL (Continued) **S127480159**

Operable Unit:	01
Material ID:	2376066
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

K123 **PARK AVE BLDG & ROOFING SUPPLIES LLC** **RCRA NonGen / NLR** **1027099604**
SSE **2120 ATLANTIC AVE** **NYR000252783**
< 1/8 **BROOKLYN, NY 11233**
0.115 mi.
606 ft. **Site 7 of 8 in cluster K**

Relative: **Higher**

Actual: **97 ft.**

RCRA Listings:

Date Form Received by Agency:	20220922
Handler Name:	Park Ave Bldg & Roofing Supplies Llc
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000252783
Contact Name:	NICOLE KUBICK
Contact Address:	ATLANTIC AVE
Contact City,State,Zip:	BROOKLYN, NY 11233
Contact Telephone:	718-403-0100
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ADMINISTRATOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ATLANTIC AVE
Mailing City,State,Zip:	BROOKLYN, NY 11233
Owner Name:	Erma Realty Llc
Owner Type:	Private
Operator Name:	Park Ave Building & Roofing Supplies Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

PARK AVE BLDG & ROOFING SUPPLIES LLC (Continued) **1027099604**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220922
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ERMA REALTY LLC	
Legal Status:	Private
Date Became Current:	20060601
Date Ended Current:	Not reported
Owner/Operator Address:	2120 ATLANTIC AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11233
Owner/Operator Telephone:	718-403-0100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	MOSESRIVERA@PARKBUILDING.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: PARK AVE BUILDING & ROOFING SUPPLIES LLC	
Legal Status:	Private
Date Became Current:	20061020
Date Ended Current:	Not reported
Owner/Operator Address:	2120 ATLANTIC AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11233
Owner/Operator Telephone:	718-403-0100

PARK AVE BLDG & ROOFING SUPPLIES LLC (Continued) **1027099604**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MOSESRIVERA@PARKBUILDING.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: PARK AVE BUILDING & ROOFING SUPPLIES LLC
Legal Status: Private
Date Became Current: 20061020
Date Ended Current: Not reported
Owner/Operator Address: 2120 ATLANTIC AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11233
Owner/Operator Telephone: 718-403-0100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MOSESRIVERA@PARKBUILDING.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: ERMA REALTY LLC
Legal Status: Private
Date Became Current: 20060601
Date Ended Current: Not reported
Owner/Operator Address: 2120 ATLANTIC AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11233
Owner/Operator Telephone: 718-403-0100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MOSESRIVERA@PARKBUILDING.COM

Historic Generators:

Receive Date: 20220922
Handler Name: PARK AVE BLDG & ROOFING SUPPLIES LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20211006
Handler Name: PARK AVE BLDG & ROOFING SUPPLIES LLC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:

PARK AVE BLDG & ROOFING SUPPLIES LLC (Continued) **1027099604**

NAICS Code: 444110
NAICS Description: HOME CENTERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J124 **CON EDISON** **NY MANIFEST** **S116550413**
South **2112 ATLANTIC AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.115 mi.
606 ft. **Site 9 of 16 in cluster J**

Relative:
Higher

Actual:
96 ft.

NY MANIFEST:
Name: CON EDISON
Address: 2112 ATLANTIC AVE FRONT OF
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004487922
Facility Status: Not reported
Location Address 1: 2112 ATLANTIC AVE
Code: BP
Location Address 2: SB14997
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004487922
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/03/2014
Trans1 Recv Date: 04/03/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/04/2014
Part A Recv Date: Not reported

CON EDISON (Continued) **S116550413**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487922
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002361068GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J125 **CON EDISON SERVICE BOX: 14997** **RCRA NonGen / NLR** **1017771847**
South **2112 ATLANTIC AVE FRONT OF** **FINDS** **NYP004487922**
< 1/8 **BROOKLYN, NY 11233**
0.115 mi.
606 ft. **Site 10 of 16 in cluster J**

Relative: RCRA Listings:
Higher

Date Form Received by Agency:	20140503
Handler Name:	Con Edison Service Box: 14997
Handler Address:	ATLANTIC AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004487922
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02

Actual:
96 ft.

CON EDISON SERVICE BOX: 14997 (Continued) **1017771847**

Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: 14997 (Continued) **1017771847**

Historic Generators:

Receive Date:		20140403
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140403
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140503
Handler Name:	CON EDISON SERVICE BOX:	14997
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063799572

Click Here for FRS Facility Detail Report:

CON EDISON SERVICE BOX: 14997 (Continued) **1017771847**

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J126 **CON EDISON SERVICE BOX: 14996** **RCRA NonGen / NLR** **1017771850**
South **2100 ATLANTIC AVE FRONT OF** **FINDS** **NYP004487955**
< 1/8 **BROOKLYN, NY 11233**
0.115 mi.
607 ft. **Site 11 of 16 in cluster J**

Relative:
Higher

Actual:
95 ft.

RCRA Listings:

Date Form Received by Agency:	20140503
Handler Name:	Con Edison Service Box: 14996
Handler Address:	ATLANTIC AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004487955
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON SERVICE BOX: 14996 (Continued) **1017771850**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140503

CON EDISON SERVICE BOX: 14996 (Continued) **1017771850**

Handler Name: CON EDISON SERVICE BOX: 14996
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063799607

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J127 **CON EDISON** **NY MANIFEST** **S116550416**
South **2100 ATLANTIC AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.115 mi.
607 ft. **Site 12 of 16 in cluster J**

Relative:
Higher

Actual:
95 ft.

NY MANIFEST:
Name: CON EDISON
Address: 2100 ATLANTIC AVE FRONT OF
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004487955
Facility Status: Not reported
Location Address 1: 2100 ATLANTIC AVE
Code: BP
Location Address 2: SB14996
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY

CON EDISON (Continued) **S116550416**

Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004487955
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 04/03/2014
Trans1 Recv Date: 04/03/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/04/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004487955
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002361062GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 250
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S116550416**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P128 **CON EDISON** **NY MANIFEST** **S119074837**
NE **155 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.115 mi.
607 ft. **Site 4 of 10 in cluster P**

Relative:
Lower

Actual:
71 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	155 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004774733
Facility Status:	Not reported
Location Address 1:	147 MCDUGAL ST
Code:	BP
Location Address 2:	SB 28568
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004774733
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/27/2015
Trans1 Recv Date:	04/27/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/29/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004774733

CON EDISON (Continued) **S119074837**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454173JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P129 **CON EDISON** **NJ MANIFEST** **S120671071**
NE **155 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11215**
0.115 mi.
607 ft. **Site 5 of 10 in cluster P**

Relative: NJ MANIFEST:
Lower

Actual:
71 ft.

EPA Id:	NYP004774733
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **S120671071**

Date Change:	Not reported
Manifest:	
Manifest Number:	014454173JJK
EPA ID:	NYP004774733
Date Shipped:	4/27/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

P130 **CON EDISON** **RCRA NonGen / NLR** **1019902521**
NE **155 MACDOUGAL ST** **NYP004774733**
< 1/8 **BROOKLYN, NY 11215**
0.115 mi.
607 ft. **Site 6 of 10 in cluster P**

Relative: **Lower**

Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:	20150427
Handler Name:	Con Edison
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004774733

CON EDISON (Continued) **1019902521**

Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON (Continued) **1019902521**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150427
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150427
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I131 **233 HOWARD AVENUE** **NY Spills** **S105140429**
NW **233 HOWARD AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.115 mi.
608 ft. **Site 5 of 8 in cluster I**

Relative: **Lower**
Actual: **56 ft.**

SPILLS:
Name: SPILL NUMBER 0105366
Address: 233 HOWARD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0105366 / 2001-09-28
Facility ID: 0105366

233 HOWARD AVENUE (Continued) **S105140429**

Facility Type:	ER
DER Facility ID:	197027
Site ID:	154485
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	2001-08-17
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-08-17
CID:	211
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-17
Spill Record Last Update:	2001-09-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	WAIMAN WONG
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 09/28/2001 - Drums were pumped out by Milro under State Pin # for drum removel. Empty drums were left on site for pick up by New York City Sanatation Department. wtc "
Remarks:	"4 55 gal drums and 1 85 gal drum of waste oil on sidewalk - do not appear to be leaking"

All Materials:

Site ID:	154485
Operable Unit ID:	842268
Operable Unit:	01
Material ID:	533836
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	305.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	233 HOWARD AVENUE
Address:	233 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9401030 / 1994-04-22
Facility ID:	9401030
Facility Type:	ER

233 HOWARD AVENUE (Continued) **S105140429**

DER Facility ID:	197027
Site ID:	239554
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1994-04-21
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1994-04-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-04-22
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-27
Spill Record Last Update:	1994-04-27
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"FUEL OIL CO WASHED IT DOWN THE SEWER- THEY ARE STILL THERE. CALLED DEP-POST OFFICE # IS WRONG. DEP EN ROUTE DEP WILL CALL BACK WITH MORE INFORMATION."

All Materials:

Site ID:	239554
Operable Unit ID:	998388
Operable Unit:	01
Material ID:	384803
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

I132 **CON EDISON** **RCRA NonGen / NLR** **1018277520**
NW **250 HOWARD ST** **FINDS** **NYP004722484**
< 1/8 **BROOKLYN, NY 11206** **ECHO**
0.116 mi.
610 ft. **Site 6 of 8 in cluster I**

Relative: **Lower**
Actual: **58 ft.**

RCRA Listings:

Date Form Received by Agency:	20150131
Handler Name:	Con Edison
Handler Address:	HOWARD ST
Handler City,State,Zip:	BROOKLYN, NY 11206
EPA ID:	NYP004722484
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1018277520**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150131
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150131
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1018277520**

FINDS:
Registry ID: 110067689530

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277520
Registry ID:	110067689530
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067689530
Name:	CON EDISON
Address:	250 HOWARD ST
City,State,Zip:	BROOKLYN, NY 11206

I133 **CON EDISON** **NJ MANIFEST** **S120666465**
NW **250 HOWARD ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.116 mi.
610 ft. **Site 7 of 8 in cluster I**

Relative: **Lower**

Actual: **58 ft.**

NJ MANIFEST:

EPA Id:	NYP004722484
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610276GBF
EPA ID:	NYP004722484
Date Shipped:	1/31/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120666465**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

I134 **CON EDISON** **NY MANIFEST** **S117739152**
NW **250 HOWARD ST** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.116 mi.
610 ft. **Site 8 of 8 in cluster I**

Relative:
Lower

Actual:
58 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	250 HOWARD ST
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004722484
Facility Status:	Not reported
Location Address 1:	250 HOWARD AV
Code:	BP
Location Address 2:	SB66329
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004722484
Mailing Name:	CON EDISON

CON EDISON (Continued) **S117739152**

Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/2015
Trans1 Recv Date:	01/31/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004722484
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610276GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S117739152**

Waste Code 1_6: Not reported

J135 **CON EDISON** **NY MANIFEST** **S117736274**
SSW **2090 ATLANTIC AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.117 mi.
617 ft. **Site 13 of 16 in cluster J**

Relative:
Higher

Actual:
93 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	2090 ATLANTIC AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004487914
Facility Status:	Not reported
Location Address 1:	2090 ATLANTIC AVE FRNT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004487914
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2014
Trans1 Recv Date:	04/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487914
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002361185GBF
Import Indicator:	N

CON EDISON (Continued) **S117736274**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J136 **CON EDISON MANHOLE: 5055** **RCRA NonGen / NLR** **1017771846**
SSW **2090 ATLANTIC AVE FRONT OF** **FINDS** **NYP004487914**
< 1/8 **BROOKLYN, NY 11233**
0.117 mi.
617 ft. **Site 14 of 16 in cluster J**

Relative: **Higher**

Actual: **93 ft.**

RCRA Listings:

Date Form Received by Agency:	20140503
Handler Name:	Con Edison Manhole: 5055
Handler Address:	ATLANTIC AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004487914
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

CON EDISON MANHOLE: 5055 (Continued) **1017771846**

Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON MANHOLE: 5055 (Continued) **1017771846**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140403
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140503
Handler Name: CON EDISON MANHOLE: 5055
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063799563

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

O137 **CON EDISON** **NY MANIFEST** **S117738796**
NNE **F/O 204 SUMPTER ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.119 mi.
630 ft. **Site 3 of 6 in cluster O**

Relative:
Lower

Actual:
58 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 204 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004718722
Facility Status:	Not reported
Location Address 1:	F/O 204 SUMPTER ST
Code:	BP
Location Address 2:	SB 42249
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004718722
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/25/2015
Trans1 Recv Date:	01/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004718722
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773964JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117738796**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P138 **CON EDISON SERVICE BOX: 28568** **RCRA NonGen / NLR** **1017772761**
NE **159 MACDOUGAL ST** **NYP004497210**
< 1/8 **BROOKLYN, NY 11233**
0.120 mi.
631 ft. **Site 7 of 10 in cluster P**

Relative: **Lower**
Actual: **72 ft.**

RCRA Listings:

Date Form Received by Agency:	20140510
Handler Name:	Con Edison Service Box: 28568
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004497210
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 28568 (Continued) **1017772761**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28568 (Continued) **1017772761**

Receive Date:	20140410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140510
Handler Name: CON EDISON SERVICE BOX:	28568
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

P139 **CON EDISON** **NY MANIFEST** **S116551276**
NE **159 MACDOUGAL ST** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.120 mi.
631 ft. **Site 8 of 10 in cluster P**

Relative: **Lower**

Actual: **72 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	159 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004497210
Facility Status:	Not reported
Location Address 1:	159 MACDOUGAL ST
Code:	BP
Location Address 2:	SB28568
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233

CON EDISON (Continued) **S116551276**

Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004497210
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/10/2014
Trans1 Recv Date:	04/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004497210
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406732GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S116551276**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O140 **AUSTIN RES** **NY Spills** **S104501367**
North **201 SUMTER ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.120 mi.
636 ft. **Site 4 of 6 in cluster O**

Relative: **Lower**
Actual: **56 ft.**

SPILLS:

Name:	AUSTIN RES
Address:	201 SUMTER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9515677 / 2003-04-15
Facility ID:	9515677
Facility Type:	ER
DER Facility ID:	83012
Site ID:	92440
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-03-06
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-03-06
CID:	233
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-03-06
Spill Record Last Update:	2003-04-15
Spiller Name:	MR AUSTIN
Spiller Company:	AUSTIN RES
Spiller Address:	201 SUMTER ST
Spiller Company:	001
Contact Name:	MR AUSTIN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY OIL CO."
Remarks:	"leak around fill box outside res apx 1 quart spill clean up by service man fill box to be replaced "

All Materials:

Site ID:	92440
Operable Unit ID:	1026743
Operable Unit:	01
Material ID:	355796

AUSTIN RES (Continued) **S104501367**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

N141 **USPS - STUYVESANT STATION** **RCRA NonGen / NLR** **1004756156**
WNW **1915 FULTON ST** **FINDS** **NY8180011233**
< 1/8 **BROOKLYN, NY 11233** **ECHO**
0.124 mi.
657 ft. **Site 3 of 6 in cluster N**

Relative: **Lower**
Actual: **64 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Usps - Stuyvesant Station
Handler Address:	FULTON ST
Handler City,State,Zip:	BROOKLYN, NY 11233-9998
EPA ID:	NY8180011233
Contact Name:	WALTER HOUGH
Contact Address:	FULTON ST
Contact City,State,Zip:	BROOKLYN, NY 11233-9998
Contact Telephone:	718-555-1212
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Federal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	FULTON ST
Mailing City,State,Zip:	BROOKLYN, NY 11233-9998
Owner Name:	Usps Brooklyn Proc & Dist Center
Owner Type:	Federal
Operator Name:	Us Postal Services
Operator Type:	Federal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

USPS - STUYVESANT STATION (Continued) **1004756156**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned, The site is federally-owned, The site is federally-operated
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	USPS BROOKLYN PROC & DIST CENTER
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1050 FORBELL ST ROOM 2090
Owner/Operator City,State,Zip:	BROOKLYN, NY 11256-9731
Owner/Operator Telephone:	718-348-3510
Owner/Operator Telephone Ext:	Not reported

USPS - STUYVESANT STATION (Continued) **1004756156**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: US POSTAL SERVICES
Legal Status: Federal
Date Became Current: 19791231
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: US POSTAL SERVICES
Legal Status: Federal
Date Became Current: 19791231
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: US POSTAL SERVICES
Legal Status: Federal
Date Became Current: 19791231
Date Ended Current: Not reported
Owner/Operator Address: 1915 FULTON ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11233-9998
Owner/Operator Telephone: 718-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: USPS BROOKLYN PROC & DIST CENTER
Legal Status: Federal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1050 FORBELL ST ROOM 2090
Owner/Operator City,State,Zip: BROOKLYN, NY 11256-9731
Owner/Operator Telephone: 718-348-3510
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: US POSTAL SERVICES
Legal Status: Federal
Date Became Current: 19791231
Date Ended Current: Not reported
Owner/Operator Address: 1915 FULTON ST

USPS - STUYVESANT STATION (Continued) **1004756156**

Owner/Operator City,State,Zip: BROOKLYN, NY 11233-9998
Owner/Operator Telephone: 718-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: USPS BROOKLYN PROC & DIST CENTER
Legal Status: Federal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1050 FORBELL ST ROOM 2090
Owner/Operator City,State,Zip: BROOKLYN, NY 11256-9731
Owner/Operator Telephone: 718-348-3510
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: USPS - STUYVESANT STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: USPS - STUYVESANT STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950705
Handler Name: US POSTAL SERVICE - STUYVESANT POSTAL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

USPS - STUYVESANT STATION (Continued) **1004756156**

Receive Date: 20030730
Handler Name: USPS - STUYVESANT STATION
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 49111
NAICS Description: POSTAL SERVICE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004326122

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004756156
Registry ID: 110004326122
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004326122
Name: USPS - STUYVESANT STATION
Address: 1915 FULTON ST
City,State,Zip: BROOKLYN, NY 11233

N142 **US POSTAL SERVICE - STUYVESANT STATION** **NY AST** **A100177822**
WNW **1915 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.124 mi.
657 ft. **Site 4 of 6 in cluster N**

Relative:
Lower

Actual:
64 ft.

AST:

Name:	US POSTAL SERVICE - STUYVESANT STATION
Address:	1915 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-453145
Program Type:	PBS
UTM X:	591257.94251
UTM Y:	4503675.77791
Expiration Date:	10/14/2008
Site Type:	Other

Affiliation Records:

Site Id:	19831
Affiliation Type:	Facility Owner
Company Name:	U.S. POSTAL SERVICE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	78-02 LIBERTY AVENUE
Address2:	Not reported
City:	OZONE PARK
State:	NY
Zip Code:	11417-1045
Country Code:	001
Phone:	(718) 529-7211
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19831
Affiliation Type:	Mail Contact
Company Name:	U.S. POSTAL SERVICE
Contact Type:	Not reported
Contact Name:	ROBERT J. SKRIVANEK
Address1:	78-02 LIBERTY AVENUE
Address2:	Not reported
City:	OZONE PARK
State:	NY
Zip Code:	11417-1045
Country Code:	001
Phone:	(718) 529-7220
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19831
Affiliation Type:	Facility Operator
Company Name:	US POSTAL SERVICE - STUYVESANT STATION
Contact Type:	Not reported
Contact Name:	STATION MANAGER

US POSTAL SERVICE - STUYVESANT STATION (Continued) **A100177822**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 493-6808
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19831
Affiliation Type:	Emergency Contact
Company Name:	U.S. POSTAL SERVICE
Contact Type:	Not reported
Contact Name:	ROBERT SKRIVANEK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 529-7220
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	35648
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1979
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported

US POSTAL SERVICE - STUYVESANT STATION (Continued) **A100177822**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

K143 **CLOSED S/S** **NY UST** **U004046408**
SSE **2130 ATLANTIC AVENUE** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 12345**
0.125 mi.
661 ft. **Site 8 of 8 in cluster K**

Relative:
Higher

Actual:
98 ft.

UST:

Name:	CLOSED S/S
Address:	2130 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 12345
Id/Status:	2-608672 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	591591.23894
UTM Y:	4503410.25333
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	30524
Affiliation Type:	Facility Operator
Company Name:	CLOSED S/S
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30524
Affiliation Type:	Facility Owner
Company Name:	ERMA REALTY, LLC
Contact Type:	OWNER
Contact Name:	WILLIAM HOWARD
Address1:	81 SPENCER STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001
Phone:	(718) 852-3330
EMail:	Not reported
Fax Number:	Not reported

CLOSED S/S (Continued) **U004046408**

Modified By:	cgfreedm
Date Last Modified:	2004-04-13
Site Id:	30524
Affiliation Type:	Mail Contact
Company Name:	ERMA REALTY, LLC
Contact Type:	OWNER
Contact Name:	WILLIAM HOWARD
Address1:	81 SPENCER STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001
Phone:	(718) 852-3330
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-04-13
Site Id:	30524
Affiliation Type:	Emergency Contact
Company Name:	ERMA REALTY, LLC
Contact Type:	Not reported
Contact Name:	WILLIAM HOWARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 852-3330
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-04-13

Tank Info:

Tank Number:	10
Tank ID:	65485
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

CLOSED S/S (Continued) **U004046408**

Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 11
Tank ID: 65486
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 12
Tank ID: 65487
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

CLOSED S/S (Continued) **U004046408**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 13
Tank ID: 65488
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 2
Tank ID: 65477
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003

CLOSED S/S (Continued) **U004046408**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 3
Tank ID: 65478
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 4

CLOSED S/S (Continued) **U004046408**

Tank ID:	65479
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	5
Tank ID:	65480
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	03/01/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None

CLOSED S/S (Continued) **U004046408**

I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 6
Tank ID: 65481
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 7
Tank ID: 65482
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

CLOSED S/S (Continued) **U004046408**

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 8
Tank ID: 65483
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 9
Tank ID: 65484
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 03/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported

CLOSED S/S (Continued) **U004046408**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

AST:
Name: CLOSED S/S
Address: 2130 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 12345
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-608672
Program Type: PBS
UTM X: 591591.23894
UTM Y: 4503410.25333
Expiration Date: N/A
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 30524
Affiliation Type: Facility Operator
Company Name: CLOSED S/S
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 30524
Affiliation Type: Facility Owner
Company Name: ERMA REALTY, LLC
Contact Type: OWNER
Contact Name: WILLIAM HOWARD
Address1: 81 SPENCER STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11205

CLOSED S/S (Continued) **U004046408**

Country Code:	001
Phone:	(718) 852-3330
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-04-13

Site Id:	30524
Affiliation Type:	Mail Contact
Company Name:	ERMA REALTY, LLC
Contact Type:	OWNER
Contact Name:	WILLIAM HOWARD
Address1:	81 SPENCER STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11205
Country Code:	001
Phone:	(718) 852-3330
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-04-13

Site Id:	30524
Affiliation Type:	Emergency Contact
Company Name:	ERMA REALTY, LLC
Contact Type:	Not reported
Contact Name:	WILLIAM HOWARD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 852-3330
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-04-13

Tank Info:

Tank Number:	1
Tank Id:	65476
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

CLOSED S/S (Continued) **U004046408**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Partially buried tank (tank with 10% or more below ground).... Tank is less than 90% above grade, partially buried.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/01/2003
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

Q144 **CON EDISON** **NJ MANIFEST** **S120670732**
WNW **61 MACDOUGAL** **N/A**
1/8-1/4 **BROOKLYN, NY 11223**
0.126 mi.
664 ft. **Site 1 of 10 in cluster Q**

Relative: **Lower**

Actual: **59 ft.**

NJ MANIFEST:

EPA Id:	NYP004770780
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660996GBF
EPA ID:	NYP004770780
Date Shipped:	4/20/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported

CON EDISON (Continued) **S120670732**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q145 **CON EDISON** **RCRA NonGen / NLR** **1019902191**
WNW **61 MACDOUGAL** **FINDS** **NYP004770780**
1/8-1/4 **BROOKLYN, NY 11223** **ECHO**
0.126 mi.
664 ft. **Site 2 of 10 in cluster Q**

Relative: **Lower**

Actual: **59 ft.**

RCRA Listings:

Date Form Received by Agency:	20150420
Handler Name:	Con Edison
Handler Address:	MACDOUGAL
Handler City,State,Zip:	BROOKLYN, NY 11223
EPA ID:	NYP004770780
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **1019902191**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150420
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON (Continued) **1019902191**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150420
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069677102

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019902191
Registry ID:	110069677102
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069677102
Name:	CON EDISON
Address:	61 MACDOUGAL
City,State,Zip:	BROOKLYN, NY 11223

Q146
WNW
1/8-1/4
0.126 mi.
664 ft.

CON EDISON
61 MACDOUGAL
BROOKLYN, NY 11223

Site 3 of 10 in cluster Q

NY MANIFEST **S118089473**
N/A

Relative:
Lower

Actual:
59 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	61 MACDOUGAL
City,State,Zip:	BROOKLYN, NY 11223
Country:	USA
EPA ID:	NYP004770780
Facility Status:	Not reported
Location Address 1:	61 MACDOUGAL ST
Code:	BP
Location Address 2:	SB 28558
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004770780
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/20/2015
Trans1 Recv Date:	04/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004770780
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660996GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118089473**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J147 **CON EDISON** **NY MANIFEST** **S116550415**
South **2074 ATLANTIC AVE FRONT OF** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.127 mi.
673 ft. **Site 15 of 16 in cluster J**

Relative: **Higher**

Actual: **97 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	2074 ATLANTIC AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004487948
Facility Status:	Not reported
Location Address 1:	2074 ATLANTIC AVE
Code:	BP
Location Address 2:	SB14995
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004487948
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S116550415**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2014
Trans1 Recv Date:	04/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487948
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002361061GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J148 **CON EDISON SERVICE BOX: 14995** **RCRA NonGen / NLR** **1017771849**
South **2074 ATLANTIC AVE FRONT OF** **FINDS** **NYP004487948**
1/8-1/4 **BROOKLYN, NY 11233**
0.127 mi.
673 ft. **Site 16 of 16 in cluster J**

Relative:
Higher

Actual:
97 ft.

RCRA Listings:

Date Form Received by Agency:	20140503
Handler Name:	Con Edison Service Box: 14995
Handler Address:	ATLANTIC AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004487948
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 14995 (Continued) **1017771849**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140503
Handler Name: CON EDISON SERVICE BOX: 14995	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 14995 (Continued) **1017771849**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063799590

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P149 **CON EDISON** **NY MANIFEST** **S116550593**
ENE **156 MACDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.128 mi.
676 ft. **Site 9 of 10 in cluster P**

Relative:
Lower

Actual:
77 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	156 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004489852
Facility Status:	Not reported
Location Address 1:	F/O 156 MACDOUGAL ST
Code:	BP
Location Address 2:	SB 28575
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004489852
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S116550593**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/04/2014
Trans1 Recv Date:	04/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004489852
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407743GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P150 **CON EDISON SERVICE BOX: 28575** **RCRA NonGen / NLR** **1017772038**
ENE **156 MACDOUGAL ST** **FINDS** **NYP004489852**
1/8-1/4 **BROOKLYN, NY 11233**
0.128 mi.
676 ft. **Site 10 of 10 in cluster P**

Relative: **Lower**
Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20140504
Handler Name:	Con Edison Service Box: 28575
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004489852
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 28575 (Continued) **1017772038**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140404
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140404
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140504
Handler Name: CON EDISON SERVICE BOX:	28575
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28575 (Continued) **1017772038**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063760265

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q151 **CON EDISON** **NY MANIFEST** **S121967248**
WNW **59 MACDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.129 mi.
679 ft. **Site 4 of 10 in cluster Q**

Relative:
Lower

Actual:
60 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	59 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004697934
Facility Status:	Not reported
Location Address 1:	59 MACDOUGAL ST
Code:	BP
Location Address 2:	SB28558
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004697934
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S121967248**

Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 11/20/2014
Trans1 Recv Date: 11/20/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004697934
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002417086GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 150
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Q152 **CON EDISON SERVICE BOX: 28558** **RCRA NonGen / NLR** **1017773235**
WNW **59 MCDOUGAL ST** **FINDS** **NYP004510152**
1/8-1/4 **BROOKLYN, NY 11233**
0.129 mi.
679 ft. **Site 5 of 10 in cluster Q**

Relative: **Lower**
Actual: **60 ft.**

RCRA Listings:

Date Form Received by Agency:	20140524
Handler Name:	Con Edison Service Box: 28558
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004510152
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 28558 (Continued) **1017773235**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140424
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140524
Handler Name: CON EDISON SERVICE BOX:	28558
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28558 (Continued) **1017773235**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063769934

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Q153 **CON EDISON** **NY MANIFEST** **S121967133**
WNW **59 MCDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.129 mi.
679 ft. **Site 6 of 10 in cluster Q**

Relative:
Lower

Actual:
60 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	59 MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004510152
Facility Status:	Not reported
Location Address 1:	59 MACDOUGAL ST
Code:	BP
Location Address 2:	SB28558
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004510152
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S121967133**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/2014
Trans1 Recv Date:	04/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004510152
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002418114GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R154 **CON ED** **NY MANIFEST** **S118464109**
NNW **179 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.131 mi.
690 ft. **Site 1 of 20 in cluster R**

Relative:
Lower

Actual:
53 ft.

NY MANIFEST:

Name:	CON ED
Address:	179 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004862062
Facility Status:	Not reported
Location Address 1:	179 SUMPTER ST
Code:	BP
Location Address 2:	SB 42247
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004862062
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004862062
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245016JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118464109**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q155 **NYC DEP** **RCRA NonGen / NLR** **1019901216**
WNW **55 MACDOUGAL PLACE** **FINDS** **NYP003669819**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.133 mi.
703 ft. **Site 7 of 10 in cluster Q**

Relative: **Lower**
Actual: **60 ft.**

RCRA Listings:

Date Form Received by Agency:	20170418
Handler Name:	Nyc Dep
Handler Address:	MACDOUGAL PLACE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP003669819
Contact Name:	JEANNE NURSE
Contact Address:	JUNCTION BLVD
Contact City,State,Zip:	FLUSHING, NY 11373
Contact Telephone:	718-595-4675
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ADMIN MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	JUNCTION BLVD
Mailing City,State,Zip:	FLUSHING, NY 11373
Owner Name:	Not reported
Owner Type:	Not reported

NYC DEP (Continued) **1019901216**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170526
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20161006
Handler Name: NYC DEP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

NYC DEP (Continued) **1019901216**

Receive Date:	20170418
Handler Name: NYC DEP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069707730

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019901216
Registry ID:	110069707730
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069707730
Name:	NYC DEP
Address:	55 MACDOUGAL PLACE
City,State,Zip:	BROOKLYN, NY 11233

Q156 **NYC DEP** **NY MANIFEST** **S119072583**
WNW **55 MACDOUGAL PLACE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.133 mi.
703 ft. **Site 8 of 10 in cluster Q**

Relative:
Lower

Actual:
60 ft.

NY MANIFEST:

Name:	NYC DEP
Address:	55 MACDOUGAL PLACE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP003669819
Facility Status:	Not reported
Location Address 1:	55 MACDOUGAL PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP003669819
Mailing Name:	NYC DEP
Mailing Contact:	NYC DEP
Mailing Address 1:	59-17 JUNCTION BLVD
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11368
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6468797328

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD049178296
Trans2 State ID:	Not reported
Generator Ship Date:	09/02/2016
Trans1 Recv Date:	09/02/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/15/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP003669819
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD083377010
TSDF ID 2:	Not reported
Manifest Tracking Number:	015339055JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

NYC DEP (Continued) **S119072583**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O157 **CON EDISON SERVICE BOX: 42249** **RCRA NonGen / NLR** **1016973484**
North **209 SUMPTER ST** **NY MANIFEST** **NYP004472874**
1/8-1/4 **BROOKLYN, NY 11233**
0.134 mi.
710 ft. **Site 5 of 6 in cluster O**

Relative: **Lower**
Actual: **55 ft.**

RCRA Listings:

Date Form Received by Agency:	20140420
Handler Name:	Con Edison Service Box: 42249
Handler Address:	SUMPTER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004472874
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 42249 (Continued) **1016973484**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140320
Handler Name: CON EDISON SERVICE BOX:	42249
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 42249 (Continued) **1016973484**

Receive Date:	20140420
Handler Name: CON EDISON SERVICE BOX:	42249
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	209 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004472874
Facility Status:	Not reported
Location Address 1:	209 SUMPTER ST
Code:	BP
Location Address 2:	SB42249
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004472874
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 42249 (Continued) **1016973484**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2014
Trans1 Recv Date:	03/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004472874
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405799GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L158 **CON EDISON** **RCRA NonGen / NLR** **1019907770**
ENE **87 HULL ST** **FINDS** **NYP004838035**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.134 mi.
710 ft. **Site 7 of 9 in cluster L**

Relative: **Higher**
Actual: **85 ft.**

RCRA Listings:

Date Form Received by Agency:	20150914
Handler Name:	Con Edison
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233

CON EDISON (Continued) **1019907770**

EPA ID:	NYP004838035
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No

CON EDISON (Continued) **1019907770**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110069640204

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

CON EDISON (Continued) **1019907770**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019907770
Registry ID:	110069640204
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069640204
Name:	CON EDISON
Address:	87 HULL ST
City,State,Zip:	BROOKLYN, NY 11233

L159 **CON EDISON** **NJ MANIFEST** **S120676650**
ENE **87 HULL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.134 mi.
710 ft. **Site 8 of 9 in cluster L**

Relative: **Higher**

Actual: **85 ft.**

NJ MANIFEST:

EPA Id:	NYP004838035
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014460113JJK
EPA ID:	NYP004838035
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120676650**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L160 **CON EDISON** **NY MANIFEST** **S118259821**
ENE **87 HULL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.134 mi.
710 ft. **Site 9 of 9 in cluster L**

Relative:
Higher

Actual:
85 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	87 HULL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004838035
Facility Status:	Not reported
Location Address 1:	87 HULL ST
Code:	BP
Location Address 2:	SB 21217
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004838035
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON (Continued) **S118259821**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004838035
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460113JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N161 **P.S. 28 THE WARREN SCHOOL** **RCRA-SQG** **1004759517**
West **1001 HERKIMER ST** **FINDS** **NYR000012039**
1/8-1/4 **BROOKLYN, NY 11233** **NY MANIFEST**
0.138 mi.
727 ft. **Site 5 of 6 in cluster N**

Relative: **Lower**
Actual: **69 ft.**

RCRA Listings:

Date Form Received by Agency:	20151020
Handler Name:	Nyc Dept Of Education - Ps 28k
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000012039
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	718-472-8500
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	SENIOR DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of School Facilities
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

P.S. 28 THE WARREN SCHOOL (Continued) **1004759517**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151209
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC BOARD OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	28-11 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-349-5600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	19130206
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC BOARD OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	28-11 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101

P.S. 28 THE WARREN SCHOOL (Continued) **1004759517**

Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES
Legal Status: Municipal
Date Became Current: 19130206
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 28 BKLYN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 28 BKLYN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950822

P.S. 28 THE WARREN SCHOOL (Continued) **1004759517**

Handler Name: NYC BD OF ED - PUBLIC SCHOOL 28 BKLYN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151020
Handler Name: NYC DEPT OF EDUCATION - PS 28K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004517746

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NY MANIFEST:
Name: NYC BOARD OF EDUCATION
Address: 1001 HERKIMER ST
City,State,Zip: BROOKLYN, NY 11233

P.S. 28 THE WARREN SCHOOL (Continued) **1004759517**

Country:	USA
EPA ID:	NYR000012039
Facility Status:	Not reported
Location Address 1:	1001 HERKIMER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000012039
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	JACK BRUCCULERI
Mailing Address 1:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183916094

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/2015
Trans1 Recv Date:	10/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/22/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000012039
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	008915142FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported

P.S. 28 THE WARREN SCHOOL (Continued) **1004759517**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	136
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B002
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N162 **P.S. 28 - BROOKLYN (TANDEM K040)** **NY AST** **A100159819**
West **1001 HERKIMER STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.138 mi.
727 ft. **Site 6 of 6 in cluster N**

Relative: **Lower**
Actual: **69 ft.**

AST:

Name:	P.S. 28 - BROOKLYN (TANDEM K040)
Address:	1001 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604477
Program Type:	PBS
UTM X:	591252.23959
UTM Y:	4503592.29980
Expiration Date:	03/31/2025
Site Type:	School

Affiliation Records:

Site Id:	26349
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2023-02-08

Site Id:	26349
Affiliation Type:	Facility Operator

P.S. 28 - BROOKLYN (TANDEM K040) (Continued) **A100159819**

Company Name:	P.S. 28 - BROOKLYN (TANDEM K040)
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 467-2865
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-10-22

Site Id:	26349
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-11-14

Site Id:	26349
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Tank Info:

Tank Number:	001
Tank Id:	57944
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

P.S. 28 - BROOKLYN (TANDEM K040) (Continued) **A100159819**

Equipment Records:
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1970
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	57945
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1970
Capacity Gallons:	7500
Tightness Test Method:	NN

P.S. 28 - BROOKLYN (TANDEM K040) (Continued) **A100159819**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Q163 **53 MACDOUGAL STREET** **NY VCP** **S128943795**
WNW **53 MACDOUGAL ST** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.139 mi.
732 ft. **Site 9 of 10 in cluster Q**

Relative: **Lower**
Actual: **60 ft.**

VCP NYC:

Project ID:	21TMP0395K,22CVCP065K
Name:	53 MACDOUGAL STREET
Address:	53 MACDOUGAL ST
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3015240043
OER Program:	VCP (Enrolled)
Phase:	Approved Remedial Plan
Latitude:	40.679232
Longitude:	-73.920178
Postcode:	3
Community Board:	41
Council District:	379
Census Tract:	3000000
BIN:	3015240043
NTA:	Stuyvesant Heights

S164 **CON EDISON SERVICE BOX: 28161** **RCRA NonGen / NLR** **1016969039**
East **170 HOPKINSON AVE** **NY MANIFEST** **NYP004426847**
1/8-1/4 **BROOKLYN, NY 11212**
0.145 mi.
767 ft. **Site 1 of 7 in cluster S**

Relative: **Higher**
Actual: **100 ft.**

RCRA Listings:

Date Form Received by Agency:	20140227
Handler Name:	Con Edison Service Box: 28161
Handler Address:	HOPKINSON AVE
Handler City,State,Zip:	BROOKLYN, NY 11212
EPA ID:	NYP004426847
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON EDISON SERVICE BOX: 28161 (Continued) **1016969039**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140127
Handler Name: CON EDISON SERVICE BOX:	28161
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny

CON EDISON SERVICE BOX: 28161 (Continued) **1016969039**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140227
Handler Name: CON EDISON SERVICE BOX:	28161
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	170 HOPKINSON AVE
City,State,Zip:	BROOKLYN, NY 11212
Country:	USA
EPA ID:	NYP004426847
Facility Status:	Not reported
Location Address 1:	AT FRON OF 170 HOPKINSON AVE
Code:	BP
Location Address 2:	SB28161
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004426847
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON SERVICE BOX: 28161 (Continued) **1016969039**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2014
Trans1 Recv Date:	01/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004426847
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329401GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	Y
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	NJD991291105
Alt Facility Sign Date:	01/31/2014
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T165 **CON ED** **NY MANIFEST** **S118464117**
NNE **229 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.147 mi.
775 ft. **Site 1 of 4 in cluster T**

Relative:
Lower

Actual:
57 ft.

NY MANIFEST:

Name:	CON ED
Address:	229 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004862237
Facility Status:	Not reported
Location Address 1:	229 SUMPTER ST
Code:	BP
Location Address 2:	SB 42255
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004862237
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004862237
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245017JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S118464117**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U166 **SHARIFA MANAGEMENT CO** **NY AST** **U003389966**
SSE **2125 PACIFIC STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.150 mi.
793 ft. **Site 1 of 7 in cluster U**

Relative:
Higher

Actual:
106 ft.

AST:

Name:	SHARIFA MANAGEMENT CO
Address:	2125 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-258792
Program Type:	PBS
UTM X:	591587.26349
UTM Y:	4503349.61648
Expiration Date:	08/17/2027
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	10736
Affiliation Type:	Facility Operator
Company Name:	SHARIFA MGMT CO
Contact Type:	Not reported
Contact Name:	OMARI FORRESTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

SHARIFA MANAGEMENT CO (Continued) **U003389966**

Phone:	(718) 342-5040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	10736
Affiliation Type:	Mail Contact
Company Name:	OMARI FORRESTER
Contact Type:	OWNER
Contact Name:	OMARI FORRESTER
Address1:	P.O. BOX 330612
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 342-5040
EMail:	SHARIFAMANAGEMENTOFCOMPANYLLC@GMAIL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-10-05

Site Id:	10736
Affiliation Type:	Emergency Contact
Company Name:	OMARI FORRESTER
Contact Type:	Not reported
Contact Name:	OMARI FORRESTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 342-5040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-04

Site Id:	10736
Affiliation Type:	Facility Owner
Company Name:	SHARIFA MANAGEMENT COMPNAY LLC
Contact Type:	OWNER
Contact Name:	OMARI FORRESTER
Address1:	P.O. BOX 330612
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 342-5040
EMail:	SHARIFAMANAGEMENTOFCOMPANYLLC@GMAIL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-10-05

SHARIFA MANAGEMENT CO (Continued) **U003389966**

Tank Info:

Tank Number:	001
Tank Id:	18066
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
B05 - Tank External Protection - Jacketed

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1962
Capacity Gallons:	2500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	10/05/2022
Material Name:	#2 fuel oil (on-site consumption)

V167 **TRI STATE TRUCK & TRAILER REPAIR INC.** **NY AST** **A100433666**
SW **1927 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.151 mi.
799 ft. **Site 1 of 11 in cluster V**

Relative:
Higher

Actual:
82 ft.

AST:

Name:	TRI STATE TRUCK & TRAILER REPAIR INC.
Address:	1927 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612675
Program Type:	PBS
UTM X:	591265.54418
UTM Y:	4503461.14585
Expiration Date:	02/13/2027
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

TRI STATE TRUCK & TRAILER REPAIR INC. (Continued) **A100433666**

Site Id:	541120
Affiliation Type:	Facility Owner
Company Name:	1927 ATLANTIC AVE. LLC
Contact Type:	PRESIDENT
Contact Name:	FRANK SCIRE
Address1:	3293 OCEAN HARBOR DRIVE
Address2:	Not reported
City:	OCEANSIDE
State:	NY
Zip Code:	11572
Country Code:	001
Phone:	(917) 270-3793
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-01-06

Site Id:	541120
Affiliation Type:	Mail Contact
Company Name:	TRI STATE TRUCK & TRAILER REPAIR INC.
Contact Type:	Not reported
Contact Name:	FRANK SCIRE
Address1:	1927 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 832-4911
EMail:	TRISTATETRUCKREPAIR@GMAIL,COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-01-06

Site Id:	541120
Affiliation Type:	Emergency Contact
Company Name:	1927 ATLANTIC AVE. LLC
Contact Type:	Not reported
Contact Name:	FRANK SCIRE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 701-1692
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-02-13

Site Id:	541120
Affiliation Type:	Facility Operator
Company Name:	TRI STATE TRUCK & TRAILER REPAIR INC.
Contact Type:	Not reported
Contact Name:	FRANK SCIRE
Address1:	Not reported

TRI STATE TRUCK & TRAILER REPAIR INC. (Continued) **A100433666**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 832-4911
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-01-06

Tank Info:

Tank Number:	001
Tank Id:	266779

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
K00 - Spill Prevention - None
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/02/2016
Capacity Gallons:	250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	266780

Equipment Records:

J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A01 - Tank Internal Protection - Epoxy Liner
K00 - Spill Prevention - None

TRI STATE TRUCK & TRAILER REPAIR INC. (Continued) **A100433666**

	B01 - Tank External Protection - Painted/Asphalt Coating
	F01 - Pipe External Protection - Painted/Asphalt Coating
	G10 - Tank Secondary Containment - Impervious Underlayment
	E01 - Piping Secondary Containment - Diking (AG only)
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/02/2016
Capacity Gallons:	250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

T168 **CON EDISON SERVICE BOX: 42256** **RCRA NonGen / NLR** **1016969355**
NNE **237 SUMPTER ST** **NY MANIFEST** **NYP004430153**
1/8-1/4 **BROOKLYN, NY 11233**
0.152 mi.
800 ft. **Site 2 of 4 in cluster T**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency:	20140228
58 ft. Handler Name:	Con Edison Service Box: 42256
Handler Address:	SUMPTER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004430153
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

CON EDISON SERVICE BOX: 42256 (Continued) **1016969355**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140130
Handler Name: CON EDISON SERVICE BOX:	42256
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140228
Handler Name: CON EDISON SERVICE BOX:	42256
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 42256 (Continued) **1016969355**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	237 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004430153
Facility Status:	Not reported
Location Address 1:	FRONT OF SUMPLER ST
Code:	BP
Location Address 2:	SB42256
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004430153
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/30/2014

CON EDISON SERVICE BOX: 42256 (Continued) **1016969355**

Trans1 Recv Date:	01/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004430153
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329550GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S169 **CON EDISON MANHOLE 65389** **RCRA NonGen / NLR** **1010327724**
ESE **HERKIMER ST & HOPKINSON AVE** **NY MANIFEST** **NYP004148367**
1/8-1/4 **BROOKLYN, NY 11206**
0.152 mi.
805 ft. **Site 2 of 7 in cluster S**

Relative:
Higher

Actual:
102 ft.

RCRA Listings:

Date Form Received by Agency:	20070411
Handler Name:	Con Edison Manhole 65389
Handler Address:	HERKIMER ST & HOPKINSON AVE
Handler City,State,Zip:	BROOKLYN, NY 11206
EPA ID:	NYP004148367
Contact Name:	STEVEN MARTIS
Contact Address:	4 IRVING PL, RM 828
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-580-8383

CON EDISON MANHOLE 65389 (Continued) **1010327724**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

CON EDISON MANHOLE 65389 (Continued) **1010327724**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20070409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070411
Handler Name: CON EDISON MANHOLE 65389	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON

CON EDISON MANHOLE 65389 (Continued) **1010327724**

Address:	HERKIMER ST & HOPKINSON AVE
City,State,Zip:	BROOKLYN, NY 11206
Country:	USA
EPA ID:	NYP004148367
Facility Status:	Not reported
Location Address 1:	THOMAS BOYLAND ST & HERKIMER
Code:	BP
Location Address 2:	MH65390
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004148367
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2007
Trans1 Recv Date:	02/26/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/27/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148367
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001450467FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141

CON EDISON MANHOLE 65389 (Continued) **1010327724**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D006
Waste Code 1_2:	D007
Waste Code 1_3:	D008
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S170 **CON EDISON** **NY MANIFEST** **S117065213**
East **171 HOPKINSON** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.153 mi.
807 ft. **Site 3 of 7 in cluster S**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	171 HOPKINSON
City,State,Zip:	BROOKLYN, NY 11212
Country:	USA
EPA ID:	NYP004577516
Facility Status:	Not reported
Location Address 1:	171 HOPKINSON AVE
Code:	BP
Location Address 2:	SB 28161
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004577516
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **S117065213**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/2014
Trans1 Recv Date:	06/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004577516
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013254888JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S171 **CON EDISON SERVICE BOX: 28161** **RCRA NonGen / NLR** **1017779740**
East **171 HOPKINSON** **FINDS** **NYP004577516**
1/8-1/4 **BROOKLYN, NY 11212**
0.153 mi.
807 ft. **Site 4 of 7 in cluster S**

Relative: RCRA Listings:
Higher

Date Form Received by Agency:	20140726
Handler Name:	Con Edison Service Box: 28161
Handler Address:	HOPKINSON
Handler City,State,Zip:	BROOKLYN, NY 11212

Actual:
100 ft.

CON EDISON SERVICE BOX: 28161 (Continued) **1017779740**

EPA ID:	NYP004577516
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No

CON EDISON SERVICE BOX: 28161 (Continued) **1017779740**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140626
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140626
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140726
Handler Name: CON EDISON SERVICE BOX:	28161
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 28161 (Continued) **1017779740**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063821155

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

S172 **CON EDISON** **NY MANIFEST** **S117067640**
East **171 THOMAS S BOYLAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.153 mi.
807 ft. **Site 5 of 7 in cluster S**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	171 THOMAS S BOYLAND ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004609715
Facility Status:	Not reported
Location Address 1:	171 THOMAS S BOYLAND ST
Code:	BP
Location Address 2:	STRUCTURE 28161
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004609715
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON (Continued) **S117067640**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/28/2014
Trans1 Recv Date:	07/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004609715
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615112GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R173 **CON EDISON** **NY MANIFEST** **S117315526**
North **FO 284 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.154 mi.
815 ft. **Site 2 of 20 in cluster R**

Relative: NY MANIFEST:
Lower

Name:	CON EDISON
Address:	FO 284 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004627030
Facility Status:	Not reported

Actual:
52 ft.

CON EDISON (Continued) **S117315526**

Location Address 1:	FO 284 MARION ST
Code:	BP
Location Address 2:	SB 75022
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004627030
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/13/2014
Trans1 Recv Date:	08/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004627030
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616135GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117315526**

Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R174 **CON EDISON** **RCRA NonGen / NLR** **1018278960**
NNW **282 MARION ST** **FINDS** **NYP004737466**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.155 mi.
816 ft. **Site 3 of 20 in cluster R**

Relative: **Lower**

Actual: **52 ft.**

RCRA Listings:

Date Form Received by Agency:	20150224
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004737466
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

CON EDISON (Continued) **1018278960**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

CON EDISON (Continued) **1018278960**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067683723

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278960
Registry ID: 110067683723
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067683723
Name: CON EDISON
Address: 282 MARION ST
City,State,Zip: BROOKLYN, NY 11233

R175 **CON EDISON** **NJ MANIFEST** **S120667807**
NNW **282 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
816 ft. **Site 4 of 20 in cluster R**

Relative: **Lower**
Actual: **52 ft.**

NJ MANIFEST:
EPA Id: NYP004737466
Mail Address: IRVING PL, 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported

CON EDISON (Continued) **S120667807**

TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610840GBF
EPA ID:	NYP004737466
Date Shipped:	2/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R176 **CON EDISON** **NY MANIFEST** **S117740575**
NNW **282 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
816 ft. **Site 5 of 20 in cluster R**

Relative: **Lower**

Actual: **52 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	282 MARION ST
City,State,Zip:	BROOKLYN, NY 11233

CON EDISON (Continued) **S117740575**

Country:	USA
EPA ID:	NYP004737466
Facility Status:	Not reported
Location Address 1:	F/O 282 MARION
Code:	BP
Location Address 2:	SB75022
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004737466
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2015
Trans1 Recv Date:	02/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004737466
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610840GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117740575**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W177 **TOWER ISLES FROZEN FOODS LTD** **NY UST** **U000394908**
ESE **2025 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
816 ft. **Site 1 of 5 in cluster W**

Relative:
Higher

Actual:
105 ft.

UST:

Name:	TOWER ISLES FROZEN FOODS LTD
Address:	2025 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-107697 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	591746.96986
UTM Y:	4503437.59589
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	3137
Affiliation Type:	Facility Owner
Company Name:	TOWER ISLES FROZEN FOODS LTD
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2025 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 495-2626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3137
Affiliation Type:	Mail Contact
Company Name:	TOWER ISLES FROZEN FOODS LTD

TOWER ISLES FROZEN FOODS LTD (Continued) **U000394908**

Contact Type:	Not reported
Contact Name:	SUPER/FACILITY MANAGER
Address1:	2025 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 495-2626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3137
Affiliation Type:	Facility Operator
Company Name:	TOWER ISLES FROZEN FOODS LTD
Contact Type:	Not reported
Contact Name:	AUBREY NEWBY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-2626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	3137
Affiliation Type:	Emergency Contact
Company Name:	TOWER ISLES FROZEN FOODS LTD
Contact Type:	Not reported
Contact Name:	AUBREY NEWBY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-2626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	3865
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	02/01/1999

TOWER ISLES FROZEN FOODS LTD (Continued) **U000394908**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	ZZ
Date Test:	12/01/1991
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G07 - Tank Secondary Containment - Excavation Liner
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H03 - Tank Leak Detection - Vapor Well
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

V178 **CON EDISON** **RCRA NonGen / NLR** **1014397127**
SW **ATLANTIC AVE & BANCROFT PL** **NJ MANIFEST** **NYP004194452**
1/8-1/4 **BROOKLYN, NY 11233** **NY MANIFEST**
0.155 mi.
817 ft. **Site 2 of 11 in cluster V**

Relative: **Higher**

Actual: **83 ft.**

RCRA Listings:

Date Form Received by Agency:	20160601
Handler Name:	Con Edison
Handler Address:	ATLANTIC AVE & BANCROFT PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004194452
Contact Name:	CAROLINE ISKANDER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CON EDISON (Continued) **1014397127**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160706
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090916
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601

CON EDISON (Continued) **1014397127**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYP004194452
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: CAROLINE ISKANDER
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 000894422GBF
EPA ID: NYP004194452
Date Shipped: 09/18/2009
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: NJD003812047
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 09/18/2009

CON EDISON (Continued) **1014397127**

Date Trans2 Transported Waste:	09/23/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/23/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	120 G

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	ATLANTIC AVE & BANCROFT PL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004194452
Facility Status:	Not reported
Location Address 1:	ATLANTIC AVE & BANCROFF PL - MH 5053
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004194452
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **1014397127**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/18/2009
Trans1 Recv Date:	09/18/2009
Trans2 Recv Date:	09/23/2009
TSD Site Recv Date:	09/23/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004194452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894422GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R179 **CON EDISON** **RCRA NonGen / NLR** **1019907338**
NNW **280 MARION ST** **FINDS** **NYP004832917**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.155 mi.
818 ft. **Site 6 of 20 in cluster R**

Relative: **Lower**
Actual: **51 ft.**

RCRA Listings:

Date Form Received by Agency:	20150901
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004832917
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019907338**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150901
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150901
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019907338**

FINDS:
Registry ID: 110069690711

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019907338
Registry ID:	110069690711
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069690711
Name:	CON EDISON
Address:	280 MARION ST
City,State,Zip:	BROOKLYN, NY 11233

R180 **CON EDISON** **NJ MANIFEST** **S120676196**
NNW **280 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
818 ft. **Site 7 of 20 in cluster R**

Relative: **Lower**

Actual: **51 ft.**

NJ MANIFEST:

EPA Id:	NYP004832917
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624844GBF
EPA ID:	NYP004832917
Date Shipped:	9/1/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120676196**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R181 **CON ED** **NY MANIFEST** **S118259498**
NNW **280 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
818 ft. **Site 8 of 20 in cluster R**

Relative: **Lower**

Actual: **51 ft.**

NY MANIFEST:

Name:	CON ED
Address:	280 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004832917
Facility Status:	Not reported
Location Address 1:	280 MARION STREET
Code:	BP
Location Address 2:	SB 30221
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004832917
Mailing Name:	CON ED

CON ED (Continued) **S118259498**

Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004832917
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624844GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON ED (Continued) **S118259498**

Waste Code 1_6: Not reported

R182 **CON EDISON** **NY MANIFEST** **S117739420**
North **292 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
819 ft. **Site 9 of 20 in cluster R**

Relative: **Lower**

Actual: **53 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	292 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004725370
Facility Status:	Not reported
Location Address 1:	292 MARION ST
Code:	BP
Location Address 2:	SB30222
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004725370
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/06/2015
Trans1 Recv Date:	02/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004725370
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610458GBF
Import Indicator:	N

CON EDISON (Continued) **S117739420**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	292 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004745386
Facility Status:	Not reported
Location Address 1:	FRONT OF 292 & MARION ST
Code:	BP
Location Address 2:	SB30222
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004745386
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117739420**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2015
Trans1 Recv Date:	03/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004745386
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611154GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R183 **CON EDISON** **NJ MANIFEST** **S120668499**
North **292 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
819 ft. **Site 10 of 20 in cluster R**

Relative:
Lower

Actual:
53 ft.

NJ MANIFEST:

EPA Id:	NYP004745386
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611154GBF
EPA ID:	NYP004745386
Date Shipped:	3/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120668499**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R184 **CON EDISON** **NJ MANIFEST** **S120666716**
North **292 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
819 ft. **Site 11 of 20 in cluster R**

Relative: **Lower**
Actual: **53 ft.**

NJ MANIFEST:

EPA Id:	NYP004725370
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610442GBF
EPA ID:	NYP004725370
Date Shipped:	2/4/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON (Continued) **S120666716**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Manifest Number:	002610458GBF
EPA ID:	NYP004725370
Date Shipped:	2/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R185 **CON EDISON** **RCRA NonGen / NLR** **1018279697**
North **292 MARION ST** **FINDS** **NYP004745386**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.155 mi.
819 ft. **Site 12 of 20 in cluster R**

Relative: **Lower**
Actual: **53 ft.**

RCRA Listings:

Date Form Received by Agency:	20150307
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004745386
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1018279697**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150307
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150307
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1018279697**

FINDS:
Registry ID: 110067694114

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279697
Registry ID:	110067694114
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067694114
Name:	CON EDISON
Address:	292 MARION ST
City,State,Zip:	BROOKLYN, NY 11233

R186 **CON EDISON** **RCRA NonGen / NLR** **1018277797**
North **292 MARION ST** **NYP004725370**
1/8-1/4 **BROOKLYN, NY 11233**
0.155 mi.
819 ft. **Site 13 of 20 in cluster R**

Relative: **Lower**

Actual: **53 ft.**

RCRA Listings:

Date Form Received by Agency:	20150204
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004725370
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CON EDISON (Continued) **1018277797**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150204
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150204

CON EDISON (Continued) **1018277797**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R187 **CON EDISON** **RCRA NonGen / NLR** **1018278959**
NNW **276 MARION ST** **FINDS** **NYP004737458**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.156 mi.
823 ft. **Site 14 of 20 in cluster R**

Relative: **Lower**

Actual: **50 ft.**

RCRA Listings:
Date Form Received by Agency: 20150224
Handler Name: Con Edison
Handler Address: MARION ST
Handler City,State,Zip: BROOKLYN, NY 11233
EPA ID: NYP004737458
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported

CON EDISON (Continued) **1018278959**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150224

CON EDISON (Continued) **1018278959**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067683714

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278959
Registry ID: 110067683714
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067683714
Name: CON EDISON
Address: 276 MARION ST
City,State,Zip: BROOKLYN, NY 11233

R188 **CON EDISON** **NY MANIFEST** **S117740574**
NNW **276 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.156 mi.
823 ft. **Site 15 of 20 in cluster R**

Relative: NY MANIFEST:
Lower
Name: CON EDISON
Actual: Address: 276 MARION ST
50 ft. City,State,Zip: BROOKLYN, NY 11233
Country: USA

CON EDISON (Continued) **S117740574**

EPA ID: NYP004737458
Facility Status: Not reported
Location Address 1: F/O 276 MARION ST
Code: BP
Location Address 2: SB30217
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004737458
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/24/2015
Trans1 Recv Date: 02/24/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/02/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004737458
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002610327GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **S117740574**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R189 **CON EDISON** **NJ MANIFEST** **S120667806**
NNW **276 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.156 mi.
823 ft. **Site 16 of 20 in cluster R**

Relative: **Lower**
Actual: **50 ft.**

NJ MANIFEST:

EPA Id:	NYP004737458
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610327GBF
EPA ID:	NYP004737458
Date Shipped:	2/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CON EDISON (Continued) **S120667806**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

O190 **CON EDISON** **NY MANIFEST** **S118259411**
North **304 MARION ST & SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11223**
0.157 mi.
830 ft. **Site 6 of 6 in cluster O**

Relative:
Lower

Actual:
52 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	304 MARION ST & SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11223
Country:	USA
EPA ID:	NYP004831430
Facility Status:	Not reported
Location Address 1:	304 MARION ST
Code:	BP
Location Address 2:	SB 30223
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004831430
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S118259411**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2015
Trans1 Recv Date:	08/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004831430
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002625243GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

X191 **CON EDISON SERVICE BOX: 30222** **RCRA NonGen / NLR** **1017774242**
North **298 MARION ST** **FINDS** **NYP004520474**
1/8-1/4 **BROOKLYN, NY 11233**
0.157 mi.
830 ft. **Site 1 of 2 in cluster X**

Relative: **Lower**
Actual: **53 ft.**

RCRA Listings:

Date Form Received by Agency:	20140603
Handler Name:	Con Edison Service Box: 30222
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004520474
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 30222 (Continued) **1017774242**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140503
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140503
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140603
Handler Name: CON EDISON SERVICE BOX:	30222
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 30222 (Continued) **1017774242**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063766875

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

X192 **CON EDISON** **NY MANIFEST** **S117059853**
North **298 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.157 mi.
830 ft. **Site 2 of 2 in cluster X**

Relative:
Lower

Actual:
53 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	298 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004520474
Facility Status:	Not reported
Location Address 1:	298 MARION ST
Code:	BP
Location Address 2:	SB30222
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004520474
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117059853**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/03/2014
Trans1 Recv Date:	05/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004520474
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002358709GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R193
NNW
1/8-1/4
0.159 mi.
837 ft.

CON EDISON
FRONT OF 270 MARION ST
BROOKLYN, NY 11233

Site 17 of 20 in cluster R

NY MANIFEST **S117318848**
N/A

Relative:
Lower

Actual:
49 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 270 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004664389
Facility Status:	Not reported
Location Address 1:	FRONT OF 270 MARION ST
Code:	BP
Location Address 2:	SB30220
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004664389
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2014
Trans1 Recv Date:	09/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004664389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617562GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117318848**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y194 **CON EDISON** **NY MANIFEST** **S117317398**
West **985 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.159 mi.
839 ft. **Site 1 of 4 in cluster Y**

Relative: **Lower**

Actual: **66 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	985 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004648226
Facility Status:	Not reported
Location Address 1:	985 HERKIMER ST
Code:	BP
Location Address 2:	SB20989
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004648226
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117317398**

Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 09/04/2014
Trans1 Recv Date: 09/04/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004648226
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616809GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 160
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Y195 **CON EDISON** **NY MANIFEST** **S117313503**
West **F/O 985 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.159 mi.
839 ft. **Site 2 of 4 in cluster Y**

Relative:
Lower

Actual:
66 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 985 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004602181
Facility Status:	Not reported
Location Address 1:	F/O 985 HERKIMER ST
Code:	BP
Location Address 2:	SB20989
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004602181
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004602181
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774102JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117313503**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y196 **CON EDISON** **NY MANIFEST** **S117319349**
West **985 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.159 mi.
839 ft. **Site 3 of 4 in cluster Y**

Relative: **Lower**

Actual: **66 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	985 HERKIMER ST
City,State,Zip:	BROOKLYN, NY
Country:	USA
EPA ID:	NYP004670741
Facility Status:	Not reported
Location Address 1:	985 HERKIMER ST
Code:	BP
Location Address 2:	STRUCTURE # 20989
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004670741
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117319349**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/02/2014
Trans1 Recv Date:	10/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004670741
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617716GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V197 **1921 LIHTC LLC - 1921 ATLANTIC AVE BCP #224279** **RCRA NonGen / NLR** **1026498448**
WSW **1921 ATLANTIC AVE** **NYR000247809**
1/8-1/4 **BROOKLYN, NY 11233**
0.159 mi.
840 ft. **Site 3 of 11 in cluster V**

Relative: **Lower**
Actual: **79 ft.**

RCRA Listings:

Date Form Received by Agency:	20220214
Handler Name:	1921 Lihtc Llc - 1921 Atlantic Ave Bcp #224279
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000247809
Contact Name:	DAWANNA WILLIAMS
Contact Address:	MADISON AVE 3RD FL DTF ATLANTIC C/O DABAR DEV
Contact City,State,Zip:	NEW YORK, NY 10017
Contact Telephone:	212-653-8878
Contact Fax:	Not reported
Contact Email:	DWILLIAMS@DABARDEVELOPMENT.COM
Contact Title:	CO-MANAGING MEMBER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	MADISON AVE 3RD FL DTF ATLANTIC C/O DABAR DEV
Mailing City,State,Zip:	NEW YORK, NY 10017
Owner Name:	Hp 1921 Atlantic Ave Housing Development Fund Company Inc
Owner Type:	Private
Operator Name:	1921 Lihtc Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

1921 LIHTC LLC - 1921 ATLANTIC AVE BCP #224279 (Continued) **1026498448**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230124
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: 1921 LIHTC LLC	
Legal Status:	Private
Date Became Current:	20200820
Date Ended Current:	Not reported
Owner/Operator Address:	315 MADISON AVE 1921 LIHTC C/O DABAR DEVELOPMENT
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-653-8878
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	DWILLIAMS@DABARDEVELOPMENT.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: HP 1921 ATLANTIC AVE HOUSING DEVELOPMENT FUND COMPANY, INC.	
Legal Status:	Private
Date Became Current:	20200820
Date Ended Current:	Not reported
Owner/Operator Address:	253 WEST 35TH ST 3RD FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10001
Owner/Operator Telephone:	626-217-3390
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	CKAY@HOUSINGPARTNERSHIP.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: 1921 LIHTC LLC	
Legal Status:	Private
Date Became Current:	20200820
Date Ended Current:	Not reported
Owner/Operator Address:	315 MADISON AVENUE
Owner/Operator City,State,Zip:	NEW YORK, NY 10017
Owner/Operator Telephone:	212-653-8878
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

1921 LIHTC LLC - 1921 ATLANTIC AVE BCP #224279 (Continued) **1026498448**

Owner/Operator Email: DWILLIAMS@DABARDEVELOPMENT.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: HP 1921 ATLANTIC AVE HOUSING DEVELOPMENT FUND COMPANY INC
Legal Status: Private
Date Became Current: 20200820
Date Ended Current: Not reported
Owner/Operator Address: 253 W 35TH ST 3RD FL
Owner/Operator City,State,Zip: NEW YORK, NY 10001
Owner/Operator Telephone: 626-217-3390
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: CKAY@HOUSINGPARTNERSHIP.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: 1921 LIHTC LLC
Legal Status: Private
Date Became Current: 20200820
Date Ended Current: Not reported
Owner/Operator Address: 315 MADISON AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-653-8878
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: DWILLIAMS@DABARDEVELOPMENT.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: HP 1921 ATLANTIC AVENUE HOUSING DEVELOPMENT FUND COMPANY, INC.
Legal Status: Private
Date Became Current: 20200820
Date Ended Current: Not reported
Owner/Operator Address: 253 WEST 35TH STREET, 3RD FL
Owner/Operator City,State,Zip: NEW YORK, NY 10001
Owner/Operator Telephone: 626-217-3390
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: CKAY@HOUSINGPARTNERSHIP.COM

Historic Generators:
Receive Date: 20210224
Handler Name: 1921 LIHTC LLC-1921 ATLANTIC AVENUE BCP SITE 224279
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220214
Handler Name: 1921 LIHTC LLC - 1921 ATLANTIC AVE BCP #224279
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

1921 LIHTC LLC - 1921 ATLANTIC AVE BCP #224279 (Continued) **1026498448**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20201020
Handler Name:	1921 ATLANTIC AVE BCP SITE NO 224279
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	531110
NAICS Description:	LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

Z198 **CON EDISON** **NY MANIFEST** **S116551485**
NW **F/O 153 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.159 mi.
840 ft. **Site 1 of 5 in cluster Z**

Relative:
Lower

Actual:
51 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 153 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004499745
Facility Status:	Not reported
Location Address 1:	F/O 153 SUMPTER ST
Code:	BP
Location Address 2:	SB42241
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004499745
Mailing Name:	CON EDISON

CON EDISON (Continued) **S116551485**

Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/2014
Trans1 Recv Date:	04/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004499745
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406707GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S116551485**

Waste Code 1_6: Not reported

Z199 **CON EDISON** **NJ MANIFEST** **S120668543**
NW **153 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.159 mi.
840 ft. **Site 2 of 5 in cluster Z**

Relative: **Lower**

Actual: **51 ft.**

NJ MANIFEST:

EPA Id:	NYP004745857
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002611175GBF
EPA ID:	NYP004745857
Date Shipped:	3/8/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S120668543**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Z200 **CON EDISON** **NY MANIFEST** **S117741360**
NW **153 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.159 mi.
840 ft. **Site 3 of 5 in cluster Z**

Relative: **Lower**

Actual: **51 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	153 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004745857
Facility Status:	Not reported
Location Address 1:	153 SUMPTER ST
Code:	BP
Location Address 2:	SB 42241
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004745857
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	03/08/2015
Trans1 Recv Date:	03/08/2015
Trans2 Recv Date:	03/11/2015

CON EDISON (Continued) **S117741360**

TSD Site Recv Date:	03/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004745857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002611175GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z201 **CON EDISON** **RCRA NonGen / NLR** **1018279743**
NW **153 SUMPTER ST** **FINDS** **NYP004745857**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.159 mi.
840 ft. **Site 4 of 5 in cluster Z**

Relative: **Lower**
Actual: **51 ft.**

RCRA Listings:

Date Form Received by Agency:	20150308
Handler Name:	Con Edison
Handler Address:	SUMPTER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004745857
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported

CON EDISON (Continued) **1018279743**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1018279743**

Historic Generators:
Receive Date: 20150308
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150308
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067695382

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279743
Registry ID: 110067695382

CON EDISON (Continued) **1018279743**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067695382
Name: CON EDISON
Address: 153 SUMPTER ST
City,State,Zip: BROOKLYN, NY 11233

W202 **2170 ATLANTIC AVE** **NY AST** **A100291800**
SE **2170 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.160 mi.
845 ft. **Site 2 of 5 in cluster W**

Relative:
Higher

Actual:
106 ft.

AST:
Name: 2170 ATLANTIC AVE
Address: 2170 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11233
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-609714
Program Type: PBS
UTM X: 591708.89277
UTM Y: 4503400.32535
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 59192
Affiliation Type: Mail Contact
Company Name: MHANY 2002 H.D.F.C.
Contact Type: Not reported
Contact Name: MHANY MGMT
Address1: 2-4 NEVINS ST. 2ND FLOOR
Address2: Not reported
City: BROOKYLN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (718) 246-8080
EMail: ISPELIOTIS@MUTUALHOUSINGNY.ORG
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-08-08

Site Id: 59192
Affiliation Type: Facility Operator
Company Name: 2170 ATLANTIC AVE
Contact Type: Not reported
Contact Name: MHANY MGMT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 246-8080
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS

2170 ATLANTIC AVE (Continued) **A100291800**

Date Last Modified: 2014-08-08

Site Id: 59192
Affiliation Type: Emergency Contact
Company Name: NEIGHBORHOOD RESTORE HDFC
Contact Type: Not reported
Contact Name: VANESSA PETERSON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 463-1200
EMail: Not reported
Fax Number: Not reported
Modified By: dxliving
Date Last Modified: 2008-12-10

Site Id: 59192
Affiliation Type: Facility Owner
Company Name: MHANY 2002 H.D.F.C.
Contact Type: EX DIR.
Contact Name: ISIMENE SPEOLITOIS
Address1: 2-4 NEVINS ST. 2ND FLOOR
Address2: Not reported
City: BROOKYLN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (718) 246-8080
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-08-08

Tank Info:

Tank Number: 01
Tank Id: 180262
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

2170 ATLANTIC AVE (Continued) **A100291800**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/17/2011
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

R203 **CON EDISON** **NJ MANIFEST** **S120667804**
NNW **266 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.161 mi.
849 ft. **Site 18 of 20 in cluster R**

Relative: **Lower**
Actual: **48 ft.**

NJ MANIFEST:

EPA Id:	NYP004737433
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002659261GBF
EPA ID:	NYP004737433
Date Shipped:	2/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

CON EDISON (Continued) **S120667804**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R204 **CON EDISON** **NY MANIFEST** **S117740572**
NNW **266 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.161 mi.
849 ft. **Site 19 of 20 in cluster R**

Relative: **Lower**
Actual: **48 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	266 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004737433
Facility Status:	Not reported
Location Address 1:	F/O 266 MARION ST
Code:	BP
Location Address 2:	SB30220
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004737433
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117740572**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2015
Trans1 Recv Date:	02/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004737433
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002659261GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R205 **CON EDISON** **RCRA NonGen / NLR** **1018278957**
NNW **266 MARION ST** **FINDS** **NYP004737433**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.161 mi.
849 ft. **Site 20 of 20 in cluster R**

Relative: **Lower**
Actual: **48 ft.**

RCRA Listings:

Date Form Received by Agency:	20150224
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004737433
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1018278957**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1018278957**

FINDS:
Registry ID: 110067683698

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278957
Registry ID:	110067683698
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067683698
Name:	CON EDISON
Address:	266 MARION ST
City,State,Zip:	BROOKLYN, NY 11233

AA206 **138 HOPKINSON ASSOCIATES LLC** **NY AST** **A100291446**
ENE **138 HOPKINSON AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.162 mi.
853 ft. **Site 1 of 3 in cluster AA**

Relative:
Lower

Actual:
76 ft.

AST:

Name:	138 HOPKINSON ASSOCIATES LLC
Address:	138 HOPKINSON AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608581
Program Type:	PBS
UTM X:	591777.22081
UTM Y:	4503769.22920
Expiration Date:	03/14/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30433
Affiliation Type:	Mail Contact
Company Name:	PROTO PROPERTY SERVICES LLC
Contact Type:	Not reported
Contact Name:	DEMETRIUS MORAGIANIS
Address1:	3441 KINGSBRIDGE AVE 2ND FL
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10463
Country Code:	001
Phone:	(718) 601-1483
EMail:	Not reported
Fax Number:	Not reported

138 HOPKINSON ASSOCIATES LLC (Continued) **A100291446**

Modified By:	DMPOKRZY
Date Last Modified:	2017-12-26
Site Id:	30433
Affiliation Type:	Facility Operator
Company Name:	138 HOPKINSON ASSOCIATES LLC
Contact Type:	Not reported
Contact Name:	EULALIO CABALLERO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 771-2290
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2018-03-15
Site Id:	30433
Affiliation Type:	Emergency Contact
Company Name:	138 HOPKINSON ASSOCIATES LLC % PROTO PROPERTY SVCS
Contact Type:	Not reported
Contact Name:	SHERLOCK BARONA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 601-1483
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	30433
Affiliation Type:	Facility Owner
Company Name:	138 HOPKINSON ASSOCIATES LLC % PROTO PROPERTY SVCS
Contact Type:	PROPERTY MANAGER
Contact Name:	DEMETRIOS MORAGANIS
Address1:	3441 KINGSBRIDGE AVE 2ND FL
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10463
Country Code:	001
Phone:	(718) 601-1483
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-12-26

Tank Info:

Tank Number:	001

138 HOPKINSON ASSOCIATES LLC (Continued) **A100291446**

Tank Id:	65348
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1942
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

U207 **VERIZON** **RCRA NonGen / NLR** **1014395197**
SSE **SARATOGA AVE & PACIFIC ST** **NYP000964486**
1/8-1/4 **BROOKLYN, NY 11233**
0.162 mi.
853 ft. **Site 2 of 7 in cluster U**

Relative:
Higher

Actual:
111 ft.

RCRA Listings:

Date Form Received by Agency:	20090219
Handler Name:	Verizon
Handler Address:	SARATOGA AVE & PACIFIC ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP000964486
Contact Name:	BILL IRWIN
Contact Address:	HANSE AVE
Contact City,State,Zip:	FREEPORT, NY 11520
Contact Telephone:	917-837-3985
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	ENVIRONMENTAL SPEC
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

VERIZON (Continued) **1014395197**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	HANSE AVE
Mailing City,State,Zip:	FREEPORT, NY 11520
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211102
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090219
Handler Name: VERIZON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported

VERIZON (Continued) **1014395197**

Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

U208 **CON EDISON** **RCRA NonGen / NLR** **1019902841**
SSE **SARATOGA AVE & PACIFIC ST** **NYP004778452**
1/8-1/4 **BROOKLYN, NY 11215**
0.162 mi.
853 ft. **Site 3 of 7 in cluster U**

Relative: **Higher**
Actual: **111 ft.**

RCRA Listings:
Date Form Received by Agency: 20150504
Handler Name: Con Edison
Handler Address: SARATOGA AVE & PACIFIC ST
Handler City,State,Zip: BROOKLYN, NY 11215
EPA ID: NYP004778452
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No

CON EDISON (Continued) **1019902841**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150504
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150504
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1019902841**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

U209 **CON EDISON** **NJ MANIFEST** **S120671410**
SSE **SARATOGA AVE & PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.162 mi.
853 ft. **Site 4 of 7 in cluster U**

Relative:
Higher

Actual:
111 ft.

NJ MANIFEST:
EPA Id: NYP004778452
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 014454482JJK
EPA ID: NYP004778452
Date Shipped: 5/4/2015
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported

CON EDISON (Continued) **S120671410**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

U210 **CON EDISON** **NY MANIFEST** **S119075075**
SSE **SARATOGA AVE & PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11215**
0.162 mi.
853 ft. **Site 5 of 7 in cluster U**

Relative:
Higher

Actual:
111 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	SARATOGA AVE & PACIFIC ST
City,State,Zip:	BROOKLYN, NY 11215
Country:	USA
EPA ID:	NYP004778452
Facility Status:	Not reported
Location Address 1:	ATLANTIC AVE & SARATOGA AVE
Code:	BP
Location Address 2:	MH 5056
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004778452
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S119075075**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/04/2015
Trans1 Recv Date:	05/04/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004778452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454482JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U211 **BELL ATLANTIC-NY** **RCRA NonGen / NLR** **1007205530**
SSE **SARATOGA AVE/PACIFIC ST** **NY MANIFEST** **NYP000935304**
1/8-1/4 **BROOKLYN, NY 00000**
0.162 mi.
857 ft. **Site 6 of 7 in cluster U**

Relative: **Higher**
Actual: **111 ft.**

RCRA Listings:

Date Form Received by Agency:	19980301
Handler Name:	Bell Atlantic-Ny
Handler Address:	SARATOGA AVE/PACIFIC ST
Handler City,State,Zip:	BROOKLYN, NY 00000-0000
EPA ID:	NYP000935304
Contact Name:	JOHN QUATRALE
Contact Address:	ENVIRONMENTAL AFFAIRS
Contact City,State,Zip:	NEW YORK, NY 10016-0000
Contact Telephone:	212-338-7141
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ENVIRONMENTAL AFFAIRS
Mailing City,State,Zip:	NEW YORK, NY 10016-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

BELL ATLANTIC-NY (Continued) **1007205530**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980228
Handler Name: BELL ATLANTIC-NY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980301
Handler Name: BELL ATLANTIC-NY	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980227
Handler Name: BELL ATLANTIC-NY	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

BELL ATLANTIC-NY (Continued) **1007205530**

List of NAICS Codes and Descriptions:
NAICS Code: 5133
NAICS Description: TELECOMMUNICATIONS

NAICS Code: 51331
NAICS Description: WIRED TELECOMMUNICATIONS CARRIERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: BELL ATLANTIC-NY
Address: SARATOGA AVE/PACIFIC ST
City,State,Zip: BROOKLYN, NY 00000-0000
Country: USA
EPA ID: NYP000935304
Facility Status: Not reported
Location Address 1: SARATOGA AVE/PACIFIC ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000935304
Mailing Name: BELL ATLANTIC-NY
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Zip 4: Not reported
Mailing Country: Not reported
Mailing Phone: Not reported

V212 **CON EDISON** **NY MANIFEST** **S116550414**
SW **2038 ATLANTIC AVE FRONT OF** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.163 mi.
863 ft. **Site 4 of 11 in cluster V**

Relative: NY MANIFEST:
Higher
Name: CON EDISON
Actual: Address: 2038 ATLANTIC AVE FRONT OF
88 ft. City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004487930

CON EDISON (Continued) **S116550414**

Facility Status:	Not reported
Location Address 1:	2038 ATLANTIC AV
Code:	BP
Location Address 2:	SB14991
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004487930
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2014
Trans1 Recv Date:	04/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004487930
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002361186GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S116550414**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V213 **CON EDISON SERVICE BOX: 14991** **RCRA NonGen / NLR** **1017771848**
SW **2038 ATLANTIC AVE FRONT OF** **NYP004487930**
1/8-1/4 **BROOKLYN, NY 11233**
0.163 mi.
863 ft. **Site 5 of 11 in cluster V**

Relative:
Higher

Actual:
88 ft.

RCRA Listings:

Date Form Received by Agency:	20140503
Handler Name:	Con Edison Service Box: 14991
Handler Address:	ATLANTIC AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004487930
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON SERVICE BOX: 14991 (Continued) **1017771848**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 14991 (Continued) **1017771848**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140503
Handler Name: CON EDISON SERVICE BOX:	14991
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Q214 **CON EDISON** **NY MANIFEST** **S116551486**
WNW **OPP 116 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.165 mi.
872 ft. **Site 10 of 10 in cluster Q**

Relative: **Lower**
Actual: **57 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 116 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004499752
Facility Status:	Not reported
Location Address 1:	OPP 116 SUMPTER ST
Code:	BP
Location Address 2:	SB42240
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004499752
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S116551486**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/2014
Trans1 Recv Date:	04/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004499752
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406708GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W215 **CON EDISON SERVICE BOX: 28164** **RCRA NonGen / NLR** **1016972079**
ESE **217 HOPKINSON AVE** **NY MANIFEST** **NYP004458394**
1/8-1/4 **BROOKLYN, NY 11212**
0.166 mi.
879 ft. **Site 3 of 5 in cluster W**

Relative: **Higher**

Actual: **103 ft.**

RCRA Listings:

Date Form Received by Agency:	20140405
Handler Name:	Con Edison Service Box: 28164
Handler Address:	HOPKINSON AVE
Handler City,State,Zip:	BROOKLYN, NY 11212
EPA ID:	NYP004458394
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 28164 (Continued) **1016972079**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140305
Handler Name: CON EDISON SERVICE BOX:	28164
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140405
Handler Name: CON EDISON SERVICE BOX:	28164
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 28164 (Continued) **1016972079**

NY MANIFEST:

Name:	CON ED
Address:	217 HOPKINSON AVE
City,State,Zip:	BROOKLYN, NY 11212
Country:	USA
EPA ID:	NYP004458394
Facility Status:	Not reported
Location Address 1:	OPP 217 THOMAS BOYLAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004458394
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2014
Trans1 Recv Date:	03/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004458394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360331GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 28164 (Continued) **1016972079**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB216 **CON EDISON** **NY MANIFEST** **S117741672**
SE **2151 PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.169 mi.
891 ft. **Site 1 of 3 in cluster AB**

Relative:
Higher

Actual:
110 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	2151 PACIFIC ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004749131
Facility Status:	Not reported
Location Address 1:	2151 PACIFIC ST
Code:	BP
Location Address 2:	SB 33401
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004749131
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117741672**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/2015
Trans1 Recv Date:	03/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004749131
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619019GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB217
SE
1/8-1/4
0.169 mi.
891 ft.

CON EDISON
2151 PACIFIC ST
BROOKLYN, NY 11233

Site 2 of 3 in cluster AB

NJ MANIFEST **S120668822**
N/A

Relative:
Higher

Actual:
110 ft.

NJ MANIFEST:

EPA Id:	NYP004749131
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619019GBF
EPA ID:	NYP004749131
Date Shipped:	3/11/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120668822**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB218 **CON EDISON** **RCRA NonGen / NLR** **1018280054**
SE **2151 PACIFIC ST** **FINDS** **NYP004749131**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.169 mi.
891 ft. **Site 3 of 3 in cluster AB**

Relative: **Higher**
Actual: **110 ft.**

RCRA Listings:

Date Form Received by Agency:	20150311
Handler Name:	Con Edison
Handler Address:	PACIFIC ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004749131
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON (Continued) **1018280054**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150311
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150311
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1018280054**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067701213

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280054
Registry ID:	110067701213
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067701213
Name:	CON EDISON
Address:	2151 PACIFIC ST
City,State,Zip:	BROOKLYN, NY 11233

T219 **CON EDISON SERVICE BOX: 30229** **RCRA NonGen / NLR** **1016973226**
NNE **322 MARION ST** **NY MANIFEST** **NYP004470209**
1/8-1/4 **BROOKLYN, NY 11233**
0.171 mi.
903 ft. **Site 3 of 4 in cluster T**

Relative:
Lower

Actual:
53 ft.

RCRA Listings:

Date Form Received by Agency:	20140418
Handler Name:	Con Edison Service Box: 30229
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004470209
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

CON EDISON SERVICE BOX: 30229 (Continued) **1016973226**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140318
Handler Name: CON EDISON SERVICE BOX:	30229
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 30229 (Continued) **1016973226**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140418
Handler Name: CON EDISON SERVICE BOX:	30229
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	322 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004470209
Facility Status:	Not reported
Location Address 1:	322 MARION ST
Code:	BP
Location Address 2:	SB30229
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004470209
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON SERVICE BOX: 30229 (Continued) **1016973226**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/18/2014
Trans1 Recv Date:	03/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004470209
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405846GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC220
NE
1/8-1/4
0.171 mi.
905 ft.

CON EDISON - SERVICE BOX 42257
255 SUMPTER ST
BROOKLYN, NY 11233

Site 1 of 3 in cluster AC

NY MANIFEST **S120958420**
N/A

Relative:
Lower

Actual:
62 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 42257
Address:	255 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004936118
Facility Status:	Not reported
Location Address 1:	255 SUMPTER ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004936118
Mailing Name:	CON EDISON - SERVICE BOX 42257
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AD221
South
1/8-1/4
0.174 mi.
918 ft.

CON EDISON
2042A PACIFIC ST
BROOKLYN, NY 11223

Site 1 of 3 in cluster AD

NY MANIFEST **S118258339**
N/A

Relative:
Higher

Actual:
103 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	2042A PACIFIC ST
City,State,Zip:	BROOKLYN, NY 11223
Country:	USA
EPA ID:	NYP004813909
Facility Status:	Not reported
Location Address 1:	2042 PACIFIC ST
Code:	BP
Location Address 2:	SB 33397
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004813909
Mailing Name:	CON EDISON

CON EDISON (Continued) **S118258339**

Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/28/2015
Trans1 Recv Date:	07/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004813909
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619681GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

CON EDISON (Continued) **S118258339**

Waste Code 1_6: Not reported

AD222 **CON EDISON** **RCRA NonGen / NLR** **1019905821**
South **2042A PACIFIC ST** **FINDS** **NYP004813909**
1/8-1/4 **BROOKLYN, NY 11223** **ECHO**
0.174 mi.
918 ft. **Site 2 of 3 in cluster AD**

Relative: **Higher**

Actual: **103 ft.**

RCRA Listings:

Date Form Received by Agency:	20150728
Handler Name:	Con Edison
Handler Address:	PACIFIC ST
Handler City,State,Zip:	BROOKLYN, NY 11223
EPA ID:	NYP004813909
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CON EDISON (Continued) **1019905821**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150728
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150728
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON (Continued) **1019905821**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069693004

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019905821
Registry ID:	110069693004
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069693004
Name:	CON EDISON
Address:	2042A PACIFIC ST
City,State,Zip:	BROOKLYN, NY 11223

AD223 **CON EDISON** **NJ MANIFEST** **S120674553**
South **2042A PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11223**
0.174 mi.
918 ft. **Site 3 of 3 in cluster AD**

Relative:
Higher

Actual:
103 ft.

NJ MANIFEST:

EPA Id:	NYP004813909
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619681GBF
EPA ID:	NYP004813909
Date Shipped:	7/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120674553**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

U224 **AFRO CARTING CO.** **NY SWF/LF** **S105841702**
SSE **286 SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.176 mi.
929 ft. **Site 7 of 7 in cluster U**

Relative:
Higher

Actual:
110 ft.

SWF/LF:

Name:	AFRO CARTING CO.
Address:	286 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11233
Flag:	INACTIVE
Region Code:	2
Phone Number:	7180000000
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	(UNKNOWN)
Contact Address:	Not reported

AFRO CARTING CO. (Continued) **S105841702**

Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T10]
Active:	No
East Coordinate:	591550
North Coordinate:	4503324
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AE225 **CON EDISON** **NJ MANIFEST** **S120676653**
ENE **84 HULL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.176 mi.
930 ft. **Site 1 of 7 in cluster AE**

Relative:
Higher

Actual:
94 ft.

NJ MANIFEST:

EPA Id:	NYP004838068
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014086173JJK
EPA ID:	NYP004838068
Date Shipped:	9/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CON EDISON (Continued) **S120676653**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AE226 **CON EDISON** **NY MANIFEST** **S118259824**
ENE **84 HULL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.176 mi.
930 ft. **Site 2 of 7 in cluster AE**

Relative:
Higher

Actual:
94 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	84 HULL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004838068
Facility Status:	Not reported
Location Address 1:	84 HULL ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004838068
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **S118259824**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/14/2015
Trans1 Recv Date:	09/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004838068
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014086173JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE227 **CON EDISON** **RCRA NonGen / NLR** **1019325568**
ENE **84 HULL ST** **NYP004838068**
1/8-1/4 **BROOKLYN, NY 11233**
0.176 mi.
930 ft. **Site 3 of 7 in cluster AE**

Relative: **Higher**
Actual: **94 ft.**

RCRA Listings:

Date Form Received by Agency:	20150914
Handler Name:	Con Edison
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004838068
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019325568**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150914
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150914
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160205
Handler Name:	CON EDISON - SERVICE BOX 2500
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON (Continued) **1019325568**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150914
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AF228 **REGIONAL MGMT & CONSULTING INC** **RCRA NonGen / NLR** **1007112720**
SSW **HOWARD AVE & PACIFIC ST** **NYR000120360**
1/8-1/4 **BROOKLYN, NY 11233**
0.177 mi.
932 ft. **Site 1 of 3 in cluster AF**

Relative: **Higher**

Actual: **95 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Regional Mgmt & Consulting Inc
Handler Address:	HOWARD AVE & PACIFIC ST

REGIONAL MGMT & CONSULTING INC (Continued) **1007112720**

Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000120360
Contact Name:	BOGDAN SZCZUREK
Contact Address:	BRIDGEWATER ST
Contact City,State,Zip:	BROOKLYN, NY 11222
Contact Telephone:	718-599-3718
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BRIDGEWATER ST
Mailing City,State,Zip:	BROOKLYN, NY 11222
Owner Name:	Nyc Dept Of Parks & Recreation
Owner Type:	Municipal
Operator Name:	No Name Found
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414

REGIONAL MGMT & CONSULTING INC (Continued) **1007112720**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	REGIONAL MGMT & CONSULTING INC
Legal Status:	Private
Date Became Current:	19791231
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	NY
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF PARKS & RECREATION
Legal Status:	Municipal
Date Became Current:	19791231
Date Ended Current:	Not reported
Owner/Operator Address:	OLMSTED CENTER CORONA PARK
Owner/Operator City,State,Zip:	FLUSHING, NY 11368
Owner/Operator Telephone:	718-760-6761
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NO NAME FOUND
Legal Status:	Private
Date Became Current:	19791231
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	NY
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF PARKS & RECREATION
Legal Status:	Municipal
Date Became Current:	19791231
Date Ended Current:	Not reported
Owner/Operator Address:	OLMSTED CENTER CORONA PARK
Owner/Operator City,State,Zip:	FLUSHING, NY 11368
Owner/Operator Telephone:	718-760-6761
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

REGIONAL MGMT & CONSULTING INC (Continued) **1007112720**

Historic Generators:

Receive Date:	20060101
Handler Name:	REGIONAL MGMT & CONSULTING INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	REGIONAL MGMT & CONSULTING INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20031118
Handler Name:	REGIONAL MGMT & CONSULTING INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	54133
NAICS Description:	ENGINEERING SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

V229 **1921 ATLANTIC AVENUE SITE** **NY BROWNFIELDS** **S125395150**
WSW **1911 ATLANTIC AVENUE** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.177 mi.
935 ft. **Site 6 of 11 in cluster V**

Relative:
Lower

Actual:
77 ft.

BROWNFIELDS:

Name:	1921 ATLANTIC AVENUE SITE
Address:	1911 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Program:	BCP
Site Code:	571794
Acres:	0.690
HW Code:	C224279
SWIS:	2401
Town:	New York City
Record Added Date:	06/21/2018
Record Updated Date:	10/04/2022
Update By:	AMSERVIS
Site Description:	Site Location: The site consists of one parcel located at 1911 Atlantic Avenue, identified as Block 1557 and Lot 38, in the Bedford-Stuyvesant neighborhood of Brooklyn, NY. The site is bounded by Bancroft Place to the east, Atlantic Avenue to the south, Prescott Place to the west, and residential buildings to the north. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: The site is 30,164 square-feet (0.69 acres) in area and is currently being redeveloped with a 100% affordable housing 14 story mixed use residential building. Current Zoning and Land Use: The site is currently zoned for M1-1/R7D for industrial, commercial, and residential use and is also within the Atlantic Avenue Special Mixed-Use District (MX-10). The surrounding properties are currently used as multi-story residential and commercial buildings. Long Island Railroad tracks are south of the site in the center of Atlantic Avenue. Past Use of the Site: Historical usage of the site indicates that it was first developed sometime prior to 1888 and used for residential purposes from sometime prior to 1888 to 1934. From approximately 1934 to 2005 the site was mostly used for commercial purposes with some residential remaining. In 1934, the subject property was listed in the city directory as having an oil and gas service station occupying lot 37. Lots 37 and 38 were used as a gas station and for auto repair. Lot 37 was operated by Ben VI Service Station. Additionally, Lot 38 was operated by CYS Auto Body Shop. The property has been vacant since 2006. Site Geology and Hydrogeology: Based on soil borings completed during the Remedial Investigation (RI) and Supplemental Remedial Investigation (SRI), the site is underlain by a historic fill material layer approximately seven to nine feet thick. Below this historic fill material, native soils were encountered consisting of silt or fine brown sand with gravel. The non-native historic fill material generally appears to consist of brown silty sands, concrete, brick, and other construction debris. No confining units were encountered in the soil borings. The depth to bedrock is expected to be greater than 100 feet below ground surface. Based on groundwater monitoring well data collected during the RI and SRI, the depth to groundwater beneath the site is approximately 70 feet below ground surface. The direction of groundwater flow is toward the east-southeast. The site appears to be at or close to the hydrogeologic divide, therefore, groundwater flow direction may be subject to change. There are no public water supply wells within a

1921 ATLANTIC AVENUE SITE (Continued) **S125395150**

	one-mile radius of the subject property.
Env Problem:	Environmental Assessment: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were heavy metals, SVOCs, pesticides and PCBs in soil. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use.
Health Problem:	Remedial actions are complete for this site and the potential for people coming in contact with site contamination was addressed by the remedy.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-10-01 13:52:00
Record Upd:	2021-07-19 12:56:00
Updated By:	GWBURKE
Own Op:	6
Sub Type:	P03
Owner Name:	Dawanna Williams
Owner Company:	DTF Atlantic, LLC
Owner Address:	315 Madison Avenue. 3rd Floor
Owner Addr2:	c/o Dabar Development
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Linda E. Johnson
Owner Company:	Brooklyn Public Library
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Dawanna Williams
Owner Company:	HP 1921 Atlantic Avenue Housing Development Fund Company, IN
Owner Address:	242 West 36th Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dawanna Williams
Owner Company:	1921 LIHTC LLC
Owner Address:	315 Madison Avenue, 3rd Floor
Owner Addr2:	c/o Dabar Development
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Henry L. Butler
Owner Company:	Brooklyn Community Board No. 3
Owner Address:	1360 Fulton Street

1921 ATLANTIC AVENUE SITE (Continued) **S125395150**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dawanna Williams
Owner Company:	1921 LIHTC LLC
Owner Address:	315 Madison Avenue, 3rd Floor
Owner Addr2:	c/o Dabar Development
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	C224279
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	lead

1921 ATLANTIC AVENUE SITE (Continued) **S125395150**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	PCB aroclor 1254
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	DDD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	tetrachloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	toluene
Waste Quantity:	UNKNOWN

1921 ATLANTIC AVENUE SITE (Continued) **S125395150**

Waste Code:	Not reported
HW Code:	C224279
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224279
Waste Type:	chlordane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224279-10-03
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-11-04 11:05:00
Record Updated:	2021-11-04 11:05:00
Updated By:	DGMCNALL
Crossref ID:	C224279
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2020-06-09 13:25:00
Record Updated:	2020-06-09 13:25:00
Updated By:	DGMCNALL
Crossref ID:	2006986
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 08:59:00
Record Updated:	2021-05-28 08:59:00
Updated By:	JHOCONNE

E DESIGNATION:

Name:	LOT 38,TAXBLOCK 1557
Address:	1911 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	38
Tax Block:	1557
Borough Code:	BK
E-No:	E-526
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	18HPD104K
Ulurp Number:	190161ZMK N190162ZRK
Zoning Map No:	17a
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

Y230 **CON EDISON SERVICE BOX: 28557** **RCRA NonGen / NLR** **1016963304**
WNW **24 MACDOUGAL ST** **NY MANIFEST** **NYP004363206**
1/8-1/4 **BROOKLYN, NY 11216**
0.177 mi.
936 ft. **Site 4 of 4 in cluster Y**

Relative: **Lower**
Actual: **62 ft.**

RCRA Listings:

Date Form Received by Agency:	20131019
Handler Name:	Con Edison Service Box: 28557
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11216
EPA ID:	NYP004363206
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 28557 (Continued) **1016963304**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130919
Handler Name: CON EDISON SERVICE BOX:	28557
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131019
Handler Name: CON EDISON SERVICE BOX:	28557
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 28557 (Continued) **1016963304**

NY MANIFEST:

Name:	CON EDISON
Address:	24 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11216
Country:	USA
EPA ID:	NYP004363206
Facility Status:	Not reported
Location Address 1:	24 MAC DOUGAL ST.
Code:	BP
Location Address 2:	SERVICE BOX # 28557
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11218
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004363206
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/19/2013
Trans1 Recv Date:	09/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004363206
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002221303GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 28557 (Continued) **1016963304**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T231 **CON EDISON SERVICE BOX: 30230** **RCRA NonGen / NLR** **1016973225**
NNE **336 MARION ST** **NY MANIFEST** **NYP004470191**
1/8-1/4 **BROOKLYN, NY 11233**
0.177 mi.
937 ft. **Site 4 of 4 in cluster T**

Relative: **Lower**

Actual: **55 ft.**

RCRA Listings:

Date Form Received by Agency:	20140418
Handler Name:	Con Edison Service Box: 30230
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004470191
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON SERVICE BOX: 30230 (Continued) **1016973225**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140318
Handler Name: CON EDISON SERVICE BOX:	30230
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140418
Handler Name: CON EDISON SERVICE BOX:	30230
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 30230 (Continued) **1016973225**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	336 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004470191
Facility Status:	Not reported
Location Address 1:	336 MARION ST
Code:	BP
Location Address 2:	SB30230
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004470191
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON SERVICE BOX: 30230 (Continued) **1016973225**

Trans2 State ID:	Not reported
Generator Ship Date:	03/18/2014
Trans1 Recv Date:	03/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004470191
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405848GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE232 **CON EDISON SERVICE BOX: 21223** **RCRA NonGen / NLR** **1017777705**
ENE **86 HULL ST** **FINDS** **NYP004556072**
1/8-1/4 **BROOKLYN, NY 11233**
0.180 mi.
948 ft. **Site 4 of 7 in cluster AE**

Relative: **Higher**
Actual: **94 ft.**

RCRA Listings:

Date Form Received by Agency:	20140706
Handler Name:	Con Edison Service Box: 21223
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004556072
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON SERVICE BOX: 21223 (Continued) **1017777705**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON SERVICE BOX: 21223 (Continued) **1017777705**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20140606
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140606
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140706
Handler Name: CON EDISON SERVICE BOX: 21223
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON SERVICE BOX: 21223 (Continued) **1017777705**

FINDS:
Registry ID: 110063823439

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AE233 **CON EDISON** **NY MANIFEST** **S117063200**
ENE **86 HULL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.180 mi.
948 ft. **Site 5 of 7 in cluster AE**

Relative:
Higher

Actual:
94 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	86 HULL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004556072
Facility Status:	Not reported
Location Address 1:	FO 86 HULL ST
Code:	BP
Location Address 2:	SB 21223
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004556072
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/06/2014

CON EDISON (Continued) **S117063200**

Trans1 Recv Date:	06/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004556072
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013246476JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE234 **CON EDISON** **NY MANIFEST** **S123252454**
ENE **105 HULL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.181 mi.
956 ft. **Site 6 of 7 in cluster AE**

Relative: NY MANIFEST:
Higher

Actual:
90 ft.

Name:	CON EDISON
Address:	105 HULL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004483954
Facility Status:	Not reported
Location Address 1:	105 HULL ST
Code:	BP
Location Address 2:	SB24220

CON EDISON (Continued) **S123252454**

Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004483954
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2014
Trans1 Recv Date:	03/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004483954
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405875GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)

CON EDISON (Continued) **S123252454**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE235 **CON EDISON SERVICE BOX: 21220** **RCRA NonGen / NLR** **1017771458**
ENE **105 HULL ST** **NYP004483954**
1/8-1/4 **BROOKLYN, NY 11233**
0.181 mi.
956 ft. **Site 7 of 7 in cluster AE**

Relative: **Higher**

Actual: **90 ft.**

RCRA Listings:

Date Form Received by Agency:	20140430
Handler Name:	Con Edison Service Box: 21220
Handler Address:	HULL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004483954
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

CON EDISON SERVICE BOX: 21220 (Continued) **1017771458**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 21220 (Continued) **1017771458**

Receive Date:	20140430
Handler Name: CON EDISON SERVICE BOX:	21220
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

V236 **CON EDISON - MANHOLE 4743** **RCRA-LQG** **1024891807**
SW **2034 ATLANTIC AVE** **NYP005150495**
1/8-1/4 **BROOKLYN, NY 11233**
0.186 mi.
981 ft. **Site 7 of 11 in cluster V**

Relative: **Higher**
Actual: **85 ft.**

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Manhole 4743
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP005150495
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.

CON EDISON - MANHOLE 4743 (Continued) **1024891807**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20171012

CON EDISON - MANHOLE 4743 (Continued) **1024891807**

Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20171012
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180410
Handler Name:	CON EDISON - MANHOLE 4743
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

V237 **CON EDISON - MANHOLE 4743** **NY MANIFEST** **S121968740**
SW **2034 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.186 mi.
981 ft. **Site 8 of 11 in cluster V**

Relative:
Higher

Actual:
85 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 4743
Address:	2034 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA

CON EDISON - MANHOLE 4743 (Continued) **S121968740**

EPA ID: NYP005150495
Facility Status: Not reported
Location Address 1: 2034 ATLANTIC AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005150495
Mailing Name: CON EDISON - MANHOLE 4743
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

AG238 **ACCUTECH FOREIN CAR SERVICES** **NY AST** **A100292957**
WSW **22 PRESCOTT PLACE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.186 mi.
983 ft. **Site 1 of 7 in cluster AG**

Relative: **Lower**
Actual: **73 ft.**

AST:
Name: ACCUTECH FOREIN CAR SERVICES
Address: 22 PRESCOTT PLACE
City,State,Zip: BROOKLYN, NY 11233
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-609603
Program Type: PBS
UTM X: 591184.55349
UTM Y: 4503502.73201
Expiration Date: N/A
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 55679
Affiliation Type: Facility Owner
Company Name: MOR ROSEN, LLC
Contact Type: OWNER'S REPRESENTATIVE
Contact Name: MORDECHAI HALBERSTAM
Address1: 991 WILLOUGHBY AVENUE, SUITE 200
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11233
Country Code: 001
Phone: (718) 302-9641
EMail: Not reported

ACCUTECH FOREIN CAR SERVICES (Continued) **A100292957**

Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-20
Site Id:	55679
Affiliation Type:	Facility Operator
Company Name:	ACCUTECH FOREIN CAR SERVICES
Contact Type:	Not reported
Contact Name:	MORDECHAI HALBERSTAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 773-2026
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-20
Site Id:	55679
Affiliation Type:	Mail Contact
Company Name:	MOR ROSEN, LLC
Contact Type:	Not reported
Contact Name:	MORDECHAI HALBERSTAM
Address1:	991 WILLOUGHBY AVENUE, SUITE 200
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11221
Country Code:	001
Phone:	(718) 302-9641
EMail:	FINANCE@MAZEHREALTY.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-20
Site Id:	55679
Affiliation Type:	Emergency Contact
Company Name:	MOR ROSEN, LLC
Contact Type:	Not reported
Contact Name:	MORDECHAI HALBERSTAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 302-9641
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-20

Tank Info:

ACCUTECH FOREIN CAR SERVICES (Continued) **A100292957**

Tank Number:	1
Tank Id:	179094
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
G06 - Tank Secondary Containment - Remote Impounding Area
H00 - Tank Leak Detection - None
F06 - Pipe External Protection - Wrapped
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/23/2016
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

S239 **15 SOMERS STREET** **NY UST** **U004272308**
East **15 SOMERS STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.186 mi.
983 ft. **Site 6 of 7 in cluster S**

Relative: **Higher**

Actual: **99 ft.**

UST:

Name:	15 SOMERS STREET
Address:	15 SOMERS STREET
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-612679 / Unregistered
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	591863.26607
UTM Y:	4503653.89515
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	541394
Affiliation Type:	Facility Owner
Company Name:	ELEVATION HOLDINGS LLC
Contact Type:	PARTNER

15 SOMERS STREET (Continued) **U004272308**

Contact Name:	BOAZ GILAD
Address1:	Not reported
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 544-3784
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-02-23

Site Id:	541394
Affiliation Type:	Emergency Contact
Company Name:	ELEVATION HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	NIMRUD EYAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 544-3784 217
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-02-23

Tank Info:

Tank Number:	001
Tank ID:	266914
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	1000
Install Date:	12/13/1971
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J06 - Dispenser - Tank Mounted Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None

15 SOMERS STREET (Continued) **U004272308**

C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number:	002
Tank ID:	266915
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/13/1971
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
J06 - Dispenser - Tank Mounted Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

S240 **CON EDISON** **NY MANIFEST** **S117538283**
East **15 SOMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.186 mi.
983 ft. **Site 7 of 7 in cluster S**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	15 SOMER ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004709440
Facility Status:	Not reported
Location Address 1:	15 SOMER ST
Code:	BP
Location Address 2:	SB37592
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201

CON EDISON (Continued) **S117538283**

Location Zip 4: Not reported

NY MANIFEST:

EPAID:	NYP004709440
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	12/22/2014
Trans1 Recv Date:	12/22/2014
Trans2 Recv Date:	12/29/2014
TSD Site Recv Date:	12/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004709440
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620159GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S117538283**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH241 **CON EDISON** **RCRA NonGen / NLR** **1018278958**
NNW **253 MARION ST** **FINDS** **NYP004737441**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.187 mi.
988 ft. **Site 1 of 4 in cluster AH**

Relative: **Lower**
Actual: **46 ft.**

RCRA Listings:

Date Form Received by Agency:	20150224
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004737441
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON (Continued) **1018278958**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150224
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1018278958**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067683705

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278958
Registry ID:	110067683705
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067683705
Name:	CON EDISON
Address:	253 MARION ST
City,State,Zip:	BROOKLYN, NY 11233

AH242 **CON EDISON** **NJ MANIFEST** **S120667805**
NNW **253 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.187 mi.
988 ft. **Site 2 of 4 in cluster AH**

Relative:
Lower

Actual:
46 ft.

NJ MANIFEST:

EPA Id:	NYP004737441
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610326GBF
EPA ID:	NYP004737441

CON EDISON (Continued) **S120667805**

Date Shipped:	2/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AH243 **CON EDISON** **NY MANIFEST** **S117740573**
NNW **253 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.187 mi.
988 ft. **Site 3 of 4 in cluster AH**

Relative: NY MANIFEST:
Lower

Actual: Name:	CON EDISON
46 ft. Address:	253 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004737441
Facility Status:	Not reported
Location Address 1:	F/O 253 MARION ST
Code:	BP
Location Address 2:	SB30216
Total Tanks:	Not reported

CON EDISON (Continued) **S117740573**

Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004737441
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 02/24/2015
Trans1 Recv Date: 02/24/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/02/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004737441
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002610326GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 1200
Units: P - Pounds
Number of Containers: 1

CON EDISON (Continued) **S117740573**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA244 **CON EDISON SERVICE BOX: 28158** **RCRA NonGen / NLR** **1016974280**
NE **129 HOPKINSON** **NY MANIFEST** **NYP004480976**
1/8-1/4 **BROOKLYN, NY 11233**
0.187 mi.
988 ft. **Site 2 of 3 in cluster AA**

Relative: **Lower**
Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20140427
Handler Name:	Con Edison Service Box: 28158
Handler Address:	HOPKINSON
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004480976
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON SERVICE BOX: 28158 (Continued) **1016974280**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140327
Handler Name: CON EDISON SERVICE BOX:	28158
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140427
Handler Name: CON EDISON SERVICE BOX:	28158
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28158 (Continued) **1016974280**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	129 HOPKINSON
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004480976
Facility Status:	Not reported
Location Address 1:	F/O 129 HOPKINSON AVE
Code:	BP
Location Address 2:	STRUCTURE 28158
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004480976
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2014
Trans1 Recv Date:	03/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480976
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON SERVICE BOX: 28158 (Continued) **1016974280**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406513GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC245 **CON EDISON** **NY MANIFEST** **S117059406**
NNE **348 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.187 mi.
988 ft. **Site 2 of 3 in cluster AC**

Relative:
Lower

Actual:
57 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	348 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004515763
Facility Status:	Not reported
Location Address 1:	FRONT OF 348 MARION ST
Code:	BP
Location Address 2:	SB30231
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004515763

CON EDISON (Continued) **S117059406**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/29/2014
Trans1 Recv Date:	04/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004515763
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002418218GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **S117059406**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

AC246 **CON EDISON SERVICE BOX: 30231** **RCRA NonGen / NLR** **1017773784**
NNE **348 MARION ST** **NYP004515763**
1/8-1/4 **BROOKLYN, NY 11233**
0.187 mi.
988 ft. **Site 3 of 3 in cluster AC**

Relative: **Lower**
Actual: **57 ft.**

RCRA Listings:

Date Form Received by Agency:	20140529
Handler Name:	Con Edison Service Box: 30231
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004515763
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

CON EDISON SERVICE BOX: 30231 (Continued) **1017773784**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140429
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140429
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140529
Handler Name: CON EDISON SERVICE BOX: 30231	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 30231 (Continued) **1017773784**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG247 **20 PRESCOTT PLACE** **NY VCP** **S125316899**
WSW **20 PRESCOTT PLACE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.189 mi.
997 ft. **Site 2 of 7 in cluster AG**

Relative:
Lower

Actual:
73 ft.

VCP NYC:
Project ID: 18TMP0304K,18EH-N124K,18CVCP064K
Name: 20 PRESCOTT PLACE
Address: 20 PRESCOTT PLACE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 3.01556002530155E+29
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Completed
Latitude: 40.677446
Longitude: -73.920908
Postcode: 3
Community Board: 41
Council District: 301
Census Tract: 3042319
BIN: 3015560025
NTA: Ocean Hill

AI248 **CON EDISON SERVICE BOX: 28554** **RCRA NonGen / NLR** **1017774062**
WNW **29-29A MCDOUGAL ST** **NYP004518601**
1/8-1/4 **BROOKLYN, NY 11233**
0.189 mi.
997 ft. **Site 1 of 17 in cluster AI**

Relative:
Lower

Actual:
60 ft.

RCRA Listings:
Date Form Received by Agency: 20140601
Handler Name: Con Edison Service Box: 28554
Handler Address: MCDOUGAL ST
Handler City,State,Zip: BROOKLYN, NY 11233
EPA ID: NYP004518601
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770

CON EDISON SERVICE BOX: 28554 (Continued) **1017774062**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 28554 (Continued) **1017774062**

Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140501
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140501
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140601
Handler Name: CON EDISON SERVICE BOX: 28554
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AI249 **CON EDISON SERVICE BOX: 28554** **NJ MANIFEST** **S120666200**
WNW **29 MCDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.189 mi.
997 ft. **Site 2 of 17 in cluster AI**

Relative:
Lower

Actual:
60 ft.

NJ MANIFEST:

EPA Id:	NYP004520821
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002625916GBF
EPA ID:	NYP004520821
Date Shipped:	2/11/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON SERVICE BOX: 28554 (Continued) **S120666200**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AI250 **CON EDISON** **NY MANIFEST** **S117059679**
WNW **29-29A MCDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.189 mi.
997 ft. **Site 3 of 17 in cluster AI**

Relative:
Lower

Actual:
60 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	29-29A MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004518601
Facility Status:	Not reported
Location Address 1:	FRONT OF 29 MACDOUGAL ST
Code:	BP
Location Address 2:	SB828554
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004518601
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/01/2014
Trans1 Recv Date:	05/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004518601
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117059679**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002418616GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI251 **CON EDISON SERVICE BOX: 28554** **RCRA NonGen / NLR** **1017774276**
WNW **29 MCDOUGAL ST** **FINDS** **NYP004520821**
1/8-1/4 **BROOKLYN, NY 11233**
0.189 mi.
997 ft. **Site 4 of 17 in cluster AI**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency:	20140605
60 ft. Handler Name:	Con Edison Service Box: 28554
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004520821
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON SERVICE BOX: 28554 (Continued) **1017774276**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140505
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator

CON EDISON SERVICE BOX: 28554 (Continued) **1017774276**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140505
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140605
Handler Name: CON EDISON SERVICE BOX: 28554
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063767197

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

CON EDISON SERVICE BOX: 28554 (Continued) **1017774276**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AI252 **CON EDISON** **NY MANIFEST** **S117059884**
WNW **29 MCDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.189 mi.
997 ft. **Site 5 of 17 in cluster AI**

Relative:
Lower

Actual:
60 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	29 MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004520821
Facility Status:	Not reported
Location Address 1:	29 MACDOUGAL
Code:	BP
Location Address 2:	SB28554
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004520821
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10001
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/05/2014
Trans1 Recv Date:	05/05/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004520821
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117059884**

Manifest Tracking Number:	002418771GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

W253 **BILL'S DRY CLEANERS** **RCRA NonGen / NLR** **1004760212**
ESE **2043 ATLANTIC AVE** **ICIS** **NYR000035881**
1/8-1/4 **BROOKLYN, NY 11233** **US AIRS**
0.190 mi. **FINDS**
1002 ft. **Site 4 of 5 in cluster W** **ECHO**

Relative: **Higher**
Actual: **102 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Bills Dry Cleaners
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000035881
Contact Name:	TREVOR DYER
Contact Address:	ATLANTIC AVE
Contact City,State,Zip:	BROOKLYN, NY 11233
Contact Telephone:	718-342-3178
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

BILL'S DRY CLEANERS (Continued) **1004760212**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ATLANTIC AVE
Mailing City,State,Zip:	BROOKLYN, NY 11233
Owner Name:	Trevor P Dyer
Owner Type:	Private
Operator Name:	Trevor P Dyer
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane,

BILL'S DRY CLEANERS (Continued) **1004760212**

Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: TREVOR P DYER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1279 HERKIMER ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11233
Owner/Operator Telephone:	718-342-3178
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TREVOR P DYER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1279 HERKIMER ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11233
Owner/Operator Telephone:	718-342-3178
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TREVOR P DYER	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1279 HERKIMER ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11233
Owner/Operator Telephone:	718-342-3178
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: BILLS DRY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

BILL'S DRY CLEANERS (Continued) **1004760212**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BILLS DRY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970219
Handler Name: BILLS DRY CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000261040131800326
FRS ID: 110004532569
Action Name: BILL'S DRY CLEANERS 36047R290400326
Facility Name: BILL'S DRY CLEANERS
Facility Address: 2043 ATLANTIC AVE
BROOKLYN, NY 112333201
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67654
Longitude in Decimal Degrees: -73.91339

BILL'S DRY CLEANERS (Continued) **1004760212**

Permit Type Desc: Not reported
Program System Acronym: NY0000002610401318
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040131800318
FRS ID: 110004532569
Action Name: BILL'S DRY CLEANERS 36047R290400318
Facility Name: BILL'S DRY CLEANERS
Facility Address: 2043 ATLANTIC AVE
BROOKLYN, NY 112333201
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67654
Longitude in Decimal Degrees: -73.91339
Permit Type Desc: Not reported
Program System Acronym: NY0000002610401318
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040131800310
FRS ID: 110004532569
Action Name: BILL'S DRY CLEANERS 36047R290400310
Facility Name: BILL'S DRY CLEANERS
Facility Address: 2043 ATLANTIC AVE
BROOKLYN, NY 112333201
Enforcement Action Type: Administrative Order
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67654
Longitude in Decimal Degrees: -73.91339
Permit Type Desc: Not reported
Program System Acronym: NY0000002610401318
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040131800307
FRS ID: 110004532569
Action Name: BILL'S DRY CLEANERS 36047R290400307
Facility Name: BILL'S DRY CLEANERS
Facility Address: 2043 ATLANTIC AVE
BROOKLYN, NY 112333201
Enforcement Action Type: Administrative Order
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 7216

BILL'S DRY CLEANERS (Continued) **1004760212**

Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67654
Longitude in Decimal Degrees: -73.91339
Permit Type Desc: Not reported
Program System Acronym: NY0000002610401318
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040131800301
FRS ID: 110004532569
Action Name: BILL'S DRY CLEANERS 36047R290400301
Facility Name: BILL'S DRY CLEANERS
Facility Address: 2043 ATLANTIC AVE
BROOKLYN, NY 112333201
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67654
Longitude in Decimal Degrees: -73.91339
Permit Type Desc: Not reported
Program System Acronym: NY0000002610401318
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1004760212
Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-08-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401318

BILL'S DRY CLEANERS (Continued) **1004760212**

Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-03-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-07-16 00:00:00
Activity Status Date: 2004-07-16 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-08-19 00:00:00
Activity Status Date: 2003-08-19 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-01-20 00:00:00
Activity Status Date: 2006-01-20 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-08-17 00:00:00
Activity Status Date: 2007-08-17 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

BILL'S DRY CLEANERS (Continued) **1004760212**

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-11-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-03-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-07-16 00:00:00
Activity Status Date: 2004-07-16 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002610401318
Facility Registry ID: 110004532569
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-19 00:00:00
Activity Status Date: 2003-08-19 00:00:00
Activity Group: Enforcement Action

BILL'S DRY CLEANERS (Continued) **1004760212**

Activity Type: Administrative - Informal
Activity Status: Achieved

FINDS:
Registry ID: 110004532569

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004760212
Registry ID: 110004532569
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004532569
Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233

W254 **BILL'S DRY CLEANERS** **NY DRYCLEANERS** **S128781785**
ESE **2043 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.190 mi.
1002 ft. **Site 5 of 5 in cluster W**

Relative:
Higher

Actual:
102 ft.

DRYCLEANERS:
Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318
Phone Number: 7183423178
Region: Not reported
Registration Effective Date: 12/08/2003
Inspection Date: 12/21/2012
Install Date: Not reported
Expiration Date: 09/21/2016
Removal Date: Not reported

BILL'S DRY CLEANERS (Continued) **S128781785**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318
Phone Number: 7183423178
Region: Not reported
Registration Effective Date: 12/08/2003
Inspection Date: 12/05/2011
Install Date: Not reported
Expiration Date: 09/21/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318
Phone Number: 7183423178
Region: Not reported
Registration Effective Date: 12/08/2003
Inspection Date: 11/10/2010
Install Date: Not reported
Expiration Date: 09/21/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318
Phone Number: 7183423178
Region: Not reported
Registration Effective Date: 12/08/2003
Inspection Date: 10/16/2007
Install Date: Not reported
Expiration Date: 09/21/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318

BILL'S DRY CLEANERS (Continued) **S128781785**

Phone Number:	7183423178
Region:	Not reported
Registration Effective Date:	12/08/2003
Inspection Date:	11/06/2008
Install Date:	Not reported
Expiration Date:	09/21/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BILL'S DRY CLEANERS
Address:	2043 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233 3201
Facility ID:	2-6104-01318
Phone Number:	7183423178
Region:	Not reported
Registration Effective Date:	12/08/2003
Inspection Date:	12/29/2015
Install Date:	Not reported
Expiration Date:	09/21/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BILL'S DRY CLEANERS
Address:	2043 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233 3201
Facility ID:	2-6104-01318
Phone Number:	7183423178
Region:	Not reported
Registration Effective Date:	12/08/2003
Inspection Date:	10/17/2006
Install Date:	Not reported
Expiration Date:	09/21/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BILL'S DRY CLEANERS
Address:	2043 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233 3201
Facility ID:	2-6104-01318
Phone Number:	7183423178
Region:	Not reported
Registration Effective Date:	12/08/2003
Inspection Date:	12/28/2013
Install Date:	Not reported
Expiration Date:	09/21/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

BILL'S DRY CLEANERS (Continued) **S128781785**

Alternate Solvent: (null)
Current Business: Not reported

Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318
Phone Number: 7183423178
Region: Not reported
Registration Effective Date: 12/08/2003
Inspection Date: 12/31/2014
Install Date: Not reported
Expiration Date: 09/21/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BILL'S DRY CLEANERS
Address: 2043 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233 3201
Facility ID: 2-6104-01318
Phone Number: 7183423178
Region: Not reported
Registration Effective Date: 12/08/2003
Inspection Date: 11/13/2009
Install Date: Not reported
Expiration Date: 09/21/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

AF255 **343 HOWARD AVENUE** **NY AST** **U003395226**
SSW **343 HOWARD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.193 mi.
1018 ft. **Site 2 of 3 in cluster AF**

Relative: **Higher**
Actual: **98 ft.**

AST:
Name: 343 HOWARD AVENUE
Address: 343 HOWARD AVENUE
City,State,Zip: BROOKLYN, NY 11233
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-479691
Program Type: PBS
UTM X: 591342.27660
UTM Y: 4503317.13579
Expiration Date: 03/19/2024
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 21373
Affiliation Type: Facility Operator

343 HOWARD AVENUE (Continued) **U003395226**

Company Name:	343 HOWARD AVENUE
Contact Type:	Not reported
Contact Name:	MOHAMMAD SAJJAD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 933-4811
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-07-23

Site Id:	21373
Affiliation Type:	Emergency Contact
Company Name:	PACIFIC HOUSING LLC
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 388-7519
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-06-24

Site Id:	21373
Affiliation Type:	Mail Contact
Company Name:	PACIFIC HOUSING LLC
Contact Type:	Not reported
Contact Name:	OREN PIRUS
Address1:	320 ROEBLING STREET #121
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-7519
EMail:	COMPLETE7519@GMAIL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-06-24

Site Id:	21373
Affiliation Type:	Facility Owner
Company Name:	PACIFIC HOUSING LLC
Contact Type:	MANAGER
Contact Name:	JOSH KOWITZ
Address1:	320 ROEBLING STREET #121
Address2:	Not reported
City:	BROOKLYN

343 HOWARD AVENUE (Continued) **U003395226**

State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-7519
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-12-04

Tank Info:

Tank Number:	001
Tank Id:	38732
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/29/1993
Capacity Gallons:	3500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AJ256 **CON EDISON - MANHOLE 4199** **RCRA-LQG** **1014396289**
NE **THOMAS S BOYLAND ST & SUMPTER** **NY MANIFEST** **NYP004185351**
1/8-1/4 **BROOKLYN, NY 11233** **NJ MANIFEST**
0.195 mi.
1031 ft. **Site 1 of 3 in cluster AJ**

Relative: **Lower**
Actual: **65 ft.**

RCRA Listings:

Date Form Received by Agency:	20100323
Handler Name:	Con Edison - Manhole 4199
Handler Address:	THOMAS S BOYLAND ST & SUMPTER
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004185351

CON EDISON - MANHOLE 4199 (Continued) **1014396289**

Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON - MANHOLE 4199 (Continued) **1014396289**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090723
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090723
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100323
Handler Name:	CON EDISON - MANHOLE 4199
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date: 20090723

CON EDISON - MANHOLE 4199 (Continued) **1014396289**

Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: THOMAS S BOYLAND ST & SUMPTER
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004185351
Facility Status: Not reported
Location Address 1: THOMAS S BOYLAND ST & SUMPTER
Code: BP
Location Address 2: ST
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004185351
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON - MANHOLE 4199 (Continued) **1014396289**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/30/2009
Trans1 Recv Date:	07/30/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004185351
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894749GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYP004185351
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047

CON EDISON - MANHOLE 4199 (Continued) **1014396289**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894749GBF
EPA ID:	NYP004185351
Date Shipped:	07/30/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/30/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/30/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	1500 G

Z257 **CON EDISON SERVICE BOX: 30213** **RCRA NonGen / NLR** **1016963453**
NW **236 MARION ST** **NY MANIFEST** **NYP004364535**
1/8-1/4 **BROOKLYN, NY 11233**
0.195 mi.
1032 ft. **Site 5 of 5 in cluster Z**

Relative: **Lower**

Actual: **49 ft.**

RCRA Listings:

Date Form Received by Agency:	20131023
Handler Name:	Con Edison Service Box: 30213
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004364535
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 30213 (Continued) **1016963453**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130923
Handler Name: CON EDISON SERVICE BOX:	30213
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131023
Handler Name: CON EDISON SERVICE BOX:	30213
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 30213 (Continued) **1016963453**

NY MANIFEST:

Name:	CON EDISON
Address:	236 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004364535
Facility Status:	Not reported
Location Address 1:	236 MARION ST
Code:	BP
Location Address 2:	SERVICE BOX # 30213
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11218
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004364535
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2013
Trans1 Recv Date:	09/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004364535
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002221301GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 30213 (Continued) **1016963453**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK258 **CON EDISON SERVICE BOX: 30225** **RCRA NonGen / NLR** **1016973046**
NNE **317 MARION ST** **NY MANIFEST** **NYP004468377**
1/8-1/4 **BROOKLYN, NY 11233**
0.196 mi.
1037 ft. **Site 1 of 6 in cluster AK**

Relative: **Lower**

Actual: **50 ft.**

RCRA Listings:

Date Form Received by Agency:	20140417
Handler Name:	Con Edison Service Box: 30225
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004468377
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON SERVICE BOX: 30225 (Continued) **1016973046**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140317
Handler Name: CON EDISON SERVICE BOX:	30225
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140417
Handler Name: CON EDISON SERVICE BOX:	30225
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 30225 (Continued) **1016973046**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	317 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004468377
Facility Status:	Not reported
Location Address 1:	FRONT OF 317 MARLON ST
Code:	BP
Location Address 2:	SB30229
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004468377
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON SERVICE BOX: 30225 (Continued) **1016973046**

Trans2 State ID:	Not reported
Generator Ship Date:	03/17/2014
Trans1 Recv Date:	03/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004468377
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360266GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI259 **RITE AID #04893** **RCRA-VSQG** **1014926856**
West **1950 FULTON ST** **NY MANIFEST** **NYR000186445**
1/8-1/4 **BROOKLYN, NY 11233**
0.202 mi.
1064 ft. **Site 6 of 17 in cluster AI**

Relative: **Lower**
Actual: **62 ft.**

RCRA Listings:

Date Form Received by Agency:	20221213
Handler Name:	Rite Aid #04893
Handler Address:	FULTON ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000186445
Contact Name:	JOSEPH A CHEST
Contact Address:	PO BOX 3165

RITE AID #04893 (Continued) **1014926856**

Contact City,State,Zip:	HARRISBURG, PA 17105
Contact Telephone:	717-975-8643
Contact Fax:	717-972-3989
Contact Email:	EHS@RITEAID.COM
Contact Title:	MANAGER, ENVIRONMENTAL HEALTH SERVICES
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	PO BOX 3165
Mailing City,State,Zip:	HARRISBURG, PA 17105
Owner Name:	50-52 Allen Street Corp
Owner Type:	Private
Operator Name:	Rite Aid Of New York Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221214
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

RITE AID #04893 (Continued) **1014926856**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D005
Waste Description: Barium

Waste Code: D007
Waste Description: Chromium

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D013
Waste Description: Lindane (1,2,3,4,5,6-Hexa-Chlorocyclohexane, Gamma Isomer)

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D022
Waste Description: Chloroform

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D026
Waste Description: Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: P001

RITE AID #04893 (Continued) **1014926856**

Waste Description:	2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%
Waste Code:	P075
Waste Description:	Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts
Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)
Waste Code:	U035
Waste Description:	Benzenebutanoic Acid, 4-[Bis(2-Chloroethyl)Amino]- (Or) Chlorambucil
Waste Code:	U044
Waste Description:	Chloroform (Or) Methane, Trichloro-
Waste Code:	U058
Waste Description:	2h-1,3,2-Oxazaphosphorin-2-Amine, N,N-Bis(2-Chloroethyl)Tetrahydro-, 2-Oxide (Or) Cyclophosphamide
Waste Code:	U072
Waste Description:	Benzene, 1,4-Dichloro- (Or) P-Dichlorobenzene
Waste Code:	U122
Waste Description:	Formaldehyde
Waste Code:	U129
Waste Description:	Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane
Waste Code:	U154
Waste Description:	Methanol (I) (Or) Methyl Alcohol (I)
Waste Code:	U165
Waste Description:	Naphthalene
Waste Code:	U188
Waste Description:	Phenol
Waste Code:	U201
Waste Description:	1,3-Benzenediol (Or) Resorcinol
Waste Code:	U205
Waste Description:	Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)
Waste Code:	U211
Waste Description:	Carbon Tetrachloride (Or) Methane, Tetrachloro-
Waste Code:	U240
Waste Description:	2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D
Waste Code:	U279
Waste Description:	U279

RITE AID #04893 (Continued) **1014926856**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RITE AID CORP	
Legal Status:	Private
Date Became Current:	19990614
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: RITE AID OF NEW YORK INC	
Legal Status:	Private
Date Became Current:	19990614
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	717-761-2633
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	717-972-3989
Owner/Operator Email:	EHS@RITEAID.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: RITE AID OF NEW YORK, INC.	
Legal Status:	Private
Date Became Current:	19990614
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: 50-52 ALLEN STREET CORP.	
Legal Status:	Private
Date Became Current:	19990614
Date Ended Current:	Not reported
Owner/Operator Address:	313 5TH AVENUE
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	212-685-6089
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: RITE AID OF NEW YORK, INC.	
Legal Status:	Private
Date Became Current:	19990614
Date Ended Current:	Not reported
Owner/Operator Address:	30 HUNTER LANE
Owner/Operator City,State,Zip:	CAMP HILL, PA 17011
Owner/Operator Telephone:	Not reported

RITE AID #04893 (Continued) **1014926856**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 50-52 ALLEN STREET CORP.
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: 313 5TH AVENUE
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-685-6089
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF NEW YORK, INC.
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: 30 HUNTER LANE
Owner/Operator City,State,Zip: CAMP HILL, PA 17011
Owner/Operator Telephone: 717-761-2633
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 717-972-3989
Owner/Operator Email: EHS@RITEAID.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: 50-52 ALLEN STREET CORP
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: 313 5TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-685-6089
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID CORP
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF NEW YORK INC
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported

RITE AID #04893 (Continued) **1014926856**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RITE AID OF NEW YORK INC
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 50-52 ALLEN STREET CORP.
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: 313 5TH AVENUE
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-685-6089
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 50-52 ALLEN STREET CORP
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: 313 5TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-685-6089
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 50-52 ALLEN STREET CORP
Legal Status: Private
Date Became Current: 19990614
Date Ended Current: Not reported
Owner/Operator Address: 313 5TH AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-685-6089
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160212

RITE AID #04893 (Continued) **1014926856**

Handler Name: RITE AID #4893
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160213
Handler Name: RITE AID #04893
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20111104
Handler Name: RITE AID #4893
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150512
Handler Name: RITE AID #4893
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151125
Handler Name: RITE AID #4893
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

RITE AID #04893 (Continued) **1014926856**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190417
Handler Name: RITE AID #04893
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20221213
Handler Name: RITE AID #04893
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: RITE AID #4893
Address: 1950 FULTON ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYR000186445
Facility Status: Not reported
Location Address 1: 1950 FULTON STREET

RITE AID #04893 (Continued) **1014926856**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000186445
Mailing Name:	RITE AID #4893
Mailing Contact:	RITE AID
Mailing Address 1:	1950 FULTON ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11233
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184930854

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJR000063677
Generator Ship Date:	12/28/2015
Trans1 Recv Date:	12/28/2015
Trans2 Recv Date:	12/30/2015
TSD Site Recv Date:	12/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000186445
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	008654042FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

RITE AID #04893 (Continued) **1014926856**

Quantity:	0.01
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	P001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI260 **RITE AID # 04893** **PA MANIFEST** **S123093873**
West **1950 FULTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.202 mi.
1064 ft. **Site 7 of 17 in cluster AI**

Relative: **Lower**
Actual: **62 ft.**

Manifest Details:

Year:	2017
Manifest Number:	016104666JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000186445
Generator Date:	06/15/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D010
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	7
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	016104666JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000186445
Generator Date:	06/15/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported

RITE AID # 04893 (Continued) **S123093873**

TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U129
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	7
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	016104666JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000186445
Generator Date:	06/15/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	P001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	016104666JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000186445
Generator Date:	06/15/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd

RITE AID # 04893 (Continued) **S123093873**

TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U205
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	7
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	016104666JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000186445
Generator Date:	06/15/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D007
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	7
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

V261 **MTA LIRR - ATLANTIC AVENUE VIADUCT** **RCRA-SQG** **1012186237**
SW **2010 ATLANTIC AVE** **NY MANIFEST** **NYR000160986**
1/8-1/4 **BROOKLYN, NY 11233** **NJ MANIFEST**
0.202 mi.
1064 ft. **Site 9 of 11 in cluster V**

Relative: **Higher**
Actual: **83 ft.**

RCRA Listings:

Date Form Received by Agency:	20230629
Handler Name:	Mta Lirr - Atlantic Avenue Viaduct
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000160986
Contact Name:	OLOLADE ADEWALE
Contact Address:	ARCHER AVE MC 1428
Contact City,State,Zip:	JAMAICA, NY 11435
Contact Telephone:	347-494-6020
Contact Fax:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Contact Email:	OADEWAL@LIRR.ORG
Contact Title:	FIELD ENGINEER - ENVIRONMENTAL ENGINEER
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ARCHER AVE MC 1428
Mailing City,State,Zip:	JAMAICA, NY 11435
Owner Name:	Mta Long Island Rail Road
Owner Type:	State
Operator Name:	Mta Lirr
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230629
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MTA LONG ISLAND RAIL ROAD
Legal Status: State
Date Became Current: 18500101
Date Ended Current: Not reported
Owner/Operator Address: 9302 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA - LIRR
Legal Status: State
Date Became Current: 19500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA LONG ISLAND RAIL ROAD
Legal Status: State
Date Became Current: 18500101
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA LIRR
Legal Status: State
Date Became Current: 19500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA LIRR
Legal Status: State
Date Became Current: 19500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA - LONG ISLAND RAIL ROAD
Legal Status: State
Date Became Current: 19500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA LONG ISLAND RAIL ROAD
Legal Status: State
Date Became Current: 19500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA LONG ISLAND RAIL ROAD
Legal Status: State
Date Became Current: 19500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100204
Handler Name: MTA LIRR - ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20081110
Handler Name: MTA LIRR - ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220831
Handler Name: MTA LIRR - ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20230629
Handler Name: MTA LIRR - ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 485112
NAICS Description: COMMUTER RAIL SYSTEMS

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110629
Actual Return to Compliance Date: 20110701

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20110713
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110713
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYACY
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110629
Actual Return to Compliance Date: 20110701
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20110713
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110713
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYACY

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110629
Actual Return to Compliance Date: 20110701
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20110713
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110713
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYACY
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20110629
Actual Return to Compliance Date: 20110701

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20110713
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20110713
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYACY
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20110629
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYACY
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20110701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20110629
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYACY
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20110701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110629
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYACY
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20110701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110629
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYACY
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20110701
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	MTA LIRR - ATLANTIC AVENUE VIADUCT
Address:	2010 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYR000160986
Facility Status:	Not reported
Location Address 1:	2010 ATLANTIC AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000160986
Mailing Name:	MTA LIRR - ATLANTIC AVENUE VIADUCT
Mailing Contact:	MTA LIRR - ATLANTIC AVENUE VIADUCT
Mailing Address 1:	93-59 183RD STREET
Mailing Address 2:	Not reported
Mailing City:	HOLLIS
Mailing State:	NY
Mailing Zip:	11423
Mailing Zip 4:	Not reported
Mailing Country:	USA

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Mailing Phone: 9176524033

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	12/19/2008
Trans1 Recv Date:	12/19/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/19/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000160986
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000201107WAS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYR000160986
Mail Address:	183RD ST DEPT 3147
Mail City/State/Zip:	HOLLIS, NY 11423

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	ALBERT S ALBANO
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000201605WAS
EPA ID:	NYR000160986
Date Shipped:	09/15/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/15/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Waste Code:	D008
Hand Code:	H111
Quantity:	1800 P

Manifest Number:	000198428WAS
EPA ID:	NYR000160986
Date Shipped:	06/08/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D006
Hand Code:	H111
Quantity:	1200 P

Manifest Number:	000423571WAS
EPA ID:	NYR000160986
Date Shipped:	6/29/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2,000.00 Pounds

Manifest Number:	000201053WAS
EPA ID:	NYR000160986
Date Shipped:	11/21/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/21/2008

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/21/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	4500 P

Manifest Number:	000423582WAS
EPA ID:	NYR000160986
Date Shipped:	7/7/2011
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	300.00 Pounds

Manifest Number:	000199590WAS
EPA ID:	NYR000160986
Date Shipped:	02/18/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/18/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/18/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2800 P

Manifest Number:	000195114WAS
EPA ID:	NYR000160986
Date Shipped:	10/08/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/08/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/08/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Quantity: 6000 P

Manifest Number: 000199335WAS
EPA ID: NYR000160986
Date Shipped: 06/30/2010
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 06/30/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 06/30/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: HOLLIS, NY 11423
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 3300 P

Manifest Number: 000201107WAS
EPA ID: NYR000160986
Date Shipped: 12/19/2008
TSDF EPA ID: NJD991291105
Transporter EPA ID: NYD046765574
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/19/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/19/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1500 P

Manifest Number:	000199674WAS
EPA ID:	NYR000160986
Date Shipped:	04/22/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/22/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/22/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	3300 P

Manifest Number:	000201205WAS
EPA ID:	NYR000160986
Date Shipped:	03/23/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/23/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	HOLLIS, NY 11423
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	1400 P

Manifest Number:	000201795WAS
EPA ID:	NYR000160986
Date Shipped:	11/02/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

MTA LIRR - ATLANTIC AVENUE VIADUCT (Continued) **1012186237**

Data Entry Number: Not reported
Was Load Rejected: HOLLIS, NY 11423
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 1500 P

V262 **FAMILY DOLLAR STORE 6602** **RCRA-VSQG** **1016975108**
SW **2010 ATLANTIC AVE SUITE 1** **NYR000215681**
1/8-1/4 **BROOKLYN, NY 11233**
0.202 mi.
1064 ft. **Site 10 of 11 in cluster V**

Relative:
Higher

Actual:
83 ft.

RCRA Listings:

Date Form Received by Agency:	20141009
Handler Name:	Family Dollar Store 6602
Handler Address:	ATLANTIC AVE SUITE 1
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000215681
Contact Name:	KEVIN STRAIGHT
Contact Address:	PO BOX 1017
Contact City,State,Zip:	CHARLOTTE, NC 28201
Contact Telephone:	704-708-1909
Contact Fax:	Not reported
Contact Email:	KSTRAIGHT@FAMILYDOLLAR.COM
Contact Title:	PROGRAM MANAGER ENVIRONMENTAL COMPLIANCE
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	PO BOX 1017
Mailing City,State,Zip:	CHARLOTTE, NC 28201
Owner Name:	2020 Atlantic Llc
Owner Type:	Private
Operator Name:	Family Dollar Stores
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

FAMILY DOLLAR STORE 6602 (Continued) **1016975108**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016

FAMILY DOLLAR STORE 6602 (Continued) **1016975108**

Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: 2020 ATLANTIC LLC
Legal Status: Private
Date Became Current: 20060512
Date Ended Current: Not reported
Owner/Operator Address: 15 OCEAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11225
Owner/Operator Telephone: 718-703-8441
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: FAMILY DOLLAR STORES
Legal Status: Private
Date Became Current: 20041124
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20141009
Handler Name: FAMILY DOLLAR STORE 6602
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45299
NAICS Description: ALL OTHER GENERAL MERCHANDISE STORES

Facility Has Received Notices of Violations:

FAMILY DOLLAR STORE 6602 (Continued) **1016975108**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

V263 **CON EDISON SERVICE BOX: 14990** **RCRA NonGen / NLR** **1016972714**
SW **2010 ATLANTIC AVE** **NY MANIFEST** **NYP004464954**
1/8-1/4 **BROOKLYN, NY 11233**
0.202 mi.
1064 ft. **Site 11 of 11 in cluster V**

Relative: **Higher**
Actual: **83 ft.**

RCRA Listings:

Date Form Received by Agency:	20140412
Handler Name:	Con Edison Service Box: 14990
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004464954
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON SERVICE BOX: 14990 (Continued) **1016972714**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140312
Handler Name: CON EDISON SERVICE BOX:	14990
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140412
Handler Name: CON EDISON SERVICE BOX:	14990
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON SERVICE BOX: 14990 (Continued) **1016972714**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 2010 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004464954
Facility Status: Not reported
Location Address 1: 2010 ATLANTIC AVE
Code: BP
Location Address 2: SB14990
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004464954
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/12/2014
Trans1 Recv Date: 03/12/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/17/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004464954
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002360568GBF
Import Indicator: N

CON EDISON SERVICE BOX: 14990 (Continued) **1016972714**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL264 **DEAN STREET TRANSITORIAL HOME** **NY AST** **A100452194**
SSE **2155 DEAN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.202 mi.
1065 ft. **Site 1 of 7 in cluster AL**

Relative:
Higher

Actual:
112 ft.

AST:

Name:	DEAN STREET TRANSITORIAL HOME
Address:	2155 DEAN STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601687
Program Type:	PBS
UTM X:	591604.84950
UTM Y:	4503261.50517
Expiration Date:	01/05/2024
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	23649
Affiliation Type:	Facility Operator
Company Name:	DEAN STREET TRANSITORIAL HOME
Contact Type:	Not reported
Contact Name:	JOHN LUCCHI
Address1:	Not reported
Address2:	Not reported

DEAN STREET TRANSITORIAL HOME (Continued) **A100452194**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 688-8941
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-31

Site Id:	23649
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPT OF HOMELESS SERVICES
Contact Type:	Not reported
Contact Name:	JOHN LUCCHI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 739-1571
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-31

Site Id:	23649
Affiliation Type:	Facility Owner
Company Name:	NYC DEPT OF HOMELESS SERVICES
Contact Type:	CONTRACT MANAGER
Contact Name:	NYC DEPARTMENT OF HOMELESS SERVICES
Address1:	101-07 FARRAGUT ROAD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11236
Country Code:	001
Phone:	(718) 688-8510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-31

Site Id:	23649
Affiliation Type:	Mail Contact
Company Name:	NYC DEPT OF HOMELESS SERVICES
Contact Type:	Not reported
Contact Name:	JAMES GREEN
Address1:	101-07 FARRAGUT ROAD
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11236
Country Code:	001
Phone:	(718) 688-8524
EMail:	JGREEN@DOH.NYC.GOV

DEAN STREET TRANSITORIAL HOME (Continued) **A100452194**

Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-31

Tank Info:

Tank Number:	001
Tank Id:	47475
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J05 - Dispenser - On Site Heating System (Supply/Return)
C03 - Pipe Location - Aboveground/Underground Combination
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1980
Capacity Gallons:	4000
Tightness Test Method:	21
Date Test:	10/02/2012
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AF265 **351 HOWARD AVE** **NY AST** **A100292218**
SSW **351 HOWARD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.203 mi.
1072 ft. **Site 3 of 3 in cluster AF**

Relative:
Higher

Actual:
100 ft.

AST:

Name:	351 HOWARD AVE
Address:	351 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608446
Program Type:	PBS
UTM X:	591341.24798
UTM Y:	4503299.81310

351 HOWARD AVE (Continued) **A100292218**

Expiration Date: 06/30/2026
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 30298
Affiliation Type: Emergency Contact
Company Name: 351 RESIDENCE LLC
Contact Type: Not reported
Contact Name: ABE BERAT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 812-1679
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-08-01

Site Id: 30298
Affiliation Type: Facility Owner
Company Name: 351 RESIDENCE LLC
Contact Type: MANAGER
Contact Name: HILLY PORGES
Address1: 331 RUTLEDGE ST #208
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 349-8067
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2016-06-15

Site Id: 30298
Affiliation Type: Facility Operator
Company Name: 351 HOWARD AVE
Contact Type: Not reported
Contact Name: ORIN PARIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (310) 663-7159
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-04-19

Site Id: 30298
Affiliation Type: Mail Contact
Company Name: 351 RESIDENCE LLC C/O THE MGMT

351 HOWARD AVE (Continued) **A100292218**

Contact Type:	Not reported
Contact Name:	JOSEPH WEISS
Address1:	331 RUTLEDGE STREET #208
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(646) 518-1108
EMail:	INFO@GARDENMGMT.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-04-19

Tank Info:

Tank Number:	001
Tank Id:	65179
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	A00 - Tank Internal Protection - None
	K00 - Spill Prevention - None
	J00 - Dispenser - None
	C02 - Pipe Location - Underground/On-ground
	G00 - Tank Secondary Containment - None
	D00 - Pipe Type - No Piping
	L00 - Piping Leak Detection - None
	B00 - Tank External Protection - None
	E02 - Piping Secondary Containment - Vault (with Access)
	F00 - Pipe External Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1972
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AM266 **2027 PACIFIC STREET** **NY AST** **A100291751**
SW **2027 PACIFIC STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.203 mi.
1074 ft. **Site 1 of 2 in cluster AM**

Relative:
Higher

Actual:
90 ft.

AST:

Name:	2027 PACIFIC STREET
Address:	2027 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609971
Program Type:	PBS
UTM X:	591223.09137
UTM Y:	4503371.19445
Expiration Date:	03/19/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	348373
Affiliation Type:	Mail Contact
Company Name:	PACIFIC HOUSING LLC
Contact Type:	Not reported
Contact Name:	OREN PIRUS
Address1:	320 ROEBLING STREET #121
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-7519
EMail:	COMPLETE7519@GMAIL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-06-24

Site Id:	348373
Affiliation Type:	Facility Operator
Company Name:	2027 PACIFIC STREET
Contact Type:	Not reported
Contact Name:	OREN PIRUS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 499-1695
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-06-24

Site Id:	348373
Affiliation Type:	Emergency Contact
Company Name:	THOMAS S. BOYLAND H.D.F.C.
Contact Type:	Not reported
Contact Name:	JOHN LEFK

2027 PACIFIC STREET (Continued) **A100291751**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 672-2181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-06-24

Site Id:	348373
Affiliation Type:	Facility Owner
Company Name:	PACIFIC HOUSING LLC
Contact Type:	MANAGER
Contact Name:	JOSH KOWITZ
Address1:	320 ROEBLING STREET #121
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-7519
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-12-04

Tank Info:

Tank Number:	2
Tank Id:	207020
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1910
Capacity Gallons:	5000

2027 PACIFIC STREET (Continued) **A100291751**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AK267 **GRANT RESIDENCE** **NY LTANKS** **S104516340**
NNE **335 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.204 mi.
1078 ft. **Site 2 of 6 in cluster AK**

Relative:
Lower

Actual:
52 ft.

LTANKS:

Name:	GRANT RESIDENCE
Address:	335 MARION ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9912025 / 2000-01-26
Facility ID:	9912025
Site ID:	237080
Spill Date:	2000-01-18
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	2000-01-18
CID:	371
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-18
Spill Record Last Update:	2000-02-22
Spiller Name:	TINA HANSEN
Spiller Company:	CLASSIC FUELS
Spiller Address:	9 WYTHE AV
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195321
DEC Memo:	""
Remarks:	"CUSTOMER ORDERED TOO MUCH OIL -- SPILL IS CLEANED UP. "

All Materials:

Site ID:	237080
Operable Unit ID:	1090717
Operable Unit:	01
Material ID:	293912

GRANT RESIDENCE (Continued) **S104516340**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

AN268 **2185 PACIFIC STREET** **NY AST** **A100291807**
SE **2185 PACIFIC STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.205 mi.
1082 ft. **Site 1 of 4 in cluster AN**

Relative:
Higher

Actual:
110 ft.

AST:

Name:	2185 PACIFIC STREET
Address:	2185 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609501
Program Type:	PBS
UTM X:	591781.17915
UTM Y:	4503338.04580
Expiration Date:	05/27/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	55515
Affiliation Type:	Mail Contact
Company Name:	C/O HSC MANAGEMENT CORP
Contact Type:	Not reported
Contact Name:	LANCE MCLAUGHLIN
Address1:	102 GRAMATAN AVENUE
Address2:	Not reported
City:	MOUNT VERNON
State:	NY
Zip Code:	10550
Country Code:	001
Phone:	(914) 237-1600
EMail:	LANCE.MCLAUGHLIN@HSCMANAGEMENT.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-18

Site Id:	55515
Affiliation Type:	Facility Operator
Company Name:	2185 PACIFIC STREET
Contact Type:	Not reported
Contact Name:	LANCE MCLAUGHLIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

2185 PACIFIC STREET (Continued) **A100291807**

Zip Code: Not reported
Country Code: 001
Phone: (914) 237-1600
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-03-19

Site Id: 55515
Affiliation Type: Facility Owner
Company Name: NY PACIFIC STREET HDFC
Contact Type: PROPERTY MANAGER
Contact Name: LANCE MCLAUGHLIN
Address1: 102 GRAMATAN AVENUE
Address2: Not reported
City: MT. VERNON
State: NY
Zip Code: 10550
Country Code: 001
Phone: (914) 237-1600
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-02-18

Site Id: 55515
Affiliation Type: Emergency Contact
Company Name: NY PACIFIC STREET HDFC
Contact Type: Not reported
Contact Name: LANCE MCLAUGHLIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 543-2800
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-12-11

Tank Info:

Tank Number: 001
Tank Id: 178346
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None

2185 PACIFIC STREET (Continued) **A100291807**

H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/18/1980
Capacity Gallons:	3000
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AO269 **CON EDISON** **NY MANIFEST** **S117067193**
NNW **F/O 348 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.205 mi.
1084 ft. **Site 1 of 9 in cluster AO**

Relative: **Lower**
Actual: **48 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 348 CHAUNCEY ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004599346
Facility Status:	Not reported
Location Address 1:	F/O 348 CHAUNCEY ST
Code:	BP
Location Address 2:	STRUCTURE 16719
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004599346
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117067193**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/23/2014
Trans1 Recv Date:	05/23/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004599346
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002419164GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AP270 **CON EDISON SERVICE BOX: 22016** **RCRA NonGen / NLR** **1016963437**
East **1235 HERKIMER ST** **NY MANIFEST** **NYP004364410**
1/8-1/4 **BROOKLYN, NY 11216**
0.206 mi.
1090 ft. **Site 1 of 5 in cluster AP**

Relative: **Higher**

Actual: **102 ft.**

RCRA Listings:

Date Form Received by Agency:	20131023
Handler Name:	Con Edison Service Box: 22016
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11216
EPA ID:	NYP004364410
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 22016 (Continued) **1016963437**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130923
Handler Name: CON EDISON SERVICE BOX:	22016
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131023
Handler Name: CON EDISON SERVICE BOX:	22016
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 22016 (Continued) **1016963437**

NY MANIFEST:

Name:	CON EDISON
Address:	1235 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11216
Country:	USA
EPA ID:	NYP004364410
Facility Status:	Not reported
Location Address 1:	1235 HERKIMER ST
Code:	BP
Location Address 2:	SERVICE BOX # 22016
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11215
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004364410
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/23/2013
Trans1 Recv Date:	09/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004364410
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002221302GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 22016 (Continued) **1016963437**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG271 **335 RALPH AVENUE** **NY VCP** **S127051305**
WSW **335 RALPH AVENUE** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.206 mi.
1090 ft. **Site 3 of 7 in cluster AG**

Relative: **Lower**
Actual: **70 ft.**

VCP NYC:

Project ID:	17TMP0084K,17EH-N064K,21CVCP031K
Name:	335 RALPH AVENUE
Address:	335 RALPH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3015560003
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.677644
Longitude:	-73.921745
Postcode:	3
Community Board:	41
Council District:	301
Census Tract:	3000000
BIN:	3015560003
NTA:	Ocean Hill

AQ272 **CON EDISON** **NJ MANIFEST** **S120670253**
ESE **30 MARCONI PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.207 mi.
1092 ft. **Site 1 of 3 in cluster AQ**

Relative: **Higher**
Actual: **99 ft.**

NJ MANIFEST:

EPA Id:	NYP004765376
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **S120670253**

Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619107GBF
EPA ID:	NYP004765376
Date Shipped:	4/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AQ273 **CON EDISON** **RCRA NonGen / NLR** **1019901731**
ESE **30 MARCONI PL** **FINDS** **NYP004765376**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.207 mi.
1092 ft. **Site 2 of 3 in cluster AQ**

Relative:
Higher

Actual:
99 ft.

RCRA Listings:

Date Form Received by Agency:	20150409
Handler Name:	Con Edison
Handler Address:	MARCONI PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004765376
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019901731**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019901731**

FINDS:
Registry ID: 110069656438

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019901731
Registry ID:	110069656438
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069656438
Name:	CON EDISON
Address:	30 MARCONI PL
City,State,Zip:	BROOKLYN, NY 11233

AQ274 **CON EDISON** **NY MANIFEST** **S119074293**
ESE **30 MARCONI PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.207 mi.
1092 ft. **Site 3 of 3 in cluster AQ**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	30 MARCONI PL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004765376
Facility Status:	Not reported
Location Address 1:	20 MARCONI PL
Code:	BP
Location Address 2:	SB 38000
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004765376
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S119074293**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2015
Trans1 Recv Date:	04/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004765376
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619107GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH275 **CON EDISON SERVICE BOX: 75632** **RCRA NonGen / NLR** **1016972924**
NW **237 MARION ST** **NY MANIFEST** **NYP004467130**
1/8-1/4 **BROOKLYN, NY 11233**
0.207 mi.
1092 ft. **Site 4 of 4 in cluster AH**

Relative: **Lower**

Actual: **48 ft.**

RCRA Listings:

Date Form Received by Agency:	20140414
Handler Name:	Con Edison Service Box: 75632
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004467130
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 75632 (Continued) **1016972924**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140314
Handler Name: CON EDISON SERVICE BOX:	75632
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140414
Handler Name: CON EDISON SERVICE BOX:	75632
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 75632 (Continued) **1016972924**

NY MANIFEST:

Name:	CON EDISON
Address:	237 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004467130
Facility Status:	Not reported
Location Address 1:	FRONT OF 237 MARION ST
Code:	BP
Location Address 2:	SB75632
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004467130
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/14/2014
Trans1 Recv Date:	03/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004467130
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360474GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 75632 (Continued) **1016972924**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AR276 **CON ED - MH 65388** **RCRA NonGen / NLR** **1007206503**
West **HERKIMER ST AND RALPH AVE** **NY MANIFEST** **NYP004010914**
1/8-1/4 **BROOKLYN, NY 11233**
0.209 mi.
1101 ft. **Site 1 of 2 in cluster AR**

Relative: **Lower**

Actual: **65 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - Mh 65388
Handler Address:	HERKIMER ST AND RALPH AVE
Handler City,State,Zip:	BROOKLYN, NY 11233-0000
EPA ID:	NYP004010914
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON ED - MH 65388 (Continued) **1007206503**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - MH 65388	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - MH 65388	
Federal Waste Generator Description:	Not a generator, verified

CON ED - MH 65388 (Continued) **1007206503**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - MH 65388
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: HERKIMER ST AND RALPH AVE
City,State,Zip: BROOKLYN, NY 11233-0000
Country: USA
EPA ID: NYP004010914
Facility Status: Not reported
Location Address 1: HERKIMER ST & RALPH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004010914
Mailing Name: CONSOLIDATED EDISON

CON ED - MH 65388 (Continued) **1007206503**

Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AR277 **CONSOLIDATED EDISON** **NY MANIFEST** **1009236223**
West **HERKIMER ST & RALPH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.209 mi.
1101 ft. **Site 2 of 2 in cluster AR**

Relative:
Lower

Actual:
65 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	HERKIMER ST & RALPH ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004010003
Facility Status:	Not reported
Location Address 1:	HERKIMER ST & RALPH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004010003
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

AS278 **CON EDISON** **NY MANIFEST** **S117738973**
NW **FRONT OF 235 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.209 mi.
1102 ft. **Site 1 of 4 in cluster AS**

Relative:
Lower

Actual:
48 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 235 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004720561
Facility Status:	Not reported
Location Address 1:	FRONT OF 235 MARION ST
Code:	BP
Location Address 2:	SB30213
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004720561
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2015
Trans1 Recv Date:	01/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004720561
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620567GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117738973**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG279 **CON EDISON SERVICE BOX: 32364** **RCRA NonGen / NLR** **1016970159**
WSW **343 RALPH AVE FRONT OF** **NY MANIFEST** **NYP004438586**
1/8-1/4 **BROOKLYN, NY 11213**
0.209 mi.
1102 ft. **Site 4 of 7 in cluster AG**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:	20140310
Handler Name:	Con Edison Service Box: 32364
Handler Address:	RALPH AVE FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11213
EPA ID:	NYP004438586
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 32364 (Continued) **1016970159**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140210
Handler Name: CON EDISON SERVICE BOX:	32364
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 32364 (Continued) **1016970159**

Receive Date:	20140310
Handler Name: CON EDISON SERVICE BOX:	32364
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	343 RALPH AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11213
Country:	USA
EPA ID:	NYP004438586
Facility Status:	Not reported
Location Address 1:	RALPH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11213
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004438586
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON SERVICE BOX: 32364 (Continued) **1016970159**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2014
Trans1 Recv Date:	02/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004438586
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697972JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AP280 **CON EDISON SERVICE BOX: 19991** **RCRA NonGen / NLR** **1017777015**
East **2118 FULTON ST** **FINDS** **NYP004548988**
1/8-1/4 **BROOKLYN, NY 11217**
0.209 mi.
1103 ft. **Site 2 of 5 in cluster AP**

Relative: RCRA Listings:
Higher

Date Form Received by Agency:	20140630
Handler Name:	Con Edison Service Box: 19991
Handler Address:	FULTON ST
Handler City,State,Zip:	BROOKLYN, NY 11217

Actual:
102 ft.

CON EDISON SERVICE BOX: 19991 (Continued) **1017777015**

EPA ID:	NYP004548988
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No

CON EDISON SERVICE BOX: 19991 (Continued) **1017777015**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140530
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140530
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140630
Handler Name: CON EDISON SERVICE BOX:	19991
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 19991 (Continued) **1017777015**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063816508

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AP281 **CON EDISON** **NY MANIFEST** **S117062543**
East **2118 FULTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.209 mi.
1103 ft. **Site 3 of 5 in cluster AP**

Relative:
Higher

Actual:
102 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	2118 FULTON ST
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004548988
Facility Status:	Not reported
Location Address 1:	FO 2118 FULTON ST
Code:	BP
Location Address 2:	STRUCTURE 19991
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004548988
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018

CON EDISON (Continued) **S117062543**

Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/2014
Trans1 Recv Date:	05/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004548988
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423409GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA282 **CON EDISON SERVICE BOX: 28574** **RCRA NonGen / NLR** **1016974250**
ENE **203 MCDOUGAL ST** **NY MANIFEST** **NYP004480679**
1/8-1/4 **BROOKLYN, NY 11233**
0.209 mi.
1106 ft. **Site 3 of 3 in cluster AA**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20140427
Handler Name:	Con Edison Service Box: 28574
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004480679
Contact Name:	THOMAS TEELING

Actual:
78 ft.

CON EDISON SERVICE BOX: 28574 (Continued) **1016974250**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON SERVICE BOX: 28574 (Continued) **1016974250**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON SERVICE BOX: 28574
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140427
Handler Name: CON EDISON SERVICE BOX: 28574
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 203 MCDOUGAL ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004480679
Facility Status: Not reported
Location Address 1: 203 MCDOUGAL ST
Code: BP
Location Address 2: SB28574
Total Tanks: Not reported
Location City: BROOKLYN

CON EDISON SERVICE BOX: 28574 (Continued) **1016974250**

Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004480679
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2014
Trans1 Recv Date:	03/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480679
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406971GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON SERVICE BOX: 28574 (Continued) **1016974250**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI283 **MTA NYCT - RALPH AVE STATION C-LINE** **RCRA NonGen / NLR** **1005444347**
West **RALPH AVE & FULTON ST** **NY MANIFEST** **NYR000106682**
1/8-1/4 **BROOKLYN, NY 11233**
0.211 mi.
1113 ft. **Site 8 of 17 in cluster AI**

Relative: **Lower**

Actual: **60 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Mta Nyct - Ralph Ave Station C-Line
Handler Address:	RALPH AVE & FULTON ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000106682
Contact Name:	WILLIAM JEHLE
Contact Address:	BROADWAY 2ND FLOOR
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-3500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 2ND FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	Mta New York City Transit
Owner Type:	Other
Operator Name:	Mta New York City Transit
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

MTA NYCT - RALPH AVE STATION C-LINE (Continued) **1005444347**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT	
Legal Status:	Other
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 2ND FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NEW YORK CITY TRANSIT	
Legal Status:	Other
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 2ND FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3500

MTA NYCT - RALPH AVE STATION C-LINE (Continued) **1005444347**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 2ND FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-3500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: MTA NYCT - RALPH AVE STATION C-LINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MTA NYCT - RALPH AVE STATION C-LINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020604
Handler Name: MTA NYCT - RALPH AVE STATION C-LINE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

MTA NYCT - RALPH AVE STATION C-LINE (Continued) **1005444347**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	MTA NYCT - RALPH AVE STATION C-LINE
Address:	RALPH AVE & FULTON ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYR000106682
Facility Status:	Not reported
Location Address 1:	RALPH AVE & FULTON STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000106682
Mailing Name:	MTA NYCT - RALPH AVE STATION C-LINE
Mailing Contact:	JENNIFER WUOTINEN
Mailing Address 1:	2 BROADWAY
Mailing Address 2:	27TH FLOOR
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

AI284 **VERIZON** **RCRA NonGen / NLR** **1014395362**
West **RALPH AVE & FULTON ST** **NYP000966861**
1/8-1/4 **BROOKLYN, NY 11235**
0.211 mi.
1113 ft. **Site 9 of 17 in cluster AI**

Relative:
Lower

Actual:
60 ft.

RCRA Listings:

Date Form Received by Agency:	20150629
Handler Name:	Verizon
Handler Address:	RALPH AVE & FULTON ST
Handler City,State,Zip:	BROOKLYN, NY 11235
EPA ID:	NYP000966861
Contact Name:	BILL IRWIN
Contact Address:	E 37TH ST
Contact City,State,Zip:	NEW YORK, NY 10016
Contact Telephone:	917-886-4019

VERIZON (Continued) **1014395362**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	MGR
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	E 37TH ST 4TH FL
Mailing City,State,Zip:	NEW YORK, NY 10016
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170426
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

VERIZON (Continued) **1014395362**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20101008
Handler Name: VERIZON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150629
Handler Name: VERIZON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AI285 **NYNEX** **NY MANIFEST** **1009234205**
West **RALPH AVE & FULTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.211 mi.
1113 ft. **Site 10 of 17 in cluster AI**

Relative: **Lower**
Actual: **60 ft.**

NY MANIFEST:

Name:	NYNEX
Address:	RALPH AVE & FULTON ST
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP000926766
Facility Status:	Not reported
Location Address 1:	RALPH AVE & FULTON ST
Code:	BP
Location Address 2:	Not reported

NYNEX (Continued) **1009234205**

Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000926766
Mailing Name: NYNEX
Mailing Contact: S BISWAS
Mailing Address 1: 221 EAST 37TH STREET
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10016
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123387126

AL286 **PUBLIC SCHOOL 178-BROOKLYN K178** **NY AST** **A100178476**
SSE **2163 DEAN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.211 mi.
1113 ft. **Site 2 of 7 in cluster AL**

Relative:
Higher

Actual:
111 ft.

AST:
Name: PUBLIC SCHOOL 178-BROOKLYN K178
Address: 2163 DEAN STREET
City,State,Zip: BROOKLYN, NY 11212
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606299
Program Type: PBS
UTM X: 591614.20926
UTM Y: 4503189.07233
Expiration Date: 07/12/2026
Site Type: School

Affiliation Records:
Site Id: 28162
Affiliation Type: Emergency Contact
Company Name: NYC DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: KEN MAHADEO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 210-7918
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-02-04

Site Id: 28162

PUBLIC SCHOOL 178-BROOKLYN K178 (Continued) **A100178476**

Affiliation Type:	Facility Operator
Company Name:	PUBLIC SCHOOL 178-BROOKLYN K178
Contact Type:	Not reported
Contact Name:	THAMASHWAR VEERASAWMY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-7513
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-15

Site Id:	28162
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	MANAGER. FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	44-36 VERNON BLVD.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	MSHARMA@SCHOOLS.NYC.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Site Id:	28162
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BLVD.
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Tank Info:

Tank Number:	2035
Tank Id:	61229
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

PUBLIC SCHOOL 178-BROOKLYN K178 (Continued) **A100178476**

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1996
Capacity Gallons:	10000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AL287 **NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K** **NY LEAD** **S118260144**
SSE **2163 DEAN ST** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.211 mi.
1113 ft. **Site 3 of 7 in cluster AL**

Relative:
Higher

Actual:
111 ft.

NYC LEAD 2:

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	201
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	205
Deteriorated Paint:	NO
Presence of LBP:	NA

NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K (Continued) **S118260144**

Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	206
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	208
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	210
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	212
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	303
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K (Continued) **S118260144**

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	510
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	511
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	6th Floor Gym
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	Auditorium
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	CAF
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 178 - BROOKLYN
Address:	2163 DEAN STREET

NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K (Continued) **S118260144**

City,State,Zip:	BROOKLYN, NY
Geographical District:	23
Building Code:	K178
Room:	Play area
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

NY MANIFEST:

Name:	NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K
Address:	2163 DEAN ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYR000213983
Facility Status:	Not reported
Location Address 1:	2163 DEAN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000213983
Mailing Name:	NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K
Mailing Contact:	NYC DEPT OF EDUCATION - PS 178K
Mailing Address 1:	2163 DEAN ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11212
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2015
Trans1 Recv Date:	08/17/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000213983
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014162255JJK

NYC DEPT OF EDUCATION - PUBLIC SCHOOL 178K (Continued) **S118260144**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2500
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	12
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL288 **NYC DEPT OF EDUCATION PS 178K** **RCRA-LQG** **1016974937**
SSE **2163 DEAN ST** **NYR000213983**
1/8-1/4 **BROOKLYN, NY 11233**
0.211 mi.
1113 ft. **Site 4 of 7 in cluster AL**

Relative:
Higher

Actual:
111 ft.

RCRA Listings:

Date Form Received by Agency:	20190213
Handler Name:	Nyc Dept Of Education Ps 178k
Handler Address:	DEAN ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000213983
Contact Name:	BERNARD P ORLAN
Contact Address:	VERNON BLVD
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-610-3117
Contact Fax:	Not reported
Contact Email:	BORLAN@SCHOOLS.NYC.GOV
Contact Title:	DIRECTOR ENVIRONMENTAL HEALTH & SAFETY
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny

NYC DEPT OF EDUCATION PS 178K (Continued) **1016974937**

State District:	NYSDEC R2
Mailing Address:	VERNON BLVD
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Department Of Education
Owner Type:	Municipal
Operator Name:	Nyc Department Of Education
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190213
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

NYC DEPT OF EDUCATION PS 178K (Continued) **1016974937**

Waste Code: D018
Waste Description: Benzene

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19150104
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-742-8501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES
Legal Status: Municipal
Date Became Current: 19150104
Date Ended Current: Not reported

NYC DEPT OF EDUCATION PS 178K (Continued) **1016974937**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160222
Handler Name: PS 178K SCHOOL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141021
Handler Name: NYC DEPT OF EDUCATION - PS 178K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190213
Handler Name: NYC DEPT OF EDUCATION PS 178K
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No

NYC DEPT OF EDUCATION PS 178K (Continued) **1016974937**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

289
SSW
1/8-1/4
0.212 mi.
1119 ft.

OCEAN HILL-BROWNSVILLE **NY AST** **A100395494**
2065 DEAN STREET **N/A**
BROOKLYN, NY 11233

Relative:
Higher

Actual:
105 ft.

AST:
Name: OCEAN HILL-BROWNSVILLE
Address: 2065 DEAN STREET
City,State,Zip: BROOKLYN, NY 11233
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-612300
Program Type: PBS
UTM X: 591350.98321
UTM Y: 4503276.90262
Expiration Date: 10/03/2019
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 500498
Affiliation Type: Mail Contact
Company Name: FUEL OIL REMEDIATION
Contact Type: Not reported
Contact Name: YELENA TKACH
Address1: 23-02 49TH AVENUE
Address2: TECH SERVS DEPT - 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5806
EMail: Y.TKACH@NYCHA.NYC.GOV
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2014-10-03

Site Id: 500498
Affiliation Type: Facility Operator
Company Name: OCEAN HILL-BROWNSVILLE

OCEAN HILL-BROWNSVILLE (Continued) **A100395494**

Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION UNIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-10-03

Site Id:	500498
Affiliation Type:	Emergency Contact
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICES DEPT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-5900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-10-03

Site Id:	500498
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	\\
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5806
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-01-17

Tank Info:

Tank Number:	1
Tank Id:	253228

Equipment Records:

B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

OCEAN HILL-BROWNSVILLE (Continued) **A100395494**

J05 - Dispenser - On Site Heating System (Supply/Return)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Fiberglass Coated Steel
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/29/2014
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AT290 **CON EDISON** **NJ MANIFEST** **S120669848**
ENE **196 MACDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.213 mi.
1122 ft. **Site 1 of 5 in cluster AT**

Relative: **Higher**
Actual: **86 ft.**

NJ MANIFEST:

EPA Id:	NYP004760807
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660400GBF
EPA ID:	NYP004760807
Date Shipped:	3/31/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120669848**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AT291 **CON EDISON** **RCRA NonGen / NLR** **1019901338**
ENE **196 MACDOUGAL ST** **NYP004760807**
1/8-1/4 **BROOKLYN, NY 11233**
0.213 mi.
1122 ft. **Site 2 of 5 in cluster AT**

Relative: **Higher**

Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:	20150331
Handler Name:	Con Edison
Handler Address:	MACDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004760807
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019901338**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150331
Handler Name:	CON EDISON

CON EDISON (Continued) **1019901338**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AU292 **CON EDISON SERVICE BOX: 30227** **RCRA NonGen / NLR** **1016973047**
NNE **349 MARION ST** **NY MANIFEST** **NYP004468385**
1/8-1/4 **BROOKLYN, NY 11233**
0.213 mi.
1127 ft. **Site 1 of 3 in cluster AU**

Relative: **Lower**
Actual: **54 ft.**

RCRA Listings:

Date Form Received by Agency:	20140417
Handler Name:	Con Edison Service Box: 30227
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004468385
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 30227 (Continued) **1016973047**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140317
Handler Name:	CON EDISON SERVICE BOX: 30227

CON EDISON SERVICE BOX: 30227 (Continued) **1016973047**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140417
Handler Name: CON EDISON SERVICE BOX:	30227
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	349 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004468385
Facility Status:	Not reported
Location Address 1:	349 MARION ST
Code:	BP
Location Address 2:	SB30227
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004468385
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST

CON EDISON SERVICE BOX: 30227 (Continued) **1016973047**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/17/2014
Trans1 Recv Date:	03/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/19/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004468385
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002360447GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG293 **CON EDISON SERVICE BOX: 32362** **RCRA NonGen / NLR** **1016969717**
WSW **347 RALPH AVE** **NY MANIFEST** **NYP004433967**
1/8-1/4 **BROOKLYN, NY 11233**
0.214 mi.
1130 ft. **Site 5 of 7 in cluster AG**

Relative: **Lower**
Actual: **72 ft.**

RCRA Listings:

Date Form Received by Agency:	20140304
Handler Name:	Con Edison Service Box: 32362
Handler Address:	RALPH AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004433967
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 32362 (Continued) **1016969717**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140204
Handler Name: CON EDISON SERVICE BOX:	32362
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140304
Handler Name: CON EDISON SERVICE BOX:	32362
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 32362 (Continued) **1016969717**

NY MANIFEST:

Name:	CON EDISON
Address:	347 RALPH AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004433967
Facility Status:	Not reported
Location Address 1:	347 RALPH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004433967
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/2014
Trans1 Recv Date:	02/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004433967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300900GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 32362 (Continued) **1016969717**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL294 **CON EDISON** **RCRA NonGen / NLR** **1019903085**
SSE **DEAN ST & SARATOGA AVE** **FINDS** **NYP004781290**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.215 mi.
1136 ft. **Site 5 of 7 in cluster AL**

Relative:
Higher

Actual:
110 ft.

RCRA Listings:

Date Form Received by Agency:	20150511
Handler Name:	Con Edison
Handler Address:	DEAN ST & SARATOGA AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004781290
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON (Continued) **1019903085**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150511
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150511
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019903085**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069646743

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903085
Registry ID:	110069646743
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069646743
Name:	CON EDISON
Address:	DEAN ST & SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11233

AL295 **CON EDISON** **NJ MANIFEST** **S120671662**
SSE **DEAN ST & SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.215 mi.
1136 ft. **Site 6 of 7 in cluster AL**

Relative: **Higher**
Actual: **110 ft.**

NJ MANIFEST:

EPA Id:	NYP004781290
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING

CON EDISON (Continued) **S120671662**

Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624428GBF
EPA ID:	NYP004781290
Date Shipped:	5/11/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AL296 **CON EDISON** **NY MANIFEST** **S118090501**
SSE **DEAN ST & SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.215 mi.
1136 ft. **Site 7 of 7 in cluster AL**

Relative:
Higher

Actual:
110 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	DEAN ST & SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004781290
Facility Status:	Not reported
Location Address 1:	DEAN ST & SARATOGA AVE
Code:	BP
Location Address 2:	CUSTOMER BOX
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004781290
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	05/11/2015
Trans1 Recv Date:	05/11/2015
Trans2 Recv Date:	05/15/2015
TSD Site Recv Date:	05/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004781290
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624428GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118090501**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI297 **MTA NYCT - RALPH AVENUE STATION - C LINE** **RCRA-SQG** **1010787666**
West **302 RALPH AVE** **NY MANIFEST** **NYR000156133**
1/8-1/4 **BROOKLYN, NY 11233** **NJ MANIFEST**
0.216 mi.
1143 ft. **Site 11 of 17 in cluster AI**

Relative: RCRA Listings:
Lower

Actual: **61 ft.**

Date Form Received by Agency:	20080228
Handler Name:	Mta Nyct - Ralph Avenue Station - C Line
Handler Address:	RALPH AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000156133
Contact Name:	LUMINITA MARINESCU
Contact Address:	BROADWAY 5TH FLOOR
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-3506
Contact Fax:	Not reported
Contact Email:	LUMINITA.MARINESCU@NYCT.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 5TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	Mta Nyct
Owner Type:	State

MTA NYCT - RALPH AVENUE STATION - C LINE (Continued) **1010787666**

Operator Name:	Mta Nyct
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

MTA NYCT - RALPH AVENUE STATION - C LINE (Continued) **1010787666**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA NYCT
Legal Status: State
Date Became Current: 19680301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYCT
Legal Status: State
Date Became Current: 19680301
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 5TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYCT
Legal Status: State
Date Became Current: 19680301
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 5TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20080228
Handler Name: MTA NYCT - RALPH AVENUE STATION - C LINE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080229
Handler Name: MTA NYCT - RALPH AVENUE STATION - C LINE

MTA NYCT - RALPH AVENUE STATION - C LINE (Continued) **1010787666**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	MIXED MODE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	MTA NYCT - RALPH AVENUE STATION - C LINE
Address:	302 RALPH AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYR000156133
Facility Status:	Not reported
Location Address 1:	RALPH AVE & FULTON STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000156133
Mailing Name:	MTA NYCT - RALPH AVENUE STATION - C LINE
Mailing Contact:	MTA NYCT - RALPH AVENUE STATION - C LINE
Mailing Address 1:	2 BROADWAY ROOM A27.64
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

MTA NYCT - RALPH AVENUE STATION - C LINE (Continued) **1010787666**

Year:	2018
Trans1 State ID:	NYD046765574
Trans2 State ID:	Not reported
Generator Ship Date:	11/11/2008
Trans1 Recv Date:	11/11/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/11/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000156133
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000196697WAS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2800
Units:	P - Pounds
Number of Containers:	7
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYR000156133
Mail Address:	BROADWAY 5TH FLOOR
Mail City/State/Zip:	NEW YORK, NY 10004
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	LUMINITA MARINESCU
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported

MTA NYCT - RALPH AVENUE STATION - C LINE (Continued) **1010787666**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000196697WAS
EPA ID:	NYR000156133
Date Shipped:	11/11/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/11/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/12/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10004
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	2800 P

AJ298 **CON EDISON SERVICE BOX: 28153** **RCRA NonGen / NLR** **1016969040**
NE **106 HOPKINSON AVE** **NY MANIFEST** **NYP004426854**
1/8-1/4 **BROOKLYN, NY 11212**
0.217 mi.
1146 ft. **Site 2 of 3 in cluster AJ**

Relative: **Lower**
Actual: **59 ft.**

RCRA Listings:

Date Form Received by Agency:	20140227
Handler Name:	Con Edison Service Box: 28153
Handler Address:	HOPKINSON AVE
Handler City,State,Zip:	BROOKLYN, NY 11212
EPA ID:	NYP004426854
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 28153 (Continued) **1016969040**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140127
Handler Name: CON EDISON SERVICE BOX:	28153
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140227
Handler Name: CON EDISON SERVICE BOX:	28153
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 28153 (Continued) **1016969040**

NY MANIFEST:

Name:	CON EDISON
Address:	106 HOPKINSON AVE
City,State,Zip:	BROOKLYN, NY 11212
Country:	USA
EPA ID:	NYP004426854
Facility Status:	Not reported
Location Address 1:	MARION & THOMAS BOYLAND ST
Code:	BP
Location Address 2:	SB28153
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004426854
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2014
Trans1 Recv Date:	01/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004426854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002329402GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	Y
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	NJD991291105

CON EDISON SERVICE BOX: 28153 (Continued) **1016969040**

Alt Facility Sign Date:	01/31/2014
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AM299 **SHIRLEY CHISHOLM DAYCARE** **NY AST** **A100178382**
SW **2023 PACIFIC STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.220 mi.
1159 ft. **Site 2 of 2 in cluster AM**

Relative:
Higher

Actual:
87 ft.

AST:

Name:	SHIRLEY CHISHOLM DAYCARE
Address:	2023 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-606194
Program Type:	PBS
UTM X:	591177.76426
UTM Y:	4503373.86903
Expiration Date:	07/05/2026
Site Type:	School

Affiliation Records:

Site Id:	28058
Affiliation Type:	Facility Owner
Company Name:	SPENCER ASSOCIATES LLC
Contact Type:	MANAGER
Contact Name:	HAROLD BLOCK
Address1:	41 BOX STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 389-6100
EMail:	CAROLYN@THEPACECOMPANIES.COM
Fax Number:	Not reported
Modified By:	ACDANIEL

SHIRLEY CHISHOLM DAYCARE (Continued) **A100178382**

Date Last Modified: 2021-07-08

Site Id: 28058
Affiliation Type: Mail Contact
Company Name: SPENCER ASSOCIATES LLC
Contact Type: MANAGER
Contact Name: HAROLD BLOCK
Address1: 41 BOX STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-6100
EMail: CAROLYN@THEPACECOMPANIES.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2021-07-08

Site Id: 28058
Affiliation Type: Facility Operator
Company Name: SHIRLEY CHISHOLM DAYCARE
Contact Type: Not reported
Contact Name: DESHAWN OR MS. ARMSTRONG
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 756-1720
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2021-07-08

Site Id: 28058
Affiliation Type: Emergency Contact
Company Name: SPENCER ASSOCIATES LLC
Contact Type: Not reported
Contact Name: HAROLD BLOCK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 612-6180
EMail: Not reported
Fax Number: Not reported
Modified By: MFLEONAR
Date Last Modified: 2017-05-23

Tank Info:

Tank Number: 001
Tank Id: 61090

SHIRLEY CHISHOLM DAYCARE (Continued) **A100178382**

Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground
J00 - Dispenser - None
I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AN300 **CON EDISON - MANHOLE 33403** **NY MANIFEST** **S120958400**
SE **PACIFIC ST & HOPKINSON AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.222 mi.
1170 ft. **Site 2 of 4 in cluster AN**

Relative:
Higher

Actual:
111 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 33403
Address:	PACIFIC ST & HOPKINSON AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004934681
Facility Status:	Not reported
Location Address 1:	PACIFIC ST & HOPKINSON AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004934681
Mailing Name:	CON EDISON - MANHOLE 33403
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON - MANHOLE 33403 (Continued) **S120958400**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AT301 **CON EDISON** **NY MANIFEST** **S117738479**
ENE **200 MCDOUGAL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.222 mi.
1170 ft. **Site 3 of 5 in cluster AT**

Relative:
Higher

Actual:
87 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	200 MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004715298
Facility Status:	Not reported
Location Address 1:	200 MCDOUGAL ST
Code:	BP
Location Address 2:	SB28579
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004715298
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/14/2015
Trans1 Recv Date:	01/14/2015
Trans2 Recv Date:	01/21/2015
TSD Site Recv Date:	01/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004715298
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117738479**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620504GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT302 **CON EDISON SERVICE BOX: 28467** **RCRA NonGen / NLR** **1016974254**
ENE **209 MCDOUGAL ST** **NY MANIFEST** **NYP004480711**
1/8-1/4 **BROOKLYN, NY 11216**
0.222 mi.
1173 ft. **Site 4 of 5 in cluster AT**

Relative: **Higher**

Actual: **80 ft.**

RCRA Listings:

Date Form Received by Agency:	20140427
Handler Name:	Con Edison Service Box: 28467
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11216
EPA ID:	NYP004480711
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON EDISON SERVICE BOX: 28467 (Continued) **1016974254**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140327
Handler Name: CON EDISON SERVICE BOX:	28467
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny

CON EDISON SERVICE BOX: 28467 (Continued) **1016974254**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140427
Handler Name: CON EDISON SERVICE BOX:	28467
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	209 MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11216
Country:	USA
EPA ID:	NYP004480711
Facility Status:	Not reported
Location Address 1:	209 MCDOUGH ST
Code:	BP
Location Address 2:	SB23467
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11216
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004480711
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON SERVICE BOX: 28467 (Continued) **1016974254**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/27/2014
Trans1 Recv Date:	03/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004480711
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406968GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI303 **GREAT DEALS DRY CLNG/B&G DRY CLNERS** **NY DRYCLEANERS** **S110246732**
WNW **291 RALPH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.223 mi.
1177 ft. **Site 12 of 17 in cluster AI**

Relative: **Lower**
Actual: **57 ft.**

DRYCLEANERS:

Name:	GREAT DEALS DRY CLNG/B&G DRY CLNERS
Address:	291 RALPH AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Facility ID:	2-6104-00394
Phone Number:	718-774-9703
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	07/04/2021
Install Date:	90/94
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Y
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

AI304 **B & G CLEANERS** **RCRA NonGen / NLR** **1000135293**
WNW **291 RALPH AVE** **US AIRS** **NYD986868560**
1/8-1/4 **BROOKLYN, NY 11213** **NY MANIFEST**
0.223 mi.
1177 ft. **Site 13 of 17 in cluster AI**

Relative: **Lower**
Actual: **57 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	B & G Cleaners
Handler Address:	RALPH AVE
Handler City,State,Zip:	BROOKLYN, NY 11213
EPA ID:	NYD986868560
Contact Name:	Not reported
Contact Address:	RALPH AVE
Contact City,State,Zip:	BROOKLYN, NY 11213
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	RALPH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11213
Owner Name:	Emma Wilson
Owner Type:	Private
Operator Name:	Emma Wilson
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

B & G CLEANERS (Continued) **1000135293**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

B & G CLEANERS (Continued) **1000135293**

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: EMMA WILSON
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EMMA WILSON
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EMMA WILSON
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950413
Handler Name: B & G CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: B & G CLEANERS

B & G CLEANERS (Continued) **1000135293**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: B & G CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19880523
Handler Name: B & G CLEANERS	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:

Envid:	1000135293
Region Code:	02
Programmatic ID:	AIR NY0000002610400394
Facility Registry ID:	110001613460
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320

B & G CLEANERS (Continued) **1000135293**

Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610400394
Facility Registry ID: 110001613460
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400394
Facility Registry ID: 110001613460
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400394
Facility Registry ID: 110001613460
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-07-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NY MANIFEST:
Name: B G CLNRS
Address: 291 RALPH AVE
City,State,Zip: BROOKLYN, NY 11213
Country: USA
EPA ID: NYD986868560
Facility Status: Not reported
Location Address 1: 291 RALPH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11223

B & G CLEANERS (Continued) **1000135293**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986868560
Mailing Name: B G CLNRS
Mailing Contact: B G CLNRS
Mailing Address 1: 291 RALPH AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11223
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187749703

AI305 **CON EDISON** **NY MANIFEST** **S117063165**
WNW **289 RALPH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.225 mi.
1186 ft. **Site 14 of 17 in cluster AI**

Relative:
Lower

Actual:
57 ft.

NY MANIFEST:
Name: CON EDISON
Address: 289 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004555694
Facility Status: Not reported
Location Address 1: 289 RALPH AVE
Code: BP
Location Address 2: SB 32356
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004555694
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported

CON EDISON (Continued) **S117063165**

Generator Ship Date:	06/06/2014
Trans1 Recv Date:	06/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004555694
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245923JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI306 **CON EDISON** **NY MANIFEST** **S117317764**
WNW **F/O 289 RALPH AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.225 mi.
1186 ft. **Site 15 of 17 in cluster AI**

Relative: **Lower**
Actual: **57 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	F/O 289 RALPH AV
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP004652236
Facility Status:	Not reported
Location Address 1:	F/O 289 RALPH AV
Code:	BP

CON EDISON (Continued) **S117317764**

Location Address 2:	SB32356
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004652236
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2014
Trans1 Recv Date:	09/09/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004652236
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616528GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150

CON EDISON (Continued) **S117317764**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI307 **CON EDISON SERVICE BOX: 32356** **RCRA NonGen / NLR** **1017777669**
WNW **289 RALPH AVE** **FINDS** **NYP004555694**
1/8-1/4 **BROOKLYN, NY 11233**
0.225 mi.
1186 ft. **Site 16 of 17 in cluster AI**

Relative: **Lower**

Actual: **57 ft.**

RCRA Listings:

Date Form Received by Agency:	20140706
Handler Name:	Con Edison Service Box: 32356
Handler Address:	RALPH AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004555694
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

CON EDISON SERVICE BOX: 32356 (Continued) **1017777669**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140606
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140606
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 32356 (Continued) **1017777669**

Receive Date:	20140706
Handler Name: CON EDISON SERVICE BOX:	32356
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063822118

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AN308 **ATLANTIC PLAZA TOWERS** **NY LTANKS** **U001834159**
SE **249 THOMAS S. BOYLAND STREET** **NY UST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.225 mi.
1190 ft. **Site 3 of 4 in cluster AN**

Relative:
Higher

Actual:
112 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	249 HOPKINSON ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0506302 / 2005-11-28
Facility ID:	0506302
Site ID:	351493
Spill Date:	2005-08-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported

ATLANTIC PLAZA TOWERS (Continued) **U001834159**

SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2005-08-22
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-22
Spill Record Last Update:	2005-11-28
Spiller Name:	ANTONIE, ANTIL
Spiller Company:	APARTMENT BUILDING
Spiller Address:	249 THOMAS BOILING AVE
Spiller County:	001
Spiller Contact:	ADAM NADEL
Spiller Phone:	(917) 559-2703
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	298758
DEC Memo:	"Sangesland spoke to Phil at Tanknology - He said there is a single 40,000 gal #6 oil UST at the site. Tank Test Failure Letter sent to Contact: Adam Nadel (917-559-2703) Nelson Management 249 Hopkinson Ave Brooklyn, NY 11233 Property is being sold and owner wants the issue cleared up quickly if possible. Sangesland suggested that the fastest way to determine if there is a large or small problem at the site was to run a series of GeoProbes around the tank in the courtyard and see if there is any contamination. If there is contamination there could be a major job to clean it up. If there is no contamination then the problem may be solved with fixing/replacing the lines. First TTF letter was returned Second letter sent to new contact: Kevin Raferty Atlantic Plaza Towers 249 Thomas S. Boyland St Brooklyn, NY 11233 10/17/05 - Austin - Spoke with Daniel of Hydrotech (631-462-5866). He indicated that the the Horner test done on this tank was invalid, due to the tank being larger than what such a test can tecnically measure in terms of leaks. He wil send his documentation on this to me, plus the results of geo-probes being placed around the tank in question, to close out this spill event in our records. I faxed him acopy of the spill report. - end 11/28/05 - Austin - Received report from Hydrotech - spill transferred to Piper for review - end 11/28/05- DEC Piper reviewed report. As per analytical results, no elevated levels above Rec'd Soil Cleanup Obj. found at 7 locations 5' from tank. No adverse impact to environment."
Remarks:	"Tank Test Failure on 40,000 gal - #6 oil - UST"

All Materials:

Site ID:	351493
Operable Unit ID:	1109003
Operable Unit:	01
Material ID:	2098982
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

ATLANTIC PLAZA TOWERS (Continued) **U001834159**

Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

UST:
Name: ATLANTIC PLAZA TOWERS
Address: 249 THOMAS S. BOYLAND STREET
City,State,Zip: BROOKLYN, NY 11233
Id/Status: 2-196053 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 591846.45411
UTM Y: 4503324.40968
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 6375
Affiliation Type: Facility Owner
Company Name: NELSON MGT GROUP LTD % ATA HOUSING CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 118-35 QUEENS BLVD, 14TH FLR
Address2: Not reported
City: FOREST HILLS
State: NY
Zip Code: 11375
Country Code: 001
Phone: (718) 385-3600
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2012-06-15

Site Id: 6375
Affiliation Type: Mail Contact
Company Name: ATA HOUSING CORP.
Contact Type: Not reported
Contact Name: KEVIN RAFFERTY
Address1: 118-35 QUEENS BOULEVARD
Address2: 14TH FLOOR
City: FOREST HILLS
State: NY
Zip Code: 11375
Country Code: 001
Phone: (718) 385-3600
EMail: NRAZAGHI@AKAM.COM
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2012-06-15

Site Id: 6375
Affiliation Type: Facility Operator
Company Name: ATLANTIC PLAZA TOWERS

ATLANTIC PLAZA TOWERS (Continued) **U001834159**

Contact Type:	Not reported
Contact Name:	SANTIAGO AQUINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 385-3600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-06-15

Site Id:	6375
Affiliation Type:	Emergency Contact
Company Name:	NELSON MGT GROUP LTD % ATA HOUSING CORP
Contact Type:	Not reported
Contact Name:	KEVIN RAFFERTY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 385-3600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-06-15

Tank Info:

Tank Number:	001
Tank ID:	10943
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	40000
Install Date:	11/01/1967
Date Tank Closed:	04/28/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping

ATLANTIC PLAZA TOWERS (Continued) **U001834159**

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	002
Tank ID:	223732
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	20000
Install Date:	04/28/2008
Date Tank Closed:	05/03/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)

AK309 **CON EDISON SERVICE BOX: 16723** **RCRA NonGen / NLR** **1016967459**
NNE **402 CHAUNCEY ST** **NY MANIFEST** **NYP004410692**
1/8-1/4 **BROOKLYN, NY 11233**
0.227 mi.
1197 ft. **Site 3 of 6 in cluster AK**

Relative: **Lower**
Actual: **48 ft.**

RCRA Listings:

Date Form Received by Agency:	20140124
Handler Name:	Con Edison Service Box: 16723
Handler Address:	CHAUNCEY ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004410692
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

CON EDISON SERVICE BOX: 16723 (Continued) **1016967459**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

CON EDISON SERVICE BOX: 16723 (Continued) **1016967459**

Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20131224
Handler Name: CON EDISON SERVICE BOX: 16723
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140124
Handler Name: CON EDISON SERVICE BOX: 16723
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 402 CHAUNCEY ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004410692
Facility Status: Not reported
Location Address 1: 402 CHAUNCY ST
Code: BP
Location Address 2: SB16723
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11217

CON EDISON SERVICE BOX: 16723 (Continued) **1016967459**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004410692
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 12/24/2013
Trans1 Recv Date: 12/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/26/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004410692
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002300611GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 45
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 16723 (Continued) **1016967459**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG310 **LIRR ATLANTIC AVENUE MANHOLES** **RCRA NonGen / NLR** **1000871619**
WSW **S35-S34 ON ATLANTIC AVE BETW** **NY MANIFEST** **NY0000078774**
1/8-1/4 **BROOKLYN, NY 11217**
0.227 mi.
1198 ft. **Site 6 of 7 in cluster AG**

Relative: **Lower**
Actual: **75 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Lirr Atlantic Avenue Manholes
Handler Address:	S35-S34 ON ATLANTIC AVE BETW
Handler City,State,Zip:	BROOKLYN, NY 11217
EPA ID:	NY0000078774
Contact Name:	Not reported
Contact Address:	LIRR JAMAICA STATION
Contact City,State,Zip:	JAMAICA, NY 11435
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	LIRR JAMAICA STATION
Mailing City,State,Zip:	JAMAICA, NY 11435
Owner Name:	Long Island Rail Road
Owner Type:	State
Operator Name:	Long Island Rail Road
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N

LIRR ATLANTIC AVENUE MANHOLES (Continued) **1000871619**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LONG ISLAND RAIL ROAD	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	JAMAICA STATION
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	718-657-1459
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: LONG ISLAND RAIL ROAD	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	JAMAICA STATION
Owner/Operator City,State,Zip:	JAMAICA, NY 11435

LIRR ATLANTIC AVENUE MANHOLES (Continued) **1000871619**

Owner/Operator Telephone: 718-657-1459
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: LONG ISLAND RAIL ROAD
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: JAMAICA STATION
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: 718-657-1459
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960520
Handler Name: LIRR ATLANTIC AVENUE MANHOLES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: LIRR ATLANTIC AVENUE MANHOLES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LIRR ATLANTIC AVENUE MANHOLES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

LIRR ATLANTIC AVENUE MANHOLES (Continued) **1000871619**

Receive Date: 19931216
Handler Name: LIRR ATLANTIC AVENUE MANHOLES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: LONG ISLAND RAILROAD
Address: S35-S34 ON ATLANTIC AVE BETW
City,State,Zip: BROOKLYN, NY 11217
Country: USA
EPA ID: NY0000078774
Facility Status: Not reported
Location Address 1: S35/S34 ATLANTIC AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000078774
Mailing Name: LONG ISLAND RAILROAD
Mailing Contact: TAMMYMOORE
Mailing Address 1: 90-27 SUTPHIN BLVD
Mailing Address 2: Not reported
Mailing City: JAMAICA
Mailing State: NY
Mailing Zip: 11435
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7186571603

AK311 **CON EDISON - MANHOLE 4179** **NJ MANIFEST** **S120667518**
North **CHAUNCEY ST & SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.228 mi.
1205 ft. **Site 4 of 6 in cluster AK**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYP004734406
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014161564JJK
EPA ID:	NYP004734406
Date Shipped:	2/20/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON - MANHOLE 4179 (Continued) **S120667518**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AK312 **CON EDISON** **NY MANIFEST** **S117740279**
North **CHAUNCEY ST & SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11217**
0.228 mi.
1205 ft. **Site 5 of 6 in cluster AK**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	CHAUNCEY ST & SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11217
Country:	USA
EPA ID:	NYP004734406
Facility Status:	Not reported
Location Address 1:	CHAUNCEY ST & SARATOGA AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11217
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004734406
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/20/2015
Trans1 Recv Date:	02/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004734406
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117740279**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014161564JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK313 **CON EDISON - MANHOLE 4179** **RCRA-LQG** **1018278660**
North **CHAUNCEY ST & SARATOGA AVE** **NYP004734406**
1/8-1/4 **BROOKLYN, NY 11217**
0.228 mi.
1205 ft. **Site 6 of 6 in cluster AK**

Relative: **Lower**

Actual: **40 ft.**

RCRA Listings:

Date Form Received by Agency:	20160205
Handler Name:	Con Edison - Manhole 4179
Handler Address:	CHAUNCEY ST & SARATOGA AVE
Handler City,State,Zip:	BROOKLYN, NY 11217
EPA ID:	NYP004734406
Contact Name:	THERESA BURKARD
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2262
Contact Fax:	646-582-2258
Contact Email:	BURKARDT@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported

CON EDISON - MANHOLE 4179 (Continued) **1018278660**

Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years

Year: 2015

Click Here for Biennial Reporting System Data:

CON EDISON - MANHOLE 4179 (Continued) **1018278660**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150220
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150220
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 4179
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150220
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON - MANHOLE 4179 (Continued) **1018278660**

Receive Date:	20150220
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AV314 **GP PETRO** **NY LTANKS** **S102962165**
WSW **1998 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.229 mi.
1208 ft. **Site 1 of 9 in cluster AV**

Relative: **Lower**

Actual: **79 ft.**

LTANKS:

Name:	GP PETRO
Address:	1998 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9712517 / 2006-05-17
Facility ID:	9712517
Site ID:	129283
Spill Date:	1998-02-09
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	1998-02-09
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-02-09
Spill Record Last Update:	2006-05-17

GP PETRO (Continued) **S102962165**

Spiller Name:	MR. ASSA SINGH
Spiller Company:	GP PETRO
Spiller Address:	1998 ATLANTIC AVENUE
Spiller County:	001
Spiller Contact:	BRUCE STRANG
Spiller Phone:	(718) 486-0011
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	111453
DEC Memo:	"5/17/06 - Mike - Could not contact GP Petro or find out if that is still current owner. From site occupant in 3/3/1998 contaminated soil was excavated while all the underground tanks were being upgraded to meet EPA regulations. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This gasoline spill case has been reassigned from DEC (Sigona) to Rommel on January 7, 2004. Jones- March 21, 2006 - unable to contact G.P. Petro. Recommend return to Region."
Remarks:	"CALLER IS DOING EXCAVATION AT SITE AND FOUND SOIL CONTAMINATION - TANK OR LINE FAILURE POSS CAUSE"

All Materials:

Site ID:	129283
Operable Unit ID:	1055380
Operable Unit:	01
Material ID:	327120
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AV315 **NORTH ATLANTIC SERVICE CENTER, INC.** **NY UST** **U001329922**
WSW **1998 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.229 mi.
1208 ft. **Site 2 of 9 in cluster AV**

Relative: **Lower**
Actual: **79 ft.**

UST:

Name:	NORTH ATLANTIC SERVICE CENTER, INC.
Address:	1998 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-601200 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	09/29/2023
UTM X:	591148.39385
UTM Y:	4503421.04777
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23170
Affiliation Type:	Mail Contact
Company Name:	NORTH ATLANTIC SERVICE CENTER, INC.

NORTH ATLANTIC SERVICE CENTER, INC. (Continued) **U001329922**

Contact Type:	PRESIDENT
Contact Name:	RATTAN SINGH
Address1:	1998 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(516) 773-2949
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-03-03

Site Id:	23170
Affiliation Type:	Emergency Contact
Company Name:	NORTH ATLANTIC SERVICE CENTER, INC.
Contact Type:	Not reported
Contact Name:	RATTAN SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 773-2949
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-03-03

Site Id:	23170
Affiliation Type:	Facility Operator
Company Name:	NORTH ATLANTIC SERVICE CENTER, INC.
Contact Type:	Not reported
Contact Name:	RATTAN SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 773-2949
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-03-03

Site Id:	23170
Affiliation Type:	Facility Owner
Company Name:	ASH / MAT ENTERPRISES, LLC
Contact Type:	PRESIDENT
Contact Name:	RATTAN SINGH
Address1:	10 HOFFSTOT LANE
Address2:	Not reported
City:	PORT WASHINGTON
State:	NY

NORTH ATLANTIC SERVICE CENTER, INC. (Continued) **U001329922**

Zip Code:	11050
Country Code:	001
Phone:	(516) 220-5549
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-03-03

Tank Info:

Tank Number:	1
Tank ID:	44928
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	06/01/1986
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	07/30/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A01 - Tank Internal Protection - Epoxy Liner
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	2
Tank ID:	44929
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	06/01/1986
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009

NORTH ATLANTIC SERVICE CENTER, INC. (Continued) **U001329922**

Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 07/30/2018
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
A01 - Tank Internal Protection - Epoxy Liner
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 3
Tank ID: 44930
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 06/01/1986
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 07/30/2018
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A01 - Tank Internal Protection - Epoxy Liner
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG

NORTH ATLANTIC SERVICE CENTER, INC. (Continued) **U001329922**

H05 - Tank Leak Detection - In-Tank System (ATG)

AV316 **PETROLEUM COMPLIANCE MANAGEMENT** **NY LTANKS** **S122481739**
WSW **1998 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.229 mi.
1208 ft. **Site 3 of 9 in cluster AV**

Relative: **Lower**
Actual: **79 ft.**

LTANKS:

Name:	PETROLEUM COMPLIANCE MANAGEMENT
Address:	1998 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1804629 / 2018-08-30
Facility ID:	1804629
Site ID:	574315
Spill Date:	2018-07-30
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2018-07-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2018-07-30
Spill Record Last Update:	2018-08-30
Spiller Name:	KEN GELOK
Spiller Company:	TANK TEST FAILURE
Spiller Address:	1998 ATLANTIC AVE
Spiller County:	999
Spiller Contact:	KEN GELOK
Spiller Phone:	(844) 726-1124
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	527300
DEC Memo:	"7/30/18 - Sekhon DEC Demeo told me to prepare TTF letter, Spoke with the facility operator to verify property owner info. TTF letter (DECDOCs unavailable for Spill # 1804629) send to property owner at manny@sigglobe.com and operator at gsingh2525@gmail.com. 7/31/18 - Sekhon Letter uploaded to DECDOCs. 8/30/18- DEC Piper received passing tightness test results. Based on work to date, this spill is closed."
Remarks:	"Tank test failure, 4000 gallons."

All Materials:

Site ID:	574315
Operable Unit ID:	1322115
Operable Unit:	01
Material ID:	2330334
Material Code:	0009

PETROLEUM COMPLIANCE MANAGEMENT (Continued) **S122481739**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

AT317 **CON EDISON SERVICE BOX: 28577** **RCRA NonGen / NLR** **1016973871**
ENE **213 MCDOUGAL ST** **NY MANIFEST** **NYP004476792**
1/8-1/4 **BROOKLYN, NY 11233**
0.230 mi.
1216 ft. **Site 5 of 5 in cluster AT**

Relative: **Higher**

Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20140424
Handler Name:	Con Edison Service Box: 28577
Handler Address:	MCDOUGAL ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004476792
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

CON EDISON SERVICE BOX: 28577 (Continued) **1016973871**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140324
Handler Name: CON EDISON SERVICE BOX:	28577
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140424
Handler Name: CON EDISON SERVICE BOX:	28577
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

CON EDISON SERVICE BOX: 28577 (Continued) **1016973871**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 213 MCDOUGAL ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004476792
Facility Status: Not reported
Location Address 1: FRONT OF 213 MACDOUGAS ST
Code: BP
Location Address 2: SB28577
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004476792
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/24/2014
Trans1 Recv Date: 03/24/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/26/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004476792
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported

CON EDISON SERVICE BOX: 28577 (Continued) **1016973871**

Manifest Tracking Number:	002406424GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	213 MCDOUGAL ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004715280
Facility Status:	Not reported
Location Address 1:	213 MCDOUGAL ST
Code:	BP
Location Address 2:	SB28577
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004715280
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON SERVICE BOX: 28577 (Continued) **1016973871**

Mailing Phone: Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/14/2015
Trans1 Recv Date:	01/14/2015
Trans2 Recv Date:	01/21/2015
TSD Site Recv Date:	01/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004715280
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620498GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG318
WSW
1/8-1/4
0.231 mi.
1219 ft.

LIRR ATLANTIC AVENUE VIADUCT
ATLANTIC AVE BETW RALPH &
BROOKLYN, NY 11204

Site 7 of 7 in cluster AG

RCRA NonGen / NLR

1000872534
NYD987037488

Relative:
Lower

Actual:
75 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Lirr Atlantic Avenue Viaduct
Handler Address:	ATLANTIC AVE BETW RALPH &
Handler City,State,Zip:	BROOKLYN, NY 11204
EPA ID:	NYD987037488
Contact Name:	Not reported
Contact Address:	LIRR JAMAICA STATION
Contact City,State,Zip:	JAMAICA, NY 11435
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	LIRR JAMAICA STATION
Mailing City,State,Zip:	JAMAICA, NY 11435
Owner Name:	Long Island Railroad
Owner Type:	State
Operator Name:	Long Island Railroad
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

LIRR ATLANTIC AVENUE VIADUCT (Continued) **1000872534**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LONG ISLAND RAILROAD	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	JAMAICA STATION
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	718-990-8252
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: LONG ISLAND RAILROAD	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	JAMAICA STATION
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	718-990-8252
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: LONG ISLAND RAILROAD	
Legal Status:	State
Date Became Current:	Not reported

LIRR ATLANTIC AVENUE VIADUCT (Continued) **1000872534**

Date Ended Current:	Not reported
Owner/Operator Address:	JAMAICA STATION
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	718-990-8252
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19960520
Handler Name:	LIRR ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	LIRR ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	LIRR ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19930715
Handler Name:	LIRR ATLANTIC AVENUE VIADUCT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

LIRR ATLANTIC AVENUE VIADUCT (Continued) **1000872534**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19940325
Handler Name:	LONG ISLAND RR / ATLANTIC AVE VIADUCT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	482111
NAICS Description:	LINE-HAUL RAILROADS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AN319 **ATA HOUSING CORP** **NY LTANKS** **S107410431**
SE **249 BOYLAND BD** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.232 mi.
1225 ft. **Site 4 of 4 in cluster AN**

Relative:
Higher

Actual:
112 ft.

LTANKS:

Name:	ATA HOUSING CORP
Address:	249 BOYLAND BD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0506553 / 2005-08-29
Facility ID:	0506553
Site ID:	351786
Spill Date:	2005-08-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2005-08-27
CID:	72
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	False

ATA HOUSING CORP (Continued) **S107410431**

UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-08-27
Spill Record Last Update:	2005-08-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	KEVIN RAFFERTY
Spiller Phone:	(716) 385-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	299062
DEC Memo:	"This spill is closed and referred back to Spill # 0506302"
Remarks:	"Must be excavated from end to end. All lines must be removed and tank must be tested alone."

All TTF:

Facility ID:	0506553
Spill Number:	0506553
Spill Tank Test:	1549255
Site ID:	351786
Tank Number:	1
Tank Size:	40000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Watchdog
Last Modified Date:	Not reported

AO320 **CON EDISON** **NY MANIFEST** **S117063440**
NNW **383 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.233 mi.
1228 ft. **Site 2 of 9 in cluster AO**

Relative: NY MANIFEST:
Lower

Actual:
43 ft.

Name:	CON EDISON
Address:	383 CHAUNCEY ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004558649
Facility Status:	Not reported
Location Address 1:	456 MARION ST
Code:	BP
Location Address 2:	SB30256
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

CON EDISON (Continued) **S117063440**

NY MANIFEST:

EPAID:	NYP004558649
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/2014
Trans1 Recv Date:	06/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004558649
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002424382GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S117063440**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO321 **CON EDISON** **NY MANIFEST** **S117063460**
NNW **383 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.233 mi.
1228 ft. **Site 3 of 9 in cluster AO**

Relative:
Lower

Actual:
43 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	383 CHAUNCEY ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004558862
Facility Status:	Not reported
Location Address 1:	383 CHAUNCEY ST
Code:	BP
Location Address 2:	SB16715
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004558862
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/2014
Trans1 Recv Date:	06/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004558862
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S117063460**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002424387GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO322 **CON EDISON SERVICE BOX: 16715** **RCRA NonGen / NLR** **1017777974**
NNW **383 CHAUNCEY ST** **NYP004558862**
1/8-1/4 **BROOKLYN, NY 11233**
0.233 mi.
1228 ft. **Site 4 of 9 in cluster AO**

Relative: **Lower**

Actual: **43 ft.**

RCRA Listings:

Date Form Received by Agency:	20140710
Handler Name:	Con Edison Service Box: 16715
Handler Address:	CHAUNCEY ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004558862
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON EDISON SERVICE BOX: 16715 (Continued) **1017777974**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140610
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON SERVICE BOX: 16715 (Continued) **1017777974**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140610
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140710
Handler Name: CON EDISON SERVICE BOX: 16715	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AO323 **CON EDISON SERVICE BOX: 30246** **RCRA NonGen / NLR** **1017777955**
NNW **383 CHAUNCEY ST** **NYP004558649**
1/8-1/4 **BROOKLYN, NY 11233**
0.233 mi.
1228 ft. **Site 5 of 9 in cluster AO**

Relative: **Lower**

Actual: **43 ft.**

RCRA Listings:

Date Form Received by Agency:	20140710
Handler Name:	Con Edison Service Box: 30246
Handler Address:	CHAUNCEY ST
Handler City,State,Zip:	BROOKLYN, NY 11233

CON EDISON SERVICE BOX: 30246 (Continued) **1017777955**

EPA ID:	NYP004558649
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No

CON EDISON SERVICE BOX: 30246 (Continued) **1017777955**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140610
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140610
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140710
Handler Name: CON EDISON SERVICE BOX: 30246	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 30246 (Continued) **1017777955**

Evaluations: No Evaluations Found

AI324 **NYCHA - BREVOORT HOUSES** **RCRA-SQG** **1024892294**
WNW **296 RALPH AVE** **NYR000238931**
1/8-1/4 **BROOKLYN, NY 11233**
0.234 mi.
1233 ft. **Site 17 of 17 in cluster AI**

Relative: **Lower**
Actual: **58 ft.**

RCRA Listings:

Date Form Received by Agency:	20181101
Handler Name:	Nycha - Brevoort Houses
Handler Address:	RALPH AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYR000238931
Contact Name:	JOHN BROWN
Contact Address:	RALPH AVE
Contact City,State,Zip:	BROOKLYN, NY 11233
Contact Telephone:	718-493-1600
Contact Fax:	Not reported
Contact Email:	JOHNBROWN@NYCHA.NYC.GOV
Contact Title:	PROPERTY MAINTENANCE SUPERVISOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	RALPH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11233
Owner Name:	Robert Mallamo
Owner Type:	Municipal
Operator Name:	John Brown
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

NYCHA - BREVOORT HOUSES (Continued) **1024892294**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181108
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOHN BROWN	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	296 RALPH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11233
Owner/Operator Telephone:	718-493-1600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JOHNBROWN@NYCHA.NYC.GOV

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROBERT MALLAMO	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	23-02 49TH AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-702-5298
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	ROBERTMALLAMO@NYCHA.NYC.GOV

Historic Generators:

Receive Date:	20181101
Handler Name:	NYCHA - BREVOORT HOUSES
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

NYCHA - BREVOORT HOUSES (Continued) **1024892294**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	92511
NAICS Description:	ADMINISTRATION OF HOUSING PROGRAMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AO325 **CON EDISON** **NJ MANIFEST** **S120673709**
NNW **375 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.235 mi.
1242 ft. **Site 6 of 9 in cluster AO**

Relative:
Lower

Actual:
41 ft.

NJ MANIFEST:

EPA Id:	NYP004804811
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619756GBF
EPA ID:	NYP004804811
Date Shipped:	7/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CON EDISON (Continued) **S120673709**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AO326 **CON EDISON** **RCRA NonGen / NLR** **1019905017**
NNW **375 CHAUNCEY ST** **NYP004804811**
1/8-1/4 **BROOKLYN, NY 11233**
0.235 mi.
1242 ft. **Site 7 of 9 in cluster AO**

Relative: **Lower**

Actual: **41 ft.**

RCRA Listings:

Date Form Received by Agency:	20150803
Handler Name:	Con Edison
Handler Address:	CHAUNCEY ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004804811
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

CON EDISON (Continued) **1019905017**

Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150803
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON (Continued) **1019905017**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150803
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AO327 **CON EDISON** **NY MANIFEST** **S118258510**
NNW **375 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.235 mi.
1242 ft. **Site 8 of 9 in cluster AO**

Relative: **Lower**
Actual: **41 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 375 CHAUNCEY ST
City,State,Zip: BROOKLYN, NY
Country: USA
EPA ID: NYP004817003
Facility Status: Not reported
Location Address 1: 375 CHAUNCEY ST
Code: BP
Location Address 2: SB 16715
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004817003
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK

CON EDISON (Continued) **S118258510**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/03/2015
Trans1 Recv Date:	08/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004817003
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619415GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AO328 **CON EDISON** **NY MANIFEST** **S118257690**
NNW **375 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.235 mi.
1242 ft. **Site 9 of 9 in cluster AO**

Relative:
Lower

Actual:
41 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	375 CHAUNCEY ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004804811
Facility Status:	Not reported
Location Address 1:	375 CHAUNCEY ST
Code:	BP
Location Address 2:	SB 16715
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004804811
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2015
Trans1 Recv Date:	07/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004804811
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619756GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118257690**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AS329 **CON EDISON** **NJ MANIFEST** **S120669257**
NW **215 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.236 mi.
1246 ft. **Site 2 of 4 in cluster AS**

Relative: **Lower**
Actual: **50 ft.**

NJ MANIFEST:

EPA Id:	NYP004754073
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002660477GBF
EPA ID:	NYP004754073
Date Shipped:	3/19/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120669257**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AS330 **CON EDISON** **RCRA NonGen / NLR** **1018280520**
NW **215 MARION ST** **FINDS** **NYP004754073**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.236 mi.
1246 ft. **Site 3 of 4 in cluster AS**

Relative: **Lower**

Actual: **50 ft.**

RCRA Listings:

Date Form Received by Agency:	20150319
Handler Name:	Con Edison
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004754073
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1018280520**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150319
Handler Name:	CON EDISON

CON EDISON (Continued) **1018280520**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150319
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067707208

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280520
Registry ID:	110067707208
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067707208
Name:	CON EDISON
Address:	215 MARION ST

CON EDISON (Continued) **1018280520**

City,State,Zip: BROOKLYN, NY 11233

AS331 **CON EDISON** **NY MANIFEST** **S117742119**
NW **215 MARION ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.236 mi.
1246 ft. **Site 4 of 4 in cluster AS**

Relative:
Lower

Actual:
50 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	215 MARION ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004754073
Facility Status:	Not reported
Location Address 1:	215 MARION ST
Code:	BP
Location Address 2:	SB30212
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004754073
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2015
Trans1 Recv Date:	03/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004754073
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002660477GBF
Import Indicator:	N
Export Indicator:	N

CON EDISON (Continued) **S117742119**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW332 **CON EDISON** **NJ MANIFEST** **S120668233**
North **138 SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.238 mi.
1259 ft. **Site 1 of 3 in cluster AW**

Relative:
Lower

Actual:
40 ft.

NJ MANIFEST:

EPA Id:	NYP004742177
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002621247GBF
EPA ID:	NYP004742177
Date Shipped:	3/3/2015
TSDF EPA ID:	NJD991291105

CON EDISON (Continued) **S120668233**

Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AW333 **CON EDISON** **NY MANIFEST** **S117741024**
North **138 SARATOGA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.238 mi.
1259 ft. **Site 2 of 3 in cluster AW**

Relative: **Lower**
Actual: **40 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	138 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004742177
Facility Status:	Not reported
Location Address 1:	138 SARATOGA AV
Code:	BP
Location Address 2:	SB41917
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY

CON EDISON (Continued) **S117741024**

Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004742177
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/03/2015
Trans1 Recv Date:	03/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004742177
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002621247GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117741024**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AW334 **CON EDISON** **RCRA NonGen / NLR** **1018279411**
North **138 SARATOGA AVE** **FINDS** **NYP004742177**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.238 mi.
1259 ft. **Site 3 of 3 in cluster AW**

Relative: **Lower**
Actual: **40 ft.**

RCRA Listings:

Date Form Received by Agency:	20150303
Handler Name:	Con Edison
Handler Address:	SARATOGA AVE
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004742177
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

CON EDISON (Continued) **1018279411**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150303
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150303
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1018279411**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067690680

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279411
Registry ID:	110067690680
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067690680
Name:	CON EDISON
Address:	138 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY 11233

AX335 **CON EDISON** **RCRA NonGen / NLR** **1019906451**
ESE **12 GUNTHER PL** **FINDS** **NYP004821209**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.241 mi.
1272 ft. **Site 1 of 4 in cluster AX**

Relative:
Higher

Actual:
100 ft.

RCRA Listings:

Date Form Received by Agency:	20150810
Handler Name:	Con Edison
Handler Address:	GUNTHER PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004821209
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

CON EDISON (Continued) **1019906451**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150810
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1019906451**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150810
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069653707

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906451
Registry ID:	110069653707
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069653707
Name:	CON EDISON
Address:	12 GUNTHER PL
City,State,Zip:	BROOKLYN, NY 11233

AX336
ESE
1/8-1/4
0.241 mi.
1272 ft.

CON EDISON
12 GUNTHER PL
BROOKLYN, NY 11233

Site 2 of 4 in cluster AX

NJ MANIFEST **S120675218**
N/A

Relative:
Higher

Actual:
100 ft.

NJ MANIFEST:

EPA Id:	NYP004821209
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624753GBF
EPA ID:	NYP004821209
Date Shipped:	8/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675218**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AX337 **CON ED** **NY MANIFEST** **S119077126**
ESE **12 GUNTHER PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.241 mi.
1272 ft. **Site 3 of 4 in cluster AX**

Relative:
Higher

Actual:
100 ft.

NY MANIFEST:

Name:	CON ED
Address:	12 GUNTHER PL
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004821209
Facility Status:	Not reported
Location Address 1:	20 GUNTHER PL
Code:	BP
Location Address 2:	SB 11890
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004821209
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2015
Trans1 Recv Date:	08/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004821209
Trans1 EPA ID:	Not reported

CON ED (Continued) **S119077126**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624753GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AV338 **CON EDISON** **RCRA NonGen / NLR** **1019909137**
WSW **1885 ATLANTIC AVE** **NYP004881427**
1/8-1/4 **BROOKLYN, NY 14977**
0.241 mi.
1273 ft. **Site 4 of 9 in cluster AV**

Relative: **Lower**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:	20151218
Handler Name:	Con Edison
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 14977
EPA ID:	NYP004881427
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON (Continued) **1019909137**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151218
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator

CON EDISON (Continued) **1019909137**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20151218
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AV339 **CON EDISON** **NJ MANIFEST** **S120678305**
WSW **1885 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 14977**
0.241 mi.
1273 ft. **Site 5 of 9 in cluster AV**

Relative: **Lower**

Actual: **71 ft.**

NJ MANIFEST:

EPA Id:	NYP004881427
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

CON EDISON (Continued) **S120678305**

Manifest:

Manifest Number:	015320242JJK
EPA ID:	NYP004881427
Date Shipped:	12/18/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AV340 **1885 ATLANTIC AVENUE REDEVELOPMENT** **NY LTANKS** **S100494351**
WSW **1885 ATLANTIC AVENUE** **NY BROWNFIELDS** **N/A**
1/8-1/4 **BROOKLYN, NY 11233** **NY Spills**
0.241 mi.
1273 ft. **Site 6 of 9 in cluster AV**

Relative:
Lower

Actual:
71 ft.

LTANKS:

Name:	1885 ATLANTIC AVE
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9209626 / 1994-07-22
Facility ID:	9209626
Site ID:	132469

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Spill Date:	1992-11-18
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	1994-07-22
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1992-11-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-11-23
Spill Record Last Update:	1994-08-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	114077
DEC Memo:	""
Remarks:	"POSS EX-ISO AND RETEST"

All TTF:

Facility ID:	9209626
Spill Number:	9209626
Spill Tank Test:	1540860
Site ID:	132469
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	132469
Operable Unit ID:	976207
Operable Unit:	01
Material ID:	406669
Material Code:	0009
Material Name:	gasoline

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BROWNFIELDS:

Name:	1885 ATLANTIC AVENUE REDEVELOPMENT
Address:	1885 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Program:	BCP
Site Code:	628592
Acres:	0.210
HW Code:	C224347
SWIS:	2401
Town:	New York City
Record Added Date:	11/18/2021
Record Updated Date:	04/18/2023
Update By:	WBBENNET
Site Description:	Site Location: The 1885 Atlantic Avenue Redevelopment Site is a 0.21-acre site located in an urban area of the Stuyvesant Heights neighborhood of Brooklyn, NY. The site is located on the north side of Atlantic Avenue between Ralph Avenue and Columbus Place. The site is comprised of a single lot identified as Block 1714 Lot 30 on the New York City Tax Map. The site is bounded by a parking lot to the north, Ralph Avenue followed by a mixed-use commercial and residential buildings to the east, Atlantic Avenue and the Long Island Railroad Tracks to the south, and a commercial building occupied by McDonald restaurant to the west. Site Features: The site was occupied by an active retail petroleum station and was improved with two low-rise buildings utilized for storage and as the Speedway Kiosk building. Both structures demolished and all known USTs, associated piping and accessories were removed during Interim Remedial Measure (IRM) activities conducted from June 2022 to August 2022. Current Zoning and Land Use: The Site is located within a residential and manufacturing zoning district (M1-1 and R7D) and special mixed-use MX-10 zoning area with Mandatory Inclusionary Housing (MIH). The surrounding properties are currently used for commercial, residential, and warehousing/manufacturing purposes. The nearest residential building is to the west side of the site, across Ralph Avenue. Past Land Use: The site was a woodworking shop before 1932, an auto repair shop and a garage from 1932 to the 1950s, a metal product manufacturing facility from the 1950s to the 1960s and was a retail petroleum station and an auto wrecking facility from the 1960s to 1978. Site Geology and Hydrogeology: The Site is underlain by a layer of fill material consisting of light to dark brown, fine to medium sand with varying amounts of silt, clay, and gravel with brick, concrete, slag/ash, glass, ceramic, and asphalt fragments. Fill extends to variable depths between 5 and 15 feet below ground surface (ft bgs). Brown to orange fine to medium sand with varying amounts of silt, gravel, and intermittent clay lenses underly the fill layer and extend to at least 35 ft bgs. Groundwater was encountered at depths ranging from 60.73 to 63.60 ft bgs and flows from northeast to southwest.

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Env Problem:

Nature and Extent of Contamination: Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor samples were analyzed for VOCs. Based upon the investigations conducted to date, the primary contaminants of concern for the site are VOCs, SVOCs and metals in soil and VOCs in groundwater. Soil - Soil data for VOCs were compared to Unrestricted Use Soil Cleanup Objectives (UUSCOs) and Protection of Groundwater Soil Cleanup Objectives (POGSCOs). The following VOCs exceeded both UUSCOs and POGSCOs in site soils: 1,2,4-trimethylbenzene at concentrations up to 300 ppm (parts per million) (UUSCO/POGSCO is 3.6 ppm), 1,3,5-trimethylbenzene at concentrations up to 110 ppm (UUSCO/POGSCO is 8.4 ppm), benzene at a concentrations up to 33 ppm (UUSCO/POGSCO is 0.06 ppm), ethylbenzene at a concentrations up to 130 ppm (UUSCO/POGSCO is 1 ppm), toluene at concentrations up to 310 ppm (UUSCO/POGSCO is 0.7 ppm), and total xylenes at concentration up to 640 ppm (UUSCO/POGSCO is 0.26 ppm). Elevated levels of VOCs in site soils extend from the site surface to at least 55 feet bgs. Based on the Supplemental Remedial Investigation extent of VOCs contamination detected at deeper locations, around 45-50 feet bgs. Two SVOCs exceeded UUSCOs in a site soil sample collected from 0 to 0.5 feet bgs: benzo(b)fluoranthene at a concentration of 1.24 ppm (UUSCO is 1 ppm) and indeno(1,2,3-cd)pyrene at a concentration of 0.537 ppm (UUSCO is 0.5 ppm). For metals, the following constituents exceeded UUSCOs in site soils: copper up to 107 ppm (UUSCO is 50 ppm), lead up to 597 ppm (UUSCO is 63 ppm), mercury up to 0.79 ppm (UUSCO is 0.18 ppm). PCBs and 1,4-dioxane were not detected in site soils above UUSCOs and per- and polyfluoroalkyl substances (PFAS) were not detected in site soils above unrestricted guidance values. Data does not indicate any off-site impacts in soil related to this site. Groundwater The chlorinated VOC tetrachloroethylene (PCE) was detected in one monitoring well at a concentration of 18 ppb exceeding the ambient water quality standard (AWQS) for PCE of 5 ppb. Other petroleum related VOCs were also detected in groundwater including 1,2,4-trimethylbenzene at maximum concentration 41.4 ppb (parts per billion) (AWQS is 5 ppb), benzene at maximum concentration 569 ppb (AWQS is 1 ppb), toluene at maximum concentration 20.5 ppb (AWQS is 5 ppb), and total xylenes at maximum concentration 98.1 ppb (AWQS is 5 ppb). Additionally, several VOCs were detected above the AWQS in only one well including 1,3,5-trimethylbenzene at 16 ppb, sec-butylbenzene at 16.8 ppb, ethylbenzene at 32 ppb, isopropylbenzene at 5.6 ppb and n-propylbenzene at 9.5 ppb. Two SVOCs were detected in groundwater samples collected from the site at levels exceeding AWQS including bis(2-ethylhexyl)phthalate at 6.1 ppb (AWQS is 5 ppb) and diethyl phthalate at 448 ppb (AWQS is 50 ppb). The metal manganese was detected in groundwater samples collected from the site at concentrations up to 1,640 ppb (AWQS is 300 ppb). VOCs over AWQS in groundwater are likely the result of an on-site source of VOCs in soil. SVOCs and metals over AWQS in groundwater are likely the result of entrained sediments in groundwater samples for SVOCs or naturally occurring phenomenon for metals. No PCBs was detected in groundwater samples above AWQS. 1,4-dioxane was not detected in groundwater samples collected from the site. Perfluorooctanesulfonic Acid (PFOS) was detected in one well at 90 ppt, exceeding the guidance value of 10 ppt. Perfluorooctanoic Acid (PFOA) was detected at concentrations exceeding the guidance value of 10 ppt in three wells at maximum

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

concentration of 330 ppt. PFOA and PFOS concentrations are higher in monitoring wells down gradient of the site compared to monitoring wells up gradient of the site, however no source of PFOA and PFOS was encountered in site soils. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several petroleum-related VOCs were detected at elevated concentrations in soil vapor samples including benzene (maximum concentration 1,190,000 micrograms per meter cubed (ug/m^3)) and toluene (maximum concentration of 240,000 ug/m^3). Total benzene, toluene, ethylbenzene, and total xylene (BTEX) concentrations ranged from non-detect to a maximum of 1,430,000 ug/m^3. Total VOC concentrations ranged from 1,348.13 ug/m^3 to 10,846,000 ug/m^3. The Supplemental Remedial Investigation confirmed the extent of petroleum VOCs contamination down to 45 feet bgs. Several other VOCs were also detected in multiple soil vapor samples including 1,3-butadiene (maximum concentration 2,460 ug/m^3), 2,2,4-trimethlypentane (maximum concentration 4,260,000 ug/m^3), 2-butanone (maximum concentration 1,100 ug/m^3), cyclohexane (maximum concentration 606,000 ug/m^3), heptane (maximum concentration 672,000 ug/m^3), and n-hexane (maximum concentration 7,190,000 ug/m^3). Data does not indicate any off-site impacts in soil vapor related to this site.

Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2022-02-01 10:18:00
Record Upd:	2022-12-22 11:55:00
Updated By:	SXAHMED
Own Op:	6
Sub Type:	P03
Owner Name:	Jacob Kohn
Owner Company:	1885 Atlantic Realty LLC
Owner Address:	40 Oser Avenue, Suite 4
Owner Addr2:	Not reported
Owner City,St,Zip:	Hauppauge, NY 11788
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Speedway LLC
Owner Company:	Speedway LLC
Owner Address:	500 Speedway Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Enon, OH 45323
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Speedway LLC
Owner Address:	500 Speedway Drive

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Owner Addr2:	Not reported
Owner City,St,Zip:	Enon, OH 45323
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Henry L. Butler
Owner Company:	Brooklyn Community Board 3
Owner Address:	1360 Fulton Street, 2nd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11216
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Paul Levy
Owner Company:	Brooklyn Public Library - Brownsville Branch
Owner Address:	61 Glenmore Ave. at Watkins St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
HW Code:	C224347
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	sec-butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	n-propylbenzene

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224347
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	HESS # 32528
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0907189 / 2009-10-07
Facility ID:	0907189
Facility Type:	ER
DER Facility ID:	114077
Site ID:	419679
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-09-25
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2009-09-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-09-25
Spill Record Last Update:	2009-10-07
Spiller Name:	MICHAEL MATRI
Spiller Company:	HESS # 32528
Spiller Address:	1885 ATLANTIC AVE
Spiller Company:	999
Contact Name:	MICHAEL MATRI
DEC Memo:	"Leak was contained & cleaned. Repairs made. Spill Closed"
Remarks:	"LEAKING FLEX CONNECTOR UNDER DISPENSER LESS THAN A GALLON SPILLED TO DISPENSER PAN. CLEAN UP AND REPAIR DONE."

All Materials:

Site ID:	419679
Operable Unit ID:	1175700
Operable Unit:	01
Material ID:	2168333
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	HESS # 32528
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0611614 / 2007-02-23
Facility ID:	0611614
Facility Type:	ER
DER Facility ID:	114077
Site ID:	376288
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-01-19
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-01-19
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-19
Spill Record Last Update:	2007-02-23

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Spiller Name:	MICHEAL MATRI
Spiller Company:	HESS # 32528
Spiller Address:	1885 ATLANTIC AVE
Spiller Company:	001
Contact Name:	MICHEAL MATRI
DEC Memo:	"spill closed - see attached eDocs > On 1/19/07 a tightness testing contractor (Crompco) identified a > leaking flex connector beneath a dispenser at Station #32528 . The > flex line was only leaking under test pressure (1.5 times working > pressure). Less than one gallon of product was contained in the > dispenser pan. The contractor cleaned-up the spill and repaired the > flex line. Attached please find Crompco's post repair tightness test > demonstrating the product line as being tight. Hess respectfully > requests closure of spill No. 06-11614 as no impact to the environment > has occurred, spilled product has been cleaned-up and the product line > has been repaired. > "
Remarks:	"pump #5 has a line leak: clean up and reapir on going:"

All Materials:

Site ID:	376288
Operable Unit ID:	1133874
Operable Unit:	01
Material ID:	2123703
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	STATION 32528
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0612533 / 2007-02-20
Facility ID:	0612533
Facility Type:	ER
DER Facility ID:	114077
Site ID:	377438
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-02-17
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2007-02-17
CID:	76
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2007-02-20
Spill Record Last Update:	2007-02-20
Spiller Name:	MANGAGER CLARENCE
Spiller Company:	AMEREDA HESS
Spiller Address:	1885 ATLANTIC AVE
Spiller Company:	001
Contact Name:	MANGAGER CLARENCE
DEC Memo:	"Spill cleaned and pump out os service until hose is replaced. Closed."
Remarks:	"CALLER REPORTS SPILL CONFINED TO CONCRETE PAD. SPILL CONTAINED AND CLEANUP USING SPEEDY DRY. CAUSE OF SPILL WAS A RUPTURED DISPENSER HOSE."

All Materials:

Site ID:	377438
Operable Unit ID:	1134972
Operable Unit:	01
Material ID:	2124857
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	6.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HESS-1885 ATLANTIC AVE
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9303355 / 2003-03-18
Facility ID:	9303355
Facility Type:	ER
DER Facility ID:	114077
Site ID:	305495
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1993-06-14
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1993-06-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

1885 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S100494351**

UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1993-06-15
Spill Record Last Update:	2008-08-11
Spiller Name:	Not reported
Spiller Company:	MERIT OIL GAS STATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND CROSS REF 0000590 & 0105801"
Remarks:	"DISCOVERED SOIL IN TANK PULL SOIL PILED AND WILL TEST FOR DISPOSAL."

All Materials:

Site ID:	305495
Operable Unit ID:	985240
Operable Unit:	01
Material ID:	396937
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AV341 **SPEEDWAY 7833** **RCRA-VSQG** **1000263760**
WSW **1885 ATLANTIC AVE** **NY UST** **NYD982185530**
1/8-1/4 **BROOKLYN, NY 11233** **US AIRS**
0.241 mi. **FINDS**
1273 ft. **Site 7 of 9 in cluster AV** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
71 ft.

RCRA Listings:

Date Form Received by Agency:	20160921
Handler Name:	Speedway 7833
Handler Address:	ATLANTIC AVE
Handler City,State,Zip:	BROOKLYN, NY 11233-3045
EPA ID:	NYD982185530
Contact Name:	CHARLES A BESSE
Contact Address:	PO BOX 1500
Contact City,State,Zip:	SPRINGFIELD, OH 45501-1500
Contact Telephone:	937-863-6272
Contact Fax:	937-863-6078
Contact Email:	CABESSE@SPEEDWAY.COM
Contact Title:	ENVIRONMENTAL COMPLIANCE ADMIN
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny

SPEEDWAY 7833 (Continued) **1000263760**

State District:	NYSDEC R2
Mailing Address:	PO BOX 1500
Mailing City,State,Zip:	SPRINGFIELD, OH 45501-1500
Owner Name:	Merit Oil Corp
Owner Type:	Private
Operator Name:	Merit Oil Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161012
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

SPEEDWAY 7833 (Continued) **1000263760**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: SPEEDWAY LLC	
Legal Status:	Private
Date Became Current:	20141001
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1500
Owner/Operator City,State,Zip:	SPRINGFIELD, OH 45501-1500
Owner/Operator Telephone:	937-864-3000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

SPEEDWAY 7833 (Continued) **1000263760**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MERIT OIL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SPEEDWAY LLC
Legal Status: Private
Date Became Current: 20141001
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MERIT OIL CORP

SPEEDWAY 7833 (Continued) **1000263760**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19870511
Handler Name: MERIT OIL CORP	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160921
Handler Name: SPEEDWAY 7833	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	447110
NAICS Description:	GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

UST:

Name:	SPEEDWAY # 7833
Address:	1885 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-297569 / Unregulated/Closed
Program Type:	PBS
Region:	STATE

SPEEDWAY 7833 (Continued) **1000263760**

DEC Region:	2
Expiration Date:	N/A
UTM X:	591093.48783
UTM Y:	4503477.39406
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	13747
Affiliation Type:	Emergency Contact
Company Name:	SPEEDWAY LLC
Contact Type:	GAS COMPLIANCE MANAGER
Contact Name:	JOEL KOHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 578-3749
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-01-27

Site Id:	13747
Affiliation Type:	Facility Operator
Company Name:	SPEEDWAY # 7833
Contact Type:	Not reported
Contact Name:	1885 ATLANTIC REALTY, LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 846-1115
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-02-02

Site Id:	13747
Affiliation Type:	Facility Owner
Company Name:	1885 ATLANTIC REALTY, LLC
Contact Type:	MEMBER
Contact Name:	JACOB KOHN
Address1:	40 OSER AVENUE
Address2:	SUITE 4
City:	HAUPPAUGE
State:	NY
Zip Code:	11788
Country Code:	001
Phone:	(917) 846-1115
EMail:	KOHNJACOB@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-02-02

SPEEDWAY 7833 (Continued) **1000263760**

Site Id:	13747
Affiliation Type:	Mail Contact
Company Name:	JACOB KOHN
Contact Type:	MEMBER
Contact Name:	JACOB KOHN
Address1:	40 OSER AVENUE, SUITE 4
Address2:	Not reported
City:	HAUPPAUGE
State:	NY
Zip Code:	11788
Country Code:	001
Phone:	(917) 846-1115
EMail:	KOHNJACOB@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	001
Tank ID:	15762
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	02/01/1971
Date Tank Closed:	05/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	11/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	15763
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	02/01/1971

SPEEDWAY 7833 (Continued) **1000263760**

Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 11/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 15764
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 02/01/1971
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 11/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

SPEEDWAY 7833 (Continued) **1000263760**

Tank Number: 004
Tank ID: 15765
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 02/01/1971
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: ZZ
Date Test: 05/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 15766
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 02/01/1971
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: ZZ
Date Test: 05/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

SPEEDWAY 7833 (Continued) **1000263760**

A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

Tank Number: 006
Tank ID: 15767
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 02/01/1971
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: ZZ
Date Test: 05/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

Tank Number: 007
Tank ID: 15768
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 02/01/1971
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 11/01/1992
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

SPEEDWAY 7833 (Continued) **1000263760**

Equipment Records:
H99 - Tank Leak Detection - Other
J00 - Dispenser - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

Tank Number: 008
Tank ID: 15769
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 02/01/1971
Date Tank Closed: 05/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:
H99 - Tank Leak Detection - Other
J00 - Dispenser - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 009
Tank ID: 46309
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1993
Date Tank Closed: 06/02/2022
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

SPEEDWAY 7833 (Continued) **1000263760**

Tightness Test Method: 00
Date Test: 09/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSALI
Last Modified: 01/24/2023

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 010
Tank ID: 46310
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1993
Date Tank Closed: 06/03/2022
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSALI
Last Modified: 01/24/2023

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
I01 - Overfill - Float Vent Valve
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser

SPEEDWAY 7833 (Continued) **1000263760**

E04 - Piping Secondary Containment - Double walled UG

Tank Number: 011
Tank ID: 46311
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1993
Date Tank Closed: 06/03/2022
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSALI
Last Modified: 01/24/2023

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 012
Tank ID: 46312
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1993
Date Tank Closed: 06/06/2022
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSALI

SPEEDWAY 7833 (Continued) **1000263760**

Last Modified: 01/24/2023

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 013
Tank ID: 46313
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1993
Date Tank Closed: 06/06/2022
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 00
Date Test: 09/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSALI
Last Modified: 01/24/2023

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 014
Tank ID: 46314

SPEEDWAY 7833 (Continued) **1000263760**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	06/01/1993
Date Tank Closed:	06/03/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	00
Date Test:	09/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSALI
Last Modified:	01/24/2023

Equipment Records:

J00 - Dispenser - None
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

US AIRS MINOR:

Envid:	1000263760
Region Code:	02
Programmatic ID:	AIR NY0000002610400146
Facility Registry ID:	110004415856
D and B Number:	Not reported
Primary SIC Code:	5541
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610400146
Facility Registry ID:	110004415856
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1988-05-03 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

SPEEDWAY 7833 (Continued) **1000263760**

FINDS:
Registry ID: 110004415856

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000263760
Registry ID:	110004415856
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004415856
Name:	MERIT RALPH
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233

NY MANIFEST:

Name:	MERIT OIL
Address:	1885 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11233-3045
Country:	USA
EPA ID:	NYD982185530
Facility Status:	Not reported
Location Address 1:	1885 ATLANTIC AVE & RALPH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	10036
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982185530
Mailing Name:	MERIT OIL
Mailing Contact:	VINCENT MENZA
Mailing Address 1:	1885 ATLANTIC AVE & RALPH AVE
Mailing Address 2:	Not reported

SPEEDWAY 7833 (Continued) **1000263760**

Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	10036
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

AU342 **CON EDISON - MANHOLE 16727** **NY MANIFEST** **S121967828**
NNE **428 CHAUNCEY ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.242 mi.
1279 ft. **Site 2 of 3 in cluster AU**

Relative:
Lower

Actual:
52 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 16727
Address:	428 CHAUNCEY ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP005050356
Facility Status:	Not reported
Location Address 1:	428 CHAUNCEY ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005050356
Mailing Name:	CON EDISON - MANHOLE 16727
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AU343 **CON EDISON - MANHOLE 16727** **RCRA-LQG** **1024890919**
NNE **428 CHAUNCEY ST** **NYP005050356**
1/8-1/4 **BROOKLYN, NY 11233**
0.242 mi.
1279 ft. **Site 3 of 3 in cluster AU**

Relative:
Lower

Actual:
52 ft.

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Manhole 16727
Handler Address:	CHAUNCEY ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP005050356
Contact Name:	ALYSSA SOTTO

CON EDISON - MANHOLE 16727 (Continued) **1024890919**

Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON - MANHOLE 16727 (Continued) **1024890919**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170321
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170321
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - MANHOLE 16727
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122

CON EDISON - MANHOLE 16727 (Continued) **1024890919**

NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AJ344 **CON EDISON SERVICE BOX: 30235** **RCRA NonGen / NLR** **1016973227**
NE **392 MARION ST** **NY MANIFEST** **NYP004470217**
1/8-1/4 **BROOKLYN, NY 11233**
0.244 mi.
1288 ft. **Site 3 of 3 in cluster AJ**

Relative:
Lower

Actual:
60 ft.

RCRA Listings:

Date Form Received by Agency:	20140418
Handler Name:	Con Edison Service Box: 30235
Handler Address:	MARION ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004470217
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

CON EDISON SERVICE BOX: 30235 (Continued) **1016973227**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140318
Handler Name: CON EDISON SERVICE BOX:	30235
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140418
Handler Name: CON EDISON SERVICE BOX:	30235
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

CON EDISON SERVICE BOX: 30235 (Continued) **1016973227**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 392 MARION ST
City,State,Zip: BROOKLYN, NY 11233
Country: USA
EPA ID: NYP004470217
Facility Status: Not reported
Location Address 1: 392 MARION ST
Code: BP
Location Address 2: SB30235
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11233
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004470217
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 03/18/2014
Trans1 Recv Date: 03/18/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/19/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004470217
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported

CON EDISON SERVICE BOX: 30235 (Continued) **1016973227**

Manifest Tracking Number:	002405847GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AY345 **CON EDISON** **NY MANIFEST** **S117319783**
NE **FRONT OF 297 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.244 mi.
1289 ft. **Site 1 of 2 in cluster AY**

Relative: **Lower**
Actual: **70 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 297 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004680195
Facility Status:	Not reported
Location Address 1:	FRONT OF 297 SUMPTER ST
Code:	BP
Location Address 2:	SB42263
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004680195
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON

CON EDISON (Continued) **S117319783**

Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2014
Trans1 Recv Date:	10/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004680195
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618098GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AX346 **CON EDISON SERVICE BOX: 11890** **RCRA NonGen / NLR** **1017772759**
ESE **20 GUNTHER PL** **FINDS** **NYP004497194**
1/8-1/4 **BROOKLYN, NY 11233**
0.245 mi.
1292 ft. **Site 4 of 4 in cluster AX**

Relative: **Higher**

Actual: **99 ft.**

RCRA Listings:

Date Form Received by Agency:	20140510
Handler Name:	Con Edison Service Box: 11890
Handler Address:	GUNTHER PL
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004497194
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 11890 (Continued) **1017772759**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140510
Handler Name: CON EDISON SERVICE BOX: 11890	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 11890 (Continued) **1017772759**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063791446

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AY347 **CON EDISON** **NY MANIFEST** **S117315181**
ENE **FRONT OF 290 SUMPTER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.247 mi.
1303 ft. **Site 2 of 2 in cluster AY**

Relative:
Lower

Actual:
76 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 290 SUMPTER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004623138
Facility Status:	Not reported
Location Address 1:	FRONT OF 290 SUMPTER ST
Code:	BP
Location Address 2:	SB42269
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004623138
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117315181**

Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/08/2014
Trans1 Recv Date:	08/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/12/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004623138
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616179GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AP348 **CON EDISON SERVICE BOX: 22022** **RCRA NonGen / NLR** **1017772756**
East **1261 HERKIMER ST** **NYP004497160**
1/8-1/4 **BROOKLYN, NY 11233**
0.247 mi.
1306 ft. **Site 4 of 5 in cluster AP**

Relative: **Higher**
Actual: **102 ft.**

RCRA Listings:

Date Form Received by Agency:	20140510
Handler Name:	Con Edison Service Box: 22022
Handler Address:	HERKIMER ST
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004497160
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 22022 (Continued) **1017772756**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140510
Handler Name: CON EDISON SERVICE BOX: 22022	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 22022 (Continued) **1017772756**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AP349 **CON EDISON** **NY MANIFEST** **S116551271**
East **1261 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.247 mi.
1306 ft. **Site 5 of 5 in cluster AP**

Relative:
Higher

Actual:
102 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	1261 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004497160
Facility Status:	Not reported
Location Address 1:	F/O 20 GUNTHER PLACE
Code:	BP
Location Address 2:	SB 22022
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004497160
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/10/2014
Trans1 Recv Date:	04/10/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/2014

CON EDISON (Continued) **S116551271**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004497160
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771342JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AV350 **SPILL NUMBER 9907632** **NY LTANKS** **S104620493**
WSW **1994 ATLANTIC AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.254 mi.
1340 ft. **Site 8 of 9 in cluster AV**

Relative: **Lower**
Actual: **77 ft.**

LTANKS:

Name:	SPILL NUMBER 9907632
Address:	1994 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9907632 / 2004-01-09
Facility ID:	9907632
Site ID:	314056
Spill Date:	1999-09-24
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401

SPILL NUMBER 9907632 (Continued) **S104620493**

Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	1999-09-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-09-24
Spill Record Last Update:	2004-01-09
Spiller Name:	JEFF REDDICK
Spiller Company:	Not reported
Spiller Address:	1994 ATLANTIC AVE
Spiller County:	001
Spiller Contact:	JEFF REDDICK
Spiller Phone:	(516) 869-6100
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	253222
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY NO PBS. 01/09/04 Transferred from Tibbe to K Foley. 1/9/04 Spoke to Victoria Ryback at Whitestone Assoc. (908) 668-7777. Checking on status of site. Site being sold and want an NFA. 1/9/04 Reviewed UST closure report. No VOCs/SVOCs above TAGM or GWQS. Sent NFA to: KFC US Properties Inc. Julie Reese, Env. Programs Mgr. 17901 Von Karmen St., MD 707 Irvine, CA 92614"
Remarks:	"SITE UNDER CONSTUCTION - SITE WAS AN OLD GAS STATION - CONTAMINATED SOIL FOUND AROUND 275 GAL WASTE OIL TANK - THERE ARE 5 OTHER TANKS ON THE SITE "

All Materials:

Site ID:	314056
Operable Unit ID:	1081925
Operable Unit:	01
Material ID:	563471
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

351
NNW
1/4-1/2
0.258 mi.
1362 ft.

444 BAINBRIDGE ST
444 BAINBRIDGE ST
BROOKLYN, NY

NY LTANKS **S106703572**
N/A

Relative:
Lower

Actual:
42 ft.

LTANKS:

Name:	444 BAINBRIDGE ST
Address:	444 BAINBRIDGE ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9106421 / 1991-09-07
Facility ID:	9106421
Site ID:	265729
Spill Date:	1991-09-14
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1991-09-07
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1991-09-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-09-25
Spill Record Last Update:	2004-03-30
Spiller Name:	Not reported
Spiller Company:	APRA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	216520
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	265729
Operable Unit ID:	960717
Operable Unit:	01
Material ID:	422127
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AV352 **1997 PACIFIC STREET** **NY LTANKS** **S102672263**
WSW **1997 PACIFIC STREET** **NY LEAD** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.275 mi.
1453 ft. **Site 9 of 9 in cluster AV**

Relative:
Higher

Actual:
82 ft.

LTANKS:

Name:	1997 PACIFIC STREET
Address:	1997 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9309613 / 1993-11-09
Facility ID:	9309613
Site ID:	214838
Spill Date:	1993-11-09
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	1993-11-09
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1993-11-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-11-10
Spill Record Last Update:	2003-02-06
Spiller Name:	Not reported
Spiller Company:	PETRO
Spiller Address:	3616 19TH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	177982
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"SEND SERVICEMAN - SPEEDY DRY WILL BE USED. THEY THINK SOME ONE ELSE DELIVERED FIRST. ANOTHER OIL CO."

All Materials:

Site ID:	214838
Operable Unit ID:	991157
Operable Unit:	01
Material ID:	392269
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

1997 PACIFIC STREET (Continued) **S102672263**

NYC LEAD:

Name:	Not reported
Address:	1997 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	14706147
Building ID:	349910
Registration ID:	344079
Apartment:	2
Story:	Not reported
Class:	Most Serious
Inspection Date:	10/07/2021
Approved Date:	11/29/2021
Original Certify By Date:	12/09/2021
Original Correct By Date:	12/04/2021
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	618
NOV ID:	7561809
NOV Description:	SECTION 27-2056.7 ADM CODE: CORRECT FAILURE TO PROVIDE TO THE DEPARTMENT WITHIN 45 DAYS OF DEMAND ALL RECORDS REQUIRED TO BE MAINTAINED BY OWNER PURSUANT TO LOCAL LAW 1 OF 2004 RELATED TO LEAD-BASED PAINT NOTICES, INSPECTIONS AND REMEDIATION/ABATEMENT ACTIVITIES.
NOV Issued Date:	11/30/2021
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	11/30/2021

---

353 **1875 ATLANTIC AVENUE** **NY VCP** **S118943286**
WSW **1875 ATLANTIC AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.278 mi.
1468 ft.

Relative:
Lower

Actual:
71 ft.

VCP NYC:

Project ID:	14TMP0393K,14EH-N393K,13CVCP149K
Name:	1875 ATLANTIC AVENUE
Address:	1875 ATLANTIC AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3017130007
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.677008
Longitude:	-73.922967
Postcode:	3
Community Board:	41
Council District:	299
Census Tract:	3421590
BIN:	3017130007
NTA:	Crown Heights North

354
SSW
1/4-1/2
0.289 mi.
1524 ft.

BROOKLYN CHILDREN CENTER
1819 BERGEN STREET
BROOKLYN, NY

NY LTANKS

1010436879
N/A

Relative:
Higher

Actual:
111 ft.

LTANKS:

Name:	BROOKLYN CHILDREN
Address:	1819 BERGEN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0106070 / 2003-07-21
Facility ID:	0106070
Site ID:	315011
Spill Date:	2001-09-07
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-09-07
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-09-07
Spill Record Last Update:	2003-07-21
Spiller Name:	WILLIAM LEE
Spiller Company:	BROOKLYN CHILDREN
Spiller Address:	1819 BERGEN ST
Spiller County:	001
Spiller Contact:	WILLIAM LEE
Spiller Phone:	(718) 221-4500
Spiller Extention:	216
DEC Region:	2
DER Facility ID:	272021
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 6/27/02 TJD Overfill of generator day tank caused by high level alarm failure caused the release of approximately 500 gallons #2 Fuel Oil. Tyree Brothers mobilized same day for initial cleanup and removed an undefined volume of contaminated soils. A floor drain was impacted by the petroleum which discharged to two dry wells. Tyree removed the oil impacted gravel from base of drywell. In April 2002, Shaw E&I (formerly IT Corp.) retained Zebra environmental to perform geoprobe sampling at site to further delinate residual contamination in sub-surface. Four soil borings were collected and samples sent to laboratory for analysis. Analytical results indicate minor residual contamination still exists, but will not be removed due to the presence of utilities and other facility structures in the area."
Remarks:	"could be more than 50 gals not sure at this time there is also some product contained"

All Materials:

Site ID:	315011
Operable Unit ID:	844474

BROOKLYN CHILDREN CENTER (Continued) **1010436879**

Operable Unit:	01
Material ID:	560299
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	BROOKLYN CHILDREN CENTER
Address:	1819 BERGEN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0411485 / 2005-12-07
Facility ID:	0411485
Site ID:	336696
Spill Date:	2005-01-25
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SXSCHARF
Referred To:	Not reported
Reported to Dept:	2005-01-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-25
Spill Record Last Update:	2006-05-19
Spiller Name:	DEBORAH YOUNG
Spiller Company:	BROOKLYN CHILDREN CENTER
Spiller Address:	1819 BURGEN STREET
Spiller County:	001
Spiller Contact:	DEBORAH YOUNG
Spiller Phone:	(718) 221-4500
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	272021
DEC Memo:	"DeMeo- initially responded to the site August 18, 2005: Spoke with Deborah Young. Spill was closed out and will send me the paperwork. Steven Scharf 12/05-Received paper work from ProTest Inc that tanks has tested ok for tightness. Close spill. S.Scharf."
Remarks:	"TANK IS UNDERGROUND AND SINCE FRIDAY THERE IS A 1000 GALLON DIFFERENCE:"

All Materials:

Site ID:	336696
Operable Unit ID:	1098705
Operable Unit:	01

BROOKLYN CHILDREN CENTER (Continued) **1010436879**

Material ID:	578881
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

---

355 417 RALPH AVENUE **NY LTANKS S100879350**
SW 417 RALPH AVENUE **N/A**
1/4-1/2 BROOKLYN, NY
0.314 mi.
1657 ft.

Relative: Higher

Actual: 97 ft.

LTANKS:

Name:	417 RALPH AVENUE
Address:	417 RALPH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9314183 / 2003-02-12
Facility ID:	9314183
Site ID:	231437
Spill Date:	1994-03-04
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1994-03-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-07
Spill Record Last Update:	2003-02-12
Spiller Name:	Not reported
Spiller Company:	UNK/NYC DEPT OF HOUSING P
Spiller Address:	TOM HALICK
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	190743
DEC Memo:	""
Remarks:	"WILL SET TANK ON END - NOT REALLY WORKING IN THAT AREA. FULL BLACK SITE IN BROOKLYN BLDG OWNED BY CITY & DEMOLITION OF BLDG STARTED BROUGHT DOWN TO GROUND LEVEL. TODAY BACK FOUND 275 GAL TANK TYREE FI"

417 RALPH AVENUE (Continued) **S100879350**

All Materials:

Site ID:	231437
Operable Unit ID:	992504
Operable Unit:	01
Material ID:	389521
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

356
North
1/4-1/2
0.332 mi.
1754 ft.

615 DECATUR ST **NY LTANKS** **S104782129**
615 DECATUR ST **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
40 ft.

LTANKS:

Name:	615 DECATUR ST
Address:	615 DECATUR ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0006043 / 2005-11-22
Facility ID:	0006043
Site ID:	180048
Spill Date:	2000-08-21
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JRSTRANG
Referred To:	Not reported
Reported to Dept:	2000-08-21
CID:	233
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-21
Spill Record Last Update:	2005-11-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	615 DECATUR ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	151094

615 DECATUR ST (Continued) **S104782129**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE 11/22/05 - Close, less than 25 gallons. Spilled confined to basement. JS"
Remarks: "tank in basement failed spill confined in basement fd on scene leak in being stopped by fd the homeowner will make contact for a clean up crew"

All Materials:
Site ID: 180048
Operable Unit ID: 828866
Operable Unit: 01
Material ID: 547174
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

357
WSW
1/4-1/2
0.336 mi.
1776 ft.

COMMERCIAL LOT **NY LTANKS** **S106471543**
1855 ATLANTIC AVE **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
68 ft.

LTANKS:
Name: COMMERCIAL LOT
Address: 1855 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0401074 / 2004-05-24
Facility ID: 0401074
Site ID: 328893
Spill Date: 2004-04-30
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: WXSUN
Referred To: Not reported
Reported to Dept: 2004-04-30
CID: 406
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-04-30
Spill Record Last Update: 2004-05-24
Spiller Name: ELLIOT POOL
Spiller Company: A1 SCAFFOLDING INC.
Spiller Address: 580 5TH AVE.

COMMERCIAL LOT (Continued) **S106471543**

Spiller County:	001
Spiller Contact:	A1 SCAFFOLDING INC.
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	264688
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 05/11/04 Mark Robbins, HydroTech called regarding status of site. Transferred from Rommel to Sun. Rommel 05/24/04-File Update by Sun: -Tank Closure Report prepared by Hydro Tech Enviromental, Corp.(Rachel Ataman, Project Manager, Tel. 631-462-5866), dated April, 5, 2004): Eight 1,000-gallon USTs, one 275 gallon and three 55-gallon drums were removed from the site. A total of 1,164 gallon of liquid and 266.54 tons of petroleum-contaminated soil were dispoed of. A total of six soil end point samples were obtained from the final excavation, including one each from four sidewalls and two from the bottom of the excavation. Analytical results showed that trace levels of total VOCs were detected in the end points EP-2 and EP-4 to EP-6. The total VOC concentrations ranged from 1.8 ug/kg in EP-6 to 3.93 ug/kg in EP-4. The results of the end point soil samples from the tank excavation indicate that no individual VOCs or SVOCs are present in the sidewalls or bottom of the tank excavation at concentrations exceeding applicable regulatory standards (TAGM #4046). Based upon these results, since no evidence of an adverse impact from the USTs is identified in the soil at the site, this spill is closed. "
Remarks:	"Caller was doing a tank removal of nine different tanks and found contaminated soil. Hydro Tech will be doing the removal of contam. soil. Area was one big tank pit. No water affected just land."

All Materials:

Site ID:	328893
Operable Unit ID:	885237
Operable Unit:	01
Material ID:	492303
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

---

358 **598 BAINBRIDGE ST** **NY LTANKS** **S102673191**
NE **598 BAINBRIDGE ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.347 mi.
1833 ft.

Relative: LTANKS:
Lower

Actual: Name:	598 BAINBRIDGE ST
58 ft. Address:	598 BAINBRIDGE ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9512828 / 1996-01-16
Facility ID:	9512828

598 BAINBRIDGE ST (Continued) **S102673191**

Site ID:	150243
Spill Date:	1996-01-15
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-01-15
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-01-15
Spill Record Last Update:	1998-01-29
Spiller Name:	Not reported
Spiller Company:	PETRO COMMANDER
Spiller Address:	36-16 19 TH AV
Spiller County:	001
Spiller Contact:	MCLEARY RES
Spiller Phone:	(718) 452-1206
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127766
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE BASEMENT WITH DRAIN BOOMED AND CLEANED TANK. CLEANED BY RP."
Remarks:	"driver overfilled tank there is a drain in the basement product may have leaked into it - licensed contractor on way to clean up"

All Materials:

Site ID:	150243
Operable Unit ID:	1027153
Operable Unit:	01
Material ID:	356569
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

359
NNW
1/4-1/2
0.348 mi.
1840 ft.

BACKYARD OF HOUSE
632 MACDONOWGH STREET
BROOKLYN, NY

NY LTANKS **S108059471**
N/A

Relative:
Lower

Actual:
40 ft.

LTANKS:

Name:	BACKYARD OF HOUSE
Address:	632 MACDONOWGH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0604106 / 2006-07-13
Facility ID:	0604106
Site ID:	367002
Spill Date:	2006-07-13
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-07-13
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-07-13
Spill Record Last Update:	2006-07-13
Spiller Name:	LORI JONES
Spiller Company:	Not reported
Spiller Address:	632 MACDONOWGH STREET
Spiller County:	001
Spiller Contact:	LORI JONES
Spiller Phone:	(718) 569-2838
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	317023
DEC Memo:	"Sangesland spoke to Mrs. Jones (homeowner) she said she had a 5 gal fuel can for an old boat standing in her back yard. She wanted it removed. Sangesland told her if the can was empty she could put it out with the trash. If the can had fuel in it, it would need to be disposed of properly. Sangesland gave Mrs. Jones the contact info for Radiac Research (718-963-2233)in Brooklyn. They will take this sort of material for a charge. Sangeland called Stanley Baldwin at City DEP Haz Waste. He said the city DOES NOT pick up this sort of material from homeowners."
Remarks:	"oil in the homeowners back yard"

All Materials:

Site ID:	367002
Operable Unit ID:	1124929
Operable Unit:	01
Material ID:	2114436
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

BACKYARD OF HOUSE (Continued) **S108059471**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

360 South 1/4-1/2 0.382 mi. 2019 ft.

1819 PROSPECT PLACE
1819 PROSPECT PL
BROOKLYN, NY

NY LTANKS **S102671499 N/A**

Relative: Higher

Actual: 87 ft.

LTANKS:

Name:	1819 PROSPECT PLACE
Address:	1819 PROSPECT PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8910858 / 1995-06-20
Facility ID:	8910858
Site ID:	307716
Spill Date:	1990-02-14
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	1995-06-20
SWIS:	2401
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	1990-02-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-02-22
Spill Record Last Update:	1995-06-20
Spiller Name:	Not reported
Spiller Company:	SAME AS CALLER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	248515
DEC Memo:	""
Remarks:	"DRIVER DELIVERED TO WRONG ADRESS-BARENKLAU TO DO CLEAN UP"

All Materials:

Site ID:	307716
Operable Unit ID:	936385
Operable Unit:	01
Material ID:	440411
Material Code:	0001A

1819 PROSPECT PLACE (Continued) **S102671499**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AZ361 **ENGINE CO. 233/LADD. CO. 176 FDNY -DDC** **NY LTANKS** **S105055038**
NE **25 ROCKAWAY AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.387 mi.
2043 ft. **Site 1 of 2 in cluster AZ**

Relative:
Lower

Actual:
68 ft.

LTANKS:

Name:	ENGINE CO. 233/LADD. CO. 176 FDNY -DDC
Address:	25 ROCKAWAY AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9709795 / 1999-04-01
Facility ID:	9709795
Site ID:	89083
Spill Date:	1997-11-15
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1997-11-22
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-11-22
Spill Record Last Update:	2004-12-20
Spiller Name:	TONY MARINO
Spiller Company:	NYC
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	TONY MARINO
Spiller Phone:	(718) 391-1062
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	252898
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD See the ISRP."
Remarks:	"CALLER JUST RECEIVED ANALYTICAL RESULTS FROM A SITE INDICATING CONTAMINATION POSSIBLY CAUSED FROM A UST. PROBABLE MATERIAL SPILLED IS DIESEL (NO GAS USTs ON THIS SITE}."

All Materials:

ENGINE CO. 233/LADD. CO. 176 FDNY -DDC (Continued) **S105055038**

Site ID:	89083
Operable Unit ID:	1056065
Operable Unit:	01
Material ID:	328127
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	ENGINE CO. 233/LADD. CO. 176 FDNY -DDC
Address:	25 ROCKAWAY AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0102559 / 2009-10-07
Facility ID:	0102559
Site ID:	313650
Spill Date:	2001-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AXDORONO
Referred To:	NFA
Reported to Dept:	2001-06-07
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-07
Spill Record Last Update:	2009-10-07
Spiller Name:	Not reported
Spiller Company:	CITY OF NEW YORK
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TONY C
Spiller Phone:	(516) 938-5476
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	252898
DEC Memo:	"6-24-2005 NFA for motor oil fuel spills was issued in April 1999. This spill occurred later and is handled by Imbdad Islam. AZ 05/30/2007: This spill case transferred to A. Doronova. - AD No file for this case, just a spill report. 06/01/2007: Sent an email to A. Samani (cc: J. Kolleeny; A. Ledins; F. Ashkan; T. Ahmad; B. Morrissey; J. Staten and H. Roberts)asking for the site status update information. Received a response email from A. Samani on the same day. She promised to get back to us with updated data. AD 04/17/2008:

ENGINE CO. 233/LADD. CO. 176 FDNY -DDC (Continued) **S105055038**

Received an email from DDC saying: Dear Sir or Madam: I am working on some spills for the NYCDDC. I was going through some spill numbers in the DEC database and saw that you were the lead DEC person for some of the ones on which I am currently working. Can you send to me the NYSDEC Spill Report Form for the following spills? Spill # - Site 0109758 - 69th Precinct 0108983 - Brooklyn West 12 0012041 - 63rd Precinct 0102559 - EC 233 / Ladder 176 I would appreciate it if you can email to me pdf files (or some other format would be fine) of the forms. Please let me know if you have any questions. Thanks again for your time and consideration. Renee Wong Renee L. Wong Project Geologist Certified Professional Geologist Sent the requested spill reports the same day. AD 06/12/2008: Send an email to Ms. Wong of DDC: Hi Renee, Thank you for keeping me informed. I am now in a process of reviewing the spill closure reports Roux had submitted to us. I would like to ask you to submit also PDF version of Tank Closure Report for NYPD - 69th Precinct, spill No. 0109758 and a hard copy and PDF version of Tank Closure report for Engine Company 233, spill No. 0102559. Regarding the 63rd Precinct site: I need Tank Closure Report for closed-in-place UST (hard copy and PDF). As for the workplan, I think the requirements will be standard. Borings at each side of the tank; PID screening; soil sampling (including sampling right above the water table,(if applicable); groundwater grab sampling (if applicable). If you would like me to take a look at the investigation work plan for this site, before you will submit it officially, you can send its finalized copy on my email. Sincerely, Ainura Doronova Environmental Engineer Division of Environmental Remediation NYSDEC Region 2 06/02/2009: Received an e-mail from Renee Wong: Hello Ainura, How are things going? I was reviewing a couple of spill closure requests that I had sent to you sometime last year and was just following up on their status. Please let me know if these spills are ready for closure or, if not, what still needs to be done for the sites before the spills may be closed. The following are spills for which I still need status information: - 0109758: 69th Precinct - 0102559: Engine Company 233 Thanks, Renee 06/09/2009: Sent a reply: Hi Renee, Here is the status information for the following spills: - 0109758: 69th Precinct - NFA letter was issued for spill No. 0109758. - 0102559: Engine Company 233 - On June 12, 2008 DEC requested submission of the additional documentation (PDF and hard copies of UST closure report) for spill No. 0102559. Approval of the Spill Closure Request has been postponed pending submission of the additional data. Regards, Ainura Doronova 06/16/2009: Received an e-mail from R. Wong: Thanks, Ainura. We will try to get the necessary data for the EC 233 spill and submit it to you for your review. Regards, Renee Renee L. Wong Project Geologist Certified Professional Geologist Email: rwong@rouxinc.com Mobile Phone: 631-774-7346 AD 09/30/2009: Received an-email from R. Wong saying: Hi Ainura, I got the additional documentation (UST Closure Report, see email below) needed to support the spill closure request for Spill 0102559. I have attached the PDFs here and am putting the hardcopy in the mail to you today. Please let me know if there is anything else that you need in order to close the spill, or if you have any questions. Thanks! Renee Renee L. Wong Project Geologist Certified Professional Geologist Email: rwong@rouxinc.com <mailto:rwong@rouxinc.com> Mobile Phone: 631-774-7346 Roux Associates, Inc. 209 Shafter Street Islandia, NY 11749 Tel: 631-232-2600 Fax: 631-232-9898 DL to eDocs. Will review. AD 10/06/2009: Reviewed the report. It states that the spill was issued following a tank test failure of a 3,500-gallon #2 fuel oil

ENGINE CO. 233/LADD. CO. 176 FDNY -DDC (Continued) **S105055038**

UST. This tank was closed-in-place in April 30, 2002 by Empire Environmental Services. Six soil samples were collected from around the tank area and analyzed for VOCs and SVOCs. Four samples were taken along the sides of the tank walls, and two samples were taken directly below the bottom of the tank. The concentrations of VOCs for all six samples were below RSCO levels. Side soil samples indicated some elevated levels of SVOCs, but no elevated levels of Naphtalene were detected in any of the six samples. Two bottom soil samples showed no exeedances in the SVOCs levels. Groundwater at this site is approximately 58 feet bgs. Roux concludes that there is little chance of the SVOC compounds migrating down to groundwater in sufficient concentrations to be a cause for concern and requests closure of this spill case. AD 10/07/2009: Discussed this site with J. Kolleeny of DEC. Based on the data provided, the decision was - to close the case. Issued and sent NFA letter. DL to eDocs. AD "

Remarks: "WILL EITHER DIG UP AND REPAIR OR REAPLACE TANK."

All TTF:

Facility ID:	0102559
Spill Number:	0102559
Spill Tank Test:	1526361
Site ID:	313650
Tank Number:	1
Tank Size:	3500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	313650
Operable Unit ID:	841261
Operable Unit:	01
Material ID:	534675
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	DRUM RUN
Address:	25 ROCKAWAY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1002698 / 2010-06-10

ENGINE CO. 233/LADD. CO. 176 FDNY -DDC (Continued) **S105055038**

Facility ID:	1002698
Facility Type:	ER
DER Facility ID:	390766
Site ID:	435873
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-06-09
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2010-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-06-09
Spill Record Last Update:	2010-06-10
Spiller Name:	NYC HAZ MAT 1
Spiller Company:	UNKNOWN
Spiller Address:	25 ROCKAWAY AVE
Spiller Company:	999
Contact Name:	NYC HAZ MAT 1
DEC Memo:	"will try to include in today's drum run (6/9/2010) 6/10/10-HRAHMED-Felney and Nicol pumped out two drums during DRUM RUN on 6/9/10. DEP and Sanitation were notified. This case is closed. "
Remarks:	"2 drums were left on sidewalk. DEP also advised."

All Materials:

Site ID:	435873
Operable Unit ID:	1186599
Operable Unit:	01
Material ID:	2181402
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	110.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

362
SE
1/4-1/2
0.401 mi.
2116 ft.

1634 SAINT MARKS PLACE
1634 SAINT MARKS PLACE
BROOKLYN, NY

NY LTANKS **S105135290**
NY Spills **N/A**

Relative:
Lower

Actual:
76 ft.

LTANKS:

Name:	REVEREND BROWN HOUSES -NYCHA
Address:	1634 SAINT MARKS PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0104652 / 2008-09-23
Facility ID:	0104652
Site ID:	144327
Spill Date:	2001-07-31
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	CLOSED PER NYCHA INFO
Reported to Dept:	2001-07-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-31
Spill Record Last Update:	2008-09-23
Spiller Name:	FUEL OIL REM. COORD.
Spiller Company:	NYCHA
Spiller Address:	23-02 49TH AVENUE
Spiller County:	001
Spiller Contact:	MARIO MANDELONE
Spiller Phone:	(718) 649-7017
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	219367
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY This spill was reassigned from DEC Sigona to Kolleeny NYCHA Monitor. 11/07/05: This spill transferred from J.Kolleeny to S.Kraszewski. 12/27/05: Only tank failure recorded, no other related spills can be found. Passes subsequent tank test in De 2001. Needs a site investigation. - SK 01/27/06: This spill transferred from S.Kraszewaski to Q.Abidi. 03/31/06: This spill transferred from Q. Abidi to Koon Tang. 09/23/08: Documents related to tank tightness testing submitted to the Department. Results indicate that manway gasket nuts and bolts were cause of testing failure, they were replaced and the tank passed testing. Spill closed based on this information. J.kann "
Remarks:	"Isolate and retest"

All TTF:

Facility ID:	0104652
Spill Number:	0104652
Spill Tank Test:	1526494
Site ID:	144327

1634 SAINT MARKS PLACE (Continued) **S105135290**

Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	144327
Operable Unit ID:	841411
Operable Unit:	01
Material ID:	533134
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	1634 SAINT MARKS PLACE
Address:	1634 SAINT MARKS PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0207612 / 2002-10-23
Facility ID:	0207612
Facility Type:	ER
DER Facility ID:	219367
Site ID:	269348
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2002-10-23
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2002-10-23
CID:	204
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

1634 SAINT MARKS PLACE (Continued) **S105135290**

Remediation Phase:	0
Date Entered In Computer:	2002-10-23
Spill Record Last Update:	2002-10-24
Spiller Name:	MARIO MANDELONE
Spiller Company:	1634 SAINT MARKS PLACE
Spiller Address:	1634 SAINT MARKS PLACE
Spiller Company:	001
Contact Name:	MARIO MANDELONE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL DO 3:45 10/23 Spoke to Mario at NYCHA. Spill has been cleaned. There are two drums on site, one with dryzol and one with wipes. The leaking pump has been taken off-line and isolated. They are not currently using oil. A work order has been issued for the repair of the pump. JMR/do boiler below grade line from pump concrete. No floor Drains, no sump pits. "
Remarks:	"BROKEN FUEL LINE "

All Materials:

Site ID:	269348
Operable Unit ID:	859210
Operable Unit:	01
Material ID:	518188
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

363 **PROSPECT PLAZA -NYCHA** **NY LTANKS** **U000418230**
South **1776 PROSPECT PLACE** **NY AST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.402 mi.
2122 ft.

Relative:
Higher

Actual:
86 ft.

LTANKS:

Name:	PROSPECT PLAZA -NYCHA
Address:	1776 PROSPECT PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9107711 / 2006-01-06
Facility ID:	9107711
Site ID:	248079
Spill Date:	1991-10-18
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1991-10-18
CID:	Not reported

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-23
Spill Record Last Update:	2006-01-06
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	128440
DEC Memo:	"01/06/06: This spill transferred from J.Kolleeny to S.Kraszewski. This spill closed to consolidate with open spill #9315474. - SK"
Remarks:	"WILL E, I & R"

All TTF:

Facility ID:	9107711
Spill Number:	9107711
Spill Tank Test:	1539190
Site ID:	248079
Tank Number:	001
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	248079
Operable Unit ID:	958169
Operable Unit:	01
Material ID:	419902
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Name:	PROSPECT PLAZA -NYCHA
Address:	1776 PROSPECT PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9315474 / 2006-12-08
Facility ID:	9315474
Site ID:	151127
Spill Date:	1993-10-27
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	NFA, 12/8/2006
Reported to Dept:	1994-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-04-05
Spill Record Last Update:	2008-08-14
Spiller Name:	Not reported
Spiller Company:	NYCHA - JOE MONTELLA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	128440
DEC Memo:	"01/06/06: This spill transferred from J.Kolleeny to S.Kraszewski. Both tanks are currently out of service and it is unknown if they still hold fuel oil. Each tank has one failure. A subsurface investigation was performed in 1995, which found elevated levels of contamination in isolated areas around the tank and piping. VOC and SVOC compounds were detected. Only soil borings were advanced, GW was not encountered to a depth of 35 feet. No specific documents subsequent to the ISRP pertain to remedial activities at this site. DEC required that NYCHA propose a schedule of examination and excavation of the contaminated soil since DEC was not aware of plans to legally close the tanks or have them removed. No documents on file that relate to this requirement. - SK 02/14/06: Email from Cris Sawyer @ NYCHA informed me of soil borings taking place at Prospect Houses, 1776 Prospect Place to assess the subsurface contamination. They will begin work February 15, 2006. Frank Inoa from NYCHA stopped by to drop off paperwork for the above-mentioned work. He said that work will begin late this week or next week, Feb. 21-24. Reviewed Description of Work - Site Investigation/Delineation of Contaminated Soil submitted by Gannett Fleming on Feb. 14, 2006. The Description of Work doucments contain an overview of the work to be performed on-site with a site plan showing boring locations. According to the diagram, at least a half-dozen borings will be taken from around the tanks, along piping and next to the fill port. Aquifer Drilling and

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Testing will perform the drilling work. Results and conclusions from the subsurface investigation will be summarized in a report and will be submitted for review. The report must include status of the remaining tanks and what their future status will be. I talked with Ralph Trocchio after reviewing the plans. The purpose of this subsurface investigation is to determine the extent of soil contamination to figure out the volume of soil that must be removed. NYCHA will try to excavate all contaminated soil encountered when they removed the tanks, which will occur after this subsurface investigation has been finished. - SK 02/17/06: Visited site to observe subsurface soil delineation. Met Chris Sawyer from NYCHA Spills Remediation, Jessica from Gannett Fleming, Ugene Bikhler a NYCHA engineer and Jim McBroom the NYCHA Project Administrator. ADT was performing the drilling. I inspected the site with Chris: a total of six soil boring would be drilled with a PID reading every 5 feet. Several of the borings would occur directly in the vacinity of the tanks, were previous borings taken in 1995 showed soil contamination. Other borings will occur near fill lines and piping. The delineation will provide a perimeter of the contaminated area so that NYCHA can accurately draft a work order. A boring next to the fill port was abandoned due to the lack of a sidewalk permit. However, Chris said that the fill port area will be excavated and any contaminated soil will be removed. I instructed that a boring be extended to 40 fbg or until GW is encountered, which ever comes first. - SK 02/21/06: Chris Sawyer called asking for advice with the soil borings: no GW at 50 feet. I asked Alex about it and he advised that when the 5 foot intervals find clean or almost-clean soil to take continuous split-spoon samples for an addtional 5 to 10 feet with PID readings. They have already completed two borings with heavy contamination at the bottom of the tanks and moderte contamination to about 35 feet. - SK 04/06/06: Called Chris Sawyer to get an update. He said they are going back and taking more borings for additional delineation. I said to give me a report that includes the first and second round of borings instead on individual reports. - SK 07/07/06: Meeting with Cris Sawyer and Luis Ponce from NYCHA, S.Kraszewski and J.Kolleeny attending. NYCHA discussed remedial excavation plans and tank removal from this site. This site is going to be sold and developed, but the site must be clean or the spill closed by DEC. NYCHA submitted an investigation summary of soil borings advanced to roughly 40 fbg. Adsorbed SVOCs were discovered as deep as 27 fbg, so NYCHA plans to excavate an entire area to 30 fbg, provided that the engineers approve. Also, two additional excavations in areas extending to 20 fbg and 5 fbg. J.Kolleeny mentioned that the depth to GW must be investigated somehow in order to compare the depth of contaminated soil in order to make a better assessment of the potential impact to groundwater. The report is missing soil boring data for borings 1 - 6 performed by Gannett Fleming. Before NYCHA can being excavation, they must check to see if they can excavate that close to the structure. NYCHA was told that closure of the site would depend on endpoint samples taken after the excavation process in complete. Staff would need to visit the open pit to assess the conditions. NYCHA will keep staff updated. - SK 07/31/06: S.Kraszewski and K.Tang met with NYCHA staff to discuss excavation measures to remove #4 source contamination. K.Tang and I looked over the investigation report boring data and lab data. Koon suggested that NYCHA limit their focus to what actually caused the TTF, the tank or the lines. Once this has been established, NYCHA must submit a remedial plan to address it.

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Also, one boring to GW must be performed in the defined area of contamination and a sampled collected to analysis. - SK 08/08/06: Chris Sawyer called (917-968-5899) to inform me that they will be testing the tanks. NYCHA is attempting to further isolate the source(s) of contamination on-site. The vent line that runs from the the east end of tank #2 has a hole, they plan to excavate more and keep testing the lines. They will continue to test the tanks today and tomorrow followed by the supply, return and fill lines. Chris will keep me updated. Chris Sawyer called me back and informed me both tanks passed their tightness tests. I said that's great, keep me updated as the other components of the system are tested and inspected. - SK 08/09/06: Crhis Sawyer called to inform me they have completed the tank and line testing. He believes that there are two areas of concern: the fill line near SB-17 and SB-25 and the vent/return/suction line vacinity between the tanks and the building. He asked me if they have to uncover and inspect the lines, which would cause problems for the drill since it can barely negotiate such a confimed space. I consulted with KST and we decided that we want to establish GW conditions beneath the two areas of concern. I told Chris to drill to GW for both locations while collecting split spoon soil samples. If they encounter contaminated soil above the GW they should develop a well in that location and prepare to install additional wells to delineate the contamination. - SK 09/22/06: Mohan Sharma from UTB (msharma@utb1.com) sent an email notifying me that the tanks will be removed on Sept. 27 - 28. - SK 09/27/06: Called Cris Sawyer (718-707-5722) to ask about when they would be taking end-point samples. He said they expect to collected soil samples next week, since they plan on excavating to about 25 fbg, which requires shoring. Shoring may delay work because of the rocky conditions. He will keep me updated. - SK 10/02/06: NYCHA emailed PDF of the Site-Specific Investigative Summary Report: uploaded into eDocs. - SK 10/05/06: Reviewed the Site-Specific Investigation Summary prepared by Gannett Fleming and submitted on September 28, 2006. Over 20 soil borings were advanced around the tanks and piping in an attempt to delineate the horizontal and zeritcal extent of the contamination. Soil contamination ranged in depth from 5 fbg to almost 45 fbg. The most affected area lies along the supply and return lines which run from the tanks to the building. According to the report, elevated SVOCs were detected in four different areas, which vary in contmaination levels. NO VOCs were detected in any soil boring samples. All borings were screened and had samples collected and analyzed. GF recommends that NYCHA remove as much soil to the maximum extent possible without comprimising the structural integrity of the building. NYCHA has already begun excavation work as part of the tank and piping removal/replacement work for Schedule C. Staff sent letter approving the removal of contmainated soil and expects the tank closure report to summarize it. - SK 11/13/06 - JK - Site reassigned from S. Kraszewski to J.Kann. 11/13/06: J. Kann - Arrived on site at 1:20pm. Visited site to observe excavation of the fill port area. Area was shored and the excavation was completed to approximately 20 feet. Endpoint samples were to be collected and included in the tank closure report. Cris Sawywer and Ralph Trocchio of NYCHA were on site. 12/8/06: JK- Spill closed on 12/8/06. NFA."

Remarks: "LEAK RATE OF 0.7GPH."

All TTF:
Facility ID: 9315474
Spill Number: 9315474

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Spill Tank Test:	1542580
Site ID:	151127
Tank Number:	002
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	151127
Operable Unit ID:	993574
Operable Unit:	01
Material ID:	387225
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	NYC HOUSING BUILDING
Address:	1776 PROSPECT PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0605275 / 2006-09-28
Facility ID:	0605275
Site ID:	368407
Spill Date:	2006-08-06
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2006-08-06
CID:	64
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-07
Spill Record Last Update:	2006-09-28

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Spiller Name:	FRANK INOA
Spiller Company:	Not reported
Spiller Address:	1776 PROSPECT PLACE
Spiller County:	001
Spiller Contact:	FRANK INOA
Spiller Phone:	(718) 707-5718
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	128440
DEC Memo:	"08/09/06 Rahman- I spoke with Frank Inoa,(718)707-5718, who indicated HA in house personnel doing the clean up. Report will be sent to DEC. 09/28/06 Rahman- UTB is doing the tank removal job. End point samples will be collected and report will be sent to DEC. Cross reference to spill#9315474."
Remarks:	"In the process of being cleaned up."

All Materials:

Site ID:	368407
Operable Unit ID:	1126285
Operable Unit:	01
Material ID:	2115812
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AST:

Name:	PROSPECT PLAZA
Address:	1776 PROSPECT PLACE
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-474193
Program Type:	PBS
UTM X:	591491.27416
UTM Y:	4502933.89612
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	20889
Affiliation Type:	Facility Operator
Company Name:	PROSPECT PLAZA
Contact Type:	Not reported
Contact Name:	FUEL OIL REMED COORD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Phone:	(212) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	20889
Affiliation Type:	Emergency Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	EMERGENCY SERVICE DEPT.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	718-707-5900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ajsigona
Date Last Modified:	2004-04-15

Site Id:	20889
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	FUEL OIL REMEDIATION COORDINATOR
Address1:	23-02 49TH AVENUE
Address2:	TECH SERVS DEPT - 5TH FLOOR
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Y.TKACH@NYCHA,NYC.GOV
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-02-03

Site Id:	20889
Affiliation Type:	Facility Owner
Company Name:	NYC HOUSING AUTHORITY
Contact Type:	FUEL OIL REMEDIATION COORDINATOR
Contact Name:	RALPH TROCCHIO
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-5725
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2007-05-07

PROSPECT PLAZA -NYCHA (Continued) **U000418230**

Tank Info:

Tank Number:	T1
Tank Id:	60278
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I03 - Overfill - Automatic Shut-Off
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1999
Capacity Gallons:	8000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/2003
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

BA364 **BREVOORT HOUSES** **NY LTANKS** **S103557948**
West **329 PATCHEN AVE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.402 mi.
2124 ft. **Site 1 of 2 in cluster BA**

Relative: LTANKS:
Lower

Actual: Name:	BREVOORT HOUSES -NYCHA
55 ft. Address:	329 PATCHEN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9808684 / 2007-11-19
Facility ID:	9808684
Site ID:	314864
Spill Date:	1998-10-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	jkkann
Referred To:	CONSOLIDATED WITH 9200971
Reported to Dept:	1998-10-13
CID:	351

BREVOORT HOUSES (Continued) **S103557948**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-13
Spill Record Last Update:	2007-11-19
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	SEBASTIAN LOREFICE
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	253848
DEC Memo:	"12/02/05: This spill transferred from J.Kolleeny to S.Kraszewski. 02/06/06: This spill transferred from S.Kraszewski to Q.Abidi. 04/04/06: This spill transferred from Q. Abidi to Koon Tang. 11/19/07: J.Kann - this spill consolidated with 9200971."
Remarks:	"TO ISOLATE AND RETEST"

All TTF:

Facility ID:	9808684
Spill Number:	9808684
Spill Tank Test:	1546380
Site ID:	314864
Tank Number:	2
Tank Size:	20000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	314864
Operable Unit ID:	1066093
Operable Unit:	01
Material ID:	316179
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BREVOORT HOUSES (Continued) **S103557948**

SPILLS:

Name:	BREVOORT
Address:	329 PATCHEN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9004479 / 1995-05-01
Facility ID:	9004479
Facility Type:	ER
DER Facility ID:	253848
Site ID:	154194
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1990-07-23
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-05-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-25
Spill Record Last Update:	2005-12-02
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL FOLLOWING FUEL LINE CHASE TO BASEMENT, SPILL CONTAINED WITH SPEEDY DRY, REPAIR & CLEAN PROPERLY."

All TTF:

Facility ID:	9004479
Spill Number:	9004479
Spill Tank Test:	1537340
Site ID:	154194
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BREVOORT HOUSES (Continued) **S103557948**

All Materials:

Site ID:	154194
Operable Unit ID:	942300
Operable Unit:	01
Material ID:	435571
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	BREVOORT -NYCHA
Address:	329 PATCHEN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9200971 / 2017-04-04
Facility ID:	9200971
Facility Type:	ER
DER Facility ID:	253848
Site ID:	296594
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1992-04-24
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1992-04-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-24
Spill Record Last Update:	2017-04-04
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"12/02/05: This spill transferred from J.Kolleeny to S.Kraszewski. 09/01/06: DEC Lead for this spill changed from unassigned to S. Kraszewski. - J. Kolleeny 11/19/07: J.Kann - closed spill 9808684 to consolidate with this spill. Site reassigned to J. Kann. 4/28/09: J.Kann - Draft work plan received on 2/25. Comments sent on 3/17. Final Work Plan received on 4/24 and approved on

BREVOORT HOUSES (Continued) **S103557948**

4/27. 4/26/16: J.Kann - ISRP received on 2/15/11. FOIA request made for the site. ISRP uploaded in
DecDocs and GovQA. File reviewed. Closure NFA requested in 2011 report. Summary of site is as
follows: 1992- USTs removed and a significant amount of impacted soils. Photos show excavation.
1995 - 7 borings advanced to determine what impacts remain after tank removal. Oil staining in two
borings, B-1 and B-3; no impacts in other borings. One groundwater well installed at B-3, no free
product or contamination detected. Groundwater at 42 feet bgs. Limited oil impacts on northeast and
northwest sides of the tank remained. This is consistent with photos from the tank excavation,
which was limited due to utilities and sidewalk. 1998/2002 - Current USTs tested and passed. They
are therefore not the source of the residual contamination. 2011 - Additional investigation
conducted (2 borings advanced). Soil samples collected in the vicinity of B-3 and a soil and
groundwater sample collected east of the tanks. A fingerprint of impacted soils collected concluded
impacts to be No. 6 fuel oil and therefore from the historic tanks. Report also indicates a
decrease in VOCs detected in soils. Groundwater at this new location was also not impacted. 6/2/16:
J.Kann - spoke with a Sharon Latz (828-319-7968) regarding the current status of the site. She is
doing a phase I for 216-218 Ralph Avenue. I informed her that we did not have product in historic
wells and that the source was removed 20 years ago. There may be residual soil contamination of No.
6 Fuel Oil. Her site is also to the northeast of the site, where contamination was delineated.
Additional borings may be necessary to the northwest of the tanks. Her concern was about vapors
related to this spill. I did tell her it was a number 6 oil spill from
over 20 years ago. 4/04/17:
J.kann - Based on 2011 ISR, source removal completed, no impact to groundwater and only residual
contamination detected in soils, spill closed."

Remarks: "20K TANKS; CONTAMINATED SOIL."

All TTF:

Facility ID:	9200971
Spill Number:	9200971
Spill Tank Test:	1539910
Site ID:	296594
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

BREVOORT HOUSES (Continued) **S103557948**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 296594
Operable Unit ID: 964945
Operable Unit: 01
Material ID: 415726
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

Name: BREVOORT HOUSES
Address: 329 PATCHEN AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9503788 / 1995-06-28
Facility ID: 9503788
Facility Type: ER
DER Facility ID: 253848
Site ID: 68868
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1995-06-27
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1995-06-27
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: 1995-06-28
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-06-28
Spill Record Last Update: 2005-12-02
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: ""
Remarks: "NYCHA FIELD SUPER DISCOVERED VAPORS IN BASEMENT OF FIVE BUILDINGS-SOURCE APPEARS TO BE HOUSE TRAP TO SEWER. NYCDEP ON-SCENE, WILL TRY TO TRACE SOURCE. BASEMENTS VENTILATED."

BREVOORT HOUSES (Continued) **S103557948**

All Materials:

Site ID:	68868
Operable Unit ID:	1015002
Operable Unit:	01
Material ID:	561370
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

BA365 **329 PATCHEN AVE/BKLYN** **NY LTANKS** **S102671252**
WNW **329 PATCHEN AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.412 mi.
2176 ft. **Site 2 of 2 in cluster BA**

Relative: **Lower**

Actual: **55 ft.**

LTANKS:

Name:	329 PATCHEN AVE/BKLYN
Address:	329 PATCHEN AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8710502 / 1988-03-16
Facility ID:	8710502
Site ID:	176361
Spill Date:	1988-03-15
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-03-16
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1988-03-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-22
Spill Record Last Update:	1988-03-29
Spiller Name:	Not reported
Spiller Company:	HOUSING COMPLEX
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	148229

329 PATCHEN AVE/BKLYN (Continued) **S102671252**

DEC Memo: ""
Remarks: "DEP RESPONDED AT (17:00), SEWERS WERE NOT EFFECTED, DEC WILL INVESTIGATE."

All Materials:
Site ID: 176361
Operable Unit ID: 916378
Operable Unit: 01
Material ID: 462275
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 200.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

366
WSW
1/4-1/2
0.413 mi.
2179 ft.

KINGSBOROUGH HOUSES -NYCHA **NY LTANKS** **S100146643**
1880 PACIFIC STREET **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
72 ft.

LTANKS:
Name: KINGSBOROUGH HOUSES -NYCHA
Address: 1880 PACIFIC STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9410866 / 2009-07-07
Facility ID: 9410866
Site ID: 290629
Spill Date: 1994-11-14
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: jkkann
Referred To: Not reported
Reported to Dept: 1994-11-15
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-11-15
Spill Record Last Update: 2009-07-07
Spiller Name: Not reported
Spiller Company: NYC HOSUING AUTHORITY
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported

KINGSBOROUGH HOUSES -NYCHA (Continued) **S100146643**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	235331
DEC Memo:	"12/29/05: This spill transferred from J.Kolleeny to S.Kraszewski. - SK 03/23/06: This spill transferred to K.Tang - SK 07/07/09- J.Kann - spill called in due to tank test failure. manway gasket and bolts were replaced and subsequent testing resulted in tank passing. information provided by NYCHA and spill closed. "
Remarks:	"ISOLATE AND RETEST."

All TTF:

Facility ID:	9410866
Spill Number:	9410866
Spill Tank Test:	1543348
Site ID:	290629
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	290629
Operable Unit ID:	1008733
Operable Unit:	01
Material ID:	561485
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	KINGSBORO HOUSES
Address:	1880 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9010149 / 1995-04-26
Facility ID:	9010149
Site ID:	276215
Spill Date:	1990-12-18
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-04-26
SWIS:	2401

KINGSBOROUGH HOUSES -NYCHA (Continued) **S100146643**

Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-20
Spill Record Last Update:	2005-12-29
Spiller Name:	MR CARTER
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	235331
DEC Memo:	""
Remarks:	"35K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, AIR POCKET, WILL EXCAVATE, ISOLATE & RETEST. SEE SPILL # 9410866"

All TTF:

Facility ID:	9010149
Spill Number:	9010149
Spill Tank Test:	1538057
Site ID:	276215
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	276215
Operable Unit ID:	950630
Operable Unit:	01
Material ID:	430315
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00

KINGSBOROUGH HOUSES -NYCHA (Continued) **S100146643**

Resource Affected: Groundwater
Oxygenate: Not reported

AZ367 **HENRY APARTMENTS SITE B - 8 ROCKAWAY AVENUE** **NY VCP** **S125317289**
NE **8 ROCKAWAY AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.415 mi.
2193 ft. **Site 2 of 2 in cluster AZ**

Relative: **Lower**
Actual: **67 ft.**

VCP NYC:

Project ID:	15TMP0587K,15CVCP120K,15CVCP120K
Name:	HENRY APARTMENTS SITE B - 8 ROCKAWAY AVENUE
Address:	8 ROCKAWAY AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0150700323014997E+79
OER Program:	VCP (Enrolled)
Phase:	Completed
Latitude:	40.683362
Longitude:	-73.911657
Postcode:	16
Community Board:	41
Council District:	373
Census Tract:	3414036
BIN:	3015077501
NTA:	Ocean Hill

BB368 **192 RALPH AVE OFF-SITE** **NY DEL SHWS** **S121933898**
NW **192 RALPH AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11233**
0.416 mi.
2199 ft. **Site 1 of 2 in cluster BB**

Relative: **Lower**
Actual: **47 ft.**

DEL SHWS:

Name:	192 RALPH AVE OFF-SITE
Address:	192 RALPH AVE
City,State,Zip:	BROOKLYN, NY 11233
Year:	Not reported
Site Code Id:	Not reported
Site Classification:	Not reported
Region:	2
Epa Id Number:	Not reported
Site Type - Dump:	No
Site Type - Structure:	No
Site Type - Lagoon:	No
Site Type - Landfill:	No
Site Type - Treat Pond:	No
Site Size (Acres):	Not reported
Site Size Comment:	Not reported
Period Assoc/HW Start:	Not reported
Period Assoc/HW End:	Not reported
Lat/Long:	Not reported
Lat/Long Decimal:	Not reported
Lat/Long (dms):	Not reported
Hazardous Waste Code:	224042A

192 RALPH AVE OFF-SITE (Continued) **S121933898**

Hazard Waste Disposed:	Not reported
Quantity:	Not reported
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	No
Soil Type:	Not reported
Sediment Data Available:	No
GW Std Contravention:	No
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	No
Federal Legal Action:	No
Enforce Status Code:	Not reported
Remedial Act Proposed:	No
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	Not reported
Depth To Groundwater:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Not reported
HW Disposal Period:	Not reported
Analytical Data Available:	Not reported
Applicable Std Exceeded:	Not reported
Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Not reported
Site Description:	Not reported
Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported

192 RALPH AVE OFF-SITE (Continued) **S121933898**

Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	People will not come into contact with contaminated soils on the site since they are located at depth and beneath a building foundation. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A soil vapor extraction system has been installed beneath the on-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building. Environmental sampling indicates that soil vapor intrusion is a concern for off-site buildings and actions have been recommended at two buildings. Additional investigation is on-going; however, many nearby property owners have declined the Agencies sampling offers.
Description:	Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a drycleaner and occupies 188 through 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear (192 Ralph Avenue). The building structure is 20' x 80' occupying an area of approximately 0.037 acres. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. With the confirmation of waste disposal on-site the property owner entered the Department's Voluntary Cleanup Program (VCP) as a Volunteer in 2004. The VCP site

192 RALPH AVE OFF-SITE (Continued) **S121933898**

is defined as the entire 80' x 20' on-site parcel. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area. A Record of Decision, declaring a remedy for OU2, was signed on October 18, 2013. Operable Unit 1 was the off-site portion. The off-site area investigated runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Going forward, the off-site portion will be identified as ID No. 224042A. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Record Added Date: 02/14/2018
Record Updated Date: 03/29/2019
Env Assessment: Not reported
HW Disposed/Quantity: Not reported
Assess/Env Prog: Not reported
Assess/Health Prob: Not reported
Site Description: Not reported

BB369 **192 RALPH AVENUE** **NY SHWS** **S109416407**
NW **192 RALPH AVE** **NY ENG CONTROLS** **N/A**
1/4-1/2 **BROOKLYN, NY 11233** **NY INST CONTROL**
0.416 mi. **NY VCP**
2199 ft. **Site 2 of 2 in cluster BB**

Relative: **Lower**
Actual: **47 ft.**

SHWS:
Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Program: HW
Site Code: 58281
Classification: Site is properly closed - requires continued management.
Region: 2
Acres: 0.009
HW Code: 224042
Record Add: 04/04/2003
Record Upd: 04/26/2023
Updated By: SMQUANDT
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for

192 RALPH AVENUE (Continued) **S109416407**

the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine

192 RALPH AVENUE (Continued) **S109416407**

if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN

192 RALPH AVENUE (Continued) **S109416407**

Own Op:	1
Sub Type:	05
Owner Name:	Peleg Neev
Owner Company:	188 Ralph, LLC
Owner Address:	161 West 54th street
Owner Addr2:	Not reported
Owner City,St,Zip:	new york, NY 10019
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Omri Minin
Owner Company:	Hubbell Mountain, LLC
Owner Address:	404 East 79th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10075-1482
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	192 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Saratoga Library
Owner Address:	8 Thomas S. Boyland St
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	188 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11576
Owner Country:	United States of America
HW Code:	224042
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042

192 RALPH AVENUE (Continued) **S109416407**

Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

ENG CONTROLS:
Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
HW Code: 224042
Control Code: 15
Control Type: ENG
Date Record Added: 10/27/2020
Date Rec Updated: 04/28/2022
Updated By: GWBURKE
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20’ x 20’ area at the southern end of the on-site parcel where disposal

192 RALPH AVENUE (Continued) **S109416407**

occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20’ x 20’ portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the

192 RALPH AVENUE (Continued) **S109416407**

groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem:	Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2003-04-04 10:25:00
Record Upd:	2018-02-20 11:28:00
Updated By:	RHFILKIN
Own Op:	1
Sub Type:	05
Owner Name:	Peleg Neev
Owner Company:	188 Ralph, LLC
Owner Address:	161 West 54th street
Owner Addr2:	Not reported
Owner City,St,Zip:	new york, NY 10019
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Omri Minin
Owner Company:	Hubbell Mountain, LLC
Owner Address:	404 East 79th Street
Owner Addr2:	Not reported

192 RALPH AVENUE (Continued) **S109416407**

Owner City,St,Zip:	New York, NY 10075-1482
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	192 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Saratoga Library
Owner Address:	8 Thomas S. Boyland St
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	188 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11576
Owner Country:	United States of America
HW Code:	224042
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	V00669
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-06-16 09:56:00
Record Updated:	2008-06-16 09:56:00
Updated By:	MOBARRIE
Crossref ID:	224042A
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-01-23 09:27:00
Record Updated:	2020-01-23 09:27:00

192 RALPH AVENUE (Continued) **S109416407**

Updated By:	NTFREEMA
Crossref ID:	2017000216710
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-03-03 13:14:00
Record Updated:	2020-03-03 13:14:00
Updated By:	GWHEITZM
Name:	192 RALPH AVENUE
Address:	192 RALPH AVE
City,State,Zip:	BROOKLYN, NY 11233
Site Code:	58281
HW Code:	224042
Control Code:	13
Control Type:	ENG
Date Record Added:	10/27/2020
Date Rec Updated:	04/28/2022
Updated By:	GWBURKE
Site Description:	Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20’ x 20’ area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around

192 RALPH AVENUE (Continued) **S109416407**

60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above

192 RALPH AVENUE (Continued) **S109416407**

	their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.
Health Problem:	Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2003-04-04 10:25:00
Record Upd:	2018-02-20 11:28:00
Updated By:	RHFILKIN
Own Op:	1
Sub Type:	05
Owner Name:	Peleg Neev
Owner Company:	188 Ralph, LLC
Owner Address:	161 West 54th street
Owner Addr2:	Not reported
Owner City,St,Zip:	new york, NY 10019
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Omri Minin
Owner Company:	Hubbell Mountain, LLC
Owner Address:	404 East 79th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10075-1482
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	192 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Saratoga Library
Owner Address:	8 Thomas S. Boyland St

192 RALPH AVENUE (Continued) **S109416407**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	188 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11576
Owner Country:	United States of America
HW Code:	224042
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	V00669
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-06-16 09:56:00
Record Updated:	2008-06-16 09:56:00
Updated By:	MOBARRIE
Crossref ID:	224042A
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-01-23 09:27:00
Record Updated:	2020-01-23 09:27:00
Updated By:	NTFREEMA
Crossref ID:	2017000216710
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-03-03 13:14:00
Record Updated:	2020-03-03 13:14:00
Updated By:	GWHEITZM

Name:	192 RALPH AVENUE
Address:	192 RALPH AVE
City,State,Zip:	BROOKLYN, NY 11233
Site Code:	58281
HW Code:	224042
Control Code:	36
Control Type:	ENG

192 RALPH AVENUE (Continued) **S109416407**

Date Record Added: 10/27/2020
Date Rec Updated: 04/28/2022
Updated By: GWBURKE
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20’ x 20’ area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has

192 RALPH AVENUE (Continued) **S109416407**

also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies

192 RALPH AVENUE (Continued) **S109416407**

	sampling offers.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2003-04-04 10:25:00
Record Upd:	2018-02-20 11:28:00
Updated By:	RHFILKIN
Own Op:	1
Sub Type:	05
Owner Name:	Peleg Neev
Owner Company:	188 Ralph, LLC
Owner Address:	161 West 54th street
Owner Addr2:	Not reported
Owner City,St,Zip:	new york, NY 10019
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Omri Minin
Owner Company:	Hubbell Mountain, LLC
Owner Address:	404 East 79th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10075-1482
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	192 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Saratoga Library
Owner Address:	8 Thomas S. Boyland St
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	6
Sub Type:	E
Owner Name:	Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	188 Ralph Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11576
Owner Country:	United States of America
HW Code:	224042
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

192 RALPH AVENUE (Continued) **S109416407**

HW Code:	224042
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224042
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	V00669
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2008-06-16 09:56:00
Record Updated:	2008-06-16 09:56:00
Updated By:	MOBARRIE
Crossref ID:	224042A
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-01-23 09:27:00
Record Updated:	2020-01-23 09:27:00
Updated By:	NTFREEMA
Crossref ID:	2017000216710
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-03-03 13:14:00
Record Updated:	2020-03-03 13:14:00
Updated By:	GWHEITZM

INST CONTROL:

Name:	192 RALPH AVENUE
Address:	192 RALPH AVE
City,State,Zip:	BROOKLYN, NY 11233
Site Code:	58281
Control Name:	Site Management Plan
HW Code:	224042
Control Code:	32
Control Type:	INST
Dt record added:	10/27/2020
Dt rec updated:	04/28/2022
Updated By:	GWBURKE
Site Code:	58281
Site Description:	Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site

192 RALPH AVENUE (Continued) **S109416407**

building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior

192 RALPH AVENUE (Continued) **S109416407**

to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00

192 RALPH AVENUE (Continued) **S109416407**

Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

192 RALPH AVENUE (Continued) **S109416407**

HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
Control Name: Monitoring Plan
HW Code: 224042
Control Code: 31
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the

192 RALPH AVENUE (Continued) **S109416407**

basement area of the building. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products,

192 RALPH AVENUE (Continued) **S109416407**

were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC

192 RALPH AVENUE (Continued) **S109416407**

Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID

192 RALPH AVENUE (Continued) **S109416407**

Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
Control Name: O&M Plan
HW Code: 224042
Control Code: 33
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and

192 RALPH AVENUE (Continued) **S109416407**

Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20’ x 20’ portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor

192 RALPH AVENUE (Continued) **S109416407**

air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository

192 RALPH AVENUE (Continued) **S109416407**

Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233

192 RALPH AVENUE (Continued) **S109416407**

Site Code: 58281
Control Name: Landuse Restriction
HW Code: 224042
Control Code: 25
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20’ x 20’ area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The

192 RALPH AVENUE (Continued) **S109416407**

significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building

192 RALPH AVENUE (Continued) **S109416407**

will be initiated under the Site Management Plan.
Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported

192 RALPH AVENUE (Continued) **S109416407**

Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
Control Name: Ground Water Use Restriction
HW Code: 224042
Control Code: 08
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is

192 RALPH AVENUE (Continued) **S109416407**

identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the

192 RALPH AVENUE (Continued) **S109416407**

latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported

192 RALPH AVENUE (Continued) **S109416407**

Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN

192 RALPH AVENUE (Continued) **S109416407**

Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
Control Name: Soil Management Plan
HW Code: 224042
Control Code: 14
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination

192 RALPH AVENUE (Continued) **S109416407**

came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20' x 20' area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives

192 RALPH AVENUE (Continued) **S109416407**

(SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019

192 RALPH AVENUE (Continued) **S109416407**

Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00

192 RALPH AVENUE (Continued) **S109416407**

Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
Control Name: Environmental Easement
HW Code: 224042
Control Code: J
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20’ x 20’ area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area

192 RALPH AVENUE (Continued) **S109416407**

Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20’ x 20’ portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3.

192 RALPH AVENUE (Continued) **S109416407**

TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC

192 RALPH AVENUE (Continued) **S109416407**

Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00

192 RALPH AVENUE (Continued) **S109416407**

Updated By: GWHEITZM

Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 58281
Control Name: IC/EC Plan
HW Code: 224042
Control Code: 34
Control Type: INST
Dt record added: 10/27/2020
Dt rec updated: 04/28/2022
Updated By: GWBURKE
Site Code: 58281
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The on-site portion (on-site) of the site (ID No. 224042) is a 20 foot x 20 foot area where contamination was found on 192 Ralph Avenue and is identified on the New York City Tax Map as Section 3, Block 1678, Lot 53. Site Features: The main on-site feature is the existing three-story building on the property and an attached one-story addition with a basement at the rear. The building structure is 20 foot x 20 foot building addition of the larger lot. The on-site building is currently occupied. Current Zoning/Use: The zoning for the off-site area near the dry cleaners that was the subject of the investigation is a mixture of Residential and Commercial (R6B) or Residential (R5B) 1 and 2 family. Past Use of the Site: Dry-cleaning operations (wet chemical) were conducted on-site from approximately 1946 until 1998. The dry-cleaning operations took place in the 20 x 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the on-site contamination came from releases of process chemicals into the basement area of the one-story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. On-site contamination was discovered in 2002 during an owner-initiated subsurface investigation within the basement area of the building. The State Superfund site is a 20’ x 20’ area at the southern end of the on-site parcel where disposal occurred. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 2 (OU2) is the on-site source area Operable Unit 1 is the off-site portion. The off-site area investigated includes the remainder of the on-site building outside the source area, and also runs along Ralph Ave. and the side streets one half a block east of Ralph Ave. from approximately MacDonough St. in the north, to Marion St. in the south. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally, there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast.
Env Problem: Nature and Extent of Contamination: Remediation at the site is

192 RALPH AVENUE (Continued) **S109416407**

complete. Prior to remediation, the primary contaminant of concern at the site is the dry-cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE). Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan. OU 2: On-Site Area: Prior to remediation: Soil: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater: Groundwater beneath the building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 2.4 to 320 ppb in the vicinity of the site in February, 2013. Soil Vapor and Indoor Air: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event. A post-IRM indoor air sample in the southern 20' x 20' portion of the parcel defined as the State Superfund site showed PCE at a concentration of 7.46 ug/m3. Three post-IRM indoor air samples were taken in the remainder of the parcel and contained a maximum PCE concentration of 6.71 ug/m3. OU 1: Off-Site Area: Prior to remediation: The off-site investigation was conducted to determine if volatile organic compound (VOC) contamination from on-site had migrated off-site. Samples were only analyzed for VOCs. The area of investigation ran along Ralph Ave. and its side streets from approximately MacDonough St. in the north to Marion St. in the south. Soil - 20 subsurface soil samples were taken at depths ranging from 34 to 62 feet below ground surface from 10 soil borings. None of the soil samples collected exceeded unrestricted Soil Cleanup Objectives (SCOs) for VOCs. Groundwater - 14 monitoring wells and piezometers were installed and sampled during the investigation in three rounds between September 2012 and January 2017. During the most recent round of groundwater sampling, the 5 wells with the greatest historical concentrations of the contaminants, PCE and its breakdown products, were resampled. Groundwater samples from 4 of these 5 wells contained tetrachloroethene (PCE) at concentrations in excess of the groundwater standard for PCE of 5 ppb. The maximum concentration detected was 95 ppb. One well also exceeded the groundwater standard of 5 ppb for trichloroethene (TCE) with a concentration of 8 ppb. Soil Vapor - 33 soil vapor samples were collected in three rounds of sampling between September 2012 and September 2013. PCE was detected in every sample, with concentrations ranging from 4.2 to 6,700 ug/m3. TCE was detected in 21 samples with concentrations ranging from 0.14 ug/m3 to 220 ug/m3. Other PCE degradation products were only present at concentrations below 1 ug/m3. Indoor Air and Sub-slab Vapor - Access to conduct indoor air and sub-slab vapor sampling was gained in five off-site buildings in 2014. PCE was detected in the indoor air of one building at a concentration of 1.1 ug/m3. PCE was not detected in the indoor air of the four other buildings above the method reporting limit of 0.11 ug/m3. TCE and other degradation products were not detected in the indoor air of any buildings above their respective reporting limits (4.6 ug/m3 or less). Sub-slab vapor samples in three of the buildings contained PCE, with a maximum concentration of 1,300 ug/m3. TCE was detected in one sub-slab vapor sample at a concentration of 6.9 ug/m3. Overall, the following

192 RALPH AVENUE (Continued) **S109416407**

actions were identified as being warranted to address exposures related to soil vapor intrusion: mitigation actions in one building, monitoring in one building, and no further actions at the remaining three buildings. The mitigation system offered by the state to one property owner was declined. A monitoring program for one building will be initiated under the Site Management Plan.

Health Problem: Remedial actions are complete onsite and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Environmental sampling indicates that soil vapor intrusion could be a concern for offsite buildings, however, many nearby property owners have declined the Agencies sampling offers.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2003-04-04 10:25:00
Record Upd: 2018-02-20 11:28:00
Updated By: RHFILKIN
Own Op: 1
Sub Type: 05
Owner Name: Peleg Neev
Owner Company: 188 Ralph, LLC
Owner Address: 161 West 54th street
Owner Addr2: Not reported
Owner City,St,Zip: new york, NY 10019
Owner Country: United States of America
Own Op: 6
Sub Type: E
Owner Name: Omri Minin
Owner Company: Hubbell Mountain, LLC
Owner Address: 404 East 79th Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10075-1482
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 192 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Saratoga Library
Owner Address: 8 Thomas S. Boyland St
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11233
Owner Country: United States of America
Own Op: 6

192 RALPH AVENUE (Continued) **S109416407**

Sub Type: E
Owner Name: Peter S. Rosenbaum
Owner Company: Brooklyn Properties 5, LLC
Owner Address: 188 Ralph Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11576
Owner Country: United States of America
HW Code: 224042
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224042
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: V00669
Cross Ref Type Code: 04
Cross Ref Type: VCP Site ID
Record Added Date: 2008-06-16 09:56:00
Record Updated: 2008-06-16 09:56:00
Updated By: MOBARRIE
Crossref ID: 224042A
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-01-23 09:27:00
Record Updated: 2020-01-23 09:27:00
Updated By: NTFREEMA
Crossref ID: 2017000216710
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-03-03 13:14:00
Record Updated: 2020-03-03 13:14:00
Updated By: GWHEITZM

VCP:
Name: 192 RALPH AVENUE
Address: 192 RALPH AVE
City,State,Zip: BROOKLYN, NY 11233
Program Type: VCP
Site Code: 58001
HW Code: V00669
Site Class: C
SWIS: 2401
Region: 2
Town: New York City

192 RALPH AVENUE (Continued) **S109416407**

Acres: 0.037
Date Record Added: 08/29/2003
Date Record Updated: 04/26/2023
Updated By: SMQUANDT
Site Description: Location: The site is located in an urban area in the southeastern part of the Bedford Stuyvesant section of Brooklyn. The site occupies 188 through 192 Ralph Avenue and is identified on the New York City Tax Map as Section 6, Block 1678, Lot 53. Site Features: The main site feature is the existing three story building on the property and an attached one story addition with a basement at the rear (192 Ralph Avenue). The building structure is 20' X 80' occupying an area of approximately 0.037 acres. Current Zoning/Use: The building at the site is zoned mixed Residential and Commercial (R6B) and is currently unoccupied. The surrounding properties are either zoned the same or as Residential 1 and 2 Family (primarily row house structures), which make up the majority of the area property uses. The row house property adjacent to the site building at 590 Macdonough Street has this latter zoning designation, while the adjacent 4 story, 14 unit apartment building to the south at 196 Ralph Avenue has the residential and commercial designation. Past Use of the Site: Dry cleaning operations (wet chemical) were conducted at the site property from approximately 1946 until 1998. From 1998 until 2000 the site was used solely as a drop shop dry cleaning operation. The dry cleaning operations took place in the 18 X 20 foot addition at the rear of the building with the equipment located on the first floor. It appears that the site contamination came from releases of process chemicals into the basement area of the one story building addition, which at the time had a dirt floor in the basement allowing migration of contaminants into the underlying soils and groundwater. Site contamination was discovered in 2002 during an Owner initiated subsurface investigation within the basement area of the building. With the confirmation of waste disposal at the site the property owner entered the Department's Voluntary Cleanup Program as a Volunteer in 2004. Site Geology and Hydrogeology: The general area geology is composed of outwash sand and gravel deposits. Locally there are highly permeable fine to medium sands with some gravel. There appears to be a confining silt/clay layer of unknown thickness present in the site area around 60 to 70 feet below the ground surface. Groundwater is encountered at 35 to 40 feet below ground surface (~9 feet above sea level). The area groundwater flow is to the south/southeast. A Decision Document for the site was signed on October 18, 2013. A release letter was issued to the property owner on July 10th, 2018. A small portion of the property remains a class 02 site, under site number 224042.
Env Problem: Site is Remediated. Prior to Remediation: Nature and Extent of Contamination: Based upon investigations conducted to date the primary contaminant of concern at the site is the dry cleaning solvent tetrachloroethylene (also known as perchloroethylene, perc or PCE) and to a minor extent the breakdown products of this chemical. Chemical concentrations are reported in parts per billion (ppb) for water, soil samples are reported in parts per million (ppm) while air samples are reported in micrograms per cubic meter (ug/m3). Soil Contamination: The significant soil contamination at the site is primarily limited to the area under the building footprint. The shallow soils are contaminated with PCE in the range of 10 to 344 ppm. The restricted residential soil cleanup objective (SCO) for PCE is 19 ppm. Groundwater Contamination: Groundwater beneath the

192 RALPH AVENUE (Continued) **S109416407**

	building footprint is contaminated with PCE above groundwater standard of 5 ppb. PCE has also migrated from the site area down-gradient to the south southeast under the adjoining sidewalks and streets. PCE contamination in the upper part of the aquifer (~ 40 feet below ground surface) ranges from approximately 80 to 7,100 ppb. Soil Vapor: Soil vapor measurements taken from the five extraction wells in the basement of the building showed PCE concentrations ranged from 678 to 19,000 ug/m3 during the latest monitoring event.
Health Problem:	People will not come into contact with contaminated soils since they are located at depth and beneath a building foundation. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A soil vapor extraction system has been installed beneath the on-site building to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building. The potential for off-site inhalation exposures due to soil vapor intrusion is being investigated as part of a separate investigation.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	40:40:58.9 / 73:55:22.6
Dell:	False
Record Add:	2004-07-14 10:13:00
Record Upd:	2013-01-03 08:38:00
Updated By:	rshough
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	L. Taylor
Owner Company:	Saratoga Library
Owner Address:	8 Thomas S. Boyle St. @ Macon St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11233
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Peter S. Rosenbaum
Owner Company:	Brooklyn Properties 5, LLC
Owner Address:	3A West Dr.
Owner Addr2:	Not reported
Owner City,St,Zip:	Port Washington, NY 11050-1456
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Omri Minin
Owner Company:	Hubbell Mountain, LLC
Owner Address:	404 East 79th Street, Apt. 15C
Owner Addr2:	Not reported

192 RALPH AVENUE (Continued) **S109416407**

Owner City,St,Zip:	New York, NY 10075-1482
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Peleg Neev
Owner Company:	188 Ralph, LLC
Owner Address:	161 West 54th Street
Owner Addr2:	Apt. 903
Owner City,St,Zip:	New York, NY 10019
Owner Country:	United States of America
HW Code:	V00669
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00669
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00669
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00669
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224042
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-06-16 09:56:00
Record Updated:	2008-06-16 09:56:00
Updated By:	MOBARRIE
Crossref ID:	2017000216710
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-03-03 13:13:00
Record Updated:	2020-03-03 13:13:00
Updated By:	GWHEITZM

---

370 ESE 1/4-1/2 0.417 mi. 2200 ft.

AKA 31-33 MONACO PLACE
2121 MONACO PLACE
BROOKLYN, NY

NY LTANKS **S106971540**
N/A

Relative: Higher

Actual: 84 ft.

LTANKS:

Name:	AKA 31-33 MONACO PLACE
Address:	2121 MONACO PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0408751 / Not Reported
Facility ID:	0408751
Site ID:	333492
Spill Date:	2004-11-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401

AKA 31-33 MONACO PLACE (Continued) **S106971540**

Investigator:	ADZHITOM
Referred To:	DELINEATION TO FOLLOW
Reported to Dept:	2004-11-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	1
Date Entered In Computer:	2004-11-08
Spill Record Last Update:	2011-06-01
Spiller Name:	MAURICE
Spiller Company:	Not reported
Spiller Address:	31-33 MONOCO PLACE
Spiller County:	001
Spiller Contact:	MAURICE
Spiller Phone:	(516) 482-0276
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	268724
DEC Memo:	"During excavation to re-develop the lot, two 550 gallon gasoline ust's were uncovered. DC Env. was retained to remove the tanks. A gas-water mix was pumped from the tanks and soil contamination was encountered. A contaminated soil letter was sent. New Owner Maurice Shami- #212-656-1338 Maurice called and stated that DC spilled the gas while conducting the pump out. Maurice requested and was given the names and numbers of 6 additional consultants upon his request. 11/17/04-Vought-Spoke to Reza Khanbilzardi who is a consultant (Indertech Consultants 914-329-3440) who is requesting DEC requirements. DEC requires: 1)collection of five endpoint soil samples and EPA Methods 8260/8270 2)collection of one groundwater sample 3)locations of fill ports and pump islands 4)copies of soil disposal manifests 5)site plan with sampling locations. 1/12/04 Bill Vardy left message 914-329-3440 requesting 10 day extension to submit report. Rommel 1/26/05-Vought-Spoke to Reza and he is requesting an additional ten days to submit report. Report will be submitted by 2/8/05. 02/08/05 Reza called 914-329-3440. He is the engineer representing the owner. He will overnight the report tomorrow. Rommel 2/11/04-Vought-Received message from Reza on 2/9/05. Vought returned call and he sent report via FedEx to Rommel. Vought told him to call Rommel on 2/14/05. 3/3/05 - Spoke to Reza Khanbilvardi, he is asking a quick review of the closure report. He stated that only minor contamination found with the soil boring and sampling. Need to find the report and get back to him for a determination. - KST 3/8/05 - Owner, Maurice, called and begging to review the closure report. I told him that we have not received the report. He will called his consultant to get a copy and hand deliver it to DEC. - KST 3/9/05-Vought-Spill transferred from Rommel to Vought as per Tang. Review of Subsurface Investigation Report submitted by InterTech Inc (Reza Khanbilvardi)dated 2/9/05 and received on 3/7/05. Owner of property is Maurice Shami. The site is vacant land... A small excavation (approximate size of 12 ft wide by 16 foot long and 7 ft deep were noticed on the southwest portion of the site. This is the location of the two empty oil tanks which resulted in above spill number to be issued . Five endpoint soil samples were collected on

AKA 31-33 MONACO PLACE (Continued) **S106971540**

12/7/05. One groundwater sample was also collected. Since all soil samples taken at the site meets recommended soil cleanup objective criteria and semi-volatile compounds in groundwater are not detected, the elevated volatile amount in groundwater could not have been due to any element on the property. It must be noted that an active commercial gas station is on the other corner of Monaco Place and Atlantic Avenue . Report recommends that we don't believe that any action with respect to soil cleanup is warranted for this site . Site plan shows three proposed two-story buildings onsite. Groundwater at depth of 12' below grade. Groundwater analyticals show 61ppb benzene, 300ppb toluene, 72ppb ethylbenzene, 200ppb xylene and 14ppb MTBE. DEC requires signing of Stipulation Agreement: 1)locations of fill ports and pump islands 2)notification to NYC agencies requesting no development of site 3)determination of groundwater flow direction via installation of three monitoring wells 4)installation of vapor barrier upon development of site 5)installation of passive venting system or performance of soil gas sampling as per NYSDOH guidance upon development of site 6)surrounding area site plan. Vought called Khanbilvardi and left message to return call to DEC. Vought sent Stipulation with above requirements with due date of 4/18/05. 3/10/05-Vought-Received message from Reza. Vought returned call and left message to return call to DEC. 3/14/05-Vought-Meeting at DEC with Reza and Maurice Shami. DEC will give approval to start construction once we receive and approve plan for vapor barrier and three onsite monitoring wells. No passive ventilation system or soil gas sampling will be required due to clean soil endpoints, lack of basement, relatively minor groundwater contamination and 6' depth to groundwater. 3/15/05-Vought-Received call from Maurice Shami (516-482-0276) and copy of bargain and sale deed which referred to previous owner as: Stephen Carter 679 East 98th Street Brooklyn, NY Vought called Shami and left message to return call to DEC. 3/22/05-Vought-Received fax from Inter Tech dated 3/16/05. .... we came to the decision to do the following: 1)the owner of the above referenced property will install a vapor barrier under the footings and basement floor slabs of the proposed construction on the site. This will be done after the excavation and prior to pouring the concrete of the foundation. The owner will install three monitoring wells...to determine groundwater flow direction with respect to the above site . You will provide approval letter to install these wells on the sidewalk . I appreciate your acknowledgement of receiving this letter and also your consent to it and start of the construction at the site so Mr. Shami can proceed with the construction . Vought sent out sidewalk permit letter and called Inter Tech to explain that consent to begin construction will not be given until groundwater results are received and groundwater flow direction is determined. 3/29/05-Vought-Called Maurice Shami for update on site and left message to return call. 3/31/05-Vought-Received call from Reza that wells were scheduled to be installed tomorrow and whether sidewalk permit was needed due to DEC sidewalk permit letter. Vought explained that letter was to effectuate the obtaining of a permit and that the permit was still required from DOT. 4/5/05-Vought-Received message from Reza. Vought returned call and left message to return call to DEC. Vought spoke to Reza and he will install wells onsite as opposed to sidewalk so that sidewalk permits are not needed. 5/19/05-Vought-Reviewed Investigation Report (Inter Tech) dated 5/17/05 and received on 5/18/05. Installation of three 4-inch monitoring wells. Contractor who installed wells was American

AKA 31-33 MONACO PLACE (Continued) **S106971540**

Environmental Assessment Corp. Report recommends ....we do not believe that any action with respect to cleanup is warranted for this site. We therefore, request your approval to start the construction project as the owner is patiently waiting for the last 6 months . Groundwater analyticals show: 13ppb ethylbenzene(MW2), 82ppb MTBE(MW2), 120ppb n-propylbenzene(MW2), 72ppb isopropylbenzene(MW2), 440ppb MTBE(MW3). Source of minor groundwater contamination may be from onsite UST excavation (despite clean endpoints) or from upgradient site(due to minor groundwater contamination in well MW2). DEC sent letter approving construction of residence with installation of vapor barrier as per 3/16/05 letter and requiring as per 3/9/05 STIP cover letter: 1)surrounding area site plan with possible upgradient sources 2)continued quarterly monitoring of groundwater 3)installation of well downgradient from former tankfield and Boring B1 on sidewalk of Atlantic Avenue 4)submission of PBS registration 5)locations of remote fill and dispenser islands. Vought called Maurice and left message. 5/27/05-Vought-Spoke with Maurice and five additional tanks discovered during excavation for building. Maurice is hiring American Environmental to remove the tanks. Maurice will call back with update on tank removal. Maurice returned call and American (631-586-2000 Danny Herzberger) will do tank removal on 6/6/05. 6/1/05-Vought-Received call from Herschberger. Vought returned call and left message to return call. 6/6/05-Vought-Received call from Herschberger(516-852-4713). Vought returned call and tanks registered with PBS. Five endpoint samples will be collected and sampled for 8021 plus MTBE and 8270. Dan will call DEC when excavation is complete so that site visit may be scheduled. Received call from Dan that tanks were removed and impacted soil was found. Vought required excavation of impacted soil and called Maurice to restate requirement. 6/7/05-Vought-Received call from Herschberger. Vought returned call and American will only be removing tanks and underlying pad. A sixth tank was discovered and Maurice's contractor will be removing contaminated soil. American will be collecting endpoint samples. Vought received call from Maurice and returned call and left message to return and stated requirement of disposal manifests. Vought received second message from Maurice and returned call. 6/8/05-Vought-Received third message from Maurice and returned call. Vought spoke to Maurice and stated requirement of disposal manifests and site visit. Maurice will collect two soil samples and submit to laboratory for analyses to see if further excavation is warranted. Vought advised use of field screening device however due to possibility of saving further cost of excavation Maurice decided to collected samples. 6/10/05-Vought-Received call from Maurice. Vought returned call and arranged site visit for Wed 6/15. 6/15/05-Vought-Site visit by Vought with Maurice, Dan Herschberger and Reza. Contaminated soil at former UST location and DEC required 1)additional excavation to groundwater 2)collection of four sidewalls and one bottom groundwater endpoint sample 3)installation of vapor barrier(agreed to by Maurice) 4)well installation downgradient from tankfield along Atlantic Ave. Vought also suggested groundwater treatment when excavation was open and boring by Amoco to see if they are contributing source. Vought will send above requirements upon receiving endpoint analyticals. 7/26/05-Vought-Called Maurice for status update of site. No work has been performed as of yet due to unable to find contractor. 7/29/05-Vought-Spoke to Gerard Rutigliano (Rutigliano Environmental 516-314-1553) and he may be performing soil removal and vapor barrier installation. Vought approved installation

AKA 31-33 MONACO PLACE (Continued) **S106971540**

of a 6.mil vapor barrier under building footprints. Four sidewall endpoint and one bottom groundwater sample will be collected. 8/8/05-Vought-Called El-Shami, Reza and Rutigliano and informed them of new project manager (DEC Zhitomirsky). Vought spoke to Maurice El-Shami and approved that he install vapor barrier provided that he sent letter in writing to DEC. Vought also stated that vapor mitigation system was not necessary as long as excavation was performed to groundwater (12' below grade). 8/8/2005 Zhitomirsky spoke with Maurice Shami and requested submittal of soil disposal manifest, drawings showing where the soil was excavated from, drawings and description of vapor barrier installation. Jeffry Voight informed me that he requested from the site owner a description of the vapor barrier. In this case Vought would not require a vapor mitigation system and allow RP to install the vapor barrier himself. AZ 8/10/2005 I discussed this site with K.Tang. I told him I am requiring environmental report describing soil excavation with pictures, drawings and disposal manifest. Also, RP should include specifications and drawings for vapor barrier. K.Tang concurred and stated that we can issue permission to start construction and install vapor barrier. K.Tang thinks that 6 mil thickness polyethylane sheeting may be not thick enough and RP consultant should suggest another one. I conveyed this information to Morris Yeroshalmi and provided him with K. Tang phone number upon his request. AZ 8/17/2004 KT visited the site on 8/12/2005. He noticed that the excavation could cave in because it is 11 feet deep. He said that there is not much to see in the excavation except gravels and dirt. No petroleum odor, no stained soil. They have put some soil back in the tank pit. He asked a soil sample at the center of the tank pit taken at the water table. He could smell a slight petro odor. Not bad though. Due to safety concern of the side walk on Atlantic Ave side of the excavation collapsing, he told Maurice to go ahead with his construction work and backfill the hole, with the condition that he put down the vapor barrier material (15 mil) below the foundation of the buildings he is putting up. He also told him to compile all the tank removal, soil excavation, wells installation, soil removal activities, soil samples, water samples and the soil disposal manifest in a report for you. He also told him to install 4 wells - 1 on Monaco Pl, 3 on Atlantic Ave. for GW monitor and/or remediation. AZ 11/22/2005 I received an e-mail from K Tang. He asked me to issue a letter to Moris Shami (Mfund Company 516-482-0276). I called him and conveyed that as per K.Tang 4 wells should be installed one on Monaco Place and three on Atlantic Avenue. His address is: 1 Linden Place Suite#302 Great Neck, New York 11021.AZ 11/29/2005 I called Moris and informed him that he should install 3 wells on Atlantic Ave. and one well between his place and BP station. I confirmed this request with K. Tang. I sent him a letter so he can obtain a permission from DOT to install sidewalk wells. AZ 1/18/2006 The owner (Moris) has contacted me. He needed some kind of a letter for the City. I replied that we do not isuue such letters. He is going to proceed with the well installation. AZ 4/4/2006 I left a message for owner Moris (516-482-0276). He called me back. Hydro Tech installed wells and is working on the report for DEC. AZ 5-11-2006 Left a message for Rachel Ataman (Hydro Tech Environmental). AZ 5-16-2006 I contacted Sharissa Singh 718-636-0800(Hydro Tech Environmental). She informed me that Rachel Ataman is no longer handles this project. I conveyed to Ms. Singh that the plume should be delineated and once the delineation has been completed a remedial plan should be

AKA 31-33 MONACO PLACE (Continued) **S106971540**

sumbitted. AZ 5-17-2006 Reviewed the Groundwater Investigation Report prepared by Hydro Tech Environmental Corp., dated April 4, 2006. The report states that VOCs were detected in the groundwater samples obtained from wells MW-1 through MW-4 at concentrations exceeding their respective TOGS standards. The total VOC concentrations at the site range from 1,111 ppb to 523 ppb in downgradient wells. Hydro Tech Environmental recommended groundwater monitoring. After consultation with Koon Tang, I requested delineation of the groundwater plume in the southern area of the site by installing two new wells. If contamination is encountered by these downgradient wells, additional wells should be installed to fully delineate the plume. Once the plume has been delineated, a remedial plan to address the contamination should be submitted to DEC. A letter was sent to the RP and the consultant. AZ 5-25-2006 I reiterated myc comments regarding the submitted report to the owner Maurice Shami over the phone. AZ 10-24-2006 Left a message for the owner Maurice @ 516-482-0276. AZ 10/25/2006 Contacted the owner Maurice @ 516-482-0276. He is hiring an environmental consultant American Environmental Co. He will get back to DEC when the consultants are hired. AZ 11-5-2007 Contacted the owner Maurice @ 516-482-0276 and requested about the site status. He stated that he thinks that no work should be done at this site. He will contact me with more information ASAP. AZ 11-7-2007 Spoke with Maurice Chami (M Fund 45 North Station Plaza Great Neck New York 11021). Mr. Shami is stating that he sold the property but he does not know whom he sold the property to, since the sale was handled by his broker. He will get back to me with this information ASAP. Mr. Shami contacted me later and informed that the buyer is Victor Inwang 31 Monaco Place, Brooklyn, New York 11221. He sold the property in May or June of 2006 (his guess).It is a private dwelling. AZ 11-14-2007 Case Initiation Form was signed by Vadim Brevdo and forwarded to John Urda. AZ 7-29-2008 J. Urda requested that CSL, STIP are send to RP. I sent drafts of CSL, STIP and CAP to John Urda and V. Brevdo for review. They approved the documents. CSL,STIP and CAP were sent to Maurice Chami- M Fund, 45 North Station Plaza, Great Neck, NY 11021 and Victor P. Inwang 1400 Bedford Avenue, Brooklyn, New York 11216. Copies were sent to V.B and John Urda. AZ 8-21-2011 The letter was returned to DEC stating: Return to Sender unclaimed unable to forward AZ 3-17-2011 As per J. Urda request, STIP, CSL and CAP were resent to Victor P. Inwang 1400 Bedford Avenue, Brooklyn, New York 11216 and send to Victor P. Inwang 583 Eastern Parkway, Brooklyn, NY 11216. AZ 4-11-2011 Two letters were returned to DEC stating Return to sender unclaimed unable to forward. I informed J. Urda about the returned letters. AZ"

Remarks: "2 550 gal tanks"

All Materials:

Site ID:	333492
Operable Unit ID:	1095646
Operable Unit:	01
Material ID:	575767
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00

AKA 31-33 MONACO PLACE (Continued) **S106971540**

Resource Affected: Groundwater
Oxygenate: Not reported

371
North
1/4-1/2
0.422 mi.
2227 ft.

RESIDENCE
842 MACON ST
BROOKLYN, NY

NY LTANKS **S106869140**
N/A

Relative:
Lower

Actual:
38 ft.

LTANKS:

Name:	RESIDENCE
Address:	842 MACON ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0500513 / 2005-04-13
Facility ID:	0500513
Site ID:	343503
Spill Date:	2005-04-12
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-04-12
CID:	407
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-04-12
Spill Record Last Update:	2005-04-13
Spiller Name:	THOMAS BUTLER
Spiller Company:	VIJAX
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	HOWARD SCOTT
Spiller Phone:	(212) 675-2761
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	289969
DEC Memo:	"Sangesland spoke to the nephew of owner (Howard Scott). He said the house is Mr Scott's weekend house. The oil company did spill, and did clean it up. If Mr. Scott does NOT like the clean up job, he will call the DEC back at Sangesland's number."
Remarks:	"Spill has been cleaned up."

All Materials:

Site ID:	343503
Operable Unit ID:	1102190
Operable Unit:	01
Material ID:	582411
Material Code:	0001A
Material Name:	#2 fuel oil

RESIDENCE (Continued) **S106869140**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

372
NNE
1/4-1/2
0.428 mi.
2260 ft.

HENRY APARTMENTS - SITE A - 1676 BROADWAY **NY VCP** **S125317288**
1676 BROADWAY **N/A**
NEW YORK CITY, NY

Relative:
Lower

Actual:
60 ft.

VCP NYC:

Project ID:	15TMP0592K,15CVCP148K,15CVCP148K
Name:	HENRY APARTMENTS - SITE A - 1676 BROADWAY
Address:	1676 BROADWAY
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3.0150300293015E+49
OER Program:	VCP (Enrolled)
Phase:	Completed
Latitude:	40.684159
Longitude:	-73.912683
Postcode:	16
Community Board:	41
Council District:	373
Census Tract:	3414048
BIN:	3015037501
NTA:	Ocean Hill

373
ENE
1/4-1/2
0.443 mi.
2341 ft.

TORES HOME **NY LTANKS** **S108466382**
211 HULL STREET **NY Spills** **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0612788 / 2007-09-17
Facility ID:	0612788
Site ID:	377715
Spill Date:	2007-02-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2007-02-26
CID:	408

TORES HOME (Continued) **S108466382**

Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-02-26
Spill Record Last Update:	2007-09-17
Spiller Name:	Not reported
Spiller Company:	APARTMENT BUILDING
Spiller Address:	211 HULL ST
Spiller County:	999
Spiller Contact:	MEADOWS, RICHARD
Spiller Phone:	(347) 203-6886
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	327460
DEC Memo:	"02/26/07-Vought-DEC Patel performing site visit due to proximity to spill in field. DEC Ketani called FDNY and left message to return call to DEC. 02/27/06-Hiralkumar Patel. visited site on 02/26/07. met Ferdrnand Torres (917-568-3022), tenant at building. Mr. Torres lives on second floor. as per Mr. Torres, there was no heat yesterday (02/26/07) morning and he compalined to NYC HPD. oil delivered during day. lateron tenant found oil in basement and called FDNY. site has two 275 gal #2 oil ASTs on leg and FDNY found one of these tanks was leaking. they pumped out oil from leaking tank and put in drums and spread absorbent in basement. three 55 gal drums were out of building on sidewalk. second tank is still in use. as per Mr. Torres there is no super in building but Mr. Torres has keys to basement. at time of visit, heavy odors inside basement, free product around tank and odors upstairs also. Mr. Torres's mother and brother living on first floor. suggest Mr. Torres to get these people on second floor as there was no odors. this building ownes by NY City. Mr. Torres gave contact info for person managing property for city. Francis SynMoie 7A Admin. Bld #042 C/O NY Residential Works Inc. 347 Lenox Avenue New York, NY 10027 Ph. (212) 987-8088 Ext. 105 left message for emergency service at NY Residential Works at night. received call from Basil Marshall (646-294-0086). asked him to get cleanup crew to start cleanup for free product and odors in building. he spoke with Anthony Lara (646-772-7180). received call from Anthony. he was ready to send cleanup crew in night but he need approval from city and proposal signed by authorized person, which he hadn't got. tried to contact Mr. Marshall again regarding signing paperwork, but no contact was made. left message for Mr. Marshall. left message for Mr. SynMoie at NY Residential works last night. spoke with Mr. SynMoie this morning. they are still working on getting authorization from city agency for cleanup. asked Mr. SynMoie to start cleanup by end of today. 2/27/07 - Raphael Ketani. I contacted Mr. Francis Synmoie (sin-moy) at NY Residential Works, Inc. (212) 987-8088, ext 101. He said that he is still waiting for authorization to hire a contractor to do the cleanup, but someone already put down absorbent. He said that he contacted Debra Thomas of Unit 7A at HPD (212) 863-7392. He said she has the authority to authorize someone to cleanup the spill. I asked him how the odors are. He said that you notice a moderate odor of oil as you walk into the building, but no one lives on the first floor. I asked him about the odors on the second floor. He said there were

TORES HOME (Continued) **S108466382**

none. He said that this building was owned by a private party, but they didn't keep it up. So the city took it over and they will refurbish it. I spoke to Ms. Thomas. She said the City doesn't own the building, but is managing it. I asked her what is happening now. She said that a call was made to the Emergency Repair Unit as there is no money in the budget to pay for the cleanup. She said she is waiting for a call back. I told her that this spill is now at least 24 hours old. She said she knows, but all she can do right now is to call the Emergency Repair people. I told her that certain things will have to be done to cleanup the spill. She asked me to e-mail her what these requirements are. The requirements are: (1) cleanup all of the free oil (2) pickup all of the spent absorbent (3) powerwash the affected areas and the concrete floor (4) take soil samples below the concrete floor and send them to a NYSDOH certified lab for 8260 and 8270 analysis (5) remove all contaminated soil (6) submit manifests for all soil and contaminated material that is removed and the soil analytical results (7) repair the tank system and send copies of the documentation verifying that the repairs were made (8) submit to DEC a short report with pictures (if possible) of the before and after conditions and all documentation Ms. Thomas' e-mail address is thomasd@hpd.nyc.gov 3/12/07 - Raphael Ketani. Spill case #0613303 came in today regarding a new spill at the site. I spoke to Patrick Fahey of Pacific Energy (718) 647-1400 about the spill. He said that it was a loose flare nut that allowed oil to drip onto the floor. About 1 gal. leaked out. The flare nut was tightened, but the earlier large spill hasn't been cleaned up yet. This later spill case was closed. I spoke to Ms. Thomas regarding the old big spill of 2 weeks ago. She said she just got back from vacation and had been told the old spill had been cleaned up. I told her that Pacific Energy had a mechanic on site about 1 hour ago and he said the old spill was not removed. She told me that she will look into the issue and call me back. 3/23/07 - Raphael Ketani. I tried to make a site visit. The front door was locked and there was no one around to let me in. I didn't see or smell any signs of an oil release. 3/27/07 - Raphael Ketani. I made a site visit at 9:45AM today and was shown the basement by a second floor resident of the building who goes by the name of Rio and serves as a helper for Mr. Synmoie. The vapors were light but noticeable in the first floor hallway. The vapor readings were: basement 1334 ppb, first floor 903 ppb, second floor 782 ppb, third floor 751 ppb. Rio explained to me that the tanks are still not sitting solidly on the floor and that there were 2 big spills - both due to the tanks moving and a line below them getting loose. There was a 12 by 6 wet spot below the oil line that connects the two tanks at the bottom. Rio showed me that one spill flowed 30 feet down the basement hallway and into the adjacent room. The floor was in very bad shape and was in pieces, many of which could be moved by hand exposing the soil below. The floor had dark staining all over and so did the floor of the adjacent room. Lastly, Rio showed me the boiler room. The floor there also had staining. 3/28/07 - Raphael Ketani. I spoke to Mr. Synmoie and told him about the floor, the high vapor readings, the oily wet spot, the oil staining, and the probability that the soil under the basement floor is contaminated. I told him that he has to hire a company to stabilize the tanks, fix the line at the bottom if it is still dripping, do a soil investigation and ventilate the building. He said he will do this. He said there is one tenant on the first floor and she will be moved to the second floor. He said that the building is scheduled for rehabilitation in the very

TORES HOME (Continued) **S108466382**

near future. I told him that the soil investigation has to get started as soon as possible. He said he will call Ms. Thomas. I sent Ms. Thomas an e-mail with my notes from 3/27 and 3/28. 3/29/07 - Raphael Ketani. Chacko Thomas (cell (646) 865-4564) [supervisor (718) 857-5444] of NYC HPD called to say that 6 soil samples were taken in the floor of the building after the last oil spill. He said samples were taken in the tank room, the hallway, and the storage rooms. The analytical results should be available soon. He asked what else needed to be done at the site. I told him that the vapors are high so ventilation needs to be provided, the tanks need to be fixed to the floor so they don't move, the line at the bottom of the tanks needs to be fixed so it doesn't drip, and a soil boring needs to be taken in the boiler room floor. Mr. Chafeko said he will have this done. 4/4/07 - Raphael Ketani. Mr. Thomas of NYC HPD sent me a FAX for SVOC analysis for 4 of the 5 samples that were taken in the basement. He said he was expecting the VOC analysis today and will FAX them as soon as he gets them. There were only 2 very low exceedences of the TAGM RSCO limits. I told him these results looked fine. I received a FAX from Mr. Thomas with the VOC analyticals for soil samples 1,2,4,5. The samples were taken on 3/22/07. There were no RSCO exceedences, except 3200 ppb for total xylenes for soil sample #1. This is the tank room sample. Again, soil sample #3 was missing from the results. 4/5/07 - Raphael Ketani. I contacted Mr. Thomas and told him that the results seemed fine, except for total xylene in sample #1. I told him that soil will have to be removed in this area. Afterwards, Mr. Thomas called me up regarding which sample came from what location in the basement. Sample #1 was the tank room. Sample #2 was the storage room next to the tank room. Samples #3 (which he will check on why the results weren't received) to sample #5 were from the hallway. He said that the drip from the pipe at the bottom of the tanks is something new and will be taken care of shortly and that the tank feet were covered in cement to stabilize the tanks. Mr. Thomas said that the stain in the boiler room is only from routine servicing of the boiler. I told him that it seemed like more than routine servicing. He said the service techinician is sloppy and he will talk to him about being careful. However, he said, the building is privately owned and HPD is just overseeing the refurbishing of the building. 4/11/07 - Raphael Ketani. Mr. Thomas FAXed me the analytical results for samples 1,2,4,5. I spoke with him shortly after I received the FAX. He said that the contractor who did the sampling also took samples 3 and 6. However, the contractor threw out these samples as he felt he had enough samples for the site, according to Mr. Thomas. I told Mr. Thomas that either the soil has to be dug out in the tank room or soil treatment needs to be used. He said that he has to make a work order, in either case. I asked him to try and push the process forward. He said he would try. 5/18/07 - Raphael Ketani. Mr. Thomas of HPD (718) 857-5444 sent me a FAX with analytical results for 3 soil samples that were taken in the tank room after the contaminated soil was removed. All 3 sets of results were non-detect. I called up Mr. Thomas and asked him to send the manifests for the removed soil. He said he will send them. Mr. Thomas added that the 2 tanks have been emptied and will replaced with one tank. So that will take care of the leaking pipe. 7/13/07 - Raphael Ketani. I tried to contact Mr. Thomas regarding the documentation for the cleanup work and the tank replacement work, but could only leave a message. (Mr. Thomas is the person to contact regarding the project, NOT Mr. Synmoie or Ms. Thomas.) 7/16/07 - Raphael Ketani. I

TORES HOME (Continued) **S108466382**

spoke to Mr. Thomas and he told me the two tanks were replaced with 2 new 275 gallon tanks. He added that the contaminated soil at boring location #1 was taken away and that I should be receiving the manifest soon. 9/17/07 - Raphael Ketani. I received the Oil Spill Site Assessment Report from Mr. Thomas. The report states that the floors of the basement, the tank room, and the boiler room were power washed and soil samples were taken. The report also states that the leaking tanks were emptied (a waste ticket is included), removed, and replaced with new tanks. On 5/11/07, soil from the tank room was excavated and removed. Based upon the above mentioned Oil Spill Site Assessment Report and the analytical results for the tank room soil that were FAXed on 5/18/07, I am closing the spill case. "

Remarks: "UNSURE IF SEWERS AND GROUNDWATERS EFFECTED; CLEAN UP IS IN PROCESS;"

All Materials:

Site ID:	377715
Operable Unit ID:	1135237
Operable Unit:	01
Material ID:	2125131
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	ON SIDEWALK
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0612954 / 2007-03-14
Facility ID:	0612954
Facility Type:	ER
DER Facility ID:	327460
Site ID:	377908
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	2007-03-02
Investigator:	sfrahman
Referred To:	Not reported
Reported to Dept:	2007-03-02
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

TORES HOME (Continued) **S108466382**

Date Entered In Computer:	2007-03-02
Spill Record Last Update:	2007-03-14
Spiller Name:	MALLORY GILMORE
Spiller Company:	ON SIDEWALK
Spiller Address:	211 HULL STREET
Spiller Company:	001
Contact Name:	MALLORY GILMORE
DEC Memo:	"added to the drum run. 03/14/07 Rahman- Drums were not found on 03/13/07."
Remarks:	"3 - 55 gallon drums left on sidewalk: not leaking"

All Materials:

Site ID:	377908
Operable Unit ID:	1135425
Operable Unit:	01
Material ID:	2125332
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	TORES HOME
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0613303 / 2007-03-12
Facility ID:	0613303
Facility Type:	ER
DER Facility ID:	327460
Site ID:	378311
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2007-03-12
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2007-03-12
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-12
Spill Record Last Update:	2007-03-12
Spiller Name:	FERDIEAND TORES
Spiller Company:	TORES HOME
Spiller Address:	211 HULL STREET

TORES HOME (Continued) **S108466382**

Spiller Company: 001
Contact Name: FERDIEAND TORES
DEC Memo: "10 days ago line under the oil tank broke. Tank was loose and when the tank is filled, the tank moves. Oil gushed onto the basement floor. FD Haz Mat cleaned the spill. Line broke again. 6 family building - Oil Company on site now - Pacific Energy 718-647-1400 3/12/07 - Raphael Ketani. I spoke to Patrick Fahey, manager at Pacific Energy. He said his mechanic was on site now. He said that a flare nut connecting two pipes came loose a little and dripped oil onto the floor. He said that about 1 gal. dripped out. The flare nut has been tightened and this problem is solved. He said that a big spill happened weeks ago (#0612788)and was caused by a rotten equalizer (pipe connecting the 2 tanks). He said this pipe was repaired back then. Mr. Fahey said that the tanks are full and are holding the oil. As there is an earlier open spill case, I am closing this later case."
Remarks: "BOILER MALFUNCTION:"

All Materials:
Site ID: 378311
Operable Unit ID: 1135815
Operable Unit: 01
Material ID: 2125740
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

374
ENE
1/4-1/2
0.444 mi.
2346 ft.

OCEAN HILL -NYCHA
24 STONE AVENUE
BROOKLYN, NY

NY LTANKS **S102149171**
NY Spills **N/A**

Relative:
Higher

Actual:
85 ft.

LTANKS:
Name: OCEAN HILL -NYCHA
Address: 24 STONE AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9010234 / 2019-01-14
Facility ID: 9010234
Site ID: 171459
Spill Date: 1990-12-20
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: AAOBLIGA

OCEAN HILL -NYCHA (Continued) **S102149171**

Referred To:	CMTS SENT 10/14/16, 6 MNTH MONIT.[INVALID]DUE 5/1/
Reported to Dept:	1990-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-08
Spill Record Last Update:	2019-01-14
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	144292
DEC Memo:	"01/24/06: This spill transferred from J.Kolleeny to S.Kraszewski. - SK 03/14/06: This spill reassigned to K.Tang. - SK 01/15/08: spill reassigned to J.Kann. Consolidated with closed spill 0302414. J.Kann 4/10/13: J.Kann - IWP approved in an email (edoced). 4/26/13: J.Kann - revised IWP rcvd and edoced. 11/4/13: J.Kann - SAR is past due (due October 2013). stip sent to NYCHA today. Must be returned by December 4, 2013. 12/6/13: J.kann - signed stip rcvd from NYCHA on 12/4 and forwarded to legal for execution on 12/6/13 4/4/14: J.Kann - extention requests made by NYCHA's consultants due to poor weather and a damaged drill rig. Extension was approved on February 12 and then again on March 12. Report was submitted today, the approved extension date. Brief glance at the report shows some VOC and SVOC constituents in groundwater above CP-51 at one location. Closure request was made by NYCHA's consultant. Will need to further review the report before making a determination. 10/21/14: J.Kann - reviewing site. One well has elevated VOCs. Groundwater is at approx. 75 fbgs. Two wells were previously installed on site as part of another investigation. An email was sent to NYCHA on 10/21/14 requesting they try to locate the report related to the previous investigation. 10/30/14: J.Kann - spoke with NYCHA today. They never received information about the investigative work that Gannett Fleming had started at the site. Therefore, no additional info is available. 11/18/14: J.Kann - information from spill 0302414 indicates NYCHA CONTRACTOR GANNETT FLEMING DOING FOLLOW-UP SITE INVESTIGATION SINCE TANK CLOSURE FOUND SVOCs IN SOIL ABOVE TAGM. PUTTING IN WELL, SOIL CONTAMINATION ENCOUNTERED FROM 25 FEET DOWN TO WATER TABLE AT 75 FT., WITH PID=220 PPM AT 50 FT., THEN FIRST SPLIT SPOON BELOW WATER TABLE, PID=230 PPM. SOIL SAMPLES WERE COLLECTED FOR LAB ANALYSIS, AND GROUNDWATER SAMPLE WILL BE TAKEN AFTER WELL IS DEVELOPED. The tank closure report was reviewed (dated February 2000 and prepared by PT&L Contracting). Endpoints were not above CP-51. No VOCs were detected, some PAHs were detected below CP-51. The investigation performed by JCB is also under review. 12/10/14: J.Kann -email sent to Yelena today- I have read the Remedial Investigation Report (RIR) prepared by JC Broderick for the referenced site. Based on the review, the spill has not been closed and the Department has

OCEAN HILL -NYCHA (Continued) **S102149171**

the following comments: -Based on the site file, JCB notified the Department of difficulty encountered during the field investigation, resulting in approved modifications to the original work plan. None of this information is discussed and presented in the RIR. These details must be discussed in the RIR since borings were not advanced to the depths proposed in the original work plan. -The conclusions and recommendations section indicates that JCB suspects the contamination in the on site groundwater monitoring well is from another source, but a potential source is not identified. The Gannett Fleming work plan for the site dated 2003 indicates that based on historic Sanborn Maps a gasoline tank was present on this property until around 1962, or when Ocean Hill Houses were built. Why is the source assumed to be off-site? Please clarify and further discuss this in the RIR. -An additional round of groundwater samples must be collected from the three wells, analyzed for VOCs/SVOCs, summarized and submitted to the Department. Once these comments are addressed, additional investigative work may be necessary at this site. 6/4/15: J.Kann - Additional round of sampling performed at MW-1 and MW-2 in February 2015. Product thickness of .02 ft found in MW-5. Based on new information, an email was sent to NYCHA requesting a fingerprint analysis and installation of two additional wells. 10/14/16: J.kann - Additional investigative work was done including the advancement of 5 more borings. All soil samples collected were below CP-51. Three wells were sampled and MW-5 had minor elevated concentrations. This was the well with a small amount of product previously. The recommendation is to install a sock in MW-6 and sample in 6 months. NYCHA was emailed today indicating that should be done. 06/05/2017: J.Kann - Spill reassigned to Andre Obligado. 1/14/19 - Obligado - I reviewed the 3Q18 monitoring report prepared by H2M. No product was observed in any of the wells since 2015. During the most recent sampling round, data submitted in December 2017, all petroleum VOCs were detected at or below GWQS. H2M recommends spill closure. After review of the report, the DEC concurs that this spill does not appear to be a threat to human health or the environment. This spill is closed based on: 1) 235 tons of contaminated soil removed from the Site during tank closure in 2000. 2) Soil samples collected during well installation were all below CP51 3) No LNAPL present for 3 years 4) No petroleum VOCs above TOGS GWQS. Spill closed. . "

Remarks: "20K TANK SYSTEM FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL EXCAVATE, ISOLATE & RETEST."

All TTF:

Facility ID:	9010234
Spill Number:	9010234
Spill Tank Test:	1538069
Site ID:	171459
Tank Number:	001
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

OCEAN HILL -NYCHA (Continued) **S102149171**

Last Modified Date: Not reported

All Materials:

Site ID:	171459
Operable Unit ID:	947383
Operable Unit:	01
Material ID:	430396
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	OCEAN HILL HOUSES -NYCHA
Address:	24 STONE AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0302414 / 2008-01-15
Facility ID:	0302414
Facility Type:	ER
DER Facility ID:	144292
Site ID:	133799
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-06-06
Investigator:	jkkann
Referred To:	SPILL CONSOLIDATED WITH 9010234
Reported to Dept:	2003-06-06
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-06
Spill Record Last Update:	2008-01-15
Spiller Name:	CALLER
Spiller Company:	OCEAN HILL HOUSES
Spiller Address:	30 MOTHER GASTEN BLVD
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY NYCHA CONTRACTOR GANNETT FLEMING DOING FOLLOW-UP SITE INVESTIGATION SINCE TANK CLOSURE FOUND SVOCs IN SOIL ABOVE

OCEAN HILL -NYCHA (Continued) **S102149171**

TAGM. PUTTING IN WELL, SOIL CONTAMINATION ENCOUNTERED FROM 25 FEET DOWN TO WATER TABLE AT 75 FT.,
WITH PID=220 PPM AT 50 FT., THEN FIRST SPLIT SPOON BELOW WATER TABLE, PID=230 PPM. SOIL SAMPLES
WERE COLLECTED FOR LAB ANALYSIS, AND GROUNDWATER SAMPLE WILL BE TAKEN AFTER WELL IS DEVELOPED. 3
MORE WELLS AND 4 SOIL BORINGS WILL BE INSTALLED. - J.KOLLEENY 6/6/03
11/03/05: This spill
transferred from J.Kolleeny to S.Kraszewski. 07/07/06: NYCHA summary
report states that no recovery
system and no MWs on-site. The site assessment is available and NYCHA
recommends that the
Department review it. - SK 02/06/07 - J.Kann - site reassigned from S.
Kraszewski to J.Kann.
01/15/08 - J.kann - spill closed and consolidated with 9011619. "

Remarks: "site work found contaminated soil."

All Materials:

Site ID:	133799
Operable Unit ID:	869251
Operable Unit:	01
Material ID:	506891
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	OCEAN HILL HOUSES -NYCHA
Address:	24 STONE AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9412305 / 1994-12-15
Facility ID:	9412305
Facility Type:	ER
DER Facility ID:	144292
Site ID:	261115
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	1994-12-14
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1994-12-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-12-15
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

OCEAN HILL -NYCHA (Continued) **S102149171**

Remediation Phase:	0
Date Entered In Computer:	1994-12-15
Spill Record Last Update:	2006-01-24
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"KNOCKED OVER FIVE GALLON BUCKET. ABSORBENT USED TO CLEAN UP."

All TTF:

Facility ID:	9412305
Spill Number:	9412305
Spill Tank Test:	1543451
Site ID:	261115
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	261115
Operable Unit ID:	1005996
Operable Unit:	01
Material ID:	564283
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

375
SW
1/4-1/2
0.451 mi.
2379 ft.

1625 PROSPECT PLACE
1625 PROSPECT PL
NEW YORK CITY, NY

NY VCP **S128943784**
N/A

Relative:
Higher

Actual:
94 ft.

VCP NYC:

Project ID:	21TMP0398K,22CVCP064K
Name:	1625 PROSPECT PLACE
Address:	1625 PROSPECT PL
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn

1625 PROSPECT PLACE (Continued) **S128943784**

BBL:	3013630060
OER Program:	VCP (Enrolled)
Phase:	Approved Remedial Plan
Latitude:	40.672836
Longitude:	-73.922893
Postcode:	8
Community Board:	41
Council District:	359
Census Tract:	3000000
BIN:	3013630060
NTA:	Crown Heights North

---

376 **NYCHA TRIBOROUGH PRESERVATION** **NY LTANKS** **U001840695**
North **930 HALSEY STREET (AKA 55 SARATOGA AVENUE)** **NY UST** **N/A**
1/4-1/2 **BROOKLYN, NY 11233** **NY Spills**
0.470 mi.
2479 ft.

Relative:
Lower

Actual:
38 ft.

LTANKS:

Name:	SARATOGA SQUARE APTS -NYCHA
Address:	930 HALSEY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9801627 / 2002-08-16
Facility ID:	9801627
Site ID:	181894
Spill Date:	1998-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1998-05-08
CID:	370
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-08
Spill Record Last Update:	2005-01-21
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	FRANK OCELLO
Spiller Phone:	(212) 306-3229
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	152511
DEC Memo:	""
Remarks:	"Tank test failure, will isolate and retest."

All TTF:

Facility ID:	9801627

NYCHA TRIBOROUGH PRESERVATION (Continued) **U001840695**

Spill Number:	9801627
Spill Tank Test:	1545875
Site ID:	181894
Tank Number:	1
Tank Size:	15000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	181894
Operable Unit ID:	1059521
Operable Unit:	01
Material ID:	323554
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

UST:

Name:	NYCHA TRIBOROUGH PRESERVATION
Address:	930 HALSEY STREET (AKA 55 SARATOGA AVENUE)
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-474266 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	591580.93735
UTM Y:	4504378.23904
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	20895
Affiliation Type:	Facility Operator
Company Name:	NYCHA TRIBOROUGH PRESERVATION
Contact Type:	Not reported
Contact Name:	C&C APARTMENT MANAGEMENT LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

NYCHA TRIBOROUGH PRESERVATION (Continued) **U001840695**

Country Code:	001
Phone:	(212) 348-3248
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-18

Site Id:	20895
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	STUART SCHWARTZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(631) 691-1700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-18

Site Id:	20895
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	23-02 49TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(914) 727-2156
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-18

Site Id:	20895
Affiliation Type:	Mail Contact
Company Name:	TRIBOROUGH PRESERVATION LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1865 PALMER AVENUE, SUITE 203
Address2:	Not reported
City:	LARCHMONT
State:	NY
Zip Code:	10538
Country Code:	001
Phone:	(914) 833-3000
EMail:	CZUK@LMDEVPARTNERS.COM
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-18

NYCHA TRIBOROUGH PRESERVATION (Continued) **U001840695**

Tank Info:

Tank Number:	1
Tank ID:	37633
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	15000
Install Date:	11/01/1980
Date Tank Closed:	02/25/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	03/04/2013
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

SPILLS:

Name:	NYC HOUSING AUTHORITY - NYCHA
Address:	930 HALSEY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0004890 / 2005-12-02
Facility ID:	0004890
Facility Type:	ER
DER Facility ID:	152511
Site ID:	199529
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2000-07-24
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	2000-07-24
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons

NYCHA TRIBOROUGH PRESERVATION (Continued) **U001840695**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-24
Spill Record Last Update:	2005-12-02
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTH '
Spiller Address:	33-35 SARATOGA VAE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"12/01/05: This spill transferred from J.Kolleeny to S.Kraszewski. Reviewed ISRP prepared by Gannett Flemingin 2003 and submitted May 2005. GF performed 8 soil borings and converted 4 of them into MWs. 7 of the soil samples came from the UST area and the remaining sample from the fill port. Soil samples were taken from all 8 borings and GW samples were taken from the wells. All samples were analyzed for PAHs, SVOCS and VOCs. B-1 was the only soil sample with contamination, however, this sample site is located up-gradient and Easterly from the former UST site: unrelated occurance. No GW contamination in any of the MWs. GF also included the site assessment results from the tank pull performed by ESPL in 2000. Eight end point samples taken revealed only 5 with contamination above RSCOs. Reevaluation of the site by GF was due to construction of a facility within the vacinity of the UST. Recommend closure. Asked Jon for his input: he agrees with closure. NFA letter written and sent to Brian Clarke at NYCHA. - SK"
Remarks:	"caller removed a tank at the above location soil samples were taken and lab results returned today above limits"

All Materials:

Site ID:	199529
Operable Unit ID:	827315
Operable Unit:	01
Material ID:	571880
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SARATOGA SQUARE HOUSES -NYCHA
Address:	930 HALSEY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9913865 / 2003-01-07
Facility ID:	9913865

NYCHA TRIBOROUGH PRESERVATION (Continued) **U001840695**

Facility Type:	ER
DER Facility ID:	152511
Site ID:	129282
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-03-08
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	2000-03-08
CID:	389
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-03-08
Spill Record Last Update:	2005-12-01
Spiller Name:	EDWARD MALONE
Spiller Company:	NEW YORK CITY HOUSING AUT
Spiller Address:	123 WILLIAMS
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"Bottom bar is missing from a joint, causing a leak and wear on the pipes causing a stain on the ground. A boom has been placed and plumbers are going to the site tomorrow. No callback necessary."

All Materials:

Site ID:	129282
Operable Unit ID:	1092225
Operable Unit:	01
Material ID:	292152
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

377
South
1/4-1/2
0.470 mi.
2480 ft.

GAS STATION
1850 PARK PLACE
BROOKLYN, NY

NY LTANKS **S107410529**
N/A

Relative:
Lower

Actual:
71 ft.

LTANKS:

Name:	GAS STATION
Address:	1850 PARK PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0507177 / 2006-02-14
Facility ID:	0507177
Site ID:	352527
Spill Date:	2005-09-07
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2005-09-14
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-09-14
Spill Record Last Update:	2006-02-14
Spiller Name:	K J LLC
Spiller Company:	GAS STATION
Spiller Address:	1850 PARK PLACE
Spiller County:	001
Spiller Contact:	K J LLC
Spiller Phone:	(718) 206-0550
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	299826
DEC Memo:	"This case stays with Jie Zhao until excavation work is complete and report showing clean endpoints is submitted. If the report shows additional contamination, THEN the case is transferred to the DEC Remediation group (Koon Tang) 2/8/2006 - JZ: As per Randy's direction, the spill is transferred to Mr. Patel to follow up. 02/14/06-Hiralkumar Patel. Received report from HydroTech Environmental Corp. Abstract of report: - HTE excavated, removed and disposed of four 550-gal and two 275-gal UST. - original scope of work involved the removal of three 1000-gal UST; upon teh commencement of field work it was discovered the tanks acutally included four 550-gal and two 275-gal UST. - upon removal of top concrete layer, each tank and all exposed piping was found to contain oily water. - total of 3,900 gal. of liquid was removed from tanks and disposed of. - olfactory evidence of petroleum contamination and elevated PID readings (>250 ppm) were encountered on top of the tanks. - contaminated soil was placed on top of polyethylene sheeting in the eastern portion of site. - final excavation was approximately 30 feet long, 25 feet wide and ranged in depth from 8 to 10 feet. -

GAS STATION (Continued) **S107410529**

no evidence of groundwater was observed to enter the excavation. - end point samples taken and analysed for method 8021 & 8270. - results shows, the compounds m&p-Xylene and 1,3,5-trimethylbeneze were detected in the bottom sample (PE-6) at concentrations exceeding limit. - no VOCs and SVOCs were identified in the remaining samples (EP-1 to EP-5) at concentrations exceeding their respective TAGM#4046 standard. - due to results of EP-6, more excavation done until no visual/no olfactory evidence of petroleum was noted and no organic vapors were detected. - final depth of excavation was 15 feet. End point samples EP-7 & EP-8 did not showed any VOCs and SVOCs. Report consists waste disposal manifest, metal disposal tickets, lab results from York Analytical Laboratories, Inc. Because end point sample are clean, no further action required. case closed."

Remarks: "4 Tank removals, Tank sizes 550 gallons, sampling also shows contamination"

All Materials:

Site ID:	352527
Operable Unit ID:	1110022
Operable Unit:	01
Material ID:	2100040
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

378
SW
1/4-1/2
0.477 mi.
2520 ft.

MILLER HOME
154 BUFFALO AVE
BROOKLYN, NY

NY LTANKS **S106971820**
NY Spills **N/A**

Relative:
Higher

Actual:
83 ft.

LTANKS:

Name:	MILLER HOME
Address:	154 BUFFALO AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0501857 / 2005-09-28
Facility ID:	0501857
Site ID:	346085
Spill Date:	2005-05-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	2005-05-16
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

MILLER HOME (Continued) **S106971820**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-16
Spill Record Last Update:	2005-09-28
Spiller Name:	LEROY MILLER
Spiller Company:	MILLER HOME
Spiller Address:	154 BUFFALO AVE
Spiller County:	001
Spiller Contact:	LEROY MILLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	292310
DEC Memo:	"Spill is duplicate to spill #0501834 Site visit may be required."
Remarks:	"IN BASEMENT OF HOUSE AND THEY HAVE TWO DRUMS, 85 GALLON AND 55 GALLON IN BASEMENT FROM CLEANING UP;"

All Materials:

Site ID:	346085
Operable Unit ID:	1103819
Operable Unit:	01
Material ID:	584016
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	VACANT BUILDING
Address:	154 BUFFALO AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0501834 / 2005-09-28
Facility ID:	0501834
Facility Type:	ER
DER Facility ID:	292310
Site ID:	346061
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-05-15
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	2005-05-15
CID:	27
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported

MILLER HOME (Continued) **S106971820**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-16
Spill Record Last Update:	2005-09-28
Spiller Name:	Not reported
Spiller Company:	VACANT BUILDING
Spiller Address:	154 BUFFALO AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"Caller reports a broken water pipe flooded the basement and tipped over the fuel oil tank. FDNY is on scene pumping out the water and oil and containing it. Unknown who owns the vacant building at this time."

All Materials:

Site ID:	346061
Operable Unit ID:	1103794
Operable Unit:	01
Material ID:	583992
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

379
ESE
1/4-1/2
0.481 mi.
2542 ft.

1860 EASTERN PARKWAY **NY VCP** **S125316888**
1860 EASTERN PARKWAY **N/A**
NEW YORK CITY, NY

Relative:
Lower

Actual:
76 ft.

VCP NYC:

Project ID:	17TMP0413K,18EH-N003K,18CVCP020K
Name:	1860 EASTERN PARKWAY
Address:	1860 EASTERN PARKWAY
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3014360006
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.675822
Longitude:	-73.908126
Postcode:	16
Community Board:	37
Council District:	36502
Census Tract:	3337899
BIN:	3014360006
NTA:	Ocean Hill

380 SSW 1/4-1/2 0.489 mi. 2583 ft. | **DCA 1 APARTMENTS**
495 HOWARD AVENUE
BROOKLYN, NY 11233 | **NY ENG CONTROLS**
NY INST CONTROL
NY BROWNFIELDS
NY LEAD | **S113913741**
N/A

Relative: Higher

Actual: 82 ft.

ENG CONTROLS:

Name:	DCA 1 APARTMENTS
Address:	495 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Site Code:	466073
HW Code:	C224162
Control Code:	15
Control Type:	ENG
Date Record Added:	06/01/2016
Date Rec Updated:	06/04/2021
Updated By:	MLSWEET
Site Description:	Location: The site is a rectangular area of 818 square feet located in the southwest corner of Brooklyn Block 1467, Lot 1. The address is 495 Howard Avenue, aka 485 Howard Avenue, in the East New York section of Brooklyn at the intersection of Howard Avenue and Sterling Place. The site is the location of a former dry cleaning building. The site is a small portion of Block 1467, Lot 1. Site Features: The site is currently paved. The remedial action consisted of a cover system. This cover system is comprised of the pavement or sidewalks comprising the site development, and a system of porous pavers and tree grates over the previously uncapped portion of the site. The site is part of a larger residential development consisting of 9 buildings, an asphalt parking lot, landscaped areas and a former playground. Current Zoning and Land Use: The site is zoned R6 for residential use with a commercial overlay of C1-3 and is used as a walking area near the restricted residential development. Historic Use: A dry-cleaning operation had been identified in a formerly existing building on this site in the 1960s. Site Geology and Hydrogeology: The site soil consists of historic fill from grade to approximately 7 feet below ground surface (bgs), glacial till consisting of dense sand, silt, gravel, and cobbles from approximately 7 to 54 ft bgs, and medium to fine grained sand from approximately 54 to 60 ft bgs. The regional groundwater aquifer is likely within the medium to fine grained sand formation. Perched groundwater was encountered at approximately 13 feet bgs. The regional groundwater table was encountered at a depth of 55 feet bgs and was found in a permeable sand formation. Above this depth, several intervals of moist to wet soil were observed. Groundwater flow direction is to the southeast.
Env Problem:	Nature and Extent of Contamination: Prior to Remediation: Soil - No volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) pesticides, herbicides or polychlorinated biphenyls (PCBs) were identified in the soil samples collected during the remedial investigation exceeding restricted residential soil cleanup objectives (RRSCOs). Metals exceeding RRSCOs were limited to the shallow samples collected within the historic fill layer. Detections of PCE were all below the unrestricted use soil cleanup objective (UUSCO) of 1.3 parts per million (ppm). Metals exceeding the RRSCOs were limited to barium in the shallow samples collected from borings in the historic fill layer from 5 to 7 feet bgs. The samples exceeding the RRSCO (350 ppm) were all within the same order of magnitude at concentrations up to 774 ppm. Site related soil contamination does not appear to extend off-site. Groundwater - There

DCA 1 APARTMENTS (Continued) **S113913741**

were no samples exceeding the groundwater standards for SVOCs, pesticides, PCBs or herbicides. Samples exceeding the groundwater standards for VOCs were primarily limited to PCE, which was detected in each of the monitoring wells sampled and was detected above the groundwater standards in seven of the eleven monitoring wells. Detections above the standard ranged from 7 parts per billion (ppb) to 71 ppb in onsite monitoring wells as compared to the groundwater standard of 5 ppb. Three of the seven monitoring wells with detections of PCE above the groundwater standards were identified in upgradient offsite monitoring well clusters. PCE was detected in each of the five upgradient wells sampled, with concentrations ranging up to 31 ppb. No onsite source of groundwater contamination has been identified and it appears that the VOCs found in the groundwater both on and offsite are due to an upgradient offsite source. Total metals exceeding the groundwater standards were identified in each of the monitoring wells sampled. The compounds exceeding the groundwater standards included chromium at 273 ppb. These compounds appear to be naturally occurring. Soil vapor - Elevated concentrations of PCE were detected in soil vapor at 3 of 4 soil vapor points at concentrations ranging from 278 micrograms per cubic meter (ug/m3) to 4,207 ug/m3. Trichloroethylene (TCE) a breakdown product of PCE was also detected in soil vapor at a maximum concentration of 69.9 ug/m3. No on-site source of soil vapor was identified. Post-Remediation Remediation at the site is complete. Prior to remediation, the contaminants of concern were tetrachloroethene (PCE), trichloroethene (TCE), chromium and barium in soil and groundwater. The selected remedy, a site cover system, has been installed. Remaining contamination is being managed under a Site Management Plan.

Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-07-05 14:19:00
Record Upd:	2016-06-03 11:10:00
Updated By:	NNCRAWFO
Own Op:	1
Sub Type:	NNN
Owner Name:	Paul Shevchuk
Owner Company:	DCA 1, L.P.
Owner Address:	885 Second Ave
Owner Addr2:	Floor 31
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library--Brownsville Branch
Owner Address:	61 Glenmore Avenue
Owner Addr2:	Not reported

DCA 1 APARTMENTS (Continued) **S113913741**

Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Paul Shevchuk
Owner Company:	DCA 1, L.P.
Owner Address:	Omni New York LLC
Owner Addr2:	885 Second Avenue, Floor 31
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	C224162
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2016000296357
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-08-31 09:48:00
Record Updated:	2016-08-31 09:48:00
Updated By:	NNCRAWFO
Crossref ID:	C224162-09-12
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-06-01 12:47:00
Record Updated:	2016-06-01 12:47:00
Updated By:	NNCRAWFO

INST CONTROL:

Name:	DCA 1 APARTMENTS
Address:	495 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Site Code:	466073
Control Name:	Environmental Easement
HW Code:	C224162
Control Code:	J
Control Type:	INST
Dt record added:	06/01/2016
Dt rec updated:	06/04/2021
Updated By:	MLSWEET
Site Code:	466073
Site Description:	Location: The site is a rectangular area of 818 square feet located

DCA 1 APARTMENTS (Continued) **S113913741**

in the southwest corner of Brooklyn Block 1467, Lot 1. The address is 495 Howard Avenue, aka 485 Howard Avenue, in the East New York section of Brooklyn at the intersection of Howard Avenue and Sterling Place. The site is the location of a former dry cleaning building. The site is a small portion of Block 1467, Lot 1. Site Features: The site is currently paved. The remedial action consisted of a cover system. This cover system is comprised of the pavement or sidewalks comprising the site development, and a system of porous pavers and tree grates over the previously uncapped portion of the site. The site is part of a larger residential development consisting of 9 buildings, an asphalt parking lot, landscaped areas and a former playground. Current Zoning and Land Use: The site is zoned R6 for residential use with a commercial overlay of C1-3 and is used as a walking area near the restricted residential development. Historic Use: A dry-cleaning operation had been identified in a formerly existing building on this site in the 1960s. Site Geology and Hydrogeology: The site soil consists of historic fill from grade to approximately 7 feet below ground surface (bgs), glacial till consisting of dense sand, silt, gravel, and cobbles from approximately 7 to 54 ft bgs, and medium to fine grained sand from approximately 54 to 60 ft bgs. The regional groundwater aquifer is likely within the medium to fine grained sand formation. Perched groundwater was encountered at approximately 13 feet bgs. The regional groundwater table was encountered at a depth of 55 feet bgs and was found in a permeable sand formation. Above this depth, several intervals of moist to wet soil were observed. Groundwater flow direction is to the southeast.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Soil - No volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) pesticides, herbicides or polychlorinated biphenyls (PCBs) were identified in the soil samples collected during the remedial investigation exceeding restricted residential soil cleanup objectives (RRSCOs). Metals exceeding RRSCOs were limited to the shallow samples collected within the historic fill layer. Detections of PCE were all below the unrestricted use soil cleanup objective (UUSCO) of 1.3 parts per million (ppm). Metals exceeding the RRSCOs were limited to barium in the shallow samples collected from borings in the historic fill layer from 5 to 7 feet bgs. The samples exceeding the RRSCO (350 ppm) were all within the same order of magnitude at concentrations up to 774 ppm. Site related soil contamination does not appear to extend off-site. Groundwater - There were no samples exceeding the groundwater standards for SVOCs, pesticides, PCBs or herbicides. Samples exceeding the groundwater standards for VOCs were primarily limited to PCE, which was detected in each of the monitoring wells sampled and was detected above the groundwater standards in seven of the eleven monitoring wells. Detections above the standard ranged from 7 parts per billion (ppb) to 71 ppb in onsite monitoring wells as compared to the groundwater standard of 5 ppb. Three of the seven monitoring wells with detections of PCE above the groundwater standards were identified in upgradient offsite monitoring well clusters. PCE was detected in each of the five upgradient wells sampled, with concentrations ranging up to 31 ppb. No onsite source of groundwater contamination has been identified and it appears that the VOCs found in the groundwater both on and offsite are due to an upgradient offsite source. Total metals exceeding the groundwater standards were identified in each of the monitoring wells sampled. The compounds exceeding the groundwater

DCA 1 APARTMENTS (Continued) **S113913741**

	standards included chromium at 273 ppb. These compounds appear to be naturally occurring. Soil vapor - Elevated concentrations of PCE were detected in soil vapor at 3 of 4 soil vapor points at concentrations ranging from 278 micrograms per cubic meter (ug/m3) to 4,207 ug/m3. Trichloroethylene (TCE) a breakdown product of PCE was also detected in soil vapor at a maximum concentration of 69.9 ug/m3. No on-site source of soil vapor was identified. Post-Remediation Remediation at the site is complete. Prior to remediation, the contaminants of concern were tetrachloroethene (PCE), trichloroethene (TCE), chromium and barium in soil and groundwater. The selected remedy, a site cover system, has been installed. Remaining contamination is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-07-05 14:19:00
Record Upd:	2016-06-03 11:10:00
Updated By:	NNCRAWFO
Own Op:	1
Sub Type:	NNN
Owner Name:	Paul Shevchuk
Owner Company:	DCA 1, L.P.
Owner Address:	885 Second Ave
Owner Addr2:	Floor 31
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library--Brownsville Branch
Owner Address:	61 Glenmore Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Paul Shevchuk
Owner Company:	DCA 1, L.P.
Owner Address:	Omni New York LLC
Owner Addr2:	885 Second Avenue, Floor 31
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	C224162
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	TETRACHLOROETHYLENE (PCE)

DCA 1 APARTMENTS (Continued) **S113913741**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2016000296357
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-08-31 09:48:00
Record Updated: 2016-08-31 09:48:00
Updated By: NNCRAWFO
Crossref ID: C224162-09-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-06-01 12:47:00
Record Updated: 2016-06-01 12:47:00
Updated By: NNCRAWFO

Name: DCA 1 APARTMENTS
Address: 495 HOWARD AVENUE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 466073
Control Name: Site Management Plan
HW Code: C224162
Control Code: 32
Control Type: INST
Dt record added: 06/01/2016
Dt rec updated: 06/04/2021
Updated By: MLSWEET
Site Code: 466073
Site Description: Location: The site is a rectangular area of 818 square feet located in the southwest corner of Brooklyn Block 1467, Lot 1. The address is 495 Howard Avenue, aka 485 Howard Avenue, in the East New York section of Brooklyn at the intersection of Howard Avenue and Sterling Place. The site is the location of a former dry cleaning building. The site is a small portion of Block 1467, Lot 1. Site Features: The site is currently paved. The remedial action consisted of a cover system. This cover system is comprised of the pavement or sidewalks comprising the site development, and a system of porous pavers and tree grates over the previously uncapped portion of the site. The site is part of a larger residential development consisting of 9 buildings, an asphalt parking lot, landscaped areas and a former playground. Current Zoning and Land Use: The site is zoned R6 for residential use with a commercial overlay of C1-3 and is used as a walking area near the restricted residential development. Historic Use: A dry-cleaning operation had been identified in a formerly existing building on this site in the 1960s. Site Geology and Hydrogeology: The site soil consists of historic fill from grade to

DCA 1 APARTMENTS (Continued) **S113913741**

approximately 7 feet below ground surface (bgs), glacial till consisting of dense sand, silt, gravel, and cobbles from approximately 7 to 54 ft bgs, and medium to fine grained sand from approximately 54 to 60 ft bgs. The regional groundwater aquifer is likely within the medium to fine grained sand formation. Perched groundwater was encountered at approximately 13 feet bgs. The regional groundwater table was encountered at a depth of 55 feet bgs and was found in a permeable sand formation. Above this depth, several intervals of moist to wet soil were observed. Groundwater flow direction is to the southeast.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Soil - No volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) pesticides, herbicides or polychlorinated biphenyls (PCBs) were identified in the soil samples collected during the remedial investigation exceeding restricted residential soil cleanup objectives (RRSCOs). Metals exceeding RRSCOs were limited to the shallow samples collected within the historic fill layer. Detections of PCE were all below the unrestricted use soil cleanup objective (UUSCO) of 1.3 parts per million (ppm). Metals exceeding the RRSCOs were limited to barium in the shallow samples collected from borings in the historic fill layer from 5 to 7 feet bgs. The samples exceeding the RRSCO (350 ppm) were all within the same order of magnitude at concentrations up to 774 ppm. Site related soil contamination does not appear to extend off-site. Groundwater - There were no samples exceeding the groundwater standards for SVOCs, pesticides, PCBs or herbicides. Samples exceeding the groundwater standards for VOCs were primarily limited to PCE, which was detected in each of the monitoring wells sampled and was detected above the groundwater standards in seven of the eleven monitoring wells. Detections above the standard ranged from 7 parts per billion (ppb) to 71 ppb in onsite monitoring wells as compared to the groundwater standard of 5 ppb. Three of the seven monitoring wells with detections of PCE above the groundwater standards were identified in upgradient offsite monitoring well clusters. PCE was detected in each of the five upgradient wells sampled, with concentrations ranging up to 31 ppb. No onsite source of groundwater contamination has been identified and it appears that the VOCs found in the groundwater both on and offsite are due to an upgradient offsite source. Total metals exceeding the groundwater standards were identified in each of the monitoring wells sampled. The compounds exceeding the groundwater standards included chromium at 273 ppb. These compounds appear to be naturally occurring. Soil vapor - Elevated concentrations of PCE were detected in soil vapor at 3 of 4 soil vapor points at concentrations ranging from 278 micrograms per cubic meter (ug/m3) to 4,207 ug/m3. Trichloroethylene (TCE) a breakdown product of PCE was also detected in soil vapor at a maximum concentration of 69.9 ug/m3. No on-site source of soil vapor was identified. Post-Remediation Remediation at the site is complete. Prior to remediation, the contaminants of concern were tetrachloroethene (PCE), trichloroethene (TCE), chromium and barium in soil and groundwater. The selected remedy, a site cover system, has been installed. Remaining contamination is being managed under a Site Management Plan.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site.

Dump: False

Structure: False

DCA 1 APARTMENTS (Continued) **S113913741**

Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-05 14:19:00
Record Upd: 2016-06-03 11:10:00
Updated By: NNCRAWFO
Own Op: 1
Sub Type: NNN
Owner Name: Paul Shevchuk
Owner Company: DCA 1, L.P.
Owner Address: 885 Second Ave
Owner Addr2: Floor 31
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library--Brownsville Branch
Owner Address: 61 Glenmore Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11212
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Paul Shevchuk
Owner Company: DCA 1, L.P.
Owner Address: Omni New York LLC
Owner Addr2: 885 Second Avenue, Floor 31
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: C224162
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2016000296357
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

DCA 1 APARTMENTS (Continued) **S113913741**

Record Added Date: 2016-08-31 09:48:00
Record Updated: 2016-08-31 09:48:00
Updated By: NNCRAWFO
Crossref ID: C224162-09-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-06-01 12:47:00
Record Updated: 2016-06-01 12:47:00
Updated By: NNCRAWFO

Name: DCA 1 APARTMENTS
Address: 495 HOWARD AVENUE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 466073
Control Name: IC/EC Plan
HW Code: C224162
Control Code: 34
Control Type: INST
Dt record added: 06/01/2016
Dt rec updated: 06/04/2021
Updated By: MLSWEET
Site Code: 466073
Site Description: Location: The site is a rectangular area of 818 square feet located in the southwest corner of Brooklyn Block 1467, Lot 1. The address is 495 Howard Avenue, aka 485 Howard Avenue, in the East New York section of Brooklyn at the intersection of Howard Avenue and Sterling Place. The site is the location of a former dry cleaning building. The site is a small portion of Block 1467, Lot 1. Site Features: The site is currently paved. The remedial action consisted of a cover system. This cover system is comprised of the pavement or sidewalks comprising the site development, and a system of porous pavers and tree grates over the previously uncapped portion of the site. The site is part of a larger residential development consisting of 9 buildings, an asphalt parking lot, landscaped areas and a former playground. Current Zoning and Land Use: The site is zoned R6 for residential use with a commercial overlay of C1-3 and is used as a walking area near the restricted residential development. Historic Use: A dry-cleaning operation had been identified in a formerly existing building on this site in the 1960s. Site Geology and Hydrogeology: The site soil consists of historic fill from grade to approximately 7 feet below ground surface (bgs), glacial till consisting of dense sand, silt, gravel, and cobbles from approximately 7 to 54 ft bgs, and medium to fine grained sand from approximately 54 to 60 ft bgs. The regional groundwater aquifer is likely within the medium to fine grained sand formation. Perched groundwater was encountered at approximately 13 feet bgs. The regional groundwater table was encountered at a depth of 55 feet bgs and was found in a permeable sand formation. Above this depth, several intervals of moist to wet soil were observed. Groundwater flow direction is to the southeast.
Env Problem: Nature and Extent of Contamination: Prior to Remediation: Soil - No volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) pesticides, herbicides or polychlorinated biphenyls (PCBs) were identified in the soil samples collected during the remedial investigation exceeding restricted residential soil cleanup objectives (RRSCOs). Metals exceeding RRSCOs were limited to the shallow samples collected within the historic fill layer. Detections

DCA 1 APARTMENTS (Continued) **S113913741**

of PCE were all below the unrestricted use soil cleanup objective (UUSCO) of 1.3 parts per million (ppm). Metals exceeding the RRSCOs were limited to barium in the shallow samples collected from borings in the historic fill layer from 5 to 7 feet bgs. The samples exceeding the RRSCO (350 ppm) were all within the same order of magnitude at concentrations up to 774 ppm. Site related soil contamination does not appear to extend off-site. Groundwater - There were no samples exceeding the groundwater standards for SVOCs, pesticides, PCBs or herbicides. Samples exceeding the groundwater standards for VOCs were primarily limited to PCE, which was detected in each of the monitoring wells sampled and was detected above the groundwater standards in seven of the eleven monitoring wells. Detections above the standard ranged from 7 parts per billion (ppb) to 71 ppb in onsite monitoring wells as compared to the groundwater standard of 5 ppb. Three of the seven monitoring wells with detections of PCE above the groundwater standards were identified in upgradient offsite monitoring well clusters. PCE was detected in each of the five upgradient wells sampled, with concentrations ranging up to 31 ppb. No onsite source of groundwater contamination has been identified and it appears that the VOCs found in the groundwater both on and offsite are due to an upgradient offsite source. Total metals exceeding the groundwater standards were identified in each of the monitoring wells sampled. The compounds exceeding the groundwater standards included chromium at 273 ppb. These compounds appear to be naturally occurring. Soil vapor - Elevated concentrations of PCE were detected in soil vapor at 3 of 4 soil vapor points at concentrations ranging from 278 micrograms per cubic meter (ug/m3) to 4,207 ug/m3. Trichloroethylene (TCE) a breakdown product of PCE was also detected in soil vapor at a maximum concentration of 69.9 ug/m3. No on-site source of soil vapor was identified. Post-Remediation Remediation at the site is complete. Prior to remediation, the contaminants of concern were tetrachloroethene (PCE), trichloroethene (TCE), chromium and barium in soil and groundwater. The selected remedy, a site cover system, has been installed. Remaining contamination is being managed under a Site Management Plan.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-05 14:19:00
Record Upd: 2016-06-03 11:10:00
Updated By: NNCRAWFO
Own Op: 1
Sub Type: NNN
Owner Name: Paul Shevchuk
Owner Company: DCA 1, L.P.
Owner Address: 885 Second Ave
Owner Addr2: Floor 31
Owner City,St,Zip: New York, NY 10017

DCA 1 APARTMENTS (Continued) **S113913741**

Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library--Brownsville Branch
Owner Address: 61 Glenmore Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11212
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Paul Shevchuk
Owner Company: DCA 1, L.P.
Owner Address: Omni New York LLC
Owner Addr2: 885 Second Avenue, Floor 31
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: C224162
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2016000296357
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-08-31 09:48:00
Record Updated: 2016-08-31 09:48:00
Updated By: NNCRAWFO
Crossref ID: C224162-09-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-06-01 12:47:00
Record Updated: 2016-06-01 12:47:00
Updated By: NNCRAWFO

Name: DCA 1 APARTMENTS
Address: 495 HOWARD AVENUE
City,State,Zip: BROOKLYN, NY 11233
Site Code: 466073
Control Name: Monitoring Plan
HW Code: C224162
Control Code: 31

DCA 1 APARTMENTS (Continued) **S113913741**

Control Type: INST
Dt record added: 06/01/2016
Dt rec updated: 06/04/2021
Updated By: MLSWEET
Site Code: 466073
Site Description: Location: The site is a rectangular area of 818 square feet located in the southwest corner of Brooklyn Block 1467, Lot 1. The address is 495 Howard Avenue, aka 485 Howard Avenue, in the East New York section of Brooklyn at the intersection of Howard Avenue and Sterling Place. The site is the location of a former dry cleaning building. The site is a small portion of Block 1467, Lot 1. Site Features: The site is currently paved. The remedial action consisted of a cover system. This cover system is comprised of the pavement or sidewalks comprising the site development, and a system of porous pavers and tree grates over the previously uncapped portion of the site. The site is part of a larger residential development consisting of 9 buildings, an asphalt parking lot, landscaped areas and a former playground. Current Zoning and Land Use: The site is zoned R6 for residential use with a commercial overlay of C1-3 and is used as a walking area near the restricted residential development. Historic Use: A dry-cleaning operation had been identified in a formerly existing building on this site in the 1960s. Site Geology and Hydrogeology: The site soil consists of historic fill from grade to approximately 7 feet below ground surface (bgs), glacial till consisting of dense sand, silt, gravel, and cobbles from approximately 7 to 54 ft bgs, and medium to fine grained sand from approximately 54 to 60 ft bgs. The regional groundwater aquifer is likely within the medium to fine grained sand formation. Perched groundwater was encountered at approximately 13 feet bgs. The regional groundwater table was encountered at a depth of 55 feet bgs and was found in a permeable sand formation. Above this depth, several intervals of moist to wet soil were observed. Groundwater flow direction is to the southeast.
Env Problem: Nature and Extent of Contamination: Prior to Remediation: Soil - No volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) pesticides, herbicides or polychlorinated biphenyls (PCBs) were identified in the soil samples collected during the remedial investigation exceeding restricted residential soil cleanup objectives (RRSCOs). Metals exceeding RRSCOs were limited to the shallow samples collected within the historic fill layer. Detections of PCE were all below the unrestricted use soil cleanup objective (UUSCO) of 1.3 parts per million (ppm). Metals exceeding the RRSCOs were limited to barium in the shallow samples collected from borings in the historic fill layer from 5 to 7 feet bgs. The samples exceeding the RRSCO (350 ppm) were all within the same order of magnitude at concentrations up to 774 ppm. Site related soil contamination does not appear to extend off-site. Groundwater - There were no samples exceeding the groundwater standards for SVOCs, pesticides, PCBs or herbicides. Samples exceeding the groundwater standards for VOCs were primarily limited to PCE, which was detected in each of the monitoring wells sampled and was detected above the groundwater standards in seven of the eleven monitoring wells. Detections above the standard ranged from 7 parts per billion (ppb) to 71 ppb in onsite monitoring wells as compared to the groundwater standard of 5 ppb. Three of the seven monitoring wells with detections of PCE above the groundwater standards were identified in upgradient offsite monitoring well clusters. PCE was detected in each

DCA 1 APARTMENTS (Continued) **S113913741**

of the five upgradient wells sampled, with concentrations ranging up to 31 ppb. No onsite source of groundwater contamination has been identified and it appears that the VOCs found in the groundwater both on and offsite are due to an upgradient offsite source. Total metals exceeding the groundwater standards were identified in each of the monitoring wells sampled. The compounds exceeding the groundwater standards included chromium at 273 ppb. These compounds appear to be naturally occurring. Soil vapor - Elevated concentrations of PCE were detected in soil vapor at 3 of 4 soil vapor points at concentrations ranging from 278 micrograms per cubic meter (ug/m3) to 4,207 ug/m3. Trichloroethylene (TCE) a breakdown product of PCE was also detected in soil vapor at a maximum concentration of 69.9 ug/m3. No on-site source of soil vapor was identified. Post-Remediation Remediation at the site is complete. Prior to remediation, the contaminants of concern were tetrachloroethene (PCE), trichloroethene (TCE), chromium and barium in soil and groundwater. The selected remedy, a site cover system, has been installed. Remaining contamination is being managed under a Site Management Plan.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-07-05 14:19:00
Record Upd: 2016-06-03 11:10:00
Updated By: NNCRAWFO
Own Op: 1
Sub Type: NNN
Owner Name: Paul Shevchuk
Owner Company: DCA 1, L.P.
Owner Address: 885 Second Ave
Owner Addr2: Floor 31
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: New York Public Library--Brownsville Branch
Owner Address: 61 Glenmore Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11212
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Paul Shevchuk
Owner Company: DCA 1, L.P.
Owner Address: Omni New York LLC
Owner Addr2: 885 Second Avenue, Floor 31
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America

DCA 1 APARTMENTS (Continued) **S113913741**

HW Code: C224162
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224162
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2016000296357
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2016-08-31 09:48:00
Record Updated: 2016-08-31 09:48:00
Updated By: NNCRAWFO
Crossref ID: C224162-09-12
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-06-01 12:47:00
Record Updated: 2016-06-01 12:47:00
Updated By: NNCRAWFO

BROWNFIELDS:

Name:	DCA 1 APARTMENTS
Address:	495 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Program:	BCP
Site Code:	466073
Acres:	0.019
HW Code:	C224162
SWIS:	2401
Town:	New York City
Record Added Date:	07/03/2012
Record Updated Date:	05/29/2021
Update By:	JHOCONNE
Site Description:	Location: The site is a rectangular area of 818 square feet located in the southwest corner of Brooklyn Block 1467, Lot 1. The address is 495 Howard Avenue, aka 485 Howard Avenue, in the East New York section of Brooklyn at the intersection of Howard Avenue and Sterling Place. The site is the location of a former dry cleaning building. The site is a small portion of Block 1467, Lot 1. Site Features: The site is currently paved. The remedial action consisted of a cover system. This cover system is comprised of the pavement or sidewalks comprising the site development, and a system of porous pavers and tree grates over the previously uncapped portion of the site. The site is part of a larger residential development consisting of 9

DCA 1 APARTMENTS (Continued) **S113913741**

buildings, an asphalt parking lot, landscaped areas and a former playground. Current Zoning and Land Use: The site is zoned R6 for residential use with a commercial overlay of C1-3 and is used as a walking area near the restricted residential development. Historic Use: A dry-cleaning operation had been identified in a formerly existing building on this site in the 1960s. Site Geology and Hydrogeology: The site soil consists of historic fill from grade to approximately 7 feet below ground surface (bgs), glacial till consisting of dense sand, silt, gravel, and cobbles from approximately 7 to 54 ft bgs, and medium to fine grained sand from approximately 54 to 60 ft bgs. The regional groundwater aquifer is likely within the medium to fine grained sand formation. Perched groundwater was encountered at approximately 13 feet bgs. The regional groundwater table was encountered at a depth of 55 feet bgs and was found in a permeable sand formation. Above this depth, several intervals of moist to wet soil were observed. Groundwater flow direction is to the southeast.

Env Problem:

Nature and Extent of Contamination: Prior to Remediation: Soil - No volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs) pesticides, herbicides or polychlorinated biphenyls (PCBs) were identified in the soil samples collected during the remedial investigation exceeding restricted residential soil cleanup objectives (RRSCOs). Metals exceeding RRSCOs were limited to the shallow samples collected within the historic fill layer. Detections of PCE were all below the unrestricted use soil cleanup objective (UUSCO) of 1.3 parts per million (ppm). Metals exceeding the RRSCOs were limited to barium in the shallow samples collected from borings in the historic fill layer from 5 to 7 feet bgs. The samples exceeding the RRSCO (350 ppm) were all within the same order of magnitude at concentrations up to 774 ppm. Site related soil contamination does not appear to extend off-site. Groundwater - There were no samples exceeding the groundwater standards for SVOCs, pesticides, PCBs or herbicides. Samples exceeding the groundwater standards for VOCs were primarily limited to PCE, which was detected in each of the monitoring wells sampled and was detected above the groundwater standards in seven of the eleven monitoring wells. Detections above the standard ranged from 7 parts per billion (ppb) to 71 ppb in onsite monitoring wells as compared to the groundwater standard of 5 ppb. Three of the seven monitoring wells with detections of PCE above the groundwater standards were identified in upgradient offsite monitoring well clusters. PCE was detected in each of the five upgradient wells sampled, with concentrations ranging up to 31 ppb. No onsite source of groundwater contamination has been identified and it appears that the VOCs found in the groundwater both on and offsite are due to an upgradient offsite source. Total metals exceeding the groundwater standards were identified in each of the monitoring wells sampled. The compounds exceeding the groundwater standards included chromium at 273 ppb. These compounds appear to be naturally occurring. Soil vapor - Elevated concentrations of PCE were detected in soil vapor at 3 of 4 soil vapor points at concentrations ranging from 278 micrograms per cubic meter (ug/m3) to 4,207 ug/m3. Trichloroethylene (TCE) a breakdown product of PCE was also detected in soil vapor at a maximum concentration of 69.9 ug/m3. No on-site source of soil vapor was identified. Post-Remediation Remediation at the site is complete. Prior to remediation, the contaminants of concern were tetrachloroethene (PCE), trichloroethene (TCE), chromium and barium in soil and groundwater. The selected remedy, a site cover

DCA 1 APARTMENTS (Continued) **S113913741**

	system, has been installed. Remaining contamination is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination that remains on-site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-07-05 14:19:00
Record Upd:	2016-06-03 11:10:00
Updated By:	NNCRAWFO
Own Op:	1
Sub Type:	NNN
Owner Name:	Paul Shevchuk
Owner Company:	DCA 1, L.P.
Owner Address:	885 Second Ave
Owner Addr2:	Floor 31
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	New York Public Library--Brownsville Branch
Owner Address:	61 Glenmore Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Paul Shevchuk
Owner Company:	DCA 1, L.P.
Owner Address:	Omni New York LLC
Owner Addr2:	885 Second Avenue, Floor 31
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	C224162
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224162
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

DCA 1 APARTMENTS (Continued) **S113913741**

HW Code:	C224162
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2016000296357
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2016-08-31 09:48:00
Record Updated:	2016-08-31 09:48:00
Updated By:	NNCRAWFO
Crossref ID:	C224162-09-12
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-06-01 12:47:00
Record Updated:	2016-06-01 12:47:00
Updated By:	NNCRAWFO

NYC LEAD:

Name:	Not reported
Address:	495 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	12139564
Building ID:	314148
Registration ID:	374449
Apartment:	1B
Story:	1
Class:	Most Serious
Inspection Date:	12/09/2017
Approved Date:	12/09/2017
Original Certify By Date:	01/13/2018
Original Correct By Date:	01/08/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5956322
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM WEST AT NORTH WALL IN THE FOYER LOCATED AT APT 1B, 1st STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	12/11/2017
Current Status ID:	9
Current Status:	VIOLATION DISMISSED
Current Status Date:	07/08/2020

Name:	Not reported
Address:	495 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	12458868
Building ID:	314148
Registration ID:	374449
Apartment:	1B
Story:	1
Class:	Most Serious
Inspection Date:	06/26/2018
Approved Date:	07/01/2018

DCA 1 APARTMENTS (Continued) **S113913741**

Original Certify By Date:	08/04/2018
Original Correct By Date:	07/30/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6129436
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE FOYER LOCATED AT APT 1B, 1st STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	07/02/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	07/05/2018

---

381 South 1/4-1/2 0.490 mi. 2588 ft.

PROSPECT PLAZA -NYCHA
430 SARATOGA AVE
BROOKLYN, NY

NY LTANKS **U000418231**
NY Spills **N/A**

Relative: Lower

Actual: 72 ft.

LTANKS:

Name:	PROSPECT PLAZA -NYCHA
Address:	430 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9010192 / 2005-12-14
Facility ID:	9010192
Site ID:	253502
Spill Date:	1990-12-19
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1990-12-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-20
Spill Record Last Update:	2005-12-14
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	192058
DEC Memo:	"12/14/05: This spill transferred from J.Kolleeny to S.Kraszewski.

PROSPECT PLAZA -NYCHA (Continued) **U000418231**

Remarks:	This spill closed to consolidate with open spill #9603220." "15K TANK FAILED HORNER EZY CHECK WITH A VISUAL LEAK (STICK LINE), TO REPAIR & RETEST."

All TTF:

Facility ID:	9010192
Spill Number:	9010192
Spill Tank Test:	1538063
Site ID:	253502
Tank Number:	001
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	253502
Operable Unit ID:	947341
Operable Unit:	01
Material ID:	430358
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	SPILL NUMBER 0201823
Address:	430 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0201823 / 2002-05-21
Facility ID:	0201823
Facility Type:	ER
DER Facility ID:	192058
Site ID:	323450
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-05-20
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2002-05-20
CID:	405

PROSPECT PLAZA -NYCHA (Continued) **U000418231**

Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-20
Spill Record Last Update:	2002-05-21
Spiller Name:	JOSEPH CAMERON
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	23-02 49TH AVE
Spiller Company:	001
Contact Name:	FRANK INOA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY KOLLEENY OF DEC SPOKE TO STEVEN SACCACIO OF NYCHA ON 5/21/02. SPILL OCCURRED BECAUSE VANDALS CUT 15-FOOT SECTION OF COPPER PIPE CARRYING WATER FROM ROOF TANK TO CONDENSATE TANK IN BOILER ROOM; BOILER ROOM FILLED WITH WATER TO 12-FOOT DEPTH, SEVERAL GALLONS OF OIL DRIPPINGS IN PAN BY BOILER GOT INTO THE WATER. CLEAN VENTURE CAME OUT AND, AFTER HOUSING AUTHORITY PUMPED MOST OF THE WATER INTO SEWER, CV PUMPED REMAINING WATER AND OIL INTO VAC TRUCK. THEY THEN POWER WASHED ROOM, ALSO RECOVERING WASH WATER INTO VAC TRUCK. CLEANUP COMPLETE; OK TO CLOSE."
Remarks:	"mechanical failure and clean up in progress "

All Materials:

Site ID:	323450
Operable Unit ID:	852794
Operable Unit:	01
Material ID:	523236
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SPILL NUMBER 0306726
Address:	430 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0306726 / 2003-09-25
Facility ID:	0306726
Facility Type:	ER
DER Facility ID:	192058
Site ID:	233099
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4

PROSPECT PLAZA -NYCHA (Continued) **U000418231**

SWIS:	2401
Spill Date:	2003-09-25
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2003-09-25
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-25
Spill Record Last Update:	2003-09-25
Spiller Name:	CALLER
Spiller Company:	MAZZOCCHI WRECKING
Spiller Address:	32 WILLIAMS PKWY
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 9/25/03, ROSSAN; DDO: Called Gerald, who confirmed that contamination is been cleaned-up. The spill is totally contained. Contaminated soil will be moved off-site. Manifest will be faxed to 718-482-4098, so that spill can be closed. Discussed with Cris, who may visit site. Ed. Cris visit site and recommends closure. Ed."
	Not reported
Remarks:	"line broke on equipt. cleanup in progress."

All Materials:

Site ID:	233099
Operable Unit ID:	873149
Operable Unit:	01
Material ID:	503917
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	PROSPECT PLAZA HOUSES -NYCHA
Address:	430 SARATOGA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9603220 / 2008-03-28
Facility ID:	9603220
Facility Type:	ER
DER Facility ID:	192058
Site ID:	233100
DEC Region:	2

PROSPECT PLAZA -NYCHA (Continued) **U000418231**

Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-06-07
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1996-06-07
CID:	312
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-06-07
Spill Record Last Update:	2008-03-28
Spiller Name:	CALLER
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller Company:	001
Contact Name:	MANAGEMENT OFFICE
DEC Memo:	"12/14/05: This spill transferred from J.Kolleeny to S.Kraszewski. 03/23/06: This spill transferred to K.Tang - SK"
Remarks:	"caller was removing tanks and found contaminated soil"

All Materials:

Site ID:	233100
Operable Unit ID:	1034496
Operable Unit:	01
Material ID:	349466
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	233100
Operable Unit ID:	1034496
Operable Unit:	01
Material ID:	349467
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Count: 4 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113922095	UNION STATION (CITIZENS BRANCH)	ATLANTIC AVE, ASHFORD ST, LIBE	11207	NY VCP
BROOKLYN	S109416448	ATLANTIC AVE. AND UTICA AVENUE (CR	ATLANTIC AVENUE; UTICA AVENUE;	11213	NY INST CONTROL, NY VCP
BROOKLYN	S126023749	SARATOGA AVE AND BERGEN STREET	BOUNDED BY SARATOGA AVENUE, BE		NY SWF/LF
BROOKLYN	S126023326	MARINE PARK	BOUNDED BY FLATBUSH AVENUE, RO		NY SWF/LF

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: N/A
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: N/A
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: N/A
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 03/26/2023
Date Data Arrived at EDR: 03/28/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/23/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/25/2023
Date Data Arrived at EDR: 05/31/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 54

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/02/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/21/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/21/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/12/2023
Date Data Arrived at EDR: 06/20/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 55

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/31/2023
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 03/08/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 82

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/06/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/06/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/06/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/06/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/17/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 09/06/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 09/27/2022
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 03/21/2023
Date Data Arrived at EDR: 06/14/2023
Date Made Active in Reports: 08/31/2023
Number of Days to Update: 78

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Semi-Annually

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 06/04/2023
Date Data Arrived at EDR: 06/06/2023
Date Made Active in Reports: 08/24/2023
Number of Days to Update: 79

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 06/06/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 04/06/2023
Date Data Arrived at EDR: 04/13/2023
Date Made Active in Reports: 04/19/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 08/30/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 08/30/2023
Next Scheduled EDR Contact: 12/18/2023
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/11/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 04/28/2023
Date Data Arrived at EDR: 04/28/2023
Date Made Active in Reports: 07/19/2023
Number of Days to Update: 82
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 07/26/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/19/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/31/2023
Number of Days to Update: 87
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 07/24/2023
Date Data Arrived at EDR: 07/31/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/08/2023
Date Data Arrived at EDR: 05/16/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 55

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/15/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/10/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/01/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/19/2023
Date Data Arrived at EDR: 06/20/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 55

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/03/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/16/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 75

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/18/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/17/2023
Date Data Arrived at EDR: 04/18/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 83

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/18/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/07/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/15/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 04/14/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 87
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/28/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/03/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/25/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/20/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 81

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 07/31/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/26/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/10/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 06/22/2023
Date Data Arrived at EDR: 07/06/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 18

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 09/01/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2023
Date Data Arrived at EDR: 05/24/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 61

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/22/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 04/03/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 01/07/2022
Date Data Arrived at EDR: 02/24/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 82

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/24/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/24/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/13/2023
Date Data Arrived at EDR: 06/14/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 61

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 08/29/2023
Next Scheduled EDR Contact: 12/18/2023
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/04/2023
Date Data Arrived at EDR: 05/25/2023
Date Made Active in Reports: 07/24/2023
Number of Days to Update: 60

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 08/29/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 11/09/2021
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/25/2023
Date Data Arrived at EDR: 03/31/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/29/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/15/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/15/2023
Date Data Arrived at EDR: 05/17/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 54

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/15/2023
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 04/27/2023
Date Data Arrived at EDR: 04/27/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of resins and lubricants used in products such as water-repellent clothing, furniture, adhesives, paint and varnish, food packaging, heat-resistant non-stick cooking surfaces and insulation of electrical wires. Chemicals in this group include perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS).

Date of Government Version: 05/05/2023
Date Data Arrived at EDR: 05/05/2023
Date Made Active in Reports: 07/26/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 08/03/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 11/14/2022
Date Data Arrived at EDR: 01/12/2023
Date Made Active in Reports: 01/23/2023
Number of Days to Update: 11

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 07/26/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 07/28/2023
Date Data Arrived at EDR: 08/02/2023
Date Made Active in Reports: 08/08/2023
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 03/22/2023
Date Data Arrived at EDR: 03/24/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 08/30/2023
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 08/30/2023
Next Scheduled EDR Contact: 12/18/2023
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 06/05/2023
Date Data Arrived at EDR: 06/13/2023
Date Made Active in Reports: 09/01/2023
Number of Days to Update: 80

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/13/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 07/31/2021
Date Data Arrived at EDR: 01/05/2023
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 08/30/2023
Next Scheduled EDR Contact: 12/18/2023
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 12/31/2022
Date Data Arrived at EDR: 02/01/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 83

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 08/01/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 05/01/2023
Date Data Arrived at EDR: 05/03/2023
Date Made Active in Reports: 07/27/2023
Number of Days to Update: 85

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 08/01/2023
Next Scheduled EDR Contact: 11/13/2023
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/08/2023
Date Made Active in Reports: 08/03/2023
Number of Days to Update: 87

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/10/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: Varies

UIC: Underground Injection Control Wells
A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 05/29/2023
Date Data Arrived at EDR: 05/30/2023
Date Made Active in Reports: 08/22/2023
Number of Days to Update: 84

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 08/30/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers
This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 04/04/2023
Date Data Arrived at EDR: 04/12/2023
Date Made Active in Reports: 06/28/2023
Number of Days to Update: 77

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: No Update Planned

PFAS TRIS: List of PFAS Added to the TRI
Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 98

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/24/2023
Next Scheduled EDR Contact: 12/04/2023
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 07/16/2023
Date Data Arrived at EDR: 07/18/2023
Date Made Active in Reports: 08/28/2023
Number of Days to Update: 41

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 07/18/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/23/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/23/2023
Next Scheduled EDR Contact: 12/11/2023
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/19/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/11/2023
Date Made Active in Reports: 08/03/2023
Number of Days to Update: 84

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/11/2023
Date Made Active in Reports: 08/03/2023
Number of Days to Update: 84

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/27/2023
Next Scheduled EDR Contact: 11/06/2023
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/16/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/06/2023
Number of Days to Update: 82

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/08/2023
Next Scheduled EDR Contact: 11/20/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/10/2022
Next Scheduled EDR Contact: 11/27/2023
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/30/2023
Next Scheduled EDR Contact: 12/18/2023
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

2014 FULTON STREET
2014 FULTON STREET
BROOKLYN, NY 11233

TARGET PROPERTY COORDINATES

Latitude (North):	40.678407 - 40° 40' 42.27''
Longitude (West):	73.917617 - 73° 55' 3.42''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	591474.4
UTM Y (Meters):	4503410.0
Elevation:	80 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970064B	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
3604970208F	FEMA FIRM Flood data
3604970065B	FEMA Q3 Flood data
3604970074B	FEMA Q3 Flood data
3604970075C	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	USGS40000828104	1/2 - 1 Mile SSE
A3	USGS40000828103	1/2 - 1 Mile SSE
4	USGS40000828574	1/2 - 1 Mile North
C7	USGS40000828320	1/2 - 1 Mile West
C8	USGS40000828321	1/2 - 1 Mile West
9	USGS40000828084	1/2 - 1 Mile SW
10	USGS40000828031	1/2 - 1 Mile SSE
11	USGS40000827986	1/2 - 1 Mile SSW
12	USGS40000828399	1/2 - 1 Mile East
D14	USGS40000828291	1/2 - 1 Mile West
D15	USGS40000828292	1/2 - 1 Mile West
E16	USGS40000827895	1/2 - 1 Mile SSW
E18	USGS40000827850	1/2 - 1 Mile SSW
19	USGS40000828659	1/2 - 1 Mile NNW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYREG1000000154	1/8 - 1/4 Mile WSW
B5	NYREG1000000076	1/2 - 1 Mile West
B6	NYREG1000000077	1/2 - 1 Mile West
13	NYREG1000000231	1/2 - 1 Mile WSW
17	NYREG1000000197	1/2 - 1 Mile ESE

PHYSICAL SETTING SOURCE MAP - 7438000.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	2014 Fulton Street	CLIENT:	Roux Associates
ADDRESS:	2014 Fulton Street Brooklyn NY 11233	CONTACT:	Stephen Loonie
LAT/LONG:	40.678407 / 73.917617	INQUIRY #:	7438000.2s
		DATE:	September 07, 2023 1:27 pm

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
WSW
1/8 - 1/4 Mile
Higher

NY WELLS **NYREG1000000154**

Well Number:	K003508	Owner:	Odessa Car Wash Incorporated
Well Depth:	160	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

A2
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS40000828104**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3257. 2	Type:	Well
Description:	CHESTER AVE AND EAST NEW YORK AVE		
HUC:	02030202	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	19980624	Well Depth:	55
Well Depth Units:	ft	Well Hole Depth:	55
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	73	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	10.53
Note:	Not Reported		

Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	10.40	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	10.44	Note:	Not Reported
Level reading date:	2004-11-23	Feet below surface:	Not Reported
Feet to sea level:	10.48	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	10.43	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	10.31	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	10.01	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	10.01	Note:	Not Reported

Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	9.88	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	9.86	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	10.03	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	10.00	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	9.99	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	10.07	Note:	Not Reported
Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	10.24	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	10.83	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	9.92	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	9.64	Note:	Not Reported
Level reading date:	2003-02-27	Feet below surface:	Not Reported
Feet to sea level:	9.37	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	9.02	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	9.01	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	8.91	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	8.78	Note:	Not Reported
Level reading date:	2002-08-27	Feet below surface:	Not Reported
Feet to sea level:	8.68	Note:	Not Reported
Level reading date:	2002-07-24	Feet below surface:	Not Reported
Feet to sea level:	8.82	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	8.77	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	8.74	Note:	Not Reported

Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	8.74	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	8.67	Note:	Not Reported
Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	8.78	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	8.91	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	9.02	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-09-25	Feet below surface:	Not Reported
Feet to sea level:	9.57	Note:	Not Reported
Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	9.46	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.76	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	9.82	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	9.83	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	9.34	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	9.39	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	9.28	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	9.49	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	9.73	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	9.98	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	9.94	Note:	Not Reported

Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.92	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	9.78	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	9.70	Note:	Not Reported
Level reading date:	2000-03-29	Feet below surface:	Not Reported
Feet to sea level:	9.69	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	9.62	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	9.68	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	9.79	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	9.94	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	10.00	Note:	Not Reported
Level reading date:	1999-06-23	Feet below surface:	Not Reported
Feet to sea level:	10.07	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	10.12	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.13	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	10.14	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	10.22	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	10.57	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	10.93	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	11.22	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
FED USGS	**USGS40000828103**

A3
SSE
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3257. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	50
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	51	Level reading date:	1999-06-23
Feet below surface:	Not Reported	Feet to sea level:	11.12
Note:	Not Reported		

Level reading date:	1997-03-17	Feet below surface:	Not Reported
Feet to sea level:	9.75	Note:	Not Reported
Level reading date:	1996-07-05	Feet below surface:	Not Reported
Feet to sea level:	10.29	Note:	Not Reported
Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	10.11	Note:	Not Reported
Level reading date:	1995-09-29	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported
Level reading date:	1995-06-21	Feet below surface:	Not Reported
Feet to sea level:	9.72	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	9.98	Note:	Not Reported
Level reading date:	1995-01-03	Feet below surface:	Not Reported
Feet to sea level:	10.11	Note:	Not Reported
Level reading date:	1994-06-29	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	1994-03-24	Feet below surface:	Not Reported
Feet to sea level:	10.42	Note:	Not Reported
Level reading date:	1993-11-22	Feet below surface:	Not Reported
Feet to sea level:	9.94	Note:	Not Reported
Level reading date:	1993-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.26	Note:	Not Reported
Level reading date:	1993-07-22	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	10.57	Note:	Not Reported

Level reading date:	1993-05-24	Feet below surface:	Not Reported
Feet to sea level:	10.65	Note:	Not Reported
Level reading date:	1993-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.65	Note:	Not Reported
Level reading date:	1993-03-22	Feet below surface:	Not Reported
Feet to sea level:	10.28	Note:	Not Reported
Level reading date:	1993-01-19	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	1992-12-28	Feet below surface:	Not Reported
Feet to sea level:	10.25	Note:	Not Reported
Level reading date:	1992-11-19	Feet below surface:	Not Reported
Feet to sea level:	10.12	Note:	Not Reported
Level reading date:	1992-11-10	Feet below surface:	Not Reported
Feet to sea level:	10.19	Note:	Not Reported
Level reading date:	1992-10-27	Feet below surface:	Not Reported
Feet to sea level:	10.29	Note:	Not Reported
Level reading date:	1992-09-18	Feet below surface:	Not Reported
Feet to sea level:	10.55	Note:	Not Reported
Level reading date:	1992-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.43	Note:	Not Reported
Level reading date:	1992-07-16	Feet below surface:	Not Reported
Feet to sea level:	10.28	Note:	Not Reported
Level reading date:	1992-06-23	Feet below surface:	Not Reported
Feet to sea level:	10.24	Note:	Not Reported
Level reading date:	1992-06-12	Feet below surface:	Not Reported
Feet to sea level:	10.21	Note:	Not Reported
Level reading date:	1992-04-06	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1985-12-04	Feet below surface:	Not Reported
Feet to sea level:	10.18	Note:	Not Reported
Level reading date:	1985-10-02	Feet below surface:	Not Reported
Feet to sea level:	10.22	Note:	Not Reported
Level reading date:	1985-05-18	Feet below surface:	Not Reported
Feet to sea level:	10.38	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	11.39	Note:	Not Reported
Level reading date:	1984-10-03	Feet below surface:	Not Reported
Feet to sea level:	12.16	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	12.51	Note:	Not Reported
Level reading date:	1984-03-19	Feet below surface:	Not Reported
Feet to sea level:	11.45	Note:	Not Reported

Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	11.19	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	11.85	Note:	Not Reported
Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	11.07	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	12.07	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	11.37	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	11.21	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	11.35	Note:	Not Reported
Level reading date:	1982-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.16	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	12.46	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	12.27	Note:	Not Reported
Level reading date:	1981-06-25	Feet below surface:	Not Reported
Feet to sea level:	11.94	Note:	Not Reported
Level reading date:	1981-03-19	Feet below surface:	Not Reported
Feet to sea level:	12.56	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	13.01	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	13.65	Note:	Not Reported
Level reading date:	1980-06-20	Feet below surface:	Not Reported
Feet to sea level:	13.96	Note:	Not Reported
Level reading date:	1980-06-10	Feet below surface:	Not Reported
Feet to sea level:	13.90	Note:	Not Reported

4
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000828574**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1199. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	76

Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	331	Level reading date:	1960-12-27
Feet below surface:	Not Reported	Feet to sea level:	5.19
Note:	Not Reported		

Level reading date:	1960-12-07	Feet below surface:	Not Reported
Feet to sea level:	4.72	Note:	Not Reported
Level reading date:	1960-11-02	Feet below surface:	Not Reported
Feet to sea level:	4.23	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	4.22	Note:	Not Reported
Level reading date:	1960-08-30	Feet below surface:	Not Reported
Feet to sea level:	4.07	Note:	Not Reported
Level reading date:	1960-07-19	Feet below surface:	Not Reported
Feet to sea level:	3.94	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	3.78	Note:	Not Reported
Level reading date:	1960-06-02	Feet below surface:	Not Reported
Feet to sea level:	3.57	Note:	Not Reported
Level reading date:	1960-05-04	Feet below surface:	Not Reported
Feet to sea level:	4.01	Note:	Not Reported
Level reading date:	1960-03-29	Feet below surface:	Not Reported
Feet to sea level:	4.32	Note:	Not Reported
Level reading date:	1960-01-27	Feet below surface:	Not Reported
Feet to sea level:	4.35	Note:	Not Reported
Level reading date:	1960-01-05	Feet below surface:	Not Reported
Feet to sea level:	4.40	Note:	Not Reported
Level reading date:	1959-12-01	Feet below surface:	Not Reported
Feet to sea level:	4.69	Note:	Not Reported
Level reading date:	1959-11-02	Feet below surface:	Not Reported
Feet to sea level:	4.37	Note:	Not Reported
Level reading date:	1959-10-06	Feet below surface:	Not Reported
Feet to sea level:	4.35	Note:	Not Reported
Level reading date:	1959-09-03	Feet below surface:	Not Reported
Feet to sea level:	4.10	Note:	Not Reported
Level reading date:	1959-08-04	Feet below surface:	Not Reported
Feet to sea level:	4.10	Note:	Not Reported
Level reading date:	1959-07-07	Feet below surface:	Not Reported
Feet to sea level:	4.26	Note:	Not Reported
Level reading date:	1959-06-02	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported

Level reading date:	1959-05-06	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1959-04-03	Feet below surface:	Not Reported
Feet to sea level:	3.87	Note:	Not Reported
Level reading date:	1959-03-05	Feet below surface:	Not Reported
Feet to sea level:	4.14	Note:	Not Reported
Level reading date:	1959-01-29	Feet below surface:	Not Reported
Feet to sea level:	4.24	Note:	Not Reported
Level reading date:	1959-01-07	Feet below surface:	Not Reported
Feet to sea level:	3.59	Note:	Not Reported
Level reading date:	1958-12-09	Feet below surface:	Not Reported
Feet to sea level:	3.64	Note:	Not Reported
Level reading date:	1958-10-30	Feet below surface:	Not Reported
Feet to sea level:	3.66	Note:	Not Reported
Level reading date:	1958-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.53	Note:	Not Reported
Level reading date:	1958-08-28	Feet below surface:	Not Reported
Feet to sea level:	3.48	Note:	Not Reported
Level reading date:	1958-07-29	Feet below surface:	Not Reported
Feet to sea level:	3.46	Note:	Not Reported
Level reading date:	1958-06-30	Feet below surface:	Not Reported
Feet to sea level:	3.38	Note:	Not Reported
Level reading date:	1958-05-29	Feet below surface:	Not Reported
Feet to sea level:	3.27	Note:	Not Reported
Level reading date:	1958-05-01	Feet below surface:	Not Reported
Feet to sea level:	3.22	Note:	Not Reported
Level reading date:	1958-04-02	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1958-03-03	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1958-01-28	Feet below surface:	Not Reported
Feet to sea level:	2.73	Note:	Not Reported
Level reading date:	1957-12-31	Feet below surface:	Not Reported
Feet to sea level:	2.93	Note:	Not Reported
Level reading date:	1957-11-22	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1957-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1957-08-26	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported

Level reading date:	1957-07-24	Feet below surface:	Not Reported
Feet to sea level:	3.19	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	3.29	Note:	Not Reported
Level reading date:	1957-05-28	Feet below surface:	Not Reported
Feet to sea level:	3.36	Note:	Not Reported
Level reading date:	1957-04-24	Feet below surface:	Not Reported
Feet to sea level:	3.18	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	3.37	Note:	Not Reported
Level reading date:	1957-02-27	Feet below surface:	Not Reported
Feet to sea level:	3.27	Note:	Not Reported
Level reading date:	1957-01-25	Feet below surface:	Not Reported
Feet to sea level:	2.94	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	3.12	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	3.05	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	2.87	Note:	Not Reported
Level reading date:	1956-07-11	Feet below surface:	Not Reported
Feet to sea level:	2.90	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	2.87	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1956-03-06	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	2.40	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1955-11-07	Feet below surface:	Not Reported
Feet to sea level:	1.99	Note:	Not Reported
Level reading date:	1955-10-05	Feet below surface:	Not Reported
Feet to sea level:	1.87	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.76	Note:	Not Reported

Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	1.73	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.76	Note:	Not Reported
Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	1.68	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	1.45	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.45	Note:	Not Reported
Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.77	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.64	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1954-10-28	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported
Level reading date:	1954-10-05	Feet below surface:	Not Reported
Feet to sea level:	1.25	Note:	Not Reported
Level reading date:	1954-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.31	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.18	Note:	Not Reported
Level reading date:	1954-07-01	Feet below surface:	Not Reported
Feet to sea level:	1.22	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	1.53	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.64	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.39	Note:	Not Reported
Level reading date:	1953-12-26	Feet below surface:	Not Reported
Feet to sea level:	0.69	Note:	Not Reported
Level reading date:	1953-12-22	Feet below surface:	Not Reported
Feet to sea level:	0.67	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	0.63	Note:	Not Reported

Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	0.40	Note:	Not Reported
Level reading date:	1953-10-01	Feet below surface:	Not Reported
Feet to sea level:	0.33	Note:	Not Reported
Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	0.29	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	0.20	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-0.02	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-0.76	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported
Level reading date:	1953-03-25	Feet below surface:	Not Reported
Feet to sea level:	-1.22	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	-1.48	Note:	Not Reported
Level reading date:	1953-02-11	Feet below surface:	Not Reported
Feet to sea level:	-1.19	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-0.96	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-1.38	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-2.31	Note:	Not Reported
Level reading date:	1952-09-22	Feet below surface:	Not Reported
Feet to sea level:	-2.37	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-3.47	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-3.78	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-4.20	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-4.44	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-4.51	Note:	Not Reported

Level reading date:	1952-01-24	Feet below surface:	Not Reported
Feet to sea level:	-4.96	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-5.20	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-5.28	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-5.43	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.49	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-5.58	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-5.74	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.98	Note:	Not Reported
Level reading date:	1951-05-01	Feet below surface:	Not Reported
Feet to sea level:	-5.86	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-5.85	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-6.07	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-6.14	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-6.80	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-6.86	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.72	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.56	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-6.49	Note:	Not Reported

Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-6.47	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-6.52	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-7.00	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-7.58	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-7.68	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-8.32	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-8.52	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-8.78	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-9.10	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-9.50	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-10.20	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-10.57	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-10.70	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-10.52	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-11.30	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-11.42	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-11.65	Note:	Not Reported

Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-12.05	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-12.32	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-12.64	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-13.15	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-13.26	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-13.91	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-13.44	Note:	Not Reported
Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-14.48	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-14.51	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-14.84	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-14.65	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-14.99	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-15.11	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-15.16	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-15.16	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-15.23	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-15.30	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-15.32	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-15.33	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-15.38	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-15.36	Note:	Not Reported

Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-15.33	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-15.28	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-15.35	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-15.35	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-15.28	Note:	Not Reported
Level reading date:	1947-05-07	Feet below surface:	Not Reported
Feet to sea level:	-15.26	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-15.34	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-15.29	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-15.22	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-15.28	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-15.29	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-15.22	Note:	Not Reported
Level reading date:	1946-09-26	Feet below surface:	Not Reported
Feet to sea level:	-15.21	Note:	Not Reported
Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-14.96	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-15.16	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1946-05-10	Feet below surface:	Not Reported
Feet to sea level:	-15.20	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-15.20	Note:	Not Reported
Level reading date:	1946-03-15	Feet below surface:	Not Reported
Feet to sea level:	-15.23	Note:	Not Reported
Level reading date:	1946-02-14	Feet below surface:	Not Reported
Feet to sea level:	-15.26	Note:	Not Reported

Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-15.43	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-15.55	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-15.63	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-15.62	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-15.61	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-15.53	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-15.22	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-15.14	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-15.28	Note:	Not Reported
Level reading date:	1945-04-04	Feet below surface:	Not Reported
Feet to sea level:	-15.35	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-15.46	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-15.70	Note:	Not Reported
Level reading date:	1944-12-06	Feet below surface:	Not Reported
Feet to sea level:	-15.84	Note:	Not Reported
Level reading date:	1944-10-27	Feet below surface:	Not Reported
Feet to sea level:	-15.98	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-16.02	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-16.07	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-16.11	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-15.91	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-16.03	Note:	Not Reported
Level reading date:	1944-04-01	Feet below surface:	Not Reported
Feet to sea level:	-16.23	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-16.29	Note:	Not Reported

Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-16.38	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-17.17	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-16.45	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-16.31	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-15.89	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-16.11	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-16.08	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-15.90	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-15.98	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-16.08	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-16.21	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-16.28	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-16.32	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-16.49	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-16.52	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-16.57	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-16.61	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-16.61	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-16.63	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-16.62	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-16.66	Note:	Not Reported

Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-16.67	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-16.68	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-16.70	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-16.67	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-16.65	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-16.62	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-16.61	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-16.56	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-16.53	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-16.43	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-16.48	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-16.44	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-16.42	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-16.38	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-16.36	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-16.35	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-16.33	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-16.26	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-16.25	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-16.22	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-16.18	Note:	Not Reported

Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-16.12	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-16.13	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-16.13	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-16.14	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-16.18	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-16.13	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-16.13	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-16.15	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-16.18	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-16.22	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-16.17	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-16.24	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-16.20	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-16.22	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-16.26	Note:	Not Reported

Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-16.31	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-16.20	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-16.28	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-16.26	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-16.30	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-16.30	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-16.28	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-16.31	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-16.23	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-16.25	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-16.27	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-16.25	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-16.18	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-16.18	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-16.06	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-16.04	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-15.98	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-15.97	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-15.95	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-15.90	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-15.89	Note:	Not Reported

Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-15.83	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-15.75	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-15.72	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-15.68	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-15.64	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-15.59	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-15.56	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-15.52	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-15.52	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-15.46	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-15.39	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-15.33	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-15.33	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-15.28	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-15.33	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-15.34	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-15.32	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-15.29	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-15.31	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-15.38	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-15.37	Note:	Not Reported

Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-15.38	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-15.43	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-15.40	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-15.47	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-15.49	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-15.54	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-15.56	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-15.56	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-15.60	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-15.61	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-15.63	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-15.68	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-15.68	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-15.70	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-15.68	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-15.71	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-15.77	Note:	Not Reported

B5
West
1/2 - 1 Mile
Lower

NY WELLS **NYREG1000000076**

Well Number:	K003436	Owner:	Nyc Sanitation Dept.
Well Depth:	100	Diameter:	6

Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

B6
West
1/2 - 1 Mile
Lower

NY WELLS **NYREG1000000077**

Well Number:	K003436	Owner:	Nyc Sanitation Dept.
Well Depth:	100	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

C7
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828320**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3425. 1	Type:	Well
Description:	5001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	19921119	Well Depth:	80
Well Depth Units:	ft	Well Hole Depth:	80
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	125	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	11.70
Note:	Not Reported		

Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	11.72	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	11.62	Note:	Not Reported
Level reading date:	2004-11-23	Feet below surface:	Not Reported
Feet to sea level:	11.69	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	11.63	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	11.58	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	11.42	Note:	Not Reported
Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	11.49	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	11.28	Note:	Not Reported

Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	11.26	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	11.17	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	11.15	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	11.14	Note:	Not Reported
Level reading date:	2004-01-30	Feet below surface:	Not Reported
Feet to sea level:	11.26	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	11.04	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	10.98	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	11.15	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	11.12	Note:	Not Reported
Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	11.07	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	10.94	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	10.71	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	10.70	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	10.49	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.49	Note:	Not Reported
Level reading date:	2003-03-17	Feet below surface:	Not Reported
Feet to sea level:	10.32	Note:	Not Reported
Level reading date:	2003-02-27	Feet below surface:	Not Reported
Feet to sea level:	10.14	Note:	Not Reported
Level reading date:	2003-01-28	Feet below surface:	Not Reported
Feet to sea level:	10.06	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	9.79	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	9.69	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported

Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	9.45	Note:	Not Reported
Level reading date:	2002-08-27	Feet below surface:	Not Reported
Feet to sea level:	9.46	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	9.58	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	9.56	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	9.68	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	9.78	Note:	Not Reported
Level reading date:	2002-03-22	Feet below surface:	Not Reported
Feet to sea level:	9.95	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	10.13	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	10.21	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	10.67	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	10.69	Note:	Not Reported
Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	10.75	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	11.01	Note:	Not Reported
Level reading date:	2001-07-17	Feet below surface:	Not Reported
Feet to sea level:	10.83	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.90	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	10.82	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	10.59	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	10.32	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	10.36	Note:	Not Reported

Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	10.45	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	10.61	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	10.66	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	10.84	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	10.85	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.86	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	10.74	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.66	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	10.52	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	10.60	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	10.75	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	10.85	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	11.02	Note:	Not Reported
Level reading date:	1999-07-20	Feet below surface:	Not Reported
Feet to sea level:	10.95	Note:	Not Reported
Level reading date:	1999-07-07	Feet below surface:	Not Reported
Feet to sea level:	11.05	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	11.05	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	11.10	Note:	Not Reported

Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	11.08	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	11.11	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	11.21	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	11.35	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	11.78	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	11.95	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	12.09	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	12.25	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	12.40	Note:	Not Reported
Level reading date:	1998-06-10	Feet below surface:	Not Reported
Feet to sea level:	12.11	Note:	Not Reported
Level reading date:	1998-05-20	Feet below surface:	Not Reported
Feet to sea level:	11.92	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	11.74	Note:	Not Reported
Level reading date:	1998-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.49	Note:	Not Reported
Level reading date:	1998-01-29	Feet below surface:	Not Reported
Feet to sea level:	11.45	Note:	Not Reported
Level reading date:	1997-12-17	Feet below surface:	Not Reported
Feet to sea level:	11.58	Note:	Not Reported
Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	11.67	Note:	Not Reported
Level reading date:	1997-11-05	Feet below surface:	Not Reported
Feet to sea level:	11.60	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	11.95	Note:	Not Reported
Level reading date:	1997-07-23	Feet below surface:	Not Reported
Feet to sea level:	11.71	Note:	Not Reported
Level reading date:	1997-06-26	Feet below surface:	Not Reported
Feet to sea level:	11.86	Note:	Not Reported
Level reading date:	1997-05-29	Feet below surface:	Not Reported
Feet to sea level:	11.77	Note:	Not Reported

Level reading date:	1997-03-17	Feet below surface:	Not Reported
Feet to sea level:	11.80	Note:	Not Reported
Level reading date:	1997-02-26	Feet below surface:	Not Reported
Feet to sea level:	11.75	Note:	Not Reported
Level reading date:	1997-01-24	Feet below surface:	Not Reported
Feet to sea level:	11.70	Note:	Not Reported
Level reading date:	1997-01-07	Feet below surface:	Not Reported
Feet to sea level:	11.66	Note:	Not Reported
Level reading date:	1996-09-19	Feet below surface:	Not Reported
Feet to sea level:	11.44	Note:	Not Reported
Level reading date:	1996-07-02	Feet below surface:	Not Reported
Feet to sea level:	11.32	Note:	Not Reported
Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	10.85	Note:	Not Reported
Level reading date:	1996-01-23	Feet below surface:	Not Reported
Feet to sea level:	10.61	Note:	Not Reported
Level reading date:	1995-11-28	Feet below surface:	Not Reported
Feet to sea level:	10.61	Note:	Not Reported
Level reading date:	1995-09-26	Feet below surface:	Not Reported
Feet to sea level:	10.64	Note:	Not Reported
Level reading date:	1995-07-19	Feet below surface:	Not Reported
Feet to sea level:	10.65	Note:	Not Reported
Level reading date:	1995-05-23	Feet below surface:	Not Reported
Feet to sea level:	10.76	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	11.03	Note:	Not Reported
Level reading date:	1995-01-25	Feet below surface:	Not Reported
Feet to sea level:	11.19	Note:	Not Reported
Level reading date:	1994-12-13	Feet below surface:	Not Reported
Feet to sea level:	11.28	Note:	Not Reported
Level reading date:	1994-09-21	Feet below surface:	Not Reported
Feet to sea level:	11.59	Note:	Not Reported
Level reading date:	1994-08-24	Feet below surface:	Not Reported
Feet to sea level:	11.60	Note:	Not Reported
Level reading date:	1994-07-27	Feet below surface:	Not Reported
Feet to sea level:	11.74	Note:	Not Reported
Level reading date:	1994-06-20	Feet below surface:	Not Reported
Feet to sea level:	11.65	Note:	Not Reported
Level reading date:	1994-05-16	Feet below surface:	Not Reported
Feet to sea level:	11.56	Note:	Not Reported
Level reading date:	1994-04-26	Feet below surface:	Not Reported
Feet to sea level:	11.32	Note:	Not Reported

Level reading date:	1994-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.09	Note:	Not Reported
Level reading date:	1994-02-22	Feet below surface:	Not Reported
Feet to sea level:	10.87	Note:	Not Reported
Level reading date:	1994-02-02	Feet below surface:	Not Reported
Feet to sea level:	10.85	Note:	Not Reported
Level reading date:	1993-12-27	Feet below surface:	Not Reported
Feet to sea level:	10.80	Note:	Not Reported
Level reading date:	1993-11-18	Feet below surface:	Not Reported
Feet to sea level:	10.98	Note:	Not Reported
Level reading date:	1993-10-27	Feet below surface:	Not Reported
Feet to sea level:	11.22	Note:	Not Reported
Level reading date:	1993-09-15	Feet below surface:	Not Reported
Feet to sea level:	11.25	Note:	Not Reported
Level reading date:	1993-08-18	Feet below surface:	Not Reported
Feet to sea level:	11.27	Note:	Not Reported
Level reading date:	1993-07-14	Feet below surface:	Not Reported
Feet to sea level:	11.42	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	11.56	Note:	Not Reported
Level reading date:	1993-03-23	Feet below surface:	Not Reported
Feet to sea level:	11.07	Note:	Not Reported

C8
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828321**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3410. 1	Type:	Well
Description:	5002	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Lloyd Aquifer	Aquifer Type:	Not Reported
Construction Date:	19941018	Well Depth:	360
Well Depth Units:	ft	Well Hole Depth:	395
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	102	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	8.58
Note:	Not Reported		
Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	8.52	Note:	Not Reported
Level reading date:	2004-12-16	Feet below surface:	Not Reported
Feet to sea level:	8.35	Note:	Not Reported
Level reading date:	2004-11-23	Feet below surface:	Not Reported

Feet to sea level:	8.29	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	8.08	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	7.94	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	7.84	Note:	Not Reported
Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	7.91	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	7.84	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	7.92	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	7.93	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	7.99	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	8.21	Note:	Not Reported
Level reading date:	2004-01-30	Feet below surface:	Not Reported
Feet to sea level:	7.86	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	8.12	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	7.90	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	7.98	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	7.74	Note:	Not Reported
Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	7.71	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	7.86	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	8.08	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	8.08	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	7.66	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	7.85	Note:	Not Reported

Level reading date:	2003-03-17	Feet below surface:	Not Reported
Feet to sea level:	7.68	Note:	Not Reported
Level reading date:	2003-02-27	Feet below surface:	Not Reported
Feet to sea level:	7.38	Note:	Not Reported
Level reading date:	2003-01-28	Feet below surface:	Not Reported
Feet to sea level:	7.41	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	7.33	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	7.33	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	7.36	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	6.77	Note:	Not Reported
Level reading date:	2002-08-27	Feet below surface:	Not Reported
Feet to sea level:	6.52	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	6.65	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	7.02	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	6.97	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	6.82	Note:	Not Reported
Level reading date:	2002-03-22	Feet below surface:	Not Reported
Feet to sea level:	6.96	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	7.14	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	6.83	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	7.04	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	6.72	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	6.73	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	6.64	Note:	Not Reported
Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	6.55	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	6.85	Note:	Not Reported

Level reading date:	2001-07-17	Feet below surface:	Not Reported
Feet to sea level:	6.81	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	6.84	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	6.99	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	6.96	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	6.76	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	6.61	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	6.60	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	6.69	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	6.63	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	6.56	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	6.58	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	6.47	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	6.51	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	6.51	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	6.82	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	6.92	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	6.71	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	6.52	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	6.21	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	6.05	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	5.98	Note:	Not Reported

Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	6.04	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	5.59	Note:	Not Reported
Level reading date:	1999-07-20	Feet below surface:	Not Reported
Feet to sea level:	5.60	Note:	Not Reported
Level reading date:	1999-07-07	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	6.11	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	6.12	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	6.26	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	6.42	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	6.58	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	5.78	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	5.78	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	5.86	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	5.86	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	6.32	Note:	Not Reported
Level reading date:	1998-06-10	Feet below surface:	Not Reported
Feet to sea level:	6.32	Note:	Not Reported
Level reading date:	1998-05-20	Feet below surface:	Not Reported
Feet to sea level:	6.66	Note:	Not Reported
Level reading date:	1998-04-28	Feet below surface:	Not Reported
Feet to sea level:	6.39	Note:	Not Reported
Level reading date:	1998-03-24	Feet below surface:	Not Reported
Feet to sea level:	6.58	Note:	Not Reported
Level reading date:	1998-01-29	Feet below surface:	Not Reported
Feet to sea level:	6.47	Note:	Not Reported
Level reading date:	1997-12-17	Feet below surface:	Not Reported
Feet to sea level:	6.60	Note:	Not Reported

Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	6.46	Note:	Not Reported
Level reading date:	1997-11-05	Feet below surface:	Not Reported
Feet to sea level:	6.39	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	6.73	Note:	Not Reported
Level reading date:	1997-07-23	Feet below surface:	Not Reported
Feet to sea level:	6.57	Note:	Not Reported
Level reading date:	1997-06-26	Feet below surface:	Not Reported
Feet to sea level:	7.50	Note:	Not Reported
Level reading date:	1997-05-29	Feet below surface:	Not Reported
Feet to sea level:	7.70	Note:	Not Reported
Level reading date:	1997-03-20	Feet below surface:	Not Reported
Feet to sea level:	7.81	Note:	Not Reported
Level reading date:	1997-02-26	Feet below surface:	Not Reported
Feet to sea level:	7.77	Note:	Not Reported
Level reading date:	1997-01-24	Feet below surface:	Not Reported
Feet to sea level:	7.72	Note:	Not Reported
Level reading date:	1997-01-07	Feet below surface:	Not Reported
Feet to sea level:	8.09	Note:	Not Reported
Level reading date:	1996-09-19	Feet below surface:	Not Reported
Feet to sea level:	8.06	Note:	Not Reported
Level reading date:	1996-07-02	Feet below surface:	Not Reported
Feet to sea level:	8.04	Note:	Not Reported
Level reading date:	1996-04-18	Feet below surface:	Not Reported
Feet to sea level:	8.21	Note:	Not Reported
Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	7.99	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	7.86	Note:	Not Reported

9
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828084**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1857. 1	Type:	Well
Description:	3301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	218	Well Depth Units:	ft
Well Hole Depth:	218	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

10
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS40000828031**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 910. 1	Type:	Well
Description:	4401	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	182	Well Hole Depth Units:	ft

11
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000827986**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1510. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	147
Well Depth Units:	ft	Well Hole Depth:	205
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	116	Level reading date:	1954-12-28
Feet below surface:	Not Reported	Feet to sea level:	2.97
Note:	Not Reported		

Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	2.84	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	2.91	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	2.93	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	2.87	Note:	Not Reported
Level reading date:	1954-02-27	Feet below surface:	Not Reported
Feet to sea level:	2.91	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	2.84	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported

Feet to sea level:	2.70	Note:	Not Reported
Level reading date:	1953-09-24	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	2.48	Note:	Not Reported
Level reading date:	1953-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1953-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.29	Note:	Not Reported
Level reading date:	1953-04-29	Feet below surface:	Not Reported
Feet to sea level:	2.04	Note:	Not Reported
Level reading date:	1953-03-23	Feet below surface:	Not Reported
Feet to sea level:	1.63	Note:	Not Reported
Level reading date:	1953-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.51	Note:	Not Reported
Level reading date:	1953-02-02	Feet below surface:	Not Reported
Feet to sea level:	1.41	Note:	Not Reported
Level reading date:	1952-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1952-12-01	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	1.11	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	0.88	Note:	Not Reported
Level reading date:	1952-08-26	Feet below surface:	Not Reported
Feet to sea level:	0.68	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	0.51	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	0.32	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	0.20	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	Not Reported
Feet to sea level:	0.19	Note:	Not Reported
Level reading date:	1952-03-19	Feet below surface:	Not Reported
Feet to sea level:	-0.41	Note:	Not Reported
Level reading date:	1952-02-19	Feet below surface:	Not Reported
Feet to sea level:	-0.63	Note:	Not Reported
Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	-0.79	Note:	Not Reported

Level reading date:	1951-12-19	Feet below surface:	Not Reported
Feet to sea level:	-1.15	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-1.63	Note:	Not Reported
Level reading date:	1951-09-25	Feet below surface:	Not Reported
Feet to sea level:	-1.71	Note:	Not Reported
Level reading date:	1951-08-27	Feet below surface:	Not Reported
Feet to sea level:	-1.81	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	-1.96	Note:	Not Reported
Level reading date:	1951-06-27	Feet below surface:	Not Reported
Feet to sea level:	-2.00	Note:	Not Reported
Level reading date:	1951-05-28	Feet below surface:	Not Reported
Feet to sea level:	-2.06	Note:	Not Reported
Level reading date:	1951-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.34	Note:	Not Reported
Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	-2.54	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-2.67	Note:	Not Reported
Level reading date:	1951-01-29	Feet below surface:	Not Reported
Feet to sea level:	-2.87	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-3.02	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-3.08	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-3.17	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-3.33	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-3.45	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-3.34	Note:	Not Reported
Level reading date:	1950-07-13	Feet below surface:	Not Reported
Feet to sea level:	-3.25	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-3.15	Note:	Not Reported
Level reading date:	1950-06-13	Feet below surface:	Not Reported
Feet to sea level:	-3.17	Note:	Not Reported
Level reading date:	1950-06-01	Feet below surface:	Not Reported
Feet to sea level:	-3.04	Note:	Not Reported

Level reading date:	1950-05-18	Feet below surface:	Not Reported
Feet to sea level:	-3.10	Note:	Not Reported
Level reading date:	1950-05-04	Feet below surface:	Not Reported
Feet to sea level:	-3.13	Note:	Not Reported
Level reading date:	1950-04-17	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1950-03-30	Feet below surface:	Not Reported
Feet to sea level:	-3.25	Note:	Not Reported
Level reading date:	1950-03-16	Feet below surface:	Not Reported
Feet to sea level:	-3.34	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1950-02-09	Feet below surface:	Not Reported
Feet to sea level:	-3.52	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-3.57	Note:	Not Reported
Level reading date:	1950-01-12	Feet below surface:	Not Reported
Feet to sea level:	-3.68	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-3.75	Note:	Not Reported
Level reading date:	1949-11-01	Feet below surface:	Not Reported
Feet to sea level:	-3.97	Note:	Not Reported
Level reading date:	1949-10-17	Feet below surface:	Not Reported
Feet to sea level:	-4.08	Note:	Not Reported
Level reading date:	1949-09-29	Feet below surface:	Not Reported
Feet to sea level:	-4.20	Note:	Not Reported
Level reading date:	1949-09-20	Feet below surface:	Not Reported
Feet to sea level:	-4.29	Note:	Not Reported
Level reading date:	1949-09-01	Feet below surface:	Not Reported
Feet to sea level:	-4.50	Note:	Not Reported
Level reading date:	1949-08-19	Feet below surface:	Not Reported
Feet to sea level:	-4.15	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-4.64	Note:	Not Reported
Level reading date:	1949-07-14	Feet below surface:	Not Reported
Feet to sea level:	-4.66	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-4.77	Note:	Not Reported
Level reading date:	1949-06-16	Feet below surface:	Not Reported
Feet to sea level:	-4.71	Note:	Not Reported
Level reading date:	1949-06-02	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported

Level reading date:	1949-05-12	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1949-04-29	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	-5.14	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1949-03-21	Feet below surface:	Not Reported
Feet to sea level:	-5.54	Note:	Not Reported
Level reading date:	1949-03-02	Feet below surface:	Not Reported
Feet to sea level:	-5.72	Note:	Not Reported
Level reading date:	1949-02-15	Feet below surface:	Not Reported
Feet to sea level:	-5.89	Note:	Not Reported
Level reading date:	1949-01-29	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1949-01-14	Feet below surface:	Not Reported
Feet to sea level:	-6.26	Note:	Not Reported
Level reading date:	1948-12-29	Feet below surface:	Not Reported
Feet to sea level:	-6.47	Note:	Not Reported
Level reading date:	1948-12-13	Feet below surface:	Not Reported
Feet to sea level:	-6.62	Note:	Not Reported
Level reading date:	1948-11-24	Feet below surface:	Not Reported
Feet to sea level:	-6.79	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-7.07	Note:	Not Reported
Level reading date:	1948-10-21	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported
Level reading date:	1948-10-05	Feet below surface:	Not Reported
Feet to sea level:	-7.54	Note:	Not Reported
Level reading date:	1948-09-23	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported
Level reading date:	1948-09-07	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1948-08-23	Feet below surface:	Not Reported
Feet to sea level:	-8.24	Note:	Not Reported
Level reading date:	1948-08-10	Feet below surface:	Not Reported
Feet to sea level:	-8.42	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-8.58	Note:	Not Reported
Level reading date:	1948-07-14	Feet below surface:	Not Reported
Feet to sea level:	-8.06	Note:	Not Reported

Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-8.86	Note:	Not Reported
Level reading date:	1948-06-10	Feet below surface:	Not Reported
Feet to sea level:	-9.06	Note:	Not Reported
Level reading date:	1948-05-22	Feet below surface:	Not Reported
Feet to sea level:	-9.30	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-9.54	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-9.95	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-10.18	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-10.42	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-10.77	Note:	Not Reported
Level reading date:	1948-02-14	Feet below surface:	Not Reported
Feet to sea level:	-10.54	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-11.23	Note:	Not Reported
Level reading date:	1947-12-18	Feet below surface:	Not Reported
Feet to sea level:	-12.04	Note:	Not Reported
Level reading date:	1947-11-28	Feet below surface:	Not Reported
Feet to sea level:	-12.31	Note:	Not Reported
Level reading date:	1947-10-29	Feet below surface:	Not Reported
Feet to sea level:	-12.97	Note:	Not Reported
Level reading date:	1947-10-20	Feet below surface:	Not Reported
Feet to sea level:	-13.18	Note:	Not Reported
Level reading date:	1947-10-13	Feet below surface:	Not Reported
Feet to sea level:	-13.33	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-13.51	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-14.10	Note:	Not Reported
Level reading date:	1947-08-28	Feet below surface:	Not Reported
Feet to sea level:	-14.40	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-14.73	Note:	Not Reported
Level reading date:	1947-07-31	Feet below surface:	Not Reported
Feet to sea level:	-14.91	Note:	Not Reported

Level reading date:	1947-07-21	Feet below surface:	Not Reported
Feet to sea level:	-15.16	Note:	Not Reported
Level reading date:	1947-07-15	Feet below surface:	Not Reported
Feet to sea level:	-15.33	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-15.57	Note:	Not Reported

12
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000828399**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 45. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	284	Well Hole Depth Units:	ft

13
WSW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000231**

Well Number:	K003579	Owner:	Classic Sayville Car Wash
Well Depth:	50	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

D14
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828291**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3258. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	70
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	6	Level reading date:	1981-09-23
Feet below surface:	Not Reported	Feet to sea level:	12.54
Note:	Well was plugged and not in hydraulic contact with formation..		
Level reading date:	1981-02-25	Feet below surface:	Not Reported
Feet to sea level:	12.81	Note:	Not Reported

Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	14.66	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	16.21	Note:	Not Reported
Level reading date:	1980-06-20	Feet below surface:	Not Reported
Feet to sea level:	15.29	Note:	Not Reported
Level reading date:	1980-06-10	Feet below surface:	Not Reported
Feet to sea level:	15.16	Note:	Not Reported

D15
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000828292**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3300. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

E16
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000827895**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 332. 1	Type:	Well
Description:	2301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

17
ESE
1/2 - 1 Mile
Lower

NY WELLS **NYREG1000000197**

Well Number:	K003547	Owner:	M And B Cement
Well Depth:	75	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E18
SSW
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000827850**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 533. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	295
Well Depth Units:	ft	Well Hole Depth:	395
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	55	Level reading date:	1948-08-20
Feet below surface:	Not Reported	Feet to sea level:	-7.51
Note:	Not Reported		

Level reading date:	1948-08-13	Feet below surface:	Not Reported
Feet to sea level:	-7.63	Note:	Not Reported
Level reading date:	1948-08-06	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1948-07-30	Feet below surface:	Not Reported
Feet to sea level:	-7.88	Note:	Not Reported
Level reading date:	1948-07-23	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1948-07-16	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1948-07-09	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1948-07-02	Feet below surface:	Not Reported
Feet to sea level:	-8.32	Note:	Not Reported
Level reading date:	1948-06-25	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1948-06-18	Feet below surface:	Not Reported
Feet to sea level:	-8.52	Note:	Not Reported
Level reading date:	1948-06-11	Feet below surface:	Not Reported
Feet to sea level:	-8.54	Note:	Not Reported
Level reading date:	1948-06-05	Feet below surface:	Not Reported
Feet to sea level:	-8.57	Note:	Not Reported
Level reading date:	1948-05-29	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1948-05-24	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported

Level reading date:	1948-05-15	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1948-05-08	Feet below surface:	Not Reported
Feet to sea level:	-9.08	Note:	Not Reported
Level reading date:	1948-05-01	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1948-04-24	Feet below surface:	Not Reported
Feet to sea level:	-9.35	Note:	Not Reported
Level reading date:	1948-04-17	Feet below surface:	Not Reported
Feet to sea level:	-9.54	Note:	Not Reported
Level reading date:	1948-04-10	Feet below surface:	Not Reported
Feet to sea level:	-9.68	Note:	Not Reported
Level reading date:	1948-04-03	Feet below surface:	Not Reported
Feet to sea level:	-9.83	Note:	Not Reported
Level reading date:	1948-03-27	Feet below surface:	Not Reported
Feet to sea level:	-9.85	Note:	Not Reported
Level reading date:	1948-03-20	Feet below surface:	Not Reported
Feet to sea level:	-10.06	Note:	Not Reported
Level reading date:	1948-03-13	Feet below surface:	Not Reported
Feet to sea level:	-10.21	Note:	Not Reported
Level reading date:	1948-03-06	Feet below surface:	Not Reported
Feet to sea level:	-10.34	Note:	Not Reported
Level reading date:	1948-02-28	Feet below surface:	Not Reported
Feet to sea level:	-10.41	Note:	Not Reported
Level reading date:	1948-02-21	Feet below surface:	Not Reported
Feet to sea level:	-10.65	Note:	Not Reported
Level reading date:	1948-02-14	Feet below surface:	Not Reported
Feet to sea level:	-10.62	Note:	Not Reported
Level reading date:	1948-02-07	Feet below surface:	Not Reported
Feet to sea level:	-10.86	Note:	Not Reported
Level reading date:	1948-01-31	Feet below surface:	Not Reported
Feet to sea level:	-11.01	Note:	Not Reported
Level reading date:	1948-01-24	Feet below surface:	Not Reported
Feet to sea level:	-11.15	Note:	Not Reported
Level reading date:	1948-01-17	Feet below surface:	Not Reported
Feet to sea level:	-11.21	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-18.83	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-19.19	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-19.19	Note:	Not Reported

Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-19.23	Note:	Not Reported
Level reading date:	1945-03-05	Feet below surface:	Not Reported
Feet to sea level:	-17.30	Note:	Not Reported
Level reading date:	1945-02-06	Feet below surface:	Not Reported
Feet to sea level:	-20.00	Note:	Not Reported
Level reading date:	1945-01-03	Feet below surface:	Not Reported
Feet to sea level:	-20.07	Note:	Not Reported
Level reading date:	1944-12-02	Feet below surface:	Not Reported
Feet to sea level:	-20.21	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-20.81	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-20.89	Note:	Not Reported
Level reading date:	1944-09-01	Feet below surface:	Not Reported
Feet to sea level:	-21.10	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-21.15	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-21.00	Note:	Not Reported
Level reading date:	1944-06-03	Feet below surface:	Not Reported
Feet to sea level:	-21.09	Note:	Not Reported
Level reading date:	1944-04-25	Feet below surface:	Not Reported
Feet to sea level:	-21.00	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-21.04	Note:	Not Reported
Level reading date:	1944-03-06	Feet below surface:	Not Reported
Feet to sea level:	-21.06	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-21.21	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-21.32	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-21.63	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-21.77	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-22.72	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-22.36	Note:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

19
NNW
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000828659**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1236. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	82
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	442	Level reading date:	1976-06-28
Feet below surface:	Not Reported	Feet to sea level:	12.98
Note:	Not Reported		

Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	12.60	Note:	Not Reported
Level reading date:	1975-12-17	Feet below surface:	Not Reported
Feet to sea level:	12.30	Note:	Not Reported
Level reading date:	1975-10-07	Feet below surface:	Not Reported
Feet to sea level:	12.04	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	11.75	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	11.75	Note:	Not Reported
Level reading date:	1974-12-19	Feet below surface:	Not Reported
Feet to sea level:	11.73	Note:	Not Reported
Level reading date:	1974-09-04	Feet below surface:	Not Reported
Feet to sea level:	11.59	Note:	Not Reported
Level reading date:	1974-06-28	Feet below surface:	Not Reported
Feet to sea level:	11.49	Note:	Not Reported
Level reading date:	1974-03-20	Feet below surface:	Not Reported
Feet to sea level:	11.41	Note:	Not Reported
Level reading date:	1974-01-08	Feet below surface:	Not Reported
Feet to sea level:	11.35	Note:	Not Reported
Level reading date:	1973-09-24	Feet below surface:	Not Reported
Feet to sea level:	11.41	Note:	Not Reported
Level reading date:	1973-07-02	Feet below surface:	Not Reported
Feet to sea level:	11.39	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	11.35	Note:	Not Reported

Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	10.22	Note:	Not Reported
Level reading date:	1972-09-29	Feet below surface:	Not Reported
Feet to sea level:	11.39	Note:	Not Reported
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	11.85	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	12.60	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	11.42	Note:	Not Reported
Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	9.27	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	7.52	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	8.91	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	9.37	Note:	Not Reported
Level reading date:	1969-11-12	Feet below surface:	Not Reported
Feet to sea level:	6.96	Note:	Not Reported
Level reading date:	1969-09-05	Feet below surface:	Not Reported
Feet to sea level:	6.54	Note:	Not Reported
Level reading date:	1969-08-04	Feet below surface:	Not Reported
Feet to sea level:	6.40	Note:	Not Reported
Level reading date:	1969-07-02	Feet below surface:	Not Reported
Feet to sea level:	6.30	Note:	Not Reported
Level reading date:	1969-05-28	Feet below surface:	Not Reported
Feet to sea level:	6.09	Note:	Not Reported
Level reading date:	1969-04-22	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	1969-04-01	Feet below surface:	Not Reported
Feet to sea level:	5.96	Note:	Not Reported
Level reading date:	1969-01-08	Feet below surface:	Not Reported
Feet to sea level:	5.88	Note:	Not Reported
Level reading date:	1968-12-03	Feet below surface:	Not Reported
Feet to sea level:	5.88	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	5.98	Note:	Not Reported
Level reading date:	1968-09-30	Feet below surface:	Not Reported
Feet to sea level:	5.89	Note:	Not Reported
Level reading date:	1968-08-28	Feet below surface:	Not Reported
Feet to sea level:	5.90	Note:	Not Reported

Level reading date:	1968-07-29	Feet below surface:	Not Reported
Feet to sea level:	5.80	Note:	Not Reported
Level reading date:	1968-06-26	Feet below surface:	Not Reported
Feet to sea level:	5.65	Note:	Not Reported
Level reading date:	1968-05-28	Feet below surface:	Not Reported
Feet to sea level:	5.48	Note:	Not Reported
Level reading date:	1968-04-23	Feet below surface:	Not Reported
Feet to sea level:	5.42	Note:	Not Reported
Level reading date:	1968-03-29	Feet below surface:	Not Reported
Feet to sea level:	5.30	Note:	Not Reported
Level reading date:	1968-02-29	Feet below surface:	Not Reported
Feet to sea level:	5.15	Note:	Not Reported
Level reading date:	1968-02-05	Feet below surface:	Not Reported
Feet to sea level:	5.13	Note:	Not Reported
Level reading date:	1968-01-02	Feet below surface:	Not Reported
Feet to sea level:	5.02	Note:	Not Reported
Level reading date:	1967-11-29	Feet below surface:	Not Reported
Feet to sea level:	4.95	Note:	Not Reported
Level reading date:	1967-10-23	Feet below surface:	Not Reported
Feet to sea level:	4.78	Note:	Not Reported
Level reading date:	1967-09-26	Feet below surface:	Not Reported
Feet to sea level:	4.71	Note:	Not Reported
Level reading date:	1967-09-07	Feet below surface:	Not Reported
Feet to sea level:	4.61	Note:	Not Reported
Level reading date:	1967-07-28	Feet below surface:	Not Reported
Feet to sea level:	4.49	Note:	Not Reported
Level reading date:	1967-07-06	Feet below surface:	Not Reported
Feet to sea level:	4.39	Note:	Not Reported
Level reading date:	1967-05-31	Feet below surface:	Not Reported
Feet to sea level:	4.24	Note:	Not Reported
Level reading date:	1967-05-04	Feet below surface:	Not Reported
Feet to sea level:	4.14	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.90	Note:	Not Reported
Level reading date:	1967-02-24	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1967-01-31	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1966-12-23	Feet below surface:	Not Reported
Feet to sea level:	4.12	Note:	Not Reported
Level reading date:	1966-12-01	Feet below surface:	Not Reported
Feet to sea level:	4.11	Note:	Not Reported

Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	4.25	Note:	Not Reported
Level reading date:	1966-09-30	Feet below surface:	Not Reported
Feet to sea level:	4.38	Note:	Not Reported
Level reading date:	1966-08-29	Feet below surface:	Not Reported
Feet to sea level:	4.42	Note:	Not Reported
Level reading date:	1966-07-29	Feet below surface:	Not Reported
Feet to sea level:	4.36	Note:	Not Reported
Level reading date:	1966-06-27	Feet below surface:	Not Reported
Feet to sea level:	4.47	Note:	Not Reported
Level reading date:	1966-05-26	Feet below surface:	Not Reported
Feet to sea level:	4.44	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	4.52	Note:	Not Reported
Level reading date:	1966-03-30	Feet below surface:	Not Reported
Feet to sea level:	4.27	Note:	Not Reported
Level reading date:	1966-03-12	Feet below surface:	Not Reported
Feet to sea level:	4.28	Note:	Not Reported
Level reading date:	1966-01-28	Feet below surface:	Not Reported
Feet to sea level:	4.36	Note:	Not Reported
Level reading date:	1965-12-30	Feet below surface:	Not Reported
Feet to sea level:	4.41	Note:	Not Reported
Level reading date:	1965-12-02	Feet below surface:	Not Reported
Feet to sea level:	4.43	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	4.57	Note:	Not Reported
Level reading date:	1965-10-07	Feet below surface:	Not Reported
Feet to sea level:	4.64	Note:	Not Reported
Level reading date:	1965-09-02	Feet below surface:	Not Reported
Feet to sea level:	4.64	Note:	Not Reported
Level reading date:	1965-07-23	Feet below surface:	Not Reported
Feet to sea level:	4.75	Note:	Not Reported
Level reading date:	1965-06-24	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1965-05-24	Feet below surface:	Not Reported
Feet to sea level:	4.74	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	4.72	Note:	Not Reported
Level reading date:	1965-03-25	Feet below surface:	Not Reported
Feet to sea level:	4.78	Note:	Not Reported
Level reading date:	1965-02-24	Feet below surface:	Not Reported
Feet to sea level:	4.95	Note:	Not Reported

Level reading date:	1965-01-29	Feet below surface:	Not Reported
Feet to sea level:	4.86	Note:	Not Reported
Level reading date:	1964-12-31	Feet below surface:	Not Reported
Feet to sea level:	4.91	Note:	Not Reported
Level reading date:	1964-11-25	Feet below surface:	Not Reported
Feet to sea level:	4.94	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	5.00	Note:	Not Reported
Level reading date:	1964-10-01	Feet below surface:	Not Reported
Feet to sea level:	5.13	Note:	Not Reported
Level reading date:	1964-09-02	Feet below surface:	Not Reported
Feet to sea level:	5.18	Note:	Not Reported
Level reading date:	1964-07-27	Feet below surface:	Not Reported
Feet to sea level:	5.20	Note:	Not Reported
Level reading date:	1964-07-06	Feet below surface:	Not Reported
Feet to sea level:	5.20	Note:	Not Reported
Level reading date:	1964-05-28	Feet below surface:	Not Reported
Feet to sea level:	5.15	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	5.02	Note:	Not Reported
Level reading date:	1964-03-30	Feet below surface:	Not Reported
Feet to sea level:	5.00	Note:	Not Reported
Level reading date:	1964-02-28	Feet below surface:	Not Reported
Feet to sea level:	4.93	Note:	Not Reported
Level reading date:	1964-01-28	Feet below surface:	Not Reported
Feet to sea level:	5.11	Note:	Not Reported
Level reading date:	1963-12-31	Feet below surface:	Not Reported
Feet to sea level:	4.96	Note:	Not Reported
Level reading date:	1963-12-05	Feet below surface:	Not Reported
Feet to sea level:	5.02	Note:	Not Reported
Level reading date:	1963-10-26	Feet below surface:	Not Reported
Feet to sea level:	5.14	Note:	Not Reported
Level reading date:	1963-09-30	Feet below surface:	Not Reported
Feet to sea level:	5.29	Note:	Not Reported
Level reading date:	1963-09-03	Feet below surface:	Not Reported
Feet to sea level:	5.49	Note:	Not Reported
Level reading date:	1963-07-30	Feet below surface:	Not Reported
Feet to sea level:	5.34	Note:	Not Reported
Level reading date:	1963-07-02	Feet below surface:	Not Reported
Feet to sea level:	5.28	Note:	Not Reported
Level reading date:	1963-06-03	Feet below surface:	Not Reported
Feet to sea level:	5.27	Note:	Not Reported

Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	5.24	Note:	Not Reported
Level reading date:	1963-03-29	Feet below surface:	Not Reported
Feet to sea level:	5.54	Note:	Not Reported
Level reading date:	1963-02-28	Feet below surface:	Not Reported
Feet to sea level:	5.59	Note:	Not Reported
Level reading date:	1963-01-03	Feet below surface:	Not Reported
Feet to sea level:	5.67	Note:	Not Reported
Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	5.55	Note:	Not Reported
Level reading date:	1962-11-06	Feet below surface:	Not Reported
Feet to sea level:	5.41	Note:	Not Reported
Level reading date:	1962-10-03	Feet below surface:	Not Reported
Feet to sea level:	5.55	Note:	Not Reported
Level reading date:	1962-08-31	Feet below surface:	Not Reported
Feet to sea level:	5.47	Note:	Not Reported
Level reading date:	1962-07-30	Feet below surface:	Not Reported
Feet to sea level:	5.32	Note:	Not Reported
Level reading date:	1962-07-02	Feet below surface:	Not Reported
Feet to sea level:	5.19	Note:	Not Reported
Level reading date:	1962-05-29	Feet below surface:	Not Reported
Feet to sea level:	5.37	Note:	Not Reported
Level reading date:	1962-05-01	Feet below surface:	Not Reported
Feet to sea level:	5.26	Note:	Not Reported
Level reading date:	1962-03-27	Feet below surface:	Not Reported
Feet to sea level:	5.20	Note:	Not Reported
Level reading date:	1962-03-05	Feet below surface:	Not Reported
Feet to sea level:	5.45	Note:	Not Reported
Level reading date:	1962-01-31	Feet below surface:	Not Reported
Feet to sea level:	5.64	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	5.68	Note:	Not Reported
Level reading date:	1961-11-28	Feet below surface:	Not Reported
Feet to sea level:	4.81	Note:	Not Reported
Level reading date:	1961-10-31	Feet below surface:	Not Reported
Feet to sea level:	4.73	Note:	Not Reported
Level reading date:	1961-10-20	Feet below surface:	Not Reported
Feet to sea level:	4.73	Note:	Not Reported
Level reading date:	1961-08-30	Feet below surface:	Not Reported
Feet to sea level:	4.74	Note:	Not Reported
Level reading date:	1961-08-01	Feet below surface:	Not Reported
Feet to sea level:	4.43	Note:	Not Reported

Level reading date:	1961-06-27	Feet below surface:	Not Reported
Feet to sea level:	6.23	Note:	Not Reported
Level reading date:	1961-05-31	Feet below surface:	Not Reported
Feet to sea level:	4.41	Note:	Not Reported
Level reading date:	1961-04-26	Feet below surface:	Not Reported
Feet to sea level:	4.17	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	3.83	Note:	Not Reported
Level reading date:	1961-03-01	Feet below surface:	Not Reported
Feet to sea level:	3.84	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	4.13	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.26	Note:	Not Reported
Level reading date:	1960-12-07	Feet below surface:	Not Reported
Feet to sea level:	4.14	Note:	Not Reported
Level reading date:	1960-11-02	Feet below surface:	Not Reported
Feet to sea level:	3.44	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	3.36	Note:	Not Reported
Level reading date:	1960-08-30	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported
Level reading date:	1960-07-19	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	2.98	Note:	Not Reported
Level reading date:	1960-06-02	Feet below surface:	Not Reported
Feet to sea level:	2.71	Note:	Not Reported
Level reading date:	1960-05-04	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1960-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.03	Note:	Not Reported
Level reading date:	1960-01-27	Feet below surface:	Not Reported
Feet to sea level:	3.22	Note:	Not Reported
Level reading date:	1960-01-05	Feet below surface:	Not Reported
Feet to sea level:	3.22	Note:	Not Reported
Level reading date:	1959-12-01	Feet below surface:	Not Reported
Feet to sea level:	3.55	Note:	Not Reported
Level reading date:	1959-11-02	Feet below surface:	Not Reported
Feet to sea level:	3.49	Note:	Not Reported
Level reading date:	1959-10-06	Feet below surface:	Not Reported
Feet to sea level:	3.63	Note:	Not Reported

Level reading date:	1959-09-03	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1959-08-04	Feet below surface:	Not Reported
Feet to sea level:	4.20	Note:	Not Reported
Level reading date:	1959-07-07	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1959-06-02	Feet below surface:	Not Reported
Feet to sea level:	3.10	Note:	Not Reported
Level reading date:	1959-05-06	Feet below surface:	Not Reported
Feet to sea level:	3.11	Note:	Not Reported
Level reading date:	1959-04-03	Feet below surface:	Not Reported
Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1959-03-02	Feet below surface:	Not Reported
Feet to sea level:	3.05	Note:	Not Reported
Level reading date:	1959-01-29	Feet below surface:	Not Reported
Feet to sea level:	2.93	Note:	Not Reported
Level reading date:	1959-01-07	Feet below surface:	Not Reported
Feet to sea level:	2.90	Note:	Not Reported
Level reading date:	1958-12-09	Feet below surface:	Not Reported
Feet to sea level:	2.76	Note:	Not Reported
Level reading date:	1958-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.72	Note:	Not Reported
Level reading date:	1958-10-07	Feet below surface:	Not Reported
Feet to sea level:	2.46	Note:	Not Reported
Level reading date:	1958-08-28	Feet below surface:	Not Reported
Feet to sea level:	2.38	Note:	Not Reported
Level reading date:	1958-07-29	Feet below surface:	Not Reported
Feet to sea level:	2.34	Note:	Not Reported
Level reading date:	1958-06-30	Feet below surface:	Not Reported
Feet to sea level:	2.45	Note:	Not Reported
Level reading date:	1958-05-29	Feet below surface:	Not Reported
Feet to sea level:	2.41	Note:	Not Reported
Level reading date:	1958-05-01	Feet below surface:	Not Reported
Feet to sea level:	1.82	Note:	Not Reported
Level reading date:	1958-04-02	Feet below surface:	Not Reported
Feet to sea level:	2.13	Note:	Not Reported
Level reading date:	1958-03-03	Feet below surface:	Not Reported
Feet to sea level:	2.14	Note:	Not Reported
Level reading date:	1958-01-28	Feet below surface:	Not Reported
Feet to sea level:	2.11	Note:	Not Reported
Level reading date:	1957-12-31	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported

Level reading date:	1957-11-22	Feet below surface:	Not Reported
Feet to sea level:	2.04	Note:	Not Reported
Level reading date:	1957-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.07	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	1.97	Note:	Not Reported
Level reading date:	1957-08-27	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported
Level reading date:	1957-07-24	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.37	Note:	Not Reported
Level reading date:	1957-05-28	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1957-04-24	Feet below surface:	Not Reported
Feet to sea level:	2.48	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1957-02-27	Feet below surface:	Not Reported
Feet to sea level:	2.39	Note:	Not Reported
Level reading date:	1957-01-25	Feet below surface:	Not Reported
Feet to sea level:	2.66	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	2.36	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	2.30	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	2.08	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	2.00	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	1.92	Note:	Not Reported
Level reading date:	1956-07-11	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	2.12	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	1.87	Note:	Not Reported
Level reading date:	1956-03-06	Feet below surface:	Not Reported
Feet to sea level:	1.87	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported

Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	1.56	Note:	Not Reported
Level reading date:	1955-11-07	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1955-10-05	Feet below surface:	Not Reported
Feet to sea level:	0.95	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	0.77	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	0.72	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	0.90	Note:	Not Reported
Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	0.95	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	0.66	Note:	Not Reported
Level reading date:	1955-03-24	Feet below surface:	Not Reported
Feet to sea level:	0.68	Note:	Not Reported
Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	0.96	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	0.74	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	0.37	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	0.28	Note:	Not Reported
Level reading date:	1954-10-28	Feet below surface:	Not Reported
Feet to sea level:	-0.10	Note:	Not Reported
Level reading date:	1954-10-05	Feet below surface:	Not Reported
Feet to sea level:	-0.08	Note:	Not Reported
Level reading date:	1954-08-25	Feet below surface:	Not Reported
Feet to sea level:	0.04	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	0.04	Note:	Not Reported
Level reading date:	1954-07-01	Feet below surface:	Not Reported
Feet to sea level:	0.34	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	0.58	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	0.13	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	0.01	Note:	Not Reported

Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	0.45	Note:	Not Reported
Level reading date:	1953-12-26	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1953-12-22	Feet below surface:	Not Reported
Feet to sea level:	-0.62	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported
Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	-1.22	Note:	Not Reported
Level reading date:	1953-10-01	Feet below surface:	Not Reported
Feet to sea level:	-1.25	Note:	Not Reported
Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	-1.52	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-1.52	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-1.50	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-1.57	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.06	Note:	Not Reported
Level reading date:	1953-03-25	Feet below surface:	Not Reported
Feet to sea level:	-2.82	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	-3.22	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-3.07	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-4.01	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-4.82	Note:	Not Reported
Level reading date:	1952-09-22	Feet below surface:	Not Reported
Feet to sea level:	-5.24	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-5.47	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-5.91	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-6.27	Note:	Not Reported

Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-6.62	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-7.12	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-7.40	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-7.75	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-8.31	Note:	Not Reported
Level reading date:	1951-09-11	Feet below surface:	Not Reported
Feet to sea level:	-8.37	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-8.46	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-8.44	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-8.29	Note:	Not Reported
Level reading date:	1951-05-01	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-8.84	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-8.59	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-8.56	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-9.38	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-9.56	Note:	Not Reported

Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-9.50	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-9.42	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-9.37	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-9.40	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-9.21	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-8.80	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-9.28	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-9.66	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-9.71	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-9.89	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-10.11	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-10.69	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-10.90	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-11.21	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-11.41	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-11.44	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-11.99	Note:	Not Reported
Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-12.09	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-12.57	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-13.19	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-13.57	Note:	Not Reported

Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-13.72	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-14.04	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-14.42	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-14.31	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-14.95	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-15.19	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-15.47	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-15.74	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-16.00	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-15.99	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-16.33	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-16.47	Note:	Not Reported
Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-17.10	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-17.14	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-17.09	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-17.83	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-18.02	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-18.02	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-17.57	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-18.13	Note:	Not Reported

Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-18.07	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-18.23	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-18.18	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-18.24	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-18.20	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-18.11	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-18.25	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-18.23	Note:	Not Reported
Level reading date:	1947-05-07	Feet below surface:	Not Reported
Feet to sea level:	-18.29	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-18.19	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-18.06	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-18.21	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-18.10	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-18.06	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-17.97	Note:	Not Reported
Level reading date:	1946-09-26	Feet below surface:	Not Reported
Feet to sea level:	-17.95	Note:	Not Reported
Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-17.86	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-17.79	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-17.84	Note:	Not Reported

Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-17.84	Note:	Not Reported
Level reading date:	1946-05-10	Feet below surface:	Not Reported
Feet to sea level:	-17.81	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-17.74	Note:	Not Reported
Level reading date:	1946-03-15	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1946-02-14	Feet below surface:	Not Reported
Feet to sea level:	-17.52	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-17.58	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-17.72	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-18.07	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-18.26	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-18.15	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-18.09	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-17.92	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-17.52	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-17.75	Note:	Not Reported
Level reading date:	1945-04-04	Feet below surface:	Not Reported
Feet to sea level:	-17.64	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-17.65	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-17.92	Note:	Not Reported
Level reading date:	1944-12-06	Feet below surface:	Not Reported
Feet to sea level:	-18.11	Note:	Not Reported
Level reading date:	1944-10-27	Feet below surface:	Not Reported
Feet to sea level:	-18.45	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-18.68	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-18.69	Note:	Not Reported

Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-18.14	Note:	Not Reported
Level reading date:	1944-07-05	Feet below surface:	Not Reported
Feet to sea level:	-18.49	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-17.93	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-18.32	Note:	Not Reported
Level reading date:	1944-04-01	Feet below surface:	Not Reported
Feet to sea level:	-18.49	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-18.96	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-19.12	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-18.89	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-19.11	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-18.97	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-18.58	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-18.54	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-18.16	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-18.15	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-17.84	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-17.99	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-18.25	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-18.29	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-18.47	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-18.56	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-18.41	Note:	Not Reported

Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-18.66	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-18.68	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-18.72	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-18.76	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-18.77	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-18.83	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-18.89	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-19.00	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-19.05	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-19.10	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-19.07	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-18.96	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-19.01	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-18.98	Note:	Not Reported
Level reading date:	1942-08-31	Feet below surface:	Not Reported
Feet to sea level:	-18.95	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-18.89	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-18.73	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-18.82	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-18.55	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-18.73	Note:	Not Reported

Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-18.69	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-18.71	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-18.35	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-18.41	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-18.35	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-18.23	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-18.16	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-18.11	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-18.10	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-18.12	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-18.12	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-18.13	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-18.16	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-18.18	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-18.35	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-18.23	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-18.26	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-18.26	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-18.26	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-18.34	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-18.38	Note:	Not Reported

Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-18.44	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-18.50	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-18.48	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-18.52	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-18.54	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-18.39	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-18.62	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-18.66	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-18.80	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-18.76	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-18.81	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-18.85	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-18.65	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-18.76	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-19.17	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-19.06	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-19.18	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-19.42	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-19.24	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-19.12	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-19.02	Note:	Not Reported

Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-19.19	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-19.06	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-18.92	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-18.81	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-18.79	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-18.75	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-18.44	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-18.48	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-18.51	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-18.41	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-18.27	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-18.17	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-17.56	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-17.41	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-17.42	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-17.46	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-17.43	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-17.47	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-17.54	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-17.56	Note:	Not Reported

Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-17.60	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-17.64	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-17.67	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-17.71	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-17.75	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-17.80	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-17.82	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-17.88	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX C

Freedom of Information Law Letters and Responses

From: donotreply@records.nyc.gov
To: Stephen Loonie
Subject: [OpenRecords] Request FOIL-2023-057-13946 Submitted to New York City Fire Department (FDNY)
Date: Wednesday, October 18, 2023 10:38:49 AM

This message originated outside your organization. Please use caution!

Your request FOIL-2023-057-13946 has been successfully submitted to the New York City Fire Department (FDNY). The details of your request are shown below.

Request Title: 2014 - 2042 Fulton Street, Brooklyn, NY

Request Description: Other Request

Request Type: Other Request

Other Request
Submission Method: Online/At Home
Description of Records: Any environmental documents (tank records, petroleum storage, hazardous chemical storage, petroleum or chemical spills or releases, Phase I reports, Phase II reports, soil analytical data, groundwater analytical data, soil vapor analytical data, environmental permits, environmental compliance and enforcement, environmental violations, discharge permits, RCRA and SARA law related documents, manifests, etc.) related to the property located at 2014 – 2042 Fulton Street in Brooklyn, New York (Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map). The entire property consists of a vacant 0.85-acre lot owned by the NYC Department of Housing Preservation and Development. No spills were identified in a preliminary search of the property.

Requester's Contact Information

Name:
Stephen Loonie
Title:
Not provided
Organization:
Roux Associates, Inc
Email:
sloonie@rouxinc.com
Phone Number:
(516) 320-5957
Fax Number:
Not provided
Street Address (line 1):
209 Shafter Street
Street Address (line 2):
Not provided
City:
Islandia
State:

NY
Zip Code:
11749

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2023-057-13946.

From: donotreply@records.nyc.gov
To: Stephen Loonie
Subject: [OpenRecords] Request FOIL-2023-826-04568 Submitted to Department of Environmental Protection (DEP)
Date: Wednesday, October 18, 2023 10:31:57 AM

This message originated outside your organization. Please use caution!

Your request FOIL-2023-826-04568 has been successfully submitted to the Department of Environmental Protection (DEP). The details of your request are shown below.

Request Title: 2014 - 2042 Fulton Street, Brooklyn, NY

Request Description: Any environmental documents (tank records, petroleum storage, hazardous chemical storage, petroleum or chemical spills or releases, Phase I reports, Phase II reports, soil analytical data, groundwater analytical data, soil vapor analytical data, environmental permits, environmental compliance and enforcement, environmental violations, discharge permits, RCRA and SARA law related documents, manifests, etc.) related to the property located at 2014 – 2042 Fulton Street in Brooklyn, New York (Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map). The entire property consists of a vacant 0.85-acre lot owned by the NYC Department of Housing Preservation and Development. No spills were identified in a preliminary search of the property.

Requester's Contact Information

Name:
Stephen Loonie
Title:
Not provided
Organization:
Roux Associates, Inc
Email:
sloonie@rouxinc.com
Phone Number:
(516) 320-5957
Fax Number:
Not provided
Street Address (line 1):
209 Shafter Street
Street Address (line 2):
Not provided
City:
Islandia
State:
NY
Zip Code:
11749

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2023-826-04568.

Form 54-155M-705277(60) 114

DEPARTMENT OF BUILDINGS

ck BOROUGH OF Brooklyn , THE CITY OF NEW YORK

No. 178321

Date JAN 18 1962

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered ~~building~~ building—premises located at

2024 Fulton Street, south side 200' West of Saratoga Avenue Block 1549 Lot 25

conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ Alt. No.— 1930-1960 Construction classification— non-fireproof

Occupancy classification— Class "A" Multiple Dwelling - converted Height 3 stories, 36 feet

Date of completion— const. 11-17-61 . Located in business Use District.

C Area Height Zone at time of issuance of permit

plumb. 11-15-61 P. S. 1-15-62

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground	-	-	-	ordinary
First	40	-	-	-	one (1) family and Doctor's office
Second	40	-	-	-	two (2) families
Third	40	-	-	-	two (2) families

TOTAL:- Five (5) families and Doctor's office

CLASS "A" MULTIPLE DWELLING - converted

CERTIFICATE OF APPROVAL #4066 ISSUED DECEMBER 19, 1961 - (fuel oil)

THIS CERTIFICATE SHALL ALSO BE CONSIDERED A CERTIFICATE OF COMPLIANCE UNDER SECTION 301 OF THE MULTIPLE DWELLING LAW.

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

B Form 54C (Rev. 11-71)-106M-702729(71) THE CITY OF NEW YORK

HOUSING AND DEVELOPMENT ADMINISTRATION

DEPARTMENT OF BUILDINGS

CERTIFICATE OF OCCUPANCY

BOROUGH BROOKLYN DATE: AUG 30 1977 NO. 215865

This certificate supersedes C.O. No. ZONING DISTRICT

THIS CERTIFIES that the new—altered—existing—building—premises located at Block 1618 Lot C2-3 in R-6

2036 Fulton Street

CONFORMS SUBSTANTIALLY TO THE APPROVED PLANS AND SPECIFICATIONS AND TO THE REQUIREMENTS OF ALL APPLICABLE LAWS, RULES AND REGULATIONS FOR THE USES AND OCCUPANCIES SPECIFIED HEREIN

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOAD LBS. PER SQ. FT.	MAXIMUM NO. OF PERSONS PERMITTED	ZONING DWELLING OR ROOMING UNITS	BUILDING CODE HABITABLE ROOMS	ZONING USE GROUP	BUILDING CODE OCCUPANCY GROUP	DESCRIPTION OF USE
Cellar							Storage
1st	100	3					Store U.G. 6
2nd	40						Vacant
3rd	40						Vacant
4th							Vacant
		Total:	Store Vacant (Upper Floors to Remain				
				Old-Code			

OPEN SPACE USES _____

(SPECIFY—PARKING SPACES, LOADING BERTHS, OTHER USES, NONE)

NO CHANGES OF USE OR OCCUPANCY SHALL BE MADE UNLESS A NEW AMENDED CERTIFICATE OF OCCUPANCY IS OBTAINED

THIS CERTIFICATE OF OCCUPANCY IS ISSUED SUBJECT TO FURTHER LIMITATIONS, CONDITIONS AND SPECIFICATIONS NOTED ON THE REVERSE SIDE.

Philip E. Olen JEREMIAH T. WALSH

BOROUGH SUPERINTENDENT COMMISSIONER

OFFICE COPY—DEPARTMENT OF BUILDINGS

THE CITY OF NEW YORK

HOUSING AND DEVELOPMENT ADMINISTRATION

CERTIFICATE OF OCCUPANCY

DATE ISSUED NO. 41306

THAT THE ZONING LOT ON WHICH THE PREMISES IS LOCATED IS BOUNDED AS FOLLOWS:

BEGINNING at a point on the South side of Fulton Street distant 69 feet from the corner formed by the intersection of Fulton Street and Saratoga Avenue

running thence West 20 feet; thence South 80 feet;

thence East 20 feet; thence North 80 feet;

thence ..... feet; thence ..... feet;

thence ..... feet; thence ..... feet;

thence ..... feet; thence ..... feet;

to the point or place of beginning.

N.B. or ALT. No. 2276/64 DATE OF COMPLETION 3/17/76 CONSTRUCTION CLASSIFICATION Class 3 N.F.P.

BUILDING OCCUPANCY GROUP CLASSIFICATION HEIGHT STORIES 4 FEET. 40

THE FOLLOWING FIRE DETECTION AND EXTINGUISHING SYSTEMS ARE REQUIRED AND WERE INSTALLED IN COMPLIANCE WITH APPLICABLE LAWS.

	YES	NO		YES	NO
STANDPIPE SYSTEM			AUTOMATIC SPRINKLER SYSTEM		
YARD HYDRANT SYSTEM					
STANDPIPE FIRE TELEPHONE AND SIGNALLING SYSTEM					
SMOKE DETECTOR					
FIRE ALARM AND SIGNAL SYSTEM					

STORM DRAINAGE DISCHARGES INTO:

A) STORM SEWER ☐ B) COMBINED SEWER ☐ C) PRIVATE SEWAGE DISPOSAL SYSTEM ☐

SANITARY DRAINAGE DISCHARGES INTO:

A) SANITARY SEWER ☐ B) COMBINED SEWER ☐ C) PRIVATE SEWAGE DISPOSAL SYSTEM ☐

LIMITATIONS OR RESTRICTIONS:

BOARD OF STANDARDS AND APPEALS CAL. NO. _____

CITY PLANNING COMMISSION CAL. NO. _____

OTHERS:

15A-0625-35 M.

DUPLICATE

CITY OF NEW YORK

No. 71266

OFFICE OF THE PRESIDENT OF THE BOROUGH OF BROOKLYN

BUREAU OF BUILDINGS

DATE June 29-1933

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standard and Appeals July 22, 1932, and issued pursuant to Section 411-a Greater New York Charter and Chapter 5, Building Code, Code of Ordinances, City of New York.)

This certificate supersedes all previously issued certificates.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~NEW~~ ALTERED —BUILDING—PREMISES

3038 Dist. 3

Located at 2036 A Fulton Street s/s 40'-0" W/o Saratoga Ave

Block 1549, Lot 32, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and CERTIFIES FURTHER that, any provisions of law relating to standpipe and sprinkler equipment have been complied with as certified by a report of the Fire Commissioner to the Superintendent of Buildings.

THIS CERTIFICATE IS ISSUED SUBJECT TO THE LIMITATIONS HEREINAFTER SPECIFIED AND TO THE FOLLOWING RESOLUTIONS OF THE BOARD OF STANDARDS AND APPEALS:
(Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS LBS. PER SQ. FT.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar					Ordinary Trades
~~Basement~~					
First					Store & tenement
Second					
Third					
Fourth					
~~Fifth~~					
Sixth	Roof	None			Tenement

Permit No. 4286 33 Type of Construction Brick

Height 4 stories, ~~—~~ feet. Date of completion, construction 6-29-33

Located in Business zone at time of issuance of permit. plumbing

(OVER)

NO CHANGE OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE SUPERINTENDENT OF BUILDINGS.

Unless an approval for the same has been obtained from the superintendent of buildings, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified above; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof, from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the tenement house commissioner unless it is also approved and endorsed by him; and it must be replaced by a full certificate at the date of its expiration.

Examined by

.....

Per.....

.....
Superintendent of Buildings.
Borough of Brooklyn.

Additional copies of this certificate will be issued, upon written request, to persons having an interest in the building or premises.

From: New York DEC FOIL Center
To: Stephen Loonie
Subject: FOIL Request :: W122367-101823
Date: Wednesday, October 18, 2023 10:31:26 AM

This message originated outside your organization. Please use caution!

Dear Stephen:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 10/18/2023 and given the reference number FOIL #W122367-101823 for tracking purposes. You may expect the Department's response to your request no later than **11/15/2023**.

Record Requested: **Any environmental documents (tank records, petroleum storage, hazardous chemical storage, petroleum or chemical spills or releases, Phase I reports, Phase II reports, soil analytical data, groundwater analytical data, soil vapor analytical data, environmental permits, environmental compliance and enforcement, environmental violations, discharge permits, RCRA and SARA law related documents, manifests, etc.) related to the property located at 2014 – 2042 Fulton Street in Brooklyn, New York (Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map). The entire property consists of a vacant 0.85-acre lot owned by the NYC Department of Housing Preservation and Development. No spills were identified in a preliminary search of the property.**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

Click here to login to the FOIL Center.

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://newyorkdec.govqa.us/WEBAPP//_rs/RequestEdit.aspx?rid=122367

From: noreply@its.ny.gov
To: Stephen Loonie
Subject: FOIL Request Confirmation from Open FOIL NY
Date: Wednesday, October 18, 2023 10:30:59 AM

This message originated outside your organization. Please use caution!

Thank you for submitting your FOIL request through Open FOIL NY.

Here is your Open FOIL NY confirmation information for future reference:

LOONIE_DOH_20231018103047196

INFORMATION SUBMITTED:

Records Requested From	Department of Health
Short Title	2014 - 2042 Fulton Street, Brooklyn, NY
Description	Any environmental documents (tank records, petroleum storage, hazardous chemical storage, petroleum or chemical spills or releases, Phase I reports, Phase II reports, soil analytical data, groundwater analytical data, soil vapor analytical data, environmental permits, environmental compliance and enforcement, environmental violations, discharge permits, RCRA and SARA law related documents, manifests, etc.) related to the property located at 2014 – 2042 Fulton Street in Brooklyn, New York (Block 1549 Lots 18, 19, 20, 21, 22, 23, 24, 25, 26, 28, 29, 30, 31, 32, 33, 34, and 35 on the New York City Tax Map). The entire property consists of a vacant 0.85-acre lot owned by the NYC Department of Housing Preservation and Development. No spills were identified in a preliminary search of the property.
Uploaded Files	
FOIL Response Format	Email
If fees apply, please contact me if costs will be greater than	$

Your FOIL request has been forwarded to the organization(s) you selected, and the respective Records Access Officer will contact you directly for further processing of your request. Please allow up to five business days for such communication(s). For your convenience, here is additional contact

information:

Department of Health
Corning Tower
Room 2364
Albany, NY 12237-0044

APPENDIX D

Historical Sanborn Maps

2014 Fulton Street

2014 Fulton Street

Brooklyn, NY 11233

Inquiry Number: 7438000.3

September 08, 2023

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

09/08/23

Site Name:

2014 Fulton Street
2014 Fulton Street
Brooklyn, NY 11233
EDR Inquiry # 7438000.3

Client Name:

Roux Associates
209 Shafter Street
Islandia, NY 11749
Contact: Stephen Loonie

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Roux Associates were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # ED42-4AD8-8668

PO # NA

Project NA

Maps Provided:

2007	1994	1980	1932
2006	1993	1979	1908
2005	1992	1978	1888
2004	1991	1976	
2003	1989	1965	
2002	1988	1963	
2001	1987	1962	
1995	1982	1951	

Sanborn® Library search results

Certification #: ED42-4AD8-8668

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Roux Associates (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


2007 Source Sheets




Volume 7, Sheet 7
2007




Volume 5, Sheet 63
2007



Volume 5, Sheet 64
2007




Volume 7, Sheet 8
2007




Volume 7, Sheet 6
2007


2006 Source Sheets




Volume 7, Sheet 6
2006




Volume 7, Sheet 8
2006



Volume 5, Sheet 64
2006



Volume 5, Sheet 63
2006





Volume 7, Sheet 7
2006


Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2005 Source Sheets



Volume 7, Sheet 7
2005



Volume 5, Sheet 63
2005



Volume 5, Sheet 64
2005



Volume 7, Sheet 8
2005


2004 Source Sheets


Volume 5, Sheet 63
2004



Volume 5, Sheet 64
2004



Volume 7, Sheet 7
2004



Volume 7, Sheet 8
2004



Volume 7, Sheet 6
2004


2003 Source Sheets


Volume 7, Sheet 6
2003



Volume 7, Sheet 8
2003



Volume 7, Sheet 7
2003



Volume 5, Sheet 63
2003



Volume 5, Sheet 64
2003


2002 Source Sheets


Volume 5, Sheet 63
2002


Volume 7, Sheet 7
2002


Volume 5, Sheet 64
2002



Volume 7, Sheet 8
2002


Volume 7, Sheet 6
2002


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


2001 Source Sheets




Volume 5, Sheet 64
2001



Volume 7, Sheet 8
2001




Volume 7, Sheet 7
2001




Volume 5, Sheet 63
2001


1995 Source Sheets




Volume 5, Sheet 63
1995-Nov




Volume 5, Sheet 64
1995-Nov




Volume 5, Sheet 63
1995-Jan




Volume 5, Sheet 64
1995-Jan



Volume 7, Sheet 6
1995



Volume 7, Sheet 8
1995





Volume 7, Sheet 7
1995


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1994 Source Sheets



Volume 7, Sheet 7
1994


Volume 7, Sheet 8
1994



Volume 7, Sheet 6
1994

1993 Source Sheets



Volume 7, Sheet 8
1993



Volume 5, Sheet 64
1993



Volume 7, Sheet 7
1993



Volume 5, Sheet 63
1993

1992 Source Sheets



Volume 5, Sheet 63
1992



Volume 7, Sheet 7
1992


Volume 7, Sheet 8
1992



Volume 5, Sheet 64
1992

1991 Source Sheets


Volume 7, Sheet 8
1991


Volume 5, Sheet 64
1991



Volume 7, Sheet 7
1991


Volume 5, Sheet 63
1991


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1989 Source Sheets




Volume 7, Sheet 7
1989




Volume 7, Sheet 8
1989


1988 Source Sheets




Volume 7, Sheet 7
1988




Volume 5, Sheet 63
1988



Volume 7, Sheet 8
1988




Volume 5, Sheet 64
1988




Volume 7, Sheet 6
1988


1987 Source Sheets




Volume 7, Sheet 8
1987



Volume 5, Sheet 64
1987




Volume 7, Sheet 7
1987




Volume 5, Sheet 63
1987


1982 Source Sheets




Volume 5, Sheet 63
1982



Volume 7, Sheet 8
1982



Volume 7, Sheet 7
1982




Volume 7, Sheet 6
1982

Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1982 Source Sheets




Volume 5, Sheet 64
1982

1980 Source Sheets




Volume 7, Sheet 8
1980




Volume 7, Sheet 6
1980



Volume 7, Sheet 7
1980




Volume 5, Sheet 63
1980




Volume 5, Sheet 64
1980


1979 Source Sheets




Volume 7, Sheet 8
1979




Volume 5, Sheet 64
1979



Volume 5, Sheet 63
1979



Volume 7, Sheet 7
1979




Volume 7, Sheet 6
1979


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1978 Source Sheets




Volume 7, Sheet 6
1978




Volume 5, Sheet 62
1978



Volume 7, Sheet 7
1978



Volume 5, Sheet 63
1978




Volume 7, Sheet 8
1978




Volume 5, Sheet 64
1978

1976 Source Sheets




Volume 5, Sheet 64
1976




Volume 5, Sheet 63
1976


1965 Source Sheets




Volume 5, Sheet 63
1965



Volume 7, Sheet 7
1965



Volume 7, Sheet 8
1965




Volume 5, Sheet 64
1965

Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1965 Source Sheets




Volume 7, Sheet 6
1965


1963 Source Sheets



Volume 7, Sheet 6
1963




Volume 7, Sheet 8
1963




Volume 7, Sheet 7
1963

1962 Source Sheets




Volume 5, Sheet 63
1962




Volume 5, Sheet 64
1962


1951 Source Sheets




Volume 5, Sheet 63
1951



Volume 7, Sheet 7
1951



Volume 5, Sheet 64
1951




Volume 7, Sheet 8
1951


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1932 Source Sheets




Volume 5, Sheet 64
1932



Volume 7, Sheet 7
1932




Volume 5, Sheet 63
1932




Volume 7, Sheet 8
1932


1908 Source Sheets




Volume 5, Sheet 54
1908



Volume 7, Sheet 16
1908




Volume 7, Sheet 17
1908



Volume 5, Sheet 53
1908

1888 Source Sheets



Volume 7, Sheet 173
1888



Volume 5, Sheet 121
1888



Volume 5, Sheet 123
1888




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 7, Sheet 6
Volume 7, Sheet 8
Volume 5, Sheet 64
Volume 5, Sheet 63
Volume 7, Sheet 7

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #	ED42-4AD8-8668
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 7
Volume 5, Sheet 63
Volume 5, Sheet 64
Volume 7, Sheet 8
Volume 7, Sheet 6

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 8
Volume 5, Sheet 64
Volume 5, Sheet 63
Volume 7, Sheet 7

0 Feet 150 300 600

N

Certified Sanborn® Map

2004




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #	ED42-4AD8-8668
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 6
Volume 7, Sheet 8
Volume 7, Sheet 7
Volume 5, Sheet 64
Volume 5, Sheet 63

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 5, Sheet 64
Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 7, Sheet 8
Volume 7, Sheet 6

N

Certified Sanborn® Map

2002



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 7, Sheet 6
Volume 7, Sheet 8
Volume 5, Sheet 64
Volume 7, Sheet 7
Volume 5, Sheet 63

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #	ED42-4AD8-8668
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 7, Sheet 8
Volume 5, Sheet 64

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

©1995 Sanborn Co., EDR Sanborn, Inc.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1995




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

©1995 Sanborn Co., EDR Sanborn, Inc.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1995




©1995 Sanborn Co., EDR Sanborn, Inc.

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1995




©1995 Sanborn Co., EDR Sanborn, Inc.

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name: 2014 Fulton Street
Address: 2014 Fulton Street
City, ST, ZIP: Brooklyn, NY 11233
Client: Roux Associates
EDR Inquiry: 7438000.3
Order Date: 09/08/2023
Certification #: ED42-4AD8-8668
Copyright 1995




©1995 Sanborn Co., EDR Sanborn, Inc.

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name: 2014 Fulton Street
Address: 2014 Fulton Street
City, ST, ZIP: Brooklyn, NY 11233
Client: Roux Associates
EDR Inquiry: 7438000.3
Order Date: 09/08/2023
Certification #: ED42-4AD8-8668
Copyright 1995




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 6
Volume 7, Sheet 8
Volume 7, Sheet 7

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 5, Sheet 64
Volume 7, Sheet 8

N

Certified Sanborn® Map

1992




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 64
Volume 7, Sheet 8
Volume 7, Sheet 7
Volume 5, Sheet 63

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 5, Sheet 64
Volume 7, Sheet 8

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 8
Volume 7, Sheet 7

0 Feet 150 300 600

N

Certified Sanborn® Map

1988




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 6
Volume 5, Sheet 64
Volume 7, Sheet 8
Volume 5, Sheet 63
Volume 7, Sheet 7

0 Feet 150 300 600

N

Certified Sanborn® Map

1987




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 5, Sheet 64
Volume 7, Sheet 8

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #	ED42-4AD8-8668
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 5, Sheet 64
Volume 7, Sheet 6
Volume 7, Sheet 7
Volume 7, Sheet 8
Volume 5, Sheet 63

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 64
Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 7, Sheet 6
Volume 7, Sheet 8

0 Feet 150 300 600

N

Certified Sanborn® Map

1979




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 6
Volume 7, Sheet 7
Volume 5, Sheet 63
Volume 5, Sheet 64
Volume 7, Sheet 8

0 Feet 150 300 600

N

Certified Sanborn® Map

1978




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 64
Volume 7, Sheet 8
Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 5, Sheet 62
Volume 7, Sheet 6

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #	ED42-4AD8-8668
Copyright	1976

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 5, Sheet 63
Volume 5, Sheet 64

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 6
Volume 5, Sheet 64
Volume 7, Sheet 8
Volume 7, Sheet 7
Volume 5, Sheet 63

0 Feet 150 300 600

N



Certification #ED42-4AD8-8668


The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1963

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 7, Sheet 7
Volume 7, Sheet 8
Volume 7, Sheet 6

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #	ED42-4AD8-8668
Copyright	1962

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 64
Volume 5, Sheet 63

0 Feet 150 300 600

N

Certified Sanborn® Map

1951



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 7, Sheet 8
Volume 5, Sheet 64
Volume 7, Sheet 7
Volume 5, Sheet 63

N

Certified Sanborn® Map

1932




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1932

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 8
Volume 5, Sheet 63
Volume 7, Sheet 7
Volume 5, Sheet 64

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #ED42-4AD8-8668

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1908

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 53
Volume 7, Sheet 17
Volume 7, Sheet 16
Volume 5, Sheet 54

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	2014 Fulton Street
Address:	2014 Fulton Street
City, ST, ZIP:	Brooklyn, NY 11233
Client:	Roux Associates
EDR Inquiry:	7438000.3
Order Date:	09/08/2023
Certification #:	ED42-4AD8-8668
Copyright	1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 5, Sheet 123
Volume 5, Sheet 121
Volume 7, Sheet 173

0 Feet 150 300 600

N

APPENDIX E

Historical Aerial Maps

2014 Fulton Street

2014 Fulton Street

Brooklyn, NY 11233

Inquiry Number: 7438000.8

September 08, 2023

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

09/08/23

Site Name:

2014 Fulton Street
2014 Fulton Street
Brooklyn, NY 11233
EDR Inquiry # 7438000.8

Client Name:

Roux Associates
209 Shafter Street
Islandia, NY 11749
Contact: Stephen Loonie

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 04, 1994	USGS/DOQQ
1984	1"=500'	Flight Date: March 26, 1984	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1976	1"=500'	Flight Date: October 29, 1976	USGS
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: April 12, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: January 04, 1954	USGS
1951	1"=500'	Flight Date: April 21, 1951	EDR Proprietary Aerial Viewpoint
1924	1"=500'	Flight Date: July 01, 1924	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 7438000.8
YEAR: 2019
= 500'
N
EDR



INQUIRY #: 7438000.8
YEAR: 2015
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 2011
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 1994
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 1984
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 1980
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 1976
= 500'
N
EDR



INQUIRY #: 7438000.8

YEAR: 1966

= 500'

N

EDR


INQUIRY #: 7438000.8
YEAR: 1961
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 1954
= 500'
N
EDR


INQUIRY #: 7438000.8
YEAR: 1951
= 500'
N
EDR



INQUIRY #: 7438000.8

YEAR: 1924

= 500'

N

EDR

APPENDIX F

Historical Topographic Maps

2014 Fulton Street

2014 Fulton Street

Brooklyn, NY 11233

Inquiry Number: 7438000.4

September 07, 2023

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

09/07/23

Site Name:

2014 Fulton Street
2014 Fulton Street
Brooklyn, NY 11233
EDR Inquiry # 7438000.4

Client Name:

Roux Associates
209 Shafter Street
Islandia, NY 11749
Contact: Stephen Loonie

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Roux Associates were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA

Project: NA

Coordinates:

Latitude:	40.678407 40° 40' 42" North
Longitude:	-73.917617 -73° 55' 3" West
UTM Zone:	Zone 18 North
UTM X Meters:	591471.91
UTM Y Meters:	4503621.39
Elevation:	79.74' above sea level

Maps Provided:

2019	1900
2016	1898
2013	1897
1995	
1979	
1967	
1956	
1947	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets




Brooklyn
2019
7.5-minute, 24000

2016 Source Sheets




Brooklyn
2016
7.5-minute, 24000

2013 Source Sheets



Brooklyn
2013
7.5-minute, 24000

1995 Source Sheets




Brooklyn
1995
7.5-minute, 24000
Aerial Photo Revised 1977

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979 Source Sheets




Brooklyn
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1967 Source Sheets



Brooklyn
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1956 Source Sheets



Brooklyn
1956
7.5-minute, 24000

1947 Source Sheets



Brooklyn
1947
7.5-minute, 24000
Aerial Photo Revised 1940

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets



Brooklyn
1900
15-minute, 62500

1898 Source Sheets



Brooklyn
1898
15-minute, 62500


1897 Source Sheets



Brooklyn
1897
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Brooklyn, 2019, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2016, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5


NW N NE
W E
SW S SE

TP, Brooklyn, 2013, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N


Ridgewood
Bushwick
Bedford-Stuyvesant
Broadway Junction
Eastern Parkway
Brownsville
East Ne
Trinity Cemetery
Evergreens Cemetery
Mount Judah Cemetery
Union Field Cemetery
Knollwood Park Cemetery
Bushwick High Sch
East Voc High Sch
Jefferson High Sch
Maxwell Voc High Sch
Hamilton Voc High Sch
Lutheran Hosp
St Marys Hosp
Unity Hosp
Wyckoff Heights Hosp
Arena
Orthopedic Hospital
Carson Beck Mem Hosp
Jewish Hospital for Chronic Diseases
Kingston Avenue Hospital
Brooklyn State Hospital
The Brookdale Hospital Center
Lincoln Terrace Park
Fulton Park
Thoracic Hospital
Jamaica
Highland
Interborough Pkwy
Queens Blvd
Atlantic
Broadway
Fulton
Myrtle
Flushing
Rockaway
Hopkinson
Pitkin
Sutter
Belmont
Livonia
Dumont
Glenmore
Liberty
Wyona
Alabama
Powell
Stone
Blake
Riverdale
Newport
Lott
Stanley
Sumpter
Hull
Herkimer
Macon
Halsey
Decatur
Madison
Hancock
Patchen
Ralph
Saratoga
Rockaway
Utica
Schenectady
Albany
Kingston
Buffalo
Rochester
New York
Nostrand
Classon
Remsen
Rutland Road
Winthrop
Ocean
Flatbush
Bergen
Prospect
Lefferts
Underhill
Washington
Irving Square
Playground
Park
Library
Armory
Police Sta
Fire Sta
Hospital
Athletic Field
Recreation Center
Dept of Health
Pumping Sta
Holy Martyrs Sch
Our Lady of Lourdes Sch
Holy Rosary Sch
Rochel Girls Sch
St Barbaras Sch
St Martins Sch
St Malachys Sch
Loreto Sch
St Benedicts Sch
Jr Academy
St Johns Prep Sch
St Josephs Hall
All Saints High Sch
St Brigids Sch
Evergreen Park
Browe Park
St Johns Park
Marcus Garvey Park
Playgrounds
JHS 57
JHS 178
JHS 55
JHS 210
JHS 263
JHS 149
JHS 232
JHS 275
PS 26
PS 21
PS 5
PS 137
PS 227
PS 87
PS 155
PS 191
PS 144
PS 167
PS 327
PS 328
PS 156
PS 183
PS 41
PS 165
PS 235
PS 268
PS 219
PS 232
PS 63
PS 68
PS 77
PS 106
PS 116
PS 45
PS 83
PS 91
PS 93
PS 289
PS 243
PS 309
PS 304
PS 44
PS 262
PS 49
PS 28
PS 150
PS 174
PS 182
PS 298
PS 76
PS 86
PS 111
PS 145
PS 120
PS 59
PS 24
PS 81
PS 79
PS 25
PS 274
PS 299
PS 365
PS 258
PS 85
PS 73
PS 178
PS 144
PS 191
PS 210
PS 167
PS 91
PS 235
PS 232
PS 219
PS 268
PS 165
PS 183
PS 41
PS 156
PS 175
PS 327
PS 328
PS 263
PS 298
PS 63
PS 68
PS 77
PS 106
PS 116
PS 45
PS 137
PS 227
PS 87
PS 155
PS 191
PS 144



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1979, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1967, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N



This report includes information from the following map sheet(s).

TP, Brooklyn, 1956, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Brooklyn, 1947, 7.5-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N

Historical Topo Map

1900



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1900, 15-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1898, 15-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1897, 15-minute

SITE NAME: 2014 Fulton Street
ADDRESS: 2014 Fulton Street
Brooklyn, NY 11233
CLIENT: Roux Associates

N

APPENDIX G

City Directory Abstract

2014 Fulton Street
2014 Fulton Street
Brooklyn, NY 11233

Inquiry Number: 7438000.5
September 13, 2023

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at approximately five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through current. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

Summary information obtained is provided in the text of this report.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2020	EDR Digital Archive	-	X	X	-
2017	Cole Information	-	X	X	-
2014	Cole Information	-	X	X	-
2010	Cole Information	-	X	X	-
2005	Cole Information	-	X	X	-
	Hill-Donnelly Corporation	-	X	X	-
2000	Cole Information	-	X	X	-
	Cole Information Services	-	X	X	-
1997	NYNEX	-	X	X	-
1995	Cole Information	-	X	X	-
1992	Cole Information	-	X	X	-
	NYNEX Informantion Resource Co.	-	X	X	-
1985	NYNEX Information Resources Company	-	X	X	-
1980	New York Telephone	-	X	X	-
1976	New York Telephone	-	X	X	-
1973	New York Telephone	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1970	New York Telephone	-	X	X	-
1965	New York Telephone	X	X	X	-
1960	New York Telephone	X	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	X	X	X	-
1945	New York Telephone	X	X	X	-
1940	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	X	X	X	-
1928	New York Telephone	X	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
2014 Fulton Street	Client Entered	
224 Saratoga Avenue	Client Entered	
231 Saratoga Avenue	Client Entered	
1079 Herkimer Street	Client Entered	
1961 Fulton Street	Client Entered	

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

2014 Fulton Street
Brooklyn, NY 11233

FINDINGS DETAIL

Target Property research detail.

FULTON

2014 FULTON

Year	*Uses*	*Source*
1960	JACOBS JAS	New York Telephone
	RIFKIN HARRY CARTNS	New York Telephone
	Jacobs Jas	New York Telephone Company
	Rifkin Harry cartns	New York Telephone Company
1949	Brown Minnie Mrs	New York Telephone Company
1945	Brown Minnie Mrs	New York Telephone
1940	Brown Minnie Mrs	New York Telephone
1934	BROWN GEO LAB H	R. L. Polk & Co.
	CANTY JOHN R	R. L. Polk & Co.
	CANTY SIMON PNTR R	R. L. Polk & Co.
	WALKER ROBT HLPR H	R. L. Polk & Co.
1928	FOSTER WILTON R	New York Telephone

FULTON St

2014 FULTON St

Year	*Uses*	*Source*
1965	Amen Leona	New York Telephone
	Jacobs Jas E	New York Telephone

FINDINGS

Fulton Street

2014 Fulton Street

Year	*Uses*	*Source*

Saratoga

224 Saratoga

Year	*Uses*	*Source*
1965	Hudson Cassan	New York Telephone
1960	Jordan C	New York Telephone Company
	Martin Ferdinand	New York Telephone Company
1934	MADELONI ANDREW INSPR H	R. L. Polk & Co.
	MORLLE JOS SHOE REPR H	R. L. Polk & Co.
	STORA NUNZIO FORMN H	R. L. Polk & Co.
	STORO NUNZIO H	R. L. Polk & Co.

Saratoga Avenue

224 Saratoga Avenue

Year	*Uses*	*Source*

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

FULTON

1941 FULTON

Year	Uses	Source
1997	BENNETT B	NYNEX
1985	DANIELS LAWRENCE	NYNEX Information Resources Company
1960	MARSHALL RUDOLPH	New York Telephone
	SIMS SALLIE M	New York Telephone
	Marshall Rudolph	New York Telephone Company
	Sims Sallie M	New York Telephone Company
1934	HAYLING THEO LAB H	R. L. Polk & Co.

1943 FULTON

Year	Uses	Source
1960	WORMSER DAVID	New York Telephone
	Wormser David	New York Telephone Company
1945	Wormsley Davild	New York Telephone
1940	Wormsley David	New York Telephone
1934	MSNGR H	R. L. Polk & Co.
	R	R. L. Polk & Co.
1928	WORMSLEY DAVID R	New York Telephone

1945 FULTON

Year	Uses	Source
1960	KELLY JOHN STATNRY	New York Telephone
	Kelly John statnry	New York Telephone Company
1949	Kelly John statnry	New York Telephone Company
1945	Kelly John statnry	New York Telephone
1940	Kelly John statnry	New York Telephone
1934	BURKE MICHL J CIGARS H DO	R. L. Polk & Co.
	SHANNON JACK PORTER R	R. L. Polk & Co.

Year	Uses	Source
1934	SHANNON LOUIS GARMENTWKR R	R. L. Polk & Co.
	SHANNON ROSE H	R. L. Polk & Co.
	SHANNON RUTH BKPR R	R. L. Polk & Co.
	SHANNON SALLY PNTR R	R. L. Polk & Co.

Fulton

1961 Fulton

Year	Uses	Source
1997	JOHNSON Leroy	NYNEX
1992	HOMEBOY VIDEO	NYNEX Informantion Resource Co.
1970	Davis Joseph rl est	New York Telephone
1965	Bargain Hse	New York Telephone
1934	LAGRAVINESE JOHN SHOE REPRNG H DO	R. L. Polk & Co.

FULTON

2002 FULTON

Year	Uses	Source
1976	JENKINS EMMA MRS	New York Telephone
1960	FULTON BEAUTY SALON	New York Telephone
	NEWKIRK ELMIRA BTY SIN	New York Telephone
	Fulton Beauty Salon	New York Telephone Company
	New kirk Elmira bty sin	New York Telephone Company
	NEWELL ORR & WALSH INC flrg	New York Telephone Company
1949	Fulton Beauty Salon	New York Telephone Company
	New kirk Elmira bty sin	New York Telephone Company
	NEWCAL CORP armtrs	New York Telephone Company
1945	Fulton Beauty Salon	New York Telephone
	New kirk Elmira bty sln	New York Telephone
	NY X Ray Lab Inc	New York Telephone
1940	Fulton Beauty Salon	New York Telephone
	New kirk Elmira bty sln	New York Telephone
	NY X Ray Lab Inc	New York Telephone
1934	MCCONKEY NATHAN LAB H	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	STANLEY JOHN PORTER R	R. L. Polk & Co.
1928	DREW CHAS R	New York Telephone
	WALD I DRY GDS	New York Telephone

2004 FULTON

Year	Uses	Source
1992	PRESCOTT AUTOMATIC TRANSMISSIONS	NYNEX Informantion Resource Co.
1985	PRESCOTT AUTOMATIC TRANSMISSIONS	NYNEX Information Resources Company
1934	BOHLINGER MICHL H	R. L. Polk & Co.

2006 FULTON

Year	Uses	Source
1992	CANARSIE FUEL	NYNEX Informantion Resource Co.
1985	CANARSIE FUEL	NYNEX Information Resources Company
1980	J MEHR ICE & ICE CUBE CO INC	New York Telephone
1976	J MEHR ICE & ICECUBE CO INC	New York Telephone
1960	TANNENBAUM S FUEL CORP	New York Telephone
	Tannenbaum S Fuel Corp	New York Telephone Company
1949	Tannenbaum S coal fuel	New York Telephone Company
1945	Tannenbaum S coal fuel	New York Telephone
1940	Tannenbaum S coal fuel	New York Telephone
1934	MOHRMANN S JOHN SONS COAL AND ICE	R. L. Polk & Co.
1928	MOHRMANN S JOHN SONS COAL & ICE	New York Telephone

2008 FULTON

Year	Uses	Source
1992	FERGUSON L	NYNEX Informantion Resource Co.
1980	SOUND NOOM THE	New York Telephone
1960	BOYCE CEBERT	New York Telephone
	DAVIS ELSIE B	New York Telephone
	WILLIAMS LUCINDA	New York Telephone
	Boyce Cebert	New York Telephone Company
	Davis Elsie B	New York Telephone Company
	Williams Lucinda	New York Telephone Company

FINDINGS

Year	Uses	Source
1934	ELDRIDGE ANN MRS DOM R	R. L. Polk & Co.
	GORDON ABR TAILOR H	R. L. Polk & Co.
	GORDON DAVID SCALE MECH R	R. L. Polk & Co.
	GORDON HAROLD HEAD MAILING DEPT R	R. L. Polk & Co.
	GORDON HYMAN SLSMN R	R. L. Polk & Co.
	THOMAS RALPH CHAUF H	R. L. Polk & Co.
1928	BOGER S E R	New York Telephone
	GORDON A CLNG & DYNG	New York Telephone

2010 FULTON

Year	Uses	Source
1985	UNIVERSAL MISSION CHURCH	NYNEX Information Resources Company
1976	COBB DAISY REV	New York Telephone
1960	BARNETT LUCY MRS	New York Telephone
	Barnett Lucy Mrs	New York Telephone Company
1940	Musa Louis	New York Telephone
1934	CEPHES EDW SCAKE MN H	R. L. Polk & Co.
	ROBERTSON EDW DOM H	R. L. Polk & Co.
	STJOHNS BAPTIST CHURCH	R. L. Polk & Co.
	SMITH WALTER LAB R	R. L. Polk & Co.
	SMITH WALTER E STUDENT R	R. L. Polk & Co.
	TINSLEY	R. L. Polk & Co.
1928	BALZHISER PHARMACY	New York Telephone

2012 FULTON

Year	Uses	Source
1992	SCIENCE OF LIFE TEMPLE INC	NYNEX Informantion Resource Co.
1985	SCIENCE OF LIFE TEMPLE INC	NYNEX Information Resources Company
1976	SCIENCE OF LIFE TEMPLE INC	New York Telephone
	SHANNON HERBERT	New York Telephone
1960	WALKER WM J MRS	New York Telephone
	Walker Wm J Mrs	New York Telephone Company
1945	Walker Wm J Mrs	New York Telephone
1940	Cohen David tnsmth	New York Telephone

FINDINGS

Year	Uses	Source
1940	Walker Wm J	New York Telephone
1934	BRYANT FRANCES H	R. L. Polk & Co.
	WASHINGTON H	R. L. Polk & Co.
1928	COHEN D TINSMITH	New York Telephone
	MOSLEY SARAH A MRS R	New York Telephone

2016 FULTON

Year	Uses	Source
1976	SMITH CARRIE	New York Telephone
1960	KENT BOB	New York Telephone
	Kent Bob	New York Telephone Company
1934	GOODMAN DANL COOK R	R. L. Polk & Co.
	HOWARD JAS LAB H	R. L. Polk & Co.
	MALLON SUSAN MAID R	R. L. Polk & Co.
	YATES HAYWARD CHAUF H	R. L. Polk & Co.
1928	STECHER RALPH C PIANO TUNER	New York Telephone

2018 FULTON

Year	Uses	Source
1960	GRADY JOS	New York Telephone
	Grady Jos	New York Telephone Company
1934	EVANS FRES JANITOR BKN PUB LIBRARY R	R. L. Polk & Co.
	KESSELMAN ANTHONY DRY GDS H DO	R. L. Polk & Co.
	THOMPSON PETER A SLSMN H	R. L. Polk & Co.
1928	ZENO R	New York Telephone
	SPARROW THOS JR R	New York Telephone

2020 FULTON

Year	Uses	Source
1992	GUTIERREZ F	NYNEX Information Resource Co.
1960	DELARUE JIMMIE	New York Telephone
	SISTRUNK EVELYN MRS	New York Telephone
	De La Rue Jimmie	New York Telephone Company
	Sistrunk Evelyn Mrs	New York Telephone Company

FINDINGS

Year	Uses	Source
1949	Kesselman Anthony	New York Telephone Company
	Lincoln Trading Co	New York Telephone Company
1945	Kesselman Anthony	New York Telephone
1940	Kesselman Anthony	New York Telephone
1934	KESSELMAN HANNAH MRS DOM R	R. L. Polk & Co.
	KESSELMAN MAY SLSWN R	R. L. Polk & Co.
1928	KESSELMAN ANTHONY DRY GOODS	New York Telephone

2022 FULTON

Year	Uses	Source
1976	BRABHAM EMMA	New York Telephone
	CUSA MARION HOUSING ACTION	New York Telephone
	COLEMAN BETTY	New York Telephone
1960	COHEN D & SONS RFSG & SHEET MTL	New York Telephone
	FULTON SHEET METAL & ROOFING	New York Telephone
	SMITH ADELE M	New York Telephone
	SMITH MARY H	New York Telephone
	Cohen D & Sons rfsg & sheet mtl	New York Telephone Company
	Fulton Sheet Metal & Roofing	New York Telephone Company
	Smith Adele M	New York Telephone Company
	Smith Mary H	New York Telephone Company
1949	Cohen D & Sons tnsmths	New York Telephone Company
1940	Fulton Etching Co	New York Telephone
	Schnaars David R ins	New York Telephone
	Wuttke Chas Inc carpntr & contr	New York Telephone
1934	EVINSON CARRIE H	R. L. Polk & Co.
1928	MULLER HENRY RL EST	New York Telephone

2024 FULTON

Year	Uses	Source
1934	BETHELL FANNIE H	R. L. Polk & Co.
	GELLES MAX NECKTIE MFR	R. L. Polk & Co.
	GREEN F UPHOL R	R. L. Polk & Co.
	HAMLIN JOHN F ELEV OPR H	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1928	BAILEY B W MRS R	New York Telephone
	NEWMAN S & SON PNTS	New York Telephone

2026 FULTON

Year	Uses	Source
1992	DANIELS CHURCH OF GOD IN CHRIST	NYNEX Informantion Resource Co.
1976	DEAN WHOL DSTRBTRS	New York Telephone
1960	NOCKOWITZ MEYER UPHLSTRY	New York Telephone
	Nockowitz Meyer uphlstry	New York Telephone Company
1934	BERLOW ABR RETALL CIGARS	R. L. Polk & Co.
	CHAMBERS LEATHE H	R. L. Polk & Co.
	CHAMBERS LINWOOD JR CLK R	R. L. Polk & Co.
1928	GELMAN SAML CIGARS	New York Telephone

2028 FULTON

Year	Uses	Source
1949	Acme Venetian Blind Mfg Co	New York Telephone Company
1945	Perey Turnstiles The	New York Telephone
1940	Perey Turnstiles The	New York Telephone
1934	SCHEAFER EDW J TURBINE OPR H	R. L. Polk & Co.
1928	PEREY MFG CO TRNSTLS	New York Telephone

2030 FULTON

Year	Uses	Source
1949	CHASIN NOODLE CO	New York Telephone Company
	Pure Home Made Food Prods Co	New York Telephone Company

1955A FULTON

Year	Uses	Source
1934	WOOTEN ELDERT SPL OFFICER H	R. L. Polk & Co.

2012A FULTON

Year	Uses	Source
1960	MC ARTHUR WM	New York Telephone
1934	JACKSON THOS LAB H	R. L. Polk & Co.

FINDINGS

2020A FULTON

Year	*Uses*	*Source*
1976	BODIE JAS REV	New York Telephone
1960	BODIE JAS REV	New York Telephone
1934	EVANS GLENN LAB H	R. L. Polk & Co.

FULTON H

2008 FULTON H

Year	*Uses*	*Source*
1934	GORDON ABR CLO CLEANING DO	R. L. Polk & Co.

FULTON H NEW HYDE PK LI

2022 FULTON H NEW HYDE PK LI

Year	*Uses*	*Source*
1934	MULLER HENRY REAL EST	R. L. Polk & Co.

FULTON PL

2016 FULTON PL

Year	*Uses*	*Source*
1934	HAYES LAURA MRS DOM R	R. L. Polk & Co.

FULTON R BALDWIN LI

2022 FULTON R BALDWIN LI

Year	*Uses*	*Source*
1934	WUTTKE CHAS CARP	R. L. Polk & Co.

FULTON R2221

2012 FULTON R2221

Year	*Uses*	*Source*
1934	COHEN DAVID TINSMITH	R. L. Polk & Co.

FINDINGS

FULTON ST

1941 FULTON ST

Year	Uses	Source
2020	LESLIE DUMMETTE	EDR Digital Archive
	RICHY CRAIG	EDR Digital Archive
2017	RICHARD CRAIG	Cole Information
	ZORENIA GRAY	Cole Information
	LATONYA WALTERS	Cole Information
2014	RICHARD CRAIG	Cole Information
	CRAIG RICHARD	Cole Information
	ZORENIA GRAY	Cole Information
2010	NIA JOHNSON	Cole Information
	RICHARD CRAIG	Cole Information
	JAN GRIFFITH	Cole Information
	CRAIG RICHARD	Cole Information
	ZORENIA GRAY	Cole Information
2005	Craig Richy v V	Hill-Donnelly Corporation
	Griffith Jan	Hill-Donnelly Corporation
	RICHARD CRAIG	Cole Information
2000	B BENNETT	Cole Information
	R JOHNSON	Cole Information
	BERTHA BENNETT	Cole Information
	R JOHNSON	Cole Information
1992	BENNETT, B	Cole Information

FULTON st

1941 FULTON st

Year	Uses	Source
1973	Bennett Chas	New York Telephone
1970	Bennett Chas	New York Telephone

FINDINGS

FULTON St

1941 FULTON St

Year	Uses	Source
1965	Sims Sallie M	New York Telephone

FULTON ST

1943 FULTON ST

Year	Uses	Source
2020	MYLES OJEIKERE	EDR Digital Archive
	OLAYINKA OJEIKERE	EDR Digital Archive
2017	LUYI AJAYI	Cole Information
	TRACY BOWEN	Cole Information
	OLAYINKA OJEIKERE	Cole Information
2014	LUYI AJAYI	Cole Information
	TRACY BOWEN	Cole Information
	OLAYINKA OJEIKERE	Cole Information
2010	ABC WONDERLAND GROUP DAY	Cole Information
	G GARLAND	Cole Information
2005	Garland G	Hill-Donnelly Corporation
	OLAYINKA OJEIKERE	Cole Information

FULTON st

1943 FULTON st

Year	Uses	Source
1970	Dean Wholesale Distribtr papr dir	New York Telephone

FULTON St

1943 FULTON St

Year	Uses	Source
1965	Wormsley David	New York Telephone

FINDINGS

FULTON ST

1945 FULTON ST

Year	Uses	Source
2020	KINZE' MULTI SVC LLC	EDR Digital Archive
	ROLAND ASANTE	EDR Digital Archive
	TEMITOPE ENEVA	EDR Digital Archive
	OMARE KINSEY	EDR Digital Archive
	JULIETTE EZIEFULA	EDR Digital Archive
	BEVERLY ASANTE	EDR Digital Archive
	PAMELA ASANTE	EDR Digital Archive
	GERALD ASANTE	EDR Digital Archive
2017	ROLAND ASANTE	Cole Information
	AVA WILSON	Cole Information
	JULIETTE EZIEFULA	Cole Information
2014	ROLAND ASANTE	Cole Information
	SAADIA GALLIMORE	Cole Information
	ASANTE ROLAND	Cole Information
	JULIETTE EZIEFULA	Cole Information
2010	ROLAND ASANTE	Cole Information
2005	Ajayi Luyi	Hill-Donnelly Corporation
	HAsarnte RA AV	Hill-Donnelly Corporation
	H Ojeikere Omon	Hill-Donnelly Corporation
	h Richardson Y	Hill-Donnelly Corporation
	OJEIKERE OLAYIAKA	Cole Information
	UNIQUE RICHARDSON	Cole Information
	LUYI AJAYI	Cole Information
	GREGORY RICHARDSON	Cole Information

FULTON st

1945 FULTON st

Year	Uses	Source
1970	Kelly John statnry	New York Telephone

FINDINGS

FULTON St

1945 FULTON St

Year	Uses	Source
1965	Kelly John statnry	New York Telephone

FULTON ST

1947 FULTON ST

Year	Uses	Source
2020	ROLAND ASANTE	EDR Digital Archive

2000 FULTON ST

Year	Uses	Source
2020	LOCKS OF NU	EDR Digital Archive
	KAYHAND'S HAIR DESIGN	EDR Digital Archive

2002 FULTON ST

Year	Uses	Source
2020	G G Y B VARIETY STORE	EDR Digital Archive
	CYNTHIA GREER	EDR Digital Archive
	CYNTHIA ISAACS	EDR Digital Archive
2017	GGYB VARIETY STORE	Cole Information
	A EMERGENCY LOCKSMITH	Cole Information
	CYNTHIA ISAACS	Cole Information
2014	GGYB VARIETY STORE	Cole Information
	360 SOUL FOOD CAFE	Cole Information
2010	360 SOUL FOOD CAFE	Cole Information
	360 VIP SOUL FOOD CAFE	Cole Information
	JACQUELINE SIMMONS-GREER	Cole Information
2005	No Current Listing	Hill-Donnelly Corporation
	CYNTHIA GREER-ISAACS	Cole Information
1973	Taylor Emanuel	New York Telephone
1970	Mc Kay Albert	New York Telephone

FINDINGS

2004 FULTON ST

Year	Uses	Source
2017	BEDSTUY CAMPAIGN	Cole Information
2014	BEDSTUY CAMPAIGN	Cole Information
2000	UNITED RECYCLERS	Cole Information
	UNITED RECYCLERS	Cole Information
1992	PRESCOTT AUTOMATIC TRANSMISSIONS	Cole Information
1973	Herskovits Sidney auctnr	New York Telephone
1970	Ceballos Boliyar b	New York Telephone

FULTON St

2004 FULTON St

Year	Uses	Source
1965	CARIBBEAN AUTO PAINTG	New York Telephone

FULTON ST

2006 FULTON ST

Year	Uses	Source
2020	NEW BIRTH DELIVERANCE	EDR Digital Archive
2014	NEW BIRTH DELIVERANCE CHRISTIAN CENT	Cole Information
2010	NEW BIRTH DELIVERANCE	Cole Information
	BB & G PROPERTY MANAGEMENT	Cole Information
2005	Losquardo Ice Co	Hill-Donnelly Corporation
	LOSQUADRO ICE INC	Cole Information
2000	CANARSIE FUEL	Cole Information
	CANARSIE FUEL	Cole Information
1995	CANARSIE FUEL	Cole Information
1992	CANARSIE FUEL	Cole Information
1973	Bolivar Auto Repr	New York Telephone

FINDINGS

FULTON st

2006 FULTON st

Year	Uses	Source
1973	Losquandro Ice Co	New York Telephone
1970	Losquandro Ice Co	New York Telephone

FULTON St

2006 FULTON St

Year	Uses	Source
1965	Tannenbaum S Fuel Corp	New York Telephone

FULTON ST

2008 FULTON ST

Year	Uses	Source
2020	OKEPIX	EDR Digital Archive
	ROMMEL ANDRIES	EDR Digital Archive
	VALLY OKE	EDR Digital Archive
	DEBORAH IRISH	EDR Digital Archive
2017	ORVAL HINDS	Cole Information
	SOLOMON OKE	Cole Information
	BRIAN IRISH	Cole Information
	ANAGHA ONUOHA	Cole Information
2014	ONUOHA ANAGHA	Cole Information
	ORVAL HINDS	Cole Information
	SOLOMON OKE	Cole Information
	ANAGHA ONUOHA	Cole Information
2010	DEBROAH IRISH	Cole Information
	ANAGHA ONUOHA	Cole Information
2005	H Winchester D o	Hill-Donnelly Corporation
	D IRISH	Cole Information
	PHYLLIS GISCOMBE	Cole Information
	KENYA WHITE	Cole Information
	ALVIN STEVENS	Cole Information

FINDINGS

Year	Uses	Source
2005	TRICIA CURTIS	Cole Information
	NADATA SKEETE	Cole Information
	COLLIE ROWE	Cole Information
	CHRIS POST	Cole Information
	WINCHESTER DENNISTON	Cole Information
	DENNISTON WINCHESTER	Cole Information
1997	FLOYD Toni	NYNEX
1992	FERGUSON, L	Cole Information
	RODRIGUEZ, M	Cole Information
	FLOYD, M	Cole Information
1973	Self Help Unit on Narcotics	New York Telephone

FULTON St

2008 FULTON St

Year	Uses	Source
1965	Boyce Cebert	New York Telephone

FULTON ST

2010 FULTON ST

Year	Uses	Source
2020	GRACE INTERNATIONAL INC	EDR Digital Archive
	BEDSTUY CAMPAIGN AGAINST HNGR	EDR Digital Archive
	MY FAVORITE PLACE THRIFT	EDR Digital Archive
	SHAUNE HARRIS	EDR Digital Archive
	DAVE GORDON	EDR Digital Archive
	NELSON PITA	EDR Digital Archive
	STEPHANIE JOSEPHS	EDR Digital Archive
	TIMOTHY PURRIS	EDR Digital Archive
	JODIAN NELSON	EDR Digital Archive
	FRANCES CAMPBELL	EDR Digital Archive
	AMRIA GORDON	EDR Digital Archive
	WINSOME STONER	EDR Digital Archive
2017	BEDSTUY CMPGN AG HNGR	Cole Information

FINDINGS

Year	Uses	Source
2017	MY FAVRT PLACE THRIFT	Cole Information
	MY FAVORITE PLACE THRIFT SHOP	Cole Information
	AMIRA GORDON	Cole Information
	AMRIA GORDOM	Cole Information
	DAVE GORDON	Cole Information
	PITA NELSON	Cole Information
2014	MY FAVRT PLACE THRIFT	Cole Information
	BEDSTUY CAMPAIGN AGAINST HUNGER	Cole Information
	MY FAVORITE PLACE THRIFT SHOP	Cole Information
	JOY STONE	Cole Information
	STEPHANIE JOSEPHS	Cole Information
	NELSON PITA	Cole Information
	FRANCES CAMPBELL	Cole Information
	MARCIA GORDON	Cole Information
	PITA NELSON	Cole Information
	CHRISTINA CASALS	Cole Information
2010	MY FAVORITE PLACE THRIFT	Cole Information
	CHRISTINA CASALS	Cole Information
2005	RAYMOND BROWN	Cole Information
2000	ARTLEY LAWRENCE	Cole Information
	HECTOR MARTINEZ	Cole Information
	EDGAR WALLACE	Cole Information
	GREATER SOY PENTE	Cole Information
	GREATER SOY PENTECOSTAL OUTREACH MINISTRIES	Cole Information
	HECTOR MARTINEZ	Cole Information
	ARTLEY LAWRENCE	Cole Information
	EDGAR WALLACE	Cole Information
1997	LAWRENCE Artle	NYNEX

FINDINGS

FULTON st

2010 FULTON st

Year	Uses	Source
1973	Cobb Daisy Rev	New York Telephone
	Potts Albert	New York Telephone
1970	Cobb Daisy Rev	New York Telephone

FULTON ST

2012 FULTON ST

Year	Uses	Source
2020	VLF MINISTRY	EDR Digital Archive
	HENRY PHIPPS	EDR Digital Archive
	ROSALIE MICKENS	EDR Digital Archive
	JOHN HUGHES	EDR Digital Archive
	CHARLES WHITEHEAD	EDR Digital Archive
2017	HENRY PHIPPS	Cole Information
2014	ROSIE MIGGINS	Cole Information
	HENRY PHIPPS	Cole Information
	ROSALIE MICKENS	Cole Information
2010	NEW LIFE MISSIONARY CHRISTIAN	Cole Information
	ROSALIE MICKENS	Cole Information
	KERTIS HUGHES	Cole Information
2005	Science Of Life Temple Inc	Hill-Donnelly Corporation
	OCCUPANT UNKNOWN	Cole Information
2000	SCIENCE LIFE TMPL	Cole Information
	SCIENCE OF LIFE TEMPLE INCORPORATED	Cole Information
1997	Science Of Life Temple Inc	NYNEX
1995	SCIENCE OF LIFE TEMPLE INC	Cole Information
1992	SCIENCE OF LIFE TEMPLE INC	Cole Information

FINDINGS

FULTON st

2012 FULTON st

Year	Uses	Source
1973	Roscoe Magnolia Mrs	New York Telephone
1970	Roscoe Magnolia Mrs	New York Telephone

FULTON St

2012 FULTON St

Year	Uses	Source
1965	Walker Wm J Mrs	New York Telephone

FULTON st

2016 FULTON st

Year	Uses	Source
1970	Hastings Arthnel L	New York Telephone
	Jones Jerry R	New York Telephone

FULTON St

2016 FULTON St

Year	Uses	Source
1965	G & L Genl Contrctrs Inc	New York Telephone
	Hastings Arlhnel L	New York Telephone
	Jones Jerry R	New York Telephone
	Lona Assocs Inc	New York Telephone

FULTON ST

2018 FULTON ST

Year	Uses	Source
1973	Rice Mattie	New York Telephone

2020 FULTON ST

Year	Uses	Source
1992	GUTIERREZ, NILDA	Cole Information

Year	Uses	Source
1973	Garcia Carmen	New York Telephone
	Varriale Alfred Rev	New York Telephone
1970	Varriale Alfred Rev	New York Telephone

2022 FULTON ST

Year	Uses	Source
1973	Brabham Emma	New York Telephone
	Coleman Betty	New York Telephone
1970	Guadalupe Miguel	New York Telephone
	Williams Edna	New York Telephone

FULTON St

2022 FULTON St

Year	Uses	Source
1965	Smith Mary H	New York Telephone
	Wooten Lilly Mrs	New York Telephone

FULTON ST

2024 FULTON ST

Year	Uses	Source
1973	Cooper Harold	New York Telephone
	Cooper James	New York Telephone
1970	Cooper Hilda	New York Telephone

FULTON st

2024 FULTON st

Year	Uses	Source
1970	Coleman Betty	New York Telephone

FULTON St

2024 FULTON St

Year	Uses	Source
1965	Preston Albertha	New York Telephone

Year	Uses	Source
1965	Thomas Leroy	New York Telephone

FULTON ST

2026 FULTON ST

Year	Uses	Source
1997	Daniels Church Of God In Christ	NYNEX
1995	DANIEL'S CHURCH OF GOD IN CHRIST	Cole Information
1992	DANIEL'S CHURCH OF GOD IN CHRIST	Cole Information
1973	Dean Whol Dstrbtrs	New York Telephone

FULTON st

2026 FULTON st

Year	Uses	Source
1970	Conley Will turn	New York Telephone
	Durant & Sons Van Line Inc	New York Telephone

FULTON St

2026 FULTON St

Year	Uses	Source
1965	Nockowitz Meyer uphlstry	New York Telephone

FULTON ST

2028 FULTON ST

Year	Uses	Source
1973	Lighthouse Real Estate	New York Telephone

FULTON St

2030 FULTON St

Year	Uses	Source
1965	Sussman Benj Sheet Metal Co Inc	New York Telephone

FINDINGS

Herkimer

1079 Herkimer

Year	*Uses*	*Source*
2005	h Neville Cyrus	Hill-Donnelly Corporation
2000	CYRUS NEVILLE	Cole Information Services
1934	MEYERS ETHEL A STEN R	R. L. Polk & Co.
	MEYERS MICHL MEATS H	R. L. Polk & Co.
	SULZER ARTH WTCHMAN R	R. L. Polk & Co.

HUL l

15 HUL l

Year	*Uses*	*Source*
1970	Austin Cecil	New York Telephone

HUL st

7 HUL st

Year	*Uses*	*Source*
1973	Rembert Eunice	New York Telephone

HULL

1 HULL

Year	*Uses*	*Source*
1934	CANCILLO	R. L. Polk & Co.
	LAPLACA ALBERT GARMENT WKR R	R. L. Polk & Co.
	LAPLACA BRACIO CLK R	R. L. Polk & Co.
	LAPLACA SANTO DRY GDS H DO	R. L. Polk & Co.

3 HULL

Year	*Uses*	*Source*
1992	GRIMES DOROTHY	NYNEX Informantion Resource Co.
1985	STRINGFIELD E	NYNEX Information Resources Company
1976	STRINGFIELD E	New York Telephone
1960	GRIMES JOHN	New York Telephone

Year	Uses	Source
1934	MURRY JAS PHONOGRAPH REPR H DO	R. L. Polk & Co.
1928	MURRY J PHONGPH REPRS	New York Telephone

4 HULL

Year	Uses	Source
1976	MANSON RANDOLPH	New York Telephone

5 HULL

Year	Uses	Source
1992	BRANCH QUEEN	NYNEX Informantion Resource Co.
1985	STROUD OCTAVIA	NYNEX Information Resources Company
1976	STROUD OCTAVIA	New York Telephone
1960	WATERMAN CLAUDE REV	New York Telephone
1934	POWELL GEO L PRINTING H DO	R. L. Polk & Co.

7 HULL

Year	Uses	Source
1976	WIN-MONT SIGNS	New York Telephone
1960	EDWARDS ELAINE	New York Telephone
	HUBBARD ELIZ	New York Telephone
	KELLAM DOROTHY I	New York Telephone
	RHODES W	New York Telephone
	WIN-MONT SIGNS	New York Telephone
1934	ARCHER ELTON FCTYWKR R	R. L. Polk & Co.
	BROWN SAML MOVER H	R. L. Polk & Co.
	BYARD EVELYN R	R. L. Polk & Co.
	BYARD JAS W LAB H	R. L. Polk & Co.
	DAVIS HAWALD FCTYWKR R	R. L. Polk & Co.
	HAYNES EDDY PORTER R	R. L. Polk & Co.
	HAYNES EDW H	R. L. Polk & Co.
	HAYNES EDW JR FCTY WKR R	R. L. Polk & Co.
	HICKS GEO A SIGN PAINTING H DO	R. L. Polk & Co.
	JONES JOHN LAB H	R. L. Polk & Co.
	KEATON GLADYA H	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	SHIPLEY IVAN H	R. L. Polk & Co.
	WILLIAMS ABR LAB H	R. L. Polk & Co.
1928	LITTLE & ABRAMS PIANO MOVERS	New York Telephone

9 HULL

Year	Uses	Source
1960	BLAND PERCY	New York Telephone
	PEPP BERTHA M	New York Telephone
	WEST ROSA	New York Telephone
1934	ANDERSON RACHAEL R	R. L. Polk & Co.
	BAXTER JULIAN CHAUF H	R. L. Polk & Co.
	HICKS JANE H	R. L. Polk & Co.
	PETERSON ALVIN R	R. L. Polk & Co.
	PETERSON EDW H	R. L. Polk & Co.
	PETERSON LEROY R	R. L. Polk & Co.
	WILLIAMS BEATRICE MAID R	R. L. Polk & Co.
	WILLIAMS PAUL CLK R	R. L. Polk & Co.
1928	JACKSON WM R	New York Telephone

10 HULL

Year	Uses	Source
1934	FRANK RESTR	R. L. Polk & Co.
	MARKOWITZ SAML PNTR R	R. L. Polk & Co.

11 HULL

Year	Uses	Source
1976	GLEATON WILLIE L	New York Telephone
1960	FRAZIER ROBT L	New York Telephone
	JONES BEN	New York Telephone
	RICHBERG LOUISE	New York Telephone
	SCOTT LEON	New York Telephone
1934	CHERRY HENRY SEC HND DIR	R. L. Polk & Co.
	CHERRY KATH R	R. L. Polk & Co.
	CHERRY ROBT H	R. L. Polk & Co.

Year	Uses	Source
1934	JOHNSON GENCY R	R. L. Polk & Co.
	JOHNSON WM H	R. L. Polk & Co.
	PAGE EARL MTRMN H	R. L. Polk & Co.
	SIMMONS OTIS HLPR R	R. L. Polk & Co.
	LAB H	R. L. Polk & Co.
1928	BROWN GEO R	New York Telephone
	MILLS ABRAHAM HKG & RIGGNG	New York Telephone

12 HULL

Year	Uses	Source
1934	CULL DOROTHY C H	R. L. Polk & Co.

13 HULL

Year	Uses	Source
1934	CULL ANNA CLK R	R. L. Polk & Co.
	CULL HELEN BKPR R	R. L. Polk & Co.
	CULL MARY BKPR R	R. L. Polk & Co.
	GILMAN SAML H	R. L. Polk & Co.
1928	MADIGAN A G PLMBG	New York Telephone

15 HULL

Year	Uses	Source
1960	AUSTIN CECIL	New York Telephone
	TRAVAGLIONE ANGELO	New York Telephone
1934	BROWN THOS LAB H	R. L. Polk & Co.
	GRANT ALEX COOK H	R. L. Polk & Co.
	GRANT SARAH R	R. L. Polk & Co.
	TRAVAGLIONE ANNUNZIO R	R. L. Polk & Co.
1928	WUTTKE CHAS CARPNTR & GENL CONTR	New York Telephone

16 HULL

Year	Uses	Source
1960	FOX MARIE MRS	New York Telephone
1928	SAML R	New York Telephone

FINDINGS

17 HULL

Year	Uses	Source
1992	DAVIS CARRIE	NYNEX Informantion Resource Co.
1985	DAUGHTRY STERLING	NYNEX Information Resources Company
1976	LEACOCK MARIE	New York Telephone
1960	FERGUSON TIMOTHY	New York Telephone
1934	MACH OPR R	R. L. Polk & Co.
	TUCKER EUG STMFTR H	R. L. Polk & Co.
1928	TUCKER E R	New York Telephone

18 HULL

Year	Uses	Source
1992	CRAIGWELL LOUIS	NYNEX Informantion Resource Co.
	JOSEPH SOOKDEO	NYNEX Informantion Resource Co.
1960	FULTON SADIE L	New York Telephone
	OWENS JAS	New York Telephone
1928	STOUTE IRENE MRS R	New York Telephone

19 HULL

Year	Uses	Source
1960	JEFFERSON FRED W	New York Telephone

20 HULL

Year	Uses	Source
1928	FLAKE SALLY MRS R	New York Telephone

21 HULL

Year	Uses	Source
1985	GIVENS HENRY	NYNEX Information Resources Company
	TAYLOR SUSAN MRS	NYNEX Information Resources Company
1976	GIVENS HENRY	New York Telephone
	TAYLOR SUSAN MRS	New York Telephone
1960	GIVENS HENRY	New York Telephone
	TAYLOR SUSAN MRS	New York Telephone

FINDINGS

23 HULL

Year	Uses	Source
1976	RODGERS JAS	New York Telephone
1960	GIORDANO DOMINICK	New York Telephone
1934	MEYER WM F PNTR R	R. L. Polk & Co.
1928	MULLER JOHN R	New York Telephone

25 HULL

Year	Uses	Source
1960	LOEFFEL HENRY A	New York Telephone
1934	HYER GEO TMKPR H	R. L. Polk & Co.
	WILSON JOHN SHOEWKR R	R. L. Polk & Co.
1928	MAYER EDITH A R	New York Telephone

5A HULL

Year	Uses	Source
1992	ENGLISH LEROY	NYNEX Informantion Resource Co.
	SIMMONS BAR & GRILL	NYNEX Informantion Resource Co.
1985	SIMMONS BAR & GRILL	NYNEX Information Resources Company
1980	SIMMONS BAR & GRILL	New York Telephone
1976	SIMMONS BAR & GRILL	New York Telephone
1960	SIMMONS WM A BAR GRLL	New York Telephone
1934	JOHNSON ELMIRA FORELADY R	R. L. Polk & Co.
	JOHNSON FRED H	R. L. Polk & Co.
	READE RYRD LAB H	R. L. Polk & Co.

15A HULL

Year	Uses	Source
1992	NEVILLOYD JOS REV	NYNEX Informantion Resource Co.
	SACRED HEART OF JESUS CHURCH	NYNEX Informantion Resource Co.
1985	NEVILLOYD JOS REV	NYNEX Information Resources Company
	SACRED HEART OF JESUS CHURCH	NYNEX Information Resources Company
1976	NEVILLOYD JOS REV	New York Telephone
	SACRED HEART OF JESUS CHURCH	New York Telephone
1960	NEVILLOYD JOS REV	New York Telephone

Year	Uses	Source
1934	GARRETT CHAS PET SHOP	R. L. Polk & Co.
	HOWARD FRANK CHAUF H	R. L. Polk & Co.
	JONES FLORENCE R	R. L. Polk & Co.
	JONES ROBT LAB R	R. L. Polk & Co.

HULL 467

21 HULL 467

Year	Uses	Source
1992	BLOUNT M	NYNEX Informantion Resource Co.

HULL 757

23 HULL 757

Year	Uses	Source
1985	ROBERTSON DANNY	NYNEX Information Resources Company

HULL AV MASPETH

3 HULL AV MASPETH

Year	Uses	Source
1934	CLK PO R BQ	R. L. Polk & Co.

HULL AVE

13 HULL AVE

Year	Uses	Source
1934	BEHRENI MARY H	R. L. Polk & Co.

HULL H

15 HULL H

Year	Uses	Source
1934	TRAVAGLIONE ANGELO CONTR DO	R. L. Polk & Co.

FINDINGS

HULL H1024

12 HULL H1024

Year	Uses	Source
1934	JONES WALTER RESTR	R. L. Polk & Co.

HULL ST

1 HULL ST

Year	Uses	Source
1949	La Placa S	New York Telephone Company
1945	La Placa S	New York Telephone

3 HULL ST

Year	Uses	Source
2020	JOSEPH BARNES	EDR Digital Archive
2010	BEATRICE GRIMES	Cole Information
	CHARISE SYVILLE	Cole Information
2005	No Current Listing	Hill-Donnelly Corporation
	SHARRAN MIXSON	Cole Information
2000	THOMAS POPE	Cole Information
	THOMAS POPE	Cole Information
1997	HILL Eugone	NYNEX
1992	GRIMES, DOROTHY	Cole Information
1960	Grimes John	New York Telephone Company
1949	La Placa Peter	New York Telephone Company

5 HULL ST

Year	Uses	Source
2020	ATM	EDR Digital Archive
	JAQUANNA ARMSTRONG	EDR Digital Archive
	MELISSA BRANCH	EDR Digital Archive
	MARIA MELISSA	EDR Digital Archive
	JOANNE ADAMS	EDR Digital Archive
	MONIQUE ELLIS	EDR Digital Archive
	FLORINE MAZE	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	AFIESHA BALTHAZAR	EDR Digital Archive
	BETHANN ARMSTRONG	EDR Digital Archive
2017	JANIEL MURPHY	Cole Information
	NADINE BROWN	Cole Information
	JERRY PAYDEN	Cole Information
	JANICE ARMSTRONG	Cole Information
	AFIESHA BALTHAZAR	Cole Information
2014	SANDRA BELLINO	Cole Information
	M BATTISTE	Cole Information
	JERRY PAYDEN	Cole Information
	MONIQUE ELLIS	Cole Information
	MARIA MELISSA	Cole Information
	QUENTIN BRANCH	Cole Information
	AFIESHA BALTHAZAR	Cole Information
2010	JANIEL MURPHY	Cole Information
	JERRY PAYDEN	Cole Information
	MELISSA BRANCH	Cole Information
	PRISCILLA CANN	Cole Information
	FLORINE MAZE	Cole Information
2005	Armstrong Vanessa	Hill-Donnelly Corporation
	H Branch Queen	Hill-Donnelly Corporation
	Brown N	Hill-Donnelly Corporation
	Gotta Do The Laundry	Hill-Donnelly Corporation
	Nicholson Candace	Hill-Donnelly Corporation
	Payden Jerry	Hill-Donnelly Corporation
	ANYMEANZ PICTURES INC	Cole Information
	QUEENESTHE BRANCH	Cole Information
	JERRY PAYDEN	Cole Information
	NADINE BROWN	Cole Information
	CRYSTAL ROBINSON	Cole Information
	VANESSA ARMSTRONG	Cole Information
2000	APARTMENTS	Cole Information

FINDINGS

Year	Uses	Source
2000	1 QUEEN BRANCH	Cole Information
	QUEENESTHER BRANCH	Cole Information
	QUEEN BRANCH	Cole Information
1995	SIMMONS BAR & GRILL	Cole Information
1992	SIMMONS BAR & GRILL	Cole Information
	ENGLISH, LEROY	Cole Information
	BRANCH, QUEEN	Cole Information
1973	Stroud Octavia	New York Telephone
1965	Gibson Jean	New York Telephone
1960	Waterman Claude Rev	New York Telephone Company
1949	Remler Jacob MD ofc	New York Telephone Company

7 HULL ST

Year	Uses	Source
1973	Win Mont Signs	New York Telephone
1965	Hubbard Eliz	New York Telephone
	Jenkins Johnnie M	New York Telephone
	Wesley Chas	New York Telephone
	Win Mont Signs	New York Telephone
1960	Edwards Elaine	New York Telephone Company
	Hubbard Eliz	New York Telephone Company
	Kellam Dorothy I	New York Telephone Company
	Rhodes W	New York Telephone Company
	WIN MONT SIGNS	New York Telephone Company
1949	Deweys Radio Svce	New York Telephone Company

9 HULL ST

Year	Uses	Source
2020	IGLESIA DE DIOS PENTECOSTAL	EDR Digital Archive
	TIFFANE SAMPSON	EDR Digital Archive
	ESTEBANA CASTELLANOS	EDR Digital Archive
	SHAKIMA NEELY	EDR Digital Archive
	JOSE SUAREZ	EDR Digital Archive
	DORIS GOMEZ	EDR Digital Archive

FINDINGS

Year	Uses	Source
2017	CARLOS GOMEZ	Cole Information
	TIFFANE SAMPSON	Cole Information
2014	CARLOS GOMEZ	Cole Information
	TIFFANE SAMPSON	Cole Information
	LARRY PERKINS	Cole Information
	RAQUEL SANTIAGO	Cole Information
	ANNIE JACOBS	Cole Information
2010	CARLOS GOMEZ	Cole Information
	TIFFANE SAMPSON	Cole Information
	AGATHA LOUIS	Cole Information
	LARRY PERKINS	Cole Information
	ALFREDO CASTELLANOS	Cole Information
	ANNIE JACOBS	Cole Information
2005	Castellanos Alfredo	Hill-Donnelly Corporation
	H Gomez C vv	Hill-Donnelly Corporation
	Gomez Doris	Hill-Donnelly Corporation
	Gomez Jenny	Hill-Donnelly Corporation
	Il HMclean WD	Hill-Donnelly Corporation
	CARLOS GOMEZ	Cole Information
	JOSE ELIAS	Cole Information
	DEBBIE PERKINS	Cole Information
	ALFREDO CASTELLANOS	Cole Information
1973	Kennedy Roby D	New York Telephone
	Raynor Eartha	New York Telephone
	Roebucki Victoria	New York Telephone
1970	Osbey Willie Ann	New York Telephone
1965	Owens Ida C	New York Telephone
1960	Bland Percy	New York Telephone Company
	Pepp Bertha M	New York Telephone Company
	West Rosa	New York Telephone Company
1949	Everett Geneva Mrs	New York Telephone Company
	Pepp Bertha M	New York Telephone Company

FINDINGS

11 HULL ST

Year	*Uses*	*Source*
2020	KYANA DAVIS	EDR Digital Archive
2017	KYANA DAVIS	Cole Information
	WENDY MCLEAN	Cole Information
	LATOYA BELLO	Cole Information
	HOWARD LETICIA	Cole Information
	LETICIA HOWARD	Cole Information
2014	MERRILL CONNELL	Cole Information
	WENDY MCLEAN	Cole Information
	LATOYA BELLO	Cole Information
	JARRARD GOLDSMITH	Cole Information
	HOWARD LETICIA	Cole Information
	LETICIA HOWARD	Cole Information
2010	WENDY MCLEAN	Cole Information
	MERRILL CONNELL	Cole Information
2005	WENDY MCLEAN	Cole Information
1973	Gleaton Willie L	New York Telephone
	Jones Ben	New York Telephone
	Morrison Frederick	New York Telephone
	Richberg Louise	New York Telephone
	Wells James	New York Telephone
1970	Gleaton Willie L	New York Telephone
	Jones Ben	New York Telephone
	Richberg Louise	New York Telephone
	Wright S A	New York Telephone
1965	Richberg Louise	New York Telephone
1960	Frazier Robt L	New York Telephone Company
	Jones Ben	New York Telephone Company
	Richberg Louise	New York Telephone Company
	Scott Leon	New York Telephone Company
1949	Perry Jas J	New York Telephone Company

FINDINGS

13 HULL ST

Year	Uses	Source
2020	SABRINA FRAZIER	EDR Digital Archive
2017	ONA OBINANI	Cole Information
	ERIC FRAZIER	Cole Information
2014	BETH ROBINSON	Cole Information
	ERIC FRAZIER	Cole Information
2010	BETH ROBINSON	Cole Information
	ONA OBINANI	Cole Information
	DENIS FELIKSON	Cole Information
	ERIC FRAZIER	Cole Information
2005	Obinani Ona	Hill-Donnelly Corporation
	H Robinson B M v	Hill-Donnelly Corporation
	Sampson Jalme	Hill-Donnelly Corporation
	ONE ENTERPRISES LTD	Cole Information
	JAIME SAMPSON	Cole Information
	ONA OBINANI	Cole Information
1949	Timmons Ernest	New York Telephone Company
1940	Cull Dorothy Mrs	New York Telephone

14 HULL ST

Year	Uses	Source
1945	Lo Vullo Nancy	New York Telephone

15 HULL ST

Year	Uses	Source
2020	FULL GOSPEL TABERNACLE-FAITH	EDR Digital Archive
	KARI SINGLETARY	EDR Digital Archive
	CORIS SINGLETARY	EDR Digital Archive
	DEVAUGHN MORRIS	EDR Digital Archive
	VIRGINIA SINGLETARY	EDR Digital Archive
2017	SINGLETARY CORIS	Cole Information
	FULL GOSPEL TABERNACLE	Cole Information
	CORIS SINGLETARY	Cole Information
	KIM MORRIS	Cole Information

FINDINGS

Year	Uses	Source
2014	FULL GOSPEL TABERNACLE OF FAITH CHUR	Cole Information
	FULL GOSPEL TABERNACLE	Cole Information
	SINGLETARY VIRGINA	Cole Information
	CORIS SINGLETARY	Cole Information
	KIM MORRIS	Cole Information
2010	FULL GOSPEL TABERNACLEFAITH	Cole Information
	SINGLETARY VIRGINA	Cole Information
	SHAWN CUMMINGS	Cole Information
	VIRGINA SINGLETARY	Cole Information
	KIM MORRIS	Cole Information
	TERANCE LAWS	Cole Information
2005	Gibson Latisha	Hill-Donnelly Corporation
	h Gibson Robert	Hill-Donnelly Corporation
	ROBERT GIBSON	Cole Information
2000	ROBERT GIBSON	Cole Information
	TANISHA PRICE	Cole Information
	TANISHA PRICE	Cole Information
	ROBERT GIBSON	Cole Information
	ROBERT SINGLETARY	Cole Information
1992	SACRED HEART OF JESUS CHURCH	Cole Information
	NEVILLOYD, JOS	Cole Information
1973	Penny Pleasant	New York Telephone
1970	Penny Pleasant	New York Telephone
1965	Austin Cecil	New York Telephone
	Penny Pleasant	New York Telephone
1960	Austin Cecil	New York Telephone Company
	Travaglione Angelo	New York Telephone Company
1949	Selkridge Ellsw orh	New York Telephone Company
1945	Selkridge Ellsw orth	New York Telephone

16 HULL ST

Year	Uses	Source
2020	SANTANA MORENO	EDR Digital Archive

FINDINGS

Year	Uses	Source
2017	WENDY PETERS	Cole Information
2014	JESSICA FLORI	Cole Information
	BOANN THORPE	Cole Information
2010	JESSICA FLORI	Cole Information
	LAURETTA ALEXANDER	Cole Information
2005	Alexander Lauretta	Hill-Donnelly Corporation
	Flori Jessica	Hill-Donnelly Corporation
	SHAVORN BAIRD	Cole Information
1965	Bryant J	New York Telephone
1960	Fox Marie Mrs	New York Telephone Company
1949	Fox David C Rev	New York Telephone Company

17 HULL ST

Year	Uses	Source
2020	JOUNTAE JOHNSON	EDR Digital Archive
	CARRIE DAVIS	EDR Digital Archive
	MARY MORRIS	EDR Digital Archive
	KEITH FRANCIS	EDR Digital Archive
	GLEN NELSON	EDR Digital Archive
2017	SPIRITUAL OF ISRAEL CHURCH	Cole Information
	AMY WATKIS	Cole Information
2014	SPIRITUAL OF ISRAEL CHURCH	Cole Information
	MARCIA GORDON	Cole Information
	CARRIE DAVIS	Cole Information
	MARY MORRIS	Cole Information
2010	SPIRITUAL OF ISRAEL CHURCH	Cole Information
	NANCY FRANCIS	Cole Information
	MARCIA GORDON	Cole Information
	HUGH WATKIS	Cole Information
2005	h Francis Nancy	Hill-Donnelly Corporation
	Gordon Marcia	Hill-Donnelly Corporation
	Spiritual Of Israel Church	Hill-Donnelly Corporation
	Tisdale E	Hill-Donnelly Corporation

Year	Uses	Source
2005	SPIRITUAL ISREAL CHURCH	Cole Information
	NANCY FRANCIS	Cole Information
	E TISDALE	Cole Information
	MAURICE PHIFER	Cole Information
2000	SPIRITUAL ISRL CH	Cole Information
	SPIRITUAL OF ISRAEL CHURCH	Cole Information
1997	Spiritual Of Israel Church	NYNEX
	SANTIAGO Raquel	NYNEX
1995	SPIRITUAL OF ISRAEL CHURCH	Cole Information
1992	SPIRITUAL OF ISRAEL CHURCH	Cole Information
1970	Simpson C	New York Telephone
1965	Jones Eliz Mrs	New York Telephone
	Jones Pearl	New York Telephone
1960	Ferguson Timothy	New York Telephone Company
1949	Stokes Wm Rev	New York Telephone Company

18 HULL ST

Year	Uses	Source
2020	ALLISON BOUTIN	EDR Digital Archive
	LISA MIKE	EDR Digital Archive
	JERRY MADSEN	EDR Digital Archive
2017	NOREEN MCLEOD	Cole Information
	CHERYL MIKE	Cole Information
	ALLISON BOUTIN	Cole Information
	JERRY MADSEN	Cole Information
	CHERYL SULUTI	Cole Information
2014	NOREEN MCLEOD	Cole Information
	SHAVORN BAIRD-JENKINS	Cole Information
	LEROY BROWNE	Cole Information
	JERRY MADSEN	Cole Information
2010	DEMOND WILSON	Cole Information
	SHAVORN BAIRD-JENKINS	Cole Information
	LEROY BROWNE	Cole Information

FINDINGS

Year	Uses	Source
2005	Brow ne leroy	Hill-Donnelly Corporation
	h Brow ne Leroy	Hill-Donnelly Corporation
	Richardson Sanadra	Hill-Donnelly Corporation
	JOSEPH EDWARDS	Cole Information
	ESMOND NIMBLETT	Cole Information
	LEROY BROWNE	Cole Information
	LEONARD RICHARDSON	Cole Information
2000	DANIELLE PHILLIPS	Cole Information
	LEROY BROWNE	Cole Information
	D PHILLIPS	Cole Information
1997	WILSON Demond	NYNEX
1992	JACKSON, JAMES	Cole Information
	CRAIGWELL, LOUIS	Cole Information
	JOSEPH, SOOKDEO	Cole Information
1973	Folks Cludier	New York Telephone
	Mc Bride Dorothy	New York Telephone
	Stephens A	New York Telephone
1970	Mc Bride Dorothy	New York Telephone
	Stephens A	New York Telephone
1965	Ow ens Jas	New York Telephone
1960	Fulton Sadie L	New York Telephone Company
	Ow ens Jas	New York Telephone Company

19 HULL ST

Year	Uses	Source
2017	IRVA ADAMS	Cole Information
	NORMAN MILLER	Cole Information
	KESHIA ALERT	Cole Information
	MICHAEL LLOYD	Cole Information
2014	IRVA ADAMS	Cole Information
	DENNIS LEWIS	Cole Information
	NORMAN MILLER	Cole Information
2010	ST CHRISTOPHER OTTILLIE	Cole Information

FINDINGS

Year	Uses	Source
2010	NORMAN MILLER	Cole Information
2005	No Current Listing	Hill-Donnelly Corporation
	NORMAN MILLER	Cole Information
1960	Jefferson Fred W	New York Telephone Company
1945	Aragona Dominick	New York Telephone

20 HULL ST

Year	Uses	Source
1970	Bright Lona M	New York Telephone

21 HULL ST

Year	Uses	Source
2020	VANESTA SINGLETARY	EDR Digital Archive
2017	VANESTA SINGLETARY	Cole Information
2014	ANTHONY LEADER	Cole Information
	VANESTA SINGLETARY	Cole Information
2010	ANTHONY LEADER	Cole Information
	VANESTA SINGLETARY	Cole Information
2005	h Pride V	Hill-Donnelly Corporation
	HSingletary V	Hill-Donnelly Corporation
	VANESTA SINGLETARY	Cole Information
2000	DONALD GIVENS	Cole Information
1997	UNIVERSAL BUILDERS	NYNEX
1973	Givens Henry	New York Telephone
	Taylor Susan Mrs	New York Telephone
1970	Givens Henry	New York Telephone
	Taylor Susan Mrs	New York Telephone
1965	Givens Henry	New York Telephone
	Taylor Susan Mrs	New York Telephone
1960	Givens Henry	New York Telephone Company
	Taylor Susan Mrs	New York Telephone Company
1940	Donker Ethel R Mrs	New York Telephone

FINDINGS

23 HULL ST

Year	Uses	Source
2020	SHAKIMA COLLINS	EDR Digital Archive
	RAMKARRAN IKRAM	EDR Digital Archive
	HENRY WORKMAN	EDR Digital Archive
2017	COLLINS SHAKIMA	Cole Information
	GERALDINE HEBERT	Cole Information
	ANGELA WORKMAN	Cole Information
	LAMAR COLLINS	Cole Information
	HENRY WORKMAN	Cole Information
2014	COLLINS SHAKIMA	Cole Information
	GERALDINE HEBERT	Cole Information
	ADA BROWN	Cole Information
	LAMAR COLLINS	Cole Information
	MELVINA WORKMAN	Cole Information
	RAHEEM DODD	Cole Information
2010	GERALDINE HEBERT	Cole Information
	LAMAR COLLINS	Cole Information
	RAHEEM DODD	Cole Information
2005	No Current Listing	Hill-Donnelly Corporation
	ROSALIND OCTOBER	Cole Information
	ENOCH SMITH	Cole Information
	EVELL DUNBAR	Cole Information
	JANICE PAUL	Cole Information
	WILMER BASS	Cole Information
	JANICE CLARKE	Cole Information
1973	Rodgers Jas	New York Telephone
1970	Rodgers Jas	New York Telephone
1960	Giordano Dominick	New York Telephone Company

25 HULL ST

Year	Uses	Source
2020	LERA POTTS	EDR Digital Archive
	TANZENIA COUSAR	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	LEELA BHAGAN	EDR Digital Archive
2017	LERA POTTS	Cole Information
	SASHA COACHMAN	Cole Information
	JOSEPHAT RANDOLPH	Cole Information
	MARCEA RANDOLPH	Cole Information
	LEELA BHAGAN	Cole Information
2014	LERA POTTS	Cole Information
	CARLOS RIVERA	Cole Information
	SASHA COACHMAN	Cole Information
	CONRAD RANDOLPH	Cole Information
	LEELA BHAGAN	Cole Information
2010	LERA POTTS	Cole Information
	CHERI BHAGAN	Cole Information
	SASHA COACHMAN	Cole Information
	JOSEPHAT RANDOLPH	Cole Information
	ANTHONY SALAS	Cole Information
2005	H Potts Lera	Hill-Donnelly Corporation
	Randolph Conrad	Hill-Donnelly Corporation
	Randolph Conrad	Hill-Donnelly Corporation
	Randolph Merle	Hill-Donnelly Corporation
	H Randolph Michael	Hill-Donnelly Corporation
	WORLD FINANCIAL GROUP	Cole Information
	LERA POTTS	Cole Information
	CONRAD RANDOLPH	Cole Information
1970	Loeffel Henry A	New York Telephone
1965	Loeffel Henry A	New York Telephone
1960	Loeffel Henry A	New York Telephone Company
1949	Loeffel Henry A	New York Telephone Company

FINDINGS

Saratoga

231 Saratoga

Year	*Uses*	*Source*
1960	Berlicchi Gluseppe	New York Telephone Company
	Cavoli Antonio	New York Telephone Company
1949	Cavoli Anthony	New York Telephone Company
1934	FARINA PHILIP LAB H	R. L. Polk & Co.
	ZERELLA PELEGRINEO H	R. L. Polk & Co.

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
1 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
1 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
10 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1079 Herkimer Street	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1079 Herkimer	2020, 2017, 2014, 2010, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
11 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
11 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
11 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
11 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
11 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
11 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
12 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
12 HULL H1024	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
13 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
13 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
13 HULL AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
13 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
13 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
13 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
13 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
13 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
13 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
13 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
14 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
15 HUL I	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
15 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
15 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
15 HULL H	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
15A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
16 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
16 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
16 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
16 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
16 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
16 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
16 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
16 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
16 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
16 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
17 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
17 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
18 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
18 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
18 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
19 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
19 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
19 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
19 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
19 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
19 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
19 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
1941 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1941 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
1941 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1941 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1943 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
1943 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
1943 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1943 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
1943 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
1943 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
1943 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1943 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
1943 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1943 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1943 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1943 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
1945 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
1945 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
1945 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
1945 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1945 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1945 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1947 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1955A FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1961 Fulton	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1985, 1980, 1976, 1973, 1960, 1949, 1945, 1940, 1928
1961 Fulton Street	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
20 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
20 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2000 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2002 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2002 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2002 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2004 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2004 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2004 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2006 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2006 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2006 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2006 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2008 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2008 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2008 FULTON H	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2008 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2008 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2010 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2010 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2010 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2010 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2010 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2012 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2012 FULTON R2221	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2012 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2012 FULTON ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2012 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2012A FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2012A FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2016 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2016 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2016 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2016 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2016 FULTON PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2016 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2016 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2018 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2018 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2018 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2018 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2020 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2020 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2020 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2020 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2020A FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2020A FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2020A FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2022 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2022 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2022 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2022 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2022 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
2022 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2022 FULTON H NEW HYDE PK LI	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2022 FULTON R BALDWIN LI	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2022 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2022 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2022 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2024 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2024 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2024 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2024 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2024 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2024 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
2026 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2026 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
2026 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2026 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2028 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
2028 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
2028 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934

FINDINGS

Address Researched	Address Not Identified in Research Source
2028 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2028 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
2028 FULTON ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2030 FULTON	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
2030 FULTON St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
21 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL 467	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
21 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
23 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
23 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
23 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
23 HULL 757	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
23 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
231 Saratoga	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1945, 1940, 1928
231 Saratoga Avenue	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
25 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
25 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
25 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
25 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
25 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
25 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
25 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
25 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
25 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
25 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
25 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
25 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
3 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
3 HULL AV MASPETH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
3 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
3 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
5 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
5 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
5A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
5A HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
7 HUL st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
7 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
7 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
7 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
7 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
7 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
7 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
7 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
7 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
9 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
9 HULL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
9 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
9 HULL ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
2014 Fulton Street	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973

APPENDIX H

Subject Property Photographs



Photograph 1: **Looking west, overview of the Subject Property.**



Photograph 2: **Looking south, overview of the Subject Property with the southern adjoining properties in the background.**



Photograph 3: **Looking west, view of sewer grate on the sidewalk to the north of the Subject Property.**



Photograph 4: **Looking east, view of eastern adjoining property.**



Photograph 5: Looking north, view of northern adjoining property.



Photograph 6: Looking southwest, view of western adjoining property.

APPENDIX I

User Provided Information

ASTM E 1527-21 Optional User Questionnaire

To qualify for the protections offered under the EPA All Appropriate Inquiry (AAI) Standard, the **User** (entities seeking to use the ASTM E1527-21 Practice to complete a Phase I Environmental Assessment (ESA) of the property; i.e. Lenders and/ or Borrowers) must conduct the following inquiries. The User should provide the following information to the environmental professional. Failure to conduct these inquires could result in a determination that AAI is not complete.

This information should be the collective knowledge of the entities relying on the Phase I ESA. **Please note that you are not being asked to evaluate the property, but rather to provide your knowledge of information on the property.**

Site Name/Address: Steps at Saratoga, 2014-2042 Fulton Street, Brooklyn, NY 11233

Person Interviewed/Title: Nathaniel Keuter, Project Manager Date: 09/07/2023

If known, when was the property initially developed? The property has not been developed yet. The land the property will be built on is currently owned by the city.

If different, when were the current building(s) on the property constructed? N/A.

1. Environmental liens that are filed or recorded against the subject property (40 CFR 312.25).

Did a search of *land title records* (or judicial records where appropriate, see Note 1 below) identify any environmental liens filed or recorded against the *subject property* under federal, tribal, state or local law? **UNKNOWN**

Yes___ No___ If you answer yes, please include an explanation in the space provided below:

_____
_____
_____
_____

2. Activity and land use limitations that are in place on the *subject property* or that have been filed or recorded in a registry (40 CFR 312.26).

Did a search of *land title records* (or judicial records where appropriate, see Note 1 below) identify any AULs, such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the *subject property* and/or have been filed against the *subject property* under federal, tribal, state, or local law?

Engineering Controls are defined as physical modifications to a site or facility to reduce or eliminate the potential for exposure to hazardous substances or petroleum products in the soil or ground water on a property). *Institutional Controls* are defined as a legal or administrative mechanism on the use of, or access to, a site or facility to 1) reduce or eliminate the potential for exposure to hazardous substances or petroleum products in the soil or ground water on the property, or 2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment.

Yes___ No_X_ If you answer yes, please include an explanation in the space provided below:

Note 1 - In certain jurisdictions, federal, tribal, state, or local statutes, or regulations specify that environmental liens and AULs be filed in judicial records rather than land title records. In such cases judicial records must be searched for environmental liens and AULs.

3. Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28).
Do you have any specialized knowledge or experience related to the *subject property* or nearby properties?
For example, are you involved in the same line of business as the current or former *occupants* of the *subject property* or an adjoining *property* so that you would have specialized knowledge of the chemicals and processes used by this type of business?

Yes___ No X If you answer yes, please include an explanation in the space provided below:

4. Relationship of the purchase price to the fair market value of the *subject property* if it were not contaminated (40 CFR 312.29) . a)

Does the purchase price being paid for this *subject property* reasonably reflect the fair market value of the *subject property*?

Yes___ No X If you answer no, please include an explanation in the space provided below, including whether the lower purchase price is because contamination is known or believed to be present at the *subject property*?

The land the subject property is on was won by a partnership of non-profit developers. The land was previously owned by the city and will continue to be owned by the city until financing is secured.

5. Commonly known or *reasonably ascertainable* information about the *subject property* (40 CFR 312.30).

Are you aware of commonly known or *reasonably ascertainable* information about the *subject property* that would help the *environmental professional* to identify conditions indicative of releases or threatened releases? For example, as *User*:

a. Do you know the past uses of the *subject property*?

Yes___ No X

b. Do you know of specific chemicals that are present or once were present at the *subject property*?

Yes___ No X

c. Do you know of spills or other chemical releases that have taken place at the *subject property*?

Yes___ No X

d. Do you know of any environmental cleanups that have taken place at the *subject property*?

Yes No X

If you answered yes to any of the questions above, please include an explanation in the space provided below:

6. The degree of obviousness of the presence of likely presence of contamination at the *subject property*, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).

Based on your knowledge and experience related to the *subject property,* are there any *obvious* indicators that point to the presence or likely presence of contamination at the *subject property*?

Yes___ No X If you answer yes, please include an explanation in the space provided below:

_____
_____
_____
_____

Please provide the following property contact information:

Property Owner: Steps at Saratoga HDFC Phone Number: (718) 366-3800

Key Site Personnel: Nathaniel Keuter Phone Number: (718) 366-3800

Past Owner: Phone Number: