HALEY ALDRICH

www.haleyaldrich.com

REPORT ON

ASTM PHASE I ENVIRONMENTAL SITE ASSESSMENT
98-114 BERRIMAN STREET DEVELOPMENT
98 BERRIMAN STREET
BROOKLYN, NEW YORK

DRAFT

by
H & A of New York Engineering and Geology, LLP
New York, New York

for
Berriman Residents LLC
Brooklyn, New York

File No. 0214078-000
September 2025

H & A OF NEW YORK ENGINEERING
AND GEOLOGY, LLP
213 W. 35th St
7th Floor
New York, NY 10001
646.277.5685

September 24, 2025
File No. 0214078-000

Berriman Residents LLC
130 Lee Avenue, #174
Brooklyn, New York 11206

Attention: David Goldberger

Subject: ASTM Phase I Environmental Site Assessment
98-114 Berriman Street Development
98 Berriman Street
Brooklyn, New York

Ladies and Gentlemen:

The enclosed report presents the results of a Phase I Environmental Site Assessment (Phase I) conducted at the above-referenced property, located at 98 Berriman Street, in Brooklyn, New York (herein referred to as the "subject property"). This work was performed by H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York), in accordance with our proposal to Berriman Residents LLC dated September 4, 2025, as authorized on September 8, 2025 ("Agreement"). This Phase I was conducted in conformance with the scope and limitations of the ASTM International (ASTM) E1527-21 Standard Practice for Environmental Site Assessments.[1] The objective of a Phase I is to assess whether known and/or suspect recognized environmental conditions (RECs), controlled RECs (CRECs), or historical RECs (HRECs) are associated with the subject property, as defined in the ASTM E1527-21 Standard.

Thank you for the opportunity to perform these services for you. Please do not hesitate to contact us if you have any questions or comments.

Sincerely yours,
H & A OF NEW YORK ENGINEERING AND GEOLOGY, LLP

Kaitlyn Moses
Staff Geologist 1

Mari C. Conlon, P.G.
Senior Associate

Enclosures

[1] The ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E1527-21 Standard) as referenced in Code of Federal Regulations Title 40 Part 312 (the All Appropriate Inquiries Rule).

DRAFT

Executive Summary

H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) has performed a Phase I Environmental Site Assessment (Phase I) of the property located at 98-114 Berriman Street in Brooklyn, New York (herein referred to as the "subject property"). The scope of work is described and conditioned by our proposal dated September 4, 2025. This Phase I was performed for Berriman Residents LLC, which seeks to acquire and redevelop the property. This Phase I was performed in conformance with the scope and limitations of the ASTM International (ASTM) E1527-21 Standard and All Appropriate Inquiries (AAI) Rule.

SUBJECT PROPERTY DESCRIPTION

The subject property, identified as Block 3989 Lots 20, 24, and 25 on the New York City tax map, is approximately 17,500 square feet (sq ft) in size and is located in the East New York neighborhood of Brooklyn, New York. The subject property is partially developed with an industrial building on Lot 20, and an auto towing yard / unlicensed parking lot on Lots 24 and 25. The subject property is currently owned by Accurate Organization 98 Corp. (Lot 20) and Accurate Organization 112-114-148-152 Corp. (Lots 24 and 25).

The subject property has been assigned an environmental E-Designation (E-366) for Air Quality (heating, ventilation, and air conditioning [HVAC] fuel limited to natural gas) and Hazardous Materials (Phase I and Phase II Testing Protocol) under City Environmental Quality Review (CEQR; No. 15DCP102K). Satisfaction of the E-Designation requirements is subject to review and approval by the New York City Office of Environmental Remediation (NYCOER) prior to redevelopment. The subject property is listed in the NYC Land Use database, categorized as "F4: Factory and Industrial Building."

OBJECTIVE

The objective of a Phase I is to assess whether recognized environmental conditions (RECs), controlled RECs (CRECs), or historical RECs (HRECs) are associated with the subject property. Our conclusions are intended to help the user evaluate the business environmental risk associated with the subject property. Our opinion regarding a REC's potential impact on the subject property is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, our experience evaluating similar sites, and on our understanding of the client's intention to acquire and redevelop the property.

SIGNIFICANT DATA GAPS

Our ability to identify and evaluate RECs at the subject property is conditioned upon significant data gaps identified as part of this Phase I. The ASTM E1527-21 Standard defines a significant data gap as a data gap that affects the ability of the Environmental Professional to identify a REC.

No significant data gaps were identified during the performance of this Phase I. Thus, it is our opinion that sufficient information was obtained to identify subject property conditions indicative of releases or threatened releases of hazardous substances and petroleum hydrocarbons. Our opinion is limited by the conditions prevailing at the time our work is performed and the applicable regulatory requirements in effect.

DRAFT

RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a REC as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

The following RECs were identified in connection with the subject property.

REC #1: Current Uses and Condition of Subject Property

At the time of inspection, the subject property was operating as a metal slitting and auto towing/parking facility. The building is used for metal slitting and storage of machinery and automotive supplies. The exterior lot is used for auto towing and storage of cars and trailers. Two active 275-gallon aboveground storage tanks (ASTs) containing No. 2 fuel oil were observed. One AST, located in the storm cellar on the east side of the building, is used to power a boiler, and the second AST, located on the first floor in the southwest corner of the building, is suspected to be used for heating. Site conditions, such as evidence of staining, improper storage of hazardous materials, and observations of kitty litter/Speedy Dry and stained cardboard located beneath equipment and vehicles, indicated previous and potentially ongoing releases. The current use of the property, in conjunction with the site conditions, is considered a REC.

REC #2: Historical Uses of the Subject Property

Sanborn Fire Insurance Maps (Sanborn Maps) indicate that the subject property formerly operated as a shoe factory and sweater factory in the late 1800s and early 1900s, as well as a razor blade manufacturer from as early as 1951 through the 1970s. Non-descript manufacturing continues through the present on Lot 20, with the most recent operator being a metal slitting facility. Two gas tanks on the southeast corner of Lot 20 were also depicted on the 1928 Sanborn Map. Potential environmental concerns associated with this historical use include the potential for release of hazardous substances commonly found in industrial practices, particularly if spills, leaks, or improper manufacturing practices occurred. The historical uses of the subject property are considered a REC.

REC #3: Historical and Current Uses of Surrounding Properties

Sanborn Maps indicate that by 1908, the east adjacent property was used as the John C. Creveling Coal & Lumber Yard with a rail spur extending northward across Liberty Avenue in apparent association with the Standard Oil Co. of New York. By 1951, the property was operated by the Harvey Lumber Co., and from 1965 to 1968, the property was utilized for metal parts storage. Additionally, by 1908, the north adjacent property was partially developed with an auto shop, and by 1965, the property was fully developed with an auto repair shop, which is currently still used as an auto repair shop. Sanborn Maps also indicate there were multiple historic small auto sheds and garages to the west and south of the subject property. Potential environmental concerns associated with auto repair and manufacturing operations include the potential for release of hazardous substances such as spent solvents, waste oils, heavy metals, and chlorinated compounds. These surrounding historical and current uses are considered a REC.

DRAFT

CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a CREC as a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

CRECs were not identified in connection with the subject property.

HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines an HREC as a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. An HREC is not a REC.

HRECs were not identified in connection with the subject property.

OTHER FINDINGS

The ASTM does not define the term "other finding"; however, Haley & Aldrich of New York utilizes the category to indicate conditions of potential risk that are not clearly defined in the ASTM Standard. While not considered RECs, Haley & Aldrich of New York identified the following Other Findings.

Other Finding #1: New York City E-Designation

The subject property has been assigned an environmental E-Designation (E-366) for Air Quality (HVAC fuel limited to natural gas) and Hazardous Materials (Phase I and Phase II Testing Protocol) under CEQR No. 15DCP102K. Satisfaction of the E-Designation requirements is subject to review and approval by the NYCOER prior to redevelopment.

Other Finding #2: Urban Fill

The overburden on the subject property is classified as Urban Land, which refers to soils that have been altered by human activities, thus making them unidentifiable. Typically, these soils have been mixed with other materials, such as brick and concrete (urban fill).

Other Finding #3: Boiler Encased in Potential Asbestos-Containing Material

During site inspection, the boiler located in the storm cellar was observed to be encased in potential asbestos-containing material. Proper confirmation sampling and decommissioning of the boiler and the encasement would be required as per New York City and State regulations as part of demolition.

SUMMARY

In summary, we identified three RECs and three Other Findings during this Phase I. The remainder of this report contains additional information regarding the Phase I, the resulting findings summarized above, and limitations affecting this report.

DRAFT

Continued Viability of Environmental Site Assessment

In accordance with the ASTM E1527-21 Standard, the following components of the Phase I Report must be conducted or updated within 180 days prior to the date of acquisition or prior to the date of the transaction:

1. Interviews with owners, operators, and occupants. Completed on: September 16, 2025
2. Searches for recorded environmental cleanup liens (a user responsibility). Completed on: September 9, 2025
3. Reviews of federal, tribal, state, and local government records. Completed on: September 10, 2025
4. Visual inspections of the subject property and of adjoining properties. Completed on: September 16, 2025
5. The declaration by the Environmental Professional responsible for the assessment or update (refer to Section 9). Completed on September __, 2025.

DRAFT

Table of Contents

		Page
Executive Summary		**i**
Continued Viability of Environmental Site Assessment		**iv**
List of Figures		**vii**
List of Appendices		**vii**
1.	**Introduction**	**1**
1.1	OBJECTIVE	1
1.2	SCOPE OF SERVICES	1
1.3	NON-SCOPE CONSIDERATIONS	1
1.4	LIMITING CONDITIONS/DEVIATIONS	2
1.5	USER RESPONSIBILITIES	2
2.	**Site Description**	**3**
2.1	SITE OWNERSHIP, LOCATION, AND VICINITY DESCRIPTION	3
2.2	PHYSICAL SETTING	4
3.	**Previous Reports**	**6**
4.	**Subject Property History**	**7**
4.1	SUBJECT PROPERTY	7
4.2	ADJOINING PROPERTIES	8
5.	**Environmental Records Review**	**10**
5.1	ENVIRONMENTAL DATABASE RECORDS SEARCH	10
5.2	ADDITIONAL ENVIRONMENTAL RECORDS OR FILE REVIEW	11
5.3	DETAILED DESCRIPTION OF RELEVANT INFORMATION	12
5.3.1	Subject Property	12
5.3.2	Nearby Sites	12
5.4	VAPOR MIGRATION	16
6.	**Subject Property Reconnaissance and Key Personnel Interview(s)**	**18**
6.1	CURRENT USE OF THE SUBJECT PROPERTY	18
6.2	GENERAL DESCRIPTION OF STRUCTURES	18
6.3	USE, STORAGE, AND DISPOSAL OF PETROLEUM PRODUCTS AND HAZARDOUS MATERIALS	18
6.4	OTHER SUBJECT PROPERTY OBSERVATIONS	20
6.5	ADJOINING PROPERTY OBSERVATIONS	22
6.6	USER RESPONSIBILITIES	22

DRAFT

Page

7. Findings and Opinions 23

7.1 SIGNIFICANT DATA GAPS 23
7.2 RECOGNIZED ENVIRONMENTAL CONDITIONS 23
7.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS 24
7.4 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS 24
7.5 DE MINIMIS CONDITIONS 24
7.6 OTHER FINDINGS 25

8. Conclusions 26

9. Environmental Professional Certification 27

10. Credentials 28

11. Glossary and Other Descriptions 29

11.1 GLOSSARY 29
11.2 DESCRIPTIONS OF DATABASES SEARCHED 30

12. References 32

DRAFT

List of Figures

Figure No.	Title
1	Project Locus
2	Site Plan

List of Appendices

Appendix	Title
A	Phase I Environmental Site Assessment Limitations
B	Historical Research Documentation
C	Regulatory Records Documentation
D	Subject Property Photographs

DRAFT

1. Introduction

This report presents the results of an ASTM International (ASTM) Phase I Environmental Site Assessment (Phase I) conducted by H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) at 98 Berriman Street located in Brooklyn, New York (herein referred to as the "subject property"). The approximately 17,500-square-foot (sq-ft) subject property is a partially developed industrial property and is shown on the Project Locus, Figure 1. This Phase I was conducted in consideration of Berriman Residents LLC's intention to acquire and redevelop the property.

1.1 OBJECTIVE

The objective of a Phase I is to assess whether recognized environmental conditions (RECs), controlled RECs (CRECs), or historical RECs (HRECs) are associated with the subject property by evaluating site history, interviews, existing observable conditions, current site use, and current and former uses of adjoining properties, as well as potential releases at surrounding properties that may impact the subject property. Our conclusions are intended to help the user evaluate the business environmental risk associated with the subject property.

The ASTM E1527-21 Standard defines a REC as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. The definitions of RECs, CRECs, and HRECs are included in the Glossary section of this report.

1.2 SCOPE OF SERVICES

This Phase I was performed by Haley & Aldrich of New York in conformance with the scope and limitations of the ASTM E1527-21 Standard and All Appropriate Inquiries (AAI) Rule and in accordance with our proposal dated September 4, 2025, as authorized on September 8, 2025 ("Agreement"). The Phase I limitations are attached hereto as Appendix A.

As part of this Phase I, Haley & Aldrich of New York conducted visual observations of site conditions and of abutting property use, and interviewed a key site manager and applicable tenant representatives (subject property reconnaissance); reviewed federal, state, tribal, and local environmental database information, federal and state environmental files, previous reports (if identified and provided), and site historical use records; and formulated conclusions regarding the potential presence and impact of RECs.

1.3 NON-SCOPE CONSIDERATIONS

The ASTM E1527-21 Standard includes the following list of "additional issues" that are non-scope considerations outside of the scope of the ASTM Phase I practice: asbestos-containing materials, biological agents, cultural and historic resources, ecological resources, endangered species, health and safety, indoor air quality related to release of hazardous substances or petroleum products into the environment, industrial hygiene, lead-based paint unrelated to releases into the environment, lead in drinking water, mold or microbial growth conditions, polychlorinated biphenyl (PCB)-containing materials, naturally-occurring radon, regulatory compliance, substances not defined as hazardous

DRAFT

substances (emerging compounds), and wetlands. These items were not included in this Phase I of the subject property.

The assessment of the presence of PCBs is limited to those potential sources specified in the ASTM E1527-21 Standard as "electrical or hydraulic equipment known or likely to contain PCBs…to the extent visually and or physically observed or identified from the interview or records review."

Note that PCBs may be present in miscellaneous building materials, such as caulking, sealants, insulation and sound-dampening materials, paint, gaskets, roofing and siding materials, waterproofing compounds, enamel coatings, and other chemical products manufactured prior to 1979. Evaluating the subject property building for potential PCB-containing building materials and possible PCB-containing materials other than "electrical or hydraulic equipment known or likely to contain PCBs" was outside the scope of this Phase I.

1.4 LIMITING CONDITIONS/DEVIATIONS

Haley & Aldrich of New York completed this Phase I in substantial conformance with the ASTM E1527-21 Standard. In our opinion, no additions were made to, or deviations or deletions made from, the ASTM work scope in completing this Phase I.

1.5 USER RESPONSIBILITIES

The completion of this Phase I is only one component of the process required to satisfy the AAI Rule. In addition, the user must adhere to a set of user responsibilities as defined by the ASTM E1527-21 Standard and the AAI Rule. User responsibilities are discussed in Section 6.6 of this report. A user seeking protection from Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) liability as an innocent landowner, bona fide prospective purchaser, or contiguous property owner must complete all components of the AAI process in addition to meeting ongoing obligations. AAI components, CERCLA liability relief, and ongoing obligations are discussed in the AAI Rule and in Appendix X1 of the ASTM E1527-21 Standard.

DRAFT

2. Site Description

A description of the subject property is detailed in the sections below. Refer to Figure 1 for a project locus and Figure 2 for a site plan showing relevant subject property features and adjacent properties.

2.1 SITE OWNERSHIP, LOCATION, AND VICINITY DESCRIPTION

Site Description		
Owner	ACCURATE ORGANIZATION 98 CORP. (Lot 20) 130 West Lido Promenade Lindenhurst, New York 11757 ACCURATE ORGANIZATION 112-114-148-152 CORP. (Lot 24) P.O. Box 362 Lindenhurst, New York 11757 ACCURATE ORGANIZATION 112-114-148-152 CORP. (Lot 25) 130 West Lido Promenade Lindenhurst, New York 11757	
Operator/ Occupant	Accurate Metal Slitting 98 Berriman Street Brooklyn, New York	
Current Subject Property Use	Lot 20: Industrial Building Lot 24: Unlicensed parking lot/auto towing yard Lot 25: Unlicensed parking lot/auto towing yard	
Size	Lot 20: 10,500 sq ft Lot 24: 2,000 sq ft Lot 25: 5,000 sq ft	
Building Square Footage	Lot 20: 10,500 sq ft	
U.S. Geological Survey (USGS) 7.5-Minute Topographic Map	Brooklyn, 2019	
Site County	Kings County	
Zoning	R6A Medium-density Residential	
Parcel Information	Borough 3, Block 3989, Lot 20 Borough 3, Block 3989, Lot 24 Borough 3, Block 3989, Lot 25	
Utilities	Water:	City of New York
	Sewerage:	New York City Department of Environmental Protection (NYCDEP)
	Electricity:	Consolidated Edison (ConEd)
	Gas/Oil/LPG:	N/A
Heating/Cooling System	Heating is provided by a boiler system connected to two on-site aboveground storage tanks (ASTs) filled with No. 2 fuel	

DRAFT

Site Vicinity Description		
General Area Description	The area surrounding the subject property consists of residential and commercial properties	
Adjoining Property Description	North:	Auto repair shop (96 Berriman Street)
	East:	Berriman Street, followed by Public School 345, a three-story elementary school (126 Atkins Avenue)
	South:	Two-story family apartments (118 Berriman Street)
	West:	Walk-up family apartments (345, 349, 355 Shepard Avenue) Undeveloped lot used for parking (341 Shepard Avenue)

2.2 PHYSICAL SETTING

Subsurface explorations and/or hydrogeologic investigations were not performed for this Phase I. Subject property geology and hydrology were evaluated on the basis of readily available public information or references, and/or based upon our experience and understanding of subsurface conditions in the vicinity of the subject property. It is unknown to what extent localized variations in groundwater depth and flow occur on the subject property.

Physical Setting		Source
Topography Summary	The subject property gently slopes to the south.	1,2
Subject Property Elevation (El.)	Approximate El. 32 feet (ft) above sea level	2
Overburden Soils	Subsurface soil at the subject property consists of urban fill, which is primarily comprised of brown silty sand with some fragments of concrete, brick, and asphalt from grade to 5 ft below grade surface (bgs). The urban fill layer is overlying glacial out wash deposits characterized as orange-brown sandy loam.	3
Bedrock Formation	Bedrock underlaying the subject property is unknown and is overlain by glacial and alluvial deposits.	4
Depth to Bedrock	Anticipated to be encountered at approximately 500 ft bgs	2
Depth to Groundwater	Anticipated to be encountered at approximately 30 to 35 ft bgs	2,3
Surface Water Flow Direction	Surface water appears to flow toward the south based on observed surface topography.	1,2
Regional Groundwater Flow Direction	Regional groundwater flow appears to flow to the south based on proximity to Hendrix Creek and Island Channel.	2, 1

DRAFT

Physical Setting		Source
Nearest Surface Water Body	Hendrix Creek is located approximately 7,972 ft south of the subject property.	1,2

Sources:

1. *Brooklyn 2019 USGS 7.5 Minute Topographic Map.*
2. *EDR Radius Map Report with Geocheck- Inquiry Number 08102930.2r, September 09, 2025.*
3. *New York State Department of Environmental Conservation (NYSDEC). DECinfo Locator [Interactive map database]. Retrieved September 11, 2025, from https://gisservices.dec.ny.gov/gis/decinfoweb/*
4. *USGS Bedrock Map of New York*

Environmentally Sensitive Areas		Source
Floodplain	No	1
Mapped Wetlands	No	2

Sources:

1. *Federal Emergency Management Agency (FEMA) Flood Map Service Center – http://msc.fema.gov/portal/home, accessed September 11, 2025.*
2. *National Wetlands Inventory Map – http://www.fws.gov/wetlands/data/mapper.html, accessed September 11, 2025.*

DRAFT

3. Previous Reports

Previously prepared reports for the subject property were not identified or provided as part of this assessment.

DRAFT

4. Subject Property History

Haley & Aldrich of New York assessed past usage of the subject property and adjoining properties through a review of:

- Sanborn Fire Insurance Maps (Sanborn Maps) dated 1887, 1908, 1928, 1951,1965, 1968, 1977, 1979, 1980, 1982, 1987, 1988, 1989, 1991, 1993, 1994, 1995, 2001, 2002, 2003, 2004, 2005, 2006, and 2007;
- Topographic Maps dated 1897, 1898, 1900, 1947, 1956, 1957, 1966, 1967, 1979, 1994, 1995, 2013, 2016, and 2019;
- Aerial Photographs dated 1924, 1951, 1954, 1961, 1966, 1976, 1980, 1984, 1994, 2006, 2011, 2015, 2019, and 2022;
- City Directories dated 1928, 1934, 1940, 1945, 1949, 1960, 1965, 1970, 1973,1976, 1980, 1985, 1992, 1995, 1997, 2000, 2005, 2010, 2014, 2017, 2020, and 2022; and
- Municipal records.

Copies of information obtained from historical references reviewed are included in Appendix B. Unless otherwise noted below, per the ASTM Standard, sources were reviewed dating back to 1940 or first developed use, whichever is earlier, and at five-year intervals if the use of the property has changed within the time period.

4.1 SUBJECT PROPERTY

According to Sanborn Maps, by 1887, the subject property was partially developed on Lot 25 with a single dwelling on the east side of the lot and a shoe factory on the west side. The shoe factory was replaced with a sweater factory, as depicted in the 1908 Sanborn Map. Lots 20 and 24 were depicted as vacant and undeveloped through the 1920s. By 1928, Lot 20 had been developed as a garage with two gas tanks depicted on the southeast corner of the lot, and Lot 24 was developed with a dwelling on the eastern side of the lot. The sweater factory on Lot 25 remained unchanged into the late 1920s; however, the dwelling on the eastern side of this lot was razed, and a small auto shop was developed in its place. By 1951, the subject property remained mostly unchanged, with the exception that Lot 20 became a razor blade manufacturer. By 1965, the razor blade manufacturing operation was relabeled as non-descript manufacturing. City Directories listed the operator of Lot 20 as Kellerman Manufacturing Co. Inc. in 1965 and 1970, and the operators of Lot 25 as various knitting operations from the mid-1930s through 1976. Lot 24 was listed as operated by several individuals during this time period. The subject property remained largely unchanged through 1987, with the exception of the buildings on Lots 24 and 25 being razed at some point during the 1980s. The subject property is currently occupied and operated by Accurate Metal Slitting on Lot 20 and an auto towing/unlicensed parking lot on Lots 24 and 25.

The table below provides a detailed summary of pertinent information from the historical sources reviewed.

DRAFT

Dates	Description of Subject Property	Sources
1887 to 1951	In 1887, Sanborn Maps depicted Lot 25 as developed with a dwelling on the east side and a shoe factory on the west. Lots 20 and 24 were shown as undeveloped. By 1908, the shoe factory was replaced with a sweater factory on Lot 25, while Lots 20 and 24 remained vacant and undeveloped. By 1928, Lot 20 was developed with a full garage with two gas tanks depicted on the southeast corner, and Lot 24 was developed with a dwelling on the eastern side of the lot. The sweater factory on Lot 25 remained unchanged; however, the dwelling on the eastern side was razed, and a small auto shop was developed. City Directories list several garages operating on Lot 20 from 1934 to 1940, and the Del Co Knitwear Factory as operating on Lot 25 in 1934.	Sanborn Maps, Aerial Photographs,
1951 to 1987	By 1951, the subject property remained mostly unchanged, with the exception of Lot 20, which was depicted as converted into a razor blade manufacturer on the Sanborn Maps. The gas tanks depicted on Lot 20 were no longer present. By 1965, the razor blade manufacturing facility was relabeled as non-descript manufacturing. City Directories indicate that Lot 20 was operated by Kellerman Manufacturing Co. Inc. in 1965 and 1970. City Directories also indicate Lot 25 was operated by knitting operations, including HS Knitting Mills Inc., Wise Mann Knitwear Corp., John Schmidt Knitting Mills Inc., Johanna Knitting Mills, and K&T Knitting Mills from 1965 through 1976. Lot 24 was listed as operated by several individuals during this time period.	Sanborn Maps, Aerial Photographs
1987 to present	The subject property remained largely unchanged through 1987, with the exception of the buildings on Lots 24 and 25 being razed at some point during the 1980s. The building on Lot 20 continued to be noted for manufacturing use. The subject property is currently occupied and operated by Accurate Metal Slitting on Lot 20 and an auto towing/unlicensed parking lot on Lots 24 and 25.	Sanborn Maps, Aerial Photographs, City Directories

4.2 ADJOINING PROPERTIES

The table below provides a summary of pertinent information from the historical sources reviewed regarding adjacent properties:

DRAFT

Dates	Description of Adjacent Properties	Sources
1887-1928	North: By 1887, the property was partially developed with a dwelling on the eastern side of the property. By 1928, the property was also developed with an auto shop on the southwest corner of the property. South: By 1887, the property was partially developed with a dwelling on the west side of the property. In the 1908 Sanborn Map, a shed was developed on the southwest corner of the property that was converted to an auto shed by 1928. East: Berriman Street, followed by the John C. Creveling & Son Inc. Coal & Lumber Yard shown on the 1908 Sanborn Map, which included multiple lumber sheds, printing operations, offices, and a toy manufacturing and machinist area. The property also had a rail spur which extended north and connected to a rail yard located north of Liberty Avenue, adjacent to the Standard Oil Co. of New York. West: By 1887, the properties were either vacant and undeveloped or developed with singular one- to two-story residential buildings per lot. By 1928, additional dwellings had been developed in addition to a junkyard and auto sheds/garages along the eastern boundary of the properties.	Sanborn Maps, Aerial Photographs
1928-1965	North: By 1951, the dwelling was removed from the property, and the auto building was expanded and remained in the southwest corner. In the 1965 Sanborn Map, the auto repair was expanded to extend to the eastern property boundary abutting Berriman Street. South: By 1951, an additional dwelling was developed on the east side of the property, and the auto shed remained on the west side. East: In the 1951 Sanborn Map, the coal and lumber yard was relabeled as the Harvey Lumber Co. Operations remained similar, with the addition of a woodworking area, and the former toy manufacturing/machinist area was replaced with metal products manufacturing operations. The rail spur and associated rail yard to the north were no longer depicted in 1951 and assumed to have been decommissioned sometime between the late 1920s and early 1950s. By 1965, the property was shown as used for metal parts storage and metal works. West: The properties and dwellings remain relatively unchanged.	Sanborn Maps, Aerial Photographs
1965-present	North: The property remains relatively unchanged. South: The property remains relatively unchanged. East: By 1968, the property is redeveloped into Public School No. 345/Liberty Public School. The school remains relatively unchanged to the present and is currently owned by the NYC Department of Education. West: The properties remain relatively unchanged.	Sanborn Maps, Aerial Photographs

DRAFT

5. Environmental Records Review

5.1 ENVIRONMENTAL DATABASE RECORDS SEARCH

Haley & Aldrich of New York used an electronic database service[2], to complete the environmental records review. The database search was used to identify properties that may be listed in the referenced agency records, located within the ASTM-specified approximate minimum search distances as shown in the table below. A description of each database searched is provided in Section 11.2 of this report. The complete environmental database report is provided in Appendix C. Pertinent information obtained from the database is summarized in Section 5.3.

Database Searched	Approximate Minimum Search Distance	Subject Property Listed?	Number of Sites within Search Distance[1]
1. NPL Sites	1 mile	No	0
2. Delisted NPL Sites	0.5 miles	No	0
3. CERCLIS/SEMs[2] Sites	0.5 miles	No	1
4. CERCLIS-NFRAP/SEMs[2] Sites	0.5 miles	No	0
5. Federal ERNS	Site only	No	Not Applicable
6. RCRA non-CORRACTS TSD Facilities	0.5 miles	No	0
7. RCRA CORRACTS TSD Facilities	1 mile	No	0
8. RCRA Generators	Site & Adjoining	No	1
9. Federal Institutional/Engineering Controls	Site Only	No	Not Applicable
10. State/Tribal Equivalent NPL Sites	1 mile	No	2
11. Lists of state and tribal hazardous waste facilities[2]	0.5 miles	No	2
12. State/Tribal Registered Storage Tanks	Site & Adjoining	No	0
13. State/Tribal Landfills and Solid Waste Disposal Sites	0.5 miles	No	2
14. State/Tribal Leaking Storage Tanks	0.5 miles	No	37
15. State/Tribal Institutional Controls/Engineering Controls	Site Only	No	Not Applicable
16. State/Tribal Voluntary Cleanup Sites	0.5 miles	No	14
17. State/Tribal Brownfield Sites	0.5 miles	No	9
18. Orphan Site List[3]	Site & Adjoining	No	0

Notes:

1. *Some sites may be included in multiple databases.*
2. *Formerly the CERCLIS database.*
3. *Haley & Aldrich of New York also searched the Orphan Site List provided in the database report for the subject property and sites adjoining the subject property. Orphan sites are those that, due to incorrect or incomplete addresses, could not be mapped.*

[2] Examples of electronic database services are EDR/Lightbox and ERIS.

DRAFT

5.2 ADDITIONAL ENVIRONMENTAL RECORDS OR FILE REVIEW

To supplement the environmental record search, we contacted the following state and local government agencies and searched applicable online databases. If copies of the documents reviewed were obtained, pertinent material is included in Appendix C. Relevant information obtained is included in the appropriate sections of the report and/or discussed in Section 5.3. Adjacent properties were also included in requests for additional information if a significant incident or release was identified.

Agency	Request Sent or Files Searched		Files Exist and are Available for Review	Files Reviewed
	Subject Property	Adjoining Properties		
NYSDEC [2]	Yes	Yes	Yes	Yes (online)
New York City Department of Finance City Registry[3]	Yes	No	Yes	Yes (online)
New York City Department of Buildings[4] (NYCDOB)	Yes	No	Yes	Yes (online)
New York State Department of Health (NYSDOH)[1,5]	Yes	No	N/A	N/A
Fire Department of New York (FDNY)[6]	Yes	No	No	N/A
NYCDEP[7]	Yes	No	No	N/A
New York City Office of Environmental Remediation (NYCOER)[8]	Yes	No	Yes	Yes (online)

Notes:

1. *To date, no responses have been received from the Freedom of Information Act (FOIA) requests noted above. Based on the information obtained through our interviews with key site personnel and our review of other records, it does not appear that responses to the FOIA requests should affect our conclusions regarding RECs on the subject property. However, when a response is received, it will be forwarded to Berriman Residents LLC and, if it affects our conclusions regarding the subject property, Berriman Residents LLC will be informed.*
2. *The NYSDEC maintains information regarding spills, petroleum bulk storage (PBS), including underground storage tanks (USTs) and ASTs, and investigations/remediations overseen by New York State regulatory programs. No records were identified in the NYSDEC online database, and a response has been received stating that no records were found.*
3. *The New York City Department of Finance City Registry maintains information regarding property transactions, including deeds, leases, and mortgage documents. Records were reviewed in the online database.*
4. *The NYCDOB maintains information regarding violations, complaints, certificates of occupancy, elevator records, asbestos assessments, and permits. Three certificates of occupancy were identified in the online database.*
5. *The NYSDOH maintains information regarding environmental concerns for public health. A response has not yet been received from the NYSDOH.*
6. *The FDNY maintains information regarding USTs and emergencies/fire episodes. A response has been received from the FDNY stating that no records were found.*
7. *The NYCDEP maintains information regarding wastewater discharge and boilers. Documents for the subject property were not available in the online database.*
8. *The NYCOER maintains information regarding investigations/remediations, manages the New York City Voluntary Cleanup Program (VCP), and assists with guidance through all the City Environmental Quality Review (CEQR) requirements. The subject property was not listed in the NYCOER database.*

DRAFT

5.3 DETAILED DESCRIPTION OF RELEVANT INFORMATION

5.3.1 Subject Property

Listing	Description	Potential Impact
E-Designation	The subject property is listed in the E-Designation database and is associated with E-366 for Air Quality (heating, ventilation, and air conditioning [HVAC] fuel limited to natural gas) and Hazardous Materials (Phase I and Phase II Testing Protocol) under CEQR No. 15DCP102K. Satisfaction of the E-Designation requirements is subject to review and approval by the NYCOER prior to redevelopment.	A listing in this database does not necessarily indicate an environmental concern; however, satisfaction of the E-Designation requirements is subject to review and approval by the NYCOER prior to redevelopment.
NYC Land Use	The NYC Land Use Database, curated by the New York City Department of City Planning (NYCDCP), includes data on land use within New York City. The subject property is categorized as "F4: Factory and Industrial Buildings."	A listing in this database does not necessarily indicate an environmental concern.

5.3.2 Nearby Sites

Several sites were listed in the database report within the applicable search radii or identified in regulatory records reviews. Due to their location with respect to the subject property (on the opposite side of a hydrogeologic barrier, distance from the site, location of the site relative to inferred groundwater flow, subsurface utilities and building levels, etc.), or their status (closed-out release, etc.), several of the sites are not likely to adversely affect the subject property and are not discussed herein. Only those sites adjacent to the subject property and sites with the potential to have impacted the subject property are discussed below. The complete database report and relevant records review information are included in Appendix C.

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
ConEd 778 Liberty Avenue (Approximately 42 ft northwest)	Manifest NYC Land Use E-Designation	ConEd is listed in the Manifest database under U.S. Environmental Protection Agency (USEPA) ID: NYR000114579 for the transportation of 200 pounds (lbs) of hazardous waste containing lead from this address on August 13, 2021. The property is also listed in the NYC Land Use database as class "G7: Garages and Gasoline Stations – Unlicensed Parking" and the E-Designation database with E-366 for hazardous materials, air quality, and noise.	A listing in these databases alone is not anticipated to adversely affect the subject property.

DRAFT

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
790 Liberty Avenue (Approximately 63 ft north)	NYCOER E-Designation	This property has an E-Designation for hazardous material, air quality, and noise, and is under review in the NYCOER database (Project Numbers: 22TMP0328K, 22EHAN065K). This property is currently in the Site Management phase for long-term management of residual soil contamination. Remedial activities were completed in April 2025.	As the property has been remediated under the NYCOER program and residual contamination is currently being controlled in the site management phase, this is not anticipated to adversely affect the subject property.
New York City Department of Education, Public School 345 (Approximately 57 ft east)	RCRA SQG Manifest AST	The property is listed in the Resource Conservation and Recovery Act (RCRA) database as a small quantity generator (SQG) with a USEPA ID: NYR000242271 for the production of waste containing lead. The property is listed in the Manifest database under USEPA ID: NYR000242271 for the transportation of 10 lbs of hazardous waste containing lead from this address on February 4, 2024. The property is listed in the AST database under PBS facility ID: 2-355763 for three ASTs, including: • a 7,500-gallon AST containing No. 4 fuel oil that was installed on September 3, 1967, and closed on January 10, 2020; • a 7,500-gallon AST containing No. 4 fuel oil that was installed on September 3, 1967, and closed on January 10, 2020; and • a 6,000-gallon AST containing No. 4 fuel oil that was installed on September 13, 2019, and closed on May 25, 2023 (closure date obtained from NYSDEC's online PCBs database).	Since there are no violations associated with the RCRA generator and manifest listings, it is not anticipated to adversely affect the subject property; however, it is notable as lead may be indicative of urban fill in the area. In addition, as no releases were reported associated with the AST listing, it is not anticipated to adversely affect the subject property.

DRAFT

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
Manhole No. 4750 Liberty Avenue & Berriman Street (Approximately 110 ft northeast)	NY Spills NY Manifest RCRA NonGen/NLR FINDS	Spill No. 0508732 was reported to NYSDEC on October 20, 2005, due to a release of one pint of unknown oil in 10 gallons of water. The cause was unknown, but oil was discovered while locating a fault. A sample was collected that identified elevated PCBs in the liquid. In 2005, approximately 144 gallons of liquid were removed from the structure, the structure was washed, and debris and personal protective equipment used during the cleanup were removed from the property. The spill was closed on May 3, 2007. This property is listed in the RCRA database as a Non-Generator/No Longer Regulated (NonGen/NLR) facility with ConEd Service Box 57327 as the handler under USEPA ID: NYP004533543. There was a historic listing of SQG in May 2014. As of 2015, the listing is identified as "not a generator, verified." No violations are associated with this listing. This property is also listed in the NY Manifest database under USEPA ID: NYP004533543 for the transportation of 50 gallons of hazardous waste containing lead from this address on May 15, 2014. This property is listed in the RCRA database as a NonGen/NLR facility with ConEd Manhole 4750 as the generator under USEPA ID: NYP004136933. There was a historic listing of Large Quantity Generator (LQG) on February 21, 2006; however, by February 23, 2006, the listing changed to "not a generator, verified." No violations are associated with this listing. This manhole is also listed in the Manifest database under USEPA ID: NYP004136933 for the transportation of 449 kilograms of unknown waste on October 22, 2005. The property is listed in FINDS databases used to track facilities and provide enforcement and compliance data. No violations were identified in the FINDS databases.	Since there are no violations associated with the RCRA generator listing and the spill case has achieved regulatory closure, this is not anticipated to adversely affect the subject property.

DRAFT

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
J&D Cleaners 770 Liberty Avenue (Approximately 110 ft northwest)	EDR Hist Cleaner NYC Land Use E-Designation	The property is listed as a historic dry cleaner under the name D&J Cleaners. The database does not provide detailed operational history, years of activity, or specific materials handled. The property is also listed in the NYC Land Use database as class "S5: residence – multiple use" and the E-Designation database with E-366 for hazardous materials, air quality, and noise.	Due to the lack of violations and documented releases associated with these listings, this is not anticipated to adversely affect the subject property.
355 Shepard Avenue (Approximately 84 ft southwest)	NYCOER VCP NY Spills	This property was remediated and achieved closure through the NYCOER VCP (Project IDs: 19TMP1307K, 19EHA310K, 22CVCP091K). As per the closure report dated February 2025, the remedy achieved a Track 1 remedial action for which engineering controls were not required. Spill No. 0410456 was reported to NYSDEC on December 12, 2004, due to an oil truck leak of kerosene onto concrete during delivery. The spill was closed on December 12, 2004.	Since the spill case has achieved regulatory closure and the property has been remediated with regulatory oversight, this is not anticipated to adversely affect the subject property.

DRAFT

Property Name & Location	Database/ Record Identified	Description	Potential Impact to Subject Property
352-362 Shepard Avenue (Approximately 206 ft southwest)	Brownfield UST NY Spills EDR Hist Auto	The former Garone Bros Auto Service Center is listed in the Brownfield Cleanup Program (BCP) as Site C224338. The property was added to the program on January 20, 2022, due to the former auto services center contaminating the site and underlying soil with volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) at concentrations exceeding Unrestricted Use Soil Cleanup Objectives (UUSCOs). Remedial actions were completed, and the site was remediated to meet unrestricted use for which engineering controls were not required. The property is listed in the UST database under PBS facility ID: 2-613563 for one closed 550-gallon UST containing an unknown substance and was reportedly installed on July 20, 2021, and closed on April 9, 2024. Spill No. 9705843 was reported to NYSDEC on August 14, 1997, due to a small leak in a gasoline dispenser, spilling oil on a concrete garage floor. The spill was cleaned and closed on June 29, 2010. The property is listed in the EDR Historic Auto database under the name Shepard Ave Garage Inc. The database does not provide detailed operational history, years of activity, or specific materials handled.	Due to (1) the distance from the subject property, (2) the location of the property (expected downgradient), (3) the spill closure, (4) the lack of violations associated with the tank, and (5) that the property has been remediated with regulatory oversight, these listings are unlikely to adversely affect the subject property.

5.4 VAPOR MIGRATION

The ASTM E1527-21 Standard states that "for the purposes of this practice, 'migrate' and 'migration' refer to the movement of hazardous substances or petroleum products in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." Thus, this section specifies whether or not we perceive a risk of vapor migration to the subject property.

To assess a vapor migration risk, Haley & Aldrich of New York conducted a detailed review and analysis of the site-specific environmental database report and/or other reasonably ascertainable records to assess whether:

1. Off-site properties have documented chlorinated volatile organic compound (CVOC) contamination located, specifically, the edge of the contamination plume, within 100 ft of the subject property boundary; or
2. Off-site properties have a documented volatile petroleum hydrocarbon (VPH) contamination plume within 30 ft of the subject property boundary.

DRAFT

Based on our records review, it is unconfirmed if a potential source of vapor migration currently exists beneath the subject property. However, based on the current and former uses of the surrounding properties, there is potential for petroleum-related compounds to be present in soil vapor throughout the area and under the subject property.

DRAFT

6. Subject Property Reconnaissance and Key Personnel Interview(s)

A site visit to observe subject property conditions was conducted by Mari Cate Conlon and Kaitlyn Moses of Haley & Aldrich of New York on September 16, 2025. Access to the subject property was provided by Kenny Duffin, a representative of the property occupant (Accurate Metal Slitting).

Haley & Aldrich of New York personnel observed accessible interior areas of the subject property building(s), including common areas, storm cellars, mechanical spaces, and tenant spaces. Haley & Aldrich of New York also observed the exterior portions of the subject property, including the property boundaries, parking lot, and observed adjoining property conditions from the subject property boundaries and/or public thoroughfares. No weather-related conditions or other conditions that would limit our ability to observe the subject property or adjoining properties occurred during our site visit.

An interview with Mr. Duffin of Accurate Metal Slitting, the key site manager and building tenant as required by the ASTM E1527-21 Standard, was performed in conjunction with the site visit. Per the ASTM Standard, past owners, operators, and occupants of the subject property who are likely to have material information regarding the potential for contamination at the subject property shall be contacted to the extent that they can be identified and that the information likely to be obtained is not duplicative of information already obtained from other sources. Haley & Aldrich of New York was not provided with contact information to interview past owners and/or operators at the subject property. Based upon historical data collected from other sources, this potential data gap is not expected to adversely impact the results of this assessment.

The findings of the site visit and interviews are discussed below. Subject property photographs are included in Appendix D.

ASTM E1527-21 Standard Section 10.8 requires that, prior to the site visit, the current subject property owner or key site manager and user, if different from the current owner or key site manager, be asked if there are any helpful documents that can be made available for review. Documents were not provided. The provided information is listed below.

6.1 CURRENT USE OF THE SUBJECT PROPERTY

The subject property is partially developed with a one-story industrial building on Lot 20 and an auto towing yard/parking lot on Lots 24 and 25. The industrial building is utilized as Accurate Metal Slitting, and the parking lot is used as storage for cars and trailers.

6.2 GENERAL DESCRIPTION OF STRUCTURES

The subject property is partially developed with a one-story industrial building and a parking lot. The industrial building has a storm cellar constructed with concrete. The exterior of the building is constructed primarily of brick and concrete. The parking lot is unpaved with loose stones and dirt.

6.3 USE, STORAGE, AND DISPOSAL OF PETROLEUM PRODUCTS AND HAZARDOUS MATERIALS

Petroleum products and/or hazardous materials were observed or reported to be used, stored, and/or disposed of at the subject property as described below.

DRAFT

The following bulk storage tanks were observed or reported to be associated with the subject property during the site visit:

Tank No.	AST/ UST	Contents/ Capacity	Location[1]	Use	Closure Status
1	AST	275 gallons of No. 2 Fuel	East side storm cellar	Stores fuel oil for boiler heating	Active
2	AST	275 gallons of No. 2 Fuel	Southwest corner of building	Fuel storage	Active
Notes: 1. *Approximate tank locations are shown on Figure 2.*					

A fill port and vent pipe were observed immediately outside the building to the east of the subject property and next to the storm cellar doors. A fill port and vent pipe were not observed in the vicinity of the AST on the first floor in the southwest corner; however, access to the exterior of the building in this area was limited due to car placement in the auto yard.

Other petroleum/hazardous materials observed at the subject property included:

Petroleum Product or Hazardous Substances	Quantity Stored	Storage Location	Use	Disposal	Observations/ Evidence of release
Antifreeze	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Automatic transmission fluid	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
97 fibered aluminum roof coating	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Lubricant	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
1,1,1,2-Tetrafluoroethane	Multiple 30-lb tanks	Main room of building	Metal slitting and auto operations	Unknown	None
Hydraulic oil	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Solvent	Multiple drums of different sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Motor/waste oil	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Diesel	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Adhesive	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None

DRAFT

Petroleum Product or Hazardous Substances	Quantity Stored	Storage Location	Use	Disposal	Observations/ Evidence of release
Paint and spray paint	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Unknown substance	Multiple gallon-sized Arizona iced tea containers	Main room of building	Unknown	Unknown	Incorrect storage and labeling
Unknown substance	Multiple 5-gallon water jugs	Main room of building	Unknown	Unknown	Incorrect storage and labeling
Compressor oil	Multiple metal drums	Main room of building	Metal slitting and auto operations	Unknown	Hand-labeled drum
Quick-set mortar and grout	Multiple containers of various sizes	Main room of building	Metal slitting and auto operations	Unknown	None
Car batteries	Multiple	Main room of building	Metal slitting and auto operations	Unknown	Stacked on the floor /dirty /next to chemicals
Propane tank	Multiple 5-gallon metal tanks	Locked metal cage on exterior of south side of building	Unknown	Unknown	One tank sitting outside the cage

Potentially hazardous materials observed on the subject property were primarily associated with automotive and metal slitting operations. The majority of materials were stored in poor condition, including in improper or unlabeled containers, with some having handwritten labels. Substances were often stored without proper secondary containment directly on the floor. Evidence of extensive staining and possible releases was observed throughout the interior of the facility, as well as in multiple areas where the concrete cover was damaged or cracked. Evidence of releases reaching floor drains was not noted at the time of site inspection. Staining and evidence of oil release were also observed in the exterior auto yard, with cardboard placed under certain vehicles for apparent containment purposes. Unknown substances were stored in reused iced tea containers, water jugs, plastic containers, and open-top drums. Car batteries were observed stacked on wood pallets and directly on the floor. Kitty litter/Speedy Dry was observed in multiple locations throughout the building in containers immediately adjacent to hydraulic machinery / metal slitting equipment, and observations were made of litter/Speedy Dry on the floor for use as an absorbent agent.

6.4 OTHER SUBJECT PROPERTY OBSERVATIONS

The table below summarizes items that were observed and/or reported at the subject property during the site visit other than those items related to use, storage, and/or disposal of petroleum or hazardous materials (described in Section 6.3 above). If items were observed or reported, they are further described either in the table or below.

DRAFT

Description	Observed or Reported at Time of Site Visit	Observations/Comments
Potable Water Supply	Yes	Potable water provided by the NYCDEP
Nearest Drinking Water Source	N/A[1]	
Sewage Disposal System	Yes	NYCDEP municipal system
Septic System	No	
Unidentified Storage Containers	Yes	Several unlabeled iced tea containers and water jugs holding unknown substances. Many drums and containers were hand-labeled.
Wastewater Discharge	No	
Stormwater Discharge	No	
Odors	Yes	Storm cellar had a strong petroleum-like odor
PCBs Associated with Electrical or Hydraulic Equipment	Yes	Multiple hydraulic lifts and hydraulic-powered equipment were noted throughout the facility
Elevators (Traction or Hydraulic)	No	
Vehicle Maintenance Lifts	Yes	Several types of hydraulic equipment were located in the main room of the facility
Emergency Generators	No	
Sprinkler System Pumps	No	Fire suppression system
Heating System	Yes	Boiler encased in assumed to be asbestos-containing-material was located in the storm cellar
Cooling System	No	
Stains or Corrosion on Floors, Walls, or Ceilings	Yes	Extensive floor staining in the building and the cellar
Floor Drains	Yes	In the storm cellar and along the east wall of the first floor of the building
Sumps	Yes	Evidence of a potential sump or sprinkler drainage structure without a concrete bottom was observed on the eastern wall within the metal slitting facility
Catch Basins	No	
Pits, Ponds, Lagoons, and Pools of Liquid	No	
Stained Soil or Pavement	Yes	Evidence of staining and oil releases in the auto yard, including stained cardboard under machinery
Stressed Vegetation	No	
Solid Waste and Evidence of Waste Filling	No	
Dry Wells	No	
Monitoring Wells	No	
Water Supply Wells	No	
Irrigation Wells	No	
Injection Wells	No	
Abandoned Wells	No	

Notes:

1. *N/A items are those that were not observed or reported and/or not anticipated to be present given the nature of the subject property (e.g., building features not present on an undeveloped property).*

DRAFT

6.5 ADJOINING PROPERTY OBSERVATIONS

Silk Auto Repair was observed adjacent to the subject property to the north. A two-story family apartment building is located to the south. To the east, Berriman Street is followed by a three-story elementary school. Several walk-up family apartment buildings were observed to the west. The auto repair shop to the north presents a potential environmental concern as it is presumed to be upgradient and due to the typical use, storage, and handling of hazardous materials such as solvents, oils, and other automotive fluids. If these substances have been released to the subsurface, they may pose a risk to the subject property.

6.6 USER RESPONSIBILITIES

The AAI Rule requires that the user of the report consider the following:

- Whether the user has specialized knowledge about previous ownership or uses of the subject property that may be material to identifying RECs;
- Whether the user has determined that the subject property's title contains environmental liens or other information related to the environmental condition of the property, including engineering and institutional controls and Activity and Use Limitations (AULs), as defined by ASTM;
- Whether the user is aware of commonly known or reasonably ascertainable information about the subject property, including whether or not the presence of contamination is likely on the subject property and to what degree it can be detected; and
- Whether the user has prior knowledge that the price of the subject property has been reduced for environmentally related reasons.

While such information is not required to be provided by the Environmental Professional(s), the information can assist the Environmental Professional in identifying RECs. The AAI Final Rule (Code of Federal Regulations Title 40 [40 CFR] Part 312) requires that these tasks be performed by or on behalf of a party seeking to qualify for one of the Landowner Liability Protections (LLPs) to CERCLA liability.

Haley & Aldrich of New York provided the user with a responsibilities questionnaire; however, a completed questionnaire was not received. The absence of such information is not considered significant to our conclusions.

DRAFT

7. Findings and Opinions

7.1 SIGNIFICANT DATA GAPS

Our ability to identify and evaluate RECs at the subject property is conditioned upon significant data gaps identified as part of this Phase I. The ASTM E1527-21 Standard defines a significant data gap as a data gap that affects the ability of the Environmental Professional to identify a REC.

No significant data gaps were identified during the performance of this Phase I. Thus, it is our opinion that sufficient information was obtained to identify subject property conditions indicative of releases or threatened releases of hazardous substances and petroleum hydrocarbons. Our opinion is limited by the conditions prevailing at the time our work is performed and the applicable regulatory requirements in effect.

7.2 RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a REC as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

Our opinion regarding a REC's potential impact on the subject property is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, our experience evaluating similar sites, and on our understanding of the client's intended use for the subject property.

The following RECs were identified in connection with the subject property.

REC #1: Current Uses and Condition of Subject Property

At the time of inspection, the subject property was operating as a metal slitting and auto towing/parking facility. The building is used for metal slitting and storage of machinery and automotive supplies. The exterior lot is used for auto towing and storage of cars and trailers. Two active 275-gallon ASTs containing No. 2 fuel oil were observed. One AST, located in the storm cellar on the east side of the building, is used to power a boiler, and the second AST, located on the first floor in the southwest corner of the building, is suspected to be used for heating. Site conditions, such as evidence of staining, improper storage of hazardous materials, and observations of kitty litter/Speedy Dry and stained cardboard located beneath equipment and vehicles, indicated previous and potentially ongoing releases. The current use of the property, in conjunction with the site conditions, is considered a REC.

REC #2: Historical Uses of the Subject Property

Sanborn Maps indicate that the subject property formerly operated as a shoe factory and sweater factory in the late 1800s and early 1900s, as well as a razor blade manufacturer from as early as 1951 through the 1970s. Non-descript manufacturing continues through the present on Lot 20, with the most

DRAFT

recent operator being a metal slitting facility. Two gas tanks were also depicted on the southeast corner of Lot 20 on the 1928 Sanborn Map. Potential environmental concerns associated with this historical use include the potential for release of hazardous substances commonly found in industrial practices, particularly if spills, leaks, or improper manufacturing practices occurred. The historical uses of the subject property are considered a REC.

REC #3: Historical and Current Uses of Surrounding Properties

Sanborn Maps indicate that by 1908, the east adjacent property was used as the John C. Creveling Coal & Lumber Yard with a rail spur extending northward across Liberty Avenue in apparent association with the Standard Oil Co. of New York. By 1951, the property was operated by the Harvey Lumber Co., and from 1965 to 1968, the property was utilized for metal parts storage. Additionally, by 1908, the north adjacent property was partially developed with an auto shop, and by 1965, the property was fully developed with an auto repair shop, which is currently still used as an auto repair shop. Sanborn Maps also indicate that there were multiple historic small auto sheds and garages to the west and south of the subject property. Potential environmental concerns associated with auto repair and manufacturing operations include the potential for release of hazardous substances such as spent solvents, waste oils, heavy metals, and chlorinated compounds. These surrounding historical and current uses are considered a REC.

7.3 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a CREC as a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

CRECs were not identified in connection with the subject property.

7.4 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines an HREC as "a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. An HREC is not a REC.

HRECs were not identified in connection with the subject property.

7.5 DE MINIMIS CONDITIONS

The ASTM E1527-21 Standard defines a *de minimis* condition as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. The ASTM E1527-21 Standard notes that conditions determined to be *de minimis* are not RECs.

De minimis conditions were not identified in connection with the subject property.

DRAFT

7.6 OTHER FINDINGS

The ASTM does not define the term “other finding”; however, Haley & Aldrich of New York utilizes the category to indicate conditions of potential risk that are not clearly defined in the ASTM Standard. While not considered RECs, Haley & Aldrich of New York identified the following Other Findings.

Other Finding #1: New York City E-Designation

The subject property has been assigned an environmental E-Designation (E-366) for Air Quality (HVAC fuel limited to natural gas) and Hazardous Materials (Phase I and Phase II Testing Protocol) under CEQR No. 15DCP102K). Satisfaction of the E-Designation requirements is subject to review and approval by the NYCOER prior to redevelopment.

Other Finding #2: Urban Fill

The overburden on the subject property is classified as Urban Land, which refers to soils that have been altered by human activities, thus making them unidentifiable. Typically, these soils have been mixed with other materials, such as brick and concrete (urban fill).

Other Finding #3: Boiler Encased in Potential Asbestos-Containing Material

During site inspection, the boiler located in the storm cellar was observed to be encased in potential asbestos-containing material. Proper confirmation sampling and decommissioning of the boiler and the encasement would be required as per New York City and State regulations as part of demolition.

DRAFT

8. Conclusions

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of the ASTM Practice E1527 of 98-114 Berriman Street, Brooklyn, New York, the subject property. Any exceptions to or deletions from this practice are described in Section 1.4 of this report.

This assessment has revealed evidence of three RECs and three "Other Findings" in connection with the subject property:

- REC #1: Current Uses and Condition of Subject Property
- REC #2: Historical Uses of the Subject Property
- REC #3: Historical and Current Uses of Surrounding Properties
- Other Finding #1: New York City E-Designation
- Other Finding #2: Urban Fill
- Other Finding #3: Boiler Encased in Potential Asbestos-Containing Material

Refer to Section 7.2 above for our opinion regarding the RECs listed above.

DRAFT

9. Environmental Professional Certification

The undersigned declares the following:

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in §312.10 of 40 CFR Part 312; and

I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Mari C. Conlon, P.G.
Senior Associate

DRAFT

10. Credentials

This Phase I report was prepared by Kaitlyn Moses under the direct supervision of Mari C. Conlon, who served as the Environmental Professional(s) for this project. Qualification information for the project personnel is provided below.

Mari C. Conlon, P.G., is a Senior Associate at Haley & Aldrich of New York and a licensed Professional Geologist in the state of New York with more than 11 years of experience conducting Phase I and Phase II Environmental Site Assessments.

Kaitlyn Moses is a staff geologist gaining experience at Haley & Aldrich of New York in Phase I and Phase II Environmental Site Assessments.

DRAFT

11. Glossary and Other Descriptions

11.1 GLOSSARY

All Appropriate Inquiry (AAI) — that inquiry constituting "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined in CERCLA, 42 U.S.C. §9601(35)(B), that will qualify a party to a commercial real estate transaction for one of threshold criteria for satisfying the LLPs to CERCLA liability (42 U.S.C. §9601(35)(A) & (B), §9607(b)(3), §9607(q); and §9607(r)), assuming compliance with other elements of the defense.

Business Environmental Risk — a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice. Consideration of business environmental risk issues may involve addressing one or more non-scope considerations.

Controlled Recognized Environmental Condition (CREC) — a recognized environmental condition resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

Significant Data Gap — a data gap that affects the ability of the Environmental Professional to identify a recognized environmental condition.

De Minimis Conditions — a condition related to a release that generally does not present those conditions which "do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies." The ASTM E1527-21 Standard notes that conditions determined to be *de minimis* are not recognized environmental conditions.

Environmental Professional — a person meeting the education, training, and experience requirements as set forth in 40 CFR §312.10(b).

Historical Recognized Environmental Condition (HREC) — a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. A historical recognized environmental condition is not a recognized environmental condition.

Key Site Manager — the person identified by the owner or operator of a subject property as having good knowledge of the uses and physical characteristics of the subject property.

Material Threat — an obvious threat which is likely to lead to a release and that, in the opinion of the Environmental Professional, would likely result in impact to public health or the environment.

Orphan Site — (not ASTM E1527-21 definition) — sites that could not be mapped due to poor or inadequate address information.

DRAFT

Recognized Environmental Condition (REC) — (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. *De minimis* conditions are not RECs.

11.2 DESCRIPTIONS OF DATABASES SEARCHED

Numerous regulatory databases were searched during this Phase I. Each database reviewed is described in the database report presented in Appendix C. Those databases required by the E1527-21 Standard are identified below.

1. **NPL Sites:** The National Priorities List (NPL) is a list of contaminated sites that are considered the highest priority for cleanup by the U.S. Environmental Protection Agency (USEPA).
2. **Delisted NPL Sites:** The Delisted NPL is a list of formal NPL sites formerly considered the highest priority for cleanup by the USEPA that met the criteria of the National Oil and Hazardous Substances Pollution Contingency Plan (NCP) for deletion from the NPL because a no further response was appropriate.
3. **CERCLIS Sites:** The Comprehensive Environmental Response, Compensation, and Liability Act Information System (CERCLIS) list identifies sites which are suspected to have contamination and require additional investigation to assess whether they should be considered for inclusion on the NPL.
4. **CERCLIS-NFRAP Sites:** CERCLIS-NFRAP status indicates that a site was once on the CERCLIS List but has No Further Response Actions Planned (NFRAP). Sites on the CERCLIS-NFRAP List were removed from the CERCLIS List in February 1995 because, after an initial investigation was performed, no contamination was found, contamination was removed quickly, or the contamination was not significant enough to warrant NPL status.
5. **Federal ERNS:** The Federal Emergency Response Notification System (ERNS) list tracks information on reported releases of oil and hazardous materials.
6. **RCRA non-CORRACTS TSD facilities:** The Resource Conservation and Recovery Act (RCRA) non-CORRACTS TSD Facilities List tracks facilities which treat, store, or dispose of hazardous waste and are not associated with corrective action activity.
7. **RCRA CORRACTS TSD facilities:** The RCRA CORRACTS TSD Facilities list catalogues facilities that treat, store, or dispose of hazardous waste and have been associated with corrective action activity.
8. **RCRA Generators:** The RCRA Generator list is maintained by the USEPA to track facilities that generate hazardous waste.
9. **Federal Institutional Controls/Engineering Controls:** The Federal Institutional Control list and Engineering Control list are maintained by the USEPA. Some Institutional Control and Engineering Control information may not be made publicly available and therefore will not be included on this registry.

DRAFT

10. **State and Tribal Equivalent NPL/CERCLIS Sites:** The ASTM E1527-21 Standard requires searching "State and Tribal Equivalent NPL Sites." In New York, the equivalent NPL is the Inactive Hazardous Waste Disposal Sites, which is maintained by the New York State Department of Environmental Conservation (NYSDEC).
11. **State and Tribal Registered Storage Tanks:** The NYSDEC maintains a list of aboveground and underground storage tanks registered with the NYSDEC Petroleum Bulk Storage Program.
12. **State and Tribal Landfills and Solid Waste Disposal Sites:** NYSDEC maintains a list of regulated waste disposal sites.
13. **State and Tribal Leaking Storage Tanks:** NYSDEC maintains a list of Leaking Storage Tanks (LUST/LAST). The LUST/LAST lists are a listing of release sites that have an underground or aboveground storage tank listed as the source.
14. **State and Tribal Institutional Controls/Engineering Controls:** NYSDEC maintains a list of sites with Institutional or Engineering Controls in place.
15. **State and Tribal Voluntary Cleanup Sites:** NYSDEC maintains a list of Voluntary Cleanup Program sites.
16. **State and Tribal Brownfield Sites:** NYSDEC maintains a list of Brownfield sites, which includes properties where redevelopment or reuse may be compromised by the presence or presumed presence of hazardous materials or petroleum.

DRAFT

12. References

1. Aerial Photographs dated 1924, 1951, 1954, 1961, 1966, 1976, 1980, 1984, 1994, 2006, 2011, 2015, 2019, and 2022.

2. City Directories dated 1928, 1934, 1940, 1945, 1949, 1960, 1965, 1970, 1973,1976, 1980, 1985, 1992, 1995, 1997, 2000, 2005, 2010, 2014, 2017, 2020, and 2022.

3. EDR Inquiry No. *08102930.2r,* Database Report, dated September 9, 2025.

4. Federal Emergency Management Agency Flood Map Service Center, accessed on September 11, 2025

5. Haley & Aldrich of New York, site visit conducted by Mari C. Conlon and Kaitlyn Moses on September 16, 2025.

6. Kenny Duffin of Accurate Metal Slitting, interview with Haley & Aldrich of New York, September 16, 2025.

7. Sanborn Fire Insurance Maps dated 1887, 1908, 1928, 1951,1965, 1968, 1977, 1979, 1980, 1982, 1987, 1988, 1989, 1991, 1993, 1994, 1995, 2001, 2002, 2003, 2004, 2005, 2006, and 2007.

8. Topographic Maps dated 1897, 1898, 1900, 1947, 1956, 1957, 1966, 1967, 1979, 1994, 1995, 2013, 2016, and 2019.

9. Topographic Map, Brooklyn, United States Geological Survey 7.5-minute series, 2019.

DRAFT

FIGURES

DRAFT



MAP SOURCE: USGS
SITE COORDINATES: 40°40'34"N, 73°52'50"W

HALEY ALDRICH

98 BERRIMAN STREET
BROOKLYN, NEW YORK

PROJECT LOCUS

APPROXIMATE SCALE: 1 IN = 2000 FT
SEPTEMBER 2025

FIGURE 1

GIS: \\haleyaldrich.com\share\CF\Projects\0214078\GIS\214078_98_BERRIMAN_ST.aprx - gwilde - 9/11/2025 1:03 PM



LEGEND

SITE BOUNDARY

PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.

2. ASSESSOR PARCEL DATA SOURCE: NYC DEPARTMENT OF CITY PLANNING, INFORMATION TECHNOLOGY DIVISION

3. AERIAL IMAGERY SOURCE: NEARMAP, JULY 3, 2025

N

0 30 60

SCALE IN FEET

HALEY ALDRICH

98 BERRIMAN STREET
BROOKLYN, NEW YORK

SITE PLAN

SEPTEMBER 2025

FIGURE 2

GIS FILE PATH: \\haleyaldrich.com\share\CP\Projects\0214078\GIS\214078_98_BERRIMAN_ST.aprx, - USER: gwilde - LAST SAVED: 9/11/2025 1:12 PM

DRAFT

APPENDIX A
Limitations

APPENDIX A

Haley & Aldrich of New York Limitations

Environmental site assessment (Phase I Environmental Site Assessment) reports prepared by H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) are for the sole and exclusive use of its Client. Haley & Aldrich of New York represents that the Phase I Environmental Site Assessment was prepared in accordance with the ASTM International (ASTM) Standard E1527-21 entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (ASTM E1527-21). The findings, opinions, conclusions, and information contained in the ASTM E1527-21 Phase I Environmental Site Assessment are limited to, and solely based upon, information reasonably ascertainable by Haley & Aldrich of New York at the time the ASTM E1527-21 Phase I Environmental Site Assessment was completed.

All users of this E1527-21 Phase I Environmental Site Assessment are bound to the terms and conditions and limitations contained in the accompanying Proposal, Terms and Conditions, and Limitations for this ASTM E1527-21 Phase I Environmental Site Assessment. The findings, opinions, conclusions, and information contained in this report are based solely on the Scope of Services provided pursuant to the Proposal and its attachments and the information reasonably ascertainable by Haley & Aldrich of New York at the time the ASTM E1527-21 Phase I Environmental Site Assessment was completed. Haley & Aldrich of New York has not performed any additional observations, investigations, studies, or other testing not specified in the Scope of Services. Haley & Aldrich of New York shall not be liable for the existence of any condition the discovery of which would have required the performance of services not authorized under the Scope of Services.

This ASTM E1527-21 Phase I Environmental Site Assessment is prepared for the exclusive use of Haley & Aldrich of New York's client in connection with the subject property for the purpose of assessing the potential or existing environmental contamination liabilities associated with the subject property. There are no intended beneficiaries other than Haley & Aldrich of New York's client. Haley & Aldrich of New York shall owe no duty whatsoever to any other person or entity by issuing the ASTM E1527-21 Phase I Environmental Site Assessment. Use of this ASTM E1527-21 Phase I Environmental Site Assessment by any person or entity, including by Haley & Aldrich of New York's client, for a purpose other than for the purpose of assessing the potential or existing environmental contamination liabilities associated with the subject property is expressly prohibited unless such person or entity obtains written authorization from Haley & Aldrich of New York indicating that the ASTM E1527-21 Phase I Environmental Site Assessment is adequate for such other use. Use of this ASTM E1527-21 Phase I Environmental Site Assessment by any person or entity for such other purpose without written authorization by Haley & Aldrich of New York shall be at such person's or entity's sole risk and shall be without legal exposure or liability to Haley & Aldrich of New York.

Haley & Aldrich of New York may authorize third-party reliance on the ASTM E1527-21 Phase I Environmental Site Assessment by providing reliance letters to third party(ies) provided that the third party(ies) agree: (1) to use the ASTM E1527-21 Phase I Environmental Site Assessment only for the purpose of assessing the potential or existing environmental contamination liabilities associated with real property; (2) to be bound by the terms and conditions and limitations contained in the ASTM E1527-21 Phase I Environmental Site Assessment report and the proposal and its Attachments, Terms and Conditions, and Limitations; (3) to accept the form and substance of Haley & Aldrich of New York's reliance letter; and (4) to deliver to Haley & Aldrich of New York a signed copy of a reliance letter by an

DRAFT

authorized representative of the relying party, within thirty (30) days after said reliance letter is provided to the relying party, signifying the relying party's acceptance of the aforementioned conditions. Upon Haley & Aldrich of New York's receipt of the signed reliance letter by the relying party(ies), the relying party(ies) will be authorized to rely on Haley & Aldrich of New York's ASTM E1527-21 Phase I Environmental Site Assessment for the limited purpose of identifying potential or existing environmental contamination liabilities associated with the subject property. The relying party(ies) agree(s) to bind each of its respective successors and assigns to the aforementioned Terms and Conditions.

This ASTM E1527-21 Phase I Environmental Site Assessment reflects subject property conditions observed and described by records available to Haley & Aldrich of New York as of the date of ASTM E1527-21 Phase I Environmental Site Assessment preparation. The passage of time may result in significant changes in subject property conditions, technology, or economic conditions, which could alter the findings and/or recommendations of the ASTM E1527-21 Phase I Environmental Site Assessment. Accordingly, Haley & Aldrich of New York's client and any other party to whom the ASTM E1527-21 Phase I Environmental Site Assessment is provided recognize and agree that Haley & Aldrich of New York shall bear no liability for deviations from observed conditions or available records after the time of ASTM E1527-21 Phase I Environmental Site Assessment preparation. Haley & Aldrich of New York makes no express or implied representation that the information contained in the E1527-21 Phase I Environmental Site Assessment has continued viability after 180 days of the ASTM E1527-21 Phase I Environmental Site Assessment's completion date, and any use or reliance on the ASTM E1527-21 Phase I Environmental Site Assessment after 180 days of the ASTM E1527-21 Phase I Environmental Site Assessment's completion date by Haley & Aldrich of New York's client or any other authorized person or entity will be at that party's sole risk and without liability to Haley & Aldrich of New York.

Notwithstanding anything contained herein, Haley & Aldrich of New York shall not be liable for any claim or damage arising from environmental contamination liabilities that occurred on the subject property after the effective date of the ASTM E1527-21 Phase I Environmental Site Assessment. Likewise, Haley & Aldrich of New York shall not be liable for any existing or future property owner's failure to satisfy any continuing obligation for CERCLA liability protection or under the Federal Environmental Protection Agency's All Appropriate Inquiries rule.

DRAFT

APPENDIX B
Historical Research Documentation

DRAFT

98-114 Berriman Street Development

98 Berriman Street

Brooklyn, NY 11208

Inquiry Number: 8102930.8

September 09, 2025

DRAFT

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

09/09/25

Site Name:

98-114 Berriman Street Develo
98 Berriman Street
Brooklyn, NY 11208
EDR Inquiry # 8102930.8

Client Name:

Haley & Aldrich, Inc.
299 Cherry Hill Road
Parsippany, NJ 07054
Contact: Kaitlyn Moses

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2022	1"=500'	Flight Year: 2022	USDA/NAIP
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Flight Year: 1994	USGS/DOQQ
1984	1"=500'	Flight Date: March 26, 1984	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1976	1"=500'	Flight Date: October 29, 1976	USGS
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: November 22, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 18, 1954	USGS
1951	1"=500'	Flight Date: April 20, 1951	EDR Proprietary Aerial Viewpoint
1924	1"=500'	Flight Date: July 01, 1924	FAIR

DRAFT

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 8102930.8
YEAR: 2022
= 500'
N
EDR


INQUIRY #: 8102930.8
YEAR: 2019
= 500'
N
EDR


INQUIRY #: 8102930.8
YEAR: 2015
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 2011
= 500'
N
EDR


INQUIRY #: 8102930.8
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 8102930.8
YEAR: 1994
= 500'
N
EDR


INQUIRY #: 8102930.8
YEAR: 1984
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 1980
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 1976
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 1966
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 1961
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 1954
= 500'
N
EDR

INQUIRY #: 8102930.8
YEAR: 1951
= 500'
N
EDR

INQUIRY #: 8102930.8

YEAR: 1924

= 500'

N

EDR

DUPLICATE

No. 26101

OFFICE OF THE PRESIDENT OF THE BOROUGH OF BROOKLYN

BUREAU OF BUILDINGS

CERTIFICATE OF OCCUPANCY

(ISSUED PURSUANT TO ARTICLE 1, SECTION 5, BUILDING CODE)

BROOKLYN, N. Y. May 24 1924

This is to certify that the NEW BUILDING

Located at 64 & 66 Livingston St & 69 & 71 Schermerhorn St

Has been COMPLETED substantially according to the approved plans and specifications and the requirements of the BUILDING CODE, and PERMISSION is hereby granted for the OCCUPANCY of said building for the following purposes:

Public Garage

Permit No. 17464 May 24

Per

DRAFT

DRAFT

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF BROOKLYN , CITY OF NEW YORK

No.

Date

CERTIFICATE OF OCCUPANCY

(...dard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the ...York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. ...ng Code.)

This certificate supersedes C. O. No.

...owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered ~~former~~ building—premises located at:

(DISP. 98) OFF. 98/108 Berriman Street, West Side, 90' South of Liberty avenue. Block 3989 Lot 20

, conforms substantially to the approved plans and specifications, and to the requirements ...building code and all other laws and ordinances, and of the rules and regulations of the Board of Stand...nd Appeals, applicable to a building of its class and kind at the time the permit was issued; and CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been ...ed with as certified by a report of the Fire Commissioner to the Borough Superintendent.

...Alt. No.— ALT. 1452/1946 Construction classification— NON-FIREPROOF

...ancy classification— FACTORY

...of completion— CONST. 9/4/46 PLUMB. 9/19/46 3D 10/9/46 . Located in BUSINESS AND / UNRESTRICTED Use District.

———Area ———— Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolu... of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

...TORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED			USE
		MALE	FEMALE	TOTAL	
...LAR	GROUND	-	-	-	Boiler Room.
...ST	GROUND	30	30	60	Factory and Storage.
	TOTAL: ————				FACTORY AND STORAGE.

...Borough Superintendent

DRAFT

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SH BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no chan rearrangement in the structural parts of the building, or affecting the light and ventilation of any part th or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasi height shall be made; nor shall the building be moved from one location or position to another; nor shall be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is cer

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses construction in any story shall not exceed the live loads specified on reverse side; the number of persons of sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of pe in any story exceed the specified total; and the use to which any story may be put shall be restricted to that by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in poss or control of the building, or any part thereof from obtaining such other permits, licenses or approvals a be prescribed by law for the uses or purposes for which the building is designed or intended, nor from obt the special certificates required for the use and operation of elevators; nor from the installation of fire systems where required by law; nor from complying with any lawful order for additional fire extingu appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful issued with the object of maintaining the building in a safe or lawful condition; nor from complying wit authorized direction to remove encroachments into a public highway or other public place, whether attac or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building ind on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to provisions and conditions applying to a final or permanent certificate; it is not applicable to any building und jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be re by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly ins and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as no the reverse side, and that on information and belief, since that date there has been no alteration or conv to a use that changed its classification as defined in the Building Code, or that would necessitate compliance some special requirement or with the State Labor Law or any other law or ordinance; that there are no of violations or orders pending in the Department of Housing and Buildings at this time; that Section of the New York City Charter has been complied with as certified by a report of the Fire Commissioner Borough Superintendent, and that, so long as the building is not altered, except by permission of the Bo Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, pl premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous subs articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extingu equipment are required by law to be or are installed, until the fire commissioner has tested and inspected a certified his approval in writing of the installation of such containers, systems or equipment to the Bo Superintendent of the borough in which the installation has been made. Such approval shall be record the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-45M-703401(61) 214

DEPARTMENT OF BUILDINGS

BOROUGH OF [redacted], THE CITY OF NEW YORK

No. 210068

Date DEC 1 1973

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the [redacted]—altered—[redacted]—building—premises located at
112 Berriman Street, W/S 185' North of Glenmore Avenue, Bklyn.

Block 3989 Lot 24

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

[redacted] Alt. No. 816/60 Construction classification—Class 1 Frame

Occupancy classification— Two (2) Families . Height Cellar & 2 stories, 25' feet.

Date of completion—Constr. 12/14/73 . Located in Residence Use District.
Plbg. 12/14/73

C Area . Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	On grade	-	-	-	Ordinary
Basement	40	-	-	-	One (1) Family
First Second	40 40	-	-	-	One (1) Family
					Total: Two (2) Families

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO

DRAFT

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same streases in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

98-114 Berriman Street Development
98 Berriman Street
Brooklyn, NY 11208

Inquiry Number: 8102930.5
September 10, 2025

DRAFT

The EDR-City Directory Abstract

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

DRAFT

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at approximately five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through current. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

Summary information obtained is provided in the text of this report.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	*Source*	*TP*	*Adjoining*	*Text Abstract*	*Source Image*
2022	EDR Digital Archive	-	X	X	-
2020	EDR Digital Archive	-	-	-	-
2017	Cole Information	-	X	X	-
2014	Cole Information	-	X	X	-
2010	Cole Information	-	X	X	-
2005	Cole Information	-	X	X	-
	Hill-Donnelly Corporation	-	X	X	-
2000	Cole Information	-	X	X	-
1997	NYNEX	-	X	X	-
1995	Cole Information	-	X	X	-
1992	Cole Information	-	X	X	-
	NYNEX Informantion Resource Co.	-	X	X	-
1985	NYNEX Information Resources Company	-	X	X	-
1980	New York Telephone	-	-	-	-
1976	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-

DRAFT

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1973	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1970	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1965	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1960	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1945	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1940	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	X	X	X	-
1928	New York Telephone	-	X	X	-

DRAFT

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
112 Berriman Street	Client Entered	
114 Berriman Street	Client Entered	

DRAFT

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

98 Berriman Street
Brooklyn, NY 11208

FINDINGS DETAIL

Target Property research detail.

DRAFT

BERIMAN

114 BERIMAN

Year	Uses	Source
1949	Rudomin Knitg Mills	New York Telephone Company
	Rudomin Saml sportsw r	New York Telephone Company

BERIMN

98 BERIMN

Year	Uses	Source
1960	Fanon Electrnc Indstries Inc	New York Telephone Company

114 BERIMN

Year	Uses	Source
1960	Wallace John	New York Telephone Company
1945	Star Novelty Co	New York Telephone
1940	Rudomin Saml sportsw r	New York Telephone
	Star Novelty Co	New York Telephone

BERIMN st

98 BERIMN st

Year	Uses	Source
1970	Kellerman Mfg Co Inc	New York Telephone

FINDINGS

BERIMN St

98 BERIMN St

Year	Uses	Source
1965	Kellerman Mfg Co Inc	New York Telephone

BERIMN st

112 BERIMN st

Year	Uses	Source
1973	Cooper G	New York Telephone
	Neives Francisco	New York Telephone
1970	Cooper G	New York Telephone
	Neives Francisco	New York Telephone

BERIMN St

112 BERIMN St

Year	Uses	Source
1965	Ashby Lana J	New York Telephone
	Farkus Zulton P	New York Telephone

114 BERIMN St

Year	Uses	Source
1965	Wise Mann Knitwear Corp	New York Telephone

BERMAN

114 BERMAN

Year	Uses	Source
1976	THE H S KNITTING MILLS INC	New York Telephone
	THE JOHN SCHMIDT KNITG MILLS INC	New York Telephone

BERMAN st

114 BERMAN st

Year	Uses	Source
1973	The H S Knitting Mills Inc	New York Telephone

DRAFT

Year	Uses	Source
1973	The John Schmidt Knitg Mills Inc	New York Telephone
1970	Johanna Knitting Mills	New York Telephone
	K & T Knitting Mills	New York Telephone
	The John Schmidt Knitg Mills Inc	New York Telephone

BERRIAN

114 BERRIAN

Year	Uses	Source
1960	WALLACE JOHN	New York Telephone

BERRIMAN

98 BERRIMAN

Year	Uses	Source
1934	BAUM NATHAN BERRIMAN-GLENMORE GARAGE	R. L. Polk & Co.
	BERRIMAN GLENMORE GARAGE	R. L. Polk & Co.

114 BERRIMAN

Year	Uses	Source
1934	DELCO KNITWEAR FACTORY	R. L. Polk & Co.

BERRIMAN MAIN OFFICE ~

114 BERRIMAN MAIN OFFICE ~

Year	Uses	Source
1934	DEERIN LAWRENCE & O DONNELL INC THOS J O DONNELL MGR FCTY 5TH APT MHN	R. L. Polk & Co.

BERRIMAN ST

98 BERRIMAN ST

Year	Uses	Source
1940	Berriman Glenmore Garage	New York Telephone

DRAFT

FINDINGS

Berriman Street

112 Berriman Street

Year	*Uses*	*Source*

114 Berriman Street

Year	*Uses*	*Source*

BERRIMN

98 BERRIMN

Year	*Uses*	*Source*
1940	Baum Nat garage	New York Telephone

DRAFT

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

111 BERMAN st

345 111 BERMAN st

Year	Uses	Source
1970	NEW YORK EDUCATION BOARD All Day Neighborhood Schools PS	New York Telephone

111 BERRIMAN st

345 111 BERRIMAN st

Year	Uses	Source
1973	PS	New York Telephone
	NEW YOK CITY OF EDUCATION CITY BOARD OF Headquarters Offices	New York Telephone

BERIMN

94 BERIMN

Year	Uses	Source
1960	DAgostino Andrew	New York Telephone Company
1940	Milano A U	New York Telephone

99 BERIMN

Year	Uses	Source
1960	Costantino L	New York Telephone Company

101 BERIMN

Year	Uses	Source
1960	Arlington Svce Centr	New York Telephone Company

BERIMN st

94 BERIMN st

Year	Uses	Source
1970	Genna Morris	New York Telephone

DRAFT

FINDINGS

BERIMN St

94 BERIMN St

Year	Uses	Source
1965	Addeo Carmen Mrs	New York Telephone
	Pennisi Mary Mrs	New York Telephone

BERIMN st

96 BERIMN st

Year	Uses	Source
1970	Bay Auto Sales repr	New York Telephone

BERIMN St

108 BERIMN St

Year	Uses	Source
1965	Patrician Jewel Case Co	New York Telephone

BERMAN

94 BERMAN

Year	Uses	Source
1997	CARRERAS Carlos	NYNEX
1985	ANDERSON JAKE	NYNEX Information Resources Company
1976	HINES JANICE	New York Telephone

96 BERMAN

Year	Uses	Source
1985	DANNOS COLLISION	NYNEX Information Resources Company
1976	BERRIMAN SVCE STA	New York Telephone

100 BERMAN

Year	Uses	Source
1992	ACCURATE METAL	NYNEX Informantion Resource Co.
	ACCURATE METAL SLITTING	NYNEX Informantion Resource Co.
1985	COPEN PRESS PRNTNG	NYNEX Information Resources Company
1976	COPAN PRESS PRNTNG	New York Telephone

DRAFT

111 BERMAN

Year	Uses	Source
1985	TAYLOR MICHAEL	NYNEX Information Resources Company
1976	CANTON ROY B	New York Telephone
	NEW YORK CITY OF SCHOOLS-ELEMENTARY	New York Telephone

BERMAN st

94 BERMAN st

Year	Uses	Source
1973	Jackson William L	New York Telephone
	Rusda Thomas	New York Telephone

96 BERMAN st

Year	Uses	Source
1973	Moonbay Auto Exch	New York Telephone

100 BERMAN st

Year	Uses	Source
1973	Copen Press prntng	New York Telephone

BERRIAN

101 BERRIAN

Year	Uses	Source
1960	ARLINGTON SVCE CENTR	New York Telephone

BERRIMAN

94 BERRIMAN

Year	Uses	Source
1934	BONAVITA ROGER PNTR H	R. L. Polk & Co.

111 BERRIMAN

Year	Uses	Source
1976	NEW YORK CITY OF EDUCATION CITY BOARD OF ALL DAY NEIGHBORHOOD SCHOOLS PS 34	New York Telephone

DRAFT

FINDINGS

BERRIMAN ST

84 BERRIMAN ST

Year	Uses	Source
2000	NINA YAKUBOVSKAYA	Cole Information

94 BERRIMAN ST

Year	Uses	Source
2022	RAMON NIEVES	EDR Digital Archive
	KRYSTAL BATISTA	EDR Digital Archive
	PEDRO GUZMAN	EDR Digital Archive
	ELY QUIROZ	EDR Digital Archive
	FELIX BATISTA	EDR Digital Archive
	MARIA BATISTA	EDR Digital Archive
	JUDITH RICKARDS	EDR Digital Archive
	AMARYLIS CRUZ	EDR Digital Archive
	EILEEN FRAZIER	EDR Digital Archive
	JULISSA CRUZ	EDR Digital Archive
	ANGELA DIAZ	EDR Digital Archive
	ELY JAQUEZ	EDR Digital Archive
2017	FELIX BATISTA	Cole Information
	JUDITH RICKARDS	Cole Information
2014	HECTOR CARRERAS	Cole Information
	ARIEL GARCIA	Cole Information
	FELIX BATISTA	Cole Information
	RICHARD STUBBS	Cole Information
	CARLOS ALMONTE	Cole Information
2010	BRIAN TAYLOR	Cole Information
	JEFFREY CRUZ	Cole Information
	MARIA BATISTA	Cole Information
	BLANCHE JACOBS	Cole Information
2005	Jaquez Felix	Hill-Donnelly Corporation
	I GIORDANO	Cole Information
	NESSATIA ANDERSON	Cole Information

DRAFT

FINDINGS

Year	Uses	Source
2005	HECTOR CARRERAS	Cole Information
	JUAN CRUZ	Cole Information
	FELIX BATISTA	Cole Information
	FELIX JAQUEZ	Cole Information
	WANDA RIOS	Cole Information
2000	MARISOL PABON	Cole Information
	MARISOL PABON	Cole Information
	KEVION LEWIS	Cole Information
1997	MORALES Sonia Y	NYNEX

96 BERRIMAN ST

Year	Uses	Source
2022	T & M AUTO COLLISION	EDR Digital Archive
	HERNANDEZ CEPEDA	EDR Digital Archive
2017	T & M AUTO REPAIR	Cole Information
2014	T & M AUTO REPAIR	Cole Information
2010	T & M AUTO REPAIR	Cole Information
2005	T&M Auto Repair	Hill-Donnelly Corporation
	T & M COLLISION INC	Cole Information
	OCCUPANT UNKNOWN	Cole Information
2000	T & M AUTO REPAIR	Cole Information
	T & M AUTO REPAIR	Cole Information
1995	T & M AUTO REPAIR	Cole Information
1992	T & M AUTO REPAIR	Cole Information

100 BERRIMAN ST

Year	Uses	Source
2017	ACCURATE METAL SLITTING	Cole Information
	ACCURATE METAL	Cole Information
	ACCURATE METAL SLITTING CO	Cole Information
2014	ACCURATE METAL SLITTING	Cole Information
	ACCURATE METAL SLITTING COMPANY	Cole Information
	ACCURATE METAL	Cole Information
2010	ACCURATE METAL	Cole Information

DRAFT

FINDINGS

Year	Uses	Source
2005	Accurate Metal Slitting	Hill-Donnelly Corporation
	OCCUPANT UNKNOWN	Cole Information
	ACCURATE METAL SLITTING CORP	Cole Information
	ACCURATE METAL	Cole Information
2000	ACCURATE METAL	Cole Information
	ACCRT METL SLTTNG	Cole Information
	ACCRT METL SLTING	Cole Information
	ACCURATE METAL SLITTING	Cole Information
	ACCURATE METAL SLITTING COMPANY	Cole Information
	ACCURATE METAL	Cole Information
1995	ACCURATE METAL SLITTING	Cole Information
	ACCURATE METAL	Cole Information
1992	ACCURATE METAL SLITTING	Cole Information
	ACCURATE METAL	Cole Information

111 BERRIMAN ST

Year	Uses	Source
2022	CHANTE GILLIAM	EDR Digital Archive
	DIANNA LOCOZO	EDR Digital Archive
	NELIBTH PLAZA	EDR Digital Archive
	BENITA MAKOWER	EDR Digital Archive
	DEBORAH KENEL	EDR Digital Archive
	BROOKLYN COLLEGEACADEMY	EDR Digital Archive
	PS 345 PATROLMAN ROBERT BOLDEN ELEM SCHL	EDR Digital Archive
	BROOKLYN BUREAU OF COMMUNITY SERVICE	EDR Digital Archive
	NYC & COMPANY	EDR Digital Archive
	PS 345 PATROLMAN ROBERT BOLDEN	EDR Digital Archive
2017	NEW YORK CITY BOARD OF EDUCATION	Cole Information
	CITY OF NEW YORK	Cole Information
2014	NEW YORK CITY BOARD OF EDUCATION	Cole Information
	CITY OF NEW YORK	Cole Information
2010	PUBLIC SCHOOL 345	Cole Information

DRAFT

FINDINGS

Year	Uses	Source
2005	Brooklyn Bureau Of Community	Hill-Donnelly Corporation
	PS 345 Pos WDS Three Fortyfive	Hill-Donnelly Corporation
	Public School	Hill-Donnelly Corporation
	PUBLIC SCHOOL 345	Cole Information
	PS 345	Cole Information
2000	NY CITY EDUCATION	Cole Information
	BRKLYN BUR COMM	Cole Information
	MCLAUGHLIN ANDREW	Cole Information
	ROMAN PABLO	Cole Information
	MCLAUGHLIN ANDREW	Cole Information
	BROOKLYN BUREAU OF COMMUNITY SERVICE	Cole Information
1997	Vito Bartolomeo	NYNEX
1995	NYC EDUCATION COMMUNITY SCHOOL BOARDS SCHOOLS-ELEMENTARY PS 3455	Cole Information
	VITO BARTOLOMEO	Cole Information
1992	NYC EDUCATION-COMMUNITY SCHOOL BOARDS-SCHOOLS-ELEMENTARY-PS 345	Cole Information

BORINM st

91 BORINM st

Year	Uses	Source
1970	Kennedy Merlva D	New York Telephone

BORUMN st

91 BORUMN st

Year	Uses	Source
1970	Filosf Lew is	New York Telephone
	Rosario Angel	New York Telephone

LIBERTY AVE

775 LIBERTY AVE

Year	Uses	Source
2022	RODCO PROPERTY MANAGEMENT	EDR Digital Archive

DRAFT

FINDINGS

Year	Uses	Source
2022	SADE HOOKS	EDR Digital Archive
	PALMA MORALES	EDR Digital Archive
2017	MANAGEMENT RODCO PROPERTIES	Cole Information
	RODCO PROPERTY MANAGEMENT	Cole Information
	SANTIAGO GOMEZ	Cole Information
2014	MANAGEMENT RODCO PROPERTIES	Cole Information
	RODCO PROPERTY MANAGEMENT	Cole Information
	SANTIAGO FLORES	Cole Information
	OSCAR RIVAS	Cole Information
	JHONY GARCIA	Cole Information
2010	RODCO PROPERTY MANAGEMENT	Cole Information
	EUGENE GEORGE	Cole Information
1970	Oddo Salvatore	New York Telephone
1965	Correale Tony	New York Telephone
	Sacco Gasper	New York Telephone
1960	BALSAMO JOS	New York Telephone
	SACCO GASPER	New York Telephone
	Balsamo Jos	New York Telephone Company
	Sacco Gasper	New York Telephone Company
1949	Nizza Alfred R	New York Telephone Company
1934	BOCCIO FRANK LAB R	R. L. Polk & Co.
	BOCCIO LOUISE CLO OPR R	R. L. Polk & Co.
	ROMANO ANTHONY LONGHOREMN H	R. L. Polk & Co.
	ROMANO JOS COMENT LAB R	R. L. Polk & Co.
	LAB H	R. L. Polk & Co.
1928	GIORDANO ORAZIO CONTR	New York Telephone

777 LIBERTY AVE

Year	Uses	Source
2022	BARBARA FERNANDEZ	EDR Digital Archive
	INGRID GONZALEZ	EDR Digital Archive
	JEFFREY EVANS	EDR Digital Archive
	MAGGIE HARDGE	EDR Digital Archive

DRAFT

FINDINGS

Year	Uses	Source
2022	BARBARA SAMUELS	EDR Digital Archive
	LYSANDRA GERMOSEN	EDR Digital Archive
	STEPHANIE GERMOSEN	EDR Digital Archive
	FELIX FERNANDEZ	EDR Digital Archive
	ELIJAH HARDGE	EDR Digital Archive
	GRACIANO FERNANDEZ	EDR Digital Archive
	JAMES HARDGE	EDR Digital Archive
2017	BARBARA SAMUELS	Cole Information
	ELIJAH HARDGE	Cole Information
	GRACIANO FERNANDEZ	Cole Information
2014	ELIJAH HARDGE	Cole Information
	GRACIANO FERNANDEZ	Cole Information
2010	DARIO PEREZ	Cole Information
	IRIS ESCALANTE	Cole Information
	ELIJAH HARDGE	Cole Information
	IRIS RIVERA	Cole Information
	GRACIANO FERNANDEZ	Cole Information
	INGRID GONZALES	Cole Information
	PAUL SMELLIE	Cole Information
2005	Fernandez Barbara	Hill-Donnelly Corporation
	h Rivera Iris	Hill-Donnelly Corporation
	BARBARA FERNANDEZ	Cole Information
	IRIS ESCALANTE	Cole Information
	ELIJAH HARDGE	Cole Information
	IRIS RIVERA	Cole Information
	L GALIL	Cole Information
	PAUL SMELLIE	Cole Information
2000	R DIOMN	Cole Information
	MARIA FORDE	Cole Information
1997	BECKER Donna	NYNEX
	RIVERA R	NYNEX
1992	GONZALEZ R	NYNEX Informantion Resource Co.

DRAFT

FINDINGS

Year	Uses	Source
1985	ELLIS P	NYNEX Information Resources Company
	GRAY MARLINE	NYNEX Information Resources Company
	JONES RICHARD	NYNEX Information Resources Company
1976	ELLIS L	New York Telephone
	JONES HENRY	New York Telephone
1973	Annunziata Patsy	New York Telephone
	Ellis L	New York Telephone
1970	Annunziata Patsy	New York Telephone
1960	ANNUNZIATA JOHN	New York Telephone
	ANNUNZIATA TILLIE MRS	New York Telephone
	PAGANO LUIGI	New York Telephone
	Annunziata John	New York Telephone Company
	Annunziata Tillie Mrs	New York Telephone Company
	Pagano Luigi	New York Telephone Company
1949	Barone Dominick	New York Telephone Company
1934	ARINI JOHN LAB H	R. L. Polk & Co.
	DASTA VINCENT LAB H	R. L. Polk & Co.
	DIPRISCO GUISEPPE LAB H	R. L. Polk & Co.
	FIDUCIA NICOLINA R	R. L. Polk & Co.
1928	ANNONCIA & BOCCIO CONTRS	New York Telephone

778 LIBERTY AVE

Year	Uses	Source
1976	MENDOLA JOS	New York Telephone
	WARE E	New York Telephone
	WORKMAN G	New York Telephone
1973	Biondollilo Vincent	New York Telephone
	Ware E	New York Telephone
1970	Sparacello Joseph	New York Telephone
1965	Ancona Jas	New York Telephone
	Mendola Jos	New York Telephone
1960	ANCONA JAS	New York Telephone
	MENDOLA JOS	New York Telephone

DRAFT

FINDINGS

Year	Uses	Source
1960	MINEO VICTOR	New York Telephone
	Ancona Jas	New York Telephone Company
	Mendola Jos	New York Telephone Company
	Mineo Victor	New York Telephone Company
1949	Benigno Antonio plmbng	New York Telephone Company
1934	CARBONE JOS PLSTR H	R. L. Polk & Co.
	CATAPANO CAROLINE H	R. L. Polk & Co.
	CATAPANO JOHN CHAUF R	R. L. Polk & Co.
	CILLUFFO SALVATORE LAB H	R. L. Polk & Co.

779 LIBERTY AVE

Year	Uses	Source
2022	FRANCIS KUMI	EDR Digital Archive
	LETTIE STARKS	EDR Digital Archive
	RAUL JEBOO	EDR Digital Archive
	KEITH SPRUILL	EDR Digital Archive
	TIFFANY CASSIDY	EDR Digital Archive
	ANDREA FINCH	EDR Digital Archive
	RONALD JEBOO	EDR Digital Archive
2017	SHERRY STARKS	Cole Information
	ROLAND JEBOO	Cole Information
	FRANCIS KUMI	Cole Information
	TIFFANY CASSIDY	Cole Information
2014	SHERRY STARKS	Cole Information
	ROLAND JEBOO	Cole Information
	FRANCIS KUMI	Cole Information
	AWILDA ROMAN	Cole Information
2010	SHERRY STARKS	Cole Information
	AWILDA ROMAN	Cole Information
	WILMARIE ROMERO	Cole Information
	JANICE MARHAEN	Cole Information
	RONALD JEBOO	Cole Information
2005	Jeboo Ronald	Hill-Donnelly Corporation

DRAFT

FINDINGS

Year	Uses	Source
2005	h Marhaen Janice	Hill-Donnelly Corporation
	h Romero Wilmarle	Hill-Donnelly Corporation
	WILMARIE ROMERO	Cole Information
	JANICE MARHAEN	Cole Information
	RONALD JEBOO	Cole Information
1992	MERTON ROBBIN	NYNEX Informantion Resource Co.
	MILFORT MERIE LOURDES	NYNEX Informantion Resource Co.
	TAYLOR, VERA	Cole Information
	MILFORT, MERIE LOURDES	Cole Information
1985	NARRANJO BLANCA	NYNEX Information Resources Company
	PASCAL GEORGE	NYNEX Information Resources Company
1976	ANTOINE ALEXANDER	New York Telephone
	BEHRMANN LUCE	New York Telephone
	FLEURANCOIS RAYMOND	New York Telephone
	JEAN E	New York Telephone
1973	Borno Augustin J	New York Telephone
	Edoward Marha	New York Telephone
	Philippe Claire Pierre	New York Telephone
	Prudhomme Marie	New York Telephone
1970	Hellback Frederick	New York Telephone
1965	Atwood Virginia S	New York Telephone
	Cannata Mary Mrs	New York Telephone
	Figuccio Albert L	New York Telephone
	Guarino Barbr Razor Co	New York Telephone
	Hellback Carol A	New York Telephone
1960	BARTSCH ROBT ARTHUR	New York Telephone
	FRANA ANTHONY J	New York Telephone
	GUARINO BARBR RAZOR CO	New York Telephone
	LEIS PETER	New York Telephone
	Bartsch Robt Arthur	New York Telephone Company
	Frana Anthony J	New York Telephone Company
	Guarino Barbr Razor Co	New York Telephone Company

DRAFT

FINDINGS

Year	Uses	Source
1960	Leis Peter	New York Telephone Company
1949	Sakolsky Alexander	New York Telephone Company
1934	ANNUNZIATO DONATO BARBER H	R. L. Polk & Co.
	CARBONE JOS PLSTR H	R. L. Polk & Co.
	DIMAIO JAS LAB H	R. L. Polk & Co.
	PERULLA VINCENZA R	R. L. Polk & Co.
	PETAGLLO JOHN COALMN H	R. L. Polk & Co.

780 LIBERTY AVE

Year	Uses	Source
1934	MINICHINO ANGELO BAKER H DO	R. L. Polk & Co.

785 LIBERTY AVE

Year	Uses	Source
2022	BROTHER AUTO REPAIR	EDR Digital Archive
2017	BROTHER AUTO REPAIR	Cole Information
2014	BROTHER AUTOMOBILE REPAIR	Cole Information
2010	BROTHER AUTO REPAIR	Cole Information
2005	Brother Auto Repair	Hill-Donnelly Corporation
	OCCUPANT UNKNOWN	Cole Information
	BROTHER AUTO REPAIR # 1	Cole Information
	HITEL VALDEZ	Cole Information
2000	BROTHER ANTO RPR	Cole Information
	BROTHER AUTO REPAIR #1	Cole Information
1997	Sunset Auto Repair Center	NYNEX
1995	SUNSET AUTO REPAIR CENTER	Cole Information
1992	JOHNSON S AUTO REPR PAINTING & COLOR MATCHING SPECIALIST	NYNEX Informantion Resource Co.
	JOHNSON'S AUTO REPR	Cole Information
1985	JOHNSONS AUTO REPR	NYNEX Information Resources Company
1976	JOHNSON S AUTO REPR	New York Telephone
1973	Johnsons Auto Repr	New York Telephone
1970	East Coast Collision Inc	New York Telephone
1965	F & C Auto Body	New York Telephone

DRAFT

FINDINGS

Year	Uses	Source
1949	Jahns R E Auto Svce	New York Telephone Company
1934	JAHN RUDOLF E AUTO REPR	R. L. Polk & Co.
	NASTASI SALVATORE BAKER H	R. L. Polk & Co.

787 LIBERTY AVE

Year	Uses	Source
2022	HEAVENLY LIGHT WORLD OUTREACH FELLOWSHIP	EDR Digital Archive
2017	CUANC QINC	Cole Information
2014	CUANC QINC	Cole Information
	CARLOS ALVAREZ	Cole Information
	QING QUANG	Cole Information
2010	QUANG QING ZHENG	Cole Information
	NICOLA BASTELLI	Cole Information
2005	Quang Qing Zheng	Hill-Donnelly Corporation
1997	TORRES Jose	NYNEX
1992	LIBERTY MEDICAL GROUP	NYNEX Informantion Resource Co.
	PAREKH B DDS	NYNEX Informantion Resource Co.
	LIBERTY AVE PHARMACY INC	NYNEX Informantion Resource Co.
	LIBERTY MEDICAL GROUP	Cole Information
	PAREKH, B, DDS	Cole Information
	787 LIBERTY AVE PHARMACY INC	Cole Information
1985	GUZMAN TEOFILO GROCER	NYNEX Information Resources Company
	PEREZ CANDY STORE	NYNEX Information Resources Company
1976	ABBRACCIAMENTO ALDA M	New York Telephone
	ABBRACCIAMENTO SALVATORE MRS	New York Telephone
	ABBRACCIAMENTO S SAL RESTRNT	New York Telephone
1973	Abbracciamento Alda M	New York Telephone
	Abbracciamento Salvatore Mrs	New York Telephone
	Sal Abbracciamnentos Restrnt	New York Telephone
1965	Sal Abbracciamentos Restrnt	New York Telephone
1960	ABBRACCIAMENTO SALVATORE MRS	New York Telephone
	SAL ABBRACCIAMENTO S RESTRNT	New York Telephone
	Abbracciamento Salvatore Mrs	New York Telephone Company

DRAFT

FINDINGS

Year	Uses	Source
1960	Sal Abbracciamentos Restrnt	New York Telephone Company
1949	Sals Grill	New York Telephone Company
1934	BOCCIO EMIL BRKLVR R	R. L. Polk & Co.
	FERRARO ANTONIO H	R. L. Polk & Co.
	GANCI CARMELIO BARBER R	R. L. Polk & Co.
1928	DORAZIO CHAS BOILER RPRG	New York Telephone
	GREENZANG A & L DRESSES	New York Telephone

788 LIBERTY AVE

Year	Uses	Source
1934	& BATTERY SERVICE CO	R. L. Polk & Co.
1928	LIBERTY IGNITION & BATTERY SER CO	New York Telephone

792 LIBERTY AVE

Year	Uses	Source
1965	S & A Lunchnet	New York Telephone
1960	S & A LUNCHNET	New York Telephone
	S & A Lunchnet	New York Telephone Company
1949	Harvey Luncheonette	New York Telephone Company
1934	CREVELLING JOHN C & SON INC JOHN C CREVELING PRES EMERSON D R CREVELING SE	R. L. Polk & Co.
1928	CREVELING JOHN C & SON INC COST	New York Telephone

799 LIBERTY AVE

Year	Uses	Source
2022	CARLOS SANTIAGO	EDR Digital Archive
2017	JOSEFINA MENDEZ	Cole Information
	SEGUNDO COTTO	Cole Information
2014	JOSEFINA MENDEZ	Cole Information
2010	JOSEFINA MENDEZ	Cole Information
2005	N CL	Hill-Donnelly Corporation
	CARLOS SANTIAGO	Cole Information
1976	DIAZ JOHN	New York Telephone
	TUDDA OSCAR	New York Telephone

DRAFT

FINDINGS

Year	Uses	Source
1973	Giordano Nicholas	New York Telephone
1970	Tudda Oscar	New York Telephone
1965	Ferrari John G	New York Telephone
	Giordano Nicholas	New York Telephone
1960	FERRARI JOHN G	New York Telephone
	GIORDANO NICHOLAS	New York Telephone
	Ferrari John G	New York Telephone Company
	Giordano Nicholas	New York Telephone Company
1949	Corb Milton	New York Telephone Company
	Rabin Claire	New York Telephone Company

800 LIBERTY AVE

Year	Uses	Source
1945	Lyon Lumbr Co bldrs matl	New York Telephone

801 LIBERTY AVE

Year	Uses	Source
2022	BRUNILDA VIVES	EDR Digital Archive
	LIZETTE VIVES	EDR Digital Archive
	DIANA VIVES	EDR Digital Archive
2017	BRUNILDA RAMOS-RAMOS	Cole Information
	ELIZABETH VIVES	Cole Information
2014	BRUNILDA VIVES	Cole Information
	BRUNILDA RAMOS-RAMOS	Cole Information
2005	h Nevares Judith	Hill-Donnelly Corporation
	JUDITH NEVARES	Cole Information
2000	JUDITH NEVARES	Cole Information
	JUDITH NEVARES	Cole Information
1997	NEVARES Judith	NYNEX
1992	NEVARES JUDITH	NYNEX Informantion Resource Co.
	NEVARES, JUDITH	Cole Information
1976	COLON LILLIAN MRS	New York Telephone
1970	Colon Annie	New York Telephone
1960	CIARAMELLA JAS V	New York Telephone

DRAFT

FINDINGS

Year	Uses	Source
1960	SALERNO NAT	New York Telephone
	Ciaramella Jas V	New York Telephone Company
	Salerno Nat	New York Telephone Company

LIBERY AVE

775 LIBERY AVE

Year	Uses	Source
1934	BOCCIO RALPH LAB H	R. L. Polk & Co.

LIBRTY AVE

779 LIBRTY AVE

Year	Uses	Source
1934	NOCERINO JERRY LAB H	R. L. Polk & Co.

DRAFT

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
100 BERMAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
100 BERMAN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
100 BERRIMAN ST	2022, 2020, 1997, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
101 BERIMN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
101 BERRIAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
108 BERIMN St	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
111 BERMAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
111 BERRIMAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
111 BERRIMAN ST	2020, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
345 111 BERMAN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
345 111 BERRIMAN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
775 LIBERTY AVE	2020, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1945, 1940
775 LIBERY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
777 LIBERTY AVE	2020, 1995, 1980, 1965, 1945, 1940
778 LIBERTY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1945, 1940, 1928
779 LIBERTY AVE	2020, 2000, 1997, 1995, 1980, 1945, 1940, 1928
779 LIBRTY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
780 LIBERTY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
785 LIBERTY AVE	2020, 1980, 1960, 1945, 1940, 1928
787 LIBERTY AVE	2020, 2000, 1995, 1980, 1970, 1945, 1940
788 LIBERTY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940

DRAFT

FINDINGS

Address Researched	Address Not Identified in Research Source
792 LIBERTY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1945, 1940
799 LIBERTY AVE	2020, 2000, 1997, 1995, 1992, 1985, 1980, 1945, 1940, 1934, 1928
800 LIBERTY AVE	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
801 LIBERTY AVE	2020, 2010, 1995, 1985, 1980, 1973, 1965, 1949, 1945, 1940, 1934, 1928
84 BERRIMAN ST	2022, 2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
91 BORINM st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
91 BORUMN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
94 BERIMN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1934, 1928
94 BERIMN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
94 BERIMN St	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
94 BERMAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
94 BERMAN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
94 BERRIMAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
94 BERRIMAN ST	2020, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
96 BERIMN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
96 BERMAN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
96 BERMAN st	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
96 BERRIMAN ST	2020, 1997, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
99 BERIMN	2022, 2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928

DRAFT

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
98 Berriman Street	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1928

DRAFT

98-114 Berriman Street Development

98 Berriman Street

Brooklyn, NY 11208

Inquiry Number: 8102930.3

September 09, 2025

DRAFT

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

09/09/25

Site Name:

98-114 Berriman Street Develo
98 Berriman Street
Brooklyn, NY 11208
EDR Inquiry # 8102930.3

Client Name:

Haley & Aldrich, Inc.
299 Cherry Hill Road
Parsippany, NJ 07054
Contact: Kaitlyn Moses

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Haley & Aldrich, Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 993F-4DC1-8045

PO # 0214078-000

Project 98-114 Berriman Street Develop

Maps Provided:

2007	1994	1979
2006	1993	1977
2005	1991	1968
2004	1989	1965
2003	1988	1951
2002	1987	1928
2001	1982	1908
1995	1980	1887

Sanborn® Library search results

Certification #: 993F-4DC1-8045

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Haley & Aldrich, Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets

Volume 8, Sheet 14
2007

Volume 8, Sheet 16
2007

Volume 8, Sheet 31
2007

Volume 8, Sheet 37
2007

2006 Source Sheets

Volume 8, Sheet 31
2006

Volume 8, Sheet 16
2006

Volume 8, Sheet 14
2006

2005 Source Sheets

Volume 8, Sheet 14
2005

Volume 8, Sheet 31
2005

Volume 8, Sheet 16
2005

Volume 8, Sheet 37
2005

2004 Source Sheets

Volume 8, Sheet 37
2004

Volume 8, Sheet 31
2004

Volume 8, Sheet 14
2004

Volume 8, Sheet 16
2004

DRAFT

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets

Volume 8, Sheet 14
2003

Volume 8, Sheet 16
2003

Volume 8, Sheet 31
2003

2002 Source Sheets


Volume 8, Sheet 31
2002

Volume 8, Sheet 14
2002

Volume 8, Sheet 16
2002

Volume 8, Sheet 37
2002

2001 Source Sheets

Volume 8, Sheet 37
2001

Volume 8, Sheet 16
2001

Volume 8, Sheet 14
2001

Volume 8, Sheet 31
2001

1995 Source Sheets


Volume 8, Sheet 31
1995

Volume 8, Sheet 37
1995

Volume 8, Sheet 14
1995

Volume 8, Sheet 16
1995

DRAFT

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets

Volume 8, Sheet 16
1994

Volume 8, Sheet 14
1994


Volume 8, Sheet 31
1994

Volume 8, Sheet 37
1994

1993 Source Sheets

Volume 8, Sheet 37
1993

Volume 8, Sheet 31
1993

Volume 8, Sheet 16
1993

Volume 8, Sheet 14
1993

1991 Source Sheets

Volume 8, Sheet 37
1991

Volume 8, Sheet 31
1991

Volume 8, Sheet 16
1991

Volume 8, Sheet 14
1991

1989 Source Sheets

Volume 8, Sheet 14
1989


Volume 8, Sheet 16
1989


Volume 8, Sheet 31
1989


Volume 8, Sheet 37
1989

DRAFT

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1988 Source Sheets


Volume 8, Sheet 37
1988

Volume 8, Sheet 16
1988


Volume 8, Sheet 31
1988


Volume 8, Sheet 14
1988

1987 Source Sheets


Volume 8, Sheet 14
1987


Volume 8, Sheet 16
1987


Volume 8, Sheet 31
1987

Volume 8, Sheet 37
1987

1982 Source Sheets

Volume 8, Sheet 31
1982

Volume 8, Sheet 16
1982


Volume 8, Sheet 14
1982

1980 Source Sheets

Volume 8, Sheet 14
1980


Volume 8, Sheet 31
1980

Volume 8, Sheet 16
1980

Volume 8, Sheet 37
1980

DRAFT

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1979 Source Sheets


Volume 8, Sheet 37
1979


Volume 8, Sheet 31
1979


Volume 8, Sheet 14
1979


Volume 8, Sheet 16
1979

1977 Source Sheets


Volume 8, Sheet 16
1977

Volume 8, Sheet 14
1977

Volume 8, Sheet 31
1977

Volume 8, Sheet 37
1977

1968 Source Sheets

Volume 8, Sheet 37
1968


Volume 8, Sheet 31
1968


Volume 8, Sheet 14
1968

Volume 8, Sheet 16
1968

1965 Source Sheets


Volume 8, Sheet 16
1965


Volume 8, Sheet 14
1965


Volume 8, Sheet 31
1965


Volume 8, Sheet 37
1965

DRAFT

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1951 Source Sheets

Volume 8, Sheet 37
1951

Volume 8, Sheet 31
1951

Volume 8, Sheet 14
1951

Volume 8, Sheet 16
1951

1928 Source Sheets

Volume 8, Sheet 16
1928

Volume 8, Sheet 14
1928

Volume 8, Sheet 31
1928


Volume 8, Sheet 37
1928

1908 Source Sheets


Volume 8, Sheet 47
1908

Volume 8, Sheet 31
1908


Volume 8, Sheet 30
1908

Volume 8, Sheet 46
1908

1887 Source Sheets

Volume 8, Sheet 216
1887

Volume 8, Sheet 211
1887

Volume 8, Sheet 216
1887

Volume 8, Sheet 211
1887

DRAFT



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 16
Volume 8, Sheet 14

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 14
Volume 8, Sheet 16
Volume 8, Sheet 31

0 Feet 150 300 600

N

Certified Sanborn® Map

2005



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

DRAFT

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 16
Volume 8, Sheet 31
Volume 8, Sheet 14

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 16
Volume 8, Sheet 14
Volume 8, Sheet 31
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 31
Volume 8, Sheet 16
Volume 8, Sheet 14

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 16
Volume 8, Sheet 14
Volume 8, Sheet 31

0 Feet 150 300 600

N



DRAFT

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 31
Volume 8, Sheet 14
Volume 8, Sheet 16
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 16
Volume 8, Sheet 14
Volume 8, Sheet 37
Volume 8, Sheet 31

0 Feet 150 300 600

N

Certified Sanborn® Map

1994



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1994

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 14
Volume 8, Sheet 16

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 14
Volume 8, Sheet 16
Volume 8, Sheet 31
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 14
Volume 8, Sheet 16
Volume 8, Sheet 31
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 16
Volume 8, Sheet 14

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1988

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 14
Volume 8, Sheet 31
Volume 8, Sheet 16
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 16
Volume 8, Sheet 14

0 Feet 150 300 600

N



Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 211
Volume 8, Sheet 216
Volume 8, Sheet 211
Volume 8, Sheet 216

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn® Map

1982



DRAFT

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 8, Sheet 14
Volume 8, Sheet 16
Volume 8, Sheet 31

N

Certified Sanborn® Map

1980



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1980

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 16
Volume 8, Sheet 31
Volume 8, Sheet 14

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 993F-4DC1-8045

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 16
Volume 8, Sheet 14
Volume 8, Sheet 31
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 14
Volume 8, Sheet 16

0 Feet 150 300 600

N

Certified Sanborn® Map

1968



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	1968

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 16
Volume 8, Sheet 14
Volume 8, Sheet 31
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 14
Volume 8, Sheet 16

0 Feet 150 300 600

N



DRAFT

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #993F-4DC1-8045

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 16
Volume 8, Sheet 14
Volume 8, Sheet 31
Volume 8, Sheet 37

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #:	993F-4DC1-8045
Copyright	1928

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 37
Volume 8, Sheet 31
Volume 8, Sheet 14
Volume 8, Sheet 16

0 Feet 150 300 600

N

Certified Sanborn® Map

1908



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	98-114 Berriman Street Development
Address:	98 Berriman Street
City, ST, ZIP:	Brooklyn, NY 11208
Client:	Haley & Aldrich, Inc.
EDR Inquiry:	8102930.3
Order Date:	09/09/2025
Certification #	993F-4DC1-8045
Copyright	1908

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 8, Sheet 46
Volume 8, Sheet 30
Volume 8, Sheet 31
Volume 8, Sheet 47

0 Feet 150 300 600

N

98-114 Berriman Street Development

98 Berriman Street

Brooklyn, NY 11208

Inquiry Number: 8102930.4

September 09, 2025

DRAFT

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

09/09/25

Site Name:	Client Name:
98-114 Berriman Street Develo	Haley & Aldrich, Inc.
98 Berriman Street	299 Cherry Hill Road
Brooklyn, NY 11208	Parsippany, NJ 07054
EDR Inquiry # 8102930.4	Contact: Kaitlyn Moses

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Haley & Aldrich, Inc. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:		*Coordinates:*	
P.O.#	0214078-000	**Latitude:**	40.67609 40° 40' 34" North
Project:	98-114 Berriman Street Develo	**Longitude:**	-73.880628 -73° 52' 50" West
		UTM Zone:	Zone 18 North
		UTM X Meters:	594601.17
		UTM Y Meters:	4503403.34
		Elevation:	32.00' above sea level

Maps Provided:

2019	1900
2016	1898
2013	1897
1994, 1995	
1979	
1966, 1967	
1956, 1957	
1947	

DRAFT

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets

Brooklyn
2019
7.5-minute, 24000

Jamaica
2019
7.5-minute, 24000

2016 Source Sheets

Brooklyn
2016
7.5-minute, 24000

Jamaica
2016
7.5-minute, 24000

2013 Source Sheets

Brooklyn
2013
7.5-minute, 24000

Jamaica
2013
7.5-minute, 24000

1994, 1995 Source Sheets

Jamaica
1994
7.5-minute, 24000

Brooklyn
1995
7.5-minute, 24000
Aerial Photo Revised 1977

DRAFT

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979 Source Sheets



Jamaica
1979
7.5-minute, 24000
Aerial Photo Revised 1977

Brooklyn
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1966, 1967 Source Sheets

Jamaica
1966
7.5-minute, 24000
Aerial Photo Revised 1953

Brooklyn
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1956, 1957 Source Sheets

Brooklyn
1956
7.5-minute, 24000

Jamaica
1957
7.5-minute, 24000
Aerial Photo Revised 1957

1947 Source Sheets

Brooklyn
1947
7.5-minute, 24000
Aerial Photo Revised 1940

Jamaica
1947
7.5-minute, 24000
Aerial Photo Revised 1941

DRAFT

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets

Brooklyn
1900
15-minute, 62500

1898 Source Sheets

Brooklyn
1898
15-minute, 62500

1897 Source Sheets

Brooklyn
1897
15-minute, 62500

DRAFT

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2019, 7.5-minute
E, Jamaica, 2019, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2016, 7.5-minute
E, Jamaica, 2016, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2013, 7.5-minute
E, Jamaica, 2013, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N


Ridgewood
Broadway Junction
East New York
Woodhaven
Ridgewood Reservoir
HIGHLAND PARK
Cypress Hills Cemetery
Mt Mehoh Cemetery
Machpelah Cemetery
Union Field Cemetery
Trinity Cemetery
Salem Field Cemetery
Franklin Lane
Bayside Cem
Acacia Cem
Linton Park
Livonia Yards
Linden Gen Hospital
Jefferson Field
Vocational High Sch
Jefferson High Sch
Maxwell Voc High Sch
Maxwell Voc High Sch Annex
Lutheran Hosp
Hospital
Recreation Center
Pumping Sta
Police Sta
Fire Sta
Library Sta
Transit
Playground
Park
Cr
Ralph Avenue Parkway
Betts Ct
Hendrix Creek
Golf Course
Interchange 8
Radio Tower
Fire Sta
Queens Co
Kings Co
Queens Blvd
Interborough Parkway
Cypress Hills Cemetery
Mount Carmel Cemetery
Mount Judah Cemetery
Knollwood Park Cemetery
Evergreen Park
Irving Square
Holy Martyrs Sch
St Martins Sch
East Voc High Sch
Our Lady of Lourdes Sch
St Malachys Sch
St Michaels High Sch
St Ritas Sch
St Sylvester Sch
St Thomas the Apostle Sch
St Elizabeths Sch
St Fortunata Sch
St John Cantius Sch
PS 68
PS 77
PS 76
PS 63
PS 65
PS 87
PS 108
PS 151
PS 64
PS 159
PS 214
PS 150
PS 328
PS 182
PS 174
PS 202
PS 224
PS 213
PS 273
PS 306
PS 260
JHS 292
JHS 149
JHS 64
JHS 166
Broadway
Atlantic
Fulton
Liberty
Pitkin
Glenmore
Rockaway
Linden
Blake
Dumont
Wortman
Stanley
Pennsylvania
Livonia
Rapid
Transit
Chestnut
Highland
Jamaica
Ridgewood
Woodhaven
East New York
Cypress Hills
Union Field
Mount Carmel
Mount Judah
Knollwood
Evergreens
Interborough
Parkway
Boulevard
Avenue
Place
Lane
Court
Terrace
Crescent
Hendrix
Atkins
Linwood
Alabama
Powell
Stone
Miller
Arlington
Elderts
Lincoln
Liberty
Glenmore
Pitkin
Conduit
Fountain
Van Sinderen
Euclid
Crescent
Chestnut
Ridgewood
Jamaica
Highland
Transit
Fulton
Arlington
Miller
Hendrix
Atkins
Linwood
Alabama
Powell
Stone
Belmont
Dumont
Blake
Livonia
Rapid
Riverdale
Rockaway
Linden
Wortman
Stanley
Pennsylvania
Van Sinderen
Euclid
Elderts
Lincoln
Liberty
Glenmore
Pitkin
Conduit
Fountain



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1979, 7.5-minute
E, Jamaica, 1979, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Brooklyn, 1967, 7.5-minute
E, Jamaica, 1966, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Brooklyn, 1956, 7.5-minute
E, Jamaica, 1957, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1947, 7.5-minute
E, Jamaica, 1947, 7.5-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1900, 15-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1898, 15-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1897, 15-minute

SITE NAME: 98-114 Berriman Street Development
ADDRESS: 98 Berriman Street
Brooklyn, NY 11208
CLIENT: Haley & Aldrich, Inc.

N

APPENDIX C
Regulatory Records Documentation

DRAFT

98-114 Berriman Street Development
98 Berriman Street
Brooklyn, NY 11208

Inquiry Number: 08102930.2r
September 09, 2025

DRAFT

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	1131
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

98 BERRIMAN STREET
BROOKLYN, NY 11208

COORDINATES

Latitude (North):	40.6760900 - 40˚ 40' 33.92''
Longitude (West):	73.8806280 - 73˚ 52' 50.26''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	594603.7
UTM Y (Meters):	4503192.0
Elevation:	32 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019
East Map:	14105978 JAMAICA, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20220915, 20220719
Source:	USDA

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1		98 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE		TP
A2		114 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Higher	1 ft.
A3	LOT 24,TAXBLOCK 3989	112 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Higher	1 ft.
A4	LOT 14,TAXBLOCK 3989	778 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	35, 0.007, NNW
A5	CON EDISON	778 LIBERTY AVE	E MANIFEST	Higher	35, 0.007, NNW
A6	P.S. 345 - BROOKLYN	111 BERRIMAN STREET	NY AST	Higher	61, 0.012, ENE
A7	NYC DEPT OF EDUCATIO	111 BERRIMAN ST	RCRA-SQG, E MANIFEST	Higher	61, 0.012, ENE
A8	790 LIBERTY AVE	790 LIBERTY AVE	NY NYC OER	Higher	63, 0.012, North
A9	LOT 34,TAXBLOCK 3989	795 GLENMORE AVENUE	NY E DESIGNATION	Lower	64, 0.012, SSW
A10	LOT 9,TAXBLOCK 3989	339 SHEPHERD AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	65, 0.012, WNW
A11	LOT 16,TAXBLOCK 3989	LIBERTY AVENUE	NY E DESIGNATION	Higher	75, 0.014, NNW
A12	LOT 1,TAXBLOCK 3989	355 SHEPHERD AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	84, 0.016, SW
A13	PRIVATE RESIDENCE	355 SHEPHARD AVE	NY Spills	Lower	84, 0.016, SW
A14	LOT 12,TAXBLOCK 3989	772 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	96, 0.018, NW
A15	MANHOLE #4750	LIBERTY AVE AND BERR	NY Spills	Higher	115, 0.022, North
A16	CON EDISON	LIBERTY AVE & BERRIM	NY MANIFEST	Higher	115, 0.022, North
A17	CON EDISON - MANHOLE	S/W/C LIBERTY AVE &	RCRA NonGen / NLR, NY MANIFEST	Higher	115, 0.022, North
A18	CON EDISON SERVICE B	LIBERTY AVE & BERRIM	RCRA NonGen / NLR, FINDS	Higher	115, 0.022, North
A19	LOT 36,TAXBLOCK 3989	793 GLENMORE AVENUE	NY E DESIGNATION	Lower	115, 0.022, SSW
A20	D&J CLEANERS	770 LIBERTY AVE	EDR Hist Cleaner	Lower	115, 0.022, NW
A21	LOT 10,TAXBLOCK 3989	770 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	115, 0.022, NW
B22	LOT 57,TAXBLOCK 3973	787 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	148, 0.028, North
B23	CON EDISON	LIBERTY AVE & SHEPHE	RCRA NonGen / NLR	Lower	163, 0.031, NW
B24	CON EDISON	LIBERTY AVE & SHEPHE	RCRA NonGen / NLR	Lower	163, 0.031, NW
B25	CON EDISON	LIBERTY AVE & SHEPHE	NJ MANIFEST	Lower	163, 0.031, NW
B26	CON ED	LIBERTY AVE & SHEPHE	NY MANIFEST	Lower	163, 0.031, NW
B27	CON EDISON	LIBERTY AVE & SHEPHE	NY MANIFEST	Lower	163, 0.031, NW
B28	CON EDISON	LIBERTY AVE & SHEPHE	NJ MANIFEST	Lower	163, 0.031, NW
B29	LOT 58,TAXBLOCK 3973	785 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	171, 0.032, North
C30	LOT 17,TAXBLOCK 4005	GLENMORE AVENUE	NY E DESIGNATION	Lower	203, 0.038, SSE
D31	LOT 34,TAXBLOCK 3988	366 SHEPHERD AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	206, 0.039, SW
D32	FORMER GARONE BROS A	352-362 SHEPHERD AVE	NY BROWNFIELDS	Lower	206, 0.039, WSW
D33	LOT 28,TAXBLOCK 3988	352 SHEPHERD AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	206, 0.039, WSW
D34	352-362 SHEPHERD AVE	352-362 SHEPHERD AVE	NY NYC OER	Lower	206, 0.039, WSW
D35	FORMER GARONE BROS.	352 - 362 SHEPHERD A	NY UST	Lower	206, 0.039, WSW
D36	SHEPPARDS AUTO PARTS	352 SHEPHERD AVE	NY Spills	Lower	206, 0.039, WSW
D37	SHEPHERD AVE GARAGE	352-362 SHEPHERD AV	EDR Hist Auto	Lower	206, 0.039, WSW
D38	777 GLENMORE AVE LLC	777 GLENMORE AVE	NY MANIFEST	Lower	228, 0.043, SW
D39	777 GLENMORE AVE LLC	777 GLENMORE AVE	RCRA NonGen / NLR, E MANIFEST	Lower	228, 0.043, SW

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
D40	777 GLENMORE AVENUE	777 GLENMORE AVENUE	NY VCP, NY NYC OER	Lower	228, 0.043, SW
D41	CONSTRUCTION SITE	368 SHEPHERD AVE	NY Spills	Lower	229, 0.043, SW
D42	LOT 35,TAXBLOCK 3988	368 SHEPHERD AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	229, 0.043, SW
B43	3100 ATLANTIC AVE LL	803 LIBERTY AVENUE	NY UST	Higher	236, 0.045, NNE
B44	803 LIBERTY AVENUE	803 LIBERTY AVENUE	UST FINDER	Higher	236, 0.045, NNE
C45	LOT 16,TAXBLOCK 4005	804 GLENMORE AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	247, 0.047, SSE
C46		810 GLENMORE AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	252, 0.048, SE
B47	LOT 55,TAXBLOCK 3973	BERRIMAN STREET	NY E DESIGNATION	Higher	255, 0.048, North
C48	LOT 13,TAXBLOCK 4006	820 GLENMORE AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	268, 0.051, SE
E49	CON EDISON - COMPANY	750 LIBERTY AVE	E MANIFEST	Lower	301, 0.057, WNW
F50	TRANSFORMER MANHOLE	ATKINS AVE & LIBERTY	NY Spills	Higher	306, 0.058, NE
F51	CON ED - MH 3739	LIBERTY AVE & ATKINS	RCRA NonGen / NLR, NY MANIFEST	Higher	306, 0.058, NE
B52	LOT 53,TAXBLOCK 3973	68 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Higher	307, 0.058, North
C53	LOT 19,TAXBLOCK 4005	148 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	308, 0.058, SSE
E54	LOT 56,TAXBLOCK 3972	749 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	318, 0.060, WNW
G55	MANHOLE #68329	GLENMORE AVE / ATKIN	NY Spills	Lower	329, 0.062, ESE
B56	LOT 52,TAXBLOCK 3973	66 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Higher	330, 0.062, North
D57		390 SHEPHERD AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	334, 0.063, SSW
C58	LOT 20,TAXBLOCK 4005	152 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	334, 0.063, SSE
D59		392 SHEPHERD AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	352, 0.067, SSW
D60	NYC DEP	394 SHEPHERD AVE	NY Spills, RCRA NonGen / NLR, NY MANIFEST, NJ...	Lower	360, 0.068, SSW
C61	LOT 21,TAXBLOCK 4005	154 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	366, 0.069, SSE
C62	CON EDISON	156 BERRIMON ST	NY MANIFEST	Lower	366, 0.069, South
C63	CON EDISON	156 BERRIMAN	NY MANIFEST	Lower	366, 0.069, South
B64	LOT 50,TAXBLOCK 3973	BERRIMAN STREET	NY E DESIGNATION	Higher	370, 0.070, North
B65	CARBUSTERS AUTO RECY	60 BERRIMAN STREET	NY SWF/LF, NY Spills	Higher	372, 0.070, North
E66	LOT 57,TAXBLOCK 3972	745 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	376, 0.071, NW
E67	MANHOLE # 4748	ESSEX STREET AND LIB	NY Spills	Lower	397, 0.075, WNW
E68	CON EDISON	LIBERTY AVE & ESSEX	NY MANIFEST	Lower	397, 0.075, WNW
E69	CON EDISON	LIBERTY AVE & ESSEX	RCRA NonGen / NLR, NY MANIFEST	Lower	397, 0.075, WNW
E70	CON EDISON	LIBERTY AVE & ESSEX	RCRA NonGen / NLR	Lower	397, 0.075, WNW
D71	MANHOLE # 67930	GLEN MORE AVE/ESSEX	NY Spills	Lower	409, 0.077, SW
E72	CON ED	320 ESSEX ST	NY MANIFEST	Lower	412, 0.078, West
E73	CON EDISON	320 ESSEX ST	NJ MANIFEST	Lower	412, 0.078, West
E74	CON EDISON	320 ESSEX ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	412, 0.078, West
F75		118 ATKINS AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	420, 0.080, ENE
H76	55 BERRIMAN STREET -	55 BERRIMAN STREET	UST FINDER	Higher	425, 0.080, North
H77	3100 ATLANTIC LLC	55 BERRIMAN STREET	NY LTANKS, NY UST	Higher	425, 0.080, North
E78	LOT 17,TAXBLOCK 3987	742 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	426, 0.081, WNW

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
D79	CON EDISON	OPP 761 GLENMORE AVE	NY MANIFEST	Lower	434, 0.082, WSW
E80	CON EDISON	330 ESSEX ST	NY MANIFEST	Lower	438, 0.083, West
H81	LOT 46,TAXBLOCK 3973	46 BERRIMAN STREET	NY E DESIGNATION, NY NYC LAND USE	Higher	443, 0.084, North
F82	MIKE'S HEAVY DUTY TO	816 LIBERTY AVENUE	NY AST	Higher	446, 0.084, ENE
E83	J. BORAH CO.	291 ESSEX STREET	NY AST	Lower	454, 0.086, NW
H84	NYC DEP DERTA	49 BERRIMAN ST	RCRA NonGen / NLR, E MANIFEST	Higher	466, 0.088, North
H85	NYC DEP DERTA	49 BERRIMAN ST	NY Spills, NY MANIFEST	Higher	466, 0.088, North
H86	3100 ATLANTIC LLC	62 ATKINS AVENUE	NY UST	Higher	471, 0.089, NNE
H87	62 ATKINS AVENUE	62 ATKINS AVENUE	UST FINDER	Higher	471, 0.089, NNE
H88	62 ATKINS AVE - TTF	62 ATKINS AVE	NY LTANKS	Higher	471, 0.089, NNE
E89	CON EDISON	737 LIBERTY AVE	E MANIFEST	Lower	474, 0.090, WNW
F90	831 LIBERTY AVENUE	831 LIBERTY AVENUE	UST FINDER	Higher	485, 0.092, NE
F91	831 LIBERTY AVENUE	831 LIBERTY AVENUE	NY UST	Higher	485, 0.092, NE
I92	SPILL NUMBER 0302806	281 ESSEX ST	NY Spills	Lower	492, 0.093, NW
E93	CON EDISON	728 LIBERTY AVE FRON	NY MANIFEST	Lower	496, 0.094, West
E94	CON EDISON	728 LIBERTY AVE FRON	RCRA NonGen / NLR, FINDS	Lower	496, 0.094, West
E95	LOT 45,TAXBLOCK 3971	298 ESSEX STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	504, 0.095, WNW
J96	ST RITA'S R.C.CHURCH	275 SHEPHERD AVENUE	UST FINDER	Higher	515, 0.098, NNW
J97	ST RITA'S R.C. CHURC	275 SHEPHERD AVENUE	NY UST	Higher	515, 0.098, NNW
K98	385 ESSEX STREET	385 ESSEX STREET	NY LTANKS, NY NYC LAND USE	Lower	528, 0.100, SSW
E99	CON EDISON/ ATTN: QU	729 LIBERTY AVE	E MANIFEST	Lower	547, 0.104, WNW
E100	CON EDISON	729 LIBERTY AVE	E MANIFEST	Lower	547, 0.104, WNW
H101	61 ATKINS AVENUE	61 ATKINS AVENUE	UST FINDER	Higher	550, 0.104, NNE
H102	61 ATKINS AVENUE	61 ATKINS AVENUE	NY LTANKS, NY UST	Higher	550, 0.104, NNE
H103	CONSOLIDATED EDISON	39 BERRIMAN STREET	E MANIFEST	Higher	553, 0.105, North
F104	DRUM RUN (SIDE OF RO	MONTAUK AVE AND LIBE	NY Spills	Higher	554, 0.105, ENE
F105	CON EDISON MANHOLE 3	MONTAUK AVE & LIBERT	RCRA NonGen / NLR, NY MANIFEST	Higher	554, 0.105, ENE
F106	CON ED	MONTAUK AVE & LIBERT	NY MANIFEST	Higher	554, 0.105, ENE
F107	CON EDISON	MONTAUK AVE & LIBERT	RCRA NonGen / NLR, FINDS, ECHO	Higher	554, 0.105, ENE
L108	SOUTH WEST CRNER	LIBERTY AVE/MONTAUK	NY Spills	Higher	563, 0.107, ENE
I109	LOT 44,TAXBLOCK 3971	294 ESSEX STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	568, 0.108, WNW
G110	VAULT # 67400	GLENMORE AVE/MONTAUK	NY Spills	Lower	569, 0.108, East
M111	LOT 28,TAXBLOCK 4005	2501 PITKIN AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	581, 0.110, South
M112	PITKIN BERRIMAN SITE	2501 PITKIN AVENUE	US BROWNFIELDS	Lower	581, 0.110, South
G113	CON EDISON	166 MONTAUK AVE FRON	NY MANIFEST	Lower	585, 0.111, ESE
G114	CON EDISON	166 MONTAUK AVE FRON	NJ MANIFEST	Lower	585, 0.111, ESE
G115	CON EDISON	166 MONTAUK AVE FRON	RCRA NonGen / NLR, FINDS, ECHO	Lower	585, 0.111, ESE
I116	LOT 39,TAXBLOCK 3971	278 ESSEX STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	595, 0.113, NW
N117	LOT 53,TAXBLOCK 3971	725 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	596, 0.113, WNW

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
N118	CON EDISON	720 LIBERTY AVE	E MANIFEST	Lower	602, 0.114, West
L119	CON EDISON	113 MONTAUK AVE	E MANIFEST	Higher	604, 0.114, ENE
I120		282 ESSEX STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	607, 0.115, WNW
I121	LOT 41,TAXBLOCK 3971	286 ESSEX STREET	NY E DESIGNATION, NY NYC LAND USE	Lower	613, 0.116, WNW
N122	LOT 54,TAXBLOCK 3971	LIBERTY AVENUE	NY E DESIGNATION	Lower	616, 0.117, WNW
H123	31 BERRIMAN STREET	31 BERRIMAN STREET	NY UST	Higher	623, 0.118, North
H124	31 BERRIMAN STREET	31 BERRIMAN STREET	UST FINDER	Higher	623, 0.118, North
H125	31 BERRIMAN ST.- TTF	31 BERRIMAN ST	NY LTANKS	Higher	623, 0.118, North
L126	LOT 15,TAXBLOCK 3992	844 LIBERTY AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	638, 0.121, ENE
N127	CON EDISON	LIBERTY AVE & LINWOO	NJ MANIFEST	Lower	640, 0.121, West
N128	CON EDISON	LIBERTY AVE & LINWOO	RCRA NonGen / NLR	Lower	640, 0.121, West
N129	CON EDISON	LINWOOD ST & LIBERTY	NY MANIFEST	Lower	640, 0.121, West
N130	CON EDISON	LINWOOD ST & LIBERTY	RCRA NonGen / NLR	Lower	640, 0.121, West
M131	NYCT - SHEPHERD AVEN	SHEPHERD AVE & PITKI	NY MANIFEST	Lower	641, 0.121, South
M132	NYCT - SHEPHERD AVEN	SHEPHERD AVE & PITKI	E MANIFEST	Lower	641, 0.121, South
O133	64 MONTAUK AVENUE	64 MONTAUK AVENUE	NY LTANKS, NY UST	Higher	649, 0.123, NNE
O134	64 MONTAUK AVENUE	64 MONTAUK AVENUE	UST FINDER	Higher	649, 0.123, NNE
N135	MANHOLE 4747	LIBERTY AV/LINWOOD S	NY Spills	Lower	653, 0.124, West
P136	SPILL NUMBER 0003444	GLENMORE AV/LINWOOD	NY Spills	Lower	653, 0.124, WSW
P137	GLENMORE AV/LINWOOD	GLENMORE AV/LINWOOD	NY Spills	Lower	653, 0.124, WSW
H138	3100 ATLANTIC LLC	36 ATKINS AVENUE	NY UST	Higher	655, 0.124, North
H139	36 ATKINS AVENUE	36 ATKINS AVENUE	UST FINDER	Higher	655, 0.124, North
L140	CON EDISON - COMPANY	OPP OF 87 MONTAUK AV	E MANIFEST	Higher	657, 0.124, NE
Q141	CON ED COMPANY OF NY	2531 PITKIN AVE	E MANIFEST	Lower	676, 0.128, SE
P142	398 LINWOOD ST	398 LINWOOD ST	NY LTANKS	Lower	693, 0.131, West
M143	CON EDISON	2488 PITKIN AVE	E MANIFEST	Lower	708, 0.134, South
O144	35 ATKINS AVE - TTF	35 ATKINS AVE	NY LTANKS	Higher	715, 0.135, NNE
O145	33 ATKINS AVENUE	33 ATKINS AVENUE	UST FINDER	Higher	738, 0.140, NNE
O146	33 ATKINS AVENUE	33 ATKINS AVENUE	NY UST	Higher	738, 0.140, NNE
P147	CON EDISON	734 GLENMORE AVE	NY MANIFEST	Lower	755, 0.143, WSW
K148	NARVAEZ CLEANERS	2458 PITKIN AVE	NY DRYCLEANERS	Lower	759, 0.144, SSW
K149	NARVAEZ CLEANERS	2458 PITKIN AVE	RCRA-VSQG, ICIS, US AIRS, NY MANIFEST	Lower	759, 0.144, SSW
Q150	CON EDISON/ ATTN: QU	2538 PITKIN AVE	E MANIFEST	Lower	798, 0.151, SE
R151	I.S. 302 - BROOKLYN	350 LINWOOD STREET	NY AST	Lower	801, 0.152, WNW
R152	IS 302K SCHOOL	350 LINWOOD ST	RCRA-LQG, E MANIFEST, NY MANIFEST	Lower	801, 0.152, WNW
Q153	CON EDISON/ ATTN: QU	2540 PITKIN AVE	E MANIFEST	Lower	806, 0.153, SE
L154	CON ED - MH 3741	LIBERTY AVE & MILFOR	RCRA NonGen / NLR, NY MANIFEST	Higher	811, 0.154, ENE
L155	CON ED - MH 57244	LIBERTY AVE & MILFOR	RCRA NonGen / NLR, NY MANIFEST	Higher	811, 0.154, ENE
L156	CON EDISON	LIBERTY AVE & MILFOR	RCRA NonGen / NLR, NY MANIFEST	Higher	811, 0.154, ENE

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
O157	36 MONTAUK AVENUE	36 MONTAUK AVENUE	NY UST	Higher	817, 0.155, NNE
O158	36 MONTAUK AVENUE	36 MONTAUK AVENUE	UST FINDER	Higher	817, 0.155, NNE
O159	PRIVATE RESIDENCE	36 MONTAUK AVE	NY LTANKS	Higher	817, 0.155, NNE
S160	PRIVATE RESIDENCE	172 MILLFORD ST	NY LTANKS	Lower	823, 0.156, ESE
T161	ST RITA'S SCHOOL	260 SHEPHERD AVENUE	UST FINDER	Higher	824, 0.156, NNW
T162	ST RITAS YOUTH CENTE	260 SHEPHERD AVENUE	UST FINDER	Higher	824, 0.156, NNW
T163	ST RITAS YOUTH CENTE	260 SHEPHERD AVENUE	NY UST	Higher	824, 0.156, NNW
U164	2437 PITKIN AVENUE	2437 PITKIN AVENUE	NY VCP, NY NYC OER	Lower	825, 0.156, SSW
U165	TAPIA AUTO REPAIR	2437 PITKIN AVENUE	NY AST	Lower	825, 0.156, SSW
U166	CON EDISON - BROOKLY	2446 PITKIN AVE	E MANIFEST	Lower	834, 0.158, SSW
S167	CON ED COMPANY OF NY	2561 PITKINS AVE	E MANIFEST	Lower	865, 0.164, ESE
V168	TANK TEST FAILURES T	3100 ATLANTIC AVENUE	NY LTANKS, NY NYC LAND USE	Higher	870, 0.165, North
P169	CON EDISON	SEC GLENMORE & ELTON	NY MANIFEST	Lower	880, 0.167, WSW
V170	3100 ATLANTIC LLC	3104 ATLANTIC AVENUE	NY UST	Higher	880, 0.167, North
V171	3104 ATLANTIC AVENUE	3104 ATLANTIC AVENUE	UST FINDER	Higher	880, 0.167, North
V172	CON EDISON - SERVICE	3104 ATLANTIC AVE	NY LTANKS, NY MANIFEST	Higher	880, 0.167, North
U173	CON EDISON - SERVICE	418 ESSEX ST	NY MANIFEST	Lower	889, 0.168, SSW
U174	CON EDISON - BROOKLY	418 ESSEX ST	E MANIFEST	Lower	889, 0.168, SSW
W175	VERIZON NEW YORK INC	862 LIBERTY AVENUE	NY TANKS, NY Spills	Higher	900, 0.170, ENE
T176	MTA LIRR - ATLANTIC	ATLANTIC AVE & ESSEX	RCRA NonGen / NLR	Higher	905, 0.171, NW
X177	B&B URBAN LLC - 315	315 LINWOOD STREET	RCRA-LQG, E MANIFEST	Lower	911, 0.173, NW
X178	315 LINWOOD STREET	315 LINWOOD	NY VCP, NY NYC OER	Lower	911, 0.173, NW
X179	B&B URBAN LLC - 315	315 LINWOOD STREET	NY MANIFEST	Lower	911, 0.173, NW
V180	CON EDISON - MANHOLE	ATLANTIC AVE & BERRI	NY MANIFEST	Higher	916, 0.173, North
T181		3051 ATLANTIC AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	964, 0.183, NNW
W182	TES AUTO SERVICE, IN	873 LIBERTY AVENUE	NY TANKS, NY NYC LAND USE	Higher	967, 0.183, ENE
T183	FOLLOWERS OF JESUS M	3065 ATLANTIC AVENUE	NY AST	Higher	971, 0.184, NNW
T184	CON EDISON - COMPANY	3065 ATLANTIC AVE	E MANIFEST	Higher	971, 0.184, NNW
Y185	KEY CAPITAL FUNDING	23 MONTAUK AVENUE	NY AST	Higher	975, 0.185, NNE
186	CON EDISON - EXTERIO	2564 PITKIN AVE	E MANIFEST	Lower	980, 0.186, ESE
V187	3126 ATLANTIC AVENUE	3126 ATLANTIC AVENUE	NY UST	Higher	987, 0.187, NNE
V188	3126 ATLANTIC AVENUE	3126 ATLANTIC AVENUE	UST FINDER	Higher	987, 0.187, NNE
U189	CON EDISON - COMPANY	OPP OF 24-28 PITKIN	E MANIFEST	Lower	988, 0.187, SSW
T190	DYNAMIC AUTO CLINIC	3053 ATLANTIC AVENUE	NY AST	Higher	997, 0.189, NNW
V191	CON EDISON	ATLANTIC AVE & ATKIN	NJ MANIFEST	Higher	1001, 0.190, North
V192	CON EDISON	ATLANTIC AVE & ATKIN	RCRA NonGen / NLR, FINDS, ECHO	Higher	1001, 0.190, North
V193	CON EDISON	ATLANTIC AVE & ATKIN	NY MANIFEST	Higher	1001, 0.190, North
Y194	CON EDISON	3130 ATLANTIC AVE	NY MANIFEST	Higher	1002, 0.190, NNE
Z195	CON ED COMPANY OF NY	680 LIBERTY AVE	E MANIFEST	Lower	1012, 0.192, West

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
S196	CON ED COMPANY OF NY	432 LOGAN ST	E MANIFEST	Lower	1043, 0.198, East
197	CON EDISON SERVICE B	3027 ATLANTIC AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1043, 0.198, NNW
198	R & O MGMT CORP	785 BELMONT AVE	NY AST	Lower	1059, 0.201, South
AA199	NYCTA - ELTON SUBSTA	ELTON ST & PITKIN AV	RCRA NonGen / NLR, NY MANIFEST	Lower	1069, 0.202, SW
AA200	CON EDISON MANHOLE 5	PITKIN AVE & ELTON S	RCRA NonGen / NLR, NY MANIFEST	Lower	1069, 0.202, SW
W201	NYNEX	LOGAN ST & LIBERTY A	NY MANIFEST	Lower	1070, 0.203, ENE
W202	CON EDISON - COMPANY	LOGAN ST & LIBERTY A	E MANIFEST	Lower	1070, 0.203, ENE
W203	CON ED - V 3742	LIBERTY AVE & LOGAN	RCRA NonGen / NLR, NY MANIFEST	Lower	1070, 0.203, ENE
204	CONSOLIDATED EDISON	LOGAN & GLENMORE MH6	NY MANIFEST	Lower	1080, 0.205, East
205	NEW GENESIS CHRISTIA	224 SHEPHERD AVENUE	NY AST	Higher	1082, 0.205, NNW
X206	CON EDISON - COMPANY	2976 ATLANTIC AVE	E MANIFEST	Lower	1097, 0.208, WNW
AB207	CON EDISON	496 LINWOOD ST	NY MANIFEST	Lower	1100, 0.208, SSW
AC208	CON EDISON SERVICE B	BELMONT AVE & BERRIM	RCRA NonGen / NLR, NY MANIFEST	Lower	1104, 0.209, SSE
Y209	CON EDISON	3144 ATLANTIC AVE	NY MANIFEST	Higher	1112, 0.211, NNE
Y210	CON EDISON - MANHOLE	3144 ATLANTIC AVE	RCRA NonGen / NLR	Higher	1112, 0.211, NNE
Z211	CONSOLIDATED EDISON	374 CLEVELAND ST	E MANIFEST	Higher	1119, 0.212, West
Z212	670 LIBERTY AVE REPA	670 LIBERTY AVENUE	NY AST	Higher	1121, 0.212, West
AC213	CON EDISON	814 BELMONT AVE	RCRA NonGen / NLR	Lower	1135, 0.215, SSE
AC214	CON EDISON - EXTERIO	ATKINS AVE & BELMONT	E MANIFEST	Lower	1141, 0.216, SSE
AD215	CON EDISON	ATLANTIC AVE & ELTON	RCRA NonGen / NLR, FINDS, ECHO	Lower	1141, 0.216, WNW
AD216	CON EDISON	ATLANTIC AVE & ELTON	NY MANIFEST	Lower	1141, 0.216, WNW
AD217	CON EDISON	ATLANTIC AVE & ELTON	NJ MANIFEST	Lower	1141, 0.216, WNW
AD218	CON EDISON - COMPANY	2972 ATLANTIC AVE	E MANIFEST	Lower	1144, 0.217, WNW
AA219	CON EDISON	390 ELTON STREET	NY MANIFEST	Higher	1146, 0.217, SW
AE220	LOT 25,TAXBLOCK 4153	29 MILFORD STREET	NY E DESIGNATION, NY NYC LAND USE, NY NYC OER	Higher	1151, 0.218, NE
X221	2969 ATLANTIC AVE	2969 ATLANTIC AVENUE	UST FINDER	Higher	1170, 0.222, NW
X222	2969 ATLANTIC AVE	2969 ATLANTIC AVENUE	NY UST	Higher	1170, 0.222, NW
X223	RIVEIRA MOTEL	2969 ATLANTIC AVENUE	NY LTANKS	Higher	1170, 0.222, NW
AA224	CON EDISON/ ATTN: BR	2406 PITKIN AVE	E MANIFEST	Higher	1171, 0.222, SW
AA225	CON EDISON	2406 PITKIN AV	NY MANIFEST	Higher	1171, 0.222, SW
AF226	ATLANTIC AVE - NY -	3123 ATLANTIC AVE &	RCRA NonGen / NLR, FINDS, ECHO	Higher	1175, 0.223, North
AF227	LOT 52,TAXBLOCK 3959	3123 ATLANTIC AVENUE	NY AST, NY E DESIGNATION, NY NYC LAND USE	Higher	1175, 0.223, North
AF228	ATLANTIC AVENUE INC	3123 ATLANTIC AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1175, 0.223, North
AF229	CYPRESS HILLS SERVIC	3123 ATLANTIC AVENUE	UST FINDER	Higher	1175, 0.223, North
AF230	ATLANTIC SERVICE STA	3123 ATLANTIC AVENUE	NY UST	Higher	1175, 0.223, North
AE231	25 MILFORD STREET	25 MILFORD STREET	NY VCP, NY NYC OER	Higher	1190, 0.225, NE
AF232	CON EDISON	FRONT OF 224 HIGHLAN	NY MANIFEST	Higher	1198, 0.227, North
AG233	CON EDISON SERVICE B	422 CLEVELAND ST FRO	RCRA NonGen / NLR	Higher	1198, 0.227, WSW
AG234	CON EDISON	422 CLEVELAND ST	NY MANIFEST	Higher	1198, 0.227, WSW

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AE235	LOT 28,TAXBLOCK 4153	23 MILFORD STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	1200, 0.227, NE
AE236	23 MILFORD STREET VC	23 MILFORD ST	RCRA NonGen / NLR, E MANIFEST	Higher	1200, 0.227, NE
AA237	LOT 19,TAXBLOCK 4017	2400 PITKIN AVENUE	NY VCP, NY E DESIGNATION, NY NYC OER	Higher	1206, 0.228, SW
AB238	CON EDISON SERVICE B	510 LINWOOD ST	RCRA NonGen / NLR, FINDS	Lower	1212, 0.230, SSW
AB239	CON EDISON	510 LINWOOD ST	NY MANIFEST	Lower	1212, 0.230, SSW
AD240	2958 ATLANTIC AVENUE	2958 ATLANTIC AVENUE	NY AST	Lower	1213, 0.230, WNW
AD241	2958 ATLANTIC AVENUE	2958 ATLANTIC AVENUE	NY UST	Lower	1213, 0.230, WNW
AD242	2958 ATLANTIC AVENUE	2958 ATLANTIC AVENUE	UST FINDER	Lower	1213, 0.230, WNW
AG243	CON EDISON	FRONT OF 681 GLENMOR	NY MANIFEST	Higher	1232, 0.233, WSW
AA244	CON EDISON	408 ELTON ST	NY MANIFEST	Lower	1258, 0.238, SW
AH245	FORMER KFC RESTAURAN	3143 ATLANTIC AVENUE	NY UST	Higher	1294, 0.245, NNE
AH246	FORMER KFC RESTAURAN	3143 ATLANTIC AVENUE	UST FINDER	Higher	1294, 0.245, NNE
AI247	CON EDISON - COMPANY	212 HIGHLAND PL	E MANIFEST	Higher	1298, 0.246, North
AI248	CON EDISON	FO 212 HIGHLAND PL	NY MANIFEST	Higher	1298, 0.246, North
249	BROOKLYN DEVELOPMENT	88 FOUNTAIN ST	NY LTANKS	Higher	1314, 0.249, ENE
AJ250	INDUSTRIAL FINISHING	465 LOGAN STREET	NJ MANIFEST	Lower	1315, 0.249, ESE
AJ251	INDUSTRIAL FINISHING	465 LOGAN ST.	NY CBS UST	Lower	1315, 0.249, ESE
AJ252	INDUSTRIAL FINISHING	465 LOGAN STREET	NY AIRS, NY MANIFEST	Lower	1315, 0.249, ESE
AJ253	INDUSTRIAL FINISHING	465 LOGAN ST	NY CBS, NY Spills, NY MANIFEST	Lower	1315, 0.249, ESE
AJ254	INDUSTRIAL FINISHING	465 LOGAN ST	RCRA-LQG, ICIS, US AIRS, FINDS, ECHO, E MANIFEST	Lower	1315, 0.249, ESE
AK255	CONSOLIDATED EDISON	2950 ATLANTIC AVE	NY Spills, NY MANIFEST	Higher	1319, 0.250, WNW
AK256	ATLANTIC AVE. SERVIC	2950 ATLANTIC AVENUE	NY UST	Higher	1319, 0.250, WNW
AK257	CON EDISON - CLEVELA	2950 ATLANTIC AVE	RCRA-LQG, FINDS, ECHO, E MANIFEST, NY MANIFEST	Higher	1319, 0.250, WNW
AK258	CON ED MH 64858	2950 ATLANTIC AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1319, 0.250, WNW
AK259	ATLANTIC AVE. SERVIC	2950 ATLANTIC AVENUE	NY AST	Higher	1319, 0.250, WNW
AK260	ATLANTIC AVE. SERVIC	2950 ATLANTIC AVENUE	UST FINDER	Higher	1319, 0.250, WNW
AK261	UNION STATION (CITIZ	ATLANTIC AVE., ASHFO	EDR MGP	Higher	1334, 0.253, WNW
AK262	K - UNION STATION HO	ATLANTIC AVE, ASHFOR	NY SHWS, NY BROWNFIELDS, NY MGP	Higher	1336, 0.253, WNW
AJ263	LOT 13,TAXBLOCK 4228	2602 PITKIN AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	1348, 0.255, ESE
264	249 LINWOOD ST/BKLYN	249 LINWOOD STREET	NY LTANKS	Higher	1417, 0.268, NNW
AL265	3294 ATLANTIC AVENUE	3192 ATLANTIC AVENUE	NY VCP, NY NYC OER	Higher	1442, 0.273, NNE
AL266	3200 ATLANTIC AVENUE	8 FOUNTAIN AVENUE AN	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS,	Higher	1514, 0.287, NE
267	DOMINICK VITUCCI TRU	2 FOUNTAIN AVE	NY SWF/LF	Higher	1585, 0.300, NE
268	PRIVATE RESIDENCE	229 NORWOOD AVE	NY LTANKS	Higher	1625, 0.308, NNE
269	POLYTECH	1 WELLS ST	NY LTANKS, NY Spills, NY MANIFEST, NY NYC LAND USE	Higher	1651, 0.313, ENE
270	LOT 30,TAXBLOCK 3998	2337 PITKIN AVENUE	NY VCP, NY E DESIGNATION, NY NYC OER	Higher	1691, 0.320, WSW
271	2942 FULTON ST	2942 FULTON STREET	NY LTANKS, NY NYC LAND USE	Higher	1792, 0.339, NW
AM272	HESS#32518	2880 ATLANTIC AVENUE	RCRA-VSQG, NY LTANKS, NY UST, NY Spills, US AIRS,...	Higher	1966, 0.372, West
AM273	2864 ATLANTIC AVENUE	2864 ATLANTIC AVENUE	NY BROWNFIELDS, NY E DESIGNATION, NY NYC OER, NY...	Higher	1998, 0.378, West

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
274	ATLANTIC AVE AT CARL	ATLANTIC AVE AT CARL	NY LTANKS	Higher	2064, 0.391, ENE
275	318 FOUNTAIN AVE	318 FOUNTAIN AVE	NY LTANKS	Lower	2164, 0.410, SE
276	1199 SUTTER AVENUE	1199 SUTTER AVENUE	NY SHWS, NY BROWNFIELDS, NY Spills, NY NYC LAND...	Lower	2224, 0.421, ESE
277	2840 ATLANTIC AVENUE	2840 ATLANTIC AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS,	Higher	2250, 0.426, West
AN278	CHESTNUT COMMONS ATL	110 DINSMORE PLACE	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS,	Higher	2279, 0.432, NE
AO279	2862 FULTON STREET	2862 FULTON STREET	NY NYC OER	Higher	2330, 0.441, WNW
AO280	208 BARBEY ST	208 BARBEY ST	NY LTANKS	Higher	2345, 0.444, WNW
281	223 & 227 RICHMOND S	223 RICHMOND ST	NY LTANKS, NY Spills	Higher	2346, 0.444, NNE
282	447 EUCLID AVENUE	447 EUCLID AVENUE	NY VCP, NY NYC OER	Lower	2352, 0.445, East
AN283	ATLANTIC CHESTNUT AF	275 CHESTNUT ST	NY BROWNFIELDS, NY MANIFEST	Higher	2364, 0.448, NE
AN284	ATLANTIC CHESTNUT -	275 CHESTNUT STREET	NY BROWNFIELDS	Higher	2364, 0.448, NE
285	70 ELCON ST/BKLYN	70 ELCON STREET	NY LTANKS	Higher	2390, 0.453, NNW
AP286		180 ARLINGTON AVENUE	NY LTANKS, NY Spills, NY NYC LAND USE	Higher	2410, 0.456, NW
AN287	242 CHESTNUT STREET	242 CHESTNUT STREET	US BROWNFIELDS, FINDS	Higher	2424, 0.459, NNE
AP288	187 ARLINGTON AVE/BK	187 ARLINGTON AVENUE	NY LTANKS	Higher	2470, 0.468, NW
AO289	MALDONDAO HOME - TTF	2849 FULTON STREET	NY LTANKS, NY NYC LAND USE	Higher	2492, 0.472, WNW
AQ290	P.S. 290 - BROOKLYN	135 SCHENCK AVENUE	NY LTANKS, NY LEAD	Higher	2517, 0.477, WNW
291	90 MCKINLEY AVE	90 MCKINLEY AVE	NY LTANKS, NY Spills	Higher	2518, 0.477, ENE
AR292	2827 ATLANTIC AVENUE	2827 ATLANTIC AVENUE	US BROWNFIELDS, FINDS	Higher	2518, 0.477, West
AS293	SPILL NUMBER 9312952	2820 ATLANTIC AVENUE	UST FINDER RELEASE	Higher	2530, 0.479, West
AS294	GASETERIA	2820 ATLANTIC AVENUE	UST FINDER RELEASE	Higher	2530, 0.479, West
AS295	GASETERIA	2820 ATLANTIC AVENUE	NY LTANKS	Higher	2530, 0.479, West
296	APT BUILDING	2736 PITKIN AVE	NY LTANKS, NY LEAD, NY NYC LAND USE	Lower	2541, 0.481, East
AR297	2817 ATLANTIC AVENUE	2817 ATLANTIC AVENUE	US BROWNFIELDS, FINDS	Higher	2559, 0.485, West
298	SMITH RESIDENCE	363 MONTAUK AVE	NY LTANKS	Lower	2575, 0.488, SSE
299	ANNA CORP REALITY	78 HIGHLAND PLACE	NY LTANKS, NY Spills, NY LEAD, NY NYC LAND USE	Higher	2578, 0.488, North
AQ300	CORNER OF W. 1ST ST	AND SCHENCK ST	NY LTANKS	Higher	2592, 0.491, WNW
AT301	SPILL NUMBER 8805745	3301 ATLANTIC AVENUE	UST FINDER RELEASE	Higher	2616, 0.495, NE
AT302	BLUE RIDGE FARMS INC	3301 ATLANTIC AVENUE	UST FINDER, UST FINDER RELEASE	Higher	2616, 0.495, NE
AT303	BLUE RIDGE FARMS	3301 ATLANTIC AVENUE	NY LTANKS, NY CBS, NY AST, NY Spills	Higher	2616, 0.495, NE
AT304	CHLOE FOODS	3301 ATLANTIC AVENUE	SEMS	Higher	2616, 0.495, NE
AR305	207 HENDRIX ST./ST.	207 HENDRIX ST.	NY LTANKS	Higher	2626, 0.497, West
AU306	GULF SERVICE STATION	1249 SUTTER AVENUE	UST FINDER RELEASE	Lower	2636, 0.499, ESE
AU307		1249 SUTTER AVENUE	NY LTANKS, NY Spills, NY NYC LAND USE	Lower	2636, 0.499, ESE
AU308	LOX SERVICE STATION	1249 SUTTER AVENUE	UST FINDER RELEASE	Lower	2636, 0.499, ESE
AV309	LOT 55,TAXBLOCK 3933	2795 FULTON STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	3006, 0.569, WNW
AV310	LOT 18,TAXBLOCK 3946	2776 FULTON STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	3127, 0.592, West
311	LOT 15,TAXBLOCK 3690	2738 ATLANTIC AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	3400, 0.644, West
AW312		2718 FULTON STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	3706, 0.702, West

DRAFT

MAPPED SITES SUMMARY

Target Property Address:
98 BERRIMAN STREET
BROOKLYN, NY 11208

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AX313		876 LIVONIA AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	3736, 0.708, SSW
314	2700 ATLANTIC AVENUE	2700 ATLANTIC AVENUE	NY VCP, NY NYC OER	Higher	3793, 0.718, West
AX315	691-715 NEW LOTS AVE	691-715 NEW LOTS AVE	NY NYC OER	Lower	3833, 0.726, SSW
AW316	2701-2715 FULTON STR	2701-2715 FULTON STR	NY VCP, NY NYC OER	Higher	3906, 0.740, West
317	157 NEW JERSEY AVENU	157 NEW JERSEY AVENU	NY VCP, NY NYC OER	Higher	4113, 0.779, West
318	2667 FULTON STREET	2667 FULTON STREET	NY VCP, NY NYC OER	Higher	4257, 0.806, West
319	LOT 54,TAXBLOCK 4151	3513 ATLANTIC AVENUE	NY LTANKS, NY VCP, NY Spills, NY E DESIGNATION, NY...	Lower	4347, 0.823, NE
320	EXXON DIV OF CFI #70	225 PENNSYLVANIA AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NY...	Higher	4353, 0.824, WSW
321		184 PENNSYLVANIA AVE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	4487, 0.850, WSW
322	MAJESTIC CLNRS	740 PINE ST	NY SHWS, NY VCP, NY MANIFEST	Lower	4507, 0.854, SE
323		461 NEW JERSEY AVENU	NY VCP, NY NYC LAND USE, NY NYC OER	Higher	4536, 0.859, SW
324	50 PENN LLC	2618 FULTON ST	NY VCP, NY Spills, NY MANIFEST, NY NYC OER	Higher	4598, 0.871, West
325	673 LIVONIA AVENUE	673 LIVONIA AVENUE	NY SHWS, NY NYC LAND USE	Lower	4965, 0.940, SW
AY326	869 STANLEY AVENUE	869 STANLEY AVENUE	NY SHWS, NY NYC LAND USE	Lower	4991, 0.945, SSE
AY327	LINWOOD STREET GW	LINWOOD ST BETWEEN W	NY SHWS	Lower	5076, 0.961, South

DRAFT

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
98 BERRIMAN STREET 98 BERRIMAN STREET BROOKLYN, NY 11208	NY E DESIGNATION NY NYC LAND USE	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List

DRAFT

US INST CONTROLS ..... Institutional Controls Sites List

Federal ERNS list

ERNS ..... Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ..... Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ..... Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ..... Underground Storage Tank Listing
NY MOSF UST ..... Major Oil Storage Facilities Database
NY MOSF ..... Major Oil Storage Facility Site Listing
NY CBS AST ..... Chemical Bulk Storage Database
NY MOSF AST ..... Major Oil Storage Facilities Database
INDIAN UST ..... Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL ..... Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ..... Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ..... Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ..... Registered Recycling Facility List
NY SWTIRE ..... Registered Waste Tire Storage & Facility List
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
ODI ..... Open Dump Inventory
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register
NY DEL SHWS ..... Delisted Registry Sites
US CDL ..... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ..... Historical Petroleum Bulk Storage Database
NY HIST AST ..... Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ..... Spill Liens Information

DRAFT

LIENS 2	CERCLA Lien Information

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
NY Hist Spills	SPILLS Database
NY SPILLS 90	SPILLS 90 data from FirstSearch
NY SPILLS 80	SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS	Formerly Used Defense Sites
DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
ROD	Records Of Decision
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US MINES	Mines Master Index File
MINES MRDS	Mineral Resources Data System
ABANDONED MINES	Abandoned Mines
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TRIS	List of PFAS Added to the TRI
PFAS TSCA	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR	PFAS Contamination Site Location Listing
PFAS WQP	Ambient Environmental Sampling for PFAS
PFAS NPDES	Clean Water Act Discharge Monitoring Information
PFAS PROJECT	NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing

DRAFT

PFAS ECHO FIRE TRAIN Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC Aqueous Foam Related Incidents Listing
BIOSOLIDS ICIS-NPDES Biosolids Facility Data
NY PFAS PFAS Contamination Site Location Listing
NY COAL ASH Coal Ash Disposal Site Listing
NY Financial Assurance Financial Assurance Information Listing
NY HSWDS Hazardous Substance Waste Disposal Site Inventory
NY SPDES State Pollutant Discharge Elimination System
NY VAPOR REOPENED Vapor Intrusion Legacy Site List
NY UIC Underground Injection Control Wells
NY COOLING TOWERS Registered Cooling Towers
NY ILI New York State Inactive Landfill Initiative

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal sites subject to CERCLA removals and CERCLA orders

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 06/26/2025 has revealed that there is 1 SEMS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHLOE FOODS	3301 ATLANTIC AVENUE	NE 1/4 - 1/2 (0.495 mi.)	AT304	1042

DRAFT

EXECUTIVE SUMMARY

Site ID: 0206581
EPA Id: NYN000206581

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 4 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - CLEVELA EPA ID:: NYD982272841	***2950 ATLANTIC AVE***	***WNW 1/8 - 1/4 (0.250 mi.)***	***AK257***	***676***

Lower Elevation	Address	Direction / Distance	Map ID	Page
IS 302K SCHOOL EPA ID:: NYR000176511	***350 LINWOOD ST***	***WNW 1/8 - 1/4 (0.152 mi.)***	***R152***	***351***
B&B URBAN LLC - 315 EPA ID:: NYR000237008	***315 LINWOOD STREET***	***NW 1/8 - 1/4 (0.173 mi.)***	***X177***	***421***
INDUSTRIAL FINISHING EPA ID:: NYD001303205	***465 LOGAN ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***AJ254***	***635***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYC DEPT OF EDUCATIO EPA ID:: NYR000242271	***111 BERRIMAN ST***	***ENE 0 - 1/8 (0.012 mi.)***	***A7***	***22***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1

DRAFT

RCRA-VSQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NARVAEZ CLEANERS	***2458 PITKIN AVE***	***SSW 1/8 - 1/4 (0.144 mi.)***	***K149***	***328***
EPA ID:: NYD981079254				

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 04/30/2025 has revealed that there are 6 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
K - UNION STATION HO	***ATLANTIC AVE, ASHFOR***	***WNW 1/4 - 1/2 (0.253 mi.)***	***AK262***	***701***
Site Code: 378991				

Lower Elevation	Address	Direction / Distance	Map ID	Page
1199 SUTTER AVENUE	***1199 SUTTER AVENUE***	***ESE 1/4 - 1/2 (0.421 mi.)***	***276***	***849***
Site Code: 434283				
MAJESTIC CLNRS	***740 PINE ST***	***SE 1/2 - 1 (0.854 mi.)***	***322***	***1098***
Site Code: 58590				
Class Code: Significant threat to the public health or environment - action required.				
673 LIVONIA AVENUE	***673 LIVONIA AVENUE***	***SW 1/2 - 1 (0.940 mi.)***	***325***	***1122***
Site Code: 631213				
869 STANLEY AVENUE	***869 STANLEY AVENUE***	***SSE 1/2 - 1 (0.945 mi.)***	***AY326***	***1125***
Site Code: 651358				
Class Code: Significant threat to the public health or environment - action required.				
LINWOOD STREET GW	LINWOOD ST BETWEEN W	S 1/2 - 1 (0.961 mi.)	AY327	1129
Site Code: 594129				

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 02/20/2025 has revealed that there are 2 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CARBUSTERS AUTO RECY	***60 BERRIMAN STREET***	***N 0 - 1/8 (0.070 mi.)***	***B65***	***140***
DOMINICK VITUCCI TRU	2 FOUNTAIN AVE	NE 1/4 - 1/2 (0.300 mi.)	267	756

DRAFT

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/03/2025 has revealed that there are 37 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
3100 ATLANTIC LLC Spill Number/Closed Date: 0407618 / 2007-06-22 Site ID: 332137 Spill Date: 2004-10-08	***55 BERRIMAN STREET***	***N 0 - 1/8 (0.080 mi.)***	***H77***	***164***
62 ATKINS AVE - TTF Spill Number/Closed Date: 0407614 / 2006-01-23 Site ID: 332133 Spill Date: 2004-10-08	62 ATKINS AVE	NNE 0 - 1/8 (0.089 mi.)	H88	188
61 ATKINS AVENUE Spill Number/Closed Date: 0407729 / 2010-04-30 Site ID: 332262 Spill Date: 2004-10-12	***61 ATKINS AVENUE***	***NNE 0 - 1/8 (0.104 mi.)***	***H102***	***211***
31 BERRIMAN ST.- TTF Spill Number/Closed Date: 0407617 / 2017-02-21 Site ID: 332136 Spill Date: 2004-10-08	31 BERRIMAN ST	N 0 - 1/8 (0.118 mi.)	H125	272
64 MONTAUK AVENUE Spill Number/Closed Date: 0407730 / 2010-04-30 Site ID: 332263 Spill Date: 2004-10-12	***64 MONTAUK AVENUE***	***NNE 0 - 1/8 (0.123 mi.)***	***O133***	***285***
35 ATKINS AVE - TTF Spill Number/Closed Date: 0407615 / 2006-01-23 Site ID: 332134 Spill Date: 2004-10-08	35 ATKINS AVE	NNE 1/8 - 1/4 (0.135 mi.)	O144	302
PRIVATE RESIDENCE Spill Number/Closed Date: 0407731 / 2005-08-18 Spill Number/Closed Date: 0408110 / 2005-12-30 Site ID: 332264 Site ID: 332748 Spill Date: 2004-10-12 Spill Date: 2004-10-22	36 MONTAUK AVE	NNE 1/8 - 1/4 (0.155 mi.)	O159	386
TANK TEST FAILURES T Spill Number/Closed Date: 1509573 / 2023-04-06 Site ID: 520207 Spill Date: 2015-12-21	***3100 ATLANTIC AVENUE***	***N 1/8 - 1/4 (0.165 mi.)***	***V168***	***404***
CON EDISON - SERVICE Spill Number/Closed Date: 0407616 / 2006-01-23 Site ID: 332135 Spill Date: 2004-10-08	***3104 ATLANTIC AVE***	***N 1/8 - 1/4 (0.167 mi.)***	***V172***	***412***
RIVEIRA MOTEL	2969 ATLANTIC AVENUE	NW 1/8 - 1/4 (0.222 mi.)	X223	524

DRAFT

Spill Number/Closed Date: 0305319 / 2006-03-14
Site ID: 226027
Spill Date: 2003-08-19

BROOKLYN DEVELOPMENT — 88 FOUNTAIN ST — ENE 1/8 - 1/4 (0.249 mi.) — 249 — 603
Spill Number/Closed Date: 8806149 / 1992-09-30
Site ID: 140891
Spill Date: 1988-10-20

249 LINWOOD ST/BKLYN — 249 LINWOOD STREET — NNW 1/4 - 1/2 (0.268 mi.) — 264 — 708
Spill Number/Closed Date: 9000036 / 1995-06-07
Site ID: 93305
Spill Date: 1990-04-02

PRIVATE RESIDENCE — 229 NORWOOD AVE — NNE 1/4 - 1/2 (0.308 mi.) — 268 — 757
Spill Number/Closed Date: 0500041 / 2005-11-21
Site ID: 342916
Spill Date: 2005-04-01

POLYTECH — ***1 WELLS ST*** — ***ENE 1/4 - 1/2 (0.313 mi.)*** — ***269*** — ***758***
Spill Number/Closed Date: 1301729 / 2021-03-31
Spill Number/Closed Date: 2010548 / 2021-07-30
Spill Number/Closed Date: 0000950 / 2006-01-04
Site ID: 482131
Site ID: 617599
Site ID: 285128
Spill Date: 2013-05-20
Spill Date: 2021-03-30
Spill Date: 2000-04-24

2942 FULTON ST — ***2942 FULTON STREET*** — ***NW 1/4 - 1/2 (0.339 mi.)*** — ***271*** — ***778***
Spill Number/Closed Date: 9411155 / 1994-11-21
Spill Number/Closed Date: 9411203 / 1994-11-22
Site ID: 256827
Site ID: 190755
Spill Date: 1994-11-21

HESS#32518 — ***2880 ATLANTIC AVENUE*** — ***W 1/4 - 1/2 (0.372 mi.)*** — ***AM272*** — ***782***
Spill Number/Closed Date: 9200248 / 1994-08-03
Site ID: 147618
Spill Date: 1992-04-07

ATLANTIC AVE AT CARL — ATLANTIC AVE AT CARL — ENE 1/4 - 1/2 (0.391 mi.) — 274 — 847
Spill Number/Closed Date: 9701786 / 2003-02-24
Site ID: 330576
Spill Date: 1997-05-10

208 BARBEY ST — 208 BARBEY ST — WNW 1/4 - 1/2 (0.444 mi.) — AO280 — 947
Spill Number/Closed Date: 9512002 / 1995-12-26
Site ID: 124613
Spill Date: 1995-12-22

223 & 227 RICHMOND S — ***223 RICHMOND ST*** — ***NNE 1/4 - 1/2 (0.444 mi.)*** — ***281*** — ***949***
Spill Number/Closed Date: 9303118 / 1993-06-09
Site ID: 187167
Spill Date: 1993-06-08

70 ELCON ST/BKLYN — 70 ELCON STREET — NNW 1/4 - 1/2 (0.453 mi.) — 285 — 959
Spill Number/Closed Date: 8910317 / 1992-12-08
Site ID: 68948
Spill Date: 1990-01-27

Not reported — ***180 ARLINGTON AVENUE*** — ***NW 1/4 - 1/2 (0.456 mi.)*** — ***AP286*** — ***960***

DRAFT

Spill Number/Closed Date: 9413591 / 1995-01-12
Site ID: 65678
Spill Date: 1995-01-12

187 ARLINGTON AVE/BK | 187 ARLINGTON AVENUE | NW 1/4 - 1/2 (0.468 mi.) | AP288 | 971
Spill Number/Closed Date: 9009774 / 1990-12-08
Site ID: 106791
Spill Date: 1990-12-08

MALDONDAO HOME - TTF | ***2849 FULTON STREET*** | ***WNW 1/4 - 1/2 (0.472 mi.)*** | ***AO289*** | ***972***
Spill Number/Closed Date: 0608616 / 2015-04-02
Site ID: 372626
Spill Date: 2006-10-26

P.S. 290 - BROOKLYN | ***135 SCHENCK AVENUE*** | ***WNW 1/4 - 1/2 (0.477 mi.)*** | ***AQ290*** | ***975***
Spill Number/Closed Date: 0610197 / 2007-02-26
Site ID: 374588
Spill Date: 2006-12-07

90 MCKINLEY AVE | ***90 MCKINLEY AVE*** | ***ENE 1/4 - 1/2 (0.477 mi.)*** | ***291*** | ***981***
Spill Number/Closed Date: 0001910 / 2003-03-21
Site ID: 123566
Spill Date: 2000-05-11

GASETERIA | 2820 ATLANTIC AVENUE | W 1/4 - 1/2 (0.479 mi.) | AS295 | 990
Spill Number/Closed Date: 9312952 / 2003-01-27
Spill Number/Closed Date: 9403819 / 2006-02-14
Site ID: 229957
Site ID: 229958
Spill Date: 1993-08-17
Spill Date: 1994-06-17

ANNA CORP REALITY | ***78 HIGHLAND PLACE*** | ***N 1/4 - 1/2 (0.488 mi.)*** | ***299*** | ***1006***
Spill Number/Closed Date: 0212208 / 2009-06-02
Site ID: 315891
Spill Date: 2003-03-12

CORNER OF W. 1ST ST | AND SCHENCK ST | WNW 1/4 - 1/2 (0.491 mi.) | AQ300 | 1028
Spill Number/Closed Date: 9906643 / 2000-03-07
Site ID: 120569
Spill Date: 1999-09-03

BLUE RIDGE FARMS | ***3301 ATLANTIC AVENUE*** | ***NE 1/4 - 1/2 (0.495 mi.)*** | ***AT303*** | ***1032***
Spill Number/Closed Date: 8805745 / 2003-03-04
Spill Number/Closed Date: 0101620 / 2007-09-19
Site ID: 235578
Site ID: 290367
Spill Date: 1988-10-05
Spill Date: 2001-05-11

207 HENDRIX ST./ST. | 207 HENDRIX ST. | W 1/4 - 1/2 (0.497 mi.) | AR305 | 1042
Spill Number/Closed Date: 8705786 / 1993-02-25
Site ID: 148832
Spill Date: 1987-10-08

Lower Elevation	Address	Direction / Distance	Map ID	Page

385 ESSEX STREET | ***385 ESSEX STREET*** | ***SSW 0 - 1/8 (0.100 mi.)*** | ***K98*** | ***204***
Spill Number/Closed Date: 9708809 / 1998-06-17
Site ID: 245641
Spill Date: 1997-10-22

398 LINWOOD ST | 398 LINWOOD ST | W 1/8 - 1/4 (0.131 mi.) | P142 | 299

DRAFT

Spill Number/Closed Date: 9412321 / 2003-02-13
Site ID: 153913
Spill Date: 1994-12-14

PRIVATE RESIDENCE — 172 MILLFORD ST — ESE 1/8 - 1/4 (0.156 mi.) — S160 — 389
Spill Number/Closed Date: 0312000 / 2004-03-04
Site ID: 257620
Spill Date: 2004-01-26

318 FOUNTAIN AVE — 318 FOUNTAIN AVE — SE 1/4 - 1/2 (0.410 mi.) — 275 — 848
Spill Number/Closed Date: 9303855 / 1993-06-25
Site ID: 112210
Spill Date: 1993-06-25

APT BUILDING — 2736 PITKIN AVE — E 1/4 - 1/2 (0.481 mi.) — 296 — 993
Spill Number/Closed Date: 1307476 / 2013-12-16
Site ID: 488145
Spill Date: 2013-10-21

SMITH RESIDENCE — 363 MONTAUK AVE — SSE 1/4 - 1/2 (0.488 mi.) — 298 — 1004
Spill Number/Closed Date: 0507203 / 2005-10-05
Site ID: 352562
Spill Date: 2005-09-14

Not reported — 1249 SUTTER AVENUE — ESE 1/4 - 1/2 (0.499 mi.) — AU307 — 1044
Spill Number/Closed Date: 0300827 / 2004-06-04
Spill Number/Closed Date: 9901190 / 2003-08-16
Site ID: 107549
Site ID: 190732
Spill Date: 2003-04-23
Spill Date: 1999-04-30

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 20 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
3100 ATLANTIC AVE LL	803 LIBERTY AVENUE	NNE 0 - 1/8 (0.045 mi.)	B43	95
Database: UST, Date of Government Version: 03/17/2025				
3100 ATLANTIC LLC	***55 BERRIMAN STREET***	***N 0 - 1/8 (0.080 mi.)***	***H77***	***164***
Database: UST, Date of Government Version: 03/17/2025				
3100 ATLANTIC LLC	62 ATKINS AVENUE	NNE 0 - 1/8 (0.089 mi.)	H86	185
Database: UST, Date of Government Version: 03/17/2025				
831 LIBERTY AVENUE	831 LIBERTY AVENUE	NE 0 - 1/8 (0.092 mi.)	F91	192
Database: UST, Date of Government Version: 03/17/2025				
ST RITA'S R.C. CHURC	275 SHEPHERD AVENUE	NNW 0 - 1/8 (0.098 mi.)	J97	202
Database: UST, Date of Government Version: 03/17/2025				
61 ATKINS AVENUE	***61 ATKINS AVENUE***	***NNE 0 - 1/8 (0.104 mi.)***	***H102***	***211***
Database: UST, Date of Government Version: 03/17/2025				
31 BERRIMAN STREET	31 BERRIMAN STREET	N 0 - 1/8 (0.118 mi.)	H123	268
Database: UST, Date of Government Version: 03/17/2025				

DRAFT

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
64 MONTAUK AVENUE	***64 MONTAUK AVENUE***	***NNE 0 - 1/8 (0.123 mi.)***	***O133***	***285***
Database: UST, Date of Government Version: 03/17/2025				
3100 ATLANTIC LLC	36 ATKINS AVENUE	N 0 - 1/8 (0.124 mi.)	H138	293
Database: UST, Date of Government Version: 03/17/2025				
33 ATKINS AVENUE	33 ATKINS AVENUE	NNE 1/8 - 1/4 (0.140 mi.)	O146	304
Database: UST, Date of Government Version: 03/17/2025				
36 MONTAUK AVENUE	36 MONTAUK AVENUE	NNE 1/8 - 1/4 (0.155 mi.)	O157	383
Database: UST, Date of Government Version: 03/17/2025				
ST RITAS YOUTH CENTE	260 SHEPHERD AVENUE	NNW 1/8 - 1/4 (0.156 mi.)	T163	393
Database: UST, Date of Government Version: 03/17/2025				
3100 ATLANTIC LLC	3104 ATLANTIC AVENUE	N 1/8 - 1/4 (0.167 mi.)	V170	409
Database: UST, Date of Government Version: 03/17/2025				
3126 ATLANTIC AVENUE	3126 ATLANTIC AVENUE	NNE 1/8 - 1/4 (0.187 mi.)	V187	448
Database: UST, Date of Government Version: 03/17/2025				
2969 ATLANTIC AVE	2969 ATLANTIC AVENUE	NW 1/8 - 1/4 (0.222 mi.)	X222	522
Database: UST, Date of Government Version: 03/17/2025				
ATLANTIC SERVICE STA	3123 ATLANTIC AVENUE	N 1/8 - 1/4 (0.223 mi.)	AF230	546
Database: UST, Date of Government Version: 03/17/2025				
FORMER KFC RESTAURAN	3143 ATLANTIC AVENUE	NNE 1/8 - 1/4 (0.245 mi.)	AH245	589
Database: UST, Date of Government Version: 03/17/2025				
ATLANTIC AVE. SERVIC	2950 ATLANTIC AVENUE	WNW 1/8 - 1/4 (0.250 mi.)	AK256	675
Database: UST, Date of Government Version: 03/17/2025				

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER GARONE BROS.	352 - 362 SHEPHERD A	WSW 0 - 1/8 (0.039 mi.)	D35	75
Database: UST, Date of Government Version: 03/17/2025				
2958 ATLANTIC AVENUE	2958 ATLANTIC AVENUE	WNW 1/8 - 1/4 (0.230 mi.)	AD241	582
Database: UST, Date of Government Version: 03/17/2025				

NY CBS UST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS UST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS UST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL FINISHING	465 LOGAN ST.	ESE 1/8 - 1/4 (0.249 mi.)	AJ251	612
Facility Status: 3				
Facility Status: 1				
Id/Status: 2-000162				
Tank Status: 1				

DRAFT

EXECUTIVE SUMMARY

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 03/17/2025 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INDUSTRIAL FINISHING	***465 LOGAN ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***AJ253***	***632***
Facility Status: Active				
CBS Number: 2-000162				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 14 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
P.S. 345 - BROOKLYN	111 BERRIMAN STREET	ENE 0 - 1/8 (0.012 mi.)	A6	19
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-355763				
MIKE'S HEAVY DUTY TO	816 LIBERTY AVENUE	ENE 0 - 1/8 (0.084 mi.)	F82	175
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-613180				
FOLLOWERS OF JESUS M	3065 ATLANTIC AVENUE	NNW 1/8 - 1/4 (0.184 mi.)	T183	440
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-610342				
KEY CAPITAL FUNDING	23 MONTAUK AVENUE	NNE 1/8 - 1/4 (0.185 mi.)	Y185	444
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-610935				
DYNAMIC AUTO CLINIC	3053 ATLANTIC AVENUE	NNW 1/8 - 1/4 (0.189 mi.)	T190	452
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-610270				
NEW GENESIS CHRISTIA	224 SHEPHERD AVENUE	NNW 1/8 - 1/4 (0.205 mi.)	205	489
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-114774				
670 LIBERTY AVE REPA	670 LIBERTY AVENUE	W 1/8 - 1/4 (0.212 mi.)	Z212	503
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-610204				
LOT 52,TAXBLOCK 3959	***3123 ATLANTIC AVENUE***	***N 1/8 - 1/4 (0.223 mi.)***	***AF227***	***532***
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-601367				
ATLANTIC AVE. SERVIC	2950 ATLANTIC AVENUE	WNW 1/8 - 1/4 (0.250 mi.)	AK259	699
Database: AST, Date of Government Version: 03/17/2025				
Facility Id: 2-452718				

Lower Elevation	Address	Direction / Distance	Map ID	Page
J. BORAH CO.	291 ESSEX STREET	NW 0 - 1/8 (0.086 mi.)	E83	177
Database: AST, Date of Government Version: 03/17/2025				

DRAFT

Facility Id: 2-608411

I.S. 302 - BROOKLYN Database: AST, Date of Government Version: 03/17/2025 Facility Id: 2-354589	350 LINWOOD STREET	WNW 1/8 - 1/4 (0.152 mi.)	R151	348
TAPIA AUTO REPAIR Database: AST, Date of Government Version: 03/17/2025 Facility Id: 2-605088	2437 PITKIN AVENUE	SSW 1/8 - 1/4 (0.156 mi.)	U165	398
R & O MGMT CORP Database: AST, Date of Government Version: 03/17/2025 Facility Id: 2-611368	785 BELMONT AVE	S 1/8 - 1/4 (0.201 mi.)	198	468
2958 ATLANTIC AVENUE Database: AST, Date of Government Version: 03/17/2025 Facility Id: 2-610301	2958 ATLANTIC AVENUE	WNW 1/8 - 1/4 (0.230 mi.)	AD240	580

NY TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the NY TANKS list, as provided by EDR, has revealed that there are 2 NY TANKS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VERIZON NEW YORK INC Database: TANKS, Date of Government Version: 03/17/2025 Facility Id: 2-344559 Site Status: Active	***862 LIBERTY AVENUE***	***ENE 1/8 - 1/4 (0.170 mi.)***	***W175***	***416***
TES AUTO SERVICE, IN Database: TANKS, Date of Government Version: 03/17/2025 Facility Id: 2-609249 Site Status: Active	***873 LIBERTY AVENUE***	***ENE 1/8 - 1/4 (0.183 mi.)***	***W182***	***438***

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 04/30/2025 has revealed that there are 3 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
3200 ATLANTIC AVENUE Site Code: 579723	***8 FOUNTAIN AVENUE AN***	***NE 1/4 - 1/2 (0.287 mi.)***	***AL266***	***710***
2840 ATLANTIC AVENUE Site Code: 544636	***2840 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.426 mi.)***	***277***	***857***
CHESTNUT COMMONS ATL Site Code: 571272	***110 DINSMORE PLACE***	***NE 1/4 - 1/2 (0.432 mi.)***	***AN278***	***906***

DRAFT

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 04/30/2025 has revealed that there are 3 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
3200 ATLANTIC AVENUE Site Code: 579723	***8 FOUNTAIN AVENUE AN***	***NE 1/4 - 1/2 (0.287 mi.)***	***AL266***	***710***
2840 ATLANTIC AVENUE Site Code: 544636	***2840 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.426 mi.)***	***277***	***857***
CHESTNUT COMMONS ATL Site Code: 571272	***110 DINSMORE PLACE***	***NE 1/4 - 1/2 (0.432 mi.)***	***AN278***	***906***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 14 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported Database: VCP NYC, Date of Government Version: 06/01/2025	***3051 ATLANTIC AVENUE***	***NNW 1/8 - 1/4 (0.183 mi.)***	***T181***	***435***
25 MILFORD STREET Database: VCP NYC, Date of Government Version: 06/01/2025	***25 MILFORD STREET***	***NE 1/8 - 1/4 (0.225 mi.)***	***AE231***	***559***
LOT 28,TAXBLOCK 4153 Database: VCP NYC, Date of Government Version: 06/01/2025	***23 MILFORD STREET***	***NE 1/8 - 1/4 (0.227 mi.)***	***AE235***	***568***
LOT 19,TAXBLOCK 4017 Database: VCP NYC, Date of Government Version: 06/01/2025	***2400 PITKIN AVENUE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AA237***	***575***
3294 ATLANTIC AVENUE Database: VCP NYC, Date of Government Version: 06/01/2025	***3192 ATLANTIC AVENUE***	***NNE 1/4 - 1/2 (0.273 mi.)***	***AL265***	***709***
LOT 30,TAXBLOCK 3998 Database: VCP NYC, Date of Government Version: 06/01/2025	***2337 PITKIN AVENUE***	***WSW 1/4 - 1/2 (0.320 mi.)***	***270***	***777***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 3989 Database: VCP NYC, Date of Government Version: 06/01/2025	***355 SHEPHERD AVENUE***	***SW 0 - 1/8 (0.016 mi.)***	***A12***	***30***
777 GLENMORE AVENUE Database: VCP NYC, Date of Government Version: 06/01/2025	***777 GLENMORE AVENUE***	***SW 0 - 1/8 (0.043 mi.)***	***D40***	***91***
LOT 13,TAXBLOCK 4006 Database: VCP NYC, Date of Government Version: 06/01/2025	***820 GLENMORE AVENUE***	***SE 0 - 1/8 (0.051 mi.)***	***C48***	***103***
LOT 28,TAXBLOCK 4005 Database: VCP NYC, Date of Government Version: 06/01/2025	***2501 PITKIN AVENUE***	***S 0 - 1/8 (0.110 mi.)***	***M111***	***230***
2437 PITKIN AVENUE Database: VCP NYC, Date of Government Version: 06/01/2025	***2437 PITKIN AVENUE***	***SSW 1/8 - 1/4 (0.156 mi.)***	***U164***	***398***
315 LINWOOD STREET Database: VCP NYC, Date of Government Version: 06/01/2025	***315 LINWOOD***	***NW 1/8 - 1/4 (0.173 mi.)***	***X178***	***433***

DRAFT

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 13,TAXBLOCK 4228	***2602 PITKIN AVENUE***	***ESE 1/4 - 1/2 (0.255 mi.)***	***AJ263***	***705***
Database: VCP NYC, Date of Government Version: 06/01/2025				
447 EUCLID AVENUE	***447 EUCLID AVENUE***	***E 1/4 - 1/2 (0.445 mi.)***	***282***	***951***
Database: VCP NYC, Date of Government Version: 06/01/2025				

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 04/30/2025 has revealed that there are 9 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
K - UNION STATION HO	***ATLANTIC AVE, ASHFOR***	***WNW 1/4 - 1/2 (0.253 mi.)***	***AK262***	***701***
Site Code: 57390				
3200 ATLANTIC AVENUE	***8 FOUNTAIN AVENUE AN***	***NE 1/4 - 1/2 (0.287 mi.)***	***AL266***	***710***
Site Code: 579723				
2864 ATLANTIC AVENUE	***2864 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.378 mi.)***	***AM273***	***840***
Site Code: 629738				
2840 ATLANTIC AVENUE	***2840 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.426 mi.)***	***277***	***857***
Site Code: 544636				
CHESTNUT COMMONS ATL	***110 DINSMORE PLACE***	***NE 1/4 - 1/2 (0.432 mi.)***	***AN278***	***906***
Site Code: 571272				
ATLANTIC CHESTNUT AF	***275 CHESTNUT ST***	***NE 1/4 - 1/2 (0.448 mi.)***	***AN283***	***952***
Site Code: 522944				
ATLANTIC CHESTNUT -	275 CHESTNUT STREET	NE 1/4 - 1/2 (0.448 mi.)	AN284	956
Site Code: 568005				

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER GARONE BROS A	352-362 SHEPHERD AVE	WSW 0 - 1/8 (0.039 mi.)	D32	67
Site Code: 625573				
1199 SUTTER AVENUE	***1199 SUTTER AVENUE***	***ESE 1/4 - 1/2 (0.421 mi.)***	***276***	***849***
Site Code: 465638				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 09/09/2024 has revealed that there

DRAFT

are 4 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
242 CHESTNUT STREET	***242 CHESTNUT STREET***	***NNE 1/4 - 1/2 (0.459 mi.)***	***AN287***	***964***
2827 ATLANTIC AVENUE	***2827 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.477 mi.)***	***AR292***	***984***
2817 ATLANTIC AVENUE	***2817 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.485 mi.)***	***AR297***	***999***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
PITKIN BERRIMAN SITE Cleanup Completion Date: 04/19/0018	2501 PITKIN AVENUE	S 0 - 1/8 (0.110 mi.)	M112	232

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/03/2025 has revealed that there are 18 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MANHOLE #4750 Spill Number/Closed Date: 0508732 / 2007-05-03 Site ID: 354377 Spill Date: 2005-10-20	LIBERTY AVE AND BERR	N 0 - 1/8 (0.022 mi.)	A15	36
TRANSFORMER MANHOLE Spill Number/Closed Date: 0100552 / 2001-04-18 Site ID: 331003 Spill Date: 2001-04-15	ATKINS AVE & LIBERTY	NE 0 - 1/8 (0.058 mi.)	F50	107
CARBUSTERS AUTO RECY Spill Number/Closed Date: 0551819 / 2009-10-08 Site ID: 361785 Spill Date: 2006-03-29	***60 BERRIMAN STREET***	***N 0 - 1/8 (0.070 mi.)***	***B65***	***140***
NYC DEP DERTA Spill Number/Closed Date: 1905730 / 2019-09-03 Site ID: 593775 Spill Date: 2019-09-02	***49 BERRIMAN ST***	***N 0 - 1/8 (0.088 mi.)***	***H85***	***183***
DRUM RUN (SIDE OF RO Spill Number/Closed Date: 2302739 / 2023-07-25 Site ID: 653601 Spill Date: 2023-07-05	MONTAUK AVE AND LIBE	ENE 0 - 1/8 (0.105 mi.)	F104	217
SOUTH WEST CRNER Spill Number/Closed Date: 0406087 / 2004-11-12 Site ID: 114857 Spill Date: 2004-09-02	LIBERTY AVE/MONTAUK	ENE 0 - 1/8 (0.107 mi.)	L108	225
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
PRIVATE RESIDENCE	355 SHEPHARD AVE	SW 0 - 1/8 (0.016 mi.)	A13	33

DRAFT

Spill Number/Closed Date: 0410456 / 2004-12-24 Site ID: 335541 Spill Date: 2004-12-20				
SHEPPARDS AUTO PARTS Spill Number/Closed Date: 9705843 / 2010-06-29 Site ID: 143269 Spill Date: 1997-08-14	352 SHEPHERD AVE	WSW 0 - 1/8 (0.039 mi.)	D36	77
CONSTRUCTION SITE Spill Number/Closed Date: 1906045 / 2019-09-17 Site ID: 594106 Spill Date: 2019-09-11	368 SHEPHERD AVE	SW 0 - 1/8 (0.043 mi.)	D41	92
MANHOLE #68329 Spill Number/Closed Date: 0409404 / 2005-05-18 Site ID: 334131 Spill Date: 2004-11-19	GLENMORE AVE / ATKIN	ESE 0 - 1/8 (0.062 mi.)	G55	119
NYC DEP Spill Number/Closed Date: 2210047 / 2023-05-08 Site ID: 649445 Spill Date: 2023-03-21	***394 SHEPHERD AVE***	***SSW 0 - 1/8 (0.068 mi.)***	***D60***	***129***
MANHOLE # 4748 Spill Number/Closed Date: 0601418 / 2008-01-10 Site ID: 363646 Spill Date: 2006-05-08	ESSEX STREET AND LIB	WNW 0 - 1/8 (0.075 mi.)	E67	146
MANHOLE # 67930 Spill Number/Closed Date: 0409636 / 2005-12-27 Site ID: 334434 Spill Date: 2004-11-29	GLEN MORE AVE/ESSEX	SW 0 - 1/8 (0.077 mi.)	D71	154
SPILL NUMBER 0302806 Spill Number/Closed Date: 0302806 / 2003-06-17 Site ID: 320395 Spill Date: 2003-06-16	281 ESSEX ST	NW 0 - 1/8 (0.093 mi.)	I92	194
VAULT # 67400 Spill Number/Closed Date: 0101761 / 2001-06-19 Site ID: 188910 Spill Date: 2001-05-15	GLENMORE AVE/MONTAUK	E 0 - 1/8 (0.108 mi.)	G110	228
MANHOLE 4747 Spill Number/Closed Date: 0004179 / 2001-10-17 Site ID: 309809 Spill Date: 2000-07-07	LIBERTY AV/LINWOOD S	W 0 - 1/8 (0.124 mi.)	N135	289
SPILL NUMBER 0003444 Spill Number/Closed Date: 0003444 / 2000-08-03 Site ID: 187978 Spill Date: 2000-06-20	GLENMORE AV/LINWOOD	WSW 0 - 1/8 (0.124 mi.)	P136	290
GLENMORE AV/LINWOOD Spill Number/Closed Date: 0005184 / 2003-05-14 Site ID: 187979 Spill Date: 2000-07-31	GLENMORE AV/LINWOOD	WSW 0 - 1/8 (0.124 mi.)	P137	291

DRAFT

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/02/2025 has revealed that there are 36 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004136933	***S/W/C LIBERTY AVE &***	***N 0 - 1/8 (0.022 mi.)***	***A17***	***39***
CON EDISON SERVICE B EPA ID:: NYP004533543	***LIBERTY AVE & BERRIM***	***N 0 - 1/8 (0.022 mi.)***	***A18***	***45***
CON ED - MH 3739 EPA ID:: NYP004009163	***LIBERTY AVE & ATKINS***	***NE 0 - 1/8 (0.058 mi.)***	***F51***	***109***
NYC DEP DERTA EPA ID:: NYP000975860	***49 BERRIMAN ST***	***N 0 - 1/8 (0.088 mi.)***	***H84***	***180***
CON EDISON MANHOLE 3 EPA ID:: NYP004235552	***MONTAUK AVE & LIBERT***	***ENE 0 - 1/8 (0.105 mi.)***	***F105***	***218***
CON EDISON EPA ID:: NYP004881468	***MONTAUK AVE & LIBERT***	***ENE 0 - 1/8 (0.105 mi.)***	***F107***	***222***
CON ED - MH 3741 EPA ID:: NYP004003802	***LIBERTY AVE & MILFOR***	***ENE 1/8 - 1/4 (0.154 mi.)***	***L154***	***367***
CON ED - MH 57244 EPA ID:: NYP004004164	***LIBERTY AVE & MILFOR***	***ENE 1/8 - 1/4 (0.154 mi.)***	***L155***	***375***
CON EDISON EPA ID:: NYP004204541	***LIBERTY AVE & MILFOR***	***ENE 1/8 - 1/4 (0.154 mi.)***	***L156***	***379***
MTA LIRR - ATLANTIC EPA ID:: NYR000255521	ATLANTIC AVE & ESSEX	NW 1/8 - 1/4 (0.171 mi.)	T176	418
CON EDISON EPA ID:: NYP004723680	***ATLANTIC AVE & ATKIN***	***N 1/8 - 1/4 (0.190 mi.)***	***V192***	***456***
CON EDISON SERVICE B EPA ID:: NYP004439006	***3027 ATLANTIC AVE***	***NNW 1/8 - 1/4 (0.198 mi.)***	***197***	***464***
CON EDISON - MANHOLE EPA ID:: NYP005125893	3144 ATLANTIC AVE	NNE 1/8 - 1/4 (0.211 mi.)	Y210	499
ATLANTIC AVE - NY - EPA ID:: NYD000816561	***3123 ATLANTIC AVE &***	***N 1/8 - 1/4 (0.223 mi.)***	***AF226***	***529***
ATLANTIC AVENUE INC EPA ID:: NYU005000286	***3123 ATLANTIC AVE***	***N 1/8 - 1/4 (0.223 mi.)***	***AF228***	***537***
CON EDISON SERVICE B EPA ID:: NYP004533527	422 CLEVELAND ST FRO	WSW 1/8 - 1/4 (0.227 mi.)	AG233	561
23 MILFORD STREET VC EPA ID:: NYR000265371	***23 MILFORD ST***	***NE 1/8 - 1/4 (0.227 mi.)***	***AE236***	***570***
CON ED MH 64858 EPA ID:: NYP004015509	***2950 ATLANTIC AVE***	***WNW 1/8 - 1/4 (0.250 mi.)***	***AK258***	***695***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	LIBERTY AVE & SHEPHE	NW 0 - 1/8 (0.031 mi.)	B23	53

DRAFT

EPA ID:: NYP004814063				
CON EDISON EPA ID:: NYP004814071	LIBERTY AVE & SHEPHE	NW 0 - 1/8 (0.031 mi.)	B24	56
777 GLENMORE AVE LLC EPA ID:: NYR000242859	***777 GLENMORE AVE***	***SW 0 - 1/8 (0.043 mi.)***	***D39***	***80***
NYC DEP EPA ID:: NYP003664794	***394 SHEPHERD AVE***	***SSW 0 - 1/8 (0.068 mi.)***	***D60***	***129***
CON EDISON EPA ID:: NYP004161295	***LIBERTY AVE & ESSEX***	***WNW 0 - 1/8 (0.075 mi.)***	***E69***	***149***
CON EDISON EPA ID:: NYP004539136	LIBERTY AVE & ESSEX	WNW 0 - 1/8 (0.075 mi.)	E70	152
CON EDISON EPA ID:: NYP004824732	***320 ESSEX ST***	***W 0 - 1/8 (0.078 mi.)***	***E74***	***158***
CON EDISON EPA ID:: NYP004539110	***728 LIBERTY AVE FRON***	***W 0 - 1/8 (0.094 mi.)***	***E94***	***197***
CON EDISON EPA ID:: NYP004820664	***166 MONTAUK AVE FRON***	***ESE 0 - 1/8 (0.111 mi.)***	***G115***	***254***
CON EDISON EPA ID:: NYP004884298	LIBERTY AVE & LINWOO	W 0 - 1/8 (0.121 mi.)	N128	277
CON EDISON EPA ID:: NYP004539094	LINWOOD ST & LIBERTY	W 0 - 1/8 (0.121 mi.)	N130	280
NYCTA - ELTON SUBSTA EPA ID:: NYD982739468	***ELTON ST & PITKIN AV***	***SW 1/8 - 1/4 (0.202 mi.)***	***AA199***	***470***
CON EDISON MANHOLE 5 EPA ID:: NYP004241329	***PITKIN AVE & ELTON S***	***SW 1/8 - 1/4 (0.202 mi.)***	***AA200***	***475***
CON ED - V 3742 EPA ID:: NYP004004289	***LIBERTY AVE & LOGAN***	***ENE 1/8 - 1/4 (0.203 mi.)***	***W203***	***482***
CON EDISON SERVICE B EPA ID:: NYP004417135	***BELMONT AVE & BERRIM***	***SSE 1/8 - 1/4 (0.209 mi.)***	***AC208***	***495***
CON EDISON EPA ID:: NYP004815706	814 BELMONT AVE	SSE 1/8 - 1/4 (0.215 mi.)	AC213	507
CON EDISON EPA ID:: NYP004769485	***ATLANTIC AVE & ELTON***	***WNW 1/8 - 1/4 (0.216 mi.)***	***AD215***	***510***
CON EDISON SERVICE B EPA ID:: NYP004570446	***510 LINWOOD ST***	***SSW 1/8 - 1/4 (0.230 mi.)***	***AB238***	***576***

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 6 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPILL NUMBER 9312952	2820 ATLANTIC AVENUE	W 1/4 - 1/2 (0.479 mi.)	AS293	989
GASETERIA	2820 ATLANTIC AVENUE	W 1/4 - 1/2 (0.479 mi.)	AS294	990

DRAFT

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPILL NUMBER 8805745	3301 ATLANTIC AVENUE	NE 1/4 - 1/2 (0.495 mi.)	AT301	1029
BLUE RIDGE FARMS INC	***3301 ATLANTIC AVENUE***	***NE 1/4 - 1/2 (0.495 mi.)***	***AT302***	***1030***

Lower Elevation	Address	Direction / Distance	Map ID	Page
GULF SERVICE STATION	1249 SUTTER AVENUE	ESE 1/4 - 1/2 (0.499 mi.)	AU306	1044
LOX SERVICE STATION	1249 SUTTER AVENUE	ESE 1/4 - 1/2 (0.499 mi.)	AU308	1052

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are 20 UST FINDER sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
803 LIBERTY AVENUE	803 LIBERTY AVENUE	NNE 0 - 1/8 (0.045 mi.)	B44	97
55 BERRIMAN STREET -	55 BERRIMAN STREET	N 0 - 1/8 (0.080 mi.)	H76	163
62 ATKINS AVENUE	62 ATKINS AVENUE	NNE 0 - 1/8 (0.089 mi.)	H87	187
831 LIBERTY AVENUE	831 LIBERTY AVENUE	NE 0 - 1/8 (0.092 mi.)	F90	191
ST RITA'S R.C.CHURCH	275 SHEPHERD AVENUE	NNW 0 - 1/8 (0.098 mi.)	J96	201
61 ATKINS AVENUE	61 ATKINS AVENUE	NNE 0 - 1/8 (0.104 mi.)	H101	210
31 BERRIMAN STREET	31 BERRIMAN STREET	N 0 - 1/8 (0.118 mi.)	H124	271
64 MONTAUK AVENUE	64 MONTAUK AVENUE	NNE 0 - 1/8 (0.123 mi.)	O134	288
36 ATKINS AVENUE	36 ATKINS AVENUE	N 0 - 1/8 (0.124 mi.)	H139	295
33 ATKINS AVENUE	33 ATKINS AVENUE	NNE 1/8 - 1/4 (0.140 mi.)	O145	303
36 MONTAUK AVENUE	36 MONTAUK AVENUE	NNE 1/8 - 1/4 (0.155 mi.)	O158	385
ST RITA'S SCHOOL	260 SHEPHERD AVENUE	NNW 1/8 - 1/4 (0.156 mi.)	T161	391
ST RITAS YOUTH CENTE	260 SHEPHERD AVENUE	NNW 1/8 - 1/4 (0.156 mi.)	T162	392
3104 ATLANTIC AVENUE	3104 ATLANTIC AVENUE	N 1/8 - 1/4 (0.167 mi.)	V171	411
3126 ATLANTIC AVENUE	3126 ATLANTIC AVENUE	NNE 1/8 - 1/4 (0.187 mi.)	V188	450
2969 ATLANTIC AVE	2969 ATLANTIC AVENUE	NW 1/8 - 1/4 (0.222 mi.)	X221	521
CYPRESS HILLS SERVIC	3123 ATLANTIC AVENUE	N 1/8 - 1/4 (0.223 mi.)	AF229	541
FORMER KFC RESTAURAN	3143 ATLANTIC AVENUE	NNE 1/8 - 1/4 (0.245 mi.)	AH246	597
ATLANTIC AVE. SERVIC	2950 ATLANTIC AVENUE	WNW 1/8 - 1/4 (0.250 mi.)	AK260	700

Lower Elevation	Address	Direction / Distance	Map ID	Page
2958 ATLANTIC AVENUE	2958 ATLANTIC AVENUE	WNW 1/8 - 1/4 (0.230 mi.)	AD242	585

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 06/02/2025 has revealed that there are 37 E MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	778 LIBERTY AVE	NNW 0 - 1/8 (0.007 mi.)	A5	17

DRAFT

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYC DEPT OF EDUCATIO	***111 BERRIMAN ST***	***ENE 0 - 1/8 (0.012 mi.)***	***A7***	***22***
NYC DEP DERTA	***49 BERRIMAN ST***	***N 0 - 1/8 (0.088 mi.)***	***H84***	***180***
CONSOLIDATED EDISON	39 BERRIMAN STREET	N 0 - 1/8 (0.105 mi.)	H103	215
CON EDISON	113 MONTAUK AVE	ENE 0 - 1/8 (0.114 mi.)	L119	262
CON EDISON - COMPANY	OPP OF 87 MONTAUK AV	NE 0 - 1/8 (0.124 mi.)	L140	296
CON EDISON - COMPANY	3065 ATLANTIC AVE	NNW 1/8 - 1/4 (0.184 mi.)	T184	442
CONSOLIDATED EDISON	374 CLEVELAND ST	W 1/8 - 1/4 (0.212 mi.)	Z211	502
CON EDISON/ ATTN: BR	2406 PITKIN AVE	SW 1/8 - 1/4 (0.222 mi.)	AA224	526
23 MILFORD STREET VC	***23 MILFORD ST***	***NE 1/8 - 1/4 (0.227 mi.)***	***AE236***	***570***
CON EDISON - COMPANY	212 HIGHLAND PL	N 1/8 - 1/4 (0.246 mi.)	AI247	600
CON EDISON - CLEVELA	***2950 ATLANTIC AVE***	***WNW 1/8 - 1/4 (0.250 mi.)***	***AK257***	***676***

Lower Elevation	Address	Direction / Distance	Map ID	Page
777 GLENMORE AVE LLC	***777 GLENMORE AVE***	***SW 0 - 1/8 (0.043 mi.)***	***D39***	***80***
CON EDISON - COMPANY	750 LIBERTY AVE	WNW 0 - 1/8 (0.057 mi.)	E49	105
CON EDISON	737 LIBERTY AVE	WNW 0 - 1/8 (0.090 mi.)	E89	189
CON EDISON/ ATTN: QU	729 LIBERTY AVE	WNW 0 - 1/8 (0.104 mi.)	E99	207
CON EDISON	729 LIBERTY AVE	WNW 0 - 1/8 (0.104 mi.)	E100	209
CON EDISON	720 LIBERTY AVE	W 0 - 1/8 (0.114 mi.)	N118	260
NYCT - SHEPHERD AVEN	SHEPHERD AVE & PITKI	S 0 - 1/8 (0.121 mi.)	M132	283
CON ED COMPANY OF NY	2531 PITKIN AVE	SE 1/8 - 1/4 (0.128 mi.)	Q141	297
CON EDISON	2488 PITKIN AVE	S 1/8 - 1/4 (0.134 mi.)	M143	300
CON EDISON/ ATTN: QU	2538 PITKIN AVE	SE 1/8 - 1/4 (0.151 mi.)	Q150	346
IS 302K SCHOOL	***350 LINWOOD ST***	***WNW 1/8 - 1/4 (0.152 mi.)***	***R152***	***351***
CON EDISON/ ATTN: QU	2540 PITKIN AVE	SE 1/8 - 1/4 (0.153 mi.)	Q153	365
CON EDISON - BROOKLY	2446 PITKIN AVE	SSW 1/8 - 1/4 (0.158 mi.)	U166	401
CON ED COMPANY OF NY	2561 PITKINS AVE	ESE 1/8 - 1/4 (0.164 mi.)	S167	402
CON EDISON - BROOKLY	418 ESSEX ST	SSW 1/8 - 1/4 (0.168 mi.)	U174	415
B&B URBAN LLC - 315	***315 LINWOOD STREET***	***NW 1/8 - 1/4 (0.173 mi.)***	***X177***	***421***
CON EDISON - EXTERIO	2564 PITKIN AVE	ESE 1/8 - 1/4 (0.186 mi.)	186	446
CON EDISON - COMPANY	OPP OF 24-28 PITKIN	SSW 1/8 - 1/4 (0.187 mi.)	U189	451
CON ED COMPANY OF NY	680 LIBERTY AVE	W 1/8 - 1/4 (0.192 mi.)	Z195	461
CON ED COMPANY OF NY	432 LOGAN ST	E 1/8 - 1/4 (0.198 mi.)	S196	463
CON EDISON - COMPANY	LOGAN ST & LIBERTY A	ENE 1/8 - 1/4 (0.203 mi.)	W202	480
CON EDISON - COMPANY	2976 ATLANTIC AVE	WNW 1/8 - 1/4 (0.208 mi.)	X206	492
CON EDISON - EXTERIO	ATKINS AVE & BELMONT	SSE 1/8 - 1/4 (0.216 mi.)	AC214	509
CON EDISON - COMPANY	2972 ATLANTIC AVE	WNW 1/8 - 1/4 (0.217 mi.)	AD218	516
INDUSTRIAL FINISHING	***465 LOGAN ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***AJ254***	***635***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 06/03/2025 has revealed that there is 1 NY DRYCLEANERS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NARVAEZ CLEANERS Facility Id: 2-6105-00346	2458 PITKIN AVE	SSW 1/8 - 1/4 (0.144 mi.)	K148	308

DRAFT

EXECUTIVE SUMMARY

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 05/30/2025 has revealed that there are 42 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	***114 BERRIMAN STREET***	***0 - 1/8 (0.000 mi.)***	***A2***	***11***
LOT 24,TAXBLOCK 3989	***112 BERRIMAN STREET***	***0 - 1/8 (0.000 mi.)***	***A3***	***13***
LOT 14,TAXBLOCK 3989	***778 LIBERTY AVENUE***	***NNW 0 - 1/8 (0.007 mi.)***	***A4***	***15***
LOT 9,TAXBLOCK 3989	***339 SHEPHERD AVENUE***	***WNW 0 - 1/8 (0.012 mi.)***	***A10***	***28***
LOT 16,TAXBLOCK 3989	LIBERTY AVENUE	NNW 0 - 1/8 (0.014 mi.)	A11	30
LOT 57,TAXBLOCK 3973	***787 LIBERTY AVENUE***	***N 0 - 1/8 (0.028 mi.)***	***B22***	***51***
LOT 58,TAXBLOCK 3973	***785 LIBERTY AVENUE***	***N 0 - 1/8 (0.032 mi.)***	***B29***	***62***
LOT 55,TAXBLOCK 3973	BERRIMAN STREET	N 0 - 1/8 (0.048 mi.)	B47	102
LOT 53,TAXBLOCK 3973	***68 BERRIMAN STREET***	***N 0 - 1/8 (0.058 mi.)***	***B52***	***113***
LOT 52,TAXBLOCK 3973	***66 BERRIMAN STREET***	***N 0 - 1/8 (0.062 mi.)***	***B56***	***121***
LOT 50,TAXBLOCK 3973	BERRIMAN STREET	N 0 - 1/8 (0.070 mi.)	B64	140
Not reported	***118 ATKINS AVENUE***	***ENE 0 - 1/8 (0.080 mi.)***	***F75***	***161***
LOT 46,TAXBLOCK 3973	***46 BERRIMAN STREET***	***N 0 - 1/8 (0.084 mi.)***	***H81***	***173***
LOT 15,TAXBLOCK 3992	***844 LIBERTY AVENUE***	***ENE 0 - 1/8 (0.121 mi.)***	***L126***	***273***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 34,TAXBLOCK 3989	795 GLENMORE AVENUE	SSW 0 - 1/8 (0.012 mi.)	A9	27
LOT 1,TAXBLOCK 3989	***355 SHEPHERD AVENUE***	***SW 0 - 1/8 (0.016 mi.)***	***A12***	***30***
LOT 12,TAXBLOCK 3989	***772 LIBERTY AVENUE***	***NW 0 - 1/8 (0.018 mi.)***	***A14***	***34***
LOT 36,TAXBLOCK 3989	793 GLENMORE AVENUE	SSW 0 - 1/8 (0.022 mi.)	A19	48
LOT 10,TAXBLOCK 3989	***770 LIBERTY AVENUE***	***NW 0 - 1/8 (0.022 mi.)***	***A21***	***48***
LOT 17,TAXBLOCK 4005	GLENMORE AVENUE	SSE 0 - 1/8 (0.038 mi.)	C30	64
LOT 34,TAXBLOCK 3988	***366 SHEPHERD AVENUE***	***SW 0 - 1/8 (0.039 mi.)***	***D31***	***65***
LOT 28,TAXBLOCK 3988	***352 SHEPHERD AVENUE***	***WSW 0 - 1/8 (0.039 mi.)***	***D33***	***72***
LOT 35,TAXBLOCK 3988	***368 SHEPHERD AVENUE***	***SW 0 - 1/8 (0.043 mi.)***	***D42***	***93***
LOT 16,TAXBLOCK 4005	***804 GLENMORE AVENUE***	***SSE 0 - 1/8 (0.047 mi.)***	***C45***	***98***
Not reported	***810 GLENMORE AVENUE***	***SE 0 - 1/8 (0.048 mi.)***	***C46***	***100***
LOT 13,TAXBLOCK 4006	***820 GLENMORE AVENUE***	***SE 0 - 1/8 (0.051 mi.)***	***C48***	***103***
LOT 19,TAXBLOCK 4005	***148 BERRIMAN STREET***	***SSE 0 - 1/8 (0.058 mi.)***	***C53***	***115***
LOT 56,TAXBLOCK 3972	***749 LIBERTY AVENUE***	***WNW 0 - 1/8 (0.060 mi.)***	***E54***	***117***
Not reported	***390 SHEPHERD AVENUE***	***SSW 0 - 1/8 (0.063 mi.)***	***D57***	***123***
LOT 20,TAXBLOCK 4005	***152 BERRIMAN STREET***	***SSE 0 - 1/8 (0.063 mi.)***	***C58***	***125***
Not reported	***392 SHEPHERD AVENUE***	***SSW 0 - 1/8 (0.067 mi.)***	***D59***	***127***
LOT 21,TAXBLOCK 4005	***154 BERRIMAN STREET***	***SSE 0 - 1/8 (0.069 mi.)***	***C61***	***135***
LOT 57,TAXBLOCK 3972	***745 LIBERTY AVENUE***	***NW 0 - 1/8 (0.071 mi.)***	***E66***	***144***
LOT 17,TAXBLOCK 3987	***742 LIBERTY AVENUE***	***WNW 0 - 1/8 (0.081 mi.)***	***E78***	***168***
LOT 45,TAXBLOCK 3971	***298 ESSEX STREET***	***WNW 0 - 1/8 (0.095 mi.)***	***E95***	***199***
LOT 44,TAXBLOCK 3971	***294 ESSEX STREET***	***WNW 0 - 1/8 (0.108 mi.)***	***I109***	***226***
LOT 28,TAXBLOCK 4005	***2501 PITKIN AVENUE***	***S 0 - 1/8 (0.110 mi.)***	***M111***	***230***
LOT 39,TAXBLOCK 3971	***278 ESSEX STREET***	***NW 0 - 1/8 (0.113 mi.)***	***I116***	***256***
LOT 53,TAXBLOCK 3971	***725 LIBERTY AVENUE***	***WNW 0 - 1/8 (0.113 mi.)***	***N117***	***258***
Not reported	***282 ESSEX STREET***	***WNW 0 - 1/8 (0.115 mi.)***	***I120***	***264***
LOT 41,TAXBLOCK 3971	***286 ESSEX STREET***	***WNW 0 - 1/8 (0.116 mi.)***	***I121***	***266***
LOT 54,TAXBLOCK 3971	LIBERTY AVENUE	WNW 0 - 1/8 (0.117 mi.)	N122	268

DRAFT

EXECUTIVE SUMMARY

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are 57 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004533543	LIBERTY AVE & BERRIM	N 0 - 1/8 (0.022 mi.)	A16	38
CON EDISON - MANHOLE EPA ID: NYP004136933	***S/W/C LIBERTY AVE &***	***N 0 - 1/8 (0.022 mi.)***	***A17***	***39***
CON ED - MH 3739 EPA ID: NYP004009163	***LIBERTY AVE & ATKINS***	***NE 0 - 1/8 (0.058 mi.)***	***F51***	***109***
NYC DEP DERTA EPA ID: NYP000975860	***49 BERRIMAN ST***	***N 0 - 1/8 (0.088 mi.)***	***H85***	***183***
CON EDISON MANHOLE 3 EPA ID: NYP004235552	***MONTAUK AVE & LIBERT***	***ENE 0 - 1/8 (0.105 mi.)***	***F105***	***218***
CON ED EPA ID: NYP004881468	MONTAUK AVE & LIBERT	ENE 0 - 1/8 (0.105 mi.)	F106	221
CON ED - MH 3741 EPA ID: NYP004003802	***LIBERTY AVE & MILFOR***	***ENE 1/8 - 1/4 (0.154 mi.)***	***L154***	***367***
CON ED - MH 57244 EPA ID: NYP004004164	***LIBERTY AVE & MILFOR***	***ENE 1/8 - 1/4 (0.154 mi.)***	***L155***	***375***
CON EDISON EPA ID: NYP004204541	***LIBERTY AVE & MILFOR***	***ENE 1/8 - 1/4 (0.154 mi.)***	***L156***	***379***
CON EDISON - SERVICE EPA ID: NYP005175260	***3104 ATLANTIC AVE***	***N 1/8 - 1/4 (0.167 mi.)***	***V172***	***412***
CON EDISON - MANHOLE EPA ID: NYP005188400	ATLANTIC AVE & BERRI	N 1/8 - 1/4 (0.173 mi.)	V180	434
CON EDISON EPA ID: NYP004723680	ATLANTIC AVE & ATKIN	N 1/8 - 1/4 (0.190 mi.)	V193	458
CON EDISON EPA ID: NYP004867610	3130 ATLANTIC AVE	NNE 1/8 - 1/4 (0.190 mi.)	Y194	460
CON EDISON SERVICE B EPA ID: NYP004439006	***3027 ATLANTIC AVE***	***NNW 1/8 - 1/4 (0.198 mi.)***	***197***	***464***
CON EDISON EPA ID: NYP005125893	3144 ATLANTIC AVE	NNE 1/8 - 1/4 (0.211 mi.)	Y209	498
CON EDISON EPA ID: NYP004599338	390 ELTON STREET	SW 1/8 - 1/4 (0.217 mi.)	AA219	517
CON EDISON EPA ID: NYP004593950	2406 PITKIN AV	SW 1/8 - 1/4 (0.222 mi.)	AA225	527
CON EDISON EPA ID: NYP004602520	FRONT OF 224 HIGHLAN	N 1/8 - 1/4 (0.227 mi.)	AF232	560
CON EDISON EPA ID: NYP004696233 EPA ID: NYP004533527 EPA ID: NYP004708707	422 CLEVELAND ST	WSW 1/8 - 1/4 (0.227 mi.)	AG234	564
CON EDISON	FRONT OF 681 GLENMOR	WSW 1/8 - 1/4 (0.233 mi.)	AG243	586

DRAFT

EPA ID: NYP004614160				
CON EDISON EPA ID: NYP004602546	FO 212 HIGHLAND PL	N 1/8 - 1/4 (0.246 mi.)	AI248	602
CONSOLIDATED EDISON EPA ID: NYD982273831	***2950 ATLANTIC AVE***	***WNW 1/8 - 1/4 (0.250 mi.)***	***AK255***	***660***
CON EDISON - CLEVELA EPA ID: NYD982272841	***2950 ATLANTIC AVE***	***WNW 1/8 - 1/4 (0.250 mi.)***	***AK257***	***676***
CON ED MH 64858 EPA ID: NYP004015509	***2950 ATLANTIC AVE***	***WNW 1/8 - 1/4 (0.250 mi.)***	***AK258***	***695***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON ED EPA ID: NYP004814063	LIBERTY AVE & SHEPHE	NW 0 - 1/8 (0.031 mi.)	B26	59
CON EDISON EPA ID: NYP004814071	LIBERTY AVE & SHEPHE	NW 0 - 1/8 (0.031 mi.)	B27	59
777 GLENMORE AVE LLC EPA ID: NYR000242859	777 GLENMORE AVE	SW 0 - 1/8 (0.043 mi.)	D38	79
NYC DEP EPA ID: NYP003664794	***394 SHEPHERD AVE***	***SSW 0 - 1/8 (0.068 mi.)***	***D60***	***129***
CON EDISON EPA ID: NYP004701181	156 BERRIMON ST	S 0 - 1/8 (0.069 mi.)	C62	137
CON EDISON EPA ID: NYP004702874	156 BERRIMAN	S 0 - 1/8 (0.069 mi.)	C63	138
CON EDISON EPA ID: NYP004539136	LIBERTY AVE & ESSEX	WNW 0 - 1/8 (0.075 mi.)	E68	147
CON EDISON EPA ID: NYP004161295	***LIBERTY AVE & ESSEX***	***WNW 0 - 1/8 (0.075 mi.)***	***E69***	***149***
CON ED EPA ID: NYP004824732	320 ESSEX ST	W 0 - 1/8 (0.078 mi.)	E72	156
CON EDISON EPA ID: NYP004598546	OPP 761 GLENMORE AVE	WSW 0 - 1/8 (0.082 mi.)	D79	170
CON EDISON EPA ID: NYP004598520	330 ESSEX ST	W 0 - 1/8 (0.083 mi.)	E80	171
CON EDISON EPA ID: NYP004539110	728 LIBERTY AVE FRON	W 0 - 1/8 (0.094 mi.)	E93	195
CON EDISON EPA ID: NYP004820664	166 MONTAUK AVE FRON	ESE 0 - 1/8 (0.111 mi.)	G113	251
CON EDISON EPA ID: NYP004539094	LINWOOD ST & LIBERTY	W 0 - 1/8 (0.121 mi.)	N129	279
NYCT - SHEPHERD AVEN EPA ID: NYR000225391	SHEPHERD AVE & PITKI	S 0 - 1/8 (0.121 mi.)	M131	282
CON EDISON EPA ID: NYP004598587	734 GLENMORE AVE	WSW 1/8 - 1/4 (0.143 mi.)	P147	306
NARVAEZ CLEANERS EPA ID: NYD981079254	***2458 PITKIN AVE***	***SSW 1/8 - 1/4 (0.144 mi.)***	***K149***	***328***
IS 302K SCHOOL	***350 LINWOOD ST***	***WNW 1/8 - 1/4 (0.152 mi.)***	***R152***	***351***

DRAFT

EPA ID: NYR000176511				
CON EDISON EPA ID: NYP004598561	SEC GLENMORE & ELTON	WSW 1/8 - 1/4 (0.167 mi.)	P169	408
CON EDISON - SERVICE EPA ID: NYP004925473	418 ESSEX ST	SSW 1/8 - 1/4 (0.168 mi.)	U173	414
B&B URBAN LLC - 315 EPA ID: NYR000237008	315 LINWOOD STREET	NW 1/8 - 1/4 (0.173 mi.)	X179	434
NYCTA - ELTON SUBSTA EPA ID: NYD982739468	***ELTON ST & PITKIN AV***	***SW 1/8 - 1/4 (0.202 mi.)***	***AA199***	***470***
CON EDISON MANHOLE 5 EPA ID: NYP004241329	***PITKIN AVE & ELTON S***	***SW 1/8 - 1/4 (0.202 mi.)***	***AA200***	***475***
NYNEX EPA ID: NYP000914846	LOGAN ST & LIBERTY A	ENE 1/8 - 1/4 (0.203 mi.)	W201	479
CON ED - V 3742 EPA ID: NYP004004289	***LIBERTY AVE & LOGAN***	***ENE 1/8 - 1/4 (0.203 mi.)***	***W203***	***482***
CONSOLIDATED EDISON EPA ID: NYP004126991	LOGAN & GLENMORE MH6	E 1/8 - 1/4 (0.205 mi.)	204	486
CON EDISON EPA ID: NYP004593711	496 LINWOOD ST	SSW 1/8 - 1/4 (0.208 mi.)	AB207	494
CON EDISON SERVICE B EPA ID: NYP004417135	***BELMONT AVE & BERRIM***	***SSE 1/8 - 1/4 (0.209 mi.)***	***AC208***	***495***
CON EDISON EPA ID: NYP004769485	ATLANTIC AVE & ELTON	WNW 1/8 - 1/4 (0.216 mi.)	AD216	513
CON EDISON EPA ID: NYP004570446	510 LINWOOD ST	SSW 1/8 - 1/4 (0.230 mi.)	AB239	579
CON EDISON EPA ID: NYP004590794	408 ELTON ST	SW 1/8 - 1/4 (0.238 mi.)	AA244	587
INDUSTRIAL FINISHING EPA ID: NYD001303205	***465 LOGAN STREET***	***ESE 1/8 - 1/4 (0.249 mi.)***	***AJ252***	***622***
INDUSTRIAL FINISHING EPA ID: NYP010000511	***465 LOGAN ST***	***ESE 1/8 - 1/4 (0.249 mi.)***	***AJ253***	***632***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 9 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004723680	ATLANTIC AVE & ATKIN	N 1/8 - 1/4 (0.190 mi.)	V191	455

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004814071	LIBERTY AVE & SHEPHE	NW 0 - 1/8 (0.031 mi.)	B25	58
CON EDISON EPA Id: NYP004814063	LIBERTY AVE & SHEPHE	NW 0 - 1/8 (0.031 mi.)	B28	61
NYC DEP	***394 SHEPHERD AVE***	***SSW 0 - 1/8 (0.068 mi.)***	***D60***	***129***

DRAFT

EPA Id: NYP003664794				
CON EDISON EPA Id: NYP004824732	320 ESSEX ST	W 0 - 1/8 (0.078 mi.)	E73	157
CON EDISON EPA Id: NYP004820664	166 MONTAUK AVE FRON	ESE 0 - 1/8 (0.111 mi.)	G114	253
CON EDISON EPA Id: NYP004884298	LIBERTY AVE & LINWOO	W 0 - 1/8 (0.121 mi.)	N127	276
CON EDISON EPA Id: NYP004769485	ATLANTIC AVE & ELTON	WNW 1/8 - 1/4 (0.216 mi.)	AD217	514
INDUSTRIAL FINISHING EPA Id: NYD001303205	465 LOGAN STREET	ESE 1/8 - 1/4 (0.249 mi.)	AJ250	605

NY NYC OER: Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

A review of the NY NYC OER list, as provided by EDR, and dated 06/01/2025 has revealed that there are 34 NY NYC OER sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
790 LIBERTY AVE	790 LIBERTY AVE	N 0 - 1/8 (0.012 mi.)	A8	27
Not reported	***3051 ATLANTIC AVENUE***	***NNW 1/8 - 1/4 (0.183 mi.)***	***T181***	***435***
LOT 25,TAXBLOCK 4153	***29 MILFORD STREET***	***NE 1/8 - 1/4 (0.218 mi.)***	***AE220***	***519***
25 MILFORD STREET	***25 MILFORD STREET***	***NE 1/8 - 1/4 (0.225 mi.)***	***AE231***	***559***
LOT 28,TAXBLOCK 4153	***23 MILFORD STREET***	***NE 1/8 - 1/4 (0.227 mi.)***	***AE235***	***568***
LOT 19,TAXBLOCK 4017	***2400 PITKIN AVENUE***	***SW 1/8 - 1/4 (0.228 mi.)***	***AA237***	***575***
3294 ATLANTIC AVENUE	***3192 ATLANTIC AVENUE***	***NNE 1/4 - 1/2 (0.273 mi.)***	***AL265***	***709***
LOT 30,TAXBLOCK 3998	***2337 PITKIN AVENUE***	***WSW 1/4 - 1/2 (0.320 mi.)***	***270***	***777***
2864 ATLANTIC AVENUE	***2864 ATLANTIC AVENUE***	***W 1/4 - 1/2 (0.378 mi.)***	***AM273***	***840***
2862 FULTON STREET	2862 FULTON STREET	WNW 1/4 - 1/2 (0.441 mi.)	AO279	947
LOT 55,TAXBLOCK 3933	***2795 FULTON STREET***	***WNW 1/2 - 1 (0.569 mi.)***	***AV309***	***1053***
LOT 18,TAXBLOCK 3946	***2776 FULTON STREET***	***W 1/2 - 1 (0.592 mi.)***	***AV310***	***1056***
LOT 15,TAXBLOCK 3690	***2738 ATLANTIC AVENUE***	***W 1/2 - 1 (0.644 mi.)***	***311***	***1058***
Not reported	***2718 FULTON STREET***	***W 1/2 - 1 (0.702 mi.)***	***AW312***	***1061***
2700 ATLANTIC AVENUE	***2700 ATLANTIC AVENUE***	***W 1/2 - 1 (0.718 mi.)***	***314***	***1067***
2701-2715 FULTON STR	***2701-2715 FULTON STR***	***W 1/2 - 1 (0.740 mi.)***	***AW316***	***1068***
157 NEW JERSEY AVENU	***157 NEW JERSEY AVENU***	***W 1/2 - 1 (0.779 mi.)***	***317***	***1069***
2667 FULTON STREET	***2667 FULTON STREET***	***W 1/2 - 1 (0.806 mi.)***	***318***	***1069***
EXXON DIV OF CFI #70	***225 PENNSYLVANIA AVE***	***WSW 1/2 - 1 (0.824 mi.)***	***320***	***1086***
Not reported	***184 PENNSYLVANIA AVE***	***WSW 1/2 - 1 (0.850 mi.)***	***321***	***1095***
Not reported	***461 NEW JERSEY AVENU***	***SW 1/2 - 1 (0.859 mi.)***	***323***	***1117***
50 PENN LLC	***2618 FULTON ST***	***W 1/2 - 1 (0.871 mi.)***	***324***	***1119***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 3989	***355 SHEPHERD AVENUE***	***SW 0 - 1/8 (0.016 mi.)***	***A12***	***30***
352-362 SHEPHERD AVE	352-362 SHEPHERD AVE	WSW 0 - 1/8 (0.039 mi.)	D34	74
777 GLENMORE AVENUE	***777 GLENMORE AVENUE***	***SW 0 - 1/8 (0.043 mi.)***	***D40***	***91***
LOT 13,TAXBLOCK 4006	***820 GLENMORE AVENUE***	***SE 0 - 1/8 (0.051 mi.)***	***C48***	***103***
LOT 28,TAXBLOCK 4005	***2501 PITKIN AVENUE***	***S 0 - 1/8 (0.110 mi.)***	***M111***	***230***
2437 PITKIN AVENUE	***2437 PITKIN AVENUE***	***SSW 1/8 - 1/4 (0.156 mi.)***	***U164***	***398***
315 LINWOOD STREET	***315 LINWOOD***	***NW 1/8 - 1/4 (0.173 mi.)***	***X178***	***433***
LOT 13,TAXBLOCK 4228	***2602 PITKIN AVENUE***	***ESE 1/4 - 1/2 (0.255 mi.)***	***AJ263***	***705***
447 EUCLID AVENUE	***447 EUCLID AVENUE***	***E 1/4 - 1/2 (0.445 mi.)***	***282***	***951***

DRAFT

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	***876 LIVONIA AVENUE***	***SSW 1/2 - 1 (0.708 mi.)***	***AX313***	***1064***
691-715 NEW LOTS AVE	691-715 NEW LOTS AVE	SSW 1/2 - 1 (0.726 mi.)	AX315	1067
LOT 54,TAXBLOCK 4151	***3513 ATLANTIC AVENUE***	***NE 1/2 - 1 (0.823 mi.)***	***319***	***1070***

NY MGP: From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

A review of the NY MGP list, as provided by EDR, and dated 02/28/2025 has revealed that there is 1 NY MGP site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
K - UNION STATION HO	***ATLANTIC AVE, ASHFOR***	***WNW 1/4 - 1/2 (0.253 mi.)***	***AK262***	***701***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UNION STATION (CITIZ	ATLANTIC AVE., ASHFO	WNW 1/4 - 1/2 (0.253 mi.)	AK261	701

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there is 1 EDR Hist Auto site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHEPHERD AVE GARAGE	352-362 SHEPHERD AV	WSW 0 - 1/8 (0.039 mi.)	D37	79

DRAFT

EXECUTIVE SUMMARY

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
D&J CLEANERS	770 LIBERTY AVE	NW 0 - 1/8 (0.022 mi.)	A20	48

DRAFT

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 3 records.

Site Name	Database(s)
SPRING CREEK/GATEWAY ESTATES	NY HSWDS
UNION STATION (CITIZENS BRANCH)	NY VCP
BELMONT STATION	NY VCP

DRAFT

OVERVIEW MAP - 08102930.2R



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

County Boundary

Pipelines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 98-114 Berriman Street Development	CLIENT: Haley & Aldrich, Inc.
ADDRESS: 98 Berriman Street Brooklyn NY 11208	CONTACT: Kaitlyn Moses
LAT/LONG: 40.67609 / 73.880628	INQUIRY #: 08102930.2r DATE: September 09, 2025 3:56 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 08102930.2R



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

0 1/16 1/8 1/4 Miles

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	98-114 Berriman Street Development	CLIENT:	Haley & Aldrich, Inc.
ADDRESS:	98 Berriman Street Brooklyn NY 11208	CONTACT: INQUIRY #:	Kaitlyn Moses 08102930.2r
LAT/LONG:	40.67609 / 73.880628	DATE:	September 09, 2025 4:00 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	1	NR	NR	1
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	4	NR	NR	NR	4
RCRA-SQG	0.250		1	0	NR	NR	NR	1
RCRA-VSQG	0.250		0	1	NR	NR	NR	1
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	0	2	4	NR	6
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		1	0	1	NR	NR	2
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

DRAFT

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		6	8	23	NR	NR	37
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		10	10	NR	NR	NR	20
NY CBS UST	0.250		0	1	NR	NR	NR	1
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250		3	11	NR	NR	NR	14
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	2	NR	NR	NR	2
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	3	NR	NR	3
NY INST CONTROL	0.500		0	0	3	NR	NR	3
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		4	6	4	NR	NR	14
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		1	0	8	NR	NR	9
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		1	0	3	NR	NR	4
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

DRAFT

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		18	NR	NR	NR	NR	18
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		17	19	NR	NR	NR	36
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0

DRAFT

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	TP		NR	NR	NR	NR	NR	0
UST FINDER RELEASE	0.500		0	0	6	NR	NR	6
UST FINDER	0.250		9	11	NR	NR	NR	20
E MANIFEST	0.250		13	24	NR	NR	NR	37
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	1	NR	NR	NR	1
NY E DESIGNATION	0.125	1	42	NR	NR	NR	NR	43
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		21	36	NR	NR	NR	57
NJ MANIFEST	0.250		6	3	NR	NR	NR	9
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY NYC OER	1.000		6	7	6	15	NR	34
NY MGP	1.000		0	0	1	0	NR	1
NY ILI	0.500		0	0	0	NR	NR	0
NY NYC LAND USE	TP	1	NR	NR	NR	NR	NR	1
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		1	NR	NR	NR	NR	1
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		2	161	145	62	19	0	389

DRAFT

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

DRAFT

A1
Target Property **98 BERRIMAN STREET**
BROOKLYN, NY 11208

NY E DESIGNATION **S118704197**
NY NYC LAND USE **N/A**

Site 1 of 21 in cluster A

Actual:
32 ft.

E DESIGNATION:

Name:	LOT 20,TAXBLOCK 3989
Address:	98 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	20
Tax Block:	3989
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	98 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6762581
Longitude:	-73.8806725
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 98 CORP.
Borough:	BK
Tax Block:	3989
Tax Lot:	20
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

DRAFT

(Continued) **S118704197**

Spill Boundary Indicator:	N
Building Class:	F4: Factory And Industrial Buildings - Semi-Fireproof
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	10500
Total Building Floor Area:	10500
Commercial Floor Area:	10500
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	10500
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	105.0000000
Lot Depth:	100.0000000
Building Frontage:	105.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	189000.00000
Assessed Total Value:	401850.00000
Exempt Total Value:	0.00000
Year Built:	1935
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890020.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017349
Y Coordinate:	185678
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1

DRAFT

(Continued) **S118704197**

Changed By DCP: Not reported

A2 **NY E DESIGNATION** **S118704247**
NY NYC LAND USE **N/A**

< 1/8 **114 BERRIMAN STREET**
1 ft. **BROOKLYN, NY 11208**

Site 2 of 21 in cluster A

Relative: Higher
Actual: 32 ft.

E DESIGNATION:

Name:	LOT 25,TAXBLOCK 3989
Address:	114 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	25
Tax Block:	3989
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	114 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6759945
Longitude:	-73.8806045
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 112-114-148-152 CO RP.
Borough:	BK
Tax Block:	3989
Tax Lot:	25
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported

DRAFT

(Continued) **S118704247**

Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G7: Garages And Gasoline Stations - Unlicensed Parking Lot
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	203850.00000
Assessed Total Value:	203850.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890025.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017368
Y Coordinate:	185582
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported

DRAFT

(Continued) **S118704247**

Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

A3 **LOT 24,TAXBLOCK 3989** **NY E DESIGNATION** **S118704238**
112 BERRIMAN STREET **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
1 ft.

Site 3 of 21 in cluster A

Relative:
Higher

Actual:
32 ft.

E DESIGNATION:

Name:	LOT 24,TAXBLOCK 3989
Address:	112 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	24
Tax Block:	3989
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	112 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6760878
Longitude:	-73.8806295
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 112-114-148-152 CO RP.
Borough:	BK
Tax Block:	3989
Tax Lot:	24
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported

DRAFT

LOT 24,TAXBLOCK 3989 (Continued) **S118704238**

Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G7: Garages And Gasoline Stations - Unlicensed Parking Lot
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	2000
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	20.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	73350.00000
Assessed Total Value:	73350.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890024.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017361
Y Coordinate:	185616
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014

DRAFT

LOT 24,TAXBLOCK 3989 (Continued) **S118704238**

Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

A4 **LOT 14,TAXBLOCK 3989** **NY E DESIGNATION** **S118704093**
NNW **778 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.007 mi.
35 ft. **Site 4 of 21 in cluster A**

Relative:
Higher

Actual:
32 ft.

E DESIGNATION:

Name:	LOT 14,TAXBLOCK 3989
Address:	778 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	14
Tax Block:	3989
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	778 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6764917
Longitude:	-73.8809569
Type Of Ownership Code:	Not reported
Owner Name:	LIBERTY APARTMENTS LLC
Borough:	BK
Tax Block:	3989
Tax Lot:	14
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200

DRAFT

LOT 14,TAXBLOCK 3989 (Continued) **S118704093**

Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G7: Garages And Gasoline Stations - Unlicensed Parking Lot
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	2250
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	90.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	82800.00000
Assessed Total Value:	82800.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890014.00000000
Condominium Number:	Not reported
Census Tract 2:	1166

DRAFT

LOT 14,TAXBLOCK 3989 (Continued) **S118704093**

X Coordinate:	1017270
Y Coordinate:	185763
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

A5 **CON EDISON** **E MANIFEST** **1031966789**
NNW **778 LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.007 mi.
35 ft. **Site 5 of 21 in cluster A**

Relative:
Higher

Actual:
32 ft.

E MANIFEST:

Manifest Tracking Number:	006869624GBF
Last Updated Date:	20210823
Shipped Date:	20210813
Received Date:	20210816
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	778 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ

DRAFT

CON EDISON (Continued) **1031966789**

Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 006869624GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006869624GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 200
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.1
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.1
Waste Quantity, in Kilograms: 90.703
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 90.703
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 90.703
Quantity Haz Tons: 0.1
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

DRAFT

A6 **P.S. 345 - BROOKLYN K345** **NY AST** **U003394314**
ENE **111 BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.012 mi.
61 ft. **Site 6 of 21 in cluster A**

Relative:
Higher

Actual:
32 ft.

AST:

Name:	P.S. 345 - BROOKLYN K345
Address:	111 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-355763
Program Type:	PBS
UTM X:	594635.05794
UTM Y:	4503414.62247
Expiration Date:	06/28/2028
Site Type:	School

Affiliation Records:

Site Id:	17744
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	ATHNASIOS GUIRGUIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 392-3884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2025-03-11

Site Id:	17744
Affiliation Type:	Facility Operator
Company Name:	P.S. 345 - BROOKLYN K345
Contact Type:	Not reported
Contact Name:	CARL SMITH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 348-2432
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2023-04-21

Site Id:	17744
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	NEW YORK CITY DEPARTMENT OF EDUCATION

DRAFT

P.S. 345 - BROOKLYN K345 (Continued) **U003394314**

Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	bcu@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-11-01

Site Id:	17744
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2025-03-12

Tank Info:

Tank Number:	001
Tank Id:	34743
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/03/1967

DRAFT

P.S. 345 - BROOKLYN K345 (Continued) **U003394314**

Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/10/2020
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34744
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
I04 - Overfill - Product Level Gauge (A/G)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/03/1967
Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/10/2020
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	003
Tank Id:	285485

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

DRAFT

P.S. 345 - BROOKLYN K345 (Continued) **U003394314**

K01 - Spill Prevention - Catch Basin
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/13/2019
Capacity Gallons:	6000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXLIU
Last Modified:	04/21/2023
Material Name:	#2 fuel oil (on-site consumption)

A7 **NYC DEPT OF EDUCATION PS 345K** **RCRA-SQG** **1025887658**
ENE **111 BERRIMAN ST** **E MANIFEST** **NYR000242271**
< 1/8 **BROOKLYN, NY 11208**
0.012 mi.
61 ft. **Site 7 of 21 in cluster A**

Relative: **Higher**
Actual: **32 ft.**

RCRA Listings:

Date Form Received by Agency:	20190729
Handler Name:	Nyc Dept Of Education Ps 345k
Handler Address:	Berriman St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYR000242271
Contact Name:	TRENTON BROWN
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-752-5496
Contact Fax:	718-472-8500
Contact Email:	TBROWN2@NYCSA.ORG
Contact Title:	MANAGER, OPERATIONS
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of School Facilities
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No

DRAFT

NYC DEPT OF EDUCATION PS 345K (Continued) **1025887658**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190730
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	19671222
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-752-5296
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8500
Owner/Operator Email:	TBROWN2@NYCSA.ORG

DRAFT

NYC DEPT OF EDUCATION PS 345K (Continued) **1025887658**

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES
Legal Status: Municipal
Date Became Current: 19671222
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-752-5296
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 718-472-8500
Owner/Operator Email: TBROWN2@NYCSA.ORG

Historic Generators:
Receive Date: 20190729
Handler Name: NYC DEPT OF EDUCATION PS 345K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: Elementary And Secondary Schools

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 019350651FLE
Last Updated Date: 20240305
Shipped Date: 20240204
Received Date: 20240221
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYR000242271
Generator Name: Nyc Doe 345k
Generator Location Street Number: 111
Generator Location Street 1: 111 BERRIMAN STREET
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY
Generator Location Zip: 11208
Generator Mail Street Number: 30-30
Generator Mail Street 1: 44-36 Vernon Blvd.

DRAFT

NYC DEPT OF EDUCATION PS 345K (Continued) **1025887658**

Generator Mail Street 2:	Not reported
Generator Mail City:	Long Island City
Generator Mail Zip:	11101
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NYD077444263
Designated Facility Name:	Triumvirate Environmental (Nyc), Llc
Designated Facility Mail Street Number:	42-14
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	19th Avenue
Designated Facility Mail City:	Astoria
Designated Facility Mail Zip:	11105
Designated Facility Mail State:	NY
Designated Facility Location Street Number:	42-14
Designated Facility Location Street 1:	19th Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Astoria
Designated Facility Location Zip:	11105
Designated Facility Location State:	NY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	021048018JJK
Last Updated Date:	20190930
Shipped Date:	20190916
Received Date:	20190916
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Ps 345k
Generator Location Street Number:	Not reported
Generator Location Street 1:	111 BERRIMAN STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	589 JOHNSON AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11237
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH

DRAFT

NYC DEPT OF EDUCATION PS 345K (Continued) **1025887658**

Designated Facility Location Zip: 07206
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 021048018JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Allstate Power Vac, Inc.

Waste Line:
Manifest Tracking Number: 021048018JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3077
U.S. DOT Description: Rq, Na3077, Hazardous Waste, Solid, N.O.S. (Lead), 9 , Iii
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 10
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.005
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.005
Waste Quantity, in Kilograms: 4.53515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 4.53515
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 4.53515
Quantity Haz Tons: 0.005
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

DRAFT

A8
North
< 1/8
0.012 mi.
63 ft.

790 LIBERTY AVE
790 LIBERTY AVE
BROOKLYN, NY

Site 8 of 21 in cluster A

NY NYC OER **S132180050**
N/A

Relative:
Higher

Actual:
33 ft.

NYC OER:

Name:	790 LIBERTY AVE
Address:	790 LIBERTY AVE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676741
Longitude:	-73.880643
OER Project Numbers:	22TMP0328K,22EHAN065K
BBL:	3.03989001630398E+29
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3000000
BIN:	3039890016
NTA:	East New York

A9
SSW
< 1/8
0.012 mi.
64 ft.

LOT 34,TAXBLOCK 3989
795 GLENMORE AVENUE
BROOKLYN, NY 11208

Site 9 of 21 in cluster A

NY E DESIGNATION **S118704309**
N/A

Relative:
Lower

Actual:
30 ft.

E DESIGNATION:

Name:	LOT 34,TAXBLOCK 3989
Address:	795 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	34
Tax Block:	3989
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

DRAFT

A10
WNW
< 1/8
0.012 mi.
65 ft.

LOT 9,TAXBLOCK 3989
339 SHEPHERD AVENUE
BROOKLYN, NY

Site 10 of 21 in cluster A

NY E DESIGNATION **S118704455**
NY NYC LAND USE **N/A**

Relative:
Higher

Actual:
32 ft.

E DESIGNATION:

Name:	LOT 9,TAXBLOCK 3989
Address:	339 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	9
Tax Block:	3989
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	339 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6763161
Longitude:	-73.8810545
Type Of Ownership Code:	Not reported
Owner Name:	RODRIGUEZ NILDA
Borough:	BK
Tax Block:	3989
Tax Lot:	9
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported

DRAFT

LOT 9,TAXBLOCK 3989 (Continued) **S118704455**

Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B2: Two Family Dwellings - Frame
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	1900
Commercial Floor Area:	0
Residential Floor Area:	1900
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	18.0000000
Building Depth:	45.0000000
Extension Code:	EG
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	14640.00000
Assessed Total Value:	48600.00000
Exempt Total Value:	0.00000
Year Built:	1915
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.76000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890009.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017243
Y Coordinate:	185699
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

DRAFT

LOT 9,TAXBLOCK 3989 (Continued) **S118704455**

Version Number: 24v4.1
Changed By DCP: Not reported

A11 **LOT 16,TAXBLOCK 3989** **NY E DESIGNATION** **S118704127**
NNW **LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.014 mi.
75 ft. **Site 11 of 21 in cluster A**

Relative:
Higher

Actual:
33 ft.

E DESIGNATION:
Name: LOT 16,TAXBLOCK 3989
Address: LIBERTY AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 16
Tax Block: 3989
Borough Code: Not reported
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

A12 **LOT 1,TAXBLOCK 3989** **NY VCP** **S118704033**
SW **355 SHEPHERD AVENUE** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY** **NY NYC LAND USE**
0.016 mi. **NY NYC OER**
84 ft. **Site 12 of 21 in cluster A**

Relative:
Lower

Actual:
30 ft.

VCP NYC:
Project ID: 19TMP1307K,19EH-A310K,22CVCP091K
Name: 355 SHEPHERD AVENUE
Address: 355 SHEPHERD AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 3,039,890,001,303,980,000,000,000,000,000,000,000,000
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Completed
Latitude: 40.675993
Longitude: -73.881257
Postcode: 5
Community Board: 37
Council District: 1166
Census Tract: 3327154
BIN: 3039890001
NTA: East New York

E DESIGNATION:
Name: LOT 1,TAXBLOCK 3989
Address: 355 SHEPHERD AVENUE
City,State,Zip: BROOKLYN, NY

DRAFT

LOT 1,TAXBLOCK 3989 (Continued) **S118704033**

Tax Lot(s):	1
Tax Block:	3989
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	355 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6757560
Longitude:	-73.8809149
Type Of Ownership Code:	Not reported
Owner Name:	SHEPHERD GLENMORE HOUSING DEVELOPMENT FU ND CORPORA
Borough:	BK
Tax Block:	3989
Tax Lot:	1
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	M1-1/R6A: Mixed Manufacturing & Residential Districts
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	MX-16
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Y
Building Class:	D1: Elevator Apartments - Semi-Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	18500
Total Building Floor Area:	81341
Commercial Floor Area:	4936
Residential Floor Area:	76405

DRAFT

LOT 1,TAXBLOCK 3989 (Continued) **S118704033**

Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	4936
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	7.0000000
Residential Units:	125
Total Units:	126
Lot Frontage:	185.0000000
Lot Depth:	100.0000000
Building Frontage:	119.2500000
Building Depth:	185.0000000
Extension Code:	Not reported
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	2
Assessed Land Value:	765900.00000
Assessed Total Value:	765900.00000
Exempt Total Value:	0.00000
Year Built:	2023
Year Altered 1:	2023
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.40000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890001.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017282
Y Coordinate:	185495
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	3039890001.00000000
Apportionment Date:	01/19/2023
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	355 SHEPHERD AVENUE
Address:	355 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.675993
Longitude:	-73.881257

DRAFT

LOT 1,TAXBLOCK 3989 (Continued) **S118704033**

OER Project Numbers:	19TMP1307K,19EH-A310K,22CVCP091K
BBL:	3.0398900013039803E+39
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3327154
BIN:	3039890001
NTA:	East New York

A13 **PRIVATE RESIDENCE** **NY Spills** **S106736313**
SW **355 SHEPHARD AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.016 mi.
84 ft. **Site 13 of 21 in cluster A**

Relative: **Lower**
Actual: **30 ft.**

SPILLS:

Name:	PRIVATE RESIDENCE
Address:	355 SHEPHARD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0410456 / 2004-12-24
Facility ID:	0410456
Facility Type:	ER
DER Facility ID:	270787
Site ID:	335541
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-12-20
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2004-12-20
CID:	71
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-23
Spill Record Last Update:	2004-12-24
Spiller Name:	SEAN DONOHUE
Spiller Company:	PRIVATE RESIDENCE
Spiller Address:	355 SHEPHARD AVE
Spiller Company:	001
Contact Name:	SEAN DONOHUE
Latitude:	40.6758760
Longitude:	-73.8811540
DEC Memo:	Forwarded to DEC Encon Police for enforcement Closed
Remarks:	OIL TRUCK HOLDING 4500 KEROSENE (WITH NO LICENSE PLATES) STAYS ON THE

DRAFT

PRIVATE RESIDENCE (Continued) **S106736313**

PROPERTY AND GRADUALLY DISPENSES KEROSENE TO RETAIL CUSTOMERS. EACH TIME KEROSENE IS DISPENSED, AN UNDETERMINED AMOUNT LEAKS ONTO THE GROUND. REQUESTING DEC CALL-BACK. NAME ON SIDE OF TRUCK IS 'FERRANTINO'.

All Materials:

Site ID:	335541
Operable Unit ID:	1097602
Operable Unit:	01
Material ID:	577586
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A14 **LOT 12,TAXBLOCK 3989** **NY E DESIGNATION** **S118704066**
NW **772 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.018 mi.
96 ft. **Site 14 of 21 in cluster A**

Relative: **Lower**
Actual: **31 ft.**

E DESIGNATION:

Name:	LOT 12,TAXBLOCK 3989
Address:	772 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	12
Tax Block:	3989
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	772 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6764726
Longitude:	-73.8810903
Type Of Ownership Code:	Not reported
Owner Name:	BATISTA, FROLIAN
Borough:	BK
Tax Block:	3989
Tax Lot:	12
Community District:	305
Census Tract 2020:	3116600

DRAFT

LOT 12,TAXBLOCK 3989 (Continued) **S118704066**

Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G1: Garages And Gasoline Stations - All Parking Garages
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	4500
Total Building Floor Area:	980
Commercial Floor Area:	980
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	980
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	50.0000000
Lot Depth:	90.0000000
Building Frontage:	20.0000000
Building Depth:	45.0000000
Extension Code:	E
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	30600.00000
Assessed Total Value:	106200.00000
Exempt Total Value:	0.00000
Year Built:	1910
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported

DRAFT

LOT 12,TAXBLOCK 3989 (Continued) **S118704066**

Landmark Status:	Not reported
Built Floor Area Ratio:	0.22000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890012.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017233
Y Coordinate:	185756
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

A15 **MANHOLE #4750** **NY Spills** **S107416250**
North **LIBERTY AVE AND BERRIMAN ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.022 mi.
115 ft. **Site 15 of 21 in cluster A**

Relative: **Higher**

Actual: **34 ft.**

SPILLS:

Name:	MANHOLE #4750
Address:	LIBERTY AVE AND BERRIMAN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0508732 / 2007-05-03
Facility ID:	0508732
Facility Type:	ER
DER Facility ID:	301714
Site ID:	354377
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-10-20
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-10-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-21

DRAFT

MANHOLE #4750 (Continued) **S107416250**

Spill Record Last Update:	2007-05-03
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	LIBERTY AVE/BERRIMAN
Spiller Company:	999
Contact Name:	ERT DESK'
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	05/03/07 - See e-docs for Con Ed report detailing cleanup and closure. 161579. 10-20-05 13:40HRS G. MOORE 18872 (FOD) REPORTS, FOUND ONE PINT OF UNKNOWN OIL ON 10 GALLONS OF WATER. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. OIL WAS DISCOVERED WHILE LOCATING FAULT FOR 9B94. NO FIRE SMOKE OR PRIVATE PROPERTY INVOLVED AND NO INJURIES RELATED TO SPILL WITH NO WEATHER CONDITIONS CONTRIBUTING TO THE HAZARD OF THE SPILL. UNABLE TO DETERMINE IF THERE IS ANY SEWER CONNECTIONS OR SUMPS IN STRUCTURE. THE STANDING WATER THAT IS PRESENT HAS NO MOVEMENT. ENV STOP TAG 30244 WAS PLACED, AND ONE LIQUID SAMPLE WAS TAKEN ON A E PRIORTY AND CLEANUP PENDING LAB RESULTS. CHAIN OF CUSTODY# DD-11632 AND ACCOUNT# C3242. S. PACE 49874. LAB RESULT RECEIVED 10/20/05 - 2208. 05-11042. 1012 PPM. EPA # ISSUED - NYP 004 136 933. TANKER ORDERED. ENV OPS CREW ON WAY TO LOC. TJ - 50495 10/21/05 Update: 0300 hrs O.S. R. Quijije reports that Env. Ops. crew went to do 1012PPM PCB clean up at Berriman St & Liberty Ave.Inc.#161579. Crew pump the structure with Clean Venture >500 PPM tanker and removed 144 gallons of liquid from structure. #9 was called to location to inspect structure for possible D fault. #9 found two D fault in structure and hang a D fault tag #02396. Crew generated one drum of PPE and Zone material and will one trip back to CPB yard on the one trip rule. Clean up will be followed when structure is safe to enter. Rom Quijije, Operating Supervisor, B/Q Environmental Operations. 718 321-4812 Office 347 672-5430 Cell. G DONATONE 10/21/05 09:04 HRS DUE TO HIGH PCB COUNT INCIDENT TO BE REMOVED FROM THE 72 HOUR PROGRAM. UPDATE 10/22/05 17:05 HRS ENV OPS GEORGIANI REPORTS THAT 5 DRUMS OF DEBRIS, CABLE, AND ZONE MATERIAL HAVE BEEN PICKED UP, THE STRUCTURE WAS DOUBLE WASHED WITH SAFE WASH, THE TANKER REMOVED 200 GALS OF LIQUID, AND THE ENV TAG REMAINS IN PLACE PENDING SODA BLASTING. J ANDERSON
Remarks:	ON 10 GALLONS OF WATER: NO TO 5 QUESTIONS; 1/2 PINT; CONED # 161579

All Materials:

Site ID:	354377
Operable Unit ID:	1111790
Operable Unit:	01
Material ID:	2101836
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported

DRAFT

MANHOLE #4750 (Continued) **S107416250**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A16 **CON EDISON** **NY MANIFEST** **S117061080**
North **LIBERTY AVE & BERRIMAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.022 mi.
115 ft. **Site 16 of 21 in cluster A**

Relative:
Higher

Actual:
34 ft.

NY MANIFEST:

EPA ID:	NYP004533543
Country:	USA
Name:	Con Edison
Address:	LIBERTY AVE & BERRIMAN AVE
Address 2:	50 FEET S OF
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	WS OF BERRIMAN ST & LIBERTY AVE
Location Address 2:	SB 57327
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/15/2014
Trans1 Recv Date:	05/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004533543
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013246346JJK
Import Indicator:	N

DRAFT

CON EDISON (Continued) **S117061080**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

A17 **CON EDISON - MANHOLE 4750** **RCRA NonGen / NLR** **1010326001**
North **S/W/C LIBERTY AVE & BERRIMAN S** **NY MANIFEST** **NYP004136933**
< 1/8 **BROOKLYN, NY 11208**
0.022 mi.
115 ft. **Site 17 of 21 in cluster A**

Relative:
Higher

Actual:
34 ft.

RCRA Listings:

Date Form Received by Agency:	20060223
Handler Name:	Con Edison - Manhole 4750
Handler Address:	S/W/C Liberty Ave & Berriman S
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004136933
Contact Name:	FRANKLIN MURRAY
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

DRAFT

CON EDISON - MANHOLE 4750 (Continued) **1010326001**

Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years

Year:	2005

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

DRAFT

CON EDISON - MANHOLE 4750 (Continued) **1010326001**

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20051020
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20051020
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20051020
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20051020
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060222
Handler Name: CON EDISON - MANHOLE 4750
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

DRAFT

CON EDISON - MANHOLE 4750 (Continued) **1010326001**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060223
Handler Name: CON EDISON - MANHOLE 4750
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - MANHOLE 4750
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004136933
Country: USA
Name: Consolidated Edison
Address: S/W/C LIBERTY AVE & BERRIMAN S
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: LIBERTY AV & BERRIMAN MH4750
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11208

DRAFT

CON EDISON - MANHOLE 4750 (Continued) **1010326001**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYE1575342
Manifest Status: Not reported
Trans1 State ID: 46630JM
Year: 2005
Trans2 State ID: Not reported
Generator Ship Date: 10/22/2005
Trans1 Recv Date: 10/22/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/26/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004136933
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B007
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00449
Units: Kilograms
Number of Containers: 004
Container Type: Metal drums, barrels, kegs
Handling Method: Landfill
Specific Gravity: 01.00
Waste Code 7: B007

DRAFT

CON EDISON - MANHOLE 4750 (Continued) **1010326001**

Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00160
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA5240582
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	2005
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/2005
Trans1 Recv Date:	10/21/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004136933
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00654
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA5240592
Manifest Status:	Not reported
Trans1 State ID:	S09363
Year:	2005
Trans2 State ID:	Not reported

DRAFT

CON EDISON - MANHOLE 4750 (Continued) **1010326001**

Generator Ship Date:	10/22/2005
Trans1 Recv Date:	10/22/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004136933
Trans1 EPA ID:	NJD063147797
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00909
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

A18 **CON EDISON SERVICE BOX: 57327** **RCRA NonGen / NLR** **1017775516**
North **LIBERTY AVE & BERRIMAN AVE** **FINDS** **NYP004533543**
< 1/8 **BROOKLYN, NY 11208**
0.022 mi.
115 ft. **Site 18 of 21 in cluster A**

Relative:
Higher

Actual:
34 ft.

RCRA Listings:

Date Form Received by Agency:	20140615
Handler Name:	Con Edison Service Box: 57327
Handler Address:	Liberty Ave & Berriman Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004533543
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private

DRAFT

CON EDISON SERVICE BOX: 57327 (Continued) **1017775516**

Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150211
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:
Receive Date: 20140515

DRAFT

CON EDISON SERVICE BOX: 57327 (Continued) **1017775516**

Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140515
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140615
Handler Name: CON EDISON SERVICE BOX: 57327
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063776515

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the

DRAFT

CON EDISON SERVICE BOX: 57327 (Continued) **1017775516**

Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A19 **LOT 36,TAXBLOCK 3989** **NY E DESIGNATION** **S118704325**
SSW **793 GLENMORE AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.022 mi.
115 ft. **Site 19 of 21 in cluster A**

Relative: **Lower**
Actual: **30 ft.**

E DESIGNATION:

Name:	LOT 36,TAXBLOCK 3989
Address:	793 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	36
Tax Block:	3989
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

A20 **D&J CLEANERS** **EDR Hist Cleaner** **1019968147**
NW **770 LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.022 mi.
115 ft. **Site 20 of 21 in cluster A**

Relative: **Lower**
Actual: **31 ft.**

EDR Hist Cleaner

Year:	Name:	Type:
1995	D&J CLEANERS	Drycleaning Plants, Except Rugs
1996	D&J CLEANERS	Drycleaning Plants, Except Rugs

A21 **LOT 10,TAXBLOCK 3989** **NY E DESIGNATION** **S118704044**
NW **770 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.022 mi.
115 ft. **Site 21 of 21 in cluster A**

Relative: **Lower**
Actual: **31 ft.**

E DESIGNATION:

Name:	LOT 10,TAXBLOCK 3989
Address:	770 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	10
Tax Block:	3989

DRAFT

LOT 10,TAXBLOCK 3989 (Continued) **S118704044**

Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	770 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6764508
Longitude:	-73.8812274
Type Of Ownership Code:	Not reported
Owner Name:	RODRIGUEZ, NOEL
Borough:	BK
Tax Block:	3989
Tax Lot:	10
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001000
Census Tract 2010:	1166
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	S5: Residence - Multiple Use - Primarily Five To Six Family With One Store Or Office
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	2250
Total Building Floor Area:	6250
Commercial Floor Area:	850
Residential Floor Area:	5400

DRAFT

LOT 10,TAXBLOCK 3989 (Continued) **S118704044**

Office Floor Area:	0
Retail Floor Area:	850
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	5
Total Units:	6
Lot Frontage:	25.0000000
Lot Depth:	90.0000000
Building Frontage:	25.0000000
Building Depth:	80.0000000
Extension Code:	E
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	7650.00000
Assessed Total Value:	260100.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.78000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039890010.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017195
Y Coordinate:	185748
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

DRAFT

B22 **LOT 57,TAXBLOCK 3973** **NY E DESIGNATION** **S118704415**
North **787 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.028 mi.
148 ft. **Site 1 of 15 in cluster B**

Relative:
Higher

Actual:
34 ft.

E DESIGNATION:

Name:	LOT 57,TAXBLOCK 3973
Address:	787 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	57
Tax Block:	3973
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	787 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6769580
Longitude:	-73.8807073
Type Of Ownership Code:	Not reported
Owner Name:	CONTA CT HOLDINGS CORP.
Borough:	BK
Tax Block:	3973
Tax Lot:	57
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001004
Census Tract 2010:	1168
Census Block 2010:	1004
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

DRAFT

LOT 57,TAXBLOCK 3973 (Continued) **S118704415**

Spill Boundary Indicator:	N
Building Class:	S9: Residence - Multiple Use - Single Or Multiple Dwelling With Stores Or Offices
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	3000
Commercial Floor Area:	1020
Residential Floor Area:	1980
Office Floor Area:	0
Retail Floor Area:	1020
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	2
Total Units:	4
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	25.0000000
Building Depth:	40.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	11700.00000
Assessed Total Value:	147150.00000
Exempt Total Value:	0.00000
Year Built:	1920
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.20000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039730057.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1017339
Y Coordinate:	185933
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

DRAFT

LOT 57,TAXBLOCK 3973 (Continued) **S118704415**

Version Number: 24v4.1
Changed By DCP: Not reported

B23 **CON EDISON** **RCRA NonGen / NLR** **1019325299**
NW **LIBERTY AVE & SHEPHERD AVE** **NYP004814063**
< 1/8 **BROOKLYN, NY 11208**
0.031 mi.
163 ft. **Site 2 of 15 in cluster B**

Relative: **Lower**
Actual: **30 ft.**

RCRA Listings:

Date Form Received by Agency:	20150728
Handler Name:	Con Edison
Handler Address:	Liberty Ave & Shepherd Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004814063
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

DRAFT

CON EDISON (Continued) **1019325299**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20150728
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20150728
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

DRAFT

CON EDISON (Continued) **1019325299**

Receive Date: 20160226
Handler Name: CON EDISON - MANHOLE 4749
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150728
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150728
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

DRAFT

B24
NW
< 1/8
0.031 mi.
163 ft.

CON EDISON
LIBERTY AVE & SHEPHERD AVE
BROOKLYN, NY 11208

Site 3 of 15 in cluster B

RCRA NonGen / NLR

1019905834
NYP004814071

Relative:
Lower

Actual:
30 ft.

RCRA Listings:

Date Form Received by Agency:	20150728
Handler Name:	Con Edison
Handler Address:	Liberty Ave & Shepherd Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004814071
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

DRAFT

CON EDISON (Continued) **1019905834**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150728
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150728
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

DRAFT

B25
NW
< 1/8
0.031 mi.
163 ft.

CON EDISON
LIBERTY AVE & SHEPHERD AVE
BROOKLYN, NY 11208

Site 4 of 15 in cluster B

NJ MANIFEST **S120674569**
N/A

Relative:
Lower

Actual:
30 ft.

NJ MANIFEST:

EPA ID:	NYP004814071
Name:	CON EDISON
Address:	LIBERTY AVE & SHEPHERD AVE
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004814071
Manifest Number:	002624745GBF
Date Shipped:	7/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

DRAFT

CON EDISON (Continued) **S120674569**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

B26 **CON ED** **NY MANIFEST** **S118563397**
NW **LIBERTY AVE & SHEPHERD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.031 mi.
163 ft. **Site 5 of 15 in cluster B**

Relative: **Lower**
Actual: **30 ft.**

NY MANIFEST:

EPA ID:	NYP004814063
Country:	USA
Name:	Con Ed
Address:	LIBERTY AVE & SHEPHERD AVE
Address 2:	MH4749
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	LIBERTY AVE & SHEPHERD AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Ed
Mailing Contact:	Theresa Burkard
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602262

B27 **CON EDISON** **NY MANIFEST** **S119076813**
NW **LIBERTY AVE & SHEPHERD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.031 mi.
163 ft. **Site 6 of 15 in cluster B**

Relative: **Lower**
Actual: **30 ft.**

NY MANIFEST:

EPA ID:	NYP004814071
Country:	USA
Name:	Con Edison
Address:	LIBERTY AVE & SHEPHERD AVE
Address 2:	MH4749
City,State,Zip:	BROOKLYN, NY 11208

DRAFT

CON EDISON (Continued) **S119076813**

Zip 4:	Not reported
Location Address 1:	OPP 775 LIBERTY AVE
Location Address 2:	SB 29446
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Dennis Huacon
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/28/2015
Trans1 Recv Date:	07/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004814071
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624745GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported

DRAFT

CON EDISON (Continued) **S119076813**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

B28 **CON EDISON** **NJ MANIFEST** **S120674568**
NW **LIBERTY AVE & SHEPHERD AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.031 mi.
163 ft. **Site 7 of 15 in cluster B**

Relative:
Lower

Actual:
30 ft.

NJ MANIFEST:

EPA ID:	NYP004814063
Name:	CON EDISON
Address:	LIBERTY AVE & SHEPHERD AVE
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004814063
Manifest Number:	002624744GBF
Date Shipped:	7/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

DRAFT

CON EDISON (Continued) **S120674568**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

B29 **LOT 58,TAXBLOCK 3973** **NY E DESIGNATION** **S118704418**
North **785 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.032 mi.
171 ft. **Site 8 of 15 in cluster B**

Relative:
Higher

Actual:
34 ft.

E DESIGNATION:

Name:	LOT 58,TAXBLOCK 3973
Address:	785 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	58
Tax Block:	3973
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	785 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6769389
Longitude:	-73.8808407
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 785 CORP.
Borough:	BK

DRAFT

LOT 58,TAXBLOCK 3973 (Continued) **S118704418**

Tax Block:	3973
Tax Lot:	58
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001004
Census Tract 2010:	1168
Census Block 2010:	1004
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G2: Garages And Gasoline Stations - Auto Body/Collision Or Auto Repair
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	2642
Commercial Floor Area:	2642
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	2642
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	25.0000000
Building Depth:	55.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	56250.00000
Assessed Total Value:	236700.00000
Exempt Total Value:	0.00000

DRAFT

LOT 58,TAXBLOCK 3973 (Continued) **S118704418**

Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.53000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039730058.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1017302
Y Coordinate:	185926
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

C30 **LOT 17,TAXBLOCK 4005** **NY E DESIGNATION** **S118704142**
SSE **GLENMORE AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
203 ft. **Site 1 of 9 in cluster C**

Relative:
Lower

Actual:
30 ft.

E DESIGNATION:

Name:	LOT 17,TAXBLOCK 4005
Address:	GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	17
Tax Block:	4005
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

DRAFT

D31 **LOT 34,TAXBLOCK 3988** **NY E DESIGNATION** **S118704308**
SW **366 SHEPHERD AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.039 mi.
206 ft. **Site 1 of 17 in cluster D**

Relative:
Lower

Actual:
29 ft.

E DESIGNATION:

Name:	LOT 34,TAXBLOCK 3988
Address:	366 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	34
Tax Block:	3988
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	366 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6756276
Longitude:	-73.8814704
Type Of Ownership Code:	Not reported
Owner Name:	JP SHEPHERD, INC
Borough:	BK
Tax Block:	3988
Tax Lot:	34
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001001
Census Tract 2010:	1166
Census Block 2010:	1001
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

DRAFT

LOT 34,TAXBLOCK 3988 (Continued) **S118704308**

Spill Boundary Indicator:	N
Building Class:	B2: Two Family Dwellings - Frame
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	2210
Commercial Floor Area:	0
Residential Floor Area:	2210
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	17.0000000
Building Depth:	65.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	12900.00000
Assessed Total Value:	50520.00000
Exempt Total Value:	0.00000
Year Built:	2004
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.88000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039880034.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017128
Y Coordinate:	185448
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1

DRAFT

LOT 34,TAXBLOCK 3988 (Continued) **S118704308**

Changed By DCP: Not reported

D32
WSW
< 1/8
0.039 mi.
206 ft.

FORMER GARONE BROS AUTO SERVICE CENTER **NY BROWNFIELDS** **S127990286**
352-362 SHEPHERD AVENUE **N/A**
BROOKLYN, NY 11208

Site 2 of 17 in cluster D

Relative:
Lower

Actual:
30 ft.

BROWNFIELDS:

Name:	FORMER GARONE BROS AUTO SERVICE CENTER
Address:	352-362 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Program:	BCP
Site Code:	625573
Acres:	0.230
HW Code:	C224338
SWIS:	2401
Town:	New York City
Record Added Date:	10/15/2021
Record Updated Date:	12/31/2024
Update By:	AMSERVIS

Site Description: Site Location: The site s address is 352-362 Shepherd Avenue, Brooklyn, NY 11208. The site is located in Kings County, New York and is identified as Brooklyn Block 3988, Lot 28. The site is located in an urban area of the East New York neighborhood of Brooklyn, NY on the west side of Shepherd Avenue between Liberty Avenue and Glenmore Avenue. The site is bounded by residential homes to the north and south, Shepherd Avenue followed by a residential home and a miscellaneous garage/parking area to the east, and residential apartments to the west. The site is 0.230 acres in size. Site Features: The site is a rectangular shaped lot formerly occupied by a one-story warehouse/garage building encompassing the entire site footprint with a partial cellar located in the southwest corner of the property. The site was vacant and undeveloped as of 2022. Construction for the new development is ongoing and, when completed, the site will be improved with an eight-story residential building with 53 units, a 421-a affordable housing component, and one cellar level extending to 10 feet below grade surface. Current Zoning and Land Use: The site is currently developed land that is zoned R6 for residential use. The surrounding properties are currently used for residential purposes. The site is listed with an environmental E-Designation (E-366) East New York Rezoning (CEQR 15DCP102K). The requirements under the E-Designation program are satisfaction of the requirements for Hazardous Material and Air Quality components with the New York City Office of Environmental Remediation (NYCOER) to obtain a NTP or NNO prior to obtaining building permits. Past Land Use: As found during the Phase I Environmental Site Assessment, the site was developed in the late 1880s with several dwellings. In the early 1900s, the site was used as a toy animal factory and by the late 1920s, the previous site buildings were razed and began operation as a garage. The site continued to operate as a garage until the late 1960s/early 1970s. From the late 1970s through the present, the site was primarily used for auto-related purposes including an auto repair shop and service center, used car sales shop, and a towing center. The site is currently improved with a one-story warehouse/garage building encompassing the entire site footprint and is currently occupied by Gils Auto Body and Hi-Tech Heating. Site Geology and Hydrogeology: The stratigraphy of the site,

DRAFT

FORMER GARONE BROS AUTO SERVICE CENTER (Continued) **S127990286**

from the surface down, consists of 0-5 feet of urban fill material, comprised of brown silty sand with some fragments of concrete, brick, and asphalt underlain by brown to orange-brown well graded sand to 12 ft bgs. The average depth to groundwater is 22.13 feet and the range in depth is 21.76 to 22.63 feet below grade. Groundwater is inferred to flow from south to north. The site has since been remediated to Track 1 with excavation depths extending 2 ft bgs sitewide and up to 12.5 ft bgs at localized excavation areas.

Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved Track 1 Unrestricted Use soil cleanup objectives. Prior to Completion of Remediation Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Soil vapor was analyzed for VOCs. Based on findings summarized in the September 2021 Remedial Investigation Report (RIR), the primary contaminants of concern include VOCs (TCE), SVOCs (PAHs), and metals. Soil: No VOCs were identified in soils at concentrations exceeding the 6NYCRR Part 375 unrestricted use soil cleanup objectives (UUSCOs). Soil impacts at the subject site primarily consisted of SVOCs, specifically polyaromatic hydrocarbons (PAHs), and metals, at concentrations exceeding the UUSCOs within the historic fill layer which extends to approximately 6 - 7 ft below ground surface. In general, the highest concentrations were detected in the upper two feet of site soils. However, elevated concentrations of SVOCs and metals did extend into deeper soils in the southeast portion of the site (10-12 ft bgs). More notably, mercury was identified in shallow fill collected from 0-2 ft bgs in the southwest region of the site at a concentration of 30.2 mg/kg compared with its respective RRSCO of 0.81 mg/kg. PAH concentrations were generally 2- to 6-times greater than their respective RRSCOs with the exception of Soil Boring B03 where the magnitude of exceedances was much higher at the depth interval of 0 - 6 inches jsut below the impervious site cover. SVOCs detected at levels exceeding RRSCOs include: benzo(a)anthracene (270 mg/kg, RRSCO of 1 mg/kg), benzo(a)pyrene (260 mg/kg, RRSCO of 1 mg/kg), benzo(b)fluoranthene (280 mg/kg, RRSCO of 1 mg/kg and PGWSCO of 1.7 mg/kg), benzo(ghi)perylene (140 mg/kg, RRSCO of 100 mg/kg),benzo(k)fluoranthene (62 mg/kg, RRSCO of 3.9 mg/kg and PGWSCO of 1.7 mg/kg), chrysene (260 mg/kg, RRSCO of 3.9 mg/kg and PGWSCO of 1 mg/kg), dibenzo(a,h)anthracene (31 mg/kg, RRSCO of 0.33 mg/kg), fluoranthene (560 mg/kg, RRSCO of 100 mg/kg), indeno(1,2,3-cd)pyrene (170 mg/kg, RRSCO of 0.5 mg/kg and PGWSCO of 8.2 mg/kg), phenanthrene (270 mg/kg, RRSCO of 100 mg/kg), and pyrene (480 mg/kg, RRSCO of 100 mg/kg). Metals detected at levels exceeding RRSCOs include: arsenic (36.6 mg/kg, RRSCO of 16 mg/kg), barium (1060 mg/kg, RRSCO of 400 mg/kg), cadmium (4.42 mg/kg, RRSCO of 4.3 mg/kg), copper (25,100 mg/kg, RRSCO of 270 mg/kg), lead (1,840 mg/kg, RRSCO of 400 mg/kg), and mercury (30.2 mg/kg, RRSCO of 0.81 mg/kg) Five soil samples were analyzed for lead and one soil sample was analyzed for mercury via TCLP due to hazardous concentrations above 100 mg/kg and 4 mg/kg respectively. TCLP lead and/or mercury results for the samples did not exceed the USEPA Allowable limit of 5 mg/L for TCLP lead or 0.2 mg/L for TCLP mercury. Data does not indicate any off-site impacts in soil related to this site. Groundwater: A single VOC, Tetrachloroethene (PCE), was detected at a maximum concentration of 3.6 ppb. This is below the Class GA Ambient Water Quality Standard

DRAFT

FORMER GARONE BROS AUTO SERVICE CENTER (Continued) **S127990286**

(AWQS) of 5 ppb. SVOCs detected at levels exceeding AWQS include: dimethyl phthalate (100 ppb, AWQS of 5 ppb), benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, and indeno(1,2,3-cd)pyrene, each of which were detected at a concentration of 0.01 ppb (AWQS of 0.002 ppb) in the single monitoring well MW-04. Metals detected above AWQS include: dissolved antimony (7.84 ppb, AWQS of 3 ppb), dissolved manganese (416.7 ppb, AWQS of 300 ppb), and dissolved sodium (88700 ppb, AWQS of 20000 ppb). For PFAS compounds, PFOA and PFOS were reported at concentrations up to 0.0596 ppb and 0.0764 ppt, respectively, exceeding the NYSDOH Maximum Contaminant Levels (MCLs). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor: Total VOC concentrations in soil vapor samples ranged from 90.883 g/m3 in sample SG4 to 408.08 g/m3 in sample SG2. Total benzene, toluene, ethylbenzene, and xylenes (BTEX) concentrations ranged from 44.97 g/m3 in sample SG4 to 270.8 g/m3 in sample SG1. PCE was detected in one soil vapor sample, SG2, at a concentration 35.5 g/m3 exceeding the NYSDEC AGV of 30 g/m3.PCE concentrations were detected in the remaining five soil vapor samples; however, with the exception of SG2, were detected at concentrations below the NYSDEC AGV. TCE detected in in one soil vapor sample, SG3, at a TCE concentration 2.26 g/m3, exceeding the NYSDEC AGV of 2 g/m3. TCE was not detected above laboratory detection limits in any other soil vapor samples analyzed. Methylene chloride was identified above laboratory detection limits, but below NYSDEC AGV, in two soil vapor samples analyzed including, SG6 at a concentration of 3.23 g/m3, and, SG1 at a concentration of 3.28 vg/m3. No other CVOCs were detected above laboratory detection limits in soil vapor samples analyzed. Data does not indicate any off-site impacts in soil vapor related to this site.

Health Problem:	Remedial actions are complete, the site was cleaned up to meet unrestricted use, and all known exposure pathways were addressed by the remedy for the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2022-01-20 15:30:00
Record Upd:	2024-11-05 14:46:00
Updated By:	MDSOLLEC
Own Op:	6
Sub Type:	P03
Owner Name:	Shacne Rabi and Shulem Weiss
Owner Company:	362 Shepherd Development LLC
Owner Address:	183 wILSON sT., sUITE 133
Owner Addr2:	Not reported
Owner City,St,Zip:	bROOKLYN, NY 11211
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Shacne Rabi and Shulem Weiss
Owner Company:	362 Shepherd Development LLC
Owner Address:	183 wILSON sT., sUITE 133

DRAFT

FORMER GARONE BROS AUTO SERVICE CENTER (Continued) **S127990286**

Owner Addr2:	Not reported
Owner City,St,Zip:	bROOKLYN, NY 11211
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Rowshon A. Perveen
Owner Company:	Brooklyn Public Library - Cypress Hills
Owner Address:	1197 Sutter Avenue at Crystal Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Melinda Perkins
Owner Company:	Brooklyn Community Board 5
Owner Address:	127 Pennsylvania Avenue, 2nd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
HW Code:	C224338
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	dimethyl phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	cadmium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	phenol
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	antimony
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	chrysene

DRAFT

FORMER GARONE BROS AUTO SERVICE CENTER (Continued) **S127990286**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	silver
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	benzo(g,h,i)perylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	selenium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	methylene chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN

DRAFT

FORMER GARONE BROS AUTO SERVICE CENTER (Continued) **S127990286**

Waste Code:	Not reported
HW Code:	C224338
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	dibenzofuran
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224338
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-613563
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2024-09-13 15:43:00
Record Updated:	2024-09-13 15:43:00
Updated By:	DAFRANCI
Crossref ID:	C224338-01-22
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2024-11-05 15:10:00
Record Updated:	2024-11-05 15:10:00
Updated By:	MDSOLLEC

D33 **LOT 28,TAXBLOCK 3988** **NY E DESIGNATION** **S118704265**
WSW **352 SHEPHERD AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.039 mi.
206 ft. **Site 3 of 17 in cluster D**

Relative: **Lower**

Actual: **30 ft.**

E DESIGNATION:

Name:	LOT 28,TAXBLOCK 3988
Address:	352 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	28
Tax Block:	3988
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

DRAFT

LOT 28,TAXBLOCK 3988 (Continued) **S118704265**

NYC LAND USE:

Name:	Not reported
Address:	352 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6757978
Longitude:	-73.8815133
Type Of Ownership Code:	Not reported
Owner Name:	362 SHEPHERD DEVELOPMENT LLC
Borough:	BK
Tax Block:	3988
Tax Lot:	28
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001001
Census Tract 2010:	1166
Census Block 2010:	1001
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V0: Vacant Land - Zoned Residential; Not Manhattan
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000

DRAFT

LOT 28,TAXBLOCK 3988 (Continued) **S118704265**

Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	54300.00000
Assessed Total Value:	54300.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039880028.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017116
Y Coordinate:	185510
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

D34 **352-362 SHEPHERD AVENUE** **NY NYC OER** **S132757589**
WSW **352-362 SHEPHERD AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.039 mi.
206 ft. **Site 4 of 17 in cluster D**

Relative:
Lower

Actual:
30 ft.

NYC OER:

Name:	352-362 SHEPHERD AVENUE
Address:	352-362 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676083
Longitude:	-73.8813
OER Project Numbers:	22TMP0141K,22EH-A048K
BBL:	3039880028
OER Program:	E/RD (Review), State BCP
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	5
Community Board:	37

DRAFT

352-362 SHEPHERD AVENUE (Continued) **S132757589**

Council District: 1166
Census Tract: 3088713
BIN: 3039880028
NTA: East New York

D35 **FORMER GARONE BROS. AUTO SERVICE CENTER SITE** **NY UST** **U004450892**
WSW **352 - 362 SHEPHERD AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.039 mi.
206 ft. **Site 5 of 17 in cluster D**

Relative:
Lower

Actual:
30 ft.

UST:
Name: FORMER GARONE BROS. AUTO SERVICE CENTER SITE
Address: 352 - 362 SHEPHERD AVENUE
City,State,Zip: BROOKLYN, NY 11208
Id/Status: 2-613563 / Unregistered
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: Not reported
UTM Y: Not reported
Site Type: Other

Affiliation Records:
Site Id: 671993
Affiliation Type: Facility Owner
Company Name: 362 SHEPHERD DEVELOPMENT LLC
Contact Type: MANAGER
Contact Name: JOEL SCHWARTZ
Address1: 183 WILSON STREET, SUITE 133
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: Not reported
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2024-09-13

Site Id: 671993
Affiliation Type: Mail Contact
Company Name: 362 SHEPHERD DEVELOPMENT LLC
Contact Type: Not reported
Contact Name: SHULEM WEISS
Address1: 183 WILSON STREET, SUITE 133
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (646) 880-7883
EMail: SW@BLUESHINEDEVELOPERS.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2024-09-13

DRAFT

FORMER GARONE BROS. AUTO SERVICE CENTER SITE (Continued) **U004450892**

Site Id:	671993
Affiliation Type:	Facility Operator
Company Name:	FORMER GARONE BROS. AUTO SERVICE CENTER SITE
Contact Type:	Not reported
Contact Name:	362 SHEPHERD DEVELOPMENT LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2024-09-13

Site Id:	671993
Affiliation Type:	Emergency Contact
Company Name:	362 SHEPHERD DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	SHULEM WEISS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 880-7883
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2024-09-13

Tank Info:

Tank Number:	01
Tank ID:	303283
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/20/2021
Date Tank Closed:	04/09/2024
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	09/13/2024

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None

DRAFT

FORMER GARONE BROS. AUTO SERVICE CENTER SITE (Continued) **U004450892**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None

Tank Number:	02
Tank ID:	303284
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/20/2021
Date Tank Closed:	04/09/2024
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	09/13/2024

Equipment Records:

G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None

D36 **SHEPPARDS AUTO PARTS** **NY Spills** **S102663479**
WSW **352 SHEPHERD AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.039 mi.
206 ft. **Site 6 of 17 in cluster D**

Relative:
Lower

Actual:
30 ft.

SPILLS:

Name:	SHEPPARDS AUTO PARTS
Address:	352 SHEPHERD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9705843 / 2010-06-29
Facility ID:	9705843
Facility Type:	ER
DER Facility ID:	122200
Site ID:	143269
DEC Region:	2

DRAFT

SHEPPARDS AUTO PARTS (Continued) **S102663479**

Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-08-14
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	1997-08-14
CID:	369
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-14
Spill Record Last Update:	2010-06-29
Spiller Name:	DOMINIK
Spiller Company:	SHEPPARDS AUTO PARTS
Spiller Address:	352 SHEPHERD AVE
Spiller Company:	001
Contact Name:	DOMINIK
Latitude:	40.6759494
Longitude:	-73.8813186
DEC Memo:	3/8/06, Dyber: No response from Dominik. Referred back to region 2. Next Step: Perform state-funded investigation. 2/2/06, Dyber: Sent letter to Dominik asking for more information on UST removal. Gave March 3 deadline. 1/3/06, Dyber: Inspected the site. There was a small oil spill on the concrete floor of the garage. The spill was immediately cleaned up. Concrete had some petroleum stains, but no other liquid spills. An old gasoline dispenser was observed. Dominick said that the associated UST was about 350 gallons and was removed in the 1950's. 12/20/05, Dyber: Dominick Garone called. He said that spill was cleaned up but has no documentation. I said that I would call him to arrange an inspection after the transit strike is over. He would then have to write a letter stating the facts of the spill and cleanup. 7/27/05, Dyber: Spoke with the property owner, Bonita Garone, at home (See file for phone). She does not know about spill and said that the building on the property was vacant at the time. She said to call her husband, Dominik, after 8/1/05 after 6 pm. 7/26/05, Dyber: Left message for Cyril Parris. Spiller's phone number has been disconnected. 3/31/09 - Austin - Transferred from Needs Reassignment to Rahman for further work to remeidate and close - end 06/29/10 Reviewing the spill report, it seems that the spill was minor and it was cleaned up.Case closed.(sr)
Remarks:	VARIOUS AUTO FLUIDS TO CONCRETE-KERRI INVESTIGATIING SPILL WITH PARRIS
	Not reported

DRAFT

SHEPPARDS AUTO PARTS (Continued) **S102663479**

All Materials:

Site ID:	143269
Operable Unit ID:	1052021
Operable Unit:	01
Material ID:	331460
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D37 **SHEPHERD AVE GARAGE INC** **EDR Hist Auto** **1021041984**
WSW **352-362 SHEPHERD AV** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.039 mi.
206 ft. **Site 7 of 17 in cluster D**

Relative: EDR Hist Auto
Lower

Actual:
30 ft.

Year:	Name:	Type:
1969	SHEPHERD AVE GARAGE INC	Gasoline Service Stations
1969	SHEPHERD AVE GARAGE INC	Gasoline Service Stations
1970	SHEPHERD AVE GARAGE INC	Gasoline Service Stations
1971	SHEPHERD AVE GARAGE INC	Gasoline Service Stations
1972	SHEPHERD AVE GARAGE INC	Gasoline Service Stations
1973	SHEPHERD AVE GARAGE INC	General Automotive Repair Shops
1974	SHEPHERD AVE GARAGE INC	General Automotive Repair Shops
1975	SHEPHERD AVE GARAGE INC	General Automotive Repair Shops
1976	SHEPHERD AVE GARAGE INC	General Automotive Repair Shops
1977	SHEPHERD AVE GARAGE INC	General Automotive Repair Shops

D38 **777 GLENMORE AVE LLC** **NY MANIFEST** **S130582404**
SW **777 GLENMORE AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.043 mi.
228 ft. **Site 8 of 17 in cluster D**

Relative: NY MANIFEST:
Lower

Actual:
29 ft.

EPA ID:	NYR000242859
Country:	USA
Name:	777 Glenmore Ave Llc
Address:	777 GLENMORE AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	777 GLENMORE AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

DRAFT

777 GLENMORE AVE LLC (Continued) **S130582404**

Mailing:

Mailing Name:	777 Glenmore Ave Llc
Mailing Contact:	Sunshine Construction Llc
Mailing Address 1:	42 SKILLMAN ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11205
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

D39 **777 GLENMORE AVE LLC** **RCRA NonGen / NLR** **1025887705**
SW **777 GLENMORE AVE** **E MANIFEST** **NYR000242859**
< 1/8 **BROOKLYN, NY 11208**
0.043 mi.
228 ft. **Site 9 of 17 in cluster D**

Relative: **Lower**

Actual: **29 ft.**

RCRA Listings:

Date Form Received by Agency:	20200406
Handler Name:	777 Glenmore Ave Llc
Handler Address:	Glenmore Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYR000242859
Contact Name:	JOEL SCHWARTZ
Contact Address:	SKILLMAN ST
Contact City,State,Zip:	BROOKLYN, NY 11205
Contact Telephone:	718-222-3822
Contact Fax:	Not reported
Contact Email:	JOEL@SOUTHSIDEUNITS.COM
Contact Title:	OWNER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	SKILLMAN ST
Mailing City,State,Zip:	BROOKLYN, NY 11205
Owner Name:	777-778 Glenmore Avenue Llc
Owner Type:	Private
Operator Name:	Sunshine Construction Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200406
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	777-778 GLENMORE AVENUE LLC
Legal Status:	Private
Date Became Current:	20180205
Date Ended Current:	Not reported
Owner/Operator Address:	42 SKILLMAN ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11205
Owner/Operator Telephone:	718-222-3822
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JOEL@SOUTHSIDEUNITS.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SUNSHINE CONSTRUCTION LLC
Legal Status:	Private
Date Became Current:	20180205
Date Ended Current:	Not reported
Owner/Operator Address:	42 SKILLMAN ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11205
Owner/Operator Telephone:	718-222-3822
Owner/Operator Telephone Ext:	Not reported

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Owner/Operator Fax: Not reported
Owner/Operator Email: JOEL@SOUTHSIDEUNITS.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: SUNSHINE CONSTRUCTION LLC
Legal Status: Private
Date Became Current: 20180205
Date Ended Current: Not reported
Owner/Operator Address: 42 SKILLMAN ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11205
Owner/Operator Telephone: 718-222-3822
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JOEL@SOUTHSIDEUNITS.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: 777-778 GLENMORE AVENUE LLC
Legal Status: Private
Date Became Current: 20180205
Date Ended Current: Not reported
Owner/Operator Address: 42 SKILLMAN ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11205
Owner/Operator Telephone: 718-222-3822
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JOEL@SOUTHSIDEUNITS.COM

Historic Generators:
Receive Date: 20200406
Handler Name: 777 GLENMORE AVE LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20190909
Handler Name: 777 GLENMORE AVE LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 812930

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

NAICS Description: Parking Lots And Garages

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	013713861FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713863FLE
Last Updated Date:	20200713
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 GLENMORE AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Environmental Systems (Pa) Llc
Designated Facility Mail Street Number:	2869
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SANDSTONE DR
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	2869
Designated Facility Location Street 1:	SANDSTONE DR
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	HATFIELD
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713864FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713865FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Manifest Tracking Number:	013713866FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713867FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713868FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713869FLE
Last Updated Date:	20200109
Shipped Date:	20191007
Received Date:	20191007
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713870FLE
Last Updated Date:	20200109
Shipped Date:	20191010
Received Date:	20191010
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713871FLE
Last Updated Date:	20200109
Shipped Date:	20191010
Received Date:	20191010
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013713872FLE
Last Updated Date:	20200109
Shipped Date:	20191010
Received Date:	20191010
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000242859
Generator Name:	Sunshine Construction
Generator Location Street Number:	Not reported
Generator Location Street 1:	777 GLENMORE AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	777 Glenmore Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	013713873FLE
Transporter Line Number:	1
Transporter EPA ID:	NJR000029967
Transporter Name:	J And D Trucking

DRAFT

777 GLENMORE AVE LLC (Continued) **1025887705**

Waste Line:

Manifest Tracking Number:	013713873FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Na3077 Hazardous Waste, Solid, N.O.S. (Soil, Stone And Gravle) Iii 9 D008=10#
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DT
Container Type Description:	Dump truck
Waste Quantity:	44000
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	22
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	22
Waste Quantity, in Kilograms:	19954.66
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	19954.66
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	19954.66
Quantity Haz Tons:	22
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Click this hyperlink while viewing on your computer to access
23 additional US EManifest: record(s) in the EDR Site Report.

D40 **777 GLENMORE AVENUE** **NY VCP** **S129932637**
SW **777 GLENMORE AVENUE** **NY NYC OER** **N/A**
< 1/8 **BROOKLYN, NY**
0.043 mi.
228 ft. **Site 10 of 17 in cluster D**

Relative:
Lower

Actual:
29 ft.

VCP NYC:

Project ID:	18TMP1177K,18EH-A406K,19CVCP001K
Name:	777 GLENMORE AVENUE
Address:	777 GLENMORE AVENUE
City,State,Zip:	NEW YORK CITY, NY

DRAFT

777 GLENMORE AVENUE (Continued) **S129932637**

Borough:	Brooklyn
BBL:	3039880035
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.675337
Longitude:	-73.881543
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3088714
BIN:	3039880035
NTA:	East New York

NYC OER:

Name:	777 GLENMORE AVENUE
Address:	777 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.675337
Longitude:	-73.881543
OER Project Numbers:	18TMP1177K,18EH-A406K,19CVCP001K
BBL:	3039880035
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3088714
BIN:	3039880035
NTA:	East New York

D41 **CONSTRUCTION SITE** **NY Spills** **S125359921**
SW **368 SHEPHERD AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.043 mi.
229 ft. **Site 11 of 17 in cluster D**

Relative:
Lower

Actual:
29 ft.

SPILLS:

Name:	CONSTRUCTION SITE
Address:	368 SHEPHERD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1906045 / 2019-09-17
Facility ID:	1906045
Facility Type:	ER
DER Facility ID:	544058
Site ID:	594106
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2019-09-11
Investigator:	RJFENG
Referred To:	Not reported
Reported to Dept:	2019-09-11
CID:	Not reported

DRAFT

CONSTRUCTION SITE (Continued) **S125359921**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-11
Spill Record Last Update:	2019-09-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	UNKNOWN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	9/17/2019 - Feng - Duty Desk. Anonymous caller. Checked spill database and found closed Spill 19-05136. Rick Lin and Hermandeep Sekhon had inspected the site on 8/15/2019 and nothing has been found. Spill is closed and referred to 19-06045.
Remarks:	was a junkyard - no cleanup noted

D42 **LOT 35,TAXBLOCK 3988** **NY E DESIGNATION** **S118704317**
SW **368 SHEPHERD AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.043 mi.
229 ft. **Site 12 of 17 in cluster D**

Relative:
Lower

Actual:
29 ft.

E DESIGNATION:

Name:	LOT 35,TAXBLOCK 3988
Address:	368 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	35
Tax Block:	3988
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	368 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6755095
Longitude:	-73.8814417
Type Of Ownership Code:	Not reported
Owner Name:	777-787 GLENMORE AVENUE LLC

DRAFT

LOT 35,TAXBLOCK 3988 (Continued) **S118704317**

Borough:	BK
Tax Block:	3988
Tax Lot:	35
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001001
Census Tract 2010:	1166
Census Block 2010:	1001
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D3: Elevator Apartments - Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	6000
Total Building Floor Area:	26507
Commercial Floor Area:	0
Residential Floor Area:	26507
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	7.0000000
Residential Units:	32
Total Units:	32
Lot Frontage:	60.0000000
Lot Depth:	100.0000000
Building Frontage:	59.0000000
Building Depth:	70.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	189000.00000
Assessed Total Value:	2169450.00000

DRAFT

LOT 35,TAXBLOCK 3988 (Continued) **S118704317**

Exempt Total Value:	2087550.00000
Year Built:	2020
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.42000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039880035.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017136
Y Coordinate:	185405
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

B43 **3100 ATLANTIC AVE LLC** **NY UST** **U000411493**
NNE **803 LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.045 mi.
236 ft. **Site 9 of 15 in cluster B**

Relative:
Higher

Actual:
35 ft.

UST:

Name:	3100 ATLANTIC AVE LLC
Address:	803 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510084 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594646.07697
UTM Y:	4503503.57311
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21825
Affiliation Type:	Mail Contact
Company Name:	LIBERTY ONE GROUP
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY

DRAFT

3100 ATLANTIC AVE LLC (Continued) **U000411493**

Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2020-01-13

Site Id:	21825
Affiliation Type:	Facility Operator
Company Name:	803 LIBERTY AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569 206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-02

Site Id:	21825
Affiliation Type:	Emergency Contact
Company Name:	3100ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2020-01-13

Site Id:	21825
Affiliation Type:	Facility Owner
Company Name:	MORDY PERKOWSKI
Contact Type:	CONTRACTOR
Contact Name:	DANNY SINGH
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU

DRAFT

3100 ATLANTIC AVE LLC (Continued) **U000411493**

Date Last Modified: 2020-01-13

Tank Info:

Tank Number:	001
Tank ID:	39476
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	12/01/1948
Date Tank Closed:	11/03/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	08/23/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None

B44 **803 LIBERTY AVENUE** **UST FINDER** **1028571477**
NNE **803 LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11423**
0.045 mi.
236 ft. **Site 10 of 15 in cluster B**

Relative: **Higher**
Actual: **35 ft.**

UST FINDER:

Object ID:	295837
Facility ID:	NY21825
Name:	803 LIBERTY AVENUE
Address:	803 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11423
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9756
Private Wells 1500ft:	61
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity

DRAFT

803 LIBERTY AVENUE (Continued) **1028571477**

Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.880048
Y Coord:	40.676209
Latitude:	40.676209
Longitude:	-73.880048

UST FINDER:

Object ID:	1216770
Facility ID:	NY21825
Tank ID:	NY25829
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

C45 **LOT 16,TAXBLOCK 4005** **NY E DESIGNATION** **S118704128**
SSE **804 GLENMORE AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.047 mi.
247 ft. **Site 2 of 9 in cluster C**

Relative:
Lower

Actual:
30 ft.

E DESIGNATION:

Name:	LOT 16,TAXBLOCK 4005
Address:	804 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	16
Tax Block:	4005
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported

DRAFT

LOT 16,TAXBLOCK 4005 (Continued) **S118704128**

Address:	804 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6752696
Longitude:	-73.8803823
Type Of Ownership Code:	Not reported
Owner Name:	VERDUGO, GASTON RENE
Borough:	BK
Tax Block:	4005
Tax Lot:	16
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002000
Census Tract 2010:	1166
Census Block 2010:	2000
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	2
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported

DRAFT

LOT 16,TAXBLOCK 4005 (Continued) **S118704128**

Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	95850.00000
Assessed Total Value:	95850.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040050016.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017430
Y Coordinate:	185318
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

C46 **NY E DESIGNATION** **S118704057**
SE **810 GLENMORE AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.048 mi.
252 ft. **Site 3 of 9 in cluster C**

Relative: E DESIGNATION:
Lower

Name:	LOT 11,TAXBLOCK 4006
Address:	810 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	11
Tax Block:	4006
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

Actual:
30 ft.

DRAFT

(Continued) **S118704057**

NYC LAND USE:

Name:	Not reported
Address:	810 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6753351
Longitude:	-73.8799567
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 810 CORP
Borough:	BK
Tax Block:	4006
Tax Lot:	11
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192002004
Census Tract 2010:	1192
Census Block 2010:	2004
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G2: Garages And Gasoline Stations - Auto Body/Collision Or Auto Repair
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	2378
Commercial Floor Area:	2378
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	2378
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	40.0000000

DRAFT

(Continued) **S118704057**

Building Depth:	56.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	67500.00000
Assessed Total Value:	194400.00000
Exempt Total Value:	0.00000
Year Built:	1935
Year Altered 1:	1954
Year Altered 2:	1990
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.48000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040060011.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1017548
Y Coordinate:	185342
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

B47 **LOT 55,TAXBLOCK 3973** **NY E DESIGNATION** **S118704411**
North **BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.048 mi.
255 ft. **Site 11 of 15 in cluster B**

Relative: **Higher**
Actual: **34 ft.**

E DESIGNATION:

Name:	LOT 55,TAXBLOCK 3973
Address:	BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	55
Tax Block:	3973
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location

DRAFT

LOT 55,TAXBLOCK 3973 (Continued) **S118704411**

limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

C48 **LOT 13,TAXBLOCK 4006** **NY VCP** **S118704080**
SE **820 GLENMORE AVENUE** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY** **NY NYC LAND USE**
0.051 mi. **NY NYC OER**
268 ft. **Site 4 of 9 in cluster C**

Relative: Lower

Actual: 30 ft.

VCP NYC:

Project ID:	17TMP0600K,17EHAZ240K,18CVCP009K
Name:	820 GLENMORE AVENUE
Address:	820 GLENMORE AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,400,600,133,040,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.675563
Longitude:	-73.879881
Postcode:	5
Community Board:	37
Council District:	1192
Census Tract:	3000000
BIN:	3040060013
NTA:	East New York

E DESIGNATION:

Name:	LOT 13,TAXBLOCK 4006
Address:	820 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	13
Tax Block:	4006
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	820 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6753868
Longitude:	-73.8795889
Type Of Ownership Code:	Not reported
Owner Name:	820 GLENMORE AVE HOLDINGS LLC
Borough:	BK
Tax Block:	4006
Tax Lot:	13
Community District:	305
Census Tract 2020:	3119200

DRAFT

LOT 13,TAXBLOCK 4006 (Continued) **S118704080**

Census Block 2020:	31192002004
Census Tract 2010:	1192
Census Block 2010:	2004
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D3: Elevator Apartments - Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	15000
Total Building Floor Area:	68780
Commercial Floor Area:	0
Residential Floor Area:	68780
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	8.0000000
Residential Units:	79
Total Units:	79
Lot Frontage:	120.0000000
Lot Depth:	100.0000000
Building Frontage:	150.0000000
Building Depth:	64.5000000
Extension Code:	Not reported
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	405000.00000
Assessed Total Value:	4442850.00000
Exempt Total Value:	4305150.00000
Year Built:	2019
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported

DRAFT

LOT 13,TAXBLOCK 4006 (Continued) **S118704080**

Landmark Status:	Not reported
Built Floor Area Ratio:	4.59000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040060013.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1017650
Y Coordinate:	185361
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	3040060013.00000000
Apportionment Date:	09/20/2018
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	820 GLENMORE AVENUE
Address:	820 GLENMORE AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.675563
Longitude:	-73.879881
OER Project Numbers:	17TMP0600K,17EHAZ240K,18CVCP009K
BBL:	3.0400600133040001E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	5
Community Board:	37
Council District:	1192
Census Tract:	3000000
BIN:	3040060013
NTA:	East New York

E49 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031950985**
WNW **750 LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.057 mi.
301 ft. **Site 1 of 19 in cluster E**

Relative:
Lower

Actual:
29 ft.

E MANIFEST:

Manifest Tracking Number:	006857333GBF
Last Updated Date:	20210719
Shipped Date:	20210706
Received Date:	20210709
Manifest Status:	Signed
Submission Type:	DataImage5Copy

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950985**

Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	750 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006857333GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006857333GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950985**

Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

F50 **TRANSFORMER MANHOLE 1442** **NY Spills** **S105056583**
NE **ATKINS AVE & LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.058 mi.
306 ft. **Site 1 of 10 in cluster F**

Relative: **Higher**
Actual: **35 ft.**

SPILLS:

Name:	TRANSFORMER MANHOLE 1442
Address:	ATKINS AVE & LIBERTY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0100552 / 2001-04-18
Facility ID:	0100552
Facility Type:	ER
DER Facility ID:	266212
Site ID:	331003
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-04-15
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2001-04-15
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

DRAFT

TRANSFORMER MANHOLE 1442 (Continued) **S105056583**

Remediation Phase:	0
Date Entered In Computer:	2001-04-15
Spill Record Last Update:	2001-09-13
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY CON ED E2MIS REPORT 4-15-01 Found approx. 5gals.unknown oil while looking for fault. Crew to be dispatched to location to do a pressure test on unit. Only oil filled equipment instructure is transformer. 1 liquid sample taken. LSN 01-03698 61ppm Due to no I&A netwrok crew on schedule will be unable to pressure test and drain transformer FOD confirmed fault to be transformer. Unit to be pressure tested and drained on Monday morning. An over 50 tanker will start to remove all liquid from structure. 4-16-01 03:00hrs. While on location for cleanup found that this oil is from the transformer. Env. Ops crew and tanker remain on location. 0910hrs. I&A netwrok reports that there is more than 10gals. oil in structure. Network crew will start to pressure test and removed liquid from transformer as soon as FOD identify and tag transformer. Transformer has been dropped from FDR 9B08 Dipped unit and found no oil intransformer. Plate on transformer says cap. is 465gals. Tanker pulled out 260gals. in hole. engineer plates was unclear if structure is wewered. There is 205gal.of oil missing from transformer. Transformer holds 465gals. of oil and tanker removed approx. 260 gals. of oil. No water instructure. No sewer connection is visible at this time. Floor ducts visible, no sign of oil in ducts. Does not see any sign of oil in ducts. MH line was also checked and found no signs of oil. Flush crew removed 12 drums of oil soaked solid waste from structure. The dirt line is approx. 2' high from the floor. Emv.Ops crew has approx. another 3-55gal. drums of oil soaked dirt to complete a partial cleanup. Removal of transformer is scheduled for 4-17-01 0700hrs. After TM is removed there will be approx. another 10-55gal. drum of oilsaoked dirt to be remoed. 1225hrs. At this time we believe 205gals,of unaccountable oil is soaked in the dirt that is/has been removed from structure. After the cleanup is completed structure will be checked for any major cracks and any escape into the environment. Three more drum sof oil soaked waste was removed. Found floor drain pack with dirt. They removed dirt and found no signs of oil.Cemented floor drain. Crew removed 7more drums of dirt

DRAFT

TRANSFORMER MANHOLE 1442 (Continued) **S105056583**

for a total of 22 55-gal drums
removed. Double washed structure with Bio Gen 760. Tanker moved additional 100gals. of liquid for a
total of 360gals. Liquid removed by tanker. DEF Reactor was removed at 2030hrs. They install new
reactor at 2200hrs.

Remarks: they have to pressure test it before they start clean up - ref #136458 - transformer is not involved in the spill itself per the caller

All Materials:

Site ID:	331003
Operable Unit ID:	839285
Operable Unit:	01
Material ID:	536269
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F51 **CON ED - MH 3739** **RCRA NonGen / NLR** **1007206389**
NE **LIBERTY AVE & ATKINS AVE** **NY MANIFEST** **NYP004009163**
< 1/8 **BROOKLYN, NY 11212**
0.058 mi.
306 ft. **Site 2 of 10 in cluster F**

Relative: **Higher**
Actual: **35 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - Mh 3739
Handler Address:	Liberty Ave & Atkins Ave
Handler City,State,Zip:	BROOKLYN, NY 11212-0000
EPA ID:	NYP004009163
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported

DRAFT

CON ED - MH 3739 (Continued) **1007206389**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - MH 3739	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

DRAFT

CON ED - MH 3739 (Continued) **1007206389**

Receive Date: 19980228
Handler Name: CON ED - MH 3739
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - MH 3739
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004009163
Country: USA
Name: Consolidated Edison
Address: LIBERTY AVE & ATKINS AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11212-0000
Zip 4: Not reported
Location Address 1: MH 3739 - ATKINS AVE
Location Address 2: Not reported
Location City,State,Zip: QUEENS, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

DRAFT

CON ED - MH 3739 (Continued) **1007206389**

Mailing:
- Mailing Name: Consolidated Edison
- Mailing Contact: Franklin Murray
- Mailing Address 1: 4 IRVING PLACE RM 828
- Mailing Address 2: Not reported
- Mailing City,State,Zip: NEW YORK, NY 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124602808

Manifest Data:
- Document ID: NYG0096516
- Manifest Status: Not reported
- Trans1 State ID: 80416AB
- Year: 1997
- Trans2 State ID: Not reported
- Generator Ship Date: 07/11/1997
- Trans1 Recv Date: 07/11/1997
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 07/14/1997
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004009163
- Trans1 EPA ID: NYD006982359
- Trans2 EPA ID: Not reported
- TSDF ID 1: NYD980593636
- TSDF ID 2: Not reported
- Manifest Tracking Number: Not reported
- Import Indicator: Not reported
- Export Indicator: Not reported
- Discr Quantity Indicator: Not reported
- Discr Type Indicator: Not reported
- Discr Residue Indicator: Not reported
- Discr Partial Reject Indicator: Not reported
- Discr Full Reject Indicator: Not reported
- Manifest Ref Number: Not reported
- Alt Facility RCRA ID: Not reported
- Alt Facility Sign Date: Not reported
- MGMT Method Type Code: Not reported
- Waste Code 1: B002
- Waste Code 2: Not reported
- Waste Code 3: Not reported
- Waste Code 4: Not reported
- Waste Code 5: Not reported
- Waste Code 6: Not reported
- Quantity: 01345
- Units: Kilograms
- Number of Containers: 001
- Container Type: Cargo tanks (tank trucks)
- Handling Method: Treat
- Specific Gravity: 01.00

- Document ID: NYG0095031
- Manifest Status: Not reported
- Trans1 State ID: 80303AB
- Year: 1997

DRAFT

CON ED - MH 3739 (Continued) **1007206389**

Trans2 State ID:	Not reported
Generator Ship Date:	07/11/1997
Trans1 Recv Date:	07/11/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/14/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004009163
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

B52 **LOT 53,TAXBLOCK 3973** **NY E DESIGNATION** **S118704405**
North **68 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.058 mi.
307 ft. **Site 12 of 15 in cluster B**

Relative: **Higher**
Actual: **35 ft.**

E DESIGNATION:

Name:	LOT 53,TAXBLOCK 3973
Address:	68 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	53
Tax Block:	3973
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported

DRAFT

LOT 53,TAXBLOCK 3973 (Continued) **S118704405**

Description: Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	68 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6772107
Longitude:	-73.8809087
Type Of Ownership Code:	Not reported
Owner Name:	ALVAREZ, CARLOS JR
Borough:	BK
Tax Block:	3973
Tax Lot:	53
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001004
Census Tract 2010:	1168
Census Block 2010:	1004
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B2: Two Family Dwellings - Frame
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	2156
Commercial Floor Area:	0
Residential Floor Area:	2156
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	2.0000000
Residential Units:	2

DRAFT

LOT 53,TAXBLOCK 3973 (Continued) **S118704405**

Total Units:	2
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	22.0000000
Building Depth:	49.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	19800.00000
Assessed Total Value:	51780.00000
Exempt Total Value:	0.00000
Year Built:	1910
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.43000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039730053.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1017283
Y Coordinate:	186025
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

C53 **LOT 19,TAXBLOCK 4005** **NY E DESIGNATION** **S118704175**
SSE **148 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.058 mi.
308 ft. **Site 5 of 9 in cluster C**

Relative: **Lower**
Actual: **30 ft.**

E DESIGNATION:

Name:	LOT 19,TAXBLOCK 4005
Address:	148 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	19
Tax Block:	4005
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K

DRAFT

LOT 19,TAXBLOCK 4005 (Continued) **S118704175**

Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	148 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6750885
Longitude:	-73.8803826
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 112-114-148-152 CO RP.
Borough:	BK
Tax Block:	4005
Tax Lot:	19
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002000
Census Tract 2010:	1166
Census Block 2010:	2000
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2600
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7

DRAFT

LOT 19,TAXBLOCK 4005 (Continued) **S118704175**

Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	26.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	29250.00000
Assessed Total Value:	46350.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040050019.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017430
Y Coordinate:	185252
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

E54 **LOT 56,TAXBLOCK 3972** **NY E DESIGNATION** **S118704412**
WNW **749 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.060 mi.
318 ft. **Site 2 of 19 in cluster E**

Relative: **Lower**
Actual: **29 ft.**

E DESIGNATION:

Name:	LOT 56,TAXBLOCK 3972
Address:	749 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	56
Tax Block:	3972
Borough Code:	Not reported
E-No:	E-366

DRAFT

LOT 56,TAXBLOCK 3972 (Continued) **S118704412**

Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	749 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6767754
Longitude:	-73.8819911
Type Of Ownership Code:	Not reported
Owner Name:	RAMPERSAUD, HEMCHAND
Borough:	BK
Tax Block:	3972
Tax Lot:	56
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001005
Census Tract 2010:	1168
Census Block 2010:	1005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G1: Garages And Gasoline Stations - All Parking Garages
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	2605
Total Building Floor Area:	2166
Commercial Floor Area:	2166
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	2166
Storage Floor Area:	0

DRAFT

LOT 56,TAXBLOCK 3972 (Continued) **S118704412**

Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	25.8300000
Lot Depth:	100.8300000
Building Frontage:	25.8300000
Building Depth:	83.8300000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	46800.00000
Assessed Total Value:	121500.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	2004
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.83000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039720056.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016983
Y Coordinate:	185866
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

G55 **MANHOLE #68329** **NY Spills** **S106720768**
ESE **GLENMORE AVE / ATKINS AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.062 mi.
329 ft. **Site 1 of 5 in cluster G**

Relative: SPILLS:
Lower

Name:	MANHOLE #68329
Address:	GLENMORE AVE / ATKINS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0409404 / 2005-05-18

Actual:
30 ft.

DRAFT

MANHOLE #68329 (Continued) **S106720768**

Facility ID:	0409404
Facility Type:	ER
DER Facility ID:	269327
Site ID:	334131
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-11-19
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2004-11-19
CID:	64
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-20
Spill Record Last Update:	2005-05-18
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT DESK
Latitude:	40.6756570
Longitude:	-73.8792750
DEC Memo:	19-NOV-2004 10:35 HRS. UNDERGROUND DEPT.MECH-B A.FRESCA EMP# 17011 REPORTS he FOUND APPROX. 2qt OF UNKNOWN OIL ON APPROX. 50 GAL'S OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENIVIR. TAG# 44512 PLACED. 1 LIQ. SAMPLE TAKEN. Lab Sequence Number: 04-09633-001 Date Approved: 11/19/2004 TOTAL PCB 2545 ppm UPDATE 11/20/04 02:21 ENV OPS A. GLODOWSKI REPORTS UNCAPPED CABLE ENDS IN STRUCTURE. An Environmental Crew set up zones at M68329 on 20 Nov 2004. #9 was called and they capped two oil cable ends. A sump was found cemented. The structure was double washed using 10 gal. Biogen 715, 5 gal Biogen 760, and 2.5 gal. Safety Wash. 175 gal of liquid was sucked up by an Astoria >50 tanker. UPDATE 12/14/04 19:38 HRS ENV SUPV R. QUIJIJE REPORTS THAT THE TANKER REMOVED 1,000 GALS OF WASH LIQUID, 2 DRUMS OF PPE, ZONE MATERIAL, AND USED SODA BLAST MATERIAL WERE GENERATED AND PICKED UP BY CORPORATE TRANSPORTATION. THE SODA BLAST WAS COMPLETED 100% AND THE CHEMIST TOOK 9 WIPE SAMPLES. THE ENV TAG REMAINS IN PLACE PENDING LAB RESULTS. WIPE RESULTS RECEIVED 12/15/04 - 1459. 8 WIPE RESULTS CAME BACK AND ALL 8 WIPES (TEST POINTS 1 THROUGH 8) PASSED (LSN# FOR ABOVE SAMPLES IS 04-10401). 1 WIPE

DRAFT

MANHOLE #68329 (Continued) **S106720768**

SAMPLE WAS NOT TAKEN. FOLLOW UP REQUIRED TO TAKE ONE MORE WIPE. Lab Sequence Number: 04-10481-001
Date DESCRIPTION: TEST POINT NO.9 Aroclor 1254 1.0 ug/100cm^2 EPA 608/8082 LAST WIPE PASSED. TAG
CAN BE REMOVED AND INCIDENT CLOSED. Update - 12/17/04 1205hrs E. Williams, env. ops OS reports
removed env. stop tag # 44512. Incident closed.

Remarks: pcb count 2545 ppm. No to 5 questions. 4 qts of pcb oil. See e2MIS # 156307.

All Materials:

Site ID:	334131
Operable Unit ID:	1096269
Operable Unit:	01
Material ID:	576181
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B56 **LOT 52,TAXBLOCK 3973** **NY E DESIGNATION** **S118704400**
North **66 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.062 mi.
330 ft. **Site 13 of 15 in cluster B**

Relative: **Higher**
Actual: **34 ft.**

E DESIGNATION:

Name:	LOT 52,TAXBLOCK 3973
Address:	66 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	52
Tax Block:	3973
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	66 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6773123
Longitude:	-73.8809338
Type Of Ownership Code:	Not reported
Owner Name:	FLEX NY LLC
Borough:	BK

DRAFT

LOT 52,TAXBLOCK 3973 (Continued) **S118704400**

Tax Block:	3973
Tax Lot:	52
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001004
Census Tract 2010:	1168
Census Block 2010:	1004
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G1: Garages And Gasoline Stations - All Parking Garages
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	2500
Commercial Floor Area:	2500
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	2500
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	25.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	45000.00000
Assessed Total Value:	292950.00000
Exempt Total Value:	0.00000

DRAFT

LOT 52,TAXBLOCK 3973 (Continued) **S118704400**

Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.00000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039730052.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1017276
Y Coordinate:	186062
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

D57 **NY E DESIGNATION** **S118704174**
SSW **390 SHEPHERD AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.063 mi.
334 ft. **Site 13 of 17 in cluster D**

Relative:
Lower

Actual:
28 ft.

E DESIGNATION:

Name:	LOT 19,TAXBLOCK 4004
Address:	390 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	19
Tax Block:	4004
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	390 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6750867
Longitude:	-73.8813343

DRAFT

(Continued) **S118704174**

Type Of Ownership Code:	Not reported
Owner Name:	1775 NOSTRAND AVENUE LLC
Borough:	BK
Tax Block:	4004
Tax Lot:	19
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002001
Census Tract 2010:	1166
Census Block 2010:	2001
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V0: Vacant Land - Zoned Residential; Not Manhattan
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5

DRAFT

(Continued) **S118704174**

Assessed Land Value:	12300.00000
Assessed Total Value:	12300.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040040019.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017166
Y Coordinate:	185251
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

C58 **LOT 20,TAXBLOCK 4005** **NY E DESIGNATION** **S118704200**
SSE **152 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.063 mi.
334 ft. **Site 6 of 9 in cluster C**

Relative:
Lower

Actual:
30 ft.

E DESIGNATION:

Name:	LOT 20,TAXBLOCK 4005
Address:	152 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	20
Tax Block:	4005
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported

DRAFT

LOT 20,TAXBLOCK 4005 (Continued) **S118704200**

Address:	152 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6750226
Longitude:	-73.8803683
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 112-114-148-152 CO RP.
Borough:	BK
Tax Block:	4005
Tax Lot:	20
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002000
Census Tract 2010:	1166
Census Block 2010:	2000
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2400
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	24.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	N

DRAFT

LOT 20,TAXBLOCK 4005 (Continued) **S118704200**

Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	27000.00000
Assessed Total Value:	45000.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040050020.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017434
Y Coordinate:	185228
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

D59 **NY E DESIGNATION** **S118704199**
SSW **392 SHEPHERD AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.067 mi.
352 ft. **Site 14 of 17 in cluster D**

Relative: E DESIGNATION:
Lower

Name:	LOT 20,TAXBLOCK 4004
Address:	392 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	20
Tax Block:	4004
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

Actual:
28 ft.

DRAFT

(Continued) **S118704199**

NYC LAND USE:

Name:	Not reported
Address:	392 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6750181
Longitude:	-73.8813200
Type Of Ownership Code:	Not reported
Owner Name:	15 EAST 19TH LLC
Borough:	BK
Tax Block:	4004
Tax Lot:	20
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002001
Census Tract 2010:	1166
Census Block 2010:	2001
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V0: Vacant Land - Zoned Residential; Not Manhattan
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000

DRAFT

(Continued) **S118704199**

Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	12300.00000
Assessed Total Value:	12300.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040040020.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017170
Y Coordinate:	185226
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

D60 **NYC DEP** **NY Spills** **1014395574**
SSW **394 SHEPHERD AVE** **RCRA NonGen / NLR** **NYP003664794**
< 1/8 **BROOKLYN, NY 11208** **NY MANIFEST**
0.068 mi. **NJ MANIFEST**
360 ft. **Site 15 of 17 in cluster D**

Relative: **Lower**
Actual: **28 ft.**

SPILLS:

Name:	DRUM RUN
Address:	394 SHEPHERD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2210047 / 2023-05-08
Facility ID:	2210047
Facility Type:	ER
DER Facility ID:	595464
Site ID:	649445
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C2
SWIS:	2401
Spill Date:	2023-03-21
Investigator:	RHLIN

DRAFT

NYC DEP (Continued) **1014395574**

Referred To:	Not reported
Reported to Dept:	2023-03-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2023-03-21
Spill Record Last Update:	2023-05-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MOHAMMED
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Several abandoned drums on vacant lot. DOH issued commissioners order to clean. No response from RP. Assigned to DEC Lin for Drum run to determine if DEC will accept. 5/8/23-Lin-Three (3) 55 gallon drums were removed. One (1) 55 gallon of water/oil mixture was punctured on the bottom of the tank. No overpack was available. The drum was left on the side so it's not leaking. Case closed.
	Not reported
Remarks:	3 55 gall and 1 30 gall - for drum run

All Materials:

Site ID:	649445
Operable Unit ID:	1396402
Operable Unit:	01
Material ID:	2412400
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20150630
Handler Name:	Nyc Dep
Handler Address:	Shepherd Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP003664794
Contact Name:	JOANNE NURSE
Contact Address:	JUNCTION BLVD
Contact City,State,Zip:	FLUSHING, NY 11373
Contact Telephone:	718-595-4675

DRAFT

NYC DEP (Continued) **1014395574**

Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		PAA
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		JUNCTION BLVD
Mailing City,State,Zip:		FLUSHING, NY 11373
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20170425
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

DRAFT

NYC DEP (Continued) **1014395574**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20100629
Handler Name: NYC DEP	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150630
Handler Name: NYC DEP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP003664794
Country:	USA
Name:	Nyc Dep
Address:	394 SHEPHERD AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	394 SHEPHERD AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

DRAFT

NYC DEP (Continued) **1014395574**

Mailing:
- Mailing Name: Nyc Dep
- Mailing Contact: Nycdep
- Mailing Address 1: 96-05 HORACE HARDING EXPRESSWAY
- Mailing Address 2: Not reported
- Mailing City,State,Zip: CORONA, NY 11368
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: Not reported

Manifest Data:
- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NYD064748304
- Year: 2018
- Trans2 State ID: NJD080631369
- Generator Ship Date: 06/11/2010
- Trans1 Recv Date: 06/11/2010
- Trans2 Recv Date: 06/11/2010
- TSD Site Recv Date: 06/23/2010
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP003664794
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID 1: NJD980536593
- TSDF ID 2: Not reported
- Manifest Tracking Number: 006657578JJK
- Import Indicator: N
- Export Indicator: N
- Discr Quantity Indicator: N
- Discr Type Indicator: N
- Discr Residue Indicator: N
- Discr Partial Reject Indicator: N
- Discr Full Reject Indicator: N
- Manifest Ref Number: Not reported
- Alt Facility RCRA ID: Not reported
- Alt Facility Sign Date: Not reported
- MGMT Method Type Code: H141
- Waste Code a: Ignitable Waste
- Waste Code b: Tetrachloroethylene
- Waste Code c: Not reported
- Waste Code e: Not reported
- Waste Code f: Not reported
- Waste Code g: Not reported
- Waste Code 1: Not reported
- Waste Code 2: Not reported
- Waste Code 3: Not reported
- Waste Code 4: Not reported
- Waste Code 5: Not reported
- Waste Code 6: Not reported
- Quantity: 500
- Units: Pounds
- Number of Containers: 4
- Container Type: Metal drums, barrels, kegs
- Handling Method: Burn

DRAFT

NYC DEP (Continued) **1014395574**

Specific Gravity: 1

NJ MANIFEST:

EPA ID:	NYP003664794
Name:	NYC DEP
Address:	394 SHEPHERD AVE
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	JUNCTION BLVD
Mailing City,State,Zip:	FLUSHING, NY 11373
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	JOANNE NURSE
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP003664794
Manifest Number:	006657578JJK
Date Shipped:	06/11/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/11/2010
Date Trans2 Transported Waste:	06/11/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/23/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

DRAFT

NYC DEP (Continued) **1014395574**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	500
Unit:	P

C61 **LOT 21,TAXBLOCK 4005** **NY E DESIGNATION** **S118704215**
SSE **154 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.069 mi.
366 ft. **Site 7 of 9 in cluster C**

Relative: **Lower**
Actual: **30 ft.**

E DESIGNATION:

Name:	LOT 21,TAXBLOCK 4005
Address:	154 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	21
Tax Block:	4005
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	154 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6749265
Longitude:	-73.8803432
Type Of Ownership Code:	Not reported
Owner Name:	ACCURATE ORGANIZATION 154 CORP.
Borough:	BK
Tax Block:	4005
Tax Lot:	21
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002000
Census Tract 2010:	1166

DRAFT

LOT 21,TAXBLOCK 4005 (Continued) **S118704215**

Census Block 2010:	2000
School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	F5: Factory And Industrial Buildings - Light Manufacturing
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	5000
Commercial Floor Area:	5000
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	5000
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	50.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	90000.00000
Assessed Total Value:	235800.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.00000000000

DRAFT

LOT 21,TAXBLOCK 4005 (Continued) **S118704215**

Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040050021.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017441
Y Coordinate:	185193
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

C62 **CON EDISON** **NY MANIFEST** **S117537543**
South **156 BERRIMON ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.069 mi.
366 ft. **Site 8 of 9 in cluster C**

Relative:
Lower

Actual:
29 ft.

NY MANIFEST:

EPA ID:	NYP004701181
Country:	USA
Name:	Con Edison
Address:	156 BERRIMON ST
Address 2:	SB 22290
City,State,Zip:	BROOKLYN, NY
Zip 4:	Not reported
Location Address 1:	156 BERRIMON ST
Location Address 2:	SB 22290
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047

DRAFT

CON EDISON (Continued) **S117537543**

Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/01/2014
Trans1 Recv Date:	12/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004701181
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618533GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	20
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

C63 **CON EDISON** **NY MANIFEST** **S117537698**
South **156 BERRIMAN** **N/A**
< 1/8 **BROOKLYN, NY**
0.069 mi.
366 ft. **Site 9 of 9 in cluster C**

Relative: NY MANIFEST:
Lower

EPA ID:	NYP004702874
Country:	USA
Name:	Con Edison
Address:	156 BERRIMAN
Address 2:	SB 22290
City,State,Zip:	BROOKLYN, NY

Actual:
29 ft.

DRAFT

CON EDISON (Continued) **S117537698**

Zip 4: Not reported
Location Address 1: 156 BERRIMAN
Location Address 2: SB 22290
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: NJD003812047
Generator Ship Date: 12/04/2014
Trans1 Recv Date: 12/04/2014
Trans2 Recv Date: 12/08/2014
TSD Site Recv Date: 12/08/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004702874
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002416997GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported

DRAFT

CON EDISON (Continued) **S117537698**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

B64 **LOT 50,TAXBLOCK 3973** **NY E DESIGNATION** **S118704393**
North **BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.070 mi.
370 ft. **Site 14 of 15 in cluster B**

Relative: **Higher**
Actual: **35 ft.**

E DESIGNATION:

Name:	LOT 50,TAXBLOCK 3973
Address:	BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	50
Tax Block:	3973
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

B65 **CARBUSTERS AUTO RECYCLING LLC** **NY SWF/LF** **S108145756**
North **60 BERRIMAN STREET** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.070 mi.
372 ft. **Site 15 of 15 in cluster B**

Relative: **Higher**
Actual: **35 ft.**

SWF/LF:

Name:	CARBUSTERS AUTO RECYCLING LLC
Address:	60 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Flag:	INACTIVE
Region Code:	2
Phone Number:	7182350242
Owner Name:	Joseph Zuccaro
Owner Type:	Private
Owner Address:	60 Berriman Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Email:	Not reported
Owner Phone:	7182350242
Contact Name:	Joseph Zuccaro

DRAFT

CARBUSTERS AUTO RECYCLING LLC (Continued) **S108145756**

Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[24J--]
Active:	No
East Coordinate:	594595
North Coordinate:	4503491
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

SPILLS:

Name:	CAR BUSTERS
Address:	60 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0551819 / 2009-10-08
Facility ID:	0551819
Facility Type:	ER
DER Facility ID:	312027
Site ID:	361785
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-29
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-29
Spill Record Last Update:	2009-10-09
Spiller Name:	Not reported
Spiller Company:	CAR BUSTERS
Spiller Address:	60 BERRY STREET
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6774380
Longitude:	-73.8807440
DEC Memo:	04/03/06-Hiralkumar Patel. Owner: Stuart Goldstein Berriman Street

DRAFT

CARBUSTERS AUTO RECYCLING LLC (Continued) **S108145756**

Associates 888 7th Ave - 24th
Flr New York, NY 10106-0001 PH. (212) 755-5390 EXt. 305 CSL sent out to Stuart Goldstein.
04/04/06-Hiralkumar Patel. DEC_Steve asked me to send the same letter to property owner, listed in
property shark list. Joseph Zuccaro 81 Miriam Street Valley Stream, NY 11581-1320 letter sent out
to owner. copy given to ECO. 04/06/06-Hiralkumar Patel. Received message from Jim Vest
(212-660-1200 Ext. 309), who is handling this property. as per him, property has gas heating system
and doesn't have any kind of oil tank, burner etc. Left message for Jim. 05/04/06-Hiralkumar Patel.
Left message for Jim. 05/11/06-Hiralkumar Patel. Left message for Jim. 05/15/06-Hiralkumar Patel.
Received call from Jim(Cell: 973-641-1139). as per him, there is no open spot, which has soil. all
property area is covered by concrete floor and property has commercial buildings like garage and
warehouses. the property side at Berryman street is touching sidewalk and there they have garage
opening. Jim is not sure about which part of site has contamination that DEC officer observed. he
wants to meet on site. 05/17/06-Hiralkumar Patel. Spoke to Jim and ECO. meeting both on site at
2:30 PM tomorrow. 05/18/06-Hiralkumar Patel. visited site with DEC Vought and ECOs. spoke to Joseph
Zuccaro, owner of property. property has piles of junk of broken parts from cars. owner is selling
this property and is in contract stage. but new owner wants those piles cleaned up from site before
they buy it, as buyer wants to do soil investigation. Mr. Zuccaro is removing piles and will be
done by July 1, 2006. buyer has planning to develop this property as residential complex. Mr.
Zuccaro denied to give buyer's information, but he is taking responsibilty of cleanup and will sign
STIP. he was also agree to forward copy of the STIP to buyer once they sell out property. DEC
Vought suggest him to inform DEC when he removes all the piles from ground, so we can see soil and
floor condition as currently most of the area is covered by these piles. he agreed with this and
will remove everything from ground for better insepction. he will not remove racks and junk from
racks by July 1. property has few ASTs onsite. as per Mr. Zuccaro, he doesn't keep gas tank from
the cars, so doesn't store any waste oil tank on location. property has multiple ASTs. few are in
use to store diesel for internal use. ECO Jeff mentioned that they have issued some violations
against Mr. Zuccaro. Carbusters Auto Recycling 66 Berriman Street, Brooklyn, NY 11208 (718)
235-0242 05/19/06-Hiralkumar Patel. Received message from Jim. after talking to Jim, found that Jim
was talking about site at 60 Berry STreet in Brooklyn. as DEC got this address in initial spill

DRAFT

CARBUSTERS AUTO RECYCLING LLC (Continued) **S108145756**

report, first letter sent out at this address, but that was not the site. ask Jim to disregard the
letter that he has from the Department. 05/23/06-Hiralkumar Patel. STIP sent out to Mr. Zuccaro at
following address: Joseph Zuccaro 81 Miriam Street Valley Stream, NY 11581-1320 Ph. (516) 872-8747
(H) (718) 235-0242 (Off., site) (516) 523-7039 (C) FAX (718) 235-8703 email: carbustersauto@aol.com
STIP sent out in registered mail (7005 1160 0000 6901 1261). faxed to Mr. Zuccaro.
06/02/06-Hiralkumar Patel. REceived certified mail receipt.
07/10/06-Hiralkumar Patel. Left message
for Joseph. 07/12/06-Hiralkumar Patel. Received message from Joseph (718-235-7015). Left message
for Mr. Zuccaro. received call from Mr. Zuccaro. he will check wiht his secretary and will send
STIP soon. he is still removing piles from area. asked to call the department once he removes all
piles from spot. 08/14/06-Hiralkumar Patel. left message for Joseph. 09/27/06-Hiralkumar Patel.
after discussing with DEC Austin and DEC Urda, case transferred to legal department. Mr. Urda is
working on this case. 05/27/08-Hiralkumar Patel. visited site as DEC Urda requested to know number
and size of tanks and type of product stored. visited site with ECO Markey. found three 275 gal
tanks at the site. two 275 gal diesel tanks were located at elevated platform. one 275 gal waste
oil tank was found on floor but covered entired with junk and only top was visible. met Joseph at
the site. he is still running business. Joseph mentioned that NYC HPD is buying this property.
asked Joseph to provide contact at NYC HPD. left message for John Garrity at NYC HPD to know status
of transaction. John Garrity NYC HPD Director, Environmental Remediaton & Special Projects Unit Ph.
(212) 863-8052 Fax (212) 863-7988 03/02/09-Hiralkumar Patel. spoke with DEC Urda. no updates yet.
10/08/09-Hiralkumar Patel. received call from DEC Urda. he requested to visit site again (with ECO)
to confirm contamination (take pics). 2:45 PM:- visited site with ECO Neil Stevens. most of the
site was covered by junk stockpile (more than during initial site visit). found middle portion
cleaned up and solid concrete in visible areas. some stains found on concrete, but no oil. other
areas were covered with piles. based on observations during the site visit, case closed. **Do not
take site visit without ECO**

Remarks: During inspection, a significant amount of engine blocks/ transmissions piled on soil. Excavation w/ foot revealed oil coming into depression. ***** Do not attempt to visit site without armed escort!*****

All Materials:
Site ID: 361785
Operable Unit ID: 1119899
Operable Unit: 01

DRAFT

CARBUSTERS AUTO RECYCLING LLC (Continued) **S108145756**

Material ID:	2109368
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E66 **LOT 57,TAXBLOCK 3972** **NY E DESIGNATION** **S118704414**
NW **745 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.071 mi.
376 ft. **Site 3 of 19 in cluster E**

Relative:
Lower

Actual:
29 ft.

E DESIGNATION:

Name:	LOT 57,TAXBLOCK 3972
Address:	745 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	57
Tax Block:	3972
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	745 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6767564
Longitude:	-73.8821245
Type Of Ownership Code:	Not reported
Owner Name:	745 LIBERTY AVENUE CORP.
Borough:	BK
Tax Block:	3972
Tax Lot:	57
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001005
Census Tract 2010:	1168
Census Block 2010:	1005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820

DRAFT

LOT 57,TAXBLOCK 3972 (Continued) **S118704414**

Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G9: Garages And Gasoline Stations - Miscellaneous Garage Or Gas Station
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	540
Commercial Floor Area:	540
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	540
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	18.0000000
Building Depth:	30.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	28350.00000
Assessed Total Value:	57150.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.11000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039720057.00000000
Condominium Number:	Not reported

DRAFT

LOT 57,TAXBLOCK 3972 (Continued) **S118704414**

Census Tract 2:	1168
X Coordinate:	1016946
Y Coordinate:	185859
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

E67 **MANHOLE # 4748** **NY Spills** **S107787977**
WNW **ESSEX STREET AND LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.075 mi.
397 ft. **Site 4 of 19 in cluster E**

Relative: **Lower**

Actual: **28 ft.**

SPILLS:

Name:	MANHOLE # 4748
Address:	ESSEX STREET AND LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0601418 / 2008-01-10
Facility ID:	0601418
Facility Type:	ER
DER Facility ID:	313815
Site ID:	363646
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-05-08
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-05-08
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-08
Spill Record Last Update:	2008-01-10
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	ESSEX AND LIBERTY AVE
Spiller Company:	999
Contact Name:	ERT DESK'
Latitude:	Not reported
Longitude:	Not reported

DRAFT

MANHOLE # 4748 (Continued) **S107787977**

DEC Memo: 01/10/08 - See eDocs for Con Ed report detailing cleanup and closure. 164155. 08-MAY-2006 11:09 HRS. I&A DEPT.DIST. MECH-A R.WIBREW EMP# 85884 REPORTS: WHILE ON LOCATION TO CHANGE SERVICE M4748 (ACC#23959) FOUND: APPROX. 2QT OF DIELECTRIC FEEDER FLUID FROM A LEAKING JOINT (FEEDER# L-27) (D-FAULT TAG# 03871) ON APPROX. 60 GALS OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. THE SPILL APPEARS TO BE CONTAINED AT THIS TIME. THERE IS NO FIRE INVOLVEMENT .NO SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. THERE ARE NO INCLEMENT WEATHER CONDITIONS OR HAZARD THAT CONTRIBUTED TO THIS SPILL. NO PRIVATE PROPERTY AFFECTED. OWNER OF SUBSTANCES IS CONED. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENIVIR. TAG# 45199 PLACED. 1 LIQ. SAMPLE TAKEN FROM SPILL & MARKED PRIORITY E . CHAIN OF CUSTODY# DD-21312. SAMPLE TO BE TAKEN TO ASTORIA CHEM. N/P S/W/C . CLEANUP PENDING SAMPLE RESULTS & FEEDER DENERGIZATION. C.HOGAN 07511

Remarks: feeder leaking and hole is defaulted:no to 5 questions: coned # 164155

Not reported

All Materials:

Site ID:	363646
Operable Unit ID:	1121695
Operable Unit:	01
Material ID:	2111195
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E68 **CON EDISON** **NY MANIFEST** **S117736597**
WNW **LIBERTY AVE & ESSEX ST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.075 mi.
397 ft. **Site 5 of 19 in cluster E**

Relative: **Lower**
Actual: **28 ft.**

NY MANIFEST:

EPA ID:	NYP004539136
Country:	USA
Name:	Con Edison
Address:	LIBERTY AVE & ESSEX ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	LIBERTY AVE & ESSEX ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

DRAFT

CON EDISON (Continued) **S117736597**

Mailing:
- Mailing Name: Con Edison
- Mailing Contact: Con Edison
- Mailing Address 1: 4 IRVING PL
- Mailing Address 2: 15TH FL
- Mailing City,State,Zip: NEW YORK, NY 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: Not reported

Manifest Data:
- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NJ0000027193
- Year: 2018
- Trans2 State ID: Not reported
- Generator Ship Date: 05/20/2014
- Trans1 Recv Date: 05/20/2014
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 05/23/2014
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004539136
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID 1: NJD002200046
- TSDF ID 2: Not reported
- Manifest Tracking Number: 013246086JJK
- Import Indicator: N
- Export Indicator: N
- Discr Quantity Indicator: N
- Discr Type Indicator: N
- Discr Residue Indicator: N
- Discr Partial Reject Indicator: N
- Discr Full Reject Indicator: N
- Manifest Ref Number: Not reported
- Alt Facility RCRA ID: Not reported
- Alt Facility Sign Date: Not reported
- MGMT Method Type Code: H110
- Waste Code a: Lead
- Waste Code b: Not reported
- Waste Code c: Not reported
- Waste Code e: Not reported
- Waste Code f: Not reported
- Waste Code g: Not reported
- Waste Code 1: Not reported
- Waste Code 2: Not reported
- Waste Code 3: Not reported
- Waste Code 4: Not reported
- Waste Code 5: Not reported
- Waste Code 6: Not reported
- Quantity: 300
- Units: Gallons (liquids only)
- Number of Containers: 1
- Container Type: Cargo tanks (tank trucks)
- Handling Method: Treat

DRAFT

CON EDISON (Continued) **S117736597**

Specific Gravity: 1

E69 **CON EDISON** **RCRA NonGen / NLR** **1012185325**
WNW **LIBERTY AVE & ESSEX ST** **NY MANIFEST** **NYP004161295**
< 1/8 **BROOKLYN, NY 11201**
0.075 mi.
397 ft. **Site 6 of 19 in cluster E**

Relative: **Lower**

Actual: **28 ft.**

RCRA Listings:

Date Form Received by Agency:	20160601
Handler Name:	Con Edison
Handler Address:	Liberty Ave & Essex St
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004161295
Contact Name:	DANIEL PONTECORVO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-203-2573
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

DRAFT

CON EDISON (Continued) **1012185325**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160609
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20080919
Handler Name: CON EDISON	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

DRAFT

CON EDISON (Continued) **1012185325**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004161295
Country:	USA
Name:	Consolidated Edison
Address:	LIBERTY AVE & ESSEX ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	ESSEX ST & LIBERTY AVE
Location Address 2:	MH4748
Location City,State,Zip:	brooklyn, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklyn Murray
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	09/19/2008
Trans1 Recv Date:	09/19/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/22/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004161295
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001432881FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

DRAFT

CON EDISON (Continued) **1012185325**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	B002
Waste Code c:	B007
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Kilograms
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

E70 **CON EDISON** **RCRA NonGen / NLR** **1017776064**
WNW **LIBERTY AVE & ESSEX ST** **NYP004539136**
< 1/8 **BROOKLYN, NY 11208**
0.075 mi.
397 ft. **Site 7 of 19 in cluster E**

Relative: **Lower**
Actual: **28 ft.**

RCRA Listings:

Date Form Received by Agency:	20140521
Handler Name:	Con Edison
Handler Address:	Liberty Ave & Essex St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004539136
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No

DRAFT

CON EDISON (Continued) **1017776064**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150814
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140521
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140521
Handler Name: CON EDISON	

DRAFT

CON EDISON (Continued) **1017776064**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140621
Handler Name:	CON EDISON MANHOLE: 4748
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D71 **MANHOLE # 67930** **NY Spills** **S106720608**
SW **GLEN MORE AVE/ESSEX STREE** **N/A**
< 1/8 **BROOKLYN, NY**
0.077 mi.
409 ft. **Site 16 of 17 in cluster D**

Relative: **Lower**
Actual: **28 ft.**

SPILLS:

Name:	MANHOLE # 67930
Address:	GLEN MORE AVE/ESSEX STREE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0409636 / 2005-12-27
Facility ID:	0409636
Facility Type:	ER
DER Facility ID:	269654
Site ID:	334434
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-11-29
Investigator:	JHOCONNE
Referred To:	Not reported

DRAFT

MANHOLE # 67930 (Continued) **S106720608**

Reported to Dept:	2004-11-29
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-30
Spill Record Last Update:	2005-12-27
Spiller Name:	ERT DESK
Spiller Company:	MANHOLE # 67930
Spiller Address:	GLEN MORE AVE/ESSEX STREE
Spiller Company:	001
Contact Name:	ERT DESK
Latitude:	40.6752600
Longitude:	-73.8820220
DEC Memo:	e2mis no. 156396: 11/29/2004 10:30 HRS. A. FRESCA #17011 OF QUEENS UNDERGROUND REPORTS WHILE ON LOCATION IN BROOKLYN FOR PRE-INSPECTION OF FEEDER 9B10 AT 10:15 HRS. FOUND APPROX. 1/2 GAL. OIL ON MUD ON FLOOR OF MH-67390. HE DETERMINED SOURCE TO BE A LEAKING JOINT, BASED ON FINDING OIL ON ARC-PROOFING AND A PUDDLE OF OIL UNDER JOINT. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. ENV STOP TAG # 27779 PLACED. SAMPLE OF OIL & MUD WAS TAKEN (UNABLE TO GET JUST OIL). CHAIN OF CUSTODY FORM # DD-12895 MARKED FOR E PRIORITY TURNAROUND. CLEANUP PENDING RESULTS FROM CHEM LAB & REPAIR OF D FAULT CONDITION. Monday, November 29, 2004 8:27 PM Lab Sequence Number: 04-09879-001 TOTAL PCB 32 ppm D FAULT # 7909 - TAG # 02115 PLACED 11/29/2004 - FEEDER 9B10. 4/20/05 12:40 HRS. -- AS PER FEEDER CONTROL REP. JOHN SANTORA, JOINT IS CUT OUT AND CABLES CAPPED, D FAULT TAG REMOVED AND OKAY TO COMPLETE CLEANUP. UPDATE 20-APR-2005 17:56 HRS. ENVIR. OPER. MECH-A D.BANKHEAD EMP# 64999 REPORTS: PLACED EVP IN STRUCTURE TO SOAK. C.HOGAN 07511 UPDATE: 4/26/05 - 0220 K. COLANERO - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. SUMP FOUND CEMENTED. TAG # 27779 REMOVED. TJ - 50495
Remarks:	DEFAULT ON FEEDER IN HOLE; OIL CAME FROM A JOINT SPILLED ONTO FLOOR: NO TO 5 QUESTIONS: WENT ONTO MUD # 156396 CONED #

All Materials:

Site ID:	334434
Operable Unit ID:	1096568
Operable Unit:	01
Material ID:	576481
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

DRAFT

MANHOLE # 67930 (Continued) **S106720608**

Units: G
Recovered: .00
Oxygenate: Not reported

E72 **CON ED** **NY MANIFEST** **S118259004**
West **320 ESSEX ST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.078 mi.
412 ft. **Site 8 of 19 in cluster E**

Relative: **Lower**
Actual: **29 ft.**

NY MANIFEST:

EPA ID:	NYP004824732
Country:	USA
Name:	Con Ed
Address:	320 ESSEX ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	320 ESSEX ST
Location Address 2:	SB 62385
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Ed
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/2015
Trans1 Recv Date:	08/17/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004824732
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014466322JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

DRAFT

CON ED (Continued) **S118259004**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

E73 **CON EDISON** **NJ MANIFEST** **S120675442**
West **320 ESSEX ST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.078 mi.
412 ft. **Site 9 of 19 in cluster E**

Relative: **Lower**

Actual: **29 ft.**

NJ MANIFEST:

EPA ID:	NYP004824732
Name:	CON EDISON
Address:	320 ESSEX ST
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004824732

DRAFT

CON EDISON (Continued) **S120675442**

Manifest Number:	014466322JJK
Date Shipped:	8/17/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

E74 **CON EDISON** **RCRA NonGen / NLR** **1019906646**
West **320 ESSEX ST** **FINDS** **NYP004824732**
< 1/8 **BROOKLYN, NY 11208** **ECHO**
0.078 mi.
412 ft. **Site 10 of 19 in cluster E**

Relative: **Lower**
Actual: **29 ft.**

RCRA Listings:

Date Form Received by Agency:	20150817
Handler Name:	Con Edison
Handler Address:	Essex St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004824732
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported

DRAFT

CON EDISON (Continued) **1019906646**

Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

DRAFT

CON EDISON (Continued) **1019906646**

Historic Generators:
Receive Date: 20150817
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150817
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069668096

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906646
Registry ID: 110069668096

DRAFT

CON EDISON (Continued) **1019906646**

DFR URL:
Name: CON EDISON
Address: 320 Essex St
City,State,Zip: BROOKLYN, NY 11208

F75 **NY E DESIGNATION** **S118704446**
ENE **118 ATKINS AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.080 mi.
420 ft. **Site 3 of 10 in cluster F**

Relative:
Higher

Actual:
34 ft.

E DESIGNATION:
Name: LOT 8,TAXBLOCK 3991
Address: 118 ATKINS AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 8
Tax Block: 3991
Borough Code: Not reported
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC LAND USE:
Name: Not reported
Address: 118 ATKINS AVENUE
City,State,Zip: BROOKLYN, NY 11208
Latitude: 40.6766626
Longitude: -73.8790350
Type Of Ownership Code: Not reported
Owner Name: GARY ROSEN TRUSTEE
Borough: BK
Tax Block: 3991
Tax Lot: 8
Community District: 305
Census Tract 2020: 3119200
Census Block 2020: 31192003004
Census Tract 2010: 1192
Census Block 2010: 3004
School District: 19
City Council District: 37
Fire Company: E332
Police Precinct: 75
Health Center District: 33
Health Area: 6200
Sanitation District Boro: 3
Sanitation District Number: 05
Sanitation Subsection: 1E
Zoning District 1: R6A: Residential Districts
Zoning District 2: Not reported

DRAFT

(Continued) **S118704446**

Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	33000
Total Building Floor Area:	8540
Commercial Floor Area:	8540
Residential Floor Area:	0
Office Floor Area:	2200
Retail Floor Area:	0
Garage Floor Area:	6340
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	150.0000000
Lot Depth:	200.0000000
Building Frontage:	40.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	2
Assessed Land Value:	260100.00000
Assessed Total Value:	450000.00000
Exempt Total Value:	0.00000
Year Built:	1950
Year Altered 1:	2007
Year Altered 2:	2007
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.26000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039910008.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1017803
Y Coordinate:	185826
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 031

DRAFT

(Continued) **S118704446**

Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

H76 **55 BERRIMAN STREET - TTF** **UST FINDER** **1028571478**
North **55 BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.080 mi.
425 ft. **Site 1 of 16 in cluster H**

Relative:
Higher

Actual:
36 ft.

UST FINDER:

Object ID:	295876
Facility ID:	NY21826
Name:	55 BERRIMAN STREET - TTF
Address:	55 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9586
Private Wells 1500ft:	57
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8806999999999
Y Coord:	40.676969
Latitude:	40.676969
Longitude:	-73.8807

UST FINDER:

Object ID:	1216771
Facility ID:	NY21826
Tank ID:	NY29544
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500

DRAFT

55 BERRIMAN STREET - TTF (Continued) **1028571478**

Substances: Not reported
Tank Wall Type: Not reported

H77 **3100 ATLANTIC LLC** **NY LTANKS** **U001841117**
North **55 BERRIMAN STREET** **NY UST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.080 mi.
425 ft. **Site 2 of 16 in cluster H**

Relative:
Higher

Actual:
36 ft.

LTANKS:

Name:	55 BERRIMAN STREET - TTF
Address:	55 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0407618 / 2007-06-22
Facility ID:	0407618
Site ID:	332137
Spill Date:	2004-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	2004-10-08
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2007-06-22
Spiller Name:	REDA
Spiller Company:	Not reported
Spiller Address:	62 ATKINS AVE.
Spiller County:	001
Spiller Contact:	REDA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	21762
Latitude:	40.6775600
Longitude:	-73.8806280
DEC Memo:	Spoke to John Leddy. This is in an estate and the estate has to make a decision where to take this. Tried to make contact and was unsuccessful 11/05-S. Scharf 3/06-Refer back to Region 2 for followup and closure.- S. Scharf 09/12/06 This case was transferred from Albany to Region 2. Zhune spoke to Elizabeth Farrel. (ph: 718-465-3600). She will fax copy of documents. 9/12/06 She sent tightness test result from 2005. I called her back let know that we need documents from 2004. 09/15/06 She only sent tank test failed results from 2004. 09/22/06-Vought-Received call and spoke to Elizabeth and she has already faxed in results. Requesting review and callback from Zhune. 06/19/07-ABC tank sent a letter and invoice

DRAFT

3100 ATLANTIC LLC (Continued) **U001841117**

describing the repair they did to the 2500 gallons UST that failed the test. The letter says: on April 11- April 15, 2005 ABC Tank dug up to expose the top of (1) 2,500 gallon underground storage tank. After tank was opened, a new gasket set along with a new stickline was installed. The tank was then cleaned and a visual inspection was performed on the interior of the tank. ABC found no evidence of leakage from the interior of the tank. Pressure was able to hold for (1) hour. On April 15,2005 a tightness test was performed on the tank. ABC Tank found no evidence of contaminated soil at the above site and any repairs made were neded in order for the tank to pass the tightness test. A copy of the pass tightness test results was also sending. Case Closed

Remarks: PBS No: 2-510092

All TTF:

Facility ID:	0407618
Spill Number:	0407618
Spill Tank Test:	1548229
Site ID:	332137
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332137
Operable Unit ID:	1094394
Operable Unit:	01
Material ID:	574500
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	3100 ATLANTIC LLC
Address:	55 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510092 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

DRAFT

3100 ATLANTIC LLC (Continued) **U001841117**

UTM X:	594608.23858
UTM Y:	4503572.82297
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21826
Affiliation Type:	Facility Operator
Company Name:	55 BERRIMAN STREET - TTF
Contact Type:	Not reported
Contact Name:	NA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2016-04-11

Site Id:	21826
Affiliation Type:	Facility Owner
Company Name:	3100 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21826
Affiliation Type:	Emergency Contact
Company Name:	3100 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21826
Affiliation Type:	Mail Contact

DRAFT

3100 ATLANTIC LLC (Continued) **U001841117**

Company Name:	LIBERTY ONE GROUP
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Tank Info:

Tank Number:	001
Tank ID:	39477
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	11/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	08/25/2017
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

DRAFT

E78 **LOT 17,TAXBLOCK 3987** **NY E DESIGNATION** **S118704140**
WNW **742 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.081 mi.
426 ft. **Site 11 of 19 in cluster E**

Relative:
Lower

Actual:
28 ft.

E DESIGNATION:

Name:	LOT 17,TAXBLOCK 3987
Address:	742 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	17
Tax Block:	3987
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	742 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6762544
Longitude:	-73.8824967
Type Of Ownership Code:	Not reported
Owner Name:	EMPIRE REALTY HOLDINGS, LLC
Borough:	BK
Tax Block:	3987
Tax Lot:	17
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166001002
Census Tract 2010:	1166
Census Block 2010:	1002
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

DRAFT

LOT 17,TAXBLOCK 3987 (Continued) **S118704140**

Spill Boundary Indicator:	N
Building Class:	E9: Warehouses - Miscellaneous
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	7504
Total Building Floor Area:	6900
Commercial Floor Area:	5010
Residential Floor Area:	1890
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	5010
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	3
Number Of Floors:	2.0000000
Residential Units:	2
Total Units:	3
Lot Frontage:	75.2900000
Lot Depth:	100.0000000
Building Frontage:	52.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	84600.00000
Assessed Total Value:	246600.00000
Exempt Total Value:	0.00000
Year Built:	1935
Year Altered 1:	1964
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.92000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039870017.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1016843
Y Coordinate:	185676
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	3039870017.00000000
Apportionment Date:	09/18/1991
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1

DRAFT

LOT 17,TAXBLOCK 3987 (Continued) **S118704140**

Changed By DCP: Not reported

D79 **CON EDISON** **NY MANIFEST** **S117067115**
WSW **OPP 761 GLENMORE AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.082 mi.
434 ft. **Site 17 of 17 in cluster D**

Relative: **Lower**

Actual: **29 ft.**

NY MANIFEST:

EPA ID:	NYP004598546
Country:	USA
Name:	Con Edison
Address:	OPP 761 GLENMORE AVE
Address 2:	STRUCTURE 58407
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	OPP 761 GLENMORE AVE
Location Address 2:	STRUCTURE 58407
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004598546
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504239GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

DRAFT

CON EDISON (Continued) **S117067115**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

E80 **CON EDISON** **NY MANIFEST** **S117067114**
West **330 ESSEX ST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.083 mi.
438 ft. **Site 12 of 19 in cluster E**

Relative: **Lower**

Actual: **29 ft.**

NY MANIFEST:

EPA ID:	NYP004598520
Country:	USA
Name:	Con Edison
Address:	330 ESSEX ST
Address 2:	STRUCTURE 65911
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	330 ESSEX ST
Location Address 2:	STRUCTURE 65911
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

DRAFT

CON EDISON (Continued) **S117067114**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004598520
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504238GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

DRAFT

H81 **LOT 46,TAXBLOCK 3973** **NY E DESIGNATION** **S118704376**
North **46 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.084 mi.
443 ft. **Site 3 of 16 in cluster H**

Relative:
Higher

Actual:
35 ft.

E DESIGNATION:

Name:	LOT 46,TAXBLOCK 3973
Address:	46 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	46
Tax Block:	3973
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	46 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6776143
Longitude:	-73.8810090
Type Of Ownership Code:	Not reported
Owner Name:	ROBLEE REALTY CORP.
Borough:	BK
Tax Block:	3973
Tax Lot:	46
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001004
Census Tract 2010:	1168
Census Block 2010:	1004
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

DRAFT

LOT 46,TAXBLOCK 3973 (Continued) **S118704376**

Spill Boundary Indicator:	N
Building Class:	E1: Warehouses - Fireproof
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	10000
Commercial Floor Area:	10000
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	10000
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	6
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	100.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	135000.00000
Assessed Total Value:	390150.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.00000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039730046.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1017255
Y Coordinate:	186172
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1

DRAFT

LOT 46,TAXBLOCK 3973 (Continued) **S118704376**

Changed By DCP: Not reported

F82 **MIKE'S HEAVY DUTY TOWING, INC.** **NY AST** **A100510013**
ENE **816 LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.084 mi.
446 ft. **Site 4 of 10 in cluster F**

Relative:
Higher

Actual:
34 ft.

AST:

Name:	MIKE'S HEAVY DUTY TOWING, INC.
Address:	816 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-613180
Program Type:	PBS
UTM X:	594745.84924
UTM Y:	4503458.27050
Expiration Date:	09/18/2025
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	611363
Affiliation Type:	Facility Owner
Company Name:	MAGARET MAZZIO LIVING TRUST
Contact Type:	ENVIRONMENTAL CONSULTANT
Contact Name:	NORMAN TEITLER
Address1:	156-21 90TH STREET
Address2:	Not reported
City:	HOWARD BEACH
State:	NY
Zip Code:	11414
Country Code:	001
Phone:	(718) 848-2047
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-09-18

Site Id:	611363
Affiliation Type:	Mail Contact
Company Name:	MIKES HEAVY DUTY TOWING, INC.
Contact Type:	Not reported
Contact Name:	MICHAEL MAZZIO
Address1:	816 LIBERTY AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 277-6060
EMail:	MIKE@MIKESHDT.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-09-18

Site Id: 611363

DRAFT

MIKE'S HEAVY DUTY TOWING, INC. (Continued) **A100510013**

Affiliation Type:	Facility Operator
Company Name:	MIKES HEAVY DUTY TOWING, INC.
Contact Type:	Not reported
Contact Name:	MICHAEL MAZZIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-09-18

Site Id:	611363
Affiliation Type:	Emergency Contact
Company Name:	MAGARET MAZZIO LIVING TRUST
Contact Type:	Not reported
Contact Name:	MICHAEL MAZZIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 576-6029
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-09-18

Tank Info:

Tank Number:	001
Tank Id:	287482

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G10 - Tank Secondary Containment - Impervious Underlayment
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/02/2020

DRAFT

MIKE'S HEAVY DUTY TOWING, INC. (Continued) **A100510013**

Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil
Tank Number:	002
Tank Id:	287483

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G10 - Tank Secondary Containment - Impervious Underlayment
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/02/2020
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

E83 **J. BORAH CO.** **NY AST** **A100294523**
NW **291 ESSEX STREET** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.086 mi.
454 ft. **Site 13 of 19 in cluster E**

Relative: **Lower**
Actual: **29 ft.**

AST:

Name:	J. BORAH CO.
Address:	291 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608411
Program Type:	PBS

DRAFT

J. BORAH CO. (Continued) **A100294523**

UTM X: 594451.48774
UTM Y: 4503502.02787
Expiration Date: N/A
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 30263
Affiliation Type: Mail Contact
Company Name: EASTEX BRIDALS HOLDING CORP
Contact Type: Not reported
Contact Name: MANJEET SINGH
Address1: 124-03 149TH AVE.
Address2: Not reported
City: SOUTH OZONE PARK
State: NY
Zip Code: 11420
Country Code: 001
Phone: (347) 624-2959
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-05-21

Site Id: 30263
Affiliation Type: Facility Operator
Company Name: J. BORAH CO.
Contact Type: Not reported
Contact Name: EASTEX BNDALS HOLDING
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (347) 624-1616
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-05-21

Site Id: 30263
Affiliation Type: Emergency Contact
Company Name: EASTEX BRIDALS HOLDING CORP
Contact Type: Not reported
Contact Name: MANJEET SINGH
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 624-1616
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2014-05-21

Site Id: 30263

DRAFT

J. BORAH CO. (Continued) **A100294523**

Affiliation Type:	Facility Owner
Company Name:	EASTEX BRIDALS HOLDING CORP
Contact Type:	OWNER
Contact Name:	G SINGH
Address1:	291 ESSEX STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(347) 624-2959
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-05-21

Tank Info:

Tank Number:	1
Tank Id:	65135
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	C02 - Pipe Location - Underground/On-ground
	D00 - Pipe Type - No Piping
	G00 - Tank Secondary Containment - None
	J00 - Dispenser - None
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Concrete
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1930
Capacity Gallons:	1500
Tightness Test Method:	34
Date Test:	03/10/2003
Next Test Date:	Not reported
Date Tank Closed:	02/22/2016
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

DRAFT

H84 **NYC DEP DERTA** **RCRA NonGen / NLR** **1025887429**
North **49 BERRIMAN ST** **E MANIFEST** **NYP000975860**
< 1/8 **BROOKLYN, NY 11208**
0.088 mi.
466 ft. **Site 4 of 16 in cluster H**

Relative: **Higher**
Actual: **36 ft.**

RCRA Listings:

Date Form Received by Agency:	20191031
Handler Name:	Nyc Dep Derta
Handler Address:	Berriman St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP000975860
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

DRAFT

NYC DEP DERTA (Continued) **1025887429**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20191031
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20190903
Handler Name: NYC DEP DERTA	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20191031
Handler Name: NYC DEP DERTA	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

DRAFT

NYC DEP DERTA (Continued) **1025887429**

E MANIFEST:

Manifest Tracking Number:	012157582FLE
Last Updated Date:	20190917
Shipped Date:	20190903
Received Date:	20190905
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYP000975860
Generator Name:	Nyc Dep
Generator Location Street Number:	Not reported
Generator Location Street 1:	49 BERRIMAN STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	96-05 Horace Harding Expresswa
Generator Mail Street 2:	Not reported
Generator Mail City:	Queens
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Veolia Es Technical Solutions Llc
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1 EDEN LANE
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	1 EDEN LANE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	012157582FLE
Transporter Line Number:	1
Transporter EPA ID:	NYD064748304
Transporter Name:	Action Trucking
Manifest Tracking Number:	012157582FLE
Transporter Line Number:	2
Transporter EPA ID:	NJD080631369
Transporter Name:	Veolia Es Technical Solutions

Waste Line:

Manifest Tracking Number:	012157582FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y

DRAFT

NYC DEP DERTA (Continued) **1025887429**

U.S. DOT ID Number:	UN1993
U.S. DOT Description:	Un1993, Waste Flammable Liquids, N.O.S. (Gasoline), 3, Ii, Rq (D001)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	600
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.3
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.3
Waste Quantity, in Kilograms:	272.109
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	272.109
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D018
Quantity Haz Kg:	272.109
Quantity Haz Tons:	0.3
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B

H85 **NYC DEP DERTA** **NY Spills S125359627**
North **49 BERRIMAN ST** **NY MANIFEST N/A**
< 1/8 **BROOKLYN, NY 11208**
0.088 mi.
466 ft. **Site 5 of 16 in cluster H**

Relative: **Higher**
Actual: **36 ft.**

SPILLS:

Name:	PAVEMENT POSSIBLE DRAIN
Address:	49 BERRIMAN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1905730 / 2019-09-03
Facility ID:	1905730
Facility Type:	ER
DER Facility ID:	543743
Site ID:	593775
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2019-09-02

DRAFT

NYC DEP DERTA (Continued) **S125359627**

Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2019-09-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-02
Spill Record Last Update:	2019-09-03
Spiller Name:	STEVE KOTLARCHYK
Spiller Company:	UNKNOWN
Spiller Address:	49 BERRIMAN ST
Spiller Company:	999
Contact Name:	STEVE KOTLARCHYK
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	09/03/19-Hiralkumar Patel. tried calling FDNY, but no response. site 49 Berriman St is a multi-story apartment building. based on nature of the call, gasoline may have spilled from a parked vehicle. after discussing with DEC Austin, case closed.
Remarks:	leaking tank clean up started

All Materials:

Site ID:	593775
Operable Unit ID:	1341353
Operable Unit:	01
Material ID:	2351230
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	9.90
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYP000975860
Country:	USA
Name:	Nyc Dep Derta
Address:	49 BERRIMAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	49 BERRIMAN ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported

DRAFT

NYC DEP DERTA (Continued) **S125359627**

Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Nyc Dep Derta
Mailing Contact: Nyc Dep
Mailing Address 1: 96-05 HORACE HARDING EXP
Mailing Address 2: Not reported
Mailing City,State,Zip: QUEENS, NY 11208
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5167813000

H86 **3100 ATLANTIC LLC** **NY UST** **U000411513**
NNE **62 ATKINS AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.089 mi.
471 ft. **Site 6 of 16 in cluster H**

Relative:
Higher

Actual:
37 ft.

UST:
Name: 3100 ATLANTIC LLC
Address: 62 ATKINS AVENUE
City,State,Zip: BROOKLYN, NY 11208
Id/Status: 2-510300 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 594654.77539
UTM Y: 4503582.12197
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 21845
Affiliation Type: Emergency Contact
Company Name: 3100 ATLANTIC LLC
Contact Type: Not reported
Contact Name: MORDY PERKOWSKI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 819-6161
EMail: Not reported
Fax Number: Not reported
Modified By: KXLIU
Date Last Modified: 2019-12-31

Site Id: 21845
Affiliation Type: Facility Owner
Company Name: 3100 ATLANTIC LLC
Contact Type: AGENT
Contact Name: MORDY PERKOWSKI
Address1: 175 BLAKE AVE
Address2: Not reported
City: BROOKLYN

DRAFT

3100 ATLANTIC LLC (Continued) **U000411513**

State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2020-01-13

Site Id:	21845
Affiliation Type:	Mail Contact
Company Name:	LIBERTY ONE GROUP
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21845
Affiliation Type:	Facility Operator
Company Name:	62 ATKINS AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-08

Tank Info:

Tank Number:	001
Tank ID:	39496
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	11/03/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

DRAFT

3100 ATLANTIC LLC (Continued) **U000411513**

Tightness Test Method: 34
Date Test: 08/25/2017
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

H87 **62 ATKINS AVENUE** **UST FINDER** **1028571494**
NNE **62 ATKINS AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.089 mi.
471 ft. **Site 7 of 16 in cluster H**

Relative:
Higher

Actual:
37 ft.

UST FINDER:

Object ID:	295885
Facility ID:	NY21845
Name:	62 ATKINS AVENUE
Address:	62 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9219
Private Wells 1500ft:	58
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.879715
Y Coord:	40.677124
Latitude:	40.677124
Longitude:	-73.879715

DRAFT

62 ATKINS AVENUE (Continued) **1028571494**

UST FINDER:

Object ID:	1216786
Facility ID:	NY21845
Tank ID:	NY24765
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

H88 **62 ATKINS AVE - TTF** **NY LTANKS** **S106971318**
NNE **62 ATKINS AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.089 mi.
471 ft. **Site 8 of 16 in cluster H**

Relative:
Higher

Actual:
37 ft.

LTANKS:

Name:	62 ATKINS AVE - TTF
Address:	62 ATKINS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0407614 / 2006-01-23
Facility ID:	0407614
Site ID:	332133
Spill Date:	2004-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2004-10-08
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2006-01-23
Spiller Name:	REDA
Spiller Company:	Not reported
Spiller Address:	62 ATKINS AVE.
Spiller County:	001
Spiller Contact:	REDA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	267298
Latitude:	40.6774660
Longitude:	-73.8797830
DEC Memo:	11/25/05- DEC Piper sent out ttf leterto Estate of Fren Stark 198-10 Jamaica Ave, Hollis NY 11423 1/23/06- DEC Piper review receipts from

DRAFT

62 ATKINS AVE - TTF (Continued) **S106971318**

ABC Tank, provided by managing agent. Repairs made to dry portion of tank (Vent line replaced). E-docs. Closed.

Remarks: Not reported

All TTF:

Facility ID:	0407614
Spill Number:	0407614
Spill Tank Test:	1548225
Site ID:	332133
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332133
Operable Unit ID:	1094390
Operable Unit:	01
Material ID:	574496
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E89 **CON EDISON** **E MANIFEST** **1031966710**
WNW **737 LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.090 mi.
474 ft. **Site 14 of 19 in cluster E**

Relative: **Lower**
Actual: **28 ft.**

E MANIFEST:

Manifest Tracking Number:	013198418FLE
Last Updated Date:	20190715
Shipped Date:	20190604
Received Date:	20190607
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	737 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN

DRAFT

CON EDISON (Continued) **1031966710**

Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	737 Liberty Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11208
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	013198418FLE
Transporter Line Number:	1
Transporter EPA ID:	MAC300016672
Transporter Name:	Triumvirate Environmental

Waste Line:

Manifest Tracking Number:	013198418FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082 Hazardous Waste, Liquid, N.O.S. (Lead) Iii 9 D008
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	100
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.05
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.05
Waste Quantity, in Kilograms:	45.3515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	45.3515
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N

DRAFT

CON EDISON (Continued) **1031966710**

Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	45.3515
Quantity Haz Tons:	0.05
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

F90 **831 LIBERTY AVENUE** **UST FINDER** **1028571487**
NE **831 LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.092 mi.
485 ft. **Site 5 of 10 in cluster F**

Relative: **Higher**

Actual: **35 ft.**

UST FINDER:

Object ID:	295847
Facility ID:	NY21838
Name:	831 LIBERTY AVENUE
Address:	831 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9929
Private Wells 1500ft:	61
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8788299999999
Y Coord:	40.676383
Latitude:	40.676383
Longitude:	-73.87883

DRAFT

831 LIBERTY AVENUE (Continued) **1028571487**

UST FINDER:
Object ID: 1216779
Facility ID: NY21838
Tank ID: NY111133
Tank Status: Open
Installation Date: 1948/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 3000
Substances: Not reported
Tank Wall Type: Not reported

F91 **831 LIBERTY AVENUE** **NY UST** **U001841123**
NE **831 LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.092 mi.
485 ft. **Site 6 of 10 in cluster F**

Relative:
Higher

Actual:
35 ft.

UST:
Name: 831 LIBERTY AVENUE
Address: 831 LIBERTY AVENUE
City,State,Zip: BROOKLYN, NY 11208
Id/Status: 2-510238 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 594752.67426
UTM Y: 4503437.81584
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 21838
Affiliation Type: Facility Owner
Company Name: 3124 ATLANTIC LLC
Contact Type: AGENT
Contact Name: DANNY SINGH
Address1: 175 BLAKE AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11212
Country Code: 001
Phone: (917) 533-2236 206
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-04

Site Id: 21838
Affiliation Type: Emergency Contact
Company Name: 3124 ATLANTIC LLC
Contact Type: Not reported
Contact Name: MORDY PERKOWSKI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN

DRAFT

831 LIBERTY AVENUE (Continued) **U001841123**

Zip Code:	Not reported
Country Code:	999
Phone:	(917) 533-2236 206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21838
Affiliation Type:	Mail Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236 206
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21838
Affiliation Type:	Facility Operator
Company Name:	831 LIBERTY AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Tank Info:

Tank Number:	001
Tank ID:	39489
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	12/01/1948
Date Tank Closed:	02/27/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

DRAFT

831 LIBERTY AVENUE (Continued) **U001841123**

Tightness Test Method:	34
Date Test:	10/31/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)

I92 **SPILL NUMBER 0302806** **NY Spills** **S106015087**
NW **281 ESSEX ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.093 mi.
492 ft. **Site 1 of 5 in cluster I**

Relative: **Lower**

Actual: **29 ft.**

SPILLS:

Name:	SPILL NUMBER 0302806
Address:	281 ESSEX ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0302806 / 2003-06-17
Facility ID:	0302806
Facility Type:	ER
DER Facility ID:	258137
Site ID:	320395
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-06-16
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2003-06-16
CID:	207
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-16
Spill Record Last Update:	2003-06-17
Spiller Name:	SUSAN MIRANDO

DRAFT

SPILL NUMBER 0302806 (Continued) **S106015087**

Spiller Company:	Not reported
Spiller Address:	281 ESSEX ST
Spiller Company:	001
Contact Name:	SUSAN MIRANDO
Latitude:	40.6772215
Longitude:	-73.8824451
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland DDO No Spills or PBS records for this address Spoke to Susan Mirando. She said this address used to be a gas station over 20+ years ago. She says there are construction workers pulling down the building and they will be putting up 2 houses. Sangesland told her that since there are no reported spills at the site and there is no sign now that a problem exists, there is nothing DEC is able to do about the site. If any contamination is found during excavation, the contractor is supposed to call in the spill. Sangesland told Ms. Mirando that she can call in a Spill if she sees or smells a problem at the site.
Remarks:	citizen concerned with the property next door being developed for residential use - was once a gas station many years ago and is concerned about product in tansks, proper disposal etc. req callback.

All Materials:

Site ID:	320395
Operable Unit ID:	869620
Operable Unit:	01
Material ID:	507259
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E93 **CON EDISON** **NY MANIFEST** **S117061597**
West **728 LIBERTY AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.094 mi.
496 ft. **Site 15 of 19 in cluster E**

Relative: NY MANIFEST:
Lower

Actual: EPA ID:	NYP004539110
28 ft. Country:	USA
Name:	Con Edison
Address:	728 LIBERTY AVE FRONT OF
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	FO 728 LIBERTY AVE
Location Address 2:	SB 29444
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported

DRAFT

CON EDISON (Continued) **S117061597**

Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/20/2014
Trans1 Recv Date: 05/20/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004539110
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013246035JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 50
Units: Gallons (liquids only)

DRAFT

CON EDISON (Continued) **S117061597**

Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

E94
West
< 1/8
0.094 mi.
496 ft.

CON EDISON **RCRA NonGen / NLR** **1017776062**
728 LIBERTY AVE FRONT OF **FINDS** **NYP004539110**
BROOKLYN, NY 11208

Site 16 of 19 in cluster E

Relative:
Lower

Actual:
28 ft.

RCRA Listings:

Date Form Received by Agency:	20140521
Handler Name:	Con Edison
Handler Address:	Liberty Ave Front Of
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004539110
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

DRAFT

CON EDISON (Continued) **1017776062**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150814
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140521
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140521
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140621
Handler Name: CON EDISON SERVICE BOX: 29444	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

DRAFT

CON EDISON (Continued) **1017776062**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063801863

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

E95 **LOT 45,TAXBLOCK 3971** **NY E DESIGNATION** **S118704369**
WNW **298 ESSEX STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
504 ft. **Site 17 of 19 in cluster E**

Relative:
Lower

Actual:
28 ft.

E DESIGNATION:
Name: LOT 45,TAXBLOCK 3971
Address: 298 ESSEX STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 45
Tax Block: 3971
Borough Code: Not reported
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

DRAFT

LOT 45,TAXBLOCK 3971 (Continued) **S118704369**

NYC LAND USE:

Name:	Not reported
Address:	298 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6768448
Longitude:	-73.8826976
Type Of Ownership Code:	Not reported
Owner Name:	FERNANDEZ, MARTIN
Borough:	BK
Tax Block:	3971
Tax Lot:	45
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168002005
Census Tract 2010:	1168
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C0: Walk Up Apartments - Three Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	2575
Total Building Floor Area:	1800
Commercial Floor Area:	0
Residential Floor Area:	1800
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	2.0000000
Residential Units:	3
Total Units:	3
Lot Frontage:	25.0000000
Lot Depth:	103.0000000
Building Frontage:	20.0000000

DRAFT

LOT 45,TAXBLOCK 3971 (Continued) **S118704369**

Building Depth:	45.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	12720.00000
Assessed Total Value:	44400.00000
Exempt Total Value:	0.00000
Year Built:	1901
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.70000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039710045.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016787
Y Coordinate:	185891
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

J96 **ST RITA'S R.C.CHURCH** **UST FINDER** **1028570528**
NNW **275 SHEPHERD AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.098 mi.
515 ft. **Site 1 of 2 in cluster J**

Relative: UST FINDER:
Higher

Actual: Object ID:	295895
34 ft. Facility ID:	NY19707
Name:	ST RITA'S R.C.CHURCH
Address:	275 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9446
Private Wells 1500ft:	47
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No

DRAFT

ST RITA'S R.C.CHURCH (Continued) **1028570528**

SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.88163
Y Coord:	40.6772120000001
Latitude:	40.677212
Longitude:	-73.88163

UST FINDER:

Object ID:	1212128
Facility ID:	NY19707
Tank ID:	NY25404
Tank Status:	Open
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

J97 **ST RITA'S R.C. CHURCH** **NY UST** **U001837883**
NNW **275 SHEPHERD AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.098 mi.
515 ft. **Site 2 of 2 in cluster J**

Relative:
Higher

Actual:
34 ft.

UST:

Name:	ST RITA'S R.C. CHURCH
Address:	275 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-407259 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594524.48880
UTM Y:	4503587.95681
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	19707
Affiliation Type:	Emergency Contact
Company Name:	ST RITAS R.C.CHURCH
Contact Type:	Not reported
Contact Name:	MARK JOHNSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported

DRAFT

ST RITA'S R.C. CHURCH (Continued) **U001837883**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 581-3427 1154
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2020-09-16

Site Id: 19707
Affiliation Type: Facility Owner
Company Name: SAINT RITAS ROMAN CATHOLIC CHURCH
Contact Type: REPRESENTATIVE
Contact Name: CHRISTOPHER QUINTANA
Address1: 275 SHEPHARD AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11208
Country Code: 001
Phone: (718) 647-4910
EMail: MJOHNSON@DIOBROOK.ORG
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2020-09-16

Site Id: 19707
Affiliation Type: Mail Contact
Company Name: ROCKLYN ASSET CORP.
Contact Type: Not reported
Contact Name: MARK JOHNSON
Address1: 243 PROSPECT PARK WEST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11215
Country Code: 001
Phone: (718) 647-4910
EMail: MJOHNSON@DIOBROOK.ORG
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2020-09-16

Site Id: 19707
Affiliation Type: Facility Operator
Company Name: ST RITAS R.C.CHURCH
Contact Type: Not reported
Contact Name: MSGR. JOHN PEYTON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 647-4910
EMail: Not reported
Fax Number: Not reported

DRAFT

ST RITA'S R.C. CHURCH (Continued) **U001837883**

Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 23259
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: Not reported
Date Tank Closed: 05/14/2020
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 03
Date Test: 12/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
D01 - Pipe Type - Steel/Carbon Steel/Iron
L09 - Piping Leak Detection - Exempt Suction Piping
B00 - Tank External Protection - None

K98 **385 ESSEX STREET** **NY LTANKS** **S102960479**
SSW **385 ESSEX STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.100 mi.
528 ft. **Site 1 of 3 in cluster K**

Relative:
Lower

Actual:
27 ft.

LTANKS:
Name: 385 ESSEX STREET
Address: 385 ESSEX STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9708809 / 1998-06-17
Facility ID: 9708809
Site ID: 245641
Spill Date: 1997-10-22
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported

DRAFT

385 ESSEX STREET (Continued) **S102960479**

Reported to Dept:	1997-10-28
CID:	204
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-28
Spill Record Last Update:	1998-06-17
Spiller Name:	PAT TURTURRO
Spiller Company:	CLASSIC FUEL
Spiller Address:	9 WYTHE AVENUE
Spiller County:	001
Spiller Contact:	LISA HAUER
Spiller Phone:	(914) 592-3385
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	201736
Latitude:	40.6745665
Longitude:	-73.8817677
DEC Memo:	Not reported
Remarks:	WENT INTO A DRYWELL ALSO

All Materials:

Site ID:	245641
Operable Unit ID:	1051891
Operable Unit:	01
Material ID:	330752
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	385 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6746094
Longitude:	-73.8815875
Type Of Ownership Code:	Not reported
Owner Name:	BISCOMBE ELSIE
Borough:	BK
Tax Block:	4004
Tax Lot:	103
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002001
Census Tract 2010:	1166
Census Block 2010:	2001
School District:	19

DRAFT

385 ESSEX STREET (Continued) **S102960479**

City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R5B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C0: Walk Up Apartments - Three Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	1783
Total Building Floor Area:	1666
Commercial Floor Area:	0
Residential Floor Area:	1666
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	3
Total Units:	3
Lot Frontage:	17.8300000
Lot Depth:	100.0000000
Building Frontage:	17.8300000
Building Depth:	49.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	9120.00000
Assessed Total Value:	51060.00000
Exempt Total Value:	0.00000
Year Built:	1910
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.93000000000
Maximum Allowable Residential Far:	1.35000000000
Maximum Allowable Commercial Far:	0.00000000000

DRAFT

385 ESSEX STREET (Continued) **S102960479**

Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040040103.00000000
Condominium Number:	Not reported
Census Tract 2:	1166
X Coordinate:	1017096
Y Coordinate:	185077
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

E99 **CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS** **E MANIFEST** **1031961133**
WNW **729 LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.104 mi.
547 ft. **Site 18 of 19 in cluster E**

Relative: **Lower**
Actual: **28 ft.**

E MANIFEST:

Manifest Tracking Number:	006869207GBF
Last Updated Date:	20211123
Shipped Date:	20211110
Received Date:	20211112
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Queens Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	729 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105

DRAFT

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1031961133**

Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 006869207GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006869207GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 200
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.1
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.1
Waste Quantity, in Kilograms: 90.703
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 90.703
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 90.703
Quantity Haz Tons: 0.1
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

DRAFT

E100
WNW
< 1/8
0.104 mi.
547 ft.

CON EDISON
729 LIBERTY AVE
BROOKLYN, NY 11208

Site 19 of 19 in cluster E

E MANIFEST **1031966680**
N/A

Relative:
Lower

Actual:
28 ft.

E MANIFEST:

Manifest Tracking Number:	006874234GBF
Last Updated Date:	20210823
Shipped Date:	20210812
Received Date:	20210816
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	729 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006874234GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006874234GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON (Continued) **1031966680**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	200
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.1
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.1
Waste Quantity, in Kilograms:	90.703
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	90.703
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	90.703
Quantity Haz Tons:	0.1
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

H101 **61 ATKINS AVENUE** **UST FINDER** **1028571486**
NNE **61 ATKINS AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.104 mi.
550 ft. **Site 9 of 16 in cluster H**

Relative: **Higher**

Actual: **37 ft.**

UST FINDER:

Object ID:	295884
Facility ID:	NY21834
Name:	61 ATKINS AVENUE
Address:	61 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9219
Private Wells 1500ft:	58
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No

DRAFT

61 ATKINS AVENUE (Continued) **1028571486**

SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.879715
Y Coord:	40.677124
Latitude:	40.677124
Longitude:	-73.879715

UST FINDER:

Object ID:	1216778
Facility ID:	NY21834
Tank ID:	NY24764
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

H102 **61 ATKINS AVENUE** **NY LTANKS** **U001841121**
NNE **61 ATKINS AVENUE** **NY UST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.104 mi.
550 ft. **Site 10 of 16 in cluster H**

Relative:
Higher

Actual:
37 ft.

LTANKS:

Name:	ESTATE OF FRED STARK
Address:	61 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0407729 / 2010-04-30
Facility ID:	0407729
Site ID:	332262
Spill Date:	2004-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2004-10-12
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

DRAFT

61 ATKINS AVENUE (Continued) **U001841121**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2010-04-30
Spiller Name:	RITA
Spiller Company:	Not reported
Spiller Address:	61 ATKINS AVE
Spiller County:	001
Spiller Contact:	RITA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	21770
Latitude:	40.6774920
Longitude:	-73.8796420
DEC Memo:	04/30/10 - LZ Reviewed documents(eDocs)sent by Liz Farrell of Estate of Fred Stark. They indicate that the stick line and the gasket set were replaced, and the tanks system subsequently passed the tightness test. The spill case is closed. 04/19/10 - LZ Sent two TTF letters (eDocs) to Estate of Fred Stark at 198-10 Jamaica Avenue and 61 Atkins Avenue. 03/07/05 - Sawyer - Sent TTF to: Estate of Fred Stark 198-10 Jamaica Avenue Hollis, NY 11423 718-465-3600 Made contact with the estate but could not get a response that the spill can be satisfactorily closed. refer back to Region.-s. scharf Transferred from CO 9/11/06
Remarks:	PBS No: 2-510173

All TTF:

Facility ID:	0407729
Spill Number:	0407729
Spill Tank Test:	1548239
Site ID:	332262
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332262
Operable Unit ID:	1094510
Operable Unit:	01
Material ID:	574617
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

DRAFT

61 ATKINS AVENUE (Continued) **U001841121**

Units: G
Recovered: .00
Oxygenate: Not reported

UST:
Name: 61 ATKINS AVENUE
Address: 61 ATKINS AVENUE
City,State,Zip: BROOKLYN, NY 11208
Id/Status: 2-510173 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 594676.91314
UTM Y: 4503519.08690
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 21834
Affiliation Type: Facility Owner
Company Name: 3124 ATLANTIC LLC
Contact Type: AGENT
Contact Name: DANNY SINGH
Address1: 175 BLAKE AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11212
Country Code: 001
Phone: (917) 533-2236 206
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-04

Site Id: 21834
Affiliation Type: Mail Contact
Company Name: 3124 ATLANTIC LLC
Contact Type: Not reported
Contact Name: MORDY PERKOWSKI
Address1: 175 BLAKE AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11212
Country Code: 001
Phone: (917) 533-2236 206
EMail: MORDY@LIBERTY1GROUP.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-04

Site Id: 21834
Affiliation Type: Emergency Contact
Company Name: 3124 ATLANTIC LLC
Contact Type: Not reported

DRAFT

61 ATKINS AVENUE (Continued) **U001841121**

Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 533-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21834
Affiliation Type:	Facility Operator
Company Name:	61 ATKINS AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Tank Info:

Tank Number:	001
Tank ID:	39485
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	02/26/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	34
Date Test:	10/31/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None

DRAFT

61 ATKINS AVENUE (Continued) **U001841121**

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

H103 **CONSOLIDATED EDISON COMPANY OF NY** **E MANIFEST** **1031975449**
North **39 BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.105 mi.
553 ft. **Site 11 of 16 in cluster H**

Relative:
Higher

Actual:
36 ft.

E MANIFEST:

Manifest Tracking Number:	023096086JJK
Last Updated Date:	20211203
Shipped Date:	20211123
Received Date:	20211129
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Consolidated Edison Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	39 BERRIMAN STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11201
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ELIZABETH
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

DRAFT

CONSOLIDATED EDISON COMPANY OF NY (Continued) **1031975449**

Transporter:
- Manifest Tracking Number: 023096086JJK
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 023096086JJK
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 500
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.25
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.25
- Waste Quantity, in Kilograms: 226.7575
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 226.7575
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y
- Federal Waste Codes: D008
- Quantity Haz Kg: 226.7575
- Quantity Haz Tons: 0.25
- Quantity Non Haz Kg: 0
- Quantity Non Haz Tons: 0
- State Waste Codes: NY-T

DRAFT

F104
ENE
< 1/8
0.105 mi.
554 ft.

DRUM RUN (SIDE OF ROAD)
MONTAUK AVE AND LIBERTY AVE
BROOKLYN, NY

Site 7 of 10 in cluster F

NY Spills **S130465397**
N/A

Relative:
Higher

Actual:
35 ft.

SPILLS:

Name:	DRUM RUN (SIDE OF ROAD)
Address:	MONTAUK AVE AND LIBERTY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2302739 / 2023-07-25
Facility ID:	2302739
Facility Type:	ER
DER Facility ID:	599376
Site ID:	653601
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C2
SWIS:	2401
Spill Date:	2023-07-05
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2023-07-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2023-07-05
Spill Record Last Update:	2023-07-25
Spiller Name:	MOSES GULUZIAN
Spiller Company:	UNKNOWN
Spiller Address:	MONTAWK AVE AND LIBERTY AVE
Spiller Company:	999
Contact Name:	MOSES GULUZIAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	7/6/23 - Sekhon Three 5 gallon plastic container having diesel fuel left abandoned onto Montauk Ave close to liberty ave in Brooklyn. Case assigned to DEC Lin for drum run. 7/25/23- Containers not found as part of 7/21/23 drum run. Spill closed.
Remarks:	3- 5 gallon abandoned plastic containers at the end of the roadway.

All Materials:

Site ID:	653601
Operable Unit ID:	1400530
Operable Unit:	01
Material ID:	2417047
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G

DRAFT

DRUM RUN (SIDE OF ROAD) (Continued) **S130465397**

Recovered: Not reported
Oxygenate: Not reported

F105 **CON EDISON MANHOLE 3740** **RCRA NonGen / NLR** **1014919392**
ENE **MONTAUK AVE & LIBERTY AVE S** **NY MANIFEST** **NYP004235552**
< 1/8 **BROOKLYN, NY 11201**
0.105 mi.
554 ft. **Site 8 of 10 in cluster F**

Relative:
Higher

Actual:
35 ft.

RCRA Listings:

Date Form Received by Agency:	20110615
Handler Name:	Con Edison Manhole 3740
Handler Address:	Montauk Ave & Liberty Ave S
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004235552
Contact Name:	DOMINICK TURITTO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-802-5194
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR OFFICE ASSISTANT A X L1-2
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLAZA RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

DRAFT

CON EDISON MANHOLE 3740 (Continued) **1014919392**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20111026
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110516
Handler Name: CON EDISON MANHOLE 3740	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110615
Handler Name: CON EDISON MANHOLE 3740	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

DRAFT

CON EDISON MANHOLE 3740 (Continued) **1014919392**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004235552
Country:	USA
Name:	Consolidated Edison - Mh 3740
Address:	MONTAUK AVE & LIBERTY AVE S
Address 2:	INTERSECTION
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	LIBERTY AVE & MOHAWK
Location Address 2:	Not reported
Location City,State,Zip:	QUEENS, NY 11420
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison - Mh 3740
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/16/2011
Trans1 Recv Date:	05/16/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004235552
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	003206969FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

DRAFT

CON EDISON MANHOLE 3740 (Continued) **1014919392**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	B007
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Kilograms
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

F106 **CON ED** **NY MANIFEST** **S119078258**
ENE **MONTAUK AVE & LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.105 mi.
554 ft. **Site 9 of 10 in cluster F**

Relative:
Higher

Actual:
35 ft.

NY MANIFEST:

EPA ID:	NYP004881468
Country:	USA
Name:	Con Ed
Address:	MONTAUK AVE & LIBERTY AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	LIBERTY AVE & MONTAUK AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11215
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Ed
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported

DRAFT

CON ED (Continued) **S119078258**

Trans1 State ID:	MAD039322250
Year:	2018
Trans2 State ID:	MAD039322250
Generator Ship Date:	12/18/2015
Trans1 Recv Date:	12/18/2015
Trans2 Recv Date:	12/22/2015
TSD Site Recv Date:	12/22/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004881468
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	008417989FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	B003
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Kilograms
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Landfill
Specific Gravity:	1

F107 **CON EDISON** **RCRA NonGen / NLR** **1019909141**
ENE **MONTAUK AVE & LIBERTY AVE** **FINDS** **NYP004881468**
< 1/8 **BROOKLYN, NY 11208** **ECHO**
0.105 mi.
554 ft. **Site 10 of 10 in cluster F**

Relative: **Higher**
Actual: **35 ft.**

RCRA Listings:

Date Form Received by Agency:	20151218
Handler Name:	Con Edison
Handler Address:	Montauk Ave & Liberty Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004881468

DRAFT

CON EDISON (Continued) **1019909141**

Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

DRAFT

CON EDISON (Continued) **1019909141**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20151218
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151218
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069650602

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters,

DRAFT

CON EDISON (Continued) **1019909141**

storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019909141
Registry ID:	110069650602

DFR URL:

Name:	CON EDISON
Address:	Montauk Ave & Liberty Ave
City,State,Zip:	BROOKLYN, NY 11208

L108 **SOUTH WEST CRNER** **NY Spills** **S106698908**
ENE **LIBERTY AVE/MONTAUK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.107 mi.
563 ft. **Site 1 of 7 in cluster L**

Relative:
Higher

Actual:
35 ft.

SPILLS:

Name:	SOUTH WEST CRNER
Address:	LIBERTY AVE/MONTAUK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0406087 / 2004-11-12
Facility ID:	0406087
Facility Type:	ER
DER Facility ID:	100149
Site ID:	114857
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2004-09-02
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2004-09-02
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-02
Spill Record Last Update:	2004-11-12
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT DESK
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	155188 Employee found 1 pt dielectric fluid leaked from joint on primary cable in MH3740 onto dirt

DRAFT

SOUTH WEST CRNER (Continued) **S106698908**

on concrete floor of structure. No sewers or waterways affected. No private property affected.
Substance owned by Coned. #9 OS dispatched to location to verify feeder and to default structure.
Sample to be taken at that time and env. stop tag to be placed at that time. Will receive follow up
call with Chain of custody #. Clean up pending safe access and sample results. Update - 9/2/04 -
1700hrs Charles Yatchem ES reports dfaulted structure #01892 - 3c leaking - arms digging into
cable. Sample taken. 9/3/04 0003HRS LAB RESULR RETURNED 21PPM LSN-04-07020-001 UPDATE 9-7-04
11:30HRS J. LIPORI (ENV OPS) REPORTS, DOUBLE WASHED STRUCTURE USING 760 BIO GEN. NO SUMP FOUND AND
TAG WAS LEFT IN PLACE PENDING UG TO REPAIRE D FAULT. UPDATE 9/7/04 13:24 HRS UG SUPV C. CARRILLO
#84029 REPORTS THAT THE D-FAULT HAS BEEN CUT OUT AND ENV TAG# 38106 HAS BEEN PULLED. CLEANUP IS
COMPLETE.

Remarks: Amount: 1 pint. manhole #3740. eMIS # 155188.

All Materials:

Site ID:	114857
Operable Unit ID:	889638
Operable Unit:	01
Material ID:	487052
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I109 **LOT 44,TAXBLOCK 3971** **NY E DESIGNATION** **S118704363**
WNW **294 ESSEX STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.108 mi.
568 ft. **Site 2 of 5 in cluster I**

Relative: **Lower**

Actual: **28 ft.**

E DESIGNATION:

Name:	LOT 44,TAXBLOCK 3971
Address:	294 ESSEX STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	44
Tax Block:	3971
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

DRAFT

LOT 44,TAXBLOCK 3971 (Continued) **S118704363**

NYC LAND USE:

Name:	Not reported
Address:	294 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6769107
Longitude:	-73.8827155
Type Of Ownership Code:	Not reported
Owner Name:	FERNANDEZ, MARTIN
Borough:	BK
Tax Block:	3971
Tax Lot:	44
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168002005
Census Tract 2010:	1168
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B3: Two Family Dwellings - Converted From One Family
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	2600
Total Building Floor Area:	1400
Commercial Floor Area:	0
Residential Floor Area:	1400
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	25.0000000
Lot Depth:	104.0000000
Building Frontage:	25.0000000

DRAFT

LOT 44,TAXBLOCK 3971 (Continued) **S118704363**

Building Depth:	25.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	13440.00000
Assessed Total Value:	38880.00000
Exempt Total Value:	0.00000
Year Built:	1901
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.54000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039710044.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016782
Y Coordinate:	185915
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

G110 **VAULT # 67400** **NY Spills** **S105057398**
East **GLENMORE AVE/MONTAUK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.108 mi.
569 ft. **Site 2 of 5 in cluster G**

Relative: SPILLS:
Lower

Actual:
30 ft.

Name:	VAULT # 67400
Address:	GLENMORE AVE/MONTAUK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0101761 / 2001-06-19
Facility ID:	0101761
Facility Type:	ER
DER Facility ID:	157750
Site ID:	188910
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-05-15
Investigator:	JHOCONNE

DRAFT

VAULT # 67400 (Continued) **S105057398**

Referred To:	Not reported
Reported to Dept:	2001-05-16
CID:	246
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-16
Spill Record Last Update:	2001-08-31
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	CALLER
Latitude:	40.6757900
Longitude:	-73.8783540
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CONED E2MIS REPORT 5-15-01 Approx. 3qts. of cable oil leaked from a blown joint(3C)in MH67400. No sewer connection, no sump. PCB sample taken on a E priority. 2200hrs. Cleanup to be done as 50-499ppm 0055hrs Found earthen sump. Removed incident from 24hr. deminimus program. 0245 Cleaned structure using Bio Gen 760, earthen sump was sampled for VOC and SVOC and sealed with cement tag left in place pending removal of Blown Joint. 1020hrs. Splicers removed blown joint Cleanup completed 100%.
Remarks:	Joint on cable failed depositing 3 qts of material into manhole. Cleanup is completed, but an earthen sump was found beneath spill, which means some material has gone into soil at site. #137100 **update88 @0125 cleanup is not complete.

All Materials:

Site ID:	188910
Operable Unit ID:	840587
Operable Unit:	01
Material ID:	537466
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

M111 **LOT 28,TAXBLOCK 4005** **NY VCP** **S113915075**
South **2501 PITKIN AVENUE** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY** **NY NYC LAND USE**
0.110 mi. **NY NYC OER**
581 ft. **Site 1 of 5 in cluster M**

Relative:
Lower

Actual:
28 ft.

VCP NYC:

Project ID:	15TMP0080K,15EH-N080K,15CVCP019K
Name:	2501 PITKIN AVENUE
Address:	2501 PITKIN AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,400,500,283,040,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,0
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.674238
Longitude:	-73.880081
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3000000
BIN:	3040057501
NTA:	East New York

E DESIGNATION:

Name:	LOT 28,TAXBLOCK 4005
Address:	2501 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	28
Tax Block:	4005
Borough Code:	Not reported
E-No:	E-298
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	13DCP067K
Ulurp Number:	C130161ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2501 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6744955
Longitude:	-73.8803079
Type Of Ownership Code:	X
Owner Name:	UNAVAILABLE OWNER
Borough:	BK
Tax Block:	4005
Tax Lot:	7501
Community District:	305
Census Tract 2020:	3116600
Census Block 2020:	31166002000
Census Tract 2010:	1166
Census Block 2010:	2000

DRAFT

LOT 28,TAXBLOCK 4005 (Continued) **S113915075**

School District:	19
City Council District:	42
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	R6A: Residential Districts
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Y
Building Class:	Rm: Condominiums -Mixed Residential & Commercial Building (Mixed Residential & Commercial)
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	20625
Total Building Floor Area:	95789
Commercial Floor Area:	11903
Residential Floor Area:	83886
Office Floor Area:	0
Retail Floor Area:	11903
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	7.0000000
Residential Units:	60
Total Units:	61
Lot Frontage:	156.2500000
Lot Depth:	100.0000000
Building Frontage:	156.2500000
Building Depth:	100.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	0
Basement Type/Grade:	5
Assessed Land Value:	1039950.00000
Assessed Total Value:	7890300.00000
Exempt Total Value:	7890300.00000
Year Built:	2014
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.64000000000

DRAFT

LOT 28,TAXBLOCK 4005 (Continued) **S113915075**

Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040057501.00000000
Condominium Number:	4016
Census Tract 2:	1166
X Coordinate:	1017451
Y Coordinate:	185036
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 016
Tax Map #:	31303
E-designation Number:	Not reported
Apportionment BBL:	3040050028.00000000
Apportionment Date:	03/31/2017
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	2501 PITKIN AVENUE
Address:	2501 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.674238
Longitude:	-73.880081
OER Project Numbers:	15TMP0080K,15EH-N080K,15CVCP019K
BBL:	3.0400500283040001E+109
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3000000
BIN:	3040057501
NTA:	East New York

M112 **PITKIN BERRIMAN SITE** **US BROWNFIELDS** **1025442563**
South **2501 PITKIN AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.110 mi.
581 ft. **Site 2 of 5 in cluster M**

Relative:
Lower

Actual:
28 ft.

US BROWNFIELDS:

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	New York, City of
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97257906
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06
Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	New York, City of
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97249607
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

	years since the prior reporting period.
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	New York, City of
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Phase II
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97257906
Start Date:	2013-05-06 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	2013-11-13 00:00:00
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Recipient Name:	New York, City of
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Phase II
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	97249607
Start Date:	2013-05-06 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	2013-11-13 00:00:00
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

	with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Supplemental Groundwater Sampling
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30,

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

	2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Supplemental Groundwater Sampling
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Supplemental Groundwater Sampling
Assessment Funding:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	2014-10-27 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	2014-12-30 00:00:00
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Supplemental Groundwater Sampling
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

Name:	Pitkin Berriman Site
Address:	2501 Pitkin Avenue
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233421
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4005, Lot 28
Parcel Size:	0.47
Latitude:	40.6742101
Longitude:	-73.880013
Census Tract:	36047116600
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	11/1/2015
Redev Completition Date:	Not reported
Completed Date:	04/19/0018
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Supplemental Groundwater Sampling
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Contaminants Found at Actionable Level:	Lead Other Metals PAHs Pesticides SVOCs VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Site Management Plan (SMP) for long-term management of residual material, including plans for operation, maintenance, inspection and certification of the performance of Engineering Controls and

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

	Institutional Controls. Inspections will be performed annually. Inspection and Certification reports will be submitted by July 30, 2020 (for the reporting period calendar years 2018-2019), July 30, 2021 (for the reporting period calendar year 2020) and every year thereafter (for the reporting period consisting of the prior calendar year). Inspection and Certification Reports will cover all calendar years since the prior reporting period.
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	RAR
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Y
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Y
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Y
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	04/19/0018
Additional Cleanup/Treatment Tech Info:	soil removal, soil fill/backfill, composite cover Achieved Track 4 with engineering controls
IC in place:	Y
Address of Data Source (URL if available) 2:	RAR March 2018, NOC 4/19/18
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Y
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Y
Other:	Not reported
Additional Engineering Controls Information:	soil removal, soil fill/backfill, composite cover, vapor barrier system. Achieved Track 4 with engineering controls
Address of Data Source (URL if available) 3:	RAR
Indicate whether Engineering Controls are in place:	Y
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	0.47
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Pesticides
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Soil
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported

DRAFT

PITKIN BERRIMAN SITE (Continued) **1025442563**

RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	NOC 4/19/18
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	11640
Below Poverty Percent:	34.92
Meidan Income:	12325
Meidan Income Number:	19721
Meidan Income Percent:	59.16
Vacant Housing Number:	2135
Vacant Housing Percent:	17.21
Unemployed Number:	1686
Unemployed Percent:	5.06

G113 **CON EDISON** **NY MANIFEST** **S119077103**
ESE **166 MONTAUK AVE FRONT OF** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.111 mi.
585 ft. **Site 3 of 5 in cluster G**

Relative: NY MANIFEST:
Lower

Actual: EPA ID:	NYP004820664
28 ft. Country:	USA
Name:	Con Edison
Address:	166 MONTAUK AVE FRONT OF
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	166 MONTAUK AVE
Location Address 2:	SB 57353
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported

DRAFT

CON EDISON (Continued) **S119077103**

Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Dennis Huacon
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/07/2015
Trans1 Recv Date: 08/07/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/11/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004820664
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014472978JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 500
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)

DRAFT

CON EDISON (Continued) **S119077103**

Handling Method: Treat
Specific Gravity: 1

G114
ESE
< 1/8
0.111 mi.
585 ft.

CON EDISON
166 MONTAUK AVE FRONT OF
BROOKLYN, NY 11208

Site 4 of 5 in cluster G

NJ MANIFEST **S120675169**
N/A

Relative:
Lower

Actual:
28 ft.

NJ MANIFEST:

EPA ID:	NYP004820664
Name:	CON EDISON
Address:	166 MONTAUK AVE FRONT OF
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004820664
Manifest Number:	014472978JJK
Date Shipped:	8/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

DRAFT

CON EDISON (Continued) **S120675169**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

G115 **CON EDISON** **RCRA NonGen / NLR** **1019906403**
ESE **166 MONTAUK AVE FRONT OF** **FINDS** **NYP004820664**
< 1/8 **BROOKLYN, NY 11208** **ECHO**
0.111 mi.
585 ft. **Site 5 of 5 in cluster G**

Relative: **Lower**
Actual: **28 ft.**

RCRA Listings:

Date Form Received by Agency:		20150807
Handler Name:		Con Edison
Handler Address:		Montauk Ave Front Of
Handler City,State,Zip:		BROOKLYN, NY 11208
EPA ID:		NYP004820664
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No

DRAFT

CON EDISON (Continued) **1019906403**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150807
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150807
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

DRAFT

CON EDISON (Continued) **1019906403**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069653351

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906403
Registry ID: 110069653351

DFR URL:
Name: CON EDISON
Address: 166 Montauk Ave Front Of
City,State,Zip: BROOKLYN, NY 11208

I116 **LOT 39,TAXBLOCK 3971** **NY E DESIGNATION** **S118704335**
NW **278 ESSEX STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.113 mi.
595 ft. **Site 3 of 5 in cluster I**

Relative:
Lower

Actual:
29 ft.

E DESIGNATION:
Name: LOT 39,TAXBLOCK 3971
Address: 278 ESSEX STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 39
Tax Block: 3971
Borough Code: Not reported
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K

DRAFT

LOT 39,TAXBLOCK 3971 (Continued) **S118704335**

Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	278 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6772511
Longitude:	-73.8828014
Type Of Ownership Code:	Not reported
Owner Name:	278 ESSEX REALTY LLC
Borough:	BK
Tax Block:	3971
Tax Lot:	39
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168002005
Census Tract 2010:	1168
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B2: Two Family Dwellings - Frame
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	2617
Total Building Floor Area:	1085
Commercial Floor Area:	0
Residential Floor Area:	1085
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2

DRAFT

LOT 39,TAXBLOCK 3971 (Continued) **S118704335**

Number Of Floors:	2.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	25.0000000
Lot Depth:	104.6700000
Building Frontage:	20.0000000
Building Depth:	30.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	11820.00000
Assessed Total Value:	28620.00000
Exempt Total Value:	0.00000
Year Built:	1901
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.41000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039710039.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016758
Y Coordinate:	186039
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

N117 **LOT 53,TAXBLOCK 3971** **NY E DESIGNATION** **S118704404**
WNW **725 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.113 mi.
596 ft. **Site 1 of 8 in cluster N**

Relative: **Lower**
Actual: **28 ft.**

E DESIGNATION:

Name:	LOT 53,TAXBLOCK 3971
Address:	725 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	53
Tax Block:	3971
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported

DRAFT

LOT 53,TAXBLOCK 3971 (Continued) **S118704404**

Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	725 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6766146
Longitude:	-73.8830585
Type Of Ownership Code:	Not reported
Owner Name:	Y.I.Z. LLC
Borough:	BK
Tax Block:	3971
Tax Lot:	53
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168002005
Census Tract 2010:	1168
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	A1: One Family Dwellings - Two Stories Detached (Small Or Moderate Size, With Or Without Attic)
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	1000
Commercial Floor Area:	0
Residential Floor Area:	1000
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0

DRAFT

LOT 53,TAXBLOCK 3971 (Continued) **S118704404**

Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	1
Total Units:	1
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	20.0000000
Building Depth:	25.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	12480.00000
Assessed Total Value:	36360.00000
Exempt Total Value:	0.00000
Year Built:	1950
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.40000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039710053.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016687
Y Coordinate:	185807
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

N118 **CON EDISON** **E MANIFEST** **1031966669**
West **720 LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.114 mi.
602 ft. **Site 2 of 8 in cluster N**

Relative: E MANIFEST:
Lower

Manifest Tracking Number:	007164812GBF
Last Updated Date:	20220510
Shipped Date:	20220426
Received Date:	20220428

Actual:
28 ft.

DRAFT

CON EDISON (Continued) **1031966669**

Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	720 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	007164812GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007164812GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25

DRAFT

CON EDISON (Continued) **1031966669**

Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

L119 **CON EDISON** **E MANIFEST** **1031962270**
ENE **113 MONTAUK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.114 mi.
604 ft. **Site 2 of 7 in cluster L**

Relative: **Higher**

Actual: **34 ft.**

E MANIFEST:

Manifest Tracking Number:	007161450GBF
Last Updated Date:	20220617
Shipped Date:	20220603
Received Date:	20220606
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	113 MONTAUK AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105

DRAFT

CON EDISON (Continued) **1031962270**

Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	007161450GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007161450GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Waste Other Regulated Substances, Liquid N.O.S, 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported

DRAFT

CON EDISON (Continued) **1031962270**

Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

I120 **NY E DESIGNATION** **S118704345**
WNW **282 ESSEX STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.115 mi.
607 ft. **Site 4 of 5 in cluster I**

Relative:
Lower

Actual:
29 ft.

E DESIGNATION:

Name:	LOT 40,TAXBLOCK 3971
Address:	282 ESSEX STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	40
Tax Block:	3971
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	282 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6771825
Longitude:	-73.8827835
Type Of Ownership Code:	Not reported
Owner Name:	282 ESSEX REALTY LLC
Borough:	BK
Tax Block:	3971
Tax Lot:	40
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168002005
Census Tract 2010:	1168
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05

DRAFT

(Continued) **S118704345**

Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2610
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	2
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	104.5800000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	49950.00000
Assessed Total Value:	60750.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039710040.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016763
Y Coordinate:	186014

DRAFT

(Continued) **S118704345**

Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

I121 **LOT 41,TAXBLOCK 3971** **NY E DESIGNATION** **S118704348**
WNW **286 ESSEX STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.116 mi.
613 ft. **Site 5 of 5 in cluster I**

Relative:
Lower

Actual:
29 ft.

E DESIGNATION:

Name:	LOT 41,TAXBLOCK 3971
Address:	286 ESSEX STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	41
Tax Block:	3971
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	286 ESSEX STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6771138
Longitude:	-73.8827656
Type Of Ownership Code:	Not reported
Owner Name:	FLORES, JUDITH
Borough:	BK
Tax Block:	3971
Tax Lot:	41
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168002005
Census Tract 2010:	1168
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34

DRAFT

LOT 41,TAXBLOCK 3971 (Continued) **S118704348**

Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G0: Garages And Gasoline Stations - Residential Tax Class 1 Garage
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	2600
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	1
Total Units:	1
Lot Frontage:	25.0000000
Lot Depth:	104.2500000
Building Frontage:	20.0000000
Building Depth:	23.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	7020.00000
Assessed Total Value:	13740.00000
Exempt Total Value:	0.00000
Year Built:	1931
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039710041.00000000
Condominium Number:	Not reported

DRAFT

LOT 41,TAXBLOCK 3971 (Continued) **S118704348**

Census Tract 2:	1168
X Coordinate:	1016768
Y Coordinate:	185989
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

N122 **LOT 54,TAXBLOCK 3971** **NY E DESIGNATION** **S118704407**
WNW **LIBERTY AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.117 mi.
616 ft. **Site 3 of 8 in cluster N**

Relative: **Lower**
Actual: **28 ft.**

E DESIGNATION:

Name:	LOT 54,TAXBLOCK 3971
Address:	LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	54
Tax Block:	3971
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

H123 **31 BERRIMAN STREET** **NY UST** **U000411495**
North **31 BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11423**
0.118 mi.
623 ft. **Site 12 of 16 in cluster H**

Relative: **Higher**
Actual: **36 ft.**

UST:

Name:	31 BERRIMAN STREET
Address:	31 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11423
Id/Status:	2-510106 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594579.91075

DRAFT

31 BERRIMAN STREET (Continued) **U000411495**

UTM Y: 4503568.19732
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 21827
Affiliation Type: Emergency Contact
Company Name: 3100 ATLANTIC, LLC
Contact Type: Not reported
Contact Name: JOJO ROBINOWITZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 864-4446
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-15

Site Id: 21827
Affiliation Type: Facility Owner
Company Name: 3100 ATLANTIC, LLC
Contact Type: VP OF OPERATIONS
Contact Name: CARLOS QUINONES
Address1: 175 BLAKER AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11212
Country Code: 001
Phone: (917) 864-4446
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-15

Site Id: 21827
Affiliation Type: Mail Contact
Company Name: HYDRO TECH ENVIRONMENTAL CORP
Contact Type: Not reported
Contact Name: CARLOS QUINONES
Address1: 77 ARKAY DR
Address2: Not reported
City: HAUPPAUGE
State: NY
Zip Code: 11788
Country Code: 001
Phone: (631) 462-5866
EMail: CQUINONES@HTECORP.INFO
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2016-01-15

Site Id: 21827
Affiliation Type: Facility Operator
Company Name: 31 BERRIMAN STREET

DRAFT

31 BERRIMAN STREET (Continued) **U000411495**

Contact Type:	Not reported
Contact Name:	RESIDENTIAL COMPLEX
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 996-6456
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-01-15

Tank Info:

Tank Number:	001
Tank ID:	39478
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	01/05/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	11/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

DRAFT

H124 **31 BERRIMAN STREET** **UST FINDER** **1028571479**
North **31 BERRIMAN STREET** **N/A**
< 1/8 **BROOKLYN, NY 11423**
0.118 mi.
623 ft. **Site 13 of 16 in cluster H**

Relative:
Higher

Actual:
36 ft.

UST FINDER:

Object ID:	295913
Facility ID:	NY21827
Name:	31 BERRIMAN STREET
Address:	31 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY 11423
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	9402
Private Wells 1500ft:	54
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8808549999999
Y Coord:	40.677577
Latitude:	40.677577
Longitude:	-73.880855

UST FINDER:

Object ID:	1216772
Facility ID:	NY21827
Tank ID:	NY29545
Tank Status:	Closed
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

DRAFT

H125 **31 BERRIMAN ST.- TTF** **NY LTANKS** **S106971321**
North **31 BERRIMAN ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.118 mi.
623 ft. **Site 14 of 16 in cluster H**

Relative: LTANKS:
Higher

Actual: Name: 31 BERRIMAN ST.- TTF
36 ft. Address: 31 BERRIMAN ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0407617 / 2017-02-21
Facility ID: 0407617
Site ID: 332136
Spill Date: 2004-10-08
Spill Cause: Tank Test Failure
Spill Source: Tank Truck
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 2004-10-08
CID: 408
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-10-12
Spill Record Last Update: 2023-04-06
Spiller Name: REDA
Spiller Company: Not reported
Spiller Address: 62 ATKINS AVE.
Spiller County: 001
Spiller Contact: REDA
Spiller Phone: (718) 465-3600
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 267301
Latitude: 40.6781360
Longitude: -73.8807720
DEC Memo: 11/25/05- DEC Piper sent out ttf leterto Estate of Fren Stark 198-10 Jamaica Ave, Hollis NY 11423 1/23/06- DEC Piper spoke w/ Liz Farral regarding site. Currently there are two temp tanks on site. The management co has not decided on the fate of the tank. Repair or abandon. Liz will contact me when a decision has been made. 4/5/06- DEC Piper left message for Liz requesting update. 4/18/06- DEC Piper spoke w/ Liz froom Fred Stark, As per her, Eastmond to provide quote for new tank. Possibly AST. 2/22/07- DECP iper left message for liz requesting callback and info 7/21/15- DEC Piper- Received call from Hydrotech. They will work with owner to have spill closed. 12/21/15-Vought-See also open spill 1509573 at same apartment complex. PBS- 2-510106 2/21/17- DEC Piper received report from Hydrotech. The top of the tank was exposed and the liquid inside the tank was pumped out via Vacuum truck. A total of 690 gallons of liquid were pumped out and disposed of in accordance with local, state and federal regulations. Upon completion of the liquid pump

DRAFT

31 BERRIMAN ST.- TTF (Continued) **S106971321**

out, two (2) endpoint samples were collected from the bottom of the tank. Consequently the fill port and vent pipe were cut and removed and the UST was properly abandoned in place by filling it with sand. The results of the endpoint samples indicate that no petroleum contamination was identified in the soil beneath the tank. This is evidenced by the analytical results from EP-1 and EP-2, which revealed neither VOCs nor SVOCs are present in concentrations exceeding the most stringent cleanup criteria. Based on work to date, this spill is closed. See report in DEC Docs.

Remarks: PBS No: 2-510106

All TTF:

Facility ID:	0407617
Spill Number:	0407617
Spill Tank Test:	1548228
Site ID:	332136
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332136
Operable Unit ID:	1094393
Operable Unit:	01
Material ID:	574499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L126 **LOT 15,TAXBLOCK 3992** **NY E DESIGNATION** **S118704110**
ENE **844 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.121 mi.
638 ft. **Site 3 of 7 in cluster L**

Relative:
Higher

Actual:
34 ft.

E DESIGNATION:

Name:	LOT 15,TAXBLOCK 3992
Address:	844 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	15
Tax Block:	3992
Borough Code:	BK

DRAFT

LOT 15,TAXBLOCK 3992 (Continued) **S118704110**

E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	844 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6768759
Longitude:	-73.8782956
Type Of Ownership Code:	Not reported
Owner Name:	GARY ROSEN TRUSTEE
Borough:	BK
Tax Block:	3992
Tax Lot:	15
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192003005
Census Tract 2010:	1192
Census Block 2010:	3005
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G7: Garages And Gasoline Stations - Unlicensed Parking Lot
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	3585
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported

DRAFT

LOT 15,TAXBLOCK 3992 (Continued) **S118704110**

Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	39.8300000
Lot Depth:	90.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	146250.00000
Assessed Total Value:	146250.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039920015.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1018008
Y Coordinate:	185904
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 031
Tax Map #:	31303
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

DRAFT

N127
West
< 1/8
0.121 mi.
640 ft.

CON EDISON
LIBERTY AVE & LINWOOD ST NW
BROOKLYN, NY 11208

Site 4 of 8 in cluster N

NJ MANIFEST **S120678544**
N/A

Relative:
Lower

Actual:
28 ft.

NJ MANIFEST:

EPA ID:	NYP004884298
Name:	CON EDISON
Address:	LIBERTY AVE & LINWOOD ST NW
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004884298
Manifest Number:	014466849JJK
Date Shipped:	12/28/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

DRAFT

CON EDISON (Continued) **S120678544**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

N128 **CON EDISON** **RCRA NonGen / NLR** **1019909394**
West **LIBERTY AVE & LINWOOD ST NW** **NYP004884298**
< 1/8 **BROOKLYN, NY 11208**
0.121 mi.
640 ft. **Site 5 of 8 in cluster N**

Relative: **Lower**
Actual: **28 ft.**

RCRA Listings:

Date Form Received by Agency:	20151228
Handler Name:	Con Edison
Handler Address:	Liberty Ave & Linwood St Nw
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004884298
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

DRAFT

CON EDISON (Continued) **1019909394**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151228
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151228
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

DRAFT

CON EDISON (Continued) **1019909394**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

N129 **CON EDISON** **NY MANIFEST** **S117736596**
West **LINWOOD ST & LIBERTY AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.121 mi.
640 ft. **Site 6 of 8 in cluster N**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:
EPA ID: NYP004539094
Country: USA
Name: Con Edison
Address: LINWOOD ST & LIBERTY AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: LINWOOD ST & LIBERTY AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/20/2014
Trans1 Recv Date: 05/20/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/23/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004539094
Trans1 EPA ID: Not reported

DRAFT

CON EDISON (Continued) **S117736596**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013246087JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	350
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

N130 **CON EDISON** **RCRA NonGen / NLR** **1017776060**
West **LINWOOD ST & LIBERTY AVE** **NYP004539094**
< 1/8 **BROOKLYN, NY 11208**
0.121 mi.
640 ft. **Site 7 of 8 in cluster N**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20140521
Handler Name:	Con Edison
Handler Address:	Linwood St & Liberty Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004539094
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

Actual:
28 ft.

DRAFT

CON EDISON (Continued) **1017776060**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150814
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		20140521
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator

DRAFT

CON EDISON (Continued) **1017776060**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140521
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140621
Handler Name: CON EDISON MANHOLE: 4747
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

M131 **NYCT - SHEPHERD AVENUE STATION - C LINE** **NY MANIFEST** **S130582138**
South **SHEPHERD AVE & PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.121 mi.
641 ft. **Site 3 of 5 in cluster M**

Relative: NY MANIFEST:
Lower
EPA ID: NYR000225391
Actual: Country: USA
26 ft. Name: Nyct - Shepherd Avenue Station - C Line

NYCT - SHEPHERD AVENUE STATION - C LINE (Continued) **S130582138**

Address:	SHEPHERD AVE & PITKIN AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	SHEPHERD AVE & PITKIN AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nyct - Shepherd Avenue Station - C Line
Mailing Contact:	Sherry Bulkley
Mailing Address 1:	2 BROADWAY RM D3.123 (MAILBOX 321)
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

M132 **NYCT - SHEPHERD AVENUE STATION - C LINE** **E MANIFEST** **1032215807**
South **SHEPHERD AVE & PITKIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.121 mi.
641 ft. **Site 4 of 5 in cluster M**

Relative: **Lower**

Actual: **26 ft.**

E MANIFEST:

Manifest Tracking Number:	017582413FLE
Last Updated Date:	20221019
Shipped Date:	20221007
Received Date:	20221012
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000225391
Generator Name:	Nyct - Shepherd Avenue Station - C Line
Generator Location Street Number:	Not reported
Generator Location Street 1:	SHEPHERD AVE & PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY, 3RD FL CS.52
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY

DRAFT

NYCT - SHEPHERD AVENUE STATION - C LINE (Continued) **1032215807**

Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 017582413FLE
Transporter Line Number: 1
Transporter EPA ID: NJR986628162
Transporter Name: Iwt Transport, Inc.

Waste Line:
Manifest Tracking Number: 017582413FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3077
U.S. DOT Description: Na3077, Hazardous Waste, Solid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 20
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 3000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 1.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 1.5
Waste Quantity, in Kilograms: 1360.545
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 1360.545
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 1360.545
Quantity Haz Tons: 1.5

DRAFT

NYCT - SHEPHERD AVENUE STATION - C LINE (Continued) **1032215807**

Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

O133 **64 MONTAUK AVENUE** **NY LTANKS** **U000411507**
NNE **64 MONTAUK AVENUE** **NY UST** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.123 mi.
649 ft. **Site 1 of 8 in cluster O**

Relative:
Higher

Actual:
38 ft.

LTANKS:

Name:	ESTATE OF FRED STARK
Address:	64 MONTAUK AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0407730 / 2010-04-30
Facility ID:	0407730
Site ID:	332263
Spill Date:	2004-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2004-10-12
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2010-04-30
Spiller Name:	RITA
Spiller Company:	Not reported
Spiller Address:	61 ATKINS AVE
Spiller County:	001
Spiller Contact:	RITA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	389081
Latitude:	40.6778760
Longitude:	-73.8789310
DEC Memo:	04/30/10 - LZ Reviewed documents(eDocs)sent by Liz Farrell of Estate of Fred Stark. They indicate that the fill line was replaced, and the tanks system subsequently passed the tightness test. The spill case is closed. 11/29/05 Contacted John Leddy at Protest. I should call Rita at Estate of Fred Stark. Contact: Estate of fred Stark Rita 198-10 Jamaica Avenue Queens, NY 718-465-3600 Spoke to the Estate of Fred Stark. have not responsed with information that can close spill. Refer back to the Region. -S. Scharf
Remarks:	PBS No: 2-510246

All TTF:

DRAFT

64 MONTAUK AVENUE (Continued) **U000411507**

Facility ID:	0407730
Spill Number:	0407730
Spill Tank Test:	1548240
Site ID:	332263
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332263
Operable Unit ID:	1094511
Operable Unit:	01
Material ID:	574618
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	64 MONTAUK AVENUE
Address:	64 MONTAUK AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510246 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594753.70857
UTM Y:	4503542.93857
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21839
Affiliation Type:	Mail Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212

DRAFT

64 MONTAUK AVENUE (Continued) **U000411507**

Country Code:	001
Phone:	(917) 533-2236 206
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21839
Affiliation Type:	Facility Operator
Company Name:	64 MONTAUK AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21839
Affiliation Type:	Emergency Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 533-2236 206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21839
Affiliation Type:	Facility Owner
Company Name:	3124 ATLANTIC LLC
Contact Type:	AGENT
Contact Name:	DANNY SINGH
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236 206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

DRAFT

64 MONTAUK AVENUE (Continued) **U000411507**

Tank Info:

Tank Number:	001
Tank ID:	39490
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	02/26/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	10/31/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
C03 - Pipe Location - Aboveground/Underground Combination
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

O134 **64 MONTAUK AVENUE** **UST FINDER** **1028571488**
NNE **64 MONTAUK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.123 mi.
649 ft. **Site 2 of 8 in cluster O**

Relative:
Higher

Actual:
38 ft.

UST FINDER:

Object ID:	295906
Facility ID:	NY21839
Name:	64 MONTAUK AVENUE
Address:	64 MONTAUK AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	8892
Private Wells 1500ft:	54
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No

DRAFT

64 MONTAUK AVENUE (Continued) **1028571488**

SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.878802
Y Coord:	40.67733
Latitude:	40.67733
Longitude:	-73.878802

UST FINDER:

Object ID:	1216780
Facility ID:	NY21839
Tank ID:	NY111134
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

N135 **MANHOLE 4747** **NY Spills** **S104786958**
West **LIBERTY AV/LINWOOD ST** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.124 mi.
653 ft. **Site 8 of 8 in cluster N**

Relative:
Lower

Actual:
28 ft.

SPILLS:

Name:	MANHOLE 4747
Address:	LIBERTY AV/LINWOOD ST
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	0004179 / 2001-10-17
Facility ID:	0004179
Facility Type:	ER
DER Facility ID:	250104
Site ID:	309809
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-07-07
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-07-07
CID:	389
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party

DRAFT

MANHOLE 4747 (Continued) **S104786958**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-07
Spill Record Last Update:	2001-10-17
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	CALLER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 7/7/00 5gal cable oil leaked from blown joint on fdr 9B93. Oil regulator attached to joint. Approx 200gal water in hole. Will start cleanup as 50-499ppm. Sample returned 31ppm. Removed all liquids with tanker and cleaned hole. Double washed. Wrapped joint with diapers. 7/10/00 Wrapped joint was cut out on 7/7/00. There was no traces of oil on floor.
Remarks:	CALLER REPORTING A SPILL FROM A BLOWN CONDUCTOR JOINT CONED#132232 CLEAN UP 50-499 PCBS 200 GAL ON .

All Materials:

Site ID:	309809
Operable Unit ID:	826577
Operable Unit:	01
Material ID:	548923
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P136 **SPILL NUMBER 0003444** **NY Spills** **S104650940**
WSW **GLENMORE AV/LINWOOD ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
653 ft. **Site 1 of 5 in cluster P**

Relative: SPILLS:
Lower
Actual:
28 ft.

Name:	SPILL NUMBER 0003444
Address:	GLENMORE AV/LINWOOD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0003444 / 2000-08-03
Facility ID:	0003444
Facility Type:	ER
DER Facility ID:	157079
Site ID:	187978
DEC Region:	2

DRAFT

SPILL NUMBER 0003444 (Continued) **S104650940**

Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-06-20
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2000-06-20
CID:	281
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-20
Spill Record Last Update:	2000-10-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	STANLEY BALDWIN
Latitude:	40.6751290
Longitude:	-73.8829080
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND no drums found
Remarks:	ABOVE MATERIAL DISCOVERED AT ABOVE LOCATION IN A 55 GALLON DRUM. CALLER REQUESTING DEC TO RETRIEVE MATERIAL. ANY FURTHER QUESTIONS CONTACT CALLER AT ABOVE #.

All Materials:

Site ID:	187978
Operable Unit ID:	825661
Operable Unit:	01
Material ID:	551767
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	55.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P137 **GLENMORE AV/LINWOOD ST** **NY Spills** **S104787847**
WSW **GLENMORE AV/LINWOOD ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
653 ft. **Site 2 of 5 in cluster P**

Relative:
Lower

Actual:
28 ft.

SPILLS:

Name:	GLENMORE AV/LINWOOD ST
Address:	GLENMORE AV/LINWOOD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0005184 / 2003-05-14

DRAFT

GLENMORE AV/LINWOOD ST (Continued) **S104787847**

Facility ID:	0005184
Facility Type:	ER
DER Facility ID:	157079
Site ID:	187979
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	2000-07-31
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2000-07-31
CID:	389
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-31
Spill Record Last Update:	2003-05-14
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
Latitude:	40.6751290
Longitude:	-73.8829080
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 05/14/2003 tIPPLE
Remarks:	UPDATING/ ROADWAY SPILL OVER 2 YRS OLD/NFA caller reporting a spill of material from an abandon drum oil is all over the road and no clean up has been done no callback

All Materials:

Site ID:	187979
Operable Unit ID:	826237
Operable Unit:	01
Material ID:	549915
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

H138 **3100 ATLANTIC LLC** **NY UST** **U001841126**
North **36 ATKINS AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.124 mi.
655 ft. **Site 15 of 16 in cluster H**

Relative:
Higher

Actual:
38 ft.

UST:

Name:	3100 ATLANTIC LLC
Address:	36 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510297 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594642.94157
UTM Y:	4503642.44293
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21844
Affiliation Type:	Emergency Contact
Company Name:	3100 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21844
Affiliation Type:	Facility Owner
Company Name:	3100 ATLANTIC LLC
Contact Type:	AGENT
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2020-01-13

Site Id:	21844
Affiliation Type:	Mail Contact
Company Name:	LIBERTY ONE GROUP
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE

DRAFT

3100 ATLANTIC LLC (Continued) **U001841126**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21844
Affiliation Type:	Facility Operator
Company Name:	36 ATKINS AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-08

Tank Info:

Tank Number:	001
Tank ID:	39495
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	11/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	34
Date Test:	08/25/2017
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

DRAFT

3100 ATLANTIC LLC (Continued) **U001841126**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

H139 **36 ATKINS AVENUE** **UST FINDER** **1028571493**
North **36 ATKINS AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11208**
0.124 mi.
655 ft. **Site 16 of 16 in cluster H**

Relative:
Higher

Actual:
38 ft.

UST FINDER:

Object ID:	295924
Facility ID:	NY21844
Name:	36 ATKINS AVENUE
Address:	36 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	8857
Private Wells 1500ft:	54
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.879879
Y Coord:	40.677761
Latitude:	40.677761
Longitude:	-73.879879

UST FINDER:

Object ID:	1216785
Facility ID:	NY21844
Tank ID:	NY25833
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

DRAFT

L140
NE
< 1/8
0.124 mi.
657 ft.

CON EDISON - COMPANY OF NY
OPP OF 87 MONTAUK AVE
BROOKLYN, NY 11208

Site 4 of 7 in cluster L

E MANIFEST **1031951561**
N/A

Relative:
Higher

Actual:
36 ft.

E MANIFEST:

Manifest Tracking Number:	006857332GBF
Last Updated Date:	20210719
Shipped Date:	20210706
Received Date:	20210709
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	OPP OF 87 MONTAUK AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006857332GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006857332GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031951561**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

Q141 **CON ED COMPANY OF NY** **E MANIFEST** **1031948511**
SE **2531 PITKIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.128 mi.
676 ft. **Site 1 of 3 in cluster Q**

Relative: E MANIFEST:
Lower

Actual: Manifest Tracking Number:	006855863GBF
26 ft. Last Updated Date:	20210607
Shipped Date:	20210526
Received Date:	20210526
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Ed Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	2531 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY

DRAFT

CON ED COMPANY OF NY (Continued) **1031948511**

Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler St
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006855863GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006855863GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N

DRAFT

CON ED COMPANY OF NY (Continued) **1031948511**

Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

P142 **398 LINWOOD ST** **NY LTANKS** **S102672736**
West **398 LINWOOD ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.131 mi.
693 ft. **Site 3 of 5 in cluster P**

Relative: LTANKS:
Lower

Actual:
28 ft.

Name:	398 LINWOOD ST
Address:	398 LINWOOD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9412321 / 2003-02-13
Facility ID:	9412321
Site ID:	153913
Spill Date:	1994-12-14
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1994-12-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-01-30
Spill Record Last Update:	2003-02-13
Spiller Name:	Not reported
Spiller Company:	GLENDALE FUEL CO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

DRAFT

398 LINWOOD ST (Continued) **S102672736**

DER Facility ID:	130550
Latitude:	40.6758050
Longitude:	-73.8831550
DEC Memo:	Not reported
Remarks:	OVERFILLE TANK-A CONTRACTOR CAME & PUMPED MOST OF IT OUT, BUT LEFT 25 GL ON FLOOR

All Materials:

Site ID:	153913
Operable Unit ID:	1010021
Operable Unit:	01
Material ID:	374642
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M143 **CON EDISON** **E MANIFEST** **1031964168**
South **2488 PITKIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.134 mi.
708 ft. **Site 5 of 5 in cluster M**

Relative: **Lower**

Actual: **26 ft.**

E MANIFEST:

Manifest Tracking Number:	007163234GBF
Last Updated Date:	20220713
Shipped Date:	20220629
Received Date:	20220630
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	2488 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032

DRAFT

CON EDISON (Continued) **1031964168**

Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 007163234GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 007163234GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Waste Other Regulated Substances, Liquid N.O.S, 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 226.7575
Quantity Haz Tons: 0.25

DRAFT

CON EDISON (Continued) **1031964168**

Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

O144 **35 ATKINS AVE - TTF** **NY LTANKS** **S106971319**
NNE **35 ATKINS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.135 mi.
715 ft. **Site 3 of 8 in cluster O**

Relative:
Higher

Actual:
39 ft.

LTANKS:

Name:	35 ATKINS AVE - TTF
Address:	35 ATKINS AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0407615 / 2006-01-23
Facility ID:	0407615
Site ID:	332134
Spill Date:	2004-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2004-10-08
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2006-01-23
Spiller Name:	REDA
Spiller Company:	Not reported
Spiller Address:	62 ATKINS AVE.
Spiller County:	001
Spiller Contact:	REDA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	267299
Latitude:	40.6783550
Longitude:	-73.8798590
DEC Memo:	11/25/05- DEC Pipper sent out ttf leterto Estate of Fren Stark 198-10 Jamaica Ave, Hollis NY 11423 1/23/06- DEC Piper reviewed invoice fromn ABC Tank. Replaced vent line, stick line, feed and return lines. System passed thereafter. Closed.
Remarks:	PBS No: 2-510262

All TTF:

Facility ID:	0407615
Spill Number:	0407615
Spill Tank Test:	1548226
Site ID:	332134

DRAFT

35 ATKINS AVE - TTF (Continued) **S106971319**

Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332134
Operable Unit ID:	1094391
Operable Unit:	01
Material ID:	574497
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

O145 **33 ATKINS AVENUE** **UST FINDER** **1028571490**
NNE **33 ATKINS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.140 mi.
738 ft. **Site 4 of 8 in cluster O**

Relative:
Higher

Actual:
39 ft.

UST FINDER:

Object ID:	295930
Facility ID:	NY21841
Name:	33 ATKINS AVENUE
Address:	33 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	8848
Private Wells 1500ft:	53
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water

DRAFT

33 ATKINS AVENUE (Continued) **1028571490**

WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.879891
Y Coord:	40.6778100000001
Latitude:	40.67781
Longitude:	-73.879891

UST FINDER:

Object ID:	1216782
Facility ID:	NY21841
Tank ID:	NY26128
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

O146 **33 ATKINS AVENUE** **NY UST** **U000411509**
NNE **33 ATKINS AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.140 mi.
738 ft. **Site 5 of 8 in cluster O**

Relative:
Higher

Actual:
39 ft.

UST:

Name:	33 ATKINS AVENUE
Address:	33 ATKINS AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510262 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594660.98771
UTM Y:	4503595.09068
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21841
Affiliation Type:	Facility Owner
Company Name:	3124 ATLANTIC LLC
Contact Type:	AGENT
Contact Name:	DANNY SINGH
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236 206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI

DRAFT

33 ATKINS AVENUE (Continued) **U000411509**

Date Last Modified: 2019-04-04

Site Id: 21841
Affiliation Type: Emergency Contact
Company Name: 3124 ATLANTIC LLC
Contact Type: Not reported
Contact Name: MORDY PERKOWSKI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 533-2236 206
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-04

Site Id: 21841
Affiliation Type: Mail Contact
Company Name: 3124 ATLANTIC LLC
Contact Type: Not reported
Contact Name: MORDY PERKOWSKI
Address1: 175 BLAKE AVE.
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11212
Country Code: 001
Phone: (917) 533-2236 206
EMail: MORDY@LIBERTY1GROUP.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-04

Site Id: 21841
Affiliation Type: Facility Operator
Company Name: 33 ATKINS AVENUE
Contact Type: Not reported
Contact Name: MORDY PERKOWSKI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 220-2569
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2019-04-04

Tank Info:

Tank Number: 001
Tank ID: 39492

DRAFT

33 ATKINS AVENUE (Continued) **U000411509**

Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	02/26/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	10/31/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)

P147 **CON EDISON** **NY MANIFEST** **S117067120**
WSW **734 GLENMORE AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.143 mi.
755 ft. **Site 4 of 5 in cluster P**

Relative: **Lower**

Actual: **29 ft.**

NY MANIFEST:

EPA ID:	NYP004598587
Country:	USA
Name:	Con Edison
Address:	734 GLENMORE AVE
Address 2:	STRUCTURE 59892
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	734 GLENMORE AVE
Location Address 2:	STRUCTURE 59892
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR

DRAFT

CON EDISON (Continued) **S117067120**

Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/16/2014
Trans1 Recv Date: 07/16/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004598587
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002615029GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 100
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

DRAFT

K148 **NARVAEZ CLEANERS** **NY DRYCLEANERS** **S110247381**
SSW **2458 PITKIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.144 mi.
759 ft. **Site 2 of 3 in cluster K**

Relative: **Lower**

Actual: **27 ft.**

DRYCLEANERS:

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/03/2005
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/03/2005
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/03/2005
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/03/2005
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	11/16/2015
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	11/16/2015
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	12/29/2016
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 12/29/2016
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 12/29/2016
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 12/29/2016
Install Date: Not reported
Expiration Date: 06/25/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Registration Effective Date:	07/31/2001
Inspection Date:	09/14/2017
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/14/2017
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/14/2017
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/14/2017
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 09/27/2000
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/27/2000
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 09/27/2000
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 09/27/2000
Install Date: Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/27/2001
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/27/2001
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/27/2001
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 09/27/2001
Install Date: Not reported
Expiration Date: 06/25/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 09/04/2002
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/04/2002
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 09/04/2002
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 09/04/2002
Install Date: Not reported
Expiration Date: 06/25/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 09/03/2003
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/03/2003
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/03/2003
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/03/2003
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	12/31/2006
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	12/31/2006
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 12/31/2006
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 12/31/2006
Install Date: Not reported
Expiration Date: 06/25/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 10/03/2007
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Registration Effective Date:	07/16/2003
Inspection Date:	10/03/2007
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	10/03/2007
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	10/03/2007
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/25/2008
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/25/2008
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/25/2008
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/25/2008
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/22/2009
Install Date:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/22/2009
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 09/22/2009
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 09/22/2009
Install Date: Not reported
Expiration Date: 06/25/2019
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 09/22/2010
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/22/2010
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 09/22/2010
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 02/02/2016
Inspection Date: 09/22/2010
Install Date: Not reported
Expiration Date: 06/25/2019
Removal Date: Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 09/07/2012
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/07/2012
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 09/07/2012
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/07/2012
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/22/2011
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/22/2011
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/22/2011
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/22/2011
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/17/2013
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/17/2013
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Registration Effective Date:	01/08/2009
Inspection Date:	09/17/2013
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/17/2013
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	09/19/2014
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	09/19/2014
Install Date:	Not reported
Expiration Date:	01/08/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	01/08/2009
Inspection Date:	09/19/2014
Install Date:	Not reported
Expiration Date:	02/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/19/2014
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/31/2001
Inspection Date:	11/16/2015
Install Date:	Not reported
Expiration Date:	07/16/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

Name:	NARVAEZ CLEANERS
Address:	2458 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	07/16/2003
Inspection Date:	11/16/2015
Install Date:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/31/2001
Inspection Date: 09/03/2004
Install Date: Not reported
Expiration Date: 07/16/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 07/16/2003
Inspection Date: 09/03/2004
Install Date: Not reported
Expiration Date: 01/08/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE
City,State,Zip: BROOKLYN, NY 11208 2256
Facility ID: 2-6105-00346
Phone Number: 7182354974
Region: Not reported
Registration Effective Date: 01/08/2009
Inspection Date: 09/03/2004
Install Date: Not reported
Expiration Date: 02/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Perchloroethylene; CAS 127-18-4
Current Business: Not reported

Name: NARVAEZ CLEANERS
Address: 2458 PITKIN AVE

DRAFT

NARVAEZ CLEANERS (Continued) **S110247381**

City,State,Zip:	BROOKLYN, NY 11208 2256
Facility ID:	2-6105-00346
Phone Number:	7182354974
Region:	Not reported
Registration Effective Date:	02/02/2016
Inspection Date:	09/03/2004
Install Date:	Not reported
Expiration Date:	06/25/2019
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Perchloroethylene; CAS 127-18-4
Current Business:	Not reported

K149 **NARVAEZ CLEANERS** **RCRA-VSQG** **1000429305**
SSW **2458 PITKIN AVE** **ICIS** **NYD981079254**
1/8-1/4 **BROOKLYN, NY 11208** **US AIRS**
0.144 mi. **NY MANIFEST**
759 ft. **Site 3 of 3 in cluster K**

Relative: **Lower**
Actual: **27 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Narvaez Cleaners
Handler Address:		Pitkin Ave
Handler City,State,Zip:		BROOKLYN, NY 11208
EPA ID:		NYD981079254
Contact Name:		Not reported
Contact Address:		PITKIN AVE
Contact City,State,Zip:		BROOKLYN, NY 11208
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		PITKIN AVE
Mailing City,State,Zip:		BROOKLYN, NY 11208
Owner Name:	Narvaez Cleaners	
Owner Type:		Private
Operator Name:	Narvaez Cleaners	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NARVAEZ CLEANERS

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NARVAEZ CLEANERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NARVAEZ CLEANERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950406
Handler Name: NARVAEZ CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NARVAEZ CLEANERS
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NARVAEZ CLEANERS
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850520
Handler Name: NARVAEZ CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000261050034600325
FRS ID: 110004395226
Action Name: NARVAEZ CLEANERS 36047R145700325
Facility Name: NARVAEZ CLEANERS
Facility Address: 2458 PITKIN AVE
BROOKLYN, NY 112082256
Enforcement Action Type: Administrative Order
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 7216

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.674
Longitude in Decimal Degrees: -73.88156
Permit Type Desc: Not reported
Program System Acronym: NY0000002610500346
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261050034600323
FRS ID: 110004395226
Action Name: NARVAEZ CLEANERS 36047R145700323
Facility Name: NARVAEZ CLEANERS
Facility Address: 2458 PITKIN AVE
BROOKLYN, NY 112082256
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.674
Longitude in Decimal Degrees: -73.88156
Permit Type Desc: Not reported
Program System Acronym: NY0000002610500346
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261050034600317
FRS ID: 110004395226
Action Name: NARVAEZ CLEANERS 36047R145700317
Facility Name: NARVAEZ CLEANERS
Facility Address: 2458 PITKIN AVE
BROOKLYN, NY 112082256
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.674
Longitude in Decimal Degrees: -73.88156
Permit Type Desc: Not reported
Program System Acronym: NY0000002610500346
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261050034600308
FRS ID: 110004395226
Action Name: NARVAEZ CLEANERS 36047R145700308
Facility Name: NARVAEZ CLEANERS
Facility Address: 2458 PITKIN AVE
BROOKLYN, NY 112082256
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.674
Longitude in Decimal Degrees:	-73.88156
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610500346
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261050034600301
FRS ID:	110004395226
Action Name:	NARVAEZ CLEANERS 36047R145700301
Facility Name:	NARVAEZ CLEANERS
Facility Address:	2458 PITKIN AVE BROOKLYN, NY 112082256
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.674
Longitude in Decimal Degrees:	-73.88156
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610500346
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1000429305
Region Code:	02
Programmatic ID:	AIR NY0000002610500346
Facility Registry ID:	110004395226
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610500346
Facility Registry ID:	110004395226
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2000-09-27 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-09-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-09-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-10-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-11-20 00:00:00
Activity Status Date: 2001-11-20 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-02-10 00:00:00
Activity Status Date: 2004-02-10 00:00:00
Activity Group: Enforcement Action

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-08-29 00:00:00
Activity Status Date: 2006-08-29 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-09-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-09-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500346
Facility Registry ID: 110004395226
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Activity Date:	2007-10-03 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002610500346
Facility Registry ID:	110004395226
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-04-10 00:00:00
Activity Status Date:	2008-04-10 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Final Order Issued
Region Code:	02
Programmatic ID:	AIR NY0000002610500346
Facility Registry ID:	110004395226
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-01-14 00:00:00
Activity Status Date:	2008-01-14 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

NY MANIFEST:

EPA ID:	NYD981079254
Country:	USA
Name:	Narvaez Clnrs
Address:	2458 PITKIN AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	2458 PITKIN AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Narvaez Clnrs
Mailing Contact:	Narvaez Clnrs
Mailing Address 1:	2458 PITKIN AVENUE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182354974

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Manifest Data:

Document ID:	NYC1103646
Manifest Status:	Not reported
Trans1 State ID:	AM6252NY
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	07/23/1991
Trans1 Recv Date:	07/23/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/23/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00060
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC5602217
Manifest Status:	Not reported
Trans1 State ID:	NYLP3931
Year:	1999
Trans2 State ID:	T486JZNJ
Generator Ship Date:	04/14/1999
Trans1 Recv Date:	04/14/1999

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/19/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00060
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC4322327
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	10/25/1996
Trans1 Recv Date:	10/25/1996
Trans2 Recv Date:	10/29/1996
TSD Site Recv Date:	10/31/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	OHD980587364

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00060
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC2248007
Manifest Status:	Not reported
Trans1 State ID:	LP3931NY
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/1993
Trans1 Recv Date:	04/16/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00195
Units: Pounds
Number of Containers: 001
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC2293391
Manifest Status: Not reported
Trans1 State ID: LP3931NY
Year: 1993
Trans2 State ID: Not reported
Generator Ship Date: 05/13/1993
Trans1 Recv Date: 05/13/1993
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/13/1993
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981079254
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980785760
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane,

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

	Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00120
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC3353220
Manifest Status:	Not reported
Trans1 State ID:	JE4550NY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	11/29/1994
Trans1 Recv Date:	11/29/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/29/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00060
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC4390650
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	1996
Trans2 State ID:	MO001
Generator Ship Date:	11/25/1996
Trans1 Recv Date:	11/25/1996
Trans2 Recv Date:	12/03/1996
TSD Site Recv Date:	12/04/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Specific Gravity: 01.00

Document ID: NYC4674453
Manifest Status: Not reported
Trans1 State ID: NYGF2859
Year: 1997
Trans2 State ID: FT97538
Generator Ship Date: 03/18/1997
Trans1 Recv Date: 03/18/1997
Trans2 Recv Date: 03/24/1997
TSD Site Recv Date: 03/25/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981079254
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: MOD095038998
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00060
Units: Pounds
Number of Containers: 001
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC6573677
Manifest Status: Not reported
Trans1 State ID: GF1411NY
Year: 2001
Trans2 State ID: NJ044
Generator Ship Date: 08/29/2001

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Trans1 Recv Date:	08/29/2001
Trans2 Recv Date:	08/31/2001
TSD Site Recv Date:	09/07/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC1387899
Manifest Status:	Not reported
Trans1 State ID:	NY9381
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	12/09/1991
Trans1 Recv Date:	12/09/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/09/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00060
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC6183393
Manifest Status:	Not reported
Trans1 State ID:	NYCGF1411
Year:	2000
Trans2 State ID:	T104414IL
Generator Ship Date:	07/05/2000
Trans1 Recv Date:	07/05/2000
Trans2 Recv Date:	07/07/2000
TSD Site Recv Date:	07/11/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981079254
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

DRAFT

NARVAEZ CLEANERS (Continued) **1000429305**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00060
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
129 additional NY MANIFEST: record(s) in the EDR Site Report.

Q150
SE
1/8-1/4
0.151 mi.
798 ft.

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS **E MANIFEST** **1031960601**
2538 PITKIN AVE **N/A**
BROOKLYN, NY 11208

Site 2 of 3 in cluster Q

Relative:
Lower

Actual:
25 ft.

E MANIFEST:

Manifest Tracking Number:	007164521GBF
Last Updated Date:	20221027
Shipped Date:	20221014
Received Date:	20221020
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Queens Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2538 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001

DRAFT

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1031960601**

Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	007164521GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007164521GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported

DRAFT

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1031960601**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

R151
WNW
1/8-1/4
0.152 mi.
801 ft.

I.S. 302 - BROOKLYN K302 **NY AST** **A100320170**
350 LINWOOD STREET **N/A**
BROOKLYN, NY 11208

Site 1 of 2 in cluster R

Relative:
Lower

Actual:
29 ft.

AST:

Name:	I.S. 302 - BROOKLYN K302
Address:	350 LINWOOD STREET
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-354589
Program Type:	PBS
UTM X:	594346.85886
UTM Y:	4503517.40716
Expiration Date:	06/28/2028
Site Type:	School

Affiliation Records:

Site Id:	17636
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	bcu@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-11-01

Site Id:	17636
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY

DRAFT

I.S. 302 - BROOKLYN K302 (Continued) **A100320170**

State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5751
EMail: JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2025-03-11

Site Id: 17636
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: ATHNASIOS GUIRGUIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 392-3884
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2025-03-11

Site Id: 17636
Affiliation Type: Facility Operator
Company Name: I.S. 302 - BROOKLYN K302
Contact Type: Not reported
Contact Name: PETER MEEHAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 647-1301
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2023-10-13

Tank Info:

Tank Number: 001
Tank Id: 34526
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

DRAFT

I.S. 302 - BROOKLYN K302 (Continued) **A100320170**

K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/03/1970
Capacity Gallons:	10000
Tightness Test Method:	34
Date Test:	07/25/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	10/13/2023
Material Name:	#4 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	34527
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/03/1970
Capacity Gallons:	10000
Tightness Test Method:	34
Date Test:	07/25/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI

DRAFT

I.S. 302 - BROOKLYN K302 (Continued) **A100320170**

Last Modified: 10/13/2023
Material Name: #4 fuel oil (on-site consumption)

R152 **IS 302K SCHOOL** **RCRA-LQG** **1014399562**
WNW **350 LINWOOD ST** **E MANIFEST** **NYR000176511**
1/8-1/4 **BROOKLYN, NY 11208** **NY MANIFEST**
0.152 mi.
801 ft. **Site 2 of 2 in cluster R**

Relative: **Lower**
Actual: **29 ft.**

RCRA Listings:

Date Form Received by Agency:	20140220
Handler Name:	Is 302k School
Handler Address:	Linwood St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYR000176511
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	Not reported
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	SCAIEH DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Department Of Education
Owner Type:	Municipal
Operator Name:	Nyc Department Of Education
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC DEPARTMENT OF EDUCATION
Legal Status:	Municipal
Date Became Current:	19000101
Date Ended Current:	Not reported
Owner/Operator Address:	44-36 VERNON BLVD
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC DEPT OF SCHOOL FACILITIES
Legal Status:	Municipal
Date Became Current:	19700219
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF SCHOOL FACILITIES

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Legal Status: Municipal
Date Became Current: 19700219
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-472-8501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140220
Handler Name: IS 302K SCHOOL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100716
Handler Name: NYC DEPT OF ED - IS 302K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: Elementary And Secondary Schools

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20150616
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYCMK
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

E MANIFEST:
Manifest Tracking Number: 021048084JJK
Last Updated Date: 20191003
Shipped Date: 20190916
Received Date: 20190919

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000176511
Generator Name:	Is 302k
Generator Location Street Number:	Not reported
Generator Location Street 1:	350 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	589 JOHNSON AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11237
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	021048084JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Allstate Power Vac, Inc.

Waste Line:

Manifest Tracking Number:	021048084JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Rq, Na3077, Hazardous Waste, Solid, N.O.S. (Lead), 9 , Iii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	20
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.01

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.01
Waste Quantity, in Kilograms:	9.0703
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	9.0703
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	9.0703
Quantity Haz Tons:	0.01
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

NY MANIFEST:

EPA ID:	NYR000176511
Country:	USA
Name:	Nyc Dept Of Ed - Is 302k
Address:	350 LINWOOD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	350 LINWOOD ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nyc Dept Of Ed - Is 302k
Mailing Contact:	Mitch Knaps
Mailing Address 1:	589 JOHNSON AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184728501

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Trans1 State ID:	NJD000692061
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/25/2014
Trans1 Recv Date:	04/25/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD000622464
TSDF ID 2:	Not reported
Manifest Tracking Number:	000923844VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2821
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000201384
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/17/2013
Trans1 Recv Date:	07/17/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/18/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: 002183838GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H132
Waste Code a: B007
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 6922
Units: Kilograms
Number of Containers: 1
Container Type: Dump truck
Handling Method: Landfill
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD000692061
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/09/2014
Trans1 Recv Date: 07/09/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/16/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000176511
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: ALD000622464
TSDF ID 2: Not reported
Manifest Tracking Number: 000723149VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H132
Waste Code a: B007
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 2948
Units: Kilograms
Number of Containers: 1
Container Type: Metal boxes, cartons, cases (including roll-offs)
Handling Method: Landfill
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD000692061
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/09/2014
Trans1 Recv Date: 05/09/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/20/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000176511
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: ALD000622464
TSDF ID 2: Not reported
Manifest Tracking Number: 000923791VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H132
Waste Code a: Not reported
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Waste Code f:	B007
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2939
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000692061
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/04/2014
Trans1 Recv Date:	04/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD000622464
TSDF ID 2:	Not reported
Manifest Tracking Number:	000923911VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3374
Units:	Kilograms

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Number of Containers:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Year:	2018
Trans2 State ID:	OHD980614374
Generator Ship Date:	01/29/2018
Trans1 Recv Date:	01/29/2018
Trans2 Recv Date:	02/01/2018
TSD Site Recv Date:	02/10/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	011104201FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	950
Units:	Pounds
Number of Containers:	2
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAC300016672
Year:	2018
Trans2 State ID:	OHD980614374

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Generator Ship Date:	01/29/2018
Trans1 Recv Date:	01/29/2018
Trans2 Recv Date:	02/01/2018
TSD Site Recv Date:	02/10/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	011104201FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	375
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000692061
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/21/2014
Trans1 Recv Date:	03/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD000622464

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

TSDF ID 2: Not reported
Manifest Tracking Number: 000926404VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H132
Waste Code a: B007
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 3257
Units: Kilograms
Number of Containers: 1
Container Type: Metal boxes, cartons, cases (including roll-offs)
Handling Method: Landfill
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD000692061
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/15/2014
Trans1 Recv Date: 07/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000176511
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: ALD000622464
TSDF ID 2: Not reported
Manifest Tracking Number: 000805938VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1642
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD000692061
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/16/2014
Trans1 Recv Date:	05/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000176511
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD000622464
TSDF ID 2:	Not reported
Manifest Tracking Number:	000923781VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported

DRAFT

IS 302K SCHOOL (Continued) **1014399562**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3239
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	1

Q153 **CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS** **E MANIFEST** **1031960602**
SE **2540 PITKIN AVE** **N/A**
1/8-1/4 **QUEENS, NY 11208**
0.153 mi.
806 ft. **Site 3 of 3 in cluster Q**

Relative: **Lower**

Actual: **25 ft.**

E MANIFEST:

Manifest Tracking Number:	007166444GBF
Last Updated Date:	20230103
Shipped Date:	20221220
Received Date:	20221228
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Queens Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2540 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	QUEENS
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N

DRAFT

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1031960602**

Rejection Indicator: N

Transporter:
Manifest Tracking Number: 007166444GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 007166444GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 226.7575
Quantity Haz Tons: 0.25
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

DRAFT

L154 **CON ED - MH 3741** **RCRA NonGen / NLR** **1007206113**
ENE **LIBERTY AVE & MILFORD** **NY MANIFEST** **NYP004003802**
1/8-1/4 **BROOKLYN, NY 11212**
0.154 mi.
811 ft. **Site 5 of 7 in cluster L**

Relative: **Higher**
Actual: **33 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - Mh 3741
Handler Address:	Liberty Ave & Milford
Handler City,State,Zip:	BROOKLYN, NY 11212-0000
EPA ID:	NYP004003802
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - MH 3741	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - MH 3741	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - MH 3741	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004003802
Country: USA
Name: Consolidated Edison Co Mh03741
Address: LIBERTY AVE & MILFORD
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11212-0000
Zip 4: Not reported
Location Address 1: LIBERTY AVENUE MILFORD STREET
Location Address 2: Not reported
Location City,State,Zip: NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison Co Mh03741
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYB8467038
Manifest Status: Not reported
Trans1 State ID: 80416AB
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/17/1997
Trans1 Recv Date: 01/17/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/21/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004003802
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B003
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00882
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYB8467119
Manifest Status: Not reported
Trans1 State ID: 20854AD
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/22/1997
Trans1 Recv Date: 01/22/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/23/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004003802
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B003
Waste Code 2: Not reported

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00483
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYB8467218
Manifest Status:	Not reported
Trans1 State ID:	20854AD
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1997
Trans1 Recv Date:	01/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/28/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004003802
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B003
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00878
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYB8467785
Manifest Status:	Not reported
Trans1 State ID:	20859AD
Year:	1997
Trans2 State ID:	Not reported

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

Generator Ship Date:	01/21/1997
Trans1 Recv Date:	01/21/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/22/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004003802
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B003
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00861
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYB8468181
Manifest Status:	Not reported
Trans1 State ID:	ES9944
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1997
Trans1 Recv Date:	01/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/27/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004003802
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B007
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00001
Units: Cubic Yards
Number of Containers: 003
Container Type: Metal drums, barrels, kegs
Handling Method: Landfill
Specific Gravity: 01.00

Document ID: NYB8415738
Manifest Status: Not reported
Trans1 State ID: 80680AE
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/17/1997
Trans1 Recv Date: 01/17/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/21/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004003802
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B007
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00001
Units: Cubic Yards
Number of Containers: 002

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

Container Type: Metal drums, barrels, kegs
Handling Method: Landfill
Specific Gravity: 01.00

Document ID: NYB8415774
Manifest Status: Not reported
Trans1 State ID: 80680AE
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/23/1997
Trans1 Recv Date: 01/23/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/23/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004003802
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B007
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00001
Units: Cubic Yards
Number of Containers: 003
Container Type: Metal drums, barrels, kegs
Handling Method: Landfill
Specific Gravity: 01.00

Document ID: NYB8415792
Manifest Status: Not reported
Trans1 State ID: 80680AE
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/21/1997
Trans1 Recv Date: 01/21/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/22/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004003802

DRAFT

CON ED - MH 3741 (Continued) **1007206113**

Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

L155 **CON ED - MH 57244** **RCRA NonGen / NLR** **1007206129**
ENE **LIBERTY AVE & MILFORD ST** **NY MANIFEST** **NYP004004164**
1/8-1/4 **BROOKLYN, NY 11212**
0.154 mi.
811 ft. **Site 6 of 7 in cluster L**

Relative:
Higher

Actual:
33 ft.

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - Mh 57244
Handler Address:	Liberty Ave & Milford St
Handler City,State,Zip:	BROOKLYN, NY 11212-0000
EPA ID:	NYP004004164
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

DRAFT

CON ED - MH 57244 (Continued) **1007206129**

Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		19980227
Handler Name:	CON ED - MH 57244	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No

DRAFT

CON ED - MH 57244 (Continued) **1007206129**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - MH 57244	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - MH 57244	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	Electric Power Generation, Transmission And Distribution

NAICS Code:	22111
NAICS Description:	Electric Power Generation

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004004164
Country:	USA
Name:	Consolidated Edison Co
Address:	LIBERTY AVE & MILFORD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11212-0000
Zip 4:	Not reported
Location Address 1:	LIBERTY AND MILFORD MH57244
Location Address 2:	Not reported

DRAFT

CON ED - MH 57244 (Continued) **1007206129**

Location City,State,Zip: NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison Co
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYB8467209
Manifest Status: Not reported
Trans1 State ID: 20854AD
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/24/1997
Trans1 Recv Date: 01/24/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/28/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004004164
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B003
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00878
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

DRAFT

CON ED - MH 57244 (Continued) **1007206129**

Document ID:	NYB8468172
Manifest Status:	Not reported
Trans1 State ID:	ES9944
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1997
Trans1 Recv Date:	01/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/27/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004004164
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

L156 **CON EDISON** **RCRA NonGen / NLR** **1014398103**
ENE **LIBERTY AVE & MILFORD ST** **NY MANIFEST** **NYP004204541**
1/8-1/4 **BROOKLYN, NY 11201**
0.154 mi.
811 ft. **Site 7 of 7 in cluster L**

Relative: **Higher**
Actual: **33 ft.**

RCRA Listings:

Date Form Received by Agency:	20100319
Handler Name:	Con Edison
Handler Address:	Liberty Ave & Milford St
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004204541
Contact Name:	HERMAN BAKER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-267-3853

DRAFT

CON EDISON (Continued) **1014398103**

Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20100910
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

DRAFT

CON EDISON (Continued) **1014398103**

Sub-Part P Indicator: No

Historic Generators:
- Receive Date: 20100319
- Handler Name: CON EDISON
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Ny
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

NY MANIFEST:
- EPA ID: NYP004204541
- Country: USA
- Name: Consolidated Edison Mh57244
- Address: LIBERTY AVE & MILFORD ST
- Address 2: Not reported
- City,State,Zip: BROOKLYN, NY 11201
- Zip 4: Not reported
- Location Address 1: MH57244 LIBERTY AVE & MILFORD ST
- Location Address 2: Not reported
- Location City,State,Zip: BROOKLYN, NY
- Location Zip 4: Not reported
- Facility Status: Not reported
- Total Tanks: Not reported
- Code: BP

Mailing:
- Mailing Name: Consolidated Edison Mh57244
- Mailing Contact: Thomas Teeling
- Mailing Address 1: 4 IRVING PL RM 828
- Mailing Address 2: Not reported
- Mailing City,State,Zip: NEW YORK, NY 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

Manifest Data:
- Document ID: Not reported

DRAFT

CON EDISON (Continued) **1014398103**

Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2010
Trans1 Recv Date:	03/19/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/22/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004204541
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001442083FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	B007
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Kilograms
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2010
Trans1 Recv Date:	03/31/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

DRAFT

CON EDISON (Continued) **1014398103**

Generator EPA ID:	NYP004204541
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433646FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	B007
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

O157 **36 MONTAUK AVENUE** **NY UST** **U001841124**
NNE **36 MONTAUK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.155 mi.
817 ft. **Site 6 of 8 in cluster O**

Relative:
Higher

Actual:
39 ft.

UST:

Name:	36 MONTAUK AVENUE
Address:	36 MONTAUK AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510254 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594737.41069
UTM Y:	4503619.82290
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21840

DRAFT

36 MONTAUK AVENUE (Continued) **U001841124**

Affiliation Type:	Emergency Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 533-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21840
Affiliation Type:	Facility Owner
Company Name:	3124 ATLANTIC LLC
Contact Type:	AGENT
Contact Name:	DANNY SINGH
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21840
Affiliation Type:	Mail Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21840
Affiliation Type:	Facility Operator
Company Name:	36 MONTAUK AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported

DRAFT

36 MONTAUK AVENUE (Continued) **U001841124**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Tank Info:

Tank Number:	001
Tank ID:	39491
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	12/01/1948
Date Tank Closed:	02/26/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	10/31/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination
I05 - Overfill - Vent Whistle
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

O158 **36 MONTAUK AVENUE** **UST FINDER** **1028571489**
NNE **36 MONTAUK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.155 mi.
817 ft. **Site 7 of 8 in cluster O**

Relative:
Higher

Actual:
39 ft.

UST FINDER:

Object ID:	295945
Facility ID:	NY21840
Name:	36 MONTAUK AVENUE
Address:	36 MONTAUK AVENUE

DRAFT

36 MONTAUK AVENUE (Continued) **1028571489**

City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	8521
Private Wells 1500ft:	51
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8789839999999
Y Coord:	40.6780240000001
Latitude:	40.678024
Longitude:	-73.878984

UST FINDER:

Object ID:	1216781
Facility ID:	NY21840
Tank ID:	NY111135
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

O159 **PRIVATE RESIDENCE** **NY LTANKS** **S106971336**
NNE **36 MONTAUK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.155 mi.
817 ft. **Site 8 of 8 in cluster O**

Relative:
Higher

Actual:
39 ft.

LTANKS:

Name:	TTF
Address:	36 MONTAUK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0407731 / 2005-08-18
Facility ID:	0407731
Site ID:	332264
Spill Date:	2004-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4

DRAFT

PRIVATE RESIDENCE (Continued) **S106971336**

Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2004-10-12
CID:	403
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2005-08-18
Spiller Name:	RITA
Spiller Company:	Not reported
Spiller Address:	61 ATKINS AVE
Spiller County:	001
Spiller Contact:	RITA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	267421
Latitude:	40.6785370
Longitude:	-73.8790990
DEC Memo:	8/18/05. J.Krimgold closed this case due to a duplicate reporting see spill # 0407731.
Remarks:	PBS No: 2-510254

All TTF:

Facility ID:	0407731
Spill Number:	0407731
Spill Tank Test:	1548241
Site ID:	332264
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332264
Operable Unit ID:	1094512
Operable Unit:	01
Material ID:	574619
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

DRAFT

PRIVATE RESIDENCE (Continued) **S106971336**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	PRIVATE RESIDENCE
Address:	36 MONTAUK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0408110 / 2005-12-30
Facility ID:	0408110
Site ID:	332748
Spill Date:	2004-10-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	Con Ed Unassigned
Referred To:	Not reported
Reported to Dept:	2004-10-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-22
Spill Record Last Update:	2006-02-06
Spiller Name:	LIZ FARRELL
Spiller Company:	PRIVATE RESIDENCE
Spiller Address:	36 MAUNTAUK AVE
Spiller County:	001
Spiller Contact:	LIZ FARRELL
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	267421
Latitude:	40.6785370
Longitude:	-73.8790990
DEC Memo:	10/22/04 ttf letter sent 12/19/05 Feroze. Spill is transferred from Ketani to Feroze. 12/28/05. Talked to Mrs. Liz Farrell (718-465-3600). she informed me that she sent the tank test result to Albany. she is requested to submit tank test result to NYSDEC Region-2 office. TTF is also sent. 12/30/05.Mrs. Liz Farrel submitted Tank Test result. The result show that the Tank & the System is tight.Consultation with DEC Jeffery, the spill is closed.
Remarks:	RECOMMEND- REPAIR & RETEST

All TTF:

Facility ID:	0408110
Spill Number:	0408110
Spill Tank Test:	1548270
Site ID:	332748
Tank Number:	1

DRAFT

PRIVATE RESIDENCE (Continued) **S106971336**

Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332748
Operable Unit ID:	1094960
Operable Unit:	01
Material ID:	575093
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S160 **PRIVATE RESIDENCE** **NY LTANKS** **S106124044**
ESE **172 MILLFORD ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.156 mi.
823 ft. **Site 1 of 3 in cluster S**

Relative:
Lower

Actual:
27 ft.

LTANKS:

Name:	PRIVATE RESIDENCE
Address:	172 MILLFORD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0312000 / 2004-03-04
Facility ID:	0312000
Site ID:	257620
Spill Date:	2004-01-26
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2004-01-26
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

DRAFT

PRIVATE RESIDENCE (Continued) **S106124044**

Remediation Phase:	0
Date Entered In Computer:	2004-01-26
Spill Record Last Update:	2004-03-16
Spiller Name:	Not reported
Spiller Company:	TRUCKING USA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	DAVID PEREZ
Spiller Phone:	(917) 531-4502
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	210936
Latitude:	40.6753794
Longitude:	-73.8773526
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 1/26/04. J.Krimgold responded to the site. During fuel delivery to a 275 gal AST located in the basement of a two family house, was over-pressurized and split-open its side wall. About 250 gal of #2 oil was released onto the basement concrete floor. Trucking USA made a delivery ordered by Empire Fuel. Trucking USA contacted its insurance co. AIG to report a spill. Trade-Winds was hired to clean up. Currently oil is contained and due to a good floor condition can be picked up by vacuum truck. 20:15 Trade-Winds crew arrived and began the cleanup. Doug Schrimp is a project manager. 2/2/04. Krimgold/Embrose/phone. Investigation revealed that tank was over-pressurize due to a completely clogged vent line. Some oil went through the cracs in the concrete. These aras will be excavated to remove contaminated soil. 2/10/04. J. Krimgold spoke to Clif Embrose (Embrose Envir. 888-556-4734) a consultant for AIG Insurance. He stated that a cleanup has been completed and will request Trade-Winds to submit a closure report to DEC. Also, spoke to David Perez- house owner. He conferred that a cleanup and restoration has been completed. Closure pending report from Trade-Winds. 3/04/04. J.Krimgold reviewed a closure letter report prepared by Trade-Winds and dated February 26, 2004. Soil analytical results show no residual contamination inside the house but exceedance over TAGM criteria around exterior drain, where excavation was stopped at 5' due to the construction constraints. BIO-Solution has been applied at this area and then backfilled and cemented. NFA.
Remarks:	asbout 250 gallons spilled due to tank overfill they are in the process of cleaning it up

All Materials:

Site ID:	257620
Operable Unit ID:	877232
Operable Unit:	01
Material ID:	497235
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	250.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

T161
NNW
1/8-1/4
0.156 mi.
824 ft.

ST RITA'S SCHOOL
260 SHEPHERD AVENUE
BROOKLYN, NY 11208

Site 1 of 8 in cluster T

UST FINDER **1028600057**
N/A

Relative:
Higher

Actual:
33 ft.

UST FINDER:

Object ID:	295917
Facility ID:	NY8044
Name:	ST RITA'S SCHOOL
Address:	260 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	9502
Private Wells 1500ft:	44
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.88174
Y Coord:	40.6776520000001
Latitude:	40.677652
Longitude:	-73.88174

UST FINDER:

Object ID:	1319455
Facility ID:	NY8044
Tank ID:	NY108852
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

DRAFT

T162 **ST RITAS YOUTH CENTER** **UST FINDER** **1028600056**
NNW **260 SHEPHERD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.156 mi.
824 ft. **Site 2 of 8 in cluster T**

Relative:
Higher

Actual:
33 ft.

UST FINDER:

Object ID:	295916
Facility ID:	NY8043
Name:	ST RITAS YOUTH CENTER
Address:	260 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	9502
Private Wells 1500ft:	44
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.88174
Y Coord:	40.6776520000001
Latitude:	40.677652
Longitude:	-73.88174

UST FINDER:

Object ID:	1319454
Facility ID:	NY8043
Tank ID:	NY10643
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

DRAFT

T163 **ST RITAS YOUTH CENTER** **NY UST** **U001837635**
NNW **260 SHEPHERD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.156 mi.
824 ft. **Site 3 of 8 in cluster T**

Relative:
Higher

Actual:
33 ft.

UST:

Name:	ST RITA'S SCHOOL
Address:	260 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-215341 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594505.00471
UTM Y:	4503575.51902
Site Type:	School

Affiliation Records:

Site Id:	8044
Affiliation Type:	Facility Owner
Company Name:	ST RITAS SCHOOL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	260 SHEPHARD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 647-6040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8044
Affiliation Type:	Mail Contact
Company Name:	ST RITAS SCHOOL
Contact Type:	Not reported
Contact Name:	REV JOHN PEYTON
Address1:	260 SHEPHARD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 647-6040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8044
Affiliation Type:	Facility Operator
Company Name:	ST RITAS SCHOOL
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	Not reported

DRAFT

ST RITAS YOUTH CENTER (Continued) **U001837635**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 647-6040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8044
Affiliation Type:	Emergency Contact
Company Name:	ST RITAS SCHOOL
Contact Type:	Not reported
Contact Name:	REV JOHN PEYTON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 647-6040
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	22255
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None

DRAFT

ST RITAS YOUTH CENTER (Continued) **U001837635**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	001
Tank ID:	22256
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Affiliation Records:

Site Id:	8043
Affiliation Type:	Facility Owner
Company Name:	ST RITAS YOUTH CENTER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	260 SHEPHARD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(000) 647-5727
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	8043
Affiliation Type:	Mail Contact
Company Name:	ST RITAS YOUTH CENTER

DRAFT

ST RITAS YOUTH CENTER (Continued) **U001837635**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	260 SHEPHARD AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(000) 647-5727
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8043
Affiliation Type:	Facility Operator
Company Name:	ST RITAS YOUTH CENTER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(000) 647-5727
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8043
Affiliation Type:	Emergency Contact
Company Name:	ST RITAS YOUTH CENTER
Contact Type:	Not reported
Contact Name:	REV JOHN PEYTON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 647-4910
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	22255
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	10/01/1993

DRAFT

ST RITAS YOUTH CENTER (Continued) **U001837635**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	001
Tank ID:	22256
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

DRAFT

U164 **2437 PITKIN AVENUE** **NY VCP** **S129932219**
SSW **2437 PITKIN AVENUE** **NY NYC OER** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.156 mi.
825 ft. **Site 1 of 6 in cluster U**

Relative:
Lower

Actual:
29 ft.

VCP NYC:

Project ID:	17TMP0606K,17EH-N247K,18CVCP016K
Name:	2437 PITKIN AVENUE
Address:	2437 PITKIN AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3040030035
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.673905
Longitude:	-73.882342
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3319656
BIN:	3040030035
NTA:	East New York

NYC OER:

Name:	2437 PITKIN AVENUE
Address:	2437 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.673905
Longitude:	-73.882342
OER Project Numbers:	17TMP0606K,17EH-N247K,18CVCP016K
BBL:	3040030035
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3319656
BIN:	3040030035
NTA:	East New York

U165 **TAPIA AUTO REPAIR** **NY AST** **A100175396**
SSW **2437 PITKIN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.156 mi.
825 ft. **Site 2 of 6 in cluster U**

Relative:
Lower

Actual:
29 ft.

AST:

Name:	TAPIA AUTO REPAIR
Address:	2437 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-605088
Program Type:	PBS

DRAFT

TAPIA AUTO REPAIR (Continued) **A100175396**

UTM X: 594457.21409
UTM Y: 4503173.18274
Expiration Date: 01/31/2016
Site Type: Other

Affiliation Records:

Site Id: 26957
Affiliation Type: Facility Owner
Company Name: JOSE TAPIA
Contact Type: OWNER
Contact Name: JOSE TAPIA
Address1: 9121-84 AVE
Address2: Not reported
City: WOODHAVEN
State: NY
Zip Code: 11421
Country Code: 001
Phone: (718) 850-1931
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 2010-10-21

Site Id: 26957
Affiliation Type: Mail Contact
Company Name: TAPIA AUTO REPAIR
Contact Type: Not reported
Contact Name: JOSE TAPIA
Address1: 2437 PITKIN AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11208
Country Code: 001
Phone: (718) 647-6534
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 26957
Affiliation Type: Facility Operator
Company Name: TAPIA AUTO REPAIR
Contact Type: Not reported
Contact Name: JOSE TAPIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 647-6534
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 26957

DRAFT

TAPIA AUTO REPAIR (Continued) **A100175396**

Affiliation Type:	Emergency Contact
Company Name:	JOSE TAPIA
Contact Type:	Not reported
Contact Name:	JOSE TAPIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 861-4968
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	A-713600
Tank Id:	59419
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	D00 - Pipe Type - No Piping G01 - Tank Secondary Containment - Diking (Aboveground) J02 - Dispenser - Suction Dispenser A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating H00 - Tank Leak Detection - None L09 - Piping Leak Detection - Exempt Suction Piping C01 - Pipe Location - Aboveground I04 - Overfill - Product Level Gauge (A/G) F00 - Pipe External Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1996
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

DRAFT

U166
SSW
1/8-1/4
0.158 mi.
834 ft.

CON EDISON - BROOKLYN ENVIRONMENTAL OPS
2446 PITKIN AVE
BROOKLYN, NY 11208

Site 3 of 6 in cluster U

E MANIFEST **1031949034**
N/A

Relative:
Lower

Actual:
28 ft.

E MANIFEST:

Manifest Tracking Number:	006875080GBF
Last Updated Date:	20210712
Shipped Date:	20210702
Received Date:	20210702
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2446 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 Rahway Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Avenel
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006875080GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006875080GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON - BROOKLYN ENVIRONMENTAL OPS (Continued) **1031949034**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	400
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.2
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2
Waste Quantity, in Kilograms:	181.406
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	181.406
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	181.406
Quantity Haz Tons:	0.2
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

S167 **CON ED COMPANY OF NY** **E MANIFEST** **1031948512**
ESE **2561 PITKINS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.164 mi.
865 ft. **Site 2 of 3 in cluster S**

Relative: E MANIFEST:
Lower

Actual: Manifest Tracking Number:	006855860GBF
24 ft. Last Updated Date:	20210607
Shipped Date:	20210525
Received Date:	20210526
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Ed Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	2561 PITKINS AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY

DRAFT

CON ED COMPANY OF NY (Continued) **1031948512**

Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler St
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006855860GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006855860GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N

DRAFT

CON ED COMPANY OF NY (Continued) **1031948512**

Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

V168 **TANK TEST FAILURES TTF (TWO)** **NY LTANKS** **S118462523**
North **3100 ATLANTIC AVENUE/31 BERRIMAN STREET** **NY NYC LAND USE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.165 mi.
870 ft. **Site 1 of 10 in cluster V**

Relative: **Higher**

Actual: **37 ft.**

LTANKS:

Name:	TANK TEST FAILURES TTF (TWO)
Address:	3100 ATLANTIC AVENUE/31 BERRIMAN STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1509573 / 2023-04-06
Facility ID:	1509573
Site ID:	520207
Spill Date:	2015-12-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2015-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-21
Spill Record Last Update:	2023-04-06
Spiller Name:	Not reported
Spiller Company:	FRED CATAPANO
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ZAID NALLY
Spiller Phone:	(800) 385-2650
Spiller Extention:	Not reported
DEC Region:	2

DRAFT

TANK TEST FAILURES TTF (TWO) (Continued) **S118462523**

DER Facility ID: 474508
Latitude: Not reported
Longitude: Not reported
DEC Memo: 12/21/15-Vought-Duty desk officer. Called and spoke to Zaida Nally (Universal Tank Services Ph:(800)385-2650) and she noted that call was for two tank test failures (at Building #6 and Building #7) and both failures were dry leaks. Vought provided email address so that she could send in failed reports and also provided contact information for DEC Mahat (who as runner will be assigned the case). Nally noted that they were contracted out by Carlos Quinonez from HydroTech Environmental and she had no contact information for the property owner. Nally also noted that there were going to test three additional USTs tomorrow and Vought requested that this spill number be updated so that there was one DEC Project manager for all the cases as one responsible party. No PBS Registration found in PBS database. Vought called HydroTech (Ph:631-462-5866) and he noted that the tests were part of the requirement for open spill 0407617 that is being managed by DEC Piper. He also noted that the tanks that were the subject of this report were both 2,500-gallon tanks and there are a total of eleven that are going to be tested. Owners information as per Quinonez is: FCA Realty 325 East 104th Street New York, NY 10029 Ph: (212)996-6456 Email: sberger@familynyc.com Vought to discuss site with Piper to determine if spill should be assigned to him and whether TTFs should be sent out as per standard protocol. 2/16/17-Vought-Received email from Douglas Sullivan (Dewberry) on 2/14/17 that Mr. Vought: Raphael Ketani identified you as the case manager for this open spill. For the subject spill it is my understanding that an unknown volume of No. 2 FO was spilled (tank test failure), with unknown resources affected (in 2015). I am trying to assess if this spill may impact some proposed green infrastructure borings in the vicinity of these spills. I am wondering if you can provide me with any current information that will help me to assess if this spill is something to be concerned about when advancing the borings and potentially installing bioswales? Any information to assist would be appreciated, I can be reached at the number below. Thanks, Vought sent reply to Dewberry (Sullivan) that Douglas, With respect to your inquiry below, that particular case, albeit under my name, is currently being managed by Ryan Piper as he is looking into all spills at the Berriman Avenue apartment complex. In talking to Ryan about your inquiry, as well as Andre Obligado and Hiralkumar Patel, they have all also received requests from Dewberry for more information on spills in relation to the proposed green infrastructure borings near their sites. Multiple inquiries to multiple DEC Project Managers on multiple sites may necessitate a more effective way of getting Dewberry the information it needs. We had set up a prior arrangement with Dewberry, when they were working on the numerous Hurricane Sandy Build-it Back projects, where they came into our DEC offices and we gave them review access to our Spills database and files so that they could do the research here in the office and also save time to the numerous Project Mangers managing the sites. As such, please provide more background on the proposed green infrastructure borings including the scope of the project, which government agency the projects is for, and any other information that may be useful to us. Pending your reply, we may request that Dewberry come into our DEC Region 2 Office to do the database research directly. Thanks! DEC Requires: 1)submission of PBS registration of for failed tanks 2)submission of copies of failed

TANK TEST FAILURES TTF (TWO) (Continued) **S118462523**

test reports. 12/19/2017 - Austin - Project transferred from Vought to Lakhani - end 08/05/19 - Lakhani - Spill being transferred to Lin. 4/6/23-Lin-The tanks failed as a dry leak. All eleven (11) tanks in the apartment complex were closed out or closed in place. Spill#0407617 for the tank test failure at building 10 managed by DEC Ryan was closed out. Case closed.

Remarks: tank failure. there are 2 building that fail the test building # 6 and #7

All Materials:

Site ID:	520207
Operable Unit ID:	1269248
Operable Unit:	01
Material ID:	2273250
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	3100 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6779347
Longitude:	-73.8803198
Type Of Ownership Code:	Not reported
Owner Name:	3100 ATLANTIC LLC
Borough:	BK
Tax Block:	3974
Tax Lot:	1
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192003002
Census Tract 2010:	1192
Census Block 2010:	3002
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R5: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported

DRAFT

TANK TEST FAILURES TTF (TWO) (Continued) **S118462523**

Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	150600
Total Building Floor Area:	79254
Commercial Floor Area:	0
Residential Floor Area:	79254
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	53
Number Of Floors:	2.0000000
Residential Units:	108
Total Units:	108
Lot Frontage:	200.0000000
Lot Depth:	745.0000000
Building Frontage:	336.0000000
Building Depth:	34.0000000
Extension Code:	E
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	1
Basement Type/Grade:	2
Assessed Land Value:	227700.00000
Assessed Total Value:	2778750.00000
Exempt Total Value:	0.00000
Year Built:	1950
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.53000000000
Maximum Allowable Residential Far:	1.25000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039740001.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1017446
Y Coordinate:	186289
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 014
Tax Map #:	31302
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported

DRAFT

TANK TEST FAILURES TTF (TWO) (Continued) **S118462523**

2015 Preliminary Flood Insurance Rate Map Indicator: Not reported
Version Number: 24v4.1
Changed By DCP: Not reported

P169 **CON EDISON** **NY MANIFEST** **S117067117**
WSW **SEC GLENMORE & ELTON** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.167 mi.
880 ft. **Site 5 of 5 in cluster P**

Relative:
Lower

Actual:
30 ft.

NY MANIFEST:

EPA ID:	NYP004598561
Country:	USA
Name:	Con Edison
Address:	SEC GLENMORE & ELTON
Address 2:	STRUCTURE 58493
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	SEC GLENMORE & ELTON
Location Address 2:	STRUCTURE 58493
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/16/2014
Trans1 Recv Date:	07/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004598561
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504290GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

DRAFT

CON EDISON (Continued) **S117067117**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

V170 **3100 ATLANTIC LLC** **NY UST** **U000411511**
North **3104 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.167 mi.
880 ft. **Site 2 of 10 in cluster V**

Relative:
Higher

Actual:
37 ft.

UST:

Name:	3100 ATLANTIC LLC
Address:	3104 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510289 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594606.01667
UTM Y:	4503715.38767
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21843
Affiliation Type:	Facility Operator
Company Name:	3104 ATLANTIC AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

DRAFT

3100 ATLANTIC LLC (Continued) **U000411511**

Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21843
Affiliation Type:	Emergency Contact
Company Name:	3100 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21843
Affiliation Type:	Mail Contact
Company Name:	LIBERTY ONE GROUP
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2019-12-31

Site Id:	21843
Affiliation Type:	Facility Owner
Company Name:	3100 ATLANTIC LLC
Contact Type:	AGENT
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 819-6161
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2020-01-13

DRAFT

3100 ATLANTIC LLC (Continued) **U000411511**

Tank Info:

Tank Number:	001
Tank ID:	39494
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	12/01/1948
Date Tank Closed:	11/03/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	08/23/2017
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

V171 **3104 ATLANTIC AVENUE** **UST FINDER** **1028571492**
North **3104 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.167 mi.
880 ft. **Site 3 of 10 in cluster V**

Relative:
Higher

Actual:
37 ft.

UST FINDER:

Object ID:	295970
Facility ID:	NY21843
Name:	3104 ATLANTIC AVENUE
Address:	3104 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	9227
Private Wells 1500ft:	47
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported

DRAFT

3104 ATLANTIC AVENUE (Continued) **1028571492**

SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.880555
Y Coord:	40.6785360000001
Latitude:	40.678536
Longitude:	-73.880555

UST FINDER:

Object ID:	1216784
Facility ID:	NY21843
Tank ID:	NY26130
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

V172 **CON EDISON - SERVICE BOX 18072** **NY LTANKS** **S106971320**
North **3104 ATLANTIC AVE** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.167 mi.
880 ft. **Site 4 of 10 in cluster V**

Relative:
Higher

Actual:
37 ft.

LTANKS:

Name:	3104ATLANTIC AVE - TTF
Address:	3104 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0407616 / 2006-01-23
Facility ID:	0407616
Site ID:	332135
Spill Date:	2004-10-08
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2004-10-08
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

DRAFT

CON EDISON - SERVICE BOX 18072 (Continued) **S106971320**

Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2006-01-23
Spiller Name:	REDA
Spiller Company:	Not reported
Spiller Address:	62 ATKINS AVE.
Spiller County:	001
Spiller Contact:	REDA
Spiller Phone:	(718) 465-3600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	267300
Latitude:	40.6789630
Longitude:	-73.8806450
DEC Memo:	11/25/05- DEC Pipper sent out ttf leterto Estate of Fren Stark 198-10 Jamaica Ave, Hollis NY 11423 1/23/06- DEC Piper review receipts form ABC Tank. Repairs made to gaskets, vent line, stick line and feed and return lines. System passed thereafter. E-docs. Closed.
Remarks:	PBS No: 2-510289

All TTF:

Facility ID:	0407616
Spill Number:	0407616
Spill Tank Test:	1548227
Site ID:	332135
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	332135
Operable Unit ID:	1094392
Operable Unit:	01
Material ID:	574498
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYP005175260
Country:	USA
Name:	Con Edison - Service Box 18072

DRAFT

CON EDISON - SERVICE BOX 18072 (Continued) **S106971320**

Address:	3104 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	3104 ATLANTIC AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison - Service Box 18072
Mailing Contact:	Annamarie Moylan
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602278

U173 **CON EDISON - SERVICE BOX 61800** **NY MANIFEST** **S120958251**
SSW **418 ESSEX ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.168 mi.
889 ft. **Site 4 of 6 in cluster U**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:

EPA ID:	NYP004925473
Country:	USA
Name:	Con Edison - Service Box 61800
Address:	418 ESSEX ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	418 ESSEX ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison - Service Box 61800
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

DRAFT

U174 **CON EDISON - BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031949180**
SSW **418 ESSEX ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.168 mi.
889 ft. **Site 5 of 6 in cluster U**

Relative:
Lower

Actual:
28 ft.

E MANIFEST:

Manifest Tracking Number:	006870244GBF
Last Updated Date:	20220203
Shipped Date:	20220119
Received Date:	20220119
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	418 ESSEX ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 Rahway Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Avenel
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006870244GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006870244GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON - BROOKLYN ENVIRONMENTAL OPS (Continued) **1031949180**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	300
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.15
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.15
Waste Quantity, in Kilograms:	136.0545
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	136.0545
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	136.0545
Quantity Haz Tons:	0.15
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

W175 **VERIZON NEW YORK INC-NY. (NY34307)** **NY TANKS** **U003074742**
ENE **862 LIBERTY AVENUE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.170 mi.
900 ft. **Site 1 of 5 in cluster W**

Relative: **Higher**

Actual: **33 ft.**

TANKS:

Name:	VERIZON NEW YORK INC-NY. (NY34307)
Address:	862 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Facility Id:	2-344559
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	12/14/2027
UTM X:	594842.99538
UTM Y:	4503519.44733

SPILLS:

DRAFT

VERIZON NEW YORK INC-NY. (NY34307) (Continued) **U003074742**

Name:	VERIZON
Address:	862 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0130020 / 2001-08-28
Facility ID:	0130020
Facility Type:	ER
DER Facility ID:	150135
Site ID:	178821
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-08-28
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2001-08-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-08-28
Spill Record Last Update:	2002-04-10
Spiller Name:	Not reported
Spiller Company:	VERIZON
Spiller Address:	221 EAST 37TH STREET
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6770955
Longitude:	-73.8778089
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE
Remarks:	MINOR SOIL CONTAMINATION ENCOUNTERED DURING TANK REMOVAL. SPILL OPENED FOR TRACKING PURPOSES.

All Materials:

Site ID:	178821
Operable Unit ID:	851655
Operable Unit:	01
Material ID:	526709
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

T176 **MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST** **RCRA NonGen / NLR** **1027222210**
NW **ATLANTIC AVE & ESSEX ST** **NYR000255521**
1/8-1/4 **BROOKLYN, NY 11208**
0.171 mi.
905 ft. **Site 4 of 8 in cluster T**

Relative:
Higher

Actual:
33 ft.

RCRA Listings:

Date Form Received by Agency:		20250407
Handler Name:		Mta Lirr - Atlantic Ave Tunnel At Essex St
Handler Address:		Atlantic Ave & Essex St
Handler City,State,Zip:		BROOKLYN, NY 11208
EPA ID:		NYR000255521
Contact Name:		MAGDALENA RYCHTECKA
Contact Address:		183RD ST MC 3147
Contact City,State,Zip:		HOLLIS, NY 11423
Contact Telephone:		347-804-3069
Contact Fax:		Not reported
Contact Email:		MRYCHTE@LIRR.ORG
Contact Title:		MANAGER CORP PROJECT EHS COMPLIANCE
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		183RD ST MC 3147
Mailing City,State,Zip:		HOLLIS, NY 11423
Owner Name:	Mta Lirr	
Owner Type:		State
Operator Name:	Mta Lirr	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

DRAFT

MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST (Continued) **1027222210**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250411
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA LIRR	
Legal Status:	State
Date Became Current:	18500101
Date Ended Current:	Not reported
Owner/Operator Address:	93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA LIRR	
Legal Status:	State
Date Became Current:	18500101
Date Ended Current:	Not reported
Owner/Operator Address:	93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA LIRR	
Legal Status:	State
Date Became Current:	18500101
Date Ended Current:	Not reported
Owner/Operator Address:	93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip:	JAMAICA, NY 11435
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

DRAFT

MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST (Continued) **1027222210**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA LIRR
Legal Status: State
Date Became Current: 18500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA LIRR
Legal Status: State
Date Became Current: 18500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA LIRR
Legal Status: State
Date Became Current: 18500101
Date Ended Current: Not reported
Owner/Operator Address: 93-02 SUTPHIN BLVD
Owner/Operator City,State,Zip: JAMAICA, NY 11435
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20230928
Handler Name: MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220523
Handler Name: MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

DRAFT

MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST (Continued) **1027222210**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250407
Handler Name: MTA LIRR - ATLANTIC AVE TUNNEL AT ESSEX ST
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 485112
NAICS Description: Commuter Rail Systems

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

X177 **B&B URBAN LLC - 315 LINWOOD STREET** **RCRA-LQG** **1024892107**
NW **315 LINWOOD STREET** **E MANIFEST** **NYR000237008**
1/8-1/4 **BROOKLYN, NY 11208**
0.173 mi.
911 ft. **Site 1 of 7 in cluster X**

Relative: **Lower**
Actual: **31 ft.**

RCRA Listings:
Date Form Received by Agency: 20180711
Handler Name: B&B Urban Llc - 315 Linwood Street
Handler Address: Linwood Street
Handler City,State,Zip: BROOKLYN, NY 11208
EPA ID: NYR000237008
Contact Name: HELI PINILLOS
Contact Address: PARK AVENUE SOUTH
Contact City,State,Zip: NEW YORK, NY 10016
Contact Telephone: 646-484-5700 x12
Contact Fax: Not reported
Contact Email: HPINILLOS@BANDBURBAN.COM
Contact Title: PROJECT MANAGER
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		PARK AVENUE SOUTH
Mailing City,State,Zip:		NEW YORK, NY 10016
Owner Name:	B&B Urban Llc	
Owner Type:		Private
Operator Name:	B&B Urban Llc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20180713
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: B&B URBAN LLC	
Legal Status:	Private
Date Became Current:	20180626
Date Ended Current:	Not reported
Owner/Operator Address:	419 PARK AVENUE SOUTH
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	646-484-5700
Owner/Operator Telephone Ext:	12
Owner/Operator Fax:	Not reported
Owner/Operator Email:	HPINILLOS@BANDBURBAN.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: B&B URBAN LLC	
Legal Status:	Private
Date Became Current:	20180626
Date Ended Current:	Not reported
Owner/Operator Address:	419 PARK AVENUE SOUTH
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	646-484-5700
Owner/Operator Telephone Ext:	12
Owner/Operator Fax:	Not reported
Owner/Operator Email:	HPINILLOS@BANDBURBAN.COM

Historic Generators:

Receive Date:	20180711
Handler Name:	B&B URBAN LLC - 315 LINWOOD STREET
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	236116
NAICS Description:	New Multifamily Housing Construction (Except Operative Builders)

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20180724
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

E MANIFEST:

Manifest Tracking Number:	016324875JJK
Last Updated Date:	20190618
Shipped Date:	20180727
Received Date:	20180727
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324876JJK
Last Updated Date:	20191023
Shipped Date:	20180727
Received Date:	20180727
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324879JJK
Last Updated Date:	20211201
Shipped Date:	20180807
Received Date:	20180811
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324880JJK
Last Updated Date:	20191112
Shipped Date:	20180803
Received Date:	20180803
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324881JJK
Last Updated Date:	20200106
Shipped Date:	20180803
Received Date:	20180803
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	315
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	419
Generator Mail Street 1:	PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324882JJK
Last Updated Date:	20200110
Shipped Date:	20180803
Received Date:	20180803
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	315
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	419
Generator Mail Street 1:	PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324883JJK

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Last Updated Date:	20200109
Shipped Date:	20180803
Received Date:	20180803
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	315
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	419
Generator Mail Street 1:	PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324884JJK
Last Updated Date:	20190927
Shipped Date:	20180831
Received Date:	20180831
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016324885JJK
Last Updated Date:	20190927
Shipped Date:	20180831
Received Date:	20180831
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	016324923JJK
Last Updated Date:	20200212
Shipped Date:	20180730
Received Date:	20180730
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	016324924JJK
Last Updated Date:	20190626
Shipped Date:	20180730
Received Date:	20180730
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000237008
Generator Name:	B&B Urban Llc - 315 Linwood Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	315 LINWOOD STREET
Generator Location Street 2:	Not reported

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	419 PARK AVENUE SOUTH
Generator Mail Street 2:	7TH FLOOR
Generator Mail City:	NEW YORK
Generator Mail Zip:	10016
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	016324925JJK
Transporter Line Number:	1
Transporter EPA ID:	NOSITEID
Transporter Name:	J& D #7 As337x

Waste Line:

Manifest Tracking Number:	016324925JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Rq, Na3077, Waste Hazardous Waste, Solid, N.O.S. (Epa D008), 9, Pg-Iii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DT
Container Type Description:	Dump truck
Waste Quantity:	23
Quantity Unit of Measure Code:	Y
Quantity Unit of Measure Description:	Cubic Yards
Waste Quantity, in Tons:	19.32
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	19.32
Waste Quantity, in Kilograms:	17523.82
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	17523.82
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N

DRAFT

B&B URBAN LLC - 315 LINWOOD STREET (Continued) **1024892107**

Quantity Discrepancy Indicator:	Y
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	17523.82
Quantity Haz Tons:	19.32
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional US EManifest: record(s) in the EDR Site Report.

X178 **315 LINWOOD STREET** **NY VCP** **S129932313**
NW **315 LINWOOD** **NY NYC OER** **N/A**
1/8-1/4 **NEW YORK CITY, NY**
0.173 mi.
911 ft. **Site 2 of 7 in cluster X**

Relative:
Lower

Actual:
31 ft.

VCP NYC:

Project ID:	18TMP0064K,18EHAN037K,18CVCP084K
Name:	315 LINWOOD STREET
Address:	315 LINWOOD
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	303,971,001,930,397,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	Not reported
Longitude:	Not reported
Postcode:	Not reported
Community Board:	Not reported
Council District:	Not reported
Census Tract:	Not reported
BIN:	Not reported
NTA:	Not reported

NYC OER:

Name:	315 LINWOOD STREET
Address:	315 LINWOOD
City,State,Zip:	BROOKLYN, NY
Latitude:	Not reported
Longitude:	Not reported
OER Project Numbers:	18TMP0064K,18EHAN037K,18CVCP084K
BBL:	3.0397100193039699E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)

DRAFT

315 LINWOOD STREET (Continued) **S129932313**

Phase: Completed

URL:
Postcode: Not reported
Community Board: Not reported
Council District: Not reported
Census Tract: Not reported
BIN: Not reported
NTA: Not reported

X179 **B&B URBAN LLC - 315 LINWOOD STREET** **NY MANIFEST** **S122483166**
NW **315 LINWOOD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.173 mi.
911 ft. **Site 3 of 7 in cluster X**

Relative: NY MANIFEST:
Lower
Actual: EPA ID: NYR000237008
31 ft. Country: USA
Name: B&B Urban Llc - 315 Linwood Street
Address: 315 LINWOOD STREET
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: 315 LINWOOD STREET
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: B&B Urban Llc - 315 Linwood Street
Mailing Contact: B&B Urban Llc - 315 Linwood Street
Mailing Address 1: 315 LINWOOD STREET
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11208
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

V180 **CON EDISON - MANHOLE 3695** **NY MANIFEST** **S123692322**
North **ATLANTIC AVE & BERRIMAN ST INT** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.173 mi.
916 ft. **Site 5 of 10 in cluster V**

Relative: NY MANIFEST:
Higher
Actual: EPA ID: NYP005188400
36 ft. Country: USA
Name: Con Edison - Manhole 3695
Address: ATLANTIC AVE & BERRIMAN ST INT
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported

DRAFT

CON EDISON - MANHOLE 3695 (Continued) **S123692322**

Location Address 1:	ATLANTIC AVE & BERRIMAN ST INT
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison - Manhole 3695
Mailing Contact:	Annamarie Moylan
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602278

T181 **NY VCP** **S118704403**
NNW **3051 ATLANTIC AVENUE** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11208** **NY NYC LAND USE**
0.183 mi. **NY NYC OER**
964 ft. **Site 5 of 8 in cluster T**

Relative:
Higher

Actual:
33 ft.

VCP NYC:

Project ID:	22TMP1733K,22EH-N402K,24CVCP011K
Name:	3051 ATLANTIC AVENUE
Address:	3051 ATLANTIC AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3039570053
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Closure
Latitude:	40.678703
Longitude:	-73.882074
Postcode:	5
Community Board:	37
Council District:	1168
Census Tract:	3336148
BIN:	3039570053
NTA:	East New York

E DESIGNATION:

Name:	LOT 53,TAXBLOCK 3957
Address:	3051 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	53
Tax Block:	3957
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall

DRAFT

(Continued) **S118704403**

Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	3051 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6789414
Longitude:	-73.8822973
Type Of Ownership Code:	Not reported
Owner Name:	3051 ATLANTIC BX LLC
Borough:	BK
Tax Block:	3957
Tax Lot:	53
Community District:	305
Census Tract 2020:	3116800
Census Block 2020:	31168001002
Census Tract 2010:	1168
Census Block 2010:	1002
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R8A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	K4: Store Buildings (Taxpayers Included) - Predominant Retail With Other Uses
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	4812
Total Building Floor Area:	5720
Commercial Floor Area:	5720
Residential Floor Area:	0
Office Floor Area:	900
Retail Floor Area:	900
Garage Floor Area:	0
Storage Floor Area:	920
Factory Floor Area:	0
Other Floor Area:	3000
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	3.0000000
Residential Units:	0

DRAFT

(Continued) **S118704403**

Total Units:	1
Lot Frontage:	50.6700000
Lot Depth:	100.5800000
Building Frontage:	25.0000000
Building Depth:	34.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	2
Assessed Land Value:	29700.00000
Assessed Total Value:	353250.00000
Exempt Total Value:	0.00000
Year Built:	1920
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.19000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039570053.00000000
Condominium Number:	Not reported
Census Tract 2:	1168
X Coordinate:	1016897
Y Coordinate:	186655
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 012
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	3051 ATLANTIC AVENUE
Address:	3051 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678703
Longitude:	-73.882074
OER Project Numbers:	22TMP1733K,22EH-N402K,24CVCP011K
BBL:	3039570053
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Closure

URL:

Postcode:	5
Community Board:	37
Council District:	1168

DRAFT

(Continued) **S118704403**

Census Tract: 3336148
BIN: 3039570053
NTA: East New York

W182 **TES AUTO SERVICE, INC.** **NY TANKS** **S116349313**
ENE **873 LIBERTY AVENUE** **NY NYC LAND USE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.183 mi.
967 ft. **Site 2 of 5 in cluster W**

Relative: **Higher**

Actual: **33 ft.**

TANKS:

Name:	TES AUTO SERVICE, INC.
Address:	873 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Facility Id:	2-609249
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	09/18/2013
UTM X:	594884.98235
UTM Y:	4503546.46384

NYC LAND USE:

Name:	Not reported
Address:	873 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6774540
Longitude:	-73.8772778
Type Of Ownership Code:	Not reported
Owner Name:	CHARLES, STAN
Borough:	BK
Tax Block:	4153
Tax Lot:	79
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192001001
Census Tract 2010:	1192
Census Block 2010:	1001
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported

DRAFT

TES AUTO SERVICE, INC. (Continued) **S116349313**

Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G2: Garages And Gasoline Stations - Auto Body/Collision Or Auto Repair
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	3000
Total Building Floor Area:	1800
Commercial Floor Area:	1800
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	1800
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	30.0000000
Lot Depth:	100.0000000
Building Frontage:	30.0000000
Building Depth:	60.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	27000.00000
Assessed Total Value:	107550.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.60000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3041530079.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1018290
Y Coordinate:	186115
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 031
Tax Map #:	31306
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

DRAFT

TES AUTO SERVICE, INC. (Continued) **S116349313**

Version Number: 24v4.1
Changed By DCP: Not reported

T183 **FOLLOWERS OF JESUS MENNONITE CHURCH** **NY AST** **A100300244**
NNW **3065 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.184 mi.
971 ft. **Site 6 of 8 in cluster T**

Relative:
Higher

Actual:
34 ft.

AST:

Name:	FOLLOWERS OF JESUS MENNONITE CHURCH
Address:	3065 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610342
Program Type:	PBS
UTM X:	594501.97331
UTM Y:	4503723.43618
Expiration Date:	11/25/2028
Site Type:	Other

Affiliation Records:

Site Id:	370501
Affiliation Type:	Facility Owner
Company Name:	FOLLOWERS OF JESUS MENNONITE CHURCH
Contact Type:	TRUSTEE CHAIR
Contact Name:	JAMES E. GOCHNAUER
Address1:	3065 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 235-5493
EMail:	FJMCEMAIL@GMAIL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-11-14

Site Id:	370501
Affiliation Type:	Emergency Contact
Company Name:	FOLLOWERS OF JESUS MENNONITE CHURCH
Contact Type:	Not reported
Contact Name:	JAMES E. GOCHNAUER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 465-4800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-11-06

DRAFT

FOLLOWERS OF JESUS MENNONITE CHURCH (Continued) **A100300244**

Site Id:	370501
Affiliation Type:	Facility Operator
Company Name:	FOLLOWERS OF JESUS MENNONITE CHURE
Contact Type:	Not reported
Contact Name:	FOLLOWERS OF JESUS MENNONITE CHURE
Address1:	3065 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 235-5493
EMail:	fjmc.email@gmail.com
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-11-06

Site Id:	370501
Affiliation Type:	Mail Contact
Company Name:	FOLLOWERS OF JESUS MENNONITE CHURCH
Contact Type:	TRUSTEE CHAIR
Contact Name:	JAMES GOCHNAUER
Address1:	3065 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(646) 465-4800
EMail:	Jim@ParadisePro.com
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-11-06

Tank Info:

Tank Number:	001
Tank Id:	213616
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
G02 - Tank Secondary Containment - Vault (w/access)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.

DRAFT

FOLLOWERS OF JESUS MENNONITE CHURCH (Continued) **A100300244**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1980
Capacity Gallons:	1500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

T184 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031950428**
NNW **3065 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.184 mi.
971 ft. **Site 7 of 8 in cluster T**

Relative: **Higher**

Actual: **34 ft.**

E MANIFEST:

Manifest Tracking Number:	006747547GBF
Last Updated Date:	20211101
Shipped Date:	20211019
Received Date:	20211020
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	3065 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950428**

Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 006747547GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006747547GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 453.515
Quantity Haz Tons: 0.5
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

DRAFT

Y185
NNE
1/8-1/4
0.185 mi.
975 ft.

KEY CAPITAL FUNDING LLC
23 MONTAUK AVENUE
BROOKLYN, NY 11208

Site 1 of 4 in cluster Y

NY AST **A100321684**
N/A

Relative:
Higher

Actual:
40 ft.

AST:

Name:	KEY CAPITAL FUNDING LLC
Address:	23 MONTAUK AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610935
Program Type:	PBS
UTM X:	594732.20379
UTM Y:	4503711.25544
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	404202
Affiliation Type:	Facility Owner
Company Name:	KEY CAPITAL FUNDING LLC
Contact Type:	MANAGING MEMBER
Contact Name:	MARSHALL KESTEN
Address1:	1036 MANHATTAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 383-2409
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-09-18

Site Id:	404202
Affiliation Type:	Mail Contact
Company Name:	KEY CAPITAL FUNDING LLC
Contact Type:	MANAGING MEMBER
Contact Name:	MARSHALL KESTEN
Address1:	1036 MANHATTAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 383-2409
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-09-18

Site Id:	404202
Affiliation Type:	Facility Operator
Company Name:	KEY CAPITAL FUNDING LLC
Contact Type:	Not reported
Contact Name:	MARSHALL KESTEN

DRAFT

KEY CAPITAL FUNDING LLC (Continued) **A100321684**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 383-2409
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-09-18

Site Id:	404202
Affiliation Type:	Emergency Contact
Company Name:	KEY CAPITAL FUNDING LLC
Contact Type:	Not reported
Contact Name:	MARSHALL KESTEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 392-7555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-09-18

Tank Info:

Tank Number:	0001
Tank Id:	225198
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
I05 - Overfill - Vent Whistle
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported

DRAFT

KEY CAPITAL FUNDING LLC (Continued) **A100321684**

Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/09/2008
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

186
ESE
1/8-1/4
0.186 mi.
980 ft.

CON EDISON - EXTERIOR ST STORAGE YARD **E MANIFEST** **1031953447**
2564 PITKIN AVE **N/A**
BROOKLYN, NY 11208

Relative:
Lower

Actual:
23 ft.

E MANIFEST:

Manifest Tracking Number:	006854861GBF
Last Updated Date:	20210607
Shipped Date:	20210525
Received Date:	20210526
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Exterior St Storage Yard
Generator Location Street Number:	Not reported
Generator Location Street 1:	2564 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	ELIZABETH
Generator Mail Zip:	10462
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

DRAFT

CON EDISON - EXTERIOR ST STORAGE YARD (Continued) **1031953447**

Transporter:
- Manifest Tracking Number: 006854861GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 006854861GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Rq, Na3082, Hazardous Waste, Liquid N.O.S. (Lead) 9, Pg Iii
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 500
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.25
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.25
- Waste Quantity, in Kilograms: 226.7575
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 226.7575
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y
- Federal Waste Codes: D008
- Quantity Haz Kg: 226.7575
- Quantity Haz Tons: 0.25
- Quantity Non Haz Kg: 0
- Quantity Non Haz Tons: 0
- State Waste Codes: NY-T

DRAFT

V187 **3126 ATLANTIC AVENUE** **NY UST** **U001841125**
NNE **3126 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.187 mi.
987 ft. **Site 6 of 10 in cluster V**

Relative:
Higher

Actual:
39 ft.

UST:

Name:	3126 ATLANTIC AVENUE
Address:	3126 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-510270 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594676.96968
UTM Y:	4503704.78143
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	21842
Affiliation Type:	Facility Owner
Company Name:	3124 ATLANTIC LLC
Contact Type:	AGENT
Contact Name:	DANNY SINGH
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21842
Affiliation Type:	Emergency Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 533-2236
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Site Id:	21842
Affiliation Type:	Facility Operator
Company Name:	3126 ATLANTIC AVENUE
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	Not reported

DRAFT

3126 ATLANTIC AVENUE (Continued) **U001841125**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 220-2569
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-08

Site Id:	21842
Affiliation Type:	Mail Contact
Company Name:	3124 ATLANTIC LLC
Contact Type:	Not reported
Contact Name:	MORDY PERKOWSKI
Address1:	175 BLAKE AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(917) 533-2236
EMail:	MORDY@LIBERTY1GROUP.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-04

Tank Info:

Tank Number:	001
Tank ID:	39493
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	12/01/1948
Date Tank Closed:	02/28/2019
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	34
Date Test:	10/31/2018
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination

DRAFT

3126 ATLANTIC AVENUE (Continued) **U001841125**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle

V188 **3126 ATLANTIC AVENUE** **UST FINDER** **1028571491**
NNE **3126 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.187 mi.
987 ft. **Site 7 of 10 in cluster V**

Relative:
Higher

Actual:
39 ft.

UST FINDER:

Object ID:	295983
Facility ID:	NY21842
Name:	3126 ATLANTIC AVENUE
Address:	3126 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	8799
Private Wells 1500ft:	45
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8796859999999
Y Coord:	40.678796
Latitude:	40.678796
Longitude:	-73.879686

UST FINDER:

Object ID:	1216783
Facility ID:	NY21842
Tank ID:	NY26129
Tank Status:	Open
Installation Date:	1948/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

DRAFT

U189 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031951544**
SSW **OPP OF 24-28 PITKIN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.187 mi.
988 ft. **Site 6 of 6 in cluster U**

Relative:
Lower

Actual:
30 ft.

E MANIFEST:

Manifest Tracking Number:	006856387GBF
Last Updated Date:	20211208
Shipped Date:	20211201
Received Date:	20211201
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	OPP OF 24-28 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006856387GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006856387GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031951544**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.5
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.5
Waste Quantity, in Kilograms:	453.515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	453.515
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	453.515
Quantity Haz Tons:	0.5
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

T190 **DYNAMIC AUTO CLINIC** **NY AST** **A100298635**
NNW **3053 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.189 mi.
997 ft. **Site 8 of 8 in cluster T**

Relative:
Higher

Actual:
34 ft.

AST:

Name:	DYNAMIC AUTO CLINIC
Address:	3053 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610270
Program Type:	PBS
UTM X:	594470.03533
UTM Y:	4503710.77131
Expiration Date:	06/27/2011
Site Type:	Other

Affiliation Records:

DRAFT

DYNAMIC AUTO CLINIC (Continued) **A100298635**

Site Id:	366065
Affiliation Type:	Facility Owner
Company Name:	DERICK MALARBE
Contact Type:	OWNER
Contact Name:	DERICK MALARBE
Address1:	7 HEGEMAN AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 213-0938
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-06-27

Site Id:	366065
Affiliation Type:	Mail Contact
Company Name:	DYNAMIC AUTO CLINIC
Contact Type:	Not reported
Contact Name:	DERICK MALARBE
Address1:	3053 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 213-0938
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-06-27

Site Id:	366065
Affiliation Type:	Facility Operator
Company Name:	DYNAMIC AUTO CLINIC
Contact Type:	Not reported
Contact Name:	DERICK MALARBE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 984-1208
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-06-27

Site Id:	366065
Affiliation Type:	Emergency Contact
Company Name:	DERICK MALARBE
Contact Type:	Not reported
Contact Name:	DERICK MALARBE
Address1:	Not reported

DRAFT

DYNAMIC AUTO CLINIC (Continued) **A100298635**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 213-0938
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-06-27

Tank Info:

Tank Number:	001
Tank Id:	212469
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A02 - Tank Internal Protection - Rubber Liner
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I99 - Overfill - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/02/2002
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

DRAFT

V191 **CON EDISON** **NJ MANIFEST** **S120666567**
North **ATLANTIC AVE & ATKINS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.190 mi.
1001 ft. **Site 8 of 10 in cluster V**

Relative:
Higher

Actual:
38 ft.

NJ MANIFEST:

EPA ID:	NYP004723680
Name:	CON EDISON
Address:	ATLANTIC AVE & ATKINS AVE
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004723680
Manifest Number:	007748142FLE
Date Shipped:	2/3/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

DRAFT

CON EDISON (Continued) **S120666567**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

V192 **CON EDISON** **RCRA NonGen / NLR** **1018277631**
North **ATLANTIC AVE & ATKINS AVE** **FINDS** **NYP004723680**
1/8-1/4 **BROOKLYN, NY 11208** **ECHO**
0.190 mi.
1001 ft. **Site 9 of 10 in cluster V**

Relative: **Higher**
Actual: **38 ft.**

RCRA Listings:

Date Form Received by Agency:	20150203
Handler Name:	Con Edison
Handler Address:	Atlantic Ave & Atkins Ave
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004723680
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

DRAFT

CON EDISON (Continued) **1018277631**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150203
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150203
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

DRAFT

CON EDISON (Continued) **1018277631**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067691581

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277631
Registry ID: 110067691581

DFR URL:
Name: CON EDISON
Address: Atlantic Ave & Atkins Ave
City,State,Zip: BROOKLYN, NY 11208

V193 **CON EDISON** **NY MANIFEST** **S117739264**
North **ATLANTIC AVE & ATKINS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.190 mi.
1001 ft. **Site 10 of 10 in cluster V**

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:
EPA ID: NYP004723680
Country: USA
Name: Con Edison
Address: ATLANTIC AVE & ATKINS AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: ATLANTIC AVE & ATKINS AV
Location Address 2: SB18074
Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

DRAFT

CON EDISON (Continued) **S117739264**

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 02/03/2015
Trans1 Recv Date: 02/03/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/09/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004723680
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 007748142FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 300
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat

DRAFT

CON EDISON (Continued) **S117739264**

Specific Gravity: 1

Y194 **CON EDISON** **NY MANIFEST** **S118464211**
NNE **3130 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.190 mi.
1002 ft. **Site 2 of 4 in cluster Y**

Relative:
Higher

Actual:
39 ft.

NY MANIFEST:

EPA ID:	NYP004867610
Country:	USA
Name:	Con Edison
Address:	3130 ATLANTIC AVE
Address 2:	SB 18074
City,State,Zip:	BROOKLYN, NY
Zip 4:	Not reported
Location Address 1:	3130 ATLANTIC AVE
Location Address 2:	SB 18074
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Dennis Huacon
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/10/2015
Trans1 Recv Date:	11/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004867610
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245043JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

DRAFT

CON EDISON (Continued) **S118464211**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Z195 **CON ED COMPANY OF NY** **E MANIFEST** **1031948596**
West **680 LIBERTY AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.192 mi.
1012 ft. **Site 1 of 3 in cluster Z**

Relative: **Lower**
Actual: **30 ft.**

E MANIFEST:

Manifest Tracking Number:	006856221GBF
Last Updated Date:	20210609
Shipped Date:	20210527
Received Date:	20210602
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Ed Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	680 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler St
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105

DRAFT

CON ED COMPANY OF NY (Continued) **1031948596**

Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006856221GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006856221GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

DRAFT

CON ED COMPANY OF NY (Continued) **1031948596**

Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

S196 **CON ED COMPANY OF NY** **E MANIFEST** **1031948554**
East **432 LOGAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.198 mi.
1043 ft. **Site 3 of 3 in cluster S**

Relative:
Lower

Actual:
25 ft.

E MANIFEST:

Manifest Tracking Number:	006856224GBF
Last Updated Date:	20210609
Shipped Date:	20210527
Received Date:	20210602
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Ed Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	432 LOGAN ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler St
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006856224GBF
Transporter Line Number:	1

DRAFT

CON ED COMPANY OF NY (Continued) **1031948554**

Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006856224GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 226.7575
Quantity Haz Tons: 0.25
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

197
NNW
1/8-1/4
0.198 mi.
1043 ft.

CON EDISON SERVICE BOX: 55987
3027 ATLANTIC AVE
BROOKLYN, NY 11208

RCRA NonGen / NLR **1016970199**
NY MANIFEST **NYP004439006**

Relative:
Higher

Actual:
34 ft.

RCRA Listings:
Date Form Received by Agency: 20140310
Handler Name: Con Edison Service Box: 55987
Handler Address: Atlantic Ave
Handler City,State,Zip: BROOKLYN, NY 11208
EPA ID: NYP004439006

CON EDISON SERVICE BOX: 55987 (Continued) **1016970199**

Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20141014
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

DRAFT

CON EDISON SERVICE BOX: 55987 (Continued) **1016970199**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140210
Handler Name: CON EDISON SERVICE BOX:	55987
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140310
Handler Name: CON EDISON SERVICE BOX:	55987
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004439006
Country:	USA
Name:	Con Ed
Address:	3027 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	FO 30-27 ATLANTIC AVE
Location Address 2:	SB 55987

DRAFT

CON EDISON SERVICE BOX: 55987 (Continued) **1016970199**

Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Ed
Mailing Contact: Tpm Teeling
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 02/10/2014
Trans1 Recv Date: 02/10/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/18/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004439006
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002329682GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported

DRAFT

CON EDISON SERVICE BOX: 55987 (Continued) **1016970199**

Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

198
South
1/8-1/4
0.201 mi.
1059 ft.

R & O MGMT CORP **NY AST** **A100350458**
785 BELMONT AVE **N/A**
BROOKLYN, NY 11208

Relative:
Lower

Actual:
24 ft.

AST:

Name:	R & O MGMT CORP
Address:	785 BELMONT AVE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-611368
Program Type:	PBS
UTM X:	594591.75524
UTM Y:	4503050.97715
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	435822
Affiliation Type:	Facility Owner
Company Name:	R & O MGMT CORP
Contact Type:	MANAGING AGENT
Contact Name:	SAVITRI KHEMRAJ
Address1:	109 - 14 VAN WYCK EXPRESSWAY
Address2:	Not reported
City:	S. OZONE PARK
State:	NY
Zip Code:	11420
Country Code:	001
Phone:	(718) 551-8622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-01-15

Site Id:	435822
Affiliation Type:	Emergency Contact
Company Name:	R & O MGMT CORP
Contact Type:	Not reported
Contact Name:	KHEMRAJ MOSAPHIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 370-2763

DRAFT

R & O MGMT CORP (Continued) **A100350458**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2010-06-08

Site Id:	435822
Affiliation Type:	Mail Contact
Company Name:	R & O MGMT CORP
Contact Type:	Not reported
Contact Name:	SAVITRI KHEMRAJ
Address1:	109-10 VAN WYCK EXPRESSWAY
Address2:	Not reported
City:	S. OZONE PARK
State:	NY
Zip Code:	11420
Country Code:	001
Phone:	(718) 551-8622
EMail:	ADVANCE2754@VERIZON.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-01-15

Site Id:	435822
Affiliation Type:	Facility Operator
Company Name:	R & O MGMT CORP
Contact Type:	Not reported
Contact Name:	JOE MOSAPHIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 551-8622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-01-15

Tank Info:

Tank Number:	001
Tank Id:	234802
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H99 - Tank Leak Detection - Other

DRAFT

R & O MGMT CORP (Continued) **A100350458**

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1999
Capacity Gallons:	1200
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/12/2015
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AA199 **NYCTA - ELTON SUBSTATION** **RCRA NonGen / NLR** **1000337692**
SW **ELTON ST & PITKIN AVE** **NY MANIFEST** **NYD982739468**
1/8-1/4 **BROOKLYN, NY 11201**
0.202 mi.
1069 ft. **Site 1 of 7 in cluster AA**

Relative: **Lower**
Actual: **31 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nycta - Elton Substation
Handler Address:	Elton St & Pitkin Ave
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYD982739468
Contact Name:	Not reported
Contact Address:	JAY ST ROOM 809
Contact City,State,Zip:	BROOKLYN, NY 11201
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	JAY ST ROOM 809
Mailing City,State,Zip:	BROOKLYN, NY 11201
Owner Name:	New York City Transit Authority
Owner Type:	County
Operator Name:	New York City Transit Authority
Operator Type:	County
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

DRAFT

NYCTA - ELTON SUBSTATION (Continued) **1000337692**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	U151
Waste Description:	Mercury
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 809
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-330-4891
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DRAFT

NYCTA - ELTON SUBSTATION (Continued) **1000337692**

Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 809
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-330-4891
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 809
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-330-4891
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NYCTA - ELTON SUBSTATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYCTA - ELTON SUBSTATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA - ELTON SUBSTATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

DRAFT

NYCTA - ELTON SUBSTATION (Continued) **1000337692**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19890421
Handler Name: NYCTA - ELTON SUBSTATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYD982739468
Country: USA
Name: Nycta
Address: ELTON ST & PITKIN AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11201
Zip 4: Not reported
Location Address 1: PITKIN & ELTON ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Nycta
Mailing Contact: Michael Matkovic
Mailing Address 1: CORNER OF PITKIN & ELTON ST
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11208
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183304581

DRAFT

NYCTA - ELTON SUBSTATION (Continued) **1000337692**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2007
Trans1 Recv Date:	08/29/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982739468
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001027431JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	130
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	NYA7529175
Manifest Status:	Not reported
Trans1 State ID:	AA45997PA
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	10/02/1990
Trans1 Recv Date:	10/02/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/1990

DRAFT

NYCTA - ELTON SUBSTATION (Continued) **1000337692**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982739468
Trans1 EPA ID:	PAD008781072
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD048148175
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Mercury
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	06400
Units:	Pounds
Number of Containers:	016
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Mercury
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

AA200 **CON EDISON MANHOLE 55292** **RCRA NonGen / NLR** **1014926376**
SW **PITKIN AVE & ELTON ST** **NY MANIFEST** **NYP004241329**
1/8-1/4 **BROOKLYN, NY 11201**
0.202 mi.
1069 ft. **Site 2 of 7 in cluster AA**

Relative: **Lower**
Actual: **31 ft.**

RCRA Listings:

Date Form Received by Agency:	20111002
Handler Name:	Con Edison Manhole 55292
Handler Address:	Pitkin Ave & Elton St
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004241329
Contact Name:	JOHN ANDERSON
Contact Address:	Not reported

DRAFT

CON EDISON MANHOLE 55292 (Continued) **1014926376**

Contact City,State,Zip:		Not reported
Contact Telephone:		718-802-5196
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SR OFFICE ASSISTANT A X L1-2
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20111206
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No

DRAFT

CON EDISON MANHOLE 55292 (Continued) **1014926376**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20110902
Handler Name: CON EDISON MANHOLE 55292
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20111002
Handler Name: CON EDISON MANHOLE 55292
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004241329
Country: USA
Name: Coned
Address: PITKIN AVE & ELTON ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11201
Zip 4: Not reported
Location Address 1: PITKIN AVE
Location Address 2: CLEVELAND ST
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported

DRAFT

CON EDISON MANHOLE 55292 (Continued) **1014926376**

Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Coned
Mailing Contact: Coned
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FLOOR
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: MAD039322250
Year: 2018
Trans2 State ID: MAD039322250
Generator Ship Date: 09/02/2011
Trans1 Recv Date: 09/02/2011
Trans2 Recv Date: 09/02/2011
TSD Site Recv Date: 09/07/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004241329
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD000816629
TSDF ID 2: Not reported
Manifest Tracking Number: 003949267FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H082
Waste Code a: B002
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 64
Units: Kilograms

DRAFT

CON EDISON MANHOLE 55292 (Continued) **1014926376**

Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

W201 **NYNEX** **NY MANIFEST** **1009233402**
ENE **LOGAN ST & LIBERTY AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.203 mi.
1070 ft. **Site 3 of 5 in cluster W**

Relative:
Lower

Actual:
29 ft.

NY MANIFEST:

EPA ID:	NYP000914846
Country:	USA
Name:	Nynex
Address:	LOGAN ST & LIBERTY AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	LOGAN ST & LIBERTY AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nynex
Mailing Contact:	R Gazzo
Mailing Address 1:	1095 AVE OF AMER-RM 3025
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10036
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123956040

Manifest Data:

Document ID:	NJA1892049
Manifest Status:	Not reported
Trans1 State ID:	50060
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/1994
Trans1 Recv Date:	05/10/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000914846
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

DRAFT

NYNEX (Continued) **1009233402**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00275
Units:	Gallons (liquids only)
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

W202 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031951243**
ENE **LOGAN ST & LIBERTY AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.203 mi.
1070 ft. **Site 4 of 5 in cluster W**

Relative: **Lower**
Actual: **29 ft.**

E MANIFEST:

Manifest Tracking Number:	006857331GBF
Last Updated Date:	20210719
Shipped Date:	20210706
Received Date:	20210709
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	LOGAN ST & LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031951243**

Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 006857331GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006857331GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: Y
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 453.515
Quantity Haz Tons: 0.5

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031951243**

Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

W203 **CON ED - V 3742** **RCRA NonGen / NLR** **1007206138**
ENE **LIBERTY AVE & LOGAN** **NY MANIFEST** **NYP004004289**
1/8-1/4 **BROOKLYN, NY 11212**
0.203 mi.
1070 ft. **Site 5 of 5 in cluster W**

Relative: **Lower**
Actual: **29 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - V 3742
Handler Address:	Liberty Ave & Logan
Handler City,State,Zip:	BROOKLYN, NY 11212-0000
EPA ID:	NYP004004289
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

DRAFT

CON ED - V 3742 (Continued) **1007206138**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - V 3742	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - V 3742	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - V 3742	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

DRAFT

CON ED - V 3742 (Continued) **1007206138**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004004289
Country: USA
Name: Consolidated Edison Co
Address: LIBERTY AVE & LOGAN
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11212-0000
Zip 4: Not reported
Location Address 1: LIBERTY AND LOGAN TM3742
Location Address 2: Not reported
Location City,State,Zip: NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison Co
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYB8467632
Manifest Status: Not reported
Trans1 State ID: 20854AD
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/23/1997
Trans1 Recv Date: 01/23/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/27/1997

DRAFT

CON ED - V 3742 (Continued) **1007206138**

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004004289
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B003
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 02704
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYB8467821
Manifest Status: Not reported
Trans1 State ID: 80680AE
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 01/23/1997
Trans1 Recv Date: 01/23/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/27/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004004289
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported

DRAFT

CON ED - V 3742 (Continued) **1007206138**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00002
Units:	Cubic Yards
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

204
East
1/8-1/4
0.205 mi.
1080 ft.

CONSOLIDATED EDISON **NY MANIFEST** **1009243273**
LOGAN & GLENMORE MH67396 **N/A**
BROOKLYN, NY 11201

Relative:
Lower

Actual:
27 ft.

NY MANIFEST:

EPA ID:	NYP004126991
Country:	USA
Name:	Consolidated Edison
Address:	LOGAN & GLENMORE MH67396
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	LOGAN & GLENMORE MH67396
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	NYE0639045
Manifest Status:	Not reported
Trans1 State ID:	46299JM
Year:	2004
Trans2 State ID:	Not reported
Generator Ship Date:	11/18/2004
Trans1 Recv Date:	11/18/2004
Trans2 Recv Date:	Not reported

DRAFT

CONSOLIDATED EDISON (Continued) **1009243273**

TSD Site Recv Date:	11/18/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004126991
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00175
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYE0655677
Manifest Status:	Not reported
Trans1 State ID:	46233JM
Year:	2004
Trans2 State ID:	Not reported
Generator Ship Date:	12/14/2004
Trans1 Recv Date:	12/14/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/14/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004126991
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported

DRAFT

CONSOLIDATED EDISON (Continued) **1009243273**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00214
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYE0676881
Manifest Status:	Not reported
Trans1 State ID:	12446JT
Year:	2004
Trans2 State ID:	Not reported
Generator Ship Date:	11/18/2004
Trans1 Recv Date:	11/18/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/19/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004126991
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00039
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

DRAFT

205
NNW
1/8-1/4
0.205 mi.
1082 ft.

NEW GENESIS CHRISTIAN CHURCH
224 SHEPHERD AVENUE
BROOKLYN, NY 11208

NY AST **U000395899**
N/A

Relative:
Higher

Actual:
36 ft.

AST:

Name:	NEW GENESIS CHRISTIAN CHURCH
Address:	224 SHEPHERD AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-114774
Program Type:	PBS
UTM X:	594501.15866
UTM Y:	4503758.18037
Expiration Date:	N/A
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	3768
Affiliation Type:	Facility Owner
Company Name:	NEW GENESIS CHRISTIAN CENTER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	224 SHEPHERD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 827-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-08-20

Site Id:	3768
Affiliation Type:	Mail Contact
Company Name:	NEW GENESIS CHRISTIAN CHURCH
Contact Type:	Not reported
Contact Name:	REV. JEROME BATES
Address1:	224 SHEPHERD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 827-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-09-25

Site Id:	3768
Affiliation Type:	Facility Operator
Company Name:	NEW GENESIS CHRISTIAN CENTR
Contact Type:	Not reported
Contact Name:	REV. JEROME BATES

DRAFT

NEW GENESIS CHRISTIAN CHURCH (Continued) **U000395899**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 827-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-09-25

Site Id:	3768
Affiliation Type:	Emergency Contact
Company Name:	NEW GENESIS CHRISTIAN CHURCH
Contact Type:	Not reported
Contact Name:	REV. JEROME BATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 827-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-09-25

Tank Info:

Tank Number:	001
Tank Id:	5265
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
G00 - Tank Secondary Containment - None
L03 - Piping Leak Detection - Vapor Well
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H03 - Tank Leak Detection - Vapor Well
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/29/1928
Capacity Gallons:	3000

DRAFT

NEW GENESIS CHRISTIAN CHURCH (Continued) **U000395899**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/04/2011
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	58838
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	2
Tank Id:	5266
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

DRAFT

NEW GENESIS CHRISTIAN CHURCH (Continued) **U000395899**

	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1080
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

X206 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031950398**
WNW **2976 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.208 mi.
1097 ft. **Site 4 of 7 in cluster X**

Relative: **Lower**

Actual: **31 ft.**

E MANIFEST:

Manifest Tracking Number:	006747548GBF
Last Updated Date:	20211101
Shipped Date:	20211019
Received Date:	20211020
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	2976 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950398**

Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 006747548GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006747548GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 453.515
Quantity Haz Tons: 0.5
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

DRAFT

AB207
SSW
1/8-1/4
0.208 mi.
1100 ft.

CON EDISON
496 LINWOOD ST
BROOKLYN, NY 11201

Site 1 of 3 in cluster AB

NY MANIFEST **S117066690**
N/A

Relative:
Lower

Actual:
30 ft.

NY MANIFEST:

EPA ID:	NYP004593711
Country:	USA
Name:	Con Edison
Address:	496 LINWOOD ST
Address 2:	SB59550
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	496 LINWOOD ST
Location Address 2:	SB59550
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/11/2014
Trans1 Recv Date:	07/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004593711
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504099GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

DRAFT

CON EDISON (Continued) **S117066690**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	40
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AC208 **CON EDISON SERVICE BOX: 18120-02** **RCRA NonGen / NLR** **1016968109**
SSE **BELMONT AVE & BERRIMAN ST** **NY MANIFEST** **NYP004417135**
1/8-1/4 **BROOKLYN, NY 11208**
0.209 mi.
1104 ft. **Site 1 of 3 in cluster AC**

Relative: **Lower**

Actual: **24 ft.**

RCRA Listings:

Date Form Received by Agency:	20140212
Handler Name:	Con Edison Service Box: 18120-02
Handler Address:	Belmont Ave & Berriman St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004417135
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

DRAFT

CON EDISON SERVICE BOX: 18120-02 (Continued) **1016968109**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140112
Handler Name: CON EDISON SERVICE BOX:	18120-02
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140212
Handler Name: CON EDISON SERVICE BOX:	18120-02

DRAFT

CON EDISON SERVICE BOX: 18120-02 (Continued) **1016968109**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004417135
Country:	USA
Name:	Con Edison
Address:	BELMONT AVE & BERRIMAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	SOUTH WEST CORNER OF BERRIMAN ST & BELMONT AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/12/2014
Trans1 Recv Date:	01/12/2014

DRAFT

CON EDISON SERVICE BOX: 18120-02 (Continued) **1016968109**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004417135
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002328211GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Y209 **CON EDISON** **NY MANIFEST** **S121968526**
NNE **3144 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.211 mi.
1112 ft. **Site 3 of 4 in cluster Y**

Relative: **Higher**
Actual: **40 ft.**

NY MANIFEST:

EPA ID:	NYP005125893
Country:	USA
Name:	Con Edison
Address:	3144 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	3144 ATLANTIC AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208

DRAFT

CON EDISON (Continued) **S121968526**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Y210 **CON EDISON - MANHOLE M3697** **RCRA NonGen / NLR** **1024891596**
NNE **3144 ATLANTIC AVE** **NYP005125893**
1/8-1/4 **BROOKLYN, NY 11208**
0.211 mi.
1112 ft. **Site 4 of 4 in cluster Y**

Relative: **Higher**
Actual: **40 ft.**

RCRA Listings:
Date Form Received by Agency: 20250421
Handler Name: Con Edison - Manhole M3697
Handler Address: Atlantic Ave
Handler City,State,Zip: BROOKLYN, NY 11208
EPA ID: NYP005125893
Contact Name: ALYSSA SOTTO
Contact Address: IRVING PLACE, 15TH FL NE
Contact City,State,Zip: NEW YORK, NY 10003
Contact Telephone: 212-460-2757
Contact Fax: Not reported
Contact Email: SOTTOA@CONED.COM
Contact Title: ASSOCIATE SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PLACE, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No

DRAFT

CON EDISON - MANHOLE M3697 (Continued) **1024891596**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250421
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170814
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator

DRAFT

CON EDISON - MANHOLE M3697 (Continued) **1024891596**

Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170814
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - MANHOLE M3697
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250421
Handler Name: CON EDISON - MANHOLE M3697
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

DRAFT

Z211
West
1/8-1/4
0.212 mi.
1119 ft.

CONSOLIDATED EDISON COMPANY OF NY
374 CLEVELAND ST
BROOKLYN, NY 11208

Site 2 of 3 in cluster Z

E MANIFEST **1031975438**
N/A

Relative:
Higher

Actual:
34 ft.

E MANIFEST:

Manifest Tracking Number:	023096085JJK
Last Updated Date:	20211203
Shipped Date:	20211123
Received Date:	20211129
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Consolidated Edison Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	374 CLEVELAND ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ELIZABETH
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	023096085JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	023096085JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CONSOLIDATED EDISON COMPANY OF NY (Continued) **1031975438**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

Z212 **670 LIBERTY AVE REPAIR SHOP INC** **NY AST** **A100292660**
West **670 LIBERTY AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.212 mi.
1121 ft. **Site 3 of 3 in cluster Z**

Relative:
Higher

Actual:
33 ft.

AST:

Name:	670 LIBERTY AVE REPAIR SHOP INC
Address:	670 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610204
Program Type:	PBS
UTM X:	594242.64282
UTM Y:	4503367.66676
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

DRAFT

670 LIBERTY AVE REPAIR SHOP INC (Continued) **A100292660**

Site Id:	363891
Affiliation Type:	Emergency Contact
Company Name:	RAMON CRUZ
Contact Type:	Not reported
Contact Name:	FRANK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 235-3480
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-12

Site Id:	363891
Affiliation Type:	Facility Operator
Company Name:	670 LIBERTY AVE REPAIR SHOP INC
Contact Type:	Not reported
Contact Name:	DIONICIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 827-9713
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-12

Site Id:	363891
Affiliation Type:	Mail Contact
Company Name:	810 CAR SERVOCE
Contact Type:	Not reported
Contact Name:	RAMON CRUZ
Address1:	2672 PITKIN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 235-3480
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MJGRIFFI
Date Last Modified:	2021-06-25

Site Id:	363891
Affiliation Type:	Facility Owner
Company Name:	RAMON CRUZ
Contact Type:	MANAGER
Contact Name:	FRANCISCO SERRATA
Address1:	2672 PITKIN AVE

DRAFT

670 LIBERTY AVE REPAIR SHOP INC (Continued) **A100292660**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 235-5009
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-12

Tank Info:

Tank Number:	001
Tank Id:	211711
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F03 - Pipe External Protection - Original Impressed Current
J03 - Dispenser - Gravity
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
D08 - Pipe Type - Equivalent Technology
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
B08 - Tank External Protection - Retrofitted Impressed Current
E04 - Piping Secondary Containment - Double walled UG
L04 - Piping Leak Detection - Groundwater Well
H04 - Tank Leak Detection - Groundwater Well

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/18/2005
Capacity Gallons:	600
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/13/2008
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	211712
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

F03 - Pipe External Protection - Original Impressed Current

DRAFT

670 LIBERTY AVE REPAIR SHOP INC (Continued) **A100292660**

J03 - Dispenser - Gravity
C03 - Pipe Location - Aboveground/Underground Combination
K01 - Spill Prevention - Catch Basin
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
I00 - Overfill - None
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
D08 - Pipe Type - Equivalent Technology
B08 - Tank External Protection - Retrofitted Impressed Current
L04 - Piping Leak Detection - Groundwater Well
E04 - Piping Secondary Containment - Double walled UG
H04 - Tank Leak Detection - Groundwater Well

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/02/2005
Capacity Gallons: 800
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/14/2007
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: waste oil/used oil

Tank Number: 003
Tank Id: 238577
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

J03 - Dispenser - Gravity
F03 - Pipe External Protection - Original Impressed Current
C03 - Pipe Location - Aboveground/Underground Combination
K01 - Spill Prevention - Catch Basin
D08 - Pipe Type - Equivalent Technology
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
I00 - Overfill - None
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
B08 - Tank External Protection - Retrofitted Impressed Current
L04 - Piping Leak Detection - Groundwater Well
E04 - Piping Secondary Containment - Double walled UG
H04 - Tank Leak Detection - Groundwater Well

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 400
Tightness Test Method: NN
Date Test: Not reported

DRAFT

670 LIBERTY AVE REPAIR SHOP INC (Continued) **A100292660**

Next Test Date:	Not reported
Date Tank Closed:	03/14/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

AC213 **CON EDISON** **RCRA NonGen / NLR** **1019905970**
SSE **814 BELMONT AVE** **NYP004815706**
1/8-1/4 **BROOKLYN, NY 11208**
0.215 mi.
1135 ft. **Site 2 of 3 in cluster AC**

Relative: **Lower**
Actual: **24 ft.**

RCRA Listings:

Date Form Received by Agency:		20150730
Handler Name:		Con Edison
Handler Address:		Belmont Ave
Handler City,State,Zip:		BROOKLYN, NY 11208
EPA ID:		NYP004815706
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

DRAFT

CON EDISON (Continued) **1019905970**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150730
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150730
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

DRAFT

CON EDISON (Continued) **1019905970**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC214 **CON EDISON - EXTERIOR ST STORAGE YARD** **E MANIFEST** **1031954882**
SSE **ATKINS AVE & BELMONT AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.216 mi.
1141 ft. **Site 3 of 3 in cluster AC**

Relative:
Lower

Actual:
23 ft.

E MANIFEST:

Manifest Tracking Number:	006856133GBF
Last Updated Date:	20210707
Shipped Date:	20210614
Received Date:	20210616
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Exterior St Storage Yard
Generator Location Street Number:	Not reported
Generator Location Street 1:	ATKINS AVE & BELMONT AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:
Manifest Tracking Number: 006856133GBF

DRAFT

CON EDISON - EXTERIOR ST STORAGE YARD (Continued) **1031954882**

Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006856133GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Rq, Na3082, Hazardous Waste, Liquid, N.O.S., (Lead), 9, Pg Iii
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 226.7575
Quantity Haz Tons: 0.25
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-T

AD215 **CON EDISON** **RCRA NonGen / NLR** **1019902085**
WNW **ATLANTIC AVE & ELTON ST** **FINDS** **NYP004769485**
1/8-1/4 **BROOKLYN, NY 11208** **ECHO**
0.216 mi.
1141 ft. **Site 1 of 7 in cluster AD**

Relative: **Lower**
Actual: **31 ft.**

RCRA Listings:
Date Form Received by Agency: 20150416
Handler Name: Con Edison
Handler Address: Atlantic Ave & Elton St
Handler City,State,Zip: BROOKLYN, NY 11208

DRAFT

CON EDISON (Continued) **1019902085**

EPA ID:		NYP004769485
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909
Recognized Trader-Importer:		No

DRAFT

CON EDISON (Continued) **1019902085**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150416
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150416
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069669371

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

DRAFT

CON EDISON (Continued) **1019902085**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019902085
Registry ID: 110069669371

DFR URL:
Name: CON EDISON
Address: Atlantic Ave & Elton St
City,State,Zip: BROOKLYN, NY 11208

AD216 **CON EDISON** **NY MANIFEST** **S119074528**
WNW **ATLANTIC AVE & ELTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.216 mi.
1141 ft. **Site 2 of 7 in cluster AD**

Relative:
Lower

Actual:
31 ft.

NY MANIFEST:
EPA ID: NYP004769485
Country: USA
Name: Con Edison
Address: ATLANTIC AVE & ELTON ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: 2969 ATLANTIC AVE
Location Address 2: TM 1874
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Dennis Huacon
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: NJD003812047
Generator Ship Date: 04/16/2015
Trans1 Recv Date: 04/16/2015
Trans2 Recv Date: 04/22/2015
TSD Site Recv Date: 04/22/2015
Part A Recv Date: Not reported

DRAFT

CON EDISON (Continued) **S119074528**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004769485
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618872GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD217 **CON EDISON** **NJ MANIFEST** **S120670611**
WNW **ATLANTIC AVE & ELTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.216 mi.
1141 ft. **Site 3 of 7 in cluster AD**

Relative: NJ MANIFEST:
Lower

Actual:
31 ft.

EPA ID:	NYP004769485
Name:	CON EDISON
Address:	ATLANTIC AVE & ELTON ST
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047

DRAFT

CON EDISON (Continued) **S120670611**

Municipal: Not reported
Previous EPAID: Not reported
Generator Flag: Not reported
Transporter Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest Data:
EPA ID: NYP004769485
Manifest Number: 002618872GBF
Date Shipped: 4/16/2015
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJD003812047
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: Not reported
Reason Load Was Rejected: Not reported

DRAFT

AD218 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031950397**
WNW **2972 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.217 mi.
1144 ft. **Site 4 of 7 in cluster AD**

Relative:
Lower

Actual:
31 ft.

E MANIFEST:

Manifest Tracking Number:	023096177JJK
Last Updated Date:	20211203
Shipped Date:	20211127
Received Date:	20211129
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	2972 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	023096177JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	023096177JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950397**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

AA219 **CON EDISON** **NY MANIFEST** **S117737020**
SW **390 ELTON STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.217 mi.
1146 ft. **Site 3 of 7 in cluster AA**

Relative: NY MANIFEST:
Higher

Actual:
32 ft.

EPA ID:	NYP004599338
Country:	USA
Name:	Con Edison
Address:	390 ELTON STREET
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	390 ELTON STREET
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

DRAFT

CON EDISON (Continued) **S117737020**

Mailing:
Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/17/2014
Trans1 Recv Date: 07/17/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004599338
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002615058GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 500
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat

DRAFT

CON EDISON (Continued) **S117737020**

Specific Gravity: 1

AE220 **LOT 25,TAXBLOCK 4153** **NY E DESIGNATION** **S108075793**
NE **29 MILFORD STREET** **NY NYC LAND USE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208** **NY NYC OER**
0.218 mi.
1151 ft. **Site 1 of 4 in cluster AE**

Relative:
Higher

Actual:
39 ft.

E DESIGNATION:

Name:	LOT 25,TAXBLOCK 4153
Address:	29 MILFORD STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	25
Tax Block:	4153
Borough Code:	BK
E-No:	E-141
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	04DCP031K
Ulurp Number:	C040389ZMK
Zoning Map No:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	29 MILFORD STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6789395
Longitude:	-73.8778988
Type Of Ownership Code:	Not reported
Owner Name:	29 MILFORD ST LLC
Borough:	BK
Tax Block:	4153
Tax Lot:	25
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192001001
Census Tract 2010:	1192
Census Block 2010:	1001
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R5B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported

DRAFT

LOT 25,TAXBLOCK 4153 (Continued) **S108075793**

Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B1: Two Family Dwellings - Brick
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	3225
Commercial Floor Area:	0
Residential Floor Area:	3225
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	17.9200000
Building Depth:	60.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	10080.00000
Assessed Total Value:	62160.00000
Exempt Total Value:	0.00000
Year Built:	2020
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.29000000000
Maximum Allowable Residential Far:	1.35000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3041530025.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1018117
Y Coordinate:	186656
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 031
Tax Map #:	31306
E-designation Number:	E-141
Apportionment BBL:	Not reported
Apportionment Date:	Not reported

DRAFT

LOT 25,TAXBLOCK 4153 (Continued) **S108075793**

Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	29 MILFORD STREET
Address:	29 MILFORD STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678817
Longitude:	-73.878144
OER Project Numbers:	13TMP0473K,13EHAZ473K
BBL:	3041530025
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	5
Community Board:	37
Council District:	1192
Census Tract:	3000000
BIN:	3041530025
NTA:	East New York

X221 **2969 ATLANTIC AVE** **UST FINDER** **1028574581**
NW **2969 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.222 mi.
1170 ft. **Site 5 of 7 in cluster X**

Relative:
Higher

Actual:
33 ft.

UST FINDER:

Object ID:	295946
Facility ID:	NY31095
Name:	2969 ATLANTIC AVE
Address:	2969 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	10262
Private Wells 1500ft:	16
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)

DRAFT

2969 ATLANTIC AVE (Continued) **1028574581**

Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.884834
Y Coord:	40.678029
Latitude:	40.678029
Longitude:	-73.884834

UST FINDER:

Object ID:	1227210
Facility ID:	NY31095
Tank ID:	NY112358
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

X222 **2969 ATLANTIC AVE** **NY UST** **U004045357**
NW **2969 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.222 mi.
1170 ft. **Site 6 of 7 in cluster X**

Relative:
Higher

Actual:
33 ft.

UST:

Name:	2969 ATLANTIC AVE
Address:	2969 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-609250 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594282.41509
UTM Y:	4503637.99150
Site Type:	Unknown

Affiliation Records:

Site Id:	31095
Affiliation Type:	Emergency Contact
Company Name:	SHREE ASHTA VINAYAK INC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31095

DRAFT

2969 ATLANTIC AVE (Continued) **U004045357**

Affiliation Type:	Facility Operator
Company Name:	2969 ATLANTIC AVE
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31095
Affiliation Type:	Mail Contact
Company Name:	SUPER 8 MOTEL
Contact Type:	Not reported
Contact Name:	DAN SARTUALA
Address1:	410 ROUTE 46 WEST
Address2:	Not reported
City:	SOUTH HACKENSACK
State:	NJ
Zip Code:	07606
Country Code:	001
Phone:	(201) 951-8308
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31095
Affiliation Type:	Facility Owner
Company Name:	SHREE ASHTA VINAYAK INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2969 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11208
Country Code:	001
Phone:	(718) 827-1111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	66933
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000

DRAFT

2969 ATLANTIC AVE (Continued) **U004045357**

Install Date:	Not reported
Date Tank Closed:	08/22/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

X223 **RIVEIRA MOTEL** **NY LTANKS** **S105999669**
NW **2969 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.222 mi.
1170 ft. **Site 7 of 7 in cluster X**

Relative: **Higher**

Actual: **33 ft.**

LTANKS:

Name:	RIVEIRA MOTEL
Address:	2969 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0305319 / 2006-03-14
Facility ID:	0305319
Site ID:	226027
Spill Date:	2003-08-19
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2003-08-19
CID:	422
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-19
Spill Record Last Update:	2006-03-14
Spiller Name:	Not reported

DRAFT

RIVEIRA MOTEL (Continued) **S105999669**

Spiller Company:	RIVIERA MOTEL
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	GARY WEISSBERGER
Spiller Phone:	(732) 390-5858
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	186577
Latitude:	40.6780283
Longitude:	-73.8848337
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland spoke with Gary Weissberger of Whitman Companies. Specific direction was: 2 soil boring samples through the bottom of the tank 3 soil borings from around the tank (2 ends and one side) Depth of borings will be 0 to 2 feet below the bottom of the tank. The other side is right up against a building. Test samples to VOC/SVOC & compare to TAGM One deeper boring to confirm that Groundwater is not in the area 3/6/2006 Sangesland called Mr. Weissberger at Whitman asking about the closure report. He said a copy was submitted in Oct 2003 and sent to Anthony Sigona. Sangesland asked for another copy of the report to be sent. Mr. Weissberger says that teh site was clean and the closure report backs this up. 3/14/2006 Sangesland reviewed a UST - Site Investigation Report from Gary Weissberger of the Whitman Companies originally dated October 2003. The report confirms the information discussed above. The subject tank was properly cleaned, soil samples were taken through the bottom of the tank and then it was filled. The soil samples taken through the bottom of the tank showed slight hits for a few SVOCs, but this can be attributed to the fill material located in the area. Additional soil samples were taken adjacent to the tank and found to be clean. The tank was properly abandoned in place and the soil sampling proved to be adequate for spill closure.
Remarks:	OLD TANK UNABLE TO TIGHNESS TEST TANK WOULD LIKE CALLBACK

All Materials:

Site ID:	226027
Operable Unit ID:	871968
Operable Unit:	01
Material ID:	502574
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

AA224
SW
1/8-1/4
0.222 mi.
1171 ft.

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS
2406 PITKIN AVE
BROOKLYN, NY 11208

Site 4 of 7 in cluster AA

E MANIFEST **1031958936**
N/A

Relative:
Higher

Actual:
32 ft.

E MANIFEST:

Manifest Tracking Number:	006871715GBF
Last Updated Date:	20220104
Shipped Date:	20211217
Received Date:	20211222
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2406 PITKIN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006871715GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006871715GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082

DRAFT

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031958936**

U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	226.7575
Quantity Haz Tons:	0.25
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

AA225 **CON EDISON** **NY MANIFEST** **S117066709**
SW **2406 PITKIN AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.222 mi.
1171 ft. **Site 5 of 7 in cluster AA**

Relative:
Higher

Actual:
32 ft.

NY MANIFEST:

EPA ID:	NYP004593950
Country:	USA
Name:	Con Edison
Address:	2406 PITKIN AV
Address 2:	SB55263
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	2406 PITKIN AV
Location Address 2:	SB55263
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

DRAFT

CON EDISON (Continued) **S117066709**

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/11/2014
Trans1 Recv Date: 07/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/15/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004593950
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002361174GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 100
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat

DRAFT

CON EDISON (Continued) **S117066709**

Specific Gravity: 1

AF226 **ATLANTIC AVE - NY - INC** **RCRA NonGen / NLR** **1000328924**
North **3123 ATLANTIC AVE & HALE** **FINDS** **NYD000816561**
1/8-1/4 **BROOKLYN, NY 11208** **ECHO**
0.223 mi.
1175 ft. **Site 1 of 6 in cluster AF**

Relative:
Higher

Actual:
39 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Atlantic Ave - Ny - Inc
Handler Address:	Atlantic Ave & Hale
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYD000816561
Contact Name:	Not reported
Contact Address:	ATLANTIC AVE & HALE AVE
Contact City,State,Zip:	BROOKLYN, NY 11208
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ATLANTIC AVE & HALE AVE
Mailing City,State,Zip:	BROOKLYN, NY 11208
Owner Name:	Sun Oil Co Of Pennsylvania
Owner Type:	Private
Operator Name:	Sun Oil Co Of Pennsylvania
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

DRAFT

ATLANTIC AVE - NY - INC (Continued) **1000328924**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SUN OIL CO OF PENNSYLVANIA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: SUN OIL CO OF PENNSYLVANIA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DRAFT

ATLANTIC AVE - NY - INC (Continued) **1000328924**

Owner/Operator Indicator: Owner
Owner/Operator Name: SUN OIL CO OF PENNSYLVANIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19950324
Handler Name: ATLANTIC AVE - NY - INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ATLANTIC AVE - NY - INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ATLANTIC AVE - NY - INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: ATLANTIC AVE - NY - INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

DRAFT

ATLANTIC AVE - NY - INC (Continued) **1000328924**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110007996044

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000328924
Registry ID: 110007996044

DFR URL:
Name: ATLANTIC AVE - NY - INC
Address: 3123 Atlantic Ave & Hale
City,State,Zip: BROOKLYN, NY 11208

AF227 **LOT 52,TAXBLOCK 3959** **NY AST** **S118704399**
North **3123 ATLANTIC AVENUE** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11208** **NY NYC LAND USE**
0.223 mi.
1175 ft. **Site 2 of 6 in cluster AF**

Relative:
Higher

Actual:
39 ft.

AST:

Name:	ATLANTIC SERVICE STATION, INC.
Address:	3123 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601367

DRAFT

LOT 52,TAXBLOCK 3959 (Continued) **S118704399**

Program Type:	PBS
UTM X:	594631.55222
UTM Y:	4503790.36493
Expiration Date:	06/12/2027
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23334
Affiliation Type:	Emergency Contact
Company Name:	ATLANTIC SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 933-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-13

Site Id:	23334
Affiliation Type:	Facility Owner
Company Name:	CYPRESS HILLS SERVICE CENTER INC.
Contact Type:	MEMBER
Contact Name:	JOSEPH MACCHIA
Address1:	2975 WESTCHESTER AVENUE
Address2:	Not reported
City:	PURCHASE
State:	NY
Zip Code:	10577
Country Code:	001
Phone:	(516) 933-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2024-02-27

Site Id:	23334
Affiliation Type:	Facility Operator
Company Name:	ATLANTIC SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	HARDEEP SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 235-1376
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-13

DRAFT

LOT 52,TAXBLOCK 3959 (Continued) **S118704399**

Site Id:	23334
Affiliation Type:	Mail Contact
Company Name:	3123 ATLANTIC, LLC
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	556 CENTRAL AVENUE
Address2:	Not reported
City:	BETHPAGE
State:	NY
Zip Code:	11714
Country Code:	001
Phone:	(516) 933-0700
EMail:	JOSEPH@THEMACCHIAGROUP.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-13

Tank Info:

Tank Number:	17
Tank Id:	287244

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
G12 - Tank Secondary Containment - Double-Walled (AG only)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/17/2020
Capacity Gallons:	240
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	ACDANIEL
Last Modified:	02/27/2024
Material Name:	waste oil/used oil

E DESIGNATION:

Name:	LOT 52,TAXBLOCK 3959
Address:	3123 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	52
Tax Block:	3959

DRAFT

LOT 52,TAXBLOCK 3959 (Continued) **S118704399**

Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	3123 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6795951
Longitude:	-73.8800716
Type Of Ownership Code:	Not reported
Owner Name:	VERMES, ORIT MARKOWITZ
Borough:	BK
Tax Block:	3959
Tax Lot:	52
Community District:	305
Census Tract 2020:	3117400
Census Block 2020:	31174002003
Census Tract 2010:	1174
Census Block 2010:	2006
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3900
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	R8A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G4: Garages And Gasoline Stations - Gas Station With Service/Auto Repair
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	11061
Total Building Floor Area:	1845
Commercial Floor Area:	1845
Residential Floor Area:	0

DRAFT

LOT 52,TAXBLOCK 3959 (Continued) **S118704399**

Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	1845
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.5800000
Lot Depth:	101.4200000
Building Frontage:	30.0000000
Building Depth:	61.5000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	184050.00000
Assessed Total Value:	546750.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.17000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039590052.00000000
Condominium Number:	Not reported
Census Tract 2:	1174
X Coordinate:	1017514
Y Coordinate:	186894
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 012
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

DRAFT

AF228 **ATLANTIC AVENUE INC DBA CITY GAS** **RCRA NonGen / NLR** **1001080181**
North **3123 ATLANTIC AVE** **FINDS** **NYU005000286**
1/8-1/4 **BROOKLYN, NY 11212** **ECHO**
0.223 mi.
1175 ft. **Site 3 of 6 in cluster AF**

Relative:
Higher

Actual:
39 ft.

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Atlantic Avenue Inc Dba City Gas
Handler Address:		Atlantic Ave
Handler City,State,Zip:		BROOKLYN, NY 11212
EPA ID:		NYU005000286
Contact Name:		Not reported
Contact Address:		ATLANTIC AVE
Contact City,State,Zip:		BROOKLYN, NY 11212
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		O
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		ATLANTIC AVE
Mailing City,State,Zip:		BROOKLYN, NY 11212
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

DRAFT

ATLANTIC AVENUE INC DBA CITY GAS (Continued) **1001080181**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230629
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: UNK	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950929
Handler Name:	ATLANTIC AVENUE INC DBA CITY GAS
Federal Waste Generator Description:	Not reported
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	ATLANTIC AVENUE INC DBA CITY GAS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

DRAFT

ATLANTIC AVENUE INC DBA CITY GAS (Continued) **1001080181**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ATLANTIC AVENUE INC DBA CITY GAS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

DRAFT

ATLANTIC AVENUE INC DBA CITY GAS (Continued) **1001080181**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19990927
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: R2MML
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19950628

DRAFT

ATLANTIC AVENUE INC DBA CITY GAS (Continued) **1001080181**

Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2PM
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004568370

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001080181
Registry ID: 110004568370

DFR URL:
Name: ATLANTIC AVENUE INC DBA CITY GAS
Address: 3123 Atlantic Ave
City,State,Zip: BROOKLYN, NY 11212

AF229 **CYPRESS HILLS SERVICE CENTER INC** **UST FINDER** **1028572272**
North **3123 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.223 mi.
1175 ft. **Site 4 of 6 in cluster AF**

Relative:
Higher

Actual:
39 ft.

UST FINDER:

Object ID:	295978
Facility ID:	NY23334
Name:	CYPRESS HILLS SERVICE CENTER INC
Address:	3123 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	8
Closed USTs:	13
TOS USTs:	0
Population 1500ft:	8876
Private Wells 1500ft:	46
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity

DRAFT

CYPRESS HILLS SERVICE CENTER INC (Continued) **1028572272**

Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8799329999999
Y Coord:	40.6787130000001
Latitude:	40.678713
Longitude:	-73.879933

UST FINDER:

Object ID:	1220362
Facility ID:	NY23334
Tank ID:	NY111515
Tank Status:	Open
Installation Date:	1999/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	8000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220363
Facility ID:	NY23334
Tank ID:	NY31578
Tank Status:	Open
Installation Date:	1999/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220364
Facility ID:	NY23334
Tank ID:	NY29760
Tank Status:	Open
Installation Date:	1999/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220365
Facility ID:	NY23334
Tank ID:	NY29758
Tank Status:	Open
Installation Date:	1999/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	8000

DRAFT

CYPRESS HILLS SERVICE CENTER INC (Continued) **1028572272**

Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220366
Facility ID: NY23334
Tank ID: NY28747
Tank Status: Open
Installation Date: 1999/11/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220367
Facility ID: NY23334
Tank ID: NY28243
Tank Status: Open
Installation Date: 1999/11/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220368
Facility ID: NY23334
Tank ID: NY26977
Tank Status: Open
Installation Date: 1999/11/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220369
Facility ID: NY23334
Tank ID: NY26976
Tank Status: Open
Installation Date: 1999/11/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 8000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220370
Facility ID: NY23334
Tank ID: NY32005
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220371
Facility ID: NY23334
Tank ID: NY32004
Tank Status: Closed

DRAFT

CYPRESS HILLS SERVICE CENTER INC (Continued) **1028572272**

Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220372
Facility ID: NY23334
Tank ID: NY31579
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220373
Facility ID: NY23334
Tank ID: NY31577
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220374
Facility ID: NY23334
Tank ID: NY31576
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220375
Facility ID: NY23334
Tank ID: NY29759
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220376
Facility ID: NY23334
Tank ID: NY29757
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1220377

DRAFT

CYPRESS HILLS SERVICE CENTER INC (Continued) **1028572272**

Facility ID:	NY23334
Tank ID:	NY28879
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220378
Facility ID:	NY23334
Tank ID:	NY28878
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220379
Facility ID:	NY23334
Tank ID:	NY28877
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220380
Facility ID:	NY23334
Tank ID:	NY28749
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220381
Facility ID:	NY23334
Tank ID:	NY28748
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1220382
Facility ID:	NY23334
Tank ID:	NY28242
Tank Status:	Closed
Installation Date:	1968/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported

DRAFT

CYPRESS HILLS SERVICE CENTER INC (Continued) **1028572272**

Tank Wall Type: Not reported

AF230 **ATLANTIC SERVICE STATION, INC.** **NY UST** **U003065888**
North **3123 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.223 mi.
1175 ft. **Site 5 of 6 in cluster AF**

Relative:
Higher

Actual:
39 ft.

UST:

Name:	ATLANTIC SERVICE STATION, INC.
Address:	3123 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-601367 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/12/2027
UTM X:	594631.55222
UTM Y:	4503790.36493
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23334
Affiliation Type:	Emergency Contact
Company Name:	ATLANTIC SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 933-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-13

Site Id:	23334
Affiliation Type:	Facility Owner
Company Name:	CYPRESS HILLS SERVICE CENTER INC.
Contact Type:	MEMBER
Contact Name:	JOSEPH MACCHIA
Address1:	2975 WESTCHESTER AVENUE
Address2:	Not reported
City:	PURCHASE
State:	NY
Zip Code:	10577
Country Code:	001
Phone:	(516) 933-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2024-02-27

Site Id: 23334

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Affiliation Type:	Facility Operator
Company Name:	ATLANTIC SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	HARDEEP SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 235-1376
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-13

Site Id:	23334
Affiliation Type:	Mail Contact
Company Name:	3123 ATLANTIC, LLC
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	556 CENTRAL AVENUE
Address2:	Not reported
City:	BETHPAGE
State:	NY
Zip Code:	11714
Country Code:	001
Phone:	(516) 933-0700
EMail:	JOSEPH@THEMACCHIAGROUP.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-13

Tank Info:

Tank Number:	001
Tank ID:	167569
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	11/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 001-A
Tank ID: 167570
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 167573
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 11/01/1999
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 002-A
Tank ID: 167582
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 167583
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 4000
Install Date: 11/01/1999

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	003-A
Tank ID:	167584
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Tank Number:	004
Tank ID:	167585
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	11/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	004-A
Tank ID:	167599
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	005
Tank ID:	167600
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	11/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	005-A
Tank ID:	167601
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 45771
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 007
Tank ID: 45772
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 008
Tank ID: 45773
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 11/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 009
Tank ID: 45774
Tank Status: Closed - Removed
Material Name: Closed - Removed

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	010
Tank ID:	45775
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Tank Number:	011
Tank ID:	45776
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	012
Tank ID:	45777
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	03
Date Test:	03/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	13
Tank ID:	63605
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1968
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
D10 - Pipe Type - Copper
F00 - Pipe External Protection - None

Tank Number:	14
Tank ID:	58020
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	11/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34
Date Test:	05/05/2009
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	09/24/2024

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	15
Tank ID:	58021
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	11/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34
Date Test:	05/05/2009
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	09/24/2024

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	16

DRAFT

ATLANTIC SERVICE STATION, INC. (Continued) **U003065888**

Tank ID:	58022
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	11/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	34
Date Test:	05/05/2009
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	09/24/2024

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

AE231 **25 MILFORD STREET** **NY VCP** **S129932225**
NE **25 MILFORD STREET** **NY NYC OER** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.225 mi.
1190 ft. **Site 2 of 4 in cluster AE**

Relative: **Higher**
Actual: **39 ft.**

VCP NYC:

Project ID:	21TMP1469K,21EHAZ296K,22CVCP021K
Name:	25 MILFORD STREET
Address:	25 MILFORD STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3041530027
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.678885
Longitude:	-73.878162
Postcode:	5
Community Board:	37
Council District:	1192
Census Tract:	3000000
BIN:	3041530027

DRAFT

25 MILFORD STREET (Continued) **S129932225**

NTA: East New York

NYC OER:
Name: 25 MILFORD STREET
Address: 25 MILFORD STREET
City,State,Zip: BROOKLYN, NY
Latitude: 40.678885
Longitude: -73.878162
OER Project Numbers: 21TMP1469K,21EHAZ296K,22CVCP021K
BBL: 3041530027
OER Program: VCP (Enrolled), E/RD (Review)
Class: Completed (C)
Phase: Site Management

URL:
Postcode: 5
Community Board: 37
Council District: 1192
Census Tract: 3000000
BIN: 3041530027
NTA: East New York

AF232 **CON EDISON** **NY MANIFEST** **S117067425**
North **FRONT OF 224 HIGHLAND PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.227 mi.
1198 ft. **Site 6 of 6 in cluster AF**

Relative:
Higher

Actual:
38 ft.

NY MANIFEST:
EPA ID: NYP004602520
Country: USA
Name: Con Edison
Address: FRONT OF 224 HIGHLAND PL
Address 2: SB66709
City,State,Zip: BROOKLYN, NY 11201
Zip 4: Not reported
Location Address 1: FRONT OF 224 HIGHLAND PL
Location Address 2: SB66709
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported

DRAFT

CON EDISON (Continued) **S117067425**

Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004602520
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614976GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AG233 **CON EDISON SERVICE BOX: 23103** **RCRA NonGen / NLR** **1017775514**
WSW **422 CLEVELAND ST FRONT OF** **NYP004533527**
1/8-1/4 **BROOKLYN, NY 11208**
0.227 mi.
1198 ft. **Site 1 of 3 in cluster AG**

Relative: **Higher**
Actual: **35 ft.**

RCRA Listings:

Date Form Received by Agency:	20140615
Handler Name:	Con Edison Service Box: 23103
Handler Address:	Cleveland St Front Of
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004533527

DRAFT

CON EDISON SERVICE BOX: 23103 (Continued) **1017775514**

Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150211
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

DRAFT

CON EDISON SERVICE BOX: 23103 (Continued) **1017775514**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140515
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140515
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140615
Handler Name: CON EDISON SERVICE BOX:	23103
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

DRAFT

AG234 **CON EDISON** **NY MANIFEST** **S117061078**
WSW **422 CLEVELAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.227 mi.
1198 ft. **Site 2 of 3 in cluster AG**

Relative:
Higher

Actual:
35 ft.

NY MANIFEST:

EPA ID:	NYP004696233
Country:	USA
Name:	Con Edison
Address:	422 CLEVELAND ST
Address 2:	SB 23103
City,State,Zip:	BROOKLYN, NY
Zip 4:	Not reported
Location Address 1:	422 CLEVELAND ST
Location Address 2:	SB 23103
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/17/2014
Trans1 Recv Date:	11/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004696233
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417081GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

DRAFT

CON EDISON (Continued) **S117061078**

Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 30
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

EPA ID: NYP004533527
Country: USA
Name: Con Edison
Address: 422 CLEVELAND ST FRONT OF
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: 422 CLEVELAND ST
Location Address 2: SB 23103
Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/15/2014
Trans1 Recv Date: 05/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/16/2014

DRAFT

CON EDISON (Continued) **S117061078**

Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004533527
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013246347JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 50
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

EPA ID: NYP004708707
Country: USA
Name: Con Edison
Address: 422 CLEVELAND ST
Address 2: SB23103
City,State,Zip: BROOKLYN, NY 11208
Zip 4: Not reported
Location Address 1: 422 CLEVELAND ST
Location Address 2: SB23103
Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL

DRAFT

CON EDISON (Continued) **S117061078**

Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: NJD003812047
Generator Ship Date: 12/10/2014
Trans1 Recv Date: 12/10/2014
Trans2 Recv Date: 12/31/2014
TSD Site Recv Date: 12/31/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004708707
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002620118GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 50
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

DRAFT

AE235 **LOT 28,TAXBLOCK 4153** **NY VCP** **S108075795**
NE **23 MILFORD STREET** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY 11208** **NY NYC LAND USE**
0.227 mi. **NY NYC OER**
1200 ft. **Site 3 of 4 in cluster AE**

Relative:
Higher

Actual:
39 ft.

VCP NYC:

Project ID:	23TMP1291K,23EHAZ202K,24CVCP008K
Name:	23 MILFORD STREET
Address:	23 MILFORD ST
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3041530028
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.678918
Longitude:	-73.878169
Postcode:	5
Community Board:	37
Council District:	1192
Census Tract:	3000000
BIN:	3041530028
NTA:	East New York

E DESIGNATION:

Name:	LOT 28,TAXBLOCK 4153
Address:	23 MILFORD STREET
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	28
Tax Block:	4153
Borough Code:	BK
E-No:	E-141
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	04DCP031K
Ulurp Number:	C040389ZMK
Zoning Map No:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	23 MILFORD STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6790988
Longitude:	-73.8779382
Type Of Ownership Code:	Not reported
Owner Name:	ZHINGRI PROPERTIES LLC
Borough:	BK
Tax Block:	4153
Tax Lot:	28
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192001001
Census Tract 2010:	1192
Census Block 2010:	1001
School District:	19

DRAFT

LOT 28,TAXBLOCK 4153 (Continued) **S108075795**

City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R5B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B1: Two Family Dwellings - Brick
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	1875
Total Building Floor Area:	2531
Commercial Floor Area:	0
Residential Floor Area:	2531
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	0
Number Of Floors:	3.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	18.7500000
Lot Depth:	100.0000000
Building Frontage:	18.8000000
Building Depth:	45.0000000
Extension Code:	Not reported
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	11160.00000
Assessed Total Value:	11160.00000
Exempt Total Value:	0.00000
Year Built:	2024
Year Altered 1:	2023
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.35000000000
Maximum Allowable Residential Far:	1.35000000000
Maximum Allowable Commercial Far:	0.00000000000

DRAFT

LOT 28,TAXBLOCK 4153 (Continued) **S108075795**

Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3041530028.00000000
Condominium Number:	Not reported
Census Tract 2:	1192
X Coordinate:	1018106
Y Coordinate:	186714
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 031
Tax Map #:	31306
E-designation Number:	E-141
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	23 MILFORD STREET
Address:	23 MILFORD ST
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678918
Longitude:	-73.878169
OER Project Numbers:	23TMP1291K,23EHAZ202K,24CVCP008K
BBL:	3041530028
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	5
Community Board:	37
Council District:	1192
Census Tract:	3000000
BIN:	3041530028
NTA:	East New York

AE236 **23 MILFORD STREET VCP #24CVCP008K** **RCRA NonGen / NLR** **1031076079**
NE **23 MILFORD ST** **E MANIFEST** **NYR000265371**
1/8-1/4 **BROOKLYN, NY 11208**
0.227 mi.
1200 ft. **Site 4 of 4 in cluster AE**

Relative:
Higher

Actual:
39 ft.

RCRA Listings:

Date Form Received by Agency:	20240807
Handler Name:	23 Milford Street Vcp #24cvcp008k
Handler Address:	Milford St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYR000265371
Contact Name:	MARIO ZHINGRI
Contact Address:	MILFORD ST
Contact City,State,Zip:	BROOKLYN, NY 11208
Contact Telephone:	516-807-7434
Contact Fax:	Not reported

DRAFT

23 MILFORD STREET VCP #24CVCP008K (Continued) **1031076079**

Contact Email:		MGZBUILDER@GMAIL.COM
Contact Title:		ENVIRONMENTAL SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		178TH ST
Mailing City,State,Zip:		JAMAICA, NY 11433
Owner Name:	Zhingri Properties Llc	
Owner Type:		Private
Operator Name:	Mario Zhingri	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20240807
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

DRAFT

23 MILFORD STREET VCP #24CVCP008K (Continued) **1031076079**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ZHINGRI PROPERTIES LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 112-03 78TH ST
Owner/Operator City,State,Zip: JAMAICA, NY 11433
Owner/Operator Telephone: 516-807-7434
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MGZBUILDER@GMAIL.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MARIO ZHINGRI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 23 MILFORD ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11208
Owner/Operator Telephone: 516-807-7434
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MGZBUILDER@GMAIL.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: ZHINGRI PROPERTIES LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 112-03 178TH ST
Owner/Operator City,State,Zip: JAMAICA, NY 11433
Owner/Operator Telephone: 516-807-7434
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MGZBUILDER@GMAIL.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MARIO ZHINGRI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 23 MILFORD ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11208
Owner/Operator Telephone: 516-807-7434
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: MGZBUILDER@GMAIL.COM

Historic Generators:
Receive Date: 20240807
Handler Name: 23 MILFORD STREET VCP #24CVCP008K

DRAFT

23 MILFORD STREET VCP #24CVCP008K (Continued) **1031076079**

Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20240103
Handler Name: 23 MILFORD STREET VCP #24CVCP008K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 23611
NAICS Description: Residential Building Construction

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 018011798FLE
Last Updated Date: 20240401
Shipped Date: 20240319
Received Date: 20240319
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYR000265371
Generator Name: 23 Milford Street Vcp #24cvcp008k
Generator Location Street Number: 23
Generator Location Street 1: 23 MILFORD ST
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY
Generator Location Zip: 11208
Generator Mail Street Number: 112-03
Generator Mail Street 1: 78TH ST
Generator Mail Street 2: Not reported
Generator Mail City: JAMAICA

DRAFT

23 MILFORD STREET VCP #24CVCP008K (Continued) **1031076079**

Generator Mail Zip:	11433
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	018011798FLE
Transporter Line Number:	1
Transporter EPA ID:	NJR986628162
Transporter Name:	Iwt Transport, Inc.

Waste Line:

Manifest Tracking Number:	018011798FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Na3077, Hazardous Waste, Solid N.O.S., (Lead) 9, Pg Iii, Rq (D008)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	11
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	4950
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	2.475
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	2.475
Waste Quantity, in Kilograms:	2244.8992
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2244.8992
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported

DRAFT

23 MILFORD STREET VCP #24CVCP008K (Continued) **1031076079**

Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	2244.8992
Quantity Haz Tons:	2.475
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported

AA237 **LOT 19,TAXBLOCK 4017** **NY VCP** **S118704178**
SW **2400 PITKIN AVENUE** **NY E DESIGNATION** **N/A**
1/8-1/4 **BROOKLYN, NY** **NY NYC OER**
0.228 mi.
1206 ft. **Site 6 of 7 in cluster AA**

Relative:
Higher

Actual:
32 ft.

VCP NYC:

Project ID:	21TMP0991K,21EHAN209K,22CVCP042K
Name:	2400 PITKIN AVENUE
Address:	2400 PITKIN AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,401,700,153,040,100,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.673673
Longitude:	-73.883803
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3089210
BIN:	3040170019
NTA:	East New York

E DESIGNATION:

Name:	LOT 19,TAXBLOCK 4017
Address:	2400 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	19
Tax Block:	4017
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

DRAFT

LOT 19,TAXBLOCK 4017 (Continued) **S118704178**

NYC OER:

Name:	2400 PITKIN AVENUE
Address:	2400 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.673673
Longitude:	-73.883803
OER Project Numbers:	21TMP0991K,21EHAN209K,22CVCP042K
BBL:	3.0401700153040101E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	5
Community Board:	37
Council District:	1166
Census Tract:	3089210
BIN:	3040170019
NTA:	East New York

AB238 **CON EDISON SERVICE BOX: 60661** **RCRA NonGen / NLR** **1017779076**
SSW **510 LINWOOD ST** **FINDS** **NYP004570446**
1/8-1/4 **BROOKLYN, NY 11208**
0.230 mi.
1212 ft. **Site 2 of 3 in cluster AB**

Relative:
Lower

Actual:
29 ft.

RCRA Listings:

Date Form Received by Agency:		20140719
Handler Name:		Con Edison Service Box: 60661
Handler Address:		Linwood St
Handler City,State,Zip:		BROOKLYN, NY 11208
EPA ID:		NYP004570446
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

DRAFT

CON EDISON SERVICE BOX: 60661 (Continued) **1017779076**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny

DRAFT

CON EDISON SERVICE BOX: 60661 (Continued) **1017779076**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140719
Handler Name: CON EDISON SERVICE BOX:	60661
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063831929

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DRAFT

AB239 **CON EDISON** **NY MANIFEST** **S117064550**
SSW **510 LINWOOD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.230 mi.
1212 ft. **Site 3 of 3 in cluster AB**

Relative:
Lower

Actual:
29 ft.

NY MANIFEST:

EPA ID:	NYP004570446
Country:	USA
Name:	Con Edison
Address:	510 LINWOOD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	FO 510 LINWOOD ST
Location Address 2:	STRUCTURE 60661
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/2014
Trans1 Recv Date:	06/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004570446
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502777GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

DRAFT

CON EDISON (Continued) **S117064550**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD240 **2958 ATLANTIC AVENUE** **NY AST** **A100298619**
WNW **2958 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.230 mi.
1213 ft. **Site 5 of 7 in cluster AD**

Relative:
Lower

Actual:
31 ft.

AST:

Name:	2958 ATLANTIC AVENUE
Address:	2958 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610301
Program Type:	PBS
UTM X:	594231.52499
UTM Y:	4503568.02599
Expiration Date:	N/A
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	368493
Affiliation Type:	Facility Owner
Company Name:	ATLAND LLC C/O LAUNDRY CAPITAL CO, LLC
Contact Type:	VICE PRESIDENT
Contact Name:	OREN SAUBERMAN
Address1:	95-25 QUEENS BLVD, 10TH FLOOR
Address2:	Not reported
City:	REGO PARK
State:	NY
Zip Code:	11374
Country Code:	001
Phone:	(914) 921-8238
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM

DRAFT

2958 ATLANTIC AVENUE (Continued) **A100298619**

Date Last Modified: 2011-09-22

Site Id: 368493
Affiliation Type: Mail Contact
Company Name: ATLAND, LLC C/O LAUNDRY CAPITAL CO, LLC
Contact Type: Not reported
Contact Name: DAVID RUDDY
Address1: 95-25 QUEENS BOULEVARD
Address2: 10TH FLOOR
City: REGO PARK
State: NY
Zip Code: 11374
Country Code: 001
Phone: (914) 921-8238
EMail: DRUDDY@LAUNDRYCAPITAL.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2011-09-22

Site Id: 368493
Affiliation Type: Facility Operator
Company Name: CAESAR AUTO REPAIR CORP.
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: N/A
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-07-25

Site Id: 368493
Affiliation Type: Emergency Contact
Company Name: ATLAND LLC
Contact Type: Not reported
Contact Name: N/A
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: N/A
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2011-07-25

Tank Info:

Tank Number: 001
Tank Id: 213004

DRAFT

2958 ATLANTIC AVENUE (Continued) **A100298619**

Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:
A00 - Tank Internal Protection - None
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 03/28/2011
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: waste oil/used oil

AD241 **2958 ATLANTIC AVENUE** **NY UST** **U004182940**
WNW **2958 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.230 mi.
1213 ft. **Site 6 of 7 in cluster AD**

Relative: **Lower**
Actual: **31 ft.**

UST:
Name: 2958 ATLANTIC AVENUE
Address: 2958 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Id/Status: 2-610301 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 594231.52499
UTM Y: 4503568.02599
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 368493
Affiliation Type: Facility Owner
Company Name: ATLAND LLC C/O LAUNDRY CAPITAL CO, LLC
Contact Type: VICE PRESIDENT
Contact Name: OREN SAUBERMAN
Address1: 95-25 QUEENS BLVD, 10TH FLOOR
Address2: Not reported
City: REGO PARK
State: NY
Zip Code: 11374
Country Code: 001
Phone: (914) 921-8238
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2011-09-22

DRAFT

2958 ATLANTIC AVENUE (Continued) **U004182940**

Site Id:	368493
Affiliation Type:	Mail Contact
Company Name:	ATLAND, LLC C/O LAUNDRY CAPITAL CO, LLC
Contact Type:	Not reported
Contact Name:	DAVID RUDDY
Address1:	95-25 QUEENS BOULEVARD
Address2:	10TH FLOOR
City:	REGO PARK
State:	NY
Zip Code:	11374
Country Code:	001
Phone:	(914) 921-8238
EMail:	DRUDDY@LAUNDRYCAPITAL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2011-09-22

Site Id:	368493
Affiliation Type:	Facility Operator
Company Name:	CAESAR AUTO REPAIR CORP.
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-07-25

Site Id:	368493
Affiliation Type:	Emergency Contact
Company Name:	ATLAND LLC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-07-25

Tank Info:

Tank Number:	001A
Tank ID:	240142
Tank Status:	Closed - Removed
Material Name:	Closed - Removed

DRAFT

2958 ATLANTIC AVENUE (Continued) **U004182940**

Capacity Gallons:	1100
Install Date:	Not reported
Date Tank Closed:	04/29/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
J00 - Dispenser - None

Tank Number:	001B
Tank ID:	240143
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	0
Install Date:	Not reported
Date Tank Closed:	04/29/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

DRAFT

2958 ATLANTIC AVENUE (Continued) **U004182940**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None

AD242 **2958 ATLANTIC AVENUE** **UST FINDER** **1028580613**
WNW **2958 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.230 mi.
1213 ft. **Site 7 of 7 in cluster AD**

Relative:
Lower

Actual:
31 ft.

UST FINDER:

Object ID:	295919
Facility ID:	NY368493
Name:	2958 ATLANTIC AVENUE
Address:	2958 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	10071
Private Wells 1500ft:	16
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.885136
Y Coord:	40.677693
Latitude:	40.677693
Longitude:	-73.885136

UST FINDER:

Object ID:	1250190
Facility ID:	NY368493
Tank ID:	NY100409
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	Not reported
Substances:	Not reported
Tank Wall Type:	Not reported

DRAFT

2958 ATLANTIC AVENUE (Continued) **1028580613**

Object ID:	1250191
Facility ID:	NY368493
Tank ID:	NY102692
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1100
Substances:	Not reported
Tank Wall Type:	Not reported

AG243 **CON EDISON** **NY MANIFEST** **S117314364**
WSW **FRONT OF 681 GLENMORE AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.233 mi.
1232 ft. **Site 3 of 3 in cluster AG**

Relative:
Higher

Actual:
37 ft.

NY MANIFEST:

EPA ID:	NYP004614160
Country:	USA
Name:	Con Edison
Address:	FRONT OF 681 GLENMORE AV
Address 2:	SB60144
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	FRONT OF 681 GLENMORE AV
Location Address 2:	SB60144
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/31/2014
Trans1 Recv Date:	07/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004614160
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

DRAFT

CON EDISON (Continued) **S117314364**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615083GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AA244 **CON EDISON** **NY MANIFEST** **S117066429**
SW **408 ELTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.238 mi.
1258 ft. **Site 7 of 7 in cluster AA**

Relative: **Lower**

Actual: **31 ft.**

NY MANIFEST:

EPA ID:	NYP004590794
Country:	USA
Name:	Con Edison
Address:	408 ELTON ST
Address 2:	SB57647
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	408 ELTON ST
Location Address 2:	SB57647
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison

DRAFT

CON EDISON (Continued) **S117066429**

Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/11/2014
Trans1 Recv Date: 07/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/15/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004590794
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002504100GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 40
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

DRAFT

AH245 **FORMER KFC RESTAURANT** **NY UST** **U004197469**
NNE **3143 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.245 mi.
1294 ft. **Site 1 of 2 in cluster AH**

Relative:
Higher

Actual:
41 ft.

UST:

Name:	FORMER KFC RESTAURANT
Address:	3143 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Id/Status:	2-612075 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594721.44930
UTM Y:	4503823.04343
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	485475
Affiliation Type:	Mail Contact
Company Name:	BSB REAL ESTATE HOLDINGS, LLC
Contact Type:	MEMBER
Contact Name:	MARK BORTNICK
Address1:	PO BOX 182571
Address2:	Not reported
City:	COLUMBUS
State:	OH
Zip Code:	43218
Country Code:	001
Phone:	(516) 852-8712
EMail:	BORTNICK@AOL.COM
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-08-06

Site Id:	485475
Affiliation Type:	Facility Operator
Company Name:	FORMER KFC RESTAURANT
Contact Type:	Not reported
Contact Name:	FORMER/VACANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-08-06

Site Id:	485475
Affiliation Type:	Emergency Contact
Company Name:	BSB REAL ESTATE HOLDINGS, LLC
Contact Type:	Not reported
Contact Name:	MARK BORTNICK
Address1:	Not reported

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 852-8712
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXAJOKU
Date Last Modified:	2013-11-18

Site Id:	485475
Affiliation Type:	Facility Owner
Company Name:	BSB REAL ESTATE HOLDINGS, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	PO BOX 182571
Address2:	Not reported
City:	COLUMBUS
State:	OH
Zip Code:	43218
Country Code:	001
Phone:	(516) 852-8712
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXAJOKU
Date Last Modified:	2013-11-18

Tank Info:

Tank Number:	001
Tank ID:	249263
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	01/01/1971
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	249264
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	01/01/1971
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	003
Tank ID:	250983
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	250984
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	005
Tank ID:	250985
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 006
Tank ID: 250986
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/30/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 007
Tank ID: 250987
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/30/2013
Registered: True
Tank Location: Underground

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 008
Tank ID: 250988
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 10/30/2013
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 009
Tank ID: 250989
Tank Status: Closed - Removed

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	010
Tank ID:	250990
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

F00 - Pipe External Protection - None

Tank Number:	011
Tank ID:	250991
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	012
Tank ID:	250992
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

DRAFT

FORMER KFC RESTAURANT (Continued) **U004197469**

K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	013
Tank ID:	250993
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	10/30/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

AH246 **FORMER KFC RESTAURANT** **UST FINDER** **1028592193**
NNE **3143 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.245 mi.
1294 ft. **Site 2 of 2 in cluster AH**

Relative:
Higher

Actual:
41 ft.

UST FINDER:

Object ID:	296018
Facility ID:	NY485475
Name:	FORMER KFC RESTAURANT
Address:	3143 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	13
TOS USTs:	0
Population 1500ft:	9008
Private Wells 1500ft:	38

DRAFT

FORMER KFC RESTAURANT (Continued) **1028592193**

Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.879341
Y Coord:	40.679601
Latitude:	40.679601
Longitude:	-73.879341

UST FINDER:

Object ID:	1290109
Facility ID:	NY485475
Tank ID:	NY103125
Tank Status:	Closed
Installation Date:	1971/01/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1290110
Facility ID:	NY485475
Tank ID:	NY103388
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1290111
Facility ID:	NY485475
Tank ID:	NY103389
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1290112
Facility ID:	NY485475
Tank ID:	NY103590
Tank Status:	Closed
Installation Date:	Not reported

DRAFT

FORMER KFC RESTAURANT (Continued) **1028592193**

Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1290113
Facility ID: NY485475
Tank ID: NY105886
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1290114
Facility ID: NY485475
Tank ID: NY105887
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1290115
Facility ID: NY485475
Tank ID: NY105888
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1290116
Facility ID: NY485475
Tank ID: NY105889
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1290117
Facility ID: NY485475
Tank ID: NY106098
Tank Status: Closed
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1290118
Facility ID: NY485475

DRAFT

FORMER KFC RESTAURANT (Continued) **1028592193**

Tank ID:	NY106099
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1290119
Facility ID:	NY485475
Tank ID:	NY122473
Tank Status:	Closed
Installation Date:	1971/01/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1290120
Facility ID:	NY485475
Tank ID:	NY122474
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1290121
Facility ID:	NY485475
Tank ID:	NY122475
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

AI247 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031950156**
North **212 HIGHLAND PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.246 mi.
1298 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
39 ft.

E MANIFEST:

Manifest Tracking Number:	006747546GBF
Last Updated Date:	20211101
Shipped Date:	20211019
Received Date:	20211020
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	212 HIGHLAND PL
Generator Location Street 2:	Not reported

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950156**

Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006747546GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006747546GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.5
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.5
Waste Quantity, in Kilograms:	453.515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	453.515
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N

DRAFT

CON EDISON - COMPANY OF NY (Continued) **1031950156**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	453.515
Quantity Haz Tons:	0.5
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

AI248 **CON EDISON** **NY MANIFEST** **S117067427**
North **FO 212 HIGHLAND PL** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.246 mi.
1298 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
39 ft.

NY MANIFEST:

EPA ID:	NYP004602546
Country:	USA
Name:	Con Edison
Address:	FO 212 HIGHLAND PL
Address 2:	SB 67727
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	FO 212 HIGHLAND PL
Location Address 2:	SB 67727
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported

DRAFT

CON EDISON (Continued) **S117067427**

Generator Ship Date:	07/21/2014
Trans1 Recv Date:	07/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004602546
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002614974GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

249
ENE
1/8-1/4
0.249 mi.
1314 ft.

BROOKLYN DEVELOPMENT CNTR **NY LTANKS** **S106703284**
88 FOUNTAIN ST **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
32 ft.

LTANKS:

Name:	BROOKLYN DEVELOPMENT CNTR
Address:	88 FOUNTAIN ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8806149 / 1992-09-30
Facility ID:	8806149
Site ID:	140891
Spill Date:	1988-10-20
Spill Cause:	Tank Test Failure

DRAFT

BROOKLYN DEVELOPMENT CNTR (Continued) **S106703284**

Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1992-09-30
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-10-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-10-31
Spill Record Last Update:	2003-04-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	120325
Latitude:	40.6779981
Longitude:	-73.8761372
DEC Memo:	Not reported
Remarks:	2 25K TKS, L R'S = -0.920 & -0.235 GPH.

All TTF:

Facility ID:	8806149
Spill Number:	8806149
Spill Tank Test:	1534791
Site ID:	140891
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	140891
Operable Unit ID:	921314
Operable Unit:	01
Material ID:	454504
Material Code:	0001A
Material Name:	#2 fuel oil

DRAFT

BROOKLYN DEVELOPMENT CNTR (Continued) **S106703284**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AJ250 **INDUSTRIAL FINISHING PROD** **NJ MANIFEST** **S109533641**
ESE **465 LOGAN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.249 mi.
1315 ft. **Site 1 of 6 in cluster AJ**

Relative:
Lower

Actual:
23 ft.

NJ MANIFEST:

EPA ID:	NYD001303205
Name:	INDUSTRIAL FINISHING PROD
Address:	465 LOGAN STREET
City,State,Zip:	BROOKLYN, NY 11208
County:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYD001303205
Manifest Number:	008760369JJK
Date Shipped:	5/31/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

DRAFT

INDUSTRIAL FINISHING PROD (Continued) **S109533641**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003 D008 D010 F003
Hand Code:	Not reported
Quantity:	1,800.00
Unit:	Pounds

EPA ID:	NYD001303205
Manifest Number:	004072196JJK
Date Shipped:	07/25/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/25/2008
Date Trans2 Transported Waste:	08/01/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/01/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

DRAFT

INDUSTRIAL FINISHING PROD (Continued) **S109533641**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	3600
Unit:	P

EPA ID:	NYD001303205
Manifest Number:	008760374JJK
Date Shipped:	6/5/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported

DRAFT

INDUSTRIAL FINISHING PROD (Continued) **S109533641**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001 F003 D008 D010 F003
Hand Code: Not reported
Quantity: 2,100.00
Unit: Pounds

EPA ID: NYD001303205
Manifest Number: 004072151JJK
Date Shipped: 07/02/2008
TSDF EPA ID: NJD980536593
Transporter EPA ID: NYD064748304
Transporter 2 EPA ID: NJD080631369
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 07/02/2008
Date Trans2 Transported Waste: 07/11/2008
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 07/11/2008
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: N
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F003
Hand Code: H141
Quantity: 1800
Unit: P

DRAFT

INDUSTRIAL FINISHING PROD (Continued) **S109533641**

Generator EPA Facility Name:	INDUSTRIAL FINISHING PROD
Transporter-1 EPA Facility Name:	ACTION TRUCKING INC
EPA ID:	NYD001303205
Manifest Number:	009419720FLE
Date Shipped:	3/28/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/28/2018
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	4/3/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Generator EPA Facility Name:	INDUSTRIAL FINISHING PROD
Transporter-1 EPA Facility Name:	ACTION TRUCKING INC
EPA ID:	NYD001303205
Manifest Number:	009419720FLE
Date Shipped:	3/28/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

DRAFT

INDUSTRIAL FINISHING PROD (Continued) **S109533641**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/28/2018
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	4/3/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Generator EPA Facility Name:	INDUSTRIAL FINISHING PROD
Transporter-1 EPA Facility Name:	ACTION TRUCKING INC
EPA ID:	NYD001303205
Manifest Number:	009419594FLE
Date Shipped:	1/30/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC

DRAFT

INDUSTRIAL FINISHING PROD (Continued) **S109533641**

QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/30/2018
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/6/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
Generator EPA Facility Name:	INDUSTRIAL FINISHING PROD
Transporter-1 EPA Facility Name:	ACTION TRUCKING INC
EPA ID:	NYD001303205
Manifest Number:	009419594FLE
Date Shipped:	1/30/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/30/2018
Waste SEQ ID:	2
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	2/6/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

DRAFT

AJ251 **INDUSTRIAL FINISHINGS PROD. INC.** **NY CBS UST** **1000895959**
ESE **465 LOGAN ST.** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.249 mi.
1315 ft. **Site 2 of 6 in cluster AJ**

Relative:
Lower

Actual:
23 ft.

CBS UST:

Id/Status:	2-000162 / NO LONGER A MAJOR FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	04
Date Entered:	08/03/1989
Capacity:	3000
Chemical:	Toluene
Tank Closed:	06/99
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Install Date:	00/00
CAS No:	108883
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	None
Leak Detection:	None
Secondary Containmentt:	None
Overfill Protection:	None
Haz Percent:	100
Pipe Containment:	None
Pipe Type:	STEEL/IRON
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	14:16:04

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T
Id/Status:	2-000162 / NO LONGER A MAJOR FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	01
Date Entered:	08/03/1989
Capacity:	1000
Chemical:	Toluene
Tank Closed:	06/99
Tank Status:	In Service
Tank Type:	0
Install Date:	00/00
CAS No:	108883
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Tank External:	NONE
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	None
Leak Detection:	None
Secondary Containmentt:	None
Overfill Protection:	None
Haz Percent:	100
Pipe Containment:	None
Pipe Type:	STEEL/IRON
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	14:14:56
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

Id/Status:	2-000162 / NO LONGER A MAJOR FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Mailing Telephone:	(718) 277-3333
Tank Number:	02
Date Entered:	08/03/1989
Capacity:	1000
Chemical:	Xylene (mixed)
Tank Closed:	06/99
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Install Date:	00/00
CAS No:	1330207
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	None
Leak Detection:	None
Secondary Containmentt:	None
Overfill Protection:	None
Haz Percent:	100
Pipe Containment:	None
Pipe Type:	STEEL/IRON
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	14:15:21
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

Id/Status:	2-000162 / NO LONGER A MAJOR FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	03
Date Entered:	08/03/1989
Capacity:	1000
Chemical:	Toluene
Tank Closed:	06/99
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Install Date:	00/00
CAS No:	108883
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	None
Leak Detection:	None
Secondary Containmentt:	None
Overfill Protection:	None
Haz Percent:	100
Pipe Containment:	None
Pipe Type:	STEEL/IRON
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	14:15:43
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Id/Status:	2-000162 / ACTIVE FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	01-1199
Date Entered:	11/22/1999
Capacity:	1080
Chemical:	Toluene
Tank Closed:	Not reported
Tank Status:	In Service
Tank Type:	Concrete
Install Date:	11/99
CAS No:	108883
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	JACKETED/FIBERGLASS
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	50
Leak Detection:	41
Secondary Containmentt:	Cut-off Walls
Overfill Protection:	24
Haz Percent:	100
Pipe Containment:	Double-Walled
Pipe Type:	PLASTIC
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	13:08:05
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T
Id/Status:	2-000162 / ACTIVE FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	02-1199
Date Entered:	11/22/1999
Capacity:	1080
Chemical:	m-Xylene
Tank Closed:	Not reported
Tank Status:	In Service
Tank Type:	Concrete
Install Date:	11/99
CAS No:	108383
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	JACKETED/FIBERGLASS
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	50
Leak Detection:	41

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Secondary Containmentt:	Cut-off Walls
Overfill Protection:	24
Haz Percent:	60
Pipe Containment:	Double-Walled
Pipe Type:	PLASTIC
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	13:08:18
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T
Id/Status:	2-000162 / ACTIVE FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208
Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	03-1199
Date Entered:	11/22/1999
Capacity:	1080
Chemical:	Toluene

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Tank Closed:	Not reported
Tank Status:	In Service
Tank Type:	Concrete
Install Date:	11/99
CAS No:	108883
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	JACKETED/FIBERGLASS
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	50
Leak Detection:	41
Secondary Containmentt:	Cut-off Walls
Overfill Protection:	24
Haz Percent:	100
Pipe Containment:	Double-Walled
Pipe Type:	PLASTIC
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	13:08:39
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

Id/Status:	2-000162 / ACTIVE FACILITY
Facility Type:	D
Facility Tel:	(718) 277-3333
Total Tanks:	4
Region:	STATE
ICS No:	2-126203
PBS No:	Not reported
MOSF No:	Not reported
SPDES No:	Not reported
Town:	NEW YORK CITY
Operator:	STEPHEN GALGANO
Emergency Contact:	GUS CRISTODERO
Emergency Contact Phone:	(718) 277-3333
Certification Date:	06/19/2001
Expiration Date:	08/03/2003
Owner Name:	INDUSTRIAL FINISHINGS PROD. INC.
Owner Address:	465 LOGAN ST.
Owner City,State,Zip:	BROOKLYN, NY 11208

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **1000895959**

Owner Phone:	(718) 277-3333
Owner Type:	5
Owner Subtype:	Not reported
Mailing Name:	INDUSTRIAL FINISHINGS PROD. INC.
Mailing Contact:	STEPHEN GALGANO
Mailing Address:	465 LOGAN ST.
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Telephone:	(718) 277-3333
Tank Number:	04-1199
Date Entered:	11/22/1999
Capacity:	4000
Chemical:	Toluene
Tank Closed:	Not reported
Tank Status:	In Service
Tank Type:	Concrete
Install Date:	11/99
CAS No:	108883
Substance:	More than one Hazardous Substance on DEC List
Tank Location:	Outdoors, Belowground
Tank Internal:	None
Tank External:	JACKETED/FIBERGLASS
Pipe Location:	Underground
Pipe Internal:	None
Pipe External:	50
Leak Detection:	41
Secondary Containmentt:	Cut-off Walls
Overfill Protection:	24
Haz Percent:	100
Pipe Containment:	Double-Walled
Pipe Type:	PLASTIC
Tank Error Status:	No Missing Data
Tank Secret:	F
Date Entered:	13:08:52
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Cert Flag:	F
Is it There:	F
Is Updated:	F
Owners Mark:	First Owner
Latitude:	Not reported
Longitude:	Not reported
Renew Date:	05/03/93
Deliquent:	F
Total Capacity:	7240
Date Expired:	08/03/95
Case No:	Not reported
Federal Amt:	T
Pipe Flag:	F
Reserve Flag:	T

DRAFT

AJ252 **INDUSTRIAL FINISHING PRODUCTS** **NY AIRS** **S121488958**
ESE **465 LOGAN STREET** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11208**
0.249 mi.
1315 ft. **Site 3 of 6 in cluster AJ**

Relative:
Lower

Actual:
23 ft.

AIRS:

Name:	INDUSTRIAL FINISHING PRODUCTS
Address:	465 LOGAN STREET
City,State,Zip:	BROOKLYN, NY 11208
DECID:	2610500272
Process ID:	Not reported
Latitude:	Not reported
Longitude:	Not reported
FIPS Code:	Not reported
Auth Type Code:	AFR
Permit Status:	Issued
Auth Status Code:	2
Emissions:	Not reported
Issue date:	01/04/2002
Expired Date:	Not reported
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

NY MANIFEST:

EPA ID:	NYD001303205
Country:	USA
Name:	Industrial Finishing Products
Address:	465 LOGAN STREET
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208-0000
Zip 4:	Not reported
Location Address 1:	465 LOGAN STREET
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Industrial Finishing Products
Mailing Contact:	Industrial Finishing Products
Mailing Address 1:	465 LOGAN STREET
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11208
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

Manifest Data:

Document ID:	NJA0386287
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NJDEPS-10
Year:	1988

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Trans2 State ID:	Not reported
Generator Ship Date:	881202
Trans1 Recv Date:	881202
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	881202
Part A Recv Date:	890127
Part B Recv Date:	881212
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01245
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	100
Document ID:	NYA6402969
Manifest Status:	C - Completed copy
Trans1 State ID:	PLATE#
Year:	1988
Trans2 State ID:	57745GD
Generator Ship Date:	880121
Trans1 Recv Date:	880121
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880121
Part A Recv Date:	880127
Part B Recv Date:	880205
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

TSDF ID 1:	NYD000824334
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00825
Units:	Gallons (liquids only)
Number of Containers:	015
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NYA6458454
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	PLATE#
Year:	1988
Trans2 State ID:	MY7783
Generator Ship Date:	880603
Trans1 Recv Date:	880603
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880603
Part A Recv Date:	880609
Part B Recv Date:	880628
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000824334
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01375
Units:	Gallons (liquids only)
Number of Containers:	025
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYO3024522
Manifest Status:	C - Completed copy
Trans1 State ID:	Not reported
Year:	1984
Trans2 State ID:	Not reported
Generator Ship Date:	840209
Trans1 Recv Date:	840209
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	840209
Part A Recv Date:	840221
Part B Recv Date:	840227
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000824334
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00550
Units:	Gallons (liquids only)
Number of Containers:	010
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA2143602
Manifest Status:	C - Completed copy
Trans1 State ID:	Not reported
Year:	1985
Trans2 State ID:	Not reported
Generator Ship Date:	850208
Trans1 Recv Date:	850208
Trans2 Recv Date:	850208
TSD Site Recv Date:	850208
Part A Recv Date:	850211
Part B Recv Date:	850220
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000824334
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00825
Units:	Gallons (liquids only)
Number of Containers:	015
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYA6272739
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	Not reported
Year:	1987
Trans2 State ID:	9082GF
Generator Ship Date:	870807
Trans1 Recv Date:	870807
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870807
Part A Recv Date:	870911
Part B Recv Date:	870901
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NYD000824334
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000824334
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00495
Units:	Gallons (liquids only)

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Number of Containers:	009
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NJA0253900
Manifest Status:	C - Completed copy
Trans1 State ID:	DECAL#201
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	861229
Trans1 Recv Date:	861229
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861229
Part A Recv Date:	870106
Part B Recv Date:	870107
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01750
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NJA0182502
Manifest Status:	C - Completed copy
Trans1 State ID:	NJDEPDECA
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	860520
Trans1 Recv Date:	860520
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860520
Part A Recv Date:	860523
Part B Recv Date:	860528

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01174
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	100

Document ID:	NJA0288444
Manifest Status:	C - Completed copy
Trans1 State ID:	NJDEPS-10
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870224
Trans1 Recv Date:	870224
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870225
Part A Recv Date:	870306
Part B Recv Date:	870305
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00770
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	05/23/2018
Trans1 Recv Date:	05/23/2018
Trans2 Recv Date:	05/24/2018
TSD Site Recv Date:	05/25/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	009419823FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Arsenic
Waste Code c:	Lead
Waste Code e:	Selenium
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1600
Units:	Pounds
Number of Containers:	4

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	05/23/2018
Trans1 Recv Date:	05/23/2018
Trans2 Recv Date:	05/24/2018
TSD Site Recv Date:	05/25/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001303205
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	009419823FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Lead
Waste Code c:	Selenium
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **S121488958**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
80 additional NY MANIFEST: record(s) in the EDR Site Report.

AJ253 **INDUSTRIAL FINISHINGS PROD. INC.** **NY CBS** **S109205829**
ESE **465 LOGAN ST** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11208** **NY MANIFEST**
0.249 mi.
1315 ft. **Site 4 of 6 in cluster AJ**

Relative:
Lower

Actual:
23 ft.

CBS:

Name:	INDUSTRIAL FINISHINGS PROD. INC.
Address:	465 LOGAN ST
City,State,Zip:	BROOKLYN, NY 11208
CBS Number:	2-000162
Program Type:	CBS
Facility Status:	Active
Expiration Date:	02/11/2025
Dec Region:	2
UTMX:	594993.31317
UTMY:	4503241.02420

SPILLS:

Name:	IEP
Address:	465 LOGAN
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0803772 / 2008-07-24
Facility ID:	0803772
Facility Type:	ER
DER Facility ID:	349830
Site ID:	400556
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2008-06-30
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2008-06-30
CID:	81
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **S109205829**

Remediation Phase:	0
Date Entered In Computer:	2008-07-01
Spill Record Last Update:	2008-07-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SIBAN ANTHONY
Latitude:	40.6747620
Longitude:	-73.8760940
DEC Memo:	06/30/08-Zhune spoke to Mr. Anthony from NYC DEP Hazmat (646) 584-4925. He said the roof from a Wood and Metal finishing company located at 465 Logan Ave, Brooklyn NY. collapse. The water pipes broke. There are a shine of oil on the surface of the water and strong petroleum odors outside the building. I responded to this site. I could not get inside the building. The owner Mr. Gus Cristodero (917) 270-3425 told me odors came from lacquer thinner that they use to manufacture products for wood. The oil tanks are underground tanks and nothing happened in that area. As per Randy this spill is closed and refered to DEP Hazmat 07/08/08-Zhune spoke to Sandy from Industrial Finishing Products Inc. (718) 277-3333. She said spill was cleaned up by staff from the company. She will send papers. 07/24/08 Industrial Finishing Products, Inc. sent the report 07/8/08. Due to a roofing collapse on june 30th and substantial exposure of materials we carry, we were charged with the task of either cleaning up the hazardous fluids ourselves or outsourcing it to a cleanup company. We took the initiative in cleaning up ourselves and have successfully completed the undertaking. To date, we have pumped out all of the hazardous fluids, containerized them and had them transported and disposed of by a hazardous waste disposal company, Action Environmental Group. We have secured the building by repairing the roof and creating a scaffold around its entirety thereby ensuring the safety of pedestrians as well as our employes. Spill Closed
Remarks:	roof collapse Products outside are wood finishing products, also stored inside. All crews are un scene.

All Materials:

Site ID:	400556
Operable Unit ID:	1157376
Operable Unit:	01
Material ID:	2148396
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **S109205829**

NY MANIFEST:

EPA ID:	NYP010000511
Country:	USA
Name:	Nycdep
Address:	465 LOGAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	465 LOGAN ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycdep
Mailing Contact:	Paul Wonk
Mailing Address 1:	59-17 JUNCTION BLV
Mailing Address 2:	Not reported
Mailing City,State,Zip:	FLUSHING, NY 11373
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185954681

Manifest Data:

Document ID:	NYB2198394
Manifest Status:	Not reported
Trans1 State ID:	PC43137NY
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/1991
Trans1 Recv Date:	08/05/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/06/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP010000511
Trans1 EPA ID:	NYD049178296
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049178296
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported

DRAFT

INDUSTRIAL FINISHINGS PROD. INC. (Continued) **S109205829**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00800
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

AJ254 **INDUSTRIAL FINISHING PRODUCTS** **RCRA-LQG** **1000428069**
ESE **465 LOGAN ST** **ICIS** **NYD001303205**
1/8-1/4 **BROOKLYN, NY 11208** **US AIRS**
0.249 mi. **FINDS**
1315 ft. **Site 5 of 6 in cluster AJ** **ECHO**
E MANIFEST

Relative:
Lower

Actual:
23 ft.

RCRA Listings:

Date Form Received by Agency:	20160922
Handler Name:	Industrial Finishing Products
Handler Address:	Logan St
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYD001303205
Contact Name:	SANDRA JAGARNAUTH
Contact Address:	LOGAN ST
Contact City,State,Zip:	BROOKLYN, NY 11208
Contact Telephone:	718-277-3333
Contact Fax:	718-827-6321
Contact Email:	Not reported
Contact Title:	OFFICE MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	LOGAN ST
Mailing City,State,Zip:	BROOKLYN, NY 11208
Owner Name: Stephen Galgano	
Owner Type:	Private
Operator Name: Stephen Galgano	
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: K078
Waste Description: Not Defined

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U107
Waste Description: 1,2-Benzenedicarboxylic Acid, Dioctyl Ester (Or) Di-N-Octyl Phthalate

Waste Code: U112
Waste Description: Acetic Acid, Ethyl Ester (I) (Or) Ethyl Acetate (I)

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U161
Waste Description: 4-Methyl-2-Pentanone (I) (Or) Methyl Isobutyl Ketone (I) (Or) Pentanol, 4-Methyl-

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: STEPHEN GALGANO
Legal Status: Private

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Date Became Current:	19560101
Date Ended Current:	Not reported
Owner/Operator Address:	465 LOGAN ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11208
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: 40 ANDREW GALGANO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	403 GARFIELD AVE
Owner/Operator City,State,Zip:	WEST HEMPSTEAD, NY 11552
Owner/Operator Telephone:	516-486-6366
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: STEPHEN GALGANO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	96 MCCOUNS LANE
Owner/Operator City,State,Zip:	OPERCITY, NY 99999
Owner/Operator Telephone:	516-671-8721
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: STEPHEN GALGANO	
Legal Status:	Private
Date Became Current:	19560101
Date Ended Current:	Not reported
Owner/Operator Address:	465 LOGAN ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11208
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: 40 ANDREW GALGANO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	403 GARFIELD AVE
Owner/Operator City,State,Zip:	WEST HEMPSTEAD, NY 11552
Owner/Operator Telephone:	516-486-6366
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Owner/Operator Indicator: Operator
Owner/Operator Name: STEPHEN GALGANO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 96 MCCOUNS LANE
Owner/Operator City,State,Zip: OPERCITY, NY 99999
Owner/Operator Telephone: 516-671-8721
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19801119
Handler Name: INDUSTRIAL FINISHING PROD INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160922
Handler Name: INDUSTRIAL FINISHING PRODUCTS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990708
Handler Name: INDUSTRIAL FINISHING PROD INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: INDUSTRIAL FINISHING PROD INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: INDUSTRIAL FINISHING PROD INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800815
Handler Name: INDUSTRIAL FINISHING PROD INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: INDUSTRIAL FINISHING PRODUCTS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920131
Handler Name: INDUSTRIAL FINISHING PRODUCTS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940420
Handler Name: INDUSTRIAL FINISHING PRODUCTS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32551
NAICS Description: Paint And Coating Manufacturing

NAICS Code: 42295
NAICS Description: Paint, Varnish, And Supplies Wholesalers

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19950913
Actual Return to Compliance Date:	19960716
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19960217
Enforcement Identifier:	000
Date of Enforcement Action:	19960202
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19950913
Actual Return to Compliance Date: 19960716
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19950913
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	19950913
Actual Return to Compliance Date:	19960716
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19960217
Enforcement Identifier:	000
Date of Enforcement Action:	19960202
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	19950913
Actual Return to Compliance Date:	19960716
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	000
Date of Enforcement Action:	19950913
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NY

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 19950913
Actual Return to Compliance Date: 19960716
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19960217
Enforcement Identifier: 000
Date of Enforcement Action: 19960202
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 19950913
Actual Return to Compliance Date: 19960716
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19950913
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19930811
Actual Return to Compliance Date: 19951122
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: 19930911
Enforcement Identifier: 000
Date of Enforcement Action: 19951122
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Ii-Rcra-0217
Enforcement Attorney: R2

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: R2LG
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 5000
Paid Amount: Not reported
Final Count: 1
Final Amount: 5000

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19930811
Actual Return to Compliance Date: 19951122
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19940929
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Ii-Ust-94-0217
Enforcement Attorney: R2
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R2LG
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Proposed Amount:	59627
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19850418
Actual Return to Compliance Date: 19860617
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19851005
Enforcement Identifier: 001
Date of Enforcement Action: 19850905
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20150922
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19951122
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	NO LONGER A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19950808
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19960716
Scheduled Compliance Date:	19960217
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19950808
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19960716
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Former Citation:	Not reported
Evaluation Date:	19950808
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19960716
Scheduled Compliance Date:	19960217
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19950808
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19960716
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19950808
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19960716
Scheduled Compliance Date:	19960217
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19950808
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19960716
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19930811
Evaluation Responsible Agency:	EPA
Found Violation:	Yes

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2LG2
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19951122
Scheduled Compliance Date:	19930911
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19930811
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2LG2
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19951122
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19930811
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850702
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850418
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860617
Scheduled Compliance Date:	19851005

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ICIS:

Enforcement Action ID:	02-1994-0268
FRS ID:	110000323310
Action Name:	INDUSTRIAL FINISHING PRODUCTS, INC.
Facility Name:	INDUSTRIAL FINISHING PRODUCTS INCORPORATED
Facility Address:	465 LOGAN ST. BROOKLYN, NY 11208
Enforcement Action Type:	RCRA 9006 AO For Comp And/Or Pen (UST)
Facility County:	KINGS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	9006
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.674753
Longitude in Decimal Degrees:	-73.876184
Permit Type Desc:	Not reported
Program System Acronym:	21382
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	INDUSTRIAL FINISHING PRODUCTS
Address:	465 LOGAN STREET
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	Not reported

Facility Name:	INDUSTRIAL FINISHING PRODUCTS
Address:	465 LOGAN STREET
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	Not reported

Facility Name:	INDUSTRIAL FINISHING PRODUCTS
Address:	465 LOGAN STREET
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: INDUSTRIAL FINISHING PRODUCTS
Address: 465 LOGAN STREET
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: Not reported

US AIRS MINOR:
Envid: 1000428069
Region Code: 02
Programmatic ID: AIR NY0000002610500272
Facility Registry ID: 110000323310
D and B Number: Not reported
Primary SIC Code: 2865
NAICS Code: 325510
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610500272
Facility Registry ID: 110000323310
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1982-02-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500272
Facility Registry ID: 110000323310
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-12-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110000323310

Click Here for FRS Facility Detail Report:

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Environmental Interest/Information System:
The National Compliance Database (NCDB) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA).
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
THE EMISSION INVENTORY SYSTEM (EIS) MAINTAINS AN INVENTORY OF LARGE STATIONARY SOURCES AND VOLUNTARILY-REPORTED SMALLER SOURCES OF AIR POINT POLLUTANT EMITTERS. IT CONTAINS INFORMATION ABOUT FACILITY SITES AND THEIR PHYSICAL LOCATION, EMISSIONS UNITS, EMISSIONS PROCESSES, RELEASE POINTS, CONTROL APPROACHES, AND REGULATIONS. FACILITY INVENTORY DATA ARE KEPT SEPARATE FROM THE EMISSIONS DATA AND HAVE STABLE IDENTIFIERS TO IMPROVE CONTINUITY FROM YEAR TO YEAR AND TO HELP IDENTIFY DUPLICATE OR MISSING FACILITIES
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Toxic Release Inventory System (TRIS) is a publicly available EPA database reported annually by certain covered industry groups, as well as federal facilities. It contains information about more than 650 toxic chemicals that are being used, manufactured, treated, transported, or released into the environment, and includes information about waste management and pollution prevention activities.
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters,

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000428069
Registry ID:	110000323310
DFR URL:	
Name:	INDUSTRIAL FINISHING PRODS INC
Address:	465 Logan Street
City,State,Zip:	BROOKLYN, NY 11208

E MANIFEST:

Manifest Tracking Number:	009424947FLE
Last Updated Date:	20180814
Shipped Date:	20180725
Received Date:	20180730
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD001303205
Generator Name:	Industrial Finishing Products
Generator Location Street Number:	Not reported
Generator Location Street 1:	465 LOGAN ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208-2519
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	465 LOGAN ST
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11208-2519
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Veolia Es Technical Solutions Llc
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1 EDEN LANE
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	1 EDEN LANE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	009424988FLE
Last Updated Date:	20180823

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Shipped Date:	20180815
Received Date:	20180817
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD001303205
Generator Name:	Industrial Finishing Products
Generator Location Street Number:	Not reported
Generator Location Street 1:	465 LOGAN ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11208-2519
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	465 LOGAN ST
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11208-2519
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Veolia Es Technical Solutions Llc
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1 EDEN LANE
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	1 EDEN LANE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	009424988FLE
Transporter Line Number:	1
Transporter EPA ID:	NYD064748304
Transporter Name:	Action Trucking
Manifest Tracking Number:	009424988FLE
Transporter Line Number:	2
Transporter EPA ID:	NJD080631369
Transporter Name:	Veolia Es Technical Solutions

Waste Line:

Manifest Tracking Number:	009424988FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263, Waste Paint Related Material, 3, Ii, Rq (D001)
Non-Hazardous Waste Description:	Not reported

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	400
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.2
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2
Waste Quantity, in Kilograms:	181.406
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	181.406
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D008, D010, F003, F005
Quantity Haz Kg:	181.406
Quantity Haz Tons:	0.2
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B

Manifest Tracking Number:	009424988FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3175
U.S. DOT Description:	Un3175, Waste Solids Containing Flammable Liquid, N.O.S., (Acetone, Methyl Ethyl Ketone), 4.1, Ii, Rq (D001)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	4
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	1600
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.8
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.8
Waste Quantity, in Kilograms:	725.624
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	725.624
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N

DRAFT

INDUSTRIAL FINISHING PRODUCTS (Continued) **1000428069**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D004, D008, D010, D035, F003, F005
Quantity Haz Kg:	725.624
Quantity Haz Tons:	0.8
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B

AK255 **CONSOLIDATED EDISON** **NY Spills** **S102239118**
WNW **2950 ATLANTIC AVE** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.250 mi.
1319 ft. **Site 1 of 8 in cluster AK**

Relative:
Higher

Actual:
33 ft.

SPILLS:

Name:	ATLANTIC AVE SERVICE CNTR
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9806522 / Not Reported
Facility ID:	9806522
Facility Type:	ER
DER Facility ID:	324772
Site ID:	81585
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1998-08-26
Investigator:	GHPRATT
Referred To:	Not reported
Reported to Dept:	1998-08-26
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	1998-08-26
Spill Record Last Update:	2024-01-02
Spiller Name:	FRANK MASSERIA
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Spiller Company: 001
Contact Name: FRANK MASSERIA
Latitude: 40.6776368
Longitude: -73.8853372
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 8/27/98: site visit with Joe Floryshak and Ken Twomey (Con Ed). 2 x 2000 gallon gasoline USTs and 1 x 275 gallon hydraulic oil tank. When they were pulling the tanks out of ground they noted gasoline odors. Hole is visually contaminated - soil is still being excavated. Requested 2 additional monitoring wells be installed - one north, one west of excavation. They will excavate to concrete slab to collect soil samples. (JHO) 2/23/00: Jacques Whitford Corp. (JWC) notes approx. 0.14 feet of gasoline in well MW-1A. Passive product recovery initialted (sorbent sock deployed in well). (JHO) 6/15/00: Con Ed submits site investigation work plan to characterize site. Proposal calls for installation of 8 soil borings and 4 new wells around former tank area. Work plan approved in letter dated 6/21/00. Site investigation activities commence in late July 2000. (JHO) 4/23/01: Site investigation report submitted. Findings indicate that in addition to gasoline/diesel contamination associated with former tanks, the site is underlain by a former BUG (now KeySpan) manufactured gas plant. Comment letter on SIR sent to Con Ed 9/10/01. Request Con Ed submit proposal for additional remedial action. (KMF) 12/28/01: MGP site history report submitted by Con Ed. (KMF) 2/15/02: Supplemental site charaterization work plan submitted, which addresses some of the on-site former MGP structures. Comment letter sent to Con Ed 6/13/03. (KMF) ~~~~~~~~~~~~~~~~~~~ e2mis no. 119278: 8/26/98 STRONG ODOR OF GASOLINE OR DIESEL FLUID IN EXCAVATION 30'BY 15' BY OLD GAS PUMPS. SOIL ALSO LOOKS EFFECTED. D.E.C. JANE OCONNELY WAS ON LOCATION REQUESTED EXCAVATION BE SQUARED OFF & SAMPLED. 2/23/00 Jacques Whitford, a contractor for ConEd, reports that during a sampling event at 5:30, he encountered 0.14' of product material in monitoring well. Update 12-11-00 - Closure Report submitted to the DEC on 4/24/00. Draft Site Characterization plan submitted to the DEC on 6/09/00. Verbally approved by the DEC on 06/20/00. Nine borings and five monitoring wells were installed to evaluate the potential of soil and groundwater contamination in the vicinity of the former USTs. Five (5) of the boring locations were designated for well installation. The drilling occurred from July 24 to August 11, 2000. The analytical results indicated elevated BTEX concentrations, and to a lesser extent MTBE concentrations in the soil samples collected. With the exception of one boring (SB-6B), SVOC concentrations in soil for all boring locations were

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

relatively low. During the soil boring installation work, evidence of Manufacturing Gas Plant (MGP) residuals were encountered at the SB-6B location. The first round of groundwater sampling of the six monitoring wells was completed on August 29, 2000. The results indicated very high concentrations of MTBE and moderately high concentrations of BTEX in the wells. Relatively low levels of SVOCs were detected. A summary of the MTBE and BTEX concentrations for the groundwater sampling completed on August 29, 2000 is provided below: Well ID MTBE (ppb) BTEX (ppb) MW-1A 500,000 13,000 MW-2 37,000 660 MW-3 31,000 17,000 MW-4 6,300 ND MW-5 47,000 1,200 MW-6 100,000 8,500 A second round of groundwater sampling was completed during the week of October 30, 2000. Jacques Whitford Company (a contractor for Con Edison) is currently developing the site characterization report. The draft report is expected to be completed during the first quarter of 2001. 07/01/10 - Spill transferred to S. Deyette in Central Office. Telcon with J. Oconnell (R2) to discuss current status. Spoke with M. Gonzalez (CE PM) regarding transfer of spill. Discussed current groundwater monitoring and tentative start date of NG site characterization of MGP. 08/06/10 - The Second Quarter 2010 Groundwater Monitoring Report was received and is under review. (SD) 08/02/11 - The First Half 2011 Groundwater Monitroing report was submitted and approved. (SD) 05/12/12 - The September 2011 Report was reviewed and approved on May 2012. The next semi-annual report is expected in July 2012. (SD) 06/20/13 - The March 2012 and September 2012 reports were reviewed and accepted. No update to start of NG MGP Investigation. (SD) 09/18/13 - The March 2013 report was submitted and reviewed. Portions of the report were not included. CE was asked to revise and re-submit. (SD) 10/28/13 - CE submitted revised March 2013 report, which was subsequently approved. No update to the start of the NG MGP investigation. (SD) 02/13/2014 - CE submitted the September 2013 sampling report; no changes to sampling frequency or locations. (SD) 01/20/2015 - CE submitted the 2014 second half GW report for review.(SD) 02/25/2015 - The 2014 second half GW report was approved; there were no changes to sampling frequency or locations.(SD) 06/23/2015 - The 2015 first half GW report was received and is under review.(SD) 07/27/2015 - The 2015 First Half GW report was approved. The next sampling event is scheduled for September 2015.(SD) 04/04/2017 - The 2016 First Half GW report was approved. The second half sampling event occurred in the 4th Quarter of 2016; awaiting the report submittal.(SD) 09/18/2017 - The Second Half 2016 GW report was received and is under review. (SD) 12/17/2017 - The

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

May 2017 GW report was received and is under review. (SD) 03/19/2018 - The May 2017 GW Report was approved. (SD) 06/28/2018 - The Dec 2017 GW Report was received and is under review. (SD) 12/28/2018 - The June 2018 GW Report was received and is under review. (SD) 01/30/2019 - The December 2017 and June 2018 GW reports were approved. (SD) 07/15/2019 - The Second Half 2018 GW Report was reviewed and approved. (SD) 03/25/2020 - Conference call with R. Rosenbaum and N. O'Halloran regarding proposed ISCO remedy for spill source area. CE would concentrate on reducing the gasoline/diesel constituents rather than those related to the former MGP. A draft RAWP will be submitted in Q2/3 of 2020 for review. (SD) 12/17/2020 - The SA GW Monitoring report for June/July 2020 was approved. The draft UST ISCO RAWP was received on 12/15 and is under review. (SD) 01/20/2021 - The UST ISCO RAWP was approved on January 20. (SD) 10/13/2021 - Con Ed submitted schedule for ISCO injections: 10/29 through 11/19/21. 12/23/2021 - The June 2021 GW Report was approved. (SD) 06/15/2023 - The May 2022 SA GW Report was approved. Report showed some decreasing concentrations of BTEX constituents in UST area and down gradient, but mostly consistent with past sampling events. The second round of post-injection samples was to occur in November of 2022; report is pending. (SD)

Remarks: CON EDISON CLEVLAND STREET YARD THERE IS A STRONG ODOR IN AREA OF GASOLINE AND DIESEL. TANK EXCAVATION IN PROGRESS AT SITE.

All Materials:

Site ID:	81585
Operable Unit ID:	1064145
Operable Unit:	01
Material ID:	317675
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	81585
Operable Unit ID:	1064145
Operable Unit:	01
Material ID:	2237758
Material Code:	2645A
Material Name:	BTEX
Case No.:	Not reported
Material FA:	Oxygenates
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Site ID:	81585
Operable Unit ID:	1064145
Operable Unit:	01
Material ID:	573871
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

Site ID:	81585
Operable Unit ID:	1064145
Operable Unit:	01
Material ID:	317676
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Name:	I PT GASOLINE FROM VEH 41513
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0610593 / 2007-02-16
Facility ID:	0610593
Facility Type:	ER
DER Facility ID:	324772
Site ID:	375059
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-12-18
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-12-19
CID:	77
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-19
Spill Record Last Update:	2007-02-16
Spiller Name:	Not reported
Spiller Company:	CON EDISON 151710

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ERT DESK
Latitude:	40.6776010
Longitude:	-73.8854080
DEC Memo:	02/16/07 - See e-docs for Con Ed report detailing cleanup and closure. 203760. see eDocs
Remarks:	1 pint of gasoline spilled from veh #41513. in the yard. spill contained, clean-up schedule for 0500hrs. no to 5 questions. con ed ref # 203760.

All Materials:

Site ID:	375059
Operable Unit ID:	1132712
Operable Unit:	01
Material ID:	2122492
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CLEVELAND ST YARD
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0405593 / 2004-10-28
Facility ID:	0405593
Facility Type:	ER
DER Facility ID:	324772
Site ID:	81582
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-08-22
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-08-22
CID:	27
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-22
Spill Record Last Update:	2004-10-28
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Contact Name:	Not reported
Latitude:	40.6775990
Longitude:	-73.8854500
DEC Memo:	E2MIS NO 154999 T. KUSTERBECK FOUND 8 OZ. MOTOR OIL SPILLED ONTO ASPHALT SURFACE UNDER A TRUCK. SPILL CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. HE PLACED OIL ABSORBENT ON THE SPILL AND PUT ABSORBANT PADS (BALONEYS) AROUND IT. TRUCK MUST BE MOVED TO COMPLETE CLEANUP. KUSTERBECK REPORTS NO ONE FROM CONSTRUCTION IS AVAILABLE TO MOVE TRUCK AT THIS TIME ON SUNDAY . HE WILL NOTIFY CONSTRUCTION OF SPILL ON TOMORROW MORNING (MONDAY) AND CLEANUP WILL BE COMPLETED AT THAT TIME. IF NEEDED, VEHICLE WILL ALSO BE TURNED IN TO TRANSPORTATION FOR REPAIRS. 23-AUG-2004 0818 SSC SUPV. DENNIS JONES, EMP NO 28487 REPORTS SPILL WAS CLEANED USING ABSORB-ALL, DEBRIS BAGGED, AND DISPOSED OF IN PROPER CONTAINERS.. CLEANUP IS 100%. VEHICLE NO. 60438 HAS BEEN TURNED IN FOR REPAIR TO TRANSPORTATION.
Remarks:	Caller reports an oil leak from a dump truck #c60458. Spill is contained and will be cleaned up tomorrow by Con ED employees. Total spill was 8 oz. onto pavement. No to the 5 questions.

All Materials:

Site ID:	81582
Operable Unit ID:	889140
Operable Unit:	01
Material ID:	486365
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CLEVELAND ST YARD
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9514626 / 1998-03-30
Facility ID:	9514626
Facility Type:	ER
DER Facility ID:	324772
Site ID:	81583
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-02-15
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	351
Water Affected:	Not reported
Spill Source:	Unknown

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	1998-03-30
Spiller Name:	LISA PRIMEGGIA
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	LISA PRIMEGGIA
Latitude:	40.6776368
Longitude:	-73.8853372
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL
Remarks:	pulled truck out this morning and found material on ground - truck was checked and was not leaking - unknown where it came from

All Materials:

Site ID:	81583
Operable Unit ID:	1029173
Operable Unit:	01
Material ID:	354753
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ATLANTIC AVE SERVICE CTR
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9609446 / 2004-09-02
Facility ID:	9609446
Facility Type:	ER
DER Facility ID:	324772
Site ID:	81584
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1996-10-28
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-10-29
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-29
Spill Record Last Update:	2004-09-02
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	128 WEST END AVENUE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6776368
Longitude:	-73.8853372
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT see spill #9806522
Remarks:	fuel tank discrepancy - tank #2

All Materials:

Site ID:	81584
Operable Unit ID:	1037514
Operable Unit:	01
Material ID:	345171
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	80.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CLEVELAND YARD
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0206914 / 2002-10-08
Facility ID:	0206914
Facility Type:	ER
DER Facility ID:	324772
Site ID:	180783
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-10-04
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2002-10-04
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Date Entered In Computer:	2002-10-04
Spill Record Last Update:	2002-10-08
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6776368
Longitude:	-73.8853372
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #145412: 10/4/02 - 0913hrs - Peter Pitzer # 39376 OS FOD reports he found 16 oz of antifreeze leaked from Truck # 40941 onto asphalt in Cleveland Yard. States spill has been contained with diapers, bolognies and oil absorb. Transportation has been contacted to make repairs to vehicle. Cannot make repairs at this time. Vehicle is still leaking antifreeze onto diapers at a rate of 1 drop per minute. Clean up will proceed once truck has been moved. Advised as of 2 hrs timeframe. UPDATE 10/06/02 17:00 HRS. PER P.PITZER ON FRIDAY 10/4 10:30 HRS VEHICLE WAS MOVE TO TRANSPORTATION AND LEAK REPAIRED. AS OF 10:50 HRS CLEAN UP COMP USING DIAPERS, AND ABSORBANT.
Remarks:	16 OUNCES - TRUCK 40941 - STILL LEAKING AT 1 DROP PER MIN ONTO ABSORBANTS - REF #145412 - ORIGINAL LEAK TO ASPHAULT

All Materials:

Site ID:	180783
Operable Unit ID:	858664
Operable Unit:	01
Material ID:	517505
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CLEVELAND STREET YARD
Address:	2950 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1101622 / 2011-10-28
Facility ID:	1101622
Facility Type:	ER
DER Facility ID:	403698
Site ID:	449086
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-05-13
Investigator:	RWAUSTIN
Referred To:	Not reported

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Reported to Dept:	2011-05-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-05-13
Spill Record Last Update:	2011-10-28
Spiller Name:	ERT
Spiller Company:	CONEDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT
Latitude:	40.6776010
Longitude:	-73.8854080
DEC Memo:	5/13/11-HRAHMED- As per EMIS report, ConEd persionnel used diapers and kitty litter to contain leak from entering any sewer or waterways. Lamy reports brand new overhead Transformer is leaking from one of the top leads. Leak is starting to slow down reporting about 4 gallons total at this time. Env.ops has been dispatched and cig has been notified. Spoke to ConEd ERT desk. As per the desk, the leak has been stopped and the spill has been cleaned up. He mensioned that they reported the spill cause they couldnot clean it within 2 hours. Case assigned to Feroze Mohammad for routine closure. 10/28/11 - Austin - Approx. 4 gals. dielectric fluid spilled - Truck and pavement cleaned - Con Ed contained and cleaned up spill - See eDocs for additional info. in documents submitted - Spill closed - end
Remarks:	New transformer is leaking on the truck and the ground. Leak rate is 10z. per few mintues. Clean up is pending crew.

All Materials:

Site ID:	449086
Operable Unit ID:	1199307
Operable Unit:	01
Material ID:	2195676
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYD982273831

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Country:	USA
Name:	Consolidated Edison
Address:	2950 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	2950 ATLANTIC AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	NYG0260028
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/21/1997
Trans1 Recv Date:	01/21/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/21/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982273831
Trans1 EPA ID:	CTD983883745
Trans2 EPA ID:	Not reported
TSDF ID 1:	NY0000343889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Mercury
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00098
Units:	Pounds
Number of Containers:	007
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYG0260055
Manifest Status:	Not reported
Trans1 State ID:	H10202
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/23/1997
Trans1 Recv Date:	01/23/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982273831
Trans1 EPA ID:	CTD983883745
Trans2 EPA ID:	Not reported
TSDF ID 1:	NY0000343889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Mercury
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00075
Units:	Pounds
Number of Containers:	006
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	MAG2624850
Manifest Status:	Not reported
Trans1 State ID:	970642MA
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/1992
Trans1 Recv Date:	11/04/1992

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982273831
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	MAH7043670
Manifest Status:	Not reported
Trans1 State ID:	100E30MD
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/1994
Trans1 Recv Date:	10/14/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982273831
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	MAH2668000
Manifest Status:	Not reported
Trans1 State ID:	MD102E84
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1993
Trans1 Recv Date:	10/12/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/13/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982273831
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn

DRAFT

CONSOLIDATED EDISON (Continued) **S102239118**

Specific Gravity: 01.00

AK256 **ATLANTIC AVE. SERVICE CENTER** **NY UST** **U004198785**
WNW **2950 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.250 mi.
1319 ft. **Site 2 of 8 in cluster AK**

Relative:
Higher

Actual:
33 ft.

UST:

Name:	ATLANTIC AVE. SERVICE CENTER
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-452718 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	594192.76576
UTM Y:	4503511.54092
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	G01
Tank ID:	35556
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1981
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	14
Date Test:	09/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Tank Number:	G02
Tank ID:	35557
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1981
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	14
Date Test:	09/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

DRAFT

AK257 **CON EDISON - CLEVELAND SERVICE CENTER** **RCRA-LQG** **1000111682**
WNW **2950 ATLANTIC AVE** **FINDS** **NYD982272841**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.250 mi. **E MANIFEST**
1319 ft. **Site 3 of 8 in cluster AK** **NY MANIFEST**

Relative: **Higher**
Actual: **33 ft.**

RCRA Listings:

Date Form Received by Agency:	20100323
Handler Name:	Con Edison - Cleveland Service Center
Handler Address:	Atlantic Ave
Handler City,State,Zip:	BROOKLYN, NY 11207-2731
EPA ID:	NYD982272841
Contact Name:	FRANKLIN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F002

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: X002
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19610717
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19610717
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19610717
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19610717
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-3968
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19610717
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19610717
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20060101

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20100323
Handler Name: CON EDISON - CLEVELAND SERVICE CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060220
Handler Name: CON EDISON - CLEVELAND SERVICE CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CON EDISON - CLEVELAND SERVICE CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970815
Handler Name: CON EDISON - CLEVELAND STREET
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960329
Handler Name: CON EDISON-CLEVELAND ST SERVICE CTR
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED-CLEVELAND STREET SERVICE CTR
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040225
Handler Name: CON EDISON - CLEVELAND SERVICE CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - CLEVELAND SERVICE CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

NAICS Code: 221122
NAICS Description: Electric Power Distribution

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20090820
Actual Return to Compliance Date: 20091008
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090917
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20091020
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSAN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20090820
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20091008
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20031210
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

FINDS:
Registry ID: 110009474595

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000111682
Registry ID: 110009474595

DFR URL:
Name: CON EDISON - CLEVELAND SERVICE CENTER
Address: 2950 Atlantic Ave
City,State,Zip: BROOKLYN, NY 11207

E MANIFEST:

Manifest Tracking Number:	008168823FLE
Last Updated Date:	20191030
Shipped Date:	20190109
Received Date:	20190110
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYD982272841
Generator Name:	Con Edison - Cleveland Service Center
Generator Location Street Number:	Not reported
Generator Location Street 1:	2950 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207-2731
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	4 IRVING PLACE
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10003
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NYD980593636
Designated Facility Name:	Con Edison - Astoria
Designated Facility Mail Street Number:	Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4 IRVING PLACE, 15TH FL NE
Designated Facility Mail City:	NEW YORK
Designated Facility Mail Zip:	10003
Designated Facility Mail State:	NY
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	31-01 20TH AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	LONG ISLAND CITY
Designated Facility Location Zip:	11105-2048
Designated Facility Location State:	NY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	008168823FLE
Transporter Line Number:	1
Transporter EPA ID:	NYD006982359
Transporter Name:	Con Edison - Corporate Headquarters - 4

Waste Line:

Manifest Tracking Number:	008168823FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid, N.O.S., 9, Pg Iii (Benzene) C00071
Non-Hazardous Waste Description:	Not reported
Number of Containers:	4
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	220
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.9174312
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.9174312
Waste Quantity, in Kilograms:	832.13763
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	832.13763
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Federal Waste Codes:	D018
Quantity Haz Kg:	832.13763
Quantity Haz Tons:	0.9174312
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B

NY MANIFEST:

EPA ID:	NYD982272841
Country:	USA
Name:	Consolidated Edison
Address:	2950 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207-0000
Zip 4:	Not reported
Location Address 1:	2950 ATLANTIC AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	2731
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	NYA8779735
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	Not reported
Year:	1988
Trans2 State ID:	79026GR
Generator Ship Date:	880617
Trans1 Recv Date:	880617
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880617
Part A Recv Date:	880809
Part B Recv Date:	880628
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYC1832477
Manifest Status:	Not reported
Trans1 State ID:	JU4819
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	08/26/1992
Trans1 Recv Date:	08/26/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/26/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Specific Gravity: 01.00
Waste Code 7: Ignitable Waste
Waste Code 8: Not reported
Waste Code: Not reported
Waste Code 10: Not reported
Waste Code 11: Not reported
Quantity: 00027
Units: Pounds
Number of Containers: 001
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYB7573437
Manifest Status: Not reported
Trans1 State ID: 40137K
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 04/03/1997
Trans1 Recv Date: 04/03/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/07/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982272841
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B007
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00375
Units: Kilograms
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Landfill
Specific Gravity: 01.00

Document ID: NYB7573446
Manifest Status: Not reported
Trans1 State ID: 701496

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/1997
Trans1 Recv Date:	03/25/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00400
Units:	Kilograms
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB7574013
Manifest Status:	Not reported
Trans1 State ID:	53576V
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	02/04/1997
Trans1 Recv Date:	02/04/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/04/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00189
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYB7574049
Manifest Status:	Not reported
Trans1 State ID:	70148G
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	02/14/1997
Trans1 Recv Date:	02/14/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/14/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00550

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Units:	Kilograms
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB7574571
Manifest Status:	Not reported
Trans1 State ID:	535770
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/09/1997
Trans1 Recv Date:	01/09/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/09/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00650
Units:	Kilograms
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00
Waste Code 7:	B002
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00189
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Document ID:	NYB7574589
Manifest Status:	Not reported
Trans1 State ID:	70076G
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1997
Trans1 Recv Date:	01/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01200
Units:	Kilograms
Number of Containers:	006
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB7574616
Manifest Status:	Not reported
Trans1 State ID:	40137K
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	02/21/1997
Trans1 Recv Date:	02/21/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/21/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00300
Units:	Kilograms
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB7574634
Manifest Status:	Not reported
Trans1 State ID:	40137K
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/1997
Trans1 Recv Date:	03/07/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/07/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

DRAFT

CON EDISON - CLEVELAND SERVICE CENTER (Continued) **1000111682**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00525
Units:	Kilograms
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB7588584
Manifest Status:	Not reported
Trans1 State ID:	53576U
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	06/04/1997
Trans1 Recv Date:	06/04/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/04/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982272841
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
404 additional NY MANIFEST: record(s) in the EDR Site Report.

DRAFT

AK258 **CON ED MH 64858** **RCRA NonGen / NLR** **1007206752**
WNW **2950 ATLANTIC AVE** **NY MANIFEST** **NYP004015509**
1/8-1/4 **BROOKLYN, NY 11230**
0.250 mi.
1319 ft. **Site 4 of 8 in cluster AK**

Relative: **Higher**
Actual: **33 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed Mh 64858
Handler Address:	Atlantic Ave
Handler City,State,Zip:	BROOKLYN, NY 11230-0000
EPA ID:	NYP004015509
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

DRAFT

CON ED MH 64858 (Continued) **1007206752**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250522
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - M/H 64858	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED MH 64858	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	19980226
Handler Name: CON ED - M/H 64858	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

DRAFT

CON ED MH 64858 (Continued) **1007206752**

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004015509
Country: USA
Name: Consolidated Edison
Address: CLEVELAND ST YARD
Address 2: 2950 ATLANTIC
City,State,Zip: BROOKLYN, NY 11230-0000
Zip 4: Not reported
Location Address 1: V 3325 - 136 MACDOUGAL ST
Location Address 2: Not reported
Location City,State,Zip: QUEENS, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYE0051118
Manifest Status: Not reported
Trans1 State ID: SM1563
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 12/12/1997
Trans1 Recv Date: 12/12/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/12/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004015509
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported

DRAFT

CON ED MH 64858 (Continued) **1007206752**

TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 01309
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYE0217304
Manifest Status: Not reported
Trans1 State ID: GX32186
Year: 1998
Trans2 State ID: Not reported
Generator Ship Date: 09/09/1998
Trans1 Recv Date: 09/09/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/09/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004015509
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported

DRAFT

CON ED MH 64858 (Continued) **1007206752**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01495
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

AK259 **ATLANTIC AVE. SERVICE CENTER** **NY AST** **A100382338**
WNW **2950 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.250 mi.
1319 ft. **Site 5 of 8 in cluster AK**

Relative:
Higher

Actual:
33 ft.

AST:

Name:	ATLANTIC AVE. SERVICE CENTER
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-452718
Program Type:	PBS
UTM X:	594192.76576
UTM Y:	4503511.54092
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	CLE-1
Tank Id:	50817
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1986
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/05/2012
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	F03
Tank Id:	43614
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron

DRAFT

ATLANTIC AVE. SERVICE CENTER (Continued) **A100382338**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1982
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/1996
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

AK260 **ATLANTIC AVE. SERVICE CENTER** **UST FINDER** **1028570578**
WNW **2950 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.250 mi.
1319 ft. **Site 6 of 8 in cluster AK**

Relative:
Higher

Actual:
33 ft.

UST FINDER:

Object ID:	295883
Facility ID:	NY19791
Name:	ATLANTIC AVE. SERVICE CENTER
Address:	2950 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	9777
Private Wells 1500ft:	18
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.885443
Y Coord:	40.677111
Latitude:	40.677111
Longitude:	-73.885443

UST FINDER:

Object ID:	1212381
Facility ID:	NY19791
Tank ID:	NY110585
Tank Status:	Closed

DRAFT

ATLANTIC AVE. SERVICE CENTER (Continued) **1028570578**

Installation Date:	1981/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1212382
Facility ID:	NY19791
Tank ID:	NY110586
Tank Status:	Closed
Installation Date:	1981/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported

AK261 **UNION STATION (CITIZENS BRANCH)** **EDR MGP** **1008407901**
WNW **ATLANTIC AVE., ASHFORD ST., LIBERTY AVE.** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.253 mi.
1334 ft. **Site 7 of 8 in cluster AK**

Relative: **Higher**
Actual: **34 ft.**

EDR MGP:
No additional information available

AK262 **K - UNION STATION HOLDER** **NY SHWS** **S109580117**
WNW **ATLANTIC AVE, ASHFORD ST, LIBERTY AVE** **NY BROWNFIELDS** **N/A**
1/4-1/2 **BROOKLYN, NY 11207** **NY MGP**
0.253 mi.
1336 ft. **Site 8 of 8 in cluster AK**

Relative: **Higher**
Actual: **34 ft.**

SHWS:

Name:	K - UNION STATION HOLDER
Address:	ATLANTIC AVE, ASHFORD ST, LIBERTY AVE
City,State,Zip:	BROOKLYN, NY 11207
Program:	HW
Site Code:	378991
Classification:	A
Region:	2
Acres:	1.300
HW Code:	224054
Record Add:	03/27/2007
Record Upd:	07/17/2024
Updated By:	GHPRATT

Site Description: Location: The Union Station Holder site is located in an urban area at 2940 Atlantic Avenue in Brooklyn, Kings County. The site is 1.3 acres in size. Site Features: The main site feature is a two-story brick building located in the northeast corner of the site. The rest of the site is covered in asphalt. Current Zoning and Land Use: The site is currently an active Con Edison Service Center, and is zoned for commercial use. The surrounding parcels are currently used for a combination of residential, commercial and manufacturing/industrial. The closest residential area is within 150 feet, due west of the

DRAFT

K - UNION STATION HOLDER (Continued) **S109580117**

site. Past Use of the Site: The first two gas holders (north and center) were constructed in approximately 1887. The center gas holder was dismantled in 1906, and the north gas holder was dismantled in 1908. The southern holder was constructed in 1908 and operated until approximately 1928, then dismantled around 1950. The site was used as a distribution facility. The Con Edison facility removed two underground storage tanks (USTs) in 1998, and as a result of the impacts found in groundwater and soil, a spill number was assigned (98-06522), and remains open. Site Geology and Hydrogeology: The site is underlain by artificial fill and glacial deposits (outwash sands and gravel). The outwash sand and gravel beneath the site consists of coarse to fine gravel with sand, and ranges from 2 to 250 feet in thickness. The depth to groundwater is approximately 25 to 30 feet below ground surface (bgs), and general flow direction is to the east-southeast.

Env Problem:	Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Based upon investigations completed to date, the primary contaminants of concern for the site are VOCs and SVOCs. There have been multiple spills at the site of petroleum products and one spill remains open, associated with the removal of two USTs in 1998. Soil - Total benzene, toluene, ethylbenzene, and xylene (BTEX) ranged from non-detect (ND) to 414 ppm. In addition to BTEX, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and naphthalene were detected at elevated levels, with Total VOC concentrations as high as 2092 ppm. SVOCs, in the form of polycyclic aromatic hydrocarbons (PAHs), were detected from ND to 928 ppm. Groundwater - Total VOC concentrations were found as high as 1879 ppb, mostly downgradient of the holders. Total PAH concentrations ranged from non-detect to 601 ppb. In 2019, several monitoring wells were sampled for PFAS and 1,4-dioxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 99.5 and 38 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. There were no soil vapor samples collected as part of this investigation.
Health Problem:	The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-20 14:17:00
Record Upd:	2013-10-29 11:19:00
Updated By:	ldennist
Own Op:	1
Sub Type:	E
Owner Name:	Raphael rosenbaum
Owner Company:	Consolidated Edison Company of NY, Inc.
Owner Address:	31-01 20th Avenue - Bldg 136, 2nd Flr

DRAFT

K - UNION STATION HOLDER (Continued) **S109580117**

Owner Addr2:	Not reported
Owner City,St,Zip:	long island city, NY 11105
Owner Country:	United States of America
HW Code:	224054
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	9806522
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2017-04-04 14:52:00
Record Updated:	2017-04-04 14:52:00
Updated By:	SXDEYETT

BROWNFIELDS:

Name:	K - UNION STATION HOLDER
Address:	ATLANTIC AVE, ASHFORD ST, LIBERTY AVE
City,State,Zip:	BROOKLYN, NY 11207
Program:	BCP
Site Code:	57390
Acres:	1.300
HW Code:	C224054
SWIS:	2401
Town:	New York City
Record Added Date:	04/30/2004
Record Updated Date:	12/07/2009
Update By:	MOBARRIE
Site Description:	See Site 224054
Env Problem:	Not reported
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	KEYSPAN
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	Unknown
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported

DRAFT

K - UNION STATION HOLDER (Continued) **S109580117**

Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

MGP:
Site ID: 224054
Name: K - UNION STATION HOLDER
Address: ATLANTIC AVE, ASHFORD ST, LIBERTY AVE
City,State,Zip: BROOKLYN, NY 11207
Region: 2
Class: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Swis Code: 2401
Town: New York City
Disp Start: Not reported
Disp Term: Not reported
Acres: 1.3
Fuse: Commercial
Description: Location: The Union Station Holder site is located in an urban area at 2940 Atlantic Avenue in Brooklyn, Kings County. The site is 1.3 acres in size. Site Features: The main site feature is a two-story brick building located in the northeast corner of the site. The rest of the site is covered in asphalt. Current Zoning and Land Use: The site is currently an active Con Edison Service Center, and is zoned for commercial use. The surrounding parcels are currently used for a combination of residential, commercial and manufacturing/industrial. The closest residential area is within 150 feet, due west of the site. Past Use of the Site: The first two gas holders (north and center) were constructed in approximately 1887. The center gas holder was dismantled in 1906, and the north gas holder was dismantled in 1908. The southern holder was constructed in 1908 and operated until approximately 1928, then dismantled around 1950. The site was used as a distribution facility. The Con Edison facility removed two underground storage tanks (USTs) in 1998, and as a result of the impacts found in groundwater and soil, a spill number was assigned (98-06522), and remains open. Site Geology and Hydrogeology: The site is underlain by artificial fill and glacial deposits (outwash sands and gravel). The outwash sand and gravel beneath the site consists of coarse to fine gravel with sand, and ranges from 2 to 250 feet in thickness. The depth to groundwater is approximately 25 to 30 feet below ground surface (bgs), and general flow direction is to the east-southeast.
Assess Env: Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Based upon investigations completed to date, the primary contaminants of concern for the site are VOCs and SVOCs. There have been multiple spills at the site of petroleum products and one spill remains open, associated with the removal of two USTs in 1998. Soil - Total benzene, toluene, ethylbenzene, and xylene (BTEX) ranged from non-detect (ND) to 414 ppm. In addition to BTEX, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and naphthalene were detected at elevated levels, with Total VOC concentrations as high as

DRAFT

K - UNION STATION HOLDER (Continued) **S109580117**

2092 ppm. SVOCs, in the form of polycyclic aromatic hydrocarbons (PAHs), were detected from ND to 928 ppm. Groundwater - Total VOC concentrations were found as high as 1879 ppb, mostly downgradient of the holders. Total PAH concentrations ranged from non-detect to 601 ppb. In 2019, several monitoring wells were sampled for PFAS and 1,4-dioxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 99.5 and 38 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. There were no soil vapor samples collected as part of this investigation.

Assess Doh: The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.

Latitude: 40.677222222
Longitude: -73.885555556

AJ263 **LOT 13,TAXBLOCK 4228** **NY VCP** **S118704081**
ESE **2602 PITKIN AVENUE** **NY E DESIGNATION** **N/A**
1/4-1/2 **BROOKLYN, NY 11208** **NY NYC LAND USE**
0.255 mi. **NY NYC OER**
1348 ft. **Site 6 of 6 in cluster AJ**

Relative: **Lower**
Actual: **24 ft.**

VCP NYC:

Project ID:	20TMP0583K,20EH-N133K,22CVCP019K
Name:	2602 PITKIN AVENUE
Address:	2602 PITKIN AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3042280013
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Closure
Latitude:	40.674799
Longitude:	-73.87605
Postcode:	5
Community Board:	42
Council District:	1194
Census Tract:	3094942
BIN:	3042280013
NTA:	East New York

E DESIGNATION:

Name:	LOT 13,TAXBLOCK 4228
Address:	2602 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	13
Tax Block:	4228
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation

DRAFT

LOT 13,TAXBLOCK 4228 (Continued) **S118704081**

Lot Remediation Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	2602 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6745924
Longitude:	-73.8758951
Type Of Ownership Code:	Not reported
Owner Name:	CONCERN LOGAN HOUSING DEVELOPMENT FUND C ORP.
Borough:	BK
Tax Block:	4228
Tax Lot:	13
Community District:	305
Census Tract 2020:	3119400
Census Block 2020:	31194001000
Census Tract 2010:	1194
Census Block 2010:	1000
School District:	19
City Council District:	42
Fire Company:	L107
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D6: Elevator Apartments - Fireproof With Stores
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	7200
Total Building Floor Area:	51916
Commercial Floor Area:	7516
Residential Floor Area:	44400
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	4702
Factory Floor Area:	2814
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	9.0000000
Residential Units:	66
Total Units:	68
Lot Frontage:	80.0000000

DRAFT

LOT 13,TAXBLOCK 4228 (Continued) **S118704081**

Lot Depth:	90.0000000
Building Frontage:	80.0000000
Building Depth:	72.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	194400.00000
Assessed Total Value:	550800.00000
Exempt Total Value:	0.00000
Year Built:	2023
Year Altered 1:	2022
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	7.21000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3042280013.00000000
Condominium Number:	Not reported
Census Tract 2:	1194
X Coordinate:	1018675
Y Coordinate:	185073
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 037
Tax Map #:	31307
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	2602 PITKIN AVENUE
Address:	2602 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.674799
Longitude:	-73.87605
OER Project Numbers:	20TMP0583K,20EH-N133K,22CVCP019K
BBL:	3042280013
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Closure

URL:

Postcode:	5
Community Board:	42
Council District:	1194
Census Tract:	3094942
BIN:	3042280013

DRAFT

LOT 13,TAXBLOCK 4228 (Continued) **S118704081**

NTA: East New York

264
NNW
1/4-1/2
0.268 mi.
1417 ft.

249 LINWOOD ST/BKLYN **NY LTANKS** **S100145922**
249 LINWOOD STREET **N/A**
NEW YORK CITY, NY

Relative:
Higher

Actual:
38 ft.

LTANKS:

Name:	249 LINWOOD ST/BKLYN
Address:	249 LINWOOD STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9000036 / 1995-06-07
Facility ID:	9000036
Site ID:	93305
Spill Date:	1990-04-02
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-06-07
SWIS:	2401
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	1990-04-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-05-09
Spill Record Last Update:	1995-06-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	249 LINWOOD STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	83651
Latitude:	40.6797480
Longitude:	-73.8835730
DEC Memo:	Not reported
Remarks:	CUSTOMER DISCOVERED PINHOLE LEAK IN TANK CALLED BAERENKLAU FOUND LEAK IN TANK, APPLIED SPEEDY DRY, MAGNETIC PATCHES.

All Materials:

Site ID:	93305
Operable Unit ID:	939252
Operable Unit:	01
Material ID:	557443
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

DRAFT

249 LINWOOD ST/BKLYN (Continued) **S100145922**

Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

AL265 **3294 ATLANTIC AVENUE** **NY VCP** **S131580663**
NNE **3192 ATLANTIC AVENUE** **NY NYC OER** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.273 mi.
1442 ft. **Site 1 of 2 in cluster AL**

Relative:
Higher

Actual:
38 ft.

VCP NYC:
Project ID: 19TMP1943K,19EHAN411K,20CVCP016K
Name: 3294 ATLANTIC AVENUE
Address: 3192 ATLANTIC AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 3041530040
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Site Management
Latitude: 40.679952
Longitude: -73.877619
Postcode: 5
Community Board: 37
Council District: 1192
Census Tract: Not reported
BIN: Not reported
NTA: East New York

NYC OER:
Name: 3294 ATLANTIC AVENUE
Address: 3192 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.679952
Longitude: -73.877619
OER Project Numbers: 19TMP1943K,19EHAN411K,20CVCP016K
BBL: 3041530040
OER Program: VCP (Enrolled), E/RD (Review)
Class: Completed (C)
Phase: Site Management

URL:
Postcode: 5
Community Board: 37
Council District: 1192
Census Tract: Not reported
BIN: Not reported
NTA: East New York

DRAFT

AL266 **3200 ATLANTIC AVENUE** **NY ENG CONTROLS** **S131595063**
NE **8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11208** **NY BROWNFIELDS**
0.287 mi. **NY NYC LAND USE**
1514 ft. **Site 2 of 2 in cluster AL**

Relative: **Higher**
Actual: **37 ft.**

ENG CONTROLS:

Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	579723
HW Code:	C224289
Control Code:	12
Control Type:	ENG
Date Record Added:	07/08/2024
Date Rec Updated:	01/24/2025
Updated By:	JSDONALD
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	c/o The Hudson Companies
Owner Addr2:	826 Broadway, 11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Hudson Logan Fountain LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Jericho 265 Logan Street Housing Development Fund
Owner Company:	Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address:	c/o The Jericho Project
Owner Addr2:	245 W. 29th Street, Suite 902
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	C224289
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2024000183696
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2024-08-14 12:58:00
Record Updated:	2024-08-14 12:58:00
Updated By:	JSDONALD

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Crossref ID:	C224289-03-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2025-01-03 08:26:00
Record Updated:	2025-01-03 08:26:00
Updated By:	JSDONALD
Crossref ID:	1806390
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 09:38:00
Record Updated:	2021-05-28 09:38:00
Updated By:	JHOCONNE
Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	579723
HW Code:	C224289
Control Code:	36
Control Type:	ENG
Date Record Added:	07/08/2024
Date Rec Updated:	01/24/2025
Updated By:	JSDONALD
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	c/o The Hudson Companies
Owner Addr2:	826 Broadway, 11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Hudson Logan Fountain LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Jericho 265 Logan Street Housing Development Fund
Owner Company:	Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address:	c/o The Jericho Project
Owner Addr2:	245 W. 29th Street, Suite 902
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	C224289
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,3,5-trimethylbenzene

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2024000183696
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2024-08-14 12:58:00
Record Updated:	2024-08-14 12:58:00
Updated By:	JSDONALD
Crossref ID:	C224289-03-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2025-01-03 08:26:00
Record Updated:	2025-01-03 08:26:00
Updated By:	JSDONALD
Crossref ID:	1806390
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 09:38:00
Record Updated:	2021-05-28 09:38:00
Updated By:	JHOCONNE

Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	579723
HW Code:	C224289
Control Code:	15
Control Type:	ENG
Date Record Added:	07/08/2024
Date Rec Updated:	01/24/2025
Updated By:	JSDONALD
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.

Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	c/o The Hudson Companies
Owner Addr2:	826 Broadway, 11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Hudson Logan Fountain LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Jericho 265 Logan Street Housing Development Fund
Owner Company:	Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address:	c/o The Jericho Project

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Owner Addr2:	245 W. 29th Street, Suite 902
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	C224289
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	n-propylbenzene

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2024000183696
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2024-08-14 12:58:00
Record Updated:	2024-08-14 12:58:00
Updated By:	JSDONALD
Crossref ID:	C224289-03-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2025-01-03 08:26:00
Record Updated:	2025-01-03 08:26:00
Updated By:	JSDONALD
Crossref ID:	1806390
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 09:38:00
Record Updated:	2021-05-28 09:38:00
Updated By:	JHOCONNE

Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	579723
HW Code:	C224289
Control Code:	35
Control Type:	ENG
Date Record Added:	07/08/2024
Date Rec Updated:	01/24/2025
Updated By:	JSDONALD
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair.

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

	Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	c/o The Hudson Companies
Owner Addr2:	826 Broadway, 11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Hudson Logan Fountain LLC
Owner Address:	826 Broadway

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Jericho 265 Logan Street Housing Development Fund
Owner Company:	Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address:	c/o The Jericho Project
Owner Addr2:	245 W. 29th Street, Suite 902
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	C224289
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzene

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2024000183696
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2024-08-14 12:58:00
Record Updated:	2024-08-14 12:58:00
Updated By:	JSDONALD
Crossref ID:	C224289-03-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2025-01-03 08:26:00
Record Updated:	2025-01-03 08:26:00
Updated By:	JSDONALD
Crossref ID:	1806390
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 09:38:00
Record Updated:	2021-05-28 09:38:00
Updated By:	JHOCONNE

INST CONTROL:

Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	579723
Control Name:	Environmental Easement
HW Code:	C224289
Control Code:	J
Control Type:	INST
Dt record added:	07/08/2024
Dt rec updated:	01/24/2025
Updated By:	JSDONALD
Site Code:	579723
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-01-30 14:10:00
Record Upd: 2025-01-15 13:39:00
Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: O&M Plan
HW Code: C224289
Control Code: 33
Control Type: INST
Dt record added: 07/08/2024

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Dt rec updated:	01/24/2025
Updated By:	JSDONALD
Site Code:	579723
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11207
Owner Country:	United States of America

3200 ATLANTIC AVENUE (Continued) **S131595063**

Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	579723
Control Name:	Decision Document
HW Code:	C224289
Control Code:	D
Control Type:	INST
Dt record added:	07/08/2024
Dt rec updated:	01/24/2025
Updated By:	JSDONALD
Site Code:	579723
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00

3200 ATLANTIC AVENUE (Continued) **S131595063**

Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: Landuse Restriction
HW Code: C224289
Control Code: 25
Control Type: INST
Dt record added: 07/08/2024
Dt rec updated: 01/24/2025
Updated By: JSDONALD
Site Code: 579723
Site Description: Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump: False

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-01-30 14:10:00
Record Upd: 2025-01-15 13:39:00
Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: Soil Management Plan
HW Code: C224289
Control Code: 14
Control Type: INST
Dt record added: 07/08/2024
Dt rec updated: 01/24/2025
Updated By: JSDONALD
Site Code: 579723
Site Description: Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-01-30 14:10:00
Record Upd: 2025-01-15 13:39:00
Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: Ground Water Use Restriction
HW Code: C224289
Control Code: 08
Control Type: INST
Dt record added: 07/08/2024
Dt rec updated: 01/24/2025
Updated By: JSDONALD
Site Code: 579723
Site Description: Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop,

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair.
Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-01-30 14:10:00
Record Upd: 2025-01-15 13:39:00
Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: Monitoring Plan
HW Code: C224289
Control Code: 31
Control Type: INST
Dt record added: 07/08/2024
Dt rec updated: 01/24/2025
Updated By: JSDONALD
Site Code: 579723
Site Description: Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2019-01-30 14:10:00
Record Upd: 2025-01-15 13:39:00
Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: IC/EC Plan
HW Code: C224289
Control Code: 34

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Control Type:	INST
Dt record added:	07/08/2024
Dt rec updated:	01/24/2025
Updated By:	JSDONALD
Site Code:	579723
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported

3200 ATLANTIC AVENUE (Continued) **S131595063**

Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD
Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

Name: 3200 ATLANTIC AVENUE
Address: 8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 579723
Control Name: Site Management Plan
HW Code: C224289
Control Code: 32
Control Type: INST
Dt record added: 07/08/2024
Dt rec updated: 01/24/2025
Updated By: JSDONALD
Site Code: 579723
Site Description: Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan.
Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Dell: Not reported
Record Add: 2019-01-30 14:10:00
Record Upd: 2025-01-15 13:39:00
Updated By: JSDONALD
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: brooklyn public library - arlington branch
Owner Address: 203 arlington avenue at warwick street
Owner Addr2: Not reported
Owner City,St,Zip: brooklyn, NY 11207
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: c/o The Hudson Companies
Owner Addr2: 826 Broadway, 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Joseph Riggs
Owner Company: Logan Fountain Owner LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 6
Sub Type: P02
Owner Name: Joseph Riggs
Owner Company: Hudson Logan Fountain LLC
Owner Address: 826 Broadway
Owner Addr2: 11th Floor
Owner City,St,Zip: New York, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Jericho 265 Logan Street Housing Development Fund
Owner Company: Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address: c/o The Jericho Project
Owner Addr2: 245 W. 29th Street, Suite 902
Owner City,St,Zip: New York, NY 10001
Owner Country: United States of America
HW Code: C224289
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Type: butylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224289
Waste Type: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2024000183696
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2024-08-14 12:58:00
Record Updated: 2024-08-14 12:58:00
Updated By: JSDONALD

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Crossref ID: C224289-03-19
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2025-01-03 08:26:00
Record Updated: 2025-01-03 08:26:00
Updated By: JSDONALD
Crossref ID: 1806390
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-28 09:38:00
Record Updated: 2021-05-28 09:38:00
Updated By: JHOCONNE

BROWNFIELDS:

Name:	3200 ATLANTIC AVENUE
Address:	8 FOUNTAIN AVENUE AND 3202 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Program:	BCP
Site Code:	579723
Acres:	0.895
HW Code:	C224289
SWIS:	2401
Town:	New York City
Record Added Date:	11/21/2018
Record Updated Date:	01/24/2025
Update By:	AMSERVIS
Site Description:	Location: The project site is located on the south side of Atlantic Avenue, between Logan Street and Fountain Avenue in Brooklyn, Kings County, NY. The property lot is an irregularly shaped 0.88-acre parcel identified as Tax Block 4154, Lots 1001-1004. Site Features: Historic on-site buildings and gas station features were demolished in 2022 to facilitate remediation and redevelopment. The site is currently an active construction site with ongoing development of a mixed use apartment building. Current Zoning and Land Use: The site lot is zoned C4-4D, a designation denoting commercial centers, with bulk and height regulations, outside central business districts. The surrounding area is generally residential to the south and north with commercial uses along Atlantic Avenue and a public school east of the site, across Logan Street. Past Uses of the Site: The subject property was generally undeveloped land until sometime between 1887 and 1908. The earliest known site uses were as a carpenter shop, glazer and lumber storage, followed by coal and ice storage and a bottling facility. The most recent uses of the site include a filling station, office building, used auto parts storage and auto repair. Site Geology and Hydrogeology: The site is located at an elevation of approximately 35 feet above mean sea level, and bedrock is estimated to be present at approximately 500 feet below grade. The overburden is composed predominantly of a shallow fill layer underlain by native sands. Groundwater was encountered at depths ranging from approximately 25 to 29 feet below grade (ft-bg), and the groundwater flow direction is to the south-southwest.
Env Problem:	Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs) in groundwater, soil, and soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

	soil vapor is being managed under a Site Management Plan.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-30 14:10:00
Record Upd:	2025-01-15 13:39:00
Updated By:	JSDONALD
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	brooklyn public library - arlington branch
Owner Address:	203 arlington avenue at warwick street
Owner Addr2:	Not reported
Owner City,St,Zip:	brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	c/o The Hudson Companies
Owner Addr2:	826 Broadway, 11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Joseph Riggs
Owner Company:	Logan Fountain Owner LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Joseph Riggs
Owner Company:	Hudson Logan Fountain LLC
Owner Address:	826 Broadway
Owner Addr2:	11th Floor
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Jericho 265 Logan Street Housing Development Fund
Owner Company:	Jericho 265 Logan Street Housing Development Fund Corp.
Owner Address:	c/o The Jericho Project
Owner Addr2:	245 W. 29th Street, Suite 902
Owner City,St,Zip:	New York, NY 10001
Owner Country:	United States of America
HW Code:	C224289
Waste Type:	benzo(a)anthracene

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	butylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224289
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Waste Code:	Not reported
HW Code:	C224289
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2024000183696
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2024-08-14 12:58:00
Record Updated:	2024-08-14 12:58:00
Updated By:	JSDONALD
Crossref ID:	C224289-03-19
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2025-01-03 08:26:00
Record Updated:	2025-01-03 08:26:00
Updated By:	JSDONALD
Crossref ID:	1806390
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 09:38:00
Record Updated:	2021-05-28 09:38:00
Updated By:	JHOCONNE

NYC LAND USE:

Name:	Not reported
Address:	8 FOUNTAIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6796933
Longitude:	-73.8769456
Type Of Ownership Code:	Not reported
Owner Name:	JERICHO 265 LOGAN STREET HOUSING DEV FUN D CORP.
Borough:	BK
Tax Block:	4154
Tax Lot:	7501
Community District:	305
Census Tract 2020:	3119200
Census Block 2020:	31192001000
Census Tract 2010:	1192
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E236
Police Precinct:	75
Health Center District:	33
Health Area:	6200
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	C4-4D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Rm: Condominiums -Mixed Residential & Commercial Building (Mixed Residential & Commercial)
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	38992
Total Building Floor Area:	331041
Commercial Floor Area:	153625
Residential Floor Area:	177416
Office Floor Area:	145740
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	7885
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	13.0000000
Residential Units:	174
Total Units:	184
Lot Frontage:	190.0000000
Lot Depth:	200.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	0
Basement Type/Grade:	5
Assessed Land Value:	1403550.00000
Assessed Total Value:	1403550.00000
Exempt Total Value:	752163.00000
Year Built:	2023
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	8.49000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	3.40000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3041547501.00000000
Condominium Number:	5776
Census Tract 2:	1192
X Coordinate:	1018381
Y Coordinate:	186931
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 031
Tax Map #:	31306
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1

DRAFT

3200 ATLANTIC AVENUE (Continued) **S131595063**

2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

267
NE
1/4-1/2
0.300 mi.
1585 ft.

DOMINICK VITUCCI TRUCK SALES **NY SWF/LF** **S128178031**
2 FOUNTAIN AVE **N/A**
BROOKLYN, NY 11208

Relative:
Higher

Actual:
35 ft.

SWF/LF:

Name:	DOMINICK VITUCCI TRUCK SALES
Address:	2 FOUNTAIN AVE
City,State,Zip:	BROOKLYN, NY 11208
Flag:	INACTIVE
Region Code:	2
Phone Number:	7182350688
Owner Name:	Dominick Vitucci
Owner Type:	Private
Owner Address:	2 Fountain Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Email:	Domstrux@aol.com
Owner Phone:	7182350688
Contact Name:	Carol Citucci
Contact Address:	2 Fountian Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn;, NY 11208
Contact Email:	domstraux@aol.com
Contact Phone:	7182350688
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7017678]
Active:	No
East Coordinate:	111111
North Coordinate:	111111
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

Name:	DOMINICK VITUCCI TRUCK SALES
Address:	2 FOUNTAIN AVE
City,State,Zip:	BROOKLYN, NY 11208
Flag:	ACTIVE
Region Code:	2
Phone Number:	7182350688
Owner Name:	Dominick Vitucci
Owner Type:	Private
Owner Address:	2 Fountain Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Email:	Domstrux@aol.com

DRAFT

DOMINICK VITUCCI TRUCK SALES (Continued) **S128178031**

Owner Phone:	7182350688
Contact Name:	Carol Citucci
Contact Address:	2 Fountian Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn;, NY 11208
Contact Email:	domstraux@aol.com
Contact Phone:	7182350688
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7017678]
Active:	Yes
East Coordinate:	594950
North Coordinate:	4503782
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	6/26/2024

268
NNE
1/4-1/2
0.308 mi.
1625 ft.

PRIVATE RESIDENCE
229 NORWOOD AVE
BROOKLYN, NY

NY LTANKS **S106869058**
N/A

Relative:
Higher

Actual:
40 ft.

LTANKS:

Name:	PRIVATE RESIDENCE
Address:	229 NORWOOD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0500041 / 2005-11-21
Facility ID:	0500041
Site ID:	342916
Spill Date:	2005-04-01
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2005-04-01
CID:	41
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-01
Spill Record Last Update:	2005-11-21
Spiller Name:	Not reported
Spiller Company:	VIJAX OIL CO,
Spiller Address:	222 MERRICK AV
Spiller County:	001

DRAFT

PRIVATE RESIDENCE (Continued) **S106869058**

Spiller Contact:	SEORAJI GAYARAM
Spiller Phone:	(718) 827-1558
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	289301
Latitude:	40.6808940
Longitude:	-73.8788510
DEC Memo:	05/18/05 - Sawyer - Soeraji Gayaram from her private residence called and reported that she is still having problems with interior contamination. I called Anthony Losquadro from Vjiax Oil and he is going to send out a cleanup crew to finish the basement cleaning. I required him to call the Department when he the job is finished, so an inspection can be performed. 11/17/05- DEC Piper spoke w/ homeowner Ms. Gayaram. All cleaned up by Vijax. No complaints by her.
Remarks:	overfill of tank - being cleaned up at this time

All Materials:

Site ID:	342916
Operable Unit ID:	1101603
Operable Unit:	01
Material ID:	581816
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

269 ENE 1/4-1/2 0.313 mi. 1651 ft.

POLYTECH
1 WELLS ST
BROOKLYN, NY 11208

NY LTANKS **S104621468**
NY Spills **N/A**
NY MANIFEST
NY NYC LAND USE

Relative: Higher

Actual: 34 ft.

LTANKS:

Name:	TTF AT TRANSIT HIGH SCHOOL
Address:	1 WELLS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1301729 / 2021-03-31
Facility ID:	1301729
Site ID:	482131
Spill Date:	2013-05-20
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2013-05-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

DRAFT

POLYTECH (Continued) **S104621468**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-20
Spill Record Last Update:	2021-03-31
Spiller Name:	CHRISTOPHER STEELE
Spiller Company:	NYC BOARD OF EDUCATION
Spiller Address:	1 WELLS ST
Spiller County:	999
Spiller Contact:	CHRISTOPHER STEELE
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	236843
Latitude:	40.6783191
Longitude:	-73.8760884
DEC Memo:	6/13/14-Vought-Current Project Manager for spill but received no notification from Duty Desk officer that spill was assigned to Vought or that TTF letter was sent out. DEC PBS Unit Breen requested that spill be transferred to him as he performed site inspection, and issued a Notice of Violation which resulted in a Consent Order for site. Spill transferred from Vought to Breen. UST passed subsequent TTT on ? 3/30/21 - Austin - Transferred from Breen to Patel for research and review for possible closure - end 03/31/21-Hiralkumar Patel. alternate addresses: 51 Fountain Ave, 79 Fountain Ave, 1-57 Wells St during search of spills database, found another spill case # 2010548 which was reported yesterday due to tightness test failure of existing tank(s). as per DEC remarks, tank owner plans to abandon tanks in-place. other spills: 0000950, 0012542, 0012543, 0901377, 2008025, 2010548 PBS #: 2-354732. as per PBS record, the site has following tanks: - two (2) 10,000 gal #4 oil USTs, in-service, installed in Feb. 1940 - one (1) 280 gal diesel AST, in-service, installed in Jul. 2011 subject spill case closed administratively and merged with open spill # 2010548.
Remarks:	10,000G Tank Failure. leaking below liquid.

All Materials:

Site ID:	482131
Operable Unit ID:	1231879
Operable Unit:	01
Material ID:	2230668
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	SCHOOL
Address:	1 WELLS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2010548 / 2021-07-30
Facility ID:	2010548
Site ID:	617599
Spill Date:	2021-03-30

DRAFT

POLYTECH (Continued) **S104621468**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HSSEKHON
Referred To:	Not reported
Reported to Dept:	2021-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2021-03-30
Spill Record Last Update:	2021-07-30
Spiller Name:	Not reported
Spiller Company:	SCHOOL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOSEPH YOUNG
Spiller Phone:	(929) 351-6697
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	362506
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	DEC Piper spoke with DOE Fuel Div. Tank was recently emptied and cleaned. Tank was subsequently tested and it failed. Scholl has 2-10K tanks. This may be abandoned. If so, soil samples will be collected through tank. Tank liner is in poor condition. Assigned to DEC Sekhon for follow up and closure. 6/28 - Sekhon Email send to RP (Joseph Youngshe) to get updates. 7/12/21 - Sekhon RP hired Riteway Industries corp to investigate case. 7/27/21- Sekhon Closure report submitted for review. DECDOCS 7/29/21 - Sekhon Riteway proceeded to troubleshoot the tank test failure bu isolating the tank and performing tests on all lines. The vent, fill, suction & return all passed the pressure test and tank only test failed & RP plans to abandon the tank. Riteway cut open the tank top and took 6 samples. Tank was onto concrete pad, however some contamination encountered onto concrete. Riteway cut the tank bottom & concrete pad was scrubbed and wiped down. Out of 6 samples, only two samples were met with refusal. All the sample results came back within limits. All oil absorbent material/pads/waste generated from site was placed into two 55 gallon drums for disposal. 7/30 - Sekhon Report reviewed & accepted. Case closed.
Remarks:	Tank test failure.

All Materials:

Site ID:	617599
Operable Unit ID:	1364746
Operable Unit:	01
Material ID:	2377188
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

DRAFT

POLYTECH (Continued) **S104621468**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	PS 615
Address:	1 WELLS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0000950 / 2006-01-04
Facility ID:	0000950
Site ID:	285128
Spill Date:	2000-04-24
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AJWHITE
Referred To:	Not reported
Reported to Dept:	2000-04-24
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-24
Spill Record Last Update:	2006-01-04
Spiller Name:	Not reported
Spiller Company:	BOARD OF ED
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRANK CARDELLO
Spiller Phone:	(718) 391-6832
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	236843
Latitude:	40.6783036
Longitude:	-73.8760611
DEC Memo:	11/15/2005: Lead transferred to Joe White as part of the Spill Initiative Project. 12/08/2005: Mr. James Merlo, the coordinator for NYC School spills, called Joe White to indicate that the tank has been retested and passed. These passing results will be sent to the DEC for closure of failed tank test. 01/04/2006: The reported spill was #4 Fuel oil tank test failure. At this location there are two tanks listed in the PBS database. Tank 1 is #2 fuel oil and tank 2 is #4 fuel oil. Tank 2 was documented as passing the tank test on 7/14/2005 which is subsequent to the tank test failure reportee in this spill report. Since the quantity reported as spilled is 0 gal, the subsequent tank test pass in 2005 is sufficient to close out this spill. The PBS information is documented in PBS # 2-354732.
Remarks:	Not reported

DRAFT

POLYTECH (Continued) **S104621468**

All Materials:

Site ID:	285128
Operable Unit ID:	822669
Operable Unit:	01
Material ID:	289181
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SCHOOL K 615 - TTF - RW
Address:	1 WELLS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2201525 / 2022-11-09
Facility ID:	2201525
Facility Type:	ER
DER Facility ID:	362506
Site ID:	636580
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2022-05-19
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2022-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-05-19
Spill Record Last Update:	2022-11-09
Spiller Name:	PAUL COLLINS
Spiller Company:	DEPT ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	TOM DECRESCENZO
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	5/19/22-Lin-10,000 gallon #4 fuel oil underground tank with 3600 gallon of product inside (Tank#1). Tank test confirmed that its a wet leak. The tank is located at a school and according to the tank tester there is no vapor. A vac truck will pump the product out of the

DRAFT

POLYTECH (Continued) **S104621468**

tank today. 11/09/2022- DEC
piper received and reviewed closure documents. Based on work to date, and passing system test, this
spill is closed. Report is in DEC Docs.

Remarks: repairs and cleanup pending

All Materials:

Site ID:	636580
Operable Unit ID:	1383649
Operable Unit:	01
Material ID:	2398051
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	TRANSIT TECH H.S.
Address:	1 WELLS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012543 / 2001-02-28
Facility ID:	0012543
Facility Type:	ER
DER Facility ID:	236843
Site ID:	285129
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	2001-02-23
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2001-02-23
CID:	390
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-23
Spill Record Last Update:	2001-04-23
Spiller Name:	Not reported
Spiller Company:	TRANSIT TECH H.S.
Spiller Address:	1 WELLS ST
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6783036
Longitude:	-73.8760611
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL Also see 0012546 and

DRAFT

POLYTECH (Continued) **S104621468**

0012542. Board of Ed hired PTC to test one 10,000 gallon UST(tank #2) buried under grass to the
west of main entrance on Wells St because maintenance noticed moisture around the tank and they
were concerned of possible corrosion. PTC installed plugs and then subcontracted Crown Leak
Detection to perform test. The lines were tested on 2/16, the tank tested on 2/21, plugs never
removed. Board of Ed ordered oil on 2/16 which was delivered on 2/23 - before the plugs were
removed from vent. Pressure built up and oil was forced out of fill line onto street. Cleaned by
Petroleum Tank Cleaners. No further action.

Remarks: spill caused by plugged fill lines ***approx 200 gal spilled into a storm drain**

All Materials:

Site ID:	285129
Operable Unit ID:	834435
Operable Unit:	01
Material ID:	542807
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SCHOOL
Address:	1 WELLS STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012542 / 2001-02-23
Facility ID:	0012542
Facility Type:	ER
DER Facility ID:	236843
Site ID:	292605
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2001-02-23
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2001-02-23
CID:	389
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-23

DRAFT

POLYTECH (Continued) **S104621468**

Spill Record Last Update:	2001-04-23
Spiller Name:	Not reported
Spiller Company:	SCHOOL
Spiller Address:	1 WELLS STREET
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6783036
Longitude:	-73.8760611
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL Close cross reference to 0012546
Remarks:	caller reporting a spill of approx 2000 gal from a tank truck driver was making a delivery and somehow spilled material. unk exactly how spill happened. some of the material may have gone into the sewer

All Materials:

Site ID:	292605
Operable Unit ID:	834433
Operable Unit:	01
Material ID:	542806
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SCHOOL
Address:	1 WELLS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0901377 / 2009-09-09
Facility ID:	0901377
Facility Type:	ER
DER Facility ID:	362506
Site ID:	413365
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-05-04
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2009-05-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-04
Spill Record Last Update:	2009-09-09

DRAFT

POLYTECH (Continued) **S104621468**

Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RAY LARA
Latitude:	40.6783190
Longitude:	-73.8760880
DEC Memo:	Over fill out of a vent line. Onto soil. Area is behind a fence and away from children access. Area being dug out. PTC will send closure documentation. 05/12/09-zhune spoke to Manandra from Fuel Division 718-3495738. PTC did the cleanedup the same day. they removed the soil contaminated. oil went on top of the ground probably 1 . They removed 4 drums of soil contaminated and asked to removed extra soil. As per Manandra it was not necessary to take soil samples. Zhune told him DEC requires soil samples. He said no problem he will call PTC to do the sampling. 05/15/09- Zhune spoke to Mark from PTC. he said two soil samples were taken. Results will be ready in two weeks. 05/29/09- Zhune spoke to Ray from PTC. Results will be ready next wednesday 05/04/09 09/09/09- PTC sent the soil samples results. Two samples were taken at depth of 2 ft. The results indicate VOCs and SVOCs below the Recommended soil cleanup objectives for fuel oil contaminatd soil. spill Closed.
	Not reported
Remarks:	possible over fill spilling approx 20 gallons onto the ground, clean up is in progress.

All Materials:

Site ID:	413365
Operable Unit ID:	1169795
Operable Unit:	01
Material ID:	2161474
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	SCHOOL
Address:	1 WELLS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2008025 / 2020-12-11
Facility ID:	2008025
Facility Type:	ER
DER Facility ID:	362506
Site ID:	614945
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401

DRAFT

POLYTECH (Continued) **S104621468**

Spill Date:	2020-12-11
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2020-12-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-12-11
Spill Record Last Update:	2020-12-11
Spiller Name:	Not reported
Spiller Company:	PLATINUM OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSEPH
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/11/2020-Lin-According to Dept of Ed. The driver was making a delivery and when he was done. He was changing hose and there was residual oil in hose that leaked out onto the street and made its way into a catch basin. Pads and speedy dry were put down. Spill on the street was cleaned up. Dept of Ed will contact NYCDEP.
Remarks:	clean up in progress, spill in street and some in sewer

All Materials:

Site ID:	614945
Operable Unit ID:	1362051
Operable Unit:	01
Material ID:	2374102
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYD986945640
Country:	USA
Name:	Polytech
Address:	1 WELLS ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	1 WELLS ST
Location Address 2:	Not reported

DRAFT

POLYTECH (Continued) **S104621468**

Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Polytech
Mailing Contact: Danny Ezidiegwu
Mailing Address 1: 1 WELLS STREET
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11208
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7182350017

Manifest Data:
Document ID: NYB2409030
Manifest Status: Not reported
Trans1 State ID: MD072E59
Year: 1991
Trans2 State ID: Not reported
Generator Ship Date: 05/21/1991
Trans1 Recv Date: 05/21/1991
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/31/1991
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986945640
Trans1 EPA ID: NCD980842132
Trans2 EPA ID: Not reported
TSDF ID 1: NCD980842132
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00120
Units: Pounds
Number of Containers: 003
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

DRAFT

POLYTECH (Continued) **S104621468**

Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Corrosive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00260
Units:	Pounds
Number of Containers:	004
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Corrosive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00090
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB2409030
Manifest Status:	Not reported
Trans1 State ID:	MD072E59
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/1991
Trans1 Recv Date:	05/21/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986945640
Trans1 EPA ID:	NCD980842132
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD980842132
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

DRAFT

POLYTECH (Continued) **S104621468**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00130
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Corrosive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00080
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Reactive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	004
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Corrosive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00080
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB2409030
Manifest Status:	Not reported
Trans1 State ID:	MD072E59
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/1991

DRAFT

POLYTECH (Continued) **S104621468**

Trans1 Recv Date:	05/21/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986945640
Trans1 EPA ID:	NCD980842132
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD980842132
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Phenol
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00090
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Mercury
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00
Waste Code 12:	Reactive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00030
Units:	Pounds
Number of Containers:	003
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Barium

DRAFT

POLYTECH (Continued) **S104621468**

Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB2409030
Manifest Status:	Not reported
Trans1 State ID:	MD072E59
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	05/21/1991
Trans1 Recv Date:	05/21/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986945640
Trans1 EPA ID:	NCD980842132
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD980842132
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ethene, Trichloro- (Or) Trichloroethylene
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Chromium
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010

DRAFT

POLYTECH (Continued) **S104621468**

Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Barium
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00090
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/24/2016
Trans1 Recv Date:	09/24/2016
Trans2 Recv Date:	10/04/2016
TSD Site Recv Date:	10/05/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986945640
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAC300017498
TSDF ID 2:	Not reported
Manifest Tracking Number:	000976740VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

DRAFT

POLYTECH (Continued) **S104621468**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H039
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	272
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	1
Document ID:	NYB2247894
Manifest Status:	Not reported
Trans1 State ID:	XP61DMNJ
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	07/25/1991
Trans1 Recv Date:	07/25/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/26/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986945640
Trans1 EPA ID:	NJD000813477
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD980842132
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends

DRAFT

POLYTECH (Continued) **S104621468**

Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00090
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Reactive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

NYC LAND USE:

Name:	Not reported
Address:	1 WELLS STREET
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6787748
Longitude:	-73.8753357
Type Of Ownership Code:	C
Owner Name:	NYC DEPARTMENT OF EDUCATION
Borough:	BK
Tax Block:	4155
Tax Lot:	75
Community District:	305
Census Tract 2020:	3119600
Census Block 2020:	31196001000
Census Tract 2010:	1196
Census Block 2010:	1000
School District:	19
City Council District:	37

DRAFT

POLYTECH (Continued) **S104621468**

Fire Company:	E236
Police Precinct:	75
Health Center District:	33
Health Area:	6410
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	R5: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	W1: Educational Structures - Public Elementary, Junior Or Senior High
Land Use Category:	Public Facilities & Institutions
Number Of Easements:	0
Lot Area:	108163
Total Building Floor Area:	380788
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	5.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	436.5000000
Lot Depth:	250.0000000
Building Frontage:	348.1700000
Building Depth:	198.2500000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	778950.00000
Assessed Total Value:	20296350.00000
Exempt Total Value:	20296350.00000
Year Built:	1940
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	3.52000000000
Maximum Allowable Residential Far:	1.25000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000

DRAFT

POLYTECH (Continued) **S104621468**

Boro Code:	3
Borough, Tax Block and Lot:	3041550075.00000000
Condominium Number:	Not reported
Census Tract 2:	1196
X Coordinate:	1018828
Y Coordinate:	186597
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 032
Tax Map #:	31306
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	t

270
WSW
1/4-1/2
0.320 mi.
1691 ft.

LOT 30,TAXBLOCK 3998
2337 PITKIN AVENUE
BROOKLYN, NY

NY VCP **S118704284**
NY E DESIGNATION **N/A**
NY NYC OER

Relative:
Higher

Actual:
34 ft.

VCP NYC:

Project ID:	19TMP2102K,19EH-N449K,20CVCP019K
Name:	2337 PITKIN AVENUE
Address:	2337 PITKIN AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,399,800,303,039,900,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.673349
Longitude:	-73.8861
Postcode:	5
Community Board:	37
Council District:	1150
Census Tract:	3392571
BIN:	3039980030
NTA:	East New York

E DESIGNATION:

Name:	LOT 30,TAXBLOCK 3998
Address:	2337 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	30
Tax Block:	3998
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported

DRAFT

LOT 30,TAXBLOCK 3998 (Continued) **S118704284**

Description: Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC OER:
Name: 2337 PITKIN AVENUE
Address: 2337 PITKIN AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.673349
Longitude: -73.8861
OER Project Numbers: 19TMP2102K,19EH-N449K,20CVCP019K
BBL: 3.0399800303039902E+19
OER Program: VCP (Enrolled), E/RD (Review)
Class: Completed (C)
Phase: Site Management

URL:
Postcode: 5
Community Board: 37
Council District: 1150
Census Tract: 3392571
BIN: 3039980030
NTA: East New York

---

271 NW 1/4-1/2 0.339 mi. 1792 ft. **2942 FULTON ST** **NY LTANKS S102672684**
2942 FULTON STREET **NY NYC LAND USE N/A**
BROOKLYN, NY

Relative: Higher
Actual: 33 ft.

LTANKS:
Name: 2942 FULTON STREET
Address: 2942 FULTON STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9411155 / 1994-11-21
Facility ID: 9411155
Site ID: 256827
Spill Date: 1994-11-21
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: 1994-11-21
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1994-11-21
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-12-13
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported

DRAFT

2942 FULTON ST (Continued) **S102672684**

Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	210310
Latitude:	40.6794102
Longitude:	-73.8861359
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG
Remarks:	TANK WAS FULL WHEN DELIVERY ATTEMPTED-OIL SPILLED ON SIDEWALK. NO STORM DRAIN

All Materials:

Site ID:	256827
Operable Unit ID:	1009020
Operable Unit:	01
Material ID:	377017
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	2942 FULTON ST
Address:	2942 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9411203 / 1994-11-22
Facility ID:	9411203
Site ID:	190755
Spill Date:	1994-11-21
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1994-11-22
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1994-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-12-13
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU OIL
Spiller Address:	Not reported

DRAFT

2942 FULTON ST (Continued) **S102672684**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	210310
Latitude:	40.6794102
Longitude:	-73.8861359
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG
Remarks:	WHEN THE DRIVER MADE THE DELIVERY HE FILLED TANK TOO FULL & IT SPILLED ONTO CONCRETE FLOOR- SPEEDY DRY USED TO CLEANUP-NO CALL BACK

All Materials:

Site ID:	190755
Operable Unit ID:	1005020
Operable Unit:	01
Material ID:	377065
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2942 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6792554
Longitude:	-73.8861004
Type Of Ownership Code:	Not reported
Owner Name:	RAJCOOAR, NANCOOAR
Borough:	BK
Tax Block:	3953
Tax Lot:	22
Community District:	305
Census Tract 2020:	3117000
Census Block 2020:	31170001001
Census Tract 2010:	1170
Census Block 2010:	1001
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported

DRAFT

2942 FULTON ST (Continued) **S102672684**

Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	S2: Residence - Multiple Use - Primarily Two Family With One Store Or Office
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	1763
Total Building Floor Area:	3318
Commercial Floor Area:	1106
Residential Floor Area:	2212
Office Floor Area:	0
Retail Floor Area:	1106
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	2
Total Units:	3
Lot Frontage:	19.1500000
Lot Depth:	92.1200000
Building Frontage:	19.1500000
Building Depth:	59.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	10080.00000
Assessed Total Value:	41880.00000
Exempt Total Value:	0.00000
Year Built:	1920
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.88000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039530022.00000000
Condominium Number:	Not reported
Census Tract 2:	1170
X Coordinate:	1015842
Y Coordinate:	186768
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 011
Tax Map #:	31302

DRAFT

2942 FULTON ST (Continued) **S102672684**

E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AM272 **HESS#32518** **RCRA-VSQG** **1000263774**
West **2880 ATLANTIC AVENUE** **NY LTANKS** **NYD982185670**
1/4-1/2 **BROOKLYN, NY 11207** **NY UST**
0.372 mi. **NY Spills**
1966 ft. **Site 1 of 2 in cluster AM** **US AIRS**
FINDS
Relative: **ECHO**
Higher **NY MANIFEST**

Actual:
39 ft.

RCRA Listings:

Date Form Received by Agency:		20160921
Handler Name:		Speedway 7823
Handler Address:		Atlantic Ave
Handler City,State,Zip:		BROOKLYN, NY 11207-2725
EPA ID:		NYD982185670
Contact Name:		CHARLES A BESSE
Contact Address:		PO BOX 1500
Contact City,State,Zip:		SPRINGFIELD, OH 45501-1500
Contact Telephone:		937-863-6272
Contact Fax:		937-863-6078
Contact Email:		CABESSE@SPEEDWAY.COM
Contact Title:		ENVIRONMENTAL COMPLIANCE ADMIN
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		PO BOX 1500
Mailing City,State,Zip:		SPRINGFIELD, OH 45501-1500
Owner Name:	Speedway Llc	
Owner Type:		Private
Operator Name:	Speedway Llc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No

DRAFT

HESS#32518 (Continued) **1000263774**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161005
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SPEEDWAY LLC	
Legal Status:	Private
Date Became Current:	20141001
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1500
Owner/Operator City,State,Zip:	SPRINGFIELD, OH 45501-1500
Owner/Operator Telephone:	937-864-3000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED

DRAFT

HESS#32518 (Continued) **1000263774**

Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MERIT OIL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SPEEDWAY LLC
Legal Status: Private
Date Became Current: 20141001
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MERIT OIL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101

DRAFT

HESS#32518 (Continued) **1000263774**

Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870511
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160921
Handler Name: SPEEDWAY 7823
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 447110
NAICS Description: Gasoline Stations With Convenience Stores

DRAFT

HESS#32518 (Continued) **1000263774**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LTANKS:

Name:	2880 ATLANTIC AVE.
Address:	2880 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
Spill Number/Closed Date:	9200248 / 1994-08-03
Facility ID:	9200248
Site ID:	147618
Spill Date:	1992-04-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	1994-08-03
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1992-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-04-08
Spill Record Last Update:	1994-08-03
Spiller Name:	Not reported
Spiller Company:	MERIT GAS STA.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	13745
Latitude:	40.6770898
Longitude:	-73.8874643
DEC Memo:	Not reported
Remarks:	POSS. EX. & RETEST

All TTF:

Facility ID:	9200248
Spill Number:	9200248
Spill Tank Test:	1539836
Site ID:	147618
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported

DRAFT

HESS#32518 (Continued) **1000263774**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	147618
Operable Unit ID:	967477
Operable Unit:	01
Material ID:	415065
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	SPEEDWAY # 7823
Address:	2880 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-297747 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	593979.65845
UTM Y:	4503483.62653
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	13764
Affiliation Type:	Facility Owner
Company Name:	2864 ATLANTIC . REALTY, LLC
Contact Type:	MEMBER
Contact Name:	JACOB KOHN
Address1:	40 OSER AVENUE, SUITE 4
Address2:	Not reported
City:	HAUPPAUGE
State:	NY
Zip Code:	11788
Country Code:	999
Phone:	(917) 846-1115
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-02-02

Site Id:	13764

DRAFT

HESS#32518 (Continued) **1000263774**

Affiliation Type:	Facility Operator
Company Name:	SPEEDWAY # 7823
Contact Type:	Not reported
Contact Name:	2864 ATLANTIC REALTY, LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 846-1115
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-02-02

Site Id:	13764
Affiliation Type:	Emergency Contact
Company Name:	SPEEDWAY LLC
Contact Type:	MEMBER
Contact Name:	JACOB KOHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 578-3749
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-01-27

Site Id:	13764
Affiliation Type:	Mail Contact
Company Name:	JACOB KOHN
Contact Type:	MEMBER
Contact Name:	JACOB KOHN
Address1:	40 OSER AVENUE, SUITE 4
Address2:	ATTN.: ENVIRONMENTAL COMPLIANCE
City:	HAUPPAUGE
State:	NY
Zip Code:	11788
Country Code:	001
Phone:	(917) 846-1115
EMail:	KOHNJACOB@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	1
Tank ID:	46828
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550

DRAFT

HESS#32518 (Continued) **1000263774**

Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	10
Tank ID:	46839
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

DRAFT

HESS#32518 (Continued) **1000263774**

Tank Number:	11
Tank ID:	46837
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	12
Tank ID:	46840
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

DRAFT

HESS#32518 (Continued) **1000263774**

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 13
Tank ID: 46838
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 14
Tank ID: 46841
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

DRAFT

HESS#32518 (Continued) **1000263774**

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	15
Tank ID:	46812
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	16
Tank ID:	46813
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

DRAFT

HESS#32518 (Continued) **1000263774**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 17
Tank ID: 46814
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 18
Tank ID: 46815
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998

DRAFT

HESS#32518 (Continued) **1000263774**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 19
Tank ID: 46816
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 2

DRAFT

HESS#32518 (Continued) **1000263774**

Tank ID:	46829
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	20
Tank ID:	46817
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

DRAFT

HESS#32518 (Continued) **1000263774**

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 21
Tank ID: 46818
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 22
Tank ID: 46819
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

DRAFT

HESS#32518 (Continued) **1000263774**

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	23
Tank ID:	46820
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	24
Tank ID:	46821
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported

DRAFT

HESS#32518 (Continued) **1000263774**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 25
Tank ID: 46822
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 26
Tank ID: 46823
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground

DRAFT

HESS#32518 (Continued) **1000263774**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 27
Tank ID: 46824
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 28
Tank ID: 46825
Tank Status: Closed - Removed

DRAFT

HESS#32518 (Continued) **1000263774**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	29
Tank ID:	46826
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

DRAFT

HESS#32518 (Continued) **1000263774**

F00 - Pipe External Protection - None

Tank Number: 3
Tank ID: 46830
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 30
Tank ID: 46827
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None

DRAFT

HESS#32518 (Continued) **1000263774**

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	31
Tank ID:	16159
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	32
Tank ID:	16160
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported

DRAFT

HESS#32518 (Continued) **1000263774**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 33
Tank ID: 16161
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 10/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 34
Tank ID: 16162
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 10/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

DRAFT

HESS#32518 (Continued) **1000263774**

Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 35
Tank ID: 16163
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 10/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number: 36
Tank ID: 16164
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000

DRAFT

HESS#32518 (Continued) **1000263774**

Install Date:	10/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H99 - Tank Leak Detection - Other

Tank Number:	37
Tank ID:	16165
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	02/01/1964
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other
J00 - Dispenser - None

DRAFT

HESS#32518 (Continued) **1000263774**

Tank Number:	38
Tank ID:	16166
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	02/01/1964
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	00
Date Test:	07/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D10 - Pipe Type - Copper
H99 - Tank Leak Detection - Other

Tank Number:	39
Tank ID:	54686
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	07/01/1998
Date Tank Closed:	06/06/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSALI
Last Modified:	01/25/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm

DRAFT

HESS#32518 (Continued) **1000263774**

K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	4
Tank ID:	46831
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None

Tank Number:	40
Tank ID:	54687
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	07/01/1998
Date Tank Closed:	06/06/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	00
Date Test:	11/01/1998
Next Test Date:	Not reported

DRAFT

HESS#32518 (Continued) **1000263774**

Pipe Model: Not reported
Modified By: MSALI
Last Modified: 01/24/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 41
Tank ID: 54688
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: 07/01/1998
Date Tank Closed: 06/08/2022
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MSALI
Last Modified: 01/24/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

DRAFT

HESS#32518 (Continued) **1000263774**

Tank Number:	42
Tank ID:	54689
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	07/01/1998
Date Tank Closed:	06/08/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSALI
Last Modified:	01/24/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	43
Tank ID:	54690
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	600
Install Date:	07/01/1998
Date Tank Closed:	06/07/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	00
Date Test:	11/01/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSALI
Last Modified:	01/24/2023

Equipment Records:

A00 - Tank Internal Protection - None

DRAFT

HESS#32518 (Continued) **1000263774**

B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 5
Tank ID: 46832
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 6
Tank ID: 46833
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

DRAFT

HESS#32518 (Continued) **1000263774**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 7
Tank ID: 46834
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 8
Tank ID: 46835
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 11/01/1982
Date Tank Closed: 07/01/1998

DRAFT

HESS#32518 (Continued) **1000263774**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	9
Tank ID:	46836
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	11/01/1982
Date Tank Closed:	07/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	UST- 44

DRAFT

HESS#32518 (Continued) **1000263774**

Tank ID: 299304
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/16/2022
Date Tank Closed: 05/12/2023
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/06/2023

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

Tank Number: UST-45
Tank ID: 299305
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/16/2022
Date Tank Closed: 05/18/2023
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/06/2023

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

DRAFT

HESS#32518 (Continued) **1000263774**

G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

Tank Number:	UST-46
Tank ID:	299306
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/16/2022
Date Tank Closed:	05/12/2023
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	10/06/2023

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

Tank Number:	UST-47
Tank ID:	299307
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	03/16/2022
Date Tank Closed:	05/18/2023
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	10/06/2023

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

DRAFT

HESS#32518 (Continued) **1000263774**

I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

Tank Number: UST-48
Tank ID: 299308
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 03/16/2022
Date Tank Closed: 05/18/2023
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/06/2023

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
J00 - Dispenser - None

SPILLS:

Name: FORMER HESS STATION 32518
Address: 2880 ATLANTIC AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9830002 / 2023-12-31
Facility ID: 9830002
Facility Type: ER
DER Facility ID: 479929
Site ID: 65126
DEC Region: 2
Spill Cause: Other
Spill Class: B3
SWIS: 2401
Spill Date: 1998-08-06
Investigator: AXDORONO

DRAFT

HESS#32518 (Continued) **1000263774**

Referred To:	ENTERED INTO BCP - (BCA #C224349)
Reported to Dept:	1998-08-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-06
Spill Record Last Update:	2023-12-12
Spiller Name:	Not reported
Spiller Company:	FORMER HESS STATION
Spiller Address:	2880 ATLANTIC AVENUE
Spiller Company:	999
Contact Name:	ANGELO FATIGA
Latitude:	40.6770898
Longitude:	-73.8874643
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 12/10/2004 Reassigned from Sangesland to Sun. 10/31/05: Project reassigned from Sun to Andersen. Site needs Stip and RAP. 1/26/06: 1/25/06 meeting with Quantum, NYSDEC, and GSC/Kleinfelder: Additional delineation difficult because of residential area, an RAP will be prepared. 2/13/06: Reviewed the quarterly report dated 1/24/06. BTEX concentration in MW-6 is 7,530 ppb. Sent an RAP required letter. RAP due 4/13/06. 4/17/06: RAP not received. Sent stipulation agreement. Stip due back 5/29/06. 6/26/06: Received a RAP. Vertical delineation around MW6 proposed. Biosolve use proposed. RAP states that MW6 is too close to the tanks and remote fills for the use of chemical injection. 6/30/06: Meeting on 6/28/06 with Hess, Quantum, NYSDEC, EnviroTrac and GSC. RAP approved. Stip will be delayed for another triannual sampling period. 7/25/06: Received email from Albert Tonn of GSC/Kleinfelder: Please be advised that the soil boring adjacent to MW-6 will be advanced on August 8, 2006. 8/15/06: Received email from Al Tonn of GSC/K: Please be advised that the soil boring was completed on 8/8/06. There were no impacts observed until the water table interface. Therefore, -Kleinfelder will proceed with the Bio-Solve injection on 8/22/06, followed by an EFR event on 8/24/06. 10/4/06: Reviewed update report dated 9/27/06. Seven wells sampled on 7/20/06. Max BTEX 3,226 (MW4). No MTBE present. Report states that the approved workplan will be implemented during the third quarter of 2006 . 1/17/07: Meeting on 1/16/07 with Hess, Delta, NYDEC. Biosolve injection/EFR in August, September, and October 2006 from MW4 and MW6. 400-600 gallons recovered. 2/12/07: Received the

DRAFT

HESS#32518 (Continued) **1000263774**

third triannaul 2006 site status report. Biosolve injection and EFR performed in August, September, and October. There may have been some mobilization into MW1. Wells sampled on 12/26/06. Max BTEX 3,405 ppb (MW6). Emailed Hess, Delta asking if additional work is planned (RAP dated 6/23/06 only proposed 3 Biosolve and EFR events), and suggested that EFR should be performed in MW1. 3/13/07: Received email from Tim Fisher: As discussed during the 1/16/07 site review meeting, our approach for this site is to complete March's sampling event and then evaluate the effectiveness of the biosolve / EFR events. 5/16/07: Reviewed update report. Wells sampled on 3/28/07. Fluctuating concentrations in MW1/MW6. Max BTEX 5,069 ppb in MW1. MTBE ND in all wells. Biosolve/EFR no longer in use? What is the RAP now? 5/17/07: Received email from Timothy Fisher : Since part of the manufactured claims of Biosolve is to increase the bioavailability of the contaminants, we will be monitoring the attenuation of the residual concentrations. As expected, there was an initial increase in dissolved phase (increase in bioavailability), so the plan is to monitor the effectiveness of the injection. 5/21/07: Received email from Timothy Fisher: We intend to complete 2 additional ground water monitoring events in July and November before completing an assessment of the biosolve applications conducted in August, September, and October 2006. This will provide us a full year of monitoring data which will help us factor in season dissolved concentration fluctuations. 9/21/07: Reviewed site status report. Fluctuating concentrations in some wells. Wells sampled on 7/10/07. Max BTEX 4,472 ppb (MW6), MTBE ND. One additional sampling event and then evaluate for additional action. 2/14/08: Reviewed September 2007 through December 2007 Site Status Report. Wells sampled on November 20, 2007. Max BTEX 2,673 ppb (MW6). MTBE ND. Flucutating concentrations in MW6. 5/6/08 - Carlson: Reviewed First Triannual 2008 Update Report dated April 30, 2008. Wells sampled on March 28, 2008. Maximum BTEX concentration 8,883 ppb (MW6). MTBE below detection limit. Hess intends to submit a RAP. When will it be submitted? Meeting scheduled for May 7, 2008. 9/2/08 - Carlson: Received email from Ed Russo (Envirotrac) indicating that off-site delineation on the adjacent residential property is impossible and that they would like to install AS wells to perform short term AS/SVE. Mark Tibbe (NYSDEC) sent email in response indicating that delineation may be possible in a driveway and that short term AS/SVE is unacceptable. Sent email requesting a site meeting and a formal RAP be submitted. 9/17/08 - Carlson: Site visit. Envirotrac will submit a workplan for soil borings/SVE/AS pilot testing. 10/3/08

DRAFT

HESS#32518 (Continued) **1000263774**

- Carlson: Reviewed workplan
submitted by email on 9/18/08 for installation of 3 wells and STRE
pilot testing. Approved
workplan. Report due by 1/3/09. 10/08/08 - Carlson: Received
notification that wells will be
installed on 10/15 - 10/16/2008. 10/16/08 - Carlson: Reviewed
September 2008 Update Report. Wells
sampled on 7/2/08. Maximum BTEX concentration 5,850 ppb (MW6).
10/22/08 - Carlson: Meeting with
Hess/Envirotrac. 2/20/09 - Carlson: Reviewed January 2009 Update
Report. STRE were conducted. High
effluent PID during pilot testing. RAP for STREs will be submitted.
Wells sampled on 11/19/08.
Maximum BTEX concentration 6,041 ppb (MW1). 3/18/09 - Carlson: Meeting
with Hess and Envirotrac.
Need to complete review of submitted RAP. Quarterly gauging requested.
4/10/09 - Carlson: Reviewed
workplan. STRE pilot testing was conducted. Workplan requested two
additional quarters to evaluate
STRE effectiveness. Sent email requiring a revised workplan in 30
days. The following modifications
are required: 1) addition of SVE radius of influence for MW4 and MW6
to the site plan 2) an
additional air sparge well should be installed between AS-3 and AS-1
3) remedial action should
begin immediately upon receipt of NYSDEC workplan approval. 5/27/09 -
Carlson: Emailed Envirotrac
regarding overdue revised workplan. 6/5/09 - Carlson: Reviewed May
2009 Update Report. Wells
sampled on March 25, 2009. Maximum BTEX concentration 3,294 ppb (MW4).
MTBE ND in all wells.
Revised RAP overdue. 8/19/09 - Carlson: Meeting with Hess and
Envirotrac. Revised RAP submission
deadline extended to 9/15/09. 12/18/09 - Carlson: Revised work plan
overdue. Reviewed update
report. SVE/AS wells will be installed in January 2010. 1/22/2010 -
Carlson: Meeting with Hess.
Revised RAP will be submitted. 3/11/2010 - Carlson: Reviewed update
report. Revised work plan
received. 3/18/2010 - Carlson: Approved work plan for installation of
2 additional AS wells and an
additional STRE pilot test with new and existing wells. 4/6/2010 -
Carlson: Notified drilling will
commence on 4/13/2010. 6/11/2010 - Carlson: Reviewed update report.
Wells sampled on 3/31/2010.
Maximum BTEX concentration 3,620 ppb (MW6). Air sparge wells AS4 and
AS5 installed on 4/13/2010.
STRE conducted on 4/23/2010. 9/30/2010 - Carlson: Reviewed update
report. Air sparge wells AS4 and
AS5 installed on 4/13/2010. STRE conducted monthly. Soil data for AS4
and AS5 included. Soil impact
at 40-45 ft. 4/21/11 - Obligado - I reviewed the November 2010 Status
report. STREs conducted
during August and September 2010. BTEX concentrations up to 959 ug/L
in MW1. February 2011 update
report. No short term remediation events were conducted during the 4th
quarter. BTEX concentrations

DRAFT

HESS#32518 (Continued) **1000263774**

were detected up to 3400 ug/L in MW1. Hess to continue STREs. 10/21/11 - Obligado - This spill is
reassigned back to Sarah Carlson as per Brevdo. 2/9/2012 - Carlson: Reviewed November 2011 Update
Report. BTEX groundwater impact remains in MW-1, MW-4, and MW-5. STRE conducted in July and
September 2011. 8/29/2012 - 1Q2012, 5/31/2012, by EnviroTrac. Hess/EnviroTrac requested to abandon
monitoring wells MW-2 and MW-3 based on the historical and current groundwater sampling data.
Groundwater was sampled 3/16/2012. DTW 31.32 to 34.41'. Flows to southwest. The next sampling will
be in 6/2012. Hess will continue with the STRE events. MW-1, 3,605.6J BTEX. MW-2, ND. MW-3, ND.
MW-4, 39.3 BTEX. MW-5, 84.9 BTEX. MW-6, 1.6 BTEX. 11/13/2012 2Q2012, 8/31/2012, by EnviroTrac. The
groundwater was sampled on 6/19/2012. DTW 31.61 to 34.52. Flows to southwest. NO LNAPL. MW-4, 114.9
BTEX, MTBE ND. MW-5, 18.6 BTEX, MTBE ND. MW-1, 998 BTEX. MTBE ND. MW-6, 9.2 BTEX, MTBE ND. The next
sampling will be in September 2012. Hess to continue STREs. Based on historical and current
groundwater sampling data from MW-2 and MW-3, and based on the fact that both wells are upgradient
of site features, Hess proposes to abandon those wells. 1/25/2013 - 3Q2012, 11/30/2012, by
EnviroTrac. The groundwater was sampled on 9/27/2012. On 8/6, 9/26/2012, conducted STRE on MW-5 and
MW-1. MW-4, 151.2 BTEX, MTBE ND. MW-5, 18.7 BTEX, MTBE ND. MW-1, 3,828 BTEX, MTBE ND. MW-6,
1,055.98J BTEX, MTBE ND. The next sampling will be in 12/2012. Hess to contiune STRE events.
9/25/2013 - 1Q2013, 5/31/2013, by EnviroTrac. Groundwater was sampled on 3/11/2013. On 1/4, 2/25,
3/6/2013, STRE on selected wells, i.e. MW-1/AS-3, and MW-5/AS-3. DTW 26.16 to 33.67 feet. Flows to
southwest. NO LPH. MW-4, 596 BTEX, MTBE ND. MW-5, 88.9 BTEX, MTBE ND. MW-1, 3,188.3 BTEX, MTBE ND.
9/15/2014 - 2Q2014, 9/4/2014, by EnviroTrac. Groundwater was sampled on 6/18/2014. DTW 32.21 to
33.03 feet. Flows to southwest. Hess to continue STRE events. MW-4, 83.4 BTEX. MW-5, 33.2 BTEX.
MW-1, 4,500.9 BTEX. MW-6, 63.2 BTEX. 2/13/2015 - 3Q2014, 11/17/2014. 7/7, 9/1, 9/14/2014, STREs on
select wells. 9/22/2014, sampled 5 monitoring wells. DTW 33.63 to 34.46 feet. Flows to southwest.
MW-1, 2,446.8 J BTEX. MW-4, 475.39 J BTEX. MW-5, 99.81 J BTEX. MW-6, 40.3 BTEX. 4Q2014, 2/13/2015.
12/3/2014, STREs on select wells. 12/18/2014, gauged and sampled 5 monitoring wells. DTW 33.59 to
34.43 feet. Flows to southwest. MW-1, 147.4 BTEX. 10/29/2015 - 1Q2015, 5/8/2015. 1/18, 2/3,
3/11/2015, STREs on select wells. 3/23/2015, gauged and sampled 5 monitoring wells. DTW 32.53 to
34.02 feet. Flows to southwest. MW-1, 4,831 BTEX. MW-4, 1,567 BTEX. 2Q2015, 8/12/2015. 4/9, 5/4,
6/16/2015, STREs on select wells. 6/24/2015, gauged and sampled 5

DRAFT

HESS#32518 (Continued) **1000263774**

monitoring wells. DTW 33.62 to
34.6 feet. Flows to southwest. MW-2 and MW-3 to be abandoned. MW-1,
3,351.3 BTEX. MW-4, 80.1 BTEX.
MW-5, 55.3 BTEX. 11/20/2015 - 3Q2015, 11/20/2015. 7/29, 8/6,
9/28/2015, STREs on select wells.
9/30/2015, gauged 5 and sampled 4 monitoring wells. DTW 33.33 to 34.15
feet. Flows to southwest.
MW-1, 3,351 BTEX. MW-5, 25.1 BTEX. 2/29/2016 - 4Q2015, 2/19/2016.
11/5, 11/16, 11/25, and
12/22/2015, STREs on select wells. 11/16/2015, MW-2 and MW-3 were
abandoned according to NYSDEC
well abandonment procedures. 12/22/2015, gauged and sampled 5
monitoring wells. MW-1, 559 BTEX.
MW-5, 173.6 BTEX. MW-4, 58.7 BTEX. 3/30/2016 Feng This spill is
transferred from J. Feng to V.
Brevdo as per J. Vought. 3/30/16 - Raphael Ketani. This spill case has
been assigned to me
effective today. According to ACRIS, the block and lot are 3965 and
11. The latest deed is dated
4/24/14. The property owner is HESS Retail Stores, 1 HESS Plaza. The
PBS record is #2-297747. The
owner is Speedway #7823. There are 4 active 10,000 gallon gasoline and
diesel USTs and one 600
gallon UST with other product. These tanks were installed on 7/1/98.
Thirty eight mostly gasoline
550 gallon USTs and 7 large gasoline USTs were closed and removed on
7/1/98. The contacts are as
follows: Speedway/Hess contact: Matthew Butler, (732) 738-2924,
MButler1@Speedway.com Consultants:
Edward Russo (EnviroTrac), (631) 924-3001, EDR@EnviroTrac.com Joseph
Rennie (EnviroTrac), (631)
924-3001, JoeR@EnviroTrac.com 5/23/16 - Raphael Ketani. I reviewed the
EnviroTrac 5/20/16 Quarterly
Report for the period January to March 2016. On 1/13/16, 2/22/16 and
3/2/16 short term remediation
events (STREs) were conducted at AS-3. Wells MW-1, MW-4 to 6 were
gauged and sampled on 3/8/16. No
product was seen in the wells. Groundwater flow was to the southwest
at 33.44' to 34.28' below
grade. Monthly STREs and quarterly groundwater sampling will be
continued. The next round of
groundwater sampling will take place during June 2016. MW-7 was not
sampled. The groundwater
results for samples from MW-4 to 6 were non-detect to low in
concentration. MW-1 had 102 ppb of
ethylbenzene and 1010 ppb of total xylenes. MW-1 is situated right
next to the USTs. MW-5 is 30
feet downgradient. MW-4 is sidegradient to the west and MW-6 is
sidegradient to the east. I
approved the report without comment. 8/31/16 - Raphael Ketani. I
reviewed the EnviroTrac 8/31/16
Quarterly Report for the period April to June 2016. On 4/7/16, 5/17/16
and 6/1/16 short term
remediation events (STREs) were conducted at select wells. On 6/10/16,
MW-1 and MW-4 to MW-7 were
gauged and wells MW-1, MW-4 to 6 were sampled. No product was seen in
the wells. Groundwater flow

DRAFT

HESS#32518 (Continued) **1000263774**

was to the southwest at 33.45' to 34.61' below grade. Monthly STREs and quarterly groundwater sampling will be continued. The next round of groundwater sampling will take place during September 2016. The 6/1/16 SVE system effluent results for MW-1/AS-3 were 250.2 ppm. This value was about average when compared to the historical results. The groundwater results for samples from MW-4 to 6 were non-detect to low in concentration. MW-1 had 1480 ppb of total xylenes and 1779 ppb of total BTEX. MW-1 is situated right next to the USTs. MW-5 is 30 feet downgradient. MW-4 is sidegradient to the west and MW-6 is sidegradient to the east. I approved the report without comment. 11/29/16 - Raphael Ketani. I reviewed the EnviroTrac 11/29/16 Quarterly Report for the period July to September 2016. On 7/11/16, 8/19/16 and 9/15/16 short term remediation events (STREs) were conducted at select wells. On 9/19/16, MW-1, 5 and 6 were gauged and sampled. No product was seen in the wells. Groundwater flow was to the southwest at 24.05' to 35.04' below grade. Monthly STREs and quarterly groundwater sampling will be continued. The next round of groundwater sampling will take place during December 2016. The SVE system effluent results for MW-1/AS-3 on 7/11/16, 8/19/16 and 9/15/16 were 317.9 ppm, 105.0 ppm and 221.0 ppm, respectively. Among the results for 2015 and 2016, these value were about average. The groundwater results for samples from MW-1 were 1885 ppb total BTEX. MW-1 is situated right next to the USTs. The results for MW-5 were mostly non-detect with one low hit. MW-5 is 30 feet downgradient. The results for MW-6 were mostly non-detect with two low hits. MW-6 is sidegradient to the east. 2/2/17 - Raphael Ketani. I reviewed the EnviroTrac January 2017 Quarterly Report dated 1/31/17 for the period October to December 2016. On 10/26/16, 11/15/16 and 12/1/16 short term remediation events (STREs) were conducted at select wells. On 12/21/16, MW-1, 4, 5 and 6 were gauged and sampled. No product was seen in the wells. Groundwater flow was to the southwest at 33.45' to 34.23' below grade. BTEX was 167.6 ppb in MW-1, 12 ppb in MW-4, 137.8 ppb in MW-5 and non-detect in MW-6. The SVE system effluent results for MW-1/AS-3 on 10/26/16, 11/15/16 and 12/1/16 were 84.7 ppm, 91.3 ppm and 103.4 ppm, respectively. Among the results for 2015 and 2016, these value were below average. Additionally, Mr. Rennie [(631) 924-3001, JoeR@EnviroTrac.com] of EnviroTrac wrote that dumping of oil was taking place at MW-7, an off site well. He included pictures of the location which showed oil staining on the sidewalk next to the well, oil between the riser of the well and the larger casing, oil coating the inside of the riser from the top to deep below and oil on the bailer that was

DRAFT

HESS#32518 (Continued) **1000263774**

brought up to the surface. A chemical analysis of the oil was provided in the laboratory report, along with chromatograms showing the chemical makeup. Mr. Rennie asked the DEC for permission to permanently close the well. Having seen the pictures of the damage to the well, the chemical analyses and the chromatograms, I granted permission to permanently close MW-7. 4/28/17 - Raphael Ketani. Today I received an email from Mr. Butler that he is leaving Speedway. He stated that John Engdahl [jjengdahl@speedway.com (732) 738-2923] will take over his duties. 6/5/17 - Raphael Ketani. I reviewed the EnviroTrac May 2017 Quarterly Report dated 5/31/17 for the period January to March 2017. On 1/12/17, 2/14/17 and 3/6/17 short term remediation events (STREs) were conducted at select wells. On 2/14/17, MW-7 was cleaned and abandoned. On 3/31/17, MW-1, 4, 5 and 6 were gauged and sampled. No product was seen in the wells. Groundwater flow was to the southwest at 32.89' to 33.80' below grade. BTEX was 4975.1 ppb in MW-1 (benzene non-detect), 306.8 ppb in MW-4 (benzene non-detect), 11.2 ppb in MW-5 and 13.3 ppb in MW-6. The SVE system effluent results for MW-1/AS-3 on 1/12/176, 2/14/17 and 3/6/17 were 338.1 ppm, 26.6 ppm and 349.6 ppm, respectively. Except for the 2/14/17 result, the values were about average when compared to the 2015 and 2016 results. 8/24/17 - Raphael Ketani. I reviewed the EnviroTrac August 2017 Quarterly Report dated 8/24/17 for the period April to June 2017. On 4/10/17, 5/24/17 and 6/5/17 short term remediation events (STREs) were conducted at select wells. On 6/26/17, MW-1, 4, 5 and 6 were gauged and sampled. No product was seen in the wells. Groundwater flow was to the southwest at 32.63' to 33.30' below grade. BTEX was 944 ppb in MW-1 (benzene non-detect), 291 ppb in MW-4 (benzene non-detect), 28 ppb in MW-5 and 24.7 ppb in MW-6. The SVE system effluent results for MW-1/AS-3 on 4/10/17, 5/24/17 and 6/5/17 were 356.8 ppm, 175.1 ppm and 133.1 ppm, respectively. 8/25/17 - Raphael Ketani. Mr. Russo [(631) 924-3001, EDR@EnviroTrac.com] sent me an email request to stop having the groundwater samples analyzed for MTBE as the results have been non-detect for many years. He included attachments consisting of a map of the groundwater flow direction beneath the site with the latest analytical results and a set of tables showing the analytical results for the groundwater samples going back many rounds. I reviewed this information and concluded that stopping the MTBE analyses would not affect understanding the future interpretations of the subsurface conditions. I approved his request. 11/27/17 - Raphael Ketani. I reviewed the EnviroTrac November 2017 Quarterly Report dated 11/27/17 for the period July to

DRAFT

HESS#32518 (Continued) **1000263774**

September 2017. On 7/21/17, 8/8/17 and 9/18/17 short term remediation events (STREs) were conducted at select wells. On 9/22/17, MW-1, 4, 5 and 6 were gauged and sampled. No product was seen in the wells. Groundwater flow was to the southwest at 32.57' to 33.37' below grade. BTEX was 1359.5 ppb in MW-1 (benzene non-detect), 138.8 ppb in MW-4 (benzene non-detect), 33.6 ppb in MW-5 and 203.4 ppb in MW-6. The SVE system effluent results for MW-1/AS-3 on 7/21/17, 8/8/17 and 9/18/17 were 114.5 ppm, 136.7 ppm and 183.8 ppm, respectively. 2/26/18 - Raphael Ketani. I reviewed the EnviroTrac February 2018 Update Report dated 2/26/18 for the period October to December 2017. On 10/24/17, 11/16/17 and 12/4/17 short term remediation events (STREs) were conducted at select wells. On 12/29/17, MW-1, 4, 5 and 6 were gauged and sampled. No product was seen in the wells. Groundwater flow was to the southwest at 32.89' to 33.70' below grade. BTEX was 4.3 ppb in MW-1 (benzene 4.3 ppb), 1.1 ppb in MW-4 (benzene non-detect), 58.2 ppb in MW-5 (benzene non-detect) and 100.6 ppb in MW-6 (benzene non-detect). The SVE system effluent results for MW-1/AS-3 on 10/24/17, 11/16/17 and 12/4/17 were 114.5 ppm, 1000.1 ppm, 708.8 ppm and 127.7 ppm, respectively. 05/01/2018: This spill case was transferred to A. Doronova - AD. AD 06/01/2018: Received the following e-mail from Mr. Rennie of EnviroTrac: Dear Ms. Doronova, Please find attached the most recent Update Report for the above referenced location. Sincerely, Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com DL the report to DDocs. Will review. AD 06/18/2018: Reviewed the report. It states that this spill was opened when impacted soils were encountered during an underground storage tank (UST) upgrade project in August 1998. Removed thirty (30) 550-gallon gasoline, three (3) 4,000-gallon gasoline, one (1) 2,000-gallon gasoline, one (1) 4,000-gallon diesel, two (2) 2,000-gallon gasoline, two (2) 550-gallon waste water UST s and associated remote fills, product piping, and dispensers. During this project 1,006 tons of impacted soils were removed off site for disposal. This report covers monitoring period from January 2018 to March 2018. On January 15, February 14, and March 9, 2018 the consultant conducted Short Term Remediation Events (STREs) on select wells. On March 14, 2018, EnviroTrac gauged and sampled four (4) monitoring wells. Wells Gauged: MW-1, MW-4, MW-5, and MW-6 Wells Containing LPH: None Groundwater Depth: 32.38 feet 33.14 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1, MW-4, MW-5, and MW-6 Maximum BTEX Concentration: 1,372 ug/L (MW-6). This well indicated sharp increase

DRAFT

HESS#32518 (Continued) **1000263774**

in BTEX concentrations since
last sampling event in December 2017 (100ppb). Maximum MTBE
Concentration: Non-detect (all wells)
EnviroTrac to continue with monthly STREs and quarterly sampling, with
the next groundwater
sampling event scheduled for June 2018. An Update Report summarizing
these activities will be
submitted to NYSDEC in August 2018. AD 11/30/2018: Received the
following e-mail from Mr. Rennie:
Dear Ms. Doronova - Please find attached the most recent Update Report
for the above referenced
location. Joseph Rennie - Project Manager - EnviroTrac Ltd. - 5 Old
Dock Road, Yaphank NY 11980
631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com Will
review. AD 12/06/2018:
Reviewed the report. It states that for the monitoring period: July
2018 September 2018, the
following work was performed at the site: - July 3 and September 7,
2018 Conducted Short Term
Remediation Events (STREs) on select wells. - September 17, 2018
Gauged and sampled four (4)
monitoring wells. Groundwater Monitoring: Wells Gauged: MW-1, MW-4,
MW-5, and MW-6. Wells
Containing LPH: None Groundwater Depth: 31.70 feet 32.47 feet.
Groundwater Flow: Southwesterly
Wells Sampled: MW- 1, MW-4, MW-5, and MW-6: Maximum BTEX
Concentration: 936.0 ug/L (MW-1) Maximum
MTBE Concentration: Non-detect (all wells) Total VOCs Range: 746.3
2,241.4 ug/L Recommendations:
EnviroTrac to continue with monthly STREs and quarterly sampling, with
the next groundwater
sampling event scheduled for December 2018. An Update Report
summarizing these activities will be
submitted to NYSDEC in February 2019. A Sensitive Receptor Survey will
be completed and submitted
under separate cover. AD 01/09/2019: Received the following e-mail
from Ed Russo: Ainura please
find attached a Sensitive Receptor Survey and an Update Report (which
also includes a proposed plan
to complete soil borings in the area of MW-1 to determine remaining
impacts and well as a request
for abandonment of wells that we feel are no longer needed) for the
referenced site. Let us know if
you have any questions or comments or if we are approved to move
forward. Thanks. Edward Russo -
Senior Project Manager - EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY
11980 631.924.3001 (Office)
- 631.924.5001 (Fax) - 516.523.6714 (Cell) - edr@envirotrac.com Will
review. AD 01/16/2019:
Reviewed the report. It states that for the monitoring period: October
December 2018, the following
work was performed at the site: On October 4, November 26, and
December 3, 2018 Short Term
Remediation Events (STREs) were conducted on select wells. On December
5, 2018 Gauged and sampled
four (4) monitoring wells. Groundwater Monitoring: Wells Gauged: MW-1,
MW-4, MW-5, and MW-6 Wells

DRAFT

HESS#32518 (Continued) **1000263774**

Containing LPH: None Groundwater Depth: 32.52 feet 33.11 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1, MW-4, MW-5, and MW-6 Maximum BTEX Concentration: 1,874.1 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: 308.3 4,179.1 ug/L TVOCs levels in well MW-1 increased since last GW sampling from 2,241 ppb to 4,179 ppb. In an effort to reduce contaminant mass and to obtain spill closure, Speedway/EnviroTrac propose to complete soil borings in the area of MW-1 to assess soil conditions and the vertical extent of impacts in this area. If a limited thickness of impact is observed, spill closure will be requested. If significant impact is observed during drilling, additional remedial wells will be installed to aid in localized remediation moving forward. Due to contaminant level and breakdown, as well as the locations of the wells (side-gradient of MW-1) MW-4 and MW-5, as well as their associated air sparge wells (AS-2 and AS-5), EnviroTrac is recommending abandonment of these wells. Speedway/EnviroTrac will continue with monthly STREs and quarterly groundwater sampling, with the next groundwater sampling event scheduled for March 2019. An Update Report summarizing these activities will be submitted to NYSDEC in May 2019. AD 01/17/2019: Called and spoke with Mr. Russo regarding the proposed investigation. Depth to GW at the site is around 40 feet bgs. Since Mr. Engdahl left Speedway and his replacement was not appointed yet, the approval letter should be addressed to Mr. Russo. AD 01/18/2019: Sent a correspondence to Mr. Russo approving the proposed actions: Dear Mr. Russo, The Department has reviewed the Groundwater Monitoring Update Report pertaining to the above-referenced site, submitted by EnviroTrac Ltd. on behalf of Speedway LLC. The report contains a proposal for an additional subsurface investigation in the vicinity of well MW-1 to assess soil conditions and the vertical extent of impacts in this area by advancing several soil borings, depending on site conditions, with collection of soil samples. A summary report with conclusions and recommendations for further actions will be provided to NYS DEC. If significant impact is observed during this investigation, additional wells will be installed to aid in remediation process. Based on the low or non-detect contaminant levels and locations of wells MW-4 and MW-5 and air sparge wells AS-2 and AS-5, the consultant recommended their abandonment. The Department approves the proposed soil investigation and abandonment of monitoring wells MW-4 and MW-5 and air sparge wells AS-2 and AS-5. AD 05/31/2019: Received the following e-mail from Joe Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph

DRAFT

HESS#32518 (Continued) **1000263774**

Rennie - Project Manager -
EnviroTrac Ltd. - 5 Old Dock Road, Yaphank NY 11980 631.924.3001 (Office) - 631.924.5001 (Fax) - joer@envirotrac.com Will review. AD 06/7/2019: Reviewed the report. It states that for the monitoring Period: January March 2019, the following work was performed: at the site: - January 24, February 11, and March 1, 2019 Conducted STREs on select site wells. - February 11, 2019 Abandoned two (2) monitoring wells [(MW)-4 and MW-5)] and two AS wells (AS-2 and AS-5) as per NYSDEC guidelines. - March 6, 2019 Gauged and sampled two (2) wells. Groundwater Monitoring: Wells Gauged: MW-1 and MW-6. Wells Containing LPH: None Groundwater Depth: 33.07 feet 33.55 feet. Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6. Maximum BTEX Concentration: 1,657.9 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: 325.8 4,543.4 ug/L Recommendations: The NYSDEC approved Speedway s/EnviroTrac s work plan on January 21, 2019 which proposed the completion of soil borings in the area of MW-1 to assess soil conditions. Implementation of this work plan will be done during the second quarter of 2019. Results will be summarized in the next update report. Speedway/EnviroTrac will continue with monthly STREs and quarterly groundwater sampling, with the next groundwater sampling event scheduled for June 2019. An Update Report summarizing these activities will be submitted to NYSDEC in August 2019. AD 08/23/2019: Received the following e-mail from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 -

monitoring period: April June 2019, the following work was performed at the site: - April 11, May 7, and June 4, 2019 Conducted STREs on select wells. - June 21, 2019 Gauged and sampled two (2) MWs. - June 25 and 26, 2019 Installed three (3) injection wells (IW-1, IW-2, and IW-3) as per the 01/21/19 NYSDEC approved work plan. Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 32.58 feet 32.98 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum BTEX Concentration: 965.1 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: 6.8 1,478.5 ug/L Remediation: As per the work plan that was included within the 2018 4th Quarter Update Report on 01/09/2019 to the NYSDEC (which was subsequently approved on 01/21/2019), EnviroTrac successfully installed three (3) injection wells

DRAFT

HESS#32518 (Continued) **1000263774**

in June 2019. During well installations, soil conditions were assessed to determine the extent of impacts near existing monitoring well MW-1. Soil samples at each injection well were collected and analyzed for VOCs and SVOCs and compared to NYSDEC CP-51 Soil Cleanup Levels. Based on field observations/soil data, EnviroTrac completed injections of PetroCleanze and RegenOx into IW-1, IW-2, and IW-3 followed by enhanced fluid recovery (EFR) events utilizing a vac-truck in July and August 2019 to aid in the remediation of localized areas of groundwater impact that remain. Injections and EFR events will continue on a monthly basis and will be summarized in quarterly update reports. Recommendations: Speedway/EnviroTrac will continue with monthly STREs and quarterly groundwater sampling, with the next groundwater sampling event scheduled for September 2019. An Update Report summarizing these activities will be submitted to NYSDEC in November 2019. AD 11/26/2019: Received the following email from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 -

when impacted soils were encountered during an underground storage tank (UST) upgrade project in August 1998. Removed thirty (30) 550-gallon gasoline, three (3) 4,000-gallon gasoline, one (1) 2,000-gallon gasoline, one (1) 4,000-gallon diesel, two (2) 2,000-gallon gasoline, two (2) 550-gallon waste water UST s and associated remote fills, product piping, and dispensers. During this project 1,006 tons of impacted soils were removed off site for disposal. The report states that for the reported monitoring period: July September 2019, the following work was performed at the site: - July 15 & August 7, 2019 Completed injections of RegenOx Parts A and B (PetroCleanze) into the three (3) injection wells (IWs). - July 22, 2019 Performed a post-injection gauging event on select on-site wells. - July 31 & August 21, 2019 Performed Enhanced Fluid Recovery (EFR) events on select on-site wells. - September 20, 2019 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 32.37 feet 32.78 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum BTEX Concentration: 66.6 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: 164.4 353.9 ug/L Conclusions and recommendations: The NYSDEC approved Injection Work Plan was implemented in June 2019. EnviroTrac will continue with quarterly

DRAFT

HESS#32518 (Continued) **1000263774**

groundwater sampling, with
the next sampling event scheduled for December 2019. Injections, post-injection gauging, and EFR
events will continue as per the Injection Work Plan schedule. An Update Report summarizing these
activities will be submitted to NYSDEC in February 2020. AD 02/26/2020: Received the following
email from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above
referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email:
joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD
03/12/2020: Reviewed the report. It states that for the monitoring period: October December 2019,
the following work was performed at the site: - October 1 & November 14, 2019 Completed injections
of RegenOx Parts A and B (PetroCleanze) into the three (3) injection wells (IWs). - October 11 &
November 21, 2019 Performed a post-injection gauging event on select on-site wells. - October 18 &
December 4, 2019 Performed EFR events on select on-site wells. - December 19, 2019 Gauged and
sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells
Containing LPH: None Groundwater Depth: 32.01 feet 32.42 feet Groundwater Flow: Southwesterly Wells
Sampled: MW- 1 and MW-6 Maximum BTEX Concentration: 11.5 ug/L (MW-1) Maximum MTBE Concentration:
Non-detect (all wells) Total VOCs Range: ND 44.0 ug/L Recommendations: EnviroTrac will continue
with quarterly groundwater sampling, with the next sampling event scheduled for March 2020.
Injections, post-injection gauging, and EFR events will also continue. An Update Report summarizing
these activities will be submitted to NYSDEC in May 2020. The site is ready for spill closure
petition, according to the latest results. AD 05/27/2020: Received the following email from Mr.
Rennie: Ainura - Please find attached the most recent Update Report for the above referenced
location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email:
joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD
06/12/2020: Reviewed the report. It states that this spill was reported when impacted soils were
encountered during an UST upgrade project in August 1998. Removed thirty (30) 550-gallon gasoline,
three (3) 4,000-gallon gasoline, one (1) 2,000-gallon gasoline, one (1) 4,000-gallon diesel, two
(2) 2,000-gallon gasoline, two (2) 550-gallon waste water USTs and associated remote fills, product
piping, and dispensers. During this project 1,006 tons of impacted soils were removed off site for
disposal. The following site remediation activities were historically performed at the site: -

DRAFT

HESS#32518 (Continued) **1000263774**

April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge
(AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze)
injections and Enhanced Fluid Recovery (EFR) events commenced. Current Site Status: Active station.
For the reported monitoring period: January March 2020, the following work was performed at the
site: - January 24 & March 11, 2020 Completed injections of RegenOx Parts A and B (PetroCleanze)
into the three (3) injection wells (IWs). - January 29, 2020 Performed an EFR event while
simultaneously conducting an STRE on select on-site wells. - February 20, 2020 Conducted an STRE on
select on-site wells. - March 25, 2020 Performed post injection EFR events on select on-site wells.
- March 30, 2020 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells
Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 32.12 feet 32.54 feet
Groundwater Flow: Southwesterly Wells Sampled: MW-1 and MW-6 Maximum BTEX Concentration: 85.9 ug/L
(MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: ND 232.9 ug/L
Recommendations: EnviroTrac will continue with quarterly groundwater sampling, with the next
sampling event scheduled for June 2020. Remediation will continue through Q2 and then post remedial
groundwater sampling to monitor for rebounding will happen Q3-Q4 with a 2021 Q1 closure request if
no significant rebounding occurs. An Update Report summarizing these activities will be submitted
to NYSDEC in August 2020. AD 08/18/2020: Received the following email from Ms. Quell: Hi Ainura,
Attached is the 2nd Quarter 20202 Project Summary Report for the Sunoco Service Station located
188-06 Hillside Avenue, Hollis, NYSDEC Spill # 9808686. I sent this to you yesterday, but I was
referencing the wrong site. I apologize for the confusion. Feel free to contact me if you have any
questions or concerns. Sincerely Erin Quell Project Manager Environmental Assessment & Remediations
Quell@Enviro-Asmnt.com Phone: 1-888-EAR-6789 ext. 158 Fax: 631-447-6497 Will review. AD 09/17/2020:
Reviewed the 2nd quarter 2020 report. It states that groundwater samples were collected from select
monitoring wells on June 05, 2020. Samples were submitted to Eurofins Lancaster Laboratories
Environmental, LLC for analysis of NYSDEC CP-51 compounds, according to EPA Method 8260. Prior to
sampling, each of the wells were gauged for depth to groundwater. Purged groundwater was field
screened for dissolved oxygen, temperature, pH, oxidation reduction potential, and conductivity.
During this monitoring period, no liquid phase hydrocarbons (LPH) were detected in the site wells.
Analysis of the groundwater samples indicates the presence of 7 VOC

DRAFT

HESS#32518 (Continued) **1000263774**

chemicals. All are detected above TOGS 1.1.1 Class GA water quality standards and guidance value limits.1. The highest level of total BTEX and total VOCs were observed in MW-3 at concentrations of 2,403 ug/L. Benzene was not detected in any of the wells sampled. Wells Total BTEX Total VOCs (ug/L) MW3 2,403 3,247 SVE1D 31 57 SVE3D 1 1 The current plan is to evaluate COC concentrations in groundwater, to determine if additional remediation near MW3 is warranted. Groundwater sampling of MW-3, SVE-1D and SVE-3D will continue on a quarterly basis. AD 08/28/2020: Received the following email from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD 10/05/2020: Reviewed the report. It states that the spill was reported due to impacted soils encountered during an underground storage tank (UST) upgrade project in August 1998. Removed thirty (30) 550-gallon gasoline, three (3) 4,000-gallon gasoline, one (1) 2,000-gallon gasoline, one (1) 4,000-gallon diesel, two (2) 2,000-gallon gasoline, two (2) 550-gallon waste water USTs and associated remote fills, product piping, and dispensers. During this project 1,006 tons of impacted soils were removed off site for disposal. The following remediation activities were historically performed at the ssite: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR) events commenced. Current Site Status: Active station. For the reported monitoring period: April June 2020, the following work was performed at the site: - April 22, 2020 Completed injections of RegenOx Parts A and B (PetroCleanze) into the three (3) injection wells (IWs). - April 30, 2020 Performed a post injection well gauging event on select wells. - May 8, 2020 Performed an EFR event on select on-site wells. - June 3, 2020 Conducted an STRE on select on-site wells. - June 9, 2020 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 32.20 feet 32.60 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum BTEX Concentration: 594.3 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: ND 1,089.4 ug/L Recommendations: EnviroTrac will continue with quarterly groundwater sampling, with the next sampling event scheduled for September 2020. Post remedial groundwater

DRAFT

HESS#32518 (Continued) **1000263774**

sampling to monitor for rebounding will be completed in September and December 2020. If results are favorable, closure will be requested following the December 2020 sampling event. An Update Report summarizing activities completed from July through September 2020 will be submitted to NYSDEC in November 2020. AD 11/30/2020: Received the following email fro Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD 12/30/2020: Reviewed the report. It states that the following remediation activities were performed historically at the site: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR) events commenced. Current site status: Active station For the monitoring period: July September 2020, the following work was performed at the site: - July 3, September 23, and September 30, 2020 Conducted an STRE on select on-site wells. September 30, 2020 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 31.89 feet 32.26 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum BTEX Concentration: 1,062.7 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: 90.5 2,386.8 ug/L Recommendations: EnviroTrac will continue with quarterly groundwater sampling, with the next sampling event scheduled for December 2020. Post remedial groundwater sampling to monitor for rebounding will be completed in September and December 2020. If results are favorable, closure will be requested following the December 2020 sampling event. An Update Report summarizing activities completed from October through December 2020 will be submitted to NYSDEC in February 2021. AD 02/26/2021: Received the following email from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD 03/30/2021: Reviewed the report. It states that the following remediation activities were performed historically at the site: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR)

DRAFT

HESS#32518 (Continued) **1000263774**

events commenced. Current site
status: Active station For the monitoring period: October December
2020 the following work was
performed at the site: - December 10, 2020 Performed an EFR event
while simultaneously conducting
an STRE on select on-site wells. - December 29, 2020 Gauged and
sampled two (2) monitoring wells
(MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells
Containing LPH: None Groundwater
Depth: 31.81 feet 32.20 feet Groundwater Flow: Southwesterly Wells
Sampled: MW-1 and MW-6 Maximum
BTEX Concentration: 531 ug/L (MW-1) Maximum MTBE Concentration:
Non-detect (all wells) Total VOCs
Range: 1,424.4 1,810.5 ug/L Recommendations: EnviroTrac will continue
with quarterly groundwater
sampling, with the next sampling event scheduled for March 2021. An
Update Report summarizing
activities completed from January through March 2021 will be submitted
to NYSDEC in May 2021. AD
05/26/2021: Received the following email from Mr. Rennie: Ainura -
Please find attached the most
recent Update Report for the above referenced location. Joseph Rennie
Project Manager EnviroTrac
Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road
Yaphank, NY 11980 -

following remediation activities were performed historically at the
site: - April 2010 Short-Term
Remediation Events (STREs) via soil vapor extraction (SVE) and air
sparge (AS) on select on-site
wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze)
injections and Enhanced Fluid
Recovery (EFR) events commenced. Current site status: Active station
For the monitoring period:
January March 2021, the following work was performed at the site: -
January 14, 2021 Performed an
EFR event while simultaneously conducting an STRE on select on-site
wells. - February 10, 2021
Performed an EFR event while simultaneously conducting an STRE on
select on-site wells. - March 3,
2021 Performed an EFR event while simultaneously conducting an STRE on
select on-site wells. -
March 15, 2021 Gauged and sampled two (2) monitoring wells (MWs).
Groundwater Monitoring: Wells
Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth:
32.00 feet 32.51 feet
Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum
BTEX Concentration: 352 ug/L
(MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs
Range: 23.9 1,080.9 ug/L
Recommendations: EnviroTrac will continue with quarterly groundwater
sampling, with the next
sampling event scheduled for June 2021. An Update Report summarizing
activities completed from
April through June 2021 will be submitted to NYSDEC in August 2021. AD
08/27/2021: Received the

DRAFT

HESS#32518 (Continued) **1000263774**

following email from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD 09/13/2021: Reviewed the report. It states that the following remediation activities were performed historically at the site: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR) events commenced. Current site status: Active station For the monitoring period: April June 2021, the following work was performed at the site: - April 16, 2021 Performed an EFR event while simultaneously conducting an STRE on select on-site wells. - June 2, 2021 Performed an STRE on select on-site wells. - June 14, 2021 Performed an STRE on select on-site wells. - June 21, 2021 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 31.30 feet 32.33 feet Groundwater Flow: Southwesterly Wells Sampled: MW-1 and MW-6 Maximum BTEX Concentration: 333.5 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: 48.5 820.4 ug/L Wells 09/2020 12/2020 03/2021 06/2021 (in TVOCs ug/L) MW-1 2,386 1,810 1080 820 MW-6 90 1420 21 48 Recommendations: EnviroTrac will continue with quarterly groundwater sampling, with the next sampling event scheduled for September 2021. An Update Report summarizing activities completed from July through September 2021 will be submitted to NYSDEC in November 2021. AD 11/28/2021: Received the following email from Mr. Rennie: Ainura - Please find attached the most recent Update Report for the above referenced location. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 - https://envirotrac.com Will review. AD 12/27/2021: Reviewed the report. It states that the following remediation activities were performed historically at the site: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR) events commenced. Current site status: Active station For the monitoring period: July September 2021, the following work was performed at the site: - September 22, 2021 Performed an STRE on select on-site wells. - September 30, 2021 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and

DRAFT

HESS#32518 (Continued) **1000263774**

MW-6 Wells Containing LPH:
None Groundwater Depth: 31.40 feet 31.80 feet Groundwater Flow:
Southwesterly Wells Sampled: MW- 1
and MW-6 Maximum BTEX Concentration: 366.3 ug/L (MW-1) Maximum MTBE
Concentration: Non-detect (all
wells) Total VOCs Range: 612.2 660.3 ug/L Recommendations: EnviroTrac
will continue with quarterly
groundwater sampling, with the next sampling event scheduled for
December 2021. An Update Report
summarizing activities completed from October through December 2021
will be submitted to NYSDEC in
January 2022. AD 01/13/2021: Received the following email from Ed
Russo: Ainura good morning. If
you are available, we d like to have a very brief discussion about
these 2 sites. Please let us
know if you have time today or in the next few days. Thanks. Edward
Russo Senior Project Manager
EnviroTrac Ltd. phone: 631.924.3001 - mobile: 516.523.6714 - email:
edr@envirotrac.com 5 Old Dock
Road Yaphank, NY 11980 - https://envirotrac.com Sent him a response
with available times. Later in
the day received a call from Ed. He informed me that Speedway selling
these two sites to J Group,
which is planning to redeveloped the sites and they already filed for
the participation in
Brownfield program. Asked him to put this info into email and send it
to me. Received the following
email from Ed: Ainura good morning. As discussed, Speedway is in the
process of selling these
properties to a developer that is working with the NYSDEC to enter the
sites into the Brownfields
program, with plans to remove all USTs and commence redevelopment of
the sites in 2022. As such, we
would like your permission to discontinue localized remediation at
both sites (chemical
injections/vac truck work at the Manhattan site and localized
injections/short term remediation
events at the Brooklyn site). We will continue to groundwater sample
the sites and report to you
until the Brownfield Cleanup Agreements are finalized. If for any
reason the property transactions
fall through or the site(s) aren t accepted into the Brownfields
program, we will start localized
remediation again. Please confirm that you are ok with this plan.
Thanks. Edward Russo Senior
Project Manager EnviroTrac Ltd. phone: 631.924.3001 - mobile:
516.523.6714 - email:
edr@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 -
https://envirotrac.com AD 02/23/2022:
Received the following email from Joe Rennie: Ainura - Please find
attached the most recent Update
Report for the above referenced location. Joseph Rennie Project
Manager EnviroTrac Ltd. phone:
631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY
11980 -

DRAFT

HESS#32518 (Continued) **1000263774**

following remediation activities were performed historically at the site: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR) events commenced. Current site status: Active station For the monitoring period: October December 2021, the following work was performed at the site: - December 29, 2021 Gauged and sampled two (2) monitoring wells (MWs). Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth: 32.11 feet 37.51 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum BTEX Concentration: 1.7 ug/L (MW-1) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range: ND 150.3 ug/L Recommendations: Speedway is in contract to sell this property to a developer that plans to enter the site into the Brownfield Cleanup Program. As such, localized remediation is currently on hold. If the sale of the property falls through, EnviroTrac will discuss options to move Spill #98-30002 to closure with NYSDEC. AD 05/25/2022: Received the following email from Mr. Rennie: Ainura - Please find attached the latest update report for the above referenced location. Please note, this property has been sold and accepted into the Brownfields Cleanup Program (BCA #C224349). No further sampling or remedial actions are planned by EnviroTrac/Speedway moving forward. Joseph Rennie Project Manager EnviroTrac Ltd. phone: 631.924.3001 - email: joer@envirotrac.com 5 Old Dock Road Yaphank, NY 11980 -

Impacted soils encountered during an underground storage tank (UST) upgrade project in August 1998. Removed thirty (30) 550-gallon gasoline, three (3) 4,000-gallon gasoline, one (1) 2,000-gallon gasoline, one (1) 4,000-gallon diesel, two (2) 2,000-gallon gasoline, two (2) 550-gallon wastewater USTs and associated remote fills, product piping, and dispensers. During this project 1,006 tons of impacted soils were removed off site for disposal. The following remediation activities were performed historically at the site: - April 2010 Short-Term Remediation Events (STREs) via soil vapor extraction (SVE) and air sparge (AS) on select on-site wells commenced. - July 2019 RegenOx Parts A and B (PetroCleanze) injections and Enhanced Fluid Recovery (EFR) events commenced. Current site status: Active station For the monitoring period: January March 2022, the following work was performed at the site: - March 8, 2022 Gauged and sampled two

DRAFT

HESS#32518 (Continued) **1000263774**

(2) monitoring wells (MWs).
Groundwater Monitoring: Wells Gauged: MW-1 and MW-6 Wells Containing LPH: None Groundwater Depth:
32.07 feet 32.47 feet Groundwater Flow: Southwesterly Wells Sampled: MW- 1 and MW-6 Maximum BTEX
Concentration: 1.3 ug/L (MW-6) Maximum MTBE Concentration: Non-detect (all wells) Total VOCs Range:
7.7 61.7 ug/L Recommendations: This property has been sold and accepted into the Brownfields
Cleanup Program (BCA #C224349). No further sampling or remedial actions are planned by
EnviroTrac/Speedway moving forward. AD 12/12/2023: COC package sent out for review. COC expected to
be executed by 12/31/23. Site has achieved a Conditional Track 1 cleanup. Remediation has included
sitewide excavation from 8 - 14 ft-bgs, removal of an additional 5 unregistered USTs, installation
of a passive SSDS, and 5 monitoring well injections of AP-pH which will continue to be monitored
under a recorded Easement and an approved SMP.

Remarks: STAINING ON SOIL. SAMPLES SUBMITTED TO THE LAB.

All Materials:

Site ID:	65126
Operable Unit ID:	1073908
Operable Unit:	01
Material ID:	309027
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	HESS STATION
Address:	2880 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1006577 / 2010-10-20
Facility ID:	1006577
Facility Type:	ER
DER Facility ID:	62609
Site ID:	439937
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-09-16
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2010-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported

DRAFT

HESS#32518 (Continued) **1000263774**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-17
Spill Record Last Update:	2010-10-20
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ED RUSSO
Latitude:	40.6769640
Longitude:	-73.8879310
DEC Memo:	Sangesland spoke to Joe Rennie at EnviroTrak. He said the site was MW7 on the West side of Barbey St, Brooklyn. At the time person sampling the well said they had a trace amount of oil on the outside of the bailer. 8270 results showed minor hits for the benzos and 8260 was Non-Detect. No additional information was available.
Remarks:	Caller advised that unknown material possibly fuel oil spilled in a monitoring well. Caller also advising that the material possibly came from the adjacent property at 2840 atlantic ave.

All Materials:

Site ID:	439937
Operable Unit ID:	1190566
Operable Unit:	01
Material ID:	2185594
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

US AIRS MINOR:

Envid:	1000263774
Region Code:	02
Programmatic ID:	AIR NY0000002610500153
Facility Registry ID:	110001572691
D and B Number:	Not reported
Primary SIC Code:	5541
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610500153
Facility Registry ID:	110001572691
Air Operating Status Code:	OPR

DRAFT

HESS#32518 (Continued) **1000263774**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001572691

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000263774
Registry ID: 110001572691

DFR URL:
Name: HESS#32518
Address: 2880 Atlantic Avenue
City,State,Zip: BROOKLYN, NY 11207

NY MANIFEST:
EPA ID: NYD982185670
Country: USA
Name: Merit Oil
Address: 2880 ATLANTIC AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207-2725
Zip 4: Not reported
Location Address 1: 2880 ATLANTIC AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207

DRAFT

HESS#32518 (Continued) **1000263774**

Location Zip 4: 2725
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Merit Oil
Mailing Contact: Nelson Flores
Mailing Address 1: 2880 ATLANTIC AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11207
Mailing Zip 4: 2725
Mailing Country: USA
Mailing Phone: 5164547677

Manifest Data:
Document ID: NYG1058085
Manifest Status: Not reported
Trans1 State ID: PD1011NY
Year: 1998
Trans2 State ID: Not reported
Generator Ship Date: 12/22/1998
Trans1 Recv Date: 12/22/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/22/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982185670
Trans1 EPA ID: NYD077444263
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00250
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

DRAFT

AM273 **2864 ATLANTIC AVENUE REDEVELOPMENT** **NY BROWNFIELDS** **S118704052**
West **2864 ATLANTIC AVENUE** **NY E DESIGNATION** **N/A**
1/4-1/2 **BROOKLYN, NY 11207** **NY NYC OER**
0.378 mi. **NY NYC LAND USE**
1998 ft. **Site 2 of 2 in cluster AM**

Relative:
Higher

Actual:
39 ft.

BROWNFIELDS:

Name:	2864 ATLANTIC AVENUE REDEVELOPMENT
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Program:	BCP
Site Code:	629738
Acres:	0.415
HW Code:	C224349
SWIS:	2401
Town:	New York City
Record Added Date:	11/24/2021
Record Updated Date:	12/28/2023
Update By:	MSBABICK
Site Description:	Site Location: The 0.415-acre site is located at 2864 Atlantic Avenue in the East New York neighborhood of Brooklyn, NY, and is designated as Brooklyn Tax Block 3965, Lot 11. The site is bounded to the north by Atlantic Avenue, to the east by Jerome Street, to the south by 2-story residential buildings, and to the west by Barbey Street followed by another BCP site (Site No. C224255). The Long Island Railroad (LIRR) is located approximately 40 feet to the north of the site, beneath Atlantic Avenue. Site Features: Construction for a new mixed-use residential/commercial, mixed-income building with a cellar is currently ongoing. Current Zoning and Land Use: The site is zoned R8-A for residential use and includes a commercial C2-4 overlay. The surrounding properties are currently used for commercial, residential, and warehousing/manufacturing purposes. The nearest residential buildings immediately adjoin the Site to the south. The proposed mixed-use commercial/residential development of this property is consistent with the current zoning. As a result of the CEQR process, Block 3965 Lot 11 was assigned an environmental E-Designation (E-366) - East New York Rezoning Action, for hazardous materials, noise (window wall attenuation & alternative means of ventilation), and air (HVAC fuel limited to natural gas) resulting from a City Environmental Quality Review (CEQR) effective 20 April 2016 (CEQR #15DCP102K). Satisfaction of the E-Designation requirements is subject to review and approval by the New York City Mayor's Office of Environmental Remediation (NYCOER) to obtain a Notice to Proceed (NTP) or a Notice of No Objection (NNO) prior to obtaining building permits. Past Land Use: The site was first developed in the early 1950s with a garage and two gasoline tanks. By 1965, the entire site was occupied by a gas filling station that was developed with an overhead canopy and a one-story office building. The site remained unchanged until 2022 when all on-site fuel tanks were decommissioned and the gas station was demolished as part of the NYSDEC approved Interim Remedial Measures Work Plan (IRMWP). Records for historic bulk petroleum storage (PBS No. 2-297747) list a total of forty-three former underground storage tanks (USTs) for the site. Five additional unregistered USTs were discovered during the 2023 remedial activities and have since been removed. Site Geology and Hydrogeology: As of the 2023 remedial activities, nearly all urban fill has been excavated and removed from the site. The site has been backfilled with approximately 225 tons of 3/4 clean stone from the building foundation sub-base at 13 feet below ground surface

DRAFT

2864 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S118704052**

Env Problem:

(ft-bgs)up to 14 ft-bgs. This layer of clean stone is underlain by a native layer consisting of brown to orange-brown coarse to fine sand with varying amounts of silt and gravel and intermittent clay lenses. Bedrock underlying the site is present at depths greater than 100 ft-bgs and is part of the Raritan formation consisting of unconsolidated coastal plain deposits. Groundwater was encountered at approximately 25 to 35 ft-bgs and groundwater flows to the southeast. Remediation at the site is complete. Prior to the 2023 remediation, the primary contaminants of concern for the site were SVOCs and lead in soil, SVOCs and petroleum-related VOCs in groundwater, and petroleum-related VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for Unrestricted Use. Residual contamination remaining in groundwater and soil vapor is being managed under a Site Management Plan. Prior to the 2023 Remediation: Soil One VOC of concern, total xylene, was detected at a maximum concentration of 1.7 parts per million (ppm), exceeding the Unrestricted Use Soil Cleanup Objective (UUSCO) of 0.26 ppm and the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.6 ppm. Several SVOCs were detected at concentrations exceeding the UUSCOs and PGWSCOs, including benzo(a)anthracene (max. 7.1 ppm, UUSCO and PGWSCO is 1 ppm), benzo(b)fluoranthene (max. 8.3 ppm, UUSCO is 1 ppm, PGWSCO is 1.7 ppm), benzo(k)fluoranthene (max. 2.2 ppm, UUSCO is 0.8 ppm, PGWSCO is 1.7 ppm), and chrysene (max. 7.4 ppm, UUSCO and PGWSCO is 1 ppm). For metals in soil, lead was detected at a maximum concentration of 932 ppm (UUSCO is 64 ppm). For PFAS compounds, perfluorooctanesulfonic acid (PFOS) was detected at a maximum concentration of 1.25 parts per billion (ppb), exceeding the guidance value for unrestricted use of 0.88 ppb. Data did not indicate any off-site impacts in soil related to this site. Groundwater Several VOCs were identified in groundwater samples at concentrations above the Ambient Water Quality Standards (AWQSs), including 1,2,4-trimethylbenzene (max. 3,800 ppb, AWQS is 5 ppb), 1,3,5-trimethylbenzene (max. 760 ppb, AWQS is 5 ppb), ethylbenzene (max. 1,500 ppb, AWQS is 5 ppb), o-xylene (max. 1,300 ppb, AWQS is 5 ppb), p/m-xyelene (max. 5,200 ppb, AWQS is 5 ppb), and benzene (max. 22 ppb, AQWS is 1 ppb). Several SVOCs were identified at concentrations exceeding the AWQSs, including benzo(a)anthracene (max. 0.12 ppb, AWQS is 0.002 ppb), benzo(b)fluoranthene (max. 0.18 ppb, AWQS is 0.002 ppb), benzo(k)fluoranthene (max. 0.06 ppb, AWQS is 0.002 ppb), and chrysene (max. 0.13 ppb, AWQS is 0.002 ppb). Several dissolved metals were detected in groundwater, including iron, manganese, and sodium. These are naturally occurring metals and are not considered to be site-related contaminants. PFOS and perfluorooctanoic acid (PFOA) were detected in groundwater at maximum concentrations of 105 parts per trillion (ppt) and 92.1 ppt, respectively. These concentrations exceed the applicable Maximum Contaminant Level (drinking water standard) of 10 ppt each. Data did not indicate any off-site impacts in groundwater-related to this site. Soil Vapor Several petroleum-related VOCs were detected in soil vapor throughout the site, including benzene (max. 69.6 micrograms per cubic meter (ug/m3)), toluene (max. 288 ug/m3), ethylbenzene (max. 34 ug/m3), total xylenes (max. 29.4 ug/m3), 2,2,4-trimethylpentane (max. 27,200 ug/m3), n-hexane (max. 9,060 ug/m3), 2-butanone (max. 2,140 ug/m3), heptane (max. 1,750 ug/m3), 1,2,4-trimethylbenzene (max. 29.6 ug/m3), and 1,3,5-trimethylbenzene (max. 7.18 ug/m3). Data did not indicate any off-site impacts in soil vapor related to this site.

DRAFT

2864 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S118704052**

Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining contamination at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2022-01-25 12:53:00
Record Upd:	2023-12-12 16:37:00
Updated By:	MSBABICK
Own Op:	1
Sub Type:	P03
Owner Name:	Jacob Kohn
Owner Company:	2864 Atlantic Realty LLC
Owner Address:	40 Oser Avenue, Suite 4
Owner Addr2:	Not reported
Owner City,St,Zip:	Hauppauge, NY 11788
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Jacob Kohn
Owner Company:	2864 Atlantic Realty LLC
Owner Address:	40 Oser Avenue, Suite 4
Owner Addr2:	Not reported
Owner City,St,Zip:	Hauppauge, NY 11788
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Melinda Perkins
Owner Company:	Brooklyn Community Board 5
Owner Address:	127 Pennsylvania Avenue, 2nd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Rowshon A. Perveen
Owner Company:	Cypress Hills Library
Owner Address:	1197 Sutter Ave. at Crystal St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
HW Code:	C224349
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(k)fluoranthene

DRAFT

2864 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S118704052**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN

DRAFT

2864 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S118704052**

Waste Code:	Not reported
HW Code:	C224349
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-297747
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2022-09-22 13:23:00
Record Updated:	2022-09-22 13:23:00
Updated By:	KXLIU
Crossref ID:	9830002
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2023-08-29 11:26:00
Record Updated:	2023-08-29 11:26:00
Updated By:	MSBABICK
Crossref ID:	C224349-03-22
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2023-08-29 11:24:00
Record Updated:	2023-08-29 11:24:00
Updated By:	MSBABICK
Crossref ID:	2023000304719
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2023-12-04 10:02:00
Record Updated:	2023-12-04 10:02:00
Updated By:	MSBABICK

E DESIGNATION:

Name:	LOT 11,TAXBLOCK 3965
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	11
Tax Block:	3965
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	2886 ATLANTIC AVENUE
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676977
Longitude:	-73.888458
OER Project Numbers:	22TMP0805K,22EHAN181K

DRAFT

2864 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S118704052**

BBL:	3039650011
OER Program:	E/RD (Review), State BCP
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	5
Community Board:	37
Council District:	1170
Census Tract:	3327107
BIN:	3039650011
NTA:	East New York

NYC LAND USE:

Name:	Not reported
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6767760
Longitude:	-73.8880767
Type Of Ownership Code:	Not reported
Owner Name:	2864 ATLANTIC REALTY LLC
Borough:	BK
Tax Block:	3965
Tax Lot:	11
Community District:	305
Census Tract 2020:	3117000
Census Block 2020:	31170002006
Census Tract 2010:	1170
Census Block 2010:	2006
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R8A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D7: Elevator Apartments - Semi-Fireproof With Stores
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	18111
Total Building Floor Area:	154888
Commercial Floor Area:	16043
Residential Floor Area:	138845
Office Floor Area:	0

DRAFT

2864 ATLANTIC AVENUE REDEVELOPMENT (Continued) **S118704052**

Retail Floor Area:	5293
Garage Floor Area:	10750
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	10.0000000
Residential Units:	183
Total Units:	184
Lot Frontage:	200.9200000
Lot Depth:	99.9200000
Building Frontage:	190.0000000
Building Depth:	90.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	448200.00000
Assessed Total Value:	448200.00000
Exempt Total Value:	0.00000
Year Built:	2023
Year Altered 1:	2023
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	8.55000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039650011.00000000
Condominium Number:	Not reported
Census Tract 2:	1170
X Coordinate:	1015295
Y Coordinate:	185864
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 003
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

DRAFT

274
ENE
1/4-1/2
0.391 mi.
2064 ft.

ATLANTIC AVE AT CARLTON
ATLANTIC AVE AT CARLTON
BROOKLYN, NY

NY LTANKS **S102619286**
N/A

Relative:
Higher

Actual:
33 ft.

LTANKS:

Name:	ATLANTIC AVE AT CARLTON
Address:	ATLANTIC AVE AT CARLTON
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9701786 / 2003-02-24
Facility ID:	9701786
Site ID:	330576
Spill Date:	1997-05-10
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-05-10
CID:	322
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-10
Spill Record Last Update:	2003-02-24
Spiller Name:	KEVIN HEATHER
Spiller Company:	MYSTIC TRANSPORTATION
Spiller Address:	1901 STEINWAY ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	265901
Latitude:	40.6776799
Longitude:	-73.8732500
DEC Memo:	Not reported
Remarks:	TANK WAS LEAKING FROM TOP OF TANK - SPILL INTO STREET - FD ON SCENE AND SPILL CLEANED UP

All Materials:

Site ID:	330576
Operable Unit ID:	1044397
Operable Unit:	01
Material ID:	338329
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

DRAFT

275
SE
1/4-1/2
0.410 mi.
2164 ft.

318 FOUNTAIN AVE
318 FOUNTAIN AVE
BROOKLYN, NY

NY LTANKS **S102672188**
N/A

Relative:
Lower

Actual:
18 ft.

LTANKS:

Name:	318 FOUNTAIN AVE
Address:	318 FOUNTAIN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9303855 / 1993-06-25
Facility ID:	9303855
Site ID:	112210
Spill Date:	1993-06-25
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	1993-06-25
SWIS:	2401
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-06-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-06-28
Spill Record Last Update:	1993-07-20
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	98027
Latitude:	40.6719111
Longitude:	-73.8745712
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CAMMISA.
Remarks:	CONTAINED ON SIDEWALK SORBENT APPLIED AND WILL P/U.

All Materials:

Site ID:	112210
Operable Unit ID:	985575
Operable Unit:	01
Material ID:	397396
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

276
ESE
1/4-1/2
0.421 mi.
2224 ft.

1199 SUTTER AVENUE
1199 SUTTER AVENUE
BROOKLYN, NY 11208

NY SHWS **S109583525**
NY BROWNFIELDS **N/A**
NY Spills
NY NYC LAND USE

Relative:
Lower

Actual:
19 ft.

SHWS:

Name:	1199 SUTTER AVENUE
Address:	1199 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Program:	HW
Site Code:	434283
Classification:	N
Region:	2
Acres:	0.530
HW Code:	224141
Record Add:	05/03/2010
Record Upd:	06/13/2013
Updated By:	BXANDERS

Site Description: Location: The site is specifically known as 1199-1221 Sutter Avenue in a mixed residential / commercial area of Brooklyn. Site Features: The site occupies about half of a city block on the north side of Sutter Avenue. Approximately one-half of the site is occupied by a one-story building divided into five separate units used for commercial and office purposes. A dry cleaner establishment formerly occupied the eastern-most unit. The former location of the dry cleaner is presently occupied by a self-service laundromat. The laundromat unit is underlain with a basement segmented with utilities, storage and several rooms. The other units also have basements. The adjacent unit is a grocery store that uses their basement as a warehouse. Current Zoning/Use: The site is within an R5 (residential) zoned area. The site is zoned C1-2 (commercial) as are the properties along the north side of a seven-block stretch of Sutter Avenue. Historic Uses: The structures on the site were constructed in 1957 and were the original development on the property. A dry cleaning facility had operated on the site for many years. Site Geology and Hydrogeology: The property is located within the Pavement and Buildings-Flatbush-Riverhead Series Soil Map Unit, which is described as anthropogenic urban fill overlying glacial out wash deposits and characterized as a sandy loam. The groundwater table is approximately 13 feet below grade and is characterized as Class GA indicating it as a potential source of potable water. Groundwater flows south. Groundwater is not utilized as a source of potable water at site.

Env Problem: Nature and Extent of Contamination: A limited Phase II conducted in 2009 found the dry cleaning solvent tetrachloroethene (PCE) and its daughter products trichloroethene (TCE) and cis-1,2-dichloroethene (DCE) at elevated concentrations in groundwater. Permanent monitoring wells were constructed in 2009 and sampled before (August 2009) and after (November 2009) a remedial action consisting of potassium permanganate injections into on-site groundwater. The data are inconclusive as to the effectiveness of the injections. A site characterization investigation was conducted by Associated Environmental Services under NYSDEC oversight in July 2011. PCE and its daughter products remain above groundwater standards in the preexisting monitoring wells constructed during the Phase II investigation. PCE concentrations ranged from below its standard of 5 ppb to a maximum concentration of 470 ppb in MW-4. MW-4 is located in the basement of the former location of the dry cleaner. TCE and DCE

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

were present in some wells and non-detect in others. The new down-gradient monitoring well (MW-5) located across Sutter Avenue had PCE, TCE and DCE at respective concentrations of 98 ppb, 5.2 ppb and 9.8 ppb. The investigation found tetrachloroethene (PCE) and trichloroethene (TCE) in indoor air in the basement of the laundromat (former dry cleaner). Elevated concentrations of PCE, TCE, cis-1,2-dichloroethene (DCE) and vinyl chloride were observed in sub-slab vapor. The indoor air sample had PCE and TCE at 68.5 micrograms per cubic meter (ug/M3) and 1.27 ug/M3 respectively. Respective sub-slab concentrations of PCE, TCE, DCE and vinyl chloride were 428,000 ug/M3, 9,730 ug/M3, 4,220 ug/M3 and 795 ug/M3. The elevated concentrations of these chlorinated VOCs in soil vapor present a significant threat to human health and indicate the presence of an on-site source. Also present in the sub-slab vapor were chloroform, dichloroethene, ethylbenzene, freon 113, styrene and toluene. The highest concentrations of contaminants in groundwater were found in a well constructed in the laundromat. PCE, TCE and DCE were dtected at the the respective concentrations of 470 parts per billion (ppm), 14 ppb and 4.3 ppb. Soil data are limited, but two soil borings behind the laundromat had PCE and TCE above their respective unrestricted soil cleanup objectives (USCOs) parts per million (ppm). DCE was also detected above its USCO in one boring. However, all were well below the commercial SCOs More soil data are needed for an accurate analysis of soil contamination at the site.
Significant Threat:

Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

BROWNFIELDS:

Name:	1199 SUTTER AVENUE
Address:	1199 - 1221 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Program:	BCP
Site Code:	465638
Acres:	0.532
HW Code:	C224141
SWIS:	2401
Town:	New York City
Record Added Date:	06/22/2012
Record Updated Date:	09/14/2023
Update By:	SMQUANDT
Site Description:	Location: The site is located at 1199-1221 Sutter Avenue in a mixed residential / commercial area of Brooklyn. The site is bounded by Sutter Ave. to the south, Chestnut St. to the east, Crystal St. to the west and the property rear parking lot and a residential area to the north. Site Features: An asphalt parking lot covers the northern portion of the site and a single-story building is located along the southern portion of the site abutting Sutter Avenue. The building is underlain with a basement segmented for each retail/office unit with utilities, storage and service rooms. Current Zoning and Land Use: The site is within an R5 (residential) zoned area. The site is zoned C1-2 (commercial) as are the properties along the north side of a seven-block stretch of Sutter Avenue. Past use of the Site: The structures on the site were constructed in 1957 and were the original development on the property. Spanish American Dry Cleaners occupied the eastern-most unit from September 1988 to May 1995. The former location of the dry cleaner is presently occupied by a self-service laundromat. Site Geology and Hydrogeology: The property is located within the Pavement and Buildings-Flatbush-Riverhead Series Soil Map Unit, which is described as anthropogenic urban fill overlying glacial out wash deposits and characterized as a sandy loam. The groundwater table is approximately 13 feet below grade and flows south. Groundwater is not utilized as a source of potable water at site. As detailed and managed under the Site Management System, the entire site is overlain by a NYSDEC approved cover system that consists of the buildings and pavement.
Env Problem:	Remediation at the site is underway via an air sparge / soil vapor extraction (AS/SVE) system. The primary contaminants of concern are the dry cleaning solvent tetrachloroethene (PCE) and its daughter products trichloroethene (TCE) and cis-1,2-dichloroethene (DCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil and groundwater is being managed under a Site Management Plan. Site management includes operation of the AS/SVE system that will address soil and groundwater contamination under the building. A sub-slab depressurization system is also operating to prevent migration of contaminants into the occupied, on-site buildings. The SMP includes a provision to investigate off-site vapor when previously-denied access is gained, and to mitigate as necessary.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-06-22 11:41:00
Record Upd:	2018-12-17 10:06:00
Updated By:	MDMACCAB
Own Op:	6
Sub Type:	P02
Owner Name:	Anthony Bileddo
Owner Company:	AAA Sutter Realty LLC
Owner Address:	153-157 Seventh Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Anthony Bileddo
Owner Company:	AAA Sutter Realty LLC
Owner Address:	153-157 Seventh Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Ms. Lisa Goldstein
Owner Company:	Cypress Hills Branch
Owner Address:	Brooklyn Public Library
Owner Addr2:	1197 Sutter Ave. at Crystal St.
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Melinda Perkins
Owner Company:	Brooklyn Community Board 5
Owner Address:	404 Pine Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
HW Code:	C224141
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224141
Waste Type:	1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224141
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224141
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

HW Code:	C224141
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224141
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224141
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	0902686
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-07-15 15:14:00
Record Updated:	2015-07-15 15:14:00
Updated By:	MDMACCAB
Crossref ID:	2018000405070
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-03-26 11:34:00
Record Updated:	2019-12-12 16:14:00
Updated By:	GWHEITZM
Crossref ID:	2018000405070
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2019-03-26 11:34:00
Record Updated:	2019-03-26 11:34:00
Updated By:	MDMACCAB
Crossref ID:	C224141-04-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-11-14 14:28:00
Record Updated:	2018-11-14 14:28:00
Updated By:	MDMACCAB
Crossref ID:	224141
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2012-08-02 11:14:00
Record Updated:	2012-08-02 11:14:00
Updated By:	BXANDERS

SPILLS:

Name:	COMMERCIAL PROPERTY
Address:	1199 SUTTER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0902686 / 2010-07-15
Facility ID:	0902686
Facility Type:	ER
DER Facility ID:	363885
Site ID:	414744
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-06-05

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

Investigator:	JMOCONNE
Referred To:	SITE # 224141
Reported to Dept:	2009-06-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-05
Spill Record Last Update:	2010-07-15
Spiller Name:	ANTHONY BILEDO
Spiller Company:	COMMERCIAL PROPERTY
Spiller Address:	1199 SUTTER AVE
Spiller Company:	999
Contact Name:	CHRISTINE MAZZARELLA
Latitude:	40.6725840
Longitude:	-73.8736920
DEC Memo:	6/17/2009 Sangesland reviewed Phase 2 report (see e-Docs) - Summary below. Krimgold reviewed these notes and agrees with Phase 2 report Recommendation plan. Report Summary: Boring B7 contained 5100ppb of Tetrachloroethene, over the RSCO of 1400ppb. Several GW samples were above limits for VOCs, PCE, Methylene Chloride, Trichloroethene and cis-1,2-Dichloroethene - see report for details Report Recommendations: ...it is recommended that an injection program utilizing Potassium Permanganate...be implemented... In addition shallow and deep monitoring wells should be installed in several strategic locations to monitor the effectiveness of the injection event. 6/17/2009 - Krimgold gave approval for Sangesland to give direction to Associated Environmental to go forward with the Recommended Plan. 4/21/10 (JOC) - re-assigned to Joe O'Connell; - System is prompting for 17-1743 notification determination: This event was not reported pursuant to 17-1743, nor does it qualify for it. No was selected in the system to resolve the prompt; - P-site memo was distributed March 24, 2010; no responses to date; proceeding with P-site owner letter. 7/15/10 - the circumstances that were being evaluated under this spill number will be further evaluated under SSF as site #224141. No further tracking of activities will occur under this spill number. Administratively closed. See site #224141 for further information. (JOC)
Remarks:	CALLER STATES THAT THEY GOT TEST RESULTS BACK SHOWING CONTAMINATED GROUND WATER AND SOIL. CLEAN UP PENDING.

All Materials:

Site ID:	414744
Operable Unit ID:	1171122

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

Operable Unit:	01
Material ID:	2162910
Material Code:	0040A
Material Name:	tetrachloroethene (PCE)
Case No.:	00127184
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	414744
Operable Unit ID:	1171122
Operable Unit:	01
Material ID:	2162911
Material Code:	1782A
Material Name:	tetrachloroethene
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	1199 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6728467
Longitude:	-73.8733497
Type Of Ownership Code:	Not reported
Owner Name:	AAA SUTTER REALTY LLC
Borough:	BK
Tax Block:	4248
Tax Lot:	1
Community District:	305
Census Tract 2020:	3119600
Census Block 2020:	31196004004
Census Tract 2010:	1196
Census Block 2010:	4004
School District:	19
City Council District:	42
Fire Company:	L107
Police Precinct:	75
Health Center District:	33
Health Area:	6410
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	3D
Zoning District 1:	R5: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C1-2
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	K1: Store Buildings (Taxpayers Included) - One Story Retail Building
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	23025
Total Building Floor Area:	15825
Commercial Floor Area:	15825
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	15825
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	5
Lot Frontage:	200.0000000
Lot Depth:	100.0000000
Building Frontage:	200.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	383400.00000
Assessed Total Value:	1169550.00000
Exempt Total Value:	0.00000
Year Built:	1965
Year Altered 1:	2007
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.69000000000
Maximum Allowable Residential Far:	1.25000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3042480001.00000000
Condominium Number:	Not reported
Census Tract 2:	1196
X Coordinate:	1019382
Y Coordinate:	184438
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 044
Tax Map #:	31308
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1

DRAFT

1199 SUTTER AVENUE (Continued) **S109583525**

2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

277
West
1/4-1/2
0.426 mi.
2250 ft.

2840 ATLANTIC AVENUE
2840 ATLANTIC AVENUE
BROOKLYN, NY 11207

NY ENG CONTROLS **S120706216**
NY INST CONTROL **N/A**
NY BROWNFIELDS
NY NYC LAND USE

Relative:
Higher

Actual:
42 ft.

ENG CONTROLS:

Name:	2840 ATLANTIC AVENUE
Address:	2840 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Site Code:	544636
HW Code:	C224255
Control Code:	15
Control Type:	ENG
Date Record Added:	11/29/2022
Date Rec Updated:	10/21/2024
Updated By:	SXSCHARF
Site Description:	Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem:	Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Addr2:	suite 215
Owner City,St,Zip:	brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	shalom Laine
Owner Company:	Empire State Dairy LLC
Owner Address:	3611 14th Avenue
Owner Addr2:	suite 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 5
Owner Address:	404 Pine Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	6
Sub Type:	09
Owner Name:	Abraham Hoffman
Owner Company:	HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address:	3611 14th Avenue
Owner Addr2:	SUITE 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	6
Sub Type:	09
Owner Name:	Shalom Laine
Owner Company:	2840 Atlantic LLC
Owner Address:	3611 14th Avenue
Owner Addr2:	suite 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
HW Code:	C224255
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	o-xylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzene

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	PCB aroclor 1254
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2022000456068
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2022-12-22 10:25:00
Record Updated:	2022-12-22 10:25:00
Updated By:	SXSCHARF
Crossref ID:	2-064742
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2021-03-29 11:12:00
Record Updated:	2021-03-29 11:12:00
Updated By:	LXZIELIN
Crossref ID:	1605901
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-03-06 15:19:00
Record Updated:	2019-03-06 15:19:00
Updated By:	RDDECAND
Crossref ID:	100
Cross Ref Type Code:	21
Cross Ref Type:	Environmental Zone
Record Added Date:	2022-11-18 13:57:00
Record Updated:	2022-11-18 13:57:00
Updated By:	SXSCHARF
Crossref ID:	C224255-11-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Record Added Date:	2022-11-18 14:45:00
Record Updated:	2022-11-18 14:45:00
Updated By:	SXSCHARF
Crossref ID:	2018-04-16
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2022-11-18 14:45:00
Record Updated:	2022-11-18 14:45:00
Updated By:	SXSCHARF
Name:	2840 ATLANTIC AVENUE
Address:	2840 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Site Code:	544636
HW Code:	C224255
Control Code:	36
Control Type:	ENG
Date Record Added:	11/29/2022
Date Rec Updated:	10/21/2024
Updated By:	SXSCHARF
Site Description:	Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem:	Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner City,St,Zip:	brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	shalom Laine
Owner Company:	Empire State Dairy LLC
Owner Address:	3611 14th Avenue
Owner Addr2:	suite 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 5
Owner Address:	404 Pine Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	6
Sub Type:	09
Owner Name:	Abraham Hoffman
Owner Company:	HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address:	3611 14th Avenue
Owner Addr2:	SUITE 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	6
Sub Type:	09
Owner Name:	Shalom Laine
Owner Company:	2840 Atlantic LLC
Owner Address:	3611 14th Avenue
Owner Addr2:	suite 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
HW Code:	C224255
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	o-xylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzene
Waste Quantity:	UNKNOWN

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	PCB aroclor 1254
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2022000456068
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2022-12-22 10:25:00
Record Updated:	2022-12-22 10:25:00
Updated By:	SXSCHARF
Crossref ID:	2-064742
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2021-03-29 11:12:00
Record Updated:	2021-03-29 11:12:00
Updated By:	LXZIELIN
Crossref ID:	1605901
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-03-06 15:19:00
Record Updated:	2019-03-06 15:19:00
Updated By:	RDDECAND
Crossref ID:	100
Cross Ref Type Code:	21
Cross Ref Type:	Environmental Zone
Record Added Date:	2022-11-18 13:57:00
Record Updated:	2022-11-18 13:57:00
Updated By:	SXSCHARF
Crossref ID:	C224255-11-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2022-11-18 14:45:00

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

INST CONTROL:
Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: Site Management Plan
HW Code: C224255
Control Code: 32
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: o-xylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF
Crossref ID: C224255-11-17
Cross Ref Type Code: 23

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: Soil Management Plan
HW Code: C224255
Control Code: 14
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: o-xylene
Waste Quantity: UNKNOWN
Waste Code: Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF
Crossref ID: C224255-11-17

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: IC/EC Plan
HW Code: C224255
Control Code: 34
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

(VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: o-xylene
Waste Quantity: UNKNOWN

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Code: Not reported
HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Crossref ID: C224255-11-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: Environmental Easement
HW Code: C224255
Control Code: J
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1

2840 ATLANTIC AVENUE (Continued) **S120706216**

Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: o-xylene

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Updated By: SXSCHARF
Crossref ID: C224255-11-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: Monitoring Plan
HW Code: C224255
Control Code: 31
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.
Env Problem: Soil Boring Sampling Results- Soil sample results from all soil

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America

2840 ATLANTIC AVENUE (Continued) **S120706216**

Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Type: o-xylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF
Crossref ID: C224255-11-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: Ground Water Use Restriction
HW Code: C224255
Control Code: 08
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.
Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

HW Code: C224255
Waste Type: o-xylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF
Crossref ID: C224255-11-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: O&M Plan
HW Code: C224255
Control Code: 33
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

groundwater flow direction at the site is towards the southwest.

Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street
Owner Addr2: Not reported

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead
Waste Quantity: UNKNOWN

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Code: Not reported
HW Code: C224255
Waste Type: o-xylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100
Cross Ref Type Code: 21

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF
Crossref ID: C224255-11-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

Name: 2840 ATLANTIC AVENUE
Address: 2840 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207
Site Code: 544636
Control Name: Landuse Restriction
HW Code: C224255
Control Code: 25
Control Type: INST
Dt record added: 11/29/2022
Dt rec updated: 10/21/2024
Updated By: SXSCHARF
Site Code: 544636
Site Description: Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS).

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.

Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - New Lots Branch
Owner Address: 665 New Lots Avenue at Barbey Street

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: shalom Laine/Sam Goldstein
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14TH AVENUE
Owner Addr2: suite 215
Owner City,St,Zip: brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: shalom Laine
Owner Company: Empire State Dairy LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Abraham Hoffman
Owner Company: HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address: 3611 14th Avenue
Owner Addr2: SUITE 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
Own Op: 6
Sub Type: 09
Owner Name: Shalom Laine
Owner Company: 2840 Atlantic LLC
Owner Address: 3611 14th Avenue
Owner Addr2: suite 215
Owner City,St,Zip: Brooklyn, NY 11218
Owner Country: United States of America
HW Code: C224255
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: lead

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: o-xylene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: PCB aroclor 1254
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: naphthalene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224255
Waste Type: DDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2022000456068
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2022-12-22 10:25:00
Record Updated: 2022-12-22 10:25:00
Updated By: SXSCHARF
Crossref ID: 2-064742
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2021-03-29 11:12:00
Record Updated: 2021-03-29 11:12:00
Updated By: LXZIELIN
Crossref ID: 1605901
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2019-03-06 15:19:00
Record Updated: 2019-03-06 15:19:00
Updated By: RDDECAND
Crossref ID: 100

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Cross Ref Type Code: 21
Cross Ref Type: Environmental Zone
Record Added Date: 2022-11-18 13:57:00
Record Updated: 2022-11-18 13:57:00
Updated By: SXSCHARF
Crossref ID: C224255-11-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF
Crossref ID: 2018-04-16
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2022-11-18 14:45:00
Record Updated: 2022-11-18 14:45:00
Updated By: SXSCHARF

BROWNFIELDS:

Name:	2840 ATLANTIC AVENUE
Address:	2840 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Program:	BCP
Site Code:	544636
Acres:	1.001
HW Code:	C224255
SWIS:	2401
Town:	New York City
Record Added Date:	04/03/2017
Record Updated Date:	08/16/2024
Update By:	JBSWARTO
Site Description:	Location: The 2840 Atlantic Avenue Site is located in an urban area of Brooklyn with a mix of industrial, commercial, and residential buildings. The site is comprised, with the addition of two extra lots through a Brownfield cleanup Agreement amendment, of three contiguous parcels identified now joined as Block 3964 Lots 8 and is located on the south side of Atlantic Avenue, the east side of Schenck Avenue, and the west side of Barbey Street. The approximate site area is 43,600 square feet. Site Features: The 1.0009-acre site is currently developed with a three-story former industrial building that is a historic landmark and is currently undergoing renovation on the northern portion of the site. The rear portion of the site structure that is not part of the historic landmark was demolished and is now the location of the new apartment complex. A 5,000-gallon No. 4 fuel oil underground storage tank, originally closed in-place has since been removed. Current Zoning and Land Use: The site is zoned for manufacturing(M1-4) and residential uses (R6A and R8A) and is currently vacant. The surrounding area consists of commercial, industrial, and residential buildings. The new construction for affordable housing is now complete. Past Use of the Site: The earliest identified use of the site included a lumber yard, retail buildings, and residences in 1887. The existing structures were constructed circa 1908 and expanded in 1914 / 1915. The property was operated as a dairy and food product manufacturing facility from at least 1908 to the mid to late 1970s. The site was operated as a plastics and floor tile products manufacturing facility from the 1980s until 2016. Site Geology and Hydrogeology: Subsurface soils at

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

the site consist of brown sands, gravel, and silts. Bedrock was not encountered to a depth of 40 feet below land surface (BLS). Groundwater was encountered between 35 feet BLS and 40 feet BLS. The groundwater flow direction at the site is towards the southwest.

Env Problem: Soil Boring Sampling Results- Soil sample results from all soil borings were compared to the NYSDEC Part 375 Unrestricted use soil cleanup objectives (UUSCO s). Several volatile organic compounds (VOCs), and semi-volatile organic compounds (SVOCs) were detected at concentrations above their respective NYSDEC Part 375 UUSCOs in sample SB-8.2, from approximately 37-38 below ground surface (bgs) at a location just east of the 20,000-gallon heating oil UST, fuel oil and several metals from borings SB-7 & SB-9 were detected at concentrations above their respective NYSDEC Part 375 UUSCOs. These metals included lead, zinc, and mercury. Pure product in number 4 fuel oil was also found in this area. Groundwater Sampling Results- Based upon review of the groundwater analytical laboratory data VOC's and semi-VOCs were detected in the groundwater sample collected at SB-1 and the SB-5 location. In addition, fuel oil was also detected within the area of the leaking underground storage tank. Emerging Contaminant Results- Per- and polyfluoroalkyl substances (PFAS): PFAS compounds were detected fairly ubiquitously in the upgradient and downgradient onsite monitoring wells. PFOA concentrations ranged from 27.3 to 91.6 ng/l and PFOS concentrations ranged from 1.21 to 19.3 ng/l. Groundwater analytical results for 1, 4 Dioxane were all non-detect. Soil Vapor Sampling Results- Based upon the analytical laboratory data, the presence of petroleum-related and solvent-related vapors were confirmed in the subsurface and ambient air at concentrations above their respective NYSDOH 25th and/or 75th percentile concentrations for Indoor Air. These compounds included 1,2,4-trimethylbenzene, 2-butanone, acetone, benzene, chloromethane, cyclohexane, dichlorodifluoromethane, n-heptane, n-hexane, p&m xylenes, PCE, tetrahydrofuran, toluene, TCE, and trichlorofluoromethane (Freon 11). Current Status: Implementation of the remedial design, found in the Remedial Action Work Plan (RAWP) and codified in the Decision Document, detailing the remedial action that began fall 2021 is now complete and the site has been redeveloped. The project is now in the site management phase for the ongoing Vaccuum enhanced fluid recovery (VEFR) and sub-slab depressurization (SSD) systems.

Health Problem: Remedial actions are complete and measures are in place to control the potential for coming in contact with contamination remaining at the site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2020-08-24 08:59:00
Record Upd: 2022-12-29 13:34:00
Updated By: SXSCHARF
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Owner Company:	Brooklyn Public Library - New Lots Branch
Owner Address:	665 New Lots Avenue at Barbey Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	shalom Laine/Sam Goldstein
Owner Company:	Empire State Dairy LLC
Owner Address:	3611 14TH AVENUE
Owner Addr2:	suite 215
Owner City,St,Zip:	brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	shalom Laine
Owner Company:	Empire State Dairy LLC
Owner Address:	3611 14th Avenue
Owner Addr2:	suite 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 5
Owner Address:	404 Pine Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	6
Sub Type:	09
Owner Name:	Abraham Hoffman
Owner Company:	HP Brooklyn Dairy Housing Development Fund Company, Inc.
Owner Address:	3611 14th Avenue
Owner Addr2:	SUITE 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
Own Op:	6
Sub Type:	09
Owner Name:	Shalom Laine
Owner Company:	2840 Atlantic LLC
Owner Address:	3611 14th Avenue
Owner Addr2:	suite 215
Owner City,St,Zip:	Brooklyn, NY 11218
Owner Country:	United States of America
HW Code:	C224255
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

HW Code:	C224255
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	o-xylene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	PCB aroclor 1254
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224255
Waste Type:	DDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2022000456068
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2022-12-22 10:25:00
Record Updated:	2022-12-22 10:25:00
Updated By:	SXSCHARF
Crossref ID:	2-064742
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2021-03-29 11:12:00
Record Updated:	2021-03-29 11:12:00
Updated By:	LXZIELIN
Crossref ID:	1605901
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2019-03-06 15:19:00
Record Updated:	2019-03-06 15:19:00

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Updated By:	RDDECAND
Crossref ID:	100
Cross Ref Type Code:	21
Cross Ref Type:	Environmental Zone
Record Added Date:	2022-11-18 13:57:00
Record Updated:	2022-11-18 13:57:00
Updated By:	SXSCHARF
Crossref ID:	C224255-11-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2022-11-18 14:45:00
Record Updated:	2022-11-18 14:45:00
Updated By:	SXSCHARF
Crossref ID:	2018-04-16
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2022-11-18 14:45:00
Record Updated:	2022-11-18 14:45:00
Updated By:	SXSCHARF

NYC LAND USE:

Name:	Not reported
Address:	2840 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6764036
Longitude:	-73.8889353
Type Of Ownership Code:	Not reported
Owner Name:	EMPIRE STATE DAIRY LLC
Borough:	BK
Tax Block:	3964
Tax Lot:	8
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198003007
Census Tract 2010:	1198
Census Block 2010:	3007
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	M1-4/R8A: Mixed Manufacturing & Residential Districts
Zoning District 2:	M1-4/R6A: Mixed Manufacturing & Residential Districts
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	MX-16
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Y
Building Class:	D6: Elevator Apartments - Fireproof With Stores

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	43648
Total Building Floor Area:	323953
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	14.0000000
Residential Units:	640
Total Units:	642
Lot Frontage:	200.6700000
Lot Depth:	235.0000000
Building Frontage:	200.0000000
Building Depth:	235.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	0
Basement Type/Grade:	5
Assessed Land Value:	785700.00000
Assessed Total Value:	4321688.00000
Exempt Total Value:	0.00000
Year Built:	1921
Year Altered 1:	0
Year Altered 2:	2021
Historic District Name:	Individual Landmark
Landmark Status:	INDIVIDUAL LANDMARK
Built Floor Area Ratio:	7.42000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039640008.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1015057
Y Coordinate:	185728
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 003
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	3039640008.00000000
Apportionment Date:	07/18/2018
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Name:	Not reported
Address:	2840 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	Not reported
Longitude:	Not reported
Type Of Ownership Code:	X
Owner Name:	EMPIRE STATE DAIRY LLC
Borough:	BK
Tax Block:	3964
Tax Lot:	7501
Community District:	Not reported
Census Tract 2020:	Not reported
Census Block 2020:	Not reported
Census Tract 2010:	Not reported
Census Block 2010:	Not reported
School District:	Not reported
City Council District:	Not reported
Fire Company:	Not reported
Police Precinct:	Not reported
Health Center District:	Not reported
Health Area:	Not reported
Sanitation District Boro:	Not reported
Sanitation District Number:	Not reported
Sanitation Subsection:	Not reported
Zoning District 1:	Not reported
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Not reported
Building Class:	R0: Condominiums - Condo Billing Lot
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	43600
Total Building Floor Area:	658000
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	5
Number Of Buildings:	2
Number Of Floors:	14.0000000
Residential Units:	Not reported
Total Units:	Not reported
Lot Frontage:	200.6700000
Lot Depth:	235.0000000
Building Frontage:	200.0000000
Building Depth:	235.0000000

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	0
Basement Type/Grade:	5
Assessed Land Value:	0.00000
Assessed Total Value:	0.00000
Exempt Total Value:	0.00000
Year Built:	2021
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	15.09000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	0.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039647501.00000000
Condominium Number:	5863
Census Tract 2:	Not reported
X Coordinate:	Not reported
Y Coordinate:	Not reported
Zoning Map #:	Not reported
Zoning Map Code:	Not reported
Sanborn Map #:	Not reported
Tax Map #:	Not reported
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	2
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported
Name:	Not reported
Address:	2840 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	Not reported
Longitude:	Not reported
Type Of Ownership Code:	X
Owner Name:	Not reported
Borough:	BK
Tax Block:	3964
Tax Lot:	1001
Community District:	Not reported
Census Tract 2020:	Not reported
Census Block 2020:	Not reported
Census Tract 2010:	Not reported
Census Block 2010:	Not reported
School District:	Not reported
City Council District:	Not reported
Fire Company:	Not reported
Police Precinct:	Not reported
Health Center District:	Not reported
Health Area:	Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

Sanitation District Boro:	Not reported
Sanitation District Number:	Not reported
Sanitation Subsection:	Not reported
Zoning District 1:	Not reported
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Not reported
Building Class:	R5: Condominiums - Miscellaneous Commercial
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	Not reported
Total Building Floor Area:	44386
Commercial Floor Area:	44386
Residential Floor Area:	0
Office Floor Area:	44386
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	Not reported
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	1
Lot Frontage:	Not reported
Lot Depth:	Not reported
Building Frontage:	Not reported
Building Depth:	Not reported
Extension Code:	Not reported
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	0
Basement Type/Grade:	2
Assessed Land Value:	0.00000
Assessed Total Value:	0.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	Not reported
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	0.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039641001.00000000
Condominium Number:	Not reported
Census Tract 2:	Not reported

DRAFT

2840 ATLANTIC AVENUE (Continued) **S120706216**

X Coordinate:	Not reported
Y Coordinate:	Not reported
Zoning Map #:	Not reported
Zoning Map Code:	Not reported
Sanborn Map #:	Not reported
Tax Map #:	Not reported
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	2
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AN278 **CHESTNUT COMMONS ATLANTIC AVE SITE** **NY ENG CONTROLS** **S122449244**
NE **110 DINSMORE PLACE** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11208** **NY BROWNFIELDS**
0.432 mi. **NY NYC LAND USE**
2279 ft. **Site 1 of 4 in cluster AN**

Relative: **Higher**
Actual: **37 ft.**

ENG CONTROLS:

Name:	CHESTNUT COMMONS ATLANTIC AVE SITE
Address:	110 DINSMORE PLACE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	571272
HW Code:	C224276
Control Code:	13
Control Type:	ENG
Date Record Added:	09/22/2020
Date Rec Updated:	08/16/2023
Updated By:	JSDONALD
Site Description:	Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

of the site.

Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Record Upd:	2020-12-23 09:56:00
Updated By:	NNCRAWFO
Own Op:	6
Sub Type:	P03
Owner Name:	Matthew Gross
Owner Company:	Chestnut Commons Apartments LLC
Owner Address:	Urban Builders Collaborative
Owner Addr2:	334-336 110th Street
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Arlington Branch
Owner Address:	203 Arlington Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Ismene Speliotis
Owner Company:	Chestnut Commons Housing Development Fund Corporation
Owner Address:	470 vanderbilt Avenue, 9th Floor
Owner Addr2:	c/o mhany Management inc.
Owner City,St,Zip:	BROOKLYN, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board No. 5
Owner Address:	404 Pine Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	MATTHEW GROSS
Owner Company:	Chestnut Commons Apartments LLC
Owner Address:	334-336 110th Street
Owner Addr2:	URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	C224276
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	mercury
Waste Quantity:	UNKNOWN

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Code:	Not reported
HW Code:	C224276
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	dieldrin
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	chlordane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224276-08-29
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-09-22 10:33:00

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Record Updated:	2020-09-22 10:33:00
Updated By:	NNCRAWFO
Crossref ID:	2020000294461
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-11-03 14:49:00
Record Updated:	2020-11-03 14:49:00
Updated By:	GWHEITZM
Crossref ID:	9/14/18
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-09-22 10:33:00
Record Updated:	2020-09-22 10:33:00
Updated By:	NNCRAWFO

INST CONTROL:

Name:	CHESTNUT COMMONS ATLANTIC AVE SITE
Address:	110 DINSMORE PLACE
City,State,Zip:	BROOKLYN, NY 11208
Site Code:	571272
Control Name:	Landuse Restriction
HW Code:	C224276
Control Code:	25
Control Type:	INST
Dt record added:	09/22/2020
Dt rec updated:	08/16/2023
Updated By:	JSDONALD
Site Code:	571272
Site Description:	Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem:	Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 28
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272
Control Name: Ground Water Use Restriction
HW Code: C224276
Control Code: 08
Control Type: INST
Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272
Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals,

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272
Control Name: Soil Management Plan
HW Code: C224276
Control Code: 14
Control Type: INST
Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272
Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil -

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272
Control Name: IC/EC Plan
HW Code: C224276
Control Code: 34
Control Type: INST
Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272
Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272
Control Name: Site Management Plan
HW Code: C224276
Control Code: 32
Control Type: INST
Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272
Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

(UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Control Name: O&M Plan
HW Code: C224276
Control Code: 33
Control Type: INST
Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272
Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272
Control Name: Environmental Easement
HW Code: C224276
Control Code: J
Control Type: INST

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272
Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.
Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

Name: CHESTNUT COMMONS ATLANTIC AVE SITE
Address: 110 DINSMORE PLACE
City,State,Zip: BROOKLYN, NY 11208
Site Code: 571272
Control Name: Monitoring Plan
HW Code: C224276
Control Code: 31
Control Type: INST
Dt record added: 09/22/2020
Dt rec updated: 08/16/2023
Updated By: JSDONALD
Site Code: 571272

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Site Description: Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.

Env Problem: Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).

Health Problem: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-08-30 14:13:00
Record Upd: 2020-12-23 09:56:00
Updated By: NNCRAWFO
Own Op: 6
Sub Type: P03
Owner Name: Matthew Gross
Owner Company: Chestnut Commons Apartments LLC
Owner Address: Urban Builders Collaborative
Owner Addr2: 334-336 110th Street
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Public Library - Arlington Branch
Owner Address: 203 Arlington Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: Ismene Speliotis
Owner Company: Chestnut Commons Housing Development Fund Corporation
Owner Address: 470 vanderbilt Avenue, 9th Floor
Owner Addr2: c/o mhany Management inc.
Owner City,St,Zip: BROOKLYN, NY 11238
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Brooklyn Community Board No. 5
Owner Address: 404 Pine Street, 3rd Floor

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: MATTHEW GROSS
Owner Company: Chestnut Commons Apartments LLC
Owner Address: 334-336 110th Street
Owner Addr2: URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: C224276
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: DDT
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: mercury
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: dieldrin
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: chlordane

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: arsenic
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224276
Waste Type: toluene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C224276-08-29
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO
Crossref ID: 2020000294461
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2020-11-03 14:49:00
Record Updated: 2020-11-03 14:49:00
Updated By: GWHEITZM
Crossref ID: 9/14/18
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2020-09-22 10:33:00
Record Updated: 2020-09-22 10:33:00
Updated By: NNCRAWFO

BROWNFIELDS:

Name:	CHESTNUT COMMONS ATLANTIC AVE SITE
Address:	110 DINSMORE PLACE
City,State,Zip:	BROOKLYN, NY 11208
Program:	BCP
Site Code:	571272
Acres:	0.659
HW Code:	C224276
SWIS:	2401
Town:	New York City
Record Added Date:	06/07/2018
Record Updated Date:	03/20/2025
Update By:	RKCORCOR
Site Description:	Site Location: The site is an approximately 0.659 acre fenced-in vacant lot with heavy vegetation located at 110 Dinsmore Place in Brooklyn, NY. The site is located in a highly developed urban area of

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Brooklyn consisting primarily of industrial and commercial structures. Site Features: A building is being erected on site. Current Zoning and Land Use: The site is currently zoned M1-4 (manufacturing) with an R8A (residential) overlay. There are various commercial buildings to the north; to the west is a lot currently undergoing development by the New York City School Construction Authority (NYCSCA) as a school; to the east is a large vacant lot that is also participating in the Department's BCP (site no. C224236); and to the south is Atlantic Avenue and Conduit Boulevard (major thoroughfares). Immediately adjacent to the south of these thoroughfares is a baseball field. An aboveground subway line is one block to the north of the site and an underground Long Island Rail Road line is located to the south and runs east-west below Atlantic Avenue. Past Use of the Site: Past uses of the site include a water pump house with associated railroad tracks, and coal storage yard from 1887 to 1980, and an automobile, trailer, and heavy equipment sales facility from 1980 to 1992. The site has been vacant since 2006. Site Geology and Hydrogeology: The site is underlain by approximately 5 to 10 feet of historic fill material, consisting of sand, silt and brick. Native soils beneath the fill layer consist of sand and trace gravel. Depth to groundwater at the site is approximately 25 to 30 feet bgs and flows in a southerly direction towards Jamaica Bay, which is located approximately 3.1 miles south of the site.

Env Problem:

Post-Remediation Remediation at the site is complete. Remedial actions have successfully achieved soil cleanup objectives for residential use. Residential contamination in the soil is being managed under a Site Management Plan. Prior to Completion of Remediation Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater samples were also analyzed for Emerging Contaminants. Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern are VOCs, SVOCs and metals. Soil - VOCs were detected above NYSDEC Unrestricted Use SCOs (UUSCOs) including benzene at a maximum concentration of 4.2 parts per million (ppm) as compared to the UUSCO of 0.6 ppm, and toluene at 2.7 ppm (compared to UUSCO of 0.7 ppm). PCE and TCE were detected at concentrations below the UUSCOs. SVOCs were detected at concentrations exceeding the UUSCOs including benzo(a)anthracene at 2.8 ppm (UUSCO is 1 ppm), benzo(a)pyrene at 2.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene at 3.1 ppm (UUSCO is 1 ppm), chrysene at 3.4 ppm (UUSCO is 1 ppm), and indeno(1,2,3-cd)pyrene at 1.4 ppm (UUSCO is 0.5 ppm). Metals detected in exceedance of UUSCOs include lead at 487 ppm (UUSCO is 63 ppm), arsenic at 21.8 ppm (UUSCO is 13 ppm), and mercury at 0.51 ppm (UUSCO is 0.18 ppm). Pesticides and herbicides were detected at concentrations above UUSCOs, including dieldrin at 0.031 ppm (UUSCO is 0.005 ppm), and 4,4-DDT at 0.08 ppm (UUSCO is 0.0033 ppm). PCBs were not detected in any soil samples at concentrations exceeding UUSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater - VOCs were detected at concentrations above their respective ambient water quality standards (AWQSs) including tetrachloroethylene (PCE) at a maximum concentration of 22 parts per billion (ppb) as compared to the AWQS of 5 ppb, and trichloroethene (TCE) at a maximum concentration of 5.4 ppb (AWQS is 5 ppb). One SVOC, bis(2-ethylhexyl)phthalate, was detected at 18 ppb (AWQS is 5 ppb). Only 2 dissolved metals were

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

	detected at concentrations exceeding their AWQS: sodium and manganese. These are naturally-occurring metals and are not site-related contaminants. One pesticide, chlordane, was detected at a concentration of 1.4 ppb (AWQS is 0.05 ppb). Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Several VOCs were detected in soil vapor samples throughout the site, including benzene at a maximum concentration of 57 micrograms per cubic meter (ug/m3), toluene at 150 ug/m3, xylenes at 190 ug/m3, TCE at 4,600 ug/m3, and PCE at 13,000 ug/m3. Data indicates that the VOCs in soil vapor are migrating onto the site from an off-site source to the east (BCP site no. C224236).
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-08-30 14:13:00
Record Upd:	2020-12-23 09:56:00
Updated By:	NNCRAWFO
Own Op:	6
Sub Type:	P03
Owner Name:	Matthew Gross
Owner Company:	Chestnut Commons Apartments LLC
Owner Address:	Urban Builders Collaborative
Owner Addr2:	334-336 110th Street
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Arlington Branch
Owner Address:	203 Arlington Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Ismene Speliotis
Owner Company:	Chestnut Commons Housing Development Fund Corporation
Owner Address:	470 vanderbilt Avenue, 9th Floor
Owner Addr2:	c/o mhany Management inc.
Owner City,St,Zip:	BROOKLYN, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board No. 5
Owner Address:	404 Pine Street, 3rd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Own Op:	1
Sub Type:	E
Owner Name:	MATTHEW GROSS
Owner Company:	Chestnut Commons Apartments LLC
Owner Address:	334-336 110th Street
Owner Addr2:	URBAN BUILDERS COLLABORATIVE
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	C224276
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	DDT
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	dieldrin
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	chlordane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224276
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224276-08-29
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-09-22 10:33:00
Record Updated:	2020-09-22 10:33:00
Updated By:	NNCRAWFO
Crossref ID:	2020000294461
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2020-11-03 14:49:00
Record Updated:	2020-11-03 14:49:00
Updated By:	GWHEITZM
Crossref ID:	9/14/18
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-09-22 10:33:00
Record Updated:	2020-09-22 10:33:00
Updated By:	NNCRAWFO

NYC LAND USE:

Name:	Not reported
Address:	110 DINSMORE PLACE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6810805
Longitude:	-73.8753423
Type Of Ownership Code:	Not reported
Owner Name:	CHESTNUT COMMONS HOUSING DEVELOPMENT FUN D CORPORAT
Borough:	BK
Tax Block:	4142
Tax Lot:	7501
Community District:	305
Census Tract 2020:	3117800
Census Block 2020:	31178001006
Census Tract 2010:	1178
Census Block 2010:	1006
School District:	19
City Council District:	37
Fire Company:	E236

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Police Precinct:	75
Health Center District:	34
Health Area:	3900
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	M1-4/R8A: Mixed Manufacturing & Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	MX-16
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Y
Building Class:	Rm: Condominiums -Mixed Residential & Commercial Building (Mixed Residential & Commercial)
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	28450
Total Building Floor Area:	250853
Commercial Floor Area:	6363
Residential Floor Area:	244490
Office Floor Area:	0
Retail Floor Area:	6363
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	14.0000000
Residential Units:	274
Total Units:	551
Lot Frontage:	143.0800000
Lot Depth:	189.6200000
Building Frontage:	191.0000000
Building Depth:	143.0000000
Extension Code:	Not reported
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	0
Basement Type/Grade:	5
Assessed Land Value:	599850.00000
Assessed Total Value:	20692800.00000
Exempt Total Value:	19981864.00000
Year Built:	2020
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	8.82000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	6.50000000000

DRAFT

CHESTNUT COMMONS ATLANTIC AVE SITE (Continued) **S122449244**

Boro Code:	3
Borough, Tax Block and Lot:	3041427501.00000000
Condominium Number:	5546
Census Tract 2:	1178
X Coordinate:	1018825
Y Coordinate:	187437
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 028
Tax Map #:	31306
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AO279 **2862 FULTON STREET** **NY NYC OER** **S132179920**
WNW **2862 FULTON STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.441 mi.
2330 ft. **Site 1 of 3 in cluster AO**

Relative:
Higher

Actual:
41 ft.

NYC OER:

Name:	2862 FULTON STREET
Address:	2862 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678605
Longitude:	-73.888831
OER Project Numbers:	19TMP0585K,19EH-N180K
BBL:	3039500017
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	5
Community Board:	37
Council District:	1170
Census Tract:	3087843
BIN:	3039500017
NTA:	East New York

AO280 **208 BARBEY ST** **NY LTANKS** **S102233260**
WNW **208 BARBEY ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.444 mi.
2345 ft. **Site 2 of 3 in cluster AO**

Relative:
Higher

Actual:
44 ft.

LTANKS:

Name:	208 BARBEY ST
Address:	208 BARBEY ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9512002 / 1995-12-26

DRAFT

208 BARBEY ST (Continued) **S102233260**

Facility ID:	9512002
Site ID:	124613
Spill Date:	1995-12-22
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-12-22
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-22
Spill Record Last Update:	1998-01-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	208 BARBEY ST
Spiller County:	001
Spiller Contact:	BRENDA SCALES
Spiller Phone:	(718) 647-8980
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	107897
Latitude:	40.6781222
Longitude:	-73.8889617
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE OWNER MERILLE TEMISLL 718-523-0424. CLEANED WITH SPEEDY DRY.
Remarks:	WHILE DELIVERING AN OIL LOAD THE TANK SPLIT IN HALF RELEASING OIL ONTO THE CEMENT BASEMENT FLOOR

All Materials:

Site ID:	124613
Operable Unit ID:	1022684
Operable Unit:	01
Material ID:	359324
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	25.00
Oxygenate:	Not reported

DRAFT

281
NNE
1/4-1/2
0.444 mi.
2346 ft.

223 & 227 RICHMOND ST
223 RICHMOND ST
BROOKLYN, NY

NY LTANKS
NY Spills

S102150089
N/A

Relative:
Higher

Actual:
41 ft.

LTANKS:

Name:	223 RICHMOND ST
Address:	223 RICHMOND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9303118 / 1993-06-09
Facility ID:	9303118
Site ID:	187167
Spill Date:	1993-06-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1993-06-09
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1993-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-06-11
Spill Record Last Update:	1993-07-19
Spiller Name:	Not reported
Spiller Company:	MICHAEL ADRAGNA -
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	156393
Latitude:	40.6820461
Longitude:	-73.8764715
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG
Remarks:	LINE LEAKES TO FLOOR - SPEEDI-DRI APPLIED - NCB

All Materials:

Site ID:	187167
Operable Unit ID:	985109
Operable Unit:	01
Material ID:	396712
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

223 & 227 RICHMOND ST (Continued) **S102150089**

SPILLS:

Name:	223 & 227 RICHMOND ST
Address:	223 RICHMOND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9501706 / 2006-02-17
Facility ID:	9501706
Facility Type:	ER
DER Facility ID:	156393
Site ID:	187168
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-05-09
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1995-05-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-18
Spill Record Last Update:	2006-02-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
Latitude:	40.6820461
Longitude:	-73.8764715
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 5/10: Bob Kushner, General Watch Supervisor - think it is transmission fluid. Transmission shop across street. Have not yet gotten analysis results. 5/16: Mr. Devenny, CIG - Analysis results show presence of motor oil, PCB <1 ppm. 12/13/05: Service box inspected by Con Ed personnel - no sign of oil in structure. Close out. (JHO, 2/16/06)
Remarks:	FOUND IN CON EDISON #32553. SAMPLES TAKEN FOR ANALYSIS. POSSIBLY TRANSMISSION FLUID POURED INTO MANHOLE.

All Materials:

Site ID:	187168
Operable Unit ID:	1012722
Operable Unit:	01
Material ID:	366780
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum

DRAFT

223 & 227 RICHMOND ST (Continued) **S102150089**

Quantity: 450.00
Units: G
Recovered: .00
Oxygenate: Not reported

282
East
1/4-1/2
0.445 mi.
2352 ft.

447 EUCLID AVENUE **NY VCP** **S129932453**
447 EUCLID AVENUE **NY NYC OER** **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
31 ft.

VCP NYC:
Project ID: 19TMP1428K,19EH-N325K
Name: 447 EUCLID AVENUE
Address: 447 EUCLID AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 30,421,400,123,042,100,000
OER Program: VCP (Withdrawn), E/RD (Review)
Phase: Completed
Latitude: 40.676252
Longitude: -73.872114
Postcode: 5
Community Board: 42
Council District: 1196
Census Tract: 3000000
BIN: 3042140012
NTA: East New York

NYC OER:
Name: 447 EUCLID AVENUE
Address: 447 EUCLID AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.676252
Longitude: -73.872114
OER Project Numbers: 19TMP1428K,19EH-N325K
BBL: 3.0421400123042099E+19
OER Program: VCP (Withdrawn), E/RD (Review)
Class: Completed (C)
Phase: Completed

URL:
Postcode: 5
Community Board: 42
Council District: 1196
Census Tract: 3000000
BIN: 3042140012
NTA: East New York

DRAFT

AN283 **ATLANTIC CHESTNUT AFFORDABLE HOUSING LLC- LOT 3** **NY BROWNFIELDS** **S128906192**
NE **275 CHESTNUT ST** **NY MANIFEST** **N/A**
1/4-1/2 **BROOKLYN, NY 11208**
0.448 mi.
2364 ft. **Site 2 of 4 in cluster AN**

Relative: **Higher**
Actual: **39 ft.**

BROWNFIELDS:

Name:	ATLANTIC CHESTNUT - LOT 3
Address:	275 CHESTNUT STREET
City,State,Zip:	BROOKLYN, NY 11208
Program:	BCP
Site Code:	522944
Acres:	1.202
HW Code:	C224236
SWIS:	2401
Town:	New York City
Record Added Date:	02/22/2016
Record Updated Date:	10/02/2024
Update By:	CXMAYCOC
Site Description:	Location: The site is located at 275 Chestnut Street in an urban area in the East New York neighborhood of Brooklyn. The site is approximately 52,360 square feet and is denoted on New York City tax maps as Block 4143, Lot 3. The rectangular-shaped site is bounded to the north by the Atlantic Chestnut - Lot 2 (C224235) and Atlantic Chestnut - Lot 1 (C224234) followed by Fulton Street; to the east by Euclid Avenue, followed by residential properties; to the south by Atlantic Avenue and Long Island Railroad tracks; and to the west by Chestnut Street, followed by commercial and residential properties. Site Features: The site is comprised of a concrete and asphalt-paved vacant lot with former truck loading bays on the central portion. The site formerly consisted of a series of vacant, fire-damaged factory buildings that extended to the north-adjacent properties. The buildings were demolished between July and December 2016. Current Zoning and Land Use: The site is currently vacant and is zoned as M1-4 for light manufacturing with an R8A residential overlay. The surrounding area is developed with residential, commercial, manufacturing, transportation, and industrial uses. Past Use of the Site: The site was developed for industrial and manufacturing uses, including the Columbia Machine Works and Malleable Iron Company, the Columbia Cable and Electric Corporation, Blue Ridge Farms, Inc., and Chloe Foods Corp. between 1908 and 2012. Other previous uses include blacksmithing and stamping, a brass foundry, wood working, a blacksmith, a machine shop, tank and engine rooms, an iron works, wire braiding, and cable manufacturing. Site Geology and Hydrogeology: Surface topography at the Site is generally level and lies at an elevation of approximately 38 feet above mean sea level. Historic fill materials (including sand, gravel, silt, ash, slag, concrete, and asphalt) exist from just below the surface to approximately 3 to 5 feet below grade surface (bgs). The fill is underlain by apparent native sand and gravel to approximately 40 feet bgs. Bedrock was not encountered during any of the investigations conducted at the site. The surrounding area slopes down to the south. Groundwater was encountered approximately 30 feet below grade and flows to the south.
Env Problem:	Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Soil vapor was analyzed for VOCs. Based on the investigation conducted to date, the primary contaminants of

DRAFT

ATLANTIC CHESTNUT AFFORDABLE HOUSING LLC- LOT 3 (Continued) **S128906192**

concern for the site include chlorinated solvent-related VOCs and metals in soil, and chlorinated VOCs in soil vapor. Soil - VOCs were found at concentrations exceeding the applicable restricted residential soil cleanup objectives (RRSCOs) and protection of groundwater soil cleanup objectives (PGWSCOs) including trichloroethene (TCE) at a maximum concentration of 570 parts per million, or ppm (RRSCO is 21 ppm, PGSCO is 0.47 ppm) and tetrachloroethene (PCE) at 3 ppm (PGWSCO is 1.3 ppm). These contaminants were detected in soil borings located in the northern and southern portion of the site at depths ranging from grade to 21 feet (bgs). Metals found in exceedance of their applicable RRSCOs including arsenic at 21.2 ppm (RRSCO is 16 ppm) and mercury at 7.1 (RRSCO is 0.81). These metals were found in the central and northeastern portions of the site at 2 to 5 feet bgs. No SVOCs, PCBs or pesticides were detected at concentrations exceeding RRSCOs. PFAS compounds were not sampled in soil. The remedial investigation was conducted in 2017, prior to NYSDEC's requirement to sample soil for PFAS. Data does not indicate any off-site impacts in soil related to the site. Groundwater - In groundwater, VOCs including PCE, TCE and vinyl chloride were detected at concentrations above their respective NYS Ambient Water Quality Standards and Guidance Values (AWQSGVs). During the original RI in 2017 PCE was detected at a maximum concentration of 10.8 parts per billion, or ppb (AWQSGV is 5 ppb), TCE at 1,070 ppb (AWQSGV is 5 ppb), and vinyl chloride at 203 ppb (AWQSGV is 2 ppb). During a subsequent groundwater pre-design investigation (PDI) conducted in 2024, the maximum detections of these compounds was PCE at 8.7 ppb and vinyl chloride at 80 ppb. TCE was not detected in groundwater during the PDI. The compounds 1,4-dioxane was detected at a maximum concentration of 3.4 ppb (AWQSGV is 0.35 ppb), perfluorooctanesulfonic acid (PFOS) at a maximum concentration of 29.9 parts per trillion, or ppt (AWQSGV is 2.7 ppt), and perfluorooctanoic acid (PFOA) at a maximum concentration of 52 ppt (AWQSGV is 6.7 ppt). No SVOCs, PCBs or pesticides were detected exceeding AWQSGVs. Data does not indicate any off-site impacts in groundwater related to the site. Soil vapor - VOCs were detected at elevated concentrations in on-site soil vapor samples throughout the site. Cis-1,2-dichloroethene was detected at 1,150 micrograms per cubic meter (g/m3) on the southwestern portion of the site. The highest concentrations of PCE and TCE were 8,070 ug/m3 and 7,690 ug/m3 collected from the southeastern and southwestern site boundaries, respectively. PCE and TCE appear to be related to historic manufacturing operations at the site. Elevated concentrations are present at the site boundaries, indicating a potential for off-site migration.

Health Problem:

Access is restricted by a fence. People who enter the site may come into contact with site-related soil and groundwater contamination if they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. There are no occupied buildings on the site so soil vapor intrusion is not a current concern, however environmental sampling indicates soil vapor intrusion from site contamination is a potential concern both off-site and for any future on-site development and occupancy.

DRAFT

ATLANTIC CHESTNUT AFFORDABLE HOUSING LLC- LOT 3 (Continued) **S128906192**

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2016-06-06 09:07:00
Record Upd:	2024-08-16 09:09:00
Updated By:	JHOCONNE
Own Op:	1
Sub Type:	P03
Owner Name:	Michael Wadman
Owner Company:	Atlantic Chestnut Affordable Housing LLC
Owner Address:	902 Broadway, 13th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Michael Wadman
Owner Company:	Atlantic Chestnut Affordable Housing LLC
Owner Address:	902 Broadway, 13th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Cypress Hills Branch
Owner Address:	1197 Sutter Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 5
Owner Address:	127 Pennsylvania Avenue,
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
HW Code:	C224236
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236

DRAFT

ATLANTIC CHESTNUT AFFORDABLE HOUSING LLC- LOT 3 (Continued) **S128906192**

Waste Type:	dichloroethene (cis-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	dichloroethene (1,1-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236
Waste Type:	dichloroethene (trans-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY MANIFEST:

EPA ID:	NYR000243477
Country:	USA
Name:	Atlantic Chestnut Affordable Housing Llc- Lot 3
Address:	275 CHESTNUT ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	275 CHESTNUT ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11208
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Atlantic Chestnut Affordable Housing Llc- Lot 3
Mailing Contact:	Atlantic Chestnut Affordable Housing Llc- Lot 3
Mailing Address 1:	902 BROADWAY
Mailing Address 2:	13TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10010
Mailing Zip 4:	Not reported

DRAFT

ATLANTIC CHESTNUT AFFORDABLE HOUSING LLC- LOT 3 (Continued) **S128906192**

Mailing Country: USA
Mailing Phone: 2158222676

AN284 **ATLANTIC CHESTNUT - LOT 3 - OFF-SITE** **NY BROWNFIELDS** **S128906211**
NE **275 CHESTNUT STREET** **N/A**
1/4-1/2 **BROOKLYN, NY 11208**
0.448 mi.
2364 ft. **Site 3 of 4 in cluster AN**

Relative:
Higher

Actual:
39 ft.

BROWNFIELDS:
Name: ATLANTIC CHESTNUT - LOT 3 - OFF-SITE
Address: 275 CHESTNUT STREET
City,State,Zip: BROOKLYN, NY 11208
Program: BCP
Site Code: 568005
Acres: Not reported
HW Code: C224236A
SWIS: 2401
Town: New York City
Record Added Date: 03/16/2018
Record Updated Date: 11/02/2021
Update By: JHOCONNE
Site Description: Location: The site C224236A is the off-site area associated with the Atlantic Chestnut Lot 3 BCP site C224236, which is located at 275 Chestnut Street in Brooklyn, NY. The Atlantic Chestnut Lot 3 BCP site C224236 is bounded to the north by Atlantic Chestnut Lot 2 BCP site C224235, followed by Atlantic Chestnut Lot 1 BCP site C224234. The Site does not have definite boundaries since it is an off-site project associated with an on-site BCP project. Potentially affected areas from the Atlantic Chestnut Lot 3 BCP Site C224236 include the commercial building (self-storage) to the east and the vacant land to the west of the BCP Site. The off-site areas are not necessarily limited to these areas. Site Features: The off-site area consists of eastern sidewalk of Euclid Ave across from the BCP site followed by the commercial building (self-storage), and western sidewalk of Chestnut Street across from the BCP site, followed by the vacant land. The Atlantic Chestnut Lot 3 BCP Site C224236 at 275 Chestnut Street is currently vacant. Current Zoning and Land Use: The off-site area consists of residential and commercial buildings. The Atlantic Chestnut Lot 3 BCP Site C224236 at 275 Chestnut Street is currently vacant and is zoned as M1-1 and C8-2 for manufacturing and commercial use. The Site is currently vacant and is zoned as M1 1 and C8 2 for manufacturing and commercial use. The surrounding area is developed with residential, commercial, manufacturing, transportation, and industrial uses. The elevated J and Z MTA subway tracks are located above Fulton Street to the north and the Long Island Railroad (LIRR) tracks are located beneath Atlantic Avenue to the south. The site has remained vacant since a July 2012 fire caused severe structural damage to the former site buildings. Past Use of the Site: The site has not yet been identified for its previous historic use. Historic records indicate that the Atlantic chestnut Lot 3 BCP site C224236 was developed with residences and a road in 1887 and with industrial and manufacturing uses, including the Columbia Machine Works and Malleable Iron Company, the Columbia Cable and Electric Corporation, Blue Ridge Farms, Inc., and Chloe Foods Corp. between 1908 and 2012. Prior uses that appear to have led to Site contamination include blacksmithing and stamping, a brass foundry, wood working, a

DRAFT

ATLANTIC CHESTNUT - LOT 3 - OFF-SITE (Continued) **S128906211**

blacksmith, a machine shop, tank and engine rooms, an iron works, wire braiding, and cable manufacturing. Site Geology and Hydrogeology: Surface topography at the Site is generally level, except for the former loading bays, which slope down to the north toward the Site buildings. The Site lies at an elevation of approximately 38 feet above mean sea level. Historic fill materials (including sand, gravel, silt, ash, slag, concrete, and asphalt) exist from just below the surface to approximately 3 to 5 feet below grade (fbg). The fill is underlain by apparent native sand and gravel to approximately 40 fbg. Bedrock was not encountered during any of the investigations conducted at the Site. The surrounding area slopes down to the south. Groundwater was encountered approximately 30 feet below grade and is expected to flow southerly in the Site vicinity. Jamaica Bay is the nearest water body and is located approximately 2.5 miles south of the site. Please see the three Atlantic Chestnut Sites (C224234, C224235 and C224236) for further information regarding their status in the Brownfield Cleanup program.

Env Problem:

During the on-site Remedial Investigation for the BCP Site C224236, soil and groundwater samples were collected and analyzed for volatile organic compounds (VOCs), semi volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Soil vapor samples were analyzed for VOCs. Based on the investigations conducted to date, the primary contaminants of concern for the BCP site C224236 include the solvent-related volatile organic compounds (VOCs), and metals. Soil Trichloroethylene (TCE) was detected in shallow soil on the Northern portion of the BCP site at concentrations exceeding its restricted residential use soil cleanup objective (RRUSCO). TCE was detected in shallow soil on the northern portion of the site at a maximum concentration of 90.1 parts per million (ppm) compared to the RRUSCO of 21 ppm. TCE was also detected in soil from 12 to 13 feet below grade surface on the southwestern portion of the BCP site at a concentration of 5.47 ppm, which exceeds the protection of groundwater soil cleanup objective (PGSCO) of 0.47 ppm. Metal concentrations were detected above their respective RRUSCOs. In shallow soil, mercury was detected on the western portion of the BCP site at a maximum concentration of 7.1 ppm, which exceeds the RRUSCO of 0.81 ppm; arsenic was detected in shallow soil on the Northern portion of the BCP site at a maximum concentration of 21.2 ppm (RRUSCO is 16 ppm). The elevated detection of metals in soil are most likely related to historic fill and/or historic manufacturing operations at the BCP site. Groundwater - In groundwater, VOCs including chloroform, tetrachloroethylene (PCE), TCE and TCE breakdown compounds were detected at concentrations above their respective ambient water quality standards (AWQSs). Chloroform was detected in deep groundwater on the southwestern portion of the site at a maximum concentration of 8 parts per billion (ppb), which exceeds the AWQS of 7 ppb. PCE was detected in an intermediate well on the southeastern portion of the site at a maximum concentration of 10.8 ppb. PCE was detected slightly above the AWQS in shallow groundwater at 6.4 ppb and 5.2 ppb on the northern and western portions of the BCP Site, respectively. Maximum TCE concentration in groundwater was detected at 1,070 ppb on the north-central portion of the site. TCE breakdown compounds, including 1,1-dichloroethylene (1,1-DCE), cis-1,2 dichloroethylene (cis-1,2-DCE), trans-1,2 dichloroethylene (trans-1,2-DCE), and vinyl chloride were detected above their respective AWQSs in shallow and intermediate groundwater samples on the southern portion of the BCP site, close to the in-situ

DRAFT

ATLANTIC CHESTNUT - LOT 3 - OFF-SITE (Continued) **S128906211**

chemical oxidation injection points associated with closed Spill Nos. 8805745 and 0101620. 1,1-DCE, cis-1,2-DCE and trans-1,2-DCE detected at maximum concentration of 11.5 ppb, 646 ppb and 21.3 ppb, respectively, compared to the AWQS of 5 ppb; vinyl chloride detected at a maximum concentration of 203 ppb compared to the AWQS of 2 ppb. In addition to the Chlorinated VOCs, several metals, including manganese, and nickel are present above their respective AWQSs. Manganese and Nickel were detected in the shallow groundwater on the north-central portion of the site at a maximum concentration of 4,950 ppb and 126 ppb, respectively, above their AWQSs. The emerging contaminants 1,4-Dx, PFOS, and PFOA were detected at concentrations below their respective standards. Soil vapor Chlorinated solvent VOCs were identified at elevated concentrations in on-site soil vapor. Cis-1,2-DCE was detected at 1,150 g/m3 on the southwestern portion of the Site. The highest concentrations of PCE and TCE were 8,070 ug/m3 and 7,690 ug/m3 collected from the southeastern and southwestern Site boundaries, respectively. PCE and TCE appear to be related to historic manufacturing operations at the BCP site. Elevated concentrations are present at the BCP site boundaries, indicating a potential for off-site migration.

Health Problem: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2018-05-09 16:08:00
Record Upd: 2018-05-09 16:09:00
Updated By: MXMAGLOI
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
HW Code: C224236A
Waste Type: dichloroethene (1,1-)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224236A
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224236A
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224236A
Waste Type: dichloroethene (cis-1,2-)

DRAFT

ATLANTIC CHESTNUT - LOT 3 - OFF-SITE (Continued) **S128906211**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236A
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224236A
Waste Type:	dichloroethene (trans-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

285
NNW
1/4-1/2
0.453 mi.
2390 ft.

70 ELCON ST/BKLYN **NY LTANKS** **S102671483**
70 ELCON STREET **N/A**
NEW YORK CITY, NY

Relative:
Higher

Actual:
45 ft.

LTANKS:

Name:	70 ELCON ST/BKLYN
Address:	70 ELCON STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8910317 / 1992-12-08
Facility ID:	8910317
Site ID:	68948
Spill Date:	1990-01-27
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1992-12-08
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1990-01-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-01-31
Spill Record Last Update:	1992-12-10
Spiller Name:	Not reported
Spiller Company:	PETRO OIL CO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	65603

DRAFT

70 ELCON ST/BKLYN (Continued) **S102671483**

Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	TANK OVERFILL, SPEEDY DRY USED FOR CLEAN UP.

All Materials:

Site ID:	68948
Operable Unit ID:	937334
Operable Unit:	01
Material ID:	443422
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP286 **NY LTANKS** **S101341290**
NW **180 ARLINGTON AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.456 mi.
2410 ft. **Site 1 of 2 in cluster AP**

Relative:
Higher

Actual:
39 ft.

LTANKS:

Name:	180 ARLINGTON AVE
Address:	180 ARLINGTON AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9413591 / 1995-01-12
Facility ID:	9413591
Site ID:	65678
Spill Date:	1995-01-12
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1995-01-12
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-01
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU OIL CO
Spiller Address:	740 JAMICA AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

DRAFT

(Continued) **S101341290**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266255
Latitude:	40.6802760
Longitude:	-73.8881095
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE
Remarks:	CUSTOMER OVERORDERED 400 GALS OF FUEL-DID NOT NEED THAT MUCH CAUSIONG OVERFILL.

All Materials:

Site ID:	65678
Operable Unit ID:	1011156
Operable Unit:	01
Material ID:	372338
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

SPILLS:

Name:	180 ARLINGTON AVENUE
Address:	180 ARLINGTON AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9313892 / 1994-02-24
Facility ID:	9313892
Facility Type:	ER
DER Facility ID:	266255
Site ID:	331052
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1994-02-24
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1994-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-02-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-02-25
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU
Spiller Address:	Not reported

DRAFT

(Continued) **S101341290**

Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6802760
Longitude:	-73.8881095
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG
Remarks:	FILL BOX LEAKING - SPILL DID CLEAN UP.

All Materials:

Site ID:	331052
Operable Unit ID:	995932
Operable Unit:	01
Material ID:	389249
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	180 ARLINGTON AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6801219
Longitude:	-73.8880314
Type Of Ownership Code:	Not reported
Owner Name:	CRESPO, ARLENNY
Borough:	BK
Tax Block:	3937
Tax Lot:	20
Community District:	305
Census Tract 2020:	3117201
Census Block 2020:	31172012003
Census Tract 2010:	1172.01
Census Block 2010:	2003
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R4: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported

DRAFT

(Continued) **S101341290**

Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B2: Two Family Dwellings - Frame
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	3750
Total Building Floor Area:	2480
Commercial Floor Area:	0
Residential Floor Area:	2480
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	2.5000000
Residential Units:	2
Total Units:	2
Lot Frontage:	37.5000000
Lot Depth:	100.0000000
Building Frontage:	21.0000000
Building Depth:	48.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	22560.00000
Assessed Total Value:	46200.00000
Exempt Total Value:	0.00000
Year Built:	1905
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.66000000000
Maximum Allowable Residential Far:	0.75000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039370020.00000000
Condominium Number:	Not reported
Census Tract 2:	117201
X Coordinate:	1015306
Y Coordinate:	187083
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 002
Tax Map #:	31302
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

DRAFT

(Continued) **S101341290**

Version Number:	24v4.1
Changed By DCP:	Not reported

AN287 **242 CHESTNUT STREET** **US BROWNFIELDS** **1027574055**
NNE **242 CHESTNUT STREET** **FINDS** **N/A**
1/4-1/2 **BROOKLYN, NY 11208**
0.459 mi.
2424 ft. **Site 4 of 4 in cluster AN**

Relative: **Higher**

Actual: **39 ft.**

US BROWNFIELDS:

Name:	242 Chestnut Street
Address:	242 Chestnut Street
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233521
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4141, Lot 30
Parcel Size:	0.26
Latitude:	40.6819119
Longitude:	-73.875538
Census Tract:	36047117800
State or Tribal Voluntary Response Program:	N
Program Name:	BF
AA Activity Funded:	Phase I
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	2016-02-10 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2016-05-31 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported

DRAFT

242 CHESTNUT STREET (Continued) **1027574055**

Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	0.26
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

DRAFT

242 CHESTNUT STREET (Continued) **1027574055**

Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	10959
Below Poverty Percent:	30.86
Meidan Income:	15853
Meidan Income Number:	19896
Meidan Income Percent:	56.03
Vacant Housing Number:	2017
Vacant Housing Percent:	16.91
Unemployed Number:	1148
Unemployed Percent:	3.23

Name:	242 Chestnut Street
Address:	242 Chestnut Street
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233521
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4141, Lot 30
Parcel Size:	0.26
Latitude:	40.6819119
Longitude:	-73.875538
Census Tract:	36047117800
State or Tribal Voluntary Response Program:	N
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported

DRAFT

242 CHESTNUT STREET (Continued) **1027574055**

Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported

DRAFT

242 CHESTNUT STREET (Continued) **1027574055**

Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	0.26
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	10959
Below Poverty Percent:	30.86
Meidan Income:	15853
Meidan Income Number:	19896
Meidan Income Percent:	56.03
Vacant Housing Number:	2017
Vacant Housing Percent:	16.91
Unemployed Number:	1148
Unemployed Percent:	3.23

Name:	242 Chestnut Street
Address:	242 Chestnut Street
City,State,Zip:	BROOKLYN, NY 11208
Property ID:	233521
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 4141, Lot 30
Parcel Size:	0.26
Latitude:	40.6819119
Longitude:	-73.875538
Census Tract:	36047117800
State or Tribal Voluntary Response Program:	N
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported

DRAFT

242 CHESTNUT STREET (Continued) **1027574055**

Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported

DRAFT

242 CHESTNUT STREET (Continued) **1027574055**

RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	0.26
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	10959
Below Poverty Percent:	30.86
Meidan Income:	15853
Meidan Income Number:	19896
Meidan Income Percent:	56.03
Vacant Housing Number:	2017
Vacant Housing Percent:	16.91
Unemployed Number:	1148
Unemployed Percent:	3.23

FINDS:
Registry ID: 110071349633

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DRAFT

AP288 **187 ARLINGTON AVE/BKLYN** **NY LTANKS** **S102671607**
NW **187 ARLINGTON AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.468 mi.
2470 ft. **Site 2 of 2 in cluster AP**

Relative:
Higher

Actual:
39 ft.

LTANKS:

Name:	187 ARLINGTON AVE/BKLYN
Address:	187 ARLINGTON AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9009774 / 1990-12-08
Facility ID:	9009774
Site ID:	106791
Spill Date:	1990-12-08
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1990-12-08
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1990-12-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-18
Spill Record Last Update:	1991-01-08
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU OIL CO
Spiller Address:	740 JAMAICA AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	93988
Latitude:	40.6804450
Longitude:	-73.8878330
DEC Memo:	Not reported
Remarks:	CUSTOMER OVERORDERED, BAERENKLAU TO CLEAN UP WITH SPEEDY DRY.

All Materials:

Site ID:	106791
Operable Unit ID:	946811
Operable Unit:	01
Material ID:	429969
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

AO289 **MALDONDAO HOME - TTF** **NY LTANKS** **S108298717**
WNW **2849 FULTON STREET** **NY NYC LAND USE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.472 mi.
2492 ft. **Site 3 of 3 in cluster AO**

Relative: **Higher**
Actual: **44 ft.**

LTANKS:

Name:	MALDONDAO HOME - TTF
Address:	2849 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0608616 / 2015-04-02
Facility ID:	0608616
Site ID:	372626
Spill Date:	2006-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-10-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-27
Spill Record Last Update:	2015-04-03
Spiller Name:	RAMONE MALDONADO
Spiller Company:	MALDONDAO HOME
Spiller Address:	2849 FULTON STREET
Spiller County:	001
Spiller Contact:	RAMONE MALDONADO
Spiller Phone:	(718) 827-0074
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	322361
Latitude:	40.6784936
Longitude:	-73.8894724
DEC Memo:	8/17/12 Spill re-assigned to T. Demeo as per RSE. bf 10/16/14-Hiralkumar Patel. reviewed available information for DEC DeMeo. alternate address: none no PBS or other spills found. the subject case was reported due to tightness test failure of 1,000 gal #2 oil tank. Ramon Maldonado **property owner** 90-22 215th Place Queens Village, NY 11428-1230 PH. (718) 827-0074 email: cranecooling@hotmail.COM 2/12/15 TJD Spill reassigned from DeMeo to Patel 04/02/15-Hiralkumar Patel. 2:30 PM:- visited site. met Mr. Maldonado. he mentioned that the 1,000 gal tank was aboveground and located in basement along building's southern foundation wall. he also mentioned that the tank was out-of-service since they installed a new gas service sometime in 2000. during a refinance process in 2006, bank asked for tank test. after it failed, the out-of-service tank was removed. no signs of oil spill or petroleum odors noted in the basement. case closed.
Remarks:	Not reported

DRAFT

MALDONDAO HOME - TTF (Continued) **S108298717**

All TTF:

Facility ID:	0608616
Spill Number:	0608616
Spill Tank Test:	1550390
Site ID:	372626
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	372626
Operable Unit ID:	1130363
Operable Unit:	01
Material ID:	2120039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2849 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6786574
Longitude:	-73.8893714
Type Of Ownership Code:	Not reported
Owner Name:	MALDONADO RAMON C
Borough:	BK
Tax Block:	3935
Tax Lot:	44
Community District:	305
Census Tract 2020:	3114600
Census Block 2020:	31146001005
Census Tract 2010:	1146
Census Block 2010:	1005
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820

DRAFT

MALDONDAO HOME - TTF (Continued) **S108298717**

Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	K1: Store Buildings (Taxpayers Included) - One Story Retail Building
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	6061
Total Building Floor Area:	6005
Commercial Floor Area:	6005
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	5405
Garage Floor Area:	600
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	2
Lot Frontage:	73.0000000
Lot Depth:	90.5000000
Building Frontage:	73.0000000
Building Depth:	90.8000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	108900.00000
Assessed Total Value:	361800.00000
Exempt Total Value:	0.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.99000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039350044.00000000
Condominium Number:	Not reported
Census Tract 2:	1146

DRAFT

MALDONDAO HOME - TTF (Continued) **S108298717**

X Coordinate:	1014935
Y Coordinate:	186549
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 002
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AQ290 **P.S. 290 - BROOKLYN** **NY LTANKS** **S108299052**
WNW **135 SCHENCK AVENUE** **NY LEAD** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.477 mi.
2517 ft. **Site 1 of 2 in cluster AQ**

Relative: **Higher**

Actual: **45 ft.**

LTANKS:

Name:	PS 290 (SCHOOL)
Address:	135 SCHENCK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0610197 / 2007-02-26
Facility ID:	0610197
Site ID:	374588
Spill Date:	2006-12-07
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2006-12-07
CID:	406
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-07
Spill Record Last Update:	2007-02-26
Spiller Name:	KIM LEE ALLEN
Spiller Company:	PS 290 (SCHOOL)
Spiller Address:	135 SCHENCK AVE.
Spiller County:	001
Spiller Contact:	KIM LEE ALLEN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	324261
Latitude:	40.6780150
Longitude:	-73.8897090

DRAFT

P.S. 290 - BROOKLYN (Continued) **S108299052**

DEC Memo: 12/11/2006 Sangesland spoke to Joe Ostrowski at PTC. He said PTC cleaned up a spill in the basement of the building and outside. There was soil contamination and the area was dug out. Several endpoint samples were taken and the results will be submitted to DEC as soon as PTC gets them from the lab. 12/19/06 - Raphael Ketani. On 12/7/06, T&S Trucking (718) 499-2900 (Angelo Solimine) delivered the oil. Custodian had ordered 5000 gals., but tank already had 3900 gals. of #4. Oil shot out the vent pipe and onto the concrete. Kim Lee Allen is the school contact. The PBS case is #2-356581 and shows an active 10,000 gal. tank with #4 oil. 1/5/07 - Raphael Ketani. I tried to call Ms. Allen (718) 647-1113 and Mark Salamack of PTC (718) 624-4842, but could only leave messages. Mr. Salamack called me back. He said that the school usually produces its own report, but he will send me the analyticals. 2/23/07 - Raphael Ketani. I tried to call Mr. Salamack, but could only leave a message. 3/26/07 - Raphael Ketani. I received a FAX from Mr. Salamack containing manifests and end-point sample results. There were 2 manifests and 5 sample results. All of the samples were either non-detect or had hits that were very far below the TAGM RSCO limit. One sample had a number of VOC and SVOC hits, but these were well below the limits, except for benzo(a)pyrene which was just very slightly above with 81.2 ppb (limit 61 ppb). I called up Mr. Salamack regarding the amount of oil that had spilled inside the school and the vapor concentrations in the school. He said that he will have to talk to someone in PTC who knows the cleanup and get back to me. He said that it was #4 oil. I told him I needed a letter describing how much was spilled and the cleanup. He said that he would send me the letter. Mr. Salamack called me back a little while later. He said that the spill was an overfill and that the tank doesn't have a vent alarm or high level alarm. Mr. Salamack FAXed me a letter describing how the spill happened and what was done to clean it up. It said that 30 gals. came out the vent pipe as an overfill and contaminated the soil and conrete. It was also stated that the custodian opened the stick line and another 10 gals. spilled out, ran down the tank, and onto the painted floor of the tank room. Mr. Salamack's letter stated that the soil was dug out, absorbent was put down on the concrete outside, and the conrete next to the tank was pressure washed. Based upon the letter mentioned above, the manifests and the soil sample results, I am closing the spill case.

Remarks: Driver was making a delivery for Castle Oil. The Custodian for the school read the gauge and gave the okay for a 5000gal. Tank originally had 3989 gal. Material shot out of the vent which is outside the school. Spill impacted the concrete. T& S Trucking has a crew on route to contain the spill but caller does not know who is doing the clean up.

All TTF:

Facility ID:	0610197
Spill Number:	0610197
Spill Tank Test:	1550490
Site ID:	374588
Tank Number:	Not reported
Tank Size:	10000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	02
Source:	Not reported

DRAFT

P.S. 290 - BROOKLYN (Continued) **S108299052**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	374588
Operable Unit ID:	1132260
Operable Unit:	01
Material ID:	2121991
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	60.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LEAD 2:

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	309
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	108 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	114 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

DRAFT

P.S. 290 - BROOKLYN (Continued) **S108299052**

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	116 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	208 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	216 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	308 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	316 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE

DRAFT

P.S. 290 - BROOKLYN (Continued) **S108299052**

City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	408 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	416 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	Caf
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	1st Floor
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	Caf
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19

DRAFT

P.S. 290 - BROOKLYN (Continued) **S108299052**

Building Code:	K290
Room:	201
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	203
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	209
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	213
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	217
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	219

DRAFT

P.S. 290 - BROOKLYN (Continued) **S108299052**

Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	221
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	223
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA
Name:	P.S. 290 - BROOKLYN
Address:	135 SCHENCK AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	19
Building Code:	K290
Room:	Not reported
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

291
ENE
1/4-1/2
0.477 mi.
2518 ft.

90 MCKINLEY AVE
90 MCKINLEY AVE
BROOKLYN, NY

NY LTANKS **S104621601**
NY Spills **N/A**

Relative:
Higher

Actual:
40 ft.

LTANKS:

Name:	RESIDENCE
Address:	90 MCKINLEY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001910 / 2003-03-21
Facility ID:	0001910
Site ID:	123566
Spill Date:	2000-05-11
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SACCACIO

DRAFT

90 MCKINLEY AVE (Continued) **S104621601**

Referred To:	Not reported
Reported to Dept:	2000-05-15
CID:	389
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-15
Spill Record Last Update:	2003-09-26
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	UNKNOWN
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	107094
Latitude:	40.6793958
Longitude:	-73.8716645
DEC Memo:	Not reported
Remarks:	caller reporting a spill of material from an overfill from an oil company two oil companies filled the same tank and caused a overfill and spill unk who filled last. clean up was done but there are still fumes no callbac necessary

All Materials:

Site ID:	123566
Operable Unit ID:	823821
Operable Unit:	01
Material ID:	550294
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	90 MCKINLEY AVE
Address:	90 MCKINLEY AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0001900 / 2005-11-03
Facility ID:	0001900
Facility Type:	ER
DER Facility ID:	107094
Site ID:	123565
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401

DRAFT

90 MCKINLEY AVE (Continued) **S104621601**

Spill Date:	2000-05-12
Investigator:	TXSMITH
Referred To:	Not reported
Reported to Dept:	2000-05-15
CID:	397
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-15
Spill Record Last Update:	2005-11-03
Spiller Name:	Not reported
Spiller Company:	APRA FUEL OIL CO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
Latitude:	40.6793958
Longitude:	-73.8716645
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 12/20/00 Reassinged from Saccacio. Daniel Sully called, the attorney fro APRE Fuel Oil Co. Mr. Sully was upset by Saccacio's letter requiring additional work within 45 days. Sully will submit to DEC the following information: 1 - Whether APRA delivered oil on or about the spill date 2 - The name of the other oil company that APRA is claiming may have delivered the oil 3 - Who performed/contracted the original mop-up 4 - The results of the pressure test paid for by APRA 5 - Photos taken by Mr. Sully days after the spill 1/11/00 Attempted to return Mr. Sukal's call, no answer, no voice mail. 1/17/00 Called Adrien Sukal at work. 2/09/01 Referred to legal. Administrative Order on Consent signed by APRA From: Jennifer Rommel [mailto:jmrommel@gw.dec.state.ny.us] Sent: Thursday, September 25, 2003 3:22 PM To: 'Dave Rubinton (dsrubinton@gw.dec.state.ny.us)'; charlies@pwgrosser.com Subject: Re: APRA Fuel Co. - 90 McKinley Ave. Franklyn Sukal just called. He can be reached at XX. >>> Charles Sosik <charlies@pwgrosser.com> 09/25/03 04:03PM >>> Jennifer, I spoke with Mr. Sukal. He said that he has been sick for some time and is still recovering. When I mentioned sealing the floor around the tank he said that he was not ready and probably would not be ready this year. He said he would call me when he was. >>> Jennifer Rommel 09/26/03 10:21AM >>> Charlie, I discussed with Dave Rubinton. The AOC will be extended for another year to allow Mr. Sukal to recover. Call with questions. Jennifer 718-482-4934 01/26/04 Transferred from Rommel to Austin 02/17/04:

DRAFT

90 MCKINLEY AVE (Continued) **S104621601**

Reassigned from AUSTIN to KRIMGOLD. 7/14/05 TAS Tried calling Mr. Sukal, woman who did not speak
english answered and did not provide any help. Contacted APRA's consultant (P.W. Grosser), he
stated the samples did not show a problem and the only work to do was to seal the floor around the
tank. Mr. Sukal has not contacted anyone to seal the floor. Will try calling at another time.
9/26/05 TAS Sent letter requesting information. Letter was not deliverable. 11/3/05 TAS Since I
have been unable to contact the property owner and the September 23, 2003 letter from P.W. Grosser
to Jennifer Rommel states that the work still required was minor (and there was no contact from the
site owner to complete the work) the spill has been closed.

Remarks: caller has oil in basement after service call

All Materials:

Site ID:	123565
Operable Unit ID:	823811
Operable Unit:	01
Material ID:	550284
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR292 **2827 ATLANTIC AVENUE** **US BROWNFIELDS 1027574057**
West **2827 ATLANTIC AVENUE** **FINDS N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.477 mi.
2518 ft. **Site 1 of 3 in cluster AR**

Relative:
Higher

Actual:
44 ft.

US BROWNFIELDS:

Name:	2827 Atlantic Avenue
Address:	2827 Atlantic Avenue
City,State,Zip:	BROOKLYN, NY 11207
Property ID:	233523
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 3948, Lot 134
Parcel Size:	0.14
Latitude:	40.6769324
Longitude:	-73.8900294
Census Tract:	36047119800
State or Tribal Voluntary Response Program:	N
Program Name:	BF
AA Activity Funded:	Phase I
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported

DRAFT

2827 ATLANTIC AVENUE (Continued) **1027574057**

Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	2016-02-10 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2016-05-31 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported

DRAFT

2827 ATLANTIC AVENUE (Continued) **1027574057**

Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.14
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	9120
Below Poverty Percent:	32.45
Meidan Income:	19776
Meidan Income Number:	15461
Meidan Income Percent:	55.01
Vacant Housing Number:	1180
Vacant Housing Percent:	11.64
Unemployed Number:	1442
Unemployed Percent:	5.13

Name:	2827 Atlantic Avenue
Address:	2827 Atlantic Avenue
City,State,Zip:	BROOKLYN, NY 11207
Property ID:	233523
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 3948, Lot 134
Parcel Size:	0.14
Latitude:	40.6769324

DRAFT

2827 ATLANTIC AVENUE (Continued) **1027574057**

Longitude:	-73.8900294
Census Tract:	36047119800
State or Tribal Voluntary Response Program:	N
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported

DRAFT

2827 ATLANTIC AVENUE (Continued) **1027574057**

Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.14
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	9120
Below Poverty Percent:	32.45
Meidan Income:	19776
Meidan Income Number:	15461
Meidan Income Percent:	55.01
Vacant Housing Number:	1180
Vacant Housing Percent:	11.64
Unemployed Number:	1442
Unemployed Percent:	5.13

DRAFT

2827 ATLANTIC AVENUE (Continued) **1027574057**

FINDS:
Registry ID: 110071349635

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AS293 **SPILL NUMBER 9312952** **UST FINDER RELEASE** **1029063740**
West **2820 ATLANTIC AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.479 mi.
2530 ft. **Site 1 of 3 in cluster AS**

Relative:
Higher

Actual:
44 ft.

UST FINDER RELEASE:

Object ID:	259173
Facility ID:	NY189529
Lust ID:	NY9312952
Name:	SPILL NUMBER 9312952
Address:	2820 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1993/08/17 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	10261
Domestic Wells within 1500ft:	3
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8892099999999
Y Coord:	40.6766900000001
Latitude:	40.67669
Longitude:	-73.88921

DRAFT

AS294 **GASETERIA** **UST FINDER RELEASE** **1029063739**
West **2820 ATLANTIC AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.479 mi.
2530 ft. **Site 2 of 3 in cluster AS**

Relative: **Higher**
Actual: **44 ft.**

UST FINDER RELEASE:

Object ID:	259143
Facility ID:	NY189529
Lust ID:	NY9403819
Name:	GASETERIA
Address:	2820 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1994/06/17 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	10366
Domestic Wells within 1500ft:	1
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.89014
Y Coord:	40.6765100000001
Latitude:	40.67651
Longitude:	-73.89014

AS295 **GASETERIA** **NY LTANKS** **S102672366**
West **2820 ATLANTIC AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.479 mi.
2530 ft. **Site 3 of 3 in cluster AS**

Relative: **Higher**
Actual: **44 ft.**

LTANKS:

Name:	SPILL NUMBER 9312952
Address:	2820 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9312952 / 2003-01-27
Facility ID:	9312952
Site ID:	229957
Spill Date:	1993-08-17
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility

DRAFT

GASETERIA (Continued) **S102672366**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1994-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-02-10
Spill Record Last Update:	2004-01-29
Spiller Name:	Not reported
Spiller Company:	GASETERIA - GEORGE ESAYAN
Spiller Address:	53-02 11TH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	189529
Latitude:	40.6766922
Longitude:	-73.8892103
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Operated as a Mobil as of approx. 10/95. All 550's pulled 5/95 as per Mobil's new PBS report #2-602236. GOC never notified DEC when tanks were pulled or when property transferred. Tank closure report pending. 1/27/2003-Vought-Spill transferred from Rommel to Vought. Vought spoke to Steven Muller and site is currently Mobil Exxon. This spill closed due to historic spill (at least ten years old) and tank overfill spill on concrete. Tanks involved in original spill were removed and replaced by Mobil. Spill closed by Vought.
Remarks:	DISCOVERED AS RESULT OF ONGOING INSPECTION OF GASETERIA STATIONS.(SULLIVAN)

All Materials:

Site ID:	229957
Operable Unit ID:	994844
Operable Unit:	01
Material ID:	388356
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	GASETERIA
Address:	2820 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9403819 / 2006-02-14

DRAFT

GASETERIA (Continued) **S102672366**

Facility ID:	9403819
Site ID:	229958
Spill Date:	1994-06-17
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	aaobliga
Referred To:	Not reported
Reported to Dept:	1994-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-09-26
Spill Record Last Update:	2008-08-07
Spiller Name:	Not reported
Spiller Company:	GASETERIA
Spiller Address:	2820 ATLANTIC AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	189529
Latitude:	40.6765149
Longitude:	-73.8901380
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Formerly Wilson Spill. 1/12/2004-Vought-Spill transferred from Rommel to Vought. 9/26/05-Obligado-Spill transferred from Vought to Obligado 2/14/06 - Obligado - Close spill, consolidate with spill already closed by Vought sp#9312952
Remarks:	CONTAMINATED SOIL FOUND AT FILL BOXES AND SUCTION PUMPS.

All Materials:

Site ID:	229958
Operable Unit ID:	997506
Operable Unit:	01
Material ID:	383983
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

DRAFT

296
East
1/4-1/2
0.481 mi.
2541 ft.

APT BUILDING
2736 PITKIN AVE
BROOKLYN, NY

NY LTANKS **S114561793**
NY LEAD **N/A**
NY NYC LAND USE

Relative:
Lower

Actual:
28 ft.

LTANKS:

Name:	APT BUILDING
Address:	2736 PITKIN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1307476 / 2013-12-16
Facility ID:	1307476
Site ID:	488145
Spill Date:	2013-10-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2013-10-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-10-21
Spill Record Last Update:	2013-12-16
Spiller Name:	TED HUGH
Spiller Company:	TED HUGH
Spiller Address:	2736 PITKIN AVE
Spiller County:	999
Spiller Contact:	TED HUGH
Spiller Phone:	(646) 431-6147
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	443234
Latitude:	40.6754430
Longitude:	-73.8711620
DEC Memo:	10/21/13 - Obligado (DDO) - I contacted BOB IRVIN # (631) 321-4670 at ProTest. According to Mr. Irvin, the tank is a 1080 gallon AST in the apt basement. They believe it was a dry leak caused by the vent line - they noticed corrosion on the vent line. They said no oil was spilled. They gave Mr. Ted Hugh a proposal for a retest. I contacted Ted Hugh (646) 431-6147. TTF letter sent to Ted Hugh P.O. Box 250748 NY, NY 10025 11/1/13 - Obligado - I returned Ted Hughes voicemail message. He was inquiring about what to do about the failed test. However from the time of the original voice mail message, he had spoken with the tank test company and he said he will investigate and fix the cause of the tank failure and retest. He said he will keep me updated. 11/12/13-Hiralkumar Patel. alternate address: 2732-2736 Pitkin Ave no PBS or other spills found. 3:49 PM:- left message for Mr. Hughes. 11/26/13-Hiralkumar Patel. received message from Mr. Hughes. he mentioned that tank system failed the test due to corroded vent pipe. 12/02/13-Hiralkumar Patel. received report from Elite

DRAFT

APT BUILDING (Continued) **S114561793**

Environmental. Elite Env. disconnected the corroded vent line and tested remaining tank system which was found tight. after testing, they reconnected the corroded vent line. the tank test result dated 11/14/13 is missing calculation page. 12/05/13-Hiralkumar Patel. 12:55 PM:- received call from Mr. Hugh inquiring about case closure. informed him that the department requires repair/replacement of leaking vent line and submission of document confirming such work. DJW Mgmt, LLC. **property owner** 532 West 111th Street, # 83 New York, NY 10025 DJW Mgmt, LLC. **property owner** c/o Ted Hugh P.O. Box 250748 New York, NY 10025 PH. (646) 431-6147 email: hucap_mgmt@yahoo.com 1:51 PM:- sent email to Mr. Hugh and asked to submit document confirming repair/replacement of leaking vent pipe and result of tank system testing. 12/13/13-Hiralkumar Patel. 2:31 PM:- received email from Mr. Hugh including report from Elite Env. William Silsdorf of Elite Env. mentioned that the vent pipe was found to be repaired when it entered the building. Elite Env. performed tightness test of UST system on 12/11/13 and it passed. the report is missing calculation part of tank test result. 2:46 PM:- left message for William Silsdorf at Elite Environmental. William Silsdorf Elite Environmental & Tank Testing Services Ph. (845) 528-0370 2:48 PM:- spoke with Mr. Hugh. he mentioned that the vent pipe was repaired by his plumber. leak was found in portion of vent line that crosses the foundation wall. Mr. Hugh confirmed that the vent pipe does not run underground, except when it crosses the wall. asked him to submit color pics of vent pipe area and complete test result. 2:52 PM:- sent email to Mr. Hugh and asked him to submit following: - color pictures of vent pipe - inside and outside the building, area where repair made - complete tank test report (including calculation part) and confirmation on test result showing tight tank system (not only tank) 2:57 PM:- received email from Mr. Hugh including pics of vent pipe. 3:08 PM:- received call from Mr. Silsdorf. asked him to submit calculation page of tank test result and revised result showing tight tank system.. 3:24 PM:- received email from Mr. Silsdorf including revised report. 12/16/13-Hiralkumar Patel. based on available information, case closed. 11:17 AM:- sent spill closure letter to Mr. Hugh. letter emailed to Mr. Hugh.

Remarks: test failure, retest pending

All Materials:

Site ID:	488145
Operable Unit ID:	1237775
Operable Unit:	01
Material ID:	2237533
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208

DRAFT

APT BUILDING (Continued) **S114561793**

Violation ID:	17457647
Building ID:	354371
Registration ID:	359099
Apartment:	5
Story:	2
Class:	Most Serious
Inspection Date:	11/24/2024
Approved Date:	11/24/2024
Original Certify By Date:	12/24/2024
Original Correct By Date:	12/19/2024
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	9449780
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM WEST AT NORTH WALL DOOR FRAME, 2nd CLOSET FROM WEST AT NORTH WALL DOOR, 2nd CLOSET FROM WEST AT NORTH WALL DOO FRAME, NORTH WALL, SOUTH WALL, EAST WALL, WEST WALL, 1st WINDOW FRAME FROM NORTH AT EAST WALL, 2nd WINDOW FRAME FROM NORTH AT EAST WALL IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT 5, 2nd STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	11/25/2024
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	11/25/2024
Name:	Not reported
Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	16566051
Building ID:	354371
Registration ID:	359099
Apartment:	4
Story:	Not reported
Class:	Most Serious
Inspection Date:	10/31/2023
Approved Date:	01/01/2024
Original Certify By Date:	01/11/2024
Original Correct By Date:	01/06/2024
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	618
NOV ID:	8870644
NOV Description:	27-2056.7 ADM CODE: CORRECT FAILURE TO PROVIDE TO THE DEPARTMENT WITHIN 45 DAYS OF DEMAND ALL RECORDS REQUIRED TO BE MAINTAINED BY OWNER PURSUANT TO LOCAL LAW 1 OF 2004 RELATED TO LEAD-BASED PAINT NOTICES, INSPECTIONS AND REMEDIATION/ABATEMENT ACTIVITIES.
NOV Issued Date:	01/02/2024
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	01/02/2024
Name:	Not reported

DRAFT

APT BUILDING (Continued) **S114561793**

Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	13334792
Building ID:	354371
Registration ID:	359099
Apartment:	4
Story:	1
Class:	Most Serious
Inspection Date:	10/09/2019
Approved Date:	10/10/2019
Original Certify By Date:	11/13/2019
Original Correct By Date:	11/08/2019
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6633400
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FROM EAST AT SOUTH WALL, 1st DOOR FRAME FROM EAST AT SOUTH WALL IN THE FOYER LOCATED AT APT 4, 1st STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	10/11/2019
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	03/10/2020

Name:	Not reported
Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	17457608
Building ID:	354371
Registration ID:	359099
Apartment:	5
Story:	2
Class:	Most Serious
Inspection Date:	11/24/2024
Approved Date:	11/24/2024
Original Certify By Date:	12/24/2024
Original Correct By Date:	12/19/2024
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	9449780
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FROM SOUTH AT WEST WALL, NORTH WALL IN THE FOYER LOCATED AT APT 5, 2nd STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	11/25/2024
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	11/25/2024

Name:	Not reported

DRAFT

APT BUILDING (Continued) **S114561793**

Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	17457649
Building ID:	354371
Registration ID:	359099
Apartment:	5
Story:	2
Class:	Most Serious
Inspection Date:	11/24/2024
Approved Date:	11/24/2024
Original Certify By Date:	12/24/2024
Original Correct By Date:	12/19/2024
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	9449780
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, SOUTH WALL, EAST WALL, WEST WALL, 1st WINDOW FRAME FROM NORTH AT EAST WALL IN THE 1st ROOM FROM EAST AT SOUTH LOCATED AT APT 5, 2nd STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	11/25/2024
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	11/25/2024

Name:	Not reported
Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	17457651
Building ID:	354371
Registration ID:	359099
Apartment:	5
Story:	2
Class:	Most Serious
Inspection Date:	11/24/2024
Approved Date:	11/24/2024
Original Certify By Date:	12/24/2024
Original Correct By Date:	12/19/2024
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	9449780
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL, EAST WALL, 1st WALL CABINET FROM WEST AT NORTH WALL, 1st WINDOW FRAME FROM EAST AT SOUTH WALL IN THE KITCHEN LOCATED AT APT 5, 2nd STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	11/25/2024
Current Status ID:	2
Current Status:	NOV SENT OUT
Current Status Date:	11/25/2024

DRAFT

APT BUILDING (Continued) **S114561793**

NYC LAND USE:

Name:	Not reported
Address:	2736 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6752488
Longitude:	-73.8712577
Type Of Ownership Code:	Not reported
Owner Name:	DJW MGMT LLC
Borough:	BK
Tax Block:	4233
Tax Lot:	23
Community District:	305
Census Tract 2020:	3119600
Census Block 2020:	31196003001
Census Tract 2010:	1196
Census Block 2010:	3001
School District:	19
City Council District:	42
Fire Company:	L107
Police Precinct:	75
Health Center District:	33
Health Area:	6410
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2D
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	4308
Total Building Floor Area:	8151
Commercial Floor Area:	0
Residential Floor Area:	8151
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	12
Total Units:	12
Lot Frontage:	43.0800000
Lot Depth:	100.0000000
Building Frontage:	27.5000000

DRAFT

APT BUILDING (Continued) **S114561793**

Building Depth:	90.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	1
Assessed Land Value:	58050.00000
Assessed Total Value:	291150.00000
Exempt Total Value:	0.00000
Year Built:	1925
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.89000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3042330023.00000000
Condominium Number:	Not reported
Census Tract 2:	1196
X Coordinate:	1019961
Y Coordinate:	185314
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 041
Tax Map #:	31307
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AR297 **2817 ATLANTIC AVENUE** **US BROWNFIELDS** **1027574056**
West **2817 ATLANTIC AVENUE** **FINDS** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.485 mi.
2559 ft. **Site 2 of 3 in cluster AR**

Relative: **Higher**

Actual: **44 ft.**

US BROWNFIELDS:

Name:	2817 Atlantic Avenue
Address:	2817 Atlantic Avenue
City,State,Zip:	BROOKLYN, NY 11207
Property ID:	233522
Property Alias:	Not reported
Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 3948, Lot 43
Parcel Size:	0.15
Latitude:	40.676893
Longitude:	-73.890222
Census Tract:	36047119800
State or Tribal Voluntary Response Program:	N
Program Name:	BF

DRAFT

2817 ATLANTIC AVENUE (Continued) **1027574056**

AA Activity Funded:	Phase I
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	2016-02-10 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2016-05-31 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported

DRAFT

2817 ATLANTIC AVENUE (Continued) **1027574056**

RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.15
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	9124
Below Poverty Percent:	32.45
Meidan Income:	19936
Meidan Income Number:	15466
Meidan Income Percent:	55.01
Vacant Housing Number:	1180
Vacant Housing Percent:	11.63
Unemployed Number:	1442
Unemployed Percent:	5.13

Name:	2817 Atlantic Avenue
Address:	2817 Atlantic Avenue
City,State,Zip:	BROOKLYN, NY 11207
Property ID:	233522
Property Alias:	Not reported

DRAFT

2817 ATLANTIC AVENUE (Continued) **1027574056**

Recipient Name:	City of New York
Grant Type:	Hazardous
Property Number:	Block 3948, Lot 43
Parcel Size:	0.15
Latitude:	40.676893
Longitude:	-73.890222
Census Tract:	36047119800
State or Tribal Voluntary Response Program:	N
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96281015
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported

DRAFT

2817 ATLANTIC AVENUE (Continued) **1027574056**

Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.15
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	9124
Below Poverty Percent:	32.45
Meidan Income:	19936
Meidan Income Number:	15466
Meidan Income Percent:	55.01
Vacant Housing Number:	1180

DRAFT

2817 ATLANTIC AVENUE (Continued) **1027574056**

Vacant Housing Percent: 11.63
Unemployed Number: 1442
Unemployed Percent: 5.13

FINDS:
Registry ID: 110071349634

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

298
SSE
1/4-1/2
0.488 mi.
2575 ft.

SMITH RESIDENCE
363 MONTAUK AVE
BROOKLYN, NY

NY LTANKS **S107410536**
N/A

Relative:
Lower

Actual:
19 ft.

LTANKS:

Name:	SMITH RESIDENCE
Address:	363 MONTAUK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0507203 / 2005-10-05
Facility ID:	0507203
Site ID:	352562
Spill Date:	2005-09-14
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2005-09-14
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-14
Spill Record Last Update:	2005-10-05
Spiller Name:	MARTHA SMITH
Spiller Company:	SMITH RESIDENCE
Spiller Address:	363 MONTAUK AVE
Spiller County:	001
Spiller Contact:	MARTHA SMITH
Spiller Phone:	(718) 647-3130
Spiller Extention:	Not reported
DEC Region:	2

DRAFT

SMITH RESIDENCE (Continued) **S107410536**

DER Facility ID:	299863
Latitude:	40.6694930
Longitude:	-73.8767230
DEC Memo:	9/15/05 - Raphael Ketani. A spill report came in for a tank test failure. This was the first test of the underground tank at this site (PBS #2-604452). I spoke to Mr. Malchick at Pro Test and he said that the test had been done as a routine 5 year test. However, the test failed. He said it was a wet failure, and he believes that it was the petrometer. He's waiting for the owner to call back and tell him what she wants to do. A test failure letter was sent to Martha Smith (RP). 9/21/2005 Sangesland spoke to Mrs. Smith. She said the building is a 2 family house and the tank is 1500 gal buried next to her house. The tank company repaired something? and now the tank test passed. She will send in a copy of all the repair and retest paperwork. 10/5/05 - Raphael Ketani. I received a FAXed copy of a passing tank tightness test report for the property's tank. The tank passed the test. I will close this case.
Remarks:	NO REMARKS.

All TTF:

Facility ID:	0507203
Spill Number:	0507203
Spill Tank Test:	1549301
Site ID:	352562
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	352562
Operable Unit ID:	1110056
Operable Unit:	01
Material ID:	2100073
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DRAFT

299
North
1/4-1/2
0.488 mi.
2578 ft.

ANNA CORP REALITY
78 HIGHLAND PLACE
BROOKLYN, NY 11208

NY LTANKS **S107657273**
NY Spills **N/A**
NY LEAD
NY NYC LAND USE

Relative:
Higher

Actual:
51 ft.

LTANKS:

Name:	ANNA CORP REALITY
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0212208 / 2009-06-02
Facility ID:	0212208
Site ID:	315891
Spill Date:	2003-03-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2003-03-12
CID:	297
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-12
Spill Record Last Update:	2009-07-20
Spiller Name:	ISAAC KATZ
Spiller Company:	ANNA CORP REALITY
Spiller Address:	78 HIGHLAND PLACE
Spiller County:	001
Spiller Contact:	ISAAC KATZ
Spiller Phone:	(516) 924-5840
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	21716
Latitude:	40.6835030
Longitude:	-73.8817840
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 01/04/2006- Isaac Katz on phone asked to have Spill report to be Faxed at 1-718-623 -9436. He will response by end of Jan, 2006. 6/2/09. According to a Clean Solutions Technologies letter dated 12/18/06 (see spill # 0513778), borings were done outside the building and next to the former UST location on 11/6/06 and 11/7/06. Two outside borings were performed to 12' and 36'. No contamination was detected. Boring B-1 was done next to the former UST location to a depth of 15' bg. Results from the soil sample taken on 11/17/06 were virtually entirely non-detect. Residual contamination was found at less than 6' at the other borings. 5/18/07 letter from Clean Solutions Technologies stated that the second treatment solution injection took place on 3/19/07 and soil samples were taken on 4/19/07. The results for soil samples from SB-1 and SB-2 (next to the tank) showed only a few hits for both and the total SVOCs were below TAGM. All of the other soil samples taken from borings throughout the

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

basement were almost entirely non-detect. 7/12/07 letter from Clean Solutions Technologies stated that a soil sample taken on 6/29/07 from boring S-1 next to the former UST location had results that were below TAGM. Based on the data obtained case closed. SCL. JK.

Remarks: THE ONLY POSSIBLE SPILL WAS A COUPLE OF STAINS ON THE WALL NEED NEAR THE FILL TUBE

All TTF:

Facility ID:	0212208
Spill Number:	0212208
Spill Tank Test:	1528077
Site ID:	315891
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	315891
Operable Unit ID:	863217
Operable Unit:	01
Material ID:	565752
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	APRT BUILDING
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0513965 / 2006-03-07
Facility ID:	0513965
Facility Type:	ER
DER Facility ID:	21716
Site ID:	360561
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-07
Investigator:	SMSANGES
Referred To:	Not reported

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Reported to Dept:	2006-03-07
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-03-07
Spill Record Last Update:	2009-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN OIL COMPANY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BAINCA
Latitude:	40.6834870
Longitude:	-73.8817700
DEC Memo:	duplicate spill - Ref #0513778
Remarks:	call bianca with any further questions:

All Materials:

Site ID:	360561
Operable Unit ID:	1117705
Operable Unit:	01
Material ID:	2108216
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	APARTMENT BUILDING
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0513778 / 2007-07-19
Facility ID:	0513778
Facility Type:	ER
DER Facility ID:	21716
Site ID:	360323
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-01
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2006-03-01
CID:	409
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-01
Spill Record Last Update:	2011-02-11
Spiller Name:	ALEX ZEBLOVICH
Spiller Company:	APARTMENT BUILDING
Spiller Address:	78 HIGHLAND PLACE
Spiller Company:	001
Contact Name:	ALEX ZEBLOVICH
Latitude:	40.6834870
Longitude:	-73.8817700
DEC Memo:	Sangesland called eastmond to get a status on the cleanup 03/02/06 Feroze, PBS case of this spill is # 2-509531. CSL is sent to: ISSAC KATZ Anna Court Realty LLC 174 Broadway, #215 Brooklyn, NY 11211 03/07/06 Feroze, received a call from Mrs. Bianca (718-827-0184). She told me that she feel too odor in her apartment. Eastman & Sons is working on the site. Issack Mangoa of Eastmond & Sons (718-378-3000)is requested to use air ventelation of that building to reduce oil smell. Mr.Rene 917-299-7257 of Eastmond & Sons is taking care of that work. 03/08/06 Feroze, I talked to Ms. Bianca. She complained about the odor of fuel. She cann't stay in her room. I talked to Rene. He informed that the concrete floor is impacted by fuel. I talked to Mr.Anthony (718-627-5100) of Empire Fuel Oil Corp. He informed that they will send Eastman & Sons for further cleaning work. 3/8/05 - Raphael Ketani. I arrived at the site at 1:15PM. I was met by Mrs. Bianca (cell (718) 753-1884), the building manager. There was a slight oil odor (160 ppb total VOCs with the PID)in the foyer which was enclosed by steel with glass doors front and back. She took me to the first floor lobby, which had a slight odor (187 ppb). Then she took me to see Mr. Kissoon, the resident of apartment 5A (first floor). Mr. Kissoon's apartment had about 80 to 125 ppb depending on how well the rooms were ventilated. She took me to the basement. There I saw many dark stains all over the floor of the basement and inside the boiler room. There were many fine cracks throughout the basement and the boiler room, and many of them had oil stains along their lengths. The ambient air in the basement had 3,400 ppb. There were wet looking stains where the basement walls met the floor, especially inside the tank room. The PID indicated 5,000 to 9,000 ppb at these stains. The 2,000 gal. #2 fuel tank looked dry on the outside. All of the associated piping looked dry and intact. The tank looked like a recently installed unit as the paint was shiny black. The boiler

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

looked dry and intact, but the ambient air had 3,000 ppb. Mrs. Bianca said that K. C. Transportation had arrived at the building on 3/1/06 and started pumping oil into the fill port and pipe. However, she said, it was an unplugged pipe that was no longer used which opened into the tank room. Mrs. Bianca said that after some time her husband noticed a strong odor coming from the basement and went to investigate. He saw the oil flowing through the cinder block wall of the tank room and over the floor of the basement. He ran outside to stop the truck driver from pumping more oil. She said that the oil was all over the floor of the basement and the floor of the boiler room and the tank room. She said that Eastmond told her that 50 gallons had spilled. However, given the amount of time that elapsed from when pumping started and when Mr. Bianca had the oil delivery stopped, I estimated the spillage at atleast 280 gals. I did not see any drains in the basement, but there is a sump with a pump in the boiler room. She said that it hasn't been running. (It didn't look wet when I saw it.) She said that Eastmond was hired by Empire Oil who had subcontracted K. C. Transportation. Eastmond had knocked out most of the cinder blocks from the tank room vault and piled them up nearby. They had also bagged up some oil soaked debris, but they didn't take away the saturated blocks or the bags. Additionally, there is still alot of oil soaked sediment and cement within the tank room on the floor and along the bottom of the walls of the basement. The floor staining is also obvious, despite a round of power washing. Eastmond left Mrs. Bianca bottles of vinegar and Sweet-Air to reduce the odors. From talking to Mrs. Bianca, it is not clear why Eastmond left the oil soaked debris. The floor needs at least another power washing. I told Mrs. Bianca to immediately get someone to plug up the old fill port and pipe with cement. She said she would, but seemed a bit upset and so she may not remember my telling her this. Mrs. Bianca took me up to her apartment to measure the vapor levels. The second floor landing had 415 ppb. The ambient air in her apartment was 200 to 375 ppb, the first bedroom was 280 ppb with ventilation, and the second bedroom (which was closed) was 900 ppb. I asked her for the building owners phone number. She said Mr. Issac Katz was at (718) 623-9430. I told Mrs. Bianca that I will call Empire State Fuel Corp. ((718)627-5142), K. C. Transportation (Paul Sano at cell (516) 322-3820), and Eastmond ((718)378-3000) and write letters to Issac Katz, the building's owner, to get the vapors resolved. vapor recap: foyer - 160 ppb first floor lobby - 187 ppb Kissoon's apartment - 80 to 125 ppb basement ambient air - 3400 ppb tank room floor sediment - 5000 to

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

9000 ppb boiler room ambient
air - 3000 ppb second floor landing - 415 ppb Mrs. Beanka's apartment - 200 to 375 ppb Mrs.
Beanka's first bedroom - 280 ppb Mrs. Beanka's second bedroom - 900 ppb I spoke to Rene of Eastmond
and he said that he was working for Empire State Fuel and Anthony Reitano hired his company. He
said they arrived on 3/1/06 and spread Speedi-Dri inside the tank room, but to soak up some of the
oil. However, he said, they were not authorized to break down the cinder block wall to get inside
and clean up more oil. So they power washed the floor. Later, he said, the super's own crew knocked
down the cinder blocks. He added that his crew had picked up all of the debris they made and that
the cinder blocks and black bags that are present were generated by the super's crew, though he is
willing to pick them up. Rene said that he wont do more work as there are arguments (between Empire
and the super) as to who is responsible for paying for the cleanup and who will pay for more work.
Later, Mahendra of NYC DEP called ((347) 386-3702) to say that Mrs. Bianca had called him about the
oil spill and the high vapors in the building. He asked what the situation was there and I told
him. He asked whether DEC needed any help and I told him that we are responding to the case and
will get the responsible parties to clean up the spill. I tried to call Issac Katz, the owner, but
could only leave a message. 3/9/06 - Raphael Ketani. I tried calling Mr. Katz again, but could only
leave a message. I will send spill cleanup letters to Mr. Katz and to Empire State Fuel. I called
up Mr. Reitano of Empire State Fuel to ask what was happening with the cleanup of the basement. He
said that nothing was happening right now. I told him about the oil soaked conditions and high
vapors in the basement and how the vapors were affecting people in the floors above. He said he
will talk to Rene of Eastmond and find out what is the status of his company going out there to
continue the cleanup. Also, as of 1:37PM, I still haven't heard from Mr. Katz. 3/10/06 - Raphael
Ketani. Jeff Vought of DEC Spill Response Region 2 called Mrs. Bianca to find out how the vapors
were in the building and if someone was ventilating the building. She said that no one had come to
get rid of the odors. Mr. Vought told me that the vapors weren't being removed and I called Mr.
Katz, Mr. Reitano of Empire, Mr. Alex Zeblovich of K. C. Transportation (the subcontractor) and
Rene of Eastmond. I told each of them that a contractor had to be brought to the building
immediately and had to set up large fans to ventilate the building and get rid of the vapors. Mr.
Katz, Mr. Reitano, and Mr. Zeblovich all told me that it was the other guys' responsibility and not

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

theirs. I told them that they were all responsible and that this must be done by four o'clock today. I added that if they don't call me by four o'clock to tell me the fans are in place and blowing, then I will call the ECOs and have them visit everyone and issue fines and violations to everyone. They seemed to understand. I informed Randy Austin, Chief Spills Engineer of Region 2, of the situation with the heavy vapors in the basement, the residents complaining, and in one case leaving to stay elsewhere, and he agreed with my actions. Later, at about 3:45PM, Mrs. Bianca called to say that the vapors were again very strong in her apartment and that they were making her sick. At 4:05PM, I received a call from Mr. Katz that Eastmond was on their way to set up fans in the basement. I mentioned this to Mr. Austin and he sent Ryan Piper of the Spill Response Unit to investigate. Mr. Piper arrived on site at 5:20PM. He told me that Eastmond was present and that they were setting up 4 large fans. The odors in the basement were moderate and the odors upstairs were light. 3/15/06 - Raphael Ketani. I received a call from Mr. Katz. He asked what has to be done now. I told him the oil stained cracks need to be investigated. If oil is found below the floor, then that part of the floor needs to be dug up, the soil dug up, and everything removed. I added that there are cracks in the upper basement floor, the floor outside the boiler room, and the floor inside the boiler room. Lastly, I told him that the oil soaked bottom of the walls and the oil soaked cinder block needs to be power washed, and removed, respectively. He said he will hire ABC Tank. I told him I will need a report regarding all of this work before I close the case. Rene of Eastmond called. He said he set up 4 large fans in the basement. He said that Anthony of Empire State was contracting him for this. I told him to keep his fans there and to keep the air circulation going. He said he would. He told me that Mr. Katz hasn't contacted him regarding the investigation work. I told him that I had told Mr. Katz what needs to be done to conduct the investigation. Rene said that as soon as the other company arrives, he will remove the fans. I told him that the air circulation has to be maintained because there are children and sick people in the building. I spoke to Mr. Reitano and told him to keep at least one large fan in the basement. He said he will, but HE WANTED TO KNOW WHEN HE CAN TAKE THEM OUT. I told him I would let him know. 3/17/06 - Raphael Ketani. I tried to find out whether the clean up had started by calling Mr. Katz, but I could only leave a message. I called Mrs. Bianca and asked her how things were and whether any work had started. She said the odors were better in her apartment,

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

but the elderly couple on
the first floor still hasn't returned. She said the fans are working,
but no digging or debris
removal has started. She said someone from the NYC DOH came over to
the building. She said this
person issued a notice that the oil soaked debris had to be cleaned up
by April 1. Mr. Katz called
me back. He said he is going to contract with ABC Tank and they will
send him a proposal. He said
they will initially do soil borings to see how bad the contamination
is under the floor. He said
that Eastmond has already done 2 power washes. I told him that all oil
soaked cinder block and the
black bags of debris have to be removed. He said he will have this
done. I told him that the cement
walls at their base are oil soaked and that this needs to be power
washed and sealed with expoxy
paint, as they are bearing walls that can't be removed. He said he
will also have this done.
Lastly, I asked him to keep me informed as to what ABC Tank finds and
as to what they recommend. He
said he would. 3/21/06 - Raphael Ketani. I spoke to Mrs. Bianca. She
said that John Sabatino,
Project Manager from AB Environmental (631) 567-6545, was in the
basement with another person
inspecting the site. She said that he had also been there about a week
ago. Mrs. Bianca said that
no work has taken place, yet, but the fans are still blowing and the
vapors are low enough in her
apartment to live comfortably. Later, Mark Robbins of Hydro Tech
Environmental (631) 462-5866
called to find out what the remediation job would entail. He said he
was contacted by Mr. Katz. I
explained to him the extent of the contamination that I had seen
during my site visit. 3/24/06 -
Raphael Ketani. I spoke to Mr. Sabatino today. He asked what kind of
analysis DEC wanted. I told
him methods 8260 and 8270 with TAGM 4046. He said he would have this
done. He told me the soil PID
results he obtained. He said the following: between wall and tank at
10' bgl: 426 ppm 5' away from
tank: 289 ppm SB-4 at 20 bgl: 60 ppm SB-6 at 16 bgl: 235 ppm SB-10 at
right side of tank: 414 ppm
SB-14 at floor drain: 28 ppm I asked Mr. Sabatino whether his company
would do the soil digging
below the slab and the power washing of the base of the walls. He said
they would. 3/29/06 -
Raphael Ketani. I left a message for Mr. Sabatino to call me back
regarding the status of the
cleanup and investigation at the site. I spoke to Rene of Eastmond. He
said he is taking his fans
out of the basement as his company is no longer the contractor there.
I told him he can do this.
Next, I called up Mr. Sabatino and told him that ventilation must be
maintained in the basement,
that Eastmond has to take there equipment out to bring it to another
job, and so AB Environmental

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

must install fans for ventilation. He said he will do this. 4/3/06 - Raphael Ketani. I spoke to Mr. Sabatino (cell (631) 466-2793). He said that he has the analytical results for SVOCs for the soil samples and that he is expecting the VOC results within a week. I asked him about the fans. He said that his boss is worried about getting paid and so he can't put the fans in - it's a contract issue. Mr. Sabatino told me to call or write Mr. Katz directly to get him to order putting in the fans. I tried calling Mr. Katz, but could only leave a message with his answering service. I tried to call Mrs. Bianca to find out how the odors are in her building, but could only leave a message. Mr. Katz called me back. He said that he had talked to A B Environmental last friday, 3/31, and they agreed to put in the fans. I told him that I had just talked to Mr. Sabatino today and he said that A.B. had not agreed to do so. I told him that I was told it was a contractual issue and they were concerned about getting paid. Mr. Katz said he would talk to A.B. and straighten the situation out. I told him to resolve the situation quickly so that the floors above don't get filled with vapors again. 4/4/06 - Raphael Ketani. Mrs. Bianca called to say that the fans were taken out yesterday and that last night the vapors became more noticeable in the first floor apartments. She said some of the residents complained to her. I told her that if the fans are not installed today, she should call me back tomorrow. She said she will do that if no ventilation is provided. Mr. Sabatino called at 2:20PM and said that his company will install fans in the basement and do power washing tomorrow. 4/10/06 - Raphael Ketani. I spoke to Mr. Sabatino at 11:28AM. He said that the fans were installed thursday, 4/6/06, and that they power washed the tank containment area and the basement floor. He said they found a lot of residue in the tank containment area. I asked him about the soil below the slab. He said he is putting together an investigation proposal right now which will include soil removal below the floor. I asked about the odors. He said they are slight due to the ventilation. 4/17/06 - Raphael Ketani. I tried calling Mrs. Bianca, but could only leave a voice mail message. 4/18/06 - Raphael Ketani. I reviewed the Site Assessment Report produced by ABLE Environmental, submitted by AB Oil Service Ltd. and dated 4/12/06. The report was acceptable to the Department. Significant contamination was found in the soil at sites SB-1, SB-2, SB-6, and SB-10. I will send a letter to this effect with the addition that they have to do several rounds of bioremediation to get the oil under the tank room and under inaccessable areas of the basement. 4/26/06 - Raphael Ketani. Mr. Sabatino called and asked for

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

clarification regarding my 4/18/06 letter. I told him I wanted soil to be dug up only at the boring sites I indicated: SB-1, SB-2, SB-6, and SB-10. He said that he will do bioremediation by injection from outside the building and possibly via a trench dug inside the basement in the exposed soil below the concrete floor. Mr. Sabatino said that it may take a number of injections. I told him to send me a letter describing what he wants to do. He said he would. As an aside, I asked him what the vapors were like in the basement. He said that you can hardly smell them. He said that the last time he measured the vapors, they were at 10 ppm. I told him that is very high and that this is dangerous to elderly people, sick people, and children in the building. He said that his company is not in the business of ventilating buildings. I told him that the basement needs ventilation. He said that he has one fan going all the time and the windows and doors are open. Later, I called up Mrs. Bianca and asked her how the vapors were in her apartment. She said that the vapors are bad in her place, even with the windows open. She said that the elderly couple on the first floor still haven't returned due to the odors. I told her I will make a site visit tomorrow at 10:30AM. She said she will be there to let me into the building. 4/27/06 - Raphael Ketani. I made my site visit and met Rosemary Addison, Public Health Sanitarian with the Office of Environmental Investigations, Div. of Environmental Health, NYC DOH ((212) 442-3372). I did not expect to meet her, but she said that Mr. Kisson of apt. 1A had asked her to come and she was responding to a nusiance odor complaint. I told her that A.B. Environmental was going to start work soon to dig out the soil below the basement and do bioremediation. She said she wasn't going to issue a ticket at this time and will talk to her supervisor on what to do. Next, I met Mrs. Bianca and she showed me the basement, her apartment, Mr. Kisson's apartment and Mr. Kisson's parents' apartment (5A). The vapor levels were: basement ambient air - 300 ppb stained areas where basement walls meet the floor, and the tank room floor - up to 690 ppb boiler room - 350 ppb first floor hall - 29 ppb Mr. Kisson's apartment - 250 ppb Mr. Kisson's parents' apartment - 110 ppb Mrs. Bianca's apartment - 250 ppb in kitchen and 162 ppb in the second bedroom Except for the basement, there were no detectable odors. The apartments have odors primarily because they are over the basement and because the floor boards have many gaps and the pipes for the radiators pass through holes that are too large - creating more gaps. All of the measurements were made with open windows in the apartments, the hallway, and the basement. Two fans

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

were running in the basement. One to draw in air and one to exhaust air. I spoke to Mr. Sabatino of A.B. Environmental and told him that there are still stains along the base of the walls. I asked him to power wash those areas where the floor meets the walls inside and outside the tank room. He said he would do it. I asked him when the digging will start. He said probably next week. He said he will put up plastic sheeting on the ceiling to prevent additional vapors from migrating up into the apartments. 5/25/06 - Raphael Ketani. Received a FAXed letter from Scott N. Fein, attorney for Mr. Katz and Anna Court Realty, stating that DEC should also go after Empire State Fuel to get them to pay for some of the cleanup costs. I brought the letter to the attention of John Urda of Legal Affairs and he said he would call Mr. Fein. I tried calling Mr. Sabatino, but could only leave a message. Mr. Sabatino returned my called at 3:20PM and said he spoke to Mr. Katz last week, but Mr. Katz told him he's not going any further with the cleanup (only soil sampling was done). 6/7/06 - Raphael Ketani. I left a message for Mr. Sabatino at his desk number (631) 567-6545 and at his new cell number (631) 300-6493. Mr. Sabatino returned my call. He said that things are at a standstill. I will contact John Urda of Region 2 Legal Affairs and let him know. 6/13/06 - Raphael Ketani. I sent STIP letters to Issac Katz of Anna Court Realty LLC, Anthony Reitano of Empire State Fuel Corp, and Casey Transportation. 6/26/06 - Raphael Ketani. I received a call from Mary Ellen of Coverage Concepts, the insurance broker for Empire State Fuel and K C. Transportation. She inquired as to what the STIPS mean. I explained the letters to her and stated that they have until the deadline, June 27, to get me the signed stipulations. I told her that if I don't receive them, then I will have the ECOs go out and issue fines. She said she understood. 6/27/06 - Raphael Ketani. I visited the site today after Mary Ellen Fatscher ((631) 331-7700, ext. 134), the Coverage Concepts insurance agent for Empire and K.C., called to say that she had talked to A. B. Environmental and wasn't sure the cleanup work was continuing. I looked inside the basement window from the street and saw that nothing had changed since the investigation took place. There was only a slight odor in the basement. I talked to Ms. Fatscher after returning and told her nothing was taking place. I told her that I still held Mr. Katz responsible, even if he doesn't send in a STIP, and that he will get fines because of this. She said that, in that case, she will have both Empire and K.C. send in their STIPs. Ms. Fatscher called back and asked for a 1 day extension of the STIP submittal deadline. I told her that would be alright, but not more than 1 day. I

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

tried calling Mr. Katz, but
no one picked up the phone and the answering machine would not come on. Ms. Fatscher said that she
thought Mr. Katz was out of town for a vacation or due to a death in the family. 6/28/06 - Raphael
Ketani. I received a call from Bob Spears of Ambrose Environmental (732) 312-2375. He said he
represents the insurance carrrier, AIG. He wanted to know what was needed to remedy the situation
at the site. I told him that only the cleanup is needed. I told him what was involved in order to
collect and remove the oil. I asked him to send me a cleanup plan for review. He said he would. Mr.
Sabatino called because he received a call from Ambrose that they were going to do the cleanup. I
told him that was true and that Ambrose has been hired by the insurance company for Empire and K.C.
I told him I was sorry this was happening, but things are standing still and Mr. Katz is
unresponsive because he feels he has paid enough of the costs. Mr. Sabatino said he wasn't upset
about Ambrose doing the cleanup and he will talk to them again. 6/30/06 - Raphael Ketani. Ms.
Fatscher FAXed me a copy of the building permit that was granted by the NYC Department of Buildings
for replacing the tank, boiler and associated piping. She also FAXed me a copy of the court summons
whereby Anna Court Realty is suing Empire State Fuel. 7/5/06 - Raphael Ketani. Mr. Robert Martin
(212) 989-5337, an investigator for Mr. Krol ((212) 595-8009; the lawyer for Empire State Fuel),
called and asked whether there were any witnesses to the oil spill, other than the super, and how
much oil spilled. I told him that, as far as I knew, the super was the only witness and that it was
impossible to tell how much oil had been released and whether this followed a previous spill.
7/10/06 - Raphael Ketani. I sent out new letters containing STIP forms to be signed to Empire and
K. C. I did this because they both scratched out paragraph 3 on the STIPs they sent in. However,
Mr. Katz never responded. Mr. Sabatino of A. B. Environmental tried to call me last friday
(7/7/06). I called him today. He said that A. B. will do the actual physical removal and treatment
work and Ambrose will be the overseeing company. I told him that sounded fine. He said he expected
work to start either this week or next week. 7/11/06 - Raphael Ketani. Ms. Bianca called to say
that she has a 9 to 5 job now and so she will not be at the apartment building during business
hours. She said her husband is a part-time super. and so he may or may not be in the building
during business hours. She added that possibly she can make special arrangements for me to visit
the basement if I call her enough ahead of time. 7/14/06 - Raphael Ketani. Mr. Sabatino called and

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

said that he sent the cleanup proposal to Ambrose. He said if they approve it soon, then maybe he
can start work next week. 7/25/06 - Raphael Ketani. I spoke to Bob Spears (732) 312-2375 regarding
the cleanup of the oil in the soil. He said that Ambrose has taken the approved A. B. Environmental
proposal and has given it to Clean Solutions to design a soil treatment method. He said that Clean
Solutions has a lot more experience on Long Island in treating oil contaminated soil. He added that
A. B. and Clean Solutions will sit down together and come to an agreement on the method to be used.
8/2/06 - Raphael Ketani. I spoke to Mr. Spears. He said that A.B. Environmental and Clean Solutions
have put togther a remediation plan and that I should receive it either this week or next week. Mr.
Sabatino of A. B. called at 2:25PM. He said that Ambrose has taken the lead as to who is supposed
to do what. However, he believed A. B. will still do the digging and later Clean Solutions will
inject the bio or ORC solution. 8/9/06 - Raphael Ketani. I spoke with Mr. Spears of Ambrose
Environmental. He said that Clean Solutions has finished their proposal and will mail it to DEC
sometime this week. 8/23/06 - Raphael Ketani. I contacted Mr. Spears. He said that Ambrose told him
the plan had been mailed last week. I told Mr. Spears that I will wait until monday, 8/28, to get
it. Tom from Clean Solutions cell (516) 857-9822 called to say that he mailed the proposal 2
fridays ago. I told him I never received it. He said he will mail it out again and I should get it
by 8/28, monday. 8/30/06 - Raphael Ketani. I received the Remedial Action Work Plan from Clean
Solutions Technologies, Inc. 8/31/06 - Raphael Ketani. I finished my review of the RAP. In it,
Clean Solutions states that they will install 18 borings. Most will be in the general basement
area, 2 will be in the boiler room, 1 will be in a small room outside the basement, and the rest
will be in the street on the south side of the building. They will inject Fenton Chemistry - dilute
solutions of hydrogen peroxide and enhanced acetic acid - and ferrous salt ions. The site is over 2
miles to the west of the nearest pumping well of the Jamaica Water Supply district. They will
inject the solution slowly over several rounds of treatment. Monitoring of the concentrations of
the chemicals and the oil in the groundwater and the soil will take place. I will send a letter
approving the location and number of borings, the rounds of application, and the continual
monitoring of the groundwater and the soil. However, I will write that it is the responsibility of
Clean Solutions to insure that the process goes smoothly, that there are no impacts to the people
living in the building, that the DEC expects Clean Solutions to

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

remediate any mishaps with the
treatment process, and that there must be no damage to the soil or groundwater. The letter will be
cc'd to: Issac Katz, Anna Court Realty, LLC, 174 Broadway, #215, Brooklyn, 11211 Anthony Reitano,
Empire Fuel Oil Corp., 1640 McDonald Ave., Brooklyn, 11230 John Sabatino, A. B. Environmental, 1599
Ocean Avenue, Bohemia, NY, 11716 Bob Spears, Ambrose Environmental Management, 5 Cherry Hill Park,
Ste. 100, Danvers, MA, 01923 9/11/06 - Raphael Ketani. The letter addressed to Mr. Katz at 174
Broadway came back undeliverable as addressed. 9/12/06 - Raphael Ketani. Tom Dehaney of Clean
Solutions Technologies, Inc. (cell (516) 857-9822) called me today to explain what happens when the
oil removal solutions are injected and to calm any fears I might have, as he felt were expressed in
my 8/31/06 letter to his company regarding the remediation of the oil. He said he will work with
all of the residents of the building and notify them when work is to start and he stated that he
will communicate with all of them if they have any questions. 9/19/06 - Raphael Ketani. Bob Spears
of Ambrose called and said that everyone had a meeting a while ago. He added that A. B.
Environmental will put together a package describing the work that will take place to seal the
ceiling. He said I will be notified when the well drilling will take place. 9/29/06 - Raphael
Ketani. I received a FAX today of a letter dated 9/28/06 from Thomas Doheny, Jr. of Clean Solutions
Technologies. The letter addressed the concerns DEC had regarding vapors and odors during the soil
treatment process. Mr. Doheny included a diagram for another site that was also the subject of soil
treatment. 10/13/06 - Raphael Ketani. Bob Spears of Ambrose called to say that the wells will be
put in 10/23/06. 11/3/06 - Raphael Ketani. I called up Bob Spears of Ambrose (732) 312-2375 and
asked him what was happening at the site. He said that there was a problem with A.B. Environmental
where they wanted to install only 1 wells, when 4 wells were needed. So Ambrose got rid of A.B. and
hired Trade Winds Environmental (800) 282-8701. Trade Winds told Ambrose they will install the 4
wells. Trade Winds and Ambrose set a date for the installations starting the week of 11/6/06.
12/26/06 - Raphael Ketani. Mr. Spears called regarding the oil spill. He said that the first oil
treatment solution injection will take place on 12/28/06. 1/2/07 - Raphael Ketani. I tried calling
Mr. Spears to see how the injection went, but could only leave a voice mail. I received a report
dated 12/18/06 from Thomas Doheny, Jr. (516) 897-2880 of Clean Solutions Technologies, Inc. (CST)
regarding work at the site. The cover letter stated that the oil didn't migrate outside of the

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

basement. Through the sidewalk, continuous cores were taken to 36 feet below grade. Analytical
results were included in the report for soil samples collected from the outside borings and for
several inside borings. With the exception of well #1 (A B Environmental boring #10), the
contamination is at less than 6 feet below the basement floor. Cracks were investigated and it was
determined that the contamination was at a depth of 2 feet or less below the floor. CST will
install injection points to treat the contamination at these locations. The analytical results for
B-1, B-1A, B-14, B1-12, and B1-36 show that contamination is non-detect or at most well below the
TAGM 4046 RSCO limits. Pictures were included in the report that show the debris and oil staining
has been cleaned up. I found the report to be acceptable. 1/3/07 - Raphael Ketani. Bob Spears of
Ambrose (732) 312-2375 called to give me an update. He said that the solution injection did not
take place as planned due to the alternate side of the street parking. CST couldn't put there
trucks next to the building. So some setup and initial injection will take place tomorrow, 1/4/07.
The bulk of the injection will take place on 1/8/07. The first soil samples will be taken 30 days
later. 1/10/07 - Raphael Ketani. Bob Spears called and said that they are working in step with the
alternate side of the street parking regulations. He said that partial introductions of the
treatment solution were done last thursday (1/4/07) and monday (1/8/07). He added that additional
work will take place this monday (1/15/07) and the following thursday (1/18/07). 2/14/07 - Raphael
Ketani. Bob Spears called to say that I should receive the soil analytical results soon. He said
they look good. He said that a vapor suctioning device was installed on each of the 2 most
contaminated borings. He said that the vapors are exhausted directly to the outside. Two sets of
galleries (shallow wells) were installed for the impacted soil. Three deep wells will be installed
soon. 3/12/07 - Raphael Ketani. Today I received a cover letter dated 2/28/07 with attachments from
Clean Solutions describing the progress they have made in treating the contaminated soil. There was
a site map, soil analytical results from 3 locations (MW-1, MW-5, MW-7) a copy of the flyer that
was sent to the residents notifying them about the work that was to take place, and photos of the
exhaust fan setup and the injection piping. The analyticals show that the 3 sites were essentially
non-detect for the 2/1/07 round of sampling for VOCs and SVOCs. 4/10/07 - Raphael Ketanni. Mr.
Spears called to say that the next round of soil sampling will take place on about 4/16/07. 4/17/07
- Raphael Ketani. Mr. Spears called to say that soil sampling will

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

take place this thursday, 4/19,
at the site. He said that the water table is greater than 30 feet
below the surface. 5/2/07 -
Raphael Ketani. Jean Gerbini (ger-bee-nee) of Whiteman, Ostraman, and
Hanna (518) 487-7725 called
and left a message that her firm is representing Anna Court (78
Highland Pl.) and that she would
like an update on the situation. I spoke with Ms. Gerbini later today
and told her that DEC needed
another round of soil analyticals with good results in order to
consider closing the spill case. I
added that the last round of soil samples took place 4/19/07 and that
we were hoping to get the
results soon. She said that if everything is good, then she would like
an NFA letter. I told her I
would send one if the results are at or below TAGM RSCOs. 5/16/07 -
Raphael Ketani. Mr. Spears
called and said that the soil samples were non-detect. He said that
there was only some odor from
the ground just under the tank, but they will address that in the
final report. He said DEC should
get the final report by week's end. 6/1/07 - Raphael Ketani. Today I
received a FAXed progress
report regarding the soil treatment by Clean Solutions. The report was
sent by Thomas Doheny, Jr.
(516) 897-2880. All of the VOCs were non-detect for the 15 wells.
There were some SVOC hits, but
they were well below TAGM. I spoke to Mr. Doheny regarding the soil
under the tank pad, which still
had oil. He said that this is the only area that still needs treatment
and they are thinking of
drilling horizontal wells. He said that the 3 galleries around the
perimeter of the pad were
helping, but they were not enough. He said that they may also drill an
injection well outside the
building and through the sidewalk. I told him this sounded fine. I
asked about the oil vapors and
odors. He said that 2 wells still have some odors, but the exhaust
fans are keeping the building
odor free. He said that they will pour new concrete and epoxy paint
the floor when everything is
done. 7/19/07 - Raphael Ketani. I received a 7/12/07 letter from Clean
Solutions Technologies, Inc.
The letter listed the analytical results for a soil sample from under
the concrete slab supporting
the tank. This was the last location that needed to be addressed. The
results were all well below
TAGM. Based upon the 7/12/07 letter from Clean Solutions, the FAXed
progress report from Clean
Solutions that was received on 6/1/07 and the other documents in the
case file, I am closing the
spill case. I will send the NFA letter to Ms. Gerbini, Mr. Spears
(Ambrose Environmental
Management, 3400 Belmar Blvd., Wall, NJ, 07719), Mr. Reitano and Mr.
Doheny, Jr. The letter went
out today. 10/22/07 - Raphael Ketani. Mr. Spears called to let me know
that all of the injection

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

wells have been closed up and the floor of the basement has been sealed. 6/1/09 - Raphael Ketani.
Dale Lanier of EFI Global (704) 246-2420 (an environmental consulting company) called to inquire
whether any more environmental work was needed at the site, including borings around the area where
the old UST used to be (see case #0212208). I told him that I would have to research what took
place at the site with my spill. 6/2/09 - Raphael Ketani. I called Mr. Lanier back and told him
that according to a Clean Solutions Technologies letter dated 12/18/06, borings were done outside
the building and next to the former UST location on 11/6/06 and 11/7/06. Two outside borings were
performed to 12' and 36'. No contamination was detected. Boring B-1 was done next to the former UST
location to a depth of 15' bg. Results from the soil sample taken on 11/17/06 were virtually
entirely non-detect. Residual contamination was found at less than 6' at the other borings. A
5/18/07 letter from Clean Solutions Technologies stated that the second treatment solution
injection took place on 3/19/07 and soil samples were taken on 4/19/07. The results for soil
samples from SB-1 and SB-2 (next to the tank) showed only a few hits for both and the total SVOCs
were below TAGM. All of the other soil samples taken from borings throughout the basement were
almost entirely non-detect. A 7/12/07 letter from Clean Solutions Technologies stated that a soil
sample taken on 6/29/07 from boring S-1 next to the former UST location had results that were below
TAGM.

Remarks: EASTMAN TANK CLEANERS HAVE BEEN DISPATCHED TO SCENE. LOCATECD IN THE BASEMENT. WAS A BROKEN FILL PIPE AND WHEN THE DRVIER BEGAN TO FILL TANK IN WENT INTO THE BASEMENT.

All Materials:

Site ID:	360323
Operable Unit ID:	1117494
Operable Unit:	01
Material ID:	2108007
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	12337370

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Building ID:	312659
Registration ID:	331187
Apartment:	C2
Story:	2
Class:	Most Serious
Inspection Date:	04/14/2018
Approved Date:	04/15/2018
Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6066028
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL IN THE FOYER LOCATED AT APT C2, 2nd STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	04/16/2018
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	06/14/2022
Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	12337372
Building ID:	312659
Registration ID:	331187
Apartment:	C2
Story:	2
Class:	Most Serious
Inspection Date:	04/14/2018
Approved Date:	04/15/2018
Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6066028
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st WINDOW FRAME FROM WEST AT NORTH WALL IN THE BATHROOM LOCATED AT APT C2, 2nd STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	04/16/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/02/2018
Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	12337373

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Building ID:	312659
Registration ID:	331187
Apartment:	C2
Story:	2
Class:	Most Serious
Inspection Date:	04/14/2018
Approved Date:	04/15/2018
Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6066028
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st RADIATOR FROM NORTH AT EAST WALL IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT C2, 2nd STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	04/16/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/02/2018
Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	12337374
Building ID:	312659
Registration ID:	331187
Apartment:	C2
Story:	2
Class:	Most Serious
Inspection Date:	04/14/2018
Approved Date:	04/15/2018
Original Certify By Date:	05/19/2018
Original Correct By Date:	05/14/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	6066028
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 2nd WINDOW FRAME FROM WEST AT NORTH WALL IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT C2, 2nd STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	04/16/2018
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	11/02/2018
Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	11714866

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Building ID:	312659
Registration ID:	331187
Apartment:	1C
Story:	3
Class:	Most Serious
Inspection Date:	03/27/2017
Approved Date:	03/31/2017
Original Certify By Date:	05/03/2017
Original Correct By Date:	04/28/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	5717079
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st RADIATOR FROM WEST AT NORTH WALL IN THE 1st ROOM FROM NORTH LOCATED AT APT 1C, 3rd STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	03/31/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	10/05/2022
Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	11221426
Building ID:	312659
Registration ID:	331187
Apartment:	1C
Story:	3
Class:	Most Serious
Inspection Date:	05/02/2016
Approved Date:	05/03/2016
Original Certify By Date:	06/06/2016
Original Correct By Date:	06/01/2016
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5422455
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st RADIATOR FROM WEST AT NORTH WALL, 2nd WINDOW FRAME FROM WEST AT NORTH WALL IN THE 1st ROOM FROM NORTH LOCATED AT APT 1C, 3rd STORY, 1st APARTMENT FROM WEST AT NORTH
NOV Issued Date:	05/04/2016
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	10/05/2022
Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	14462501

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Building ID:	312659
Registration ID:	331187
Apartment:	1B
Story:	2
Class:	Most Serious
Inspection Date:	07/22/2021
Approved Date:	07/26/2021
Original Certify By Date:	08/25/2021
Original Correct By Date:	08/20/2021
New Certify By Date:	09/08/2021
New Correct By Date:	09/03/2021
Certified Date:	Not reported
Order Number:	617
NOV ID:	7420885
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM WEST AT NORTH WALL IN THE FOYER LOCATED AT APT 1B, 2nd STORY, 1st APARTMENT FROM EAST AT SOUTH
NOV Issued Date:	07/27/2021
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	06/26/2022

Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208
Violation ID:	14462503
Building ID:	312659
Registration ID:	331187
Apartment:	4C
Story:	3
Class:	Most Serious
Inspection Date:	07/22/2021
Approved Date:	07/26/2021
Original Certify By Date:	08/25/2021
Original Correct By Date:	08/20/2021
New Certify By Date:	09/08/2021
New Correct By Date:	09/03/2021
Certified Date:	Not reported
Order Number:	617
NOV ID:	7420886
NOV Description:	27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FROM NORTH AT EAST WALL, 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE FOYER LOCATED AT APT 4C, 3rd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	07/27/2021
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	10/05/2022

NYC LAND USE:

Name:	Not reported
Address:	78 HIGHLAND PLACE
City,State,Zip:	BROOKLYN, NY 11208

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Latitude:	40.6834561
Longitude:	-73.8818963
Type Of Ownership Code:	Not reported
Owner Name:	HIGHLAND APARTMENTS LLC
Borough:	BK
Tax Block:	3912
Tax Lot:	58
Community District:	305
Census Tract 2020:	3117202
Census Block 2020:	31172021000
Census Tract 2010:	1172.02
Census Block 2010:	1000
School District:	19
City Council District:	37
Fire Company:	E332
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2E
Zoning District 1:	R4: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	5000
Total Building Floor Area:	14276
Commercial Floor Area:	0
Residential Floor Area:	14276
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	4.0000000
Residential Units:	23
Total Units:	23
Lot Frontage:	50.0000000
Lot Depth:	100.0000000
Building Frontage:	50.0000000
Building Depth:	90.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N

DRAFT

ANNA CORP REALITY (Continued) **S107657273**

Lot Type:	3
Basement Type/Grade:	2
Assessed Land Value:	63450.00000
Assessed Total Value:	753750.00000
Exempt Total Value:	0.00000
Year Built:	1923
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.86000000000
Maximum Allowable Residential Far:	0.75000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039120058.00000000
Condominium Number:	Not reported
Census Tract 2:	117202
X Coordinate:	1017006
Y Coordinate:	188300
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 010
Tax Map #:	31301
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AQ300 **CORNER OF W. 1ST ST** **NY LTANKS** **S104191918**
WNW **AND SCHENCK ST** **N/A**
1/4-1/2 **FULTON, NY**
0.491 mi.
2592 ft. **Site 2 of 2 in cluster AQ**

Relative: **Higher**

Actual: **45 ft.**

LTANKS:

Name:	CORNER OF W. 1ST ST
Address:	AND SCHENCK ST
City,State,Zip:	FULTON, NY
Spill Number/Closed Date:	9906643 / 2000-03-07
Facility ID:	9906643
Site ID:	120569
Spill Date:	1999-09-03
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3804
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1999-09-03
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other

DRAFT

CORNER OF W. 1ST ST (Continued) **S104191918**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-09-03
Spill Record Last Update:	2000-03-07
Spiller Name:	STEVE THOMAS
Spiller Company:	CORNER OF W. 1ST ST
Spiller Address:	AND SCHENCK ST
Spiller County:	001
Spiller Contact:	FORMER NEIL OBRIEN PROP.
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	104677
Latitude:	40.6782950
Longitude:	-73.8899100
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	former lumberyard /hardware shop being demolished and contamined soil found around an old gasoline tank (2000 gal)

All Materials:

Site ID:	120569
Operable Unit ID:	1081022
Operable Unit:	01
Material ID:	299365
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT301 **SPILL NUMBER 8805745** **UST FINDER RELEASE** **1029079694**
NE **3301 ATLANTIC AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.495 mi.
2616 ft. **Site 1 of 4 in cluster AT**

Relative: **Higher**
Actual: **40 ft.**

UST FINDER RELEASE:

Object ID:	259443
Facility ID:	NY95065
Lust ID:	NY8805745
Name:	SPILL NUMBER 8805745
Address:	3301 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1988/10/05 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	10312
Domestic Wells within 1500ft:	49
Land Use:	Developed, Medium Intensity
Within SPA:	No

DRAFT

SPILL NUMBER 8805745 (Continued) **1029079694**

SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.87526
Y Coord:	40.6807700000001
Latitude:	40.68077
Longitude:	-73.8752599999999

AT302 **BLUE RIDGE FARMS INC** **UST FINDER** **1028573707**
NE **3301 ATLANTIC AVENUE** **UST FINDER RELEASE** **N/A**
1/4-1/2 **BROOKLYN, NY 11208**
0.495 mi.
2616 ft. **Site 2 of 4 in cluster AT**

Relative:
Higher

Actual:
40 ft.

UST FINDER:

Object ID:	296067
Facility ID:	NY2685
Name:	BLUE RIDGE FARMS INC
Address:	3301 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	5
TOS USTs:	0
Population 1500ft:	10452
Private Wells 1500ft:	45
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State

DRAFT

BLUE RIDGE FARMS INC (Continued) **1028573707**

X Coord: -73.874006
Y Coord: 40.6803830000001
Latitude: 40.680383
Longitude: -73.874006

UST FINDER:
Object ID: 1225265
Facility ID: NY2685
Tank ID: NY2501
Tank Status: Closed
Installation Date: 1982/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1225266
Facility ID: NY2685
Tank ID: NY2502
Tank Status: Closed
Installation Date: 1982/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1225267
Facility ID: NY2685
Tank ID: NY2718
Tank Status: Closed
Installation Date: 1981/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 10000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1225268
Facility ID: NY2685
Tank ID: NY2719
Tank Status: Closed
Installation Date: 1982/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1225269
Facility ID: NY2685
Tank ID: NY2928
Tank Status: Closed
Installation Date: 1982/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

DRAFT

BLUE RIDGE FARMS INC (Continued) **1028573707**

UST FINDER RELEASE:

Object ID:	259444
Facility ID:	NY327667
Lust ID:	NY101620
Name:	BLUE RIDGE FARMS
Address:	3301 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2001/05/11 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	10312
Domestic Wells within 1500ft:	49
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.87526
Y Coord:	40.6807700000001
Latitude:	40.68077
Longitude:	-73.8752599999999

AT303 **BLUE RIDGE FARMS** **NY LTANKS** **1002988545**
NE **3301 ATLANTIC AVENUE** **NY CBS** **N/A**
1/4-1/2 **BROOKLYN, NY 11208** **NY AST**
0.495 mi. **NY Spills**
2616 ft. **Site 3 of 4 in cluster AT**

Relative:
Higher

Actual:
40 ft.

LTANKS:

Name:	SPILL NUMBER 8805745
Address:	3301 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8805745 / 2003-03-04
Facility ID:	8805745
Site ID:	235578
Spill Date:	1988-10-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	2401

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	1988-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-10-06
Spill Record Last Update:	2004-06-14
Spiller Name:	Not reported
Spiller Company:	CHEVRON/BLUE RIDGE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	95065
Latitude:	40.6807732
Longitude:	-73.8752623
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 10/10/95: This Is Additional Information About Material Spilled From The Translation Of The Old Spill File: 2 Tks(Diesel & Gas). Refer to 0101620 for current status on site remediation. Rommel. Not reported
Remarks:	2 4K TKS FAILED INIT SYS PETRO-TITE. L R =-0.160 GPH, DIESEL ; L R = -0.108 GPH, PREM UNL GAS.

All TTF:

Facility ID:	8805745
Spill Number:	8805745
Spill Tank Test:	1534722
Site ID:	235578
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	235578
Operable Unit ID:	920906
Operable Unit:	01
Material ID:	457653
Material Code:	0008

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported
Site ID:	235578
Operable Unit ID:	920906
Operable Unit:	01
Material ID:	457654
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	BLUE RIDGE FARMS
Address:	3301 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0101620 / 2007-09-19
Facility ID:	0101620
Site ID:	290367
Spill Date:	2001-05-11
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2001-05-11
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2001-05-11
Spill Record Last Update:	2011-09-27
Spiller Name:	OWNER
Spiller Company:	BLUE RIDGE FARMS
Spiller Address:	3301 ATLANTIC AVE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	327667
Latitude:	40.6807732

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Longitude: -73.8752623

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 12/9/03 TJD Spill reassigned Demeo >>> Rommel. 06/14/04 Received call from Tony Ying of CRA, 716-297-2160 who represents new owner. They would like to know what needs to be done to investigate/remediate the spill. Rommel. No file exists. 2:30pm Left message for Mr. Ying that the soil and groundwater around all the tanks (gas, diesel and fuel oil) must be investigated due to the three spill numbers at this site. 9412423 and 8805745. Offered to review a work plan. Rommel 07/11/05 Received a Phase II report, dated 2001, for the site from Brian Kramer of CRA. The report recommends additional sampling. Discussed the current status with Brain Kramer. He advised that the owner or possibly a buyer of the propoerty is eager to complete the additional testing and sign off on a remediation plan. Bishop 7/25/2005 Sangesland spoke with Bank Officer from a potential purchasers bank who asked about the project and what work needs to be done. Sangesland noted that the Spill Manager was still listed as Rommel, so Sangesland told the owner to get in touch with Koon Tang (Head of Region 2 Gasoline Remediation Group). (Unknown who wrote the notes above listed as 7/11/05)SS 8/1/05 AKRF Environmental Consultants have submitted a Subsurface Investigation Report Phase II dated May 2001 including an electromagnetic survey and collection an analysis of soil, groundwater, and process water samples. The report has been reviewed. Bishop Previously assigned to Heather Bishop in CO. 2/26/07 - Austin - Received report from Conestoga-Rovers Associates, dated 2/21/07 for this location - Spill reassigned to Ketani for review of submission and contiuation of work. - end 2/27/06 - Raphael Ketani. There are 2 PBS cases for the site: #2-336726 and #2-095923. #2-336726= four 4,000 gal. tanks, closed and removed 6/1/88 #2-095923= 5 tanks, four 4,000 gal. and one 10,000 gal., all closed and removed 12/1/89 one 10,000 gal. #2 fuel oil tank, above ground, temporarily out of service one 300 gal. lube oil tank, above ground, in service I found the following documents: 5/17/01: AKRF phase II report with FAXes of tables of analytical results, and boring logs dated 5/20/05 6/14/04: several sets of Spill Reports with notes attached 2/21/07: status report from Conestoga-Rovers & Associates 2/26/07: Spill Report with notes 3/1/07 - Raphael Ketani. I finished my review of the case file. From the AKRF 5/17/01 report, parcel D contained the main building. Two tanks failed their tank tests, according to spill case #8805745. Borings B-12 to B-15 were done in the receiving dock area at the west side of the building. Borings B-4, and B-9 to B-11 were done in the shipping dock area on the east side of the building. B-10 had the worst contamination with very high TAGM exceedences for many VOCs. B-9 and B-11 had several VOC hits, but they were below TAGM. Water samples were also taken. B-9 had 3 hits with 1 VOC above TAGM and B-12 had 2 hits with none above TAGM. B-4, and B-12 to B-15 had no groundwater VOC hits. In the Consetoga-Rovers 2/21/07 report, SB-2 was installed in the approximate vicinity of B-10 of AKRF's report. All of the chemical species for SB-2 were non-detect. The groundwater sample taken from MW-1 after the chemical treatment in 8/06 was almost completely non-detect. There were exceedences for isopropylbenzene and trichloroethylene. MW-1 is situated upgradient of former B-10 and the other sites that had contamination. However, the MDL was set at 10ppb. SB-5 (to the right of former B-10) was sampled in 8/05 and had many VOC exceedences. Boring BH-10 had the highest contamination, according to the report, but there wasn't any excavation. I tried to

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

reach Brian Kramer of Conestoga-Rovers & Assocs. (716) 206-0202, ext 210, but could only leave a voice mail. The owners of the site at block/lot 04143/0001 are 3301 Atlantic Avenue, 1 Plaza Road, Greenvale, NY 11548-1027. 3/5/07 - Raphael Ketani. Brian Kramer and Kevin Lynch of CRA returned my call. They said that some typographical errors were made on Table 1 and the site map. They said that the North arrow should be turned 90 degrees to point toward the facility. The BH series of boirngs in Table 1 should be listed only as B. Mr. Kramer said that IP-3 is the nearest boring to B-10. They said that the potassium permanganate was injected into the smear zone/upper zone in order to have the chemical seep down into the affected soil, rather than just going laterally and missing the zone. The trichloroethylene detected in the groundwater is present everywhere under the site and appears to be originating from upgradient. In the end, I asked them for one more soil sample from a boring just south of B-10 and another groundwater sample from MW-1. They agreed to do this. 3/7/07 - Raphael Ketani. I received the following e-mail from Mr. Lynch: Per our conversation on Monday March 5, 2007, I am attaching a revised Figure 1 and revised Table 1 for inclusion in the Letter Report dated February 21, 2007 for the Chloe Foods Site. Figure 1 has been revised to show the correct orientation of the North arrow. Table 1 was revised to add the depths at which the soil samples were collected and to correct the designations of B-9, B-10, and B-11(incorrectly shown as BH-9, BH-10, and BH-11). We are also aware the spill number was incorrect on the letter, and should be 1010620, not 101060. To help clarify the TCE in groundwater issue, attached is a figure showing the upgradient locations at which AKRF collected soil and groundwater samples at the site, and the analytical summary tables for the compounds detected at those locations. These results indicate that trichloroethylene was detected in the groundwater upgradient of the production facility (at B-1, B-2 and B-12, and the process water extraction wells), and that this compound is not present in any of the soil samples from the site. Therefore, TCE and related chlorinated compounds are not considered to be site related, but rather present in the water regionally. We understand that the NYSDEC is requesting additional sample collection to verify that treatment was effective at the site. This sampling is to consist of collection of one additional groundwater sample at the MW-1 monitoring well, and collection of one additional soil sample adjacent to historical locations B-10 and SB-5. The soil sample will be collected from the interval(s) exhibiting the highest PID reading, strongest odor, or most staining. In absense of these items, the sample will be collected from just above the water table in the smear zone. Both the groundwater and the soil sample are to be analyzed for volatile organic compounds. CRA will contract with a driller to install the soil boring and collect the soil sample. The groundwater sample will be collected at the same time. The NYSDEC will be notified of the date of the work. Should you have any questions, please contact Mr. Brian Kramer at (716) 583-5730 or Mr. Kevin Lynch at the numbers below. Mr. Kramer and Mr. Lynch are both in the same office so mailing and office phone numbers are the same. Mr. Kramer is at extension 210. Kevin Lynch Conestoga Rovers and Associates, Inc. 2371 George Urban Boulevard Depew, New York 14043 6/22/07 - Raphael Ketani. I made contact with Mr. Kramer. He said that things were delayed twice as the client was not on board with the idea of doing another boring and more sampling. However, the boring was done and a soil sample and a groundwater sample were taken. He said that 5

BLUE RIDGE FARMS (Continued) **1002988545**

or 6 injection points for soil treatment were also installed. Mr. Kramer said that the results for the groundwater sample are all in the single digits, except for MTBE, which is at 11 ppb. He said that the results for the soil sample haven't come back yet, but if they are above TAGM, then they are ready to do soil treatment. He said they will send me the results and all of the additional information when it is available. 9/17/07 - Raphael Ketani. I received the 9/7/07 letter report from Kevin Lynch of Conestoga-Rovers. It stated that borings IP-17 to IP-21 were installed around boring B-10. Only the soil sample from IP-17 at the 15' to 17' interval had high PID readings. Total volatiles were detected at a reading of 668 ppm. This sample was sent off for analysis. The soil analyses came back with very low hits for 4 VOCs and non-detects for 4 other VOCs. A groundwater sample was taken from MW-1. The results showed that the 4 VOC hits were at or below the TAGM limits, including a 5J hit for TCE. 9/19/07 - Raphael Ketani. I contacted Brian Kramer of Conestoga-Rovers regarding the process water injection that had been depicted on some old diagrams in the file. He said that this water was used for cooling only, not for any type of commercial process. I reviewed the old analytical results packages and found listings for PERC (tetrachloroethylene) among the VOCs. However, PERC was always non-detect. Also, PERC and TCE were never detected in the soil samples. Based upon the analytical results of the letter reports for 2/21/07 and 9/7/07, and the existence of the site in an industrial area where TCE is probably ubiquitous in the groundwater, I am closing the spill case. 9/27/11 - Raphael Ketani. Jim Kelly of Property Solutions (732) 417-0999 ext 222 called requesting information about several issues regarding the property and the spills that took place on the site (also spills #9412423 and #8805745). I spoke to him. He said that a Phase I was being done and, in the process, they discovered information about the spills and the tanks. The Phase I is being done for a transaction. The property is in receivership. I told Mr. Kelly that there are two reports in the e-docs and that the FOIL people will copy them onto a disk and send it to him. He asked what should be done with the 19 injection wells. I told him that it would be up to the owner whether he wants to keep them open. However, if they are going to be abandoned, then they must be abandoned in accordance with DER-10. He said that he will follow the instructions in DER-10. With that, the conversation ended.

Remarks: CALLER DOING SITE WORK FOUND CONTAMINATED SOIL.

All Materials:

Site ID:	290367
Operable Unit ID:	838495
Operable Unit:	01
Material ID:	537323
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CBS:

BLUE RIDGE FARMS (Continued) **1002988545**

Name: BLUE RIDGE FARMS
Address: 3301 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
CBS Number: 2-000338
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 595108.82773
UTMY: 4504031.06423

AST:
Name: BLUE RIDGE FARMS
Address: 3301 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11208
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-000338
Program Type: CBS
UTM X: 595108.82773
UTM Y: 4504031.06423
Expiration Date: N/A
Site Type: Manufacturing (Other than Chemical)/Processing

Tank Info:

Tank Number: 001
Tank Id: 192577
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 06/01/1990
Capacity Gallons: 3644
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 002
Tank Id: 192578
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 12/01/1994
Capacity Gallons: 3644
Tightness Test Method: NN
Date Test: Not reported

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 1
Tank Id: 194046
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Other
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 08/01/2000
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/01/2000
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 2
Tank Id: 194045
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Other
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1991
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/01/2000
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 3
Tank Id: 194044
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Other
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 08/01/2000
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Next Test Date:	Not reported
Date Tank Closed:	02/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

SPILLS:

Name:	BLUE RIDGE FARMS
Address:	3301 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9412423 / 1994-12-16
Facility ID:	9412423
Facility Type:	ER
DER Facility ID:	95065
Site ID:	108146
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1994-12-16
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1994-12-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1994-12-16
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-16
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BLUE RIDGE FARMS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6807732
Longitude:	-73.8752623
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT 10/10/95: This is additional information about material spilled from the translation of the old spill file: FUEL OIL.
Remarks:	ON SITE TANK GAUGE FAILED, ON CONCRETE YARD-CLEANED WITH SPEEDI DRY PADS, OUT OF VENT.

All Materials:

Site ID:	108146
Operable Unit ID:	1006065
Operable Unit:	01
Material ID:	374734
Material Code:	0001A
Material Name:	#2 fuel oil

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	STREET
Address:	3301 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0205903 / 2002-09-09
Facility ID:	0205903
Facility Type:	ER
DER Facility ID:	95065
Site ID:	290368
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-09-06
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2002-09-06
CID:	398
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-06
Spill Record Last Update:	2002-09-09
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
Latitude:	40.6807732
Longitude:	-73.8752623
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE
Remarks:	diked and contained but still leaking. no call back needed. saddle tank puncted by grade.

All Materials:

Site ID:	290368
Operable Unit ID:	858411
Operable Unit:	01
Material ID:	516517
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00

DRAFT

BLUE RIDGE FARMS (Continued) **1002988545**

Units: G
Recovered: .00
Oxygenate: Not reported

AT304 **CHLOE FOODS** **SEMS** **1015731698**
NE **3301 ATLANTIC AVENUE** **NYN000206581**
1/4-1/2 **BROOKLYN, NY 11208**
0.495 mi.
2616 ft. **Site 4 of 4 in cluster AT**

Relative: SEMS:
Higher
Actual: Site ID: 0206581
40 ft. EPA ID: NYN000206581
Name: CHLOE FOODS
Address: 3301 ATLANTIC AVENUE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11208
Cong District: 10
FIPS Code: 36047
Latitude: +40.68102
Longitude: -073.87415
FF: N
NPL: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

AR305 **207 HENDRIX ST./ST. MALAC** **NY LTANKS** **S100144840**
West **207 HENDRIX ST.** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.497 mi.
2626 ft. **Site 3 of 3 in cluster AR**

Relative: LTANKS:
Higher
Actual: Name: 207 HENDRIX ST./ST. MALAC
45 ft. Address: 207 HENDRIX ST.
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8705786 / 1993-02-25
Facility ID: 8705786
Site ID: 148832
Spill Date: 1987-10-08
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: 1993-02-25
SWIS: 2401
Investigator: BATTISTA
Referred To: Not reported
Reported to Dept: 1987-10-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0

DRAFT

207 HENDRIX ST./ST. MALAC (Continued) **S100144840**

Date Entered In Computer:	1987-10-28
Spill Record Last Update:	1994-02-15
Spiller Name:	Not reported
Spiller Company:	ST. MALACHYS CHURCH
Spiller Address:	207 HENDRIX ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	126642
Latitude:	40.6772530
Longitude:	-73.8904480
DEC Memo:	Not reported
Remarks:	5K TANK SYSTEM FAILURE, LEAK RATE WAS -.177 G/HR. WILL EXCAVATE, ISOLATE, REPAIR, AND RETEST. CONTACT: FR. KING (718) 647-5900.

All TTF:

Facility ID:	8705786
Spill Number:	8705786
Spill Tank Test:	1531871
Site ID:	148832
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	148832
Operable Unit ID:	911820
Operable Unit:	01
Material ID:	468360
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

DRAFT

AU306 **GULF SERVICE STATION** **UST FINDER RELEASE** **1029061308**
ESE **1249 SUTTER AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.499 mi.
2636 ft. **Site 1 of 3 in cluster AU**

Relative: **Lower**
Actual: **19 ft.**

UST FINDER RELEASE:

Object ID:	259500
Facility ID:	NY159083
Lust ID:	NY9901190
Name:	GULF SERVICE STATION
Address:	1249 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1999/04/30 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	14398
Domestic Wells within 1500ft:	10
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	020302020103
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.87325
Y Coord:	40.67265
Latitude:	40.6726499999999
Longitude:	-73.8732499999999

AU307 **NY LTANKS** **S103941028**
ESE **1249 SUTTER AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11208** **NY NYC LAND USE**
0.499 mi.
2636 ft. **Site 2 of 3 in cluster AU**

Relative: **Lower**
Actual: **19 ft.**

LTANKS:

Name:	LOX SERVICE STATION
Address:	1249 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0300827 / 2004-06-04
Facility ID:	0300827
Site ID:	107549
Spill Date:	2003-04-23
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility

DRAFT

(Continued) **S103941028**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	2003-04-23
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-04-23
Spill Record Last Update:	2004-06-04
Spiller Name:	MARTIN SIEZEL
Spiller Company:	LOX SERVICE STATION
Spiller Address:	1249 SUTTER AVE
Spiller County:	001
Spiller Contact:	JEFF BEAUDETTE
Spiller Phone:	(800) 666-2605
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159083
Latitude:	40.6726459
Longitude:	-73.8732455
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/24/03 TJD DDO sent TTF letter. 03/29/04 Transferred from DeMeo to Rommel Spill closed and referenced to 0304092 Rommel
Remarks:	TANK FAILED THE TEST.

All TTF:

Facility ID:	0300827
Spill Number:	0300827
Spill Tank Test:	1528288
Site ID:	107549
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	107549
Operable Unit ID:	868958
Operable Unit:	01
Material ID:	508898
Material Code:	0009

DRAFT

(Continued) **S103941028**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GULF SERVICE STATION
Address:	1249 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9901190 / 2003-08-16
Facility ID:	9901190
Site ID:	190732
Spill Date:	1999-04-30
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1999-04-30
CID:	382
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-04-30
Spill Record Last Update:	2004-02-06
Spiller Name:	MARTIN SIEGEL
Spiller Company:	CUMBERLAND FARMS
Spiller Address:	777 DEDHAM ST
Spiller County:	001
Spiller Contact:	ZEKRIA MANELY
Spiller Phone:	(718) 827-8622
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	159083
Latitude:	40.6726459
Longitude:	-73.8732455
DEC Memo:	Not reported
Remarks:	FD CALLED OUT TO INVESTIGATE AN ODOR OF GAS. 10 X 15 FT AREA CLEAN ED WITH SPEEDY DRY. STILL POSSIBLY A LEAK FROM AN UNDERGROUND TANK AND POSSIBLY ENTERING A SEWER. STILL UNKNOWN AT THIS TIME.

All Materials:

Site ID:	190732
Operable Unit ID:	1075958
Operable Unit:	01
Material ID:	304739
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported

DRAFT

(Continued) **S103941028**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GAS STATION
Address:	1249 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0304092 / 2013-07-16
Facility ID:	0304092
Facility Type:	ER
DER Facility ID:	159083
Site ID:	107550
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-07-18
Investigator:	aaobliga
Referred To:	Not reported
Reported to Dept:	2003-07-18
CID:	257
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-18
Spill Record Last Update:	2013-07-16
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PATTY BADDING
Latitude:	40.6726459
Longitude:	-73.8732455
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Contaminated Soil Letter sent to consultant. 1/28/2003-Vought-Spoke to David Schentov (landlord not owner-718-376-5400). Owner contact info is Sutter Avenue LLC 1946 Coney Island Avenue, Brooklyn NY 11223. 2/4/04-Vought-Received message from Patricia Badding (908-604-2291). Vought returned call and left message to call DEC. See spill #0304092, tank test failure. Rommel 10/18/04-Vought-Reviewed Underground Storage Tank Closure Report (Environmental Management)dated May 14, 2004. Site currently occupied by a automobile repair facility, car wash and detail shop. Two new 8000-gallon

DRAFT

(Continued) **S103941028**

gasoline USTs were installed subsequent to tank removal . 1/25/06 - Obligado - Reviewed UST closure report. 10 550 gallon USTs, 1 4000 gallon UST removed. tanks and dispenser islands excavated, totatl of 375 tons of contaminated soil removed. 15 soil samples collected and 1 gw sample. Ground water at 16 ft bgs. Soil had impacts at 2 locations: S14 sidewall north of 550s had 1500 benzene, 6600 toluene, 9400 ethylbenzene, 62000 xylenese, 4000 MTBE and at S10 at base with 80 ppb benzene. S15 had metal hits of 11.8 chromium and 0.61 Mercury. Ground water sample collected east of S14 showed ND. Requests NFA based on clean ground water sample. GW sample was northeast of tankfield, according to DER10, gw sample should be in or downgradient (south) of tankfield. Sent letter requiring downgradient sample. 2/3/06 - Obligado - Received returned letter - no such number, unable to forward. 2/23/06 - Obligado - Spoke with Patricia Badding, (Environmental Management) 908-604-2291. Told her the Department is requiring sample downgradient of the tank field - south. Said she will inform client. 10/25/06 - Obligado - Sent another letter to different address. Due date for 12/29/06. 1/3/07 - Obligado - Left message for Zekria Manely (718) 827-8622. Told to call DEC. Zekria Manely called me back. I told him they needed to do additional investigation due to contaminated soil that was found. I told him I would send him a letter and he would have 90 days to complete the investigation. 1/8/07 - Obligado - Delivery confirmation. Due date is April 8, 2007. 4/13/07 - Obligado - Investigation report is overdue. Called Zekria Manely, left message to call DEC. 4/13/07 - Obligado - Received phone call from Zekria Manely. He has not performed any work, said he was trying to put the money together. He said he would contact his contractor and he would call me back on Monday to tell me when I could receive the report. 4/16/07 - Obligado - Phone call from Zekria Manely. He was not able to get in touch with his environmental contractor yet. He said he will try again to get in touch this week and call me back in the next few days. 11/16/07 - Obligado - Spoke with Patricia Badding. I forwarded the letter requiring the subsurface investigation. 2/15/08 - Obligado - Email from Patty. The investigation is scheduled for 2/18/08. She sent a map with proposed boring locations. 5 borings are proposed in the vicinity of the former tanks and dispensers. I sent email saying the locations were fine and advising markout of subsurface utilites/structures prior to drilling. 9/15/08 - Obligado - Reviewed Subsurface Investigation Report, dated 7/15/08. 6 geoprobe soil borings. Soil and gw samples collected, and contamination in excess of TOGS groundwater standards and Soil Cleanup

DRAFT

(Continued) **S103941028**

Objectives was found in
several borings. Will send Stipulation Agreement. 9/29/08 - Obligado -
Sent STIPULATION agreement
to Euclid Enterprises. Deadline of 30 days for signature 10/2/08 -
Obligado - Delivery confirmation
on 9/30/08. - Due date is 10/30/08. 12/12/08 - Obligado - Called Mr.
Zekria Manely, regarding the
Stipulation Agreement. He said he did not recall the letter. He said
he will find the letter and
speak to Ms. Badding (consultant) and call me back by next Friday -
12/19/09. 12/22/08 - Obligado -
Spoke with Mr. Zekria Manely. He said he did not receive the letter.
It may have been received by
one of the businesses operating at the 1249 address. I told him I
would resend a Stipulation
Agreement. I would also fax to him as well. 12/29/08 - Obligado -
Resent letter and stipulation to
Mr. Manely. Faxed letter to (718) 235 - 2178. 12/31/08 - Obligado -
Delivery Confirmation. Signed
STIPULATION due 2/2/09 2/5/09 - Obligado - Called Mr. Manely regarding
the Stipulation. He said he
will sign and fax the Stipulation Agreement immediately. I told him he
needs to send the original
as well and he said he would. 2/13/09 - Obligado - Called Mr. Manely.
I told him I have not
received the Stipulation yet. He said he faxed it. I told him I did
not receive it. I gave him my
fax number again and told him to mail the original by 2/20/09. He said
he will fax the copy
tomorrow and he call to confirm on Tuesday that I received it. 3/3/09
- Obligado - Received the
signed Stipulation. 3/3/09 - Obligado - STIPULATION executed by Mattei
3/5/09 - Obligado - Fazed
the dually signed agreement to Mr. Manely. 4/7/09 - Obligado -
Workplan received. 5/18/09 -
Obligado - Reviewed workplan proposing 6 monitoring wells. Called
Patricia to discuss boring
locations. She wills submit a revised workplan. 5/20/09 - Obligado -
Received revised workplan.
Sent approval letter to Mr. Manely. CC to Patricia Badding. 11/23/09 -
Obligado- Called Patricia
Badding about the overdue report. She said she could get it to me next
week. 1/15/10 - Obligado -
Reviewed Remedial Investigation Report submitted by EMS. 6 additional
wells installed. 2 of the 6
wells had elevated VOCs in excess of Standards. Report recommends
additional delineation. I sent a
letter to Mr. Manely requiring submission of work plan for
installation of 4 additional wells to
complete delineation. CC to EMS Badding via email. 1/25/10 - Obligado
- Received delivery
confirmation receipt. Letter was received by Mr. Manely on 1/22/10.
4/21/10 - Obligado - I reviewed
the IWP for addtiional 4 wells. 3 wells were proposed across Sutter
Avenue. 1 upgradient well also
proposed. I sent approval for the work plan to Mr. Manely, with a cc
to Patty Badding. 4/6/11 -

DRAFT

(Continued) **S103941028**

Obligado - I emailed Patricia to inquire about the progres at this site. 4/7/11 - Obligado - According to Patricia, the report is completed, except for maps. She should have the report to me early next week. 3/26/13 - Obligado - I reviewed the investigation report. 4 wells were intalled, 1 upgradient, 3 downgradient. One downgradient well MW8 had exceedences of 70 ug/L benzene and 120 ug/L total VOCs. No soil impacts were detected off-site. MW2 had 2046 ug/L BTEX and MW6 had 896 ug/L BTEX. 2011 ground water results were significantly reduced from initial groundwater sampling in 2009, with 5200 ug/L BTEX in MW2 and 3800 ug/L in MW6. I sent a letter to Mr. Manely approving the investigation and requiring a quarterly groundwater monitroing program to monitor gw trends and to ensure the plume is not migrating further. The next QMR is due within 90 days. 7/16/13 - Obligado - I received the groundwater monitoring report. Total BTEX in MW2 was 570 ug/L, which is a dramatic decrease from the initial 5,200 ug/L in 2009. That is a 90% reduction. MW6 was 408 ug/L BTEX, which is down from 3200 ug/L in 2009. Also a 90% reduction. BTEX concentrations in MW8 offiste reduced to 2.6 ug/L. This indicates the plume is shrinking. Following UST source removal the plume appears to be naturally attenuating and rather quickly. I anticipate this plume to continue to attenuate therefore additional remediation is not warranted. I notified Patricia Badding that additional monitoring is not required. I sent a Spill Closure letter to Mr. Manely.

Remarks: caller uncovered tanks and found contaminted soil

All Materials:

Site ID:	107550
Operable Unit ID:	872354
Operable Unit:	01
Material ID:	504957
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	1249 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6730123
Longitude:	-73.8717127
Type Of Ownership Code:	Not reported
Owner Name:	1249 SUTTER LLC

DRAFT

(Continued) **S103941028**

Borough:	BK
Tax Block:	4249
Tax Lot:	55
Community District:	305
Census Tract 2020:	3119600
Census Block 2020:	31196004002
Census Tract 2010:	1196
Census Block 2010:	4002
School District:	19
City Council District:	42
Fire Company:	L107
Police Precinct:	75
Health Center District:	33
Health Area:	6410
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	3D
Zoning District 1:	R5: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C1-2
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G3: Garages And Gasoline Stations - Gas Station With Retail Store
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	11246
Total Building Floor Area:	2400
Commercial Floor Area:	2400
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	2400
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	158.6700000
Lot Depth:	74.4000000
Building Frontage:	80.0000000
Building Depth:	30.0000000
Extension Code:	G
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	188100.00000
Assessed Total Value:	695700.00000

DRAFT

(Continued) **S103941028**

Exempt Total Value:	0.00000
Year Built:	1962
Year Altered 1:	2003
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.21000000000
Maximum Allowable Residential Far:	1.25000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3042490055.00000000
Condominium Number:	Not reported
Census Tract 2:	1196
X Coordinate:	1019836
Y Coordinate:	184499
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 044
Tax Map #:	31308
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AU308 **LOX SERVICE STATION** **UST FINDER RELEASE** **1029061309**
ESE **1249 SUTTER AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.499 mi.
2636 ft. **Site 3 of 3 in cluster AU**

Relative: **Lower**
Actual: **19 ft.**

UST FINDER RELEASE:

Object ID:	259501
Facility ID:	NY159083
Lust ID:	NY300827
Name:	LOX SERVICE STATION
Address:	1249 SUTTER AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2003/04/23 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	14398
Domestic Wells within 1500ft:	10
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY7003493_77021
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well

DRAFT

LOX SERVICE STATION (Continued) **1029061309**

WHPA HUC12:	020302020103
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.87325
Y Coord:	40.67265
Latitude:	40.6726499999999
Longitude:	-73.8732499999999

AV309 **LOT 55,TAXBLOCK 3933** **NY VCP** **S118704409**
WNW **2795 FULTON STREET** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.569 mi. **NY NYC OER**
3006 ft. **Site 1 of 2 in cluster AV**

Relative:
Higher

Actual:
49 ft.

VCP NYC:

Project ID:	20TMP0836K,20EH-N258K
Name:	2795 FULTON STREET
Address:	2795 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3039330055
OER Program:	VCP (Withdrawn), E/RD (Review)
Phase:	Site Management
Latitude:	40.678086
Longitude:	-73.89137
Postcode:	5
Community Board:	37
Council District:	1146
Census Tract:	3000000
BIN:	3039330055
NTA:	Cypress Hills-City Line

E DESIGNATION:

Name:	LOT 55,TAXBLOCK 3933
Address:	2795 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	55
Tax Block:	3933
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

DRAFT

LOT 55,TAXBLOCK 3933 (Continued) **S118704409**

NYC LAND USE:

Name:	Not reported
Address:	2795 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6782861
Longitude:	-73.8914523
Type Of Ownership Code:	Not reported
Owner Name:	2795 FULTON ST LLC
Borough:	BK
Tax Block:	3933
Tax Lot:	55
Community District:	305
Census Tract 2020:	3114600
Census Block 2020:	31146001003
Census Tract 2010:	1146
Census Block 2010:	1003
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V1: Vacant Land - Zoned Commercial Or Manhattan Residential
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000

DRAFT

LOT 55,TAXBLOCK 3933 (Continued) **S118704409**

Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	382950.00000
Assessed Total Value:	382950.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039330055.00000000
Condominium Number:	Not reported
Census Tract 2:	1146
X Coordinate:	1014358
Y Coordinate:	186413
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 005
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	3039330055.00000000
Apportionment Date:	04/03/2012
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	2795 FULTON STREET
Address:	2795 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678086
Longitude:	-73.89137
OER Project Numbers:	20TMP0836K,20EH-N258K
BBL:	3039330055
OER Program:	VCP (Withdrawn), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	5
Community Board:	37
Council District:	1146
Census Tract:	3000000
BIN:	3039330055
NTA:	Cypress Hills-City Line

DRAFT

AV310 **LOT 18,TAXBLOCK 3946** **NY VCP** **S118704153**
West **2776 FULTON STREET** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.592 mi. **NY NYC OER**
3127 ft. **Site 2 of 2 in cluster AV**

Relative:
Higher

Actual:
50 ft.

VCP NYC:

Project ID:	19TMP1818K,19EH-N392K,20CVCP007K
Name:	2776 FULTON STREET
Address:	2776 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,394,600,183,039,400,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.677955
Longitude:	-73.892152
Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3039460018
NTA:	East New York

E DESIGNATION:

Name:	LOT 18,TAXBLOCK 3946
Address:	2776 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	18
Tax Block:	3946
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2776 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6777542
Longitude:	-73.8920336
Type Of Ownership Code:	Not reported
Owner Name:	FULTON PROJECTS LLC
Borough:	BK
Tax Block:	3946
Tax Lot:	18
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198003003
Census Tract 2010:	1198
Census Block 2010:	3003

DRAFT

LOT 18,TAXBLOCK 3946 (Continued) **S118704153**

School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	39150.00000
Assessed Total Value:	39150.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000

DRAFT

LOT 18,TAXBLOCK 3946 (Continued) **S118704153**

Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039460018.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1014197
Y Coordinate:	186219
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 012
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	2776 FULTON STREET
Address:	2776 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677955
Longitude:	-73.892152
OER Project Numbers:	19TMP1818K,19EH-N392K,20CVCP007K
BBL:	3.0394600183039402E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Construction

URL:

Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3039460018
NTA:	East New York

---

311 West 1/2-1 0.644 mi. 3400 ft.

LOT 15,TAXBLOCK 3690
2738 ATLANTIC AVENUE
BROOKLYN, NY

NY VCP **S118704098**
NY E DESIGNATION **N/A**
NY NYC LAND USE
NY NYC OER

Relative: Higher

Actual: 49 ft.

VCP NYC:

Project ID:	22TMP0839K,22EH-N233K,25CVCP004K
Name:	2738 ATLANTIC AVENUE
Address:	2738 ATLANTIC AVE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3036900015
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.676101

DRAFT

LOT 15,TAXBLOCK 3690 (Continued) **S118704098**

Longitude:	-73.89332
Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3036900015
NTA:	East New York

E DESIGNATION:

Name:	LOT 15,TAXBLOCK 3690
Address:	2738 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	15
Tax Block:	3690
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2738 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6758284
Longitude:	-73.8931435
Type Of Ownership Code:	Not reported
Owner Name:	2738 ATLANTIC AVENUE LLC
Borough:	BK
Tax Block:	3690
Tax Lot:	15
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198002006
Census Tract 2010:	1198
Census Block 2010:	2006
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	C4-4D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported

DRAFT

LOT 15,TAXBLOCK 3690 (Continued) **S118704098**

Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2513
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.5000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	24750.00000
Assessed Total Value:	28755.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	3.40000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036900015.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1013890
Y Coordinate:	185517
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 012
Tax Map #:	31205
E-designation Number:	E-366
Apportionment BBL:	Not reported

DRAFT

LOT 15,TAXBLOCK 3690 (Continued) **S118704098**

Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	2738 ATLANTIC AVENUE
Address:	2738 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676101
Longitude:	-73.89332
OER Project Numbers:	22TMP0839K,22EH-N233K,25CVCP004K
BBL:	3036900015
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Construction

URL:

Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3036900015
NTA:	East New York

AW312 **NY VCP** **S118704084**
West **2718 FULTON STREET** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.702 mi. **NY NYC OER**
3706 ft. **Site 1 of 2 in cluster AW**

Relative:
Higher

Actual:
55 ft.

VCP NYC:

Project ID:	17TMP0622K,18CVCP046K,18EH-N452K
Name:	2718 FULTON STREET
Address:	2718 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	303,673,001,430,367,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.677641
Longitude:	-73.894251
Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3036730014
NTA:	East New York

E DESIGNATION:

Name:	LOT 14,TAXBLOCK 3673
Address:	2718 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	14
Tax Block:	3673

DRAFT

(Continued) **S118704084**

Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2718 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6774432
Longitude:	-73.8941143
Type Of Ownership Code:	Not reported
Owner Name:	2722 FULTON LLC
Borough:	BK
Tax Block:	3673
Tax Lot:	14
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198002001
Census Tract 2010:	1198
Census Block 2010:	2001
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	C4-4L: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	H3: Hotels - Limited Service ? Many Affiliated With National Chain
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	7513
Total Building Floor Area:	36769
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported

DRAFT

(Continued) **S118704084**

Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	7.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	75.0000000
Lot Depth:	100.5000000
Building Frontage:	48.0000000
Building Depth:	100.0000000
Extension Code:	Not reported
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	270450.00000
Assessed Total Value:	2942550.00000
Exempt Total Value:	0.00000
Year Built:	2020
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.89000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	4.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036730014.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1013620
Y Coordinate:	186105
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 012
Tax Map #:	31205
E-designation Number:	E-366
Apportionment BBL:	3036730014.00000000
Apportionment Date:	11/09/2017
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	2718 FULTON STREET
Address:	2718 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677641
Longitude:	-73.894251
OER Project Numbers:	17TMP0622K,18CVCP046K,18EH-N452K
BBL:	3.0367300143036699E+29

DRAFT

(Continued) **S118704084**

OER Program: VCP (Enrolled), E/RD (Review)
Class: Completed (C)
Phase: Site Management

URL:
Postcode: 5
Community Board: 37
Council District: 1198
Census Tract: 3000000
BIN: 3036730014
NTA: East New York

AX313 **NY VCP** **S109155523**
SSW **876 LIVONIA AVENUE** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.708 mi. **NY NYC OER**
3736 ft. **Site 1 of 2 in cluster AX**

Relative:
Lower

Actual:
17 ft.

VCP NYC:
Project ID: 11TMP0272K,11EH-N272K,13CVCP070K
Name: 876 LIVONIA AVENUE NEW 2-STORY COMMERICAL BLDG. - DOB JOB NO. NB - 320232930
Address: 876 LIVONIA AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 3040920003
OER Program: VCP (Enrolled)
Phase: Closure
Latitude: 40.666186
Longitude: -73.88449
Postcode: 5
Community Board: 42
Council District: 1124
Census Tract: 3252958
BIN: 3040920003
NTA: East New York

E DESIGNATION:
Name: LOT 3,TAXBLOCK 4092
Address: 876 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 3
Tax Block: 4092
Borough Code: Not reported
E-No: E-209
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 08HPD012K
Ulurp Number: C080228ZMK
Zoning Map No: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC LAND USE:
Name: Not reported
Address: 876 LIVONIA AVENUE

DRAFT

(Continued) **S109155523**

City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6660321
Longitude:	-73.8844576
Type Of Ownership Code:	Not reported
Owner Name:	877 LIVONIA AVE LLC
Borough:	BK
Tax Block:	4092
Tax Lot:	3
Community District:	305
Census Tract 2020:	3112400
Census Block 2020:	31124001004
Census Tract 2010:	1124
Census Block 2010:	1004
School District:	19
City Council District:	42
Fire Company:	E225
Police Precinct:	75
Health Center District:	33
Health Area:	6420
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	4E
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V1: Vacant Land - Zoned Commercial Or Manhattan Residential
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	800
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	20.0000000
Lot Depth:	40.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0

DRAFT

(Continued) **S109155523**

Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	26100.00000
Assessed Total Value:	26100.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3040920003.00000000
Condominium Number:	Not reported
Census Tract 2:	1124
X Coordinate:	1016304
Y Coordinate:	181951
Zoning Map #:	17d
Zoning Map Code:	Not reported
Sanborn Map #:	308 008
Tax Map #:	31304
E-designation Number:	E-209
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	876 LIVONIA AVENUE NEW 2-STORY COMMERICAL BLDG. - DOB JOB NO. NB - 320232930
Address:	876 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.666186
Longitude:	-73.88449
OER Project Numbers:	11TMP0272K,11EH-N272K,13CVCP070K
BBL:	3040920003
OER Program:	VCP (Enrolled)
Class:	Active (A)
Phase:	Closure

URL:

Postcode:	5
Community Board:	42
Council District:	1124
Census Tract:	3252958
BIN:	3040920003
NTA:	East New York

DRAFT

314
West
1/2-1
0.718 mi.
3793 ft.

2700 ATLANTIC AVENUE
2700 ATLANTIC AVENUE
BROOKLYN, NY

NY VCP **S129932256**
NY NYC OER **N/A**

Relative:
Higher

Actual:
51 ft.

VCP NYC:

Project ID:	19TMP0704K,19EHAN181K,22CVCP001K
Name:	2700 ATLANTIC AVENUE
Address:	2700 ATLANTIC AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3,036,890,012,303,680,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.675937
Longitude:	-73.894603
Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3326746
BIN:	3036890012
NTA:	East New York

NYC OER:

Name:	2700 ATLANTIC AVENUE
Address:	2700 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.675937
Longitude:	-73.894603
OER Project Numbers:	19TMP0704K,19EHAN181K,22CVCP001K
BBL:	3.03689001230368E+69
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3326746
BIN:	3036890012
NTA:	East New York

AX315
SSW
1/2-1
0.726 mi.
3833 ft.

691-715 NEW LOTS AVENUE
691-715 NEW LOTS AVENUE
BROOKLYN, NY

Site 2 of 2 in cluster AX

NY NYC OER **S131580680**
N/A

Relative:
Lower

Actual:
17 ft.

NYC OER:

Name:	691-715 NEW LOTS AVENUE
Address:	691-715 NEW LOTS AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.665541
Longitude:	-73.884657
OER Project Numbers:	19TMP1620K,19EH-N380K
BBL:	3.0409200103040901E+19
OER Program:	E/RD (Review)

DRAFT

691-715 NEW LOTS AVENUE (Continued) **S131580680**

Class: Completed (C)
Phase: Site Management

URL:
Postcode: 5
Community Board: 42
Council District: 1124
Census Tract: 3090735
BIN: 3040920011
NTA: East New York

AW316 **2701-2715 FULTON STREET** **NY VCP** **S129932257**
West **2701-2715 FULTON STREET** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY**
0.740 mi.
3906 ft. **Site 2 of 2 in cluster AW**

Relative:
Higher

Actual:
57 ft.

VCP NYC:
Project ID: 22TMP0913K,22EH-N211K,22CVCP068K
Name: 2701-2715 FULTON STREET
Address: 2701-2715 FULTON STREET
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 303,662,005,230,366,000,000,000,000,000
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Completed
Latitude: 40.67756
Longitude: -73.894943
Postcode: 5
Community Board: 37
Council District: 1146
Census Tract: 3083146
BIN: 3036620052
NTA: Cypress Hills-City Line

NYC OER:
Name: 2701-2715 FULTON STREET
Address: 2701-2715 FULTON STREET
City,State,Zip: BROOKLYN, NY
Latitude: 40.67756
Longitude: -73.894943
OER Project Numbers: 22TMP0913K,22EH-N211K,22CVCP068K
BBL: 3.0366200523036599E+29
OER Program: VCP (Enrolled), E/RD (Review)
Class: Completed (C)
Phase: Completed

URL:
Postcode: 5
Community Board: 37
Council District: 1146
Census Tract: 3083146
BIN: 3036620052
NTA: Cypress Hills-City Line

DRAFT

317
West
1/2-1
0.779 mi.
4113 ft.

157 NEW JERSEY AVENUE
157 NEW JERSEY AVENUE
NEW YORK CITY, NY

NY VCP **S129932074**
NY NYC OER **N/A**

Relative:
Higher

Actual:
54 ft.

VCP NYC:

Project ID:	18TMP0088K,18EH-N061K,18CVCP043K
Name:	157 NEW JERSEY AVENUE
Address:	157 NEW JERSEY AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,367,101,433,036,700,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.676216
Longitude:	-73.895915
Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3036710043
NTA:	East New York

NYC OER:

Name:	157 NEW JERSEY AVENUE
Address:	157 NEW JERSEY AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676216
Longitude:	-73.895915
OER Project Numbers:	18TMP0088K,18EH-N061K,18CVCP043K
BBL:	3.0367101433036702E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	5
Community Board:	37
Council District:	1198
Census Tract:	3000000
BIN:	3036710043
NTA:	East New York

318
West
1/2-1
0.806 mi.
4257 ft.

2667 FULTON STREET
2667 FULTON STREET
NEW YORK CITY, NY

NY VCP **S129932248**
NY NYC OER **N/A**

Relative:
Higher

Actual:
58 ft.

VCP NYC:

Project ID:	22TMP1353K,22EHAN317K,22CVCP079K
Name:	2667 FULTON STREET
Address:	2667 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3036610001
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed

DRAFT

2667 FULTON STREET (Continued) **S129932248**

Latitude:	40.677388
Longitude:	-73.896083
Postcode:	5
Community Board:	37
Council District:	1146
Census Tract:	3000000
BIN:	3036610001
NTA:	Cypress Hills-City Line

NYC OER:

Name:	2667 FULTON STREET
Address:	2667 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677388
Longitude:	-73.896083
OER Project Numbers:	22TMP1353K,22EHAN317K,22CVCP079K
BBL:	3036610001
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	5
Community Board:	37
Council District:	1146
Census Tract:	3000000
BIN:	3036610001
NTA:	Cypress Hills-City Line

319
NE
1/2-1
0.823 mi.
4347 ft.

Relative:
Lower

Actual:
31 ft.

LOT 54,TAXBLOCK 4151
3513 ATLANTIC AVENUE
BROOKLYN, NY 11208

NY LTANKS **S104951429**
NY VCP **N/A**
NY Spills
NY E DESIGNATION
NY NYC LAND USE
NY NYC OER

LTANKS:

Name:	GETTY#411
Address:	3513 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11208
Spill Number/Closed Date:	0708912 / 2008-06-06
Facility ID:	0708912
Site ID:	389902
Spill Date:	2007-11-15
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-11-15
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-11-15
Spill Record Last Update:	2008-06-06
Spiller Name:	STEVE
Spiller Company:	GETTY#411
Spiller Address:	3513 ATLANTIC AVE
Spiller County:	001
Spiller Contact:	STEVE
Spiller Phone:	(718) 348-1800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	348103
Latitude:	40.6830550
Longitude:	-73.8672360
DEC Memo:	11/21/07 called Steve at station (718)348-1800. He was shut down for 5 days. Failure was at vent pipe. This conflicts with Spill Report. He said Tyree made repairs. Called Tyree 1-800-545-1235 to find out what was repaired. Spoke to Elisa Tibitsky. Her boss not in. He will be back Tuesday. Told her I will fax copy of ttf letter. Sent original letter to: Scott Hanley Getty Petroleum Marketing 1500 Hempstead Turnpike East Meadow, NY 11554 Fax sent to Tyree. bf 5/22/2008 Sangesland sent a TTF 2nd notice letter to: Scott Hanley Getty Petroleum Marketing 1500 Hempstead Turnpike East Meadow, NY 11554 6/6/08 Received letter by fax dated 6/6/08 from Erin reilly of Tyree. Failure due to damaged vent lines. Lines were repaired and systems retested and passed. No contamination found. NFA. bf
Remarks:	PBS No: 2-146684 ESTER BROOK TEST: ULIDGE PORTION AND IS ABOVE LIQUID LEVEL AND ARE DOUBLE WALL: STATION IS CLOSED AND TYREE HAS BEEN NOTIFIED

All TTF:

Facility ID:	0708912
Spill Number:	0708912
Spill Tank Test:	1815882
Site ID:	389902
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	True
Cause:	99
Source:	03
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	389902
Operable Unit ID:	1147026
Operable Unit:	01
Material ID:	2137420
Material Code:	0008

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	389902
Operable Unit ID:	1147026
Operable Unit:	01
Material ID:	2137421
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	GETTY
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9507252 / 2004-09-24
Facility ID:	9507252
Site ID:	129874
Spill Date:	1995-09-13
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1995-09-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1948-12-27
Spill Record Last Update:	2004-09-27
Spiller Name:	Not reported
Spiller Company:	GETTY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	128513
Latitude:	40.6826015

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Longitude: -73.8687705
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 3/13/03 REASSIGNED FROM ROMMEL TO VOUGHT. 7/15/04-Vought-File review by Vought: Letter from DEC Tomasello to Getty Oil Co-4/27/91. Due to the occurence or a gasoline spill into the LIRR Atlantic Avenue. the DEC requires the installation of three monitoring wellsin the center of the traffic lane of Atlantic Avenue westbound... Letter from Tyree(Racaniello) to DEC Sullivan-5/8/91. Shown is the sketch for the proposed recovery system . The recovery well will be 12 inches in diameter and 55 feet deep The well will incorporate a product recovery system to capture free phase petroleum products . Site Report (Tyree)-May 1991. Fourteen monitoring wells onsite and one recovery well. Product recovery system began on 6/4/91. Site undergoing weekly monitoring and sampling of influent/effluent to air stripper tower. Letter from Tyree(Racaniello) to DEC Sullivan-5/9/91. Harris Sewer Service will be installing a heavy six inch iron line from the property line to the existing manhole on Atlantic Avenue. Letter to DEP(Joe Cuzzo) from DEC Sullivan-5/9/91. We are presently installing a recovery system . It is essential that we discharge the treated water into a sewer manhole located in front of this station on your 18 inch sewer line . Letter from DEC Sullivan to DEP LaGrotta-5/14/91. What we need is a written okay to tie into the sewer at the above location . Letter from DEP Farag to DEC Sullivan-5/21/91. Letter sent listing requirements for connection to sewer line. Site Report (Tyree)-June 1991. A total of 1457 gallons of product were recovered by this system in June . LIRR has notified Tyree that LEL readings on the explosion meter in the tunnel under Atlantic Avenue has declined from 90% to 10% Site Report (Tyree)-August 1991. This makes a total of 1717 gallons of gasoline recovered from the recovery system since it began operating in June . Site Report (Tyree)-Sept and Oct 1991. A total of 1717 gallons of gasoline has been recovered to date from the recovery system . Site changed to biweekly product monitoring. Letter from Tyree(Pisel) to DEP(Garafallis)-1/14/92. Please find the stripper tower influent and effluent sample results.. Site Report (Tyree)-Nov and Dec 1991. A total of 1717 gallons of gasoline has been recovered to date from the recovery tank . Tank to be scheduled to be emptied in June. Letter from Tyree(Pisel) to DEP(Garafallis)-4/17/92. Please find the stripper tower influent and effluent sample results.. for Jan, Feb and March 1992. Site Report (Tyree)-Jan, Feb and March 1992. A total of 1891 gallons of gasoline has been recovered to date from the recovery tank. Seventy gallons of free product have been removed via manual bailing. Site Report (Tyree)-April 1992. A total of 1891 gallons of gasoline has been recovered to date from the recovery tank. Letter from Tyree(Pisel) to Getty(Ochotorena)-6/18/92. Due to a scheduling error the recovery system at the above referenced site was not sampled during the month of May 1992 . Letter from Tyree(Pisel) to DEP(Garafallis)-7/30/92. Please find the stripper tower influent and effluent sample results.. for the months of June and July 1992. Site Report (Tyree)-June and July 1992. A total of 2737 gallons of gasoline has been recovered to date from the recovery tank. FOIL Request-8/25/92. FOIL request from Richard Berka (LIRR attorney). Site Report (Tyree)-September and October 1992. A total of 2737 gallons of gasoline has been recovered to date from the recovery tank. The system is down at this time awaiting a scheduled pump maintenance . Site Report (Tyree)-Nov and Dec 1992. A total of 2737 gallons of gasoline has been recovered to date from the recovery

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

tank. The system is down at this time pending an investigation of the temporary electical service . Groundwater analyticals-4/13/93. Groundwater analyticals show 213ppb xylene(W6), 1490ppb MTBE(W5), 40ppb MTBE(W10), 41ppb MTBE(W11), 39ppb MTBE(W12) and 16ppb toluene(W9). Status Report (Tyree)-January 1995. Approximately 3237 gallons of gasoline was recovered by the system prior to shut down at the end of June 1993. The previous year of operation and monitoring had shown free-product to be virtually absent from the site wells. Given the diminishment of free product, the NYSDEC authorized abandonment of the four wells in the westbound Atlantic Avenue Roadway . Ten monitoring wells onsite. Report requests spill closure. Site Report (Tyree)-Feb 1995. Recovery system is off. Cycling tower on and off, checking for dissolved levels from recovery well. Maintaining biweekly monitoring. Letter from Tyree(Pisel) to DEC Tomasello-8/23/95. Please recall that closure of the spill case on this site was granted at our last meeting on March 2, 1995. Tyre Brothers plans on removing the recovery equipment and decomissioning the site monitoring wells in the near future. Letter from Tyree(Rennie) to DEC Tomasello-1/14/96. Enclosed please find the analtyical data for the stripper tower sampling performed .....during the month of December 1996 . Status Report (Tyree)-1995. On September 13, 1995 NDE Tank Testing was peforming tank and associated line testing at the site. A failure was detected and spill 9507252 was generated. Six inches of free product was detected in W2. In September 1995 the groundwater remediation system was put back on line . Biweekly monitoring was implemented. Depth to water is 20-22' below grade. Pump truck visits were made while system was put back on line recovering approximately 500gallons. Quarterly Monitoring Report (Tyree)-January thru December 1996. Ten monitoring wells onsite. Weekly gauging. Groundwater flow to the south and later to the south-southwest and later to the south again. Monthly sampling of pump and treat system. Product recovered to date is 941.50 gallons. Stripper Tower Results (Tyree)-July 1996, August 1996, September 1996, October 1996, November 1996. Quarterly Monitoring Report (Tyree)-Jan to March 1997. System not operating/no sampling due to tank removals/installations . Quarterly Monitoring Report (Tyree)-April 1997 thru June 1997. Pump and treat system not operating due to need of temporary electrical connection. SVE system in process of being designed . Tank Closure Report (Tyree)-September 1997. Tank removals performed as part of service station upgrade. Two pump islands located adjacent to Atlantic Avenue. Residential housing to the north and car dealership to the west. Removal of twelve (550-gallon) gasoline USTs and one (550-gallon) waste oil UST. Approximately 450.48 tons of impacted soil were removed. Installation of two (4000-gallon) gasoline and one (4000-gallon) diesel UST in the same location as former tankfield. Six endpoint soil samples were collected. Soil analyticals show 1920ppb xylene(BS1 12'bg), 707ppb MTBE(BS1 12'bg), 130000ppb 1,2,4-trimethylbenzene(BS2 12'bg), 609ppb MTBE(BS2 12'bg), 1480ppb xylene(BS5 12'bg), 13100ppb 1,2,4-trimethylbenzene(BS5 12'bg) and 751ppb MTBE(BS5 12'bg). Quarterly Monitoring Reports (Tyree) July 1997 thru Nov 1998. Nine monitoring wells onsite. Ten monitoring wells onsite from May 1998 thru Nov 1998. Groundwater flow to the south. Product recovery system not operating due to need of temporary electrical connection. SVE system in process of being designed. LNAPL thickness is O feet. Quarterly Monitoring Reports (Tyree) March 1999 thru Nov 1999. Nine monitoring wells onsite. Groundwater flow to the south. LNAPL

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

thickness is O feet. Pump and treat system not operating due to need of electrical connection but Periodic vac truck pump out if needed . SVE system not operating-need temp. electric connection . Quarterly Monitoring Reports (Tyree) Sept 2000 thru Feb 2001. Ten monitoring wells onsite. Groundwater flow to the southwest. No LNAPL detected. Groundwater pump and treat is operational. Letter from Tyree(Ewald) to DEC Rommel-5/7/01. Tyree Brothers Environmental Services respectfully requests closure of this spill number based on the following... Included passing system tightness test for new USTs onsite. Letter from Tyree to DEC Rommel-6/15/01. Letter sent to request the following changes: influent sampling frequency will be changed to quarterly, system maintenance will be bimonthly. These changes will be effected as of July 1, 2001. If there are any objections please notify us in writing.... . Quarterly Monitoring Reports (Tyree) March 2001 thru June 2003. Ten monitoring wells onsite. Groundwater flow to the southwest. No LNAPL detected. Groundwater pump and treat is operational. SVE system installed with influent and effluent readings. System shut down due to electrical problems from Dec 2001 thru Oct 2002. Pump and treat system back in operation from Oct 2002 to June 2003. Quarterly Monitoring Report (Tyree)-Jan 2004 thru March 2004. Ten monitoring wells onsite. No LNAPL detected. Pump and treat and SVE shut down in May 2003. Tyree requested a no further action ruling in a sensitive receptor survey in August 2003. Groundwater analyticals show 26ppb toluene(W2), 603ppb xylene(W2), and 11ppb ethylbenzene(W2). DEC requires: 1)copy of sensitive receptor survey 2)sampling of all onsite wells (including recovery well) for at least one more quarter. Vought sent email to Hatcher/Lindell with requirements. 9/24/04-Vought-Received Quarterly Monitoring Report and Sensitive Receptor Survey (Tyree). Quarterly Monitoring Report- April 2004 thru June 2004. Ten monitoring wells and one recovery well onsite. Groundwater at depths of 20-22' and flow to the southwest. Groundwater analyticals show 258ppb MTBE(W1), 12ppb toluene(W2), 520ppb xylene(W2) and 344ppb MTBE(W8). Downgradient wells W14 and W8 show non detect for MTBE and xylene (contamination confined to onsite). Sensitive Receptor Survey (Tyree) dated August 2004. Long Island Railroad present downgradient across Atlantic Avenue. Groundwater depth is at 20' and therefore below adjacent foundations and utilities. Spill closed by Vought.

Remarks: UPPER PORTION OF TANK FAILED TEST; 2 TANKS FAILED; CHARLES TRUCELLO HAS BEEN DEALING WITH THIS CASE.

VCP NYC:

Project ID:	20TMP0547K,20EHAN140K,20CVCP053K
Name:	3513 ATLANTIC AVENUE
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3041510054
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.682908
Longitude:	-73.867309
Postcode:	5
Community Board:	37
Council District:	1184
Census Tract:	3093045
BIN:	3041510054

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

NTA: Cypress Hills-City Line

SPILLS:

Name:	GETTY # 411
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0508956 / 2005-10-27
Facility ID:	0508956
Facility Type:	ER
DER Facility ID:	128513
Site ID:	354656
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-10-26
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2005-10-26
CID:	408
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-26
Spill Record Last Update:	2005-10-27
Spiller Name:	CAILYN DINAN
Spiller Company:	GETTY # 411
Spiller Address:	3513 ATLANTIC AVE
Spiller Company:	001
Contact Name:	CAILYN DINAN
Latitude:	40.6830380
Longitude:	-73.8672350
DEC Memo:	Not reported
Remarks:	PRODUCT IS ABOUT 1/2 CUP. HAS BEEN CLEANE DUP

All Materials:

Site ID:	354656
Operable Unit ID:	1112052
Operable Unit:	01
Material ID:	2102093
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name: GETTY

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0204967 / 2003-12-05
Facility ID:	0204967
Facility Type:	ER
DER Facility ID:	128513
Site ID:	151206
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-08-10
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2002-08-10
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-10
Spill Record Last Update:	2004-07-12
Spiller Name:	Not reported
Spiller Company:	GETTY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
Latitude:	40.6826015
Longitude:	-73.8687705
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Assigned to Vought on Monday, 8/12/02 from Krimgold. email to Tyree and Delta, Getty's consultants on 8/12/02: FYI Spill #: 02-04967 was reported to DEC on 8/10/02 at 7:36pm from NYCDEP. A malfunction of the stripper tower caused contaminated water to spill onto the street. DEP turned off the system to stop the flow of water. Please visit the site and ensure that the system is up and running ASAP to prevent any impact to the subway. >>> Jennifer Rommel 08/12/02 04:23PM >>> Eric, DEP Contact: Doug Greeley Water and Sewer Operations 718-595-5330 Mention the Atlantic Avenue and Grant Avenue site DEP Reference #494553 As per your Quarterly Report dated 7/26/02, the system temporarily shut down due to electrical problems, but was repaired on July 15. Was the system ever put back on line? Has the system been operating with a broken discharge line since the water main installation? I wouldn't worry so much about the lost water. Discussions with DEP did however mention they saw a sheen on the water? I would focus on getting the system re-connected and back

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

on line. Call with questions
718-482-4934 Thank you. >>> Eric Ewald <EEwald@tyreeorg.com> 08/12/02 03:45PM >>> Tyree's
environmental technician visited this site August 12, 2002. All that remains is a road plate in the
middle of Atlantic avenue. The station operator informed our technician that a DEP subcontractor
installed a water main along Atlantic avenue within the past two months, during a time when the
remediation system was not operating. The discharge line was damaged by the subcontractor and Tyree
will have to obtain necessary permits and clearances to complete repairs in Atlantic Avenue.
Jennifer, do you have contact information for the DEP regarding this issue? It would be ideal If we
can work with them under an emergency repair order to prevent permit delays. Are we certain
contaminated water spilled onto Atlantic Avenue? This should have been discharge water which has
shown Below Detectable Limits in the past. 12/4/03-Vought-This spill on concrete and closed due to
open spill #9013177 at same location. See also closed spill #0012591 at same location.

Remarks: dep rep called in a leak from an oil/water seperater - spill to the street

All Materials:

Site ID:	151206
Operable Unit ID:	856265
Operable Unit:	01
Material ID:	552588
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY#411
Address:	3513 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0711716 / 2008-04-03
Facility ID:	0711716
Facility Type:	ER
DER Facility ID:	339480
Site ID:	393237
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-02-06
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2008-02-06
CID:	444

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-06
Spill Record Last Update:	2008-04-03
Spiller Name:	MIKE CARR\\
Spiller Company:	GETTY#411
Spiller Address:	3513 ATLANTIC AVE
Spiller Company:	001
Contact Name:	MIKE CARR\\
Latitude:	40.6830550
Longitude:	-73.8672360
DEC Memo:	Tyree submitted a spill form which says there was only sweating from the pipes. Pipes were opened & reconnected to solve problem. No leak found
Remarks:	less then 1 gallon and in process of cleaning

All Materials:

Site ID:	393237
Operable Unit ID:	1150205
Operable Unit:	01
Material ID:	2140799
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY#411
Address:	3513 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0711782 / 2008-02-08
Facility ID:	0711782
Facility Type:	ER
DER Facility ID:	339480
Site ID:	393312
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-02-08
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2008-02-08
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-08
Spill Record Last Update:	2008-02-08
Spiller Name:	MIKE CARR\\
Spiller Company:	GETTY#411
Spiller Address:	3513 ATLANTIC AVE
Spiller Company:	001
Contact Name:	MIKE CARR\\
Latitude:	40.6830550
Longitude:	-73.8672360
DEC Memo:	minor case - all cleaned
Remarks:	SWEAT ON LINE AND ALL CLEANED UP

All Materials:

Site ID:	393312
Operable Unit ID:	1150279
Operable Unit:	01
Material ID:	2140882
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY#411
Address:	3513 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0709615 / 2007-12-06
Facility ID:	0709615
Facility Type:	ER
DER Facility ID:	339480
Site ID:	390722
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	D4
SWIS:	2401
Spill Date:	2007-12-06
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2007-12-06
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Remediation Phase:	0
Date Entered In Computer:	2007-12-06
Spill Record Last Update:	2007-12-06
Spiller Name:	MIKE CARR\\
Spiller Company:	GETTY#411
Spiller Address:	3513 ATLANTIC AVE
Spiller Company:	001
Contact Name:	MIKE CARR\\
Latitude:	40.6830550
Longitude:	-73.8672360
DEC Memo:	small spill to surface. closed.
Remarks:	CLEANED UP

All Materials:

Site ID:	390722
Operable Unit ID:	1147817
Operable Unit:	01
Material ID:	2138280
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY#411
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0705161 / 2008-10-24
Facility ID:	0705161
Facility Type:	ER
DER Facility ID:	128513
Site ID:	385440
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-08-06
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-08-06
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-08-06
Spill Record Last Update:	2008-10-24
Spiller Name:	MIKE CARR\\
Spiller Company:	GETTY#411

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Spiller Address:	3513 ATLANTIC AVE
Spiller Company:	001
Contact Name:	MIKE CARR\\
Latitude:	40.6830550
Longitude:	-73.8672360
DEC Memo:	Tyree report says: spill to gravel below the dispenser was all contained. 8/8/07 manifest for 42 gal vac truck from all sumps on the site.
Remarks:	LESS THEN ONE GALLON AND VAC TRUCK ENROUTE AND DIESEL IS ON GRAVEL BENEATH DISPENSER

All Materials:

Site ID:	385440
Operable Unit ID:	1142710
Operable Unit:	01
Material ID:	2132952
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	385440
Operable Unit ID:	1142710
Operable Unit:	01
Material ID:	2132953
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0012591
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012591 / 2003-12-05
Facility ID:	0012591
Facility Type:	ER
DER Facility ID:	128513
Site ID:	129873
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-02-26
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2001-02-26
CID:	207
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2001-02-26
Spill Record Last Update:	2003-12-05
Spiller Name:	ERIC EWALD
Spiller Company:	Not reported
Spiller Address:	3513 ATLANTIC AVE
Spiller Company:	001
Contact Name:	ERIC EWALD
Latitude:	40.6826015
Longitude:	-73.8687705
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 12/5/03-Vought-Spill transferred from Rommel to Vought. Spill closed by Vought due to open spill #9013177 at same location. See also closed spill #0204967 at same location.
Remarks:	product in monitoring well will notify case manager re status

All Materials:

Site ID:	129873
Operable Unit ID:	834134
Operable Unit:	01
Material ID:	542854
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E DESIGNATION:

Name:	LOT 54,TAXBLOCK 4151
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Tax Lot(s):	54
Tax Block:	4151
Borough Code:	BK
E-No:	E-529
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	18DCP180K
Ulurp Number:	190222ZMK
Zoning Map No:	Not reported
Description:	Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

NYC LAND USE:

Name:	Not reported
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6831853
Longitude:	-73.8675684
Type Of Ownership Code:	Not reported
Owner Name:	LEEMILT'S PETROLEUMINC
Borough:	BK
Tax Block:	4151
Tax Lot:	54
Community District:	305
Census Tract 2020:	3118400
Census Block 2020:	31184001002
Census Tract 2010:	1184
Census Block 2010:	1002
School District:	19
City Council District:	37
Fire Company:	E236
Police Precinct:	75
Health Center District:	34
Health Area:	3900
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	2C
Zoning District 1:	R5: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	K1: Store Buildings (Taxpayers Included) - One Story Retail Building
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	18760
Total Building Floor Area:	6816
Commercial Floor Area:	6816
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	6816
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	152.4200000
Lot Depth:	115.4200000
Building Frontage:	75.0000000

DRAFT

LOT 54,TAXBLOCK 4151 (Continued) **S104951429**

Building Depth:	72.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	219600.00000
Assessed Total Value:	219600.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.36000000000
Maximum Allowable Residential Far:	1.25000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3041510054.00000000
Condominium Number:	Not reported
Census Tract 2:	1184
X Coordinate:	1020980
Y Coordinate:	188207
Zoning Map #:	18a
Zoning Map Code:	Y
Sanborn Map #:	308 035
Tax Map #:	31306
E-designation Number:	E-529
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:

Name:	3513 ATLANTIC AVENUE
Address:	3513 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.682908
Longitude:	-73.867309
OER Project Numbers:	20TMP0547K,20EHAN140K,20CVCP053K
BBL:	3041510054
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	5
Community Board:	37
Council District:	1184
Census Tract:	3093045
BIN:	3041510054
NTA:	Cypress Hills-City Line

DRAFT

320 WSW 1/2-1 0.824 mi. 4353 ft. — **EXXON DIV OF CFI #70227**, **225 PENNSYLVANIA AVE**, **BROOKLYN, NY 11236**

Database(s): **RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NY NYC OER**

EDR ID Number: **1000335601**
EPA ID Number: **NYD986894186**

Relative: Higher
Actual: 41 ft.

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Exxon Div Of Cfi #70227
Handler Address:		Pennsylvania Ave
Handler City,State,Zip:		BROOKLYN, NY 11236
EPA ID:		NYD986894186
Contact Name:		MAUREEN JERNSTEDT
Contact Address:		DEDHAM ST
Contact City,State,Zip:		CANTON, MA 02021
Contact Telephone:		800-225-9702 x3378
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		DEDHAM ST
Mailing City,State,Zip:		CANTON, MA 02021
Owner Name:	Tosco	
Owner Type:		Private
Operator Name:	No Name Found	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Owner/Operator Telephone: 602-728-8000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CUMBERLAND FARMS INC
Legal Status: Private
Date Became Current: 20030910
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CUMBERLAND FARMS INC
Legal Status: Private
Date Became Current: 20030910
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND
Legal Status: Private
Date Became Current: 20030910
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TOSCO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 52085
Owner/Operator City,State,Zip: PHOENIX, AZ 85072-2085
Owner/Operator Telephone: 602-728-8000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: TOSCO #34780
Federal Waste Generator Description: Not a generator, verified

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EXXON DIV OF CFI #70227
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EXXON DIV OF CFI #70227
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900404
Handler Name: TOSCO #34780
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010808
Handler Name: TOSCO #34780
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20041001
Handler Name: EXXON DIV OF CFI #70227
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44711
NAICS Description: Gasoline Stations With Convenience Stores

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004444192

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000335601
Registry ID: 110004444192

DFR URL:
Name: EXXON DIV OF CFI #70227
Address: 225 Pennsylvania Ave
City,State,Zip: BROOKLYN, NY 11236

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

NY MANIFEST:

EPA ID:	NYD986894186
Country:	USA
Name:	Exxon Company Usa
Address:	225 PENNSYLVANIA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11236
Zip 4:	Not reported
Location Address 1:	225 PENNSYLVANIA AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 13775
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Exxon Company Usa
Mailing Contact:	Christine Coluccio
Mailing Address 1:	P O BOX 4415
Mailing Address 2:	Not reported
Mailing City,State,Zip:	HOUSTON, TX 77210
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5168641772

Manifest Data:

Document ID:	NYB2128320
Manifest Status:	Not reported
Trans1 State ID:	IL015
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	10/11/1990
Trans1 Recv Date:	10/11/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/12/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Carbon Tetrachloride
Waste Code 2:	Not reported

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00100
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB2445165
Manifest Status:	Not reported
Trans1 State ID:	HW6917
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	01/07/1992
Trans1 Recv Date:	01/07/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	NYD986910222
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00010
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	MAF3182630
Manifest Status:	Not reported
Trans1 State ID:	50C143OH
Year:	1991
Trans2 State ID:	Not reported

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Generator Ship Date:	05/12/1991
Trans1 Recv Date:	05/30/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA1565917
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES50
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	03/24/1993
Trans1 Recv Date:	03/24/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/24/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	NYD980761191

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	CTF0180176
Manifest Status:	Not reported
Trans1 State ID:	PP1384
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1992
Trans1 Recv Date:	10/12/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	NYD986910222
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste

DRAFT

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00600
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

NYC OER:

Name:	225 PENNSYLVANIA AVENUE
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.672274
Longitude:	-73.895954
OER Project Numbers:	17TMP0295K,17EH-N250K
BBL:	3037210001
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	5
Community Board:	37
Council District:	1144
Census Tract:	3426261
BIN:	3037210001
NTA:	East New York (Pennsylvania Ave)

321
WSW
1/2-1
0.850 mi.
4487 ft.

184 PENNSYLVANIA AVENUE
BROOKLYN, NY 11207

NY VCP **S118704314**
NY E DESIGNATION **N/A**
NY NYC LAND USE
NY NYC OER

Relative:
Higher

Actual:
47 ft.

VCP NYC:

Project ID:	22TMP1653K,22EHAZ371K,23CVCP013K
Name:	184 PENNSYLVANIA AVENUE
Address:	184 PENNSYLVANIA AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	303,703,003,530,370,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.673405
Longitude:	-73.896266
Postcode:	5
Community Board:	37
Council District:	1144
Census Tract:	3000000
BIN:	3037030035
NTA:	East New York (Pennsylvania Ave)

DRAFT

(Continued) **S118704314**

E DESIGNATION:

Name:	LOT 35,TAXBLOCK 3703
Address:	184 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	35
Tax Block:	3703
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	184 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6732871
Longitude:	-73.8965795
Type Of Ownership Code:	Not reported
Owner Name:	180 PENNSYLVANIA LLC
Borough:	BK
Tax Block:	3703
Tax Lot:	35
Community District:	305
Census Tract 2020:	3114400
Census Block 2020:	31144002003
Census Tract 2010:	1144
Census Block 2010:	2003
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	33
Health Area:	5700
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D3: Elevator Apartments - Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0

DRAFT

(Continued) **S118704314**

Lot Area:	7500
Total Building Floor Area:	38755
Commercial Floor Area:	0
Residential Floor Area:	38755
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	50
Total Units:	50
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	50850.00000
Assessed Total Value:	108000.00000
Exempt Total Value:	0.00000
Year Built:	2024
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	5.17000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3037030035.00000000
Condominium Number:	Not reported
Census Tract 2:	1144
X Coordinate:	1012938
Y Coordinate:	184590
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 010
Tax Map #:	31205
E-designation Number:	E-366
Apportionment BBL:	3037030034.00000000
Apportionment Date:	07/19/2024
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

NYC OER:
Name: 184 PENNSYLVANIA AVENUE

DRAFT

(Continued) **S118704314**

Address:	184 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.673405
Longitude:	-73.896266
OER Project Numbers:	22TMP1653K,22EHAZ371K,23CVCP013K
BBL:	3.0370300353037001E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	5
Community Board:	37
Council District:	1144
Census Tract:	3000000
BIN:	3037030035
NTA:	East New York (Pennsylvania Ave)

322
SE
1/2-1
0.854 mi.
4507 ft.

MAJESTIC CLNRS
740 PINE ST
BROOKLYN, NY 11364

NY SHWS **S110248343**
NY VCP **N/A**
NY MANIFEST

Relative:
Lower

Actual:
9 ft.

SHWS:

Name:	FORMER MAJESTIC GARMENT CLEANERS
Address:	740 PINE STREET
City,State,Zip:	BROOKLYN, NY 11208
Program:	HW
Site Code:	58590
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	0.470
HW Code:	224035
Record Add:	02/21/2001
Record Upd:	02/28/2020
Updated By:	JCGRATHW

Site Description: {see Site Code C224035 for further details as this project entered the Brownfield Cleanup Program} Location: The Former Majestic Garment Cleaners site is approximately 0.47 acres in size and is located at 740 Pine Street (a.k.a. 1151 Loring Avenue) in Brooklyn, at the northeast corner of the intersection of Loring Avenue and Pine Street in the East New York section of Brooklyn. Site Features: The property is surrounded by a chain link fence and previously contained a one-story brick building which was demolished sometime in 2008. The property is currently vacant except for construction and demolition debris and parked vehicles. Current Zoning and Land Use: The property is a vacant lot in a residential zone. It is zoned R4 (Residential) with a C1-2 (Commercial) overlay. The surrounding parcels are currently used for a mix of commercial and residential uses. Past Use of Site: The site was formerly used as an industrial laundry and dry cleaning facility from 1926 to 2007, and operated out of a large one-story brick building which was constructed in 1926. The building was later expanded with a smaller attached one-story cinder block building on its north side. In early 1999, the U. S. Environmental Protection Agency (EPA) conducted two separate inspections of the Majestic Garment Cleaners facility, one on January 25, 1999, and the

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

other on March 29, 1999. During those inspections EPA personnel observed employees disposing of tetrachloroethene (PCE) contaminated water from steam presses onto the ground behind the facility on the western side of the property. They also noticed that the areas around the dry- cleaning equipment were visibly contaminated with PCE-contaminated lint and a dark liquid residue. EPA subsequently learned that Majestic employees regularly vacuumed PCE-contaminated lint and disposed of it in a dumpster behind the building. In the Fall of 2001, the Department conducted an investigation which showed that the groundwater underlying the site was contaminated with PCE and its breakdown products. A Phase II investigation was conducted in June 2009. Soil samples were collected and the results showed exceedances above unrestricted soil cleanup objectives (SCOs) for volatile organic compounds (VOCs) and semi-volatile organic compounds (SVOCs). Site Geology and Hydrogeology: Much of the surface soil at the site consists of urban fill composed of mixed sand with varying amounts of gravel, brick, and concrete debris. The urban fill (i.e., debris, brick, etc.) at the site extends down to approximately 8 feet below ground surface (bgs); the fill is underlain by organic rich clay and sand. The depth to groundwater has been observed to be approximately 10 feet bgs. The groundwater flow direction in the vicinity of the site is to the southwest. It appears that a local hydraulic low, which was historically observed near piezometer PZ-2, may have been due to efforts to dewater the basement of the former on-site building when the building was present and in use.

Env Problem: Nature and Extent of Contamination: Based on the Remedial Investigation, the primary contaminants of concern (COCs) at the site include tetrachloroethylene (PCE), trichloroethylene (TCE), 1,2-dichloroethylene (1,2-DCE), vinyl chloride, and benzo(a)pyrene. Elevated levels of these constituents were found primarily in the western portion of the site. Groundwater - PCE (detected up to 260 ppb) and associated daughter products, cis-1,2-DCE (detected up to 410 ppb), TCE (detected up to 72 ppb) and vinyl chloride (detected up to 150 ppb) were identified at levels exceeding their respective groundwater standards. The groundwater standard for PCE, 1,2-DCE, and TCE is 5 ppb. The groundwater standard for vinyl chloride is 2 ppb. Soils - Soils exceeding residential soil cleanup objective (SCOs) are present only in the western portion of the site. Benzo(a)pyrene was detected in subsurface soil (in a sample collected from the 10-foot to 11-foot depth interval) at a level of 2.6 ppm which exceeded the residential use soil cleanup objective (SCO) of 1 ppm. PCE was detected in subsurface soil at 8.1 ppm in a soil boring sample collected from the 11-foot to 12-foot depth interval in the western portion of the site in the vicinity of the former loading dock area. PCE was also detected in another soil boring sample from the 10-foot to 11-foot depth interval at a concentration of 6.8 ppm. This sample was also collected in the western portion of the site. Both of these concentration levels exceeded the protection of groundwater SCO of 1.3 ppm. Soil Vapor - Elevated soil vapor concentration levels were detected in the western portion of the site in the same general area of the highest groundwater and soil contamination. The most significant results were: PCE at 640,000 g/m3; vinyl chloride at 330,000 g/m3; cis-1,2-DCE at 440,000 g/m3; trans-1,2-DCE at 4,800 g/m3; TCE at 25,000 g/m3; and 1,1-DCE at 2,000 g/m3. Based on the elevated soil vapor concentrations in the western portion of the site, additional off-site soil vapor sampling was conducted. Elevated soil vapor concentrations were observed in most of the off-site

MAJESTIC CLNRS (Continued) **S110248343**

samples located west of the site including samples collected near the laundromat. The most significant results were: PCE at 310,000 g/m3; cis-1,2-DCE at 1,300 g/m3; and TCE at 7,000 g/m3. Elevated levels of gasoline-related compounds were also observed in some of the samples, but these compounds are not considered to be site-related. Environmental sampling indicates soil vapor intrusion may be a concern for on-site and off-site structures.

Health Problem: People are not drinking the contaminated groundwater because the area is served by a public water supply that is not contaminated by the site. The site is fenced, which limits public access. However, part of the lot is being used for parking and storage of building materials and persons who enter the site could contact contaminants in the soil by walking on the site, digging or otherwise disturbing the soil. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The on-site building has been demolished, however the potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future on-site building development and occupancy. Elevated concentrations of site-related contaminants were detected in soil vapor off-site. The potential for exposures in off-site buildings needs to be monitored and/or evaluated to determine if mitigation measures should be implemented.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2001-02-21 08:32:00
Record Upd: 2013-09-20 14:13:00
Updated By: ldennist
Own Op: 1
Sub Type: 01
Owner Name: Not reported
Owner Company: M & A Holdings I LLC
Owner Address: 94-28 85th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Woodhaven, NY 11421
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Ms. Dowshon A. Perveen
Owner Company: Brooklyn Public Library
Owner Address: 1197 Sutter Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11208
Owner Country: United States of America
Own Op: 4
Sub Type: 01
Owner Name: Nick Persaud

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Owner Company:	1151 Loring Avenue, LLC
Owner Address:	78-50 65th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Glendale, NY 11385
Owner Country:	United States of America
HW Code:	224035
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224035
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

HW Code: 224035
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224035
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224035
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 0905690
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2010-01-14 11:34:00
Record Updated: 2010-01-14 11:34:00
Updated By: RMPIPER

VCP:
Name: FORMER MAJESTIC CLEANERS SITE
Address: 740 PINE STREET
City,State,Zip: BROOKLYN, NY 11235
Program Type: VCP
Site Code: 58591
HW Code: V00608
Site Class: N
SWIS: 2401
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 08/30/2002
Date Record Updated: 07/31/2007
Updated By: MOBARRIE
Site Description: The Former Majestic Garment Cleaners is located at the northeast corner of the intersection of Loring Avenue and Pine Street in the East New York section of Brooklyn. The property contains a 1-story brick building and a parking lot which is surrounded by a chain link fence. The site is currently occupied by a dry cleaning operation (World Cleaners). In early 1999, EPA conducted two separate inspections of the Majestic Garment Cleaners facility. During those inspections, EPA personnel observed employees disposing of tetrachloroethene (PCE) contaminated water from steam presses onto the ground behind the facility. They also noticed that the areas around the dry cleaning equipment were visibly contaminated with PCE-contaminated lint and a dark liquid residue. EPA subsequently learned that Majestic employees regularly vacuumed PCE-contaminated lint and disposed of it in a dumpster behind the building. Completed investigations include an Immediate Investigation Work Assignment (2001). In January 2004, a Voluntary Cleanup Agreement was signed, and in July 2005, the Volunteer performed fieldwork associated with the Remedial Investigation (RI). However, the Volunteer never submitted a formal RI Report documenting the results of the investigation, and in June 2006, the State terminated the agreement with the owner of the site due to their failure to respond appropriately. The site investigation and cleanup will be done under the Inactive Hazardous Waste Disposal Site remedial program-see site

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

	#224035 for more information.
Env Problem:	The primary contaminants of concern at the site known at this time include tetrachloroethylene (PCE), trichloroethylene (TCE), 1,2-dichloroethylene (1,2-DCE)and vinyl chloride. The initial investigation indicates groundwater beneath the site has been impacted. Exceedances of standards, criteria and guidance include PCE, TCE, 1,2-DCE and vinyl chloride in groundwater.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	ZZZ
Owner Name:	David J. Von Lindern
Owner Company:	Jodave Realty, Inc.
Owner Address:	740 Pine Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11235
Owner Country:	United States of America
Own Op:	4
Sub Type:	01
Owner Name:	David J. Von Lindern
Owner Company:	World Cleaners, Inc.
Owner Address:	740 Pine Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11235
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NY MANIFEST:

EPA ID:	NYD080451529
Country:	USA
Name:	Majestic Clnrs
Address:	740 PINE ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11364-0000
Zip 4:	Not reported
Location Address 1:	1147 LORRING AVE
Location Address 2:	Not reported

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Location City,State,Zip: BROOKLYN, NY 11208
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Majestic Clnrs
Mailing Contact: Majestic Clnrs
Mailing Address 1: 740 PINE STREET
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11208
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7182720010

Manifest Data:
Document ID: NYC1103589
Manifest Status: Not reported
Trans1 State ID: AM6252NY
Year: 1991
Trans2 State ID: Not reported
Generator Ship Date: 07/26/1991
Trans1 Recv Date: 07/26/1991
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/26/1991
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080451529
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980785760
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00975
Units:	Pounds
Number of Containers:	005
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA6835083
Manifest Status:	C - Completed copy
Trans1 State ID:	NY16549GW
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	871023
Trans1 Recv Date:	871023
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	871023
Part A Recv Date:	871028
Part B Recv Date:	871029
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00675
Units:	Pounds
Number of Containers:	005
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	02925
Units:	Pounds
Number of Containers:	015
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYA9218529
Manifest Status:	C - Completed copy
Trans1 State ID:	NYAY9381
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890113
Trans1 Recv Date:	890113
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890113
Part A Recv Date:	890120
Part B Recv Date:	890123
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01755
Units:	Pounds
Number of Containers:	009
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00135
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYC5602241
Manifest Status:	Not reported
Trans1 State ID:	NYLP3931
Year:	1999
Trans2 State ID:	T104414IL
Generator Ship Date:	04/20/1999
Trans1 Recv Date:	04/20/1999
Trans2 Recv Date:	04/22/1999
TSD Site Recv Date:	04/27/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Quantity:	00240
Units:	Pounds
Number of Containers:	004
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00390
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC4322305
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	10/25/1996
Trans1 Recv Date:	10/25/1996
Trans2 Recv Date:	10/29/1996
TSD Site Recv Date:	10/31/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane,

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00300
Units:	Pounds
Number of Containers:	005
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00585
Units:	Pounds
Number of Containers:	003
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00585
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID: NYC2247952

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Manifest Status:	Not reported
Trans1 State ID:	LP3931NY
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	04/16/1993
Trans1 Recv Date:	04/16/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00945
Units:	Pounds
Number of Containers:	007
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00240
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC2293345
Manifest Status:	Not reported
Trans1 State ID:	LP3931NY
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/1993
Trans1 Recv Date:	05/12/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00240
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00675
Units:	Pounds
Number of Containers:	005
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC3353174
Manifest Status:	Not reported
Trans1 State ID:	JE4550NY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	11/29/1994
Trans1 Recv Date:	11/29/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/29/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00700
Units: Pounds
Number of Containers: 007
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC4390637
Manifest Status: Not reported
Trans1 State ID: NYGF2859
Year: 1996
Trans2 State ID: MO001
Generator Ship Date: 11/25/1996
Trans1 Recv Date: 11/25/1996
Trans2 Recv Date: 12/03/1996
TSD Site Recv Date: 12/04/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD080451529
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: MOD095038998
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00240
Units: Pounds

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Number of Containers:	004
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	01170
Units:	Pounds
Number of Containers:	006
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC4674431
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	1997
Trans2 State ID:	FT97538
Generator Ship Date:	03/18/1997
Trans1 Recv Date:	03/18/1997
Trans2 Recv Date:	03/24/1997
TSD Site Recv Date:	03/25/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

	Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00240
Units:	Pounds
Number of Containers:	004
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00390
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA0018639
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWAS581
Year:	1985
Trans2 State ID:	Not reported
Generator Ship Date:	850507
Trans1 Recv Date:	850507
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	850507
Part A Recv Date:	850524
Part B Recv Date:	850522
Generator EPA ID:	NYD080451529
Trans1 EPA ID:	NJD085634335
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

DRAFT

MAJESTIC CLNRS (Continued) **S110248343**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	003
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Treat
Specific Gravity:	100
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Treat
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
182 additional NY MANIFEST: record(s) in the EDR Site Report.

DRAFT

323
SW
1/2-1
0.859 mi.
4536 ft.

461 NEW JERSEY AVENUE
BROOKLYN, NY 11207

NY VCP **S131159521**
NY NYC LAND USE **N/A**
NY NYC OER

Relative:
Higher

Actual:
34 ft.

VCP NYC:

Project ID:	25TMP0236K,25CVCP014K
Name:	461 NEW JERSEY AVENUE - HPD NCP CLUSTER
Address:	461 NEW JERSEY AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3037730056
OER Program:	VCP (Enrolled)
Phase:	Construction
Latitude:	40.668213
Longitude:	-73.893887
Postcode:	5
Community Board:	42
Council District:	1158
Census Tract:	3084339
BIN:	3037730056
NTA:	East New York (Pennsylvania Ave)

NYC LAND USE:

Name:	Not reported
Address:	461 NEW JERSEY AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6681379
Longitude:	-73.8935848
Type Of Ownership Code:	C
Owner Name:	NYC HOUSING PRESERVATION AND DEVELOPMENT
Borough:	BK
Tax Block:	3773
Tax Lot:	56
Community District:	305
Census Tract 2020:	3115800
Census Block 2020:	31158002003
Census Tract 2010:	1158
Census Block 2010:	2003
School District:	19
City Council District:	42
Fire Company:	L103
Police Precinct:	75
Health Center District:	33
Health Area:	6100
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	4D
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-3
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

DRAFT

(Continued) **S131159521**

Spill Boundary Indicator:	N
Building Class:	V1: Vacant Land - Zoned Commercial Or Manhattan Residential
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	2000
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	20.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	63000.00000
Assessed Total Value:	63000.00000
Exempt Total Value:	63000.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3037730056.00000000
Condominium Number:	Not reported
Census Tract 2:	1158
X Coordinate:	1013771
Y Coordinate:	182715
Zoning Map #:	17d
Zoning Map Code:	Not reported
Sanborn Map #:	316 025
Tax Map #:	31206
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1

DRAFT

(Continued) **S131159521**

Changed By DCP: t

NYC OER:
Name: 461 NEW JERSEY AVENUE - HPD NCP CLUSTER
Address: 461 NEW JERSEY AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.668213
Longitude: -73.893887
OER Project Numbers: 25TMP0236K,25CVCP014K
BBL: 3037730056
OER Program: VCP (Enrolled)
Class: Active (A)
Phase: Construction

URL:
Postcode: 5
Community Board: 42
Council District: 1158
Census Tract: 3084339
BIN: 3037730056
NTA: East New York (Pennsylvania Ave)

---

324 West 1/2-1 0.871 mi. 4598 ft.

50 PENN LLC
2618 FULTON ST
BROOKLYN, NY 11207

NY VCP **S118704070**
NY Spills **N/A**
NY MANIFEST
NY NYC OER

Relative: Higher

Actual: 58 ft.

VCP NYC:
Project ID: 18TMP1429K,18EHAN480K,19CVCP033K
Name: 2618 FULTON STREET
Address: 2618 FULTON STREET
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 303,669,001,330,366,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Site Management
Latitude: 40.677079
Longitude: -73.898052
Postcode: 5
Community Board: 37
Council District: 1198
Census Tract: 3083272
BIN: 3036690022
NTA: East New York

SPILLS:
Name: SOIL
Address: 2618 FULTON STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1901557 / 2021-11-05
Facility ID: 1901557
Facility Type: ER
DER Facility ID: 539729
Site ID: 588446
DEC Region: 2
Spill Cause: Unknown

DRAFT

50 PENN LLC (Continued) **S118704070**

Spill Class:	Not reported
SWIS:	2401
Spill Date:	2019-05-14
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-05-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-05-14
Spill Record Last Update:	2021-11-05
Spiller Name:	STEWART KNOOP
Spiller Company:	50 PENN LLC
Spiller Address:	2618 FULTON STREET
Spiller Company:	999
Contact Name:	STEWART KNOOP
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	5/16/19-Lin-This site along with a few neighboring lots are currently under OER s cleanup program to redevelop the sites. They found a few underground tanks that were previously identified and underground tanks that were not found during the GPR survey. Langan suspect that they will encounter more tanks going forward. 9/10/19-Lin-Received call from langan that they found multiple tank near the site boundary that had soil contamination where the tank were. They made us aware that they would have trouble obtaining side wall samples due to the shoring put in place. Off site borings might be require to delineate the contaminated soil. The whole site is going to be excavated down to 15' and 30 bottoms samples would be taken across the site. 11/5/21-Lin-A total of sixteen (16) underground storage tanks were removed. Contaminated soil was excavated. Groundwater was encountered around 50 bgs and the groundwater is inferred to flow to the southeast towards Jamaica Bay. One groundwater sample was collected and came back clean. Groundwater is not expected to be impacted at this site. The whole site was excavated to varies depth. A total of 18 endpoint samples were collected from the base of the remedial excavation. The sample results confirmed that a Track 4 residential cleanup was achieved. An engineered composite cover system consisting of 46 inch and 40 inch thick structural mat slabs in the partial cellar and in the ground floor garage was constructed. A 12 inch thick concrete slab above a 20 mil vapor barrier and an active SSDS were

DRAFT

50 PENN LLC (Continued) **S118704070**

installed. Case closed Stewart from langan 212-479-5461 sknoop@langan.com
Remarks: clean up is done

All Materials:
Site ID: 588446
Operable Unit ID: 1336105
Operable Unit: 01
Material ID: 2345435
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: 2.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

NY MANIFEST:
EPA ID: NYR000242487
Country: USA
Name: 50 Penn Llc
Address: 2618 FULTON ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: 2618 FULTON ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: 50 Penn Llc
Mailing Contact: 50 Penn Llc
Mailing Address 1: 2618 FULTON ST
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11207
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NYC OER:
Name: 2618 FULTON STREET
Address: 2618 FULTON STREET
City,State,Zip: BROOKLYN, NY
Latitude: 40.677079
Longitude: -73.898052
OER Project Numbers: 18TMP1429K,18EHAN480K,19CVCP033K
BBL: 3.0366900133036599E+59
OER Program: VCP (Enrolled), E/RD (Review)
Class: Completed (C)
Phase: Site Management

DRAFT

50 PENN LLC (Continued) **S118704070**

URL:
Postcode: 5
Community Board: 37
Council District: 1198
Census Tract: 3083272
BIN: 3036690022
NTA: East New York

325
SW
1/2-1
0.940 mi.
4965 ft.

673 LIVONIA AVENUE
673 LIVONIA AVENUE
BROOKLYN, NY 11207

NY SHWS **S129982655**
NY NYC LAND USE **N/A**

Relative:
Lower

Actual:
29 ft.

SHWS:
Name: 673 LIVONIA AVENUE
Address: 673 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11207
Program: HW
Site Code: 631213
Classification: P
Region: 2
Acres: 0.230
HW Code: 224352
Record Add: 01/24/2022
Record Upd: 07/16/2024
Updated By: CXMAYCOC
Site Description: Location: The 0.23-acre site is located at 673 Livonia Avenue in Brooklyn, Kings County, NY in an urban area. Site Features: The site currently consists of a vacant, 8,300 square foot, one-story, slab-on-grade, concrete warehouse building with a concrete driveway to the north. A former UST below the northwest corner of the driveway was closed and removed sometime prior to 1991. Current Zoning and Land Use: The site is currently zoned as R6 (medium-density residence district) with a C2-3 (local retail/service district) overlay and is surrounded by other residential and retail commercial parcels. The site is bound to the north by Dumont Avenue, to the east by Wyona Street, to the south by Livonia Avenue as well as the MTA 2 and 3 aboveground subway lines, and to the west by Vermont Street. Past Use of the Site: The current building was constructed between 1954 1966 and was most recently occupied by Fleetwood Cabinet Co for furniture manufacturing and spray-painting operations from 1985 2017. Historical on-site uses include a knitting mill, textile processing, and dry-cleaning. Site reconnaissance during June 2021 observed a vent pipe reportedly connected to an out-of-service 2,500-gallon #2 fuel oil UST under the northern driveway. An empty 55-gallon drum and two active 250-gallon aboveground storage tanks were observed inside the building as well as evidence of spray-painting on the walls and floor slab in the southeast corner. Site Geology and Hydrogeology: Sub-surface samples collected in June 2021 identified soil consisting of red-brown sand and brown sandy silt. Groundwater was encountered at approximately 22.5 feet below grade and flows at a slight gradient (0.001 ft/ft) to the southeast.
Env Problem: Nature and Extent of Contamination: SOIL No VOCs were detected at concentrations exceeding the applicable protection of groundwater soil cleanup objectives (PGSCO). PCE was detected at a maximum concentration of 0.17 parts per million (ppm) compared to the PGSCO

DRAFT

673 LIVONIA AVENUE (Continued) **S129982655**

of 1.3 ppm, and TCE at a maximum concentration of 0.11 ppm (PGSCO is 0.47 ppm). One SVOC, benzo(a)pyrene, was identified as exceeding the restricted commercial (RC) SCO of 1 ppm at a maximum of 1.69 ppm. One RCRA metal, barium, was detected at a maximum concentration of 723 ppm (RCSCO is 400 ppm). GROUNDWATER PCE was detected at concentrations exceeding the applicable Ambient Water Quality Standard (AWQS) of 5 parts per billion (ppb) at a maximum concentration of 8.98 ppb. Chloroform was detected at a maximum of 28 ppb (AWQS is 7 ppb). Detected TCE concentrations did not exceed the AWQS of 5 ppb at a maximum of 0.95 ppb. PFOS was detected at a maximum concertation of 0.0747 ppb (AWQS is 0.01 ppb) and PFOA at a maximum of 0.0635 ppb (AWQS is 0.01 ppb). SOIL VAPOR PCE and TCE were detected at maximum concentrations of 180,000 micrograms per cubic meter (ug/m3) and 52,700 ug/m3, respectively. Additionally, the degradation compounds cis-1,2-dichloroethene and trans-1,2-dicholorethene were detected at maximum concentrations of 16,500 ug/m3 and 1,870 ug/m3. Several petroleum-related VOCs were also detected, including benzene (max. 94 ug/m3), toluene (max. 1,800 ug/m3), ethylbenzene (max. 170 ug/m3), and total xylene (max. 800 ug/m3). --- Significant Threat: No evaluation has been made thus far to determine if the contaminants represent a significant environmental threat.

Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	ElderServe Health, Inc.
Owner Address:	80 West 225th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10463
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

DRAFT

673 LIVONIA AVENUE (Continued) **S129982655**

NYC LAND USE:

Name:	Not reported
Address:	673 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6653147
Longitude:	-73.8919023
Type Of Ownership Code:	X
Owner Name:	ELDERSERVE HEALTH, INC.
Borough:	BK
Tax Block:	3808
Tax Lot:	1
Community District:	305
Census Tract 2020:	3112600
Census Block 2020:	31126001001
Census Tract 2010:	1126
Census Block 2010:	1001
School District:	19
City Council District:	42
Fire Company:	L103
Police Precinct:	75
Health Center District:	33
Health Area:	6300
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	4D
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-3
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	F5: Factory And Industrial Buildings - Light Manufacturing
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	8300
Commercial Floor Area:	8300
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	8300
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	83.0000000

DRAFT

673 LIVONIA AVENUE (Continued) **S129982655**

Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	81000.00000
Assessed Total Value:	403200.00000
Exempt Total Value:	403200.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.83000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3038080001.00000000
Condominium Number:	Not reported
Census Tract 2:	1126
X Coordinate:	1014239
Y Coordinate:	181687
Zoning Map #:	17d
Zoning Map Code:	Not reported
Sanborn Map #:	316 032
Tax Map #:	31207
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AY326 **869 STANLEY AVENUE** **NY SHWS** **S131354999**
SSE **869 STANLEY AVENUE** **NY NYC LAND USE** **N/A**
1/2-1 **BROOKLYN, NY 11208**
0.945 mi.
4991 ft. **Site 1 of 2 in cluster AY**

Relative:
Lower

Actual:
14 ft.

SHWS:

Name:	869 STANLEY AVENUE
Address:	869 STANLEY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Program:	HW
Site Code:	651358
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	0.753
HW Code:	224394
Record Add:	04/21/2023
Record Upd:	12/10/2024
Updated By:	AMSERVIS
Site Description:	Location: The site is located at 869 Stanley Avenue, Brooklyn, NY.

DRAFT

869 STANLEY AVENUE (Continued) **S131354999**

Site Features: The site is covered by a commercial/industrial building. Surrounding properties include a railyard across the street to the west, commercial/industrial buildings across the street to the south and east, and an Amazon Flex courier facility to the north. Current Zoning and Land Use: The site is in a district zoned M1-1. M1-1 zoning is identified as light manufacturing (high performance) which may be developed as manufacturing, commercial, or community facility. The building on site is currently used for commercial/industrial purposes and is currently occupied by an ambulance center, Seniorcare Emergency Medical Services. Past Use of Site: Specific past use of the site is unknown at this time. The larger neighborhood has an industrial history. Site Geology and Hydrogeology: The site is located over the Long Island aquifer system. Subsurface geology is comprised of historic fill material overlying native sands. Groundwater at a nearby site is approximately 15 feet below ground surface. Groundwater flow in the neighborhood has been observed flowing in a southwesterly direction.

Env Problem: Groundwater and soil vapor sampling was conducted in the surrounding area along Linwood and Stanley Avenues as part of two plume track down investigations related to site Nos. 224250 and 224301. A shallow groundwater well, HRP-MW-22S, located immediately adjacent and downgradient from 869 Stanley Avenue, had elevated levels of total chlorinated volatile organic compounds (CVOCs); the total COVCs in HRP-MW-22S were 115,990 parts per billion (ppb). Detections in a second well (HRP-MW-20S) located approximately 200ft downgradient from HRP-MW-22S had a total CVOC level of 5,539 ppb. Soil vapor intrusion sampling found elevated vapor levels for PCE (19,000 ug/m^3), TCE (23,000 ug/m^3), and DCE (400 ug/m^3) under the building immediately downgradient of the site (Sample location 4384-1). NYSDOH matrices indicate mitigation is required for the downgradient building. The basis for this proposal is observed concentrations of total CVOCs in shallow groundwater and soil vapor immediately adjacent and downgradient from the site, specifically trichloroethene. Analytical data strongly suggests the disposal of hazardous waste on the site.

Health Problem: Direct contact with contaminants in the soil is unlikely because the site is covered with building foundation, pavement, or sidewalk. Persons who dig below the ground surface may come into contact with contaminants in subsurface soil. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in currently occupied on-site buildings, or buildings that are occupied in the future. A sub-slab depressurization system (system that ventilates / removes the air beneath a building) has been installed at an off-site structure to address soil vapor intrusion. The potential for people to contact site-related contamination will continue to be evaluated on and off-site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported

869 STANLEY AVENUE (Continued) **S131354999**

Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Isidor Friedenberg
Owner Company:	SC Brooklyn Land LLC
Owner Address:	2 Cara Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Suffern, NY 10901
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	869 STANLEY AVENUE
City,State,Zip:	BROOKLYN, NY 11208
Latitude:	40.6626785
Longitude:	-73.8769878
Type Of Ownership Code:	Not reported
Owner Name:	SC BROOKLYN LAND LLC
Borough:	BK
Tax Block:	4362
Tax Lot:	1
Community District:	305
Census Tract 2020:	3111600
Census Block 2020:	31116002013
Census Tract 2010:	1116
Census Block 2010:	2007
School District:	19
City Council District:	42
Fire Company:	E225
Police Precinct:	75
Health Center District:	33
Health Area:	6420
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	3E
Zoning District 1:	M1-1: Manufacturing Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported

DRAFT

869 STANLEY AVENUE (Continued) **S131354999**

Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	E1: Warehouses - Fireproof
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	30150
Total Building Floor Area:	32784
Commercial Floor Area:	32784
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	32784
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	200.0000000
Lot Depth:	151.0000000
Building Frontage:	200.0000000
Building Depth:	151.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	271350.00000
Assessed Total Value:	1819350.00000
Exempt Total Value:	0.00000
Year Built:	1957
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.09000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	1.00000000000
Maximum Allowable Community Facility Far:	2.40000000000
Boro Code:	3
Borough, Tax Block and Lot:	3043620001.00000000
Condominium Number:	Not reported
Census Tract 2:	1116
X Coordinate:	1018378
Y Coordinate:	180732
Zoning Map #:	17d
Zoning Map Code:	Not reported
Sanborn Map #:	308 051
Tax Map #:	31402
E-designation Number:	Not reported

DRAFT

869 STANLEY AVENUE (Continued) **S131354999**

Apportionment BBL:	3043620001.00000000
Apportionment Date:	09/03/2020
Pluto DTM Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v4.1
Changed By DCP:	Not reported

AY327 **LINWOOD STREET GW** **NY SHWS** **S125465259**
South **LINWOOD ST BETWEEN WORTMAN ST AND STANLEY AVE** **N/A**
1/2-1 **BROOKLYN, NY 11208**
0.961 mi.
5076 ft. **Site 2 of 2 in cluster AY**

Relative: **Lower**
Actual: **14 ft.**

SHWS:

Name:	LINWOOD STREET GW
Address:	LINWOOD ST BETWEEN WORTMAN ST AND STANLEY AVE
City,State,Zip:	BROOKLYN, NY 11208
Program:	HW
Site Code:	594129
Classification:	P
Region:	2
Acres:	Not reported
HW Code:	224301
Record Add:	09/12/2019
Record Upd:	05/10/2024
Updated By:	HMDUDEK
Site Description:	Location: The site is on the eastern side of Linwood Street between Wortman Street and Stanley Street, Brooklyn, NY 11208. The full extent of the site is unknown. Site Features: The full extent of the site has yet to be identified. Current Zoning and Land Use: This plume track down is being conducted in an area that is currently and historically an industrial and commercial area. The full extent of the site has yet to be identified and the specific zoning and land use of the site are unknown. Past Use of Site: The full extent of the site has yet to be identified; the surrounding neighborhood has a history of industrial use. Site Geology and Hydrogeology: The site is located over the Long Island aquifer system, which underlies all of Nassau, Suffolk, Kings (Brooklyn), and Queens Counties. The unconsolidated aquifer formations form a southward-dipping wedge that attains a maximum thickness in Kings County about 800 feet in the southeast area of Brooklyn. Overlying bedrock is the Lloyd, Magothy, Jameco, and Upper Glacial aquifer systems. Subsurface geology is comprised of historic fill material overlying native sands. Groundwater at a nearby site is approximately 15 feet below ground surface. Groundwater flow in the neighborhood has been observed flowing in a southwesterly direction.
Env Problem:	During the investigation for Brownfield Cleanup Program site C224139, monitoring well 19 (MW-19) was installed up gradient of the site. The ground-water from the well was sampled and returned high levels of PCE (2,600 g/L), TCE (2,100 g/L), and Cis-1,2-Dichloroethene (35 g/L). Additional data need to be collected in order to determine the extent of the site and the nature of the plume.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported

DRAFT

LINWOOD STREET GW (Continued) **S125465259**

Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

DRAFT

Count: 3 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113922095	UNION STATION (CITIZENS BRANCH)	ATLANTIC AVE, ASHFORD ST, LIBE	11207	NY VCP
BROOKLYN	S113922098	BELMONT STATION	BELMONT, WILLIAMS, ALABAMA & S	11207	NY VCP
BROOKLYN	S108146271	SPRING CREEK/GATEWAY ESTATES	FOUNTAIN AVE	11208	NY HSWDS

DRAFT

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

DRAFT

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/20/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

DRAFT

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

DRAFT

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 07/29/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/19/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/15/2025
Next Scheduled EDR Contact: 12/02/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/19/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/15/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

DRAFT

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/10/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 02/20/2025
Date Data Arrived at EDR: 03/20/2025
Date Made Active in Reports: 06/09/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

DRAFT

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/03/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/05/2025
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/04/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

DRAFT

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 04/23/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 1

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/24/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

DRAFT

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/15/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

DRAFT

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/08/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

DRAFT

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 12/06/2024
Date Data Arrived at EDR: 12/11/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 82
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 06/10/2025
Date Made Active in Reports: 09/08/2025
Number of Days to Update: 90
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

DRAFT

Date of Government Version: 06/01/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 84

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/03/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

DRAFT

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024
Date Data Arrived at EDR: 09/11/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/04/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 09/02/2025
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 02/20/2025
Date Data Arrived at EDR: 03/20/2025
Date Made Active in Reports: 06/09/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/15/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/08/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

DRAFT

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

DRAFT

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 04/25/2025
Date Data Arrived at EDR: 04/25/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 74
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 07/28/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/11/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/03/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/05/2025
Number of Days to Update: 1
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/04/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

DRAFT

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 07/23/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 6

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 07/23/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/07/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

DRAFT

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

DRAFT

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/14/2025
Date Data Arrived at EDR: 04/15/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 84

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/14/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/29/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 8

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Annually

RMP: Risk Management Plans

DRAFT

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/05/2025
Date Data Arrived at EDR: 04/11/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 28

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 100

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/02/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Quarterly

DRAFT

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 27
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 07/08/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 08/28/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

DRAFT

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/22/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 86

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 05/02/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 76

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/24/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Biennially

DRAFT

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/28/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

DRAFT

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 04/01/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/18/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 84

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

DRAFT

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 05/28/2025
Date Data Arrived at EDR: 05/28/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 6

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 08/26/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/22/2025
Date Data Arrived at EDR: 05/05/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 16

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/12/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/22/2025
Date Data Arrived at EDR: 06/25/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 02/14/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 84

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/02/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

DRAFT

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/13/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 77

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

DRAFT

Date of Government Version: 03/23/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/15/2024
Date Data Arrived at EDR: 03/06/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 89

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

DRAFT

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 06/26/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: No Update Planned

DRAFT

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data
The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 04/13/2025
Date Data Arrived at EDR: 04/15/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database
US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

UST FINDER: UST Finder Database
EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

E MANIFEST: Hazardous Waste Electronic Manifest System
EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List
A list of records included in the Environmental Remediation database whose material is listed as Perfluorooctanoic Acid or Perfluorooctane Sulfonic Acid.

DRAFT

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 08/10/2023
Date Made Active in Reports: 10/25/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 04/10/2025
Date Data Arrived at EDR: 04/17/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 02/24/2025
Date Data Arrived at EDR: 03/20/2025
Date Made Active in Reports: 06/09/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

DRAFT

Date of Government Version: 05/30/2025
Date Data Arrived at EDR: 06/10/2025
Date Made Active in Reports: 09/08/2025
Number of Days to Update: 90

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Semi-Annually

FIN ASSURANCE 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 03/26/2025
Date Data Arrived at EDR: 03/27/2025
Date Made Active in Reports: 06/18/2025
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

FIN ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 04/16/2025
Date Data Arrived at EDR: 04/29/2025
Date Made Active in Reports: 07/18/2025
Number of Days to Update: 80

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

DRAFT

Date of Government Version: 04/28/2025
Date Data Arrived at EDR: 04/29/2025
Date Made Active in Reports: 07/21/2025
Number of Days to Update: 83

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/09/2025
Date Data Arrived at EDR: 07/15/2025
Date Made Active in Reports: 07/30/2025
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 05/26/2025
Date Data Arrived at EDR: 05/27/2025
Date Made Active in Reports: 08/21/2025
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 04/01/2025
Date Data Arrived at EDR: 04/08/2025
Date Made Active in Reports: 06/27/2025
Number of Days to Update: 80

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/07/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

DRAFT

NYC LAND USE: New York City Land Use Information
Land use colors

Date of Government Version: 02/21/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/28/2025
Number of Days to Update: 78

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

MGP: Manufactured Gas Plants Listing
From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

Date of Government Version: 02/28/2025
Date Data Arrived at EDR: 03/04/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

ILI: New York State Inactive Landfill Initiative
A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/29/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8671
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

NYC OER: OER Cleanup Sites Listing
Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Date of Government Version: 06/01/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 84

Source: Office of Environmental Remediation
Telephone: 212-788-8841
Last EDR Contact: 09/03/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DRAFT

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

DRAFT

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

DRAFT

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/19/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/19/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

DRAFT

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 03/28/2025
Date Data Arrived at EDR: 05/08/2025
Date Made Active in Reports: 07/24/2025
Number of Days to Update: 77

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 03/28/2025
Date Data Arrived at EDR: 05/08/2025
Date Made Active in Reports: 07/24/2025
Number of Days to Update: 77

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/04/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/21/2025
Number of Days to Update: 76

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/23/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Annually

DRAFT

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/06/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/02/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

DRAFT

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

DRAFT

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

98-114 BERRIMAN STREET DEVELOPMENT
98 BERRIMAN STREET
BROOKLYN, NY 11208

TARGET PROPERTY COORDINATES

Latitude (North):	40.67609 - 40° 40' 33.92''
Longitude (West):	73.880628 - 73° 52' 50.26''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	594603.7
UTM Y (Meters):	4503192.0
Elevation:	32 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019
East Map:	14105978 JAMAICA, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 32 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970065B	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
3604970236F	FEMA FIRM Flood data
3604970075C	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

DRAFT

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Quaternary
Series:	Pleistocene
Code:	Qp *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000828182	1/4 - 1/2 Mile ESE
2	USGS40000828360	1/4 - 1/2 Mile NW
4	USGS40000828426	1/4 - 1/2 Mile NE
A5	USGS40000828091	1/2 - 1 Mile SE
A7	USGS40000828073	1/2 - 1 Mile SE
11	USGS40000828531	1/2 - 1 Mile North
C12	USGS40000828318	1/2 - 1 Mile East
C13	USGS40000828319	1/2 - 1 Mile East
14	USGS40000827932	1/2 - 1 Mile SE
D15	USGS40000828476	1/2 - 1 Mile NE
D16	USGS40000828475	1/2 - 1 Mile NE
D17	USGS40000828486	1/2 - 1 Mile NE
D18	USGS40000828485	1/2 - 1 Mile NE
21	USGS40000828290	1/2 - 1 Mile West
22	USGS40000828135	1/2 - 1 Mile WSW
F23	USGS40000828148	1/2 - 1 Mile East
F24	USGS40000828149	1/2 - 1 Mile East
25	USGS40000828169	1/2 - 1 Mile West
26	USGS40000828517	1/2 - 1 Mile NE
27	USGS40000828433	1/2 - 1 Mile ENE
G28	USGS40000827670	1/2 - 1 Mile SSW
G29	USGS40000827671	1/2 - 1 Mile SSW
30	USGS40000827849	1/2 - 1 Mile SW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
3	NYREG1200061480	1/4 - 1/2 Mile NNE
6	NYREG1200061374	1/2 - 1 Mile ESE
8	NYREG1200061405	1/2 - 1 Mile WSW
B9	NYREG1200061346	1/2 - 1 Mile West
B10	NYREG1200061347	1/2 - 1 Mile West
E19	NYREG1200061476	1/2 - 1 Mile SE
E20	NYREG1200061510	1/2 - 1 Mile SE

DRAFT

PHYSICAL SETTING SOURCE MAP - 08102930.2r



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	98-114 Berriman Street Development	CLIENT:	Haley & Aldrich, Inc.
ADDRESS:	98 Berriman Street Brooklyn NY 11208	CONTACT:	Kaitlyn Moses
LAT/LONG:	40.67609 / 73.880628	INQUIRY #:	08102930.2r
		DATE:	September 09, 2025 4:02 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
ESE **FED USGS** **USGS40000828182**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1054. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	90	Well Hole Depth Units:	ft

2
NW **FED USGS** **USGS40000828360**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1198. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	53
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	282	Level reading date:	1968-11-06
Feet below surface:	Not Reported	Feet to sea level:	3.51
Note:	Not Reported		

Level reading date:	1968-04-30	Feet below surface:	Not Reported
Feet to sea level:	3.43	Note:	Not Reported
Level reading date:	1967-11-09	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	2.25	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	1.92	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	2.23	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	2.60	Note:	Not Reported
Level reading date:	1965-09-06	Feet below surface:	Not Reported
Feet to sea level:	2.74	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.97	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	3.25	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	3.78	Note:	Not Reported
Level reading date:	1962-04-27	Feet below surface:	Not Reported
Feet to sea level:	4.11	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.25	Note:	Not Reported
Level reading date:	1961-01-05	Feet below surface:	Not Reported
Feet to sea level:	3.29	Note:	Not Reported
Level reading date:	1960-07-18	Feet below surface:	Not Reported
Feet to sea level:	2.65	Note:	Not Reported
Level reading date:	1957-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.64	Note:	Not Reported
Level reading date:	1956-12-27	Feet below surface:	Not Reported
Feet to sea level:	2.86	Note:	Not Reported
Level reading date:	1956-01-20	Feet below surface:	Not Reported
Feet to sea level:	2.70	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.75	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.50	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.79	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	2.05	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	2.13	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	2.16	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.06	Note:	Not Reported
Level reading date:	1953-10-10	Feet below surface:	Not Reported
Feet to sea level:	2.20	Note:	Not Reported

DRAFT

Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	2.26	Note:	Not Reported
Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	1.96	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	2.01	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	1.55	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	1.47	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	1.58	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	1.61	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.60	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	1.53	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	0.91	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.70	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	0.42	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	0.24	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	0.07	Note:	Not Reported

DRAFT

Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	0.20	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-0.28	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.50	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.48	Note:	Not Reported
Level reading date:	1951-07-25	Feet below surface:	Not Reported
Feet to sea level:	-0.62	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-0.60	Note:	Not Reported
Level reading date:	1951-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.82	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-1.08	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-1.22	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-1.33	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-1.23	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-1.16	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-1.12	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.98	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.99	Note:	Not Reported

DRAFT

Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-1.00	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-1.08	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-1.37	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-1.16	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-1.28	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-1.14	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-1.13	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-1.20	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	-1.50	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-1.80	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-1.97	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-2.23	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-2.55	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-2.65	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-2.64	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-2.75	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-2.64	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported

DRAFT

Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.46	Note:	Not Reported
Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-3.67	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-4.02	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-4.32	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-4.50	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1948-01-08	Feet below surface:	Not Reported
Feet to sea level:	-4.88	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-5.10	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-5.19	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-5.34	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-5.37	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-5.30	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-5.24	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-5.13	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported

DRAFT

Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-5.05	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.01	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-5.15	Note:	Not Reported
Level reading date:	1947-02-05	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-4.77	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-4.67	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-4.57	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-4.33	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-4.34	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-4.43	Note:	Not Reported
Level reading date:	1946-06-19	Feet below surface:	Not Reported
Feet to sea level:	-4.55	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1946-03-04	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1946-02-07	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.69	Note:	Not Reported

DRAFT

Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-4.74	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-4.70	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-4.53	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-4.54	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-4.56	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-4.62	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-4.57	Note:	Not Reported
Level reading date:	1945-04-05	Feet below surface:	Not Reported
Feet to sea level:	-4.63	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-4.50	Note:	Not Reported
Level reading date:	1945-01-13	Feet below surface:	Not Reported
Feet to sea level:	-4.54	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1944-11-03	Feet below surface:	Not Reported
Feet to sea level:	-4.59	Note:	Not Reported
Level reading date:	1944-10-05	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-4.79	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-4.71	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-4.68	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-4.79	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-4.93	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported

DRAFT

Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-5.16	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-5.17	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-5.22	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-5.35	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-5.40	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.30	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-5.35	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-5.39	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.48	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-5.62	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-5.80	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-5.97	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-6.13	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-6.29	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-6.32	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-6.36	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-6.38	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-6.45	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-6.45	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-6.48	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-6.52	Note:	Not Reported

DRAFT

Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-6.61	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-6.70	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-6.83	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-6.88	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-6.94	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-7.02	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-7.10	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-7.19	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-7.28	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-7.56	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-7.65	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-7.77	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-7.84	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported

DRAFT

Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-8.30	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-8.32	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-8.35	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-8.39	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.45	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-8.35	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-8.17	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported

DRAFT

Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-7.97	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-7.81	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-7.75	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-7.66	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-7.60	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-7.55	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-7.44	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-7.40	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-7.35	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-7.30	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-7.20	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-7.16	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-7.13	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-7.06	Note:	Not Reported

DRAFT

Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-7.11	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-7.04	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-6.99	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-6.93	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.86	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-6.78	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-6.72	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-6.49	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-6.40	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-6.21	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-6.14	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-6.03	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-5.93	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-5.86	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-5.79	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-5.68	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-5.63	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported

DRAFT

Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.49	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-5.51	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-5.58	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-5.64	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-5.77	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-5.83	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-5.89	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-5.96	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-6.00	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-6.16	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-6.23	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-6.32	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-6.52	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-6.64	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-6.89	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-7.03	Note:	Not Reported

DRAFT

Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported

3
NNE **NY WELLS** **NYREG1200061480**
1/4 - 1/2 Mile
Higher

WELLS REG 1:

Well Number:	K003503	Well Type:	Commercial/Industrial Supply
Owner:	Maggies Para Transit Corporation	Diameter (in):	4
Well Depth (ft):	80	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	40

4
NE **FED USGS** **USGS40000828426**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 539. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	60
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	403	Level reading date:	1960-03-30
Feet below surface:	Not Reported	Feet to sea level:	1.45
Note:	Not Reported		

Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1959-07-13	Feet below surface:	Not Reported
Feet to sea level:	1.25	Note:	Not Reported
Level reading date:	1959-03-20	Feet below surface:	Not Reported
Feet to sea level:	1.35	Note:	Not Reported
Level reading date:	1958-07-23	Feet below surface:	Not Reported
Feet to sea level:	2.29	Note:	Not Reported
Level reading date:	1957-12-23	Feet below surface:	Not Reported
Feet to sea level:	0.62	Note:	Not Reported
Level reading date:	1957-09-25	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1957-03-28	Feet below surface:	Not Reported
Feet to sea level:	2.03	Note:	Not Reported

DRAFT

Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	2.05	Note:	Not Reported
Level reading date:	1956-11-30	Feet below surface:	Not Reported
Feet to sea level:	2.03	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	1.74	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	1.89	Note:	Not Reported
Level reading date:	1956-07-03	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported
Level reading date:	1956-06-04	Feet below surface:	Not Reported
Feet to sea level:	2.15	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	2.17	Note:	Not Reported
Level reading date:	1956-03-06	Feet below surface:	Not Reported
Feet to sea level:	1.92	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	2.20	Note:	Not Reported
Level reading date:	1955-11-07	Feet below surface:	Not Reported
Feet to sea level:	2.30	Note:	Not Reported
Level reading date:	1955-10-05	Feet below surface:	Not Reported
Feet to sea level:	2.21	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	1.55	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.73	Note:	Not Reported
Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	1.94	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1955-01-24	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported

DRAFT

Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1954-12-01	Feet below surface:	Not Reported
Feet to sea level:	1.14	Note:	Not Reported
Level reading date:	1954-10-29	Feet below surface:	Not Reported
Feet to sea level:	1.08	Note:	Not Reported
Level reading date:	1954-09-28	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1954-08-23	Feet below surface:	Not Reported
Feet to sea level:	0.76	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	0.79	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	0.89	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	0.86	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.87	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.27	Note:	Not Reported
Level reading date:	1954-02-24	Feet below surface:	Not Reported
Feet to sea level:	1.63	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	1.77	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	1.80	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1953-10-26	Feet below surface:	Not Reported
Feet to sea level:	1.73	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	1.83	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1953-07-30	Feet below surface:	Not Reported
Feet to sea level:	1.62	Note:	Not Reported
Level reading date:	1953-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	1.46	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	1.60	Note:	Not Reported

DRAFT

Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	1.44	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	1.57	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	1.51	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.39	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	1.26	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	1.44	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	1.56	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.71	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	1.68	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.61	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.44	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.25	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	0.80	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	0.59	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	0.24	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	0.18	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-0.03	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.16	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.04	Note:	Not Reported
Level reading date:	1951-07-25	Feet below surface:	Not Reported
Feet to sea level:	-0.15	Note:	Not Reported

DRAFT

Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	-0.06	Note:	Not Reported
Level reading date:	1951-05-31	Feet below surface:	Not Reported
Feet to sea level:	-0.12	Note:	Not Reported
Level reading date:	1951-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.25	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-0.71	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-0.82	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-0.85	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-0.76	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-0.88	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.87	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.74	Note:	Not Reported
Level reading date:	1950-07-25	Feet below surface:	Not Reported
Feet to sea level:	-0.61	Note:	Not Reported
Level reading date:	1950-06-27	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.46	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.42	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.44	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-0.55	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-0.72	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-0.66	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported

DRAFT

Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-0.50	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-0.51	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-0.55	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-0.57	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.86	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-0.96	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.20	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-1.41	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-1.66	Note:	Not Reported
Level reading date:	1948-12-03	Feet below surface:	Not Reported
Feet to sea level:	-1.61	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-1.53	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-1.40	Note:	Not Reported
Level reading date:	1948-09-01	Feet below surface:	Not Reported
Feet to sea level:	-1.10	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	-1.51	Note:	Not Reported
Level reading date:	1948-07-02	Feet below surface:	Not Reported
Feet to sea level:	-2.02	Note:	Not Reported
Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-2.16	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.40	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-2.71	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-2.93	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-3.14	Note:	Not Reported

DRAFT

Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-3.28	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-3.33	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-3.42	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-3.50	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-3.43	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-3.50	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-3.43	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-3.37	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-3.30	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-3.28	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-3.23	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-3.15	Note:	Not Reported
Level reading date:	1947-07-03	Feet below surface:	Not Reported
Feet to sea level:	-3.15	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-3.15	Note:	Not Reported
Level reading date:	1947-05-26	Feet below surface:	Not Reported
Feet to sea level:	-3.15	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-3.34	Note:	Not Reported

DRAFT

Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-3.26	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-3.17	Note:	Not Reported
Level reading date:	1946-12-27	Feet below surface:	Not Reported
Feet to sea level:	-2.81	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-2.78	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-2.61	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-2.50	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-2.32	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.20	Note:	Not Reported
Level reading date:	1946-07-05	Feet below surface:	Not Reported
Feet to sea level:	-2.22	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-2.78	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-2.76	Note:	Not Reported
Level reading date:	1946-03-04	Feet below surface:	Not Reported
Feet to sea level:	-2.68	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-2.63	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-2.73	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-2.30	Note:	Not Reported
Level reading date:	1945-07-04	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported

DRAFT

Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-2.57	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.61	Note:	Not Reported
Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-2.57	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-2.48	Note:	Not Reported
Level reading date:	1945-02-06	Feet below surface:	Not Reported
Feet to sea level:	-2.54	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-2.50	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-2.38	Note:	Not Reported
Level reading date:	1944-10-05	Feet below surface:	Not Reported
Feet to sea level:	-2.34	Note:	Not Reported
Level reading date:	1944-09-01	Feet below surface:	Not Reported
Feet to sea level:	-2.65	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported
Level reading date:	1944-07-03	Feet below surface:	Not Reported
Feet to sea level:	-2.40	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported
Level reading date:	1944-04-25	Feet below surface:	Not Reported
Feet to sea level:	-2.67	Note:	Not Reported
Level reading date:	1944-03-29	Feet below surface:	Not Reported
Feet to sea level:	-2.90	Note:	Not Reported
Level reading date:	1944-03-06	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-2.98	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-3.21	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-3.14	Note:	Not Reported

DRAFT

Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-3.20	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-3.37	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-3.66	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-3.84	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-4.03	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-4.23	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-4.32	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-4.34	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-4.29	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-4.46	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-4.45	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-4.51	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-4.54	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-4.58	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-4.64	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-4.69	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-4.76	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-4.85	Note:	Not Reported

DRAFT

Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-4.88	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-5.09	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-5.19	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-5.35	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-5.75	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-5.64	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-5.77	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-5.96	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-6.24	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-6.55	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-6.47	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-6.70	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-6.92	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-7.15	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-7.41	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-7.55	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-7.66	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-7.75	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported

DRAFT

Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-7.87	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-8.03	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-8.18	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.24	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-8.28	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-8.19	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-8.10	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-8.06	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-7.95	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-7.88	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-7.78	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported

DRAFT

Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-7.59	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-7.53	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-7.41	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-7.36	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-7.28	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-7.21	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-7.10	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-6.92	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-6.97	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-6.80	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-6.78	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-6.93	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-6.83	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-6.78	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-6.46	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-6.35	Note:	Not Reported

DRAFT

Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-6.20	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-6.05	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-5.76	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-5.56	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-5.14	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-4.96	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-4.51	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-4.34	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-4.09	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-3.88	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-3.71	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-3.71	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-3.77	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-3.84	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-3.90	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-3.98	Note:	Not Reported

DRAFT

Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-3.97	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-3.95	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-4.04	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-4.12	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-4.18	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-4.28	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-4.40	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-4.48	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-4.63	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-4.77	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-4.87	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-5.01	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-5.22	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-5.47	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-5.74	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-5.93	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-6.34	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-6.63	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-6.88	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-7.18	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported

DRAFT

Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-7.12	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-7.05	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-6.96	Note:	Not Reported
Level reading date:	1940-07-27	Feet below surface:	Not Reported
Feet to sea level:	-6.86	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-6.79	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-6.82	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-6.80	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-6.74	Note:	Not Reported
Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-6.69	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-6.63	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-6.51	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-6.44	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-6.37	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-6.24	Note:	Not Reported

DRAFT

Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-6.17	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-6.07	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-5.99	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-6.02	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-5.94	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-5.79	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-5.69	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-5.62	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-5.54	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-5.50	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-5.50	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-5.46	Note:	Not Reported
Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-5.48	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-5.50	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-5.57	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-5.55	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-5.49	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-5.41	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-5.55	Note:	Not Reported

DRAFT

Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-5.63	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-5.62	Note:	Not Reported
Level reading date:	1939-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.67	Note:	Not Reported
Level reading date:	1939-08-03	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1939-05-29	Feet below surface:	Not Reported
Feet to sea level:	-1.80	Note:	Not Reported
Level reading date:	1939-03-27	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1939-02-21	Feet below surface:	Not Reported
Feet to sea level:	-0.78	Note:	Not Reported
Level reading date:	1938-12-27	Feet below surface:	Not Reported
Feet to sea level:	-0.83	Note:	Not Reported
Level reading date:	1938-11-08	Feet below surface:	Not Reported
Feet to sea level:	-0.77	Note:	Not Reported
Level reading date:	1938-09-08	Feet below surface:	Not Reported
Feet to sea level:	-1.09	Note:	Not Reported
Level reading date:	1938-06-16	Feet below surface:	Not Reported
Feet to sea level:	-1.79	Note:	Not Reported
Level reading date:	1938-05-09	Feet below surface:	Not Reported
Feet to sea level:	-1.80	Note:	Not Reported
Level reading date:	1938-04-04	Feet below surface:	Not Reported
Feet to sea level:	-1.82	Note:	Not Reported
Level reading date:	1938-02-21	Feet below surface:	Not Reported
Feet to sea level:	-1.84	Note:	Not Reported
Level reading date:	1938-01-06	Feet below surface:	Not Reported
Feet to sea level:	-1.97	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-2.25	Note:	Not Reported
Level reading date:	1937-09-23	Feet below surface:	Not Reported
Feet to sea level:	-3.33	Note:	Not Reported
Level reading date:	1937-08-05	Feet below surface:	Not Reported
Feet to sea level:	-2.31	Note:	Not Reported
Level reading date:	1937-06-15	Feet below surface:	Not Reported
Feet to sea level:	-1.93	Note:	Not Reported
Level reading date:	1937-03-23	Feet below surface:	Not Reported
Feet to sea level:	-2.13	Note:	Not Reported
Level reading date:	1937-02-02	Feet below surface:	Not Reported
Feet to sea level:	-2.34	Note:	Not Reported

DRAFT

Level reading date:	1936-12-29	Feet below surface:	Not Reported
Feet to sea level:	-2.86	Note:	Not Reported
Level reading date:	1936-09-24	Feet below surface:	Not Reported
Feet to sea level:	-4.09	Note:	Not Reported
Level reading date:	1936-07-21	Feet below surface:	Not Reported
Feet to sea level:	-3.28	Note:	Not Reported
Level reading date:	1936-06-11	Feet below surface:	Not Reported
Feet to sea level:	-2.38	Note:	Not Reported
Level reading date:	1936-04-20	Feet below surface:	Not Reported
Feet to sea level:	-1.67	Note:	Not Reported
Level reading date:	1936-03-16	Feet below surface:	Not Reported
Feet to sea level:	-2.40	Note:	Not Reported
Level reading date:	1935-12-11	Feet below surface:	Not Reported
Feet to sea level:	-2.07	Note:	Not Reported
Level reading date:	1935-10-24	Feet below surface:	Not Reported
Feet to sea level:	-2.07	Note:	Not Reported
Level reading date:	1935-09-13	Feet below surface:	Not Reported
Feet to sea level:	-2.73	Note:	Not Reported
Level reading date:	1935-07-01	Feet below surface:	Not Reported
Feet to sea level:	-1.71	Note:	Not Reported
Level reading date:	1935-05-28	Feet below surface:	Not Reported
Feet to sea level:	-0.20	Note:	Not Reported
Level reading date:	1935-04-01	Feet below surface:	Not Reported
Feet to sea level:	-0.28	Note:	Not Reported
Level reading date:	1935-01-02	Feet below surface:	Not Reported
Feet to sea level:	0.13	Note:	Not Reported
Level reading date:	1934-11-05	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported
Level reading date:	1934-10-18	Feet below surface:	Not Reported
Feet to sea level:	-0.46	Note:	Not Reported
Level reading date:	1934-09-20	Feet below surface:	Not Reported
Feet to sea level:	-1.99	Note:	Not Reported
Level reading date:	1934-08-29	Feet below surface:	Not Reported
Feet to sea level:	-2.27	Note:	Not Reported
Level reading date:	1934-06-14	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported
Level reading date:	1934-04-17	Feet below surface:	Not Reported
Feet to sea level:	-0.13	Note:	Not Reported
Level reading date:	1934-03-22	Feet below surface:	Not Reported
Feet to sea level:	-0.30	Note:	Not Reported
Level reading date:	1934-01-08	Feet below surface:	Not Reported
Feet to sea level:	0.11	Note:	Not Reported

DRAFT

Level reading date:	1933-12-12	Feet below surface:	Not Reported
Feet to sea level:	0.21	Note:	Not Reported
Level reading date:	1933-11-21	Feet below surface:	Not Reported
Feet to sea level:	0.02	Note:	Not Reported
Level reading date:	1933-08-29	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported
Level reading date:	1933-07-25	Feet below surface:	Not Reported
Feet to sea level:	-1.09	Note:	Not Reported
Level reading date:	1933-06-28	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1933-05-23	Feet below surface:	Not Reported
Feet to sea level:	-0.95	Note:	Not Reported
Level reading date:	1933-04-20	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1933-02-28	Feet below surface:	Not Reported
Feet to sea level:	-0.72	Note:	Not Reported
Level reading date:	1933-01-20	Feet below surface:	Not Reported
Feet to sea level:	-0.99	Note:	Not Reported
Level reading date:	1932-11-21	Feet below surface:	Not Reported
Feet to sea level:	-1.04	Note:	Not Reported
Level reading date:	1932-10-17	Feet below surface:	Not Reported
Feet to sea level:	-1.11	Note:	Not Reported
Level reading date:	1932-09-02	Feet below surface:	Not Reported
Feet to sea level:	0.09	Note:	Not Reported
Level reading date:	1932-08-09	Feet below surface:	Not Reported
Feet to sea level:	0.09	Note:	Not Reported
Level reading date:	1932-06-13	Feet below surface:	Not Reported
Feet to sea level:	1.54	Note:	Not Reported
Level reading date:	1932-05-16	Feet below surface:	Not Reported
Feet to sea level:	1.74	Note:	Not Reported
Level reading date:	1932-05-03	Feet below surface:	Not Reported
Feet to sea level:	1.66	Note:	Not Reported

A5
SE
1/2 - 1 Mile
Lower

FED USGS USGS40000828091

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 538. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported

DRAFT

Well Hole Depth:	172	Well Hole Depth Units:	ft

6
ESE
1/2 - 1 Mile
Lower

NY WELLS **NYREG1200061374**

WELLS REG 1:

Well Number:	K003595	Well Type:	Commercial/Industrial Supply
Owner:	Liberty Car Wash	Diameter (in):	4
Well Depth (ft):	65	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	45

A7
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000828073**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1286. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	164	Well Hole Depth Units:	ft

8
WSW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1200061405**

WELLS REG 1:

Well Number:	K003566	Well Type:	Commercial/Industrial Supply
Owner:	Lee, Chin	Diameter (in):	6
Well Depth (ft):	160	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	40

B9
West
1/2 - 1 Mile
Higher

NY WELLS **NYREG1200061346**

WELLS REG 1:

Well Number:	K003623D	Well Type:	Geothermal Diffusion
Owner:	Johns Funeral Home	Diameter (in):	6
Well Depth (ft):	45	Casing Length (ft):	35
Screen Length (ft):	10	Pump Capacity (gpm):	Not Reported

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B10
West
1/2 - 1 Mile
Higher | **NY WELLS** | **NYREG1200061347**

WELLS REG 1:

Well Number:	K003622	Well Type:	Geothermal - Ac Only
Owner:	Johns Funeral Home	Diameter (in):	6
Well Depth (ft):	65	Casing Length (ft):	55
Screen Length (ft):	10	Pump Capacity (gpm):	20

11
North
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000828531**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 543. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	285	Well Hole Depth Units:	ft

C12
East
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000828318**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1296. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	34
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	204	Level reading date:	1953-03-24
Feet below surface:	Not Reported	Feet to sea level:	2.98
Note:	Not Reported		
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	2.60	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	2.53	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported

DRAFT

Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	1.68	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	2.14	Note:	Not Reported
Level reading date:	1952-08-26	Feet below surface:	Not Reported
Feet to sea level:	2.48	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	2.37	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.77	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	Not Reported
Feet to sea level:	2.56	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1952-02-19	Feet below surface:	Not Reported
Feet to sea level:	2.20	Note:	Not Reported
Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	2.28	Note:	Not Reported
Level reading date:	1951-12-26	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	1.83	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1951-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1951-08-31	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	1.45	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1951-04-27	Feet below surface:	Not Reported
Feet to sea level:	1.50	Note:	Not Reported

DRAFT

Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	1.28	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	1.24	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	0.90	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	0.61	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	0.51	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	0.62	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	0.84	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	0.80	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	0.63	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	0.80	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	0.81	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	0.96	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	0.38	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	0.37	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	0.47	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	0.54	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	0.53	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	0.68	Note:	Not Reported
Level reading date:	1949-08-02	Feet below surface:	Not Reported
Feet to sea level:	0.55	Note:	Not Reported

DRAFT

Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	0.57	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	0.75	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	0.47	Note:	Not Reported
Level reading date:	1949-04-18	Feet below surface:	Not Reported
Feet to sea level:	0.41	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	0.34	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	0.19	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-0.51	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-0.29	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-0.14	Note:	Not Reported
Level reading date:	1948-09-01	Feet below surface:	Not Reported
Feet to sea level:	0.43	Note:	Not Reported
Level reading date:	1948-07-27	Feet below surface:	Not Reported
Feet to sea level:	1.28	Note:	Not Reported
Level reading date:	1948-07-06	Feet below surface:	Not Reported
Feet to sea level:	0.21	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-0.14	Note:	Not Reported
Level reading date:	1948-04-28	Feet below surface:	Not Reported
Feet to sea level:	-0.35	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-0.70	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-1.07	Note:	Not Reported
Level reading date:	1948-01-09	Feet below surface:	Not Reported
Feet to sea level:	-1.23	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-0.99	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-1.04	Note:	Not Reported

DRAFT

Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-1.05	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-1.75	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-1.63	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-1.58	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-1.32	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-1.43	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-1.43	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-1.45	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-1.28	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-1.25	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-1.10	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-1.04	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-1.02	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-1.01	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-0.99	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-0.94	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-0.95	Note:	Not Reported
Level reading date:	1947-04-03	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-1.33	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-1.36	Note:	Not Reported

DRAFT

Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-1.05	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-0.83	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-0.73	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-0.47	Note:	Not Reported
Level reading date:	1946-07-30	Feet below surface:	Not Reported
Feet to sea level:	-0.12	Note:	Not Reported
Level reading date:	1946-07-05	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-0.89	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-0.67	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-0.83	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-0.29	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-0.66	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-0.93	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-0.74	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-0.29	Note:	Not Reported
Level reading date:	1945-07-04	Feet below surface:	Not Reported
Feet to sea level:	-0.44	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.62	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.80	Note:	Not Reported
Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-0.71	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-0.55	Note:	Not Reported

DRAFT

Level reading date:	1945-02-06	Feet below surface:	Not Reported
Feet to sea level:	-0.79	Note:	Not Reported
Level reading date:	1945-01-03	Feet below surface:	Not Reported
Feet to sea level:	-0.39	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-0.10	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-0.44	Note:	Not Reported
Level reading date:	1944-10-16	Feet below surface:	Not Reported
Feet to sea level:	-0.38	Note:	Not Reported
Level reading date:	1944-09-01	Feet below surface:	Not Reported
Feet to sea level:	-1.11	Note:	Not Reported
Level reading date:	1944-08-01	Feet below surface:	Not Reported
Feet to sea level:	-0.97	Note:	Not Reported
Level reading date:	1944-07-03	Feet below surface:	Not Reported
Feet to sea level:	-0.73	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-0.55	Note:	Not Reported
Level reading date:	1944-04-25	Feet below surface:	Not Reported
Feet to sea level:	-0.53	Note:	Not Reported
Level reading date:	1944-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.83	Note:	Not Reported
Level reading date:	1944-03-06	Feet below surface:	Not Reported
Feet to sea level:	-1.35	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-1.25	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-1.38	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-0.95	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.10	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-1.55	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-1.52	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-1.45	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-1.38	Note:	Not Reported

DRAFT

Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-1.56	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-1.40	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-1.73	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-2.15	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-2.35	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-2.30	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-2.32	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-2.34	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-2.37	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-2.41	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-2.46	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-2.52	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-2.57	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-2.56	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-2.63	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-2.69	Note:	Not Reported

DRAFT

Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-2.70	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-2.80	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-2.95	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-3.18	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-3.42	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-3.88	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-4.40	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-4.30	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-4.56	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-4.81	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-5.37	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-5.42	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-5.43	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-5.52	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-5.75	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-5.90	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-6.24	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-7.11	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-7.14	Note:	Not Reported

DRAFT

Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-7.23	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-7.32	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.06	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-7.95	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-7.57	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-7.40	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-6.64	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-6.82	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-6.62	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-6.20	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-6.27	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-6.14	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-5.97	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-5.80	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-5.59	Note:	Not Reported

DRAFT

Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-5.32	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-5.10	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-4.74	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-4.66	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-4.42	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-4.52	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-4.43	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported

C13
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000828319**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1591. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	21	Level reading date:	1953-02-26
Feet below surface:	Not Reported	Feet to sea level:	2.22
Note:	Not Reported		
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	2.23	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.87	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	1.57	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	1.67	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	2.00	Note:	Not Reported
Level reading date:	1952-08-26	Feet below surface:	Not Reported
Feet to sea level:	2.27	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	2.18	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.43	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.40	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	Not Reported
Feet to sea level:	2.18	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	2.19	Note:	Not Reported
Level reading date:	1952-02-19	Feet below surface:	Not Reported
Feet to sea level:	1.97	Note:	Not Reported
Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	2.03	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	1.50	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	1.10	Note:	Not Reported
Level reading date:	1951-10-02	Feet below surface:	Not Reported
Feet to sea level:	0.93	Note:	Not Reported
Level reading date:	1951-09-25	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1951-08-27	Feet below surface:	Not Reported
Feet to sea level:	1.17	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	1.38	Note:	Not Reported

14
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000827932**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 680. 1	Type:	Well
Description:	Not Reported	HUC:	02030202

DRAFT

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	434	Well Hole Depth Units:	ft

D15
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828476**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1194. 2	Type:	Well
Description:	OLD: K 1194. 1	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	48
Well Depth Units:	ft	Well Hole Depth:	48
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	85	Level reading date:	1943-01-30
Feet below surface:	Not Reported	Feet to sea level:	-3.43
Note:	Not Reported		

Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-3.64	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-3.75	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-3.80	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-3.81	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-3.93	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-3.87	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-3.93	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-4.00	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-4.02	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-4.05	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-4.12	Note:	Not Reported

DRAFT

Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-4.29	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-4.25	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-4.34	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-4.41	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-4.55	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-4.68	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-4.76	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-4.91	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-5.20	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-5.40	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-5.59	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-5.76	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-5.90	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-6.37	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-6.90	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-7.18	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-7.51	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported

DRAFT

Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-7.88	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-7.90	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-7.98	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-8.19	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-8.31	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-8.31	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-8.19	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-8.12	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-8.10	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported

DRAFT

Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-8.03	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-7.80	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-7.65	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-7.57	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-7.52	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-7.43	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-7.30	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-7.15	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-7.07	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-6.98	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-6.97	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-7.03	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-7.02	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-6.92	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported

DRAFT

Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-6.75	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-6.55	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-6.27	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.16	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-6.00	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-5.62	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-5.41	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-5.23	Note:	Not Reported

D16
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828475**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1194. 1	Type:	Well
Description:	NEW: K 1194. 2 197000	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	48
Well Depth Units:	ft	Well Hole Depth:	48
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	25	Level reading date:	1941-04-19
Feet below surface:	Not Reported	Feet to sea level:	-4.01
Note:	Not Reported		
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-3.76	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	-3.09	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-2.86	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-2.86	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-2.93	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-2.97	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-2.96	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-3.12	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-3.12	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-3.23	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-3.40	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-3.48	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-3.56	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-3.65	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-3.73	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-3.83	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-3.91	Note:	Not Reported

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D17
NE
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000828486**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1194. 4	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	55
Well Depth Units:	ft	Well Hole Depth:	55
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	267	Level reading date:	2001-11-19
Feet below surface:	Not Reported	Feet to sea level:	9.10
Note:	Not Reported		

Level reading date:	2001-11-18	Feet below surface:	Not Reported
Feet to sea level:	9.10	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-11-10	Feet below surface:	Not Reported
Feet to sea level:	9.10	Note:	Not Reported
Level reading date:	2001-11-05	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-10-30	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-10-25	Feet below surface:	Not Reported
Feet to sea level:	9.10	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	8.90	Note:	Not Reported
Level reading date:	2001-10-20	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-10-15	Feet below surface:	Not Reported
Feet to sea level:	9.10	Note:	Not Reported
Level reading date:	2001-10-10	Feet below surface:	Not Reported
Feet to sea level:	9.10	Note:	Not Reported
Level reading date:	2001-10-05	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-09-30	Feet below surface:	Not Reported
Feet to sea level:	9.09	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	9.09	Note:	Not Reported

DRAFT

Level reading date:	2001-09-25	Feet below surface:	Not Reported
Feet to sea level:	9.09	Note:	Not Reported
Level reading date:	2001-09-20	Feet below surface:	Not Reported
Feet to sea level:	9.1	Note:	Not Reported
Level reading date:	2001-09-15	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-09-10	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-09-05	Feet below surface:	Not Reported
Feet to sea level:	9.13	Note:	Not Reported
Level reading date:	2001-08-30	Feet below surface:	Not Reported
Feet to sea level:	9.13	Note:	Not Reported
Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	8.71	Note:	Not Reported
Level reading date:	2001-08-25	Feet below surface:	Not Reported
Feet to sea level:	9.14	Note:	Not Reported
Level reading date:	2001-08-20	Feet below surface:	Not Reported
Feet to sea level:	9.14	Note:	Not Reported
Level reading date:	2001-08-15	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-08-10	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-08-05	Feet below surface:	Not Reported
Feet to sea level:	9.16	Note:	Not Reported
Level reading date:	2001-07-31	Feet below surface:	Not Reported
Feet to sea level:	9.16	Note:	Not Reported
Level reading date:	2001-07-30	Feet below surface:	Not Reported
Feet to sea level:	9.16	Note:	Not Reported
Level reading date:	2001-07-25	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	8.94	Note:	Not Reported
Level reading date:	2001-07-20	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-07-15	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-07-10	Feet below surface:	Not Reported
Feet to sea level:	9.14	Note:	Not Reported
Level reading date:	2001-07-05	Feet below surface:	Not Reported
Feet to sea level:	9.13	Note:	Not Reported
Level reading date:	2001-06-30	Feet below surface:	Not Reported
Feet to sea level:	9.12	Note:	Not Reported

DRAFT

Level reading date:	2001-06-25	Feet below surface:	Not Reported
Feet to sea level:	9.11	Note:	Not Reported
Level reading date:	2001-06-20	Feet below surface:	Not Reported
Feet to sea level:	9.1	Note:	Not Reported
Level reading date:	2001-06-15	Feet below surface:	Not Reported
Feet to sea level:	9.09	Note:	Not Reported
Level reading date:	2001-06-10	Feet below surface:	Not Reported
Feet to sea level:	9.08	Note:	Not Reported
Level reading date:	2001-06-05	Feet below surface:	Not Reported
Feet to sea level:	9.07	Note:	Not Reported
Level reading date:	2001-05-30	Feet below surface:	Not Reported
Feet to sea level:	9.06	Note:	Not Reported
Level reading date:	2001-05-25	Feet below surface:	Not Reported
Feet to sea level:	9.05	Note:	Not Reported
Level reading date:	2001-05-20	Feet below surface:	Not Reported
Feet to sea level:	9.04	Note:	Not Reported
Level reading date:	2001-05-16	Feet below surface:	Not Reported
Feet to sea level:	9.03	Note:	Not Reported
Level reading date:	2001-05-15	Feet below surface:	Not Reported
Feet to sea level:	9.02	Note:	Not Reported
Level reading date:	2001-05-10	Feet below surface:	Not Reported
Feet to sea level:	8.97	Note:	Not Reported
Level reading date:	2001-05-05	Feet below surface:	Not Reported
Feet to sea level:	8.92	Note:	Not Reported
Level reading date:	2001-04-30	Feet below surface:	Not Reported
Feet to sea level:	8.87	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	8.81	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	8.79	Note:	Not Reported
Level reading date:	2001-04-20	Feet below surface:	Not Reported
Feet to sea level:	8.76	Note:	Not Reported
Level reading date:	2001-04-15	Feet below surface:	Not Reported
Feet to sea level:	8.7	Note:	Not Reported
Level reading date:	2001-04-10	Feet below surface:	Not Reported
Feet to sea level:	8.65	Note:	Not Reported
Level reading date:	2001-04-05	Feet below surface:	Not Reported
Feet to sea level:	8.59	Note:	Not Reported
Level reading date:	2001-04-02	Feet below surface:	Not Reported
Feet to sea level:	8.56	Note:	Not Reported
Level reading date:	2001-03-30	Feet below surface:	Not Reported
Feet to sea level:	8.55	Note:	Not Reported

DRAFT

Level reading date:	2001-03-25	Feet below surface:	Not Reported
Feet to sea level:	8.54	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	8.52	Note:	Not Reported
Level reading date:	2001-03-15	Feet below surface:	Not Reported
Feet to sea level:	8.52	Note:	Not Reported
Level reading date:	2001-03-10	Feet below surface:	Not Reported
Feet to sea level:	8.51	Note:	Not Reported
Level reading date:	2001-03-05	Feet below surface:	Not Reported
Feet to sea level:	8.51	Note:	Not Reported
Level reading date:	2001-02-25	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	8.76	Note:	Not Reported
Level reading date:	2001-02-20	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2001-02-15	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-02-10	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-02-05	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-01-30	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-01-25	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-01-20	Feet below surface:	Not Reported
Feet to sea level:	8.48	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	8.93	Note:	Not Reported
Level reading date:	2001-01-15	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-01-10	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2001-01-05	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2000-12-30	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2000-12-25	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2000-12-20	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported

DRAFT

Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	9.02	Note:	Not Reported
Level reading date:	2000-12-15	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2000-12-10	Feet below surface:	Not Reported
Feet to sea level:	8.5	Note:	Not Reported
Level reading date:	2000-12-05	Feet below surface:	Not Reported
Feet to sea level:	8.51	Note:	Not Reported
Level reading date:	2000-11-30	Feet below surface:	Not Reported
Feet to sea level:	8.52	Note:	Not Reported
Level reading date:	2000-11-25	Feet below surface:	Not Reported
Feet to sea level:	8.52	Note:	Not Reported
Level reading date:	2000-11-20	Feet below surface:	Not Reported
Feet to sea level:	8.53	Note:	Not Reported
Level reading date:	2000-11-15	Feet below surface:	Not Reported
Feet to sea level:	8.54	Note:	Not Reported
Level reading date:	2000-11-10	Feet below surface:	Not Reported
Feet to sea level:	8.55	Note:	Not Reported
Level reading date:	2000-11-05	Feet below surface:	Not Reported
Feet to sea level:	8.57	Note:	Not Reported
Level reading date:	2000-10-30	Feet below surface:	Not Reported
Feet to sea level:	8.58	Note:	Not Reported
Level reading date:	2000-10-25	Feet below surface:	Not Reported
Feet to sea level:	8.59	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	8.59	Note:	Not Reported
Level reading date:	2000-10-20	Feet below surface:	Not Reported
Feet to sea level:	8.62	Note:	Not Reported
Level reading date:	2000-10-15	Feet below surface:	Not Reported
Feet to sea level:	8.65	Note:	Not Reported
Level reading date:	2000-10-10	Feet below surface:	Not Reported
Feet to sea level:	8.68	Note:	Not Reported
Level reading date:	2000-10-05	Feet below surface:	Not Reported
Feet to sea level:	8.71	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	9.66	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	9.30	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	9.35	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.40	Note:	Not Reported

DRAFT

Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	9.43	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	9.53	Note:	Not Reported
Level reading date:	2000-03-22	Feet below surface:	Not Reported
Feet to sea level:	9.71	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	9.85	Note:	Not Reported
Level reading date:	1999-12-22	Feet below surface:	Not Reported
Feet to sea level:	9.91	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	9.90	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	9.92	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	10.03	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	10.12	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	10.06	Note:	Not Reported
Level reading date:	1999-07-16	Feet below surface:	Not Reported
Feet to sea level:	10.05	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	10.05	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	10.30	Note:	Not Reported
Level reading date:	1999-02-26	Feet below surface:	Not Reported
Feet to sea level:	10.44	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	10.37	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	10.53	Note:	Not Reported

DRAFT

Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	10.55	Note:	Not Reported
Level reading date:	1998-06-10	Feet below surface:	Not Reported
Feet to sea level:	10.40	Note:	Not Reported
Level reading date:	1998-05-20	Feet below surface:	Not Reported
Feet to sea level:	10.33	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	10.28	Note:	Not Reported
Level reading date:	1998-03-24	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	1998-01-29	Feet below surface:	Not Reported
Feet to sea level:	10.27	Note:	Not Reported
Level reading date:	1997-12-17	Feet below surface:	Not Reported
Feet to sea level:	10.33	Note:	Not Reported
Level reading date:	1997-11-26	Feet below surface:	Not Reported
Feet to sea level:	10.41	Note:	Not Reported
Level reading date:	1997-11-05	Feet below surface:	Not Reported
Feet to sea level:	10.48	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	10.54	Note:	Not Reported
Level reading date:	1997-07-23	Feet below surface:	Not Reported
Feet to sea level:	10.15	Note:	Not Reported
Level reading date:	1997-06-26	Feet below surface:	Not Reported
Feet to sea level:	10.13	Note:	Not Reported
Level reading date:	1997-05-29	Feet below surface:	Not Reported
Feet to sea level:	10.06	Note:	Not Reported
Level reading date:	1997-03-17	Feet below surface:	Not Reported
Feet to sea level:	9.91	Note:	Not Reported
Level reading date:	1997-02-26	Feet below surface:	Not Reported
Feet to sea level:	9.88	Note:	Not Reported
Level reading date:	1997-01-24	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	1997-01-07	Feet below surface:	Not Reported
Feet to sea level:	9.87	Note:	Not Reported
Level reading date:	1996-09-19	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	1996-07-02	Feet below surface:	Not Reported
Feet to sea level:	9.38	Note:	Not Reported
Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	9.33	Note:	Not Reported
Level reading date:	1996-01-23	Feet below surface:	Not Reported
Feet to sea level:	9.28	Note:	Not Reported

DRAFT

Level reading date:	1995-11-28	Feet below surface:	Not Reported
Feet to sea level:	9.03	Note:	Not Reported
Level reading date:	1995-09-26	Feet below surface:	Not Reported
Feet to sea level:	9.14	Note:	Not Reported
Level reading date:	1995-07-19	Feet below surface:	Not Reported
Feet to sea level:	9.28	Note:	Not Reported
Level reading date:	1995-05-23	Feet below surface:	Not Reported
Feet to sea level:	9.55	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	11.30	Note:	Not Reported
Level reading date:	1995-01-25	Feet below surface:	Not Reported
Feet to sea level:	10.42	Note:	Not Reported
Level reading date:	1994-12-13	Feet below surface:	Not Reported
Feet to sea level:	9.56	Note:	Not Reported
Level reading date:	1994-10-18	Feet below surface:	Not Reported
Feet to sea level:	9.85	Note:	Not Reported
Level reading date:	1994-09-21	Feet below surface:	Not Reported
Feet to sea level:	10.03	Note:	Not Reported
Level reading date:	1994-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.32	Note:	Not Reported
Level reading date:	1994-07-27	Feet below surface:	Not Reported
Feet to sea level:	11.27	Note:	Not Reported
Level reading date:	1994-05-16	Feet below surface:	Not Reported
Feet to sea level:	10.78	Note:	Not Reported
Level reading date:	1994-04-26	Feet below surface:	Not Reported
Feet to sea level:	11.26	Note:	Not Reported
Level reading date:	1994-02-22	Feet below surface:	Not Reported
Feet to sea level:	9.76	Note:	Not Reported
Level reading date:	1993-12-27	Feet below surface:	Not Reported
Feet to sea level:	9.21	Note:	Not Reported
Level reading date:	1993-11-18	Feet below surface:	Not Reported
Feet to sea level:	9.32	Note:	Not Reported
Level reading date:	1993-10-27	Feet below surface:	Not Reported
Feet to sea level:	9.41	Note:	Not Reported
Level reading date:	1993-09-15	Feet below surface:	Not Reported
Feet to sea level:	9.65	Note:	Not Reported
Level reading date:	1993-08-18	Feet below surface:	Not Reported
Feet to sea level:	9.83	Note:	Not Reported
Level reading date:	1993-07-14	Feet below surface:	Not Reported
Feet to sea level:	9.79	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	9.90	Note:	Not Reported

DRAFT

Level reading date:	1993-05-19	Feet below surface:	Not Reported
Feet to sea level:	9.95	Note:	Not Reported
Level reading date:	1993-04-29	Feet below surface:	Not Reported
Feet to sea level:	9.99	Note:	Not Reported
Level reading date:	1993-03-22	Feet below surface:	Not Reported
Feet to sea level:	10.11	Note:	Not Reported
Level reading date:	1993-02-24	Feet below surface:	Not Reported
Feet to sea level:	10.57	Note:	Not Reported
Level reading date:	1993-01-26	Feet below surface:	Not Reported
Feet to sea level:	10.34	Note:	Not Reported
Level reading date:	1993-01-22	Feet below surface:	Not Reported
Feet to sea level:	9.76	Note:	Not Reported
Level reading date:	1992-12-29	Feet below surface:	Not Reported
Feet to sea level:	10.85	Note:	Not Reported
Level reading date:	1992-08-25	Feet below surface:	Not Reported
Feet to sea level:	9.66	Note:	Not Reported
Level reading date:	1992-07-15	Feet below surface:	Not Reported
Feet to sea level:	9.35	Note:	Not Reported
Level reading date:	1992-06-22	Feet below surface:	Not Reported
Feet to sea level:	9.38	Note:	Not Reported
Level reading date:	1992-05-12	Feet below surface:	Not Reported
Feet to sea level:	9.46	Note:	Not Reported
Level reading date:	1992-04-14	Feet below surface:	Not Reported
Feet to sea level:	9.62	Note:	Not Reported
Level reading date:	1992-03-17	Feet below surface:	Not Reported
Feet to sea level:	9.75	Note:	Not Reported
Level reading date:	1992-02-19	Feet below surface:	Not Reported
Feet to sea level:	9.93	Note:	Not Reported
Level reading date:	1992-01-21	Feet below surface:	Not Reported
Feet to sea level:	10.31	Note:	Not Reported
Level reading date:	1991-09-17	Feet below surface:	Not Reported
Feet to sea level:	10.80	Note:	Not Reported
Level reading date:	1991-08-15	Feet below surface:	Not Reported
Feet to sea level:	10.48	Note:	Not Reported
Level reading date:	1991-07-15	Feet below surface:	Not Reported
Feet to sea level:	10.42	Note:	Not Reported
Level reading date:	1991-06-12	Feet below surface:	Not Reported
Feet to sea level:	10.59	Note:	Not Reported
Level reading date:	1991-05-15	Feet below surface:	Not Reported
Feet to sea level:	10.50	Note:	Not Reported
Level reading date:	1991-04-15	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported

DRAFT

Level reading date:	1991-03-19	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1991-02-21	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1991-01-23	Feet below surface:	Not Reported
Feet to sea level:	10.33	Note:	Not Reported
Level reading date:	1990-12-10	Feet below surface:	Not Reported
Feet to sea level:	10.34	Note:	Not Reported
Level reading date:	1990-11-13	Feet below surface:	Not Reported
Feet to sea level:	10.43	Note:	Not Reported
Level reading date:	1990-10-10	Feet below surface:	Not Reported
Feet to sea level:	10.27	Note:	Not Reported
Level reading date:	1990-09-12	Feet below surface:	Not Reported
Feet to sea level:	10.32	Note:	Not Reported
Level reading date:	1990-08-14	Feet below surface:	Not Reported
Feet to sea level:	10.28	Note:	Not Reported
Level reading date:	1990-07-12	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1990-06-20	Feet below surface:	Not Reported
Feet to sea level:	10.19	Note:	Not Reported
Level reading date:	1990-05-25	Feet below surface:	Not Reported
Feet to sea level:	10.05	Note:	Not Reported
Level reading date:	1990-04-23	Feet below surface:	Not Reported
Feet to sea level:	9.87	Note:	Not Reported
Level reading date:	1990-03-27	Feet below surface:	Not Reported
Feet to sea level:	9.79	Note:	Not Reported
Level reading date:	1990-02-26	Feet below surface:	Not Reported
Feet to sea level:	9.90	Note:	Not Reported
Level reading date:	1990-01-23	Feet below surface:	Not Reported
Feet to sea level:	10.26	Note:	Not Reported
Level reading date:	1989-12-27	Feet below surface:	Not Reported
Feet to sea level:	10.11	Note:	Not Reported
Level reading date:	1989-11-21	Feet below surface:	Not Reported
Feet to sea level:	10.27	Note:	Not Reported
Level reading date:	1989-10-27	Feet below surface:	Not Reported
Feet to sea level:	10.22	Note:	Not Reported
Level reading date:	1989-09-28	Feet below surface:	Not Reported
Feet to sea level:	10.30	Note:	Not Reported
Level reading date:	1989-08-30	Feet below surface:	Not Reported
Feet to sea level:	10.34	Note:	Not Reported
Level reading date:	1989-07-24	Feet below surface:	Not Reported
Feet to sea level:	10.18	Note:	Not Reported

DRAFT

Level reading date:	1989-06-21	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	1989-05-22	Feet below surface:	Not Reported
Feet to sea level:	9.37	Note:	Not Reported
Level reading date:	1989-04-27	Feet below surface:	Not Reported
Feet to sea level:	9.20	Note:	Not Reported
Level reading date:	1989-03-29	Feet below surface:	Not Reported
Feet to sea level:	8.97	Note:	Not Reported
Level reading date:	1989-02-28	Feet below surface:	Not Reported
Feet to sea level:	9.06	Note:	Not Reported
Level reading date:	1989-01-17	Feet below surface:	Not Reported
Feet to sea level:	9.21	Note:	Not Reported
Level reading date:	1988-12-09	Feet below surface:	Not Reported
Feet to sea level:	9.23	Note:	Not Reported
Level reading date:	1988-11-16	Feet below surface:	Not Reported
Feet to sea level:	9.07	Note:	Not Reported
Level reading date:	1988-10-19	Feet below surface:	Not Reported
Feet to sea level:	9.12	Note:	Not Reported
Level reading date:	1988-09-14	Feet below surface:	Not Reported
Feet to sea level:	9.19	Note:	Not Reported
Level reading date:	1988-08-31	Feet below surface:	Not Reported
Feet to sea level:	9.13	Note:	Not Reported
Level reading date:	1988-07-22	Feet below surface:	Not Reported
Feet to sea level:	9.00	Note:	Not Reported
Level reading date:	1988-06-17	Feet below surface:	Not Reported
Feet to sea level:	9.03	Note:	Not Reported
Level reading date:	1988-05-05	Feet below surface:	Not Reported
Feet to sea level:	8.32	Note:	Not Reported
Level reading date:	1985-10-02	Feet below surface:	Not Reported
Feet to sea level:	10.66	Note:	Not Reported
Level reading date:	1985-05-20	Feet below surface:	Not Reported
Feet to sea level:	8.51	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	9.16	Note:	Not Reported
Level reading date:	1984-10-03	Feet below surface:	Not Reported
Feet to sea level:	9.76	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.79	Note:	Not Reported
Level reading date:	1984-03-19	Feet below surface:	Not Reported
Feet to sea level:	8.79	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	7.76	Note:	Not Reported

DRAFT

Level reading date:	1983-09-29	Feet below surface:	Not Reported
Feet to sea level:	7.96	Note:	Not Reported
Level reading date:	1983-06-28	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	1983-03-22	Feet below surface:	Not Reported
Feet to sea level:	7.92	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	7.96	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	8.16	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	8.66	Note:	Not Reported
Level reading date:	1982-03-26	Feet below surface:	Not Reported
Feet to sea level:	8.51	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	8.45	Note:	Not Reported
Level reading date:	1981-09-22	Feet below surface:	Not Reported
Feet to sea level:	8.81	Note:	Not Reported
Level reading date:	1981-03-16	Feet below surface:	Not Reported
Feet to sea level:	9.56	Note:	Not Reported
Level reading date:	1980-12-22	Feet below surface:	Not Reported
Feet to sea level:	9.67	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	10.21	Note:	Not Reported
Level reading date:	1980-03-01	Feet below surface:	Not Reported
Feet to sea level:	9.68	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	10.26	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	10.36	Note:	Not Reported
Level reading date:	1979-03-26	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	1978-12-21	Feet below surface:	Not Reported
Feet to sea level:	9.69	Note:	Not Reported
Level reading date:	1978-12-18	Feet below surface:	Not Reported
Feet to sea level:	10.08	Note:	Not Reported
Level reading date:	1978-10-02	Feet below surface:	Not Reported
Feet to sea level:	9.86	Note:	Not Reported
Level reading date:	1978-06-23	Feet below surface:	Not Reported
Feet to sea level:	10.16	Note:	Not Reported
Level reading date:	1978-04-04	Feet below surface:	Not Reported
Feet to sea level:	10.76	Note:	Not Reported

DRAFT

Level reading date:	1978-01-03	Feet below surface:	Not Reported
Feet to sea level:	9.27	Note:	Not Reported
Level reading date:	1977-09-23	Feet below surface:	Not Reported
Feet to sea level:	8.70	Note:	Not Reported
Level reading date:	1977-07-08	Feet below surface:	Not Reported
Feet to sea level:	8.90	Note:	Not Reported
Level reading date:	1977-03-28	Feet below surface:	Not Reported
Feet to sea level:	8.78	Note:	Not Reported
Level reading date:	1976-12-21	Feet below surface:	Not Reported
Feet to sea level:	8.89	Note:	Not Reported
Level reading date:	1976-09-23	Feet below surface:	Not Reported
Feet to sea level:	8.98	Note:	Not Reported
Level reading date:	1976-06-30	Feet below surface:	Not Reported
Feet to sea level:	8.42	Note:	Not Reported
Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	10.03	Note:	Not Reported
Level reading date:	1975-12-15	Feet below surface:	Not Reported
Feet to sea level:	8.96	Note:	Not Reported
Level reading date:	1975-10-06	Feet below surface:	Not Reported
Feet to sea level:	8.87	Note:	Not Reported
Level reading date:	1975-07-01	Feet below surface:	Not Reported
Feet to sea level:	7.92	Note:	Not Reported
Level reading date:	1975-03-25	Feet below surface:	Not Reported
Feet to sea level:	7.40	Note:	Not Reported
Level reading date:	1973-07-02	Feet below surface:	Not Reported
Feet to sea level:	4.32	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	3.94	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	2.61	Note:	Not Reported
Level reading date:	1972-10-03	Feet below surface:	Not Reported
Feet to sea level:	1.02	Note:	Not Reported
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	0.46	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	-0.05	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	-0.09	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	-0.63	Note:	Not Reported

DRAFT

Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	-0.83	Note:	Not Reported

D18
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000828485**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1194. 3	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	43
Well Depth Units:	ft	Well Hole Depth:	43
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	180	Level reading date:	1967-11-09
Feet below surface:	Not Reported	Feet to sea level:	-0.41
Note:	Not Reported		

Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	-1.88	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	-1.60	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	-1.06	Note:	Not Reported
Level reading date:	1965-09-16	Feet below surface:	Not Reported
Feet to sea level:	1.02	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	0.26	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	0.79	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	0.02	Note:	Not Reported
Level reading date:	1963-10-19	Feet below surface:	Not Reported
Feet to sea level:	0.06	Note:	Not Reported
Level reading date:	1963-04-25	Feet below surface:	Not Reported
Feet to sea level:	1.19	Note:	Not Reported
Level reading date:	1962-11-09	Feet below surface:	Not Reported
Feet to sea level:	1.12	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	1.67	Note:	Not Reported
Level reading date:	1962-04-03	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	3.20	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	0.55	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	0.38	Note:	Not Reported
Level reading date:	1961-06-28	Feet below surface:	Not Reported
Feet to sea level:	0.41	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	-0.06	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	0.91	Note:	Not Reported
Level reading date:	1960-09-27	Feet below surface:	Not Reported
Feet to sea level:	-0.02	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported
Level reading date:	1960-03-30	Feet below surface:	Not Reported
Feet to sea level:	-0.26	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	-0.28	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	-0.97	Note:	Not Reported
Level reading date:	1959-07-10	Feet below surface:	Not Reported
Feet to sea level:	-0.80	Note:	Not Reported
Level reading date:	1959-03-20	Feet below surface:	Not Reported
Feet to sea level:	-0.20	Note:	Not Reported
Level reading date:	1957-12-23	Feet below surface:	Not Reported
Feet to sea level:	0.05	Note:	Not Reported
Level reading date:	1957-09-25	Feet below surface:	Not Reported
Feet to sea level:	0.06	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	0.15	Note:	Not Reported
Level reading date:	1957-03-28	Feet below surface:	Not Reported
Feet to sea level:	0.72	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	0.89	Note:	Not Reported
Level reading date:	1956-11-30	Feet below surface:	Not Reported
Feet to sea level:	0.50	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	0.76	Note:	Not Reported
Level reading date:	1956-10-01	Feet below surface:	Not Reported
Feet to sea level:	0.63	Note:	Not Reported

DRAFT

Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	0.84	Note:	Not Reported
Level reading date:	1956-07-03	Feet below surface:	Not Reported
Feet to sea level:	0.76	Note:	Not Reported
Level reading date:	1956-06-04	Feet below surface:	Not Reported
Feet to sea level:	1.20	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	0.98	Note:	Not Reported
Level reading date:	1956-03-06	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	0.98	Note:	Not Reported
Level reading date:	1955-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.45	Note:	Not Reported
Level reading date:	1955-11-07	Feet below surface:	Not Reported
Feet to sea level:	1.11	Note:	Not Reported
Level reading date:	1955-10-05	Feet below surface:	Not Reported
Feet to sea level:	1.08	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	0.80	Note:	Not Reported
Level reading date:	1955-07-28	Feet below surface:	Not Reported
Feet to sea level:	0.10	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	0.46	Note:	Not Reported
Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	0.48	Note:	Not Reported
Level reading date:	1955-04-28	Feet below surface:	Not Reported
Feet to sea level:	0.66	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	0.61	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	0.70	Note:	Not Reported
Level reading date:	1955-01-24	Feet below surface:	Not Reported
Feet to sea level:	0.43	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	0.59	Note:	Not Reported
Level reading date:	1954-12-01	Feet below surface:	Not Reported
Feet to sea level:	0.33	Note:	Not Reported
Level reading date:	1954-10-27	Feet below surface:	Not Reported
Feet to sea level:	-0.14	Note:	Not Reported
Level reading date:	1954-09-28	Feet below surface:	Not Reported
Feet to sea level:	-0.10	Note:	Not Reported

DRAFT

Level reading date:	1954-08-24	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	-0.26	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	-0.06	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.14	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	0.39	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	0.62	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	0.98	Note:	Not Reported
Level reading date:	1953-12-22	Feet below surface:	Not Reported
Feet to sea level:	0.71	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	1.10	Note:	Not Reported
Level reading date:	1953-10-26	Feet below surface:	Not Reported
Feet to sea level:	0.93	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	0.62	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	0.53	Note:	Not Reported
Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	0.45	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	0.21	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	0.01	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-0.24	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	0.30	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	0.40	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	0.35	Note:	Not Reported

DRAFT

Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	0.20	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	0.27	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	0.47	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	0.50	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	0.61	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	0.70	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	0.52	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.34	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	0.18	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	0.00	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-0.17	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-0.61	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-0.65	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-0.82	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-1.13	Note:	Not Reported
Level reading date:	1951-09-12	Feet below surface:	Not Reported
Feet to sea level:	-1.10	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.97	Note:	Not Reported
Level reading date:	1951-07-25	Feet below surface:	Not Reported
Feet to sea level:	-1.00	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	-0.84	Note:	Not Reported
Level reading date:	1951-05-31	Feet below surface:	Not Reported
Feet to sea level:	-0.90	Note:	Not Reported
Level reading date:	1951-04-26	Feet below surface:	Not Reported
Feet to sea level:	-1.08	Note:	Not Reported

DRAFT

Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.51	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-1.66	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-1.65	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-1.74	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.70	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-1.68	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-1.53	Note:	Not Reported
Level reading date:	1950-07-25	Feet below surface:	Not Reported
Feet to sea level:	-1.36	Note:	Not Reported
Level reading date:	1950-06-27	Feet below surface:	Not Reported
Feet to sea level:	-1.18	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-1.06	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.96	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.98	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-1.15	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-1.32	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-1.34	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-1.37	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-1.32	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported

DRAFT

Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	-1.09	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-1.27	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-1.37	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.55	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-1.75	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-2.01	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-1.92	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-1.90	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-1.79	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-1.54	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-1.85	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-2.23	Note:	Not Reported
Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-2.40	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.59	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-3.10	Note:	Not Reported
Level reading date:	1948-01-09	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-3.43	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-3.47	Note:	Not Reported

DRAFT

Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-3.51	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-3.64	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-3.60	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-3.62	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-3.59	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-3.45	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-3.36	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-3.26	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-3.22	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-3.17	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.04	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1947-05-26	Feet below surface:	Not Reported
Feet to sea level:	-2.97	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-3.08	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-3.09	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-2.87	Note:	Not Reported

DRAFT

Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-2.63	Note:	Not Reported
Level reading date:	1946-10-23	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-2.35	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-2.20	Note:	Not Reported
Level reading date:	1946-07-30	Feet below surface:	Not Reported
Feet to sea level:	-2.05	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-2.07	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-2.15	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-2.50	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-2.52	Note:	Not Reported
Level reading date:	1946-03-04	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-2.39	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-2.42	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-2.40	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.20	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-2.17	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-2.00	Note:	Not Reported
Level reading date:	1945-07-04	Feet below surface:	Not Reported
Feet to sea level:	-2.14	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-2.12	Note:	Not Reported
Level reading date:	1945-05-18	Feet below surface:	Not Reported
Feet to sea level:	-2.05	Note:	Not Reported

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E19
SE
1/2 - 1 Mile
Lower

NY WELLS **NYREG1200061476**

WELLS REG 1:

Well Number:	K003507	Well Type:	Commercial/Industrial Supply
Owner:	Laundry Land	Diameter (in):	6
Well Depth (ft):	100	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	45

E20
SE
1/2 - 1 Mile
Lower

NY WELLS **NYREG1200061510**

WELLS REG 1:

Well Number:	K003475	Well Type:	Commercial/Industrial Supply
Owner:	World Cleaners	Diameter (in):	6
Well Depth (ft):	100	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	45

21
West
1/2 - 1 Mile
Higher

FED USGS **USGS40000828290**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1235. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	80
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	432	Level reading date:	1972-08-31
Feet below surface:	Not Reported	Feet to sea level:	7.12
Note:	Not Reported		

Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	7.03	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	7.16	Note:	Not Reported
Level reading date:	1971-10-22	Feet below surface:	Not Reported
Feet to sea level:	7.07	Note:	Not Reported
Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	7.07	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	6.83	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	5.79	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	6.40	Note:	Not Reported
Level reading date:	1969-09-05	Feet below surface:	Not Reported
Feet to sea level:	6.06	Note:	Not Reported
Level reading date:	1969-08-04	Feet below surface:	Not Reported
Feet to sea level:	5.82	Note:	Not Reported
Level reading date:	1969-07-02	Feet below surface:	Not Reported
Feet to sea level:	5.77	Note:	Not Reported
Level reading date:	1969-05-28	Feet below surface:	Not Reported
Feet to sea level:	5.53	Note:	Not Reported
Level reading date:	1969-04-21	Feet below surface:	Not Reported
Feet to sea level:	5.52	Note:	Not Reported
Level reading date:	1969-04-01	Feet below surface:	Not Reported
Feet to sea level:	5.44	Note:	Not Reported
Level reading date:	1969-02-20	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported
Level reading date:	1969-01-08	Feet below surface:	Not Reported
Feet to sea level:	5.04	Note:	Not Reported
Level reading date:	1968-12-03	Feet below surface:	Not Reported
Feet to sea level:	4.77	Note:	Not Reported
Level reading date:	1968-11-05	Feet below surface:	Not Reported
Feet to sea level:	4.52	Note:	Not Reported
Level reading date:	1968-09-30	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1968-08-28	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1968-07-29	Feet below surface:	Not Reported
Feet to sea level:	4.64	Note:	Not Reported
Level reading date:	1968-06-26	Feet below surface:	Not Reported
Feet to sea level:	4.58	Note:	Not Reported
Level reading date:	1968-05-28	Feet below surface:	Not Reported
Feet to sea level:	4.47	Note:	Not Reported
Level reading date:	1968-04-23	Feet below surface:	Not Reported
Feet to sea level:	4.48	Note:	Not Reported
Level reading date:	1968-03-27	Feet below surface:	Not Reported
Feet to sea level:	4.45	Note:	Not Reported
Level reading date:	1968-02-29	Feet below surface:	Not Reported
Feet to sea level:	5.74	Note:	Not Reported

DRAFT

Level reading date:	1968-02-05	Feet below surface:	Not Reported
Feet to sea level:	8.43	Note:	Not Reported
Level reading date:	1968-01-02	Feet below surface:	Not Reported
Feet to sea level:	4.07	Note:	Not Reported
Level reading date:	1967-11-29	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1967-10-23	Feet below surface:	Not Reported
Feet to sea level:	3.91	Note:	Not Reported
Level reading date:	1967-09-26	Feet below surface:	Not Reported
Feet to sea level:	3.88	Note:	Not Reported
Level reading date:	1967-09-07	Feet below surface:	Not Reported
Feet to sea level:	3.75	Note:	Not Reported
Level reading date:	1967-07-28	Feet below surface:	Not Reported
Feet to sea level:	3.62	Note:	Not Reported
Level reading date:	1967-07-06	Feet below surface:	Not Reported
Feet to sea level:	3.54	Note:	Not Reported
Level reading date:	1967-05-31	Feet below surface:	Not Reported
Feet to sea level:	3.46	Note:	Not Reported
Level reading date:	1967-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.30	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.23	Note:	Not Reported
Level reading date:	1967-01-31	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1966-12-23	Feet below surface:	Not Reported
Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1966-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.93	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1966-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.83	Note:	Not Reported
Level reading date:	1966-08-29	Feet below surface:	Not Reported
Feet to sea level:	2.88	Note:	Not Reported
Level reading date:	1966-07-29	Feet below surface:	Not Reported
Feet to sea level:	2.97	Note:	Not Reported
Level reading date:	1966-06-27	Feet below surface:	Not Reported
Feet to sea level:	3.12	Note:	Not Reported
Level reading date:	1966-05-26	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported

DRAFT

Level reading date:	1966-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1966-02-02	Feet below surface:	Not Reported
Feet to sea level:	3.21	Note:	Not Reported
Level reading date:	1966-01-28	Feet below surface:	Not Reported
Feet to sea level:	3.23	Note:	Not Reported
Level reading date:	1965-12-30	Feet below surface:	Not Reported
Feet to sea level:	3.32	Note:	Not Reported
Level reading date:	1965-12-02	Feet below surface:	Not Reported
Feet to sea level:	3.38	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	3.49	Note:	Not Reported
Level reading date:	1965-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.52	Note:	Not Reported
Level reading date:	1965-09-09	Feet below surface:	Not Reported
Feet to sea level:	3.62	Note:	Not Reported
Level reading date:	1965-07-23	Feet below surface:	Not Reported
Feet to sea level:	3.71	Note:	Not Reported
Level reading date:	1965-06-24	Feet below surface:	Not Reported
Feet to sea level:	3.82	Note:	Not Reported
Level reading date:	1965-05-24	Feet below surface:	Not Reported
Feet to sea level:	3.86	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	3.87	Note:	Not Reported
Level reading date:	1965-03-25	Feet below surface:	Not Reported
Feet to sea level:	3.88	Note:	Not Reported
Level reading date:	1965-02-24	Feet below surface:	Not Reported
Feet to sea level:	3.88	Note:	Not Reported
Level reading date:	1965-02-10	Feet below surface:	Not Reported
Feet to sea level:	3.84	Note:	Not Reported
Level reading date:	1964-12-31	Feet below surface:	Not Reported
Feet to sea level:	3.90	Note:	Not Reported
Level reading date:	1964-11-25	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	3.77	Note:	Not Reported
Level reading date:	1964-10-01	Feet below surface:	Not Reported
Feet to sea level:	3.83	Note:	Not Reported
Level reading date:	1964-09-02	Feet below surface:	Not Reported
Feet to sea level:	3.82	Note:	Not Reported
Level reading date:	1964-07-27	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported

DRAFT

Level reading date:	1964-07-06	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1964-05-28	Feet below surface:	Not Reported
Feet to sea level:	4.03	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1964-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1964-02-28	Feet below surface:	Not Reported
Feet to sea level:	3.83	Note:	Not Reported
Level reading date:	1964-01-28	Feet below surface:	Not Reported
Feet to sea level:	3.81	Note:	Not Reported
Level reading date:	1963-12-31	Feet below surface:	Not Reported
Feet to sea level:	3.67	Note:	Not Reported
Level reading date:	1963-12-05	Feet below surface:	Not Reported
Feet to sea level:	3.91	Note:	Not Reported
Level reading date:	1963-10-26	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1963-09-30	Feet below surface:	Not Reported
Feet to sea level:	4.21	Note:	Not Reported
Level reading date:	1963-09-03	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1963-07-30	Feet below surface:	Not Reported
Feet to sea level:	4.27	Note:	Not Reported
Level reading date:	1963-07-02	Feet below surface:	Not Reported
Feet to sea level:	4.25	Note:	Not Reported
Level reading date:	1963-06-03	Feet below surface:	Not Reported
Feet to sea level:	4.44	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	4.42	Note:	Not Reported
Level reading date:	1963-03-29	Feet below surface:	Not Reported
Feet to sea level:	4.49	Note:	Not Reported
Level reading date:	1963-02-28	Feet below surface:	Not Reported
Feet to sea level:	4.54	Note:	Not Reported
Level reading date:	1963-01-03	Feet below surface:	Not Reported
Feet to sea level:	4.64	Note:	Not Reported
Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	4.71	Note:	Not Reported
Level reading date:	1962-11-06	Feet below surface:	Not Reported
Feet to sea level:	4.77	Note:	Not Reported
Level reading date:	1962-10-03	Feet below surface:	Not Reported
Feet to sea level:	4.89	Note:	Not Reported

DRAFT

Level reading date:	1962-08-31	Feet below surface:	Not Reported
Feet to sea level:	4.97	Note:	Not Reported
Level reading date:	1962-07-30	Feet below surface:	Not Reported
Feet to sea level:	4.76	Note:	Not Reported
Level reading date:	1962-07-02	Feet below surface:	Not Reported
Feet to sea level:	4.58	Note:	Not Reported
Level reading date:	1962-05-29	Feet below surface:	Not Reported
Feet to sea level:	4.69	Note:	Not Reported
Level reading date:	1962-04-27	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1962-03-27	Feet below surface:	Not Reported
Feet to sea level:	4.63	Note:	Not Reported
Level reading date:	1962-03-05	Feet below surface:	Not Reported
Feet to sea level:	4.55	Note:	Not Reported
Level reading date:	1962-01-31	Feet below surface:	Not Reported
Feet to sea level:	4.48	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	5.16	Note:	Not Reported
Level reading date:	1961-11-28	Feet below surface:	Not Reported
Feet to sea level:	4.68	Note:	Not Reported
Level reading date:	1961-10-31	Feet below surface:	Not Reported
Feet to sea level:	4.61	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	4.62	Note:	Not Reported
Level reading date:	1961-08-30	Feet below surface:	Not Reported
Feet to sea level:	4.72	Note:	Not Reported
Level reading date:	1961-08-01	Feet below surface:	Not Reported
Feet to sea level:	4.59	Note:	Not Reported
Level reading date:	1961-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.58	Note:	Not Reported
Level reading date:	1961-05-31	Feet below surface:	Not Reported
Feet to sea level:	4.50	Note:	Not Reported
Level reading date:	1961-04-26	Feet below surface:	Not Reported
Feet to sea level:	4.14	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	3.98	Note:	Not Reported
Level reading date:	1961-03-01	Feet below surface:	Not Reported
Feet to sea level:	4.12	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	3.94	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.26	Note:	Not Reported

DRAFT

Level reading date:	1960-12-07	Feet below surface:	Not Reported
Feet to sea level:	3.72	Note:	Not Reported
Level reading date:	1960-11-02	Feet below surface:	Not Reported
Feet to sea level:	3.48	Note:	Not Reported
Level reading date:	1960-09-27	Feet below surface:	Not Reported
Feet to sea level:	3.37	Note:	Not Reported
Level reading date:	1960-08-30	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1960-07-18	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	3.06	Note:	Not Reported
Level reading date:	1960-06-02	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1960-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported
Level reading date:	1960-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.04	Note:	Not Reported
Level reading date:	1960-01-27	Feet below surface:	Not Reported
Feet to sea level:	2.86	Note:	Not Reported
Level reading date:	1960-01-05	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1959-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.85	Note:	Not Reported
Level reading date:	1959-11-02	Feet below surface:	Not Reported
Feet to sea level:	2.54	Note:	Not Reported
Level reading date:	1959-10-06	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1959-09-03	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1959-08-04	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1959-07-07	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1959-06-02	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1959-05-06	Feet below surface:	Not Reported
Feet to sea level:	2.84	Note:	Not Reported
Level reading date:	1959-04-03	Feet below surface:	Not Reported
Feet to sea level:	2.94	Note:	Not Reported
Level reading date:	1959-03-02	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported

DRAFT

Level reading date:	1959-01-29	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1959-01-07	Feet below surface:	Not Reported
Feet to sea level:	3.40	Note:	Not Reported
Level reading date:	1958-12-09	Feet below surface:	Not Reported
Feet to sea level:	3.32	Note:	Not Reported
Level reading date:	1958-10-30	Feet below surface:	Not Reported
Feet to sea level:	3.21	Note:	Not Reported
Level reading date:	1958-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1958-08-28	Feet below surface:	Not Reported
Feet to sea level:	3.01	Note:	Not Reported
Level reading date:	1958-07-29	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1958-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1958-05-29	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1958-05-01	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1958-04-02	Feet below surface:	Not Reported
Feet to sea level:	1.96	Note:	Not Reported
Level reading date:	1958-03-03	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported
Level reading date:	1958-01-28	Feet below surface:	Not Reported
Feet to sea level:	1.90	Note:	Not Reported
Level reading date:	1957-12-31	Feet below surface:	Not Reported
Feet to sea level:	1.85	Note:	Not Reported
Level reading date:	1957-11-22	Feet below surface:	Not Reported
Feet to sea level:	1.99	Note:	Not Reported
Level reading date:	1957-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.11	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	2.34	Note:	Not Reported
Level reading date:	1957-08-26	Feet below surface:	Not Reported
Feet to sea level:	2.51	Note:	Not Reported
Level reading date:	1957-07-24	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.67	Note:	Not Reported
Level reading date:	1957-05-28	Feet below surface:	Not Reported
Feet to sea level:	2.76	Note:	Not Reported

DRAFT

Level reading date:	1957-04-24	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	2.78	Note:	Not Reported
Level reading date:	1957-02-27	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1957-01-25	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	2.85	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	2.68	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	2.51	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	2.51	Note:	Not Reported
Level reading date:	1956-07-10	Feet below surface:	Not Reported
Feet to sea level:	2.53	Note:	Not Reported
Level reading date:	1956-06-04	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	2.41	Note:	Not Reported
Level reading date:	1956-03-06	Feet below surface:	Not Reported
Feet to sea level:	2.39	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	2.55	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1955-11-07	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1955-10-05	Feet below surface:	Not Reported
Feet to sea level:	2.26	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	1.67	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported
Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported

DRAFT

Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	1.83	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.73	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	1.68	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	1.62	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	1.26	Note:	Not Reported
Level reading date:	1954-11-29	Feet below surface:	Not Reported
Feet to sea level:	1.14	Note:	Not Reported
Level reading date:	1954-09-28	Feet below surface:	Not Reported
Feet to sea level:	0.96	Note:	Not Reported
Level reading date:	1954-08-23	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.05	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.12	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.23	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.39	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.48	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.60	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	1.45	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	1.44	Note:	Not Reported
Level reading date:	1953-10-26	Feet below surface:	Not Reported
Feet to sea level:	1.48	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported
Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported

DRAFT

Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	1.18	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	0.92	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	0.83	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	0.71	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	0.59	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	0.51	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	0.56	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	0.41	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	0.03	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	-0.22	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	-0.31	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-0.50	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	-0.93	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-1.07	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-1.06	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-1.67	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-1.74	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-1.69	Note:	Not Reported

DRAFT

Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-2.03	Note:	Not Reported
Level reading date:	1951-09-11	Feet below surface:	Not Reported
Feet to sea level:	-1.86	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.04	Note:	Not Reported
Level reading date:	1951-07-25	Feet below surface:	Not Reported
Feet to sea level:	-2.06	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	-1.89	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-2.24	Note:	Not Reported
Level reading date:	1951-04-26	Feet below surface:	Not Reported
Feet to sea level:	-1.72	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-2.59	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-2.55	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-2.75	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-2.92	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-2.37	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.96	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.91	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-2.76	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-2.55	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-2.33	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported

DRAFT

Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-2.03	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-2.16	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-2.57	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-3.04	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.08	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	-3.17	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-4.11	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-4.17	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-4.26	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-4.82	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-4.41	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-4.26	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-4.98	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1948-07-23	Feet below surface:	Not Reported
Feet to sea level:	-6.25	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-6.45	Note:	Not Reported
Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-6.60	Note:	Not Reported

DRAFT

Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-6.92	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-7.11	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-7.51	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-7.40	Note:	Not Reported
Level reading date:	1948-01-08	Feet below surface:	Not Reported
Feet to sea level:	-8.01	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-7.65	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-8.59	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-7.90	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-8.60	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-8.42	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-8.12	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-8.64	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-8.64	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-8.81	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-8.75	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-8.66	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-8.77	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-8.57	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-8.52	Note:	Not Reported

DRAFT

Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-8.49	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1947-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.39	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-8.15	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-8.12	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1946-03-15	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-8.15	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-8.28	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-8.31	Note:	Not Reported

DRAFT

Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-8.39	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-8.35	Note:	Not Reported
Level reading date:	1945-08-07	Feet below surface:	Not Reported
Feet to sea level:	-8.30	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-8.19	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-8.24	Note:	Not Reported
Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1945-03-05	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1944-11-03	Feet below surface:	Not Reported
Feet to sea level:	-8.47	Note:	Not Reported
Level reading date:	1944-10-05	Feet below surface:	Not Reported
Feet to sea level:	-8.50	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-8.79	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-8.63	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-8.58	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-8.63	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-8.64	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-8.78	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-8.78	Note:	Not Reported

DRAFT

Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-8.93	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-9.26	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-9.16	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-9.08	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-9.15	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-9.31	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-9.49	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-9.66	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-9.70	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-9.70	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-9.72	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-9.78	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-9.83	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-9.85	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-9.90	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-9.95	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-10.01	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-10.06	Note:	Not Reported

DRAFT

Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-10.08	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-10.12	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-10.21	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-10.26	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-10.29	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-10.32	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-10.37	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-10.41	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-10.45	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-10.50	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-10.57	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-10.58	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-10.62	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-10.61	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-10.65	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-10.61	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-10.59	Note:	Not Reported

DRAFT

Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-10.52	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-10.51	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-10.48	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-10.46	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-10.42	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-10.42	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-10.39	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-10.36	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-10.40	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-10.38	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-10.33	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-10.31	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-10.27	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-10.23	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-10.19	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-10.15	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-10.13	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-10.13	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-10.10	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-10.06	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-10.03	Note:	Not Reported

DRAFT

Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-9.99	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-9.96	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-9.90	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-9.91	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-9.88	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-9.87	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-9.86	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-9.80	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-9.80	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-9.74	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-9.68	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-9.65	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-9.63	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-9.65	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-9.65	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-9.63	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-9.60	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-9.60	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-9.56	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-9.50	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-9.45	Note:	Not Reported

DRAFT

Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-9.42	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-9.38	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-9.35	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-9.33	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-9.18	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-9.14	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-9.06	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-9.06	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-9.01	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-8.95	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-8.89	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-8.84	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-8.84	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-8.89	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-8.87	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-8.91	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-9.03	Note:	Not Reported

DRAFT

Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-9.07	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-9.12	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-9.15	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-9.17	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-9.19	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported

22
WSW **FED USGS** **USGS40000828135**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 136. 1	Type:	Well
Description:	5201	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

F23
East **FED USGS** **USGS40000828148**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3271. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	34
Well Depth Units:	ft	Well Hole Depth:	34
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	127	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	6.27
Note:	Not Reported		
Level reading date:	2005-01-21	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	6.26	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	6.25	Note:	Not Reported
Level reading date:	2004-11-23	Feet below surface:	Not Reported
Feet to sea level:	6.28	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	6.53	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	6.58	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	6.64	Note:	Not Reported
Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	6.57	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	6.10	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	6.22	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	6.17	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	5.95	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	6.29	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	6.03	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	6.00	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	6.09	Note:	Not Reported
Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	6.26	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	6.34	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	6.55	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	5.96	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	6.07	Note:	Not Reported

DRAFT

Level reading date:	2003-03-18	Feet below surface:	Not Reported
Feet to sea level:	6.04	Note:	Not Reported
Level reading date:	2003-01-28	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	2002-11-25	Feet below surface:	Not Reported
Feet to sea level:	6.04	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	5.93	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	2002-08-27	Feet below surface:	Not Reported
Feet to sea level:	5.39	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	5.53	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	5.60	Note:	Not Reported
Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	5.60	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	5.48	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	5.52	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	5.61	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	5.72	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	5.91	Note:	Not Reported
Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	5.93	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	6.01	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	6.07	Note:	Not Reported

DRAFT

Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	5.99	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	6.20	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	5.92	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	5.86	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	5.73	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	5.69	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	5.97	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	6.03	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	6.00	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	5.97	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	5.99	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	5.98	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	5.83	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	5.74	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	5.73	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	5.67	Note:	Not Reported

DRAFT

Level reading date:	1999-07-16	Feet below surface:	Not Reported
Feet to sea level:	5.64	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	5.74	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	5.83	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	5.96	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	6.29	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	6.30	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	6.52	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	5.94	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	6.23	Note:	Not Reported
Level reading date:	1998-04-29	Feet below surface:	Not Reported
Feet to sea level:	6.39	Note:	Not Reported
Level reading date:	1998-03-26	Feet below surface:	Not Reported
Feet to sea level:	6.08	Note:	Not Reported
Level reading date:	1998-02-25	Feet below surface:	Not Reported
Feet to sea level:	6.20	Note:	Not Reported
Level reading date:	1998-01-27	Feet below surface:	Not Reported
Feet to sea level:	6.13	Note:	Not Reported
Level reading date:	1997-12-29	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	1997-11-25	Feet below surface:	Not Reported
Feet to sea level:	6.20	Note:	Not Reported
Level reading date:	1997-10-29	Feet below surface:	Not Reported
Feet to sea level:	6.24	Note:	Not Reported
Level reading date:	1997-09-29	Feet below surface:	Not Reported
Feet to sea level:	6.48	Note:	Not Reported
Level reading date:	1997-03-24	Feet below surface:	Not Reported
Feet to sea level:	5.98	Note:	Not Reported
Level reading date:	1996-07-05	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported

DRAFT

Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	5.93	Note:	Not Reported
Level reading date:	1995-09-29	Feet below surface:	Not Reported
Feet to sea level:	5.38	Note:	Not Reported
Level reading date:	1995-06-21	Feet below surface:	Not Reported
Feet to sea level:	5.48	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	5.63	Note:	Not Reported
Level reading date:	1995-01-03	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported
Level reading date:	1994-03-24	Feet below surface:	Not Reported
Feet to sea level:	4.52	Note:	Not Reported
Level reading date:	1993-08-24	Feet below surface:	Not Reported
Feet to sea level:	5.01	Note:	Not Reported
Level reading date:	1993-07-22	Feet below surface:	Not Reported
Feet to sea level:	4.90	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	5.16	Note:	Not Reported
Level reading date:	1993-05-24	Feet below surface:	Not Reported
Feet to sea level:	5.43	Note:	Not Reported
Level reading date:	1993-04-28	Feet below surface:	Not Reported
Feet to sea level:	6.01	Note:	Not Reported
Level reading date:	1993-03-22	Feet below surface:	Not Reported
Feet to sea level:	6.10	Note:	Not Reported
Level reading date:	1993-01-19	Feet below surface:	Not Reported
Feet to sea level:	5.89	Note:	Not Reported
Level reading date:	1992-12-28	Feet below surface:	Not Reported
Feet to sea level:	5.95	Note:	Not Reported
Level reading date:	1992-11-19	Feet below surface:	Not Reported
Feet to sea level:	5.68	Note:	Not Reported
Level reading date:	1992-10-27	Feet below surface:	Not Reported
Feet to sea level:	5.73	Note:	Not Reported
Level reading date:	1992-09-18	Feet below surface:	Not Reported
Feet to sea level:	5.89	Note:	Not Reported
Level reading date:	1992-08-24	Feet below surface:	Not Reported
Feet to sea level:	6.20	Note:	Not Reported
Level reading date:	1992-07-16	Feet below surface:	Not Reported
Feet to sea level:	5.87	Note:	Not Reported
Level reading date:	1992-06-23	Feet below surface:	Not Reported
Feet to sea level:	5.73	Note:	Not Reported
Level reading date:	1992-06-12	Feet below surface:	Not Reported
Feet to sea level:	5.82	Note:	Not Reported

DRAFT

Level reading date:	1992-03-17	Feet below surface:	Not Reported
Feet to sea level:	5.73	Note:	Not Reported
Level reading date:	1991-03-20	Feet below surface:	Not Reported
Feet to sea level:	6.22	Note:	Not Reported
Level reading date:	1990-03-27	Feet below surface:	Not Reported
Feet to sea level:	5.52	Note:	Not Reported
Level reading date:	1989-03-08	Feet below surface:	Not Reported
Feet to sea level:	5.27	Note:	Not Reported
Level reading date:	1985-10-02	Feet below surface:	Not Reported
Feet to sea level:	4.79	Note:	Not Reported
Level reading date:	1985-05-20	Feet below surface:	Not Reported
Feet to sea level:	4.63	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.92	Note:	Not Reported
Level reading date:	1984-10-03	Feet below surface:	Not Reported
Feet to sea level:	5.09	Note:	Not Reported
Level reading date:	1984-06-26	Feet below surface:	Not Reported
Feet to sea level:	5.61	Note:	Not Reported
Level reading date:	1984-03-27	Feet below surface:	Not Reported
Feet to sea level:	5.32	Note:	Not Reported
Level reading date:	1984-03-19	Feet below surface:	Not Reported
Feet to sea level:	5.51	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	5.47	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	5.60	Note:	Not Reported
Level reading date:	1983-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.85	Note:	Not Reported
Level reading date:	1983-03-22	Feet below surface:	Not Reported
Feet to sea level:	5.20	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	4.46	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	4.72	Note:	Not Reported
Level reading date:	1982-06-01	Feet below surface:	Not Reported
Feet to sea level:	4.85	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	4.83	Note:	Not Reported
Level reading date:	1981-09-22	Feet below surface:	Not Reported
Feet to sea level:	4.80	Note:	Not Reported
Level reading date:	1981-06-30	Feet below surface:	Not Reported
Feet to sea level:	4.86	Note:	Not Reported

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F24
East
1/2 - 1 Mile
Lower

FED USGS **USGS40000828149**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3271. 2	Type:	Well
Description:	S/E CORNER OF ELDERT LAND AND SUTTER AVE, ENY		
HUC:	02030202	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	20050606	Well Depth:	45
Well Depth Units:	ft	Well Hole Depth:	45
Well Hole Depth Units:	ft		

25
West
1/2 - 1 Mile
Higher

FED USGS **USGS40000828169**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2622. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	105
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

26
NE
1/2 - 1 Mile
Lower

FED USGS **USGS40000828517**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 141. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	20-foot Clay
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	64	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

DRAFT

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

27
ENE
1/2 - 1 Mile
Lower | **FED USGS** | **USGS40000828433**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1194. 5	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	20021003	Well Depth:	55
Well Depth Units:	ft	Well Hole Depth:	55
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	23	Level reading date:	2005-02-01
Feet below surface:	Not Reported	Feet to sea level:	8.49
Note:	Not Reported		

Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	8.50	Note:	Not Reported
Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	8.53	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	8.46	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	8.57	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	8.58	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	8.32	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	8.41	Note:	Not Reported
Level reading date:	2004-01-30	Feet below surface:	Not Reported
Feet to sea level:	8.44	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	8.64	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	8.36	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	8.40	Note:	Not Reported
Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	8.00	Note:	Not Reported

DRAFT

Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	8.49	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	8.77	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	8.03	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	8.20	Note:	Not Reported
Level reading date:	2003-02-26	Feet below surface:	Not Reported
Feet to sea level:	8.15	Note:	Not Reported
Level reading date:	2003-01-28	Feet below surface:	Not Reported
Feet to sea level:	8.02	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	7.97	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	8.00	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	8.03	Note:	Not Reported

G28
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000827670**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3256. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	29
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	54	Level reading date:	1999-06-24
Feet below surface:	Not Reported	Feet to sea level:	6.20
Note:	Not Reported		
Level reading date:	1997-07-23	Feet below surface:	Not Reported
Feet to sea level:	5.75	Note:	Not Reported
Level reading date:	1997-06-26	Feet below surface:	Not Reported
Feet to sea level:	5.81	Note:	Not Reported
Level reading date:	1997-03-17	Feet below surface:	Not Reported
Feet to sea level:	5.78	Note:	Not Reported
Level reading date:	1997-02-26	Feet below surface:	Not Reported
Feet to sea level:	5.89	Note:	Not Reported
Level reading date:	1996-07-05	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	5.40	Note:	Not Reported
Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	5.30	Note:	Not Reported
Level reading date:	1995-09-29	Feet below surface:	Not Reported
Feet to sea level:	5.26	Note:	Not Reported
Level reading date:	1995-06-21	Feet below surface:	Not Reported
Feet to sea level:	5.31	Note:	Not Reported
Level reading date:	1995-01-03	Feet below surface:	Not Reported
Feet to sea level:	5.51	Note:	Not Reported
Level reading date:	1994-06-29	Feet below surface:	Not Reported
Feet to sea level:	5.69	Note:	Not Reported
Level reading date:	1994-03-24	Feet below surface:	Not Reported
Feet to sea level:	6.01	Note:	Not Reported
Level reading date:	1993-11-22	Feet below surface:	Not Reported
Feet to sea level:	5.28	Note:	Not Reported
Level reading date:	1993-08-24	Feet below surface:	Not Reported
Feet to sea level:	5.48	Note:	Not Reported
Level reading date:	1993-07-22	Feet below surface:	Not Reported
Feet to sea level:	5.46	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	5.58	Note:	Not Reported
Level reading date:	1993-05-24	Feet below surface:	Not Reported
Feet to sea level:	5.88	Note:	Not Reported
Level reading date:	1993-04-28	Feet below surface:	Not Reported
Feet to sea level:	6.13	Note:	Not Reported
Level reading date:	1993-03-22	Feet below surface:	Not Reported
Feet to sea level:	5.70	Note:	Not Reported
Level reading date:	1993-01-19	Feet below surface:	Not Reported
Feet to sea level:	5.75	Note:	Not Reported
Level reading date:	1992-12-28	Feet below surface:	Not Reported
Feet to sea level:	5.93	Note:	Not Reported
Level reading date:	1992-11-19	Feet below surface:	Not Reported
Feet to sea level:	5.56	Note:	Not Reported
Level reading date:	1992-10-27	Feet below surface:	Not Reported
Feet to sea level:	5.71	Note:	Not Reported
Level reading date:	1992-09-18	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	1992-08-24	Feet below surface:	Not Reported
Feet to sea level:	6.25	Note:	Not Reported
Level reading date:	1992-07-16	Feet below surface:	Not Reported
Feet to sea level:	5.98	Note:	Not Reported

DRAFT

Level reading date:	1992-06-23	Feet below surface:	Not Reported
Feet to sea level:	5.77	Note:	Not Reported
Level reading date:	1992-06-12	Feet below surface:	Not Reported
Feet to sea level:	5.74	Note:	Not Reported
Level reading date:	1992-03-17	Feet below surface:	Not Reported
Feet to sea level:	5.23	Note:	Not Reported
Level reading date:	1991-03-19	Feet below surface:	Not Reported
Feet to sea level:	6.11	Note:	Not Reported
Level reading date:	1990-03-27	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported
Level reading date:	1989-03-08	Feet below surface:	Not Reported
Feet to sea level:	6.07	Note:	Not Reported
Level reading date:	1985-10-02	Feet below surface:	Not Reported
Feet to sea level:	5.45	Note:	Not Reported
Level reading date:	1985-05-20	Feet below surface:	Not Reported
Feet to sea level:	4.34	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.71	Note:	Not Reported
Level reading date:	1984-10-03	Feet below surface:	Not Reported
Feet to sea level:	6.26	Note:	Not Reported
Level reading date:	1984-06-26	Feet below surface:	Not Reported
Feet to sea level:	6.21	Note:	Not Reported
Level reading date:	1984-03-27	Feet below surface:	Not Reported
Feet to sea level:	5.63	Note:	Not Reported
Level reading date:	1984-03-19	Feet below surface:	Not Reported
Feet to sea level:	5.63	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	5.46	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	4.96	Note:	Not Reported
Level reading date:	1983-06-28	Feet below surface:	Not Reported
Feet to sea level:	5.86	Note:	Not Reported
Level reading date:	1983-03-22	Feet below surface:	Not Reported
Feet to sea level:	5.37	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	5.40	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	6.16	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	6.25	Note:	Not Reported
Level reading date:	1982-03-26	Feet below surface:	Not Reported
Feet to sea level:	6.10	Note:	Not Reported

DRAFT

Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	6.30	Note:	Not Reported
Level reading date:	1981-09-22	Feet below surface:	Not Reported
Feet to sea level:	6.15	Note:	Not Reported
Level reading date:	1981-06-30	Feet below surface:	Not Reported
Feet to sea level:	6.12	Note:	Not Reported
Level reading date:	1981-03-19	Feet below surface:	Not Reported
Feet to sea level:	6.69	Note:	Not Reported
Level reading date:	1981-02-10	Feet below surface:	Not Reported
Feet to sea level:	6.66	Note:	Not Reported
Level reading date:	1980-12-24	Feet below surface:	Not Reported
Feet to sea level:	6.86	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	7.04	Note:	Not Reported

G29
SSW **FED USGS** **USGS40000827671**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3256. 2	Type:	Well
Description:	RIVERDALE AVE & MILLER AVE & NEW LOTS AVE		
HUC:	02030202	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	19980624	Well Depth:	40
Well Depth Units:	ft	Well Hole Depth:	40
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	72	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	5.97
Note:	Not Reported		
Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	6.01	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	5.99	Note:	Not Reported
Level reading date:	2004-11-23	Feet below surface:	Not Reported
Feet to sea level:	5.84	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	6.02	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	6.04	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	5.99	Note:	Not Reported

DRAFT

Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	5.79	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	5.67	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	5.79	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	5.83	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	5.61	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	5.63	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	5.84	Note:	Not Reported
Level reading date:	2003-11-22	Feet below surface:	Not Reported
Feet to sea level:	5.72	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	5.64	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	5.84	Note:	Not Reported
Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	6.05	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	6.07	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	6.44	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	5.75	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	5.96	Note:	Not Reported
Level reading date:	2003-03-18	Feet below surface:	Not Reported
Feet to sea level:	5.95	Note:	Not Reported
Level reading date:	2003-02-27	Feet below surface:	Not Reported
Feet to sea level:	5.88	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	5.78	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	5.84	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	5.88	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	5.47	Note:	Not Reported

DRAFT

Level reading date:	2002-08-27	Feet below surface:	Not Reported
Feet to sea level:	5.09	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	5.22	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	5.44	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	5.40	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	5.15	Note:	Not Reported
Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	5.09	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	5.02	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	5.10	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	5.21	Note:	Not Reported
Level reading date:	2001-11-15	Feet below surface:	Not Reported
Feet to sea level:	5.29	Note:	Not Reported
Level reading date:	2001-10-24	Feet below surface:	Not Reported
Feet to sea level:	5.43	Note:	Not Reported
Level reading date:	2001-09-26	Feet below surface:	Not Reported
Feet to sea level:	5.55	Note:	Not Reported
Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	5.65	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	5.79	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	5.94	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	5.92	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	6.15	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	5.72	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	5.58	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	5.56	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported

DRAFT

Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	5.83	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	5.83	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	5.82	Note:	Not Reported
Level reading date:	2000-03-23	Feet below surface:	Not Reported
Feet to sea level:	5.74	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	5.55	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	5.58	Note:	Not Reported
Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	5.69	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	5.91	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	5.64	Note:	Not Reported
Level reading date:	1999-07-16	Feet below surface:	Not Reported
Feet to sea level:	5.70	Note:	Not Reported
Level reading date:	1999-06-24	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	5.80	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	5.88	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	6.05	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	6.01	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	6.03	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	5.63	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	5.67	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	5.72	Note:	Not Reported

DRAFT

Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	5.86	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	6.04	Note:	Not Reported

30
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000827849**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1266. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	41
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	300	Level reading date:	1968-04-30
Feet below surface:	Not Reported	Feet to sea level:	4.51
Note:	Not Reported		
Level reading date:	1967-11-09	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.55	Note:	Not Reported
Level reading date:	1966-10-25	Feet below surface:	Not Reported
Feet to sea level:	3.09	Note:	Not Reported
Level reading date:	1966-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1965-09-16	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1965-04-29	Feet below surface:	Not Reported
Feet to sea level:	3.70	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	3.85	Note:	Not Reported
Level reading date:	1963-11-05	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported
Level reading date:	1963-04-25	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1962-11-09	Feet below surface:	Not Reported
Feet to sea level:	3.86	Note:	Not Reported
Level reading date:	1962-04-03	Feet below surface:	Not Reported

DRAFT

Feet to sea level:	4.33	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.30	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	4.28	Note:	Not Reported
Level reading date:	1961-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.26	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	4.19	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	3.77	Note:	Not Reported
Level reading date:	1960-09-27	Feet below surface:	Not Reported
Feet to sea level:	3.77	Note:	Not Reported
Level reading date:	1960-07-01	Feet below surface:	Not Reported
Feet to sea level:	3.22	Note:	Not Reported
Level reading date:	1960-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.40	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	3.06	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1959-07-13	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1959-03-20	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported
Level reading date:	1957-12-30	Feet below surface:	Not Reported
Feet to sea level:	1.49	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.95	Note:	Not Reported
Level reading date:	1957-03-28	Feet below surface:	Not Reported
Feet to sea level:	3.00	Note:	Not Reported
Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	2.52	Note:	Not Reported
Level reading date:	1955-01-26	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1954-08-24	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.74	Note:	Not Reported

DRAFT

Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.90	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.90	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.85	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.87	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.83	Note:	Not Reported
Level reading date:	1953-12-26	Feet below surface:	Not Reported
Feet to sea level:	1.84	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	2.08	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1953-10-26	Feet below surface:	Not Reported
Feet to sea level:	2.50	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.53	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1953-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.74	Note:	Not Reported
Level reading date:	1953-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.98	Note:	Not Reported
Level reading date:	1953-04-29	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	2.42	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	2.12	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.97	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	2.04	Note:	Not Reported

DRAFT

Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	2.32	Note:	Not Reported
Level reading date:	1952-08-26	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	2.49	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.40	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.01	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	1.57	Note:	Not Reported
Level reading date:	1952-02-19	Feet below surface:	Not Reported
Feet to sea level:	1.48	Note:	Not Reported
Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	1.00	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	0.84	Note:	Not Reported
Level reading date:	1951-10-03	Feet below surface:	Not Reported
Feet to sea level:	0.40	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	0.62	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	0.52	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	0.60	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	0.69	Note:	Not Reported
Level reading date:	1951-05-01	Feet below surface:	Not Reported
Feet to sea level:	0.54	Note:	Not Reported
Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	0.28	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-0.12	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported

DRAFT

Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	0.22	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-0.30	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-0.32	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.51	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.33	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-0.35	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.36	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.20	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-0.49	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-0.76	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-0.65	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-0.89	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-0.75	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-1.07	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-1.63	Note:	Not Reported

DRAFT

Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-1.83	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.89	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-1.96	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-2.06	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-2.59	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-3.10	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-2.80	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1948-04-28	Feet below surface:	Not Reported
Feet to sea level:	-3.66	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-3.94	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-4.32	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-3.94	Note:	Not Reported
Level reading date:	1948-01-09	Feet below surface:	Not Reported
Feet to sea level:	-4.82	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-5.04	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-5.34	Note:	Not Reported

DRAFT

Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-5.27	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-5.26	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-5.30	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-5.27	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-5.22	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-5.16	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-5.12	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-5.11	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-5.14	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-5.08	Note:	Not Reported
Level reading date:	1947-04-03	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-4.85	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-4.96	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-4.90	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-4.83	Note:	Not Reported

DRAFT

Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-4.45	Note:	Not Reported
Level reading date:	1946-07-05	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-4.52	Note:	Not Reported
Level reading date:	1946-05-09	Feet below surface:	Not Reported
Feet to sea level:	-5.10	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1946-03-15	Feet below surface:	Not Reported
Feet to sea level:	-4.98	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-4.83	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-5.20	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-5.24	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-5.12	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-5.97	Note:	Not Reported
Level reading date:	1945-07-04	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-4.91	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-5.17	Note:	Not Reported
Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-5.04	Note:	Not Reported
Level reading date:	1945-03-05	Feet below surface:	Not Reported
Feet to sea level:	-5.11	Note:	Not Reported
Level reading date:	1945-01-03	Feet below surface:	Not Reported
Feet to sea level:	-4.98	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-5.08	Note:	Not Reported

DRAFT

Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-5.09	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-5.08	Note:	Not Reported
Level reading date:	1944-09-01	Feet below surface:	Not Reported
Feet to sea level:	-5.51	Note:	Not Reported
Level reading date:	1944-08-01	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1944-06-03	Feet below surface:	Not Reported
Feet to sea level:	-5.15	Note:	Not Reported
Level reading date:	1944-04-25	Feet below surface:	Not Reported
Feet to sea level:	-5.42	Note:	Not Reported
Level reading date:	1944-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.66	Note:	Not Reported
Level reading date:	1944-03-07	Feet below surface:	Not Reported
Feet to sea level:	-6.07	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-5.81	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-5.90	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-6.15	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.96	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-5.77	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.92	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-6.04	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported

DRAFT

Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-6.39	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-6.64	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-6.55	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-6.59	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-6.70	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-6.81	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-6.81	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-6.83	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-6.86	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-6.88	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-6.90	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-6.91	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-6.98	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-7.00	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-7.08	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-7.23	Note:	Not Reported

DRAFT

Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-7.18	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-7.26	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-7.42	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-7.19	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-7.27	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported

DRAFT

Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-7.15	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-7.10	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-7.21	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-6.77	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-6.77	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-6.74	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-6.71	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-6.48	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-6.55	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-6.54	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-6.49	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-6.22	Note:	Not Reported

DRAFT

Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-6.40	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-6.29	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-6.19	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.17	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-6.02	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.01	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-5.86	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-5.92	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-5.76	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-5.73	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-5.19	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-5.68	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-5.41	Note:	Not Reported
Level reading date:	1937-06-15	Feet below surface:	Not Reported
Feet to sea level:	-4.28	Note:	Not Reported

DRAFT

Level reading date:	1937-03-23	Feet below surface:	Not Reported
Feet to sea level:	-3.77	Note:	Not Reported
Level reading date:	1937-02-02	Feet below surface:	Not Reported
Feet to sea level:	-3.97	Note:	Not Reported
Level reading date:	1936-12-29	Feet below surface:	Not Reported
Feet to sea level:	-3.70	Note:	Not Reported
Level reading date:	1936-09-24	Feet below surface:	Not Reported
Feet to sea level:	-4.70	Note:	Not Reported
Level reading date:	1936-07-21	Feet below surface:	Not Reported
Feet to sea level:	-4.14	Note:	Not Reported
Level reading date:	1936-06-11	Feet below surface:	Not Reported
Feet to sea level:	-4.04	Note:	Not Reported
Level reading date:	1936-04-20	Feet below surface:	Not Reported
Feet to sea level:	-3.68	Note:	Not Reported
Level reading date:	1936-03-16	Feet below surface:	Not Reported
Feet to sea level:	-3.75	Note:	Not Reported
Level reading date:	1935-12-11	Feet below surface:	Not Reported
Feet to sea level:	-4.31	Note:	Not Reported
Level reading date:	1935-10-24	Feet below surface:	Not Reported
Feet to sea level:	-4.37	Note:	Not Reported
Level reading date:	1935-09-13	Feet below surface:	Not Reported
Feet to sea level:	-4.42	Note:	Not Reported
Level reading date:	1935-07-01	Feet below surface:	Not Reported
Feet to sea level:	-3.73	Note:	Not Reported
Level reading date:	1935-05-28	Feet below surface:	Not Reported
Feet to sea level:	-3.51	Note:	Not Reported
Level reading date:	1935-04-01	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1935-03-04	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1935-01-02	Feet below surface:	Not Reported
Feet to sea level:	-3.14	Note:	Not Reported
Level reading date:	1934-12-07	Feet below surface:	Not Reported
Feet to sea level:	-3.07	Note:	Not Reported
Level reading date:	1934-11-09	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1934-10-18	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1934-09-20	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1934-08-21	Feet below surface:	Not Reported
Feet to sea level:	-3.47	Note:	Not Reported

DRAFT

Level reading date:	1934-08-01	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1934-07-09	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1934-06-13	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1934-04-11	Feet below surface:	Not Reported
Feet to sea level:	-2.82	Note:	Not Reported
Level reading date:	1934-03-22	Feet below surface:	Not Reported
Feet to sea level:	-2.41	Note:	Not Reported
Level reading date:	1934-01-09	Feet below surface:	Not Reported
Feet to sea level:	-2.90	Note:	Not Reported
Level reading date:	1933-12-11	Feet below surface:	Not Reported
Feet to sea level:	-2.67	Note:	Not Reported
Level reading date:	1933-11-22	Feet below surface:	Not Reported
Feet to sea level:	-2.73	Note:	Not Reported
Level reading date:	1933-11-02	Feet below surface:	Not Reported
Feet to sea level:	-2.37	Note:	Not Reported
Level reading date:	1933-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1933-08-29	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1933-07-25	Feet below surface:	Not Reported
Feet to sea level:	-2.60	Note:	Not Reported
Level reading date:	1933-06-28	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported
Level reading date:	1933-05-29	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1933-04-21	Feet below surface:	Not Reported
Feet to sea level:	-2.02	Note:	Not Reported

DRAFT

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

DRAFT

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

DRAFT

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

DRAFT

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

DRAFT

W152892-091025 - Freedom of Information Law Request

Message History (2)

DRAFT

On 9/10/2025 10:00:30 AM, New York DEC FOIL Center wrote:

Dear Kaitlyn:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 9/10/2025 and given the reference number FOIL #W152892-091025 for tracking purposes. You may expect the Department's response to your request no later than **10/8/2025**.

Record Requested: **Address: 98 Berriman Street, 112 Berriman Street, 114 Berriman Street Brooklyn, NY**
BBL: Block 3988, Lot 20, 24 and 25
Request: Any environmental reports for the site above pertaining to current or previous investigations, spills, or remediation. Reports we seek include any Remedial Investigation Work Plans, Remedial Investigation Reports, Remedial Action Work Plans, Remedial Action Reports, Remedial Closure Reports, Spill Reports, and tank closure documentation.

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

Click here to login to the FOIL Center.

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://newyorkdec.govqa.us/WEBAPP//_rs/RequestEdit.aspx?rid=152892

DRAFT

On 9/10/2025 10:00:29 AM, Kaitlyn Moses wrote:

Request Created on Public Portal

DRAFT

R004393-091025 - FOIL Records Request

Message History (2)

On 9/10/2025 10:05:01 AM, NYS DOH FOIL Records Access Center wrote:

NEW YORK STATE | Department of Health

RE: FOIL Records Request of September 10, 2025, Reference # R004393-091025

Dear Kaitlyn Moses,

The NYS Department of Health received a FOIL request from you on September 10, 2025. You requested:

"Address: 98 Berriman Street, 112 Berriman Street, 114 Berriman street Brooklyn, NY
BBL: block 3989 Lots 20, 24 and 25
Requesting a records search for any environmental incidents, hazardous materials, or hazardous waste information pertaining to the above property."

Your request is acknowledged by the Records Access Office of the New York State Department of Health and, if appropriate, will be forwarded to the responsive program area(s) to identify documents that are responsive to your request.

A determination as to whether your request is granted or denied will be reached in approximately 20 business days, on October 08, 2025. We will notify you in writing if the responsible program area(s) should require additional time to locate, assemble and review documents that may be responsive to your request.

DRAFT

Sincerely,

David J. Harvey, Records Access Officer

NYS Department of Health

To monitor the progress or update this request, please log into the FOIL Records Access Center

Powered by GovQA

On 9/10/2025 10:05:00 AM, Kaitlyn Moses wrote:

Request Created on Public Portal

DRAFT

APPENDIX D
Subject Property Photographs

DRAFT

Photo 1: View of the subject property from Berriman Street, facing west.

Photo 2: View of the subject property from the parking lot, facing northwest.

Photo 3: View of a building on the subject property from Berriman Street, facing west.

Photo 4: View of the subject property from Berriman Street, facing south.

Photo 5: View of the east-adjacent property, facing east.

Photo 6: View of the north-adjacent properties, facing north.

Photo 7: View of the south-adjacent property, facing southwest.

Photo 8: View of the west-adjacent properties, facing east.

Photo 9: View of the east side storm cellar entrance, facing west.

Photo 10: View of the east side entrance of the building on the subject property, facing west.

Photo 11: View of 275-gallon aboveground storage tank (AST) storing No. 2 fuel in storm cellar, facing northwest.

Photo 12: View of boiler in storm cellar, facing west.

DRAFT

Photo 13: View of floor under AST in storm cellar, facing west.

Photo 14: View of floor drain in storm cellar.



Photo 15: View of fill port from Berriman Street, facing west.

Photo 16: View of vent pipe from Berriman Street, facing northwest.



Photo 17: View of building interior, facing north.

Photo 18: View of building interior, facing west.

DRAFT



Photo 19: View of hydraulic lift and building interior, facing southwest.

Photo 20: View of AST in the building, facing south.

Photo 21: View of equipment and staining in the exterior auto towing yard/parking lot.

Photo 22: View of parking lot on the subject property, facing southwest

Photo 23: View of hydraulic equipment in the building on the subject property, facing west.

Photo 24: View of improperly labeled and stored hazardous materials in the building on the subject property.

Photo 25: View of sprinkler system in the storm cellar, facing north.



Photo 26: View of supply closet and floor staining within the building of the subject property.

Photo 27: View of floor staining and absorbent material inside the building.

Photo 28: View of floor staining and absorbent material inside the building.

Photo 29: View of batteries located within the building on the subject property.

Photo 30: View of improperly contained hazardous materials stored in the building on the subject property.