45 VAN SINDEREN COAL YARD AND GOLD LEAF FACTORY SITE
45 VAN SINDEREN AVENUE
BROOKLYN, NEW YORK 11207
TAX MAP ID: BLOCK 1576, LOT 1

PHASE I
ENVIRONMENTAL SITE ASSESSMENT
(ASTM E1527-21/40 CFR PART 312)

PREPARED FOR:

45 Van Sinderen Owner LLC
c/o
GO Herkimer Williams LLC
111 5th Avenue, 9th Floor
New York, NY 10003
and
Ailanthus Herkimer Williams LLC
634 Dean Street
Brooklyn, NY 11238

PREPARED BY:

P.W. Grosser Consulting, Inc.
630 Johnson Avenue, Suite 7
Bohemia, New York 11716
Phone: 631-589-6353
Fax: 631-589-8705

Jennifer Lewis, PG, Vice President — JenniferL@pwgrosser.com
Michael Pecoraro, Project Manager — MPecoraro@pwgrosser.com

PWGC Project Number: TOT2503

JUNE 2025

TABLE OF CONTENTS

PAGE

1.0 EXECUTIVE SUMMARY 1
2.0 INTRODUCTION 3
2.1 Purpose 3
2.2 Scope of Services 3
2.3 Definitions 3
2.4 Significant Assumptions 4
2.5 Limitations and Exceptions 4
2.6 Special Terms and Conditions 5
2.7 User Reliance 5
2.8 Data Gaps 6
2.9 Viability of Phase I ESA 6
3.0 PROPERTY DESCRIPTION AND PHYSICAL SETTING 7
3.1 Location and Legal Description 7
3.2 Subject Property Description and Improvements 7
3.2.1 Municipal Services and Utilities 7
3.3 Physical Setting 7
3.3.1 Regional Geology / Hydrogeology 7
3.3.2 Local Hydrogeology 8
3.3.3 Flood Potential 8
3.3.4 Direction and Distance to Nearest Surface Water 8
4.0 PROPERTY USAGE 9
4.1 Current Property Usage 9
4.2 Current Usage of Adjoining/Surrounding Properties 9
4.3 Historical Usage of Subject Property and Surrounding Properties 9
4.3.1 Sanborn Fire Insurance Maps 9
4.3.2 Historical Topographic Maps 13
4.3.3 Historical Aerial Photographs 14
4.3.4 City Directory Listings 16
4.3.5 Subject Property Historical Summary 18
4.3.6 Surrounding Area Historical Summary 18
5.0 USER PROVIDED INFORMATION 19
5.1 User Requirements 19
5.2 Title Records 19
5.3 Environmental Liens 19
5.4 Specialized Knowledge 19
5.5 Commonly Known or Reasonably Ascertainable Information 19
5.6 Valuation Reduction for Environmental Issues 19
5.7 Owner, Property Manager, and Occupant Information 19
5.8 Reason for Performing Phase I ESA 20
6.0 RECORDS REVIEW 21
6.1 Standard Environmental Record Sources 21
6.1.1 Federal Databases 21
6.1.2 State and Local Databases 22
6.1.3 EDR Databases 24
6.1.4 Orphan Sites 24
6.1.5 Sites of Potential Concern 24
6.2 Vapor Encroachment 25
6.3 Additional Environmental Record Sources 26
6.3.1 Freedom of Information Act Requests 26
6.3.2 Publicly Available Online Information 26
7.0 SITE RECONNAISSANCE 27
7.1 Methodology and Limiting Conditions 27
7.2 Aboveground Storage Tanks (AST) 27
7.3 Underground Storage Tanks (UST) 27

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

TABLE OF CONTENTS PAGE

7.4 Hazardous and Non-Hazardous Chemical Storage 27
7.5 Waste Generation, Storage, and Disposal 27
7.6 Polychlorinated Biphenyls (PCBs) 27
7.7 Additional Site Conditions 27
7.8 Neighboring Properties 28
8.0 INTERVIEWS 29
8.1 Current Owner 29
8.2 Occupant 29
8.3 Previous Environmental Reports 29
8.3.1 Phase I Environmental Site Assessment Report (September 2018) 29
8.3.2 Phase II Environmental Site Assessment Report (May 2024) 29
8.4 Local Government Officials 30
9.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM 1527-21 31
9.1 Wetland Delineation 31
9.2 Radon Risk Evaluation 31
9.3 Asbestos 31
9.4 Lead-Based Paint (LBP) 31
9.5 Mold 31
9.6 Historic Fill 32
9.7 Emerging Contaminants 32
9.7.1 Per- and Poly-Fluoroalkyl Substances 32
10.0 FINDINGS AND OPINIONS 33
11.0 CONCLUSIONS AND RECOMMENDATIONS 34
12.0 DEVIATIONS 35
13.0 REFERENCES 36
14.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL 37

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

TABLES

Table 2-1	Report Viability Dates
Table 4-1	Current Usage of Surrounding Properties
Table 4-2	Sanborn Map Summary – Subject Property
Table 4-3	Sanborn Map Summary – Surrounding Area
Table 4-4	Topographic Map Summary – Subject Property
Table 4-5	Topographic Map Summary – Surrounding Area
Table 4-6	Aerial Photograph Summary – Subject Property
Table 4-7	Aerial Photograph Summary – Surrounding Area
Table 4-8	City Directory Summary – Subject Property
Table 4-9	City Directory Summary – Surrounding Area
Table 6-1	Federal Databases Searched
Table 6-2	State and Local Databases Searched
Table 6-3	Additional Databases Searched
Table 7-1	Additional Site Conditions

FIGURES

Figure 1	Vicinity Map
Figure 2	Site Plan

APPENDICES

Appendix A	Site Photographs
Appendix B	Sanborn Maps
Appendix C	Topographic Maps
Appendix D	Aerial Photos
Appendix E	City Directory Report
Appendix F	Site Questionnaire and Relevant Documents
Appendix G	Radius Map Report
Appendix H	Vapor Encroachment Screening
Appendix I	Public Records
Appendix J	Site Inspection Checklist
Appendix K	Qualifications of Environmental Professional

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

1.0 EXECUTIVE SUMMARY

45 Van Sinderen Owner LLC (Client) retained P.W. Grosser Consulting, Inc. (PWGC) to prepare a Phase I Environmental Site Assessment (ESA) for the subject property located at 45 Van Sinderen Avenue, Brooklyn, New York. The purpose of the Phase I ESA was to identify and evaluate the presence of Recognized Environmental Conditions (RECs) at the subject property. RECs are the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

The subject property consists of one parcel located at 45 Van Sinderen Avenue in Brooklyn, New York. The subject property is located in the borough of Brooklyn in Kings County. The property is identified in the NYC Tax Map as Block 1576, Lot 1.

The subject property measures approximately 0.3 acres and is improved with an approximately 103-year-old (built in 1921) two-story warehouse and loft building covering approximately 40% of the lot on the south, with an attached storage yard to the north. The building has a partial cellar covering approximately half the building area on the west, featuring stone rubble walls with a superstructure of wood frame and masonry construction.

The subject property is currently used as the following:

- Garbage truck storage, north yard tenant.
- Great Goods Co, Inc., Amazon product distributor, tenant of first floor.
- Rented artist studio space, tenant of second floor of building on site.

Work was conducted in accordance with the American Society for Testing and Materials (ASTM) Standard E1527-21 (Standard Practices for Environmental Site Assessment: Phase I Environmental Site Assessment Process), 40 Code of Federal Regulations (CFR) Part 312 (Standards and Practices for All Appropriate Inquiry; Final Rule), and PWGC's proposal for services.

PWGC evaluated the findings associated with the subject property and identified three RECs, no HRECs, and no CRECs with respect to the subject property. Conditions determined to be RECs are detailed below:

- The subject property was historically used for coal and lime storage as part of a lumber yard from approximately 1888 to 1908. Lumber storage may result in treated wood containing chromated copper arsenate or creosote, which may leach into the subsurface through stormwater runoff. Coal

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

and lime storage similarly may result in subsurface impact through infiltration. There are no records confirming treated wood storage at the subject property; however, the presence of the lumber yard predates most environmental regulations and documentation related to past releases may not exist. As such, PWGC believes the past usage of the site as a lumber yard represents a REC.

- The subject property was historically used for gold foil manufacturing from approximately 1920 to 1934. Such usages are likely to have used/stored hazardous substances, such as sodium cyanide, and/or petroleum products. While there are no open spills or violations associated with the subject property, the gold foil manufacturing listing predates most environmental regulations and documentation related to past releases may not exist. As such, PWGC believes the past usage of the subject property for gold foil manufacturing represents a REC.
- Dark-stained soil/pavement was observed in the northern yard. The property is a storage yard for diesel-powered garbage trucks. The yard is poorly maintained with miscellaneous trash/junk stored across the property. The potential exists for the material causing the staining to the yard to impact the subsurface. As such, PWGC believes the presence of dark staining in the northern yard represents a REC.

Based on the identified RECs, PWGC recommends a supplemental Phase II ESA be performed at the subject property. The Phase II ESA should include:

- Additional soil sampling to more completely characterize subsurface soil and historic fill conditions.
    - Based on the potential PFAS impact from the garbage truck fire, and potential cyanide impact from the gold foil manufacturing usage, PWGC recommends including PFAS and cyanide in the soil sampling analyses.

Although not a part of the ASTM E1527-21 scope, the following additional concerns associated with the subject property must be considered:

- Based on inspection of the subject property, it is possible that ACM and/or lead-based paint are present within the structure. PWGC recommends that, prior to demolition or renovation of the building, a detailed asbestos and/or lead based paint survey should be performed by a qualified asbestos/lead inspector in accordance with applicable federal, state, and local regulations prior to renovation or demolition of the building; please note that the asbestos/lead inspection performed as part of this Phase I ESA does not meet those criteria.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

2.0 INTRODUCTION

2.1 Purpose

45 Van Sinderen Owner LLC (Client) retained P.W. Grosser Consulting, Inc. (PWGC) to prepare a Phase I Environmental Site Assessment (ESA) for the subject property located at 45 Van Sinderen Avenue, Brooklyn, New York. The purpose of the Phase I ESA was to identify and evaluate the presence of Recognized Environmental Conditions (RECs) at the subject property. RECs are the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

2.2 Scope of Services

The assessment consisted of a visual inspection of the subject property and surrounding areas, interviews, a review of historical information and aerial photographs, and a review of pertinent local, state, federal and facility records. Environmental Data Resources (EDR) of Shelton, Connecticut provided the following: a database search of environmental compliance records of sites within an ASTM standard radius of the property, a Sanborn fire insurance map search, historical topographic map search, historical aerial photograph search, and a historical telephone directory search.

PWGC reviewed the environmental database report compiled by EDR as a part of the assessment. The purpose of the review was to identify reported listings for the subject property or other properties in the vicinity of the subject property. Databases reviewed included federal and state lists of known or suspected contaminated sites, lists of known handlers or generators of hazardous waste, lists of known waste disposal facilities, and lists of aboveground and underground storage tanks (ASTs and USTs). PWGC's review of the database has been incorporated into this report along with a copy of the EDR report.

The work was conducted in accordance with the American Society for Testing and Materials (ASTM) Standard E1527-21 (Standard Practices for Environmental Site Assessment: Phase I Environmental Site Assessment Process), 40 CFR Part 312 (Standards and Practices for All Appropriate Inquiry; Final Rule) and PWGC's proposal for services.

2.3 Definitions

1. RECs are—(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

subject property under conditions that pose a material threat of a future release to the environment.

2. Historic RECs (HREC) are a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition.
3. Controlled RECs (CREC) are recognized environmental conditions (RECs) affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).
4. A *de minimus* condition is a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis* condition is not a recognized environmental condition nor a controlled recognized environmental condition.
5. Business environmental risk (BER) is a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in this practice. Consideration of BER issues may involve addressing one or more non-scope considerations.

2.4 Significant Assumptions

PWGC has made the following significant assumptions in the preparation of this report:

1. Groundwater Flow Direction – Based upon regional groundwater elevation maps and local topography, regional groundwater flow direction appears to be toward the southeast.
2. Regulatory Records Information - PWGC assumes that all information provided by EDR regarding the regulatory status of facilities within the ASTM Standard approximate minimum search distance is complete, accurate, and current.
3. Other - PWGC assumes that all information provided through interviews is complete and unbiased.

2.5 Limitations and Exceptions

The conclusions presented in this report are professional opinions based on the data described in this report. These opinions have been arrived at in accordance with currently accepted engineering and

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

hydrogeologic standards and practices applicable to this location and are subject to the following inherent limitations:

1. The data presented in this report are from visual inspections, examination of records in the public domain, and interviews with individuals having information about the subject property. The passage of time, manifestation of latent conditions, or occurrence of future events may require further exploration of the subject property, analysis of data, and re-evaluation of the findings, observations, and conclusions presented in this report.
2. The data reported and the findings, observations, and conclusions expressed are limited by the scope of work. The scope of work was defined by the request of the client.
3. No warranty or guarantee, whether expressed or implied, is made with respect to the data reported, findings, observations, or conclusions. These are based solely upon conditions in existence at subject property at the time of the investigation, and other information obtained and reviewed by PWGC.
4. PWGC's Phase I ESA report presents professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, or regulations or policies of federal, state, or local government agencies. PWGC does not assume liability for financial or other losses or subsequent damage caused by or related to any use of this document.
5. The conclusions presented in this report are professional opinions based on data described in this report. They are intended only for the purpose, subject property location, and project indicated. This report is not a definitive study of contamination at the subject property and should not be interpreted as such.
6. This report is based, in part, on information supplied to PWGC by third-party sources. While efforts have been made to substantiate this third-party information, PWGC cannot attest to the completeness or accuracy of information provided by others.

2.6 Special Terms and Conditions

Authorization to perform this assessment was given by a proposal for services between the Client and PWGC.

2.7 User Reliance

This report was prepared for the exclusive use of the Client. PWGC assumes no liability for use of this report by any person or entity other than those for which it was prepared.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

2.8 Data Gaps

Any data gaps identified herein, as defined by ASTM Practice E1527-21 § 3.2.19, are not considered to have significantly affected the ability to identify RECs in connection with the subject property and do not alter the conclusions of this report, unless otherwise noted. Data gaps identified during the preparation of this Phase I ESA include:

- Portions of the second floor were locked and inaccessible during site reconnaissance.
- The presence of multiple garbage trucks in the northern, open portion of the subject property obscured a significant portion of the yard, limiting the ability to inspect ground conditions.
- Reasonably ascertainable standard sources do not show pre-development conditions at the subject property. The earliest available source (1888 Sanborn Map) shows the subject property developed with residential buildings.
- Gaps of greater than five years (1888 to 1908, 1908 to 1924, 1984 to 1994, 1994 to 2006) was identified in the history of the subject property when reviewing of standard historical sources in ASTM Practice E 1527-21 § 8.3.4.1 through 8.3.4.8 that are reasonably ascertainable and likely to be useful.

Significant data gaps as defined by ASTM E1527-21 § 3.2.78 include data gaps that affect the ability of the environmental professional to identify a REC. No significant data gaps were identified.

2.9 Viability of Phase I ESA

Generally, in accordance with ASTM Practice E1527-21 § 4.6, a Phase I ESA for which the information was collected or updated within one year prior to the date of acquisition or date of the intended transaction may be used provided that the components of the ESA detailed in Table 2-1 were updated within 180 days prior to the date of purchase or date of the intended transaction.

Table 2-1 – Report Viability Dates

Phase I ESA Component	Date Completed
Interviews with Owner, Operators and/or Occupants	3/26/2025
Environmental Lien Search	N/A*
Government Records Review	3/19/2025
Site Reconnaissance	3/26/2025 & 4/8/2025
Declaration of Environmental Professional	6/16/2025

*The environmental lien search is a user requirement. PWGC was not contracted to perform one as part of this Phase I ESA.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

3.0 PROPERTY DESCRIPTION AND PHYSICAL SETTING

3.1 Location and Legal Description

The subject property consists of one parcel located at 45 Van Sinderen Avenue in Brooklyn, New York. The subject property is located in the borough of Brooklyn in Kings County. The property is identified in the NYC Tax Map as Block 1576, Lot 1.

A Site Location Map is included as **Figure 1** and a Site Plan is included as **Figure 2**; photos of the subject property are included in **Appendix A**.

3.2 Subject Property Description and Improvements

The subject property measures approximately 0.3 acres and is improved with an approximately 103-year-old (built in 1921) two-story warehouse and loft building covering approximately 40% of the lot on the south, with an attached storage yard to the north. The building has a partial cellar covering approximately half the building area on the west, featuring stone rubble walls with a superstructure of wood frame and masonry construction.

3.2.1 Municipal Services and Utilities

Utility services are provided to the property as follows:

- Heating/Cooling System – The building on the property is heated via a natural gas boiler heating system with natural gas supplied by National Grid and cooled via window-mounted air conditioning units.
- Water Supply – The property is connected to a municipal water supply system provided by the New York City Department of Environmental Protection (NYCDEP).
- Sanitary System – The property is connected to the New York City municipal sewer system.
- Electric – Electricity is provided to the property by Consolidated Edison.

3.3 Physical Setting

The topography of the subject property and surrounding area was reviewed from the USGS 7.5-minute series topographic map for the Brooklyn, New York quadrangle. The property elevation is approximately 70 feet above the National Geodetic Vertical Datum (NGVD). Regional physiographic conditions are summarized below.

3.3.1 Regional Geology / Hydrogeology

The geologic setting of Long Island is well documented and consists of crystalline bedrock composed of schist and gneiss overlain by layers of unconsolidated deposits. Immediately overlying the bedrock is the Raritan Formation, consisting of the Lloyd sand confined by the Raritan Clay Member. The Lloyd sand is

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

an aquifer and consists of discontinuous layers of gravel, sand, sandy and silty clay, and solid clay. The Raritan Clay is a solid and silty clay with: few lenses of sand and gravel, abundant lignite and pyrite, and gray, red, or white in color.

Above the Raritan Clay lies the Magothy Formation. The Magothy Aquifer consists of layers of fine to coarse sand of moderate to high permeability, with inter-bedded lenses of silt and clay of low permeability resulting in areas of preferential horizontal flow; therefore, this aquifer generally becomes more confined with depth. The Magothy Aquifer is overlain by the Upper Glacial Aquifer. The Upper Glacial Aquifer is the water table aquifer at this location and is comprised of medium to coarse sand and gravel with occasional thin lenses of fine sand and brown clay. This aquifer extends from the land surface to the top of the Magothy Aquifer; therefore, is hydraulically connected to the Magothy Aquifer.

3.3.2 Local Hydrogeology

Based upon the subject property elevation and regional groundwater contour maps, the depth to groundwater beneath the subject property is approximately 59 feet below existing grade. Regional groundwater flow is estimated to be toward the southeast direction.

Based upon information contained within the EDR report, there are no public water supply wells within a one-mile radius of the subject property.

3.3.3 Flood Potential

PWGC reviewed the Federal Emergency Management Agency (FEMA) Flood Insurance Rate Maps (FIRMs) to determine if the subject property is located within a flood hazard area. Based upon FIRM data, it appears that the subject property is/is not located within a Special Flood Hazard Area (1%) or a 0.2% Annual Chance Flood Hazard area (FEMA Map Panel ID: 3604970065B).

3.3.4 Direction and Distance to Nearest Surface Water

Based on topographic maps, no permanent surface water bodies are located within a one-mile radius of the subject property.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

4.0 PROPERTY USAGE

4.1 Current Property Usage

The subject property is currently used as the following:

- Garbage truck storage, north yard tenant.
- Great Goods Co, Inc., Amazon product distributor, tenant of first floor.
- Rented artist studio space, tenant of second floor of building on site.

4.2 Current Usage of Adjoining/Surrounding Properties

A summary of the surrounding properties is as follows:

Table 4-1 – Current Usage of Surrounding Properties

Direction	Adjoining Properties	Surrounding Area
North	Church inside a 2-story building.	Railroad lines and transportation property.
South	'Noble Signs' sign shop; East New York Inn.	Long Island Railroad line and station.
East	Parking lot beneath subway/railroad lines.	Railroad lines; NYC Transit Maintenance Facility.
West	Van Sinderen Avenue; Garage space.	Light industrial property and residential.

4.3 Historical Usage of Subject Property and Surrounding Properties

Historical sources researched to determine past usage of the subject property and surrounding properties are as follows:

4.3.1 Sanborn Fire Insurance Maps

EDR was retained to provide historical Sanborn fire insurance maps of the subject and adjacent properties. Historical Sanborn maps for the subject property and surrounding area were reviewed for the years available which include 1887 to 2007. Review of the maps is summarized in Table 4-2. A copy of the historical Sanborn report is included in **Appendix B**.

Table 4-2 – Sanborn Map Summary – Subject Property

Date	Subject Property Usage
1887	Reasonably ascertainable Sanborn maps do not exist.
1888	The northern portion of the property appears to be undeveloped. The southern portion appears to be used for lime and coal storage with a shed in the southwest corner of the property. The storage buildings are part of the Thatford and Ackerman Coal and Lumber Yard. A rail spur appears to service the property.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Subject Property Usage
1908	The Thatford and Ackerman Coal and lumber Yard has expanded farther to the north, encompassing the entirety of the subject property. A coal pocket occupies the eastern portion of the property. A wood sawing conveyor and engine are present on the northwestern portion of the property.
1928	Reasonably ascertainable Sanborn maps do not exist.
1932	The northern portion of the property appears to be undeveloped. The southern portion of the property is occupied by a small storage structure and a larger building, Rolled Gold Manufacturing.
1950	Reasonably ascertainable Sanborn maps do not exist.
1951-2007	The northern portion of the property appears to be undeveloped. The southern portion of the property is occupied by a small storage structure and a larger building, now used for instrument testing. This appears to be the currently existing building.

Table 4-3 – Sanborn Map Summary – Surrounding Area

Date	Adjoining Properties	Surrounding Area
North		
1887	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1888	One residential dwelling appears to be present.	Herkimer Street, undeveloped lots, residential dwellings.
1908	Two single-story buildings of unspecified usage appear to be present.	Herkimer Street, lumber yard, residential dwellings.
1928	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1932	One single-story storage building appears to be present.	Herkimer Street, undeveloped lot.
1950	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1951-1965	A two-story building with wired glass skylights is present, used for label weaving. A single-story storage building is present.	Herkimer Street, parking lot, and one small office building.
1967-1977	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1978-1989	A two-story building is present; the western portion is used as a Masonic Temple, the eastern portion is used as a public/institutional building.	Herkimer Street, parking lot, and one small office building.
1991-2007	The two-story building is used as a Baptist Church.	Herkimer Street, parking lot, and one small office building.
South		

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Adjoining Properties	Surrounding Area
1887	Reasonably ascertainable Sanborn maps do not exist.	Long Island Railroad.
1888	The southern portion of Thatford & Ackerman Coal & Lumber Yard is present; Two single-story buildings and one two-story building, office space, and planning mill.	Long Island Railroad.
1908	Multiple three- and four-story buildings are present (unspecified storefronts, one office and one residential dwelling).	Long Island Railroad.
1928	Reasonably ascertainable Sanborn maps do not exist.	Long Island Railroad.
1932	Multiple three- and four-story buildings are present (Palace Hotel, unspecified storefronts, and one office building).	Long Island Railroad . Concrete platforms developed for elevated rail line.
1950	Reasonably ascertainable Sanborn maps do not exist.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
1951	A clothing manufacturer, office, and a machine shop are present. One commercial building is now vacant.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long island Railroad.
1963-1965	Loft, manufacturing (unspecified), offices, commercial (unspecified), residential dwelling.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
1966-1977	Reasonably ascertainable Sanborn maps do not exist.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
1978-1982	The manufacturing building is no longer present. The loft, commercial (unspecified), and residential dwelling are still present.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
1983-1986	Reasonably ascertainable Sanborn maps do not exist.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
1987-2006	The commercial and residential buildings are no longer present. The loft is still present.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
2007	Loft, hotel.	Long Island Railroad. Concrete platforms developed for elevated rail line. Vehicular viaduct constructed over Long Island Railroad.
East		
1887	Reasonably ascertainable Sanborn maps do not exist.	Williams Street.
1888	Six undeveloped lots, paint shop, carpet shop.	Williams Place (formerly Street). Undeveloped lots are present across Williams Place.
1908	A stable is present, bottling and barreling.	Williams Place, residential dwellings.
1928	Reasonably ascertainable Sanborn maps do not exist.	Williams Place.
1932	B.M.T overhead tracks are present, iron works.	Auto sales and services (gasoline tank present), lumber yard.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Adjoining Properties	Surrounding Area
1950	Reasonably ascertainable Sanborn maps do not exist.	Williams Place.
1951	B.M.T overhead tracks are present, iron works.	Steel Manufacturing, lumber sawing and planing.
1963	B.M.T overhead tracks are present, iron works.	Steel Manufacturing, woodworking.
1965-1980	B.M.T overhead tracks are present, iron works.	Steel Manufacturing.
1981	Reasonably ascertainable Sanborn maps do not exist.	Williams Place.
1982-2007	B.M.T overhead tracks are present.	Steel Manufacturing.
West		
1887	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1888	Van Sinderen Avenue, commercial (unspecified), four undeveloped lots.	Undeveloped lots.
1908	Van Sinderen Avenue, commercial (unspecified), three undeveloped lots.	Undeveloped lots, residential dwelling.
1928	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1932	Van Sinderen Avenue, commercial (unspecified), two undeveloped lots, auto repair (gasoline tank present).	Undeveloped lots, residential apartments.
1950	Reasonably ascertainable Sanborn maps do not exist.	Reasonably ascertainable Sanborn maps do not exist.
1951	Van Sinderen Avenue, parking lot, auto repair (gasoline tank present).	Undeveloped lots, residential apartments.
1963	Van Sinderen Avenue, parking lot, warehouse, manufacturing (unspecified).	Undeveloped lots, residential apartments, commercial (unspecified).
1965-1993	Van Sinderen Avenue, steel cabinet manufacturing.	Undeveloped lots, parking area, residential apartments, commercial (unspecified).
1994-2001	Van Sinderen Avenue, steel cabinet manufacturing.	Undeveloped lots, bus parking, residential apartments, commercial (unspecified).
2002-2007	Van Sinderen Avenue, steel cabinet manufacturing.	Bus parking, residential apartments, storage building.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

4.3.2 *Historical Topographic Maps*

Historical topographic maps for the subject property and surrounding area were reviewed for the years available which include 1897 to 2019. Review of the maps is summarized in Table 4-3. Copies of historical topographic maps are included as **Appendix C**.

Table 4-4 – Topographic Map Summary – Subject Property

Date	Subject Property Usage
1897-2019	The subject property appears to be located within a developed, urban area; however, the resolution of reasonably ascertainable topographic maps is insufficient to draw conclusions as to the specific usage of the subject property.

Table 4-4 – Topographic Map Summary – Surrounding Area

Date	Adjoining Properties	Surrounding Area
North		
1897-1900	A railroad appears to be present.	A railroad appears to be present.
1947-1994	A railroad appears to be present.	Broadway Junction railroad tracks.
2013-2019	A railroad appears to be present.	A railroad appears to be present.
South		
1897-1900	A railroad appears to be present.	A railroad appears to be present.
1947-1994	Additional railroad tracks running east-west appear to be present.	A railroad and a railroad station appear to be present.
2013-2019	A railroad appears to be present.	A railroad appears to be present.
East		
1897-1947	A railroad appears to be present.	A railroad appears to be present.
1956-1994	Additional railroad tracks appear to be present.	A railroad appears to be present.
2013-2019	A railroad appears to be present.	A railroad appears to be present.
West		
1897-1900	The resolution of reasonably ascertainable topographic maps is insufficient to draw conclusions as to the specific usage of the adjoining property.	The resolution of reasonably ascertainable topographic maps is insufficient to draw conclusions as to the specific usage of the surrounding property.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Adjoining Properties	Surrounding Area
1947-2019	The resolution of reasonably ascertainable topographic maps is insufficient to draw conclusions as to the specific usage of the adjoining property.	Subway tracks appear to be present.

4.3.3 Historical Aerial Photographs

PWGC performed a review of readily available aerial photographs showing the subject property and surrounding area. Photographs were reviewed for the years available which include 1924 to 2019. Review of the photos is summarized in Table 4-4. A copy of the aerial photograph search is included in **Appendix D**.

Table 4-6 – Aerial Photograph Summary – Subject Property

Date	Subject Property Usage
1924-1961	The northern portion of the subject property appears to be undeveloped. The southern portion of the property appears to be developed with one small building (shed) and one larger building (with six skylights).
1966-1976	The resolution of reasonably ascertainable aerial photographs maps is insufficient to draw conclusions as to the specific usage of the subject property.
1980-1984	The larger building appears to have been renovated (the skylights no longer appear to be present). This appears to be the currently existing building.
1994	The shed no longer appears to be present.
2006-2015	The undeveloped northern portion of the property appears to be overgrown with vegetation.
2019	The undeveloped northern portion of the property no longer appears to be overgrown; vehicles appear to be staged in this area. This appears consistent with currently existing conditions at the subject property.

Table 4-7 – Aerial Photograph Summary – Surrounding Area

Date	Adjoining Properties	Surrounding Area
North		
1924	Appears to be undeveloped.	One building is present. Overhead train tracks.
1951-1976	Four buildings appear to be present.	One large building and a parking lot are present. Overhead train tracks.
1980-2019	Two buildings appear to be present (three of the previous buildings were replaced by one larger building).	One large building and a parking lot are present. Overhead train tracks.
South		

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Adjoining Properties	Surrounding Area
1924	Four buildings appear to be present.	Railroad tracks appear to be present.
1951-1980	Four buildings appear to be present.	Railroad tracks appear to be present. A roadway has been constructed over east-west-running tracks.
1984	Two buildings appear to be present.	Railroad tracks appear to be present. A roadway has been constructed over east-west-running tracks.
1994	One building appears to be present.	Railroad tracks appear to be present. A roadway has been constructed over east-west-running tracks.
2006	One building appears to be present, with an additional building under construction.	Railroad tracks appear to be present. A roadway has been constructed over east-west-running tracks.
2011-2019	Two buildings appear to be present.	Railroad tracks appear to be present. A roadway has been constructed over east-west-running tracks.
East		
1924	Railroad tracks appear to be present.	Industrial, commercial, and residential buildings are present
1951-1961	Railroad tracks appear to be present.	Industrial, commercial, and residential buildings are present. Additional commercial/industrial development to the northeast.
1966	Railroad tracks appear to be present.	Industrial, commercial, and residential buildings are present. The northeastern commercial/industrial building has been reconstructed.
1976	Railroad tracks appear to be present.	The resolution of reasonably ascertainable aerial photographs maps is insufficient to draw conclusions as to the specific usage of the surrounding property.
1980-2006	Railroad tracks appear to be present.	Industrial, commercial, and residential buildings are present. Additional commercial/industrial development has occurred to the southeast.
2011	Railroad tracks appear to be present.	Industrial, commercial, and residential buildings are present. Only one residential building is standing (the others have been demolished and replaced by a paved lot).
2015-2019	Railroad tracks appear to be present.	Industrial and commercial buildings are present. No residential buildings remain.
West		
1924	Road, one large building and seven smaller buildings appear to be present. A vehicle/storage yard appears to be present	Residential and commercial buildings are present.
1951-1954	Road, two large buildings, a vehicle/storage yard, and a parking lot appear to be present	Residential and commercial buildings are present.
1961-2019	Road, one large building, and a parking lot appear to be present.	Residential and commercial buildings are present.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

4.3.4 *City Directory Listings*

EDR was retained to provide a directory of historical telephone listings at the subject property and surrounding properties. City directories were reviewed for the years available which include 1928 to 2020. Review of city directories is summarized below. A copy of the city directory report is included as **Appendix E.**

Alternate addresses that appear to be associated with the subject property include the following:

- 45, 49, and 53 Van Sinderen Avenue.

Table 4-8 – City Directory Summary – Subject Property

Date	Subject Property Usage
1934	45 Van Sinderen: Schumacher Bros Rolled Gold Leaf Company.
1940	45 Van Sinderen: Terminix Insulation Co Inc., Waldrogel Bros.
1945-1976	45 Van Sinderen: Amthor Testing Instrument Co.
1997	45 Van Sinderen: Stanley Majerski.

Addresses that appear to be associated with the properties adjoining the subject property include the following:

- North: 25 to 25 Van Sinderen Avenue (odd addresses only), 1520-1530 Herkimer Street (even addresses only).
- South: 65 Van Sinderen Avenue, 2465 to 2475 Atlantic Avenue (odd addresses only).
- East: 50 to 54 Williams Place (even addresses only).
- West: 26 to 56 Van Sinderen Avenue (even addresses only). 1508 Herkimer Street.

Table 4-9 – City Directory Summary – Surrounding Area

Date	Adjoining Properties	Surrounding Area
North		
1940	35 Van Sinderen: Hercules Corner Bread Co.	No listings.
1985-2005	1520 Herkimer: Baptist church.	No listings.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Adjoining Properties	Surrounding Area
2010-2014	1520 Herkimer: Baptist church.	1515 Herkimer: 2020 Car Services
2017-2020	1520 Herkimer: Baptist church.	No listings.
South		
1928	2465 Atlantic: Triangle Electrical Supply. 2471 Atlantic: Western Union.	No listings.
1934	Residential listings.	No listings.
1940	2465 Atlantic: Palace Hotel. 2471 Atlantic: Western Union.	No listings.
1949	2465 Atlantic: Comet Pad Co. Inc., Sportwear Co., Undergarment Co. Residential listings.	No listings.
1960	2465 Atlantic: Contractor, lamp products. 2467 Atlantic: Apex Airtronics. 2471 Atlantic: Western Union	No listings.
1965	2465 Atlantic: Contractor. 2467 Atlantic: Apex Airtronics. 2471 Atlantic: Western Union Residential listings.	No listings.
1970	2465 Atlantic: Contractor. 2467 Atlantic: Apex Airtronics. Residential listings.	No listings.
1973-2000	2467 Atlantic: Apex Airtronics.	No listings.
2005	2465 Atlantic: Apex Airtronics. 2471 Atlantic: Uptown Demolition	No listings.
2010	2465 Atlantic: Apex Airtronics. 2473 Atlantic: Inn.	No listings.
2014-2017	2467 Atlantic: Apex Airtronics. 2473 Atlantic: Inn.	No listings.
2020	Residential listings.	No listings.
East		
1928-2020	No listings.	Commercial listings. 45 Williams: Lumber Co (1928-1945).
West		
1934	26 Van Sinderen: Ruth & Matthews, Inc. Residential listing.	No listings.
1960-1965	50 Van Sinderen: Atlantic Cabinet Corp.	No listings.
1970	38 Van Sinderen: Steel Cabinet Corp. 50 Van Sinderen: Atlantic Cabinet Corp.	No listings.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Date	Adjoining Properties	Surrounding Area
1973	50 Van Sinderen: Atlantic Cabinet Corp.	No listings.
1976	38 Van Sinderen: Knitting Mills.	No listings.
1992	38 Van Sinderen: Knitting Mills.	No listings.
1995-1997	38 Van Sinderen: Wrought Originals, Inc.	No listings.
2000	38 Van Sinderen: Wrought Originals, Inc., Display Depot, Inc.	No listings.

4.3.5 Subject Property Historical Summary

Based on review of historical sources, as described in Section 4.3.1 through 4.3.4, the subject property was first developed prior to 1888. The property was used for coal/lime storage for a lumber yard from approximately 1888 to 1908, Gold foil manufacturing from approximately 1932 to 1934, Terminix Insulation in 1940, instrument testing from approximately 1951 to 2007, and as a distribution warehouse and art studio (present day)

- industrial usage
- lumber yard

4.3.6 Surrounding Area Historical Summary

Based on review of historical sources, as described in Section 4.3.1 through 4.3.4, the area surrounding the subject property was first developed prior to 1888. Surrounding property development was a mix of residential, commercial, and industrial uses until approximately 1965, after which residential use decreased, and commercial/industrial usage increased to the present-day extent. Historical usage of properties in the surrounding area indicative of potential RECs include the following:

- lumber yard
- railroad
- steel manufacturing
- auto sales and services
- knitting mill

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

5.0 USER PROVIDED INFORMATION

5.1 User Requirements

The user of a Phase I ESA report, in accordance with the USEPA All Appropriate Inquiries (AAI) Rule and ASTM E1527-21 has certain responsibilities which include providing the following information, if available, to PWGC to be included within the Phase I Report. Additionally, PWGC provided the user of the report a User Questionnaire form. The information requested in the User Questionnaire is intended to assist in gathering information that may be material to identify if RECs are present at the subject property. A copy of the User Questionnaire and any provided documents are included in **Appendix F**; relevant information has been incorporated into this report.

5.2 Title Records

Title records for the subject property may contain information about past owners and uses of the subject property. The title report may also contain information, such as restrictive declarations which are limitations on site uses based upon know environmental conditions. As of the date of this report, the user has not provided PWGC with a title search or requested that PWGC perform a title search.

5.3 Environmental Liens

An environmental lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property, including, but not limited to, liens imposed pursuant to CERCLA 42 USC § 9607 (1) & 9607(r) and similar state and local laws. As of the date of this report, the user has not provided PWGC with a lien search or requested that PWGC perform a lien search.

5.4 Specialized Knowledge

The user provided no specialized knowledge about the property to PWGC.

5.5 Commonly Known or Reasonably Ascertainable Information

The user provided no commonly known information about the property to PWGC.

5.6 Valuation Reduction for Environmental Issues

The user provided no information regarding price adjustments to the subject parcels value due to environmental issues.

5.7 Owner, Property Manager, and Occupant Information

The subject property is currently owned by 2465 Atlantic LLC.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

The subject property is currently occupied by the following:

- Great Goods, Co., 1st floor warehouse
- Artist Studios, 2nd floor
- Garbage truck storage, north yard.

5.8 Reason for Performing Phase I ESA

The Phase I ESA was performed to evaluate potential RECs prior to a potential property transaction.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

6.0 RECORDS REVIEW

6.1 Standard Environmental Record Sources

EDR of Shelton, Connecticut was retained to provide a database search of the project area within an ASTM-standard radius of the subject property. A list of the databases searched and the search radius is shown on the summary table below. PWGC reviewed the database output to determine if the property appears on any of the regulatory agency lists. Detailed information concerning each database list is provided in the EDR report (**Appendix G**).

In order to evaluate the potential for a site to have an adverse impact to the subject property, the migration pattern of contaminants in media such as groundwater or soil vapor is considered. Based upon the presumed regional flow towards the southeast, the following is assumed:

- Sites located northwest of the subject property or sites that are neighboring or adjacent to the subject property are considered to have the highest potential to impact the subject property and are referred to as "up gradient."
- Sites located southeast of the subject property, which are not neighboring or adjacent to the subject property are considered to have the least potential to impact the subject property and are referred to as "down gradient."
- All other sites not adjacent to or neighboring the subject property are referred to as "cross gradient" and are considered to have minimal potential to impact the subject property.
- The migration pathway for potential soil vapor impact may not match the migration pattern of potential groundwater impact. As such, sites that are located down or cross gradient of the subject property with respect to groundwater flow may still represent a potential source of vapor encroachment at the subject property. Such sites, if identified are discussed in Section 6.2.

A summary of standard environmental record sources researched is as follows:

6.1.1 Federal Databases

The table below summarizes the Federal databases that were searched.

Table 6-1 - Federal Databases Searched

Agency	Listing Name or database Searched	Abbreviation	Search Distance	Target Property Identified	Total Nearby Properties Identified	Up Gradient and Adjacent Properties Identified	Down or Cross Gradient Properties Identified
USEPA	National Priority List	NPL	1.0 mile	No	1	1	0
USEPA	National Priority List Deletions	Delisted NPL	0.5 mile	No	0	0	0

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Agency	Listing Name or database Searched	Abbreviation	Search Distance	Target Property Identified	Total Nearby Properties Identified	Up Gradient and Adjacent Properties Identified	Down or Cross Gradient Properties Identified
USEPA	Superfund Enterprise Management System	SEMS	0.5 mile	No	0	0	0
USEPA	Superfund Enterprise Management System Archive	SEMS-ARCHIVE	0.5 mile	No	0	0	0
USEPA	Resource Conservation and Recovery Act Corrective Action Activity	CORRACTS	1.0 mile	No	0	0	0
USEPA	Resource Conservation and Recovery Act Treatment/Storage/ Disposal Facilities	RCRA TSD	0.5 mile	No	0	0	0
USEPA	Resource Conservation and Recovery Act Small/Large Quantity Hazardous Waste Generators	RCRA SQG/LQG/ VSQG/ Non-Gen	Subject Property and Adjoining	No	0	0	N/A
USEPA	Federal Institutional/ Engineering Control Registries	US INST/ENG Controls	Subject Property	No	N/A	N/A	N/A
USEPA	Emergency Response Notification System	ERNS	Subject Property	No	N/A	N/A	N/A

Review of the EDR Radius Map Report indicates that the subject property is not listed in Federal environmental databases searched.

Based on review of environmental database records, as described above, the following sites within the ASTM standard Federal database search radii of the subject property were identified as potential concerns (see section 6.1.5 for further detail on these sites):

- Wolff-Alport Chemical Company - NPL

Remaining sites identified within the ASTM standard Federal database search radii were ruled out as potential concerns due to their distance, direction relative to groundwater flow, and/or closed status.

6.1.2 State and Local Databases

The table below summarizes the State databases that were searched.

Table 6-2 - New York State and Local Databases Searched

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Agency	Listing Name or database Searched	Abbreviation	Search Distance	Target Property Identified	Total Nearby Properties Identified	Up Gradient and Adjacent Properties Identified	Down or Cross Gradient Properties Identified
NYSDEC	Inactive Hazardous Waste Disposal Sites in New York State	SHWS	1.0 mile	No	3	0	3
NYSDEC	Hazardous Substance Waste Disposal Site Study	HSWDS	0.5 mile	No	0	0	0
NYSDEC	Solid Waste Facility Register	SWF/LF	0.5 mile	No	6	2	4
NYSDEC	Registered Recycling Facilities	SWRCY	0.5 mile	No	1	0	1
NYSDEC	Registered Waste Tire Storage Facilities	SWTIRE	0.5 mile	No	0	0	0
NYSDEC	Petroleum Bulk Storage (PBS)	UST/AST	Subject Property and Adjoining	No	1	1	N/A
NYSDEC	Chemical Bulk Storage (CBS)	CBS AST/UST	Subject Property and Adjoining	No	0	0	N/A
NYSDEC	Major Oil Storage Facilities	MOSF	0.5 mile	No	0	0	0
NYSDEC	Leaking Underground Storage Tank Sites	LTANKS	0.5 mile	No	23	7	16
NYSDEC	New York State Spills	NYSPILLS	0.125 mile	No	21	5	16
NYSDEC	Institutional/ Engineering Control Registries	INST/ENG Controls	Subject Property	No	N/A	N/A	N/A
NYSDEC	Voluntary Cleanup Agreements	VCP	0.5 mile	No	16	1	15
NYSDEC	Brownfield Cleanup Program & Environmental Restoration Program	BCP/ERP	0.5 mile	No	2	0	2
NYSDEC	Dry Cleaner Site	Dry cleaners	0.25 mile	No	0	0	0
NYC	E-Designation	E-DES	Subject Property	No	N/A	N/A	N/A

Review of the EDR Radius Map Report indicates that the subject property is not listed in State environmental databases searched (see section 6.1.5 for further detail).

Based on review of environmental database records, as described above, due to their distance, direction relative to groundwater flow, and/or closed status, no database records related to surrounding properties within the ASTM standard State database search radii indicative of potential environmental concerns were identified.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

6.1.3 *EDR Databases*

The table below summarizes the EDR databases that were searched.

Table 6-3 - Additional Databases Searched

Agency	Listing Name or database Searched	Abbreviation	Search Distance	Target Property Identified	Total Nearby Properties Identified	Up Gradient and Adjacent Properties Identified	Down or Cross Gradient Properties Identified
EDR	Manufactured Gas Plants	MGP	1.0 mile	No	2	0	2
EDR	Historical Drycleaners	HDC	0.25 mile	No	0	0	0
EDR	Historical Auto Station	HAS	0.125 mile	No	2	0	2

Review of the EDR Radius Map Report indicates that the subject property is not listed in EDR proprietary environmental databases searched.

Based on review of environmental database records, as described above, due to their distance, direction relative to groundwater flow, and/or closed status, no database records related to surrounding properties within the EDR proprietary database search radii indicative of potential environmental concerns were identified.

6.1.4 *Orphan Sites*

Orphan sites are properties, that due to an inadequate or incomplete address in government databases or in base map files, are not able to be geographically located (i.e. mapped or geocoded). This can occur for several reasons: no street number or street name in address given, the street address is given only as a P.O. Box, or when inconsistencies exist in the address (street number does not exist in the city / zip code given).

Four orphan sites were identified in the EDR report. PWGC performed a cursory review of the addresses listed. It does not appear that the subject property or neighboring properties are identified in the orphan summary.

6.1.5 *Sites of Potential Concern*

Based on review of environmental database records, as described above, the following sites within ASTM standard search radii were identified as potential environmental concerns related to the subject property:

- Wolff-Alport Chemical Company is listed in the NPL database and is located approximately 0.9 miles upgradient of the subject property at 1125-1139 Irving Avenue. According to USEPA's Database records, the Wolff-Alport Chemical Company imported monazite sand and extracted

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

rare earth metals onsite from the early 1920s until 1954. Monazite contains approximately 6-8% thorium. Until 1947, the Wolff-Alport Chemical Company dumped the thorium waste in the sewer and possibly buried the waste on the property. Investigations confirmed radiological contamination still existed on the property and in/around sewer lines downstream of the former facility. EPA included the adjacent streets, sidewalks, sewers, and commercial and residential properties where radiological contaminants migrated or have the potential to migrate as part of the site, indicating the area of concern related to this site is well outside the subject property boundary. As such, this site does not appear to represent an environmental concern to the subject property.

6.2 Vapor Encroachment

PWGC performed a Tier 1 Vapor Encroachment Screening for the subject property in accordance with ASTM E2600-15, Vapor Encroachment Screening on Property Involved in Real Estate Transactions. In accordance with ASTM E2600-15, the default Area of Concern (AOC), adjusted to account for the groundwater flow direction in the vicinity of the subject property, is defined as follows:

Direction Relative to Subject Property	Petroleum Impacted Sites AOC Radius	Contaminants of Concern Impacted Sites AOC Radius
Up Gradient	528 feet	1,760 feet
Cross Gradient	165 feet (LNAPL) 95 feet (dissolved)	365 feet
Down Gradient	100 feet (LNAPL) 30 feet (dissolved)	100 feet

PWGC evaluated sites identified in Federal and State databases (see Section 6.1) located within the adjusted AOC radii for the potential for petroleum impact and or contaminants of concern (such as perc) to be present. The following sites were identified within the adjusted AOC:

- Four LTANKS sites
- One VCP site

Each of these sites was evaluated for the potential for a vapor encroachment condition (VEC) to be present. Based on these sites' lack of apparent impact present and/or closed status, PWGC has determined that none are likely to represent a VEC at the subject property.

A copy of the Tier 1 Vapor Encroachment Screening is included as **Appendix H**.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

6.3 Additional Environmental Record Sources

6.3.1 Freedom of Information Act Requests

Freedom of Information Act (FOIA) requests were sent to the United States Environmental Protection Agency, Region 2 (USEPA) via USEPA's MyProperty database, the New York State Department of Environmental Conservation, Region 2 (NYSDEC), The New York City Mayor's Office of Environmental Remediation (NYCOER), the New York City Department of Environmental Protection (NYCDEP) and the New York City Fire Department (FDNY). Copies of FOIA requests are included in **Appendix I**.

As of the date of this report, responses to FOIA requests have not been received, except as noted below. As responses were not provided within the allotted due diligence period, the records were deemed not to be "reasonably ascertainable" at this time. Should records become available at a later date, pertinent information will be forwarded as an addendum upon receipt.

6.3.2 Publicly Available Online Information

Information regarding the subject property was collected from several publicly available online sources, including the following:

- Property Shark (www.propertyshark.com, an aggregator of publicly available real estate information).
- NYSDEC DECInfo Locator (https://www.dec.ny.gov/pubs/109457.html)
- NYCDOB Building Information System (https://www1.nyc.gov/site/buildings/index.page)

Information regarding the subject property available on above listed sources was reviewed to identify pertinent information. No indication of environmental issues was identified.

- NYCDOB Building Information System: A 1920 Certificate of Occupancy identified the subject property as a gold leaf factory.
- NYCDOB Building Information System: Oil burner applications were filed in 1942 and 1943.

Copies of publicly available information are included in **Appendix I**.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

7.0 SITE RECONNAISSANCE

7.1 Methodology and Limiting Conditions

Ms. Danielle Dulligan of PWGC performed site reconnaissance on Wednesday, March 26, 2025. Weather conditions during the inspection were cloudy with a temperature of approximately 43-52° Fahrenheit. PWGC returned to the subject property on April 8, 2025, to access the property basement that was inaccessible during the initial inspection.

The site reconnaissance consisted of an inspection of the interior portions of the existing building, followed by inspection of the exterior portions of the property. A Site Inspection Checklist is included as **Appendix J**. The presence of multiple garbage trucks in the northern, open portion of the subject property obscured a significant portion of the yard, limiting the ability to inspect ground conditions. Additionally, the second floor of the building (rented artist space) contained several locked areas that were inaccessible during site reconnaissance.

7.2 Aboveground Storage Tanks (AST)

PWGC did not identify ASTs at the subject property.

7.3 Underground Storage Tanks (UST)

PWGC did not identify evidence of USTs, such as fill ports or vent lines at the subject property.

7.4 Hazardous and Non-Hazardous Chemical Storage

PWGC observed chemical storage consisting of the following:

- Paint and lacquer were observed, stored in their retail containers, within the second-floor art studio. No staining was observed in the vicinity of the chemical storage, and containers appeared to be in good condition at the time of inspection.
- A five-gallon bucket of lubricant was observed laying on its side in the northern yard. Multiple dark stains were observed across the yard.

7.5 Waste Generation, Storage, and Disposal

PWGC did not identify evidence of waste generation, storage or disposal at the subject property.

7.6 Polychlorinated Biphenyls (PCBs)

PWGC did not identify potentially PCB containing equipment such as electrical transformers or hydraulic lifts at the subject property.

7.7 Additional Site Conditions

The following is a summary of visual and/or physical observations made by PWGC at the time of site reconnaissance. Photographs of pertinent observations are included in **Appendix A**.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Table 7-1 - Additional Site Conditions

Condition	Identified
Interior drains, trenches or sumps.	No
Interior stains or corrosion	No
Unusual odors	No
Interior pools of liquid	No
Stained Soils or Pavement	Yes[1]
Stressed Vegetation	No
Indications of solid waste disposal	No
Exterior ponds, pits, or lagoons	No
Wastewater discharge/disposal	No
Storm water discharge/disposal	No
Oil water separators/clarifiers	No
Septic Systems/Cesspools	No
Wells (Drinking water, monitoring wells, agricultural/ irrigation wells, or process water wells)	No
Petroleum or natural gas pipelines or easements	No
Other	No

1 – Dark-stained pavement was observed in the northern yard. The property is a storage yard for diesel-powered garbage trucks. The yard is poorly maintained with miscellaneous trash/junk stored across the property.

7.8 Neighboring Properties

PWGC performed a cursory inspection of the neighboring properties from the subject property and public right of ways. The neighboring properties are used for commercial purposes. Potential environmental concerns were not observed at neighboring properties.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

8.0 INTERVIEWS

8.1 Current Owner

PWGC emailed a property owner questionnaire to the client, Elizabeth Canela, via email on April 2, 2025, to be forwarded to the current property owner. As of the date of this report, a response from the property owner has not been received.

8.2 Occupant

PWGC interviewed Stephen of Great Goods, Co., an employee of the current first floor occupant. Stephen did have knowledge of one incident that may have added to environmental issues at the subject property. Information provided by Stephen is summarized below and has been incorporated into this report where appropriate.

- One of the garbage trucks in the northern yard caught fire. The fire department was called and the fire was extinguished. It was unclear if water or foam were utilized to extinguish the fire.

8.3 Previous Environmental Reports

PWGC was provided copies of a Phase I Environmental Site Assessment Report by CBRE, Inc. from September 2018 for the subject property. PWGC prepared a Phase II ESA in May 2024 for the subject property and the adjoining southern property located at 2465 Atlantic Avenue. Information included in these reports is summarized below.

8.3.1 Phase I Environmental Site Assessment Report (September 2018)

CBRE, Inc. prepared a Phase I ESA in September of 2018 for 45 Van Sinderen Avenue. The Phase I ESA did not identify RECs associated with subject property; however, the presence of "fill" material (material with fragments of brick, concrete, cinder, etc) commonly found within the five boroughs of New York City was noted to represent an environmental concern and require special handling and disposal if the site were to be redeveloped.

8.3.2 Phase II Environmental Site Assessment Report (May 2024)

PWGC prepared a Phase II ESA in May of 2024 for 45 Van Sinderen Avenue (subject property) and 2465 Atlantic Avenue (adjoining southern property). The Phase II ESA documented the findings of the Subsurface Investigation performed at the subject property. The Phase II ESA results for 45 Van Sinderen Avenue is summarized below and includes results from soil borings SB001-B and SB004-B, as well as soil vapor result SV001-B.

Subsurface anomalies indicative of potential USTs, drywells, or other objects which would warrant further investigation were not identified during the geophysical survey.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

Soil quality across the soil borings exhibited the presence of fill material in the top 15 feet. Three soil samples were collected from two soil borings installed across the site as part of this assessment. Analytical results for each of the three samples did not identify concentrations of Volatile Organic Compounds (VOCs) greater than Unrestricted Use Soil Cleanup Objectives (UUSCOs) with the exception of tetrachloroethene (PCE) at a concentration of 2.3 mg/kg and trichloroethylene (TCE) at a concentration of 1.1 mg/kg in SB001 at 0 to 2 feet. Both concentrations are slightly higher than their respective UUSCOs, but less than their Restricted Residential Soil Cleanup Objectives (RRSCOs). Semi-volatile Organic Compounds (SVOCs), namely polyaromatic hydrocarbons (PAHs), were detected in SB004 from the 0 to 2-foot interval at concentrations greater than Commercial Use SCOs (CUSCOs). Metals including arsenic and copper were detected at concentrations greater than CUSCOs in SB001 and SB004 in the 0 to 2-foot interval, and manganese exceeded UUSCOs in SB004 in the 13 to 15-foot interval. In general, elevated concentrations of SVOCs and metals were identified at locations and depths where the upper layer of fill material was observed, with manganese being the only analyte detected greater than UUSCOs in the lower fill layer.

One soil vapor sample was collected from the upgradient portion of the property in the northern yard. There were no VOC concentrations detected in the upgradient soil vapor sample that would warrant mitigation based on NYSDOH matrices; however, concentrations of petroleum related compounds, such as the trimethylbenzenes and BTEX (benzene, toluene, ethylbenzene, xylene) and chlorinated VOCs such as tetrachloroethylene were detected at lower concentrations.

8.4 Local Government Officials

Freedom of Information Act (FOIA) requests were sent to the United States Environmental Protection Agency, Region 2 (USEPA) via USEPA's MyProperty database, the New York State Department of Environmental Conservation, Region 2 (NYSDEC), The New York City Mayor's Office of Environmental Remediation (NYCOER), the New York City Department of Environmental Protection (NYCDEP) and the New York City Fire Department (FDNY).

Based upon the subject property history, interviews with government officials to obtain additional information are not warranted at this time.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

9.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM 1527-21

9.1 Wetland Delineation

Based on review of the EDR Radius Map Report, which includes State and Federal wetlands, it appears that State and/or Federal wetlands are not present on the subject property.

Based on review of the EDR Radius Map Report, no State or Federal wetlands are located within a one-mile radius of the subject property.

9.2 Radon Risk Evaluation

Radon is a colorless, radioactive, inert gas formed by the decay of radium and may be present in soils and rocks containing granite, shale, phosphate, and pitchblende. The USEPA's "Map of Radon Zones for New York State," September 1993 indicates that Kings County is not a radon risk area. The EDR report provides information from the New York State Department of Health radon survey which indicates that the average result for sites tested in Kings County is 0.750 Pico curies per liter (pCi/L) in the living area, which is less than the USEPA radon action level of 4 pCi/L, and 100% of sites tested in Kings County were less than the action level of 4 pCi/L in the living area.

9.3 Asbestos

PWGC performed a cursory visual inspection of the building during site reconnaissance for potential asbestos containing material (ACM) and did not identify obvious potential ACM. However, regardless of the age of the building, ACM may be present in building products such as drywall, acoustic ceiling tiles, plaster, joint compound, roofing materials, waterproofing material, caulk, grout, flooring, mastics, thermal systems, and pipe wrap. A detailed asbestos survey should be performed by a qualified asbestos inspector in accordance with applicable federal, state, and local regulations prior to renovation or demolition of the building(s); please note that the asbestos inspection performed as part of this Phase I ESA does not meet those criteria.

9.4 Lead-Based Paint (LBP)

PWGC did not identify evidence of potential lead-based paint at the subject property. Based on the apparent age of the building, it is possible that lead based paint is present.

9.5 Mold

PWGC did not visually observe significant sources of mold at the subject property during site reconnaissance.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

9.6 Historic Fill

Historic fill material was found to be present beneath the subject property during the May 2024 Phase II ESA. Such material, when excavated (for the purpose of constructing a building, installing new footings, and/or utilities), will require special handling and disposal.

9.7 Emerging Contaminants

Emerging contaminants collectively refer to several chemicals/groups of chemicals that represent potential sources of groundwater impact that are becoming increasingly scrutinized and regulated in recent years. Emerging contaminants that are currently a focus of regulatory agencies in New York State are discussed below.

9.7.1 Per- and Poly-Fluoroalkyl Substances

Per- and Polyfluoroalkyl Substances (PFAS) are a group of man-made chemicals that have been in use since the 1940s that are or have been used in products such as chrome plating, electronics manufacturing, fire suppression foams, stain and water repellants, non-stick coatings, paints, and other consumer products. As of February 2023, NYSDEC has established drinking water quality guidance values, and is in the process of establishing soil quality standards for PFAS. In addition, PFAS chemicals perfluorooctanesulfonic acid (PFOS) and perfluorooctanoic acid (PFOA) have been designated "hazardous substances" as defined by USEPA. As such, the presence or potential presence of such compounds at the site, under conditions defined in Section 2.3, may represent a REC.

Based on review of the database report and site history, PWGC has not identified evidence of current or past chemical usage or storage at the site indicative of a potential source of PFAS impact; however, the fire that occurred on the garbage truck in the northern yard was addressed by the fire department may have resulted in PFAS contamination if aqueous firefighting foam (AFFF), which may contain PFAS, was utilized to extinguish the fire. PWGC prepared a FOIL request to FDNY to confirm whether AFFF was utilized. As of the date of this report, a response has not been received.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

10.0 FINDINGS AND OPINIONS

Based upon reconnaissance of the subject and surrounding properties, interviews, and review of historical records and regulatory agency databases, the following potential RECs have been identified:

Onsite

- Current and historical site usage.
- Dark staining observed in northern yard.

Offsite

- Current/historical usage of surrounding properties.

Potential RECs identified at the subject property were evaluated to determine whether items initially suspected to be RECs are in fact RECs. Evaluation of potential RECs are as follows:

- The subject property was historically used for coal and lime storage as part of a lumber yard from approximately 1888 to 1908. Lumber storage may result in treated wood containing chromated copper arsenate or creosote, which may leach into the subsurface through stormwater runoff. Coal and lime storage similarly may result in subsurface impact through infiltration. There are no records confirming treated wood storage at the subject property; however, the presence of the lumber yard predates most environmental regulations and documentation related to past releases may not exist. As such, PWGC believes the past usage of the site as a lumber yard represents a REC.
- The subject property was historically used for gold foil manufacturing from approximately 1920 to 1934. Such usages are likely to have used/stored hazardous substances, such as sodium cyanide, and/or petroleum products. While there are no open spills or violations associated with the subject property, the gold foil manufacturing listing predates most environmental regulations and documentation related to past releases may not exist. As such, PWGC believes the past usage of the subject property for gold foil manufacturing represents a REC.
- Dark-stained soil/pavement was observed in the northern yard. The property is a storage yard for diesel-powered garbage trucks. The yard is poorly maintained with miscellaneous trash/junk stored across the property. The potential exists for the material causing the staining to the yard to impact the subsurface. As such, PWGC believes the presence of dark staining in the northern yard represents a REC.
- Multiple surrounding properties were identified as having current and historical industrial uses, including steel manufacturing, auto sales and repair, a lumber yard, a knitting mill, and railroad. Identified current and historical usages are likely to have used/stored hazardous substances and/or petroleum products. However, based on these sites' lack of identified open spills or other violations, the likelihood of potential releases impacting the subject property appears to be low. Based on this information, the current and historical usage of surrounding properties does not appear to represent a REC.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

11.0 CONCLUSIONS AND RECOMMENDATIONS

PWGC has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-21 for the subject property. There were no exceptions to, or deletions from, this practice except as noted in Section 12.0 of this report. PWGC evaluated the findings associated with the subject property and identified three RECs, no HRECs, and no CRECs with respect to the subject property.

Based on the identified RECs, PWGC recommends a supplemental Phase II ESA be performed at the subject property. The Phase II ESA should include:

- Additional soil sampling to more completely characterize subsurface soil and historic fill conditions.
    - Based on the potential PFAS impact from the garbage truck fire, and potential cyanide impact from the gold foil manufacturing usage, PWGC recommends including PFAS and cyanide in the soil sampling analyses.

Although not a part of the ASTM E1527-21 scope, the following additional concerns associated with the subject property must be considered:

- Based on inspection of the subject property, it is possible that ACM and/or lead-based paint are present within the structure. PWGC recommends that, prior to demolition or renovation of the building, a detailed asbestos and/or lead based paint survey should be performed by a qualified asbestos/lead inspector in accordance with applicable federal, state, and local regulations prior to renovation or demolition of the building; please note that the asbestos/lead inspection performed as part of this Phase I ESA does not meet those criteria.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

12.0 DEVIATIONS

This Phase I ESA was conducted in accordance with the scope and limitations of the ASTM Standard E 1527-21 (Standard Practices for Environmental Site Assessment: Phase I Environmental Site Assessment Process) and 40 CFR Part 312 (Standards and Practices for All Appropriate Inquiry; Final Rule). Excluding data gaps identified in Section 2.8 and additional services outlined in Section 9.0, there were no deviations or deletions from this practice.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

13.0 REFERENCES

All Appropriate Inquiry, Final Rule, 40 CFR Part 312.

Standard practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Standard E 1527-21.

CBRE, Inc. Phase I Environmental Site Assessment, September 26, 2018.

PWGC. Phase II Environmental Site Assessment, May 28, 2024.


P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

14.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR 312.



Michael Pecoraro
Project Manager




Jennifer Lewis, PG
Vice President

Qualifications of the Environmental Professionals are included in **Appendix K.**

Report Completion Date: June 16, 2025

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO • SYRACUSE • SHELTON, CT

FIGURES



PWGC
CLIENT DRIVEN SOLUTIONS
P.W. Grosser Consulting, Inc.
630 Johnson Ave., Suite 7
Bohemia, NY 11716
Ph: 631-589-6353 • Fax: 631-589-8705
pwgc.info@pwgrosser.com


Document Path: W:\Projects\S-Z\TOT2503\Map files\Phase1_Building82.aprx

SITE LOCATION

45 Van Sinderen Ave
Brooklyn, NY

0 1 2 Miles

Project:	TOT2503
Date:	3/21/2025
Designed by:	MP
Drawn by:	AM
Approved by:	MP
Figure No:	1



PWGC
CLIENT DRIVEN SOLUTIONS
P.W. Grosser Consulting, Inc.
630 Johnson Ave., Suite 7
Bohemia, NY 11716
Ph: 631-589-6353 • Fax: 631-589-8705
pwgc.info@pwgrosser.com

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DRAWING AND RELATED DOCUMENTS IS A VIOLATION OF SEC. 7209 OF THE N.Y.S. EDUCATION LAW

DRAWING PREPARED FOR:

REVISION	DATE	INITIAL	COMMENTS

DRAWING INFORMATION:

Project:	TOT2503	Designed by:	MP
Date:	3/21/2025	Drawn by:	AM
Scale:	AS SHOWN	Approved by:	MP

SITE PLAN

45 Van Sinderen Ave
Brooklyn, NY

FIGURE NO:

2

Document Path: W:\Projects\S-Z\TOT\2503\Map files\Phase1_BuildingB2.aprx

APPENDIX A
SITE PHOTOGRAPHS



View of the subject property building, facing east.



View of the north yard of 45 Van Sinderen Street, facing east.



View of the first floor warehouse space.



View of warehouse heating.



View of first floor office space.



View of first floor bathroom.



View of basement access from street.



View of subject property northern yard.



View of materials storage in the northern yard.



View of dark-stained surface in the northern yard.



View of paint storage in the second floor studio space.



View of lubricant bucket stored in northern yard, dark-stained surface present.



View of adjoining southern property.



View of adjoining northern property.



View of adjoining eastern property.



View of adjoining western property.

APPENDIX B
SANBORN MAPS

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207

Inquiry Number: 7931531.3
March 19, 2025

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

03/19/25

Site Name:

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207
EDR Inquiry # 7931531.3

Client Name:

P.W. Grosser Consulting
630 Johnson Ave
Bohemia, NY 11550
Contact: Michael Pecoraro

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by P.W. Grosser Consulting were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 1313-403B-8C02

PO # TOT2503

Project TOT2503

Maps Provided:

2007	1995	1986	1966
2006	1994	1983	1965
2005	1993	1982	1963
2004	1992	1981	1951
2003	1991	1980	1950
2002	1989	1979	1932
2001	1988	1978	1928
1996	1987	1977	1908
			1888
			1887

Sanborn® Library search results
Certification #: 1313-403B-8C02

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

P.W. Grosser Consulting (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets



Volume 7, Sheet 13
2007



Volume 7, Sheet 12
2007



Volume 16, Sheet 9
2007



Volume 16, Sheet 8
2007

2006 Source Sheets



Volume 16, Sheet 9
2006



Volume 16, Sheet 8
2006



Volume 7, Sheet 13
2006



Volume 7, Sheet 12
2006

2005 Source Sheets



Volume 7, Sheet 12
2005



Volume 7, Sheet 13
2005



Volume 16, Sheet 8
2005



Volume 16, Sheet 9
2005

2004 Source Sheets


Volume 16, Sheet 9
2004


Volume 16, Sheet 8
2004



Volume 7, Sheet 13
2004


Volume 7, Sheet 12
2004


Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


2003 Source Sheets


Volume 7, Sheet 12
2003



Volume 7, Sheet 13
2003



Volume 16, Sheet 9
2003


Volume 5, Sheet 72
2003



Volume 16, Sheet 8
2003

2002 Source Sheets



Volume 16, Sheet 9
2002



Volume 7, Sheet 12
2002



Volume 7, Sheet 13
2002



Volume 16, Sheet 8
2002

2001 Source Sheets



Volume 7, Sheet 12
2001



Volume 7, Sheet 13
2001


Volume 16, Sheet 9
2001


Volume 16, Sheet 8
2001

1996 Source Sheets



Volume 16, Sheet 8
1996


Volume 16, Sheet 9
1996

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1995 Source Sheets




Volume 5, Sheet 72
1995-Nov




Volume 16, Sheet 9
1995



Volume 7, Sheet 12
1995



Volume 16, Sheet 8
1995




Volume 7, Sheet 13
1995


1994 Source Sheets




Volume 7, Sheet 13
1994



Volume 7, Sheet 12
1994




Volume 16, Sheet 8
1994



Volume 16, Sheet 9
1994

1993 Source Sheets



Volume 7, Sheet 12
1993




Volume 7, Sheet 13
1993


Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1992 Source Sheets



Volume 7, Sheet 13
1992



Volume 7, Sheet 12
1992



Volume 16, Sheet 8
1992


Volume 16, Sheet 9
1992

1991 Source Sheets


Volume 16, Sheet 8
1991



Volume 16, Sheet 9
1991


Volume 7, Sheet 12
1991


Volume 7, Sheet 13
1991

1989 Source Sheets



Volume 7, Sheet 13
1989



Volume 16, Sheet 8
1989


Volume 7, Sheet 12
1989


Volume 16, Sheet 9
1989

1988 Source Sheets


Volume 7, Sheet 12
1988


Volume 7, Sheet 13
1988


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1987 Source Sheets



Volume 7, Sheet 13
1987



Volume 7, Sheet 12
1987




Volume 16, Sheet 8
1987




Volume 16, Sheet 9
1987

1986 Source Sheets




Volume 16, Sheet 8
1986




Volume 16, Sheet 9
1986

1983 Source Sheets




Volume 16, Sheet 8
1983




Volume 16, Sheet 9
1983

1982 Source Sheets



Volume 5, Sheet 72
1982



Volume 7, Sheet 12
1982



Volume 7, Sheet 13
1982

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1981 Source Sheets



Volume 16, Sheet 9
1981




Volume 16, Sheet 8
1981

1980 Source Sheets




Volume 7, Sheet 13
1980




Volume 7, Sheet 12
1980

1979 Source Sheets




Volume 7, Sheet 12
1979



Volume 7, Sheet 13
1979




Volume 16, Sheet 8
1979




Volume 16, Sheet 9
1979


1978 Source Sheets



Volume 5, Sheet 72
1978



Volume 7, Sheet 12
1978




Volume 7, Sheet 13
1978

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1977 Source Sheets




Volume 16, Sheet 8
1977




Volume 16, Sheet 9
1977

1966 Source Sheets



Volume 16, Sheet 9
1966




Volume 16, Sheet 8
1966

1965 Source Sheets




Volume 7, Sheet 13
1965




Volume 7, Sheet 12
1965

1963 Source Sheets



Volume 7, Sheet 13
1963




Volume 7, Sheet 12
1963


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1951 Source Sheets




Volume 7, Sheet 13
1951




Volume 7, Sheet 12
1951

1950 Source Sheets




Volume 16, Sheet 8
1950



Volume 16, Sheet 9
1950

1932 Source Sheets




Volume 7, Sheet 12
1932



Volume 7, Sheet 13
1932

1928 Source Sheets



Volume 16, Sheet 8
1928




Volume 16, Sheet 9
1928


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1908 Source Sheets



Volume 8, Sheet 8
1908



Volume 8, Sheet 7
1908



Volume 7, Sheet 22
1908




Volume 7, Sheet 21
1908

1888 Source Sheets



Volume 7, Sheet 175
1888



Volume 7, Sheet 175
1888


1887 Source Sheets



Volume 8, Sheet 198
1887

Certified Sanborn® Map

2007




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 7, Sheet 12
Volume 7, Sheet 13

0 Feet 150 300 600

N

Certified Sanborn® Map

2006




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 12
Volume 7, Sheet 13
Volume 16, Sheet 8
Volume 16, Sheet 9

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 9
Volume 16, Sheet 8
Volume 7, Sheet 13
Volume 7, Sheet 12

0 Feet 150 300 600

N

Certified Sanborn® Map

2004




Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	2004

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 7, Sheet 12
Volume 7, Sheet 13
Volume 16, Sheet 8
Volume 16, Sheet 9


N



Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #	1313-403B-8C02
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 5, Sheet 72
Volume 16, Sheet 9
Volume 7, Sheet 13
Volume 7, Sheet 12

0 Feet 150 300 600

N

Certification #1313-403B-8C02

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 7, Sheet 13
Volume 7, Sheet 12
Volume 16, Sheet 9

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 8
Volume 16, Sheet 9
Volume 7, Sheet 13
Volume 7, Sheet 12

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 13
Volume 16, Sheet 8
Volume 7, Sheet 12
Volume 16, Sheet 9
Volume 5, Sheet 72

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8
Volume 7, Sheet 12
Volume 7, Sheet 13

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 13
Volume 7, Sheet 12

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8
Volume 7, Sheet 12
Volume 7, Sheet 13

N




Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1991

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 7, Sheet 13
Volume 7, Sheet 12
Volume 16, Sheet 9
Volume 16, Sheet 8


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 9
Volume 7, Sheet 12
Volume 16, Sheet 8
Volume 7, Sheet 13

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #	1313-403B-8C02
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 13
Volume 7, Sheet 12

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8
Volume 7, Sheet 12
Volume 7, Sheet 13

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 16, Sheet 9
Volume 16, Sheet 8

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #	1313-403B-8C02
Copyright	1983

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 13
Volume 7, Sheet 12
Volume 5, Sheet 72

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Broadway Junction Properties
Address: 45 Van Sinderen Avenue
City, ST, ZIP: Brooklyn, NY 11207
Client: P.W. Grosser Consulting
EDR Inquiry: 7931531.3
Order Date: 03/19/2025
Certification #: 1313-403B-8C02
Copyright: 1981

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 8
Volume 16, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 12
Volume 7, Sheet 13

0 Feet 150 300 600

N

Certified Sanborn® Map

1979





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8
Volume 7, Sheet 13
Volume 7, Sheet 12

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 13
Volume 7, Sheet 12
Volume 5, Sheet 72

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1966

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 8
Volume 16, Sheet 9

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 12
Volume 7, Sheet 13

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1963

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 12
Volume 7, Sheet 13

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #1313-403B-8C02

Site Name: Broadway Junction Properties
Address: 45 Van Sinderen Avenue
City, ST, ZIP: Brooklyn, NY 11207
Client: P.W. Grosser Consulting
EDR Inquiry: 7931531.3
Order Date: 03/19/2025
Certification #: 1313-403B-8C02
Copyright: 1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 12
Volume 7, Sheet 13

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Broadway Junction Properties
Address: 45 Van Sinderen Avenue
City, ST, ZIP: Brooklyn, NY 11207
Client: P.W. Grosser Consulting
EDR Inquiry: 7931531.3
Order Date: 03/19/2025
Certification #: 1313-403B-8C02
Copyright 1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1932

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 7, Sheet 13
Volume 7, Sheet 12

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1928

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 16, Sheet 9
Volume 16, Sheet 8

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #1313-403B-8C02

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1908

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 7, Sheet 21
Volume 7, Sheet 22
Volume 8, Sheet 7
Volume 8, Sheet 8


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1888


This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 7, Sheet 175
Volume 7, Sheet 175

0 Feet 150 300 600




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Site Name:	Broadway Junction Properties
Address:	45 Van Sinderen Avenue
City, ST, ZIP:	Brooklyn, NY 11207
Client:	P.W. Grosser Consulting
EDR Inquiry:	7931531.3
Order Date:	03/19/2025
Certification #:	1313-403B-8C02
Copyright	1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 8, Sheet 198





N

APPENDIX C
TOPOGRAPHIC MAPS

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207

Inquiry Number: 7931531.4
March 19, 2025

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

03/19/25

Site Name:

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207
EDR Inquiry # 7931531.4

Client Name:

P.W. Grosser Consulting
630 Johnson Ave
Bohemia, NY 11550
Contact: Michael Pecoraro

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by P.W. Grosser Consulting were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# TOT2503
Project: TOT2503

Coordinates:

Latitude:	40.676539 40° 40' 36" North
Longitude:	-73.903116 -73° 54' 11" West
UTM Zone:	Zone 18 North
UTM X Meters:	592699.99
UTM Y Meters:	4503429.23
Elevation:	70.00' above sea level

Maps Provided:

2019	1900
2016	1898
2013	1897
1994, 1995	
1979	
1966, 1967	
1956, 1957	
1947	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets




Brooklyn
2019
7.5-minute, 24000




Jamaica
2019
7.5-minute, 24000

2016 Source Sheets




Brooklyn
2016
7.5-minute, 24000




Jamaica
2016
7.5-minute, 24000

2013 Source Sheets



Brooklyn
2013
7.5-minute, 24000




Jamaica
2013
7.5-minute, 24000

1994, 1995 Source Sheets



Jamaica
1994
7.5-minute, 24000



Brooklyn
1995
7.5-minute, 24000
Aerial Photo Revised 1977


Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979 Source Sheets



Jamaica
1979
7.5-minute, 24000
Aerial Photo Revised 1977



Brooklyn
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1966, 1967 Source Sheets



Jamaica
1966
7.5-minute, 24000
Aerial Photo Revised 1953



Brooklyn
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1956, 1957 Source Sheets



Brooklyn
1956
7.5-minute, 24000



Jamaica
1957
7.5-minute, 24000
Aerial Photo Revised 1957

1947 Source Sheets



Brooklyn
1947
7.5-minute, 24000
Aerial Photo Revised 1940



Jamaica
1947
7.5-minute, 24000
Aerial Photo Revised 1941

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets



Brooklyn
1900
15-minute, 62500

1898 Source Sheets



Brooklyn
1898
15-minute, 62500


1897 Source Sheets



Brooklyn
1897
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2019, 7.5-minute
E, Jamaica, 2019, 7.5-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2016, 7.5-minute
E, Jamaica, 2016, 7.5-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 2013, 7.5-minute
E, Jamaica, 2013, 7.5-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Brooklyn, 1995, 7.5-minute
E, Jamaica, 1994, 7.5-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N

Historical Topo Map

1979



This report includes information from the following map sheet(s).


TP, Brooklyn, 1979, 7.5-minute
E, Jamaica, 1979, 7.5-minute

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).


TP, Brooklyn, 1967, 7.5-minute
E, Jamaica, 1966, 7.5-minute

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1956, 7.5-minute
E, Jamaica, 1957, 7.5-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1947, 7.5-minute
E, Jamaica, 1947, 7.5-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1900, 15-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1898, 15-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Brooklyn, 1897, 15-minute

SITE NAME: Broadway Junction Properties
ADDRESS: 45 Van Sinderen Avenue
Brooklyn, NY 11207
CLIENT: P.W. Grosser Consulting

N

APPENDIX D
AERIAL PHOTOS

Broadway Junction Properties

45 Van Sinderen Avenue

Brooklyn, NY 11207

Inquiry Number: 7931531.9

March 19, 2025

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

03/19/25

Site Name:

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207
EDR Inquiry # 7931531.9

Client Name:

P.W. Grosser Consulting
630 Johnson Ave
Bohemia, NY 11550
Contact: Michael Pecoraro

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 04, 1994	USGS/DOQQ
1984	1"=500'	Flight Date: March 26, 1984	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1976	1"=500'	Flight Date: October 29, 1976	USGS
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: April 12, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 18, 1954	USGS
1951	1"=500'	Flight Date: April 21, 1951	EDR Proprietary Aerial Viewpoint
1924	1"=500'	Flight Date: July 01, 1924	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 7931531.9
YEAR: 2019
= 500'
N
EDR


INQUIRY #: 7931531.9
YEAR: 2015
= 500'
N
EDR


INQUIRY #: 7931531.9
YEAR: 2011
= 500'
N
EDR



INQUIRY #: 7931531.9

YEAR: 2006


= 500'


N

EDR


INQUIRY #: 7931531.9
YEAR: 1994
= 500'
N
EDR


INQUIRY #: 7931531.9
YEAR: 1984
= 500'
N
EDR


INQUIRY #: 7931531.9
YEAR: 1980
= 500'
N
EDR



INQUIRY #: 7931531.9

YEAR: 1976

= 500'

N

EDR




INQUIRY #: 7931531.9

YEAR: 1966

= 500'

N

EDR


INQUIRY #: 7931531.9
YEAR: 1961
= 500'
N
EDR




INQUIRY #: 7931531.9

YEAR: 1954

= 500'

N

EDR



INQUIRY #: 7931531.9

YEAR: 1951

= 500'

N

EDR



INQUIRY #: 7931531.9

YEAR: 1924

= 500'

N

EDR

APPENDIX E
CITY DIRECTORY REPORT

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207

Inquiry Number: 7931531.6
March 20, 2025

The EDR-City Directory Abstract

Environmental Data Resources Inc
6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at approximately five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through current. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 401 feet of the target property.

Summary information obtained is provided in the text of this report.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2020	EDR Digital Archive	-	X	X	-
2017	Cole Information	-	X	X	-
2014	Cole Information	-	X	X	-
2010	Cole Information	-	X	X	-
2005	Cole Information	-	X	X	-
	Hill-Donnelly Corporation	-	X	X	-
2000	Cole Information	-	X	X	-
1997	NYNEX	X	X	X	-
1995	Cole Information	-	X	X	-
1992	Cole Information	-	X	X	-
	NYNEX Informantion Resource Co.	-	X	X	-
1985	NYNEX Information Resources Company	-	X	X	-
1980	New York Telephone	-	X	X	-
1976	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1973	New York Telephone	X	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1970	New York Telephone	X	X	X	-
1965	New York Telephone	X	X	X	-
1960	New York Telephone	X	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	X	X	X	-
1945	New York Telephone	X	X	X	-
1940	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	X	X	X	-
1928	New York Telephone	-	X	X	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
Atlantic Avenue	Client Entered	
Herkimer Street	Client Entered	
Williams Place	Client Entered	

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

45 Van Sinderen Avenue
Brooklyn, NY 11207

FINDINGS DETAIL

Target Property research detail.

VAN SINDEREN AVE

45 VAN SINDEREN AVE

Year	*Uses*	*Source*
1997	MAJERSKI Stanley	NYNEX
1973	Amnthor Testing Instrument Co	New York Telephone
1970	Amthor Testing Instrument Co	New York Telephone
1965	Amthor Testing Instrument Co	New York Telephone
1960	Amthor Testing Instrument Co	New York Telephone Company
1949	Amthor Testing Instrument Co	New York Telephone Company
1945	Amthor Testing Instruent Co	New York Telephone
1940	Terminix Insulation Co Inc	New York Telephone
	Waldrogel Bros	New York Telephone
1934	SCHUMACHER BROS (TN: WM SCHUMACHER) ROLLED GOLD LEAF	R. L. Polk & Co.
	SCHUMACHER WM R	R. L. Polk & Co.

VAN SINDRN AVE

45 VAN SINDRN AVE

Year	*Uses*	*Source*
1976	AMTHOR TESTING INSTRUMENT CO	New York Telephone
1960	AMTHOR TESTING INSTRUMENT CO	New York Telephone

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

ATLANTIC AVE

2431 ATLANTIC AVE

Year	Uses	Source
1934	GRIMALDI ANTHONY F INSPR R	R. L. Polk & Co.

2436 ATLANTIC AVE

Year	Uses	Source
2010	HI RISE STEEL INC	Cole Information

2458 ATLANTIC AVE

Year	Uses	Source
1965	Goldstein Morris statnry	New York Telephone

2461 ATLANTIC AVE

Year	Uses	Source
1934	LORENZO ANTHONY STATIONER	R. L. Polk & Co.

2463 ATLANTIC AVE

Year	Uses	Source
1945	Gold Rim Trading Corp lamps	New York Telephone
1940	Central Metl Store Front Co	New York Telephone
1928	AMER BRASS & ELEC SUPLY CO	New York Telephone
	FELTMAN SAML ELEC SUPPLIES	New York Telephone

2465 ATLANTIC AVE

Year	Uses	Source
2010	APEX AIRTRONICS INC	Cole Information
2005	Apex Airtronics Inc	Hill-Donnelly Corporation
1970	Giacalone & Co	New York Telephone
1965	Giacalone & Co	New York Telephone
1960	GIACALONE JOHN DRS CONTR	New York Telephone
	LAMP PRODS CO	New York Telephone

FINDINGS

Year	Uses	Source
1960	Giacalone John drs contr	New York Telephone Company
	Lamp Prods Co	New York Telephone Company
1949	Comet Pad Co Inc	New York Telephone Company
	Prim Rose Sportw r Co	New York Telephone Company
	Stu Ard Undrgrmnt Co Inc	New York Telephone Company
1940	Hotel Palace	New York Telephone
1934	BERGER HARRY H	R. L. Polk & Co.
	FELTMAN SIMON	R. L. Polk & Co.
	WEILL ISDIORE	R. L. Polk & Co.
1928	TRIANGLE ELECTRICAL SUPPLY CO INC	New York Telephone

2467 ATLANTIC AVE

Year	Uses	Source
2017	APEX AIRTRONICS INC	Cole Information
2014	APEX AIRTRONICS INCORPORATED	Cole Information
2000	APEX ARTRNCS INC	Cole Information
	APEX AIRTRONICS INCORPORATED	Cole Information
1997	Apex Astnics Inc	NYNEX
1995	APEX AIRTRONICS INC	Cole Information
1992	APEX AIRTRONICS INC	NYNEX Informantion Resource Co.
	APEX AIRTRONICS INC	Cole Information
1985	APEX AIRTRONICS INC	NYNEX Information Resources Company
1980	APEX AIRTRONICS INC	New York Telephone
1976	APEX AIRTRONICS INC	New York Telephone
1973	Apex Airtronics Inc	New York Telephone
	Scott Jos P airtronics	New York Telephone
	Williams Mae	New York Telephone
1970	Apex Airtronics Inc	New York Telephone
	Joshua Claudette	New York Telephone
	Scott Jos P airtronics	New York Telephone
1965	Apex Alrtronics Inc	New York Telephone
	Lundy Albert	New York Telephone
	Scott Jos P airtronics	New York Telephone

FINDINGS

Year	Uses	Source
1960	APEX AIRTRONICS INC	New York Telephone
	CITY PROPERTIES INC	New York Telephone
	SCOTT JOS P AIRTRONICS	New York Telephone
	Apex Airtronics Inc	New York Telephone Company
	City Properties Inc	New York Telephone Company
	Scott Jos P airtronics	New York Telephone Company

2469 ATLANTIC AVE

Year	Uses	Source
1934	WALSH PETER C SHIP CLK H	R. L. Polk & Co.
1928	STRUTHWOLF LOUIS SPORTG GDS	New York Telephone

2471 ATLANTIC AVE

Year	Uses	Source
2005	UPTOWN DEMOLITION	Cole Information
1965	East New York	New York Telephone
	WESTERN UNION TELEGRAPH CO	New York Telephone
1960	WESTERN TRANSPTN COINC OFC	New York Telephone
	East New York	New York Telephone Company
	WESTERN UNION TELEGRAPH CO To send a Telegram Cablegram or Radiograam anytime from Dial telephsones EXCEPT COIN	New York Telephone Company
1940	East New York	New York Telephone
	Western Union Telegraph Co Branch Offices	New York Telephone
1928	WESTERN UNION TELEGRAPH CO	New York Telephone

2473 ATLANTIC AVE

Year	Uses	Source
2020	RAINER GERALDINO	EDR Digital Archive
	KUNAL DALVI	EDR Digital Archive
	KRISTAL MARIE	EDR Digital Archive
2017	QUALITY INN	Cole Information
	AMERICAS BEST VALUE INN	Cole Information
2014	LEXINGTON INN BROOKLYN NY	Cole Information
2010	QUALITY INN	Cole Information

FINDINGS

Year	Uses	Source
1973	Colon Felipe	New York Telephone
	Franco Maria	New York Telephone
	Rodriguez Julia	New York Telephone
	Romero Felipe	New York Telephone
1970	Cordero Raul	New York Telephone
1965	Plaza Carmen Mrs	New York Telephone
1949	Giardiello John R	New York Telephone Company
1934	CELOMBRINO PASQUALE TOOL MKR H	R. L. Polk & Co.
	HUGHES FRANK J H	R. L. Polk & Co.
	HUGHES GRACE M CLK R	R. L. Polk & Co.
	O CONNOR WM MILK PASTEURIZER H	R. L. Polk & Co.

2475 ATLANTIC AVE

Year	Uses	Source
1973	Alze Corp plts	New York Telephone
	Lanzoil Prods	New York Telephone
1970	Alze Corp plts	New York Telephone
	Lanzoil Prods	New York Telephone
1965	Alze Corp plts	New York Telephone
	Lanzoil Prods	New York Telephone
1960	ALZE CORP PLTS	New York Telephone
	LANZOIL PRODS	New York Telephone
	Alze Corp plts	New York Telephone Company
	Lanzoil Prods	New York Telephone Company
1949	Meisner Murray machnst	New York Telephone Company
	Murbert Mfg Corp machnsts	New York Telephone Company
1928	UNITED CIGAR STORES CO	New York Telephone

2481 ATLANTIC AVE

Year	Uses	Source
1949	Stemwede Edw luncn wagn	New York Telephone Company
1945	Stemwede Edw lunch wagn	New York Telephone
1940	Stemwede Edw lunch wagn	New York Telephone
1934	POT RESTR	R. L. Polk & Co.

FINDINGS

ATLANTIO AVE

2471 ATLANTIO AVE

Year	Uses	Source
1934	WESTERN UNION TELEGRAPH CO THE NEWCOMB CARLTON PRES J C WILLEVER 1ST V-PRE	R. L. Polk & Co.

ATLANTIS AVE

2465 ATLANTIS AVE

Year	Uses	Source
1934	PALACE HOTEL	R. L. Polk & Co.

ATLNTC

2471 ATLNTC

Year	Uses	Source
1945	East New York	New York Telephone
	Western Union Telegraph Co Branch Offices	New York Telephone

ATLNTC AV DICKAUS st

2471 ATLNTC AV DICKAUS st

Year	Uses	Source
1970	East New York	New York Telephone
	Western	New York Telephone

E NEW YORK AVE

1761 E NEW YORK AVE

Year	Uses	Source
1995	GERSAN SCRAP & CARTING INC	Cole Information
	ATLANTIC AV AUTO SALVAGE INC	Cole Information
1992	GERSAN SCRAP & CARTING INC	Cole Information

1785 E NEW YORK AVE

Year	Uses	Source
2017	PROMOTIONAL DEVELOPMENT INC	Cole Information

FINDINGS

Year	Uses	Source
2017	A APPLE LOCKSMITH	Cole Information
2014	PROMOTIONAL DEVELOPMENT INCORPORATED	Cole Information
2010	PROMOTIONAL DEVELOPMENT INC	Cole Information
2005	PROMOTIONAL DEVELOPMENT INC	Cole Information
2000	PROMOTIONAL DEVELOPMENT INCORPORATED	Cole Information

1805 E NEW YORK AVE

Year	Uses	Source
2005	SHALOM MINSKY	Cole Information

1811 E NEW YORK AVE

Year	Uses	Source
2014	YELYNET GONZALEZ	Cole Information
2005	DIANE DIAZ	Cole Information
2000	ELSA ORTIZ	Cole Information

HAVEN

54 HAVEN

Year	Uses	Source
1960	Home Protector Device Corp	New York Telephone Company

HAVEN AV FR RKWY

15 HAVEN AV FR RKWY

Year	Uses	Source
1949	Israel Max	New York Telephone Company
1945	Israel Max	New York Telephone
1940	Israel Max	New York Telephone

HAVEN AVE

50 HAVEN AVE

Year	Uses	Source
1934	CHASE S L STUDENT R	R. L. Polk & Co.
	CHASE SAML L STUDENT R	R. L. Polk & Co.

FINDINGS

70 HAVEN AVE

Year	Uses	Source
1934	FINK N A AGT H	R. L. Polk & Co.
1928	MCDONNELL A T MRS R	New York Telephone

HAVEN MOUNT VERN

54 HAVEN MOUNT VERN

Year	Uses	Source
1960	HOME PROTECTOR DEVICE CORP	New York Telephone

HAVEN PL

1 HAVEN PL

Year	Uses	Source
2005	CECIL DAVIS	Cole Information
1973	Mutual Funds Bureau	New York Telephone

3 HAVEN PL

Year	Uses	Source
2005	VIVTOR ALMODOVAR	Cole Information

18 HAVEN PL

Year	Uses	Source
2020	TED CUEVAS	EDR Digital Archive
	CASWELL MEUSA	EDR Digital Archive
	ELISA CUEVAS	EDR Digital Archive
2017	CHRISTOPHER MEEK	Cole Information
	DENNIS NORTON	Cole Information
2014	CHRISTINE GEORGE	Cole Information
	ELISA JERONIMO	Cole Information
	RAHEEM DAWKINS	Cole Information
2010	SALOME JERONIMO	Cole Information
2005	No Current Listing	Hill-Donnelly Corporation
	ELIZABETH SOTO	Cole Information

FINDINGS

30 HAVEN PL

Year	Uses	Source
2020	Z-STUDIOS INC	EDR Digital Archive
	D R C MATTRESS CORP	EDR Digital Archive
2005	Candle Express Inc	Hill-Donnelly Corporation
	Candle Factory	Hill-Donnelly Corporation
	CANDLE EXPRESS INC	Cole Information

HAVEN St

54 HAVEN St

Year	Uses	Source
1965	Home Protector Device Corp	New York Telephone

HAVENS AVE

18 HAVENS AVE

Year	Uses	Source
1934	GROSSI ANTHONY H	R. L. Polk & Co.

HAVENS PL

1 HAVENS PL

Year	Uses	Source
2000	CARAVAN TRANSPORTATION CORPORATION	Cole Information
1992	PUPIL TRANSPORTATION	Cole Information
1973	Bodkin Laurence G MD ofc	New York Telephone
1970	Meeker S M & D E lw yrs	New York Telephone
1940	Gold Jos ins	New York Telephone
	Kelhoffer Arthur b	New York Telephone

10 HAVENS PL

Year	Uses	Source
1949	Russo Alphonso	New York Telephone Company
1934	BONO FRANK STATIONER H DO	R. L. Polk & Co.
	BONO JOHN CLK R	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	BONO JOSEPHINE MRS CLK H	R. L. Polk & Co.
	BONO MARIE T STUDENT R	R. L. Polk & Co.
	SASSANO MICHL GRO	R. L. Polk & Co.
	SASSANO ROSE CLK R	R. L. Polk & Co.

14 HAVENS PL

Year	Uses	Source
1960	DAgostino Tony	New York Telephone Company
	Saladino Gaspare Jos	New York Telephone Company
1934	CESARE ALPHONSE LAB H	R. L. Polk & Co.
	CORONA IDA R	R. L. Polk & Co.
	CORONA JENNIE DRESS OPR R	R. L. Polk & Co.
	CORONA SAML R	R. L. Polk & Co.
	CORONA STEFANO BARBER R	R. L. Polk & Co.
	CORONA VINCENT LAB R	R. L. Polk & Co.
	RUSSO CHAS NAVER R	R. L. Polk & Co.
	RUSSO JOS LAB H	R. L. Polk & Co.
	RUSSO JOSEPHINE H	R. L. Polk & Co.
	RUSSO PASQUALE MACH R	R. L. Polk & Co.
	SALAMONE JAS FCTYWKR H	R. L. Polk & Co.
	SALAMONE ROCCO FCTYWKR R	R. L. Polk & Co.

18 HAVENS PL

Year	Uses	Source
1992	CRAWFORD J	NYNEX Informantion Resource Co.
	CRAWFORD J	NYNEX Informantion Resource Co.
	MC CLEOD WANDA	NYNEX Informantion Resource Co.
	CRAWFORD, J	Cole Information
1985	RODRIGUEZ REBECCA	NYNEX Information Resources Company
1976	FIGUEROA ALBERTO	New York Telephone
1970	Marsh Virginia S	New York Telephone
1965	Marsh Virginia S	New York Telephone
	Matias Rafael	New York Telephone
1960	Pennisi Rena	New York Telephone Company

FINDINGS

Year	Uses	Source
1960	Rodriguez Hipolito	New York Telephone Company
1934	DILORENZO ANGELO LAB H	R. L. Polk & Co.
	GROSSI RACHEL INDRY WKR R	R. L. Polk & Co.
	RAIA EDW COMP H	R. L. Polk & Co.
	TRUOCCHIO MICHL LAB H	R. L. Polk & Co.

30 HAVENS PL

Year	Uses	Source
2000	ACTIVE WORLD SOLUTIONS INCORPORATED	Cole Information
	CONTINENTAL MAILING INCORPORATED	Cole Information
	ACTIVE WORLD SOLUTIONS INCORPORATED	Cole Information

62 HAVENS PL

Year	Uses	Source
1940	Ofc	New York Telephone
	Houston Warren S Dr dntst	New York Telephone

80 HAVENS PL

Year	Uses	Source
1965	Whelan Jos R MD of C	New York Telephone

1/8 HAVENS PL

Year	Uses	Source
1934	DOMBRISLO SOMINICK LAB H	R. L. Polk & Co.

HAVENS PL H D

8 HAVENS PL H D

Year	Uses	Source
1934	PIZELLA ANGELO TAILOR O	R. L. Polk & Co.

HAVM

14 HAVM

Year	Uses	Source
1928	FERRANTE G STATY	New York Telephone

FINDINGS

64 HAVM

Year	*Uses*	*Source*
1928	ANNUNCIATION CONVENT	New York Telephone

85 HAVM

Year	*Uses*	*Source*
1928	JACARUSO DONATO BANKER	New York Telephone

92 HAVM

Year	*Uses*	*Source*
1928	ACESTA JOS R	New York Telephone

94 HAVM

Year	*Uses*	*Source*
1928	COMO JOHN R	New York Telephone
	RANDAZZO A TRUCKG	New York Telephone

HAVNE PL

1 HAVNE PL

Year	*Uses*	*Source*
1992	PUPIL TRANSPORTATION	NYNEX Informantion Resource Co.

HAVNS PL

14 HAVNS PL

Year	*Uses*	*Source*
1960	D AGOSTINO TONY	New York Telephone
	SALADINO GASPARE JOS	New York Telephone

18 HAVNS PL

Year	*Uses*	*Source*
1960	PENNISI RENA	New York Telephone
	RODRIGUEZ HIPOLITO	New York Telephone

FINDINGS

HAWN AVE

39 HAWN AVE

Year	Uses	Source
1997	ROSSINA Vincent	NYNEX

HAYDEN

17 HAYDEN

Year	Uses	Source
1980	BANACH DENIS	New York Telephone

HERKIMAR

1488 HERKIMAR

Year	Uses	Source
1985	DOVE T	NYNEX Information Resources Company

HERKIMER

1480 HERKIMER

Year	Uses	Source
1985	ROBLES EMILIO	NYNEX Information Resources Company
1980	ROBLES EMILIO	New York Telephone
1934	CATALONIA PHILIP LAB H	R. L. Polk & Co.
	LABOZZETTA PHILIP FORMN DEPT WATER SUPPLY G & E H	R. L. Polk & Co.
	LORACANO THERESA MRS H	R. L. Polk & Co.
	MAIO JOHN LAB H	R. L. Polk & Co.
	MANNO DOMINICK AUTO MECH PO R	R. L. Polk & Co.
	VIACARL PHILIP PLSHR AND BUFFER H	R. L. Polk & Co.

1482 HERKIMER

Year	Uses	Source
1985	QUINTANILLA HECTOR	NYNEX Information Resources Company
	TRINIDAD WALESKA	NYNEX Information Resources Company
1976	BANKS BARBARA	New York Telephone
	BROWN MARY	New York Telephone

FINDINGS

Year	Uses	Source
1976	BROWN YVONNE	New York Telephone
	CORRIDON NIEAL D	New York Telephone
	FARMER CARLYLE	New York Telephone
	SMITH ELOUISE	New York Telephone
1934	ANOCONES ANTONIO LAB H	R. L. Polk & Co.
	ANOCONES JOS LAB R	R. L. Polk & Co.
	BANO ANTHONY R	R. L. Polk & Co.
	BENASUTTI AUGUSTINE CAR WASHER H	R. L. Polk & Co.
	ERRICO DOMINICK SHOEWKR R	R. L. Polk & Co.
	ERRICO FILOMENA H	R. L. Polk & Co.
	ETRO ANGELO LAB H	R. L. Polk & Co.
	SACCONE ANGELO LAB H	R. L. Polk & Co.
	SACCONE MARY MACH OPR R	R. L. Polk & Co.

1484 HERKIMER

Year	Uses	Source
1992	RIVERA ISRAEL	NYNEX Informantion Resource Co.
1985	RIVERA ISRAEL	NYNEX Information Resources Company
1976	HERNANDEZ ELADIO	New York Telephone
	RIVAS ACASIA	New York Telephone
	RIVERA ISRAEL	New York Telephone
1934	BENINE ANTONIO TIMBER MN H	R. L. Polk & Co.
	GALUZZO ANGELO LAB H	R. L. Polk & Co.
	GUELLA RICHD LAB	R. L. Polk & Co.
	LEVIO DAVID CARP R	R. L. Polk & Co.
	PETTI ALFONSO LAB H	R. L. Polk & Co.
	ZANONI ALDO WELDOR H	R. L. Polk & Co.
	ZANONI ANDREW LAB H	R. L. Polk & Co.
	ZANONI DAVID LAB H	R. L. Polk & Co.
	ZANONI ELIO TIMBERMN R	R. L. Polk & Co.
	ZANONI MICHL LAB R	R. L. Polk & Co.

FINDINGS

1487 HERKIMER

Year	*Uses*	*Source*
1934	MADDEN STEPH F H	R. L. Polk & Co.

1488 HERKIMER

Year	*Uses*	*Source*
1985	DOVE T	NYNEX Information Resources Company
1980	DOVE THELMA	New York Telephone
1934	CAPRIO FRANK LAB H	R. L. Polk & Co.
	CORRIDEO JAS IRON FRAZER H	R. L. Polk & Co.
	D ANDREA MARIE R	R. L. Polk & Co.
	D ANDREA PHILIP PNTR H	R. L. Polk & Co.
	MATURO JOHN H	R. L. Polk & Co.
	SASSANO MICHL GRO	R. L. Polk & Co.
	SASSOON ANTONIO LAB R	R. L. Polk & Co.
	SASSOON MICHL GRO H	R. L. Polk & Co.
	SASSOON ROSE DRESS OPR R	R. L. Polk & Co.
	SASSOON VINCENT LAB R	R. L. Polk & Co.

1495 HERKIMER

Year	*Uses*	*Source*
1992	ATLANTIC WELDING & SPRINKLER REPAIRS	NYNEX Informantion Resource Co.
	DONENFELD KNITWEAR INC	NYNEX Informantion Resource Co.
	JONES DAIDONE ELECTRIC OF N Y INC	NYNEX Informantion Resource Co.
	TRINI REALTY CORP	NYNEX Informantion Resource Co.
1934	WESTERN ELECTRIC CO INC THOS S WILLIAMS MGR	R. L. Polk & Co.

1501 HERKIMER

Year	*Uses*	*Source*
1934	LATUGZ HARRY LAB R	R. L. Polk & Co.
	LATUGZ JOS LAB R	R. L. Polk & Co.
	LATUGZ MICNL MECH R	R. L. Polk & Co.
	LATUGZ ROSE H	R. L. Polk & Co.
	VERDE RALPH CLER OPR H	R. L. Polk & Co.

FINDINGS

1520 HERKIMER

Year	Uses	Source
1992	CALVARY FREE WILL BAPTIST CHURCH INC	NYNEX Informantion Resource Co.
	CALVARY FREE WILL BAPTIST CHURCH INC	NYNEX Informantion Resource Co.
1985	CALVARY	NYNEX Information Resources Company

HERKIMER 34 4775

1495 HERKIMER 34 4775

Year	Uses	Source
1997	Ladies Committee For Puerto Rican Culture	NYNEX

HERKIMER ST

1480 HERKIMER ST

Year	Uses	Source
2020	MAYLENE THOMPSON	EDR Digital Archive
	PATRICE DURANTE	EDR Digital Archive
	JAMAYCE YARDE	EDR Digital Archive
	GERARD PLACIDE	EDR Digital Archive
	SHAKEEM MOREFIELD	EDR Digital Archive
2014	ANTHONY PETTWAY	Cole Information
	DENISE MCKNIGHT	Cole Information
2010	FRANCESCO GOMEZ	Cole Information
	DENISE MCKNIGHT	Cole Information
2005	h Gomez Francesco	Hill-Donnelly Corporation
	Grenne Shaw n YU	Hill-Donnelly Corporation
	CURTIS ROBINSON	Cole Information
	FRANCESCO GOMEZ	Cole Information
	SHAWN GRENNE	Cole Information
2000	LESBIA PINZON	Cole Information
	CYNTHIA ROBINSON	Cole Information
	FRANCES GOMEZ	Cole Information
1997	GOMEZ Francesco	NYNEX

FINDINGS

Year	Uses	Source
1997	PINZON	NYNEX
1992	KUILAN, LUIS	Cole Information
1973	Brown Judie	New York Telephone
	Davis Sarah M	New York Telephone
1970	Olivieri Mario	New York Telephone

1482 HERKIMER ST

Year	Uses	Source
2020	LEEANN HUIETT	EDR Digital Archive
	MEDINA MORRIS	EDR Digital Archive
	MARIA GERMAN	EDR Digital Archive
	EDWIN MONTALVO	EDR Digital Archive
	AURA GERMAN	EDR Digital Archive
	ANN DAVIS	EDR Digital Archive
	DEIDRA SMALL	EDR Digital Archive
	SHAKHIRA SIMMONS	EDR Digital Archive
	WILLIAM MERCED	EDR Digital Archive
	CARLOS CACERES	EDR Digital Archive
	DELORES CONRAD	EDR Digital Archive
	JEREMY JONES	EDR Digital Archive
	GERTRUDE GARCIA	EDR Digital Archive
2017	MARIA GERMAN	Cole Information
	SHAKHIRA SIMMONS	Cole Information
	IRENE SMITH	Cole Information
2014	JIMMY RODRIGUEZ	Cole Information
	WILLIAM MERCED	Cole Information
	CARLOS CACERES	Cole Information
	JEREMY JONES	Cole Information
	GORDON RHODES	Cole Information
2010	FELIPA ALMAZAN	Cole Information
	GERMAN GABIN	Cole Information
	DEIDRA SMALL	Cole Information
	CARLOS CACERES	Cole Information

FINDINGS

Year	Uses	Source
2010	FAITH LAWRENCE	Cole Information
	LAKESHA WHITE	Cole Information
2005	Almazan Felipa	Hill-Donnelly Corporation
	Caceres Carlos	Hill-Donnelly Corporation
	Smalls D	Hill-Donnelly Corporation
	White Lakesha	Hill-Donnelly Corporation
	FELIPA ALMAZAN	Cole Information
	DENISE SMALLS	Cole Information
	MARSHALL PIERCE	Cole Information
	DEIDRA SMALL	Cole Information
	PIERRE CABRAL	Cole Information
	CARLOS CACERES	Cole Information
	ANDREA VEGA	Cole Information
	ANDREW SMITH	Cole Information
	D SEABROOK	Cole Information
2000	R LOPEZ	Cole Information
1992	VELAZQUEZ, RAUL	Cole Information
1973	Austin Y	New York Telephone
	Brown Thomas	New York Telephone
	Jackson Jeanette	New York Telephone
1970	Austin Y	New York Telephone
	Brown Rufus	New York Telephone
	Brown Willie P	New York Telephone

1484 HERKIMER ST

Year	Uses	Source
2020	NORMA REID	EDR Digital Archive
	CYNTHIA ROBINSON	EDR Digital Archive
2017	ROOSEVELT REID	Cole Information
	RUBEN GAUTHIER	Cole Information
	TAKIM ROBINSON	Cole Information
2014	ROOSEVELT REID	Cole Information
	RUBEN GAUTHIER	Cole Information

FINDINGS

Year	Uses	Source
2010	RUESENIA ROBINSON	Cole Information
	RUBEN GAUTHIER	Cole Information
	KENNETH REID	Cole Information
	JEANNETTE SMITH	Cole Information
1973	Hernandez Eladio	New York Telephone
1970	Rivera Israel	New York Telephone

1488 HERKIMER ST

Year	Uses	Source
1973	Jones C	New York Telephone
1970	Peoples Ruby	New York Telephone

1495 HERKIMER ST

Year	Uses	Source
2020	ASPIRATIONS DIPLOMA PLUS HIGH	EDR Digital Archive
	MEGA SECURITIES	EDR Digital Archive
	ROADS CHARTER SCHOOL I	EDR Digital Archive
	NEW VISIONS AIM CHARTER HIGH	EDR Digital Archive
2017	MEGA SECURITIES	Cole Information
	HELPING HANDS MANAGEMENT	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZAT	Cole Information
	ASPIRATIOINS DIPLOMA PLUS HIGH SCHOO	Cole Information
	CITY OF NEW YORK	Cole Information
	EAST NEW YORK LEARNING CENTER INC	Cole Information
2014	ASPIRATIONS DIPLOMA PLUS HIGH SCHOOL	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZAT	Cole Information
	MEGA SECURITIES	Cole Information
	EAST NEW YORK LEARNING CENTER INCORP	Cole Information
	CITY OF NEW YORK	Cole Information
2010	HIGH SCHOOL FOR PUBLIC SAFETY	Cole Information
	ASPIRATIONS DIPLOMA PLUS HS	Cole Information

FINDINGS

Year	Uses	Source
2010	FEDERATION OF PUERTO RICAN ORG	Cole Information
	EAST NEW YORK LEARNING CTR INC	Cole Information
2005	Bonns Environmental Inc	Hill-Donnelly Corporation
	Delbianco Nicholas	Hill-Donnelly Corporation
	Fulton Center LLC	Hill-Donnelly Corporation
	Gutman Sam	Hill-Donnelly Corporation
	High School For Public Safety	Hill-Donnelly Corporation
	Ladies Puerto Rican Culture	Hill-Donnelly Corporation
	Sturdy Concrete Co Corp	Hill-Donnelly Corporation
	EBC HIGH SCHOOL	Cole Information
	PATRICK SARGEANT	Cole Information
2000	STURDY CONCRETE CO CORP	Cole Information
	DOHERTY HUGH	Cole Information
	TRINI REALTY CORPORATION	Cole Information
	NEW YORK CITY OF EDUCATION	Cole Information
	DELBIANCO NICHOLAS	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZATION	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZATIONS	Cole Information
	LADIES COMMITTEE FOR PUERTO RICAN CULTURE	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZATIONS	Cole Information
1997	Federation Of Puerto Rican Organization	NYNEX
	Ladies Committee For Puerto Rican Culture	NYNEX
	Monti Moving & Storage	NYNEX
	Trini Realty Corp	NYNEX
1995	LADIES COMMITTEE FOR PUERTO RICAN CULTURE	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZATION	Cole Information
	TRINI REALTY CORP	Cole Information
	NYC EDUCATION-CITY BOARD OF-SCHOOLS-HIGH-EBC DHS HIGH SCHOOL FOR PUBLIC SERVICE IN BUSHWICKK	Cole Information

FINDINGS

Year	Uses	Source
1995	FEDERATION OF PUERTO RICAN ORGANIZATIONS	Cole Information
	NYC EDUCATION-CITY BOARD OF-SCHOOLS-HIGH-EBC DHS HIGH SCHOOL FOR PUBLIC SERVICE IN EAST NEW YORKK	Cole Information
	DELBIANCO NICHOLAS	Cole Information
	MONTI MOVING & STORAGE	Cole Information
1992	JONES DAIDONE ELECTRIC OF N Y INC	Cole Information
	LADIES COMMITTEE FOR PUERTO RICAN CULTURE	Cole Information
	FEDERATION OF PUERTO RICAN ORGANIZATION	Cole Information
	TRINI REALTY CORP	Cole Information
	WORLD-WIDE PET SUPL	Cole Information
	DONENFELD KNITWEAR INC	Cole Information
	FEDERATION OF PUERTO RICAN	Cole Information
	ATLANTIC WELDING & SPRINKLER REPAIRS	Cole Information

1515 HERKIMER ST

Year	Uses	Source
2014	2020 CAR SERVICE	Cole Information
2010	2020 CAR SVC	Cole Information

1520 HERKIMER ST

Year	Uses	Source
2020	CALVARY FREE WILL BAPTIST CHR	EDR Digital Archive
	CLENSO ALLEN	EDR Digital Archive
	MONICA ALLEN	EDR Digital Archive
2017	CALVARY FREE WILL BAPTIST CHURCH	Cole Information
2014	CALVARY FREE WILL BAPTIST CHURCH	Cole Information
2010	CLENSO ALLEN	Cole Information
	CALVARY FREE WILL BAPTIST CHR	Cole Information
2005	Calvary Free Will Baptist Chr	Hill-Donnelly Corporation
	Goodwin C	Hill-Donnelly Corporation
	CALVARY FREE WILL BAPTIST CHURCH INC	Cole Information

Year	Uses	Source
2000	REACHING OUR YOUTH FOUNDATION	Cole Information
	R O Y FOUNDATION	Cole Information
	CALVARY FREE WILL BAPTIST CHURCH INCORPORATED	Cole Information
1997	Calvary Free Will Baptist Church Inc	NYNEX
	Calvary Free Will Baptist Church Inc	NYNEX
1995	TUCKER, DIANE	Cole Information
	CALVARY FREE WILL BAPTIST CHURCH INC	Cole Information
1992	CALVARY FREE WILL BAPTIST CHURCH INC	Cole Information

HERKINER

1482 HERKINER

Year	Uses	Source
1934	BONUZAO ANTHONY LAB H	R. L. Polk & Co.
	VERONESI LINO TIMBERMAN H	R. L. Polk & Co.

HERKMER

1495 HERKMER

Year	Uses	Source
1997	Federation Of Puerto Rican Organizatin	NYNEX

HERKMER st

1484 HERKMER st

Year	Uses	Source
1973	Rivera Israel	New York Telephone

NEW YORK AVE

1761 NEW YORK AVE

Year	Uses	Source
1992	GERSAN SCRAP & CARTING INC	NYNEX Informantion Resource Co.
1985	GERSAN SCRAP & CARTING INC	NYNEX Information Resources Company
1976	SAM S BY PRODS	New York Telephone

FINDINGS

Year	Uses	Source
1965	Sams By Prods	New York Telephone
1960	MESSINEO SALVATORE PRKNG STA	New York Telephone
	SAM S BY PRODS	New York Telephone
	Messineo Salvatore prkng sta	New York Telephone Company
	Sams By Prods	New York Telephone Company

1785 NEW YORK AVE

Year	Uses	Source
2005	Promotional Development Inc	Hill-Donnelly Corporation
2000	PRMTAL DEV INC	Cole Information
1985	STEWART AVIONICS INC	NYNEX Information Resources Company
	STEWART PRECISION CORP	NYNEX Information Resources Company
1976	STEWART AVIONICS INC	New York Telephone
1973	Stew art Avionics Inc	New York Telephone
1970	Stew art Avionics Inc	New York Telephone
1965	Stew art Avionics Inc	New York Telephone
1960	STEWART STEEL PRODS INC	New York Telephone
	Stew art Steel Prods Inc	New York Telephone Company
1949	Autobody Crafts Inc	New York Telephone Company
1945	Internatl Renting Svc Inc	New York Telephone
	Milano Bros auto rentng	New York Telephone

1801 NEW YORK AVE

Year	Uses	Source
1928	KANNER CHAS AUTO REPAIRS	New York Telephone
	RELIABLE SERVICE AUTO CO	New York Telephone

1809 NEW YORK AVE

Year	Uses	Source
1960	BOOKMAN MORRIS	New York Telephone
	Bookman Morris	New York Telephone Company
1949	Bookman Morris	New York Telephone Company
1945	Bookman Morris	New York Telephone
1940	Bookman Morris	New York Telephone

FINDINGS

1811 NEW YORK AVE

Year	Uses	Source
2005	No Current Listing	Hill-Donnelly Corporation
2000	ELSA P ORTIZ	Cole Information
1997	DIAZ Diana	NYNEX
1976	DIBELLA JOS	New York Telephone
1970	Di Bella Jos	New York Telephone
1960	COLUCCI ALBERT	New York Telephone
	DIBELLA JOS	New York Telephone
	Colucci Albert	New York Telephone Company
	Di Bella Jos	New York Telephone Company
1949	Di Bella Jos	New York Telephone Company
1945	Di Bella Jos	New York Telephone

NY AVE

1767 NY AVE

Year	Uses	Source
1934	TOMASONE DOMINICK LAB R	R. L. Polk & Co.

1785 NY AVE

Year	Uses	Source
1940	Tri Line Motors Inc	New York Telephone

1787 NY AVE

Year	Uses	Source
1934	MOTOR SALES INC JOS A LAU PRES-TREAS FRANK A FEGYVERESI V-PRES-SEC	R. L. Polk & Co.

1797 NY AVE

Year	Uses	Source
1934	LUBACH JOHN R	R. L. Polk & Co.

1801 NY AVE

Year	Uses	Source
1934	MINTZ LOUIS R	R. L. Polk & Co.

FINDINGS

1805 NY AVE

Year	*Uses*	*Source*
1934	GILLIS R	R. L. Polk & Co.
	GILLIS BERANGER H	R. L. Polk & Co.
	GILLIS EDMUND DIEMKR R	R. L. Polk & Co.

1811 NY AVE

Year	*Uses*	*Source*
1934	LOEFFLER WM R POLICEMN PD H	R. L. Polk & Co.

VAN SINDERE AVE

26 VAN SINDERE AVE

Year	*Uses*	*Source*
1934	RUTH & MATTHEWS INC ARTH J RUTH PRES HENRY R MATTHEWS SEC-TREAS AUTO DIRSN	R. L. Polk & Co.

VAN SINDEREN AV H

50 VAN SINDEREN AV H

Year	*Uses*	*Source*
1934	PIZELLA ANTHONY GRO DO	R. L. Polk & Co.

VAN SINDEREN AVE

35 VAN SINDEREN AVE

Year	*Uses*	*Source*
1940	Hercules Corner Bead Co	New York Telephone

38 VAN SINDEREN AVE

Year	*Uses*	*Source*
2000	DISPLAY DEPOT INC	Cole Information
	WROUGHT ORGNLS INC	Cole Information
	DISPLAY DEPOT INCORPORATED	Cole Information
	WROUGHT ORIGINALS INCORPORATED	Cole Information
1997	Wrought Originals Inc	NYNEX
1995	WROUGHT ORIGINALS INC	Cole Information

Year	Uses	Source
1976	BEJAN KNITTING MILLS	New York Telephone
1970	Majestic Steel Cabinet Corp	New York Telephone

50 VAN SINDEREN AVE

Year	Uses	Source
1973	Atlantic Cabinet Corp	New York Telephone
1970	Atlantic Cabinet Corp	New York Telephone
1965	Atlantic Cabinet Corp	New York Telephone
1960	Atlantic Cabinet Corp	New York Telephone Company
1934	PIZELLA JOS STUDENT R	R. L. Polk & Co.
	PIZELLA MARY CLK R	R. L. Polk & Co.

VAN SINDRN AVE

50 VAN SINDRN AVE

Year	Uses	Source
1960	ATLANTIC CABINET CORP	New York Telephone

VANSINDEREN AVE

38 VANSINDEREN AVE

Year	Uses	Source
1992	WROUGHT ORIGINALS INC	Cole Information

WEST HAVEN SQ

14 WEST HAVEN SQ

Year	Uses	Source
1960	PRINTUFT INC TEXTL PRNTRS	New York Telephone

WILLIAM PL

32 WILLIAM PL

Year	Uses	Source
1928	DILLON CATHERINE R MISS R	New York Telephone

FINDINGS

WILLIAMS CT

10 WILLIAMS CT

Year	Uses	Source
1928	HEITMULLER HERBERT R	New York Telephone
	MODERN CARPET CLEANING & STORAGE CORP	New York Telephone

WILLIAMS PL

9 WILLIAMS PL

Year	Uses	Source
1928	CHIAET ORNAMENTAL IRON WKS	New York Telephone
	KASSOV & PENCUS LIGHTING FIXTURES	New York Telephone
	MCGANN WM C	New York Telephone

33 WILLIAMS PL

Year	Uses	Source
1992	MYSTIC DISPLAY CO INC	NYNEX Informantion Resource Co.
1985	KEYPORT MFG INC WOOD PRODS	NYNEX Information Resources Company

45 WILLIAMS PL

Year	Uses	Source
1976	PRINT PAK CORP	New York Telephone
1928	BENZING JOS H & CO INC LUMBER	New York Telephone

WILLIAMS CT

18 WILLIAMS CT

Year	Uses	Source
1997	RYBAK Miriam	NYNEX

WILLIAMS PL

9 WILLIAMS PL

Year	Uses	Source
1976	CHIAET ORNAMENTAL IRON WKS	New York Telephone
1960	CHIAET ORNAMENTAL IRON WKS	New York Telephone

FINDINGS

Year	Uses	Source
1960	MEDITZ IRON WORKS INC	New York Telephone
1934	CHLAET ORNAMONTAL IRON WORKS INC (NY CAP $50000) SAML CHLAET PRES WM MCGRAM	R. L. Polk & Co.
	KASSOV & PENOUS LIGHTING FIXTURE	R. L. Polk & Co.

15 WILLIAMS PL

Year	Uses	Source
1934	BENZING JOS H & CO INC JOS H BENZING PRES IRVING J BENZING V-PRES CLIFFORD	R. L. Polk & Co.

24 WILLIAMS PL

Year	Uses	Source
2005	TAUBS FLOOR COVERING	Cole Information

33 WILLIAMS PL

Year	Uses	Source
2017	MYSTIC DISPLAY CO INC	Cole Information
	ACL LOCKSMITH	Cole Information
	MARKETING HORIZONS DISPLAY	Cole Information
2014	MARKETING HORIZONS DISPLAY	Cole Information
	MYSTIC DISPLAY COMPANY INCORPORATED	Cole Information
2010	MARKETING HORIZONS DISPLAY	Cole Information
	MYSTIC DISPLAY CO	Cole Information
2005	Marketing Horizons Display	Hill-Donnelly Corporation
	Mystic Display Co	Hill-Donnelly Corporation
	MYSTIC DISPLAYS CO INC	Cole Information
	MARKETING HORIZONS DISPLAY	Cole Information
2000	MYSTIC DISPLAY CO	Cole Information
	MYSTIC DISPLAY COMPANY INCORPORATED	Cole Information
1997	Mystic Display Co Inc	NYNEX
1995	MYSTIC DISPLAY CO INC	Cole Information
1992	MYSTIC DISPLAY CO INC	Cole Information

FINDINGS

45 WILLIAMS PL

Year	*Uses*	*Source*
1973	G B H Bldg Supplier Corp	New York Telephone
1945	Bending Jos H & Cp Inc lumber	New York Telephone
1940	Benzing Jos H & Co Inc lumber	New York Telephone

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
Atlantic Avenue	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
Herkimer Street	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
Williams Place	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1 HAVEN PL	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1 HAVENS PL	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1934, 1928
1 HAVNE PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1/8 HAVENS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
10 HAVENS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1928
10 WILLIAMS CT	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
14 HAVENS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1928
14 HAVM	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
14 HAVNS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
14 WEST HAVEN SQ	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
1480 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1480 HERKIMER ST	2017, 1995, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1482 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1482 HERKIMER ST	1997, 1995, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1482 HERKINER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1484 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1484 HERKIMER ST	2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
1484 HERKMER st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1487 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1488 HERKIMAR	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1488 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1488 HERKIMER ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1495 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1495 HERKIMER 34 4775	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1495 HERKIMER ST	1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1495 HERKMER	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
15 HAVEN AV FR RKWY	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1934, 1928
15 WILLIAMS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1501 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1515 HERKIMER ST	2020, 2017, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1520 HERKIMER	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1520 HERKIMER ST	1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
17 HAYDEN	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1761 E NEW YORK AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1761 NEW YORK AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1980, 1973, 1970, 1949, 1945, 1940, 1934, 1928
1767 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1785 E NEW YORK AVE	2020, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1785 NEW YORK AVE	2020, 2017, 2014, 2010, 1997, 1995, 1992, 1980, 1940, 1934, 1928
1785 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
1787 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
1797 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
18 HAVEN PL	2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
18 HAVENS AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
18 HAVENS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1980, 1973, 1949, 1945, 1940, 1928
18 HAVNS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
18 WILLIAMS CT	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1801 NEW YORK AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
1801 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1805 E NEW YORK AVE	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1805 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
1809 NEW YORK AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1934, 1928
1811 E NEW YORK AVE	2020, 2017, 2010, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
1811 NEW YORK AVE	2020, 2017, 2014, 2010, 1995, 1992, 1985, 1980, 1973, 1965, 1940, 1934, 1928
1811 NY AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
24 WILLIAMS PL	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2431 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2436 ATLANTIC AVE	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2458 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
2461 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2463 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1934
2465 ATLANTIC AVE	2020, 2017, 2014, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1945
2465 ATLANTIS AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2467 ATLANTIC AVE	2020, 2010, 2005, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
2469 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940
2471 ATLANTIC AVE	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1949, 1945, 1934
2471 ATLANTIO AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
2471 ATLNTC	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
2471 ATLNTC AV DICKAUS st	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
2473 ATLANTIC AVE	2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1960, 1945, 1940, 1928
2475 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1945, 1940, 1934
2481 ATLANTIC AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1928
26 VAN SINDERE AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3 HAVEN PL	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
30 HAVEN PL	2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
30 HAVENS PL	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
32 WILLIAM PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
33 WILLIAMS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
33 WILLIAMS PL	2020, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
35 VAN SINDEREN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
38 VAN SINDEREN AVE	2020, 2017, 2014, 2010, 2005, 1992, 1985, 1980, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
38 VANSINDEREN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
39 HAWN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
45 WILLIAMS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
45 WILLIAMS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1934, 1928
50 HAVEN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
50 VAN SINDEREN AV H	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
50 VAN SINDEREN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1949, 1945, 1940, 1928
50 VAN SINDRN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
54 HAVEN	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
54 HAVEN MOUNT VERN	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
54 HAVEN St	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
62 HAVENS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
64 HAVM	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
70 HAVEN AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940
8 HAVENS PL H D	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
80 HAVENS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
85 HAVM	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
9 WILLIAMS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
9 WILLIAMS PL	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1949, 1945, 1940, 1928
92 HAVM	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
94 HAVM	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
45 Van Sinderen Avenue	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1928

APPENDIX F
SITE QUESTIONNAIRE
AND RELEVANT DOCUMENTS

SUBJECT PROPERTY OCCUPANT QUESTIONNAIRE

P.W. Grosser Consulting Inc. (PWGC) has been contracted to perform a Phase I Environmental Site Assessment (ESA) of the property listed below. The Phase I ESA will include site observations, interviews, and review of available documentation. To ensure the success of the assessment, and in accordance with ASTM Standard E1527-21 we are required to ask the following questions of subject property occupants. If you could please complete this questionnaire and return it via email within one business day of receipt it will allow us to complete the Phase I ESA in a timely and efficient manner.

Date Completed:	Wednesday 03/26/25
Subject Property Address:	45 Van Sinderen Avenue, Brooklyn, NY
Name:	Stephen, employee of Great Goods
Company:	Great Goods, 1st Floor Tenant
Length of association with property:	At least 3 years
Phone Number:	
Email Address:	

Directions: Please read and answer all questions very carefully, to the best of your knowledge and in good faith. Mark the column corresponding to the appropriate response. Supplemental details necessary to explain any yes or unknown responses should be provided in the "Comments" column. Note: U/NR indicates "Unknown" or "No Response," and "N/A" indicates not applicable. If "Comment" box proves too small to fit your comment, please use the "additional information" section at the end of this form.

	Question	Yes	No	U/NR	Comment
1	Is the subject property currently, or to the best of your knowledge in the past, used for an industrial use?		√		
2	Are any adjoining properties currently, or to the best of your knowledge in the past, used for an industrial use?			√	
3	Is the property currently, or to the best of your knowledge in the past, used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junk yard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?			√	
4	Is any adjoining property currently, or to the best of your knowledge in the past, used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junk yard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?			√	
5	Are there currently or to the best of your knowledge in the past, any automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers greater than five gallons in the aggregate, stored on or used at the subject property?		√		

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • SYRACUSE • SHELTON, CT

Question		Yes	No	U/NR	Comment
6	Are there currently or to the best of your knowledge in the past, any industrial drums (typically 55 gallon) or sacks of chemicals located on the property?		√		
7	Is there currently or to the best of your knowledge in the past, any groundwater monitoring wells or other groundwater wells (e.g., potable drinking water wells) located on the property?		√		
8	Has fill dirt been brought onto the property which originated from a contaminated site or unknown origin?		√		
9	Are there currently or to the best of your knowledge in the past, any pits, ponds or lagoons located on the property in connection with waste treatment or waste disposal?			√	
10	Is there currently, or to the best of your knowledge in the past, any stained soil on the property?		√		
11	Are there currently or to the best of your knowledge in the past, any registered or unregistered storage tanks (above or underground) located on the property?			√	
12	Are there currently or to the best of your knowledge in the past, any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the property or adjacent to any structure located on the property?			√	
13	Are there currently, or to the best of your knowledge in the past, any onsite sanitary systems, cesspools, storm drains, floor drains, drywells or other leaching pools located on the property.			√	
14	Does the property discharge wastewater on or adjacent to the property, other than storm water, or into a sanitary system?		√		
15	Are there currently or to the best of your knowledge in the past, any flooring, drains, or walls located at the property that are stained by substances other than water or are emitting foul odors?		√		
16	If the property is served by a private well or non-public water system, have contaminants been identified in the well or system that exceed guidelines applicable to the water system, or has the well been designated as contaminated by any government environmental/health agency?			√	
17	Have you been informed of the current or past existence of hazardous substances or petroleum products with respect to the property or any facility located on the property?			√	
18	Have any hazardous substances or petroleum products, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials been dumped above grade, buried and/or burned on the property?			√	
19	Is there a transformer, capacitor or any hydraulic equipment for which there are any records indicating the presence of PCBs?		√		

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • SYRACUSE • SHELTON, CT

	Question	Yes	No	U/NR	Comment
20	Are there currently, or to the best of your knowledge in the past, any identified asbestos containing materials (ACM), in any application, on the property, ACM testing conducted on the property, or an ACM Operations and Maintenance (O&M) program in place at the property?			√	
21	Are there currently, or to the best of your knowledge in the past, any identified lead-based paint (LBP), in any application, on the property, LBP testing conducted on the property, or an LBP O&M program in place at the property?		√		Exposed brick walls
22	Are there any other O&M programs in place that we should be made aware of?			√	
23	Has potable water at the property ever been tested for lead?			√	
24	Has radon testing ever been conducted at the property?			√	
25	Has there ever been any Indoor Air Quality (IAQ) or mold testing conducted in the building(s)?			√	
26	Is there now, or to the best of your knowledge in the past, evidence of mold or mildew present at the building(s)?		√		
27	Is there now, or to the best of your knowledge in the past, water damage in the building(s), whether from flooding, plumbing, roof leaks, or other sources? If so, when?		√		
28	Is the property or any portion of the property located or involved in any environmentally sensitive areas (e.g., wetlands, coastal barrier resource areas, coastal barrier improvement act areas, flood plains, endangered species, etc.)?			√	
29	Are you aware of any environmental liens filed or recorded against the subject property under federal, tribal, state, or local law?			√	
30	Are you aware of land title records (or judicial records where appropriate) that identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the subject property and/or have been filed or recorded against the subject property under federal, tribal, state or local law?			√	
31	Are you aware of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the property?			√	
32	Are you aware of any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on or from the property?		√		

	Question	Yes	No	U/NR	Comment
33	Are you aware of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?			√	
34	Do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?			√	
35	Are you aware of commonly known or reasonably ascertainable information about the subject property that would help the environmental professional to identify conditions indicative of releases or threatened releases?			√	
36	Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of releases at the subject property			√	
37	Have there been any environmental site assessments of the property that indicated the presence of hazardous substances or petroleum products on, or contamination of, the property or recommended further assessment of the property?			√	
38	Are you aware of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?			√	
39	Are you aware of any fires at the subject property that required the municipal fire department to respond?	√			Fire in north yard, garbage truck about two years ago

In addition, are you aware of any of the following documents, and if so, please forward copies of the document(s) to P.W. Grosser Consulting at 630 Johnson Ave, Ste 7, Bohemia, NY 11716-2618 (along with a copy of this form):

- Environmental site assessment reports (e.g., Phase I or II ESAs, tank testing results, radon, lead paint, or asbestos testing, etc.).
- Environmental compliance audit reports; risk assessments; and recorded Activity and Use Limitations (AULs).
- Environmental permits (e.g., solid waste disposal, hazardous waste disposal, wastewater, NPDES, etc.).
- Registrations for underground storage tanks (USTs) and aboveground storage tanks (ASTs).
- Registrations for underground injection systems Material safety data sheets.
- Community right to know plan.
- Safety plans; preparedness and prevention plans; spill prevention, countermeasure/control plans, etc.
- Reports regarding hydrogeological or geotechnical conditions on the property and surrounding area.
- Notices/correspondence from any agency relating to past or current violations of environmental laws, or liens encumbering the property.
- Hazardous waste generator notices or report.

Please Enter Any Additional Comments or Information on This Page:

Great Goods, Stephen is employee of the tenant of first floor. Basement, accoring to Mike (tenant holder) that basement is associated with Great Goods, but is locked.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • SYRACUSE • SHELTON, CT

SUBJECT PROPERTY OCCUPANT QUESTIONNAIRE

P.W. Grosser Consulting Inc. (PWGC) has been contracted to perform a Phase I Environmental Site Assessment (ESA) of the property listed below. The Phase I ESA will include site observations, interviews, and review of available documentation. To ensure the success of the assessment, and in accordance with ASTM Standard E1527-21 we are required to ask the following questions of subject property occupants. If you could please complete this questionnaire and return it via email within one business day of receipt it will allow us to complete the Phase I ESA in a timely and efficient manner.

Date Completed:	Wednesday 03/26/25
Subject Property Address:	45 Van Sinderen Avenue, Brooklyn, NY
Name:	Tom
Company:	2nd Floor Tenant; Rented studio spaces
Length of association with property:	At least 5 years; Lease holder 2 years
Phone Number:	
Email Address:	

Directions: Please read and answer all questions very carefully, to the best of your knowledge and in good faith. Mark the column corresponding to the appropriate response. Supplemental details necessary to explain any yes or unknown responses should be provided in the "Comments" column. Note: U/NR indicates "Unknown" or "No Response," and "N/A" indicates not applicable. If "Comment" box proves too small to fit your comment, please use the "additional information" section at the end of this form.

	Question	Yes	No	U/NR	Comment
1	Is the subject property currently, or to the best of your knowledge in the past, used for an industrial use?		✓		
2	Are any adjoining properties currently, or to the best of your knowledge in the past, used for an industrial use?			✓	
3	Is the property currently, or to the best of your knowledge in the past, used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junk yard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?		✓		
4	Is any adjoining property currently, or to the best of your knowledge in the past, used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junk yard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?			✓	
5	Are there currently or to the best of your knowledge in the past, any automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers greater than five gallons in the aggregate, stored on or used at the subject property?		✓		

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • SYRACUSE • SHELTON, CT

	Question	Yes	No	U/NR	Comment
6	Are there currently or to the best of your knowledge in the past, any industrial drums (typically 55 gallon) or sacks of chemicals located on the property?		✓		Paint gallons on site (2nd floor, non lead)
7	Is there currently or to the best of your knowledge in the past, any groundwater monitoring wells or other groundwater wells (e.g., potable drinking water wells) located on the property?		✓		
8	Has fill dirt been brought onto the property which originated from a contaminated site or unknown origin?		✓		
9	Are there currently or to the best of your knowledge in the past, any pits, ponds or lagoons located on the property in connection with waste treatment or waste disposal?			✓	
10	Is there currently, or to the best of your knowledge in the past, any stained soil on the property?		✓		
11	Are there currently or to the best of your knowledge in the past, any registered or unregistered storage tanks (above or underground) located on the property?			✓	
12	Are there currently or to the best of your knowledge in the past, any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the property or adjacent to any structure located on the property?			✓	
13	Are there currently, or to the best of your knowledge in the past, any onsite sanitary systems, cesspools, storm drains, floor drains, drywells or other leaching pools located on the property.			✓	
14	Does the property discharge wastewater on or adjacent to the property, other than storm water, or into a sanitary system?		✓		
15	Are there currently or to the best of your knowledge in the past, any flooring, drains, or walls located at the property that are stained by substances other than water or are emitting foul odors?		✓		
16	If the property is served by a private well or non-public water system, have contaminants been identified in the well or system that exceed guidelines applicable to the water system, or has the well been designated as contaminated by any government environmental/health agency?			✓	Public water system
17	Have you been informed of the current or past existence of hazardous substances or petroleum products with respect to the property or any facility located on the property?			✓	
18	Have any hazardous substances or petroleum products, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials been dumped above grade, buried and/or burned on the property?			✓	
19	Is there a transformer, capacitor or any hydraulic equipment for which there are any records indicating the presence of PCBs?		✓		

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • SYRACUSE • SHELTON, CT

	Question	Yes	No	U/NR	Comment
20	Are there currently, or to the best of your knowledge in the past, any identified asbestos containing materials (ACM), in any application, on the property, ACM testing conducted on the property, or an ACM Operations and Maintenance (O&M) program in place at the property?			✓	
21	Are there currently, or to the best of your knowledge in the past, any identified lead-based paint (LBP), in any application, on the property, LBP testing conducted on the property, or an LBP O&M program in place at the property?			✓	Chipped paint on stairway walls
22	Are there any other O&M programs in place that we should be made aware of?			✓	
23	Has potable water at the property ever been tested for lead?		✓		
24	Has radon testing ever been conducted at the property?		✓		
25	Has there ever been any Indoor Air Quality (IAQ) or mold testing conducted in the building(s)?		✓		
26	Is there now, or to the best of your knowledge in the past, evidence of mold or mildew present at the building(s)?		✓		
27	Is there now, or to the best of your knowledge in the past, water damage in the building(s), whether from flooding, plumbing, roof leaks, or other sources? If so, when?		✓		Stained wall in hallway
28	Is the property or any portion of the property located or involved in any environmentally sensitive areas (e.g., wetlands, coastal barrier resource areas, coastal barrier improvement act areas, flood plains, endangered species, etc.)?		✓		
29	Are you aware of any environmental liens filed or recorded against the subject property under federal, tribal, state, or local law?			✓	
30	Are you aware of land title records (or judicial records where appropriate) that identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the subject property and/or have been filed or recorded against the subject property under federal, tribal, state or local law?			✓	
31	Are you aware of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the property?			✓	
32	Are you aware of any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on or from the property?		✓		

	Question	Yes	No	U/NR	Comment
33	Are you aware of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?			✓	
34	Do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?			✓	
35	Are you aware of commonly known or reasonably ascertainable information about the subject property that would help the environmental professional to identify conditions indicative of releases or threatened releases?			✓	
36	Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of releases at the subject property			✓	
37	Have there been any environmental site assessments of the property that indicated the presence of hazardous substances or petroleum products on, or contamination of, the property or recommended further assessment of the property?			✓	
38	Are you aware of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?			✓	
39	Are you aware of any fires at the subject property that required the municipal fire department to respond?		✓		

In addition, are you aware of any of the following documents, and if so, please forward copies of the document(s) to P.W. Grosser Consulting at 630 Johnson Ave, Ste 7, Bohemia, NY 11716-2618 (along with a copy of this form):

- Environmental site assessment reports (e.g., Phase I or II ESAs, tank testing results, radon, lead paint, or asbestos testing, etc.).
- Environmental compliance audit reports; risk assessments; and recorded Activity and Use Limitations (AULs).
- Environmental permits (e.g., solid waste disposal, hazardous waste disposal, wastewater, NPDES, etc.).
- Registrations for underground storage tanks (USTs) and aboveground storage tanks (ASTs).
- Registrations for underground injection systems Material safety data sheets.
- Community right to know plan.
- Safety plans; preparedness and prevention plans; spill prevention, countermeasure/control plans, etc.
- Reports regarding hydrogeological or geotechnical conditions on the property and surrounding area.
- Notices/correspondence from any agency relating to past or current violations of environmental laws, or liens encumbering the property.
- Hazardous waste generator notices or report.

Please Enter Any Additional Comments or Information on This Page:

Tom, lease holder of second floor. Has held the lease for about two years, was a renter of the same space starting five years ago. Space has two bathrooms, no floor drains. Tenant said he did not dump anything other than grey water down the drains, but unsure of what his renters do. Paint was observed in the bathroom sink. Spaces are rented to mostly painters and some textile artists.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • SYRACUSE • SHELTON, CT

PHASE I ENVIRONMENTAL SITE ASSESSMENT

45 Van Sinderen Avenue
Brooklyn, New York 11207
CBRE Project No.: PC80947573-102

Prepared For:
Metropolitan Commercial Bank

www.cbre.com/Assessment

CBRE



ASSESSMENT & CONSULTING SERVICES

55 West Red Oak Lane
White Plains, New York 10604
914.694.9600 Tel
914.694.1335 Fax

September 26, 2018

Ms. Rita Sirota
AVP, Credit Administration
Metropolitan Commercial Bank
99 Park Avenue, 4th Floor
New York, New York 10016
(212) 365-6731 (tel)
rsirota@MetropolitanBankNY.com

Re: Phase I Environmental Site Assessment
45 Van Sinderen Avenue
Brooklyn, New York 11207
CBRE Project No.: PC80947573-102

Dear Ms. Sirota:

CBRE, Inc., a Delaware corporation ("CBRE") is pleased to submit this copy of our Phase I Environmental Site Assessment on the above-referenced property. The report was prepared solely for the use of Metropolitan Commercial Bank and any party specifically referenced in Section 2.1. No other party shall use or rely on this report or the findings herein, without the prior written consent of CBRE.

I declare that, to the best of my professional knowledge and belief, I meet the definition of *environmental professional* as defined in § 312.10 of 40 CFR 312 and I have the specific qualifications based on education, training, and experience to assess a *property* of the nature, history, and setting of the *subject property*. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Please contact the undersigned at (703) 225-8563 or by email at jeremiah.okrasinski@cbre.com should you have any questions.

Sincerely,

CBRE, Inc. – ASSESSMENT AND CONSULTING SERVICES

Alex Singh
Environmental Professional

Jeremy Okrasinski, LEED AP
Director, Project Management

Table of Contents

Cover Sheet
Transmittal Letter

1.0 EXECUTIVE SUMMARY 1
2.0 INTRODUCTION 4
3.0 SALIENT ASSIGNMENT INFORMATION 9
4.0 SITE DESCRIPTION 10
5.0 HISTORICAL USE 15
6.0 REGULATORY REVIEW 20
7.0 SITE RECONNAISSANCE 35
8.0 INTERVIEWS 39
9.0 VAPOR ENCROACHMENT SCREENING 43
10.0 FINDINGS, CONCLUSIONS AND RECOMMENDATIONS 44
11.0 LIMITING CONDITIONS 46

APPENDICES

Photographs ..... A
Pre-Survey Questionnaire ..... B
Maps and/or Historical Aerial Photographs C
Computerized Environmental Report ..... D
Correspondence and Supporting Documents ..... E
City Directory Abstract ..... F
Personnel Qualifications ..... G

1.0 EXECUTIVE SUMMARY

This report documents CBRE's findings from our Phase I Environmental Site Assessment on the property located at 45 Van Sinderen Avenue, Brooklyn, New York (the "Subject"). The property, which is situated in an urban area characterized by light industrial and residential development, consists of a 0.30-acre parcel improved with a 97-year-old (built in 1921), two-story warehouse and loft building that is currently used as a warehouse for furniture storage on the first floor and artist studios on the second floor. The Subject also includes an attached yard that is used for truck storage for an ironworks company.

Prior to the construction of the existing improvements, the Subject property was improved with small buildings used for coal and wood storage associated with the Thatford and Ackerman Coal and Lumber Yard since at least 1888 and was likely vacant land prior to that. The current Subject building was constructed in 1921 and was used as a rolled gold manufacturing facility in 1932 and an instrument testing company from 1951 until the early 2000s.

The purpose of this Phase I Environmental Site Assessment was to assess existing site conditions and render an opinion as to the identified or potential presence of recognized environmental conditions in connection with the property within the scope and limitations of ASTM International's Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process E 1527-13 and the limitations identified herein. Exceptions to or deletions from the scope of work are described in Section 2.0.

Findings, Opinions and Conclusions

The term Recognized Environmental Conditions (RECs) is defined by ASTM Standard E 1527-13 as "...the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. This assessment has revealed no evidence of recognized environmental conditions (RECs) in connection with the Subject.

A Controlled Recognized Environmental Condition *(CREC)* as defined by ASTM Standard E 1527-13 refers to a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. CBRE did not identify CRECs in connection with the Subject.

An historical recognized environmental condition (HREC) refers to an environmental condition which would have been considered a REC in the past, but which is no longer considered a REC based on subsequent assessment and/or remediation of any contaminants to below the most restrictive (generally residential) cleanup target concentrations or regulatory closure with no formal or implied restricted uses. CBRE did not identify HRECs in connection with the Subject.

No significant data gaps were identified that would affect the ability of the environmental professional to identify RECs at the Subject.

The ASTM Standard was designed solely to meet the requirements of the USEPA's All Appropriate Inquiries (AAI) to permit the potential purchaser to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability, but recognizes that a User may choose to evaluate other business environmental risks (BERs). The investigation has revealed no BERs associated with the standard ASTM scope considerations.

At the request of Client, CBRE conducted a preliminary evaluation for asbestos-containing material (ACM), radon, lead-based paint (LBP), drinking water quality, mold and wetlands which are ASTM Non-Scope Considerations. This investigation has revealed no business environmental risks relating to these ASTM Non-Scope Considerations in connection with the Subject except for the following:

- Based on the age of the site improvements, the potential use of ACMs exists. No friable suspect ACM was identified in readily accessible areas. However, the non-friable resilient floor finish assemblies, plasters, built-up roofing system, caulking, and mastics may contain asbestos. Note, additional suspect ACMs may exist in inaccessible locations such as behind walls, above ceilings, and beneath visible flooring. Since these non-friable materials are in good condition and the potential for fiber release is low, no further action is recommended at this time, other than maintaining the materials in good condition under an Asbestos Operations and Maintenance (O&M) Program. However, in the event that building maintenance, renovation, or demolition activities require the removal or disturbance of the suspect ACM, CBRE recommends that they be characterized for asbestos by a material specific reliable method for detecting asbestos. All activities involving ACM should be conducted in accordance with governmental regulations.

- Since the Subject was constructed prior to the Consumer Product Safety Commission's 1978 ban on the sale of LBP to consumers and the use of LBP in residences, there is a potential that LBP may have been applied at the Subject. Testing would be required in order to determine whether LBP exists. Painted

surfaces observed were in good condition with no excessive peeling or flaking. No further action is recommended at this time. However, all activities involving LBP should be conducted in accordance with HUD guidelines, the USEPA's Lead-Based Paint Renovation, Repair and Painting Program Rule as well as the OSHA Lead in Construction (CFR Part 1926.62) and EPA Renovate Right regulations and RCRA guidelines.

2.1 General

CBRE was retained by Metropolitan Commercial Bank ("Client" or "User") to prepare a Phase I Environmental Site Assessment, in conformance with ASTM International's Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process E 1527-13 on the Subject in accordance with our Agreement dated September 5, 2018.

2.2 Purpose and Scope

2.2.1 Purpose

The purpose of this report is to identify Recognized Environmental Conditions in connection with the property, using the methodology recommended by ASTM International in order for a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser defenses to CERCLA liability and/or to help understand potential environmental conditions that could materially impact the operation of the business associated with the Subject. Specifically, this methodology is referred to as *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* Designation: E 1527-13.

The term Recognized Environmental Conditions (RECs) is defined by ASTM Standard E 1527-13 as "...the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions."

The term Controlled Recognized Environmental Condition *(CREC)* as defined by ASTM Standard E 1527-13 refers to a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

The term Historical Recognized Environmental Condition *(HREC)* as defined by ASTM Standard E 1527-13 refers to a past release of any hazardous substances or petroleum products that has occurred in

connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls.

The term business environmental risk (BER) as defined by ASTM Standard E 1527-13 refers to a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated per the ASTM standard.

2.2.2 Scope

In general, the scope of this assessment consisted of reviewing readily available information and environmental data relating to the property; interviewing readily available persons knowledgeable about the site; reviewing readily available maps, aerial photographs and records maintained by federal, state, and local regulatory agencies; and conducting a site visit.

Of importance, the client is advised that federal, state, and local laws may impose environmental assessment obligations beyond the scope of this practice. Client is also notified that there are likely to be other legal obligations with regard to hazardous substances or petroleum products discovered on the Subject that are not addressed in this practice and that may pose risks of civil and/or criminal sanctions for non-compliance.

The specific scope of this assignment included the following:

2.2.2.1 Performing a site reconnaissance to characterize on-site conditions and assess the site's location with respect to surrounding property uses and natural surface features. In addition, CBRE conducted a reconnaissance of the surrounding roads and readily accessible adjacent properties to identify obvious potential environmental conditions on neighboring properties. Photographs taken as part of the site reconnaissance are provided in Appendix A.

The site visit was conducted on September 13, 2018, by Alex Singh representing CBRE. The site was represented by Mr.

Moshe Simpson, the property owner. It was overcast and the temperature was approximately 85° F at the time of our site survey. CBRE conducted the site reconnaissance in a systematic manner focusing initially on the exterior, which was surveyed in a grid pattern. CBRE also surveyed a representative sampling of the interior spaces in a systematic manner.

2.2.2.2 Interviewing persons familiar with the property to obtain information on present and previous on-site activities potentially resulting in the environmental degradation of the site or adjoining properties. A Pre-Survey Questionnaire to be filled out and returned to CBRE by someone knowledgeable about the site was provided to the Site Contact. A blank copy of the Pre-Survey Questionnaire is provided in Appendix B.

The following table presents a summary of the individuals contacted or to whom requests for documentation were made as part of this assessment:

Name	Affiliation	Telephone No.
Building Information System (BIS)	New York City Department of Buildings	(212) 312-8062
Ms. Brenda Farrow	New York City Department of Environmental Protection	(718) 595-3448
Mr. Fawzy Abelsadek	New York State Department of Environmental Conservation	(718) 482-4949
Ms. Rena Bryant	New York City Health Department	(212) 788-5013
Moshe Simpson	Property Owner	(718) 938-7810

2.2.2.3 If provided, reviewing of information such as previously prepared appraisals, building plans and specifications, and environmental reports.

2.2.2.4 Reviewing readily available historical documents, such as topographic maps, aerial photographs, city directories, Sanborn Fire Insurance Maps and atlases, to identify previous activities on and in the vicinity of the Subject. Copies of these documents are included in the Appendices.

2.2.2.5 Reviewing readily available environmental databases maintained by federal, state, and local agencies within the approximate minimum search distances as described within the Regulatory Review Section 6.0 of this report. A copy of the Computerized Environmental Report can be referenced in Appendix D.

2.2.2.6 Conducting a "Tier I" (non-intrusive) Vapor Encroachment Screening (VES) on the Subject in accordance with the methodology set forth in ASTM E 2600-15 "*Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*". During the VES, the Area of Concern (AOC) was minimized using the methodology taught in the ASTM Screening for Vapor Encroachment onto Property Involved in Real Estate Transactions Training Course.

2.2.2.7 Conducting a visual survey of readily accessible common areas to identify the presence of the most obvious and common types of suspect asbestos containing materials (ACM). The basis for "suspect" determination is taken from the materials listed in Appendix G of the United States Environmental Protection Agency (USEPA) publication Managing Asbestos in Place (also known as the Green Book). All building materials listed within Appendix G of the Green Book are considered to be suspect ACMs at the Subject. This screening is not intended to be used for demolition, abatement, renovation, or repair work.

THIS LIMITED SURVEY IS NOT TO BE CONSTRUED AS A COMPREHENSIVE ASBESTOS SURVEY, WHICH OFTEN ENTAILS DESTRUCTIVE TESTING OR THE SURVEY OF AREAS BEHIND WALLS, ABOVE CEILINGS, IN TENANT SPACES AND IN OTHER TYPICALLY INACCESSIBLE AREAS. MOREOVER, CBRE DOES NOT WARRANT THAT ALL ACMs AT THE SUBJECT HAVE BEEN IDENTIFIED.

2.2.2.8 Reviewing published radon occurrence maps to determine whether the site is located in an area with a propensity for elevated radon concentrations.

2.2.2.9 An analysis of mold and/or mold issues was beyond the scope of this report.

2.2.2.10 Assessing the age of the Subject to determine whether it is predisposed to contain lead-based paint. During our walkthrough survey, CBRE noted the condition of the paint observed. Note, a compliance audit for lead paint was not conducted. NOTWITHSTANDING, THIS SCAN FOR LEAD-BASED PAINT SHOULD NOT BE CONSTRUED AS AN IN-DEPTH LEAD-BASED PAINT SURVEY.

2.2.2.11 Testing, if any, was designed solely to meet the requirements of the client's scope of work, not to meet any local, State or Federal regulations and shall not be utilized as such.

2.3 Data Gaps

According to § 3.2.21 of ASTM Standard E 1527-13, a data gap is a lack of or inability to obtain information required by the ASTM Standard despite good faith efforts to gather same. Data gaps may result from incompleteness in any of the activities required by the ASTM Standard. The following data gaps occurred in connection with this report:

Data Gap	Explanation	Significance of Gap
Site History	History not conducted back to a time when the site was undeveloped land (See § 5)	Low - not likely to alter Report's conclusions due to CBRE's search of standard historical sources of information such historic topographic maps, city directory abstracts, Sanborn Fire Insurance Maps and interviews with knowledgeable individuals who were familiar with the property.
Site History	Site history not conducted in 5-year intervals (See § 5)	Low - not likely to alter Report's conclusions due to CBRE's search of standard historical sources of information.
Former Owner or Operator Interview	Unable to interview former site owner or operator due to inability to locate	Low - not likely to alter Report's conclusions
Governmental Records	FOIAs not returned (See § 8.6)	Unknown - However, if receipt of FOIAs alters the Report's conclusion, the client will be notified

Salient Assignment Information	
Project No.:	PC80947573-102
Project Name:	45 Van Sinderen Avenue
Street Address:	45 Van Sinderen Avenue
City, State and Zip:	Brooklyn, New York 11207
Primary Use:	Warehouse and Artist Studos
Year Built and Age of Improvements:	1921; 97 Years-Old
Site Area:	0.30 Acres
Building Size:	8,000 SFG
Number of Buildings:	One

4.1 Property Location

The Subject is located at 45 Van Sinderen Avenue in the Borough of Brooklyn Kings County, New York City, New York and is identified on local tax maps as Block 1576, Lot 1. More specifically, the Subject is located on the east side of Van Sinderen Avenue midway between Herkimer Street and Atlantic Avenue. Please refer to the Site Plan and maps provided within Appendix C.

4.2 Surrounding Land Use

The Subject is located in an urban setting characterized by light industrial and residential development. The following is a tabulation of surrounding property usage:

Direction	Adjacent Properties	Surrounding Properties
North	Along Van Sinderen Avenue is the Calvary Baptist Church (1520-1530 Herkimer Street and 25-35 Van Sinderen Avenue).	Parking and transportation/railroad properties farther north.
South	Along Atlantic Avenue is a commercial loft building (2465 Atlantic Avenue/65 Van Sinderen Avenue) and a hotel (2467-2473 Atlantic Avenue).	Long Island Railroad tracks and station farther south.
East	Along Williams Place is a New York City Transit consisting of parking and a raised railroad track system (24-64 Williams Place).	Light industrial development farther east.
West	Across Van Sinderen Avenue are two light industrial buildings (38-56 Van Sinderen Avenue) (26-36 Van Sinderen Avenue/1508-1518 Herkimer Street).	Light industrial and residential development farther west.

4.3 Physical Site Setting

4.3.1 Size and Shape of Parcel

The parcel is rectangular in shape and 0.30-acres in size.

4.3.2 Topography

The Subject is essentially level and at the same approximate topographic gradient as the surrounding properties. The topography of the area is best described as flat. According to the United States Geological Survey (USGS) *Brooklyn, N.Y.* 7.5 Minute Series topographic map, the Subject's topographic elevation is approximately 70' above mean sea level (msl).

4.3.3 Surface Waters and Wetlands

Surface Waters

There are no surface water bodies or streams on or adjacent to the Subject. The closest open surface water to the Subject is the Pond at Highland Park, which is located approximately 0.75 mile to the northeast.

Wetlands

CBRE reviewed a wetlands map of the Subject area prepared using the US Department of the Interior, Fish and Wildlife Service's Internet Wetland Interactive Mapper. The source material used to produce the National Wetlands Inventory digital data for these maps was prepared primarily by stereoscopic analysis of high altitude aerial photographs. Based on this review, CBRE did not identify any federally regulated wetlands on the Subject. Additionally, CBRE did not observe vegetation characteristic of wetlands on-site.

4.3.4 Soils, Geology and Groundwater

Soils

The soils at the Subject are classified as Urban Land. Urban Land complex are those soils in which the soil's original structure and content have been so altered by human activities it has lost its original characteristics and is thus unidentifiable.

Geology

According to a report titled "Potentiometric Surface of the Water Table, Magothy and Lloyd Aquifer on Long Island, New York in 1984, Water

Resources Investigation Report 86--4189 and published by USGS in 1987, the subsurface geology in the vicinity of the Subject consists of the Upper Glacial Deposits, Gardiners Clay, Jameco Gravel, the Raritan formation, and bedrock.

The unconsolidated Upper Glacial layer, deposited during the Pleistocene, extends to a depth of 175' below grade surface (bgs) and consists of glacial outwash deposits composed of sands and gravel. The permeability of this unit is moderate to high.

The Upper Glacial deposits are underlain by Gardiners Clay consisting of clay, silt, and a few layers of sand. Also deposited during Pleistocene, the Gardiners Clay extends to a depth of 200' below sea level (bsl). The permeability of this unit is very low, so it constitutes a confining unit for the underlying aquifer.

The Gardiners Clay is underlain by the Jameco Gravel unit consisting primarily of sand and gravel with a few layers of clay and silt. This unit extends to a depth of 250' bsl and is moderately to highly permeable.

The Jameco Gravel is underlain by the Raritan formation consisting of the Raritan Confining Unit and the Lloyd Sand Member, deposited during the Cretaceous Period. The Raritan Confining Unit extends to a depth of 300' bsl and is composed of clay (solid and silty), with a few lenses and layers of sand, lignite, and pyrite. The permeability of this unit is very poor. The Lloyd Sand Member extends to a depth of 400' bsl and is composed of sand and gravel within a clayey matrix. The permeability of this layer is poor to moderate.

Underlying the Raritan formation is bedrock. Paleozoic and Precambrian in age, the bedrock consists of metamorphic and metaigneous rocks (muscovite and biotic schist, gneiss and metagranites). The bedrock is poorly permeable to virtually impregnable, and constitutes the lower boundary of groundwater reservoir.

Groundwater

Under natural, undisturbed conditions, shallow groundwater flow generally follows the topography of the land surface and on this basis, the topography suggests that groundwater flow across the Subject is in a southerly to southeasterly direction. However, localized conditions

can alter flow direction and thus the presumed flow may not coincide with the actual in the Subject area.

4.4 Site Improvements

4.4.1 Utilities

The Subject is served with the following utilities:

Water:	New York City Department of Environmental Protection (NYCDEP)
Sanitary Sewer:	NYCDEP
Storm Sewer:	NYCDEP
Electric:	Consolidated Edison (Con Ed)
Natural Gas:	National Grid

Potable water is provided to the Subject via underground tunnels and pipes by the City of New York, which derives it from surface reservoirs in the Croton, Catskill, and Delaware watersheds.

Stormwater runoff collected by roof drains is discharged into the municipal stormwater management system.

4.4.2 Building Description

The Subject is improved with an approximately 97-year-old (built in 1921), two-story warehouse and loft building with an attached storage yard. The building has a cellar featuring stone rubble walls with a superstructure of wood frame and masonry construction. Exterior walls feature brick siding. The flat roof is covered with a smooth-surface built-up roofing system.

Interior finishes include floor coverings of carpet, resilient floor finishes, and bare concrete; walls of concrete block and ceilings typically consist of an open system that exposes the underside of the roof and glued-on ceiling tile.

Heating is provided by a gas-fired boiler. The Subject is without a central air conditioning system. The Subject is not provided with vertical transportation systems.

4.5 Current Property Use

The Subject is developed with a warehouse and loft building with an attached storage yard that is currently occupied by a furniture warehouse on the first floor, artist studios on the second floor and truck storage for an ironworks company in the attached yard. Based on the operations currently conducted at the Subject, significant quantities of hazardous waste are not generated. The current on-site activities are not suspected to have degraded the environmental quality of the Subject site.

4.6 Environmental Permits

Based on our research, no environmental permits such as wastewater discharge, National Pollutant Discharge Elimination System (NPDES), air emissions, or petroleum bulk storage (PBS) tank registrations are required at the Subject.

4.7 Plans and Specifications

Neither building drawings nor specifications were provided for our review.

5.1 Historical Summary

Prior to the construction of the existing improvements, the Subject property was improved with small buildings used for coal and wood storage associated with the Thatford and Ackerman Coal and Lumber Yard since at least 1888 and was likely vacant land prior to that. The current Subject building was constructed in 1920 and was used as a rolled gold manufacturing facility in 1932 and an instrument testing company from 1951 until the early 2000's.

5.2 Topographic Maps

CBRE reviewed historic USGS *Brooklyn, N.Y.* 7.5 Minute Series topographic maps of the Subject area provided by EDR dated 2013. The topographic map only depicts contours, roadways, waterbodies, and the locations of schools. Individual structures are not depicted.

5.3 Historical Maps

Sanborn Fire Insurance Maps (Sanborn Maps)

CBRE had a search conducted for Sanborn Maps, which reference the Subject. The findings of this review are summarized below:

Year	Subject Property	Adjacent and Surrounding Properties
1887	The Subject is either vacant land or not depicted on the Sanborn Map.	Adjacent and surrounding properties are either vacant land or not depicted on the Sanborn Map. The Long Island Railroad is located farther to the south.
1888	The Subject is improved with small storage buildings as part of the Thatford and Ackerman Coal and Lumber Yard with a rail line.	Adjacent properties to the north, south and east are improved with small buildings associated with the Thatford and Ackerman Coal and Lumber Yard. The west adjacent properties across Van Sinderen Avenue are improved with stores and vacant lots.
1908 1928	The Subject appears similar to the previous Sanborn Map reviewed.	The south adjacent properties are labeled as stores and offices and the east adjacent properties are improved with stables. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.

Year	Subject Property	Adjacent and Surrounding Properties
1932 1950	The Subject is improved with the current two-story building as well as a small storage shed and is labeled as Rolled Gold Manufacturing.	The north adjacent property appears to be vacant land. The east adjacent property is labeled as an iron works for tracks. There is an auto repair facility with a gas tank father to the northwest. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.
1951	The Subject appears similar to the previous Sanborn Map reviewed and is labeled as an instrument testing facility.	The north adjacent property is improved with a label weaving facility. The south adjacent properties are labeled as a manufacturer, stores and a machine shop. There is a parking lot to the adjacent west. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.
1963 1965 1966 1977	The Subject appears similar to the previous Sanborn Map reviewed.	The aforementioned parking lot to the adjacent west has been redeveloped into a warehouse building and is labeled as a steel cabinet manufacturer. The aforementioned auto repair facility to the northwest is labeled as a manufacturing building with no gas tanks displayed. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.
1978-1981	The Subject appears similar to the previous Sanborn Map reviewed.	The north adjacent property is labeled as a temple/church building. One of the south adjacent properties has been razed and the remaining south adjacent properties are labeled as a loft, a commercial building and a dwelling. An additional commercial building has been developed to the adjacent west. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.
1982 1983 1986	The Subject appears similar to the previous Sanborn Map reviewed.	The east adjacent building has been razed and the property contains overhead railroad tracks. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.

Year	Subject Property	Adjacent and Surrounding Properties
1987-1989 1991-1996 2001-2006	The Subject appears similar to the previous Sanborn Map reviewed.	Aside from the aforementioned loft building, the adjacent south buildings have been razed. The remainder of the surrounding area appears similar to the previous Sanborn Map reviewed.
2007	The Subject appears similar to the previous Sanborn Map reviewed.	A commercial building has been developed to the adjacent south.

Several adjacent and surrounding properties were identified on regulatory databases and are discussed further in Section 6.0 below. The former auto repair facility to the northwest is not listed on any database of concern.

5.4 Aerial Photographs

Aerial photographs frequently provide visual documentation of site conditions at the time of the photographs. Activities such as dumping or industrial use of a site can often be discerned through the examination of aerial photographs. Inasmuch as the Subject has been sufficiently covered by other standard historic information sources, aerial photographs were not consulted as part of this assessment.

5.5 Chain-of-Ownership

A copy of the Subject's Chain-of-Title has not been provided to CBRE for review.

5.6 Previous Reports

Although requested, no previously prepared environmental reports such as Phase I or II Environmental Site Assessments, lead-based paint surveys, lead-in-water surveys, asbestos surveys or geotechnical reports were provided for our review.

5.7 City Directories

CBRE commissioned EDR to obtain a historical City Directory Abstract for the Subject, which provide tenant listings by address for every year covered by the directory service. EDR's City Directory Abstract included a directory review for the following years: 1928, 1934, 1940, 1945, 1949, 1960, 1965, 1970,

1973, 1976, 1980, 1985, 1992, 1997, 2000, 2005, 2010, and 2014. This review yielded the following information:

Subject Property: The Subject is listed as Schumacher Bros Rolled Gold Leaf company in 1934, Terminex Insulation Co. Inc. in 1940 and Amthor Testing Instrument Co. from 1960 to 1973. These listings are not suspected of having a negative environmental impact on the Subject.

Surrounding Properties: Adjacent and surrounding properties were identified as light industrial and manufacturing listings such as electronics, cabinets, lamps and metal supply companies. Based on hydrogeologic positions, distances, and regulatory statuses of these sites, these listings are not suspected of having a negative environmental impact on the Subject.

5.8 Interviews

According to Moshe Simpson, the Property Owner, who has been involved with the property for the past eight months, the Subject was used as a warehouse and was then vacant for nearly 20 years prior to the current use as a furniture warehouse and artist studio. According to Mr. Simpson, the attached yard is used for truck storage for an ironworks company.

5.9 Municipal Records

Tax Assessor Records

According to the tax assessor records reviewed, the Subject building was constructed in 1920 on a 0.30-acre lot and is identified on New York City tax maps as Block 1576, Lot 1.

Building Department Records

CBRE reviewed building permits and records for the Subject at the New York City Department of Building (NYCDOB), Building Information System (BIS) database. The following relevant permits were reviewed:

Permit Number	Date	Purpose of Permit
NB 1473-021320	1920	Permit to construct a new building
FO 2378-110543	1943	Fuel oil burner application

Permit Number	Date	Purpose of Permit
FO 1353-45-080662	1962	Fuel oil burner application

According to the Building Department records reviewed, the Subject was constructed after 1920. In addition, the Subject may have utilized fuel oil in at least 1943 and 1962. The Subject is not listed as a registered Petroleum Bulk Storage (PBS) tank site with the NYSDEC, nor is it listed on any database indicative of an existing or former contamination condition. Furthermore, CBRE did not observe any evidence of former or current fuel oil tank on site. As such, any possible former fuel oil usage at the Subject is not of environmental concern.

5.10 Internet Search

CBRE conducted a cursory internet search for the Subject's name and address using the Google search engine on September 18, 2018. No environmentally related information was identified on the first page of the Google search results.

A copy of regulatory database information contained within a Computerized Environmental Report (CER) appears in Appendix D. The CER is a listing of sites identified on select federal and state standard source environmental databases within the approximate minimum search distance specified by ASTM Standard Practice for Environmental Site Assessments E 1527-13. CBRE reviewed each environmental database to determine if certain sites identified in the CER are suspected to represent a material negative environmental impact to the Subject. The following table lists the number of sites by regulatory database within the prescribed minimum search distance appearing in the CER.

Databases Reviewed	Approximate Minimum Search Distance (AMSD)	Number of Sites Within AMSD
Federal National Priorities List (NPL) Site List	One-Mile	0
Federal Delisted NPL Site List	One-Half Mile	0
Superfund Enterprise Management System (SEMS) (Formerly known as Federal Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS))	One-Half Mile	0
SEMS-ARCHIVE (Formerly known as Federal CERCLIS No Further Remedial Action Planned (NFRAP) Sites)	One-Half Mile	1
Federal Resource Conservation and Recovery Information System (RCRIS) Treatment, Storage, and Disposal (TSD) List	One-Half Mile	0
Federal RCRIS Generators List	On-Site and Adjoining Properties	2
Federal Corrective Action Tracking System (CORRACTS)	One-Mile	0
Federal Emergency Response Notification System (ERNS) List	On-Site	0
Federal Institutional/Engineering Control Registries	On-Site	0
New York and Tribal Lists of NPL Equivalent Hazardous Waste Sites Identified for Investigation and/or Remediation	One-Mile	1
New York and Tribal Lists of CERCLIS Equivalent Hazardous Waste Sites Identified for Investigation and/or Remediation	One-Half Mile	0
New York and Tribal Landfills or Solid Waste Facilities List	One-Half Mile	6
New York and Tribal Petroleum Bulk Storage Tank List	On-Site and Adjoining Properties	1

Databases Reviewed	Approximate Minimum Search Distance (AMSD)	Number of Sites Within AMSD
New York and Tribal Leaking UST/Spill List	One-Half Mile	41
New York and Tribal Institutional/Engineering Control Registries	On-Site	0
New York and Tribal Voluntary Cleanup Sites	One-Half Mile	2
New York and Tribal Brownfields Sites	One-Half Mile	0

The CER identified three "Orphan Sites". "Orphan Sites" are those sites that could not be mapped or "geocoded" due to inadequate address information. Please refer to the CER for a list of these "Orphan Sites". CBRE attempted to locate these sites via a review of street maps, vehicular reconnaissance and/or interviews with people familiar with the area. "Orphan Sites" that were identified in this manner were analyzed in their respective regulatory database below.

A description of the databases reviewed by CBRE and an analysis of sites identified within the prescribed search area are presented below.

6.1 Federal Databases

NPL

The NPL database is a listing of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or "Superfund"). A site must be on the NPL to receive money from the Trust Fund for Remedial Action.

Analysis/Comment: The CER did not identify NPL sites within the AMSD.

Delisted NPL Site List

The EPA may delete a final NPL site if it determines that no further response is required to protect human health or the environment, under Section 300.425(e) of the National Contingency Plan (55 FR 8845, March 8, 1990). Sites that have been deleted from the NPL remain eligible for further Superfund-financed remedial action in the unlikely event that conditions in the future warrant such action. Partial deletions can also be conducted at NPL sites.

Analysis/Comment: The CER did not identify Delisted NPL sites within the AMSD.

SEMS

SEMS is the USEPA's system for tracking hazardous waste sites, potential hazardous-waste sites and remedial activities performed in support of the Superfund Program. The system was formerly known as CERCLIS. A site's presence on SEMS does not imply a level of federal activity or progress at a site, nor does it indicate that hazardous conditions necessarily exist at the location. Within one year of being entered into SEMS, the USEPA performs a preliminary assessment of a site. Based upon the results of the preliminary assessment, the USEPA may conduct additional investigation, which could lead to a site being listed on the NPL.

Analysis/Comment: The CER did not identify SEMS sites within the AMSD.

SEMS-ARCHIVE

SEMS-ARCHIVE tracks sites that have no further interest under the Superfund Program. The list was formerly known as CERCLIS-NFRAP. Archived status sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to warrant Federal Superfund Action or NPL consideration.

Analysis/Comment: The CER identified the following SEMS-ARCHIVE site within the AMSD:

Property Name/ Address	Distance(Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Bklyn Union Gas/Belmont Works Belmont Ave & Alabama Ave	0.49	South Southeast	Downgradient	NFRAP

The above tabulated site has been granted a No Further Remedial Action Planned (NFRAP) status by the USEPA. NFRAP sites may be sites where, following an initial investigation, no contamination was found, or the contamination was either abated or the contamination was not significant enough to warrant Federal Superfund Action or NPL consideration.

Furthermore, this site is located a sufficient distance from the Subject so as not to be reasonably suspect of having impacted same. In addition, this site is located hydrogeologically downgradient from the Subject and groundwater flow across this site is suspected to be away from the Subject. As such, CBRE does not suspect this site of having had a significant negative environmental impact on the Subject.

RCRIS TSD

The RCRIS TSD contains information pertaining to those facilities that treat, store, or dispose of hazardous waste. While these facilities represent some form of hazardous waste activity, they are most significant if determined to be out of compliance or to have violations.

Analysis/Comment: The CER did not identify RCRIS TSD facilities within the AMSD.

RCRIS Generators

CBRE reviewed the list of sites, which have filed notification with the USEPA in accordance with RCRA requirements. These sites include generators of hazardous waste regulated under RCRA. Under RCRA, hazardous waste generators are classified by the quantity of hazardous waste generated in a calendar month into the following categories: Large Quantity Generator (LQG), greater than 1,000 kilograms (kg); Small Quantity Generator (SQG), 100 to 1,000 kg; and Conditionally-Exempt Small Quantity Generator (CESQG), less than 100 kg. RCRA Generators, while they represent some form of hazardous waste activity, are most significant if they are determined to have Class I Violations or to be non-compliant.

Analysis/Comment: The CER identified the following RCRA Generators located within the AMSD:

Property Name/ Address	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Con Edison Manhole: 5027 2473 Atlantic Ave	South Southeast	Downgradient	RCRA Non-Generator Compliant/No Violations

The above tabulated site is listed as a RCRA Non-Generator under EPA ID NYP004456299 for a typical Con Edison manhole with no reported violations. Con Edison manholes and service boxes are typically located in vaults within

the streets and sidewalks adjacent to the properties for which they are listed and any releases would most likely be contained within these vaults. In addition, this site is not listed on any database indicative of an existing contamination condition. Furthermore, this site is located at a crossgradient to downgradient position in relation to the Subject. Given the above information, CBRE does not suspect this listing of having had a negative environmental impact on the Subject.

Property Name/ Address	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
APEX Airtronics Inc 2465-69 Atlantic Ave	South Southwest	Crossgradient	RCRA Non-Generator Compliant/No Violations

The above tabulated site is listed as a RCRA Non-Generator under EPA ID NYD001284439 as of 2007 and was historically a SQG in 1999 and a LQG in 1980 for the production of spent non-halogenated solvents. This site was formerly a manufacturer of radio and telecom equipment. This site is located at a crossgradient hydrogeologic position in relation to the Subject and undocumented impacts to groundwater originating at this facility are not anticipated to have encroached upon the Subject.

Corrective Action Tracking System (CORRACTS)

CORRACTS is a list of facilities that are found to have had hazardous waste releases and require RCRA corrective action activity, which can range from site investigations to remediation.

Analysis/Comment: The CER did not identify CORRACTS sites within the AMSD.

ERNS

The ERNS is a database of notifications of oil discharges and hazardous substance releases made to the Federal government. These notifications are used by "On-Scene Coordinators" to determine an emergency response and release prevention. When a call is made to the National Response Center or one of the 10 USEPA Regions, a report is created containing all of the release information that the caller provided. This report is transferred to an appropriate agency to evaluate the need for a response and the records are electronically transferred to the ERNS database. As such, if a reported release of oil or a hazardous substance is deemed to require a response, it should also

be listed in the appropriate federal or state environmental database such as CERCLIS, state equivalent CERCLIS, or state leaking underground storage tank or spills lists.

Analysis/Comment: The CER did not identify the Subject on the ERNS database.

Federal Institutional Control/Engineering Control Registries

The Federal registries contain listings of those sites which have either engineering and/or institutional controls in place. Engineering controls include various physical control devices such as fences, caps, building slabs, paved areas, liners and treatment methods to eliminate pathways for regulated substances to enter the environment or affect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions (Activity and Use Limitations) are generally required as part of institutional controls.

Analysis/Comment: The CER did not identify the Subject on the Federal Institutional or Engineering Control registries.

6.2 New York State Department of Environmental Conservation (NYSDEC) and Tribal Databases

Registry of Inactive Hazardous Waste Disposal Sites (IHWDS) and Tribal NPL Equivalent State Hazardous Waste Sites (SHWS)

The IHWDS and Tribal NPL Equivalent SHWS list is an inventory of toxic sites listed by New York and/or Tribal Environmental and Health Authorities. These sites are either under remediation, or are currently under evaluation for further action, if necessary.

Analysis/Comment: The CER identified the following IHWDS and/or Tribal NPL Equivalent Hazardous Waste sites within the AMSD:

Property Name/ Address	Distance (Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
K – Union Station Holder	0.91	East	Crossgradient	SHWS

Property Name/ Address	Distance (Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Atlantic Ave, Ashford St, Liberty Ave				

The above tabulated site is located a sufficient distance from the Subject so as not to be reasonably suspect of having impacted same. In addition, this site is located hydrogeologically crossgradient from the Subject and groundwater flow across this site is suspected to be away from the Subject. As such, CBRE does not suspect this site of having had a significant negative environmental impact on the Subject.

Vapor Intrusion Legacy Site List

"Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, the NYSDEC is currently re-evaluating pre-2003 remedial decisions on IHWDS where chlorinated hydrocarbons were released to determine the possibility of vapor intrusion at the sites. The Vapor Intrusion Legacy Site List is a database of these sites.

Analysis/Comment: The CER did not identify Vapor Intrusion Legacy sites within a mile of the Subject.

New York and Tribal CERCLIS Equivalent Hazardous Waste Sites

The State HWS is an inventory of dumps, landfills, and other toxic sites listed by Environmental and Health Authorities. The Tribal NPL Equivalent HWS list is an inventory of toxic sites listed by Tribal Environmental and Health Authorities. These sites are either under remediation, or are currently under evaluation for further action, if necessary.

Analysis/Comment: The CER did not identify New York and/or Tribal CERCLIS Equivalent Hazardous Waste sites within the AMSD.

New York and/or Tribal Solid Waste Facilities (SWF) List

The SWF list is an inventory of landfills, incinerators, transfer stations, and other sites that manage solid wastes.

Analysis/Comment: The CER identified six SWF sites the AMSD. All but one of sites are located a sufficient distance from the Subject so as not to be reasonably suspect of having impacted same. In addition, these sites are located hydrogeologically crossgradient/downgradient from the Subject and groundwater flow across these sites is not suspected to be in the direction of the Subject. As such, CBRE does not suspect these sites of having had a significant negative environmental impact on the Subject. The adjacent SWF site is discussed below:

Property Name/ Address	Distance (Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Aries Autoworld LTD 2471 Atlantic Avenue	0.02	South Southeast	Crossgradient to Downgradient	Inactive

The above tabulated site is listed as a former vehicle dismantling facility. This site is located topographically crossgradient to downgradient from the Subject and groundwater across this site is inferred to flow to the southeast, which is away from the Subject. In addition, this site has reportedly been closed in accordance with governmental regulations and has been granted an inactive status. Furthermore, this site is not listed on any database indicative of a release or existing contamination condition. As such, it is unlikely that this solid waste facility has had a significant negative environmental impact upon the Subject.

Petroleum Bulk Storage (PBS) Tanks List and/or Tribal Registered Storage Tanks (RST) Facility List

The PBS Tank list is an inventory of registered liquid bulk storage tanks maintained either by the county or the NYSDEC. Inclusion of a site on the PBS Tank list does not necessarily constitute environmental contamination, but instead merely indicates the presence of registered bulk storage tanks.

Analysis/Comment: The CER identified the following PBS Tank site within the AMSD:

Property Name/ Address	Distance	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Apex Airtronics Inc. 2465 Atlantic Avenue	Adjacent	South Southeast	Crossgradient to Downgradient	Unregulated/ Closed

The above tabulated site is listed in the NY AST database under PBS No. 2-611061 for the presence of a 550-gallon No. 2 fuel oil AST that was reportedly installed in 1956 and has been converted to non-regulated use. This site is also listed in the NY Spills database and is discussed further in the Spills Section below.

New York Leaking Underground Storage Tanks (LUST) and Spill Lists

The LUST list is an inventory of spills and leaks, both active and inactive reported to regulatory authorities. They include stationary and non-stationary source spills reported to state and federal agencies, including remediated and contaminated leaking UST sites. The Spills list is a compilation of data collected on spills and reported to the NYSDEC pursuant to either Article 12 of the Navigation Law, or 6 NYCRR Section 595.2.

Analysis/Comment: The CER identified 41 LUST/Spill/LTANKS listings within the prescribed search radius. All of these listings have been i) granted a "Case Closed" status by the NYSDEC (this classification is granted to those sites that have been remediated to the satisfaction of the NYSDEC and are not suspected to pose a significant threat to human health or the environment), ii) are located at crossgradient or downgradient hydrogeologic directions with anticipated groundwater flow away from the Subject; iii) are *de minimis* in nature; and/or iv) located over one-eighth mile away from the Subject, and based on the general non-sensitivity of the urban setting of the Subject, are not considered to represent a significant environmental concern. As such, CBRE does not suspect that these sites have had a significant negative environmental impact upon the Subject. Any adjacent spill listings are discussed below:

Property Name/ Address	Distance (Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Factory 2465 Atlantic Avenue	Adjacent	South Southeast	Crossgradient to Downgradient	Closed 4/6/2009

The above tabulated site is listed in the NY Spills database under Spill No. 0708834 for an incident that occurred on November 13, 2007 when during a

fuel delivery, oil was observed coming through the wall around the fill line. Approximately one-gallon of No. 2 fuel oil was reported to have been released. The spill was contained and cleaned up and the fill line was exposed and repaired. No evidence of contamination was found in the soils. The NYSDEC granted this incident a case closed status on April 6, 2009. Given the de minimis nature and closed status of this incident as well as the crossgradient to downgradient hydrogeologic position of this site in relation to the Subject, CBRE does not suspect this incident of having had a negative environmental impact on the Subject.

Property Name/ Address	Distance (Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
Spill No. 0206144 38 Van Sinderen Ave	Adjacent	West Northwest	Upgradient	Closed 10/8/2002

The above tabulated site is listed in the NY LTANKS database under Spill No. 0206144 for an incident that occurred on September 13, 2002 when soil contamination was discovered after the removal of a 550-gallon diesel fuel oil UST and one 550-gallon kerosene UST. The contaminated soils were removed and soil disposal manifests were documented. Endpoint sampling did not identify contamination above TAGM 4060 Required Soil Cleanup Objectives. The NYSDEC granted this incident a case closed status on October 8, 2002. Given the closed status of this incident, CBRE does not suspect this incident of having had a negative environmental impact on the Subject.

New York and Tribal Institutional Control/Engineering Control Registries

According to the NYSDEC website, Institutional Controls shall mean any non-physical means of enforcing a restriction on the use of real property that limits human or environmental exposure, restricts the use of groundwater, provides notice to potential owners, operators, or members of the public, or prevents actions that would interfere with the effectiveness of a remedial program or with the effectiveness and/or integrity of operation, maintenance, or monitoring activities at or pertaining to a brownfield site.

Engineering Control shall mean any physical barrier or method employed to actively or passively contain, stabilize, or monitor hazardous waste or petroleum, restrict the movement of hazardous waste or petroleum to ensure the long-term effectiveness of a remedial program, or eliminate potential exposure pathways to hazardous waste or petroleum. Engineering controls include, but are not limited to, pavement, caps, covers, subsurface barriers, vapor barriers, slurry walls, building ventilation systems, fences, access

controls, provision of alternative water supplies via connection to an existing public water supply, adding treatment technologies to such water supplies, and installing filtration devices on private water supplies.

- If an IC/EC is used as a component of a site cleanup plan, the Remedial Work Plan must include: a complete description of the IC/ECs and the mechanisms that will be used to implement, maintain, monitor, and enforce such restrictions and controls, both by the applicant and by any state and local government, and an evaluation of the reliability, viability, and costs of the long-term implementation, maintenance, monitoring, and enforcement of any IC/EC.
- Financial assurance for the long-term maintenance, monitoring, and enforcement of IC/ECs may be required.
- Any EC must be used in conjunction with an IC.
- The final remediation report must include a certification that any IC/ECs are included in an environmental easement that has been duly recorded.
- An annual certification that the IC/ECs are in place and protective of public health and the environment must be submitted to the NYSDEC.
- The NYSDEC must create, update, and maintain a data base available to the public of sites using IC/ECs.
- Any proposal for a change in site use must include an evaluation of the impacts of the change on the viability, reliability, and effectiveness of any IC/ECs.

Analysis/Comment: The CER did not identify the Subject on the New York and Tribal Institutional or Engineering Control registries.

New York and Tribal Voluntary Cleanup Program Sites

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. New York's Voluntary Cleanup Program is a cooperative approach among the NYSDEC, lenders, developers and prospective purchasers to investigate and/or remediate contaminated sites. Under the VCP, a volunteer performs remedial activities pursuant to one or more NYSDEC approved work plans. The volunteer agrees to remediate the site to a level which is protective of public health and the environment for the present or intended use of the property. Investigation and remediation is carried out under the oversight of the NYSDEC and the New York State Department of Health (DOH) and the volunteer pays the State's oversight costs. When the volunteer completes work, a release from liability from the NYSDEC is provided with standard reservations. Once the required remedial actions

have been completed, the NYSDEC issues a letter declaring that it agrees that the volunteer has met their obligations and that, barring an event triggering a reopener, the Department does not contemplate further action will need to be taken at the site. Non-PRP volunteers also receive a release that covers natural resource damages. All of the volunteer's successors and assigns (except the site's PRPs) benefit from the release given to the volunteer. The NYSDEC's release binds only itself, and does not bind private parties harmed, does not bind the State's Attorney General, the State's Comptroller, and does not bind the USEPA.

The Release is subject to the following reservations for further investigation or remediation the NYSDEC deems necessary due to:

- Off-site migration of contamination causing significant impacts if the Volunteer is a PRP;
- Environmental conditions or information related to the Site that were unknown when the Release was issued and that indicate that site conditions under the Contemplated Use are not sufficiently protective of human health and the environment;
- Failure to comply with the VCA (e.g., not completing OM&M, not paying State costs, not maintaining use restrictions, etc.);
- Fraud committed by the Volunteer in entering into or implementing the VCA;
- A release, discharge or threat thereof after the effective date of the VCA; or
- A change of use where the new use requires a lower level of residual contamination.

Analysis/Comment: The CER identified the following VCP site within the AMSD.

Property Name/ Address	Distance (Mile)	Direction	Presumed Hydrogeologic Relationship	Regulatory Status
91 Junius Street	0.25	South	Crossgradient	Active
201-205 Mother Gaston Boulevard/2396 Dean Street	0.29	West Southwest	Crossgradient	Active

The above tabulated sites are located a sufficient distance from the Subject so as not to be reasonably suspect of having impacted same. In addition, these sites are located hydrogeologically crossgradient from the Subject and groundwater flow across these sites is not suspected to be in the direction of

the Subject. As such, CBRE does not suspect these sites of having had a significant negative environmental impact on the Subject.

New York and Tribal Brownfield Sites

According to the NYSDEC website, brownfields are abandoned, idled, or under-used properties where expansion or redevelopment is complicated by real or perceived environmental contamination. They typically are former industrial or commercial properties where operations may have resulted in environmental contamination. Brownfields often pose not only environmental, but legal and financial burdens on communities. The impediments to contaminated site redevelopment in New York are complex. The existing liability scheme may hold all owners of contaminated property liable for cleanup costs, regardless of when or how the property was acquired. The potential cost of cleanup, which may not be known for certain at the time of purchase, is also a deterrent to parties wishing to build, relocate, or expand businesses. Lenders have been reluctant to extend credit for the purchase and cleanup of contaminated sites, fearing future liability issues.

A Brownfield Cleanup Agreement (BCA) is required for all parties who wish to participate in the Brownfield Cleanup Program. By executing a BCA, an Applicant makes a commitment to undertake certain remedial activities under the NYSDEC's oversight.

Analysis/Comment: The CER did not identify Brownfield sites within a one-half mile radius of the Subject.

New York City Building Information System

The City Environmental Quality Review (CEQR) designation "E" on New York City Zoning Maps indicates that environmental requirements pertaining to potential hazardous material contamination or noise or air quality impacts have been established on one or more tax lots. These "E" designations function as indicators of the environmental review that must be conducted when the lots are developed in accordance with the regulations of the rezoned district.

New York City Zoning Resolution § 11-15 provides that the New York City Department of Buildings (NYCDOB) may not issue a building permit for work on a tax lot labeled with an "E" due to potential hazardous material contamination, if the building permit would allow: (1) a development; (2) an enlargement, extension or change of use involving a residential or community

facility use; or (3) an enlargement that disturbs the soil. The NYCDOB identifies haz-mat "E" lots on its Building Information System ("BIS").

An "E" designation for potential hazardous material contamination may be satisfied and removed from a zoning map following receipt of a report from the NYC Office of Environmental Remediation (OER) stating that the environmental requirements for the lot have been met. These requirements may include subsurface investigations and/or remediation of contamination to the satisfaction of the OER.

Analysis/Comments: Based on our review of the NYCDOB BIS and New York City Zoning Maps, an "E" designation has not been declared on the Subject.

6.3 EDR Proprietary Databases

EDR Manufactured Gas Plants

This database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to the 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of wastes. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Analysis/Comment: The CER did not identify the Subject or any adjacent properties on the manufactured gas plant database.

EDR Historic Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

Analysis/Comment: The CER did not identify the Subject or any adjacent properties on the historical auto stations database.

EDR Historic Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc.

Analysis/Comment: The CER did not identify the Subject or any adjacent properties on the historical cleaners database.

7.1 Chemical Storage and Usage

With the exception of chemicals customarily used for routine building maintenance and cleaning, CBRE did not observe any hazardous chemicals stored on-site. For the most part, the maintenance chemicals are stored in the maintenance closet and cellar. Of note, floor drains were not observed in the vicinity of the chemical storage areas. In addition, housekeeping was generally considered satisfactory. The chemicals, which are stored in their original containers, do not appear to represent an impact to the environmental quality of the Subject provided that they are used as intended, properly handled, and the regulations pertaining to their usage are followed.

7.2 Bulk Storage Tanks

Underground Storage Tanks (USTs)

No active USTs were identified on the Subject property and no common indicators of USTs such as vent pipes, fill ports, manways, pavement cuts, fuel gauges or dispensers were observed. In addition, the Subject was not identified on the New York list of registered UST facilities. No underground storage tanks were reportedly removed, closed-in-place or abandoned at the Subject and no common indicators of closed tanks were observed.

Aboveground Storage Tanks (ASTs)

No ASTs were observed and CBRE did not identify any equipment, which should require such tanks. Moreover, visual indicators of former site ASTs, such as tank cradles, secondary containment structures, tank pedestals, etc., were not observed. In addition, according to the site contact, there are no ASTs on-site.

7.3 Site Waste and Wastewater

Solid Waste

Non-hazardous solid waste is disposed of in dumpsters and is removed from the Subject on a regular basis by the municipality. Potential sources of contamination, such as waste oil or automobile batteries, were not observed in the vicinity of the dumpsters.

Sanitary Sewage

Sanitary sewage disposal is provided by the NYCDEP. CBRE did not observe any sources of wastewater or liquid discharge into the sewer other than sanitary sewage.

Hazardous Waste

No hazardous waste was observed or reported to be generated on the Subject. Furthermore, CBRE's review of the USEPA's database of sites regulated under RCRA did not identify the Subject as a generator of hazardous waste.

7.4 Stained Soil, Stained Pavement, or Stressed Vegetation

There was no evidence of significant soil staining, stained pavement, or stressed vegetation observed on-site.

7.5 Liquid Discharges

No visible evidence of liquid discharges, suspected to represent an environmental concern were observed during our survey.

7.6 Pools of Liquid

CBRE did not observe significant standing surface water or pools containing liquids likely to be hazardous substances or petroleum products.

7.7 Pits, Ponds, or Lagoons

No pits, ponds or lagoons suspected of containing hazardous substances or petroleum products were identified on-site.

7.8 Wells

CBRE did not identify on-site dry wells, irrigation wells, injection wells, observation wells, monitoring wells, potable water wells, recovery wells or abandoned wells.

7.9 On-Site Fill

Based on our observations, other than typical engineered fill used in foundation construction, it does not appear that a significant amount of fill has been imported onto the Subject.

7.10 Drums and Containers for Storing Waste

With the exception of non-hazardous solid waste containers, CBRE did not identify containers suspected of storing waste. With respect to the non-hazardous solid waste containers, no significant environmental concerns were noted.

7.11 Floor Drains and Sumps

CBRE did not identify any floor drains or sumps that were stained, emitting foul odors, connected to an on-site sewage disposal system or located adjacent to chemical storage areas.

7.12 Odors

CBRE did not identify strong, pungent, or noxious odors suspected to represent an environmental concern.

7.13 Air Emissions

CBRE did not identify processes or equipment that emit noticeable vapors or fumes.

7.14 Polychlorinated Biphenyls (PCBs)

Transformers

No primary power electrical transformers were identified on-site.

Hydraulic Lifts

No hydraulic lifts were observed on-site.

Elevators

No hydraulic elevators were observed on-site.

Compactors and Bailers

No hydraulic compactors or bailers were observed on-site.

7.15 Asbestos-Containing Material (ACM)

Based on the age of the site improvements, the potential use of ACMs exists. No friable suspect ACM was identified in readily accessible areas. However, the non-friable resilient floor finish assemblies, plasters, built-up roofing system, caulking, and mastics may contain asbestos. Note, additional suspect ACMs may exist in inaccessible locations such as behind walls, above ceilings, and beneath visible flooring. These non-friable materials are in good condition and the potential for fiber release is low.

7.16 Lead-in-Drinking Water

Based on our conversations with utility personnel, the water at the Subject is not expected to contain elevated levels of lead.

7.17 Radon

Based on statistical information maintained within the New York State Department of Health (NYS DOH)'s Short Term Basement Radon Measurements by Town, dated January 2017, radon concentrations in Kings County average 1.94 picocuries per liter (pCi/L), which is below the 4.0 pCi/L action level established by the USEPA and places the Subject in an EPA radon Zone 3. Based solely on this data, it is unlikely that radon represents an environmental concern to the Subject.

7.18 Lead-Based Paint (LBP)

Since the Subject was constructed prior to the Consumer Product Safety Commission's 1978 ban on the sale of LBP to consumers and the use of LBP in residences, there is a potential that LBP may have been applied at the Subject. Testing would be required in order to determine whether LBP exists. Painted surfaces observed were in good condition with no excessive peeling or flaking.

8.1 Questionnaires

CBRE sent a Pre-Survey Questionnaire and an AAI User Questionnaire to the site contact and the User, respectively. The purpose of these questionnaires was to disclose any previous or existing hazardous waste or toxic material conditions, which may not have been apparent at the time of our site reconnaissance and to satisfy the User interview all appropriate inquiry requirements.

The completed AAI questionnaire is attached hereto as Appendix B. However, the site contact has not returned a completed Pre-Survey Questionnaire.

8.2 User

8.2.1 Title Records

A copy of the Subject's Chain-of-Title has not been provided to CBRE for review.

8.2.2 Environmental Clean Up Liens and Activity and Use Limitations (AULs)

The User had no knowledge of any environmental liens against the Subject that have been filed or recorded under federal, tribal, state or local law. Moreover, the User was not aware of any AULs, such as engineering controls, land use restrictions, or institutional controls that are in-place at the Subject or have been filed or recorded under federal, tribal, state or local law.

8.2.3 Specialized Knowledge

The User had no specialized knowledge of recognized or potential recognized environmental conditions in connection with the Subject.

8.2.4 Relationship of Purchase Price to Fair Market Value Due to Contamination in Connection with the Subject

The User has indicated they are unaware of any environmental conditions in connection with the Subject that have resulted in the diminution of its purchase price in relation to its Fair Market Value.

8.2.5 Common Knowledge or Reasonably Ascertainable Information

The User had no common knowledge of recognized or potential recognized environmental conditions in connection with the Subject.

8.2.6 Purpose for Conducting the Phase I Environmental Site Assessment

The purpose of conducting this Phase I Environmental Site Assessment was for underwriting purposes.

8.2.7 Proceedings Involving the Property

The User had no knowledge of pending, threatened, or past litigation, administrative proceedings, or notices from governmental agencies regarding violations of environmental laws regarding hazardous substances or petroleum products.

8.3 Key Site Manager

8.3.1 Historic Site Use

According to Moshe Simpson, the Property Owner, who has been involved with the property for the past eight months, the Subject was used as a warehouse and was then vacant for nearly 20 years prior to the current use as a furniture warehouse and artist studio. According to Mr. Simpson, the attached yard is used for truck storage for an ironworks company.

8.3.2 Proceedings Involving the Property

Mr. Simpson had no knowledge of pending, threatened, or past litigation, administrative proceedings, or notices from governmental agencies regarding violations of environmental laws regarding hazardous substances or petroleum products involving the Subject.

8.4 Occupants

Subject occupants were not available for interviews.

8.5 Past Owners

CBRE was unable to locate the Subject's former owner.

8.6 Local Regulatory Agency Interviews and/or File Reviews

Tax Assessor Records

According to the tax assessor records reviewed, the Subject building was constructed in 1920 on a 0.30-acre lot and is identified on New York City tax maps as Block 1576, Lot 1.

Building Department Records

CBRE reviewed building permits and records for the Subject at the New York City Department of Building (NYCDOB), Building Information System (BIS) database. The following relevant permits were reviewed:

Permit Number	Date	Purpose of Permit
NB 1473-021320	1920	Permit to construct a new building
FO 2378-110543	1943	Fuel oil burner application
FO 1353-45-080662	1962	Fuel oil burner application

According to the Building Department records reviewed, the Subject was constructed after 1920. In addition, the Subject may have utilized fuel oil in at least 1943 and 1962. The Subject is not listed as a registered Petroleum Bulk Storage (PBS) tank site with the NYSDEC, nor is it listed on any database indicative of an existing or former contamination condition. Furthermore, CBRE did not observe any evidence of former or current fuel oil tank on site. As such, any possible former fuel oil usage at the Subject is not of environmental concern.

Health Department

CBRE has sent a request to the New York City Health Department for environmental information pertaining to the Subject property. As of this writing,

the Health Department has not responded to our request. Should receipt of a response from the Health Department change the conclusions of this report, the Client will be notified in writing by CBRE.

New York State Department of Environmental Conservation (NYSDEC)

CBRE has sent a request to the New York State Department of Environmental Conservation (NYSDEC) for environmental information pertaining to the Subject property. As of this writing, the NYSDEC has not responded to our request. Should receipt of a response from the NYSDEC change the conclusions of this report, the Client will be notified in writing by CBRE.

New York City Department of Environmental Protection (NYCDEP)

CBRE has sent a request to the New York City Department of Environmental Protection (NYCDEP) for environmental information pertaining to the Subject property. As of this writing, the NYCDEP has not responded to our request. Should receipt of a response from the NYCDEP change the conclusions of this report, the Client will be notified in writing by CBRE.

Fire Department

CBRE did not send a request to the Fire Department of the City of New York (FDNY) as based on our experience with this agency, the information is not reasonably ascertainable, as the response time exceeds 20 calendar days and typically extends 4-6 weeks from acknowledgement of receipt of the request. However, potential tank information was requested from additional regulatory authorities (NYSDEC) under a separate FOIA and were viewed on-line via the NYSDEC database website as well as the NYC Office of Environmental Remediation (OER) Searchable Property Environmental E-Database (SPEED). Additionally, CBRE reviewed historical Sanborn maps for evidence of petroleum or chemical storage tanks on-site.

CBRE conducted a "Tier I" (non-intrusive) Vapor Encroachment Screening (VES) on the Subject in accordance with the methodology set forth in ASTM E 2600-15 "*Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*". During the VES, the Area of Concern (AOC) was minimized using the methodology taught in the ASTM Screening for Vapor Encroachment onto Property Involved in Real Estate Transactions Training Course. The purpose of the Tier I VES is to conduct an initial screen to identify, to the extent feasible, the potential for a vapor encroachment condition (VEC) in connection with the Subject with respect to chemicals of concern that may migrate as vapors into the vadose zone of the Subject as a result of contaminated soil and/or groundwater on or near the Subject.

This VES utilized readily available data sources previously discussed in this Phase I ESA to include the type of soils, geology and groundwater characteristics of the Subject area (refer to Section 4.3) as well as known or potentially contaminated sites as identified on Federal, State, tribal and local databases. CBRE also utilized previously discussed standard historical sources of information to identify potential historical sources of contamination on the Subject and surrounding properties which may be indicative of a VEC. This data collection and analysis was coupled with our site reconnaissance of the Subject and surrounding properties. Based upon the results of our data collection, reconnaissance and analysis, a summary of our Tier I VES findings is presented in the table below:

Potential for Vapor Encroachment to Impact the Subject	
Area of Concern	Conclusion
Subject Operations or Existing Conditions	None identified (Refer to Sections 4.0 Site Description and 7.0 Site Reconnaissance)
Historical Uses of the Subject Property	None identified (Refer to Section 5.0 Historical Use)
Adjoining Property Operations or Existing Conditions	None identified (Refer to Section 4.2 Surrounding Land Use)
Historical Uses of Adjoining Properties or Nearby Properties	None identified (Refer to Section 5.0 Historical Use)
Regulatory Review of sites identified on Federal, State, tribal and Local Environmental Databases which were located in Approximate Minimum Search Distance (AMSD)	Several Identified (Detailed within Section 6.0 Regulatory Review), but none of concern.

Several impacted properties were identified in CBRE's regulatory database review. However, based upon hydrogeology, groundwater flow direction and the furthest known extents of the contamination, none of these properties are suspected of having petroleum or chemical contaminant plumes that would be identified as a VEC and as such, a VEC from these properties can be ruled out.

CBRE has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Standard Practice E1527-13 of the property at 45 Van Sinderen Avenue, New York, New York. Any exceptions to, or deletions from, the standard practice are described within Section 2.0 of this report.

This assessment has revealed no evidence of recognized environmental conditions (RECs) in connection with the Subject.

CBRE did not identify CRECs in connection with the Subject.

CBRE did not identify HRECs in connection with the Subject.

No significant data gaps were identified that would affect the ability of the environmental professional to identify RECs at the Subject.

The investigation has revealed no BERs associated with the standard ASTM scope considerations.

This investigation has revealed no business environmental risks relating to these ASTM Non-Scope Considerations in connection with the Subject except for the following:

- Based on the age of the site improvements, the potential use of ACMs exists. No friable suspect ACM was identified in readily accessible areas. However, the non-friable resilient floor finish assemblies, plasters, built-up roofing system, caulking, and mastics may contain asbestos. Note, additional suspect ACMs may exist in inaccessible locations such as behind walls, above ceilings, and beneath visible flooring. Since these non-friable materials are in good condition and the potential for fiber release is low, no further action is recommended at this time, other than maintaining the materials in good condition under an Asbestos Operations and Maintenance (O&M) Program. However, in the event that building maintenance, renovation, or demolition activities require the removal or disturbance of the suspect ACM, CBRE recommends that they be characterized for asbestos by a material specific reliable method for detecting asbestos. All activities involving ACM should be conducted in accordance with governmental regulations.

- Since the Subject was constructed prior to the Consumer Product Safety Commission's 1978 ban on the sale of LBP to consumers and the use of LBP in residences, there is a potential that LBP may have been applied at the Subject. Testing would be required in order to determine whether LBP exists. Painted surfaces observed were in good condition with no excessive peeling or flaking. No further action is recommended at this time. However, all activities involving LBP

should be conducted in accordance with HUD guidelines, the USEPA's Lead-Based Paint Renovation, Repair and Painting Program Rule as well as the OSHA Lead in Construction (CFR Part 1926.62) and EPA Renovate Right regulations and RCRA guidelines.

11.1 This report has been prepared in compliance with the ASTM standard entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" E1527-13.

11.2 The observations described in this report were made under the conditions stated herein. The conclusions presented in the report were based solely upon the services described therein, and not on scientific tasks or procedures beyond the scope of described services within the constraints imposed by the client. The work described in this report was carried out in accordance with the Terms and Conditions of the contract.

11.3 In preparing this report, CBRE has relied on certain information provided by federal, state, and local officials and other parties referenced therein, and on information contained in the files of governmental agencies, that were readily available to CBRE at the time of this assessment. Although there may have been some degree of overlap in the information provided by these various sources, CBRE did not attempt to independently verify the accuracy or completeness of all information reviewed or received during the course of this site assessment. Observations were made of the site and of the structures on the site as indicated in this report. Where access to portions of the site or to structures on the site was unavailable or limited, CBRE renders no opinion as to the presence of direct or indirect evidence relating to petroleum substances, hazardous substances, or both, in that portion of the site and structure. In addition, CBRE renders no opinion as to the presence of indirect evidence relating to hazardous material or oil, where direct observation of the ground surface, interior walls, floors, ceiling or a structure is obstructed by objects or materials, including snow, covering on or over these surfaces.

11.4 As part of this assessment, CBRE submitted requests for information via the Freedom of Information Act (FOIA) to various governmental agencies. As of the preparation of this report these requests may not have been fulfilled. The conclusions of this report are subject to change upon receipt of a response from these FOIA requests.

11.5 CBRE does not represent that the site referred to herein contains no petroleum or hazardous or toxic substances or other conditions beyond those observed by CBRE during the site walkthrough.

11.6 CBRE has produced this document under an agreement between CBRE and Metropolitan Commercial Bank. All terms and conditions of that agreement are included within this document by reference. Any reliance upon this document, or upon CBRE's performance of services in preparing this document, is conditioned upon the relying party's acceptance and acknowledgement of the limitations, qualifications, terms, conditions and indemnities set forth in that agreement, and property ownership/management disclosure limitations, if any. It is not to be relied upon by any party other than Metropolitan Commercial Bank nor used for any purpose other than that specifically stated in our Agreement or within this Report's Introduction section without CBRE's advance and express written consent. The Phase I report is only valid if completed within 180 days of an acquisition or the transaction necessitating the report.

11.7 TIME LIMITATION TO ENACT CLAIM AGAINST CBRE If in the opinion of the client, or any third party claiming reliance on CBRE's report or services, that CBRE was negligent or in breach of contract, such aforementioned parties shall have two years from the date of CBRE's site visit to make a claim.

11.8 Unless specifically identified within Section 2, Chinese drywall, indoor air quality and any other non-ASTM scope issues as identified in ASTM E1527-13, Section 13.1.5, are excluded from the scope of this assessment.

BROADWAY JUNCTION
45 VAN SINDEREN AVENUE & 2465 ATLANTIC AVENUE
BROOKLYN, NEW YORK 11207
TAX MAP ID: BLOCK 1576, LOTS 1 & 34

PHASE II
ENVIRONMENTAL SITE ASSESSMENT
(ASTM 1903-19)

PREPARED FOR:

Broadway Junction Partners, LLC
26 Harbor Park Drive
Port Washington, New York 11050

PREPARED BY:

P.W. Grosser Consulting, Inc.
630 Johnson Avenue, Suite 7
Bohemia, New York 11716
Phone: 631-589-6353
Fax: 631-589-8705

Jennifer Lewis, PG, Vice President — JenniferL@pwgrosser.com
Michael Pecoraro, Project Manager — mpecoraro@pwgrosser.com

PWGC Project Number: TOT2401

MAY 29, 2024

TABLE OF CONTENTS PAGE

1.0 INTRODUCTION 1
2.0 BACKGROUND 2
2.1 Site Description and Features 2
2.2 Physical Setting 2
2.3 Site History and Land Use 3
2.4 Adjacent Property Land Use 3
2.5 Summary of Previous Assessments 3
2.5.1 Phase I Environmental Site Assessment Report (September 2018)- 2465 Atlantic Avenue 3
2.5.2 Phase I Environmental Site Assessment Report (September 2018) – 45 Van Sinderen Avenue 4
2.5.3 Phase II Environmental Site Assessment Report (November 2018) – 2465 Atlantic Avenue 4
3.0 INVESTIGATION METHODOLOGY 5
3.1 Geophysical Survey 5
3.1.1 Electromagnetic Survey 5
3.1.2 Ground Penetrating Radar Survey 5
3.2 Soil Quality Evaluation 6
3.2.1 Soil Boring Protocol 6
3.2.2 Soil Sample Collection Protocol 6
3.3 Groundwater Quality Evaluation 6
3.4 Soil Vapor Intrusion Investigation 7
3.4.1 Soil Vapor Point Installation Protocol 7
3.4.2 Soil Vapor and Air Sample Collection Protocol 8
4.0 INVESTIGATION FINDINGS 9
4.1 Geophysical Survey 9
4.2 Soil Quality Evaluation 9
4.2.1 Soil Boring Protocol 9
4.2.2 Soil Sample Collection Protocol 9
4.2.3 Soil Vapor Intrusion Investigation 10
4.3 Site Environmental Evaluation 11
5.0 CONCLUSIONS AND RECOMMENDATIONS 13
5.1 Conclusions 13
5.2 Recommendations 14
6.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL 15
7.0 REFERENCES 16
8.0 LIMITATIONS 17

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

FIGURES

FIGURE 1	Site Location Map
FIGURE 2	Site Plan
FIGURE 3	Soil Analytical Results
FIGURE 4	Soil Vapor Analytical Results

TABLES

TABLE 1	Soil Sample Analytical Results –VOCs
TABLE 2	Soil Sample Analytical Results –SVOCs
TABLE 3	Soil Sample Analytical Results –Metals
TABLE 4	Soil Vapor Sample Analytical Results – VOCs
TABLE 5	Soil Vapor Matrices Summary – VOCs

APPENDICES

APPENDIX A	Geophysical Survey Report
APPENDIX B	Soil Boring Logs
APPENDIX C	Laboratory Analytical Reports

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

ACRONYM	DEFINITION
AGS	Advanced Geological Services
ASP	Analytical Services Protocol
ASTM	American Society for Testing and Materials
CFR	Code of Federal Regulations
CU	Commercial Use
DER	Department of Environmental Remediation
ELAP	Environmental Laboratory Approval Program
EM	Electromagnetic
ESA	Environmental Site Assessment
GPR	Ground Penetrating Radar
GQS	Groundwater Quality Standard
GV	Guidance Value
NYCRR	New York Codes, Rules, and Regulations
NYSDEC	New York State Department of Environmental Conservation
NYSDOH	New York State Department of Health
PAH	Polyaromatic Hydrocarbon
PID	Photo-ionization Detector
ppm	Parts per million
PWGC	P.W. Grosser Consulting, Inc.
QA/QC	Quality Assurance / Quality Control
REC	Recognized Environmental Condition
RRU	Restricted Residential Use
SCO	Soil Cleanup Objective
SVOC	Semi-volatile Organic Compound
USCS	Unified Soil Classification System
USEPA	United States Environmental Protection Agency
UST	Underground Storage Tank
UU	Unrestricted Use
VOC	Volatile Organic Compound

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

1.0 INTRODUCTION

Broadway Junction Partners, LLC (Client) retained P.W. Grosser Consulting, Inc. (PWGC) to prepare a Phase II Environmental Site Assessment (ESA) for the properties located at 45 Van Sinderen Avenue and 2465 Atlantic Avenue, Brooklyn, New York. The purpose of the Phase II ESA was to further evaluate recognized environmental conditions (RECs) identified in September 2018 Phase I ESAs prepared by CBRE, Inc. and to obtain sound, scientifically valid data concerning actual property conditions.

Work was conducted in accordance with the American Society for Testing and Materials (ASTM) Standard E 1903-19 (Standard Practices for Environmental Site Assessment: Phase II Environmental Site Assessment Process) and in substantial conformance with the New York State Department of Environmental Conservation's (NYSDEC's) Division of Environmental Remediation's (DER's) Technical Guidance for Site Investigation and Remediation, May 2010 (DER-10).

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

2.0 BACKGROUND

2.1 Site Description and Features

The subject property consists of two parcels located at 45 Van Sinderen Avenue and 2465 Atlantic Avenue in Brooklyn, NY. The subject property is located in the borough of Brooklyn and Kings County. The property is identified in the NYC Tax Map as Block 1576, Lots 1 and 34. The subject property measures approximately 0.36 acres and is improved with:

- 45 Van Sinderen Ave: The property is improved with an approximately 103-year-old (built in 1921), two-story warehouse and loft building covering approximately 40% of the lot on the south, with an attached storage yard to the north. The building has a partial cellar covering approximately half the building area on the west, featuring stone rubble walls with a superstructure of wood frame and masonry construction.
- 2465 Atlantic Avenue: The property is improved with an approximately 116-year-old (built circa 1908) three-story vacant loft building covering the entirety of the lot. The building has a full cellar featuring stone rubble walls with a superstructure of wood frame and masonry construction.

A Site Location Map is included in **Figure 1**. A Site Plan is included as **Figure 2**.

2.2 Physical Setting

The topography of the subject property and surrounding area was reviewed from the USGS 7.5-minute series topographic map for the Brooklyn, NY quadrangle. The property elevation is approximately 70 feet above the National Geodetic Vertical Datum (NGVD).

The geologic setting of Long Island is well documented and consists of crystalline bedrock composed of schist and gneiss overlain by layers of unconsolidated deposits. Immediately overlying the bedrock is the Raritan Formation, consisting of the Lloyd sand confined by the Raritan Clay Member. The Lloyd sand is an aquifer and consists of discontinuous layers of gravel, sand, sandy and silty clay, and solid clay. The Raritan Clay is a solid and silty clay with: few lenses of sand and gravel, abundant lignite and pyrite, and gray, red, or white in color.

Above the Raritan Clay lies the Magothy Formation. The Magothy Aquifer consists of layers of fine to coarse sand of moderate to high permeability, with inter-bedded lenses of silt and clay of low permeability resulting in areas of preferential horizontal flow; therefore, this aquifer generally becomes more confined with depth. The Magothy Aquifer is overlain by the Upper Glacial Aquifer. The Upper Glacial Aquifer is the water table aquifer at this location and is comprised of medium to coarse sand and gravel with occasional thin lenses of fine sand and brown clay. This aquifer extends from the land surface to the top of the Magothy Aquifer; therefore, is hydraulically connected to the Magothy Aquifer.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

Based upon the subject property elevation and regional groundwater contour maps, the depth to groundwater beneath the subject property was estimated at 59 feet below existing grade. Regional groundwater flow is estimated to be toward the southeast direction.

2.3 Site History and Land Use

45 Van Sinderen Avenue: Prior to the construction of the existing improvements, the subject property was improved with small buildings used for coal and wood storage associated with the Thatford and Ackerman Coal and Lumber Yard since at least 1888 and was likely vacant land prior to that. The current subject building was constructed in 1920 and was used as a rolled gold manufacturing facility in 1932 and an instrument testing company from 1951 until the early 2000's. The property is currently used as a furniture warehouse.

2465 Atlantic Avenue: Prior to the construction of the existing improvements, the subject property was developed with a two-story commercial building used as part of the Thatford & Ackerman Coal and Lumber Yard since at least 1888. Prior to that, the Subject was vacant land. The current building was constructed circa 1908 and was used as a hotel, an electrical supply company, a clothing manufacturer, a lamp manufacturer and a radio and telecom manufacturer throughout the years since its construction. The property is currently used as a sign designer and manufacturer.

2.4 Adjacent Property Land Use

The area surrounding the subject property was lightly developed by 1888 and more densely developed by 1932. An elevated subway track located near the subject property has been in existence since at least 1897 and the remainder of the area has mostly been used for commercial or industrial uses up until the present day.

2.5 Summary of Previous Assessments

2.5.1 Phase I Environmental Site Assessment Report (September 2018) - 2465 Atlantic Avenue

CBRE, Inc. prepared a Phase I ESA in September of 2018 for 2465 Atlantic Avenue. The Phase I ESA identified the following RECs associated with subject property:

- REC 1 – The property was formerly occupied by APEX Airtronics, Inc. (a radio and telecom equipment manufacturer) from 1948-2014. The subject property was listed as a Resource Conservation and Recovery Act (RCRA) Non-Generator as of 2007, but in 1999 was formerly a Small Quantity Generator of hazardous waste. In 1980, the subject property was a Large Quantity Generator in 1980 for production of spent non-halogenated solvents. Given that much of the

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

operations at the property occurred during a period with little to no environmental regulations, the historical industrial usage was considered a REC.

- BER – The subject property installed a 550-gallon No. 2 fuel oil AST in 1956. The tank was converted to non-regulated use and appeared to be in good condition. The tank is encased in concrete and is considered to be an underground storage tank by the NYSDEC. This was not considered a REC, but was considered a BER.

2.5.2 Phase I Environmental Site Assessment Report (September 2018) – 45 Van Sinderen Avenue

CBRE, Inc. prepared a Phase I ESA in September of 2018 for 45 Van Sinderen Avenue. The Phase I ESA did not identify RECs associated with subject property.

2.5.3 Phase II Environmental Site Assessment Report (November 2018) – 2465 Atlantic Avenue

Castleton Environmental prepared a Phase II ESA in November of 2018. The Phase II ESA documented the findings of the Subsurface Investigation performed at the subject property. The Phase II ESA is summarized below.

On November 7, 2018, two sub-slab vapor samples (SSV01 and SSV02), two indoor air samples (IAQ01 and IAQ02), and one outdoor ambient air sample (OAQ01) were collected and analyzed for the presence of VOCs by York Analytical Laboratories using 6-liter SUMMA canisters fitted with two-hour regulators. Each sub slab location was screened with a photoionization detector for the presence of VOCs before sampling. The photoionization detector detected readings of 1.4 and 2.7 parts per million.

Multiple chlorinated VOCs, including carbon tetrachloride, cis-1,2-dichloroethylene, (DCE), trichloroethylene (TCE), methylene chloride, and tetrachloroethylene (PCE) were detected. PCE was detected at concentrations in SSV02 and IAQ02 that would warrant mitigation based on NYSDOH decision matrices and was also detected in OAQ01. All remaining analytes were reported as non-detect.

Based on the findings of the Phase II ESA, Castleton Environmental recommended the sealing of seams, piping penetrations, and floor/wall joints to prevent vapors from entering the building from beneath the slab. Castleton Environmental did not recommend further sampling that would disturb the concrete floor.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

3.0 INVESTIGATION METHODOLOGY

The Phase II ESA included the following tasks:

- Geophysical survey
- Soil quality evaluation
- Groundwater quality evaluation
- Soil vapor intrusion investigation

3.1 Geophysical Survey

On April 15 and April 16, 2024, PWGC and Advanced Geological Services (AGS) of Malvern, Pennsylvania mobilized to the subject property to perform a geophysical survey. The purpose of the geophysical survey was to determine the absence/presence of subsurface anomalies at the subject property. Descriptions of the geophysical methods are described below.

A copy of the Geophysical Survey Report, including further detail regarding the methodology and findings, is included in **Appendix A**.

3.1.1 Electromagnetic Survey

AGS utilized a RD400 by Radio-Detection, an EM61 electromagnetic (EM) instrument, and a Fisher M Scope TW-6 metal detector. The Radiodetection RD400, EM61 electromagnetic, and Fisher M Scope use the principle of EM induction to measure the variability of electrical conductivity of subsurface materials and the presence of buried metal objects. Significant contrasts in the electrical properties between non-indigenous materials and surrounding soil enable accurate delineation of buried waste materials, fill, and geologic features. The large EM response to metal makes this technique particularly well suited to identifying buried metal objects such as underground storage tanks (USTs), metallic wastes, buried drums, pipelines, reinforced building foundations, and other metal components of buried structures. It is, however, equally sensitive to metal objects on the ground surface.

3.1.2 Ground Penetrating Radar Survey

Following the electromagnetic survey, AGS utilized a GSSI SIR-3000 with a 400 Mhz antenna to further investigate the metallic anomalies. Ground penetrating radar (GPR) uses high frequency pulsed electromagnetic waves to acquire subsurface information. Energy is propagated downward into the ground and is reflected back to the surface from boundaries at which there are electrical property contrasts. Penetration is the greatest in unsaturated sands and fine gravels and dry, well cured concrete. Clayey, highly saline or saturated soils, areas covered by steel reinforced concrete, foundry slag, uncured concrete, or other highly conductive materials significantly reduce depth penetration of the GPR signal. The 400

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

MHz antenna can achieve depths of penetration up to about 20 feet, but this depth may be greatly reduced due to site-specific conditions as discussed above.

3.2 Soil Quality Evaluation

To characterize soil quality at the subject property, soil borings were installed throughout the site. A total of four soil borings were installed during the Phase II ESA investigation. Soil boring locations are illustrated in **Figure 3**.

3.2.1 Soil Boring Protocol

Lakewood Environmental Services Corp. (Lakewood) of Smithtown, New York provided environmental drilling services during the investigation. A Track Mounted Geoprobe 6610 was utilized to install the environmental soil borings. Soils were collected continuously from ground surface down to an approximate depth of 15 feet below the ground surface (bgs). For two soil borings installed in the buildings' basements, a hammer drill was utilized to break through the concrete slab and a hand auger was utilized to collect soils up to a depth of two feet bgs.

The soil cores and hand augured soils were placed on 10-mil polyethylene sheeting in the order they came out of the ground. The acetate liners were cut open and the soil core was screened for the presence of volatile organic vapors, which are commonly associated with petroleum products and industrial solvents, utilizing a photo-ionization detector (PID). Each soil core was classified by a hydrogeologist using the Unified Soil Classification System (USCS). A soil boring log was developed for each location (**Appendix B**) and includes the characterization and screening data.

3.2.2 Soil Sample Collection Protocol

Soil samples collected for volatile organic analysis were collected directly from the acetate liners utilizing terra-core sampling devices. The remaining sample volumes were transferred to a stainless-steel bowl and homogenized. Once homogenized, samples were transferred to laboratory supplied glassware and packed in a cooler with ice and shipped under proper chain-of-custody procedures to Alpha Analytical Laboratories of Westborough, Massachusetts (Alpha), a New York State Department of Health (NYSDOH) Environmental Laboratory Approval Program (ELAP) certified laboratory, for analysis following NYSDEC Analytical Services Protocol (ASP)-Category A Deliverables.

3.3 Groundwater Quality Evaluation

To characterize groundwater quality at the subject property, a total of two groundwater samples were intended to be collected as part of this Phase II ESA. Lakewood utilized a track mounted Geoprobe® direct-push drill rig to advance a SP-16 sampler in two boreholes and advance the sampler to groundwater. Due

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

to repeated refusals at depths ranging from 30 feet bgs to 40 feet bgs, Lakewood was unable to reach groundwater; therefore, groundwater samples were unable to be collected as part of this Phase II ESA.

3.4 Soil Vapor Intrusion Investigation

To evaluate potential vapor intrusion at the subject property, a soil vapor intrusion investigation was performed. The investigation consisted of the collection of one soil vapor sample and one sub-slab soil vapor sample.

3.4.1 Soil Vapor Point Installation Protocol

Soil vapor and sub-slab soil vapor sampling was performed in accordance with the NYSDOH "Guidance for Evaluating Soil Vapor Intrusion in New York State," (NYSDOH Guidance) October 2006 and subsequent addenda.

3.4.1.1 Sub-Slab Soil Vapor Sampling

The sub-slab soil vapor sampling points was installed using a hammer drill to approximately two inches beneath the floor slab in accordance with procedures specified in the NYSDOH Guidance. Sampling points were constructed of dedicated polyethylene tubing backfilled with coarse sand and sealed at the surface with hydrated bentonite.

3.4.1.2 Soil Vapor Sampling

The soil vapor sampling point was installed to a depth of five feet bgs utilizing a Geoprobe® direct-push drill rig. A six-inch stainless-steel screen was installed at the base of the sampling point with dedicated polyethylene tubing to grade. Coarse sand was placed surrounding the screen and six inches above. The remainder of the soil vapor point annulus was sealed with bentonite grout to the surface.

3.4.1.3 Tracer Gas Testing

Prior to sampling, the integrity of soil vapor and sub-slab soil vapor sampling point seals was tested using tracer gas analysis. The environment surrounding the seal was enriched with the tracer gas (helium) as readings were collected through the sampling probe with a portable helium detector. Seals were adjusted as needed until acceptable tracer gas readings were collected from each soil vapor probe indicating the seals were intact and the sampling probes were acceptable for sample collection.

After the initial tracer gas test was performed, one to three volumes of the sample tubing was purged prior to collecting samples. Flow rates for both purging and collecting did not exceed 0.2 liters per minute to minimize potential indoor air infiltration during sampling.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

3.4.2 *Soil Vapor and Air Sample Collection Protocol*

Soil vapor and sub-slab soil vapor samples were collected into 6-liter Summa® vacuum canisters fitted with 2-hour flow controllers. Canisters and flow controllers were batch certified clean by the laboratory. Proper quality assurance/quality control (QA/QC) protocol was followed during the collection of soil gas samples to ensure that cross-contamination in the field did not occur.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

4.0 INVESTIGATION FINDINGS

4.1 Geophysical Survey

A geophysical survey was performed as detailed in Section 3.1. Findings of the geophysical survey included the following:

- The maximum depth of GPR penetration at the property was approximately 5 feet bgs.
- No underground storage tanks were identified during the geophysical survey.
- Areas of elevated electromagnetic response appear to be due to the presence of smaller scrap metal.
- The northern and eastern portions of the property exterior were obstructed by vehicles and equipment storage and were not accessible for collection of geophysical data.

4.2 Soil Quality Evaluation

To characterize soil quality, soil borings were installed within the basements of 2465 Atlantic Avenue and 45 Van Sinderen Avenue, within the northern exterior yard, and in the alley between the two buildings. A total of four soil borings (SB001-B through SB004-B) were installed during the investigation. Soil boring locations are illustrated in **Figure 3**.

4.2.1 Soil Boring Protocol

Soil borings were installed as detailed in Section 3.2. Soils were collected continuously to the final depth of each boring. Borings inside the cellar (SB001-B and SB002-B) were installed to a depth of 2 feet below the slab (approximately 12 feet below ground surface). Borings outside of the building (SB003-B and SB004-B) were installed to a depth of 15 feet below ground surface. Soils in these areas generally consisted of two distinct layers of fill material. The upper layer contained brick and glass, intermixed with fine to medium grained sand with fines and gravel with slight plasticity, and ranged between surface grade and two to six feet bgs in the borings. The lower layer contained brick and glass, intermixed with fine to coarse silty sand and gravel with no plasticity, and continued to at least 15 feet bgs where the boring terminated. No visual or olfactory contamination was observed in any of the soil borings. PID readings ranged from 0.0 parts per million (ppm) to 1.3 ppm. Soil boring logs are included in **Appendix B**.

4.2.2 Soil Sample Collection Protocol

Two soil samples were collected from the buildings' basements using a hand auger from the 0 to 2 feet interval directly beneath the concrete slab. Two soil samples were collected from each of the two borings advanced using the Geoprobe, from the intervals exhibiting the highest visual or olfactory contamination. As these two borings did not exhibit visual or olfactory evidence of contamination, but did exhibit evidence of fill material throughout the boring, samples were collected from the 0 to 2 feet bgs and 13 to 15 feet bgs intervals. Soil samples were collected as detailed in Section 3.2, and were analyzed for the following:

- VOCs by USEPA Method 8260

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

- SVOCs by USEPA Method 8270
- Metals by USEPA Methods 6010/7196/7471/9012

4.2.2.1 Soil Analytical Results

Soil analytical results were compared to the Soil Cleanup Objectives (SCOs) for Unrestricted, Restricted Residential, and Commercial Use Soil Cleanup Objectives (UUSCOs, RRUSCOs, and CUSCOs, respectively) as specified in NYSDEC's Title 6 New York Codes, Rules, and Regulations (NYCRR) Part 375, Environmental Remediation Programs. A total of six samples were collected.

Analytical results from each of the soil borings did not yield concentrations of VOCs exceeding UUSCOs except for Trichloroethylene (TCE) in SB001-B_0-2' and cis-1,2-dichloroethylene (DCE) and tetrachloroethylene (PCE) in SB002-B_0-2'.

SVOCs were detected at concentrations exceeding UUSCOs in two samples, SB002-B_0-2' (benzo(k)fluoranthene) and SB004-B_0-2' (chrysene). SB002-B_0-2' exceeded RRUSCOs for chrysene and indeno(1,2,3-cd)pyrene, and SB004-B_0-2' exceeded RRUSCOs for benzo(a)anthracene, benzo(b)fluoranthene, and indeno(1,2,3-cd)pyrene. In addition, SB002-B_0-2' exceeded CUSCOs for benzo(a)anthracene (7.0 mg/kg), benzo(a)pyrene (8.5 mg/kg), benzo(b)fluoranthene (9.8 mg/kg), and dibenzo(a,h)anthracene (1.5 mg/kg), and SB004-B_0-2' exceeded CUSCOs for benzo(a)pyrene (1.4 mg/kg).

Metals were detected at concentrations exceeding UUSCOs in SB001-B_0-2' (lead, mercury, and zinc), SB002-B_0-2' (lead, mercury, and zinc), SB003-B_0-2' (copper, and zinc), SB004_0-2' (zinc and mercury), and SB004-B_13-15' (manganese). SB003-B_0-2' exceeded RRUSCOs for mercury and lead and SB004-B_0-2' exceeded RRUSCOs for lead. In addition, SB001-B_0-2' and SB004-B_0-2' exceeded the CUSCO for copper (270 mg/kg) at 311 mg/kg and 414 mg/kg, respectively) and SB003-B_0-2' exceeded the CUSCO for arsenic (16 mg/kg) at 25.8 mg/kg.

Analytical results are detailed in **Tables 1** through **3** and the complete laboratory analytical report is included in **Appendix C**.

4.2.3 Soil Vapor Intrusion Investigation

To evaluate potential vapor intrusion at the subject property, one sub-slab soil vapor (SS001-B) sample and one soil vapor (SV001-B) sample were collected. Soil vapor and air samples were collected as described in Section 3.3.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

4.2.3.1 Soil Vapor Analytical Results

The primary method for the evaluation of sub-slab vapor and indoor air data is the use of Soil Vapor / Indoor Air Matrices provided in the NYSDOH Guidance document. The matrices incorporate both sub-slab vapor concentrations and their corresponding indoor air concentrations in a table to formulate an appropriate action for a sampling site. Matrices have been developed for a limited number of chlorinated and petroleum-related VOCs. Although matrices have not yet been developed for other compounds, consideration is given to the comparisons between the sub-slab vapor and indoor air concentrations to determine if vapor intrusion is occurring.

Indoor air samples were not collected as part of this assessment. As there was no building present in the northern yard, a sub-slab vapor sample could not be collected at the up gradient end of the property; however, the analytical results for the soil vapor sample was utilized in place of a sub-slab vapor sample in comparison to the matrices to provide guidance. The analytical results for the sub-slab soil vapor and soil vapor samples were compared to the lowest values included on the NYSDOH decision matrices for sub-slab soil vapor which may warrant further action.

Analytical results for sub-sab soil vapor in SS001-B exceeded the lowest concentrations specified in the NYSDOH decision matrices for PCE (100 µg/m^3) at 1,440 100 µg/m^3, TCE (6 µg/m^3) at 111 µg/m^3, and DCE (6 µg/m^3) at 61.9 µg/m^3. Furthermore, these concentrations exceed the decision matrices that would warrant mitigation regardless of the concentration of the corresponding indoor air sample (1,000 µg/m^3 for PCE, 60 µg/m^3 for TCE and DCE).

No VOCs were detected at concentrations exceeding the lowest concentrations specified in the NYSDOH decision matrices in SV001-B. There are detectable concentrations of petroleum related compounds, such as the trimethylbenzenes and BTEX (benzene, ethylbenzene, and toluene) and chlorinated VOCs such as tetrachloroethylene. These concentrations are relatively low; however, these samples were not collected immediately beneath a slab or within 2 feet of a known source of contamination.

Analytical results are detailed in **Table 4**. The complete laboratory analytical report is included in **Appendix C**.

4.3 Site Environmental Evaluation

Soil impact at the property primarily consisted of chlorinated VOCs exceeding UUSCOs and SVOCs (polyaromatic hydrocarbons [PAHs]) and metals at concentrations exceeding their respective CUSCOs in the shallow (zero to two feet bgs) soils sampled. SVOC and metal impact at the levels detected is commonly associated with the presence of fill material. This observation is further supported by the presence of debris

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

(brick/glass) observed in the soil at the property; however, the PAH and metal impact appears to largely be limited to the upper layer of fill, as manganese was the only analyte to exceed UUSCOs in the lower fill layer. Based on the concentration of lead observed in shallow soils, if disturbed or removed from the site for disposal, waste characterization including Toxicity Characteristic Leaching Procedure (TCLP) analysis may result in the soil being deemed hazardous and requiring special handling for disposal.

The concentrations of chlorinated VOCs exceeding UUSCOs were limited to the two samples collected from beneath the building slabs and may be associated with the presence of these compounds in sub-slab soil vapor.

Chlorinated VOCs were detected in the sub-slab soil vapor sample at concentrations that warrant mitigation, regardless of their respective concentrations in the indoor air. A more comprehensive soil vapor intrusion investigation and installation of a soil vapor mitigation system may be recommended.

Petroleum related compounds and chlorinated VOCs were also detected in the soil vapor sample. While no concentrations of VOCs were observed that would warrant mitigation based on the NYSDOH matrices, the presence of a building slab in this area, if a new building were to be constructed, could potentially result in higher concentrations of compounds accumulating beneath the slab which may represent a soil vapor intrusion concern, similar to what was observed in the sub-slab vapor sample. Installation of a vapor barrier or other suitable vapor intrusion mitigation methods may be recommended here, too, if this portion of the site were to be developed in the future.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

5.0 CONCLUSIONS AND RECOMMENDATIONS

PWGC has performed a Phase II ESA at the subject property in conformance with the scope and limitations of ASTM Practice E1903-19 for the following objectives:

- Geophysical survey to identify potential USTs, utilities, and other subsurface anomalies.
- Installation of four soil borings (SB001 through SB004), and collection of one to two soil samples from each boring.
- Installation of one soil vapor sampling point (SV001) and one sub-slab soil vapor sampling point (SS001) and collection of two soil vapor samples.

5.1 Conclusions

Based on the results of the Phase II ESA, PWGC offers the following conclusions:

Subsurface anomalies indicative of potential USTs, drywells, or other objects which would warrant further investigation were not identified during the geophysical survey.

Soil quality across the soil borings exhibited the presence of fill material in the top 15 feet. Six soil samples were collected from four soil borings installed across the site as part of this assessment. Analytical results for each of the four samples did not identify concentrations of VOCs greater than Unrestricted Use SCOs with the exception of PCE, TCE, and DCE in SB002 from the 0 to 2-foot interval, collected from the basement of 2465 Atlantic Avenue. SVOCs, namely PAH compounds, were detected in SB002 and SB003 from the 0 to 2-foot interval at concentrations greater than CUSCOs. Metals including arsenic and copper were detected at concentrations greater than CUSCOs in SB001, SB003, and SB004 in the 0 to 2-foot interval, lead, mercury, and zinc exceeded UUSCOs in SB002 in the 0 to 2-foot interval, and manganese exceeded UUSCOs in SB004 in the 13 to 15-foot interval. VOCs, SVOCs, and metals were not detected at concentrations greater than UUSCOs in the two soil samples collected from the deeper interval. In general, elevated concentrations of SVOCs and metals were identified at locations and depths where the upper layer of fill material was observed, with manganese being the only analyte detected greater than UUSCOs in the lower fill layer. Elevated concentrations of VOCs were identified only in samples collected from beneath the building slab and may be associated with the presence of soil vapors.

One soil vapor sample was collected from the up gradient portion of the property in the northern yard, and one sub-slab soil vapor sample was collected from the down gradient portion of the property in the basement of 2465 Atlantic Ave, which was previously used for industrial purposes (radio and telecom manufacturing). There were no VOC concentrations detected in the up gradient soil vapor sample that would warrant mitigation based on NYSDOH matrices; however, concentrations of petroleum related compounds, such as the trimethylbenzenes and BTEX and chlorinated VOCs such as tetrachloroethylene

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

and vinyl chloride were detected at lower concentrations. The sub-slab soil vapor sample contained concentrations of PCE, TCE, and DCE that would warrant mitigation regardless of a corresponding indoor air sample. Based on the results of the sub-slab soil vapor sample and the soil samples collected in the basements of 2465 Atlantic Avenue and 45 Van Sinderen Avenue, there appears to be a soil vapor intrusion concern within this portion of the property.

5.2 Recommendations

Based on the conclusions detailed above, PWGC offers the following recommendations for the subject property:

- Based on the concentrations of SVOC and metals impact observed in the subsurface, PWGC recommends that these soils be handled in accordance with local, state, and federal regulations and guidance if they are to be disturbed and/or removed from the site for offsite disposal. This should involve appropriate waste characterization sampling to determine if some of the metal impacts (particularly lead) are deemed hazardous.
- Soil vapor intrusion mitigation is recommended in the basements of 2465 Atlantic Avenue and 45 Van Sinderen Avenue. Additional delineation of sub-slab vapor concentrations is recommended to more finely focus this mitigation area. Once this area has been better defined, a pilot study is recommended to determine the radius of influence for SSDS pits, and the SSDS system should then be designed and installed.
- Installation of a vapor barrier or other appropriate soil vapor mitigation methods if a new building is to be constructed.


P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

6.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR 312.



Michael Pecoraro
Project Manager



Jennifer Lewis, PG
Vice President

Report Completion Date: May 29, 2024

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

7.0 REFERENCES

6 NYCRR Part 375 Environmental Remediation Programs Subparts 375-1 to 375-4 and 375-6.

6 NYCRR Part 703 Surface Water and Groundwater Quality Standards and Groundwater Effluent Limitations.

Commissioners Policy CP-51, Soil Cleanup Guidance, NYSDEC, October 21, 2010.

Standard Practice for Environmental Site Assessments: Phase II Environmental Site Assessment Process, ASTM Standard E 1903-19.

Technical Guidance for Site Investigation and Remediation (DER-10), NYSDEC, May 3, 2010.

CBRE, 2465 Atlantic Avenue Phase I ESA, September 2018

CBRE, 45 Van Sinderen Avenue Phase I ESA, September 2018

Castleton Environmental, 2465 Atlantic Avenue Phase II ESA, November 2018

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT


8.0 LIMITATIONS

The conclusions presented in this report are professional opinions based on the data described in this report. These opinions have been arrived at in accordance with currently accepted engineering and hydrogeologic standards and practices applicable to this location, and are subject to the following inherent limitations:

1. The data presented in this report are from visual inspections and examination of records prepared by others. The passage of time, manifestation of latent conditions, or occurrence of future events may require further exploration of the site, analysis of data, and re-evaluation of the findings, observations, and conclusions presented in this report.
2. The data reported and the findings, observations, and conclusions expressed are limited by the scope of work. The scope of work was defined by the request of the client.
3. No warranty or guarantee, whether expressed or implied, is made with respect to the data reported, findings, observations, or conclusions. These are based solely upon site conditions in existence at the time of the investigation, and other information obtained and reviewed by PWGC.
4. The conclusions presented in this report are professional opinions based on data described in this report. They are intended only for the purpose, site location, and project indicated. This report is not a definitive study of contamination at the site and should not be interpreted as such.
5. This report is based, in part, on information supplied to PWGC by third-party sources. While efforts have been made to substantiate this third-party information, PWGC cannot attest to the completeness or accuracy of information provided by others.

P.W. GROSSER CONSULTING, INC • P.W. GROSSER CONSULTING ENGINEER & HYDROGEOLOGIST, PC
631.589.6353 • WWW.PWGROSSER.COM • PWGC.INFO@PWGROSSER.COM
BOHEMIA • MANHATTAN • SARATOGA SPRINGS • MONTICELLO, NY • SYRACUSE • SHELTON, CT

FIGURES



SITE LOCATION

2465 Atlantic Ave & 45 Van Sinderen Ave-2514
Brooklyn, NY 11207

Miles
0 ¼ ½ ¾ 1 1¼ 1½ 1¾ 2

PWGC
CLIENT DRIVEN SOLUTIONS
P.W. Grosser Consulting, Inc.
630 Johnson Ave., Suite 7
Bohemia, NY 11716
Ph: 631-589-6353 • Fax: 631-589-8705
pwgc.info@pwgrosser.com

Project:	TOT2401
Date:	5/2/2024
Designed by:	MP
Drawn by:	AM
Approved by:	MP
Figure No:	1

Document Path: W:\Projects\S-2\TOT\2401\map files\Site 4\Atlantic_Sinderen_AnalyticalResults.aprx



Document Path: W:\Projects\S-Z\TOT\2401\map files\Site 4\Site4Plan_Location.aprx

PWGC
CLIENT DRIVEN SOLUTIONS
P.W. Grosser Consulting, Inc.
630 Johnson Ave., Suite 7
Bohemia, NY 11716
Ph: 631-589-6353 • Fax: 631-589-8705
pwgc.info@pwgrosser.com

Broadway Junction Partners, LLC
26 Harbor Park Drive
Port Washington, NY 11050

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DRAWING AND RELATED DOCUMENTS IS A VIOLATION OF SEC. 7209 OF THE N.Y.S. EDUCATION LAW

DRAWING PREPARED FOR:

REVISION	DATE	INITIAL	COMMENTS

DRAWING INFORMATION:


Project:	TOT2401	Designed by:	MP
Date:	3/26/2024	Drawn by:	AM
Scale:	AS SHOWN	Approved by:	MP

SITE PLAN

2465 Atlantic Ave & 45 San Sinderen Ave
Brooklyn, NY 11207

FIGURE NO:

2



Client Sample ID:	SB004-B		
Sample Elevation:	0-2'	13-15'	
Laboratory ID:	L2420803-03	L2420803-04	
Sampling Date:	4/16/2024	4/16/2024	
Semi-Volatile Organic Compounds by USEPA method 8270 in mg/kg			
Benzo(a)anthracene	1.6	0.020	U
Benzo(a)pyrene	1.4	0.043	U
Benzo(b)fluoranthene	1.9	0.030	U
Chrysene	1.6	0.018	U
Indeno(1,2,3-cd)pyrene	0.95	0.025	U
Total Metals by USEPA Method 6010 in mg/kg			
Copper	414	29.2	
Lead	828	6.68	J
Manganese	197	1,670	
Zinc	371	43.4	
Total Mercury by USEPA Method 7471 in mg/kg			
Mercury	0.389	0.0440	U

Client Sample ID:	SB001-B
Sample Elevation:	0-2'
Laboratory ID:	L2420537-01
Sampling Date:	4/15/2024
Volatile Organic Compounds by USEPA method 8260 in mg/kg	
Trichloroethene	1.1
Total Metals by USEPA Method 6010 in mg/kg	
Copper	311
Lead	65.7
Zinc	218
Total Mercury by USEPA Method 7471 in mg/kg	
Mercury	0.193

Client Sample ID:	SB002-B
Sample Elevation:	0-2'
Laboratory ID:	L2420537-02
Sampling Date:	4/15/2024
Volatile Organic Compounds by USEPA method 8260 in mg/kg	
cis-1,2-Dichloroethene	0.37
Tetrachloroethene	13
Semi-Volatile Organic Compounds by USEPA method 8270 in mg/kg	
Benzo(a)anthracene	7.0
Benzo(a)pyrene	8.5
Benzo(b)fluoranthene	9.8
Benzo(k)fluoranthene	2.0
Chrysene	7.0
Dibenzo(a,h)anthracene	1.5
Indeno(1,2,3-cd)pyrene	3.8
Total Metals by USEPA Method 6010 in mg/kg	
Lead	207
Zinc	130
Total Mercury by USEPA Method 7471 in mg/kg	
Mercury	0.373

Client Sample ID:	SB003-B		
Sample Elevation:	0-2'	12-14'	
Laboratory ID:	L2420803-01	L2420803-02	
Sampling Date:	4/16/2024	4/16/2024	
Total Metals by USEPA Method 6010 in mg/kg			
Arsenic	25.8	5.02	
Copper	56.6	25.3	
Lead	598	5.64	J
Zinc	144	29.4	
Total Mercury by USEPA Method 7471 in mg/kg			
Mercury	1.13	0.0420	U

Notes:

U - The analyte was analyzed for, but was not detected above the reported sample quantification limit.

J - The analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.

Highlighted text denotes concentrations exceeding NYSDEC Unrestricted Use SCO

Highlighted text denotes concentrations exceeding NYSDEC Restricted Residential Use SCO

Highlighted text denotes concentrations exceeding NYSDEC Commercial Use SCO

PWGC
CLIENT DRIVEN SOLUTIONS
P.W. Grosser Consulting, Inc.
630 Johnson Ave., Suite 7
Bohemia, NY 11716
Ph: 631-589-6353 • Fax: 631-589-8705
pwgc.info@pwgrosser.com

Broadway Junction Partners, LLC
26 Harbor Park Drive
Port Washington, NY 11050

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DRAWING AND RELATED DOCUMENTS IS A VIOLATION OF SEC. 7209 OF THE N.Y.S. EDUCATION LAW

DRAWING PREPARED FOR:

REVISION	DATE	INITIAL	COMMENTS

DRAWING INFORMATION:

Project:	TOT2401	Designed by:	MP
Date:	5/2/2024	Drawn by:	AM
Scale:	AS SHOWN	Approved by:	MP


SOIL ANALYTICAL RESULTS

2465 Atlantic Ave & 45 Van Sinderen Ave
Brooklyn, NY 11207

FIGURE NO:

3

Document Path: W:\Projects\S-Z\TOT\2401\map files\Site 4\Atlantic_Sinderen_AnalyticalResults.aprx



Client Sample ID:	SS001-B
Sample Type:	Sub-SlabSoil Vapor
Sample Depth:	2"
Laboratory ID:	L2420834-01
Sampling Date:	4/15/20240
Volatile Organic Compounds by USEPA Method TO-15 in µg/m³	
1,2,4-Trimethylbenzene	19.4
1,3,5-Trimethylbenzene	5.31
2-Butanone	19.3
2-Hexanone	3.87
4-Ethyltoluene	3.17
Acetone	558
Carbon disulfide	5.79
Chloroform	9.38
cis-1,2-Dichloroethene	61.9
Ethylbenzene	3.09
Heptane	2.43
Isopropanol	9.73
o-Xylene	8.34
p/m-Xylene	14.4
Tetrachloroethene	1,440
Toluene	17.6
Trichloroethene	111

Client Sample ID:	SV001-B
Sample Type:	Soil Vapor
Sample Depth:	5'
Laboratory ID:	L2420834-02
Sampling Date:	4/16/2024
Volatile Organic Compounds by USEPA Method TO-15 in µg/m³	
1,2,4-Trimethylbenzene	18.8
1,3,5-Trimethylbenzene	5.16
1,3-Butadiene	10.6
2-Butanone	75.8
2-Hexanone	19.8
4-Ethyltoluene	2.25
4-Methyl-2-pentanone	4.63
Acetone	649
Benzene	2.92
Carbon disulfide	5.33
Chloromethane	2.87
Cyclohexane	20.3
Dichlorodifluoromethane	2.26
Ethanol	36.7
Ethylbenzene	4.52
Heptane	38.8
Isopropanol	3.47
Naphthalene	1.52
n-Hexane	50.8
o-Xylene	11.6
p/m-Xylene	18.9
Tertiary butyl Alcohol	13.6
Tetrachloroethene	23.1
Tetrahydrofuran	55.7
Toluene	18.2

Site Boundary
Tax Lots
Soil Vapor Sample
Sub-slab Soil Vapor Sample

Notes:
Only analytes with detectable concentrations are displayed.

Document Path: W:\Projects\S-Z\TOT\2401\map files\Site 4\Atlantic_Sinderen_AnalyticalResults.aprx

PWGC
CLIENT DRIVEN SOLUTIONS
P.W. Grosser Consulting, Inc.
630 Johnson Ave., Suite 7
Bohemia, NY 11716
Ph: 631-589-6353 • Fax: 631-589-8705
pwgc.info@pwgrosser.com

Broadway Junction Partners, LLC
26 Harbor Park Drive
Port Washington, NY 11050

UNAUTHORIZED ALTERATION OR ADDITION TO THIS DRAWING AND RELATED DOCUMENTS IS A VIOLATION OF SEC. 7209 OF THE N.Y.S. EDUCATION LAW

DRAWING PREPARED FOR:

REVISION	DATE	INITIAL	COMMENTS

DRAWING INFORMATION:

Project:	TOT2401	Designed by:	MP
Date:	5/28/2024	Drawn by:	AM
Scale:	AS SHOWN	Approved by:	MP

SOIL VAPOR ANALYTICAL RESULTS

2465 Atlantic Ave & 45 Van Sinderen Ave
Brooklyn, NY 11207

FIGURE NO:

4

TABLES

Table 1
Soil Sample Analytical Data Summary
Volatile Organic Compounds
2465 Atlantic Ave 45 Van Sinderen Ave, Brooklyn, NY

Client Sample ID:					SB001-B		SB002-B		SB003-B				SB004-B			
Sample Location	CAS Number	NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives (1)	NYSDEC Part 375 Restricted Residential Soil Cleanup Objectives (2)	NYSDEC Part 375 Commercial Soil Cleanup Objectives (3)	Basement		Basement		Ground Surface				Ground Surface			
Sample Depth:					0-2'		0-2'		0-2'		12-14'		0-2'		13-15'	
Laboratory ID:					L2420537-01		L2420537-02		L2420803-01		L2420803-02		L2420803-03		L2420803-04	
Sampling Date:					4/15/2024		4/15/2024		4/16/2024		4/16/2024		4/16/2024		4/16/2024	
Volatile Organic Compounds by USEPA method 8260 in mg/kg																
1,1,1,2-Tetrachloroethane	630-20-6	NS	NS	NS	0.00076	U	0.053	U	0.00015	U	0.00013	U	0.014	U	0.00016	U
1,1,1-Trichloroethane	71-55-6	0.68	100	500	0.00076	U	0.053	U	0.00019	U	0.00016	U	0.017	U	0.00021	U
1,1,2,2-Tetrachloroethane	79-34-5	NS	NS	NS	0.00076	U	0.053	U	0.00018	U	0.00016	U	0.017	U	0.00021	U
1,1,2-Trichloroethane	79-00-5	NS	NS	NS	0.0015	U	0.10	U	0.00030	U	0.00026	U	0.027	U	0.00034	U
1,1-Dichloroethane	75-34-3	0.27	26	240	0.0015	U	0.10	U	0.00016	U	0.00014	U	0.015	U	0.00018	U
1,1-Dichloroethene	75-35-4	0.33	100	500	0.0015	U	0.10	U	0.00026	U	0.00023	U	0.024	U	0.00030	U
1,1-Dichloropropene	563-58-6	NS	NS	NS	0.00076	U	0.053	U	0.00018	U	0.00015	U	0.016	U	0.00020	U
1,2,3-Trichlorobenzene	87-61-6	NS	NS	NS	0.0030	U	0.21	U	0.00036	U	0.00031	U	0.033	U	0.00040	U
1,2,3-Trichloropropane	96-18-4	NS	NS	NS	0.0030	U	0.21	U	0.00014	U	0.00012	U	0.013	U	0.00016	U
1,2,4,5-Tetramethylbenzene	95-93-2	NS	NS	NS	0.00036	J	0.21	U	0.00021	U	0.00018	U	0.020	U	0.00024	U
1,2,4-Trichlorobenzene	120-82-1	NS	NS	NS	0.0030	U	0.21	U	0.00030	U	0.00026	U	0.028	U	0.00034	U
1,2,4-Trimethylbenzene	95-63-6	3.6	52	190	0.0030	U	0.21	U	0.00037	U	0.00032	U	0.034	U	0.00042	U
1,2-Dibromo-3-chloropropane	96-12-8	NS	NS	NS	0.0046	U	0.32	U	0.0011	U	0.0010	U	0.10	U	0.0012	U
1,2-Dibromoethane	106-93-4	NS	NS	NS	0.0015	U	0.10	U	0.00031	U	0.00027	U	0.028	U	0.00035	U
1,2-Dichlorobenzene	95-50-1	1.1	100	500	0.0030	U	0.21	U	0.00016	U	0.00014	U	0.015	U	0.00018	U
1,2-Dichloroethane	107-06-2	0.02	3.1	30	0.0015	U	0.10	U	0.00029	U	0.00025	U	0.026	U	0.00032	U
1,2-Dichloroethene, Total	540-59-0	NS	NS	NS	0.031	J	0.37		0.00015	U	0.00013	U	0.014	U	0.00017	U
1,2-Dichloropropane	78-87-5	NS	NS	NS	0.0015	U	0.10	U	0.00014	U	0.00012	U	0.013	U	0.00016	U
1,3,5-Trimethylbenzene	108-67-8	8.4	52	190	0.0030	U	0.21	U	0.00022	U	0.00018	U	0.02	U	0.00024	U
1,3-Dichlorobenzene	541-73-1	2.4	49	280	0.0030	U	0.21	U	0.00016	U	0.00014	U	0.015	U	0.00018	U
1,3-Dichloropropane	142-28-9	NS	NS	NS	0.0030	U	0.21	U	0.00019	U	0.00016	U	0.017	U	0.00021	U
1,3-Dichloropropene, Total	542-75-6	NS	NS	NS	0.00076	U	0.053	U	0.00018	U	0.00015	U	0.016	U	0.00020	U
1,4-Dichlorobenzene	106-46-7	1.8	13	130	0.0030	U	0.21	U	0.00019	U	0.00016	U	0.017	U	0.00021	U
1,4-Dioxane	123-91-1	0.1	13	130	0.12	U	8.4	U	0.039	U	0.034	U	3.6	U	0.044	U
2,2-Dichloropropane	594-20-7	NS	NS	NS	0.0030	U	0.21	U	0.00022	U	0.00019	U	0.021	U	0.00025	U
2-Butanone	78-93-3	0.12	100	500	0.015	U	1.0	U	0.0025	U	0.0021	U	0.23	U	0.0028	U
2-Hexanone	591-78-6	NS	NS	NS	0.015	U	1.0	U	0.0013	U	0.0011	U	0.12	U	0.0015	U
4-Methyl-2-pentanone	108-10-1	NS	NS	NS	0.015	U	1.0	U	0.0014	U	0.0012	U	0.13	U	0.0016	U
Acetone	67-64-1	0.05	100	500	0.015	U	1.0	U	0.0054	U	0.0046	U	0.49	U	0.0060	U
Acrylonitrile	107-13-1	NS	NS	NS	0.0061	U	0.42	U	0.0013	U	0.0011	U	0.12	U	0.0014	U
Benzene	71-43-2	0.06	4.8	44	0.00076	U	0.053	U	0.00018	U	0.00016	U	0.017	U	0.00021	U
Bromobenzene	108-86-1	NS	NS	NS	0.0030	U	0.21	U	0.00016	U	0.00014	U	0.015	U	0.00018	U
Bromochloromethane	74-97-5	NS	NS	NS	0.0030	U	0.21	U	0.00023	U	0.00020	U	0.021	U	0.00026	U
Bromodichloromethane	75-27-4	NS	NS	NS	0.00076	U	0.053	U	0.00012	U	0.00010	U	0.011	U	0.00014	U
Bromoform	75-25-2	NS	NS	NS	0.0061	U	0.42	U	0.00027	U	0.00024	U	0.025	U	0.00031	U
Bromomethane	74-83-9	NS	NS	NS	0.0030	U	0.21	U	0.00065	U	0.00056	U	0.059	U	0.00073	U
Carbon disulfide	75-15-0	NS	NS	NS	0.015	U	1.0	U	0.0051	U	0.0044	U	0.46	U	0.0057	U
Carbon tetrachloride	56-23-5	0.76	2.4	22	0.0015	U	0.10	U	0.00026	U	0.00022	U	0.024	U	0.00029	U
Chlorobenzene	108-90-7	1.1	100	500	0.00076	U	0.053	U	0.00014	U	0.00012	U	0.013	U	0.00016	U
Chloroethane	75-00-3	NS	NS	NS	0.0030	U	0.21	U	0.00050	U	0.00044	U	0.046	U	0.00057	U
Chloroform	67-66-3	0.37	49	350	0.018	J	0.16	U	0.00016	U	0.00013	U	0.014	U	0.00018	U
Chloromethane	74-87-3	NS	NS	NS	0.0061	U	0.42	U	0.0010	U	0.00090	U	0.095	U	0.0012	U
cis-1,2-Dichloroethene	156-59-2	0.25	100	500	0.031	J	0.37		0.00020	U	0.00017	U	0.018	U	0.00022	U
cis-1,3-Dichloropropene	10061-01-5	NS	NS	NS	0.00076	U	0.053	U	0.00018	U	0.00015	U	0.016	U	0.00020	U
Dibromochloromethane	124-48-1	NS	NS	NS	0.0015	U	0.10	U	0.00016	U	0.00013	U	0.014	U	0.00018	U
Dibromomethane	74-95-3	NS	NS	NS	0.0030	U	0.21	U	0.00026	U	0.00023	U	0.024	U	0.00030	U
Dichlorodifluoromethane	75-71-8	NS	NS	NS	0.015	U	1.0	U	0.0010	U	0.00088	U	0.094	U	0.0011	U
Ethyl ether	60-29-7	NS	NS	NS	0.0030	U	0.21	U	0.00038	U	0.00033	U	0.035	U	0.00043	U
Ethylbenzene	100-41-4	1	41	390	0.0015	U	0.10	U	0.00016	U	0.00014	U	0.014	U	0.00018	U
Hexachlorobutadiene	87-68-3	NS	NS	NS	0.0061	U	0.42	U	0.00019	U	0.00016	U	0.017	U	0.00021	U
Isopropylbenzene	98-82-8	NS	NS	NS	0.0015	U	0.10	U	0.00012	U	0.00010	U	0.011	U	0.00014	U
Methyl tert butyl ether	1634-04-4	0.93	100	500	0.0030	U	0.21	U	0.00022	U	0.00019	U	0.02	U	0.00025	U
Methylene chloride	75-09-2	0.05	100	500	0.0076	U	0.53	U	0.0026	U	0.0022	U	0.23	U	0.0029	U
Naphthalene	91-20-3	12	100	500	0.0061	U	0.42	U	0.00072	U	0.00063	U	0.073	J	0.00082	U
n-Butylbenzene	104-51-8	12	100	500	0.0015	U	0.10	U	0.00019	U	0.00016	U	0.017	U	0.00021	U
n-Propylbenzene	103-65-1	3.9	100	500	0.0015	U	0.10	U	0.00019	U	0.00016	U	0.017	U	0.00021	U
o-Chlorotoluene	95-49-8	NS	NS	NS	0.0030	U	0.21	U	0.00021	U	0.00018	U	0.02	U	0.00024	U
o-Xylene	95-47-6	NS	NS	NS	0.0015	U	0.10	U	0.00032	U	0.00028	U	0.03	U	0.00036	U
p/m-Xylene	179601-23-1	NS	NS	NS	0.0030	U	0.21	U	0.00012	U	0.00010	U	0.011	U	0.00014	U
p-Chlorotoluene	106-43-4	NS	NS	NS	0.0030	U	0.21	U	0.00020	U	0.00017	U	0.018	U	0.00022	U
p-Diethylbenzene	105-05-5	NS	NS	NS	0.00042	J	0.21	U	0.00043	U	0.00037	U	0.039	U	0.00048	U
p-Ethyltoluene	622-96-8	NS	NS	NS	0.0030	U	0.21	U	0.00012	U	0.00010	U	0.011	U	0.00014	U
p-Isopropyltoluene	99-87-6	NS	NS	NS	0.0015	U	0.10	U	0.00062	U	0.00054	U	0.057	U	0.00070	U
sec-Butylbenzene	135-98-8	11	100	500	0.0015	U	0.10	U	0.00016	U	0.00014	U	0.015	U	0.00018	U
Styrene	100-42-5	NS	NS	NS	0.0015	U	0.10	U	0.00022	U	0.00019	U	0.02	U	0.00024	U
tert-Butylbenzene	75-65-0	NS	NS	500	0.0030	U	0.21	U	0.00013	U	0.00011	U	0.012	U	0.00015	U
Tetrachloroethene	98-06-6	5.9	100	150	2.3		13		0.00022	U	0.00019	U	0.02	U	0.00045	J
Toluene	127-18-4	1.3	19	500	0.0015	U	0.10	U	0.00060	U	0.00052	U	0.056	U	0.00068	U
trans-1,2-Dichloroethene	108-88-3	0.7	100	500	0.0023	U	0.16	U	0.00015	U	0.00013	U	0.014	U	0.00017	U
trans-1,3-Dichloropropene	156-60-5	0.19	100	500	0.0015	U	0.10	U	0.00030	U	0.00026	U	0.028	U	0.00034	U
trans-1,4-Dichloro-2-butene	10061-02-6	NS	NS	NS	0.0076	U	0.53	U	0.0016	U	0.0014	U	0.14	U	0.0018	U
Trichloroethene	79-01-6	0.47	21	200	1.1		0.29		0.00015	U	0.00013	U	0.014	U	0.00017	U
Trichlorofluoromethane	75-69-4	NS	NS	NS	0.0061	U	0.42	U	0.00077	U	0.00067	U	0.071	U	0.00087	U
Vinyl acetate	108-05-4	NS	NS	NS	0.015	U	1.0	U	0.0024	U	0.0021	U	0.22	U	0.0027	U
Vinyl chloride	75-01-4	0.02	0.9	13	0.0015	U	0.10	U	0.00037	U	0.00032	U	0.034	U	0.00042	U
Xylenes, Total	1330-20-7	0.26	100	500	0.0015	U	0.10	U	0.00032	U	0.00028	U	0.030	U	0.00036	U

Notes:
(1) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Unrestricted Use of Soil Cleanup Objective Table 375-6.8a 12/06
(2) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Restricted-Residential Use of Soil Cleanup Objective Table 375-6.8b 12/06 and CP-51 Table 1 10/10.
(3) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Commercial Use of Soil Cleanup Objective Table 375-6.8b 12/06 and CP-51 Table 1 10/10.
NS - No Standard
U - The analyte was analyzed for, but was not detected above the reported sample quantification limit.
J - The analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.
Highlighted text denotes concentrations exceeding NYSDEC Unrestricted Use SCO
Highlighted text denotes concentrations exceeding NYSDEC Restricted Residential Use SCO
Highlighted text denotes concentrations exceeding NYSDEC Commercial Use SCO

Table 2
Soil Sample Analytical Data Summary
Semivolatile Organic Compounds
2465 Atlantic Ave 45 Van Sinderen Ave, Brooklyn, NY

Client Sample ID:	CAS Number	NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives (1)	NYSDEC Part 375 Restricted Residential Soil Cleanup Objectives (2)	NYSDEC Part 375 Commercial Soil Cleanup Objectives (3)	SB001-B	SB002-B	SB003-B		SB004-B	
Sample Location					Basement	Basement	Ground Surface		Ground Surface	
Sample Depth:					0-2'	0-2'	0-2'	12-14'	0-2'	13-15'
Laboratory ID:					L2420537-01	L2420537-02	L2420803-01	L2420803-02	L2420803-03	L2420803-04
Sampling Date:					4/15/2024	4/15/2024	4/16/2024	4/16/2024	4/16/2024	4/16/2024
Semi-Volatile Organic Compounds by USEPA method 8270 in mg/kg										
1,1-Biphenyl	92-52-4	NS	NS	NS	0.42 U	0.03 J	0.024 U	0.022 U	0.025 U	0.023 U
1,2,4,5-Tetrachlorobenzene	95-94-3	NS	NS	NS	0.18 U	0.19 U	0.020 U	0.017 U	0.020 U	0.018 U
1,2,4-Trichlorobenzene	120-82-1	NS	NS	NS	NA	0.19 U	0.022 U	0.019 U	0.022 U	0.020 U
1,2-Dichlorobenzene	95-50-1	1.1	100	500	NA	0.19 U	0.034 U	0.030 U	0.034 U	0.032 U
1,3-Dichlorobenzene	541-73-1	2.4	49	280	NA	0.19 U	0.032 U	0.029 U	0.033 U	0.030 U
1,4-Dichlorobenzene	106-46-7	1.8	13	130	NA	0.19 U	0.033 U	0.029 U	0.034 U	0.031 U
1,4-Dioxane	123-91-1	0.1	13	130	0.027 U	0.028 U	0.0086 U	0.0077 U	0.0088 U	0.0081 U
2,4,5-Trichlorophenol	95-95-4	NS	NS	NS	0.18 U	0.19 U	0.036 U	0.032 U	0.037 U	0.034 U
2,4,6-Trichlorophenol	88-06-2	NS	NS	NS	0.11 U	0.11 U	0.036 U	0.032 U	0.036 U	0.033 U
2,4-Dichlorophenol	120-83-2	NS	NS	NS	0.16 U	0.17 U	0.030 U	0.027 U	0.031 U	0.028 U
2,4-Dimethylphenol	105-67-9	NS	NS	NS	0.18 U	0.19 U	0.062 U	0.055 U	0.063 U	0.058 U
2,4-Dinitrophenol	51-28-5	NS	NS	NS	0.88 U	0.90 U	0.088 U	0.078 U	0.089 U	0.082 U
2,4-Dinitrotoluene	121-14-2	NS	NS	NS	0.18 U	0.19 U	0.038 U	0.034 U	0.038 U	0.035 U
2,6-Dinitrotoluene	606-20-2	NS	NS	NS	0.18 U	0.19 U	0.032 U	0.029 U	0.033 U	0.030 U
2-Chloronaphthalene	91-58-7	NS	NS	NS	0.18 U	0.19 U	0.019 U	0.017 U	0.019 U	0.018 U
2-Chlorophenol	95-57-8	NS	NS	NS	0.18 U	0.19 U	0.022 U	0.020 U	0.023 U	0.021 U
2-Methylnaphthalene	91-57-6	NS	NS	NS	0.22 U	0.10 J	0.023 U	0.020 U	0.063 J	0.021 U
2-Methylphenol	95-48-7	0.33	100	500	0.18 U	0.19 U	0.029 U	0.026 U	0.030 U	0.027 U
2-Nitroaniline	88-74-4	NS	NS	NS	0.18 U	0.19 U	0.036 U	0.032 U	0.037 U	0.034 U
2-Nitrophenol	88-75-5	NS	NS	NS	0.39 U	0.41 U	0.071 U	0.063 U	0.072 U	0.066 U
3- & 4-Methylphenols	65794-96-9	0.33	100	500	0.18 U	0.19 U	0.029 U	0.026 U	0.050 J	0.028 U
3,3-Dichlorobenzidine	91-94-1	NS	NS	NS	0.26 U	0.27 U	0.050 U	0.044 U	0.051 U	0.047 U
3-Nitroaniline	99-09-2	NS	NS	NS	0.18 U	0.19 U	0.035 U	0.032 U	0.036 U	0.033 U
4,6-Dinitro-2-methylphenol	534-52-1	NS	NS	NS	0.48 U	0.49 U	0.090 U	0.080 U	0.092 U	0.085 U
4-Bromophenyl phenyl ether	101-55-3	NS	NS	NS	0.18 U	0.19 U	0.029 U	0.026 U	0.029 U	0.027 U
4-Chloroaniline	106-47-8	NS	NS	NS	0.18 U	0.19 U	0.034 U	0.030 U	0.035 U	0.032 U
4-Chlorophenyl phenyl ether	7005-72-3	NS	NS	NS	0.18 U	0.19 U	0.020 U	0.018 U	0.020 U	0.019 U
4-Nitroaniline	100-01-6	NS	NS	NS	0.18 U	0.19 U	0.078 U	0.069 U	0.079 U	0.073 U
4-Nitrophenol	100-02-7	NS	NS	NS	0.26 U	0.26 U	0.077 U	0.068 U	0.078 U	0.072 U
Acenaphthene	83-32-9	20	100	500	0.15 U	0.28	0.027 J	0.017 U	0.120 J	0.018 U
Acenaphthylene	208-96-8	100	100	500	0.15 U	0.61	0.078 J	0.026 U	0.17	0.027 U
Acetophenone	98-86-2	NS	NS	NS	0.18 U	0.04 J	0.023 U	0.021 U	0.024 U	0.022 U
Anthracene	120-12-7	100	100	500	0.11 U	1.1	0.11	0.033 U	0.42	0.034 U
Benzo(a)anthracene	56-55-3	1	1	5.6	0.11 U	7.0	0.36	0.019 U	1.6	0.020 U
Benzo(a)pyrene	50-32-8	1	1	1	0.15 U	8.5	0.26	0.041 U	1.4	0.043 U
Benzo(b)fluoranthene	205-99-2	1	1	5.6	0.11 U	9.8	0.39	0.028 U	1.9	0.030 U
Benzo(g,h,i)perylene	191-24-2	100	100	500	0.15 U	4.6	0.21	0.020 U	1.0	0.021 U
Benzo(k)fluoranthene	207-08-9	0.8	3.9	56	0.11 U	2.0	0.11	0.027 U	0.55	0.028 U
Benzoic acid	65-85-0	NS	NS	NS	0.59 U	0.61 U	0.19 U	0.17 U	0.19 U	0.180 U
Benzyl alcohol	100-51-6	NS	NS	NS	0.18 U	0.19 U	0.058 U	0.051 U	0.059 U	0.054 U
Bis(2-chloroethoxy)methane	111-91-1	NS	NS	NS	0.20 U	0.20 U	0.019 U	0.017 U	0.019 U	0.018 U
Bis(2-chloroethyl)ether	111-44-4	NS	NS	NS	0.16 U	0.17 U	0.026 U	0.023 U	0.026 U	0.024 U
Bis(2-chloroisopropyl)ether	108-60-1	NS	NS	NS	0.22 U	0.23 U	0.032 U	0.029 U	0.033 U	0.030 U
Bis(2-ethylhexyl)phthalate	117-81-7	NS	NS	NS	0.18 U	0.26	0.065 U	0.058 U	2.8	0.061 U
Butyl benzyl phthalate	85-68-7	NS	NS	NS	0.18 U	0.19 U	0.047 U	0.042 U	0.048 U	0.044 U
Carbazole	86-74-8	NS	NS	NS	0.18 U	0.22	0.053 J	0.016 U	0.180 J	0.017 U
Chrysene	218-01-9	1	3.9	56	0.11 U	7.0	0.37	0.017 U	1.6	0.018 U
Dibenzo(a,h)anthracene	53-70-3	0.33	0.33	0.56	0.11 U	1.5	0.036 U	0.032 U	0.036 U	0.033 U
Dibenzofuran	132-64-9	7	59	350	0.18 U	0.12 J	0.064 U	0.057 U	0.065 U	0.060 U
Diethyl phthalate	84-66-2	NS	NS	NS	0.18 U	0.19 U	0.053 J	0.019 U	0.22	0.020 U
Dimethyl phthalate	131-11-3	NS	NS	NS	0.18 U	0.19 U	0.034 J	0.016 U	0.098 J	0.017 U
Di-n-butyl phthalate	84-74-2	NS	NS	NS	0.18 U	0.19 U	0.017 U	0.016 U	0.018 U	0.016 U
Di-n-octyl phthalate	117-84-0	NS	NS	NS	0.18 U	0.19 U	0.040 U	0.035 U	0.040 U	0.037 U
Fluoranthene	206-44-0	100	100	500	0.026 J	12	0.76	0.019 U	3.0	0.020 U
Fluorene	86-73-7	30	100	500	0.18 U	0.22	0.033 J	0.016 U	0.11 J	0.017 U
Hexachlorobenzene	118-74-1	0.33	1.2	6	0.11 U	0.11 U	0.021 U	0.019 U	0.022 U	0.020 U
Hexachlorobutadiene	87-68-3	NS	NS	NS	0.18 U	0.19 U	0.028 U	0.024 U	0.028 U	0.026 U
Hexachlorocyclopentadiene	77-47-4	NS	NS	NS	0.52 U	0.54 U	0.17 U	0.150 U	0.17 U	0.16 U
Hexachloroethane	67-72-1	NS	NS	NS	0.15 U	0.15 U	0.030 U	0.027 U	0.031 U	0.028 U
Indeno(1,2,3-cd)pyrene	193-39-5	0.5	0.5	5.6	0.15 U	3.8	0.19	0.023 U	0.95	0.025 U
Isophorone	78-59-1	NS	NS	NS	0.16 U	0.17 U	0.024 U	0.022 U	0.025 U	0.023 U
Naphthalene	91-20-3	12	100	500	0.18 U	0.22	0.048 J	0.020 U	0.15 J	0.022 U
NDPA/DPA	86-30-6	NS	NS	NS	0.15 U	0.15 U	0.021 U	0.019 U	0.022 U	0.020 U
Nitrobenzene	98-95-3	NS	NS	NS	0.16 U	0.17 U	0.028 U	0.025 U	0.028 U	0.026 U
N-nitroso-di-n-propylamine	621-64-7	NS	NS	NS	0.18 U	0.19 U	0.029 U	0.026 U	0.030 U	0.027 U
p-Chloro-m-cresol	59-50-7	NS	NS	NS	0.18 U	0.19 U	0.028 U	0.025 U	0.029 U	0.026 U
Pentachlorophenol	87-86-5	0.8	6.7	6.7	0.15 U	0.15 U	0.041 U	0.037 U	0.042 U	0.039 U
Phenanthrene	85-01-8	100	100	500	0.03 J	3.9	0.43	0.020 U	1.6	0.021 U
Phenol	108-95-2	0.33	100	100	0.18 U	0.19 U	0.028 U	0.025 U	0.040 J	0.027 U
Pyrene	129-00-0	100	100	500	0.024 J	16	0.65	0.017 U	2.6	0.018 U

Notes:
(1) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Unrestricted Use of Soil Cleanup Objective Table 375-6.8a 12/06
(2) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Restricted-Residential Use of Soil Cleanup Objective Table 375-6.8b 12/06 and CP-51 Table 1 10/10.
(3) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Commercial Use of Soil Cleanup Objective Table 375-6.8b 12/06 and CP-51 Table 1 10/10.
NA - Not Analyzed
NS - No Standard
U - The analyte was analyzed for, but was not detected above the reported sample quantification limit.
J - The analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.
Highlighted text denotes concentrations exceeding NYSDEC Unrestricted Use SCO
Highlighted text denotes concentrations exceeding NYSDEC Restricted-Residential Use SCO
Highlighted text denotes concentrations exceeding NYSDEC Commercial Use SCO

Table 3
Soil Sample Analytical Data Summary
Total Metals
2465 Atlantic Ave 45 Van Sinderen Ave, Brooklyn, NY

Client Sample ID:	CAS Number	NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives (1)	NYSDEC Part 375 Restricted Residential Soil Cleanup Objectives (2)	NYSDEC Part 375 Commercial Soil Cleanup Objectives (3)	SB001-B	SB002-B	SB003-B		SB004-B	
Sample Location					Basement	Basement	Ground Surface		Ground Surface	
Sample Depth:					0-2'	0-2'	0-2'	12-14'	0-2'	13-15'
Laboratory ID:					L2420541-01	L2420541-03	L2420803-01	L2420803-02	L2420803-03	L2420803-04
Sampling Date:					4/15/2024	4/15/2024	4/16/2024	4/16/2024	4/16/2024	4/16/2024
Total Metals by USEPA Method 6010 in mg/kg										
Aluminum	7429-90-5	NS	NS	NS	5,650	2,860	5,780	6,010	3,330	6,410
Antimony	7440-36-0	NS	NS	NS	0.426 J	4.53 U	0.331 U	0.604 U	1.45 J	0.769 U
Arsenic	7440-38-2	13	16	16	2.88	4.14	25.8	5.02	6.99	6.08
Barium	7440-39-3	350	400	400	49.8	56.7	168	43.0	218	71.7
Beryllium	7440-41-7	7.2	72	590	0.270 J	0.139 J	0.364 J	0.449 J	0.265 J	0.635 J
Cadmium	7440-43-9	2.5	4.3	9.3	0.18 J	0.240 J	1.11	0.988 J	1.29	1.69 J
Calcium	7440-70-2	NS	NS	NS	21,000	19,400	5,830	1,090	13,900	879
Chromium	7440-47-3	NS	NS	NS	10.8	231	357	174	51.1	13.6
Cobalt	7440-48-4	NS	NS	NS	3.71	3.43	4.59	8.86	6.66	7.81
Copper	7440-50-8	50	270	270	311	35.4	56.6	25.3	414	29.2
Iron	7439-89-6	NS	NS	NS	7,950	7,100	10,000	52,400	13,000	77,600
Lead	7439-92-1	63	400	1,000	65.7	207	598	5.64 J	828	6.68 J
Magnesium	7439-95-4	NS	NS	NS	1,610	1,180	1,220	1,990	6,480	1,780
Manganese	7439-96-5	1,600	2,000	10,000	183	82.7	223	1,320	197	1,670
Nickel	7440-02-0	30	310	310	9.93	8.81	7.81	17.3	21.5	12.8
Potassium	7440-09-7	NS	NS	NS	906	496	321	644	364	766
Selenium	7782-49-2	3.9	180	1,500	0.901 J	0.904 J	0.578 J	0.410 U	0.500 J	0.522 U
Silver	7440-22-4	2	180	1,500	0.428 U	0.484	0.289 J	0.450 U	1.63	0.572 U
Sodium	7440-23-5	NS	NS	NS	204	225	110 J	168 J	218	104 J
Thallium	7440-28-0	NS	NS	NS	1.06 J	0.697 J	0.347 J	0.501 U	0.326 J	1.06 J
Vanadium	7440-62-2	NS	NS	NS	14.0	12.5	19.1	27.9	28.1	29.4
Zinc	7440-66-6	109	10,000	10,000	218	130	144	29.4	371	43.4
Total Mercury by USEPA Method 7471 in mg/kg										
Mercury	7439-97-6	0.18	0.81	2.8	0.193	0.373	1.13	0.0420 U	0.389	0.0440 U

Notes:

(1) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Unrestricted Use of Soil Cleanup Objective Table 375-6.8a 12/06

(2) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Restricted-Residential Use of Soil Cleanup Objective Table 375-6.8b 12/06.

(3) NYSDEC 6 NYCRR Environmental Remediation Programs Part 375 Commercial Use of Soil Cleanup Objective Table 375-6.8b 12/06 and CP-51 Table 1 10/10.

NS - No Standard

U - The analyte was analyzed for, but was not detected above the reported sample quantification limit.

J - The analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.

Highlighted text denotes concentrations exceeding NYSDEC Unrestricted Use SCO

Highlighted text denotes concentrations exceeding NYSDEC Restricted-Residential Use SCO

Highlighted text denotes concentrations exceeding NYSDEC Commercial Use SCO

Table 4
Soil Vapor Sample Analytical Data Summary
Volatile Organic Compounds
2465Atlantic Ave 45 Van Sinderen Ave, Bronx, NY

Client Sample ID: Sample Type: Sample Depth: Laboratory ID: Sampling Date:	CAS Number	SS001-B Sub-SlabSoil Vapor 2" L2420834-01 4/15/20240		SV001-B Soil Vapor 5' L2420834-02 4/16/2024	
Volatile Organic Compounds by USEPA Method TO-15 in µg/m³					
1,1,1-Trichloroethane	71-55-6	3.03	U	1.09	U
1,1,2,2-Tetrachloroethane	79-34-5	3.82	U	1.37	U
1,1,2-Trichloroethane	79-00-5	3.03	U	1.09	U
1,1-Dichloroethane	75-34-3	2.25	U	0.809	U
1,1-Dichloroethene	75-35-4	2.20	U	0.793	U
1,2,4-Trichlorobenzene	120-82-1	4.13	U	1.48	U
1,2,4-Trimethylbenzene	95-63-6	19.4		18.8	
1,2-Dibromoethane	106-93-4	4.27	U	1.54	U
1,2-Dichlorobenzene	95-50-1	3.34	U	1.20	U
1,2-Dichloroethane	107-06-2	2.25	U	0.809	U
1,2-Dichloropropane	78-87-5	2.57	U	0.924	U
1,3,5-Trimethylbenzene	108-67-8	5.31		5.16	
1,3-Butadiene	106-99-0	1.23	U	10.6	
1,3-Dichlorobenzene	541-73-1	3.34	U	1.20	U
1,4-Dichlorobenzene	106-46-7	3.34	U	1.20	U
1,4-Dioxane	123-91-1	2.00	U	0.721	U
2,2,4-Trimethylpentane	540-84-1	2.60	U	0.934	U
2-Butanone	78-93-3	19.3		75.8	
2-Hexanone	591-78-6	3.87		19.8	
3-Chloropropene	107-05-1	1.74	U	0.626	U
4-Ethyltoluene	622-96-8	3.17		2.25	
4-Methyl-2-pentanone	108-10-1	5.70	U	4.63	
Acetone	67-64-1	558		649	
Benzene	71-43-2	1.78	U	2.92	
Benzyl chloride	100-44-7	2.88	U	1.04	U
Bromodichloromethane	75-27-4	3.72	U	1.34	U
Bromoform	75-25-2	5.75	U	2.07	U
Bromomethane	74-83-9	2.16	U	0.777	U
Carbon disulfide	75-15-0	5.79		5.33	
Carbon tetrachloride	56-23-5	3.50	U	1.26	U
Chlorobenzene	108-90-7	2.56	U	0.921	U
Chloroethane	75-00-3	1.47	U	0.528	U
Chloroform	67-66-3	9.38		0.977	U
Chloromethane	74-87-3	1.15	U	2.87	
cis-1,2-Dichloroethene	156-59-2	61.9		0.793	U
cis-1,3-Dichloropropene	10061-01-5	2.52	U	0.908	U
Cyclohexane	110-82-7	1.91	U	20.3	
Dibromochloromethane	124-48-1	4.74	U	1.70	U
Dichlorodifluoromethane	75-71-8	2.75	U	2.26	
Ethanol	64-17-5	26.2	U	36.7	
Ethyl Acetate	141-78-6	5.01	U	1.80	U
Ethylbenzene	100-41-4	3.09		4.52	
Freon-113	76-13-1	4.26	U	1.53	U
Freon-114	76-14-2	3.89	U	1.40	U
Heptane	142-82-5	2.43		38.8	
Hexachlorobutadiene	87-68-3	5.93	U	2.13	U
Isopropanol	67-63-0	9.73		3.47	
Methyl tert butyl ether	1634-04-4	2.00	U	0.721	U
Methylene chloride	75-09-2	4.83	U	1.74	U
Naphthalene	91-20-3	2.92	U	1.52	
n-Hexane	110-54-3	1.96	U	50.8	
o-Xylene	95-47-6	8.34		11.6	
p/m-Xylene	179601-23-1	14.4		18.9	
Styrene	100-42-5	2.37	U	0.852	U
Tertiary butyl Alcohol	75-65-0	4.21	U	13.6	
Tetrachloroethene	127-18-4	1,440		23.1	
Tetrahydrofuran	109-99-9	4.10	U	55.7	
Toluene	108-88-3	17.6		18.2	
trans-1,2-Dichloroethene	156-60-5	2.20	U	0.793	U
trans-1,3-Dichloropropene	10061-02-6	2.52	U	0.908	U
Trichloroethene	79-01-6	111		1.07	U
Trichlorofluoromethane	75-69-4	3.12	U	1.12	U
Vinyl bromide	593-60-2	2.43	U	0.874	U
Vinyl chloride	75-01-4	1.42	U	0.511	U

Notes:

U - The compound was not detected at the indicated concentration.

J - Data indicates the presence of a compound that meets the identification criteria. The result is less than the quantitation limit but greater than MDL.

Table 5
Soil Vapor Matrices Summary
Volatile Organic Compounds
2465 Atlantic Ave 45 Van Sinderen Ave, Brooklyn, NY

Sample Date	Location	Compound	Sub-Slab Soil Vapor Concentrations (ug/m3)	Indoor Air Soil Concentrations (ug/m3)	Minimum Sub-Slab Concentration Recommended for Mitigation (ug/m3)[1]	Guidance Recommendation[(1)]	Recommended Action Based on NYSDOH Guidance
4/17/2024	Southern Portion of Property, Down Gradient, Basement of 2465 Atlantic Ave, Sub-slab soil vapor (SS001-B)	1,1,1-TCA	ND	NS	100	No Further Action	Mitigate
		1,1-DCE	ND	NS	6	No Further Action	
		Carbon tetrachloride	ND	NS	6	No Further Action	
		cis-1,2-DCE	61.9	NS	6	Mitigate	
		Methylene chloride	ND	NS	100	No Further Action	
		PCE	1440	NS	100	Mitigate	
		TCE	111	NS	6	Mitigate	
		Vinyl chloride	ND	NS	6	No Further Action	
		Benzene	ND	NS	60	No Further Action	
		Ethylbenzene	3.09	NS	60	No Further Action	
		Napthalene	ND	NS	60	No Further Action	
		Cyclohexane	ND	NS	60	No Further Action	
		2,2,4-trimethylpentane	ND	NS	60	No Further Action	
		1,2,4-trimethylbenzene	19.4	NS	60	No Further Action	
		1,3,5-trimethylbenzene	5.31	NS	60	No Further Action	
		o-xylene	8.34	NS	60	No Further Action	
		p/m-xylene	18.9	NS	200	No Further Action	
		Heptane	2.43	NS	200	No Further Action	
		Hexane	ND	NS	200	No Further Action	
		Toluene	17.6	NS	300	No Further Action	
4/17/2024	Northwest Portion of Property, Up Gradient (SV001-B)	1,1,1-TCA	ND	NS	100	No Further Action	No Further Action
		1,1-DCE	ND	NS	6	No Further Action	
		Carbon tetrachloride	ND	NS	6	No Further Action	
		cis-1,2-DCE	ND	NS	6	No Further Action	
		Methylene chloride	ND	NS	100	No Further Action	
		PCE	23.1	NS	100	No Further Action	
		TCE	ND	NS	6	No Further Action	
		Vinyl chloride	ND	NS	6	No Further Action	
		Benzene	2.92	NS	60	No Further Action	
		Ethylbenzene	4.52	NS	60	No Further Action	
		Napthalene	1.52	NS	60	No Further Action	
		Cyclohexane	20.3	NS	60	No Further Action	
		2,2,4-trimethylpentane	ND	NS	60	No Further Action	
		1,2,4-trimethylbenzene	18.8	NS	60	No Further Action	
		1,3,5-trimethylbenzene	5.16	NS	60	No Further Action	
		o-xylene	11.6	NS	60	No Further Action	
		p/m-xylene	18.9	NS	200	No Further Action	
		Heptane	38.8	NS	200	No Further Action	
		Hexane	50.8	NS	200	No Further Action	
		Toluene	18.2	NS	300	No Further Action	

Notes:

1 -Action levels based on NYSDOH Matrix A for TCE, cis-1,2-DCE, 1,1-DCE and carbon tetrachloride, Matrix B for PCE, 1,1,1-TCA and methylene chloride, Matrix C for vinyl chloride, Matrix D for benzene, ethylbenzene, naphthalene, cyclohexane, 2,2,4-trimethylpentane, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and o-xylene, Matrix E for p/m xylene, heptane, and hexane, and Matrix F for toluene from "Guidance for Evaluating Soil Vapor Intrusion in the State of New York", NYSDOH, October 2006. (Revised February 2024)

ND - Not detected at the reported detection limit for the sample.

NS - Not sampled.

APPENDIX A

ADVANCED GEOLOGICAL SERVICES

Malvern, PA19355
(610) 722-5500 (ph.)
(610) 722-0250 (fax)

May 15, 2024

Jennifer Lewis
PW Grosser Consulting
630 Johnson Ave
Suite 7
315 S. Franklin St
Bohemia, New York

Subject: Geophysical Investigation Results
Broadway Junction Project
2465 Atlantic Ave & 45 Van Sinderen Ave

Dear Ms Jenifer Lewis

Advanced Geological Services (AGS) presents this letter report to PW Grosser Consulting (PWGC) of Bohemia, New York detailing the methods and results of the geophysical investigation conducted at 2465 Atlantic Ave & 45 Van Sinderen Ave, Brooklyn, New York. The objective of the geophysical investigation was to locate and identify potential underground storage tanks (USTs) and to "clear" several proposed drilling locations of potential utilities and other drilling obstructions. The field activities for this geophysical investigation were completed by AGS on March 15 2024.

Methods

The ground penetrating radar (GPR), Electromagnetic (EM), radio frequency (RF), and metal detection (MD) methods were utilized for this geophysical investigation. To search for the potential USTs AGS collected EM data in a grid like formation as space permitted to maximize data coverage. Many large obstructions were present at this location which prohibited covering the entire survey area. AGS utilized a GPS instrument to locate each EM data point. The EM data was downloaded and contoured in the field and analyzed for potential USTs. Additional GPR profiles were collected across each area with an elevated EM response.

AGS was unable to enter more than 4 feet into the alleyway between the two buildings due to the presence of debris and obstructions. Due to the debris and obstructions no geophysical data was collated further into the alleyway.

AGS scanned the each proposed drilling location with the RF instrument looking for potentially active electric lines. Each location was further scanned with the MD instrument to locate potential metallic anomalies that could be associated with utilities or other buried metallic obstructions. GPR profiles were collected in a grid like pattern centered at the proposed drilling location, looking for potential utilities.

Ground Penetrating Radar (GPR) Method

The ground penetrating radar (GPR) method was used to locate and identify potential utilities and other buried features. The GPR method is based upon the transmission of repetitive, radio frequency electromagnetic (EM) pulses into the subsurface. When the transmitted energy of down going wave contacts an interface of dissimilar electrical character, part of the energy is returned to the surface in the form of a reflected signal. This reflected signal is detected by a receiving transducer and is displayed on the screen of the GPR unit as well as being recorded on the internal hard-drive. The received GPR response remains constant as long as the electrical contrast between media is present and constant. Lateral or vertical changes in the electrical properties of the subsurface result in equivalent changes in the GPR responses. The system records a continuous image of the subsurface by plotting two way travel time of the reflected EM pulse versus distance traveled along the ground surface. Two way travel time values are then converted to depth using known soil velocity functions.

The GPR field procedures involved (1) instrument calibration, (2) test run completion, (3) production profile collection and recording, and (4) data storage for subsequent processing and analysis in the office. Each radar profile was examined for characteristic GPR signatures that may indicate the presence of buried targets. A Geophysical Survey System SIR System 3000 and a 400 megahertz (MHz) antenna were used with a recording window of 60 nanoseconds (ns) to provide the required depth penetration and subsurface detail.

Radio Frequency (RF) Utility Locating Method

A Radiodetection RD400/PDL2 multi-frequency RF utility locating system was used for this project to locate potential electric lines and other surficially identifiable utilities and/or features. This instrument consists of a receiver/tracer and a remote transmitter, which

operates at frequencies ranging between 8 kHz and 65 kHz. In addition, the receiver can be used in 60 Hz passive mode to identify active buried electrical lines. This utility tracing instrument provides audible and visual feedback to the operator when a utility that is coupled with the transmitted signal is crossed. The transmitter produces a radio-frequency signal in the utility to be traced by either induction coupling or direct hook-up. The receiver output provides measured field strength of the received signal and varies an audible pitch depending upon how far the utility is from the receiver. By carefully adjusting the gain of the receiver it is possible to determine the location of the utility and to separate it from adjacent utilities.

Hand Held Metal Detection (MD) Method

The survey area and each proposed drilling location was scanned using a hand held metal detection (MD) instrument. This method uses the principle of electromagnetic induction to detect shallow buried metal objects such as USTs, metal utility conduits, rebar in concrete, manhole covers, and various metallic debris. This is done by carrying a hand-held radio transmitter-receiver unit above the ground and continuously scanning the surface. A primary coil broadcasts a radio signal from a transmitter. This primary radio signal induces secondary electrical currents in metal objects. These secondary currents in turn produce a magnetic field which is detected by the receiver.

The MD instrument used for this investigation was a Fisher TW-6 pipe and cable locater. This instrument is expressly designed to detect metallic pipes, cables, USTs, manhole covers, and other buried metallic objects. The instrument produces an audible response and significant meter deflections when near a metal object. The peak instrument response usually occurs when the unit is directly over the object.

Time Domain EM Metal Detection Method (EM61)

Time domain EM metal detection data were collected using a Geonics EM61 instrument. This instrument generates a pulsed primary EM field into the earth, which induces eddy currents in nearby metallic objects. The eddy current decay produces a secondary magnetic field which is measured by the receiver coil. By taking measurements at a relatively long time after the start of the decay, the current induced in the ground has fully dissipated and only the current in the metal is still producing a secondary field. In scanning mode, the instrument produces an audible response indicating the presence of buried metal beneath the antenna, as well as providing a

digital read-out of the response magnitude. The response, which is measured in millivolts (mV), can also be recorded by the integrated data logger. The instrument uses two antenna coils separated by 0.5 meters (1.6 feet) to provide potential depth information, and to both minimize and quantify effects from above ground metallic objects. This instrument is very sensitive to metal objects, but relatively insensitive to variations in soil conductivity and geologic features. The standard EM61 configuration used during this investigation is capable of detecting metal targets the size of a 55-gallon drum up to depths of 10 feet or more depending upon site conditions.

Results

AGS has included one figure (Figure 1) showing contoured EM results. The aerial photograph was taken in 2022 and was downloaded from https://data.gis.ny.gov/. All locations on Figure 1 are in the New York Long Island NAD83 state plane coordinate system with all units in feet.

No USTs were identified on either the EM or GPR data sets. AGS identified several small areas with elevated EM response. AGS collected GPR profiles across each identified EM anomaly. The small areas with elevated EM response appeared to be small buried metallic debris that did not have the size or shape typical of an UST. Furthermore, there were no additional areas with an elevated EM response that was on the contoured EM diagram that are typical of USTs.

Only a portion of the survey area was able to be surveyed with the EM instrument. Numerous obstructions prohibited the collection of geophysical data. AGS cannot make any determination on the presence or absence of USTs in areas that were not accessible to AGS for this investigation.

Furthermore, AGS "cleared" numerous proposed drilling locations. Each “cleared” proposed drilling location exhibited a reflection-free GPR signature and no RF or MD response. The final locations for each proposed drilling location was discussed and reviewed with the onsite representative.

Closing

AGS did not identify any USTs and "cleared" several proposed drilling locations. Upon completion of the geophysical investigation AGS reviewed the results with the onsite PWGC representative.

All geophysical data and field notes collected as a part of this investigation will be stored at the AGS office. The data collection and interpretation methods used in this investigation are consistent with standard practices applied to similar geophysical investigations. The correlation of geophysical responses with probable subsurface features is based on the past results of similar surveys although it is possible that some variation could exist at this site. Due to the nature of geophysical data, no guarantees can be made or implied regarding the presence or absence of additional objects or targets beyond those identified.

If you have any questions regarding the results of this field investigation, please contact me at 610-722-5500. It was a pleasure working with you on this project and we look forward to being able to provide you with sub-surface imaging services in the future.

Sincerely,
Prepared by



Christopher Call P.G.
Senior Geophysicist

Encl.: Figure 1: Contoured EM Response & Site Features



Legend

N
North

Scale
0 20 40 60 80 100
(feet)

EM Response
0 100 200 300 400 500 600 700 800
(mV)

Notes:

(1) AGS used a RF instrument, EM61 and a SIR 3000 GPR instrument with a 400MHz antenna for this investigation.
(2) EM data was collected with a line spacing of approximately 5 feet. The data was contoured and is shown above. AGS identified several locations with elevated EM responses, however upon further investigation with the GPR instrument these anomalies appear to be caused by small metallic objects. .
(3) AGS did not identify any USTs within the survey area. A large portion of the junkyard area was covered with obstructions and prohibited the collection of geophysical data across the entire area. Furthermore the entire alley way was full of obstructions that prohibited the use of the EM61 and GPR instruments.
(4) AGS identified several utilities within the survey area. Identified utilities were marked on the ground surface with spray paint.
(5) The aerial photograph was taken in 2022 and was downloaded from https://data.gis.ny.gov/.
(6) The field positions were not surveyed by a licensed surveyor and should be considered approximate.
(7) The items shown on this figure may not be all inclusive. AGS does not warrant the fact that additional buried features might be present at this site.

ADVANCED GEOLOGICAL SERVICES

FIGURE 1
Contoured EM Response,
Identified Utilities & Site Features

LOCATION: 2465 Atlantic Ave & 45 Van Sinderen Avet, Brooklyn, NY

CLIENT: PWGC

ADVANCED GEOLOGICAL SERVICES, INC.

DATE: May 15, 2024

DRAWN BY: C. Call

FIGURE 1

APPENDIX B

PROJECT #:	TOT2401		
SITE ADDRESS:	2465 Atlantic Ave & 45 Van Sinderen Ave		
BORING ID:	SB001-B	BORING DEPTH (FT): 2	CORE LENGTH (FT): 5
WELL ID:	N/A	BORING DIAMETER (IN): 2	WELL DIAMETER (IN): N/A
DRILLING CONTRACTOR:	Lakewood Environmental	DATE STARTED: 04/15/2024	DATE FINISHED: 04/15/2024
DRILLING METHOD:	Hand Auger	TIME STARTED: 14:00	TIME FINISHED: 14:28
DRILLING EQUIPMENT:	Hand Auger	LATITUDE: N/A	LONGITUDE: N/A
SAMPLING METHOD:	Grab/Composite	PROJECT MANAGER: Mike Pecoraro	LOGGED BY: Danielle Dulligan

DEPTH (feet)	SAMPLE INTERVAL	USCS KEY	RECOVERY (feet)	DESCRIPTION NAME (USCS): color, moist, plasticity, gravel, odor	PID Reading (ppm)	DEPTH (feet)	WELL CONSTRUCTION DETAILS AND/OR DRILLING REMARKS
0						0	
1			2	(FILL): Dark Brown; Fill; fine to medium grain with some fines and slight plasticity; dry and no odor	0	1	
2						2	

PROJECT #:	TOT2401		
SITE ADDRESS:	2465 Atlantic Ave & 45 Van Sinderen Ave		
BORING ID:	SB002-B	BORING DEPTH (FT): 2	CORE LENGTH (FT): 5
WELL ID:	N/A	BORING DIAMETER (IN): 2	WELL DIAMETER (IN): N/A
DRILLING CONTRACTOR:	Lakewood Environmental	DATE STARTED: 04/15/2024	DATE FINISHED: 04/15/2024
DRILLING METHOD:	Hand Auger	TIME STARTED: 14:35	TIME FINISHED: 15:03
DRILLING EQUIPMENT:	Hand Auger	LATITUDE: N/A	LONGITUDE: N/A
SAMPLING METHOD:	Grab/Composite	PROJECT MANAGER: Mike Pecoraro	LOGGED BY: Danielle Dulligan


DEPTH (feet)	SAMPLE INTERVAL	USCS KEY	RECOVERY (feet)	DESCRIPTION NAME (USCS): color, moist, plasticity, gravel, odor	PID Reading (ppm)	DEPTH (feet)	WELL CONSTRUCTION DETAILS AND/OR DRILLING REMARKS
0						0	
1			2	(FILL): Black; Fill; fine to medium grain with some fines and slight plasticity; dry and no odor	1.1	1	
2						2	

P.W. Grosser Consulting | **End of Boring Depth (feet):** 2 | **Water Table Symbol:** ▼ | Page 1 of 1

PROJECT #:	TOT2401
SITE ADDRESS:	2465 Atlantic Ave & 45 Van Sinderen Ave
BORING ID:	SB003-B
WELL ID:	N/A
DRILLING CONTRACTOR:	Lakewood Environmental
DRILLING METHOD:	Direct Push
DRILLING EQUIPMENT:	Geoprobe 6610
SAMPLING METHOD:	Grab/Composite

PWGC

BORING DEPTH (FT): 15	CORE LENGTH (FT): 5
BORING DIAMETER (IN): 2	WELL DIAMETER (IN): N/A
DATE STARTED: 04/16/2024	DATE FINISHED: 04/16/2024
TIME STARTED: 08:00	TIME FINISHED: 09:00
LATITUDE: N/A	LONGITUDE: N/A
PROJECT MANAGER: Mike Pecoraro	LOGGED BY: Danielle Dulligan



DEPTH (feet)	SAMPLE INTERVAL	USCS KEY	RECOVERY (feet)	DESCRIPTION NAME (USCS): color, moist, plasticity, gravel, odor	PID Reading (ppm)	DEPTH (feet)	WELL CONSTRUCTION DETAILS AND/OR DRILLING REMARKS
0–5			3	(FILL): Dark Brown; Fill; fine to medium grain with some fines and slight plasticity; dry and no odor	0	0–5	
5–6				(FILL): Brown; Fill; fine to medium grain with some fines and slight plasticity; red brick; some gravel (0.5" diameter); dry and no odor	0.1	5–6	
6–10			3.25	(FILL): Brown to Orange; Fill; fine to medium grain with some fines; red brick; some gravel (0.5" diameter); dry and no odor	0	6–10	
10–12			5	(FILL): White; Fill; concrete; some gravel (0.5" diameter); dry and no odor.	0	10–12	
12–15				(FILL): Brown to White; Fill; fine to coarse grain with some fines; some gravel (0.5" to 1" diameter); dry and no odor.	0	12–15	

PROJECT #:	TOT2401
SITE ADDRESS:	2465 Atlantic Ave & 45 Van Sinderen Ave
BORING ID:	SB004-B
WELL ID:	N/A
DRILLING CONTRACTOR:	Lakewood Environmental
DRILLING METHOD:	Direct Push
DRILLING EQUIPMENT:	Geoprobe 6610
SAMPLING METHOD:	Grab/Composite

PWGC

BORING DEPTH (FT): 15	CORE LENGTH (FT): 5
BORING DIAMETER (IN): 2	WELL DIAMETER (IN): N/A
DATE STARTED: 04/16/2024	DATE FINISHED: 04/16/2024
TIME STARTED: 09:30	TIME FINISHED: 10:20
LATITUDE: N/A	LONGITUDE: N/A
PROJECT MANAGER: Mike Pecoraro	LOGGED BY: Danielle Dulligan

DEPTH (feet)	SAMPLE INTERVAL	USCS KEY	RECOVERY (feet)	DESCRIPTION NAME (USCS): color, moist, plasticity, gravel, odor	PID Reading (ppm)
0–5			4	(FILL): Black; Fill; fine to medium grain with some fines and slight plasticity; dry and no odor	0
5–10			3.5	(FILL): Brown to Orange; Fill; fine to medium grain with some fines; red brick; some gravel (0.5" diameter); dry and no odor	0.1 1.3
10–15			4	(FILL): White; Fill; concrete; some gravel (0.5" diameter); dry and no odor. (FILL): Brown to White; Fill; fine to coarse grain with some fines; red brick; some gravel (0.5" to 1" diameter); dry and no odor.	0 0.1

WELL CONSTRUCTION DETAILS AND/OR DRILLING REMARKS

APPENDIX G
RADIUS MAP REPORT

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207

Inquiry Number: 7931531.2s
March 19, 2025

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	1169
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

COORDINATES

Latitude (North):	40.6765390 - 40° 40' 35.54''
Longitude (West):	73.9031160 - 73° 54' 11.21''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	592702.5
UTM Y (Meters):	4503218.0
Elevation:	70 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20190830
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1		45 VAN SINDEREN AVEN	NY NYC LAND USE		TP
Reg	WOLFF-ALPORT CHEMICA	1125-1139 IRVING AVE	NPL, SEMS, US ENG CONTROLS, PRP	Same	5071, 0.960, North
A2	CON EDISON MANHOLE:	2473 ATLANTIC AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	47, 0.009, South
A3	NOBLE SIGNS	2465 ATLANTIC AVE	E MANIFEST	Lower	47, 0.009, SSW
A4	APEX AIRTRONICS INC	2465 ATLANTIC AVE	NY AST	Lower	47, 0.009, SSW
A5	FACTORY	2465 ATLANTIC AVE	NY Spills	Lower	47, 0.009, SSW
A6	APEX AIRTRONICS INC-	2465 ATLANTIC AVENUE	RCRA NonGen / NLR, ICIS, US AIRS, FINDS, ECHO, NY...	Lower	47, 0.009, SSW
A7	NYCDEP	30 WILLIAMS PL	NY MANIFEST	Lower	95, 0.018, ENE
A8	ARIES AUTOWORLD LTD	2471 ATLANTIC AVE	NY SWF/LF	Lower	107, 0.020, SSW
A9	APEX AIRTRONICS INC-		PFAS ECHO	Lower	125, 0.024, SSW
A10	NYCTA - ATLANTIC AVE	ATLANTIC AVE & VAN S	RCRA-VSQG, NY MANIFEST, NJ MANIFEST	Lower	128, 0.024, SSW
A11	CON EDISON HTV5519	VAN SIDEREN & ATLANT	RCRA NonGen / NLR	Lower	128, 0.024, SSW
A12	CON EDISON	HERKIMER 60 FEET E O	RCRA NonGen / NLR, NY MANIFEST	Higher	130, 0.025, NNW
A13	CONSOLIDATED EDISON	HERKIMER ST & VAN SI	NY MANIFEST	Higher	131, 0.025, NNW
A14	CON EDISON MANHOLE 6	HERKIMER ST & VAN SI	RCRA NonGen / NLR	Higher	131, 0.025, NNW
A15	CONSOLIDATED EDISON	HERKIMER ST & VAN SI	NY MANIFEST	Higher	135, 0.026, NNW
A16	MANHOLE 66367	WILLIAMS AVE+LAVONIA	NY Spills	Lower	141, 0.027, SE
A17	CON EDISON	90 WILLIAMS ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	159, 0.030, SE
A18	HERKIMER ST AND BROA	HERKIMER ST AND BROA	NY Spills	Higher	165, 0.031, NE
A19	NYCT HERKIMER STREET	HERKIMER & WILLIAMS	RCRA NonGen / NLR, NY MANIFEST	Higher	176, 0.033, NE
A20	NYC TRANSIT CPM ENV-	WILLIAMS PL & HERKIM	NY MANIFEST	Higher	177, 0.034, NE
A21	CON ED - MH 3629	HERKIMER ST & WILLIA	RCRA NonGen / NLR, NY MANIFEST	Higher	177, 0.034, NE
A22	NYCDOT BRIDGE BIN 22	ATLANTIC AVE OVER LI	RCRA NonGen / NLR	Higher	206, 0.039, West
B23	CON EDISON	NEW YORK AVE & ATLAN	NY MANIFEST	Lower	220, 0.042, SSW
B24	CON EDISON SERVICE B	NEW YORK AVE & ATLAN	RCRA NonGen / NLR	Lower	220, 0.042, SSW
C25	CON EDISON SERVICE B	63 WILLIAMS PL	RCRA NonGen / NLR, NY MANIFEST	Higher	231, 0.044, NE
D26	WROUGHT ORIGINALS IN	38 VAN SINDERIN AVE	NY TANKS	Higher	273, 0.052, NNW
D27	SPILL NUMBER 0206144	38 VAN SINDEREN AVE	NY LTANKS	Higher	273, 0.052, NNW
D28	SPILL NUMBER 0007586	1 HAVENS PL	NY Spills	Higher	288, 0.055, NW
E29	SPILL NUMBER 0007769	HAVEL PLACE & ATLANT	NY Spills	Lower	294, 0.056, WSW
D30	LOT 16,TAXBLOCK 1554	1495 HERKIMER STREET	NY E DESIGNATION, NY NYC LAND USE	Higher	298, 0.056, NW
E31	NYCTA - 30 HAVENS PL	30 HAVENS PL	NY Spills, RCRA NonGen / NLR, FINDS, ECHO, NY...	Higher	302, 0.057, WNW
E32	LOT 23,TAXBLOCK 1574	30 HAVENS PLACE	NY E DESIGNATION, NY NYC LAND USE	Higher	302, 0.057, WNW
E33	NYC TRANSIT PARKING	HAVENS PLACE AND ATL	NY Spills	Lower	305, 0.058, WSW
E34	CON EDISON	ATLANTIC AVE & HAVEN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	305, 0.058, WSW
C35	2440 FULTON STREET	2440 FULTON STREET	NY VCP, NY NYC OER	Higher	350, 0.066, NNE
C36	2440 FULTON STREET	2440 FULTON STREET	NY AST	Higher	350, 0.066, NNE
B37	LOT 23,TAXBLOCK 1437	ATLANTIC AVENUE	NY E DESIGNATION	Lower	351, 0.066, SW
C38	DRUM RUN	WILLIAMS PLACE AND F	NY Spills	Higher	360, 0.068, NNE

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B39	EAST NY SUMP STATION	1762 EAST NEW YORK A	NY Spills	Lower	391, 0.074, South
F40	DRUM RUN	2509 ATLANTIC AVE	NY Spills	Lower	394, 0.075, ESE
E41	CON EDISON	2430 ATLANTIC AVE	E MANIFEST	Lower	402, 0.076, SW
E42	LOT 21,TAXBLOCK 1437	2432 ATLANTIC AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	403, 0.076, SW
D43	MANHOLE #04264	FULTON STREET & VAN	NY Spills	Higher	410, 0.078, North
D44	VANSINDREN AVE	AT FULTON STREET	NY Spills	Higher	410, 0.078, North
F45	PEREY TURNSTILES	2490 ATLANTIC AVENUE	NY UST, NY Spills, NY NYC LAND USE	Lower	415, 0.079, SSE
F46	PEREY TURNSTILES	2490 ATLANTIC AVENUE	UST FINDER	Lower	415, 0.079, SSE
F47	209176; HINSDALE ST;	HINSDALE ST; M-65896	NY Spills	Lower	434, 0.082, SE
F48	205454; HINSDALE ST;	HINSDALE ST; M65997	NY Spills	Lower	434, 0.082, SE
C49	CON EDISON	FRONT OF 2493 FULTON	NY MANIFEST	Higher	448, 0.085, NE
E50	LOT 32,TAXBLOCK 1574	2413 ATLANTIC AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	455, 0.086, West
F51	VENTURE METAL PRODUC	2523 ATLANTIC AVE	RCRA NonGen / NLR, ICIS, US AIRS, FINDS, ECHO, NY...	Lower	486, 0.092, ESE
G52	RUSBRO TRANSMISSION	2501 FULTON ST	EDR Hist Auto	Higher	502, 0.095, NE
H53	JUNIUS DEVELOPMENT L	1-25 JUNIUS STREET	NY AST	Lower	536, 0.102, SSW
H54	VAULT	1 JUNIUS ST	NY Spills	Lower	536, 0.102, SSW
H55	CON ED V 2312	1 JUNIS ST	RCRA NonGen / NLR, NY MANIFEST	Lower	536, 0.102, SSW
H56	CON EDISON - VAULT V	1 JUNIUS ST	NY LTANKS, NY Spills, NY MANIFEST	Lower	536, 0.102, SSW
G57	CON EDISON - VAULT S	2020 BROADWAY	RCRA-LQG	Higher	561, 0.106, ENE
G58	CON EDISON	2020 BROADWAY	NY MANIFEST	Higher	561, 0.106, ENE
G59	EAST NEW YORK TRUCK	1997 BROADWAY	NY AST	Higher	571, 0.108, NE
G60	EAST NEW YORK TRUCK	1997 BROADWAY	UST FINDER	Higher	571, 0.108, NE
G61	NYC TRANSIT EAST NY	1997 BROADWAY	NY Spills	Higher	571, 0.108, NE
G62	EAST NY TRUCK SHOP	1997 BROADWAY	NY Spills	Higher	571, 0.108, NE
G63	EAST NEW YORK TRUCK	1997 BROADWAY	NY AST	Higher	571, 0.108, NE
G64	NYCTA(BROADWAY ENY S	1997 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, E MANIFEST	Higher	571, 0.108, NE
G65	CON EDISON - COMPANY	OPP 2003 BROADWAY	E MANIFEST	Higher	573, 0.109, NE
66	CON EDISON	FRONT OF 12 JARDINE	NY MANIFEST	Higher	590, 0.112, West
I67	LOT 46,TAXBLOCK 1437	2435 PACIFIC STREET	NY BROWNFIELDS, NY E DESIGNATION, NY NYC OER, NY...	Lower	596, 0.113, SW
I68	FLYING SERVICE BOX C	2402 ATLANTIC AVE	NY Spills	Higher	600, 0.114, WSW
I69	CONSOLIDATED EDISON	2402 ATLANTIC AVE	E MANIFEST	Higher	600, 0.114, WSW
I70	CON EDISON	2402 ATLANTIC AVE	E MANIFEST	Higher	600, 0.114, WSW
I71	2402 ATLANTIC HOLDIN	2402 ATLANTIC AVENUE	NY AST	Higher	600, 0.114, WSW
G72	VAULT VS2603	2051 BROADWAY	NY Spills	Higher	603, 0.114, ENE
G73	CON EDISON - VAULT S	2051 BROADWAY	RCRA-LQG, E MANIFEST	Higher	603, 0.114, ENE
G74	CON EDISON	2051 BROADWAY	NY MANIFEST	Higher	603, 0.114, ENE
H75	CONSOLIDATED BUS	10 JUNIUS STREET	NY AST	Lower	612, 0.116, SSW
H76	LINCOLN SERVICE STAT	1727 E NEW YORK AVE	EDR Hist Auto	Lower	620, 0.117, SW
I77	2396 ATLANTIC AVENUE	2396 ATLANTIC AVENUE	NY NYC OER	Higher	633, 0.120, WSW

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
J78	EAST NEW SERVICE COR	36 SNEDIKER AVENUE	NY UST	Lower	663, 0.126, SSE
J79	EAST NEW SERVICE COR	36 SNEDIKER AVENUE	UST FINDER	Lower	663, 0.126, SSE
80	H E L P BROOKLYN HOU	HINSDALE ST & SNEDIK	RCRA NonGen / NLR	Lower	675, 0.128, ESE
K81	CON EDISON	2360 FULTON ST	E MANIFEST	Higher	692, 0.131, NW
I82	INSTITUTE FOR COMMUN	2384 ATLANTIC AVENUE	UST FINDER	Higher	719, 0.136, WSW
I83	ACT TEAMS	2384 ATLANTIC AVE	E MANIFEST	Higher	719, 0.136, WSW
I84	INSTITUTE FOR COMMUN	2384 ATLANTIC AVENUE	NY UST	Higher	719, 0.136, WSW
I85	INSTITUTE FOR COMMUN	2384 ATLANTIC AVE	NY LTANKS, NY VCP, NY NYC OER	Higher	719, 0.136, WSW
L86	BROADWAY FILTON	2090 BROADWAY	UST FINDER	Lower	733, 0.139, ENE
L87	BROADWAY FILTON	2090 BROADWAY	NY UST	Lower	733, 0.139, ENE
L88	MTA NYCT - JAMAICA L	KENT AVE & S 6TH ST	RCRA-LQG, E MANIFEST, NJ MANIFEST	Lower	771, 0.146, East
I89	CON EDISON	F/O 2395 PACIFIC ST	NY MANIFEST	Lower	775, 0.147, WSW
M90	CON EDISON	60 WILLIAMS AVE	NY MANIFEST	Lower	776, 0.147, SE
M91	CON EDISON - SERVICE	60 WILLIAMS AVE	RCRA-LQG	Lower	776, 0.147, SE
M92	CON EDISON - SERVICE	60 WILLIAMS AVE	NJ MANIFEST	Lower	776, 0.147, SE
L93	CON EDISON	BROADWAY & JAMAICA A	NJ MANIFEST	Lower	776, 0.147, East
L94	NYCTA-CPM ENVIRO ENG	BROADWAY & JAMAICA	NJ MANIFEST	Lower	776, 0.147, East
L95	NYCTA - BROADWAY ENY	BROADWAY & JAMAICA A	RCRA-VSQG, NY MANIFEST	Lower	776, 0.147, East
L96	CON ED	BROADWAY & JAMAICA A	NY MANIFEST	Lower	776, 0.147, East
L97	CON EDISON	BROADWAY & JAMAICA A	RCRA NonGen / NLR	Lower	776, 0.147, East
L98	CON EDISON/ ATTN: QU	JAMAICA AVE & BROADW	RCRA NonGen / NLR, E MANIFEST, NY MANIFEST	Lower	776, 0.147, East
L99	CON EDISON - MANHOLE	BROADWAY AND JAMAICA	RCRA-LQG, NY MANIFEST	Lower	776, 0.147, East
I100	CON EDISON/ ATTN: BR	2408 PACIFIC ST	E MANIFEST	Lower	781, 0.148, SW
N101	CON EDISON - MANHOLE	BROADWAY & VAN SINDE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	786, 0.149, North
N102	CON EDISON	BROADWAY & TRUXTON S	E MANIFEST	Higher	786, 0.149, North
N103	MTA NYCT - BROADWAY	BROADWAY & VAN SINDE	RCRA-SQG, E MANIFEST	Higher	786, 0.149, North
N104	MTA NYCT - MANHOLE A	BROADWAY & VAN SINDE	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Higher	786, 0.149, North
N105	MTA NYCT - BROADWAY	BROADWAY & VAN SINDE	NY MANIFEST	Higher	786, 0.149, North
106	CON EDISON	1 CONWAY ST	E MANIFEST	Higher	821, 0.155, NNW
O107	MAGNOLIA HOUSE	1430 HERKIMER STREET	NY AST	Higher	832, 0.158, WNW
P108	CON EDISON SERVICE B	102 SACKMAN ST	RCRA NonGen / NLR, NY MANIFEST	Higher	843, 0.160, West
I109	PACIFIC STREET IRA	2402A PACIFIC ST	E MANIFEST	Lower	852, 0.161, SW
L110	CON EDISON	2572 FULTON ST	NY MANIFEST	Lower	869, 0.165, East
L111	CON EDISON	2572 FULTON ST	NJ MANIFEST	Lower	869, 0.165, East
L112	CON EDISON	2572 FULTON ST	RCRA NonGen / NLR	Lower	869, 0.165, East
P113	CON EDISON - MANHOLE	2371 ATLANTIC AVE AN	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	891, 0.169, West
K114	2246 FULTON STREET	50 SACKMAN STREET	NY UST	Higher	899, 0.170, WNW
Q115	OUR LADY OF LORETO C	124 SACKMAN ST	NY UST, NY Spills, NY MANIFEST	Higher	901, 0.171, WSW
Q116	OUR LADY OF LORETO C	124 SACKMAN ST	UST FINDER	Higher	901, 0.171, WSW

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
R117	CON EDISON	21 ALABAMA AVE	NY MANIFEST	Lower	907, 0.172, East
R118	CON EDISON	21 ALABAMA AVE	NJ MANIFEST	Lower	907, 0.172, East
R119	CON EDISON	21 ALABAMA AVE	RCRA NonGen / NLR	Lower	907, 0.172, East
R120	KANES INDUSTRIES	23 ALABAMA AVE	RCRA NonGen / NLR	Lower	913, 0.173, East
R121	CON EDISON	23 ALABAMA AVE	NJ MANIFEST	Lower	913, 0.173, East
R122	CON EDISON	23 ALABAMA AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	913, 0.173, East
R123	CON EDISON	23 ALABAMA AVE	NY MANIFEST	Lower	913, 0.173, East
S124	MTA NYCT - SUBWAY EL	2020 BROADWAY	RCRA-SQG, FINDS, ECHO	Higher	923, 0.175, NNE
S125	NYCTA	25 JAMAICA AVENUE	NY LTANKS, NY CBS, NY CBS AST, NY Spills, NY...	Higher	923, 0.175, NNE
S126	EAST NEW YORK TRUCK	1997 BROADWAY	NY UST, NY CBS	Higher	923, 0.175, NNE
S127	EAST NEW YORK BUS DE	25 JAMAICA AVENUE	NY UST	Higher	923, 0.175, NNE
S128	MTA NYCT - EAST NY D	25 JAMAICA AVE	RCRA-SQG, RAATS, ICIS, FINDS, ECHO, E MANIFEST, NJ...	Higher	923, 0.175, NNE
S129	NYCT-40 CONWAY ST	40 CONWAY ST	RCRA-LQG, FINDS, ECHO, E MANIFEST, NY MANIFEST, NJ...	Higher	923, 0.175, NNE
S130	NYC-TA EAST NY BUS D	1 JAMAICA AVE	NY LTANKS, NY Spills, US AIRS, NY AIRS	Higher	923, 0.175, NNE
S131	NYCTA (ENY YARD) HAZ	1700 BUSHWICK AVENUE	RCRA NonGen / NLR, ICIS, US AIRS, E MANIFEST, RI...	Higher	923, 0.175, NNE
S132	EAST NEW YORK BOILER	1 JAMAICA AVENUE	NY UST, NY AST	Higher	923, 0.175, NNE
S133	EAST NEW YORK DEPOT	25 JAMAICA AVE/NYCTA	NY LTANKS	Higher	923, 0.175, NNE
S134	EAST NEW YORK CMF	1730 BUSHWICK AVENUE	NY AST	Higher	923, 0.175, NNE
N135	CON EDISON	BROADWAY & CONWAY ST	E MANIFEST	Higher	930, 0.176, NNW
O136	LOT 18,TAXBLOCK 1553	2246 FULTON STREET	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Higher	939, 0.178, WNW
T137	20-50 POWELL STREET	20-50 POWELL STREET	NY AST	Lower	951, 0.180, SW
N138	SOLID GOLD TOWING IN	1960 BROADWAY	NY UST, NY Spills	Higher	961, 0.182, NNW
N139	SOLID GOLD TOWING IN	1960 BROADWAY	UST FINDER	Higher	961, 0.182, NNW
R140	CON EDISON	2569 ATLANTIC AVE	NY MANIFEST	Lower	982, 0.186, ESE
R141	CON EDISON	2569 ATLANTIC AVE	NJ MANIFEST	Lower	982, 0.186, ESE
R142	CON EDISON	2569 ATLANTIC AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	982, 0.186, ESE
P143	CON EDISON/ ATTN: BR	2361 ATLANTIC AVE	E MANIFEST	Higher	987, 0.187, West
P144	CON EDISON MANHOLE:	2356 ATLANTIC AVE	RCRA NonGen / NLR, FINDS	Higher	1023, 0.194, WSW
P145	CON EDISON	2356 ATLANTIC AVE	NY MANIFEST	Higher	1023, 0.194, WSW
U146	CON EDISON	LIBERTY AVE & SNEIDI	RCRA NonGen / NLR, FINDS, ECHO	Lower	1033, 0.196, SSE
U147	CON EDISON	LIBERTY & SNEIDIKER	NJ MANIFEST	Lower	1033, 0.196, SSE
U148	CON EDISON	SNEDIKER AVE & LIBER	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1033, 0.196, SSE
U149	CON EDISON	LIBERTY AVE & SNEIDI	NY MANIFEST	Lower	1033, 0.196, SSE
U150	CON EDISON	SNEDIKER AVE & LIBER	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1033, 0.196, SSE
Q151	CON EDISON/ ATTN: BR	2363 PACIFIC STREET	E MANIFEST	Higher	1036, 0.196, WSW
V152	CON EDISON - SERVICE	92 WILLIAMS AVE	NY LEAD, NY MANIFEST, NY NYC LAND USE	Lower	1040, 0.197, SE
V153	CONSOLIDATED EDISON-	92 WILLIAMS AVE	E MANIFEST	Lower	1040, 0.197, SE
R154	CON EDISON	38 GEORGIA AVE	RCRA NonGen / NLR	Lower	1041, 0.197, East
R155	CON EDISON	38 GEORGIA AVE	NJ MANIFEST	Lower	1041, 0.197, East

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
W156	CON EDISON - MANHOLE	1 JAMAICA AVE AND BR	RCRA-LQG, NY MANIFEST	Lower	1044, 0.198, ENE
W157	EAST NEW YORK BOILER	1 JAMAICA AVENUE	UST FINDER	Lower	1044, 0.198, ENE
R158	CON EDISON	44 GEORGIA AVE	NJ MANIFEST	Lower	1054, 0.200, East
R159	CON EDISON	44 GEORGIA AVE	NY MANIFEST	Lower	1054, 0.200, East
R160	CON EDISON	44 GEORGIA AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1054, 0.200, East
X161	MILTON UNGER	2234 FULTON STREET	NY UST, NY AST	Higher	1056, 0.200, WNW
X162	MILTON UNGER	2234 FULTON STREET	UST FINDER	Higher	1056, 0.200, WNW
R163	ACT TEAMS	2581 ATLANTIC AVE ST	E MANIFEST	Lower	1059, 0.201, ESE
R164	EAST NEW YORK HEALTH	2581 ATLANTIC AVE	E MANIFEST	Lower	1059, 0.201, ESE
R165	ACT TEAMS	2581 ATLANTIC AVE, S	E MANIFEST	Lower	1059, 0.201, ESE
P166	CON EDISON SERVICE B	ATLANTIC AVE & SHERL	RCRA NonGen / NLR, NY MANIFEST	Higher	1061, 0.201, West
Q167	CON EDISON/ ATTN: BR	2372 PACIFIC ST	E MANIFEST	Lower	1069, 0.202, WSW
Y168	PARK AVENUE BUILDING	68 CONWAY STREET	NY UST	Higher	1079, 0.204, North
Y169	PARK AVENUE BUILDING	68 CONWAY STREET	UST FINDER	Higher	1079, 0.204, North
Z170	CON EDISON - SERVICE	80 ALABAMA AVE	RCRA-LQG	Lower	1082, 0.205, SE
Z171	CON EDISON - SERVICE	80 ALABAMA AVE	NJ MANIFEST	Lower	1082, 0.205, SE
X172	CON EDISON - BROOKLY	1401 HERKIMER ST	E MANIFEST	Higher	1086, 0.206, WNW
X173	CON EDISON/ ATTN: BR	1401 HERKIMER ST	E MANIFEST	Higher	1086, 0.206, WNW
AA174	156-158 SOMERS ST LL	156-158 SOMERS ST	RCRA-VSQG, E MANIFEST	Higher	1111, 0.210, NW
AA175		156 SOMERS STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	1111, 0.210, NW
AA176	EINAV GELBERG	156-158 SOMERS ST	NY MANIFEST	Higher	1111, 0.210, NW
U177	ROYAL LACE CORP.	200 LIBERTY AVENUE	NY UST	Lower	1121, 0.212, South
U178	ROYAL LACE CORP.	200 LIBERTY AVENUE	UST FINDER	Lower	1121, 0.212, South
U179	STAR POLY BAG INC		PFAS ECHO	Lower	1126, 0.213, SSE
AA180	1848 STEWART ST	1848 STEWART ST	NY LTANKS	Higher	1164, 0.220, NNW
V181	NYC BD OF ED - PUBLI	275 LIBERTY AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1173, 0.222, SE
AB182	CON EDISON	51 GEORGIA AVE	NY MANIFEST	Lower	1175, 0.223, East
AC183	CON EDISON SERVICE B	2425 DEAN ST	RCRA NonGen / NLR, FINDS	Lower	1178, 0.223, WSW
AC184	CON EDISON	2425 DEAN ST	NY MANIFEST	Lower	1178, 0.223, WSW
U185	STAR POLY BAG INC	96 SNEDIKER AVE	RCRA-VSQG	Lower	1179, 0.223, SSE
T186	VACANT LOT	170-180 SACKMAN ST	NY LTANKS	Lower	1180, 0.223, SW
W187	NYCTA	25 JAMAICA AVE NYD99	NY MANIFEST	Lower	1183, 0.224, ENE
W188	EAST NEW YORK DEPOT	25 JAMAICA AVE/NYCTA	UST FINDER RELEASE	Lower	1183, 0.224, ENE
W189	NEW YORK CITY TRANSI	25 JAMAICA AVE	PA MANIFEST	Lower	1183, 0.224, ENE
W190	EAST NEW YORK BUS DE	25 JAMAICA AVENUE	NY AST	Lower	1183, 0.224, ENE
W191	EAST NEW YORK BUS DE	25 JAMAICA AVENUE	UST FINDER	Lower	1183, 0.224, ENE
W192	EAST NEW YORK BUS DE	25 JAMAICA AVENUE	NY AST	Lower	1183, 0.224, ENE
AD193	CON EDISON	2342 ATLANTIC AV	NY LEAD, NY MANIFEST, NY NYC LAND USE	Higher	1190, 0.225, WSW
AA194	SACKMAN REALTY LLC	10 SACKMAN ST	NY AST	Higher	1197, 0.227, NW

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AD195	CON EDISON	2349 PACIFIC ST	NY MANIFEST	Higher	1200, 0.227, WSW
AD196	CON EDISON SERVICE B	2349 PACIFIC ST	RCRA NonGen / NLR, FINDS	Higher	1200, 0.227, WSW
AE197	CON EDISON	74 GEORGIA AVE	NJ MANIFEST	Lower	1204, 0.228, ESE
AE198	CON EDISON	74 GEORGIA AVE	NY MANIFEST	Lower	1204, 0.228, ESE
AE199	CON EDISON	74 GEORGIA AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1204, 0.228, ESE
X200	CON EDISON	1385 HERKIMER ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1208, 0.229, WNW
X201	CON EDISON	1385 HERKIMER ST	NJ MANIFEST	Higher	1208, 0.229, WNW
X202	CON EDISON	1385 HERKIMER ST	NY MANIFEST	Higher	1208, 0.229, WNW
AF203	CON ED	1716 BUSHWICK AVE	NY MANIFEST	Higher	1209, 0.229, NE
AF204	CON EDISON	1716 BUSHWICK AVE	NJ MANIFEST	Higher	1209, 0.229, NE
AF205	CON EDISON	1716 BUSHWICK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1209, 0.229, NE
AF206	NYCTA (NON-HAZ CONTR	1720 BUSHWICK AVENUE	E MANIFEST	Higher	1212, 0.230, NE
AF207	CON EDISON/ ATTN: BR	1700 BUSHWICK AVE	E MANIFEST	Higher	1213, 0.230, NNE
W208	BP #30129	32 JAMAICA AVE	RCRA-SQG, US AIRS, FINDS, ECHO, E MANIFEST, NY...	Lower	1214, 0.230, ENE
W209	JAMAICA ISLAND CORP.	32 JAMAICA AVENUE	NY UST	Lower	1214, 0.230, ENE
W210	JAMAICA ISLAND CORP.	32 JAMAICA AVENUE	UST FINDER	Lower	1214, 0.230, ENE
AG211	CON ED - MH 5143	LIBERTY AVE & POWELL	RCRA NonGen / NLR, NY MANIFEST	Lower	1235, 0.234, SSW
AG212	CON EDISON MANHOLE 5	POWELL ST & LIBERTY	RCRA NonGen / NLR, NY MANIFEST	Lower	1235, 0.234, SSW
AG213	CONSOLIDATED EDISON	LIBERTY AVE & POWELL	NY MANIFEST	Lower	1235, 0.234, SSW
AG214	CON EDISON MANHOLE 5	LIBERTY AVE & POWELL	RCRA NonGen / NLR	Lower	1235, 0.234, SSW
AG215	CON EDISON MANHOLE 5	LIBERTY AVE & POWELL	RCRA NonGen / NLR	Lower	1235, 0.234, SSW
AG216	CONSOLIDATED EDISON	POWELL & LIBERTY AVE	NY MANIFEST	Lower	1240, 0.235, SSW
AA217	BRADFORD SWETT	2000 EASTERN PARKWAY	NY UST	Higher	1243, 0.235, NNW
AA218	BRADFORD SWETT	2000 EASTERN PARKWAY	UST FINDER	Higher	1243, 0.235, NNW
U219	CON EDISON	103 SNEDIKER AVE	E MANIFEST	Lower	1245, 0.236, SSE
AD220	LOT 6,TAXBLOCK 1436	1860 EASTERN PARKWAY	NY VCP, NY E DESIGNATION, NY NYC OER	Higher	1249, 0.237, West
AD221	HARRY T NANCE APARTM	1860 EASTERN PARKWAY	NY UST	Higher	1249, 0.237, West
AA222	AMERICAN TRUCK REPAI	2020 EASTERN PARKWAY	UST FINDER	Higher	1259, 0.238, NNW
AA223	AMERICAN TRUCK REPAI	2020 EASTERN PARKWAY	NY UST, NY Spills	Higher	1259, 0.238, NNW
AH224	HESS#32507	1630 BUSHWICK AVE	UST FINDER RELEASE	Higher	1260, 0.239, North
AH225	SPEEDWAY # 7812	1630 BUSHWICK AVENUE	NY UST, NY AST	Higher	1260, 0.239, North
AH226	HESS #32507	1630 BUSHWICK AVE	UST FINDER RELEASE	Higher	1260, 0.239, North
AH227	HESS-MERIT STATION	1630-76 BUSHWICK AVE	UST FINDER RELEASE	Higher	1260, 0.239, North
AH228	SPEEDWAY # 7812	1630 BUSHWICK AVENUE	UST FINDER	Higher	1260, 0.239, North
AH229	HESS-MERIT GAS STATI	1630-76 BUSHWICK AVE	NY LTANKS	Higher	1260, 0.239, North
AH230	MERIT OIL CORP	1630 BUSHWICK AVE	RCRA NonGen / NLR, US AIRS, NY MANIFEST	Higher	1260, 0.239, North
AH231	HESS-MERIT GAS STATI	1630-76 BUSHWICK AVE	UST FINDER RELEASE	Higher	1260, 0.239, North
AH232	HESS # 32507	1630 BUSHWICK AVE	UST FINDER RELEASE	Higher	1260, 0.239, North
AC233	CON EDISON	FRONT OF 2413 DEAN S	NY MANIFEST	Lower	1262, 0.239, WSW

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
X234	CON EDISON SERVICE B	1910 EASTERN PKWY	RCRA NonGen / NLR	Higher	1276, 0.242, WNW
X235	CON EDISON	1910 EASTERN PKWY	NY MANIFEST	Higher	1276, 0.242, WNW
X236	CON EDISON/QUEENS EN	281 2216 FULTON ST.	E MANIFEST	Higher	1277, 0.242, WNW
237	81-111 JUNIUS STREET	81 JUNIUS STREET	NY VCP, NY NYC OER	Lower	1277, 0.242, South
AI238	MTA NYCT - NEW YARD	1925 BROADWAY	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1278, 0.242, NNW
AC239	CON EDISON SERVICE B	2346 PACIFIC ST	RCRA NonGen / NLR	Higher	1282, 0.243, WSW
AC240	CON EDISON	2346 PACIFIC ST	NY MANIFEST	Higher	1282, 0.243, WSW
AB241	WARTBURG LUTHERAN HO	50 SHEFFIELD AVENUE	NY LTANKS, NY NYC LAND USE	Lower	1285, 0.243, East
AB242	WARTBURG LUTHERAN HO	50 SHEFFIELD AVENUE	UST FINDER	Lower	1285, 0.243, East
AB243	WARTBURG LUTHERAN HO	50 SHEFFIELD AVENUE	NY UST	Lower	1285, 0.243, East
AB244	SHINY CAR WASH AND Q	2591 ATLANTIC AVENUE	NY AST	Lower	1287, 0.244, East
AB245	SHINY CAR WASH & LUB	2591 ATLANTIC AVE	NY CBS, NY AST, NY Spills	Lower	1287, 0.244, East
246	GRAFTON REALTY CORP.	1660 EAST NEW YORK A	NY AST	Lower	1287, 0.244, SW
AH247	SLS CAR WASH, INC.	1650 BUSHWICK AVENUE	NY AST	Higher	1289, 0.244, North
V248	METRO STRUCTURAL STE	282 LIBERTY AVENUE	NY UST	Lower	1294, 0.245, SE
V249	METRO STRUCTURAL STE	282 LIBERTY AVENUE	UST FINDER	Lower	1294, 0.245, SE
AC250	CON EDISON/ ATTN: BR	2409 DEAN ST	E MANIFEST	Lower	1294, 0.245, WSW
AI251	CON EDISON SERVICE B	17 STEWART ST	RCRA NonGen / NLR	Higher	1295, 0.245, NNW
AI252	CON EDISON	17 STEWART ST	NY MANIFEST	Higher	1295, 0.245, NNW
AH253	CON EDISON	FO 1654 BUSHWICK AVE	NY MANIFEST	Higher	1299, 0.246, NNE
AH254	CON EDISON	1652 BUSHWICK AVE	NY MANIFEST	Higher	1301, 0.246, NNE
AH255	CON EDISON - COMPANY	1652 BUSHWICK AVE	E MANIFEST	Higher	1301, 0.246, NNE
AE256	CON EDISON	2604 ATLANTIC AVE	NJ MANIFEST	Lower	1302, 0.247, ESE
AE257	CON EDISON	2604 ATLANTIC AVE	RCRA NonGen / NLR	Lower	1302, 0.247, ESE
AE258	CON EDISON	2604 ATLANTIC AVE	NY MANIFEST	Lower	1302, 0.247, ESE
AG259	NYC ENVIRONMENTAL PR	127 LIBERTY AVE	E MANIFEST	Lower	1303, 0.247, SSW
AB260	CON EDISON	2599 ATLANTIC AVE	E MANIFEST	Lower	1304, 0.247, ESE
261	MTA NYCT - BUS COMMA	51 FANCHON PL	RCRA-SQG	Lower	1304, 0.247, ENE
AF262	CON EDISON - QUEENS	9 HIGHLAND BLVD	E MANIFEST	Higher	1312, 0.248, NE
263	CON EDISON MANHOLE:	ALABAMA AVE & LIBERT	RCRA NonGen / NLR, NY MANIFEST	Lower	1318, 0.250, SE
AJ264	50 PENN LLC	2618 FULTON ST	NY VCP, NY Spills, NY MANIFEST, NY NYC OER	Lower	1395, 0.264, East
AC265	DEAN STREET - HABITA	2396 DEAN STREET	NY VCP, NY NYC OER	Lower	1436, 0.272, WSW
266	114 SNEDIKER AVENUE	221-241 GLENMORE AVE	NY BROWNFIELDS	Lower	1438, 0.272, South
267	228 HULL ST	228 HULL ST	NY LTANKS	Higher	1449, 0.274, NW
AK268	SUNOCO GAS STA	35 HIGHLAND BLVD	NY LTANKS, NY Spills	Higher	1500, 0.284, NE
AK269	SUNOCO GAS STA	35 HIGHLAND BLVD	UST FINDER RELEASE	Higher	1500, 0.284, NE
270	33 TRUXTON STREET	33 TRUXTON STREET	NY NYC OER	Higher	1504, 0.285, WNW
271	CON EDISON SERVICE B	103 LIBERTY AVE	NY VCP, RCRA NonGen / NLR, NY MANIFEST, NY NYC OER	Lower	1568, 0.297, SW
272	AKA 31-33 MONACO PLA	2121 MONACO PLACE	NY LTANKS	Higher	1581, 0.299, West

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
273	2175 BERGEN STREET	217-221 MOTHER GASTO	NY VCP, NY NYC OER	Lower	1587, 0.301, WSW
AJ274	UNKNOWN	2642 FULTON ST.	NY LTANKS, NY Spills	Lower	1640, 0.311, East
275	GERSHOW RECYCLING OF	1885 PITKEN AVENUE	NY SWF/LF	Lower	1773, 0.336, South
276	APARTMENT BUILDING	211 HULL STREET	NY LTANKS, NY Spills, NY NYC LAND USE	Higher	1817, 0.344, NW
AL277	117 GLENMORE AVENUE	117 GLENMORE AVENUE	NY VCP, NY NYC OER	Lower	1874, 0.355, SSW
278	2667 FULTON STREET	2667 FULTON STREET	NY VCP, NY NYC OER	Lower	1938, 0.367, East
AL279	GLENMORE PLAZA -NYCH	108 CHRISTOPHER AVE	NY LTANKS, NY Spills	Lower	1982, 0.375, SSW
280	157 NEW JERSEY AVENU	157 NEW JERSEY AVENU	NY VCP, NY NYC OER	Lower	1998, 0.378, East
AM281	BIG APPLE AUTO INC	1934 PITKIN AVE	NY SWF/LF, NY SPDES	Lower	2020, 0.383, SSE
AN282	WOLF PETROLEUM CORP	1532 BUSHWICK AVE	UST FINDER RELEASE	Higher	2066, 0.391, NNW
AN283	WOLF PETROLEUM CORP	1532 BUSHWICK AVE	NY LTANKS	Higher	2066, 0.391, NNW
AN284	FIVE STAR AUTO REBUI	1533 BUSHWICK AVE	NY SWF/LF	Higher	2096, 0.397, NNW
285	LOT 35,TAXBLOCK 3703	184 PENNSYLVANIA AVE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	2108, 0.399, ESE
AM286	NATIONWIDE SCRAP LLC	178-214 SNEDIKER AVE	NY SWRCY	Lower	2123, 0.402, SSE
287	F & S AUTO	202 SHEFFIELD AVE	NY SWF/LF	Lower	2151, 0.407, SE
AO288	2701-2715 FULTON STR	2701-2715 FULTON STR	NY VCP, NY NYC OER	Lower	2246, 0.425, East
289	OCEAN HILL HOUSES -N	24 STONE AVENUE	NY LTANKS, NY Spills	Higher	2274, 0.431, NW
290	SETH LOW HOUSES -NYC	180 POWELL STREET	NY LTANKS, NY Spills	Lower	2281, 0.432, South
291	2700 ATLANTIC AVENUE	2700 ATLANTIC AVENUE	NY VCP, NY NYC OER	Lower	2340, 0.443, East
292		110 WYONA STREET	NY LTANKS, NY Spills, NY LEAD, NY NYC LAND USE	Lower	2367, 0.448, East
AO293		2718 FULTON STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	2430, 0.460, East
AP294	EXXONMOBIL	225 PENNSYLVANIA AVE	NY LTANKS, NY Spills	Lower	2450, 0.464, SE
AP295	EXXONMOBIL	225 PENNSYLVANIA AVE	UST FINDER RELEASE	Lower	2450, 0.464, SE
AP296	EXXON DIV OF CFI #70	225 PENNSYLVANIA AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NY...	Lower	2450, 0.464, SE
297	SOLCO PLUMBING SUPPL	413 LIBERTY AVENUE	NY SWF/LF, NY NYC LAND USE	Lower	2487, 0.471, ESE
298	20 INTERBOROUGH PKWY	20 INTERBOROUGH PKWY	NY LTANKS	Higher	2500, 0.473, NE
AP299	CFI STATION #70227	189 PENNSYLVANIA AVE	NY LTANKS	Lower	2527, 0.479, SE
AQ300	BUG, BELMONT WORKS	BELMONT & ALABAMA AV	NY HSWDS	Lower	2569, 0.487, SSE
AQ301	BKLYN UNION GAS /BEL	BELMONT & ALABAMA AV	SEMS-ARCHIVE	Lower	2569, 0.487, SSE
302	LOT 15,TAXBLOCK 3690	2738 ATLANTIC AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	2726, 0.516, East
303	BELMONT STATION	BELMONT, WILLIAMS, A	EDR MGP	Lower	2764, 0.523, SSE
AR304	LOT 18,TAXBLOCK 3946	2776 FULTON STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	3040, 0.576, East
AR305	LOT 55,TAXBLOCK 3933	2795 FULTON STREET	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Lower	3230, 0.612, East
306	HENRY APARTMENTS SIT	8 ROCKAWAY AVENUE	NY VCP, NY MANIFEST, NY NYC OER	Lower	3365, 0.637, NW
AS307	LOT 56,TAXBLOCK 1468	1900 PARK PLACE	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Lower	3527, 0.668, WSW
AS308	416 THOMAS S. BOYLAN	416 THOMAS S. BOYLAN	NY NYC OER	Lower	3659, 0.693, WSW
309	HENRY APARTMENTS - S	1676 BROADWAY	NY VCP, NY NYC OER	Lower	3750, 0.710, NW
310	2862 FULTON STREET	2862 FULTON STREET	NY NYC OER	Lower	3972, 0.752, East
311		1846 PARK PLACE	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Higher	4017, 0.761, WSW

MAPPED SITES SUMMARY

Target Property Address:
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
312	LOT 11,TAXBLOCK 3965	2864 ATLANTIC AVENUE	NY BROWNFIELDS, NY E DESIGNATION, NY NYC OER, NY...	Lower	4108, 0.778, East
313	402 SNEDIKER AVENUE	402 SNEDIKER AVENUE	NY VCP, NY NYC OER	Lower	4228, 0.801, SSE
314		2064 ATLANTIC AVENUE	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Higher	4338, 0.822, West
315	53 MACDOUGAL STREET	53 MACDOUGAL ST	NY VCP, NY NYC OER	Lower	4768, 0.903, WNW
316	LOT 30,TAXBLOCK 3998	2337 PITKIN AVENUE	NY VCP, NY E DESIGNATION, NY NYC OER	Lower	4786, 0.906, ESE
AT317	K - UNION STATION HO	ATLANTIC AVE, ASHFOR	NY SHWS, NY BROWNFIELDS, NY MGP	Lower	4804, 0.910, East
318	305 CHESTER STREET -	305 CHESTER STREET	NY NYC OER	Lower	4812, 0.911, SSW
AT319	UNION STATION (CITIZ	ATLANTIC AVE., ASHFO	EDR MGP	Lower	4813, 0.912, East
320		368 LIVONIA AVENUE	NY VCP, NY NYC LAND USE, NY NYC OER	Lower	4819, 0.913, South
AU321	19 PRESCOTT PLACE -	19 PRESCOTT PLACE	NY NYC OER	Higher	4844, 0.917, West
AV322	LOT 14,TAXBLOCK 1471	1790 STERLING PLACE	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Higher	4889, 0.926, WSW
AV323		497 HOWARD AVENUE	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Higher	4953, 0.938, WSW
AU324	LOT 25,TAXBLOCK 1556	20 PRESCOTT PLACE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	4958, 0.939, West
AW325	LOT 65,TAXBLOCK 1474	1717 LINCOLN PLACE	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Lower	5027, 0.952, WSW
326	673 LIVONIA AVENUE	673 LIVONIA AVENUE	NY SHWS, NY NYC LAND USE	Lower	5067, 0.960, SE
AU327	LOT 3,TAXBLOCK 1556	335 RALPH AVENUE	NY VCP, NY E DESIGNATION, NY NYC LAND USE, NY NYC...	Higher	5069, 0.960, West
AW328	LOT 23,TAXBLOCK 1476	1319 EAST NEW YORK A	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Lower	5074, 0.961, WSW
AW329	1470 EASTERN PARKWAY	1470 EASTERN PARKWAY	NY NYC OER	Lower	5175, 0.980, WSW
AW330	LOT 5,TAXBLOCK 1474	1464 EASTERN PARKWAY	NY E DESIGNATION, NY NYC OER, NY NYC LAND USE	Lower	5204, 0.986, WSW
331	FORMER SEP S CLEANER	242-288 LIVONIA AVEN	NY SHWS, NY ENG CONTROLS, NY INST CONTROL	Lower	5250, 0.994, SSW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
45 VAN SINDEREN AVEN 45 VAN SINDEREN AVEN BROOKLYN, NY 11207	NY NYC LAND USE	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

NY HIST LTANKS - Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST - Underground Storage Tank Listing
NY CBS UST - Chemical Bulk Storage Database
NY MOSF UST - Major Oil Storage Facilities Database
NY MOSF - Major Oil Storage Facility Site Listing
NY MOSF AST - Major Oil Storage Facilities Database
INDIAN UST - Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL - Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP - Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP - Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS - A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE - Registered Waste Tire Storage & Facility List
INDIAN ODI - Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 - Torres Martinez Reservation Illegal Dump Site Locations
ODI - Open Dump Inventory
IHS OPEN DUMPS - Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL - Delisted National Clandestine Laboratory Register
NY DEL SHWS - Delisted Registry Sites
US CDL - National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST - Historical Petroleum Bulk Storage Database
NY HIST AST - Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS - Spill Liens Information
LIENS 2 - CERCLA Lien Information

Records of Emergency Release Reports

HMIRS - Hazardous Materials Information Reporting System

NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
PADS ---- PCB Activity Database System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
MINES MRDS ---- Mineral Resources Data System
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
PFAS NPL ---- Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES ---- Federal Sites PFAS Information
PFAS TSCA ---- PFAS Manufacture and Imports Information
PFAS TRIS ---- List of PFAS Added to the TRI
PFAS RCRA MANIFEST ---- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---- PFAS Contamination Site Location Listing
PFAS WQP ---- Ambient Environmental Sampling for PFAS
PFAS PROJECT ---- NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS NPDES ---- Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAIN ---- Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT ---- All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC ---- Aqueous Foam Related Incidents Listing
BIOSOLIDS ---- ICIS-NPDES Biosolids Facility Data
NY PFAS ---- PFAS Contamination Site Location Listing
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY DRYCLEANERS ---- Registered Drycleaners
NY Financial Assurance ---- Financial Assurance Information Listing

NY VAPOR REOPENED Vapor Intrusion Legacy Site List
NY UIC Underground Injection Control Wells
NY COOLING TOWERS Registered Cooling Towers
NY ILI New York State Inactive Landfill Initiative

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 12/19/2024 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WOLFF-ALPORT CHEMICA Cerclis ID:: 206479 EPA Id: NYC200400810	***1125-1139 IRVING AVE***	***N 1/2 - 1 (0.960 mi.)***	***0***	***10***

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 12/19/2024 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BKLYN UNION GAS /BEL Site ID: 0201985 EPA Id: NYD980532097	BELMONT & ALABAMA AV	SSE 1/4 - 1/2 (0.487 mi.)	AQ301	1088

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 02/17/2025 has revealed that there are 9 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - VAULT S EPA ID:: NYP005115332	2020 BROADWAY	ENE 0 - 1/8 (0.106 mi.)	G57	184
CON EDISON - VAULT S EPA ID:: NYP005115324	***2051 BROADWAY***	***ENE 0 - 1/8 (0.114 mi.)***	***G73***	***219***
MTA NYCT - MANHOLE A EPA ID:: NYP000967760	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N104***	***333***
NYCT-40 CONWAY ST EPA ID:: NYR000027821	***40 CONWAY ST***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S129***	***482***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - JAMAICA L EPA ID:: NYR000145045	***KENT AVE & S 6TH ST***	***E 1/8 - 1/4 (0.146 mi.)***	***L88***	***254***
CON EDISON - SERVICE EPA ID:: NYP004868172	60 WILLIAMS AVE	SE 1/8 - 1/4 (0.147 mi.)	M91	285
CON EDISON - MANHOLE	***BROADWAY AND JAMAICA***	***E 1/8 - 1/4 (0.147 mi.)***	***L99***	***315***

EPA ID:: NYP004198453				
CON EDISON - MANHOLE	***1 JAMAICA AVE AND BR***	***ENE 1/8 - 1/4 (0.198 mi.)***	***W156***	***686***
EPA ID:: NYP004198198				
CON EDISON - SERVICE	80 ALABAMA AVE	SE 1/8 - 1/4 (0.205 mi.)	Z170	719
EPA ID:: NYP004868206				

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/17/2025 has revealed that there are 5 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - BROADWAY	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N103***	***328***
EPA ID:: NYR000236273				
MTA NYCT - SUBWAY EL	***2020 BROADWAY***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S124***	***382***
EPA ID:: NYR000078071				
MTA NYCT - EAST NY D	***25 JAMAICA AVE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S128***	***432***
EPA ID:: NYD991290677				

Lower Elevation	Address	Direction / Distance	Map ID	Page
BP #30129	***32 JAMAICA AVE***	***ENE 1/8 - 1/4 (0.230 mi.)***	***W208***	***822***
EPA ID:: NYD986963064				
MTA NYCT - BUS COMMA	51 FANCHON PL	ENE 1/8 - 1/4 (0.247 mi.)	261	965
EPA ID:: NYR000246785				

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 02/17/2025 has revealed that there are 4 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
156-158 SOMERS ST LL	***156-158 SOMERS ST***	***NW 1/8 - 1/4 (0.210 mi.)***	***AA174***	***726***
EPA ID:: NYR000255042				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYCTA - ATLANTIC AVE	***ATLANTIC AVE & VAN S***	***SSW 0 - 1/8 (0.024 mi.)***	***A10***	***57***
EPA ID:: NYR000042838				
NYCTA - BROADWAY ENY	***BROADWAY & JAMAICA A***	***E 1/8 - 1/4 (0.147 mi.)***	***L95***	***291***

EPA ID:: NYR000072777				
STAR POLY BAG INC EPA ID:: NYR000229955	96 SNEDIKER AVE	SSE 1/8 - 1/4 (0.223 mi.)	U185	754

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 11/04/2024 has revealed that there are 3 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
K - UNION STATION HO Site Code: 378991	***ATLANTIC AVE, ASHFOR***	***E 1/2 - 1 (0.910 mi.)***	***AT317***	***1124***
673 LIVONIA AVENUE Site Code: 631213	***673 LIVONIA AVENUE***	***SE 1/2 - 1 (0.960 mi.)***	***326***	***1141***
FORMER SEP S CLEANER Site Code: 576845	***242-288 LIVONIA AVEN***	***SSW 1/2 - 1 (0.994 mi.)***	***331***	***1153***

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 12/11/2024 has revealed that there are 6 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FIVE STAR AUTO REBUI	1533 BUSHWICK AVE	NNW 1/4 - 1/2 (0.397 mi.)	AN284	1022

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARIES AUTOWORLD LTD	2471 ATLANTIC AVE	SSW 0 - 1/8 (0.020 mi.)	A8	55
GERSHOW RECYCLING OF	1885 PITKEN AVENUE	S 1/4 - 1/2 (0.336 mi.)	275	998
BIG APPLE AUTO INC	***1934 PITKIN AVE***	***SSE 1/4 - 1/2 (0.383 mi.)***	***AM281***	***1016***
F & S AUTO	202 SHEFFIELD AVE	SE 1/4 - 1/2 (0.407 mi.)	287	1026
SOLCO PLUMBING SUPPL	***413 LIBERTY AVENUE***	***ESE 1/4 - 1/2 (0.471 mi.)***	***297***	***1079***

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 11/03/2024 has revealed that there are 23 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPILL NUMBER 0206144 Spill Number/Closed Date: 0206144 / 2002-10-08 Site ID: 160781 Spill Date: 2002-09-13	38 VAN SINDEREN AVE	NNW 0 - 1/8 (0.052 mi.)	D27	115
INSTITUTE FOR COMMUN Spill Number/Closed Date: 0512499 / 2006-10-06 Spill Number/Closed Date: 9402632 / 2003-02-18 Site ID: 358824 Site ID: 69637 Spill Date: 2006-01-27 Spill Date: 1994-05-23	***2384 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.136 mi.)***	***I85***	***244***
NYCTA Spill Number/Closed Date: 0608907 / 2006-11-06 Site ID: 372980 Spill Date: 2006-11-02	***25 JAMAICA AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S125***	***387***
NYC-TA EAST NY BUS D Spill Number/Closed Date: 0902562 / 2009-08-24 Site ID: 414609 Spill Date: 2009-05-31	***1 JAMAICA AVE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S130***	***518***
EAST NEW YORK DEPOT Spill Number/Closed Date: 9102804 / 2000-12-27 Site ID: 300659 Spill Date: 1991-06-10	25 JAMAICA AVE/NYCTA	NNE 1/8 - 1/4 (0.175 mi.)	S133	633
1848 STEWART ST Spill Number/Closed Date: 9510983 / 1995-12-01 Site ID: 137876 Spill Date: 1995-12-01	1848 STEWART ST	NNW 1/8 - 1/4 (0.220 mi.)	AA180	743
HESS-MERIT GAS STATI Spill Number/Closed Date: 9704864 / 2003-03-18 Spill Number/Closed Date: 9704866 / 2003-03-18 Site ID: 290955 Site ID: 61682 Spill Date: 1997-07-23	1630-76 BUSHWICK AVE	N 1/8 - 1/4 (0.239 mi.)	AH229	896
228 HULL ST Spill Number/Closed Date: 9600752 / 2003-12-15 Site ID: 207681 Spill Date: 1996-04-16	228 HULL ST	NW 1/4 - 1/2 (0.274 mi.)	267	980
SUNOCO GAS STA Spill Number/Closed Date: 9709845 / 2006-04-14 Site ID: 267776	***35 HIGHLAND BLVD***	***NE 1/4 - 1/2 (0.284 mi.)***	***AK268***	***981***

Spill Date: 1997-11-24

AKA 31-33 MONACO PLA — 2121 MONACO PLACE — W 1/4 - 1/2 (0.299 mi.) — 272 — 989
Spill Number/Closed Date: 0408751 / Not Reported
Site ID: 333492
Spill Date: 2004-11-08

APARTMENT BUILDING — ***211 HULL STREET*** — ***NW 1/4 - 1/2 (0.344 mi.)*** — ***276*** — ***999***
Spill Number/Closed Date: 0612788 / 2007-09-17
Site ID: 377715
Spill Date: 2007-02-26

WOLF PETROLEUM CORP — 1532 BUSHWICK AVE — NNW 1/4 - 1/2 (0.391 mi.) — AN283 — 1019
Spill Number/Closed Date: 0203277 / 2003-09-25
Spill Number/Closed Date: 0212200 / 2004-10-21
Site ID: 122706
Site ID: 153386
Spill Date: 2002-06-27
Spill Date: 2003-03-12

OCEAN HILL HOUSES -N — ***24 STONE AVENUE*** — ***NW 1/4 - 1/2 (0.431 mi.)*** — ***289*** — ***1027***
Spill Number/Closed Date: 9010234 / 2019-01-14
Site ID: 171459
Spill Date: 1990-12-20

20 INTERBOROUGH PKWY — 20 INTERBOROUGH PKWY — NE 1/4 - 1/2 (0.473 mi.) — 298 — 1082
Spill Number/Closed Date: 9213957 / 1993-03-20
Site ID: 244192
Spill Date: 1993-03-20

Lower Elevation	Address	Direction / Distance	Map ID	Page

CON EDISON - VAULT V — ***1 JUNIUS ST*** — ***SSW 0 - 1/8 (0.102 mi.)*** — ***H56*** — ***181***
Spill Number/Closed Date: 0101889 / 2003-08-14
Site ID: 159948
Spill Date: 2001-05-17

VACANT LOT — 170-180 SACKMAN ST — SW 1/8 - 1/4 (0.223 mi.) — T186 — 757
Spill Number/Closed Date: 0510241 / 2006-04-25
Site ID: 356181
Spill Date: 2005-11-29

WARTBURG LUTHERAN HO — ***50 SHEFFIELD AVENUE*** — ***E 1/8 - 1/4 (0.243 mi.)*** — ***AB241*** — ***920***
Spill Number/Closed Date: 0908501 / 2010-01-15
Site ID: 421105
Spill Date: 2009-10-28

UNKNOWN — ***2642 FULTON ST.*** — ***E 1/4 - 1/2 (0.311 mi.)*** — ***AJ274*** — ***995***
Spill Number/Closed Date: 1909031 / Not Reported
Site ID: 599249
Spill Date: 2019-12-15

GLENMORE PLAZA -NYCH — ***108 CHRISTOPHER AVE*** — ***SSW 1/4 - 1/2 (0.375 mi.)*** — ***AL279*** — ***1009***
Spill Number/Closed Date: 9602447 / 1996-07-24
Spill Number/Closed Date: 9611221 / 1996-12-13
Spill Number/Closed Date: 9413245 / 2019-09-10
Site ID: 110612
Site ID: 120585
Site ID: 272843
Spill Date: 1996-05-21
Spill Date: 1996-12-11

Spill Date: 1995-01-04

SETH LOW HOUSES -NYC ***180 POWELL STREET*** ***S 1/4 - 1/2 (0.432 mi.)*** ***290*** ***1033***
Spill Number/Closed Date: 9104796 / 1995-06-28
Spill Number/Closed Date: 9503722 / 2006-02-07
Site ID: 249121
Site ID: 249122
Spill Date: 1991-08-02
Spill Date: 1995-06-26

Not reported ***110 WYONA STREET*** ***E 1/4 - 1/2 (0.448 mi.)*** ***292*** ***1041***
Spill Number/Closed Date: 0411597 / 2005-01-31
Site ID: 336825
Spill Date: 2005-01-28

EXXONMOBIL ***225 PENNSYLVANIA AVE*** ***SE 1/4 - 1/2 (0.464 mi.)*** ***AP294*** ***1050***
Spill Number/Closed Date: 9213037 / 1994-08-25
Spill Number/Closed Date: 0907694 / 2009-11-20
Spill Number/Closed Date: 8807901 / 1994-08-25
Site ID: 173885
Site ID: 420231
Site ID: 63604
Spill Date: 1993-02-22
Spill Date: 2009-10-07
Spill Date: 1988-12-28

CFI STATION #70227 189 PENNSYLVANIA AVE SE 1/4 - 1/2 (0.479 mi.) AP299 1083
Spill Number/Closed Date: 0907625 / 2015-12-09
Site ID: 420161
Spill Date: 2009-10-07

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 20 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
INSTITUTE FOR COMMUN	2384 ATLANTIC AVENUE	WSW 1/8 - 1/4 (0.136 mi.)	I84	242
Database: UST, Date of Government Version: 12/12/2024				
2246 FULTON STREET	50 SACKMAN STREET	WNW 1/8 - 1/4 (0.170 mi.)	K114	358
Database: UST, Date of Government Version: 12/12/2024				
OUR LADY OF LORETO C	***124 SACKMAN ST***	***WSW 1/8 - 1/4 (0.171 mi.)***	***Q115***	***362***
Database: UST, Date of Government Version: 12/12/2024				
EAST NEW YORK TRUCK	***1997 BROADWAY***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S126***	***417***
Database: UST, Date of Government Version: 12/12/2024				
EAST NEW YORK BUS DE	25 JAMAICA AVENUE	NNE 1/8 - 1/4 (0.175 mi.)	S127	419
Database: UST, Date of Government Version: 12/12/2024				
EAST NEW YORK BOILER	***1 JAMAICA AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S132***	***627***
Database: UST, Date of Government Version: 12/12/2024				
SOLID GOLD TOWING IN	***1960 BROADWAY***	***NNW 1/8 - 1/4 (0.182 mi.)***	***N138***	***644***
Database: UST, Date of Government Version: 12/12/2024				

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MILTON UNGER	***2234 FULTON STREET***	***WNW 1/8 - 1/4 (0.200 mi.)***	***X161***	***696***
Database: UST, Date of Government Version: 12/12/2024				
PARK AVENUE BUILDING	68 CONWAY STREET	N 1/8 - 1/4 (0.204 mi.)	Y168	715
Database: UST, Date of Government Version: 12/12/2024				
BRADFORD SWETT	2000 EASTERN PARKWAY	NNW 1/8 - 1/4 (0.235 mi.)	AA217	861
Database: UST, Date of Government Version: 12/12/2024				
HARRY T NANCE APARTM	1860 EASTERN PARKWAY	W 1/8 - 1/4 (0.237 mi.)	AD221	867
Database: UST, Date of Government Version: 12/12/2024				
AMERICAN TRUCK REPAI	***2020 EASTERN PARKWAY***	***NNW 1/8 - 1/4 (0.238 mi.)***	***AA223***	***871***
Database: UST, Date of Government Version: 12/12/2024				
SPEEDWAY # 7812	***1630 BUSHWICK AVENUE***	***N 1/8 - 1/4 (0.239 mi.)***	***AH225***	***879***
Database: UST, Date of Government Version: 12/12/2024				

Lower Elevation	Address	Direction / Distance	Map ID	Page
PEREY TURNSTILES	***2490 ATLANTIC AVENUE***	***SSE 0 - 1/8 (0.079 mi.)***	***F45***	***150***
Database: UST, Date of Government Version: 12/12/2024				
EAST NEW SERVICE COR	36 SNEDIKER AVENUE	SSE 1/8 - 1/4 (0.126 mi.)	J78	227
Database: UST, Date of Government Version: 12/12/2024				
BROADWAY FILTON	2090 BROADWAY	ENE 1/8 - 1/4 (0.139 mi.)	L87	249
Database: UST, Date of Government Version: 12/12/2024				
ROYAL LACE CORP.	200 LIBERTY AVENUE	S 1/8 - 1/4 (0.212 mi.)	U177	738
Database: UST, Date of Government Version: 12/12/2024				
JAMAICA ISLAND CORP.	32 JAMAICA AVENUE	ENE 1/8 - 1/4 (0.230 mi.)	W209	834
Database: UST, Date of Government Version: 12/12/2024				
WARTBURG LUTHERAN HO	50 SHEFFIELD AVENUE	E 1/8 - 1/4 (0.243 mi.)	AB243	924
Database: UST, Date of Government Version: 12/12/2024				
METRO STRUCTURAL STE	282 LIBERTY AVENUE	SE 1/8 - 1/4 (0.245 mi.)	V248	941
Database: UST, Date of Government Version: 12/12/2024				

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 12/12/2024 has revealed that there are 3 NY CBS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYCTA	***25 JAMAICA AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S125***	***387***
Facility Status: Unregulated/Closed				
CBS Number: 2-000284				
EAST NEW YORK TRUCK	***1997 BROADWAY***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S126***	***417***
Facility Status: Unregulated/Closed				
CBS Number: 2-000445				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHINY CAR WASH & LUB	***2591 ATLANTIC AVE***	***E 1/8 - 1/4 (0.244 mi.)***	***AB245***	***932***

Facility Status: Unregulated/Closed
CBS Number: 2-000511

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 20 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
2440 FULTON STREET Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-613260	2440 FULTON STREET	NNE 0 - 1/8 (0.066 mi.)	C36	136
EAST NEW YORK TRUCK Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-000445	1997 BROADWAY	NE 0 - 1/8 (0.108 mi.)	G59	187
EAST NEW YORK TRUCK Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-609105	1997 BROADWAY	NE 0 - 1/8 (0.108 mi.)	G63	191
2402 ATLANTIC HOLDIN Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-608095	2402 ATLANTIC AVENUE	WSW 0 - 1/8 (0.114 mi.)	I71	215
MAGNOLIA HOUSE Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-608733	1430 HERKIMER STREET	WNW 1/8 - 1/4 (0.158 mi.)	O107	341
EAST NEW YORK BOILER Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-609104	***1 JAMAICA AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S132***	***627***
EAST NEW YORK CMF Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-609106	1730 BUSHWICK AVENUE	NNE 1/8 - 1/4 (0.175 mi.)	S134	635
MILTON UNGER Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-607309	***2234 FULTON STREET***	***WNW 1/8 - 1/4 (0.200 mi.)***	***X161***	***696***
SACKMAN REALTY LLC Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-611080	10 SACKMAN ST	NW 1/8 - 1/4 (0.227 mi.)	AA194	797
SPEEDWAY # 7812 Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-297739	***1630 BUSHWICK AVENUE***	***N 1/8 - 1/4 (0.239 mi.)***	***AH225***	***879***
SLS CAR WASH, INC. Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-610338	1650 BUSHWICK AVENUE	N 1/8 - 1/4 (0.244 mi.)	AH247	936

Lower Elevation	Address	Direction / Distance	Map ID	Page
APEX AIRTRONICS INC Database: AST, Date of Government Version: 12/12/2024 Facility Id: 2-611061	2465 ATLANTIC AVE	SSW 0 - 1/8 (0.009 mi.)	A4	25
JUNIUS DEVELOPMENT L Database: AST, Date of Government Version: 12/12/2024	1-25 JUNIUS STREET	SSW 0 - 1/8 (0.102 mi.)	H53	175

Facility Id: 2-604881

CONSOLIDATED BUS | 10 JUNIUS STREET | SSW 0 - 1/8 (0.116 mi.) | H75 | 224
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-613222

20-50 POWELL STREET | 20-50 POWELL STREET | SW 1/8 - 1/4 (0.180 mi.) | T137 | 642
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-612527

EAST NEW YORK BUS DE | 25 JAMAICA AVENUE | ENE 1/8 - 1/4 (0.224 mi.) | W190 | 767
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-190292

EAST NEW YORK BUS DE | 25 JAMAICA AVENUE | ENE 1/8 - 1/4 (0.224 mi.) | W192 | 790
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-000284

SHINY CAR WASH AND Q | 2591 ATLANTIC AVENUE | E 1/8 - 1/4 (0.244 mi.) | AB244 | 927
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-609840

SHINY CAR WASH & LUB | 2591 ATLANTIC AVE | E 1/8 - 1/4 (0.244 mi.) | AB245 | 932
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-000511

GRAFTON REALTY CORP. | 1660 EAST NEW YORK A | SW 1/8 - 1/4 (0.244 mi.) | 246 | 934
Database: AST, Date of Government Version: 12/12/2024
Facility Id: 2-082570

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYCTA	***25 JAMAICA AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S125***	***387***
Facility Status: 1 Facility Status: 1 CBS Number: 2-000284				

NY TANKS: This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

A review of the NY TANKS list, as provided by EDR, has revealed that there is 1 NY TANKS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WROUGHT ORIGINALS IN	38 VAN SINDERIN AVE	NNW 0 - 1/8 (0.052 mi.)	D26	114
Database: TANKS, Date of Government Version: 12/12/2024 Facility Id: 2-608012				

Site Status: Unregulated/Closed

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 16 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
2440 FULTON STREET	***2440 FULTON STREET***	***NNE 0 - 1/8 (0.066 mi.)***	***C35***	***135***
Database: VCP NYC, Date of Government Version: 12/02/2024				
INSTITUTE FOR COMMUN	***2384 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.136 mi.)***	***I85***	***244***
Database: VCP NYC, Date of Government Version: 12/02/2024				
Not reported	***156 SOMERS STREET***	***NW 1/8 - 1/4 (0.210 mi.)***	***AA175***	***735***
Database: VCP NYC, Date of Government Version: 12/02/2024				
LOT 6,TAXBLOCK 1436	***1860 EASTERN PARKWAY***	***W 1/8 - 1/4 (0.237 mi.)***	***AD220***	***865***
Database: VCP NYC, Date of Government Version: 12/02/2024				

Lower Elevation	Address	Direction / Distance	Map ID	Page
81-111 JUNIUS STREET	***81 JUNIUS STREET***	***S 1/8 - 1/4 (0.242 mi.)***	***237***	***911***
Database: VCP NYC, Date of Government Version: 12/02/2024				
50 PENN LLC	***2618 FULTON ST***	***E 1/4 - 1/2 (0.264 mi.)***	***AJ264***	***972***
Database: VCP NYC, Date of Government Version: 12/02/2024				
DEAN STREET - HABITA	***2396 DEAN STREET***	***WSW 1/4 - 1/2 (0.272 mi.)***	***AC265***	***975***
Database: VCP NYC, Date of Government Version: 12/02/2024				
CON EDISON SERVICE B	***103 LIBERTY AVE***	***SW 1/4 - 1/2 (0.297 mi.)***	***271***	***985***
Database: VCP NYC, Date of Government Version: 12/02/2024				
2175 BERGEN STREET	***217-221 MOTHER GASTO***	***WSW 1/4 - 1/2 (0.301 mi.)***	***273***	***994***
Database: VCP NYC, Date of Government Version: 12/02/2024				
117 GLENMORE AVENUE	***117 GLENMORE AVENUE***	***SSW 1/4 - 1/2 (0.355 mi.)***	***AL277***	***1007***
Database: VCP NYC, Date of Government Version: 12/02/2024				
2667 FULTON STREET	***2667 FULTON STREET***	***E 1/4 - 1/2 (0.367 mi.)***	***278***	***1008***
Database: VCP NYC, Date of Government Version: 12/02/2024				
157 NEW JERSEY AVENU	***157 NEW JERSEY AVENU***	***E 1/4 - 1/2 (0.378 mi.)***	***280***	***1015***
Database: VCP NYC, Date of Government Version: 12/02/2024				
LOT 35,TAXBLOCK 3703	***184 PENNSYLVANIA AVE***	***ESE 1/4 - 1/2 (0.399 mi.)***	***285***	***1022***
Database: VCP NYC, Date of Government Version: 12/02/2024				
2701-2715 FULTON STR	***2701-2715 FULTON STR***	***E 1/4 - 1/2 (0.425 mi.)***	***AO288***	***1027***
Database: VCP NYC, Date of Government Version: 12/02/2024				
2700 ATLANTIC AVENUE	***2700 ATLANTIC AVENUE***	***E 1/4 - 1/2 (0.443 mi.)***	***291***	***1041***
Database: VCP NYC, Date of Government Version: 12/02/2024				
Not reported	***2718 FULTON STREET***	***E 1/4 - 1/2 (0.460 mi.)***	***AO293***	***1048***
Database: VCP NYC, Date of Government Version: 12/02/2024				

EXECUTIVE SUMMARY

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 11/04/2024 has revealed that there are 2 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 46,TAXBLOCK 1437 Site Code: 617184	***2435 PACIFIC STREET***	***SW 0 - 1/8 (0.113 mi.)***	***I67***	***203***
114 SNEDIKER AVENUE Site Code: 647562	221-241 GLENMORE AVE	S 1/4 - 1/2 (0.272 mi.)	266	976

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

Registered Recycling Facility List from the Department of Environmental Conservation.

A review of the NY SWRCY list, as provided by EDR, and dated 12/11/2024 has revealed that there is 1 NY SWRCY site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONWIDE SCRAP LLC	178-214 SNEDIKER AVE	SSE 1/4 - 1/2 (0.402 mi.)	AM286	1025

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 11/03/2024 has revealed that there are 21 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HERKIMER ST AND BROA Spill Number/Closed Date: 9702860 / 2003-02-03 Site ID: 220190 Spill Date: 1997-06-06	HERKIMER ST AND BROA	NE 0 - 1/8 (0.031 mi.)	A18	89
SPILL NUMBER 0007586 Spill Number/Closed Date: 0007586 / 2002-09-10 Site ID: 263609 Spill Date: 2000-09-28	1 HAVENS PL	NW 0 - 1/8 (0.055 mi.)	D28	116
NYCTA - 30 HAVENS PL Spill Number/Closed Date: 0106974 / 2005-12-19 Site ID: 289484	***30 HAVENS PL***	***WNW 0 - 1/8 (0.057 mi.)***	***E31***	***121***

Spill Date: 2001-10-05

DRUM RUN Spill Number/Closed Date: 2108368 / 2022-02-17 Site ID: 630309 Spill Date: 2021-12-14	WILLIAMS PLACE AND F	NNE 0 - 1/8 (0.068 mi.)	C38	139
MANHOLE #04264 Spill Number/Closed Date: 0601203 / 2006-06-14 Site ID: 363385 Spill Date: 2006-05-02	FULTON STREET & VAN	N 0 - 1/8 (0.078 mi.)	D43	148
VANSINDREN AVE Spill Number/Closed Date: 0708240 / 2007-10-29 Site ID: 389092 Spill Date: 2007-10-27	AT FULTON STREET	N 0 - 1/8 (0.078 mi.)	D44	149
NYC TRANSIT EAST NY Spill Number/Closed Date: 1509110 / 2015-12-07 Site ID: 517716 Spill Date: 2015-12-07	1997 BROADWAY	NE 0 - 1/8 (0.108 mi.)	G61	189
EAST NY TRUCK SHOP Spill Number/Closed Date: 1606041 / 2016-09-16 Site ID: 532632 Spill Date: 2016-09-15	1997 BROADWAY	NE 0 - 1/8 (0.108 mi.)	G62	190
FLYING SERVICE BOX C Spill Number/Closed Date: 0514131 / 2009-09-10 Spill Number/Closed Date: 0514130 / 2006-03-10 Site ID: 360779 Site ID: 360778 Spill Date: 2006-03-09	2402 ATLANTIC AVE	WSW 0 - 1/8 (0.114 mi.)	I68	209
VAULT VS2603 Spill Number/Closed Date: 0206776 / 2004-01-20 Site ID: 267009 Spill Date: 2002-09-30	2051 BROADWAY	ENE 0 - 1/8 (0.114 mi.)	G72	217

Lower Elevation	Address	Direction / Distance	Map ID	Page
FACTORY Spill Number/Closed Date: 0708834 / 2009-04-06 Site ID: 389803 Spill Date: 2007-11-13	2465 ATLANTIC AVE	SSW 0 - 1/8 (0.009 mi.)	A5	27
MANHOLE 66367 Spill Number/Closed Date: 9908416 / 1999-12-08 Site ID: 82598 Spill Date: 1999-10-11	WILLIAMS AVE+LAVONIA	SE 0 - 1/8 (0.027 mi.)	A16	85
SPILL NUMBER 0007769 Spill Number/Closed Date: 0007769 / 2004-02-17 Site ID: 146481 Spill Date: 2000-09-29	HAVEL PLACE & ATLANT	WSW 0 - 1/8 (0.056 mi.)	E29	117
NYC TRANSIT PARKING Spill Number/Closed Date: 1102080 / 2011-05-27 Site ID: 449570 Spill Date: 2011-05-25	HAVENS PLACE AND ATL	WSW 0 - 1/8 (0.058 mi.)	E33	130
EAST NY SUMP STATION	1762 EAST NEW YORK A	S 0 - 1/8 (0.074 mi.)	B39	140

Spill Number/Closed Date: 2100177 / 2021-06-30 Site ID: 617846 Spill Date: 2021-04-07				
DRUM RUN Spill Number/Closed Date: 0407976 / 2004-11-01 Site ID: 332572 Spill Date: 2004-10-18	2509 ATLANTIC AVE	ESE 0 - 1/8 (0.075 mi.)	F40	143
PEREY TURNSTILES Spill Number/Closed Date: 9812107 / 1999-05-17 Site ID: 263377 Spill Date: 1998-12-29	***2490 ATLANTIC AVENUE***	***SSE 0 - 1/8 (0.079 mi.)***	***F45***	***150***
209176; HINSDALE ST; Spill Number/Closed Date: 0890327 / 2007-12-28 Site ID: 399415 Spill Date: 2007-12-18	HINSDALE ST; M-65896	SE 0 - 1/8 (0.082 mi.)	F47	157
205454; HINSDALE ST; Spill Number/Closed Date: 0890040 / 2007-04-26 Site ID: 399128 Spill Date: 2007-04-19	HINSDALE ST; M65997	SE 0 - 1/8 (0.082 mi.)	F48	159
VAULT Spill Number/Closed Date: 1606763 / 2017-12-08 Site ID: 533402 Spill Date: 2016-10-10	1 JUNIUS ST	SSW 0 - 1/8 (0.102 mi.)	H54	177
CON EDISON - VAULT V Spill Number/Closed Date: 9610713 / 1998-10-19 Site ID: 159949 Spill Date: 1996-11-26	***1 JUNIUS ST***	***SSW 0 - 1/8 (0.102 mi.)***	***H56***	***181***

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 02/17/2025 has revealed that there are 52 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004148136	***HERKIMER 60 FEET E O***	***NNW 0 - 1/8 (0.025 mi.)***	***A12***	***77***
CON EDISON MANHOLE 6 EPA ID:: NYP004148144	HERKIMER ST & VAN SI	NNW 0 - 1/8 (0.025 mi.)	A14	82
NYCT HERKIMER STREET EPA ID:: NYD982183287	***HERKIMER & WILLIAMS***	***NE 0 - 1/8 (0.033 mi.)***	***A19***	***90***
CON ED - MH 3629 EPA ID:: NYP000928895	***HERKIMER ST & WILLIA***	***NE 0 - 1/8 (0.034 mi.)***	***A21***	***101***
NYCDOT BRIDGE BIN 22	ATLANTIC AVE OVER LI	W 0 - 1/8 (0.039 mi.)	A22	104

EPA ID:: NY0000445619				
CON EDISON SERVICE B EPA ID:: NYP004468666	***63 WILLIAMS PL***	***NE 0 - 1/8 (0.044 mi.)***	***C25***	***111***
NYCTA - 30 HAVENS PL EPA ID:: NY0000340430	***30 HAVENS PL***	***WNW 0 - 1/8 (0.057 mi.)***	***E31***	***121***
NYCTA(BROADWAY ENY S EPA ID:: NYP004748661	***1997 BROADWAY***	***NE 0 - 1/8 (0.108 mi.)***	***G64***	***196***
CON EDISON - MANHOLE EPA ID:: NYP004185344	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N101***	***321***
CON EDISON SERVICE B EPA ID:: NYP004465704	***102 SACKMAN ST***	***W 1/8 - 1/4 (0.160 mi.)***	***P108***	***343***
CON EDISON - MANHOLE EPA ID:: NYP004197497	***2371 ATLANTIC AVE AN***	***W 1/8 - 1/4 (0.169 mi.)***	***P113***	***352***
NYCTA (ENY YARD) HAZ EPA ID:: NYD981140023	***1700 BUSHWICK AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S131***	***588***
CON EDISON MANHOLE: EPA ID:: NYP004529905	***2356 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.194 mi.)***	***P144***	***656***
CON EDISON SERVICE B EPA ID:: NYP004471892	***ATLANTIC AVE & SHERL***	***W 1/8 - 1/4 (0.201 mi.)***	***P166***	***710***
CON EDISON SERVICE B EPA ID:: NYP004550240	***2349 PACIFIC ST***	***WSW 1/8 - 1/4 (0.227 mi.)***	***AD196***	***800***
CON EDISON EPA ID:: NYP004766895	***1385 HERKIMER ST***	***WNW 1/8 - 1/4 (0.229 mi.)***	***X200***	***808***
CON EDISON EPA ID:: NYP004817219	***1716 BUSHWICK AVE***	***NE 1/8 - 1/4 (0.229 mi.)***	***AF205***	***816***
MERIT OIL CORP EPA ID:: NYD982185589	***1630 BUSHWICK AVE***	***N 1/8 - 1/4 (0.239 mi.)***	***AH230***	***898***
CON EDISON SERVICE B EPA ID:: NYP004490033	1910 EASTERN PKWY	WNW 1/8 - 1/4 (0.242 mi.)	X234	906
MTA NYCT - NEW YARD EPA ID:: NYR000087759	***1925 BROADWAY***	***NNW 1/8 - 1/4 (0.242 mi.)***	***AI238***	***912***
CON EDISON SERVICE B EPA ID:: NYP004529723	2346 PACIFIC ST	WSW 1/8 - 1/4 (0.243 mi.)	AC239	916
CON EDISON SERVICE B EPA ID:: NYP004570578	17 STEWART ST	NNW 1/8 - 1/4 (0.245 mi.)	AI251	948

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID:: NYP004456299	***2473 ATLANTIC AVE***	***S 0 - 1/8 (0.009 mi.)***	***A2***	***20***
APEX AIRTRONICS INC- EPA ID:: NYD001284439	***2465 ATLANTIC AVENUE***	***SSW 0 - 1/8 (0.009 mi.)***	***A6***	***29***
CON EDISON HTV5519 EPA ID:: NYP005244694	VAN SIDEREN & ATLANT	SSW 0 - 1/8 (0.024 mi.)	A11	75
CON EDISON EPA ID:: NYP004726642	***90 WILLIAMS ST***	***SE 0 - 1/8 (0.030 mi.)***	***A17***	***87***
CON EDISON SERVICE B	NEW YORK AVE & ATLAN	SSW 0 - 1/8 (0.042 mi.)	B24	109

EPA ID:: NYP004486346				
CON EDISON	***ATLANTIC AVE & HAVEN***	***WSW 0 - 1/8 (0.058 mi.)***	***E34***	***131***
EPA ID:: NYP004194809				
VENTURE METAL PRODUC	***2523 ATLANTIC AVE***	***ESE 0 - 1/8 (0.092 mi.)***	***F51***	***163***
EPA ID:: NYD053563219				
CON ED V 2312	***1 JUNIS ST***	***SSW 0 - 1/8 (0.102 mi.)***	***H55***	***179***
EPA ID:: NYP004003547				
H E L P BROOKLYN HOU	HINSDALE ST & SNEDIK	ESE 1/8 - 1/4 (0.128 mi.)	80	234
EPA ID:: NYD986925220				
CON EDISON	BROADWAY & JAMAICA A	E 1/8 - 1/4 (0.147 mi.)	L97	305
EPA ID:: NYP004825200				
CON EDISON/ ATTN: QU	***JAMAICA AVE & BROADW***	***E 1/8 - 1/4 (0.147 mi.)***	***L98***	***308***
EPA ID:: NYP004134607				
CON EDISON	2572 FULTON ST	E 1/8 - 1/4 (0.165 mi.)	L112	350
EPA ID:: NYP004793527				
CON EDISON	21 ALABAMA AVE	E 1/8 - 1/4 (0.172 mi.)	R119	372
EPA ID:: NYP004793543				
KANES INDUSTRIES	23 ALABAMA AVE	E 1/8 - 1/4 (0.173 mi.)	R120	374
EPA ID:: NYD987001641				
CON EDISON	***23 ALABAMA AVE***	***E 1/8 - 1/4 (0.173 mi.)***	***R122***	***378***
EPA ID:: NYP004726790				
CON EDISON	***2569 ATLANTIC AVE***	***ESE 1/8 - 1/4 (0.186 mi.)***	***R142***	***651***
EPA ID:: NYP004728978				
CON EDISON	***LIBERTY AVE & SNEIDI***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U146***	***660***
EPA ID:: NYP004738654				
CON EDISON	***SNEDIKER AVE & LIBER***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U148***	***664***
EPA ID:: NYP004195053				
CON EDISON	***SNEDIKER AVE & LIBER***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U150***	***670***
EPA ID:: NYP004194650				
CON EDISON	38 GEORGIA AVE	E 1/8 - 1/4 (0.197 mi.)	R154	683
EPA ID:: NYP004876932				
CON EDISON	***44 GEORGIA AVE***	***E 1/8 - 1/4 (0.200 mi.)***	***R160***	***694***
EPA ID:: NYP004820326				
NYC BD OF ED - PUBLI	***275 LIBERTY AVE***	***SE 1/8 - 1/4 (0.222 mi.)***	***V181***	***744***
EPA ID:: NYR000011957				
CON EDISON SERVICE B	***2425 DEAN ST***	***WSW 1/8 - 1/4 (0.223 mi.)***	***AC183***	***750***
EPA ID:: NYP004572301				
CON EDISON	***74 GEORGIA AVE***	***ESE 1/8 - 1/4 (0.228 mi.)***	***AE199***	***806***
EPA ID:: NYP004794962				
CON ED - MH 5143	***LIBERTY AVE & POWELL***	***SSW 1/8 - 1/4 (0.234 mi.)***	***AG211***	***841***
EPA ID:: NYP004010690				
CON EDISON MANHOLE 5	***POWELL ST & LIBERTY***	***SSW 1/8 - 1/4 (0.234 mi.)***	***AG212***	***848***
EPA ID:: NYP004150199				
CON EDISON MANHOLE 5	LIBERTY AVE & POWELL	SSW 1/8 - 1/4 (0.234 mi.)	AG214	853
EPA ID:: NYP004143012				
CON EDISON MANHOLE 5	LIBERTY AVE & POWELL	SSW 1/8 - 1/4 (0.234 mi.)	AG215	855

EPA ID:: NYP004139515				
CON EDISON EPA ID:: NYP004820276	2604 ATLANTIC AVE	ESE 1/8 - 1/4 (0.247 mi.)	AE257	958
CON EDISON MANHOLE: EPA ID:: NYP004449278	***ALABAMA AVE & LIBERT***	***SE 1/8 - 1/4 (0.250 mi.)***	***263***	***969***

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 12/30/2024 has revealed that there are 2 PFAS ECHO sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
APEX AIRTRONICS INC-		SSW 0 - 1/8 (0.024 mi.)	A9	56
STAR POLY BAG INC		SSE 1/8 - 1/4 (0.213 mi.)	U179	742

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 9 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HESS#32507	1630 BUSHWICK AVE	N 1/8 - 1/4 (0.239 mi.)	AH224	878
HESS #32507	1630 BUSHWICK AVE	N 1/8 - 1/4 (0.239 mi.)	AH226	892
HESS-MERIT STATION	1630-76 BUSHWICK AVE	N 1/8 - 1/4 (0.239 mi.)	AH227	893
HESS-MERIT GAS STATI	1630-76 BUSHWICK AVE	N 1/8 - 1/4 (0.239 mi.)	AH231	903
HESS # 32507	1630 BUSHWICK AVE	N 1/8 - 1/4 (0.239 mi.)	AH232	904
SUNOCO GAS STA	35 HIGHLAND BLVD	NE 1/4 - 1/2 (0.284 mi.)	AK269	983
WOLF PETROLEUM CORP	1532 BUSHWICK AVE	NNW 1/4 - 1/2 (0.391 mi.)	AN282	1018

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST NEW YORK DEPOT	25 JAMAICA AVE/NYCTA	ENE 1/8 - 1/4 (0.224 mi.)	W188	766
EXXONMOBIL	225 PENNSYLVANIA AVE	SE 1/4 - 1/2 (0.464 mi.)	AP295	1066

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are

EXECUTIVE SUMMARY

18 UST FINDER sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EAST NEW YORK TRUCK	1997 BROADWAY	NE 0 - 1/8 (0.108 mi.)	G60	188
INSTITUTE FOR COMMUN	2384 ATLANTIC AVENUE	WSW 1/8 - 1/4 (0.136 mi.)	I82	239
OUR LADY OF LORETO C	124 SACKMAN ST	WSW 1/8 - 1/4 (0.171 mi.)	Q116	368
SOLID GOLD TOWING IN	1960 BROADWAY	NNW 1/8 - 1/4 (0.182 mi.)	N139	648
MILTON UNGER	2234 FULTON STREET	WNW 1/8 - 1/4 (0.200 mi.)	X162	700
PARK AVENUE BUILDING	68 CONWAY STREET	N 1/8 - 1/4 (0.204 mi.)	Y169	718
BRADFORD SWETT	2000 EASTERN PARKWAY	NNW 1/8 - 1/4 (0.235 mi.)	AA218	863
AMERICAN TRUCK REPAI	2020 EASTERN PARKWAY	NNW 1/8 - 1/4 (0.238 mi.)	AA222	869
SPEEDWAY # 7812	1630 BUSHWICK AVENUE	N 1/8 - 1/4 (0.239 mi.)	AH228	893

Lower Elevation	Address	Direction / Distance	Map ID	Page
PEREY TURNSTILES	2490 ATLANTIC AVENUE	SSE 0 - 1/8 (0.079 mi.)	F46	156
EAST NEW SERVICE COR	36 SNEDIKER AVENUE	SSE 1/8 - 1/4 (0.126 mi.)	J79	232
BROADWAY FILTON	2090 BROADWAY	ENE 1/8 - 1/4 (0.139 mi.)	L86	248
EAST NEW YORK BOILER	1 JAMAICA AVENUE	ENE 1/8 - 1/4 (0.198 mi.)	W157	690
ROYAL LACE CORP.	200 LIBERTY AVENUE	S 1/8 - 1/4 (0.212 mi.)	U178	741
EAST NEW YORK BUS DE	25 JAMAICA AVENUE	ENE 1/8 - 1/4 (0.224 mi.)	W191	786
JAMAICA ISLAND CORP.	32 JAMAICA AVENUE	ENE 1/8 - 1/4 (0.230 mi.)	W210	840
WARTBURG LUTHERAN HO	50 SHEFFIELD AVENUE	E 1/8 - 1/4 (0.243 mi.)	AB242	923
METRO STRUCTURAL STE	282 LIBERTY AVENUE	SE 1/8 - 1/4 (0.245 mi.)	V249	944

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 02/17/2025 has revealed that there are 40 E MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYCTA(BROADWAY ENY S	***1997 BROADWAY***	***NE 0 - 1/8 (0.108 mi.)***	***G64***	***196***
CON EDISON - COMPANY	OPP 2003 BROADWAY	NE 0 - 1/8 (0.109 mi.)	G65	200
CONSOLIDATED EDISON	2402 ATLANTIC AVE	WSW 0 - 1/8 (0.114 mi.)	I69	211
CON EDISON	2402 ATLANTIC AVE	WSW 0 - 1/8 (0.114 mi.)	I70	213
CON EDISON - VAULT S	***2051 BROADWAY***	***ENE 0 - 1/8 (0.114 mi.)***	***G73***	***219***
CON EDISON	2360 FULTON ST	NW 1/8 - 1/4 (0.131 mi.)	K81	237
ACT TEAMS	2384 ATLANTIC AVE	WSW 1/8 - 1/4 (0.136 mi.)	I83	240
CON EDISON	BROADWAY & TRUXTON S	N 1/8 - 1/4 (0.149 mi.)	N102	326
MTA NYCT - BROADWAY	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N103***	***328***
CON EDISON	1 CONWAY ST	NNW 1/8 - 1/4 (0.155 mi.)	106	339
MTA NYCT - EAST NY D	***25 JAMAICA AVE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S128***	***432***
NYCT-40 CONWAY ST	***40 CONWAY ST***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S129***	***482***
NYCTA (ENY YARD) HAZ	***1700 BUSHWICK AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S131***	***588***
CON EDISON	BROADWAY & CONWAY ST	NNW 1/8 - 1/4 (0.176 mi.)	N135	638
CON EDISON/ ATTN: BR	2361 ATLANTIC AVE	W 1/8 - 1/4 (0.187 mi.)	P143	654
CON EDISON/ ATTN: BR	2363 PACIFIC STREET	WSW 1/8 - 1/4 (0.196 mi.)	Q151	675
CON EDISON - BROOKLY	1401 HERKIMER ST	WNW 1/8 - 1/4 (0.206 mi.)	X172	723
CON EDISON/ ATTN: BR	1401 HERKIMER ST	WNW 1/8 - 1/4 (0.206 mi.)	X173	725
156-158 SOMERS ST LL	***156-158 SOMERS ST***	***NW 1/8 - 1/4 (0.210 mi.)***	***AA174***	***726***
NYCTA (NON-HAZ CONTR	1720 BUSHWICK AVENUE	NE 1/8 - 1/4 (0.230 mi.)	AF206	818
CON EDISON/ ATTN: BR	1700 BUSHWICK AVE	NNE 1/8 - 1/4 (0.230 mi.)	AF207	820
CON EDISON/QUEENS EN	281 2216 FULTON ST.	WNW 1/8 - 1/4 (0.242 mi.)	X236	909
CON EDISON - COMPANY	1652 BUSHWICK AVE	NNE 1/8 - 1/4 (0.246 mi.)	AH255	955

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - QUEENS	9 HIGHLAND BLVD	NE 1/8 - 1/4 (0.248 mi.)	AF262	967

Lower Elevation	Address	Direction / Distance	Map ID	Page
NOBLE SIGNS	2465 ATLANTIC AVE	SSW 0 - 1/8 (0.009 mi.)	A3	23
CON EDISON	2430 ATLANTIC AVE	SW 0 - 1/8 (0.076 mi.)	E41	144
MTA NYCT - JAMAICA L	***KENT AVE & S 6TH ST***	***E 1/8 - 1/4 (0.146 mi.)***	***L88***	***254***
CON EDISON/ ATTN: QU	***JAMAICA AVE & BROADW***	***E 1/8 - 1/4 (0.147 mi.)***	***L98***	***308***
CON EDISON/ ATTN: BR	2408 PACIFIC ST	SW 1/8 - 1/4 (0.148 mi.)	I100	319
PACIFIC STREET IRA	2402A PACIFIC ST	SW 1/8 - 1/4 (0.161 mi.)	I109	346
CONSOLIDATED EDISON-	92 WILLIAMS AVE	SE 1/8 - 1/4 (0.197 mi.)	V153	681
ACT TEAMS	2581 ATLANTIC AVE ST	ESE 1/8 - 1/4 (0.201 mi.)	R163	701
EAST NEW YORK HEALTH	2581 ATLANTIC AVE	ESE 1/8 - 1/4 (0.201 mi.)	R164	703
ACT TEAMS	2581 ATLANTIC AVE, S	ESE 1/8 - 1/4 (0.201 mi.)	R165	708
CON EDISON/ ATTN: BR	2372 PACIFIC ST	WSW 1/8 - 1/4 (0.202 mi.)	Q167	713
BP #30129	***32 JAMAICA AVE***	***ENE 1/8 - 1/4 (0.230 mi.)***	***W208***	***822***
CON EDISON	103 SNEDIKER AVE	SSE 1/8 - 1/4 (0.236 mi.)	U219	864
CON EDISON/ ATTN: BR	2409 DEAN ST	WSW 1/8 - 1/4 (0.245 mi.)	AC250	946
NYC ENVIRONMENTAL PR	127 LIBERTY AVE	SSW 1/8 - 1/4 (0.247 mi.)	AG259	961
CON EDISON	2599 ATLANTIC AVE	ESE 1/8 - 1/4 (0.247 mi.)	AB260	963

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 10/07/2024 has revealed that there are 6 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 16,TAXBLOCK 1554	***1495 HERKIMER STREET***	***NW 0 - 1/8 (0.056 mi.)***	***D30***	***119***
LOT 23,TAXBLOCK 1574	***30 HAVENS PLACE***	***WNW 0 - 1/8 (0.057 mi.)***	***E32***	***128***
LOT 32,TAXBLOCK 1574	***2413 ATLANTIC AVENUE***	***W 0 - 1/8 (0.086 mi.)***	***E50***	***161***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 23,TAXBLOCK 1437	ATLANTIC AVENUE	SW 0 - 1/8 (0.066 mi.)	B37	138
LOT 21,TAXBLOCK 1437	***2432 ATLANTIC AVENUE***	***SW 0 - 1/8 (0.076 mi.)***	***E42***	***146***
LOT 46,TAXBLOCK 1437	***2435 PACIFIC STREET***	***SW 0 - 1/8 (0.113 mi.)***	***I67***	***203***

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUG, BELMONT WORKS	BELMONT & ALABAMA AV	SSE 1/4 - 1/2 (0.487 mi.)	AQ300	1086

EXECUTIVE SUMMARY

Facility Id: HS2005

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are 73 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004148136	***HERKIMER 60 FEET E O***	***NNW 0 - 1/8 (0.025 mi.)***	***A12***	***77***
CONSOLIDATED EDISON EPA ID: NYP004148144	HERKIMER ST & VAN SI	NNW 0 - 1/8 (0.025 mi.)	A13	80
CONSOLIDATED EDISON EPA ID: NYP004184594	HERKIMER ST & VAN SI	NNW 0 - 1/8 (0.026 mi.)	A15	84
NYCT HERKIMER STREET EPA ID: NYD982183287	***HERKIMER & WILLIAMS***	***NE 0 - 1/8 (0.033 mi.)***	***A19***	***90***
NYC TRANSIT CPM ENV- EPA ID: NYD000076257	WILLIAMS PL & HERKIM	NE 0 - 1/8 (0.034 mi.)	A20	99
CON ED - MH 3629 EPA ID: NYP000928895	***HERKIMER ST & WILLIA***	***NE 0 - 1/8 (0.034 mi.)***	***A21***	***101***
CON EDISON SERVICE B EPA ID: NYP004468666	***63 WILLIAMS PL***	***NE 0 - 1/8 (0.044 mi.)***	***C25***	***111***
NYCTA - 30 HAVENS PL EPA ID: NY0000340430	***30 HAVENS PL***	***WNW 0 - 1/8 (0.057 mi.)***	***E31***	***121***
CON EDISON EPA ID: NYP004717518	FRONT OF 2493 FULTON	NE 0 - 1/8 (0.085 mi.)	C49	160
CON EDISON EPA ID: NYP005115332	2020 BROADWAY	ENE 0 - 1/8 (0.106 mi.)	G58	187
CON EDISON EPA ID: NYP004719621	FRONT OF 12 JARDINE	W 0 - 1/8 (0.112 mi.)	66	202
CON EDISON EPA ID: NYP005115324	2051 BROADWAY	ENE 0 - 1/8 (0.114 mi.)	G74	223
CON EDISON - MANHOLE EPA ID: NYP004185344	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N101***	***321***
MTA NYCT - MANHOLE A EPA ID: NYP000967760	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N104***	***333***
MTA NYCT - BROADWAY EPA ID: NYR000236273	BROADWAY & VAN SINDE	N 1/8 - 1/4 (0.149 mi.)	N105	338
CON EDISON SERVICE B EPA ID: NYP004465704	***102 SACKMAN ST***	***W 1/8 - 1/4 (0.160 mi.)***	***P108***	***343***
CON EDISON - MANHOLE EPA ID: NYP004197497	***2371 ATLANTIC AVE AN***	***W 1/8 - 1/4 (0.169 mi.)***	***P113***	***352***
OUR LADY OF LORETO C EPA ID: NYP004631859	***124 SACKMAN ST***	***WSW 1/8 - 1/4 (0.171 mi.)***	***Q115***	***362***
NYCTA	***25 JAMAICA AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S125***	***387***

EPA ID: NYD991290677				
NYCT-40 CONWAY ST EPA ID: NYR000027821	***40 CONWAY ST***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S129***	***482***
NYCTA (ENY YARD) HAZ EPA ID: NYD981140023	***1700 BUSHWICK AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S131***	***588***
CON EDISON EPA ID: NYP004529905	2356 ATLANTIC AVE	WSW 1/8 - 1/4 (0.194 mi.)	P145	658
CON EDISON SERVICE B EPA ID: NYP004471892	***ATLANTIC AVE & SHERL***	***W 1/8 - 1/4 (0.201 mi.)***	***P166***	***710***
EINAV GELBERG EPA ID: NYR000255042	156-158 SOMERS ST	NW 1/8 - 1/4 (0.210 mi.)	AA176	737
CON EDISON EPA ID: NYP004632832	***2342 ATLANTIC AV***	***WSW 1/8 - 1/4 (0.225 mi.)***	***AD193***	***792***
CON EDISON EPA ID: NYP004550240	2349 PACIFIC ST	WSW 1/8 - 1/4 (0.227 mi.)	AD195	799
CON EDISON EPA ID: NYP004766895	1385 HERKIMER ST	WNW 1/8 - 1/4 (0.229 mi.)	X202	812
CON ED EPA ID: NYP004817219	1716 BUSHWICK AVE	NE 1/8 - 1/4 (0.229 mi.)	AF203	813
MERIT OIL CORP EPA ID: NYD982185589	***1630 BUSHWICK AVE***	***N 1/8 - 1/4 (0.239 mi.)***	***AH230***	***898***
CON EDISON EPA ID: NYP004490033	1910 EASTERN PKWY	WNW 1/8 - 1/4 (0.242 mi.)	X235	908
MTA NYCT - NEW YARD EPA ID: NYR000087759	***1925 BROADWAY***	***NNW 1/8 - 1/4 (0.242 mi.)***	***AI238***	***912***
CON EDISON EPA ID: NYP004529723	2346 PACIFIC ST	WSW 1/8 - 1/4 (0.243 mi.)	AC240	919
CON EDISON EPA ID: NYP004570578	17 STEWART ST	NNW 1/8 - 1/4 (0.245 mi.)	AI252	950
CON EDISON EPA ID: NYP004620266	FO 1654 BUSHWICK AVE	NNE 1/8 - 1/4 (0.246 mi.)	AH253	951
CON EDISON EPA ID: NYP004620324	1652 BUSHWICK AVE	NNE 1/8 - 1/4 (0.246 mi.)	AH254	953

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID: NYP004456299	***2473 ATLANTIC AVE***	***S 0 - 1/8 (0.009 mi.)***	***A2***	***20***
APEX AIRTRONICS INC- EPA ID: NYD001284439	***2465 ATLANTIC AVENUE***	***SSW 0 - 1/8 (0.009 mi.)***	***A6***	***29***
NYCDEP EPA ID: NYP010000214	30 WILLIAMS PL	ENE 0 - 1/8 (0.018 mi.)	A7	54
NYCTA - ATLANTIC AVE EPA ID: NYR000042838	***ATLANTIC AVE & VAN S***	***SSW 0 - 1/8 (0.024 mi.)***	***A10***	***57***
CON EDISON EPA ID: NYP004486346	NEW YORK AVE & ATLAN	SSW 0 - 1/8 (0.042 mi.)	B23	107
CON EDISON	***ATLANTIC AVE & HAVEN***	***WSW 0 - 1/8 (0.058 mi.)***	***E34***	***131***

EPA ID: NYP004194809				
VENTURE METAL PRODUC EPA ID: NYD053563219	***2523 ATLANTIC AVE***	***ESE 0 - 1/8 (0.092 mi.)***	***F51***	***163***
CON ED V 2312 EPA ID: NYP004003547	***1 JUNIS ST***	***SSW 0 - 1/8 (0.102 mi.)***	***H55***	***179***
CON EDISON - VAULT V EPA ID: NYP004994735	***1 JUNIUS ST***	***SSW 0 - 1/8 (0.102 mi.)***	***H56***	***181***
CON EDISON EPA ID: NYP004602231	F/O 2395 PACIFIC ST	WSW 1/8 - 1/4 (0.147 mi.)	I89	282
CON EDISON EPA ID: NYP004868172	60 WILLIAMS AVE	SE 1/8 - 1/4 (0.147 mi.)	M90	284
NYCTA - BROADWAY ENY EPA ID: NYR000072777	***BROADWAY & JAMAICA A***	***E 1/8 - 1/4 (0.147 mi.)***	***L95***	***291***
CON ED EPA ID: NYP004825200	BROADWAY & JAMAICA A	E 1/8 - 1/4 (0.147 mi.)	L96	304
CON EDISON/ ATTN: QU EPA ID: NYP004134607	***JAMAICA AVE & BROADW***	***E 1/8 - 1/4 (0.147 mi.)***	***L98***	***308***
CON EDISON - MANHOLE EPA ID: NYP004198453	***BROADWAY AND JAMAICA***	***E 1/8 - 1/4 (0.147 mi.)***	***L99***	***315***
CON EDISON EPA ID: NYP004793527	2572 FULTON ST	E 1/8 - 1/4 (0.165 mi.)	L110	348
CON EDISON EPA ID: NYP004793543	21 ALABAMA AVE	E 1/8 - 1/4 (0.172 mi.)	R117	369
CON EDISON EPA ID: NYP004726790	23 ALABAMA AVE	E 1/8 - 1/4 (0.173 mi.)	R123	381
CON EDISON EPA ID: NYP004728978	2569 ATLANTIC AVE	ESE 1/8 - 1/4 (0.186 mi.)	R140	649
CON EDISON EPA ID: NYP004195053	***SNEDIKER AVE & LIBER***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U148***	***664***
CON EDISON EPA ID: NYP004738654	LIBERTY AVE & SNEIDI	SSE 1/8 - 1/4 (0.196 mi.)	U149	669
CON EDISON EPA ID: NYP004194650	***SNEDIKER AVE & LIBER***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U150***	***670***
CON EDISON - SERVICE EPA ID: NYP004903884	***92 WILLIAMS AVE***	***SE 1/8 - 1/4 (0.197 mi.)***	***V152***	***677***
CON EDISON - MANHOLE EPA ID: NYP004198198	***1 JAMAICA AVE AND BR***	***ENE 1/8 - 1/4 (0.198 mi.)***	***W156***	***686***
CON EDISON EPA ID: NYP004820326	44 GEORGIA AVE	E 1/8 - 1/4 (0.200 mi.)	R159	692
NYC BD OF ED - PUBLI EPA ID: NYR000011957	***275 LIBERTY AVE***	***SE 1/8 - 1/4 (0.222 mi.)***	***V181***	***744***
CON EDISON EPA ID: NYP004603775	51 GEORGIA AVE	E 1/8 - 1/4 (0.223 mi.)	AB182	749
CON EDISON EPA ID: NYP004572301	2425 DEAN ST	WSW 1/8 - 1/4 (0.223 mi.)	AC184	753
NYCTA	25 JAMAICA AVE NYD99	ENE 1/8 - 1/4 (0.224 mi.)	W187	759

EPA ID: NYT370011371				
CON EDISON EPA ID: NYP004794962	74 GEORGIA AVE	ESE 1/8 - 1/4 (0.228 mi.)	AE198	804
BP #30129 EPA ID: NYD986963064	***32 JAMAICA AVE***	***ENE 1/8 - 1/4 (0.230 mi.)***	***W208***	***822***
CON ED - MH 5143 EPA ID: NYP004139515 EPA ID: NYP004010690	***LIBERTY AVE & POWELL***	***SSW 1/8 - 1/4 (0.234 mi.)***	***AG211***	***841***
CON EDISON MANHOLE 5 EPA ID: NYP004150199	***POWELL ST & LIBERTY***	***SSW 1/8 - 1/4 (0.234 mi.)***	***AG212***	***848***
CONSOLIDATED EDISON EPA ID: NYP004147526	LIBERTY AVE & POWELL	SSW 1/8 - 1/4 (0.234 mi.)	AG213	851
CONSOLIDATED EDISON EPA ID: NYP004103420	POWELL & LIBERTY AVE	SSW 1/8 - 1/4 (0.235 mi.)	AG216	858
CON EDISON EPA ID: NYP004627618	FRONT OF 2413 DEAN S	WSW 1/8 - 1/4 (0.239 mi.)	AC233	904
CON EDISON EPA ID: NYP004820276	2604 ATLANTIC AVE	ESE 1/8 - 1/4 (0.247 mi.)	AE258	960
CON EDISON MANHOLE: EPA ID: NYP004449278	***ALABAMA AVE & LIBERT***	***SE 1/8 - 1/4 (0.250 mi.)***	***263***	***969***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEW YORK CITY TRANSI Generator EPA Id: NYD991290677	25 JAMAICA AVE	ENE 1/8 - 1/4 (0.224 mi.)	W189	766

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2020 has revealed that there are 2 RI MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA NYCT - EAST NY D EPA Id: NYD991290677 Manifest Document Number: 000126743UIS	***25 JAMAICA AVE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S128***	***432***
NYCTA (ENY YARD) HAZ EPA Id: NYD981140023 Manifest Document Number: 000007536UIS	***1700 BUSHWICK AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S131***	***588***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 27 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA Id: NYP004185344	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N101***	***321***
MTA NYCT - MANHOLE A EPA Id: NYP000967760	***BROADWAY & VAN SINDE***	***N 1/8 - 1/4 (0.149 mi.)***	***N104***	***333***
CON EDISON - MANHOLE EPA Id: NYP004197497	***2371 ATLANTIC AVE AN***	***W 1/8 - 1/4 (0.169 mi.)***	***P113***	***352***
MTA NYCT - EAST NY D EPA Id: NYD991290677	***25 JAMAICA AVE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S128***	***432***
NYCT-40 CONWAY ST EPA Id: NYR000027821	***40 CONWAY ST***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S129***	***482***
NYCTA (ENY YARD) HAZ EPA Id: NYD981140023	***1700 BUSHWICK AVENUE***	***NNE 1/8 - 1/4 (0.175 mi.)***	***S131***	***588***
CON EDISON EPA Id: NYP004766895	1385 HERKIMER ST	WNW 1/8 - 1/4 (0.229 mi.)	X201	811
CON EDISON EPA Id: NYP004817219	1716 BUSHWICK AVE	NE 1/8 - 1/4 (0.229 mi.)	AF204	815

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYCTA - ATLANTIC AVE EPA Id: NYR000042838	***ATLANTIC AVE & VAN S***	***SSW 0 - 1/8 (0.024 mi.)***	***A10***	***57***
CON EDISON EPA Id: NYP004194809	***ATLANTIC AVE & HAVEN***	***WSW 0 - 1/8 (0.058 mi.)***	***E34***	***131***
MTA NYCT - JAMAICA L EPA Id: NYR000145045	***KENT AVE & S 6TH ST***	***E 1/8 - 1/4 (0.146 mi.)***	***L88***	***254***
CON EDISON - SERVICE EPA Id: NYP004868172	60 WILLIAMS AVE	SE 1/8 - 1/4 (0.147 mi.)	M92	288
CON EDISON EPA Id: NYP004825200	BROADWAY & JAMAICA A	E 1/8 - 1/4 (0.147 mi.)	L93	289
NYCTA-CPM ENVIRO ENG EPA Id: NYR000072777	BROADWAY & JAMAICA	E 1/8 - 1/4 (0.147 mi.)	L94	290
CON EDISON EPA Id: NYP004793527	2572 FULTON ST	E 1/8 - 1/4 (0.165 mi.)	L111	349
CON EDISON EPA Id: NYP004793543	21 ALABAMA AVE	E 1/8 - 1/4 (0.172 mi.)	R118	371
CON EDISON EPA Id: NYP004726790	23 ALABAMA AVE	E 1/8 - 1/4 (0.173 mi.)	R121	377
CON EDISON EPA Id: NYP004728978	2569 ATLANTIC AVE	ESE 1/8 - 1/4 (0.186 mi.)	R141	650
CON EDISON EPA Id: NYP004738654	LIBERTY & SNEIDIKER	SSE 1/8 - 1/4 (0.196 mi.)	U147	663
CON EDISON	***SNEDIKER AVE & LIBER***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U148***	***664***

EPA Id: NYP004195053				
CON EDISON	***SNEDIKER AVE & LIBER***	***SSE 1/8 - 1/4 (0.196 mi.)***	***U150***	***670***
EPA Id: NYP004194650				
CON EDISON	38 GEORGIA AVE	E 1/8 - 1/4 (0.197 mi.)	R155	685
EPA Id: NYP004876932				
CON EDISON	44 GEORGIA AVE	E 1/8 - 1/4 (0.200 mi.)	R158	691
EPA Id: NYP004820326				
CON EDISON - SERVICE	80 ALABAMA AVE	SE 1/8 - 1/4 (0.205 mi.)	Z171	722
EPA Id: NYP004868206				
CON EDISON	74 GEORGIA AVE	ESE 1/8 - 1/4 (0.228 mi.)	AE197	803
EPA Id: NYP004794962				
BP #30129	***32 JAMAICA AVE***	***ENE 1/8 - 1/4 (0.230 mi.)***	***W208***	***822***
EPA Id: NYD986963064				
CON EDISON	2604 ATLANTIC AVE	ESE 1/8 - 1/4 (0.247 mi.)	AE256	957
EPA Id: NYP004820276				

NY MGP: From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

A review of the NY MGP list, as provided by EDR, and dated 12/02/2024 has revealed that there is 1 NY MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
K - UNION STATION HO	***ATLANTIC AVE, ASHFOR***	***E 1/2 - 1 (0.910 mi.)***	***AT317***	***1124***

NY NYC OER: Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

A review of the NY NYC OER list, as provided by EDR, and dated 12/02/2024 has revealed that there are 46 NY NYC OER sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
2440 FULTON STREET	***2440 FULTON STREET***	***NNE 0 - 1/8 (0.066 mi.)***	***C35***	***135***
2396 ATLANTIC AVENUE	2396 ATLANTIC AVENUE	WSW 0 - 1/8 (0.120 mi.)	I77	226
INSTITUTE FOR COMMUN	***2384 ATLANTIC AVE***	***WSW 1/8 - 1/4 (0.136 mi.)***	***I85***	***244***
LOT 18,TAXBLOCK 1553	***2246 FULTON STREET***	***WNW 1/8 - 1/4 (0.178 mi.)***	***O136***	***639***
Not reported	***156 SOMERS STREET***	***NW 1/8 - 1/4 (0.210 mi.)***	***AA175***	***735***
LOT 6,TAXBLOCK 1436	***1860 EASTERN PARKWAY***	***W 1/8 - 1/4 (0.237 mi.)***	***AD220***	***865***
33 TRUXTON STREET	33 TRUXTON STREET	WNW 1/4 - 1/2 (0.285 mi.)	270	984
Not reported	***1846 PARK PLACE***	***WSW 1/2 - 1 (0.761 mi.)***	***311***	***1109***
Not reported	***2064 ATLANTIC AVENUE***	***W 1/2 - 1 (0.822 mi.)***	***314***	***1119***
19 PRESCOTT PLACE -	19 PRESCOTT PLACE	W 1/2 - 1 (0.917 mi.)	AU321	1131
LOT 14,TAXBLOCK 1471	***1790 STERLING PLACE***	***WSW 1/2 - 1 (0.926 mi.)***	***AV322***	***1131***
Not reported	***497 HOWARD AVENUE***	***WSW 1/2 - 1 (0.938 mi.)***	***AV323***	***1134***
LOT 25,TAXBLOCK 1556	***20 PRESCOTT PLACE***	***W 1/2 - 1 (0.939 mi.)***	***AU324***	***1136***
LOT 3,TAXBLOCK 1556	***335 RALPH AVENUE***	***W 1/2 - 1 (0.960 mi.)***	***AU327***	***1145***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 46,TAXBLOCK 1437	***2435 PACIFIC STREET***	***SW 0 - 1/8 (0.113 mi.)***	***I67***	***203***

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
81-111 JUNIUS STREET	***81 JUNIUS STREET***	***S 1/8 - 1/4 (0.242 mi.)***	***237***	***911***
50 PENN LLC	***2618 FULTON ST***	***E 1/4 - 1/2 (0.264 mi.)***	***AJ264***	***972***
DEAN STREET - HABITA	***2396 DEAN STREET***	***WSW 1/4 - 1/2 (0.272 mi.)***	***AC265***	***975***
CON EDISON SERVICE B	***103 LIBERTY AVE***	***SW 1/4 - 1/2 (0.297 mi.)***	***271***	***985***
2175 BERGEN STREET	***217-221 MOTHER GASTO***	***WSW 1/4 - 1/2 (0.301 mi.)***	***273***	***994***
117 GLENMORE AVENUE	***117 GLENMORE AVENUE***	***SSW 1/4 - 1/2 (0.355 mi.)***	***AL277***	***1007***
2667 FULTON STREET	***2667 FULTON STREET***	***E 1/4 - 1/2 (0.367 mi.)***	***278***	***1008***
157 NEW JERSEY AVENU	***157 NEW JERSEY AVENU***	***E 1/4 - 1/2 (0.378 mi.)***	***280***	***1015***
LOT 35,TAXBLOCK 3703	***184 PENNSYLVANIA AVE***	***ESE 1/4 - 1/2 (0.399 mi.)***	***285***	***1022***
2701-2715 FULTON STR	***2701-2715 FULTON STR***	***E 1/4 - 1/2 (0.425 mi.)***	***AO288***	***1027***
2700 ATLANTIC AVENUE	***2700 ATLANTIC AVENUE***	***E 1/4 - 1/2 (0.443 mi.)***	***291***	***1041***
Not reported	***2718 FULTON STREET***	***E 1/4 - 1/2 (0.460 mi.)***	***AO293***	***1048***
EXXON DIV OF CFI #70	***225 PENNSYLVANIA AVE***	***SE 1/4 - 1/2 (0.464 mi.)***	***AP296***	***1070***
LOT 15,TAXBLOCK 3690	***2738 ATLANTIC AVENUE***	***E 1/2 - 1 (0.516 mi.)***	***302***	***1089***
LOT 18,TAXBLOCK 3946	***2776 FULTON STREET***	***E 1/2 - 1 (0.576 mi.)***	***AR304***	***1092***
LOT 55,TAXBLOCK 3933	***2795 FULTON STREET***	***E 1/2 - 1 (0.612 mi.)***	***AR305***	***1095***
HENRY APARTMENTS SIT	***8 ROCKAWAY AVENUE***	***NW 1/2 - 1 (0.637 mi.)***	***306***	***1097***
LOT 56,TAXBLOCK 1468	***1900 PARK PLACE***	***WSW 1/2 - 1 (0.668 mi.)***	***AS307***	***1105***
416 THOMAS S. BOYLAN	416 THOMAS S. BOYLAN	WSW 1/2 - 1 (0.693 mi.)	AS308	1108
HENRY APARTMENTS - S	***1676 BROADWAY***	***NW 1/2 - 1 (0.710 mi.)***	***309***	***1108***
2862 FULTON STREET	2862 FULTON STREET	E 1/2 - 1 (0.752 mi.)	310	1109
LOT 11,TAXBLOCK 3965	***2864 ATLANTIC AVENUE***	***E 1/2 - 1 (0.778 mi.)***	***312***	***1112***
402 SNEDIKER AVENUE	***402 SNEDIKER AVENUE***	***SSE 1/2 - 1 (0.801 mi.)***	***313***	***1119***
53 MACDOUGAL STREET	***53 MACDOUGAL ST***	***WNW 1/2 - 1 (0.903 mi.)***	***315***	***1122***
LOT 30,TAXBLOCK 3998	***2337 PITKIN AVENUE***	***ESE 1/2 - 1 (0.906 mi.)***	***316***	***1123***
305 CHESTER STREET -	305 CHESTER STREET	SSW 1/2 - 1 (0.911 mi.)	318	1128
Not reported	***368 LIVONIA AVENUE***	***S 1/2 - 1 (0.913 mi.)***	***320***	***1128***
LOT 65,TAXBLOCK 1474	***1717 LINCOLN PLACE***	***WSW 1/2 - 1 (0.952 mi.)***	***AW325***	***1139***
LOT 23,TAXBLOCK 1476	***1319 EAST NEW YORK A***	***WSW 1/2 - 1 (0.961 mi.)***	***AW328***	***1147***
1470 EASTERN PARKWAY	1470 EASTERN PARKWAY	WSW 1/2 - 1 (0.980 mi.)	AW329	1150
LOT 5,TAXBLOCK 1474	***1464 EASTERN PARKWAY***	***WSW 1/2 - 1 (0.986 mi.)***	***AW330***	***1150***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 2 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BELMONT STATION	BELMONT, WILLIAMS, A	SSE 1/2 - 1 (0.523 mi.)	303	1092
UNION STATION (CITIZ	ATLANTIC AVE., ASHFO	E 1/2 - 1 (0.912 mi.)	AT319	1128

EXECUTIVE SUMMARY

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RUSBRO TRANSMISSION	2501 FULTON ST	NE 0 - 1/8 (0.095 mi.)	G52	175

Lower Elevation	Address	Direction / Distance	Map ID	Page
LINCOLN SERVICE STAT	1727 E NEW YORK AVE	SW 0 - 1/8 (0.117 mi.)	H76	226

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name	Database(s)
PENNSYLAVANIA AVE MUNICIPAL LANDFI	SEMS-ARCHIVE, RCRA NonGen / NLR
COMMERCIAL	NY LTANKS
UNION STATION (CITIZENS BRANCH)	NY VCP
BELMONT STATION	NY VCP

OVERVIEW MAP - 7931531.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Broadway Junction Properties	CLIENT:	P.W. Grosser Consulting
ADDRESS:	45 Van Sinderen Avenue Brooklyn NY 11207	CONTACT:	Michael Pecoraro
		INQUIRY #:	7931531.2s
LAT/LONG:	40.676539 / 73.903116	DATE:	March 19, 2025 3:33 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7931531.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Broadway Junction Properties	CLIENT:	P.W. Grosser Consulting
ADDRESS:	45 Van Sinderen Avenue Brooklyn NY 11207	CONTACT:	Michael Pecoraro
LAT/LONG:	40.676539 / 73.903116	INQUIRY #:	7931531.2s
		DATE:	March 19, 2025 3:33 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		2	7	NR	NR	NR	9
RCRA-SQG	0.250		0	5	NR	NR	NR	5
RCRA-VSQG	0.250		1	3	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	0	0	3	NR	3
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		1	0	5	NR	NR	6
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		2	8	13	NR	NR	23
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		1	19	NR	NR	NR	20
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	3	NR	NR	NR	3
NY AST	0.250		7	13	NR	NR	NR	20
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		1	0	NR	NR	NR	1
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		1	4	11	NR	NR	16
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		1	0	1	NR	NR	2
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	1	NR	NR	1
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		21	NR	NR	NR	NR	21
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		16	36	NR	NR	NR	52
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		1	1	NR	NR	NR	2
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	TP		NR	NR	NR	NR	NR	0
UST FINDER RELEASE	0.500		0	6	3	NR	NR	9
UST FINDER	0.250		2	16	NR	NR	NR	18
E MANIFEST	0.250		7	33	NR	NR	NR	40
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		6	NR	NR	NR	NR	6
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	1	NR	NR	1
NY LEAD	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		21	52	NR	NR	NR	73
PA MANIFEST	0.250		0	1	NR	NR	NR	1
RI MANIFEST	0.250		0	2	NR	NR	NR	2
NJ MANIFEST	0.250		2	25	NR	NR	NR	27
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY ILI	0.500		0	0	0	NR	NR	0
NY NYC LAND USE	TP	1	NR	NR	NR	NR	NR	1
NY MGP	1.000		0	0	0	1	NR	1
NY NYC OER	1.000		3	5	13	25	NR	46
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	2	NR	2
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		1	98	240	49	32	0	420

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **NY NYC LAND USE** **S131150236**
Target Property **45 VAN SINDEREN AVENUE**
BROOKLYN, NY 11207 **N/A**

Site 1 of 22 in cluster A

Actual:
70 ft.

NYC LAND USE:

Name:	Not reported
Address:	45 VAN SINDEREN AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6765372
Longitude:	-73.9031179
Type Of Ownership Code:	Not reported
Owner Name:	2465 ATLANTIC LLC
Borough:	BK
Tax Block:	1576
Tax Lot:	1
Community District:	305
Census Tract 2020:	3036700
Census Block 2020:	30367001003
Census Tract 2010:	367
Census Block 2010:	1007
School District:	23
City Council District:	37
Fire Company:	L176
Police Precinct:	75
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	M1-2: Manufacturing Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	E1: Warehouses - Fireproof
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	13110
Total Building Floor Area:	8000
Commercial Floor Area:	8000
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	8000
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	0

(Continued) **S131150236**

Total Units:	1
Lot Frontage:	138.0000000
Lot Depth:	95.0000000
Building Frontage:	55.0000000
Building Depth:	85.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	115650.00000
Assessed Total Value:	328950.00000
Exempt Total Value:	0.00000
Year Built:	1921
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.61000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015760001.00000000
Condominium Number:	Not reported
Census Tract 2:	0367
X Coordinate:	1011123
Y Coordinate:	185772
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 013
Tax Map #:	30603
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NPL Region North 1/2-1 5071 ft. **WOLFF-ALPORT CHEMICAL COMPANY**
1125-1139 IRVING AVENUE
RIDGEWOOD, NY 11385

NPL 1016170699
SEMS NYC200400810
US ENG CONTROLS
PRP

NPL:

EPA Region:	02
EPA ID:	NYC200400810
Site ID:	0206479
Name:	WOLFF-ALPORT CHEMICAL COMPANY
Address:	1125-1139 Irving Avenue
City,State,Zip:	RIDGEWOOD, NY 11385
Federal:	N
Final Date:	2014-05-12 00:00:00
Latitude:	40.692672
Longitude:	-73.901997

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

Site Score: 50
NAI: Not reported
Native American Entity: Not reported

Narr:
Site Name: Wolff-Alport Chemical Company
Site EPA ID: NYC200400810
Listing Date: 5/12/2014
Site Score: 50
Federal Facility Indicator: No

Site List URL:

Site Progress URL:

Federal Register URL:

Site Location URL:

SEMS:
Site ID: 0206479
EPA ID: NYC200400810
Name: WOLFF-ALPORT CHEMICAL COMPANY
Address: 1125-1139 IRVING AVENUE
Address 2: Not reported
City,State,Zip: RIDGEWOOD, NY 11385
Cong District: 12
FIPS Code: 36081
Latitude: +40.692672
Longitude: -73.901997
FF: N
NPL: Currently on the Final NPL
Non NPL Status: Not reported

SEMS Detail:
Region: 02
Site ID: 0206479
EPA ID: NYC200400810
Site Name: WOLFF-ALPORT CHEMICAL COMPANY
NPL: F
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 1
Start Date: 2012-09-27 05:00:00
Finish Date: 2014-08-09 05:00:00
Qual: S
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206479
EPA ID: NYC200400810
Site Name: WOLFF-ALPORT CHEMICAL COMPANY
NPL: F
FF: N

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

OU:	00
Action Code:	RV
Action Name:	RMVL
SEQ:	2
Start Date:	2021-09-21 05:00:00
Finish Date:	2021-11-10 06:00:00
Qual:	S
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	2012-05-04 05:00:00
Finish Date:	2012-05-04 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	HR
Action Name:	HAZRANK
SEQ:	1
Start Date:	2013-12-12 05:00:00
Finish Date:	2013-12-12 05:00:00
Qual:	O
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	NF
Action Name:	NPL FINL
SEQ:	1
Start Date:	2014-05-12 05:00:00
Finish Date:	2014-05-12 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	NP
Action Name:	PROPOSED
SEQ:	1
Start Date:	2013-12-12 05:00:00
Finish Date:	2013-12-12 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	2012-08-02 04:00:00
Finish Date:	2012-08-02 04:00:00
Qual:	H
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	2012-05-14 05:00:00
Finish Date:	2012-05-14 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	00
Action Code:	TA
Action Name:	TECH ASSIST
SEQ:	1
Start Date:	2013-07-23 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	RA
Action Name:	RA
SEQ:	1
Start Date:	2020-09-09 05:00:00
Finish Date:	2023-09-19 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	RA
Action Name:	RA
SEQ:	2
Start Date:	2020-09-09 05:00:00
Finish Date:	2024-09-19 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	RA
Action Name:	RA
SEQ:	3
Start Date:	2023-09-12 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	RD
Action Name:	RD
SEQ:	1
Start Date:	2017-09-28 05:00:00
Finish Date:	2019-03-19 05:00:00

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	RD
Action Name:	RD
SEQ:	2
Start Date:	2018-08-08 05:00:00
Finish Date:	2023-09-21 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	RD
Action Name:	RD
SEQ:	3
Start Date:	2018-08-08 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	2014-06-03 05:00:00
Finish Date:	2017-09-26 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206479
EPA ID:	NYC200400810
Site Name:	WOLFF-ALPORT CHEMICAL COMPANY
NPL:	F
FF:	N
OU:	01
Action Code:	BE
Action Name:	PRP RD

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

SEQ: 1
Start Date: 2019-09-30 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 02
Site ID: 0206479
EPA ID: NYC200400810
Site Name: WOLFF-ALPORT CHEMICAL COMPANY
NPL: F
FF: N
OU: 01
Action Code: RO
Action Name: ROD
SEQ: 1
Start Date: 2017-09-26 05:00:00
Finish Date: 2017-09-26 05:00:00
Qual: R
Current Action Lead: EPA Perf

SIte:
Name: WOLFF-ALPORT CHEMICAL COMPANY
Address: 1125-1139 IRVING AVENUE
Address 2: Not reported
City,State,Zip: RIDGEWOOD, NY 11385
Event Code: Not reported
Action Taken Date: 09/26/2017
EPA ID: NYC200400810
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Contaminated Media: Buildings/Structures
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2017
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: +40.692672
Longitude: -73.901997

Media:
EPA ID: NYC200400810
Contaminated Media: Buildings/Structures
Action ID: 1
Operable Unit: 01
Action Name: Record of Decision
Action Taken Date: 09/26/2017
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2017

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Sludge
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Sludge
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID: NYC200400810

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Buildings/Structures
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Buildings/Structures
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Buildings/Structures
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported

WOLFF-ALPORT CHEMICAL COMPANY (Continued) **1016170699**

Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

EPA ID:	NYC200400810
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/26/2017
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2017
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+40.692672
Longitude:	-73.901997

PRP:

PRP Name:
1127-1129 IRVING AVENUE LLC
1127-1129 IRVING AVENUE LLC
1127-1129 IRVING AVENUE LLC
1127-1129 IRVING AVENUE LLC
ADVAM PROPERTY HOLDINGS LLC
BETHEL CHURCH OF GOD, 7TH DAY INC.
BETHEL CHURCH OF GOD, 7TH DAY INC.
COOPER STREET HOLDINGS
IRVING UNIQUE DEVELOPMENT LLC
IRVING UNIQUE DEVELOPMENT LLC
LA JARABACOA DELI AND GROCERY CORP
LML REALTY EQUITIES LLC
LPL PROPERTIES INC.
MOFFAT HOLDINGS LLC
NEW YORK CITY
NEW YORK CITY
NEW YORK CITY
PRIMO FLAT FIX INC
RUDY L. REYES
RUDY L. REYES

Click this hyperlink while viewing on your computer to access
5 additional PRP: record(s) in the EDR Site Report.

A2 **CON EDISON MANHOLE: 5072** **RCRA NonGen / NLR** **1016971878**
South **2473 ATLANTIC AVE** **NY MANIFEST** **NYP004456299**
< 1/8 **BROOKLYN, NY 11233**
0.009 mi.
47 ft. **Site 2 of 22 in cluster A**

Relative: **Lower**
Actual: **67 ft.**

RCRA Listings:

Date Form Received by Agency:		20140403
Handler Name:		Con Edison Manhole: 5072
Handler Address:		Atlantic Ave
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004456299
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON MANHOLE: 5072 (Continued) **1016971878**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140303
Handler Name: CON EDISON MANHOLE: 5072	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140403
Handler Name: CON EDISON MANHOLE: 5072	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON MANHOLE: 5072 (Continued) **1016971878**

NY MANIFEST:

EPA ID:	NYP004456299
Country:	USA
Name:	Con Edison
Address:	2473 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	FRONT OF 2473 ATLANTIC AVE
Location Address 2:	SB5072
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edision
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/03/2014
Trans1 Recv Date:	03/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004456299
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002301048GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported

CON EDISON MANHOLE: 5072 (Continued) **1016971878**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	120
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

A3 **NOBLE SIGNS** **E MANIFEST** **1028032003**
SSW **2465 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.009 mi.
47 ft. **Site 3 of 22 in cluster A**

Relative: **Lower**
Actual: **68 ft.**

E MANIFEST:

Manifest Tracking Number:	023907696JJK
Last Updated Date:	20220311
Shipped Date:	20220214
Received Date:	20220214
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	VSQG
Generator Name:	Noble Signs
Generator Location Street Number:	Not reported
Generator Location Street 1:	2465 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2465 ATLANTIC AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported

NOBLE SIGNS (Continued) **1028032003**

Designated Facility Location City: ELIZABETH
Designated Facility Location Zip: 07206
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 023907696JJK
Waste Line Number: 1
Federal Waste Code: D001
Federal Waste: IGNITABLE WASTE

Transporter:
Manifest Tracking Number: 023907696JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services, Inc

Waste Line:
Manifest Tracking Number: 023907696JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1268
U.S. DOT Description: Un1268, Waste Petroleum Distillates, N.O.S. (Stoddard Solvent), 3 , li
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 100
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.05
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.05
Waste Quantity, in Kilograms: 45.3515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 45.3515
Management Method Code: H061
Management Method Description: FUEL BLENDING
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

Manifest Tracking Number: 023907696JJK

NOBLE SIGNS (Continued) **1028032003**

Waste Line Number:	2
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	NON RCRA NON DOT REGULATED MATERIAL (NON PCB NEON TRANSFORMERS)
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	50
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.025
Waste Quantity, in Kilograms:	22.67575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	22.67575
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N

A4 **APEX AIRTRONICS INC** **NY AST** **A100343927**
SSW **2465 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.009 mi.
47 ft. **Site 4 of 22 in cluster A**

Relative: **Lower**

Actual: **68 ft.**

AST:

Name:	APEX AIRTRONICS INC
Address:	2465 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-611061
Program Type:	PBS
UTM X:	592686.30560
UTM Y:	4503381.39613
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	413008
Affiliation Type:	Facility Owner
Company Name:	APEX AIRTRONICS INC

APEX AIRTRONICS INC (Continued) **A100343927**

Contact Type:	MGR
Contact Name:	HOWARD KARP
Address1:	2465 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 485-8560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-04-27

Site Id:	413008
Affiliation Type:	Mail Contact
Company Name:	APEX AIRTRONICS INC
Contact Type:	MGR
Contact Name:	HOWARD KARP
Address1:	2465 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 485-8560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-04-27

Site Id:	413008
Affiliation Type:	Facility Operator
Company Name:	APEX AIRTRONICS INC
Contact Type:	Not reported
Contact Name:	APEX AIRTRONICS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 485-8560
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-04-27

Site Id:	413008
Affiliation Type:	Emergency Contact
Company Name:	APEX AIRTRONICS INC
Contact Type:	Not reported
Contact Name:	HOWARD KAPP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

APEX AIRTRONICS INC (Continued) **A100343927**

Zip Code:	Not reported
Country Code:	001
Phone:	(516) 295-1748
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-04-27

Tank Info:

Tank Number:	01
Tank Id:	228149
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
G03 - Tank Secondary Containment - Vault (w/o access)
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
E03 - Piping Secondary Containment - Vault (without Access)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel Tank in Concrete
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/01/1956
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

A5 **FACTORY** **NY Spills** **S108956688**
SSW **2465 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
47 ft. **Site 5 of 22 in cluster A**

Relative: **Lower**
Actual: **68 ft.**

SPILLS:

Name:	FACTORY
Address:	2465 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0708834 / 2009-04-06
Facility ID:	0708834
Facility Type:	ER
DER Facility ID:	339389

FACTORY (Continued) **S108956688**

Site ID:	389803
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2007-11-13
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2007-11-13
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-11-13
Spill Record Last Update:	2009-04-06
Spiller Name:	HOWARD KARP
Spiller Company:	FACTORY
Spiller Address:	2465 ATLANTIC AVE
Spiller Company:	001
Contact Name:	HOWARD KARP
Latitude:	40.6761010
Longitude:	-73.9034290
DEC Memo:	contact at Petro is: Sangesland spoke to Mr. Karp. Yesterday during a fuel delivery they noticed oil coming through the wall around the fill line. Probably oil in the soil under the sidewalk cement along the remote fill pipe line. Mr. Karp said that Petro would be repairing the pipe, but Sangesland specifically wanted to know who would do the soil digout/remediation once the sidewalk was opened up and the fill line exposed. Mr. Karp said Petro would come back on Nov 20th to make the repairs. There is a chance that the sidewalk fill line is installed through a coal chute into the basement wall and NOT through soil. When Petro opens up the sidewalk on Nov 20th they will call the DEC to confirm that either No soil was impacted OR there was soil impact and they will hire a company to do the cleanup. 12/19/08 Spoke with Mr. Karp. Mr. Karp told me the spill in the basement was cleaned up with speedy dry.He has no idea about any soil contamination at the site. I told him to find out exactly where was the leak on fill line and if the leaky portion of the line runs underground through the soil.He said he would contact Petro oil to find out the information. Letter was sent to Apex Airtronics Inc 2465 Atlantic Avenue Brooklyn, NY 11207-2305 Attn: Howard Karp (sr) 03/31/09 Performed site visit today. Tank is totally vaulted,i.e can't be seen without taking the top cement off.No PBS registration found though the capacity is above

FACTORY (Continued) **S108956688**

1,100 gallon. Tightness
testing required.As per Mr. Karp, the spill was minor quantity from the fill line in the tank
room.Spill was on the concrete floor that was cleaned up by Petro Oil.Fill line has been
replaced.No evidence of spill exists in the tank room.I told Mr. Karp to register the tank and have
the tightness testing done.(sr) ** Case closed as there is no evidence of oil spill present at the
site**S.R.

Remarks: FILL PIPE IS LEAKING AND SEEPED THROUGH THE WALL; PETRO ON SCENE

All Materials:

Site ID:	389803
Operable Unit ID:	1146930
Operable Unit:	01
Material ID:	2137321
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A6 **APEX AIRTRONICS INC-2465 ATLANTIC AVE** **RCRA NonGen / NLR** **1000438728**
SSW **2465 ATLANTIC AVENUE** **ICIS** **NYD001284439**
< 1/8 **BROOKLYN, NY 11207** **US AIRS**
0.009 mi. **FINDS**
47 ft. **Site 6 of 22 in cluster A** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
68 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Apex Airtronics Inc
Handler Address:	Atlantic Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYD001284439
Contact Name:	Not reported
Contact Address:	ATLANTIC AVE
Contact City,State,Zip:	BROOKLYN, NY 11207
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ATLANTIC AVE

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Mailing City,State,Zip:		BROOKLYN, NY 11207
Owner Name:	Apex Airtronics Inc	
Owner Type:		Private
Operator Name:	Apex Airtronics Inc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F017
Waste Description: Not Defined

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U140
Waste Description: 1-Propanol, 2-Methyl- (I,T) (Or) Isobutyl Alcohol (I,T)

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: APEX AIRTRONICS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: APEX AIRTRONICS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: APEX AIRTRONICS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: APEX AIRTRONICS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: APEX AIRTRONICS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: APEX AIRTRONICS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: APEX AIRTRONICS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

List of NAICS Codes and Descriptions:
NAICS Code: 336413
NAICS Description: Other Aircraft Parts And Auxiliary Equipment Manufacturing

NAICS Code: 42161
NAICS Description: Electrical Apparatus And Equipment, Wiring Supplies, And Construction Material Wholesalers

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19920723
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19920723
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Date of Enforcement Action: 19920723
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19910607
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19930508
Enforcement Identifier: 000
Date of Enforcement Action: 19930423
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19930508
Enforcement Identifier: 000

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Date of Enforcement Action: 19930423
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19910607
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19920723
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19920723
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19930508
Enforcement Identifier: 000

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Date of Enforcement Action: 19930423
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19920723
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19910607
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19920723
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19930508
Enforcement Identifier: 000

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Date of Enforcement Action: 19930423
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910607
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19930508
Enforcement Identifier: 000
Date of Enforcement Action: 19930423
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19920723
Actual Return to Compliance Date: 19980922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 000
Date of Enforcement Action: 19920723
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19910117
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19980922
Scheduled Compliance Date: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19920619
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19910117
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19910117
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	19930508
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19980916
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	19930508
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Evaluation Date:	19920619
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19920619
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19980916
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	19930508
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19980916
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19980916
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19920619
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	19930508
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19920619
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	19930508
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19980916
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19980922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ICIS:

Enforcement Action ID:	02-000F000360470101500002
FRS ID:	110001596096
Action Name:	APEX AIRTRONICS INC-2465 ATLANTIC AVE 360470101500002
Facility Name:	APEX AIRTRONICS INC-2465 ATLANTIC AVE
Facility Address:	2465 ATLANTIC AVENUE BROOKLYN, NY 11207
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3479
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.67601
Longitude in Decimal Degrees: -73.9033
Permit Type Desc: Not reported
Program System Acronym: NY0000002610500246
Facility NAICS Code: 336413
Tribal Land Code: Not reported

US AIRS (AFS):
Region Code: 02
County Code: NY047
Programmatic ID: AIR NY0000002610500246
Facility Registry ID: 110001596096
D and B Number: Not reported
Facility Site Name: APEX AIRTRONICS INC-2465 ATLANTIC AVE
Primary SIC Code: 3479
NAICS Code: 336413
Default Air Classification Code: SMI
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002610500246
Facility Registry ID: 110001596096
Air Operating Status Code: OPR
Default Air Classification Code: SMI

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-12-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-06-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1993-11-16 00:00:00
Activity Status Date: 1993-11-16 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-08-20 00:00:00

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001596096

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000438728
Registry ID: 110001596096

DFR URL:
Name: APEX AIRTRONICS INC-2465 ATLANTIC AVE
Address: 2465 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11207

NY MANIFEST:
EPA ID: NYD001284439
Country: USA
Name: Apex Airtronics Inc
Address: 2465-69 ATLANTIC AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: 2465-69 ATLANTIC AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Code: BP

Mailing:
Mailing Name: Apex Airtronics Inc
Mailing Contact: Frank Rosenblum
Mailing Address 1: 2465-69 ATLANTIC AVENUE
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11207
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184858560

Manifest Data:
Document ID: PAE1197184
Manifest Status: Not reported
Trans1 State ID: 31124MA
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 11/05/1997
Trans1 Recv Date: 11/05/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/19/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001284439
Trans1 EPA ID: CTD982191942
Trans2 EPA ID: Not reported
TSDF ID 1: PAD085690592
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00600
Units: Pounds
Number of Containers: 003
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00
Waste Code 7: Lead
Waste Code 8: Not reported
Waste Code: Not reported
Waste Code 10: Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Waste Code 11: Not reported
Quantity: 00165
Units: Gallons (liquids only)
Number of Containers: 003
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: PAC5809882
Manifest Status: Not reported
Trans1 State ID: PAAH0067
Year: 1993
Trans2 State ID: Not reported
Generator Ship Date: 06/09/1993
Trans1 Recv Date: 06/09/1993
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/10/1993
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD001284439
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID 1: PAD085690592
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00090
Units: Pounds
Number of Containers: 006
Container Type: Metal drums, barrels, kegs
Handling Method: Landfill
Specific Gravity: 01.00
Waste Code 7: Ignitable Waste
Waste Code 8: Not reported
Waste Code: Not reported
Waste Code 10: Not reported
Waste Code 11: Not reported
Quantity: 00400
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	PAE9140655
Manifest Status:	Not reported
Trans1 State ID:	0440375ME
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	01/04/2000
Trans1 Recv Date:	01/04/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/13/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00600
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Quantity:	00400
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	PAE1197766
Manifest Status:	Not reported
Trans1 State ID:	PAAH0414
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/1995
Trans1 Recv Date:	07/20/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/14/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD054126164
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	09/25/2008
Trans1 Recv Date:	09/25/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/07/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	003110110JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	Lead
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	750
Units:	Pounds
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Document ID:	PAG0368513
Manifest Status:	Not reported
Trans1 State ID:	PAAH0067
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2002
Trans1 Recv Date:	10/10/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Cadmium
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	02000
Units:	Pounds
Number of Containers:	005

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	PAC8927273
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/1994
Trans1 Recv Date:	03/28/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001284439
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Cadmium
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1000438728**

Waste Code 11:	Not reported
Quantity:	00600
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

A7 **NYCDEP** **NY MANIFEST** **1009244177**
ENE **30 WILLIAMS PL** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.018 mi.
95 ft. **Site 7 of 22 in cluster A**

Relative:
Lower

Actual:
69 ft.

NY MANIFEST:

EPA ID:	NYP010000214
Country:	USA
Name:	Nycdep
Address:	30 WILLIAMS PL
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	30 WILLIAMS PL
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycdep
Mailing Contact:	Lionel Mackenne
Mailing Address 1:	1 CENTRE ST RM 2444
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10007
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2126698930

Manifest Data:

Document ID:	NJA0978075
Manifest Status:	Not reported
Trans1 State ID:	NJDEPS568
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	11/30/1990
Trans1 Recv Date:	11/30/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/30/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP010000214
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

NYCDEP (Continued) **1009244177**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00040
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00100
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

A8 **ARIES AUTOWORLD LTD** **NY SWF/LF** **S108145674**
SSW **2471 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.020 mi.
107 ft. **Site 8 of 22 in cluster A**

Relative: SWF/LF:
Lower

Name:	ARIES AUTOWORLD LTD
Address:	2471 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported

Actual:
67 ft.

ARIES AUTOWORLD LTD (Continued) **S108145674**

Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	592730
North Coordinate:	4503291
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

A9 **APEX AIRTRONICS INC-2465 ATLANTIC AVE** **PFAS ECHO** **1027326164**
SSW **N/A**
< 1/8 **BROOKLYN, NY**
0.024 mi.
125 ft. **Site 9 of 22 in cluster A**

Relative:
Lower

Actual:
66 ft.

PFAS ECHO:

Name:	Apex Airtronics Inc-2465 Atlantic Ave
Address:	Not reported
City,State,Zip:	BROOKLYN, NY
Latitude:	40.67601
Longitude:	-73.90331
Count:	1
County:	KINGS
Status:	Active
Region:	02
Industry:	Metal Coating

ECHO Facility Report:

Facility Percent Minority:	87.486
Facility Derived Tribes:	-
Facility Population:	37294.44
EPA Programs:	CAA; RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36047
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	02030202
Facility Derived WBD:	020302020103
Facility Derived CD113:	08
Facility Derived CB2010:	360470367001007
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	12/15/2003
Facility Days Last Inspection:	7,677
Facility Informal Count:	0

APEX AIRTRONICS INC-2465 ATLANTIC AVE (Continued) **1027326164**

Facility Date Last Informal Action:	11/16/1993
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	Y
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	NY0000002610500246
CAA Permit Types:	Synthetic Minor Emissions
CAA NAICS:	336413
CAA SICS:	3479
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	NYD001284439
RCRA Permit Types:	Other
RCRA NAICS:	336413 42161
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y

EJSCREEN Report:

A10 **NYCTA - ATLANTIC AVE STATION L LINE** **RCRA-VSQG** **1001202984**
SSW **ATLANTIC AVE & VAN SINDEREN AVE** **NY MANIFEST** **NYR000042838**
< 1/8 **BROOKLYN, NY 11201** **NJ MANIFEST**
0.024 mi.
128 ft. **Site 10 of 22 in cluster A**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20070101
Handler Name:	Nycta - Atlantic Ave Station L Line
Handler Address:	Atlantic Ave & Van Sinderen Ave
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYR000042838
Contact Name:	JOSEPHINE F BROWN
Contact Address:	JAY ST RM 819
Contact City,State,Zip:	BROOKLYN, NY 11201
Contact Telephone:	718-243-4581

Actual:
67 ft.

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		JAY ST RM 819
Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:	Mta Nyct	
Owner Type:		Municipal
Operator Name:	Mta Nyct	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20220111
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYCT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10 COLUMBUS CIRCLE 25TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 212-307-5589
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYCT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10 COLUMBUS CIR 25TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 212-307-5589
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA NYCT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10 COLUMBUS CIRCLE 25TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 212-307-5589
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MTA NYCT - ATLANTIC AVE STATION
Federal Waste Generator Description: Not a generator, verified

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYCTA-ATLANTIC AVENUE STATION (L LINE)
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA - ATLANTIC AVE STATION L LINE
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19970724
Handler Name: MTA NYCT - ATLANTIC AVE STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020220
Handler Name: NYCTA-ATLANTIC AVENUE STATION (L LINE)
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: Mixed Mode Transit Systems

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20080220
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYFBR

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

EPA ID:	NYR000042838
Country:	USA
Name:	Nycta-Office Of System Safety
Address:	ATLANTIC AVENUE AND VAN
Address 2:	SINDEREN AVENUE
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	ATLANTIC AVE STATION
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta-Office Of System Safety
Mailing Contact:	N/S
Mailing Address 1:	370 JAY ST-RM 819
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182434581

Manifest Data:

Document ID:	NYG2901933
Manifest Status:	Not reported
Trans1 State ID:	PD1011NY
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	04/25/2001
Trans1 Recv Date:	04/25/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/27/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 03800
Units: Pounds
Number of Containers: 010
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NJA5025344
Manifest Status: Not reported
Trans1 State ID: 08424
Year: 2004
Trans2 State ID: Not reported
Generator Ship Date: 08/23/2004
Trans1 Recv Date: 08/23/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/23/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: NYD046765574
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00200
Units: Pounds
Number of Containers: 001

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR986628162
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/11/2016
Trans1 Recv Date: 07/11/2016
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/11/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 009140754FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 500
Units: Pounds
Number of Containers: 1
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 1

Document ID: NJA4049860
Manifest Status: Not reported
Trans1 State ID: S8424
Year: 2002
Trans2 State ID: Not reported
Generator Ship Date: 07/12/2002

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Trans1 Recv Date:	07/12/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/12/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	03500
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NJA5045071
Manifest Status:	Not reported
Trans1 State ID:	S8424
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	08/20/2003
Trans1 Recv Date:	08/20/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/20/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00100
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR986628162
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2015
Trans1 Recv Date:	12/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	008273839FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2000
Units:	Pounds
Number of Containers:	4
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR986628162
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2016
Trans1 Recv Date:	02/26/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/26/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	009140443FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Manifest Status: Not reported
Trans1 State ID: NJR986628162
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/05/2016
Trans1 Recv Date: 10/05/2016
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/05/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000042838
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 009401548FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 300
Units: Pounds
Number of Containers: 1
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 1

Document ID: NYG2934423
Manifest Status: Not reported
Trans1 State ID: PD1011NY
Year: 2001
Trans2 State ID: Not reported
Generator Ship Date: 06/15/2001
Trans1 Recv Date: 06/15/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/18/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	03500
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYG1056546
Manifest Status:	Not reported
Trans1 State ID:	PD1011NY
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	11/25/1998
Trans1 Recv Date:	11/25/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/30/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00100
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NJA5104708
Manifest Status:	Not reported
Trans1 State ID:	08424
Year:	2004
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/2004
Trans1 Recv Date:	05/12/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/12/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000042838
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00500
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Click this hyperlink while viewing on your computer to access
7 additional NY MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA ID:	NYR000042838
Name:	NYCTA-CPM ENVIRO ENG DIV
Address:	ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11201
County:	Not reported
Mailing Address:	2 BROADWAY, 4TH FL
Mailing City,State,Zip:	NEW YORK 10004
Telephone:	6462523500
Emergency Telephone:	Not reported
Contact:	LOU DEFORTE
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000042838
Manifest Number:	NJA5025344
Date Shipped:	08/23/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/23/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/23/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09210421
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported
EPA ID:	NYR000042838
Manifest Number:	008273839FLE
Date Shipped:	12/23/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
EPA ID:	NYR000042838
Manifest Number:	NJA5104708
Date Shipped:	05/12/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/12/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/12/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05270421
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYR000042838
Manifest Number:	009140443FLE
Date Shipped:	2/26/2016
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

EPA ID:	NYR000042838
Manifest Number:	NJA5006850
Date Shipped:	02/18/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/18/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/19/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

NYCTA - ATLANTIC AVE STATION L LINE (Continued) **1001202984**

Data Entry Number: 03180425
Was Load Rejected: N
Reason Load Was Rejected: Not reported

A11 **CON EDISON HTV5519** **RCRA NonGen / NLR** **1026059499**
SSW **VAN SIDEREN & ATLANTIC AVE** **NYP005244694**
< 1/8 **BROOKLYN, NY 11207**
0.024 mi.
128 ft. **Site 11 of 22 in cluster A**

Relative: **Lower**
Actual: **67 ft.**

RCRA Listings:

Date Form Received by Agency:	20220316
Handler Name:	Con Edison Htv5519
Handler Address:	Van Sideren & Atlantic Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP005244694
Contact Name:	THOMAS TEELING
Contact Address:	IRVING PL 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

CON EDISON HTV5519 (Continued) **1026059499**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220316
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20220316
Handler Name: CON EDISON HTV5519	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20191112
Handler Name: CON EDISON HTV5519	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON HTV5519 (Continued) **1026059499**

Evaluation Action Summary:
Evaluations: No Evaluations Found

A12 **CON EDISON** **RCRA NonGen / NLR** **1010327678**
NNW **HERKIMER 60 FEET E OF VAN** **NY MANIFEST** **NYP004148136**
< 1/8 **BROOKLYN, NY 11203**
0.025 mi.
130 ft. **Site 12 of 22 in cluster A**

Relative:
Higher

Actual:
73 ft.

RCRA Listings:

Date Form Received by Agency:	20070411
Handler Name:	Con Edison
Handler Address:	Herkimer 60 Feet E Of Van
Handler City,State,Zip:	BROOKLYN, NY 11203
EPA ID:	NYP004148136
Contact Name:	MICHAEL DAUGHTREY
Contact Address:	4 IRVING PL, RM 828
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-580-8383
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

CON EDISON (Continued) **1010327678**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20070409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070411
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON (Continued) **1010327678**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004148136
Country: USA
Name: Consolidated Edison
Address: HERKIMER 60 FEET E OF VAN
Address 2: SINDEREN AVE
City,State,Zip: BROOKLYN, NY 11203
Zip 4: Not reported
Location Address 1: HERKIMER & VAN SINDEREN
Location Address 2: EXCAVATION
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 02/13/2007
Trans1 Recv Date: 02/13/2007
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/22/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004148136

CON EDISON (Continued) **1010327678**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001436016FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Cadmium
Waste Code b:	Chromium
Waste Code c:	Lead
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

A13 **CONSOLIDATED EDISON** **NY MANIFEST** **S119072876**
NNW **HERKIMER ST & VAN SINDEREN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11203**
0.025 mi.
131 ft. **Site 13 of 22 in cluster A**

Relative: NY MANIFEST:
Higher

EPA ID:	NYP004148144
Country:	USA
Name:	Consolidated Edison
Address:	HERKIMER ST & VAN SINDEREN AVE
Address 2:	160 FT W OF VAN SINDEREN AVE
City,State,Zip:	BROOKLYN, NY 11203
Zip 4:	Not reported
Location Address 1:	HERKIMER ST & VAN SINDEREN
Location Address 2:	EXCAVATION
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Actual:
73 ft.

CONSOLIDATED EDISON (Continued) **S119072876**

Mailing:
- Mailing Name: Consolidated Edison
- Mailing Contact: Franklyn Murray
- Mailing Address 1: 4 IRVING PL RM 828
- Mailing Address 2: Not reported
- Mailing City,State,Zip: NEW YORK, NY 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124602808

Manifest Data:
- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NYD006982359
- Year: 2018
- Trans2 State ID: Not reported
- Generator Ship Date: 02/13/2007
- Trans1 Recv Date: 02/13/2007
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 02/22/2007
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004148144
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID 1: NYD077444263
- TSDF ID 2: Not reported
- Manifest Tracking Number: 001436014FLE
- Import Indicator: N
- Export Indicator: N
- Discr Quantity Indicator: N
- Discr Type Indicator: N
- Discr Residue Indicator: N
- Discr Partial Reject Indicator: N
- Discr Full Reject Indicator: N
- Manifest Ref Number: Not reported
- Alt Facility RCRA ID: Not reported
- Alt Facility Sign Date: Not reported
- MGMT Method Type Code: H141
- Waste Code a: Cadmium
- Waste Code b: Chromium
- Waste Code c: Lead
- Waste Code e: B007
- Waste Code f: Not reported
- Waste Code g: Not reported
- Waste Code 1: Not reported
- Waste Code 2: Not reported
- Waste Code 3: Not reported
- Waste Code 4: Not reported
- Waste Code 5: Not reported
- Waste Code 6: Not reported
- Quantity: 50
- Units: Kilograms
- Number of Containers: 1
- Container Type: Metal drums, barrels, kegs
- Handling Method: Landfill

CONSOLIDATED EDISON (Continued) **S119072876**

Specific Gravity: 1

A14
NNW
< 1/8
0.025 mi.
131 ft.

CON EDISON MANHOLE 65390 **RCRA NonGen / NLR** **1010327680**
HERKIMER ST & VAN SINDEREN AVE **NYP004148144**
BROOKLYN, NY 11203

Site 14 of 22 in cluster A

Relative:
Higher

Actual:
73 ft.

RCRA Listings:

Date Form Received by Agency:		20070411
Handler Name:		Con Edison Manhole 65390
Handler Address:		Herkimer St & Van Sinderen Ave
Handler City,State,Zip:		BROOKLYN, NY 11203
EPA ID:		NYP004148144
Contact Name:		MICHAEL DAUGHTREY
Contact Address:		4 IRVING PL, RM 828
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-580-8383
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No

CON EDISON MANHOLE 65390 (Continued) **1010327680**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20070409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070411
Handler Name: CON EDISON MANHOLE 65390	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON MANHOLE 65390 (Continued) **1010327680**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A15 **CONSOLIDATED EDISON** **NY MANIFEST** **S110046396**
NNW **HERKIMER ST & VAN SINDEREN AVE - MH 65390** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.026 mi.
135 ft. **Site 15 of 22 in cluster A**

Relative: **Higher**
Actual: **73 ft.**

NY MANIFEST:
EPA ID: NYP004184594
Country: USA
Name: Consolidated Edison
Address: HERKIMER ST & VAN SINDEREN AVE - MH 65390
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11201
Zip 4: Not reported
Location Address 1: HERKIMER ST & VAN SINDEREN AVE - MH 65390
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/21/2009
Trans1 Recv Date: 07/21/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/22/2009

CONSOLIDATED EDISON (Continued) **S110046396**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004184594
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433310FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Chromium
Waste Code c:	Cadmium
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	45
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

A16 **MANHOLE 66367** **NY Spills** **S104282941**
SE **WILLIAMS AVE+LAVONIA** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
141 ft. **Site 16 of 22 in cluster A**

Relative: **Lower**
Actual: **65 ft.**

SPILLS:

Name:	MANHOLE 66367
Address:	WILLIAMS AVE+LAVONIA
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9908416 / 1999-12-08
Facility ID:	9908416
Facility Type:	ER
DER Facility ID:	76128
Site ID:	82598
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401

MANHOLE 66367 (Continued) **S104282941**

Spill Date:	1999-10-11
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-10-11
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-11
Spill Record Last Update:	2000-05-23
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	FRANK MASSERIA
Latitude:	40.6760949
Longitude:	-73.9025550
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed E2MIS notes: while on routine flush assignment found approx 1 gallon of dielectric fluid coming from cable due to contractor damage boulders, rocks and debris in MH66367, joint regulator in structure, no outside inpact, cannot see sump in structure due to debris. Not safe at this time to take a sample. waterbury fitting was leaking at the 3C joint-tightened fitting to stop leak - no D fault exists at this time. Also verified that there is about 3 cubic ft. of dirt and rocks. Will try to take liquid sample from joint regulator and call back to advise. Lab sequence# 99-10699 results 10PPM. Oil clean up completed in mh66367 and e.s.tag#12338 was removed. Incident is closed.
Remarks:	THEY HAD A SUB CONTRACTOR DUMP MATERIAL IN THE HOLE AND THE MATERIAL HIT A JOINT REGULATOR CAUSING THE LEAK. SPILL WILL BE CLEANED UP. CON ED 128365

All Materials:

Site ID:	82598
Operable Unit ID:	1087083
Operable Unit:	01
Material ID:	297529
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A17 **CON EDISON** **RCRA NonGen / NLR** **1018277920**
SE **90 WILLIAMS ST** **FINDS** **NYP004726642**
< 1/8 **BROOKLYN, NY 11207** **ECHO**
0.030 mi.
159 ft. **Site 17 of 22 in cluster A**

Relative: **Lower**
Actual: **64 ft.**

RCRA Listings:

Date Form Received by Agency:		20150205
Handler Name:		Con Edison
Handler Address:		Williams St
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004726642
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON (Continued) **1018277920**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150205
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150205
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1018277920**

FINDS:
Registry ID: 110067696265

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277920
Registry ID: 110067696265

DFR URL:
Name: CON EDISON
Address: 90 WILLIAMS ST
City,State,Zip: BROOKLYN, NY 11207

A18 **HERKIMER ST AND BROADWAY** **NY Spills** **S102663097**
NE **HERKIMER ST AND BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.031 mi.
165 ft. **Site 18 of 22 in cluster A**

Relative:
Higher

Actual:
71 ft.

SPILLS:

Name:	HERKIMER ST AND BROADWAY
Address:	HERKIMER ST AND BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702860 / 2003-02-03
Facility ID:	9702860
Facility Type:	ER
DER Facility ID:	182130
Site ID:	220190
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-06-06
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1997-06-06
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

HERKIMER ST AND BROADWAY (Continued) **S102663097**

Date Entered In Computer:	1997-06-06
Spill Record Last Update:	2003-02-03
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6770509
Longitude:	-73.9025060
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT E2MIS 108024 J.AVANZATO C&M REPORTS TK40554 SPILLED A 1/2 GALLON OF ANTI-FREEZE OFF THE CORNER OF HERKIMER ST & BWAY.NO SEWERS OR WATERWAYS AFFECTED.SPILL IS ALSO UNDER PRIVATE CAR.SPILL HAS BEEN CONTAINED . TRANSPORTATION TO RESPOND TO REPAIR LEAK & ASSIST IN CLEAN UP OF SPILL. CREW TO CALL BACK.....CIG CESARE NOTIFIED AT 08:25HRS.....V.DECANIO 0900 HRS CREW CALLED BACK CLEANUP IS COMPLETED WITH DIAPERS AND ABSORBANT AND TRUCK IS IN TRANSPORTATION.
Remarks:	overheated con ed vehicle caused spill - spill on blacktop and being cleaned up

All Materials:

Site ID:	220190
Operable Unit ID:	1048773
Operable Unit:	01
Material ID:	335786
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

A19 **NYCT HERKIMER STREET YARD** **RCRA NonGen / NLR** **1000270478**
NE **HERKIMER & WILLIAMS ST** **NY MANIFEST** **NYD982183287**
< 1/8 **BROOKLYN, NY 11207**
0.033 mi.
176 ft. **Site 19 of 22 in cluster A**

Relative:
Higher

Actual:
71 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nyct Herkimer Street Yard
Handler Address:	Herkimer & Williams St
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYD982183287
Contact Name:	Not reported
Contact Address:	JAY ST ROOM 809
Contact City,State,Zip:	BROOKLYN, NY 11201
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

NYCT HERKIMER STREET YARD (Continued) **1000270478**

EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		JAY ST ROOM 809
Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:	Nyc Transit Authority	
Owner Type:		Private
Operator Name:	Nyc Transit Authority	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYC TRANSIT AUTHORITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC TRANSIT AUTHORITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC TRANSIT AUTHORITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NYCT HERKIMER STREET YARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYCT HERKIMER STREET YARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCT HERKIMER STREET YARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870512
Handler Name: NYCT HERKIMER STREET YARD
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYD982183287
Country: USA
Name: Nycta

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Address:	HERKIMER & WILLIAMS ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	HERKIMER & WILLIAM ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta
Mailing Contact:	N/S
Mailing Address 1:	370 JAY ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188524134

Manifest Data:

Document ID:	NJA0453469
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWAS300
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890414
Trans1 Recv Date:	890414
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890414
Part A Recv Date:	890421
Part B Recv Date:	890427
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Document ID:	NJA0571115
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWA3002
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890331
Trans1 Recv Date:	890331
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890331
Part A Recv Date:	890410
Part B Recv Date:	890407
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	X721
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00385
Units:	Gallons (liquids only)
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Specific Gravity:	100
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100

Document ID:	NJA0571044
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWAS300
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890317
Trans1 Recv Date:	890317
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890317
Part A Recv Date:	890324
Part B Recv Date:	890324
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	X910
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	04800
Units:	Pounds
Number of Containers:	016
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Waste Code 11:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 12:	X910
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	03600
Units:	Pounds
Number of Containers:	012
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00440
Units:	Gallons (liquids only)
Number of Containers:	008
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 22:	Ignitable Waste
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 23:	IGNITABLE WASTE
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100

Document ID:	NJA0293567
Manifest Status:	C - Completed copy
Trans1 State ID:	NJWSASX30
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870612
Trans1 Recv Date:	870612
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870612
Part A Recv Date:	870623
Part B Recv Date:	870624
Generator EPA ID:	NYD982183287
Trans1 EPA ID:	NJD991291105

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00825
Units:	Gallons (liquids only)
Number of Containers:	015
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00385
Units:	Gallons (liquids only)
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100

NYCT HERKIMER STREET YARD (Continued) **1000270478**

Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 22:	X725
Quantity:	01000
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Waste Code 23:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100

A20 **NYC TRANSIT CPM ENV-MTA NYT BUS PKG LOT** **NY MANIFEST** **S108933828**
NE **WILLIAMS PL & HERKIMER** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.034 mi.
177 ft. **Site 20 of 22 in cluster A**

Relative: **Higher**
Actual: **71 ft.**

NY MANIFEST:

EPA ID:	NYD000076257
Country:	USA
Name:	Nyc Transit Cpm Env-Mta Nyt Bus Pkg Lot
Address:	WILLIAMS PL & HERKIMER
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	WILLIAMS PL & HERKIMER
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

NYC TRANSIT CPM ENV-MTA NYT BUS PKG LOT (Continued) **S108933828**

Mailing Name:	Nyc Transit Cpm Env-Mta Nyt Bus Pkg Lot
Mailing Contact:	Lou Deforte
Mailing Address 1:	2 BROADWAY 2ND FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523500

Manifest Data:

Document ID:	NYG1874394
Manifest Status:	Not reported
Trans1 State ID:	PP5193NY
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	01/17/2001
Trans1 Recv Date:	01/17/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000076257
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00300
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

A21 **CON ED - MH 3629** **RCRA NonGen / NLR** **1007205297**
NE **HERKIMER ST & WILLIAM PL** **NY MANIFEST** **NYP000928895**
< 1/8 **BROOKLYN, NY 11233**
0.034 mi.
177 ft. **Site 21 of 22 in cluster A**

Relative: **Higher**
Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:		19980228
Handler Name:		Con Ed - Mh 3629
Handler Address:		Herkimer St & William Pl
Handler City,State,Zip:		BROOKLYN, NY 11233-0000
EPA ID:		NYP000928895
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON ED - MH 3629 (Continued) **1007205297**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - MH 3629	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - MH 3629	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - MH 3629	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON ED - MH 3629 (Continued) **1007205297**

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP000928895
Country: USA
Name: Consolidated Edison
Address: HERKIMER ST & WILLIAM PL
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11233-0000
Zip 4: Not reported
Location Address 1: MH362-HERKIMER & WILLIAMS PL
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklin Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: CTF0387055
Manifest Status: Not reported
Trans1 State ID: AB299KNJ
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 03/19/1997
Trans1 Recv Date: 03/19/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/24/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000928895
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: Not reported

CON ED - MH 3629 (Continued) **1007205297**

TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00002
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

A22 **NYCDOT BRIDGE BIN 2243569** **RCRA NonGen / NLR** **1000912082**
West **ATLANTIC AVE OVER LIRR** **NY0000445619**
< 1/8 **BROOKLYN, NY 11233**
0.039 mi.
206 ft. **Site 22 of 22 in cluster A**

Relative: **Higher**

Actual: **71 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nycdot Bridge Bin 2243569
Handler Address:	Atlantic Ave Over Lirr
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NY0000445619
Contact Name:	ANTHONY GROSSO
Contact Address:	RECTOR ST - 4TH FLOOR
Contact City,State,Zip:	NEW YORK, NY 10006
Contact Telephone:	212-788-1705
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	RECTOR ST - 4TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10006

NYCDOT BRIDGE BIN 2243569 (Continued) **1000912082**

Owner Name:	Nycdot Bureau Of Bridge	
Owner Type:		Municipal
Operator Name:	Nycdot Bureau Of Bridge	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCDOT BUREAU OF BRIDGE

NYCDOT BRIDGE BIN 2243569 (Continued) **1000912082**

Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 RECTOR ST
Owner/Operator City,State,Zip: NEW YORK, NY 10006
Owner/Operator Telephone: 212-788-1705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYCDOT BUREAU OF BRIDGE
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 RECTOR ST
Owner/Operator City,State,Zip: NEW YORK, NY 10006
Owner/Operator Telephone: 212-788-1705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCDOT BUREAU OF BRIDGE
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 RECTOR ST
Owner/Operator City,State,Zip: NEW YORK, NY 10006
Owner/Operator Telephone: 212-788-1705
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYCDOT BRIDGE BIN 2243569
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCDOT BRIDGE BIN 2243569
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

NYCDOT BRIDGE BIN 2243569 (Continued) **1000912082**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940711
Handler Name: NYCDOT BRIDGE BIN 2243569
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B23 **CON EDISON** **NY MANIFEST** **S116297094**
SSW **NEW YORK AVE & ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.042 mi.
220 ft. **Site 1 of 4 in cluster B**

Relative: **Lower**
Actual: **63 ft.**

NY MANIFEST:
EPA ID: NYP004486346
Country: USA
Name: Con Edison
Address: NEW YORK AVE & ATLANTIC AVE
Address 2: NW COR
City,State,Zip: BROOKLYN, NY 11233
Zip 4: Not reported
Location Address 1: NORTH WEST CORNER NEW YORK AVE & ATLANTIC
Location Address 2: SB14893
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA

CON EDISON (Continued) **S116297094**

Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/02/2014
Trans1 Recv Date: 04/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/02/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004486346
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002361074GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 100
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

B24 **CON EDISON SERVICE BOX: 14893** **RCRA NonGen / NLR** **1017771693**
SSW **NEW YORK AVE & ATLANTIC AVE** **NYP004486346**
< 1/8 **BROOKLYN, NY 11233**
0.042 mi.
220 ft. **Site 2 of 4 in cluster B**

Relative: **Lower**
Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:		20140502
Handler Name:		Con Edison Service Box: 14893
Handler Address:		New York Ave & Atlantic Ave
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004486346
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON SERVICE BOX: 14893 (Continued) **1017771693**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140402
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140402
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140502
Handler Name: CON EDISON SERVICE BOX: 14893	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 14893 (Continued) **1017771693**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C25 **CON EDISON SERVICE BOX: 53166** **RCRA NonGen / NLR** **1016973075**
NE **63 WILLIAMS PL** **NY MANIFEST** **NYP004468666**
< 1/8 **BROOKLYN, NY 11207**
0.044 mi.
231 ft. **Site 1 of 5 in cluster C**

Relative: Higher
Actual: 72 ft.

RCRA Listings:

Date Form Received by Agency:		20140417
Handler Name:		Con Edison Service Box: 53166
Handler Address:		Williams Pl
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004468666
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No

CON EDISON SERVICE BOX: 53166 (Continued) **1016973075**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140317
Handler Name: CON EDISON SERVICE BOX:	53166
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140417
Handler Name: CON EDISON SERVICE BOX:	53166
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 53166 (Continued) **1016973075**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004468666
Country:	USA
Name:	Con Edison
Address:	63 WILLIAMS PL
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	OPP 53 WILLIAMS PL
Location Address 2:	SB53164
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	15TH ST
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/17/2014
Trans1 Recv Date:	03/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004468666
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405731GBF
Import Indicator:	N

CON EDISON SERVICE BOX: 53166 (Continued) **1016973075**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	60
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

D26 **WROUGHT ORIGINALS INC** **NY TANKS** **S110772084**
NNW **38 VAN SINDERIN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.052 mi.
273 ft. **Site 1 of 6 in cluster D**

Relative:
Higher

Actual:
75 ft.

TANKS:

Name:	WROUGHT ORIGINALS INC
Address:	38 VAN SINDERIN AVE
City,State,Zip:	BROOKLYN, NY 11207
Facility Id:	2-608012
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Program Type:	PBS
Expiration Date:	N/A
UTM X:	592670.61104
UTM Y:	4503460.50048

D27 **SPILL NUMBER 0206144** **NY LTANKS** **S105996747**
NNW **38 VAN SINDEREN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.052 mi.
273 ft. **Site 2 of 6 in cluster D**

Relative: **Higher**

Actual: **75 ft.**

LTANKS:

Name:	SPILL NUMBER 0206144
Address:	38 VAN SINDEREN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0206144 / 2002-10-08
Facility ID:	0206144
Site ID:	160781
Spill Date:	2002-09-13
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2002-09-13
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-13
Spill Record Last Update:	2002-10-08
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DENNIS MADIGAN
Spiller Phone:	(631) 249-3150
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	135751
Latitude:	40.6768284
Longitude:	-73.9034543
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 10/8/2002-VOUGHT-Spill reported soil contamination from one (550-gallon) diesel and one (550-gallon) kerosene tank. Second set of endpoint soil samples show no exceedances above TAGM 4046 Required Soil Cleanup Objectives (analyticals sent to DEC), Soil disposal manifest also sent to DEC. Spill closed by Vought.
Remarks:	site is abandoned warehouse - after tanks were removed test results show contamination

All Materials:

Site ID:	160781
Operable Unit ID:	857676
Operable Unit:	01
Material ID:	516755
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported

SPILL NUMBER 0206144 (Continued) **S105996747**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D28 **SPILL NUMBER 0007586** **NY Spills** **S104790043**
NW **1 HAVENS PL** **N/A**
< 1/8 **BROOKLYN, NY**
0.055 mi.
288 ft. **Site 3 of 6 in cluster D**

Relative: SPILLS:
Higher

Actual:
75 ft.

Name:	SPILL NUMBER 0007586
Address:	1 HAVENS PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0007586 / 2002-09-10
Facility ID:	0007586
Facility Type:	ER
DER Facility ID:	214893
Site ID:	263609
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C1
SWIS:	2401
Spill Date:	2000-09-28
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2000-09-28
CID:	312
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-09-28
Spill Record Last Update:	2002-09-10
Spiller Name:	IRA TURRET
Spiller Company:	CARAVAN TRANSPORTATION
Spiller Address:	141 PILING STR
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6770877
Longitude:	-73.9041955
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE LOT WAS A REPAIR SHOP. ACCORDING TO NYCT, LOT CONTAINED APPROX. 20 DRUMS OF WASTE OIL. NYCT WAS SUPPOSED TO START USING THE LOT TODAY TO STORE BUSES, WHEN THEY NOTICED THAT MOST OF THE DRUMS WERE GONE EXCEPT FOR A FEW CRUSHED ONES. THERE APPEARED TO BE STAINING AROUND THE STORM WATER DRAIN ON THE PROERTY. NYCT

SPILL NUMBER 0007586 (Continued) **S104790043**

(SANJIV'S PAGER # 917-651-4670) OBSERVED SERVERAL INCHES OF WASTE OIL IN THE STORM WATER DRAIN. DEP
NOTIFIED. DEP REQUESTED THAT I NOTIFY ENCON POLICE. 9/29/00 SITE VISIT. MET WITH SANJIV KURAY
(NYCT), CECIL MORRIS (CARAVAN TRANSPORTATION), ALDO VASAPOLLI (CONTRACTOR), MARK TIBBE (DEC). MR.
VASAPOLLI INFORMED TIBBE THAT THERE WERE SEVERAL DRUMS ONSITE THAT HIS COMPANY TOOK DURING THE
CLEANING OF THE LOT. MOST OF THEM WERE EMPTY AND WERE TAKEN BACK TO HIS YARD. ONE CONTAINED WATER,
ONE CONTAINED ANTI-FREEZE, ONE CONTAINED WINDSHIELD WASHER FLUID, ONE CONTAINED A LITTLE WASTE OIL
AND TWO CONTAINED WHAT APPEARED TO HYDRALIC OR TRANSMISSION FLUID. NONE OF THE DRUMS WERE FULL.
ACCORDING TO MR. VASAPOLLI, ALL BUT THE HYDRALIC FLUID WERE DUMPED IN THE STORM WATER DRAIN ON THE
PROPERTY. THE HYDRALIC OIL DRUMS WERE PUNCTURED BY THE BACKHOE WHILE IT WAS CLEANING SOME DEBRIS.
THE RESULTING SPILL WAS SWEPT INTO THE SAME DRAIN. TIBBE PLACED A CALL TO IRA TURRET (OWNERS
ATTORNEY) AND INFORMED HIM THE THE SPILL AND THE DRAIN WOULD HAVE TO BE CLEANED. HE INFORMED TIBBE
THAT HE WAS ALREADY WORKING ON GETTING A CONTRACTOR, BUT HE WOULD LIKE A LETTER DIRECTING THEM WHAT
TO DO. THE OWNER OF THE PROPERTY IS LAWRENCE GREEN. As per 10/19/00 letter from Ira Turret, the
spill was cleaned by Dola Construction.

Remarks: PARKING LOT - NYC TRANSIT WAS SUPPOSED TO OCCUPY THIS TODAY, BUT THERE A LOT OF DRUMS ON SITE - SUBJ MAY HAVE DUMPED THE OIL INTO SEWER
Not reported

All Materials:

Site ID:	263609
Operable Unit ID:	828340
Operable Unit:	01
Material ID:	545120
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E29 **SPILL NUMBER 0007769** **NY Spills** **S104790176**
WSW **HAVEL PLACE & ATLANTIC AV** **N/A**
< 1/8 **BROOKLYN, NY**
0.056 mi.
294 ft. **Site 1 of 8 in cluster E**

Relative: SPILLS:
Lower

Actual:
69 ft.

Name:	SPILL NUMBER 0007769
Address:	HAVEL PLACE & ATLANTIC AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0007769 / 2004-02-17

SPILL NUMBER 0007769 (Continued) **S104790176**

Facility ID:	0007769
Facility Type:	ER
DER Facility ID:	124739
Site ID:	146481
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	2401
Spill Date:	2000-09-29
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-10-02
CID:	396
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-02
Spill Record Last Update:	2004-02-17
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ALDO VASAPOLLI
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	barrels of hyd oil were hit by a truck..speedy dry was put down...some did get into dry wells.

All Materials:

Site ID:	146481
Operable Unit ID:	830272
Operable Unit:	01
Material ID:	545295
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

D30 **LOT 16,TAXBLOCK 1554** **NY E DESIGNATION** **S118704114**
NW **1495 HERKIMER STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.056 mi.
298 ft. **Site 4 of 6 in cluster D**

Relative:
Higher

Actual:
75 ft.

E DESIGNATION:

Name:	LOT 16,TAXBLOCK 1554
Address:	1495 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	16
Tax Block:	1554
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	1495 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6775316
Longitude:	-73.9041403
Type Of Ownership Code:	P
Owner Name:	TLG FULTON LLC
Borough:	BK
Tax Block:	1554
Tax Lot:	16
Community District:	316
Census Tract 2020:	3036700
Census Block 2020:	30367002000
Census Tract 2010:	367
Census Block 2010:	1002
School District:	23
City Council District:	37
Fire Company:	L176
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	2B
Zoning District 1:	C4-5D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported

LOT 16,TAXBLOCK 1554 (Continued) **S118704114**

Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	O5: Office Buildings - Office With Comm ? 1 To 6 Stories
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	1
Lot Area:	77500
Total Building Floor Area:	333424
Commercial Floor Area:	333424
Residential Floor Area:	0
Office Floor Area:	257734
Retail Floor Area:	53090
Garage Floor Area:	22600
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	2
Lot Frontage:	200.0000000
Lot Depth:	400.0000000
Building Frontage:	200.0000000
Building Depth:	300.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	1220850.00000
Assessed Total Value:	1220850.00000
Exempt Total Value:	0.00000
Year Built:	2023
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.30000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	4.20000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015540016.00000000
Condominium Number:	Not reported
Census Tract 2:	0367
X Coordinate:	1010839
Y Coordinate:	186134
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 012
Tax Map #:	30603
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

LOT 16,TAXBLOCK 1554 (Continued) **S118704114**

Version Number: 24v3.1
Changed By DCP: Not reported

E31 **NYCTA - 30 HAVENS PLACE** **NY Spills** **1000890325**
WNW **30 HAVENS PL** **RCRA NonGen / NLR** **NY0000340430**
< 1/8 **BROOKLYN, NY 11233** **FINDS**
0.057 mi. **ECHO**
302 ft. **Site 2 of 8 in cluster E** **NY MANIFEST**

Relative: Higher

Actual: 73 ft.

SPILLS:

Name:	30 HAVENS PL
Address:	30 HAVENS PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0106974 / 2005-12-19
Facility ID:	0106974
Facility Type:	ER
DER Facility ID:	234418
Site ID:	289484
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	2001-10-05
Investigator:	DJEATON
Referred To:	Not reported
Reported to Dept:	2001-10-05
CID:	205
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-05
Spill Record Last Update:	2005-12-19
Spiller Name:	MIKE HEMLOCK
Spiller Company:	30 HAVENS PLACE
Spiller Address:	30 HAVENS PLACE
Spiller Company:	001
Contact Name:	CALLER
Latitude:	40.6764500
Longitude:	-73.9043952
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 1K, UST, FULL HAS BEEN EXCAVATED FROM SITE. UST WAS FULL OF OLD FUEL (SPENT), WAS VACATED OUT, CLEANED, CUT, AND WILL BE REMOVED FROM SITED TODAY. CALLER THINKS CONTAMINATED SOILS ARE DUE TO LINE LEAKING DURING PAST YEARS OF DELIVERER. SOILS ARE BEING EXCAVATED, NO GW REACHED AND SOILS TO BE SAMPLED VIA 4046 TAGM. PART OF SAMPLES WILL BE TAKEN AND CLOSURE REPORT TO BE SUBMITTED TO TIPPLE FOR REVIEW. SPILLER HAS BEEN HOOKED UP TO NG FOR SOME YEARS?. RS DEC Received a tank closure report dated Nov. 15, 2001, submitted to PBS and transferred to DEC (Tipple) on Dec. 3, 2001.

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Referenced report is not in
files, called Impact Environmental to try to obtain second copy.
12/06/05. (Eaton, Albany) No
additional files available, closed spill based on tank closure
information indicated above. DE

Remarks: contaminated soil from leaking u/g tank. cleanup started.

All Materials:

Site ID:	289484
Operable Unit ID:	845164
Operable Unit:	01
Material ID:	531813
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nycta - 30 Havens Place
Handler Address:	Havens Pl
Handler City,State,Zip:	BROOKLYN, NY 11233-3408
EPA ID:	NY0000340430
Contact Name:	Not reported
Contact Address:	JAY ST ROOM 809
Contact City,State,Zip:	BROOKLYN, NY 11201
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	JAY ST ROOM 809
Mailing City,State,Zip:	BROOKLYN, NY 11201
Owner Name:	New York City Transit Authority
Owner Type:	Municipal
Operator Name:	New York City Transit Authority
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D009
Waste Description:	Mercury

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK CITY TRANSIT AUTHORITY
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 809
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-330-4581
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 809
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-330-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 809
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-330-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NYCTA - 30 HAVENS PLACE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYCTA - 30 HAVENS PLACE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA - 30 HAVENS PLACE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19940601
Handler Name:	NYCTA - 30 HAVENS PLACE
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004315795

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000890325
Registry ID: 110004315795

DFR URL:
Name: NYCTA - 30 HAVENS PLACE
Address: 30 HAVENS PL
City,State,Zip: BROOKLYN, NY 11233

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

NY MANIFEST:

EPA ID:	NY0000340430
Country:	USA
Name:	Nycta
Address:	30 HAVENS PL
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233-3408
Zip 4:	Not reported
Location Address 1:	30 HAVENS PL
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11237
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta
Mailing Contact:	Oliver Shoy
Mailing Address 1:	370 JAY ST RM 809
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183304581

Manifest Data:

Document ID:	NJA1967995
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	09/20/1994
Trans1 Recv Date:	09/20/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/20/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000340430
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported

NYCTA - 30 HAVENS PLACE (Continued) **1000890325**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16000
Units:	Pounds
Number of Containers:	032
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA1870656
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES58
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	06/24/1994
Trans1 Recv Date:	06/24/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/24/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000340430
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	15900
Units:	Pounds
Number of Containers:	030
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

E32 **LOT 23,TAXBLOCK 1574** **NY E DESIGNATION** **S118704226**
WNW **30 HAVENS PLACE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.057 mi.
302 ft. **Site 3 of 8 in cluster E**

Relative:
Higher

Actual:
73 ft.

E DESIGNATION:

Name:	LOT 23,TAXBLOCK 1574
Address:	30 HAVENS PLACE
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	23
Tax Block:	1574
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	30 HAVENS PLACE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6764259
Longitude:	-73.9045926
Type Of Ownership Code:	Not reported
Owner Name:	2425 HOLDING CORP
Borough:	BK
Tax Block:	1574
Tax Lot:	23
Community District:	316
Census Tract 2020:	3036700
Census Block 2020:	30367002003
Census Tract 2010:	367
Census Block 2010:	1005
School District:	23
City Council District:	37
Fire Company:	L176
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	2B
Zoning District 1:	C4-5D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported

LOT 23,TAXBLOCK 1574 (Continued) **S118704226**

Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	E1: Warehouses - Fireproof
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	17533
Total Building Floor Area:	20000
Commercial Floor Area:	20000
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	20000
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	190.5800000
Lot Depth:	92.0000000
Building Frontage:	92.0000000
Building Depth:	122.0000000
Extension Code:	E
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	197100.00000
Assessed Total Value:	864900.00000
Exempt Total Value:	0.00000
Year Built:	1926
Year Altered 1:	2002
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.14000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	4.20000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015740023.00000000
Condominium Number:	Not reported
Census Tract 2:	0367
X Coordinate:	1010714
Y Coordinate:	185731
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 012
Tax Map #:	30603
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

LOT 23,TAXBLOCK 1574 (Continued) **S118704226**

Version Number: 24v3.1
Changed By DCP: Not reported

E33
WSW
< 1/8
0.058 mi.
305 ft.

NYC TRANSIT PARKING LOT **NY Spills** **S111063983**
HAVENS PLACE AND ATLANTIC AVE **N/A**
BROOKLYN, NY

Site 4 of 8 in cluster E

Relative:
Lower

Actual:
69 ft.

SPILLS:

Name:	NYC TRANSIT PARKING LOT
Address:	HAVENS PLACE AND ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1102080 / 2011-05-27
Facility ID:	1102080
Facility Type:	ER
DER Facility ID:	404159
Site ID:	449570
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-05-25
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2011-05-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-05-25
Spill Record Last Update:	2011-05-27
Spiller Name:	JENNIFER WOUTINEN
Spiller Company:	NYC TRANSIT
Spiller Address:	HAVENS PLACE AND ATLANTIC AVE
Spiller Company:	999
Contact Name:	JENNIFER WOUTINEN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Hydrualic line on a vehicle failed. Spilled to cement. cleanup complete
Remarks:	line broke, loss to pavement, clean up in progress, no resources

All Materials:

Site ID:	449570
Operable Unit ID:	1199779
Operable Unit:	01
Material ID:	2196180
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum

NYC TRANSIT PARKING LOT (Continued) **S111063983**

Quantity:	30.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

E34 **CON EDISON** **RCRA NonGen / NLR** **1014397162**
WSW **ATLANTIC AVE & HAVENS PL** **NJ MANIFEST** **NYP004194809**
< 1/8 **BROOKLYN, NY 11233** **NY MANIFEST**
0.058 mi.
305 ft. **Site 5 of 8 in cluster E**

Relative: **Lower**
Actual: **69 ft.**

RCRA Listings:

Date Form Received by Agency:		20160601
Handler Name:		Con Edison
Handler Address:		Atlantic Ave & Havens Pl
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004194809
Contact Name:		CAROLINE ISKANDER
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4714
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

CON EDISON (Continued) **1014397162**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160706
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090918
Handler Name: CON EDISON	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1014397162**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA ID:	NYP004194809
Name:	CON EDISON
Address:	ATLANTIC AVE & HAVENS PL
City,State,Zip:	BROOKLYN, NY 11233
County:	Not reported
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004194809
Manifest Number:	000894418GBF
Date Shipped:	09/21/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/21/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/21/2009
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **1014397162**

QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: N
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 200
Unit: G

NY MANIFEST:
EPA ID: NYP004194809
Country: USA
Name: Consolidated Edison
Address: ATLANTIC AVE & HAVENS PL
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11233
Zip 4: Not reported
Location Address 1: ATLANTIC AVE & HAVENS PL - MH 5074
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 09/21/2009

CON EDISON (Continued) **1014397162**

Trans1 Recv Date:	09/21/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/21/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004194809
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894418GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

C35 **2440 FULTON STREET** **NY VCP** **S129932220**
NNE **2440 FULTON STREET** **NY NYC OER** **N/A**
< 1/8 **BROOKLYN, NY**
0.066 mi.
350 ft. **Site 2 of 5 in cluster C**

Relative:
Higher

Actual:
76 ft.

VCP NYC:

Project ID:	20TMP1156K,21EHAN084K,21CVCP036K
Name:	2440 FULTON STREET
Address:	2440 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3015540016
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.677869

2440 FULTON STREET (Continued) **S129932220**

Longitude: -73.903473
Postcode: 11233
Community Board: 16
Council District: 37
Census Tract: 367
BIN: 3042309
NTA: Ocean Hill

NYC OER:
Name: 2440 FULTON STREET
Address: 2440 FULTON STREET
City,State,Zip: BROOKLYN, NY
Latitude: 40.677869
Longitude: -73.903473
OER Project Numbers: 20TMP1156K,21EHAN084K,21CVCP036K
BBL: 3015540016
OER Program: VCP (Enrolled), E/RD (Review)
Class: Active (A)
Phase: Construction

URL:
Postcode: 11233
Community Board: 16
Council District: 37
Census Tract: 367
BIN: 3042309
NTA: Ocean Hill

C36 **2440 FULTON STREET** **NY AST** **A100516171**
NNE **2440 FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.066 mi.
350 ft. **Site 3 of 5 in cluster C**

Relative:
Higher

Actual:
76 ft.

AST:
Name: 2440 FULTON STREET
Address: 2440 FULTON STREET
City,State,Zip: BROOKLYN, NY 11233
Region: STATE
DEC Region: 2
Site Status: Unregistered
Facility Id: 2-613260
Program Type: PBS
UTM X: Not reported
UTM Y: Not reported
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 623365
Affiliation Type: Facility Owner
Company Name: TLG FULTON LLC
Contact Type: AUTHORIZED SIGNATORY
Contact Name: SAM BLOBSTEIN
Address1: 1481 47TH STREET
Address2: Not reported
City: BROOKLYN
State: NY

2440 FULTON STREET (Continued) **A100516171**

Zip Code:	11219
Country Code:	001
Phone:	(929) 287-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-08-13

Site Id:	623365
Affiliation Type:	Mail Contact
Company Name:	ELI ROTH
Contact Type:	Not reported
Contact Name:	XOLLE DEMO LLC
Address1:	2071 FLATBUSH AVENUE
Address2:	SUITE N. 6
City:	BROOKLYN
State:	NY
Zip Code:	11234
Country Code:	001
Phone:	(929) 287-2100
EMail:	ELI@XOLLEDEMO.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-08-13

Site Id:	623365
Affiliation Type:	Emergency Contact
Company Name:	TLG FULTON LLC
Contact Type:	Not reported
Contact Name:	ELI ROTH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(929) 287-2100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-08-13

Site Id:	623365
Affiliation Type:	Facility Operator
Company Name:	2440 FULTON STREET
Contact Type:	Not reported
Contact Name:	XOLLE DEMO LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL

2440 FULTON STREET (Continued) **A100516171**

Date Last Modified: 2021-08-13

Tank Info:

Tank Number: 001
Tank Id: 290494

Equipment Records:

C01 - Pipe Location - Aboveground
I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Temporarily Out of Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 10000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #6 fuel oil (on-site consumption)

B37 **LOT 23,TAXBLOCK 1437** **NY E DESIGNATION** **S118704225**
SW **ATLANTIC AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.066 mi.
351 ft. **Site 3 of 4 in cluster B**

Relative: **Lower**
Actual: **67 ft.**

E DESIGNATION:
Name: LOT 23,TAXBLOCK 1437
Address: ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 23
Tax Block: 1437
Borough Code: Not reported
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation &

LOT 23,TAXBLOCK 1437 (Continued) **S118704225**

Alternate Ventilation
Lot Remediation Date: Not reported

C38 **DRUM RUN** **NY Spills** **S128170678**
NNE **WILLIAMS PLACE AND FULTON AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.068 mi.
360 ft. **Site 4 of 5 in cluster C**

Relative:
Higher

Actual:
75 ft.

SPILLS:

Name:	DRUM RUN
Address:	WILLIAMS PLACE AND FULTON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2108368 / 2022-02-17
Facility ID:	2108368
Facility Type:	ER
DER Facility ID:	577355
Site ID:	630309
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C2
SWIS:	2401
Spill Date:	2021-12-14
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2021-12-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-12-14
Spill Record Last Update:	2022-02-17
Spiller Name:	MOHAMMED
Spiller Company:	DRUMS
Spiller Address:	WILLIAM PL
Spiller Company:	999
Contact Name:	MOHAMMED
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/14/2021 - Feng - Desk Duty. Spoke to Mohammed of NYCDEP. 2 Drums, (1) 55-gallon and (1) 15-gallon, waste oil. Location at William Place and Fulton Ave, Brooklyn. Assigned to Ryan Piper for drum run. NYCDEP Mohammed 646-584-5527 2/17/22- DEC Piper- Drums not found at or near location as part of drum run. Spill closed.
Remarks:	2 containers, intact. * caller is near train tracks, difficult to hear
	Not reported

All Materials:

Site ID:	630309
Operable Unit ID:	1377418

DRUM RUN (Continued) **S128170678**

Operable Unit:	01
Material ID:	2390993
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported
Site ID:	630309
Operable Unit ID:	1377418
Operable Unit:	01
Material ID:	2390994
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

B39 **EAST NY SUMP STATION** **NY Spills** **S127481056**
South **1762 EAST NEW YORK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.074 mi.
391 ft. **Site 4 of 4 in cluster B**

Relative: SPILLS:
Lower

Actual:
60 ft.

Name:	EAST NY SUMP STATION
Address:	1762 EAST NEW YORK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2100177 / 2021-06-30
Facility ID:	2100177
Facility Type:	ER
DER Facility ID:	565560
Site ID:	617846
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2021-04-07
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	2021-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

EAST NY SUMP STATION (Continued) **S127481056**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-04-07
Spill Record Last Update:	2021-07-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MAGDALENA RYCHTECHA
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	4/7/21 - Obligado - 1244pm - I called LI Railroad and left a message to call back the NYDEC. About 100 gallons of diesel spilled leaked on the gravel. Emergency spill contractor is mobilizing. It is an ongoing spill that is being contained with buckets and spill pads. They are trying to get a vactor truck to mobilize. The spill is from an emergency generator with a 275 gallon tank. The spill is in substation. Spill assigned to Veronica Zhune for response. Entrance to the Site is on Van Sinderen Ave. Contact is Magdalen (347) 804-3069. 4/8/21-Zhune-Magdalena Rychtecka sent the following email. Summary of the event on 4/7/21 . On 4/7/21 @ noon: LIRR Substation Department personnel notified LIRR Corporate Safety Department- Environmental Planning and Compliance (LIRR CSD-EPC) of a diesel spill in the East NY Substation that was found during a monthly inspection. The 275-gallon diesel tank connected to an emergency generator was found on its side-dripping diesel through a vent pipe. We are assuming approximately 100 gallons of diesel spill into soil and ballast under the tank. . Initial Spill Response on 4/7/2021: . Long Island personal placed oil absorption pads underneath the dripping vent to minimize the spill to the gravel and soil under the tank . LIRR CSD-EPC: . Called NYSDEC hotline to report the spill & obtained Spill # 2100177 . Coordinated with LIRR Sub station personnel regarding the access, utilities to assess the limiting conditions for emergency response contractor (AB Environmental, referred herein as AB) . Requested AB's spill response team to mobilize to the site. . Mobilize to the site to oversee the spill response activities. . Spill response activities performed by AB Environmental: . AB removed approximately 137 gallons of diesel from the tank utilizing pump truck . AB disconnected the tank from the emergency generator, drained all the associated piping and filter, and placed the empty tank in a secure position. . AB removed 3.8 CY of soil and ballast impacted by the diesel utilizing vactor truck . AB collected (5) endpoint soil samples to be analyzed for contaminants listed in NYSDEC CP-51 table 3 Soil Cleanup levels for Fuel Oil Contaminated Soil. 5/18/21-Zhune-Magdalena

EAST NY SUMP STATION (Continued) **S127481056**

Rychtecka sent the following email. To follow up the East NY Substation Spill Response (summarized in the attached email from April 8, 2021 -including photo documentation), please see the attached waste Manifest for the removed wastes from the site and the Lab Report for (5) endpoint samples collected on April,2021. The analytical results were compared to 6 NYCRR Part 375 Soil Cleanup Objectives for Industrial Use. All Concentrations were found within the limits except for the following: . Benzo (a) pyrene concentrations of 3,600 uk/kg and 3,700 ug/kg associated with North and South wall Endpoint samples, respectively, were slightly above the Industrial SCO of 1,100 ug/kg (1.1 ppm) LIRR removed all impacted material from the spill location as practicable. Therefore, we will like to request that NYSDEC consider the merit of closing the spoll, so we can backfill the excavation with a clean general fill and ballast. 5/21/21-Zhune-Magdalena Rychtecka sent the following email I wanted to follow up our phone conversation from Wednesday regarding the next steps at ENY Substation (located at 1762 East NY Ave, Brooklyn, NY 11207).Can we backfill the excavation given that the endpoint concentrations were within the SCOs of 6NYCRR OPart 375 for Industrial Use except Benzo (a)pyrene concentrations associated with North and South wall Endpoint Samples. 5/25/21-Zhune-Magdalena Rychtecka sent the following email I compare the endpoint samples to restricted Use (Industrial Use)Soil Clean up Objective in the table 375-6.8(b).It stars at page 6-11 through 6-13 of the 6 NYCRR Part 375. I summarized the analytical results into a table along along with the industrial SCOs for easier comparison. 5/25/21- Zhune sent and email to Magdalena Rychtecka. Additional excavation is required to remove diesel contamination at the east side sample. Also you should take an endpoint sample at the east wall after the excavation. East wall 4/8/21 1,2,4 trimethylbenzene 110,000 1,3,5 trimethylbenzene 28,000 Benzene 490 Ethylbenzene 19,000 Isopropylbenzene 6,300 Naphthalene 13,000 n-butylbenzene 13,000 n-propylbenzene 17.000 0-xylene 32,000 p-&m-xylenes 69,000 p-isopropyltoluene 4,900 sec-buthylbenzene 8,00 toluene 16,000 xylenes 100,000 6/8/21-Zhune - Magdalena Rychtecka sent the following email On May 28, 2021 AB Environmental mobilize to the East NY substation on 5/28/21 to excavate more soil and ballast from the east side of the excavation area, The endpoint sample from the east wall was collected and attached are the lab Results. The analytical result indicate ND VOCs. The fallowing SVOCs are detected above the standards Benzo (a)anthracene 10.000ug/kg, Benzo (a) pyrene 7.000 ug /kg, Benzo (b)fluoranthene, Benzo (g, h,i) Benzo (k)fluoranthene 6.400 ug/kg ,

EAST NY SUMP STATION (Continued) **S127481056**

Crysene 9600 ug/kg, Dibenzo
(a,h)anthracene 1.500 ug/kg, indeno (1,2,3-cd)pyrene 4.300 ug/kg.
Spill Closed.

Remarks: Clean-up pending.

All Materials:

Site ID:	617846
Operable Unit ID:	1365008
Operable Unit:	01
Material ID:	2377492
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

F40 **DRUM RUN** **NY Spills** **S106722295**
ESE **2509 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.075 mi.
394 ft. **Site 1 of 6 in cluster F**

Relative: **Lower**

Actual: **59 ft.**

SPILLS:

Name:	DRUM RUN
Address:	2509 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0407976 / 2004-11-01
Facility ID:	0407976
Facility Type:	ER
DER Facility ID:	267780
Site ID:	332572
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	D4
SWIS:	2401
Spill Date:	2004-10-18
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2004-10-18
CID:	73
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-19
Spill Record Last Update:	2004-11-01
Spiller Name:	Not reported
Spiller Company:	Not reported

DRUM RUN (Continued) **S106722295**

Spiller Address:	2 PETTICOAT LA
Spiller Company:	001
Contact Name:	JOSEPH MCGOVERN
Latitude:	40.6759690
Longitude:	-73.9026750
DEC Memo:	11/1/04 TJD Drum emptied as part of Drum Run on 10/29/04. Spill closed
Remarks:	5 DRUMS VARYING SIZE CONTAINING WASTE OIL FOUND ABANDONED. NO LEAK AT THIS TIME. FD IS PACKING THE DRUMS.

All Materials:

Site ID:	332572
Operable Unit ID:	1094804
Operable Unit:	01
Material ID:	574936
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E41 **CON EDISON** **E MANIFEST** **1031624858**
SW **2430 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.076 mi.
402 ft. **Site 6 of 8 in cluster E**

Relative: **Lower**

Actual: **69 ft.**

E MANIFEST:

Manifest Tracking Number:	006747945GBF
Last Updated Date:	20211119
Shipped Date:	20211108
Received Date:	20211109
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	2430 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported

CON EDISON (Continued) **1031624858**

Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	CLEAN EARTH OF NORTH JERSEY
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	006747945GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	006747945GBF
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T
State Waste:	Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:

Manifest Tracking Number:	006747945GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	006747945GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	750
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.375
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.375
Waste Quantity, in Kilograms:	340.13626
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	340.13626
Management Method Code:	H110
Management Method Description:	STABILIZATION

CON EDISON (Continued) **1031624858**

Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

E42 **LOT 21,TAXBLOCK 1437** **NY E DESIGNATION** **S118704202**
SW **2432 ATLANTIC AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.076 mi.
403 ft. **Site 7 of 8 in cluster E**

Relative:
Lower

Actual:
68 ft.

E DESIGNATION:

Name:	LOT 21,TAXBLOCK 1437
Address:	2432 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	21
Tax Block:	1437
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2432 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6755392
Longitude:	-73.9044857
Type Of Ownership Code:	Not reported
Owner Name:	ENY HOLDING GROUP LLC
Borough:	BK
Tax Block:	1437
Tax Lot:	21
Community District:	316
Census Tract 2020:	3036502
Census Block 2020:	30365021004
Census Tract 2010:	365.02
Census Block 2010:	1001
School District:	23

LOT 21,TAXBLOCK 1437 (Continued) **S118704202**

City Council District:	37
Fire Company:	L176
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	C4-5D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	F9: Factory And Industrial Buildings - Miscellaneous
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	12500
Total Building Floor Area:	4641
Commercial Floor Area:	4641
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	720
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	3921
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	77.0000000
Lot Depth:	200.0000000
Building Frontage:	25.0000000
Building Depth:	150.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	4
Basement Type/Grade:	0
Assessed Land Value:	101250.00000
Assessed Total Value:	313650.00000
Exempt Total Value:	0.00000
Year Built:	1926
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.37000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	4.20000000000

LOT 21,TAXBLOCK 1437 (Continued) **S118704202**

Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014370021.00000000
Condominium Number:	Not reported
Census Tract 2:	036502
X Coordinate:	1010744
Y Coordinate:	185408
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 012
Tax Map #:	30508
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

D43 **MANHOLE #04264** **NY Spills** **S107787827**
North **FULTON STREET & VAN SINDEREN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.078 mi.
410 ft. **Site 5 of 6 in cluster D**

Relative: SPILLS:
Higher

Actual: Name:	MANHOLE #04264
78 ft. Address:	FULTON STREET & VAN SINDEREN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0601203 / 2006-06-14
Facility ID:	0601203
Facility Type:	ER
DER Facility ID:	313566
Site ID:	363385
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-05-02
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-05-02
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-02
Spill Record Last Update:	2006-07-17
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON MH #04264
Spiller Address:	FULTON STREET/VAN SINDERE

MANHOLE #04264 (Continued) **S107787827**

Spiller Company: 999
Contact Name: ERT DESK'
Latitude: Not reported
Longitude: Not reported
DEC Memo: 06/14/06 - See e-docs for Con Ed report detailing cleanup and closure.
164045. 5/2/06 10:25 HRS. V.
BAUCCIO #85835 UG REPORTS WHILE ON ROUTINE WORK IN MH04264 (ACCT 14893) FOUND APPROX 1 PT.
DIELECTRIC OIL ON 2 GALS OF WATER. NO FIRE/ SMOKE/ INJURIES INVOLVED. NO SEWERS/ WATERWAYS/PVT
PROPERTY AFFECTED.NO VISUAL WATER MOVEMENT. PRESENCE OF SUMPS/DRAINS NOT VERIFIED AT THIS TIME.
SPILL IS CONTAINED TO THE STRUCTURE & THE SOURCE APPEARS TO COME FROM A LEAKING 3c STRAIGHT JT. MS.
BAUCCIO & HER SUPV. REMOVED SOME ARC PROOFING AND SAW THE LEAK. FDR # TO FOLLOW. D-FAULT TAG #
06573 PLACED. ENV. STOP TAG # 48003 PLACED & SAMPLE TAKEN FOR PCB ON CHAIN OF CUSTODY #EE-08285
MARKED E-PRIORITY. CLEANUP PENDING DFAULT REPAIR & TEST RESULTS. CIG TO BE NOTIFIED. J. MASON
5/2/06 11:20 HRS AS PER CCR SHIFT MGR D-FAULT 06573 IS ON DEAD FDR 10225. J. MASON UPDATE 5/2/06
17:05 HRS CHEM LAB RESULTS RETURNED 2PPM LSN 06-04779-001 MATRIX: OIL GRAB LOCATION: S/S FULTON ST
144' E/O VAN SINDEREN AVE, STRUCTURE: MANHOLE 04264. J. MASON
Remarks: 1 pint on 2 gallons of water: no top 5 questions: coned # 164045

All Materials:
Site ID: 363385
Operable Unit ID: 1121440
Operable Unit: 01
Material ID: 2110937
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

D44 **VANSINDREN AVE** **NY Spills** **S108956156**
North **AT FULTON STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.078 mi.
410 ft. **Site 6 of 6 in cluster D**

Relative: **Higher**
Actual: **78 ft.**

SPILLS:
Name: VANSINDREN AVE
Address: AT FULTON STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0708240 / 2007-10-29
Facility ID: 0708240
Facility Type: ER
DER Facility ID: 338649
Site ID: 389092

VANSINDREN AVE (Continued) **S108956156**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-10-27
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-10-27
CID:	71
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-27
Spill Record Last Update:	2007-10-29
Spiller Name:	Not reported
Spiller Company:	NYC TRANSIT
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BOBBY ISAAC
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	minor spill - cleanup complete
Remarks:	LEAK IN TRANSMISSION ONTO STREET. CLEAN UP COMPLETE.

All Materials:

Site ID:	389092
Operable Unit ID:	1146243
Operable Unit:	01
Material ID:	2136608
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

F45 **PEREY TURNSTILES** **NY UST** **U003652029**
SSE **2490 ATLANTIC AVENUE** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.079 mi.
415 ft. **Site 2 of 6 in cluster F**

Relative: UST:
Lower

Actual: Name:	PEREY TURNSTILES
62 ft. Address:	2490 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-603884 / Unregulated/Closed
Program Type:	PBS

PEREY TURNSTILES (Continued) **U003652029**

Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592765.63096
UTM Y:	4503287.49506
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	25781
Affiliation Type:	Facility Owner
Company Name:	PEREY MANUFACTURING COMPANY, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	45 CHURCH STREET
Address2:	Not reported
City:	STAMFORD
State:	CT
Zip Code:	06906-1710
Country Code:	001
Phone:	(203) 961-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25781
Affiliation Type:	Mail Contact
Company Name:	PEREY TURNSTILES
Contact Type:	Not reported
Contact Name:	JOE TARNOWSKI
Address1:	45 CHURCH STREET
Address2:	Not reported
City:	STAMFORD
State:	CT
Zip Code:	06906
Country Code:	001
Phone:	(203) 961-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25781
Affiliation Type:	Facility Operator
Company Name:	PEREY TURNSTILES
Contact Type:	Not reported
Contact Name:	ED HENDRICKSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 498-6320
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

PEREY TURNSTILES (Continued) **U003652029**

Site Id:	25781
Affiliation Type:	Emergency Contact
Company Name:	PEREY MANUFACTURING COMPANY, INC.
Contact Type:	Not reported
Contact Name:	ED HENDRICKSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(203) 961-8444
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	55858
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	55859
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	12/01/1998

PEREY TURNSTILES (Continued) **U003652029**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None

Tank Number: 003
Tank ID: 55860
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

SPILLS:
Name: 2490 ATLANTIC AVENUE
Address: 2490 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY

PEREY TURNSTILES (Continued) **U003652029**

Spill Number/Closed Date:	9812107 / 1999-05-17
Facility ID:	9812107
Facility Type:	ER
DER Facility ID:	214707
Site ID:	263377
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	2401
Spill Date:	1998-12-29
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1998-12-29
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-29
Spill Record Last Update:	1999-05-17
Spiller Name:	JOE TARNOWSKI
Spiller Company:	PEREY MANUAFACTURING CO.
Spiller Address:	45 CHURCH STREET
Spiller Company:	001
Contact Name:	ED HENDRICKSON
Latitude:	40.6754395
Longitude:	-73.8995014
DEC Memo:	Not reported
Remarks:	CONTAMINATED SOIL - NO PRODUCT OR ODORS

All Materials:

Site ID:	263377
Operable Unit ID:	1069366
Operable Unit:	01
Material ID:	312390
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2490 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6753094
Longitude:	-73.9021787

PEREY TURNSTILES (Continued) **U003652029**

Type Of Ownership Code:	Not reported
Owner Name:	CLARENDON HOLDING CO., INC.
Borough:	BK
Tax Block:	3681
Tax Lot:	22
Community District:	305
Census Tract 2020:	3114400
Census Block 2020:	31144001010
Census Tract 2010:	1144
Census Block 2010:	1003
School District:	19
City Council District:	37
Fire Company:	L120
Police Precinct:	75
Health Center District:	33
Health Area:	5700
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	M1-4: Manufacturing Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G1: Garages And Gasoline Stations - All Parking Garages
Land Use Category:	Parking Facilities
Number Of Easements:	0
Lot Area:	6931
Total Building Floor Area:	7674
Commercial Floor Area:	7674
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	7674
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	76.8300000
Lot Depth:	100.5800000
Building Frontage:	76.1700000
Building Depth:	100.7500000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0

PEREY TURNSTILES (Continued) **U003652029**

Assessed Land Value:	37350.00000
Assessed Total Value:	337050.00000
Exempt Total Value:	0.00000
Year Built:	1966
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.11000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036810022.00000000
Condominium Number:	Not reported
Census Tract 2:	1144
X Coordinate:	1011384
Y Coordinate:	185325
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 009
Tax Map #:	31205
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

F46 **PEREY TURNSTILES** **UST FINDER** **1028573357**
SSE **2490 ATLANTIC AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.079 mi.
415 ft. **Site 3 of 6 in cluster F**

Relative: **Lower**

Actual: **62 ft.**

UST FINDER:

Object ID:	295796
Facility ID:	NY25781
Name:	PEREY TURNSTILES
Address:	2490 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	3
TOS USTs:	0
Population 1500ft:	3499
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported

PEREY TURNSTILES (Continued) **1028573357**

WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.90236
Y Coord:	40.675255
Latitude:	40.675255
Longitude:	-73.90236

UST FINDER:

Object ID:	1224403
Facility ID:	NY25781
Tank ID:	NY31654
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1224404
Facility ID:	NY25781
Tank ID:	NY34065
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	500
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1224405
Facility ID:	NY25781
Tank ID:	NY32454
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

F47 **209176; HINSDALE ST; M-65896** **NY Spills** **S109208161**
SE **HINSDALE ST; M-65896** **N/A**
< 1/8 **KINGS (County), NY**
0.082 mi.
434 ft. **Site 4 of 6 in cluster F**

Relative: **Lower**

Actual: **62 ft.**

SPILLS:

Name:	209176; HINSDALE ST; M-65896
Address:	HINSDALE ST; M-65896
City,State,Zip:	NY
Spill Number/Closed Date:	0890327 / 2007-12-28
Facility ID:	0890327
Facility Type:	ER

209176; HINSDALE ST; M-65896 (Continued) **S109208161**

DER Facility ID:	348704
Site ID:	399415
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2007-12-18
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2008-01-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-06-12
Spill Record Last Update:	2008-06-12
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
Latitude:	40.6756440
Longitude:	-73.9016780
DEC Memo:	Not reported
Remarks:	M-65896 FOUND 8 OZ. DIELECTRIC OIL ON 50 GALLONS OF WATER IN STRUCTURE Closed: Agency Approval Not Required

All Materials:

Site ID:	399415
Operable Unit ID:	1156281
Operable Unit:	01
Material ID:	2147160
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.06
Units:	G
Recovered:	Not reported
Resource Affected:	Utility
Oxygenate:	Not reported

F48 **205454; HINSDALE ST; M65997** **NY Spills** **S109207875**
SE **HINSDALE ST; M65997** **N/A**
< 1/8 **KINGS (County), NY**
0.082 mi.
434 ft. **Site 5 of 6 in cluster F**

Relative: **Lower**

Actual: **62 ft.**

SPILLS:

Name:	205454; HINSDALE ST; M65997
Address:	HINSDALE ST; M65997
City,State,Zip:	NY
Spill Number/Closed Date:	0890040 / 2007-04-26
Facility ID:	0890040
Facility Type:	ER
DER Facility ID:	348705
Site ID:	399128
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	2401
Spill Date:	2007-04-19
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2007-08-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	Not reported
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-06-12
Spill Record Last Update:	2008-06-12
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	5030 BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
Latitude:	40.6756440
Longitude:	-73.9016780
DEC Memo:	Not reported
Remarks:	M65997 FOUND IQT OF UNKNOWN OIL ON 2 QT OF WATER Closed: Agency Approval Not Required

All Materials:

Site ID:	399128
Operable Unit ID:	1155994
Operable Unit:	01
Material ID:	2147347
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.25
Units:	G
Recovered:	Not reported
Resource Affected:	Utility
Oxygenate:	Not reported

C49
NE
< 1/8
0.085 mi.
448 ft.

CON EDISON
FRONT OF 2493 FULTON ST
BROOKLYN, NY 11201

Site 5 of 5 in cluster C

NY MANIFEST **S117738680**
N/A

Relative:
Higher

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004717518
Country:	USA
Name:	Con Edison
Address:	FRONT OF 2493 FULTON ST
Address 2:	SB59112
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	FRONT OF 2493 FULTON ST
Location Address 2:	SB59112
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/22/2015
Trans1 Recv Date:	01/22/2015
Trans2 Recv Date:	01/26/2015
TSD Site Recv Date:	01/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004717518
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620367GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117738680**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

E50 **LOT 32,TAXBLOCK 1574** **NY E DESIGNATION** **S118704294**
West **2413 ATLANTIC AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.086 mi.
455 ft. **Site 8 of 8 in cluster E**

Relative:
Higher

Actual:
72 ft.

E DESIGNATION:

Name:	LOT 32,TAXBLOCK 1574
Address:	2413 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	32
Tax Block:	1574
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2413 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6762971
Longitude:	-73.9049569
Type Of Ownership Code:	Not reported
Owner Name:	2413 ATLANTIC AVE RTY CP
Borough:	BK
Tax Block:	1574

LOT 32,TAXBLOCK 1574 (Continued) **S118704294**

Tax Lot:	32
Community District:	316
Census Tract 2020:	3036700
Census Block 2020:	30367002003
Census Tract 2010:	367
Census Block 2010:	1005
School District:	23
City Council District:	37
Fire Company:	L176
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	2B
Zoning District 1:	C4-5D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	F5: Factory And Industrial Buildings - Light Manufacturing
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	7866
Total Building Floor Area:	12085
Commercial Floor Area:	12085
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	12085
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	2.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	93.0000000
Lot Depth:	84.5800000
Building Frontage:	43.0000000
Building Depth:	84.5800000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	63900.00000
Assessed Total Value:	484200.00000
Exempt Total Value:	0.00000
Year Built:	1921

LOT 32,TAXBLOCK 1574 (Continued) **S118704294**

Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.54000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	4.20000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015740032.00000000
Condominium Number:	Not reported
Census Tract 2:	0367
X Coordinate:	1010613
Y Coordinate:	185684
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 012
Tax Map #:	30603
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

F51 **VENTURE METAL PRODUCTS CORP** **RCRA NonGen / NLR** **1001405076**
ESE **2523 ATLANTIC AVE** **ICIS** **NYD053563219**
< 1/8 **BROOKLYN, NY 11207** **US AIRS**
0.092 mi. **FINDS**
486 ft. **Site 6 of 6 in cluster F** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
63 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Venture Metal Products Corp
Handler Address:	Atlantic Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYD053563219
Contact Name:	Not reported
Contact Address:	ATLANTIC AVE
Contact City,State,Zip:	BROOKLYN, NY 11207
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ATLANTIC AVE
Mailing City,State,Zip:	BROOKLYN, NY 11207

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Owner Name:	Venture Metal Products	
Owner Type:		County
Operator Name:	Venture Metal Products	
Operator Type:		County
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Mixtures.

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: VENTURE METAL PRODUCTS
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: VENTURE METAL PRODUCTS
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: VENTURE METAL PRODUCTS
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19981217
Handler Name: VENTURE METAL PRODUCTS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Receive Date:	20060101
Handler Name:	VENTURE METAL PRODUCTS CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	VENTURE METAL PRODUCTS CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19880617
Handler Name:	VENTURE METAL PRODUCTS CORP
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19990120
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ICIS:

Enforcement Action ID:	02-1991-0087
FRS ID:	110001571503
Action Name:	VENTURE METALS
Facility Name:	VENTURE METAL PRODUCTS INCORPORATED
Facility Address:	2523 ATLANTIC AVENUE BROOKLYN, NY 11207
Enforcement Action Type:	CAA 113 Notice Of Violation
Facility County:	KINGS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	113
Facility SIC Code:	3479
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.675706
Longitude in Decimal Degrees:	-73.900853

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Permit Type Desc: Not reported
Program System Acronym: 13717
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-000F000360470024300005
FRS ID: 110001571503
Action Name: VENTURE METAL PRODUCTS CORP 360470024300005
Facility Name: VENTURE METAL PRODUCTS CORP
Facility Address: 2523 ATLANTIC AVENUE
BROOKLYN, NY 11207
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3951
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.675916
Longitude in Decimal Degrees: -73.902588
Permit Type Desc: Not reported
Program System Acronym: NY0000002610500170
Facility NAICS Code: 339941
Tribal Land Code: Not reported

Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Fed Facility: No
NAIC Code: Not reported
SIC Code: 3471

Facility Name: VENTURE METAL PRODUCTS CORP
Address: 2523 ATLANTIC AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3479

US AIRS MINOR:
Envid: 1001405076
Region Code: 02
Programmatic ID: AIR NY0000002610500170
Facility Registry ID: 110001571503
D and B Number: Not reported
Primary SIC Code: 3951
NAICS Code: 339941
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610500170
Facility Registry ID: 110001571503
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-09-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500170
Facility Registry ID: 110001571503
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-04-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610500170
Facility Registry ID: 110001571503
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-10-09 00:00:00
Activity Status Date: Not reported

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	02
Programmatic ID:	AIR NY0000002610500170
Facility Registry ID:	110001571503
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1991-05-17 00:00:00
Activity Status Date:	1991-05-17 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

FINDS:
Registry ID: 110001571503

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001405076
Registry ID:	110001571503

DFR URL:

Name:	VENTURE METAL PRODUCTS CORP
Address:	2523 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207

NY MANIFEST:

EPA ID:	NYD053563219
Country:	USA
Name:	Venture Metal
Address:	2523 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	2525 ATLANTIC AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Venture Metal
Mailing Contact:	Venture Metal
Mailing Address 1:	2525 ATLANTIC AVENUE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11207
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183460596

Manifest Data:

Document ID:	NYB4018311
Manifest Status:	Not reported
Trans1 State ID:	PD1011
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	02/02/1993
Trans1 Recv Date:	02/02/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	SCA1124980
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5005
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	11/24/1998
Trans1 Recv Date:	11/24/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/07/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID 1:	SCD036275626
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

	One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00440
Units:	Gallons (liquids only)
Number of Containers:	008
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYB6773148
Manifest Status:	Not reported
Trans1 State ID:	NYPD1011
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	06/13/1996
Trans1 Recv Date:	06/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB2147004
Manifest Status:	Not reported
Trans1 State ID:	PD1011
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/1993
Trans1 Recv Date:	10/21/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD053563219
Trans1 EPA ID:	NYD077444263
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs

VENTURE METAL PRODUCTS CORP (Continued) **1001405076**

Handling Method: Burn
Specific Gravity: 01.00

G52 **RUSBRO TRANSMISSION INC** **EDR Hist Auto** **1020261970**
NE **2501 FULTON ST** **N/A**
< 1/8 **BROOKLYN, NY 11223**
0.095 mi.
502 ft. **Site 1 of 13 in cluster G**

Relative: EDR Hist Auto
Higher

Actual: **75 ft.**

Year:	Name:	Type:
1969	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1969	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1970	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1971	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1972	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1973	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1974	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1975	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1975	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1976	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1977	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1978	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1979	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1980	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1982	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1983	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1985	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1986	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1987	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1988	RUSBRO TRANSMISSION INC	Automotive Repair Shops, NEC
1989	RUSBRO TRANSMISSION INC	Automotive Transmission Repair Shops

---

H53 **JUNIUS DEVELOPMENT LLC** **NY AST** **A100301202**
SSW **1-25 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.102 mi.
536 ft. **Site 1 of 6 in cluster H**

Relative: AST:
Lower

Actual: **61 ft.**

Name:	JUNIUS DEVELOPMENT LLC
Address:	1-25 JUNIUS STREET
City,State,Zip:	BROOKLYN, NY 11212
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-604881
Program Type:	PBS
UTM X:	592600.96919
UTM Y:	4503273.61059
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	26750

JUNIUS DEVELOPMENT LLC (Continued) **A100301202**

Affiliation Type:	Facility Owner
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	325 E. 104TH ST.
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10029
Country Code:	001
Phone:	(212) 996-6456
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26750
Affiliation Type:	Mail Contact
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE MARGULIES
Address1:	325 EAST 104TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10029
Country Code:	001
Phone:	(212) 996-6456
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26750
Affiliation Type:	Facility Operator
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE MARGULIES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 335-9590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26750
Affiliation Type:	Emergency Contact
Company Name:	JUNIUS DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	STEVE MARGULIES
Address1:	Not reported
Address2:	Not reported

JUNIUS DEVELOPMENT LLC (Continued) **A100301202**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 335-9590
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	59055
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
B99 - Tank External Protection - Other
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/16/2002
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

H54 **VAULT** **NY Spills** **S118952400**
SSW **1 JUNIUS ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
536 ft. **Site 2 of 6 in cluster H**

Relative: **Lower**
Actual: **61 ft.**

SPILLS:

Name:	VAULT
Address:	1 JUNIUS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1606763 / 2017-12-08
Facility ID:	1606763
Facility Type:	ER
DER Facility ID:	135108

VAULT (Continued) **S118952400**

Site ID:	533402
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A4
SWIS:	2401
Spill Date:	2016-10-10
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2016-10-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-10-10
Spill Record Last Update:	2017-12-08
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	10/11/16 TJD EMIS Report 251707. Brooklyn underground vault transformer fire-failure; crews pending safe access to inspect and clean area. 12/8/17 - Austin - Transformer fire caused oil/soot to spray approx. 1 gal dielectric fluid onto adjoining sidewalk, street, and building wall - Con Ed contained and cleaned up the spill, and wipe samples came back as <1 ppm PCBs; Affected transformer was removed - See document files for further information - Spill closed - end
Remarks:	clean up pending outage

All Materials:

Site ID:	533402
Operable Unit ID:	1282123
Operable Unit:	01
Material ID:	2287454
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

H55 **CON ED V 2312** **RCRA NonGen / NLR** **1007206098**
SSW **1 JUNIS ST** **NY MANIFEST** **NYP004003547**
< 1/8 **BROOKLYN, NY 11201**
0.102 mi.
536 ft. **Site 3 of 6 in cluster H**

Relative: **Lower**
Actual: **61 ft.**

RCRA Listings:

Date Form Received by Agency:		19980228
Handler Name:		Con Ed V 2312
Handler Address:		1 Junis St
Handler City,State,Zip:		BROOKLYN, NY 11201-0000
EPA ID:		NYP004003547
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CON EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		CON EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON ED V 2312 (Continued) **1007206098**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED V 2312	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED V 2312	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED V 2312	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON ED V 2312 (Continued) **1007206098**

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004003547
Country: USA
Name: Con Ed V 2312
Address: 1 JUNIS ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11201-0000
Zip 4: Not reported
Location Address 1: 1 JUNIS ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: 0000
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Ed V 2312
Mailing Contact: Not reported
Mailing Address 1: Not reported
Mailing Address 2: Not reported
Mailing City,State,Zip: Not reported
Mailing Zip 4: Not reported
Mailing Country: Not reported
Mailing Phone: Not reported

H56 **CON EDISON - VAULT V2483** **NY LTANKS** **S105054906**
SSW **1 JUNIUS ST** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11212** **NY MANIFEST**
0.102 mi.
536 ft. **Site 4 of 6 in cluster H**

Relative: **Lower**
Actual: **61 ft.**

LTANKS:
Name: FACTORY
Address: 1 JUNIUS ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0101889 / 2003-08-14
Facility ID: 0101889
Site ID: 159948
Spill Date: 2001-05-17
Spill Cause: Tank Test Failure

CON EDISON - VAULT V2483 (Continued) **S105054906**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-05-18
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-18
Spill Record Last Update:	2003-08-14
Spiller Name:	SAME
Spiller Company:	FACTORY
Spiller Address:	1 JUNIUS ST
Spiller County:	001
Spiller Contact:	BILL SILVERI
Spiller Phone:	(212) 563-3933
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	135108
Latitude:	40.6751338
Longitude:	-73.9042985
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 8/14/2003 Property owner Paul Verricelli 631-842-9595 submitted a letter and photos showing that the aboveground tank had been removed and there was no contamination left behind.
Remarks:	obvious vent pipe leak, minimally.

All TTF:

Facility ID:	0101889
Spill Number:	0101889
Spill Tank Test:	1526308
Site ID:	159948
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	159948
Operable Unit ID:	838763
Operable Unit:	01

CON EDISON - VAULT V2483 (Continued) **S105054906**

Material ID:	537584
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	1 JUNIUS ST
Address:	1 JUNIUS ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9610713 / 1998-10-19
Facility ID:	9610713
Facility Type:	ER
DER Facility ID:	135108
Site ID:	159949
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-11-26
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1996-11-27
CID:	351
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-27
Spill Record Last Update:	2003-03-17
Spiller Name:	PAT MCHUGH
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	PAT MCHUGH
Latitude:	40.6751338
Longitude:	-73.9042985
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL
Remarks:	a network protector set on fire possibly causing a release - samples are currently being taken

All Materials:

Site ID:	159949
Operable Unit ID:	1042096
Operable Unit:	01

CON EDISON - VAULT V2483 (Continued) **S105054906**

Material ID:	342925
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYP004994735
Country:	USA
Name:	Con Edison - Vault V2483
Address:	1 JUNIUS ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11212
Zip 4:	Not reported
Location Address 1:	1 JUNIUS ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11212
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison - Vault V2483
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

G57 **CON EDISON - VAULT SUBMERSIBLE 2538** **RCRA-LQG** **1024891483**
ENE **2020 BROADWAY** **NYP005115332**
< 1/8 **BROOKLYN, NY 11207**
0.106 mi.
561 ft. **Site 2 of 13 in cluster G**

Relative:
Higher

Actual:
76 ft.

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Vault Submersible 2538
Handler Address:	Broadway
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP005115332
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST

CON EDISON - VAULT SUBMERSIBLE 2538 (Continued) **1024891483**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON - VAULT SUBMERSIBLE 2538 (Continued) **1024891483**

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170723
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170723
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - VAULT SUBMERSIBLE 2538
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G58 **CON EDISON** **NY MANIFEST** **S121968412**
ENE **2020 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.106 mi.
561 ft. **Site 3 of 13 in cluster G**

Relative:
Higher

Actual:
76 ft.

NY MANIFEST:

EPA ID:	NYP005115332
Country:	USA
Name:	Con Edison
Address:	2020 BROADWAY
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	2020 BROADWAY
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

G59 **EAST NEW YORK TRUCK SHOP** **NY AST** **A100520445**
NE **1997 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.108 mi.
571 ft. **Site 4 of 13 in cluster G**

Relative:
Higher

Actual:
77 ft.

AST:

Name:	EAST NEW YORK TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000445
Program Type:	CBS
UTM X:	592679.18231
UTM Y:	4503688.09487
Expiration Date:	N/A
Site Type:	Trucking/Transportation/Fleet Operation

Tank Info:

Tank Number:	ANTI
Tank Id:	212416
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed

EAST NEW YORK TRUCK SHOP (Continued) **A100520445**

Pipe Model:	Not reported
Install Date:	06/01/2001
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/28/2012
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	W. ANTI
Tank Id:	212417
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/2001
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/28/2012
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

G60 **EAST NEW YORK TRUCK SHOP** **UST FINDER** **1028574538**
NE **1997 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.108 mi.
571 ft. **Site 5 of 13 in cluster G**

Relative:
Higher

Actual:
77 ft.

UST FINDER:

Object ID:	295958
Facility ID:	NY30951
Name:	EAST NEW YORK TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	3339
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported

EAST NEW YORK TRUCK SHOP (Continued) **1028574538**

WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.902167
Y Coord:	40.6783
Latitude:	40.6783
Longitude:	-73.902167

UST FINDER:

Object ID:	1227086
Facility ID:	NY30951
Tank ID:	NY34382
Tank Status:	Open
Installation Date:	1999/03/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

G61 **NYC TRANSIT EAST NY TRUCK SHOP** **NY Spills** **S118460217**
NE **1997 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.108 mi.
571 ft. **Site 6 of 13 in cluster G**

Relative: **Higher**

Actual: **77 ft.**

SPILLS:

Name:	NYC TRANSIT EAST NY TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1509110 / 2015-12-07
Facility ID:	1509110
Facility Type:	ER
DER Facility ID:	472033
Site ID:	517716
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2015-12-07
Investigator:	RMOMAR
Referred To:	Not reported
Reported to Dept:	2015-12-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

NYC TRANSIT EAST NY TRUCK SHOP (Continued) **S118460217**

Date Entered In Computer:	2015-12-07
Spill Record Last Update:	2015-12-07
Spiller Name:	Not reported
Spiller Company:	NYC TRANSIT
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ISABEL POTTER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/7/2015: Rashad Duty Desk Called Isabel from NYC Transit, she said vendors truck broke down and about 25 gallons of hydraulic fluid spilled, they initially cleaned about 10 gallons of the spill with sand and other adsorbents. Isabel said the oil did not impact any drains and sewers and they will be cleaning up the rest of the oil shortly. Spill will be closed.
Remarks:	LOSS TO ROADWAY, C/U IN PROGRESS- 10 GALLONS RECOVERED, CONTAINED

All Materials:

Site ID:	517716
Operable Unit ID:	1266784
Operable Unit:	01
Material ID:	2270741
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

G62 **EAST NY TRUCK SHOP** **NY Spills** **S118951726**
NE **1997 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.108 mi.
571 ft. **Site 7 of 13 in cluster G**

Relative: **Higher**
Actual: **77 ft.**

SPILLS:

Name:	EAST NY TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1606041 / 2016-09-16
Facility ID:	1606041
Facility Type:	ER
DER Facility ID:	472033
Site ID:	532632
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2016-09-15
Investigator:	JKKANN
Referred To:	Not reported
Reported to Dept:	2016-09-16
CID:	Not reported

EAST NY TRUCK SHOP (Continued) **S118951726**

Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-09-16
Spill Record Last Update:	2016-09-16
Spiller Name:	Not reported
Spiller Company:	NYC TRANSIT
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KERMONI
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	9/16/16: J.Kann - contacted Ire Adelei. He confirmed that spill was 5 gallons to the containment area. Pavement only affected. No drains or sewers. Cleanup done with speedi dry and mats. Tank is being wiped down now. Spill closed.
Remarks:	Caller advised aprx 5 gal of oil was overfilled from storage tank #2. Clean up is in progress.

All Materials:

Site ID:	532632
Operable Unit ID:	1281379
Operable Unit:	01
Material ID:	2286650
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

G63 **EAST NEW YORK TRUCK SHOP** **NY AST** **A100521307**
NE **1997 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.108 mi.
571 ft. **Site 8 of 13 in cluster G**

Relative:
Higher

Actual:
77 ft.

AST:

Name:	EAST NEW YORK TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609105
Program Type:	PBS
UTM X:	592777.77447

EAST NEW YORK TRUCK SHOP (Continued) **A100521307**

UTM Y: 4503625.69156
Expiration Date: 07/16/2028
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 30951
Affiliation Type: Mail Contact
Company Name: NEW YORK CITY TRANSIT
Contact Type: DIRECTOR, EPIH
Contact Name: DOREEN BOATSWAIN
Address1: 2 BROADWAY
Address2: 27TH FLOOR
City: NEW YORK
State: NY
Zip Code: 10004
Country Code: 001
Phone: (646) 252-5777
EMail: EnvironmentalProtectionNYCT@nyct.com
Fax Number: Not reported
Modified By: nFormUpd
Date Last Modified: 2024-10-18

Site Id: 30951
Affiliation Type: Facility Operator
Company Name: EAST NEW YORK TRUCK SHOP
Contact Type: Not reported
Contact Name: PETER CASSAR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 566-3880
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2023-06-06

Site Id: 30951
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY TRANSIT
Contact Type: DIRECTOR, ENVIRONMENTAL PROTECTION
Contact Name: DOREEN BOATSWAIN
Address1: 2 BROADWAY 27TH FLR.
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10004
Country Code: 001
Phone: (646) 252-5777
EMail: DOREEN.BOATSWAIN@NYCT.COM
Fax Number: Not reported
Modified By: KXLIU
Date Last Modified: 2021-09-14

Site Id: 30951
Affiliation Type: Emergency Contact

EAST NEW YORK TRUCK SHOP (Continued) **A100521307**

Company Name:	NEW YORK CITY TRANSIT
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-11-22

Tank Info:

Tank Number:	ATF-1
Tank Id:	66445
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G) C01 - Pipe Location - Aboveground J02 - Dispenser - Suction Dispenser L00 - Piping Leak Detection - None G12 - Tank Secondary Containment - Double-Walled (AG only) I02 - Overfill - High Level Alarm K01 - Spill Prevention - Catch Basin D01 - Pipe Type - Steel/Carbon Steel/Iron E00 - Piping Secondary Containment - None F01 - Pipe External Protection - Painted/Asphalt Coating H01 - Tank Leak Detection - Interstitial - Electronic Monitoring A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1999
Capacity Gallons:	1000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	transmission fluid

Tank Number:	M/O-1
Tank Id:	66446
Material Code:	0013

EAST NEW YORK TRUCK SHOP (Continued) **A100521307**

Common Name of Substance: Lube Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/01/1999
Capacity Gallons: 1000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: motor oil

Tank Number: M/O-2
Tank Id: 66447
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

EAST NEW YORK TRUCK SHOP (Continued) **A100521307**

Pipe Model:	Not reported
Install Date:	03/01/1999
Capacity Gallons:	1000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil

Tank Number:	W/O-02
Tank Id:	66448
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
K01 - Spill Prevention - Catch Basin
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/1999
Capacity Gallons:	500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

G64 **NYCTA(BROADWAY ENY SUBSTATION)** **RCRA NonGen / NLR** **1018280008**
NE **1997 BROADWAY** **FINDS** **NYP004748661**
< 1/8 **BROOKLYN, NY 11207** **ECHO**
0.108 mi. **E MANIFEST**
571 ft. **Site 9 of 13 in cluster G**

Relative: **Higher**
Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:		20150311
Handler Name:		Con Edison
Handler Address:		Broadway
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004748661
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

NYCTA(BROADWAY ENY SUBSTATION) (Continued) **1018280008**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150311
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150311
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NYCTA(BROADWAY ENY SUBSTATION) (Continued) **1018280008**

FINDS:
Registry ID: 110067699949

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280008
Registry ID:	110067699949
DFR URL:	
Name:	CON EDISON
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207

E MANIFEST:

Manifest Tracking Number:	020507045JJK
Last Updated Date:	20190927
Shipped Date:	20190423
Received Date:	20190423
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Nycta(Broadway Eny Substation)
Generator Location Street Number:	Not reported
Generator Location Street 1:	1997 BROADWAY
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1997 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported

NYCTA(BROADWAY ENY SUBSTATION) (Continued) **1018280008**

Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

State Waste:

Manifest Tracking Number:	020507045JJK
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	L
State Waste:	Landfill. Waste management method code to be used on e-Manifest only

Transporter:

Manifest Tracking Number:	020507045JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Allstate Power Vac, Inc.

Waste Line:

Manifest Tracking Number:	020507045JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	UN3432, Polychlorinated biphenyls, solid, 9 , II
Number of Containers:	1
Container Type Code:	CW
Container Type Description:	Wooden boxes, cartons, cases
Waste Quantity:	633
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	0.69788206
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.69788206
Waste Quantity, in Kilograms:	633
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	633
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported

NYCTA(BROADWAY ENY SUBSTATION) (Continued) **1018280008**

EPA Waste Indicator: N

G65 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031612313**
NE **OPP 2003 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.109 mi.
573 ft. **Site 10 of 13 in cluster G**

Relative:
Higher

Actual:
78 ft.

E MANIFEST:

Manifest Tracking Number:	023096271JJK
Last Updated Date:	20211220
Shipped Date:	20211205
Received Date:	20211206
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	OPP 2003 BROADWAY
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	023096271JJK
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	023096271JJK

CON EDISON - COMPANY OF NY (Continued) **1031612313**

Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 023096271JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 023096271JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

66
West
< 1/8
0.112 mi.
590 ft.

CON EDISON
FRONT OF 12 JARDINE PL
BROOKLYN, NY 11237

NY MANIFEST **S117738882**
N/A

Relative:
Higher

Actual:
75 ft.

NY MANIFEST:

EPA ID:	NYP004719621
Country:	USA
Name:	Con Edison
Address:	FRONT OF 12 JARDINE PL
Address 2:	SB21350
City,State,Zip:	BROOKLYN, NY 11237
Zip 4:	Not reported
Location Address 1:	FRONT OF 12 JARDINE PL
Location Address 2:	SB21350
Location City,State,Zip:	BROOKLYN, NY 11237
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/28/2015
Trans1 Recv Date:	01/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004719621
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620892GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117738882**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	60
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

I67 **LOT 46,TAXBLOCK 1437** **NY BROWNFIELDS** **S118704373**
SW **2435 PACIFIC STREET** **NY E DESIGNATION** **N/A**
< 1/8 **BROOKLYN, NY 11233** **NY NYC OER**
0.113 mi. **NY NYC LAND USE**
596 ft. **Site 1 of 13 in cluster I**

Relative: **Lower**
Actual: **68 ft.**

BROWNFIELDS:

Name:	2435 PACIFIC STREET
Address:	2435 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Program:	BCP
Site Code:	617184
Acres:	0.800
HW Code:	C224322
SWIS:	2401
Town:	New York City
Record Added Date:	03/17/2021
Record Updated Date:	08/25/2023
Update By:	RKCORCOR
Site Description:	Location: The 0.8-acre site is located in an urban area of Brooklyn on the northern side of Pacific Street, between Sackman Street to the west and East New York Avenue to the east. The site is comprised of two contiguous tax lots (Lot 46 to the east and Lot 58 to the west). Site Features: The site is primarily grassy land. Gravel and paved surface areas are located along the western and southern property borders, respectively. Chain-link fences and concrete block walls define the property borders. Current Zoning and Land Use: The site is currently vacant and is located in a mixed-use C4-5D/R7D zoning district (a general commercial district with a residential overlay). The adjoining parcels are currently used for a combination of institutional (north), industrial (east), residential (south), and commercial (northeast and west) purposes. Past Uses of the Site: The site was first developed for commercial and manufacturing use sometime between 1908 and 1928. Known commercial uses have included a large automobile garage containing gasoline tanks on Lot 46, subsequently used as a manufacturing facility for elevators, lamps

LOT 46,TAXBLOCK 1437 (Continued) **S118704373**

and clothing, and a warehouse on Lot 58 that was occupied by a clothing manufacturer and several retail stores. On-site buildings were demolished by the 1980s (Lot 58) and 2007 (Lot 46). Site Geology and Hydrogeology: Site soils are derived from glacial materials, which overlie deep glacial deposits of sand, gravel and clay, with bedrock located well below the surface, beyond 102 feet below ground surface (bgs). Subsurface soils generally consist of fill (coarse to medium sand, clay, crushed stone, crushed brick and crushed concrete), ranging in depth from three to 15 feet bgs, and underlying native materials were generally comprised of sands with variable size gravel. Geotechnical borings documented deeper native materials comprised of dense sands and gravels. Site elevation is about 68 feet above mean sea level. Depth to groundwater (from well casings) is about 60 feet bgs. Groundwater flow in the vicinity of the property generally follows surficial topography in a southeasterly direction, toward Jamaica Bay (located approximately three miles from the property).

Env Problem:

Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), pesticides, herbicides, and cyanide during the Remedial Investigation. Soil results were compared to restricted residential soil cleanup objectives (RRSCOs) and the restricted residential guidance values for PFAS. Groundwater results were compared to the Ambient Water Quality Standards and Guidance Values (AWQSs and AWQGVs). Soil vapor samples were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern for the site are lead and polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Soil PAHs (e.g., benzo(a)anthracene) and lead were detected above RRSCOs in on-site fill materials. PAHs were detected above RRSCOs in soil in the majority of the soil borings from the surface to as deep as 15 feet below ground surface (bgs). However, the majority of the impacts were in the shallower sample intervals. For PAHs, the maximum values, as compared to the RRSCO include: benzo(a)anthracene at 82 parts per million (ppm); benzo(a)pyrene at 77 ppm; and benzo(b)fluoranthene at 75 ppm (RRSCOs 1 ppm); and benzo(k)fluoranthene at 71 ppm (RRSCO 3.9 ppm). Lead was detected above the RRSCO of 400 ppm at up to 2,620 ppm. Sampling of the deepest soil intervals, which reached clean native materials, generally showed limited contamination. These findings are consistent with general impacts from poor-quality fill, demolition debris, and/or former commercial uses, rather than any localized source areas of soil contamination. Data do not indicate any off-site impacts in soil related to this site. Groundwater Concentrations of some ubiquitous metals (e.g., sodium and manganese) exceed, and some PAH compounds in groundwater slightly exceed, their respective AWQS and are not considered contaminants of concern in groundwater. PFAS were reported in all groundwater samples, including the upgradient wells. Perfluorooctanesulfonic acid (PFOS) was detected up to 57.0 parts per trillion (ppt) (AWQGV 2.7 ppt), and perfluorooctanoic acid PFOA was detected up to 87.2 ppt (AWQGV 6.7 ppt). The results indicate that the site is not a source of PFAS to groundwater. Groundwater contamination may, in part, be related to the presence of poor-quality on-site fill materials. However, groundwater impacts are similar to conditions typically encountered in urban areas and are likely related to local groundwater conditions, rather than a significant onsite source areas. Data do not indicate any off-site

LOT 46,TAXBLOCK 1437 (Continued) **S118704373**

	impacts in groundwater related to the site. Soil Vapor - Soil vapor samples were analyzed for VOCs. Soil vapor was not found to be impacted by site-related contamination. The highest detections were for acetone up to 945 micrograms per cubic meter (?g/m3), tertiary butyl alcohol up to 355 ?g/m3, chloroform up to 532 ?g/m3, and tetrachloroethene up to 180 ?g/m3. Data do not indicate any off-site impacts in soil vapor related to the site.
Health Problem:	People will not come into contact with contaminated soil or groundwater unless they dig below the ground surface. People are not drinking the groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air is not a current concern, however could be a concern for future on-site occupied structures. Environmental sampling indicates soil vapor is not a concern for off-site buildings.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-06-18 09:16:00
Record Upd:	2023-05-19 14:34:00
Updated By:	TLRUTLAN
Own Op:	1
Sub Type:	NNN
Owner Name:	Elaine Frazier
Owner Company:	Love Fellowship Tabernacle, Inc.
Owner Address:	464 Liberty Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mike McCarthy
Owner Company:	2435 Pacific Street LLC
Owner Address:	111 John Street, Suite 1710
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10038
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Paul Levy
Owner Company:	Brooklyn Public Library - Brownsville Branch
Owner Address:	61 Glenmore Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN

LOT 46,TAXBLOCK 1437 (Continued) **S118704373**

Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 16
Owner Address:	444 Thomas Boyland Street, Rm. 103
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
HW Code:	C224322
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224322
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224322
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224322
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224322
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

E DESIGNATION:

Name:	LOT 46,TAXBLOCK 1437
Address:	2435 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	46
Tax Block:	1437
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	2435 PACIFIC STREET
Address:	2435 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY

LOT 46,TAXBLOCK 1437 (Continued) **S118704373**

Latitude:	40.675235
Longitude:	-73.904872
OER Project Numbers:	19TMP1561K,19EHAN348K
BBL:	3.0143700463014302E+19
OER Program:	E/RD (Review), State BCP, Jumpstart
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3038668
NTA:	Ocean Hill

NYC LAND USE:

Name:	Not reported
Address:	2435 PACIFIC STREET
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6754575
Longitude:	-73.9052609
Type Of Ownership Code:	Not reported
Owner Name:	LOVE FELLOWSHIP TABERNACLE INC
Borough:	BK
Tax Block:	1437
Tax Lot:	46
Community District:	316
Census Tract 2020:	3036502
Census Block 2020:	30365021004
Census Tract 2010:	365.02
Census Block 2010:	1001
School District:	23
City Council District:	37
Fire Company:	L176
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	C4-5D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D6: Elevator Apartments - Fireproof With Stores
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0
Lot Area:	35000
Total Building Floor Area:	236732

LOT 46,TAXBLOCK 1437 (Continued) **S118704373**

Commercial Floor Area:	26140
Residential Floor Area:	210592
Office Floor Area:	0
Retail Floor Area:	6963
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	19177
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	10.0000000
Residential Units:	236
Total Units:	237
Lot Frontage:	350.0000000
Lot Depth:	100.0000000
Building Frontage:	215.0000000
Building Depth:	60.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	1274850.00000
Assessed Total Value:	1274850.00000
Exempt Total Value:	0.00000
Year Built:	2024
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	6.76000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	4.20000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014370046.00000000
Condominium Number:	Not reported
Census Tract 2:	036502
X Coordinate:	1010529
Y Coordinate:	185378
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 012
Tax Map #:	30508
E-designation Number:	E-366
Apportionment BBL:	3014370046.00000000
Apportionment Date:	01/19/2023
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

I68 **FLYING SERVICE BOX COVER** **NY Spills** **S107657546**
WSW **2402 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.114 mi.
600 ft. **Site 2 of 13 in cluster I**

Relative: **Higher**
Actual: **71 ft.**

SPILLS:

Name:	FLYING SERVICE BOX COVER
Address:	2402 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514131 / 2009-09-10
Facility ID:	0514131
Facility Type:	ER
DER Facility ID:	310961
Site ID:	360779
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-09
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2006-03-09
CID:	73
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-10
Spill Record Last Update:	2009-09-10
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	ERT DESK'
Latitude:	40.6758750
Longitude:	-73.9055780
DEC Memo:	09/10/09 - See eDocs for Con Ed report detailing cleanup and closure. 163273. 3/9/06 2220HRS O.S TINO FERNADEZ #56150 ENVIR OPPS REPORTS ARRIVED ON LOCATION 2402 ATLANTIC AVE AND FOUND THAT A SERVICE BOX COVER F/O 2402 ATLANTIC AVE HIT A TRACTER TRAILER FUEL TANK CAUSING IT TO SPILL APPPROX 100 GALLONS OF DIESEL FUEL ONTO AN AREA OF 400' BY 30' OF ASPHALT .ALSO FOUND APPROX 5-GALLONS OF DIESEL FUEL THAT ENTERED A SB W/O 2402 ATLANTIC AVE.REPORTS 3-CATCH BASINS ALONG THE CURB ALSO AFFECTED WITH FUEL AND 3- PRIVATE VEHICLES THAT WERE PARKED ON LOCATION HAD FUEL ON TIRES . .NYPD ON LOCATION CORDIN AREA OFF STREET .DEPT OF SANITATION ON LOCATION AND PLACED SAND DOWN ON STREET.TINO REPORTS DEP CELEST OKOLI ON LOCATION .ENVIR EH&S RON CONSENTINO WAS NOTIFIED.CIG P MCGUIRE NOTIFIED AT 2240HRS .MORE INFO TO FOLLOW.G DONATONE 3/9/06

FLYING SERVICE BOX COVER (Continued) **S107657546**

Remarks: UPDATE T.FERNANDEZ REPORTS AREA
AFFECTED AT THIS TIME IS 400' BY 15' AND ALSO 2-CATCH BASIN WERE AFFECTED.PLATE # TO TRACTOR
-TRAILER IS (253228. INDIANA) THE OWNER OF TRUCK IS (RYAN FARRELL) FERRELL TRUCKING.DRIVER OF
TRUCK IS ELVIN MASON.DRIVER WAS TAKEN TO UNKNOWN HOSIPTAL. G DONATONE EXPLOSION IN A MANHOLE CAUSE COVER TO FLY AND HIT A PARKED VEHICLE WHICH RESULTED IN FUEL LEAK COVERING AN AREA OF 400'X30' AREA. SOME MAY HAVE REACHED A CATCH BASIN (PER DEP). On 3/9/06 at 2340pm Petty Officer 2nd Class of the US Coast Guard called inquiring about this report and asked to have the DEC Rep contact him at 917-439-5919 or 203-577-8898. DEC Rep Ryan Piper advised. 163273.

All Materials:

Site ID:	360779
Operable Unit ID:	1117898
Operable Unit:	01
Material ID:	2108404
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	2402 ATLANTIC AVE
Address:	2402 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514130 / 2006-03-10
Facility ID:	0514130
Facility Type:	ER
DER Facility ID:	310961
Site ID:	360778
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-03-09
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2006-03-09
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-03-10
Spill Record Last Update:	2006-03-10
Spiller Name:	Not reported

FLYING SERVICE BOX COVER (Continued) **S107657546**

Spiller Company:	FARRELL TRUCKING
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	SAME AS ABOVE
Latitude:	40.6758750
Longitude:	-73.9055780
DEC Memo:	3/9/06- DEC Piper placed call into FDNY. They forwarded me to on site responder. Left message requesting call back. DEC Piper contacted DEP. As per them a truck traveling over a recessed manhole, popped up the manhole and ruptured the saddle tank. Spill to roadway. FDNY pumped catch basin, approx 80 gal. and speedy dried roadway. DEC Piper spoke w/ DEP Celeste on site. No DEC response needed. Under control. Closed.
Remarks:	SUNKEN MANHOLE COVER POPPED UP AND RUPTURED TANK - UNKNOWN QTY WENT INTO STORM DRAIN

All Materials:

Site ID:	360778
Operable Unit ID:	1117897
Operable Unit:	01
Material ID:	2108403
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

I69 **CONSOLIDATED EDISON COMPANY OF NY INC** **E MANIFEST** **1031632998**
WSW **2402 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11223**
0.114 mi.
600 ft. **Site 3 of 13 in cluster I**

Relative:
Higher

Actual:
71 ft.

E MANIFEST:

Manifest Tracking Number:	016955053FLE
Last Updated Date:	20220921
Shipped Date:	20220913
Received Date:	20220914
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Consolidated Edison Company Of Ny Inc
Generator Location Street Number:	Not reported
Generator Location Street 1:	2402 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11223
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	116 SKYLINE DRIVE

CONSOLIDATED EDISON COMPANY OF NY INC (Continued) **1031632998**

Generator Mail Street 2:	Not reported
Generator Mail City:	SOUTH PLAINFIELD
Generator Mail Zip:	07080
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	016955053FLE
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	016955053FLE
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T
State Waste:	Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:

Manifest Tracking Number:	016955053FLE
Transporter Line Number:	1
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services Inc

Waste Line:

Manifest Tracking Number:	016955053FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	2000
Quantity Unit of Measure Code:	P

CONSOLIDATED EDISON COMPANY OF NY INC (Continued) **1031632998**

Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	1
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	1
Waste Quantity, in Kilograms:	907.03
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	907.03
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

I70 **CON EDISON** **E MANIFEST** **1031624835**
WSW **2402 ATLANTIC AVE** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.114 mi.
600 ft. **Site 4 of 13 in cluster I**

Relative: **Higher**

Actual: **71 ft.**

E MANIFEST:

Manifest Tracking Number:	006747944GBF
Last Updated Date:	20211119
Shipped Date:	20211108
Received Date:	20211109
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	2402 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE

CON EDISON (Continued) **1031624835**

Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: CLEAN EARTH OF NORTH JERSEY
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 006747944GBF
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 006747944GBF
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 006747944GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006747944GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 750
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.375
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.375
Waste Quantity, in Kilograms: 340.13626
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 340.13626
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N

CON EDISON (Continued) **1031624835**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

I71 **2402 ATLANTIC HOLDINGS LLC** **NY AST** **A100300849**
WSW **2402 ATLANTIC AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 10038**
0.114 mi.
600 ft. **Site 5 of 13 in cluster I**

Relative: **Higher**

Actual: **71 ft.**

AST:

Name:	2402 ATLANTIC HOLDINGS LLC
Address:	2402 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 10038
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608095
Program Type:	PBS
UTM X:	592492.28127
UTM Y:	4503353.46483
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	29947
Affiliation Type:	Facility Owner
Company Name:	2402 ATLANTIC HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	49 WEST 44TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 453-4005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29947
Affiliation Type:	Mail Contact
Company Name:	2402 ATLANTIC HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	49 WEST 44TH STREET

2402 ATLANTIC HOLDINGS LLC (Continued) **A100300849**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10038
Country Code:	001
Phone:	(212) 453-4005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29947
Affiliation Type:	Facility Operator
Company Name:	2402 ATLANTIC HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	NA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29947
Affiliation Type:	Emergency Contact
Company Name:	2402 ATLANTIC HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	SUIMMY HORN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 453-4005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	64433
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

2402 ATLANTIC HOLDINGS LLC (Continued) **A100300849**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/2002
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

G72 **VAULT VS2603** **NY Spills** **S106007972**
ENE **2051 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY**
0.114 mi.
603 ft. **Site 11 of 13 in cluster G**

Relative:
Higher

Actual:
77 ft.

SPILLS:

Name:	VAULT VS2603
Address:	2051 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0206776 / 2004-01-20
Facility ID:	0206776
Facility Type:	ER
DER Facility ID:	217501
Site ID:	267009
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-09-30
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2002-09-30
CID:	281
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-30
Spill Record Last Update:	2004-01-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN

VAULT VS2603 (Continued) **S106007972**

Spiller Address: Not reported
Spiller Company: 999
Contact Name: TOM MARCINEK
Latitude: 40.6776359
Longitude: -73.9012165
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was
FOLEY Con Ed e2mis #145316:
9/30/02 10:00 HRS. S. FULLER #37342 OF EQUIPMENT GROUP REPORTS WHILE PUMPING WATER OUT OF V-2603 AT
09:50 HRS. FOUND AN UNDIAPERABLE SHEEN OF UNKNOWN OIL ON APPROX. 75 GAL WATER. NO OIL WAS PUMPED
OUT OF VAULT. NO SEWER OR WATERWAYS APPEAR TO BE AFFECTED. NO PRIVATE PROPERTY AFFECTED. NO FIRE OR
SMOKE INVOLVED. NO SUMP PUMP AND PIPING FROM OLD PUMP WAS FOUND SEALED. VAULT IS CONNECTED TO
ADJACENT VAULT V-2538 VIA FLOOR DRAIN (SAW WATER GOING DOWN IN V-2538 WHILE PUMPING OUT V-2603).
ENV. STOP TAG #31086 PLACED. TRANSFORMER WILL BE PRESSURE TESTED AND SAMPLE WILL BE TAKEN. CLEANUP
PENDING PCB RESULTS FROM CHEM LAB. PARKING RESTRICTIONS: NO PARKING MID. - 3AM, MON. & THUR.
TRANSFORMER INFO FROM ECC WAREHOUSE -- MANUFACTURER: AC, MFR. DATE 1980, INSTALLED DATE 1988,
HISTORICAL PCB RESULTS FROM 1988 SAMPLE ARE 20 PPM. UPDATE 9/30/02 10:15 HRS. -- S. FULLER REPORTS
PRESSURE TEST OF V-2603 FAILED, BUT ONLY NITROGEN IS LEAKING OUT OF TOP-MOUNTED GROUND SWITCH
HANDLE -- NO OIL LEAK VISIBLE. HE WILL TAKE AN OIL& WATER SAMPLE FROM THE SPILL. UPDATE 9/30/02
10:25 HRS. -- AFTER SPEAKING WITH R. JAMES OF EH&S, I ASKED FULLER TO ALSO TAKE AN OIL SAMPLE FROM
THE TRANSFORMER. FULLER REPORTS BOTH SAMPLES WILL BE DELIVERED TO CHEM LAB VIA COURIER. 9/30/02
10:51 HRS. -- NOTIFIED C. McCARTHY OF C.I.G. 9/30/02=1110hrs UPDATE S.FULLER REPORTS ENVIR
TAG#31086 THAT WAS PLACED FELL INTO STRUCTURE.PLACED NEW TAG 30032, ALSO REPORTS WHEN FEEDER 3B82
IS TAKEN OFF SYSTEM REPAIRS AND PRESSURE TEST WILL BE DONE. UPDATE - 30-SEP-2002 20:00 HRS. DUE TO
PENDING FEEDER OUTAGE : INCIDENT #145316 WILL NOT BE MEETING THE 24 HR. CRITERIA. SPILL WILL BE
RECLASSIFIED AS SPILL DIELECTRIC TRANSFORMER. UPDATE - 30-SEP-2002 20:28 HRS. CIG MR. T.MARCINEK
NOTIFIED OF CHANGE OF STATUES. 1/20/04 Sample results for oil in vault is < 1 ppm PCBs. Transformer
removed and cleanup completed on 7/10/03.
Remarks: ABOVE MATERIAL DISCOVERED AT ABOVE LOCATION IN VAULT. MATERIAL IS ON TOP OF APPROX 75 GALLONS OF WATER. SAMPLE TAKEN AND CLEANUP IS PENDING DE-ENERGIZING OF FEEDER. CON # 145316.

All Materials:
Site ID: 267009
Operable Unit ID: 859432
Operable Unit: 01
Material ID: 517373
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported

VAULT VS2603 (Continued) **S106007972**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

G73 **CON EDISON - VAULT SUBMERSIBLE 2603** **RCRA-LQG** **1024891482**
ENE **2051 BROADWAY** **E MANIFEST** **NYP005115324**
< 1/8 **BROOKLYN, NY 11207**
0.114 mi.
603 ft. **Site 12 of 13 in cluster G**

Relative: **Higher**
Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Vault Submersible 2603
Handler Address:	Broadway
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP005115324
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N

CON EDISON - VAULT SUBMERSIBLE 2603 (Continued) **1024891482**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170723
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20170723
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	212-460-2757
Owner/Operator Telephone Ext:	Not reported

CON EDISON - VAULT SUBMERSIBLE 2603 (Continued) **1024891482**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - VAULT SUBMERSIBLE 2603
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 007170201GBF
Last Updated Date: 20220523
Shipped Date: 20220511
Received Date: 20220512
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYR000114579
Generator Name: Con Edison - Exterior St Storage Yard
Generator Location Street Number: Not reported
Generator Location Street 1: 2051 BROADWAY
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY
Generator Location Zip: 11207
Generator Mail Street Number: Not reported
Generator Mail Street 1: 1500 Rahway Ave
Generator Mail Street 2: Not reported
Generator Mail City: Avenel
Generator Mail Zip: 07001
Generator Mail State: NJ
Generator Contact Company Name: Not reported
Designated Facility EPA ID: NJD991291105
Designated Facility Name: Clean Earth Of North Jersey
Designated Facility Mail Street Number: 105
Designated Facility Mail Street 1: Not reported

CON EDISON - VAULT SUBMERSIBLE 2603 (Continued) **1024891482**

Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	007170201GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste: LEAD	

State Waste:

Manifest Tracking Number:	007170201GBF
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T
State Waste:	Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:

Manifest Tracking Number:	007170201GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007170201GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION

CON EDISON - VAULT SUBMERSIBLE 2603 (Continued) **1024891482**

Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

G74 **CON EDISON** **NY MANIFEST** **S121968411**
ENE **2051 BROADWAY** **N/A**
< 1/8 **BROOKLYN, NY 11207**
0.114 mi.
603 ft. **Site 13 of 13 in cluster G**

Relative:
Higher

Actual:
77 ft.

NY MANIFEST:

EPA ID:	NYP005115324
Country:	USA
Name:	Con Edison
Address:	2051 BROADWAY
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	2051 BROADWAY
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

H75 **CONSOLIDATED BUS** **NY AST** **A100513777**
SSW **10 JUNIUS STREET** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.116 mi.
612 ft. **Site 5 of 6 in cluster H**

Relative:
Lower

Actual:
62 ft.

AST:

Name:	CONSOLIDATED BUS
Address:	10 JUNIUS STREET
City,State,Zip:	BROOKLYN, NY 11212
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-613222
Program Type:	PBS
UTM X:	592593.98057
UTM Y:	4503246.61738
Expiration Date:	01/15/2026
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	616137
Affiliation Type:	Facility Owner
Company Name:	CLARENDON HOLDING CORP.
Contact Type:	FM
Contact Name:	STEPHEN GENOVESE
Address1:	2 JUNIUS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 346-9600
EMail:	SGENOVESE@CBTTRANS.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2021-02-02

Site Id:	616137
Affiliation Type:	Mail Contact
Company Name:	CLARENDON HOLDING CORP.
Contact Type:	FM
Contact Name:	STEPHEN GENOVESE
Address1:	2 JUNIUS STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	(718) 346-9600
EMail:	SGENOVESE@CBTTRANS.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2021-02-02

Site Id:	616137
Affiliation Type:	Facility Operator
Company Name:	CONSOLIDATED BUS
Contact Type:	Not reported
Contact Name:	STEPHEN GENOVESE

CONSOLIDATED BUS (Continued) **A100513777**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2021-02-02

Site Id:	616137
Affiliation Type:	Emergency Contact
Company Name:	CLARENDON HOLDING CORP.
Contact Type:	Not reported
Contact Name:	STEPHEN GENOVESE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 346-9600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2021-02-02

Tank Info:

Tank Number:	001
Tank Id:	289398

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/15/2021
Capacity Gallons:	8000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

CONSOLIDATED BUS (Continued) **A100513777**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

H76 **LINCOLN SERVICE STATION** **EDR Hist Auto** **1020663340**
SW **1727 E NEW YORK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11212**
0.117 mi.
620 ft. **Site 6 of 6 in cluster H**

Relative: EDR Hist Auto
Lower

Actual:
65 ft.

Year:	Name:	Type:
1969	LINCOLN SERVICE STATION	Gasoline Service Stations
1969	LINCOLN SERVICE STATION	Gasoline Service Stations
1970	LINCOLN SERVICE STATION	Gasoline Service Stations
1971	LINCOLN SERVICE STATION	Gasoline Service Stations
1972	LINCOLN SERVICE STATION	Gasoline Service Stations
1973	LINCOLN SERVICE STATION	Gasoline Service Stations
1974	LINCOLN SERVICE STATION	Gasoline Service Stations
1975	LINCOLN SERVICE STATION	Gasoline Service Stations
1983	LINCOLN SERVICE STATION	Gasoline Service Stations
1985	LINCOLN SERVICE STATION	Gasoline Service Stations
1986	LINCOLN SERVICE STATION	Gasoline Service Stations
1987	LINCOLN SERVICE STATION	Gasoline Service Stations
1988	LINCOLN SERVICE STATION	Gasoline Service Stations
1989	LINCOLN SERVICE STATION	Gasoline Service Stations
1990	LINCOLN SERVICE STATION	Gasoline Service Stations
1991	LINCOLN SERVICE STATION	Gasoline Service Stations
1992	LINCOLN SERVICE STATION	Gasoline Service Stations
1993	LINCOLN SERVICE STATION	Gasoline Service Stations
1994	LINCOLN SERVICE STATION	Gasoline Service Stations
1995	LINCOLN SERVICE STATION	Gasoline Service Stations

I77 **2396 ATLANTIC AVENUE** **NY NYC OER** **S129932210**
WSW **2396 ATLANTIC AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.120 mi.
633 ft. **Site 6 of 13 in cluster I**

Relative: NYC OER:
Higher

Actual:
71 ft.

Name:	2396 ATLANTIC AVENUE
Address:	2396 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676037
Longitude:	-73.905494
OER Project Numbers:	22TMP0304K,22EHAN062K
BBL:	3.0143700013014299E+19
OER Program:	E/RD (Review)
Class:	Active (A)
Phase:	Closure
URL:	
Postcode:	11233

2396 ATLANTIC AVENUE (Continued) **S129932210**

Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	Not reported
NTA:	Ocean Hill

J78 **EAST NEW SERVICE CORPORATION** **NY UST** **U000417953**
SSE **36 SNEDIKER AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.126 mi.
663 ft. **Site 1 of 2 in cluster J**

Relative:
Lower

Actual:
59 ft.

UST:

Name:	EAST NEW SERVICE CORPORATION
Address:	36 SNEDIKER AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-344346 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592770.22243
UTM Y:	4503180.66160
Site Type:	Other

Affiliation Records:

Site Id:	16748
Affiliation Type:	Emergency Contact
Company Name:	CLARENDON HOLDING COMPANY
Contact Type:	Not reported
Contact Name:	ANTHONY CURCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 342-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16748
Affiliation Type:	Facility Operator
Company Name:	EAST NEW SERVICE CORPORATION
Contact Type:	Not reported
Contact Name:	ANTHONY CURCIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 342-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Date Last Modified:	2004-03-04

Site Id:	16748
Affiliation Type:	Mail Contact
Company Name:	EAST NEW YORK SERVICE CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5381 KINGS HIGHWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11203
Country Code:	001
Phone:	(718) 629-6900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16748
Affiliation Type:	Facility Owner
Company Name:	CLARENDON HOLDING COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5381 KINGS HIGHWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11203
Country Code:	001
Phone:	(718) 629-6900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	32551
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	11/01/1994
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	32552
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	11/01/1994
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	48528
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	05/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 004
Tank ID: 48529
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 005
Tank ID: 48530
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/01/1997

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 006
Tank ID: 48531
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 05/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 007

EAST NEW SERVICE CORPORATION (Continued) **U000417953**

Tank ID:	48741
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	05/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

J79 **EAST NEW SERVICE CORPORATION** **UST FINDER** **1028569378**
SSE **36 SNEDIKER AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.126 mi.
663 ft. **Site 2 of 2 in cluster J**

Relative: **Lower**

Actual: **59 ft.**

UST FINDER:

Object ID:	295759
Facility ID:	NY16748
Name:	EAST NEW SERVICE CORPORATION
Address:	36 SNEDIKER AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	7
TOS USTs:	0
Population 1500ft:	3695
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported

EAST NEW SERVICE CORPORATION (Continued) **1028569378**

WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.902322
Y Coord:	40.674292
Latitude:	40.674292
Longitude:	-73.902322

UST FINDER:

Object ID:	1208180
Facility ID:	NY16748
Tank ID:	NY17853
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1208181
Facility ID:	NY16748
Tank ID:	NY17854
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1208182
Facility ID:	NY16748
Tank ID:	NY18793
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1208183
Facility ID:	NY16748
Tank ID:	NY18942
Tank Status:	Closed
Installation Date:	1994/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1208184
Facility ID:	NY16748
Tank ID:	NY19866
Tank Status:	Closed
Installation Date:	1994/11/01 15:59:59+00

EAST NEW SERVICE CORPORATION (Continued) **1028569378**

Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1208185
Facility ID:	NY16748
Tank ID:	NY21585
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1208186
Facility ID:	NY16748
Tank ID:	NY21586
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

80
ESE
1/8-1/4
0.128 mi.
675 ft.

H E L P BROOKLYN HOUSING NEW YORK
HINSDALE ST & SNEDIKER AVE
BROOKLYN, NY 11207

RCRA NonGen / NLR **1000457372** **NYD986925220**

Relative:
Lower

Actual:
62 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	H E L P Brooklyn Housing New York
Handler Address:	Hinsdale St & Snediker Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYD986925220
Contact Name:	Not reported
Contact Address:	OLD POST RD
Contact City,State,Zip:	EDISON, NY 08817
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	OLD POST RD
Mailing City,State,Zip:	EDISON, NY 08817
Owner Name: Andrew Cuomo	
Owner Type:	Private

H E L P BROOKLYN HOUSING NEW YORK (Continued) **1000457372**

Operator Name:	Andrew Cuomo
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ANDREW CUOMO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

H E L P BROOKLYN HOUSING NEW YORK (Continued) **1000457372**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ANDREW CUOMO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANDREW CUOMO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: H E L P BROOKLYN HOUSING NEW YORK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: H E L P BROOKLYN HOUSING NEW YORK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101

H E L P BROOKLYN HOUSING NEW YORK (Continued) **1000457372**

Handler Name: H E L P BROOKLYN HOUSING NEW YORK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901002
Handler Name: H E L P BROOKLYN HOUSING NEW YORK
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K81 **CON EDISON** **E MANIFEST** **1031624784**
NW **2360 FULTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.131 mi.
692 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
82 ft.

E MANIFEST:
Manifest Tracking Number: 016952546FLE
Last Updated Date: 20220216
Shipped Date: 20220202
Received Date: 20220204
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYR000114579
Generator Name: Con Edison
Generator Location Street Number: Not reported
Generator Location Street 1: 2360 FULTON ST
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY

CON EDISON (Continued) **1031624784**

Generator Location Zip: 11233
Generator Mail Street Number: Not reported
Generator Mail Street 1: 116 Skyline Drive
Generator Mail Street 2: Not reported
Generator Mail City: South Plainfield
Generator Mail Zip: 07080
Generator Mail State: NJ
Generator Contact Company Name: Not reported
Designated Facility EPA ID: NJD991291105
Designated Facility Name: Clean Earth Of North Jersey
Designated Facility Mail Street Number: 105
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: JACOBUS AVE
Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 016952546FLE
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 016952546FLE
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 016952546FLE
Transporter Line Number: 1
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services Inc

Waste Line:
Manifest Tracking Number: 016952546FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Rq, Na3082, Hazardous Waste, Liquid N.O.S., (Lead) 9, Pg Iii (D008)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT

CON EDISON (Continued) **1031624784**

Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.5
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.5
Waste Quantity, in Kilograms:	453.515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	453.515
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

I82 **INSTITUTE FOR COMMUNITY LIVING, INC.** **UST FINDER** **1028572638**
WSW **2384 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.136 mi.
719 ft. **Site 7 of 13 in cluster I**

Relative: **Higher**

Actual: **71 ft.**

UST FINDER:

Object ID:	295807
Facility ID:	NY24013
Name:	INSTITUTE FOR COMMUNITY LIVING, INC.
Address:	2384 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	7020
Private Wells 1500ft:	9
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)

INSTITUTE FOR COMMUNITY LIVING, INC. (Continued) **1028572638**

Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.906032
Y Coord:	40.675503
Latitude:	40.675503
Longitude:	-73.906032

UST FINDER:

Object ID:	1221430
Facility ID:	NY24013
Tank ID:	NY29628
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1080
Substances:	Not reported
Tank Wall Type:	Not reported

I83 **ACT TEAMS** **E MANIFEST** **1031530623**
WSW **2384 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.136 mi.
719 ft. **Site 8 of 13 in cluster I**

Relative:
Higher

Actual:
71 ft.

E MANIFEST:

Manifest Tracking Number:	200922639CLE
Last Updated Date:	20241017
Shipped Date:	20240905
Received Date:	20241014
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Act Teams
Generator Location Street Number:	Not reported
Generator Location Street 1:	2384 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2384 ATLANTIC AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys (Pa) Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 SANDSTONE DRIVE
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA

ACT TEAMS (Continued) **1031530623**

Designated Facility Location Street Number: Not reported
Designated Facility Location Street 1: 2869 SANDSTONE DRIVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: HATFIELD
Designated Facility Location Zip: 19440
Designated Facility Location State: PA
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 200922639CLE
Transporter Line Number: 1
Transporter EPA ID: PAD982661381
Transporter Name: Republic Env Sys (Trans Group), Llc

Waste Line:
Manifest Tracking Number: 200922639CLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3248
U.S. DOT Description: Un3248, Waste Medicine, Liquid, Flammable, Toxic, N.O.S. (Alcohol, Phenol), 3 (6.1), Pg-Ii,Rq(D009 = 1 Lb)
Non-Hazardous Waste Description: Not reported
Number of Containers: 4
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 56
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.028
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.028
Waste Quantity, in Kilograms: 25.39684
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 25.39684
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

I84 **INSTITUTE FOR COMMUNITY LIVING, INC.** **NY UST** **U002170635**
WSW **2384 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.136 mi.
719 ft. **Site 9 of 13 in cluster I**

Relative:
Higher

Actual:
71 ft.

UST:

Name:	INSTITUTE FOR COMMUNITY LIVING, INC.
Address:	2384 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-602054 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592465.98200
UTM Y:	4503355.46602
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	24013
Affiliation Type:	Facility Owner
Company Name:	EASTERN INDUSTRIAL DEVELOPMENT CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	655 PELHAM PARKWAY NORTH
Address2:	Not reported
City:	BRONX
State:	NY
Zip Code:	10467
Country Code:	001
Phone:	(718) 654-5959
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-22

Site Id:	24013
Affiliation Type:	Mail Contact
Company Name:	INSTITUTE FOR COMMUNITY LIVING, INC.
Contact Type:	Not reported
Contact Name:	PAT VALERIO
Address1:	40 RECTOR STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10006
Country Code:	001
Phone:	(212) 385-3030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-22

Site Id:	24013
Affiliation Type:	Facility Operator
Company Name:	INSTITUTE FOR COMMUNITY LIVING, INC.
Contact Type:	Not reported
Contact Name:	CHRISTOPHER HEIGHTER
Address1:	Not reported

INSTITUTE FOR COMMUNITY LIVING, INC. (Continued) **U002170635**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 219-8991
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-22

Site Id:	24013
Affiliation Type:	Emergency Contact
Company Name:	EASTERN INDUSTRIAL DEVELOPMENT CORPORATION
Contact Type:	Not reported
Contact Name:	CHRISTOPHER HEIGHTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 219-8991
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-22

Tank Info:

Tank Number:	001
Tank ID:	48948
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	10/19/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	03/22/2001
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
I05 - Overfill - Vent Whistle

INSTITUTE FOR COMMUNITY LIVING, INC. (Continued) **U002170635**

A01 - Tank Internal Protection - Epoxy Liner
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)

I85 **INSTITUTE FOR COMMUNITY R** **NY LTANKS** **S101174394**
WSW **2384 ATLANTIC AVE** **NY VCP** **N/A**
1/8-1/4 **BROOKLYN, NY** **NY NYC OER**
0.136 mi.
719 ft. **Site 10 of 13 in cluster I**

Relative: **Higher**
Actual: **71 ft.**

LTANKS:

Name:	INSTITUTE FOR COMMUNITY R
Address:	2384 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0512499 / 2006-10-06
Facility ID:	0512499
Site ID:	358824
Spill Date:	2006-01-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-01-27
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-27
Spill Record Last Update:	2006-10-06
Spiller Name:	BOB TURRENTINE
Spiller Company:	INSTITUTE FOR COMMUNITY R
Spiller Address:	2384 ATLANTIC AVE
Spiller County:	001
Spiller Contact:	BOB TURRENTINE
Spiller Phone:	(212) 385-3030
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	66192
Latitude:	40.6758960
Longitude:	-73.9059670
DEC Memo:	send TTF letter 01/30/06. Feroze . TTF is sent to: Robert Turrentine Institute For Community Living 40 Rector Street New York, NY 10006. 02/22/06. Feroze, I received a letter from above address that they found a leak at dry portion of the tank. They will repair the tank and test it again. 02/28/06 Feroze. I received a letter from Mr.Robert Turrentine that they will repair or replace the tank and pipe systems. DEC will be informed about their work progress.\\ 03/15/06. Spill is transferred from Feroze to Kumer Patel. 05/17/06-Hiralkumar Patel. Spoke to Jim at Protest. they haven't

INSTITUTE FOR COMMUNITY R (Continued) **S101174394**

heard after they submit proposal. Spoke to Pat Valzalerio as Mr. Turrentine is no longer working at management. Pat will call back with more information. 05/18/06-Hiralkumar Patel. Received call from Pat (Ph. 212-385-3030 Ext. 3222, FAX: 212-385-2380). he suggested refurbishing of tank from inside, but landlord is not agree with that. Pat asked to issue a letter requiring such work. Left message for Pat. 05/19/06-Hiralkumar Patel. Received call from Pat. he has an agreement with landlord which covers repair work. and landlord wants this company to do repair, but Pat thinks that this problem can not be solved by repair work as tank needs either to be replaced or refurbished. he gave me owner's information: Scott Milchman (718) 654-5959 Spoke to Mr. Milchman. he doesn't know anything. sent out TTF letter again at following address to owner. Scott Milchman Eastern Industrial Development Corp. 655 Pelham Parkway North Bronx, NY 10467 Ph. (718) 654-5959 FAX (718) 654-6396 letter faxed to Mr. Milchman and to Pat. 05/24/06-Hiralkumar Patel. REceived message from Scott. left message for Scott. 06/05/06-Hiralkumar Patel. REceived message from Pat. left message for Pat. Received message from Pat. they are planning to remove old tank and to install new tank at same location. left message for Pat. 06/26/06-Hiralkumar Patel. Received call from Mr. Milchman. he has hired Eastmond to remove tank. and after removal Eastmond will take required samples and will send tank closure report. 08/01/06-Hiralkumar Patel. left message for Mr. Milchman. left message for Rene at Eastmond. received call from Mr. Milchman. he asked me to talk to Rene at Eastmond. spoke with Rene. they finished tank removal work last thursday and took endpoint samples. they removed 7-10 yards of contaminated soil. Rene will forward lab results once he gets it. 08/29/06-Hiralkumar Patel. spoke with Isaac at Eastmond. he has everything ready but lab analyticals. once he gets it, he will put together and send final report. 09/25/06-Hiralkumar Patel. spoke with Isaac. he will send final report by end of this week. 10/05/06-Hiralkumar Patel. received closure report from Isaac. they removed tank and removed approx. 10 cubic yard of contaminated soil. excavated area has been backfilled and restored to grade. collected 3 endpoint samples. samples doesn't show any contamination. based on available information, case closed.

Remarks: Not reported

All Materials:

Site ID:	358824
Operable Unit ID:	1116051
Operable Unit:	01
Material ID:	2106175
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	2384 ATLANTIC AVE
Address:	2384 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9402632 / 2003-02-18

INSTITUTE FOR COMMUNITY R (Continued) **S101174394**

Facility ID:	9402632
Site ID:	69637
Spill Date:	1994-05-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1994-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-06-08
Spill Record Last Update:	2003-02-18
Spiller Name:	Not reported
Spiller Company:	APT BLDG - HOWIE
Spiller Address:	2384 ATLANTIC AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	66192
Latitude:	40.6758981
Longitude:	-73.9060490
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKATXX Insufficient Information2/18/2003 - Closed Due To The Nature / Extent Of The Spill Report
Remarks:	PUMPING TANK OUT TODAY. (TANK NOT REGISTERED)

All TTF:

Facility ID:	9402632
Spill Number:	9402632
Spill Tank Test:	1542768
Site ID:	69637
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

INSTITUTE FOR COMMUNITY R (Continued) **S101174394**

Site ID:	69637
Operable Unit ID:	999695
Operable Unit:	01
Material ID:	553954
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

VCP NYC:

Project ID:	20TMP1085K,20EHAN224K,21CVCP012K
Name:	2384 ATLANTIC AVENUE
Address:	2384 ATLANTIC AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3014370001
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Closure
Latitude:	40.676059
Longitude:	-73.905866
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3038665
NTA:	Ocean Hill

NYC OER:

Name:	2384 ATLANTIC AVENUE
Address:	2384 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676059
Longitude:	-73.905866
OER Project Numbers:	20TMP1085K,20EHAN224K,21CVCP012K
BBL:	3014370001
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Closure

URL:

Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3038665
NTA:	Ocean Hill

L86 **BROADWAY FILTON** **UST FINDER** **1028586202**
ENE **2090 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.139 mi.
733 ft. **Site 1 of 13 in cluster L**

Relative: **Lower**

Actual: **69 ft.**

UST FINDER:

Object ID:	295871
Facility ID:	NY4228
Name:	BROADWAY FILTON
Address:	2090 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	6
TOS USTs:	0
Population 1500ft:	3084
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.9008699999999
Y Coord:	40.676879
Latitude:	40.676879
Longitude:	-73.90087

UST FINDER:

Object ID:	1269594
Facility ID:	NY4228
Tank ID:	NY3348
Tank Status:	Closed
Installation Date:	1971/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1269595
Facility ID:	NY4228
Tank ID:	NY3347
Tank Status:	Closed
Installation Date:	1971/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

BROADWAY FILTON (Continued) **1028586202**

Object ID:	1269596
Facility ID:	NY4228
Tank ID:	NY3346
Tank Status:	Closed
Installation Date:	1971/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1269597
Facility ID:	NY4228
Tank ID:	NY3345
Tank Status:	Closed
Installation Date:	1971/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1269598
Facility ID:	NY4228
Tank ID:	NY3208
Tank Status:	Closed
Installation Date:	1971/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1269599
Facility ID:	NY4228
Tank ID:	NY3207
Tank Status:	Closed
Installation Date:	1971/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

L87 **BROADWAY FILTON** **NY UST** **U000403356**
ENE **2090 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.139 mi.
733 ft. **Site 2 of 13 in cluster L**

Relative: UST:
Lower

Actual:
69 ft.

Name:	BROADWAY FILTON
Address:	2090 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-146188 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592892.97317
UTM Y:	4503512.65169

BROADWAY FILTON (Continued) **U000403356**

Site Type: Unknown

Affiliation Records:

Site Id: 4228
Affiliation Type: Facility Owner
Company Name: POWER TEST REALTY COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 175 SUNNYSIDE PL
Address2: Not reported
City: PLAINVIEW
State: NY
Zip Code: 11803
Country Code: 001
Phone: (516) 576-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4228
Affiliation Type: Mail Contact
Company Name: POWER TEST REALTY COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 175 SUNNYSIDE PL
Address2: Not reported
City: PLAINVIEW
State: NY
Zip Code: 11803
Country Code: 001
Phone: (516) 576-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4228
Affiliation Type: Facility Operator
Company Name: BROADWAY FILTON
Contact Type: Not reported
Contact Name: BROADWAY FULTON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (718) 342-8780
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-07-21

Site Id: 4228
Affiliation Type: Emergency Contact
Company Name: POWER TEST REALTY COMPANY
Contact Type: Not reported

BROADWAY FILTON (Continued) **U000403356**

Contact Name:	TOM DICKSON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 729-6500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-07-21

Tank Info:

Tank Number:	001
Tank ID:	19133
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1971
Date Tank Closed:	04/20/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	19134
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1971
Date Tank Closed:	04/20/1988
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

BROADWAY FILTON (Continued) **U000403356**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 19135
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1971
Date Tank Closed: 04/20/1988
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 19136
Tank Status: Closed - Removed
Material Name: Closed - Removed

BROADWAY FILTON (Continued) **U000403356**

Capacity Gallons:	550
Install Date:	10/01/1971
Date Tank Closed:	04/20/1988
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number:	005
Tank ID:	19137
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1971
Date Tank Closed:	04/20/1988
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

BROADWAY FILTON (Continued) **U000403356**

Tank Number:	006
Tank ID:	19138
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1971
Date Tank Closed:	04/20/1988
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

L88 **MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK** **RCRA-LQG 1010328805**
East **KENT AVE & S 6TH ST TO 75TH ST** **E MANIFEST NYR000145045**
1/8-1/4 **BROOKLYN, NY 11249** **NJ MANIFEST**
0.146 mi.
771 ft. **Site 3 of 13 in cluster L**

Relative: **Lower**
Actual: **69 ft.**

RCRA Listings:

Date Form Received by Agency:	20250210
Handler Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Handler Address:	Kent Ave & S 6th St To 75th St
Handler City,State,Zip:	BROOKLYN, NY 11249
EPA ID:	NYR000145045
Contact Name:	BRIAN MCLEAN
Contact Address:	BROADWAY 27TH FL 27.64
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-3540
Contact Fax:	646-252-3509
Contact Email:	BRIAN.MCLEAN@MTACD.ORG
Contact Title:	AVP CONSTRUCTION EXECUTIVE
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2024
Accessibility:	Not reported
Active Site Indicator:	Handler Activities

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		BROADWAY 27TH FL 27.64
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	Mta Nyct	
Owner Type:		State
Operator Name:	Mta Nyct	
Operator Type:		State
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20250210
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Biennial: List of Years
Year: 2023

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 5TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 5TH FL 503
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3506
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY D3.123 MAILBOX 321
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	PO
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19330101
Date Ended Current:	20150910
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19330101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY D3.123 MAILBOX 321
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19330101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	PP
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19330101
Date Ended Current:	20150910
Owner/Operator Address:	2 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYCT
Legal Status: State
Date Became Current: 19680301
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYCT
Legal Status: State
Date Became Current: 19680301
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140210
Handler Name: MTA NYCT - JAMAICA LINE BENTS 750 -1007
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20240223
Handler Name: MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD & LOOPS TRACKS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250210
Handler Name: MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD & LOOPS

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

TRACKS

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20070205
Handler Name:	MTA NYCT JAMAICA LN J & Z BENTS 750-1007
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070205
Handler Name:	MTA NYCT JAMAICA LN J & Z BENTS 750-1007
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150910
Handler Name:	MTA NYCT - JAMAICA LINE BENTS 750 -1007
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070206
Handler Name:	MTA NYCT JAMAICA LN J & Z BENTS 750-1007
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160624
Handler Name: MTA NYCT - JAMAICA LINE II - JMZ
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20230427
Handler Name: MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD & LOOPS TRACKS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250117
Handler Name: MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD & LOOPS TRACKS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250204
Handler Name: MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD & LOOPS TRACKS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: Mixed Mode Transit Systems

NAICS Code: 485112
NAICS Description: Commuter Rail Systems

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20150901
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

E MANIFEST:

Manifest Tracking Number:	018569283FLE
Last Updated Date:	20230725
Shipped Date:	20230714
Received Date:	20230714
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018569350FLE
Last Updated Date:	20230825
Shipped Date:	20230816
Received Date:	20230817
Manifest Status:	Signed

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	018569373FLE
Last Updated Date:	20230925
Shipped Date:	20230911
Received Date:	20230912
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018569392FLE
Last Updated Date:	20231004
Shipped Date:	20230922
Received Date:	20230922
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	018569599FLE
Last Updated Date:	20240517
Shipped Date:	20240415
Received Date:	20240415
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Nyct -Office Systems Safety (Mta C&D), Contract C-34921r
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY-ROOM D3,123 (MAILBOX 321)
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	018570125FLE
Last Updated Date:	20231026
Shipped Date:	20231012
Received Date:	20231012
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018570208FLE
Last Updated Date:	20240321
Shipped Date:	20231114
Received Date:	20231114
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY-D3.123 (MAILBOX 321)
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018570287FLE
Last Updated Date:	20240325
Shipped Date:	20231211
Received Date:	20231211
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018570296FLE
Last Updated Date:	20240325
Shipped Date:	20231213
Received Date:	20231213

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) 1010328805

Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	018570359FLE
Last Updated Date:	20240603
Shipped Date:	20240109
Received Date:	20240109
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	018570391FLE
Last Updated Date:	20240129
Shipped Date:	20240118
Received Date:	20240118
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000145045
Generator Name:	Mta Nyct - Jamaica Line Ii Jmz Incl East New York Yard Lead & Loops Tracks
Generator Location Street Number:	Not reported
Generator Location Street 1:	KENT AVE & S 6TH ST TO 75TH ST
Generator Location Street 2:	& JAMAICA AVE
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11249
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 5TH FL 503
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 018570419FLE
Transporter Line Number: 1
Transporter EPA ID: NJR986628162
Transporter Name: Iwt Transport, Inc.

Waste Line:
Manifest Tracking Number: 018570419FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3077
U.S. DOT Description: Rq Na3077, Hazardous Waste, Solid N.O.S.(Contains Lead Compounds), 9, Pg Iii,
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: CM
Container Type Description: Metal boxes, cartons, cases (including roll offs)
Waste Quantity: 23200
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 11.6
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 11.6
Waste Quantity, in Kilograms: 10521.548
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 10521.548
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: Y
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

Click this hyperlink while viewing on your computer to access
41 additional US EManifest: record(s) in the EDR Site Report.

NJ MANIFEST:
EPA ID: NYR000145045
Name: MTA NYCT - JAMAICA LINE II - JMZ
Address: KENT AVE & S 6TH ST TO 75TH ST
City,State,Zip: BROOKLYN, NY 11249

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

County:	Not reported
Mailing Address:	BROADWAY 5TH FL 503
Mailing City,State,Zip:	NEW YORK, NY 10004
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	LUMINITA MARINESCU
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000145045
Manifest Number:	000067829WAS
Date Shipped:	05/04/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/04/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H11
Quantity:	600
Unit:	P

EPA ID:	NYR000145045
Manifest Number:	006736291FLE
Date Shipped:	10/17/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	28,900.00
Unit:	Pounds

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

EPA ID:	NYR000145045
Manifest Number:	006736343FLE
Date Shipped:	10/31/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	22,060.00
Unit:	Pounds

EPA ID:	NYR000145045
Manifest Number:	000517877WAS
Date Shipped:	4/9/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	26,820.00
Unit:	Pounds

EPA ID:	NYR000145045
Manifest Number:	000518069WAS
Date Shipped:	6/24/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	24,080.00
Unit:	Pounds

EPA ID:	NYR000145045
Manifest Number:	006739930FLE
Date Shipped:	12/3/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	200.00
Unit:	Pounds

EPA ID:	NYR000145045
Manifest Number:	000458076WAS
Date Shipped:	12/10/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: Not reported
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported
Quantity: 400.00
Unit: Pounds

EPA ID: NYR000145045
Manifest Number: 000457880WAS
Date Shipped: 11/15/2012
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR986628162
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: Not reported
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Quantity:	29,660.00
Unit:	Pounds
EPA ID:	NYR000145045
Manifest Number:	006739947FLE
Date Shipped:	12/9/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	24,800.00
Unit:	Pounds
EPA ID:	NYR000145045
Manifest Number:	000518059WAS
Date Shipped:	6/19/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	300.00
Unit:	Pounds

EPA ID:	NYR000145045
Manifest Number:	000517908WAS
Date Shipped:	5/3/2013
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR986628162
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

MTA NYCT - JAMAICA LINE II JMZ INCL EAST NEW YORK YARD LEAD (Continued) **1010328805**

Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	31,000.00
Unit:	Pounds

Click this hyperlink while viewing on your computer to access
7 additional NJ MANIFEST: record(s) in the EDR Site Report.

I89
WSW
1/8-1/4
0.147 mi.
775 ft.

CON EDISON
F/O 2395 PACIFIC ST
BROOKLYN, NY 11233

Site 11 of 13 in cluster I

NY MANIFEST **S117313507**
N/A

Relative:
Lower

Actual:
69 ft.

NY MANIFEST:

EPA ID:	NYP004602231
Country:	USA
Name:	Con Edison
Address:	F/O 2395 PACIFIC ST
Address 2:	SB33417
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	F/O 2395 PACIFIC ST
Location Address 2:	SB33417
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported

CON EDISON (Continued) **S117313507**

Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/21/2014
Trans1 Recv Date: 07/21/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/30/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004602231
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012774103JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 100
Units: Gallons (liquids only)
Number of Containers: 1

CON EDISON (Continued) **S117313507**

Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M90 **CON EDISON** **NY MANIFEST** **S118464217**
SE **60 WILLIAMS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.147 mi.
776 ft. **Site 1 of 3 in cluster M**

Relative: **Lower**
Actual: **59 ft.**

NY MANIFEST:

EPA ID:	NYP004868172
Country:	USA
Name:	Con Edison
Address:	60 WILLIAMS AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	60 WILLIAMS AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Dennis Huacon
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/11/2015
Trans1 Recv Date:	11/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004868172
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	015319425JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S118464217**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	4000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M91 **CON EDISON - SERVICE BOX 53136** **RCRA-LQG** **1019325884**
SE **60 WILLIAMS AVE** **NYP004868172**
1/8-1/4 **BROOKLYN, NY 11207**
0.147 mi.
776 ft. **Site 2 of 3 in cluster M**

Relative: **Lower**

Actual: **59 ft.**

RCRA Listings:

Date Form Received by Agency:	20160205
Handler Name:	Con Edison - Service Box 53136
Handler Address:	Williams Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004868172
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	HUACOND@CONED.COM
Contact Title:	SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON - SERVICE BOX 53136 (Continued) **1019325884**

Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator

CON EDISON - SERVICE BOX 53136 (Continued) **1019325884**

Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151111
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL 15TH FL NE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151111
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL 15TH FL NE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - SERVICE BOX 53136
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

M92 **CON EDISON - SERVICE BOX 53136** **NJ MANIFEST** **S120677848**
SE **60 WILLIAMS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.147 mi.
776 ft. **Site 3 of 3 in cluster M**

Relative:
Lower

Actual:
59 ft.

NJ MANIFEST:

EPA ID:	NYP004868172
Name:	CON EDISON - SERVICE BOX 53136
Address:	60 WILLIAMS AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	DENNIS HUACON
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004868172
Manifest Number:	015319425JJK
Date Shipped:	11/11/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON - SERVICE BOX 53136 (Continued) **S120677848**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

L93 **CON EDISON** **NJ MANIFEST** **S120675486**
East **BROADWAY & JAMAICA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11238**
0.147 mi.
776 ft. **Site 4 of 13 in cluster L**

Relative: **Lower**
Actual: **68 ft.**

NJ MANIFEST:

EPA ID:	NYP004825200
Name:	CON EDISON
Address:	BROADWAY & JAMAICA AVE
City,State,Zip:	BROOKLYN, NY 11238
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004825200
Manifest Number:	002624825GBF
Date Shipped:	8/17/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON (Continued) **S120675486**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

L94 **NYCTA-CPM ENVIRO ENGINEERING** **NJ MANIFEST** **S111074862**
East **BROADWAY & JAMAICA** **N/A**
1/8-1/4 **BROOKLYN, NY 10004**
0.147 mi.
776 ft. **Site 5 of 13 in cluster L**

Relative: **Lower**
Actual: **68 ft.**

NJ MANIFEST:

EPA ID:	NYR000072777
Name:	NYCTA-CPM ENVIRO ENGINEERING
Address:	BROADWAY & JAMAICA
City,State,Zip:	BROOKLYN, NY 10004
County:	Not reported
Mailing Address:	2 BROADWAY, 3RD FLOOR
Mailing City,State,Zip:	NEW YORK 10004
Telephone:	6462523500
Emergency Telephone:	Not reported
Contact:	FINTAN FRAYNOR
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000072777
Manifest Number:	000199616WAS
Date Shipped:	03/31/2010
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574

NYCTA-CPM ENVIRO ENGINEERING (Continued) **S111074862**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/31/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/31/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200
Unit:	P

L95 **NYCTA - BROADWAY ENY STATION A & C LINE** **RCRA-VSQG** **1001489220**
East **BROADWAY & JAMAICA AVE** **NY MANIFEST** **NYR000072777**
1/8-1/4 **BROOKLYN, NY 11201**
0.147 mi.
776 ft. **Site 6 of 13 in cluster L**

Relative: **Lower**

Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nycta - Broadway Eny Station A & C Line
Handler Address:	Broadway & Jamaica Ave
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYR000072777
Contact Name:	JOSEPHINE F BROWN

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Contact Address:		JAY ST RM 819
Contact City,State,Zip:		BROOKLYN, NY 11201
Contact Telephone:		718-243-4581
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		JAY ST RM 819
Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:	Mta New York City Transit	
Owner Type:		Municipal
Operator Name:	Mta New York City Transit	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20220111
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MTA NEW YORK CITY TRANSIT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10 COLUMBUS CIRCLE 25TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 212-307-6010
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10 COLUMBUS CIR 25TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 212-307-6010
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10 COLUMBUS CIRCLE 25TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10019
Owner/Operator Telephone: 212-307-6010
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Receive Date: 20060101
Handler Name: NYCTA-BROADWAY/ENY STATION (A/C LINE)
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA - BROADWAY ENY STATION A & C LINE
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990617
Handler Name: MTA NYCT BROADWAY & EAST NEW YORK STA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020220
Handler Name: NYCTA-BROADWAY/ENY STATION (A/C LINE)
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: Mixed Mode Transit Systems

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Has the Facility Received Notices of Violations:
- Found Violation: No
- Agency Which Determined Violation: Not reported
- Violation Short Description: Not reported
- Date Violation was Determined: Not reported
- Actual Return to Compliance Date: Not reported
- Return to Compliance Qualifier: Not reported
- Violation Responsible Agency: Not reported
- Scheduled Compliance Date: Not reported
- Enforcement Identifier: Not reported
- Date of Enforcement Action: Not reported
- Enforcement Responsible Agency: Not reported
- Enforcement Docket Number: Not reported
- Enforcement Attorney: Not reported
- Corrective Action Component: Not reported
- Appeal Initiated Date: Not reported
- Appeal Resolution Date: Not reported
- Disposition Status Date: Not reported
- Disposition Status: Not reported
- Disposition Status Description: Not reported
- Consent/Final Order Sequence Number: Not reported
- Consent/Final Order Respondent Name: Not reported
- Consent/Final Order Lead Agency: Not reported
- Enforcement Type: Not reported
- Enforcement Responsible Person: Not reported
- Enforcement Responsible Sub-Organization: Not reported
- SEP Sequence Number: Not reported
- SEP Expenditure Amount: Not reported
- SEP Scheduled Completion Date: Not reported
- SEP Actual Date: Not reported
- SEP Defaulted Date: Not reported
- SEP Type: Not reported
- SEP Type Description: Not reported
- Proposed Amount: Not reported
- Final Monetary Amount: Not reported
- Paid Amount: Not reported
- Final Count: Not reported
- Final Amount: Not reported

Evaluation Action Summary:
- Evaluation Date: 20080219
- Evaluation Responsible Agency: State
- Found Violation: No
- Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
- Evaluation Responsible Person Identifier: NYFBR
- Evaluation Responsible Sub-Organization: R2
- Actual Return to Compliance Date: Not reported
- Scheduled Compliance Date: Not reported
- Date of Request: Not reported
- Date Response Received: Not reported
- Request Agency: Not reported
- Former Citation: Not reported

NY MANIFEST:
- EPA ID: NYR000072777

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Country:	USA
Name:	Nycta Bway East Ny Station A/C Line
Address:	BROADWAY AND JAMAICA AVENUE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	BROADAY AND JAMAICA AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta Bway East Ny Station A/C Line
Mailing Contact:	Norman Oppenheimer
Mailing Address 1:	2 BROADWAY 4TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523500

Manifest Data:

Document ID:	MIA9093202
Manifest Status:	Not reported
Trans1 State ID:	0440464ME
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2003
Trans1 Recv Date:	12/23/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00650
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	MIA9026368
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2003
Trans1 Recv Date:	05/29/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/11/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00800
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	MIA7096731
Manifest Status:	Not reported
Trans1 State ID:	0440465MF
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	09/25/2003
Trans1 Recv Date:	09/25/2003

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/09/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01200
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	MIA8630417
Manifest Status:	Not reported
Trans1 State ID:	0440465ME
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	09/12/2003
Trans1 Recv Date:	09/12/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/18/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00600
Units: Pounds
Number of Containers: 003
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYG2455002
Manifest Status: Not reported
Trans1 State ID: 0440464ME
Year: 2000
Trans2 State ID: Not reported
Generator Ship Date: 10/19/2000
Trans1 Recv Date: 10/19/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/21/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000072777
Trans1 EPA ID: NJD054126164
Trans2 EPA ID: Not reported
TSDF ID 1: OHD055522429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 02100
Units: Pounds
Number of Containers: 007
Container Type: Metal drums, barrels, kegs
Handling Method: Treat

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Specific Gravity:	01.00
Document ID:	MIA7018234
Manifest Status:	Not reported
Trans1 State ID:	0440375ME
Year:	1999
Trans2 State ID:	Not reported
Generator Ship Date:	07/15/1999
Trans1 Recv Date:	07/15/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/30/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	MIA9658622
Manifest Status:	Not reported
Trans1 State ID:	1638070ME
Year:	2005
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2005
Trans1 Recv Date:	04/28/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	MIA9658653
Manifest Status:	Not reported
Trans1 State ID:	1637983ME
Year:	2005
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2005
Trans1 Recv Date:	07/20/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/01/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00100
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	NJA2926971
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	02/02/2000
Trans1 Recv Date:	02/02/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01500
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	MIA9109775
Manifest Status:	Not reported
Trans1 State ID:	1637905ME
Year:	2004
Trans2 State ID:	Not reported

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Generator Ship Date:	11/23/2004
Trans1 Recv Date:	11/23/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/09/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02800
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	MIA9093246
Manifest Status:	Not reported
Trans1 State ID:	1637905ME
Year:	2004
Trans2 State ID:	Not reported
Generator Ship Date:	03/18/2004
Trans1 Recv Date:	03/18/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000072777
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

NYCTA - BROADWAY ENY STATION A & C LINE (Continued) **1001489220**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
5 additional NY MANIFEST: record(s) in the EDR Site Report.

L96 **CON ED** **NY MANIFEST** **S118259040**
East **BROADWAY & JAMAICA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11238**
0.147 mi.
776 ft. **Site 7 of 13 in cluster L**

Relative:
Lower

Actual:
68 ft.

NY MANIFEST:

EPA ID:	NYP004825200
Country:	USA
Name:	Con Ed
Address:	BROADWAY & JAMAICA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11238
Zip 4:	Not reported
Location Address 1:	BROADWAY & JAMAICA AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11238
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Ed
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported

CON ED (Continued) **S118259040**

Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	NJD003812047
Generator Ship Date:	08/17/2015
Trans1 Recv Date:	08/17/2015
Trans2 Recv Date:	08/20/2015
TSD Site Recv Date:	08/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004825200
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624825GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	300
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

L97 **CON EDISON** **RCRA NonGen / NLR** **1019325412**
East **BROADWAY & JAMAICA AVE** **NYP004825200**
1/8-1/4 **BROOKLYN, NY 11238**
0.147 mi.
776 ft. **Site 8 of 13 in cluster L**

Relative: **Lower**
Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20150817
Handler Name:	Con Edison
Handler Address:	Broadway & Jamaica Ave
Handler City,State,Zip:	BROOKLYN, NY 11238

CON EDISON (Continued) **1019325412**

EPA ID:		NYP004825200
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909
Recognized Trader-Importer:		No

CON EDISON (Continued) **1019325412**

Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150817
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150817
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - VAULT SUBMERSIBLE 1357
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON (Continued) **1019325412**

Receive Date:	20150817
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150817
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	Electric Power Distribution

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

L98 **CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS** **RCRA NonGen / NLR** **1010325857**
East **JAMAICA AVE & BROADWAY** **E MANIFEST** **NYP004134607**
1/8-1/4 **BROOKLYN, NY 11207** **NY MANIFEST**
0.147 mi.
776 ft. **Site 9 of 13 in cluster L**

Relative: **Lower**

Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20060223
Handler Name:	Con Edison - Vault 1291
Handler Address:	Jamaica Ave & Broadway
Handler City,State,Zip:	BROOKLYN, NY 11208
EPA ID:	NYP004134607
Contact Name:	FRANKLIN MURRAY
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1010325857**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PLACE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.	
Owner Type:		Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1010325857**

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050817
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050817
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050817
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20050817
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060222

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1010325857**

Handler Name: CON EDISON - VAULT 1291
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060223
Handler Name: CON EDISON - VAULT 1291
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - VAULT 1291
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 006869981GBF
Last Updated Date: 20220117
Shipped Date: 20211220
Received Date: 20211221
Manifest Status: Signed

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1010325857**

Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Queens Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	JAMAICA AVE & BROADWAY
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	006869981GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste: LEAD	

State Waste:

Manifest Tracking Number:	006869981GBF
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T
State Waste:	Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:

Manifest Tracking Number:	006869981GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1010325857**

Waste Line:

Manifest Tracking Number:	006869981GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.5
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.5
Waste Quantity, in Kilograms:	453.515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	453.515
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	Y
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

NY MANIFEST:

EPA ID:	NYP004134607
Country:	USA
Name:	Consolidated Edison
Address:	JAMAICA AVE & BROADWAY
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11208
Zip 4:	Not reported
Location Address 1:	JAMACIA AVE & BROADWAY V1357
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported

CON EDISON/ ATTN: QUEENS ENVIRONMENTAL OPS (Continued) **1010325857**

Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYE0624402
Manifest Status: Not reported
Trans1 State ID: 46235JM
Year: 2005
Trans2 State ID: Not reported
Generator Ship Date: 08/17/2005
Trans1 Recv Date: 08/17/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/17/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004134607
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 04445
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

L99 **CON EDISON - MANHOLE 15869** **RCRA-LQG** **1014397516**
East **BROADWAY AND JAMAICA AVE** **NY MANIFEST** **NYP004198453**
1/8-1/4 **BROOKLYN, NY 11211**
0.147 mi.
776 ft. **Site 10 of 13 in cluster L**

Relative: **Lower**
Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20100416
Handler Name:	Con Edison - Manhole 15869
Handler Address:	Broadway And Jamaica Ave
Handler City,State,Zip:	BROOKLYN, NY 11211
EPA ID:	NYP004198453
Contact Name:	THOMAS P TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	TEELINGT@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Co. Of Ny Inc
Owner Type:	Private
Operator Name:	Consolidated Edison Co. Of Ny Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - MANHOLE 15869 (Continued) **1014397516**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON CO. OF NY INC.
Legal Status:	Private
Date Became Current:	20091022
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NYC, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO. OF NY INC
Legal Status:	Private
Date Became Current:	20091022
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NYC, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100416
Handler Name:	CON EDISON - MANHOLE 15869
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported

CON EDISON - MANHOLE 15869 (Continued) **1014397516**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	Electric Power Distribution

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004198453
Country:	USA
Name:	Consolidated Edison
Address:	BROADWAY AND JAMAICA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11211
Zip 4:	Not reported
Location Address 1:	BROADWAY AND JAMAICA AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11211
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklyn Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2009
Trans1 Recv Date:	10/22/2009
Trans2 Recv Date:	Not reported

CON EDISON - MANHOLE 15869 (Continued) **1014397516**

TSD Site Recv Date:	10/23/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004198453
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000893943GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3660
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/2009
Trans1 Recv Date:	10/22/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004198453
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000893944GBF
Import Indicator:	N

CON EDISON - MANHOLE 15869 (Continued) **1014397516**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

I100 **CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031619690**
SW **2408 PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.148 mi.
781 ft. **Site 12 of 13 in cluster I**

Relative: **Lower**
Actual: **67 ft.**

E MANIFEST:

Manifest Tracking Number:	007359940GBF
Last Updated Date:	20230515
Shipped Date:	20230428
Received Date:	20230502
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2408 PACIFIC ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619690**

Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	007359940GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007359940GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S. (Lead), 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	200
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.1
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.1
Waste Quantity, in Kilograms:	90.703
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	90.703
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619690**

Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

N101 **CON EDISON - MANHOLE 15861** **RCRA NonGen / NLR** **1014396288**
North **BROADWAY & VAN SINDEREN AV** **NJ MANIFEST** **NYP004185344**
1/8-1/4 **BROOKLYN, NY 11207** **NY MANIFEST**
0.149 mi.
786 ft. **Site 1 of 8 in cluster N**

Relative: **Higher**
Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:	20250115
Handler Name:	Con Edison - Manhole 15861
Handler Address:	Broadway & Van Sinderen Av
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004185344
Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

CON EDISON - MANHOLE 15861 (Continued) **1014396288**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250115
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090723
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090723
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CON EDISON - MANHOLE 15861 (Continued) **1014396288**

Historic Generators:

Receive Date:	20100323
Handler Name:	CON EDISON - MANHOLE 15861
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20090723
Handler Name:	CON EDISON
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20250115
Handler Name:	CON EDISON - MANHOLE 15861
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	Electric Power Distribution

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA ID:	NYP004185344
Name:	CON EDISON - MANHOLE 15861

CON EDISON - MANHOLE 15861 (Continued) **1014396288**

Address:	BROADWAY & VAN SINDEREN AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004185344
Manifest Number:	000894657GBF
Date Shipped:	08/13/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/13/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/13/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

CON EDISON - MANHOLE 15861 (Continued) **1014396288**

Was Load Rejected: N
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 900
Unit: G

NY MANIFEST:
EPA ID: NYP004185344
Country: USA
Name: Consolidated Edison Mh15861
Address: BROADWAY & VAN SINDEREN AV
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: BROADWAY & VAN SINDEREN AV
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison Mh15861
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/13/2009
Trans1 Recv Date: 08/13/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004185344
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000894657GBF
Import Indicator: N

CON EDISON - MANHOLE 15861 (Continued) **1014396288**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	900
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

N102 **CON EDISON** **E MANIFEST** **1031628159**
North **BROADWAY & TRUXTON STR** **N/A**
1/8-1/4 **BROOKLYN, NY 11245**
0.149 mi.
786 ft. **Site 2 of 8 in cluster N**

Relative: **Higher**
Actual: **86 ft.**

E MANIFEST:

Manifest Tracking Number:	023096273JJK
Last Updated Date:	20211220
Shipped Date:	20211206
Received Date:	20211206
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	BROADWAY & TRUXTON STR
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11245
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NY

CON EDISON (Continued) **1031628159**

Generator Contact Company Name: Not reported
Designated Facility EPA ID: NJD991291105
Designated Facility Name: Clean Earth Of North Jersey
Designated Facility Mail Street Number: 105
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: JACOBUS AVE
Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 023096273JJK
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 023096273JJK
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 023096273JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 023096273JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5

CON EDISON (Continued) **1031628159**

Waste Quantity, in Kilograms:	453.515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	453.515
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

N103 **MTA NYCT - BROADWAY JUNCTION A C J Z L LINES** **RCRA-SQG 1024892047**
North **BROADWAY & VAN SINDEREN AVE** **E MANIFEST NYR000236273**
1/8-1/4 **BROOKLYN, NY 11207**
0.149 mi.
786 ft. **Site 3 of 8 in cluster N**

Relative: RCRA Listings:
Higher

Actual: Date Form Received by Agency: 20180524
86 ft. Handler Name: Mta Nyct - Broadway Junction A C J Z L Lines
Handler Address: Broadway & Van Sinderen Ave
Handler City,State,Zip: BROOKLYN, NY 11207
EPA ID: NYR000236273
Contact Name: LUMINITA MARINESCU
Contact Address: BROADWAY 5TH FLOOR 503
Contact City,State,Zip: NEW YORK, NY 10004
Contact Telephone: 646-252-3506
Contact Fax: 646-252-3509
Contact Email: LUMINITA.MARINESCU@NYCT.COM
Contact Title: ADMIN STAFF ANALYST
EPA Region: 02
Land Type: State
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: BROADWAY 5TH FLOOR 503
Mailing City,State,Zip: NEW YORK, NY 10004
Owner Name: Mta Nyct
Owner Type: Private
Operator Name: Mta Nyct
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES (Continued) **1024892047**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180524
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	Private
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 5TH FLOOR 503
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3506
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES (Continued) **1024892047**

Owner/Operator Name: MTA NYCT

Legal Status:	Private
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 5TH FLOOR 503
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3506
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180524
Handler Name:	MTA NYCT - BROADWAY JUNCTION A C J Z L LINES
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	Mixed Mode Transit Systems

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	012779440FLE
Last Updated Date:	20191227
Shipped Date:	20190531
Received Date:	20190531
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000236273
Generator Name:	Mta Nyct - Broadway Junction A C J Z L Lines
Generator Location Street Number:	Not reported
Generator Location Street 1:	BROADWAY & VAN SINDEREN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY 5TH FLOOR 503
Generator Mail Street 2:	Not reported

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES (Continued) **1024892047**

Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	105 JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	105 JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	023096272JJK
Last Updated Date:	20211220
Shipped Date:	20211205
Received Date:	20211206
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Consolidated Edison Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	BROADWAY & VAN SINDEREN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER ST
Generator Mail Street 2:	Not reported
Generator Mail City:	ELIZABETH
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES (Continued) **1024892047**

Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 023096272JJK
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 023096272JJK
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 023096272JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 023096272JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES (Continued) **1024892047**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

N104 **MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H** **RCRA-LQG 1014917908**
North **BROADWAY & VAN SINDEREN AVE** **NY MANIFEST NYP000967760**
1/8-1/4 **BROOKLYN, NY 11223** **NJ MANIFEST**
0.149 mi.
786 ft. **Site 4 of 8 in cluster N**

Relative: **Higher**
Actual: **86 ft.**

RCRA Listings:

Date Form Received by Agency:		20120302
Handler Name:		Mta Nyct - Manhole A - Adjacent To Col Jb763h
Handler Address:		Broadway & Van Sinderen Ave
Handler City,State,Zip:		BROOKLYN, NY 11223
EPA ID:		NYP000967760
Contact Name:		CLARE SAMMON
Contact Address:		BROADWAY
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-5777
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		ACTING MANGER
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2011
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		BROADWAY 27TH FL
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	Mta- Nyc Transit	
Owner Type:		State
Operator Name:	Mta- Nyc Transit	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline

MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H (Continued) **1014917908**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2011

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA- NYC TRANSIT	
Legal Status:	State
Date Became Current:	19530101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA- NYC TRANSIT	
Legal Status:	State
Date Became Current:	19530101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27 TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-5777
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H (Continued) **1014917908**

Historic Generators:

Receive Date:	20120302
Handler Name:	MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110923
Handler Name:	MTA NYCT MANHOLE A
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110930
Handler Name:	MTA NYCT MANHOLE A
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485119
NAICS Description:	Other Urban Transit Systems

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP000967760
Country:	USA

MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H (Continued) **1014917908**

Name:	Mta Nyct Manhole A
Address:	BROADWAY & VAN SINDERAN AVE
Address 2:	MANHOLE A ADJ TO COL JB763H
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	BROADWAY & VAN SINDEREN AVE.
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11223
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Mta Nyct Manhole A
Mailing Contact:	S Bulkley
Mailing Address 1:	2 BROADWAY
Mailing Address 2:	ROOM: A27.72
Mailing City,State,Zip:	NEW YORK, NY 10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462625774

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	09/24/2011
Trans1 Recv Date:	09/24/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/26/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000967760
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003634466JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported

MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H (Continued) **1014917908**

Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1500
Units:	Kilograms
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

NJ MANIFEST:

EPA ID:	NYP000967760
Name:	MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H
Address:	BROADWAY & VAN SINDEREN AVE
City,State,Zip:	BROOKLYN, NY 11223
County:	Not reported
Mailing Address:	BROADWAY 27TH FL
Mailing City,State,Zip:	NEW YORK, NY 10004
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	CLARE SAMMON
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP000967760
Manifest Number:	003634466JJK
Date Shipped:	9/24/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

MTA NYCT - MANHOLE A - ADJACENT TO COL JB763H (Continued) **1014917908**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	1,500.00
Unit:	Pounds

N105
North
1/8-1/4
0.149 mi.
786 ft.

Relative:
Higher

Actual:
86 ft.

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES **NY MANIFEST** **S130582205**
BROADWAY & VAN SINDEREN AVE **N/A**
BROOKLYN, NY 11207

Site 5 of 8 in cluster N

NY MANIFEST:

EPA ID:	NYR000236273
Country:	USA
Name:	Mta Nyct - Broadway Junction A C J Z L Lines
Address:	BROADWAY & VAN SINDEREN AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	BROADWAY & VAN SINDEREN AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Mta Nyct - Broadway Junction A C J Z L Lines
Mailing Contact:	Mta Nyct - Broadway Junction A C J Z L Lines
Mailing Address 1:	2 BROADWAY 5TH FLOOR 503
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10004

MTA NYCT - BROADWAY JUNCTION A C J Z L LINES (Continued) **S130582205**

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 6462523506

106
NNW
1/8-1/4
0.155 mi.
821 ft.

CON EDISON
1 CONWAY ST
BROOKLYN, NY 11233

E MANIFEST **1031622720**
N/A

Relative:
Higher

Actual:
86 ft.

E MANIFEST:

Manifest Tracking Number:	007157900GBF
Last Updated Date:	20220512
Shipped Date:	20220502
Received Date:	20220502
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	1 CONWAY ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	007157900GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

CON EDISON (Continued) **1031622720**

State Waste:
- Manifest Tracking Number: 007157900GBF
- Waste Line Number: 1
- State Waste Code Owner: NY
- State Waste Code: T
- State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 007157900GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 007157900GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 4000
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 2
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 2
- Waste Quantity, in Kilograms: 1814.06
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 1814.06
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

O107 **MAGNOLIA HOUSE** **NY AST** **A100295023**
WNW **1430 HERKIMER STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.158 mi.
832 ft. **Site 1 of 2 in cluster O**

Relative:
Higher

Actual:
79 ft.

AST:

Name:	MAGNOLIA HOUSE
Address:	1430 HERKIMER STREET
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608733
Program Type:	PBS
UTM X:	592437.28808
UTM Y:	4503501.77735
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30585
Affiliation Type:	Mail Contact
Company Name:	CAMBA - MAGNOLIA HOUSE
Contact Type:	Not reported
Contact Name:	TOM DAMBAKLY
Address1:	1430 HERKIMER STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 278-2600
EMail:	TOMD@CAMBA.ORG
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-07

Site Id:	30585
Affiliation Type:	Facility Operator
Company Name:	MAGNOLIA HOUSE
Contact Type:	Not reported
Contact Name:	TOM DAMBAKLY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 278-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-07

Site Id:	30585
Affiliation Type:	Emergency Contact
Company Name:	1424 HERKIMER DEVELOPMENT LLC
Contact Type:	Not reported
Contact Name:	TOM DAMBAKLY

MAGNOLIA HOUSE (Continued) **A100295023**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 278-2600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-07

Site Id:	30585
Affiliation Type:	Facility Owner
Company Name:	1424 HERKIMER DEVELOPMENT LLC
Contact Type:	PROJECT MANAGER
Contact Name:	LISA K COSTA
Address1:	49 W 44TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10036
Country Code:	001
Phone:	(212) 453-4274
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-07

Tank Info:

Tank Number:	001
Tank Id:	65579
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	J02 - Dispenser - Suction Dispenser
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	I05 - Overfill - Vent Whistle
	C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2003
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported

MAGNOLIA HOUSE (Continued) **A100295023**

Next Test Date:	Not reported
Date Tank Closed:	03/08/2016
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

P108 **CON EDISON SERVICE BOX: 55797** **RCRA NonGen / NLR** **1016972788**
West **102 SACKMAN ST** **NY MANIFEST** **NYP004465704**
1/8-1/4 **BROOKLYN, NY 11233**
0.160 mi.
843 ft. **Site 1 of 6 in cluster P**

Relative: **Higher**

Actual: **75 ft.**

RCRA Listings:

Date Form Received by Agency:		20140413
Handler Name:		Con Edison Service Box: 55797
Handler Address:		Sackman St
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004465704
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

CON EDISON SERVICE BOX: 55797 (Continued) **1016972788**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140313
Handler Name: CON EDISON SERVICE BOX:	55797
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140413
Handler Name: CON EDISON SERVICE BOX:	55797
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON SERVICE BOX: 55797 (Continued) **1016972788**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004465704
Country:	USA
Name:	Con Edison
Address:	102 SACKMAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	102 SACKMAN ST
Location Address 2:	SB55797
Location City,State,Zip:	BROOKLYN, NY 11212
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING ST
Mailing Address 2:	SB55797
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/13/2014
Trans1 Recv Date:	03/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/17/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004465704
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002405709GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON SERVICE BOX: 55797 (Continued) **1016972788**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	60
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

I109 **PACIFIC STREET IRA** **E MANIFEST** **1031542716**
SW **2402A PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.161 mi.
852 ft. **Site 13 of 13 in cluster I**

Relative: **Lower**
Actual: **67 ft.**

E MANIFEST:

Manifest Tracking Number:	200491671CLE
Last Updated Date:	20230714
Shipped Date:	20230616
Received Date:	20230710
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Pacific Street Ira
Generator Location Street Number:	Not reported
Generator Location Street 1:	2402A PACIFIC ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2402A Pacific St
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported

PACIFIC STREET IRA (Continued) **1031542716**

Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	200491671CLE
Transporter Line Number:	1
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Environmental Systems

Waste Line:

Manifest Tracking Number:	200491671CLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3248
U.S. DOT Description:	Un3248, Waste Medicine, Liquid, Flammable, Toxic, N.O.S. (Alcohol, Phenol), 3 (6.1), Pg Ii, (Ltd Qty), Erg#131
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	5
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0025
Waste Quantity, in Kilograms:	2.267575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2.267575
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported

PACIFIC STREET IRA (Continued) **1031542716**

EPA Waste Indicator: Y

L110 **CON EDISON** **NY MANIFEST** **S118256852**
East **2572 FULTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.165 mi.
869 ft. **Site 11 of 13 in cluster L**

Relative: **Lower**

Actual: **65 ft.**

NY MANIFEST:

EPA ID:	NYP004793527
Country:	USA
Name:	Con Edison
Address:	2572 FULTON ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	2572 FULTON ST
Location Address 2:	MH 21029
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Dennis Huacon
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/11/2015
Trans1 Recv Date:	06/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004793527
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619992GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

CON EDISON (Continued) **S118256852**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

L111 **CON EDISON** **NJ MANIFEST** **S120672725**
East **2572 FULTON ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.165 mi.
869 ft. **Site 12 of 13 in cluster L**

Relative: **Lower**
Actual: **65 ft.**

NJ MANIFEST:

EPA ID:	NYP004793527
Name:	CON EDISON
Address:	2572 FULTON ST
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004793527
Manifest Number:	002619992GBF
Date Shipped:	6/11/2015
TSDF EPA ID:	NJD991291105

CON EDISON (Continued) **S120672725**

Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

L112 **CON EDISON** **RCRA NonGen / NLR** **1019904083**
East **2572 FULTON ST** **NYP004793527**
1/8-1/4 **BROOKLYN, NY 11207**
0.165 mi.
869 ft. **Site 13 of 13 in cluster L**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency:	20150612
65 ft. Handler Name:	Con Edison
Handler Address:	Fulton St
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004793527
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02

CON EDISON (Continued) **1019904083**

Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160909
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

CON EDISON (Continued) **1019904083**

Historic Generators:
Receive Date: 20150612
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150612
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

P113 **CON EDISON - MANHOLE 5076** **RCRA NonGen / NLR** **1014397429**
West **2371 ATLANTIC AVE AND SACKMAN** **NJ MANIFEST** **NYP004197497**
1/8-1/4 **BROOKLYN, NY 11233** **NY MANIFEST**
0.169 mi.
891 ft. **Site 2 of 6 in cluster P**

Relative: **Higher**
Actual: **76 ft.**

RCRA Listings:
Date Form Received by Agency: 20250115
Handler Name: Con Edison - Manhole 5076
Handler Address: 2371 Atlantic Ave And Sackman
Handler City,State,Zip: BROOKLYN, NY 11233
EPA ID: NYP004197497
Contact Name: FRANKLYN MURRAY
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-2808
Contact Fax: Not reported
Contact Email: MURRAYFR@CONED.COM
Contact Title: Not reported

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		Not reported
Mailing City,State,Zip:		Not reported
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20250115
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20091002
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20091002
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100323
Handler Name: CON EDISON - MANHOLE 5076
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091002
Handler Name: CON EDISON
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20250115
Handler Name:	CON EDISON - MANHOLE 5076
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	Electric Power Distribution

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA ID:	NYP004197497
Name:	CON EDISON - MANHOLE 5076
Address:	2371 ATLANTIC AVE AND SACKMAN
City,State,Zip:	BROOKLYN, NY 11233
County:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	FRANKLYN MURRAY
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004197497
Manifest Number:	000893809GBF

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

Date Shipped:	10/02/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/02/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/07/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	300
Unit:	G

NY MANIFEST:

EPA ID:	NYP004197497
Country:	USA
Name:	Consolidated Edison
Address:	2371 ATLANTIC AVE & SACKMAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	2371 ATLANTIC AVE AND SACKMAN

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

Location Address 2: ST
Location City,State,Zip: BROOKLYN, NY 11233
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/02/2009
Trans1 Recv Date: 10/02/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/07/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004197497
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000893809GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported

CON EDISON - MANHOLE 5076 (Continued) **1014397429**

Waste Code 6:	Not reported
Quantity:	300
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

K114 **2246 FULTON STREET** **NY UST** **U004457386**
WNW **50 SACKMAN STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.170 mi.
899 ft. **Site 2 of 2 in cluster K**

Relative:
Higher

Actual:
85 ft.

UST:

Name:	2246 FULTON STREET
Address:	50 SACKMAN STREET
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-613582 / Unregistered
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592450.81652
UTM Y:	4503559.76231
Site Type:	Other

Affiliation Records:

Site Id:	673869
Affiliation Type:	Emergency Contact
Company Name:	50 SACKMAN LLC
Contact Type:	Not reported
Contact Name:	PETER ABOWITZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 807-7937
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2024-11-20

Site Id:	673869
Affiliation Type:	Facility Operator
Company Name:	2246 FULTON STREET
Contact Type:	Not reported
Contact Name:	50 SACKMAN LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported

2246 FULTON STREET (Continued) **U004457386**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2024-11-20

Site Id:	673869
Affiliation Type:	Mail Contact
Company Name:	50 SACKMAN LLC
Contact Type:	MEMBER
Contact Name:	PETER ABOWITZ
Address1:	5604 14 AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(917) 807-7937
EMail:	PETER.ABOWITZ@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2024-11-20

Site Id:	673869
Affiliation Type:	Facility Owner
Company Name:	50 SACKMAN LLC
Contact Type:	MEMBER
Contact Name:	PETER ABOWITZ
Address1:	5604 14 AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(917) 807-7937
EMail:	PETER.ABOWITZ@GMAIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2024-11-20

Tank Info:

Tank Number:	001
Tank ID:	303643
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	1000
Install Date:	01/01/1932
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	11/20/2024

2246 FULTON STREET (Continued) **U004457386**

Equipment Records:

J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	303644
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	01/01/1932
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	ACDANIEL
Last Modified:	11/20/2024

Equipment Records:

J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	003
Tank ID:	303645
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	01/01/1932
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

2246 FULTON STREET (Continued) **U004457386**

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: ACDANIEL
Last Modified: 11/20/2024

Equipment Records:

J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 303646
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: 01/01/1932
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: ACDANIEL
Last Modified: 11/20/2024

Equipment Records:

J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Q115 **OUR LADY OF LORETO CHURCH** **NY UST** **U000402330**
WSW **124 SACKMAN ST** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11233** **NY MANIFEST**
0.171 mi.
901 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
70 ft.

UST:

Name:	OUR LADY OF LORETO CHURCH
Address:	124 SACKMAN ST
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-237973 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592442.38818
UTM Y:	4503262.69945
Site Type:	Religious Building (Church, Synagogue, Mosque, Temple, etc.)

Affiliation Records:

Site Id:	8893
Affiliation Type:	Facility Owner
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	MGR
Contact Name:	WILLIAM BURKE
Address1:	124 SACKMAN ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 385-3740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-07-18

Site Id:	8893
Affiliation Type:	Mail Contact
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	124 SACKMAN STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 385-3740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-01-06

Site Id:	8893
Affiliation Type:	Facility Operator
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	OUR LADY OF LORETO CHURCH
Address1:	Not reported

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 385-3740
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8893
Affiliation Type:	Emergency Contact
Company Name:	OUR LADY OF LORETO CHURCH
Contact Type:	Not reported
Contact Name:	DIOCESE OF BROOKLYN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 628-5500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	17345
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4800
Install Date:	Not reported
Date Tank Closed:	07/11/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

SPILLS:

Name:	OUR LADY OF LORETO CHURCH
Address:	124 SACKMAN ST
City,State,Zip:	BROOKLYN, NY 11233
Spill Number/Closed Date:	1010406 / 2011-09-14
Facility ID:	1010406
Facility Type:	ER
DER Facility ID:	8881
Site ID:	444009
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2011-01-05
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2011-01-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-01-05
Spill Record Last Update:	2011-11-07
Spiller Name:	MOHAMMED AHMED
Spiller Company:	OUR LADY OF LORETO CHURCH
Spiller Address:	124 SACKMAN ST
Spiller Company:	999
Contact Name:	MOHAMMED AHMED
Latitude:	40.6754150
Longitude:	-73.9062800
DEC Memo:	1/6/11-Vought-Primary off hours responder. Vought called FLS (Mohammed Ahmed 212-675-3225) and left message to return call to DEC Vought. As per PBS #2-237973 tank has 5000-gallon #2 fuel oil UST and site is owned by: Our Lady Of Loreto Church 124 Sackman Street Brooklyn, NY 11233 Ph: (718)387-3740 Vought spoke to RSE and spill assigned to DEC Ahmed as secondary off-hours responder. Vought to send out CSL with possible additional requirements upon callback from FLS Ahmed. Vought received callback from and spoke to FLS Ahmed who noted that he was hired by property developer (Reese & Sons) and that the property was to be developed for affordable housing units. They were onsite to remove an abandoned 4,800-gallon fuel oil UST (See PBS #2-237973) and noted contaminated soil

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

around and below the tank. Vought noted that DEC Ahmed was the project manager and that CSL would
be drafted by Vought and signed by Ahmed. Vought drafted CSL with one month due date and the
following requirements: 1)delineation of soil and groundwater (if applicable) contamination
2)collection of endpoint samples 3)strong recommendation for installation of SSDS and VB 4)Updating
PBS Registration 2-237973 to reflect current closed status of UST (as per DEC Falvey this was
required, PBS registration also expired as of 7/20/92). 5)cc to FLS Ahmed 6)advisement that site
should not be developed until RAP approved by DEC. Vought sent letter with above requirements to
address provided by FLS Ahmed: Our Lady of Loreto Catholic Church c/o Progress of Peoples
Development Corporation 191 Joralemon Street Brooklyn, NY 11201
Attention: Claire Hilger
11/7/11-Fu-Intern Fu completed summary of reports: SUMMARY UST CLOSURE REPORT & REMEDIAL ACTION
PLAN (Fleming Lee Shue)- 08/17/11. On Jan 05 2011, at request of L Riso & Sons, Fleming-Lee Shue
performed an UST field investigation in order to remove the tank but end in finding approximately
30 by 30 feet in size and extending approximately 16-37 feet below grade petroleum-impacted area.
Then a spill was reported. Between June and July 2011, the UST removal activities was observed,
including the removal of the decommissioning material, consisting of cement slurry, and the removal
of the tank and associated piping. A 3 section was required to remain in the excavation due to
structural and shoring concerns. Excavation and removal of 1249 tons of petroleum-impacted soil (to
depth approximately 32ft-bgs) were conducted. On July 8 2011, 8 soil samples were collected per
NYSDEC s request. 3 VOCs, Ethylbenzene, Xylene, and Isopropylbenzene, were detected above standard
at EP-BE; Ethylbenzene was detected above SCO at EP-BW. One MW will be installed at the site. After
installation, the MW will be sampled. If the gw is not found to be contaminated, Closure Report
will be submitted; if the gw is contaminated, two additional MWs will be installed downgradient.
SUMMARY SPILL CLOSURE REPORT (Tenen Environmental)-Sept 2011. Based on the removal of all
structurally-accessible soil, documentation that gw has not been impacted, the incorporation of
vapor barrier and SSDS and composite cover system over the area of UST, Tenen requests that this
spill be closed. The subsurface investigation dated January 2011 consisted of: 1)Excavation of the
soil in the area of the UST, visual and olfactory observations, and PID measurements of organic
vapors; and 2) Installation of five (5) soil borings adjacent to the UST and sampling and analysis
of soil. The results of the investigation, which are detailed in FLS

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

letter dated January 20, 2011,
identify a petroleum-impacted area approximately 30 by 30 feet in size and extending to
approximately 16 to 37 feet bgs. Based on the results of the January 2011 subsurface investigation,
FLS prepared a January 21, 2011 Remedial Action Work Plan (RAWP). The RAWP described the following
remedial actions: installation of sheeting and shoring, excavation of non-impacted soil, tank
removal, excavation and disposal of petroleum-impacted soil, post excavation soil sampling,
installation of a vapor barrier and SSDS, and preparation of a closure report. June-July 2011 Tank
Closure / Interim Remedial Measures On August 17, 2011, FLS submitted an Underground Storage Tank
Closure and Remedial Action Report. July-August 2011 Supplemental Remedial Investigation: MW-1, in
the center of the excavation was installed on July 29, 2011. The soil boring was advanced using a
Sonic drill rig with continuous samples collected starting at a depth of 30 feet bgs and continuing
to the groundwater table. 9 samples were collected and analyzed. The analytical results indicate
the presence of several petroleum-related VOCs in seven (7) of the nine (9) soil samples collected.
All detected VOCs were below the Part 375 Unrestricted Use and Protection of Groundwater SCOs and
CP-51 Fuel Oil SCLs except ethylbenzene, isopropylbenzene and xylenes in samples collected from
43-45 and 48-50 feet bgs. The analytical results detected several SVOCs in eight (8) of the nine
(9) soil samples collected. SVOCs detected in the soil samples primarily included polycyclic
aromatic hydrocarbons (PAHs). All VOCs in MW-1 were detected at concentrations below the Class GA
Standards except chloroform, which was detected at 21.9 parts per billion (ppb), above the Class GA
Standard of 7 ppb. No SVOCs were detected above the NYSDEC Class GA Standards except phenol. The
proposed redevelopment of site includes construction of 4 buildings of 8 dwellings each for a total
of 32 dwelling units, designed as the Pacific St Cluster. The area directly above the impacted soil
will be redeveloped as a paved parking area. The following potential exposure routes have been
indentified: direct contact & inhalation of VOCs from soil and inhalation of VOC from soil vapor. A
vapor barrier and SSDS (73 wide *52 deep) will be incorporated into the two buildings closest to
the church. The principal components of the SSDS are a layer of gravel beneath the basement slab, a
suction pit within the gravel layer, solid-construction piping from the suction pit to an exterior
suction fan on the roof and monitoring points through the basement slab. The system has been
designed in general accordance with NYSDOH s Guidance for Evaluating Soil Vapor Intrusion in the

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

State of New York, October 2006 (NYSDOH Soil Vapor Guidance), including Section 4.2.2,
System-specific recommendations. Several types of composite cover systems will be employed to
prevent direct contact with and mitigate inhalation of residual petroleum constituents.

Remarks: Contaminated soil found at construction site. Cleanup pending assessment and pre-plan.

All Materials:

Site ID:	444009
Operable Unit ID:	1194454
Operable Unit:	01
Material ID:	2190280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYP004631859
Country:	USA
Name:	Con Edison
Address:	124 SACKMAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	124 SACKMAN ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported

OUR LADY OF LORETO CHURCH (Continued) **U000402330**

Generator Ship Date:	08/19/2014
Trans1 Recv Date:	08/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004631859
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012775244JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	300
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Q116 **OUR LADY OF LORETO CHURCH** **UST FINDER** **1028600407**
WSW **124 SACKMAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.171 mi.
901 ft. **Site 2 of 4 in cluster Q**

Relative: UST FINDER:
Higher

Object ID:	295789
Facility ID:	NY8893
Name:	OUR LADY OF LORETO CHURCH
Address:	124 SACKMAN ST
City,State,Zip:	BROOKLYN, NY 11233
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1

Actual:
70 ft.

OUR LADY OF LORETO CHURCH (Continued) **1028600407**

TOS USTs:	0
Population 1500ft:	7367
Private Wells 1500ft:	8
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.906188
Y Coord:	40.6750680000001
Latitude:	40.675068
Longitude:	-73.906188

UST FINDER:

Object ID:	1320798
Facility ID:	NY8893
Tank ID:	NY11625
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	4800
Substances:	Not reported
Tank Wall Type:	Not reported

R117 **CON EDISON** **NY MANIFEST** **S118256854**
East **21 ALABAMA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.172 mi.
907 ft. **Site 1 of 18 in cluster R**

Relative: **Lower**
Actual: **63 ft.**

NY MANIFEST:

EPA ID:	NYP004793543
Country:	USA
Name:	Con Edison
Address:	21 ALABAMA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	21 ALABAMA AVE
Location Address 2:	SB 18409
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

CON EDISON (Continued) **S118256854**

Mailing:
- Mailing Name: Con Edison
- Mailing Contact: Dennis Huacon
- Mailing Address 1: 4 IRVING PL 15TH FL
- Mailing Address 2: Not reported
- Mailing City,State,Zip: NEW YORK, NY 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 2124603770

Manifest Data:
- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: NJD003812047
- Year: 2018
- Trans2 State ID: Not reported
- Generator Ship Date: 06/12/2015
- Trans1 Recv Date: 06/12/2015
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 06/15/2015
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004793543
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID 1: NJD991291105
- TSDF ID 2: Not reported
- Manifest Tracking Number: 002619993GBF
- Import Indicator: N
- Export Indicator: N
- Discr Quantity Indicator: N
- Discr Type Indicator: N
- Discr Residue Indicator: N
- Discr Partial Reject Indicator: N
- Discr Full Reject Indicator: N
- Manifest Ref Number: Not reported
- Alt Facility RCRA ID: Not reported
- Alt Facility Sign Date: Not reported
- MGMT Method Type Code: H110
- Waste Code a: Lead
- Waste Code b: Not reported
- Waste Code c: Not reported
- Waste Code e: Not reported
- Waste Code f: Not reported
- Waste Code g: Not reported
- Waste Code 1: Not reported
- Waste Code 2: Not reported
- Waste Code 3: Not reported
- Waste Code 4: Not reported
- Waste Code 5: Not reported
- Waste Code 6: Not reported
- Quantity: 200
- Units: Pounds
- Number of Containers: 1
- Container Type: Cargo tanks (tank trucks)
- Handling Method: Treat

CON EDISON (Continued) **S118256854**

Specific Gravity: 1

R118
East
1/8-1/4
0.172 mi.
907 ft.

CON EDISON **NJ MANIFEST** **S120672727**
21 ALABAMA AVE **N/A**
BROOKLYN, NY 11207

Site 2 of 18 in cluster R

Relative:
Lower

Actual:
63 ft.

NJ MANIFEST:

EPA ID:	NYP004793543
Name:	CON EDISON
Address:	21 ALABAMA AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004793543
Manifest Number:	002619993GBF
Date Shipped:	6/12/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120672727**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

R119 **CON EDISON** **RCRA NonGen / NLR** **1019904085**
East **21 ALABAMA AVE** **NYP004793543**
1/8-1/4 **BROOKLYN, NY 11207**
0.172 mi.
907 ft. **Site 3 of 18 in cluster R**

Relative: **Lower**
Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:	20150612
Handler Name:	Con Edison
Handler Address:	Alabama Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004793543
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON (Continued) **1019904085**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150612
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150612
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON (Continued) **1019904085**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R120 **KANES INDUSTRIES** **RCRA NonGen / NLR** **1000693992**
East **23 ALABAMA AVE** **NYD987001641**
1/8-1/4 **BROOKLYN, NY 11207**
0.173 mi.
913 ft. **Site 4 of 18 in cluster R**

Relative: **Lower**
Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Kanes Industries
Handler Address:		Alabama Ave
Handler City,State,Zip:		BROOKLYN, NY 11207-2303
EPA ID:		NYD987001641
Contact Name:		Not reported
Contact Address:		ALABAMA AVE
Contact City,State,Zip:		BROOKLYN, NY 11207
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		ALABAMA AVE
Mailing City,State,Zip:		BROOKLYN, NY 11207
Owner Name:	William G Kanes	
Owner Type:		Private
Operator Name:	William G Kanes	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

KANES INDUSTRIES (Continued) **1000693992**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: WILLIAM G KANES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	330 E 38TH ST APT 54P
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	212-557-4419
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: WILLIAM G KANES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

KANES INDUSTRIES (Continued) **1000693992**

Owner/Operator Address: 330 E 38TH ST APT 54P
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-557-4419
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WILLIAM G KANES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 330 E 38TH ST APT 54P
Owner/Operator City,State,Zip: NEW YORK, NY 10016
Owner/Operator Telephone: 212-557-4419
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: KANES INDUSTRIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: KANES INDUSTRIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: KANES INDUSTRIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported

KANES INDUSTRIES (Continued) **1000693992**

Electronic Manifest Broker: Not reported

Receive Date: 19920514
Handler Name: KANES INDUSTRIES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R121 **CON EDISON** **NJ MANIFEST** **S120666843**
East **23 ALABAMA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.173 mi.
913 ft. **Site 5 of 18 in cluster R**

Relative: **Lower**
Actual: **63 ft.**

NJ MANIFEST:
EPA ID: NYP004726790
Name: CON EDISON
Address: 23 ALABAMA AVE
City,State,Zip: BROOKLYN, NY 11207
County: Not reported
Mailing Address: IRVING PL, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Telephone: Not reported
Emergency Telephone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY047
Municipal: Not reported
Previous EPAID: Not reported
Generator Flag: Not reported
Transporter Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest Data:
EPA ID: NYP004726790
Manifest Number: 002610399GBF
Date Shipped: 2/5/2015

CON EDISON (Continued) **S120666843**

TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

R122 **CON EDISON** **RCRA NonGen / NLR** **1018277932**
East **23 ALABAMA AVE** **FINDS** **NYP004726790**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.173 mi.
913 ft. **Site 6 of 18 in cluster R**

Relative: **Lower**
Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:	20150206
Handler Name:	Con Edison
Handler Address:	Alabama Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004726790
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

CON EDISON (Continued) **1018277932**

EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160502
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

CON EDISON (Continued) **1018277932**

Historic Generators:
Receive Date: 20150206
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150206
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067696372

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277932
Registry ID: 110067696372

CON EDISON (Continued) **1018277932**

DFR URL:
Name: CON EDISON
Address: 23 ALABAMA AVE
City,State,Zip: BROOKLYN, NY 11207

R123 **CON EDISON** **NY MANIFEST** **S117739554**
East **23 ALABAMA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.173 mi.
913 ft. **Site 7 of 18 in cluster R**

Relative:
Lower

Actual:
63 ft.

NY MANIFEST:
EPA ID: NYP004726790
Country: USA
Name: Con Edison
Address: 23 ALABAMA AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: F/O 23 ALABAMA AV
Location Address 2: SB18408
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 02/05/2015
Trans1 Recv Date: 02/05/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/11/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004726790
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002610399GBF
Import Indicator: N
Export Indicator: N

CON EDISON (Continued) **S117739554**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

S124 **MTA NYCT - SUBWAY ELECTRONICS MAINT DIV** **RCRA-SQG** **1001818274**
NNE **2020 BROADWAY** **FINDS** **NYR000078071**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.175 mi.
923 ft. **Site 1 of 11 in cluster S**

Relative:
Higher

Actual:
92 ft.

Client Plot

RCRA Listings:

Date Form Received by Agency:	20070731
Handler Name:	Mta Nyct - Subway Electronics Maint Div
Handler Address:	Broadway
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYR000078071
Contact Name:	SHERRY L BULKLEY
Contact Address:	BROADWAY 27TH FLOOR A27.63
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	642-252-5774
Contact Fax:	Not reported
Contact Email:	SHERRYBULKLEY@NYCT.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 27TH FLOOR A27.63

MTA NYCT - SUBWAY ELECTRONICS MAINT DIV (Continued) **1001818274**

Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	New York City Transit	
Owner Type:		State
Operator Name:	Sherry Bulkley	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D006
Waste Description:	Cadmium

MTA NYCT - SUBWAY ELECTRONICS MAINT DIV (Continued) **1001818274**

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: SHERRY BULKLEY
Legal Status: State
Date Became Current: 19540701
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MAT NEW YORK CITY TRANSIT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST ROOM 819
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-243-4501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT
Legal Status: State
Date Became Current: 19631201
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: MTA NYCT - ENY ELECTRONIC SHOP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070730
Handler Name: MTA NYCT - SUBWAY ELECTRONICS MAINT DIV

MTA NYCT - SUBWAY ELECTRONICS MAINT DIV (Continued) **1001818274**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19991101
Handler Name:	MTA NYCT - ENY ELECTRONIC SHOP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070731
Handler Name:	MTA NYCT - SUBWAY ELECTRONICS MAINT DIV
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	42111
NAICS Description:	Automobile And Other Motor Vehicle Wholesalers

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported

MTA NYCT - SUBWAY ELECTRONICS MAINT DIV (Continued) **1001818274**

Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20120828
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004557275

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001818274

MTA NYCT - SUBWAY ELECTRONICS MAINT DIV (Continued) **1001818274**

Registry ID: 110004557275

DER URL:
Name: MTA NYCT - SUBWAY ELECTRONICS MAINT DIV
Address: 2020 BROADWAY
City,State,Zip: BROOKLYN, NY 11207

S125 **NYCTA** **NY LTANKS** **U003080332**
NNE **25 JAMAICA AVENUE** **NY CBS** **N/A**
1/8-1/4 **BROOKLYN, NY 11201** **NY CBS AST**
0.175 mi. **NY Spills**
923 ft. **Site 2 of 11 in cluster S** **NY MANIFEST**

Relative:
Higher

Actual:
92 ft.

Client Plot

LTANKS:

Name:	EAST NEW YORK BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0608907 / 2006-11-06
Facility ID:	0608907
Site ID:	372980
Spill Date:	2006-11-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-11-02
CID:	406
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-02
Spill Record Last Update:	2006-11-06
Spiller Name:	TAYLOR (LINE SUPER)
Spiller Company:	EAST NEW YORK BUS DEPOT
Spiller Address:	25 JAMAICA AVE.
Spiller County:	001
Spiller Contact:	TAYLOR (LINE SUPER)
Spiller Phone:	(718) 927-8282
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	137218
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	11/06/06-Hiralkumar Patel. left message at system safety (646-252-5763). received call from Ms. Clare. she will call back with updates. received message from Clare. spill was contained and cleaned up. no soil/drain/sewer affected.
Remarks:	Spill took place in the truck shop at the depot. Caller said that the tank 'Exploded'. Material was spilled onto the conrete and is contained there. NYC Transit personnel is doing clean up. NYC Transit will be investigating this further.

NYCTA (Continued) **U003080332**

All Materials:

Site ID:	372980
Operable Unit ID:	1130709
Operable Unit:	01
Material ID:	2120382
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Resource Affected:	Soil
Oxygenate:	Not reported

CBS:

Name:	EAST NEW YORK BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
CBS Number:	2-000284
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	592990.74775
UTMY:	4503579.01980

CBS AST:

CBS Number:	2-000284
ICS Number:	Not reported
PBS Number:	2-190292
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	F
Telephone:	(718) 690-9602
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	08/11/2003
Total Capacity of All Active Tanks(gal):	1000
Operator:	NEW YORK CITY TRANSIT
Emergency Contact:	HOWARD MATZA
Emergency Phone:	(718) 243-4581
Owner Name:	NEW YORK CITY TRANSIT
Owner Address:	370 JAY STREET ROOM 819
Owner City,St,Zip:	BROOKLYN, NY 11203
Owner Telephone:	(718) 243-4581
Owner Type:	State Government
Owner Sub Type:	None
Mail Name:	NEW YORK CITY TRANSIT
Mail Contact Addr:	370 JAY STREET
Mail Contact Addr2:	ROOM 819
Mail Contact Contact:	JOSEPHINE BROWN
Mail Contact City,St,Zip:	BROOKLYN, NY 11203
Mail Phone:	(718) 243-4581

NYCTA (Continued) **U003080332**

Tank Id:	CBS-ENY-1
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	09/95
Tank Closed:	03/01
Capacity (Gal):	1000
Chemical:	Ethylene glycol
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Cut-off Walls
Tank Error Status:	No Missing Data
Date Entered:	03/05/1996
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Galvanized Steel
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	Other
Overfill Protection:	Product Level Gauge
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/30/2001

Tank Id:	CBS-ENY-2
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	03/01
Tank Closed:	Not reported
Capacity (Gal):	1000
Chemical:	Ethylene glycol
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Cut-off Walls
Tank Error Status:	No Missing Data

NYCTA (Continued) **U003080332**

Date Entered:	02/12/2001
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Galvanized Steel
Pipe Internal:	None
Pipe External:	Other
Pipe Flag:	Other
Leak Detection:	64
Overfill Protection:	High Level Alarm
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/30/2001

Tank Id:	1
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	00/80
Tank Closed:	00/95
Capacity (Gal):	1000
Chemical:	Ethylene glycol
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	08/10/1995
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	50
Last Test:	Not reported

NYCTA (Continued) **U003080332**

Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/30/2001

SPILLS:

Name:	EAST NY BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0007658 / 2000-12-28
Facility ID:	0007658
Facility Type:	ER
DER Facility ID:	137218
Site ID:	326107
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-09-29
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2000-09-29
CID:	389
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-09-29
Spill Record Last Update:	2001-04-19
Spiller Name:	PASHKO CAMAJ
Spiller Company:	NYC TRANSIT
Spiller Address:	370 JAY ST
Spiller Company:	001
Contact Name:	CALLER
Latitude:	40.6774454
Longitude:	-73.8991844
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE ABOUT 10 GALLONS SPILLED DURING DELIVERY. NYCT CONTAINED AND CLEANED. see also 00-07655.
Remarks:	caller reporting a spill from a malfunction of a piece of equipment and leaked material. clena up has been preformed and no callbck is necessary

NYCTA (Continued) **U003080332**

All Materials:

Site ID:	326107
Operable Unit ID:	828394
Operable Unit:	01
Material ID:	563276
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EAST NY BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0406828 / 2004-10-20
Facility ID:	0406828
Facility Type:	ER
DER Facility ID:	137218
Site ID:	326108
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	D4
SWIS:	2401
Spill Date:	2004-09-21
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-09-21
CID:	27
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-21
Spill Record Last Update:	2004-10-20
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
Latitude:	40.6775870
Longitude:	-73.8988470
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Testing equipment was discarded in a dumpster and leaked out. Approximately 3 galons leaked into the parking lot with one gallons going into a storm drain. NYCT contained and cleaned all product except what went into the

NYCTA (Continued) **U003080332**

sewer. NYCT attempted to notify DEP but, after being put on hold for several minutes, NYCT
discontinued call.

Remarks: Caller reports someone dumped the oil in their dumpster. It leaked onto pavement and approximately 1 gallon went into the sewer. Cleanup is in progress by NYC transit employees.

All Materials:

Site ID:	326108
Operable Unit ID:	890221
Operable Unit:	01
Material ID:	484588
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	EAST NY DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0511344 / 2006-02-10
Facility ID:	0511344
Facility Type:	ER
DER Facility ID:	137218
Site ID:	357476
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-12-30
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2005-12-30
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-30
Spill Record Last Update:	2006-02-10
Spiller Name:	Not reported
Spiller Company:	TRANSIT
Spiller Address:	2 BROADWAY 27TH FLOOR
Spiller Company:	001
Contact Name:	SHERRY BULKLEY
Latitude:	40.6775870
Longitude:	-73.8988470

NYCTA (Continued) **U003080332**

DEC Memo: 12/30/05-Hiralkumar Patel. I spoke with Sherry Bulkley at NYC Transit. According to her, spill happend from fill line of tank. and all the spilled diesel collected in sump. Tank is out of service now and they have pumped diesel from sump. this sump is not connected to any sewer or drain line. I spoke with Mr. Frank Ocello (917-578-8826) at loction, and he told me that sump is on top of tank. they going to test lines for any leak today (12/30/05) noon. I spoke with Mr. Steve Miller, and he will send me a address for further correspondence regarding case after 2nd Jan. 2006
1/5/06-Hiralkumar Patel. I received an address at 1:00PM and have sent a tank test failure letter.
02/02/06-Hiralkumar Patel. Talked with Jaikisan Achaibar (PH: 646-252-5772, FAX: 646-252-5960) at System Safety department, NYC Transit. As per him, there was a line leakage on top of tank, not the tank. they have repaired it. Jai going to send me their internal report in mail today or tomorrow.
02/10/06-Hiralkumar Patel. Received report from Jay Achaibar at NYC Transit. Abstracts of report: - on 12/30/05, during periodic maintenance inspection, approxi. 5 gal fo diesel was found in the fill sump of tank#8. system shut down. - primary line between the fill port and the tank sump was leading at flex connnectors. no leaks found in secondary line at connectors. - spill contained by secondary line and drained to sump, no soil contamination. - 01/25/06, Franklin company replaced flex connector. - primary system, secondary system and sump test were passed. - 5 gal diesel removed by trained NYCT plant and equipment personnel and disposal as non-hazardous industrial waste. we received NYCT spill incident fact sheet, & line testing results. Case Closed based on the report from NYC transit.

Remarks: IN SUMP, ARRANGING TO HAVE THE PUMP CLEANED, CLEAN UP IS IN PROGRESS.

All Materials:

Site ID:	357476
Operable Unit ID:	1114752
Operable Unit:	01
Material ID:	2104814
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	3.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EAST NY DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY

NYCTA (Continued) **U003080332**

Spill Number/Closed Date:	0510494 / 2005-12-07
Facility ID:	0510494
Facility Type:	ER
DER Facility ID:	137218
Site ID:	356482
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2005-12-07
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2005-12-07
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-07
Spill Record Last Update:	2005-12-07
Spiller Name:	RACHEAL KROWN
Spiller Company:	EAST NY DEPOT
Spiller Address:	25 JAMICA AVE
Spiller Company:	001
Contact Name:	RACHEAL KROWN
Latitude:	40.6775870
Longitude:	-73.8988470
DEC Memo:	12/06/05-Vought-Called Rachel Krone and spill on concrete and cleaned using adsobent material. No sewers or drains affected. Spill closed by Vought.
Remarks:	HOSE FITTING FAILED AND IS ALL CLEANED UP: NO SEWERS OR WATERWAYS EFFECTED

All Materials:

Site ID:	356482
Operable Unit ID:	1113787
Operable Unit:	01
Material ID:	2103845
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	EAST NY DEPOT
Address:	25 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0707060 / 2007-09-26

NYCTA (Continued) **U003080332**

Facility ID:	0707060
Facility Type:	ER
DER Facility ID:	337137
Site ID:	387686
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-09-26
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-09-26
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-26
Spill Record Last Update:	2007-09-26
Spiller Name:	GEORGE CUNNINGHAM
Spiller Company:	EAST NY DEPOT
Spiller Address:	25 JAMICA AVE
Spiller Company:	001
Contact Name:	GEORGE CUNNINGHAM
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	spill has been cleaned by Transit
Remarks:	UNKNOWN WHAT CAUSED LEAK AND STILL INVESTIGAITNG, TANKS ARE LOCKED OUT: AND ALL CLEANED UP

All Materials:

Site ID:	387686
Operable Unit ID:	1144885
Operable Unit:	01
Material ID:	2135198
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	8.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EAST NY DEPOT
Address:	25 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0911748 / 2010-02-05
Facility ID:	0911748
Facility Type:	ER
DER Facility ID:	337137

NYCTA (Continued) **U003080332**

Site ID:	424585
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-02-03
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	2010-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-03
Spill Record Last Update:	2010-02-05
Spiller Name:	JENNIFER WOUTIN
Spiller Company:	EAST NY DEPOT
Spiller Address:	25 JAMAICA AVE
Spiller Company:	999
Contact Name:	JENNIFER WOUTIN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	2/3/2010 - Sangesland spoke to Jennifer Woutin. Bus was up on the lift over a work pit in the depot. Line on the bus broke and spilled into the pit. Pit is fulled contained (no drains). Jennifer said the pit was pumped out and was being cleaned now. Need to follow up tomorrow. 02/04/10 Performed site visit on 02/03/10 evening.Hydraulic oil spilled from hydraulic lift#10.Spill was contained in the rectangular sump at the base of the lift.Oil was recovered.Minor loose oil in the sump.Each lift has a sump at the base and all sumps are connected through pipe.Facility personnel told me the the sump is made of concrete and there is no leak or holes in the pit.Need confirmatory report from NYCT indicating that the oil has not impacted subsurface.(sr) 2/4/10 - Raphael Ketani. I tried to contact Jennifer Woutin of the NYCTA (646) 252-5768, but could only leave a message. The message stated that the DEC needs a short letter report (possibly accompanied by pictures and manifests) indicating that the spill has been cleaned up. I stated that the report must be received. Otherwise, the DEC can’t close the spill case. Ms. Woutin called me back and left a message. She said that the oil was from a broken line on a lift. She said that the great majority of the oil was recovered. Cleanup is proceeding and the DEC will receive a report when everything is finished. 2/5/10 - Raphael Ketani. Haroon Aslam of

NYCTA (Continued) **U003080332**

	the NYC Transit Authority sent me an e-mail containing a report regarding the spill incident. The e-mail stated that the spill was completely cleaned up and that all of the spilled oil was accounted for and recovered. Based upon Ms. Aslam's e-mail, and Mr. Rahman's site inspection on 2/3/10, and on the fact that the oil went directly into a secondary containment structure, I have determined that there is no threat to the public or the environment. Therefore, I am closing the spill case.
Remarks:	LINE BROKE DURING REPAIR; CONTAINED TO INTERIOR.CLEAN UP PENDING

All Materials:

Site ID:	424585
Operable Unit ID:	1180350
Operable Unit:	01
Material ID:	2174234
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	180.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	EAST NY BUS DEPOT
Address:	25 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0911972 / 2010-02-12
Facility ID:	0911972
Facility Type:	ER
DER Facility ID:	337137
Site ID:	424833
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-02-12
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2010-02-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-12
Spill Record Last Update:	2010-02-12
Spiller Name:	Not reported

NYCTA (Continued) **U003080332**

Spiller Company: NYC TRANSIT
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CHRISTINA RYSZEWSKI
Latitude: Not reported
Longitude: Not reported
DEC Memo: minor spill - contained - spill cleaned up.
Remarks: at filling station - cleanup done

All Materials:
Site ID: 424833
Operable Unit ID: 1180577
Operable Unit: 01
Material ID: 2174541
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Name: NYC EAST NY DEPOT
Address: 25 JAMAICA AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1205789 / 2012-09-12
Facility ID: 1205789
Facility Type: ER
DER Facility ID: 337137
Site ID: 468757
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2012-09-11
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2012-09-11
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-09-11
Spill Record Last Update: 2012-09-12
Spiller Name: ROCHELLE KNOWLDEN
Spiller Company: NYC TRANSIT
Spiller Address: 25 JAMAICA AVE
Spiller Company: 999
Contact Name: ROCHELLE KNOWLDEN

NYCTA (Continued) **U003080332**

Latitude:	40.6775860
Longitude:	-73.8988880
DEC Memo:	09/11/12-Hiralkumar Patel. 2:50 PM:- spoke with Rochelle. she mentioned that due to flooding in depot, oily water came to sump. she doesn't know where the oil came from. she asked to contact Josephine Brown at the depot. 2:52 PM:- left message for Ms. Brown. Josephine Brown NYC Transit Ph. (718) 566-3415 (O) (646) 879-8573 (C) 4:26 PM:- received message from Ms. Brown. 09/12/12-Hiralkumar Patel. 11:30 AM:- spoke with Ms. Brown. she mentioned that they have a waste oil UST under the depot floor. over the weekend, due to heavy rain, depot was flooded. during inspection, Ms. Brown found mostly water, with some minor oil, in sump right above the waste oil tank. oil on water could be the residual oil from sump. oily water was contained in the sump and was clened up immediately. no oil found on depot floor. case closed.
Remarks:	into sump, repair and c/u pending

All Materials:

Site ID:	468757
Operable Unit ID:	1218674
Operable Unit:	01
Material ID:	2217079
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	FUEL PUMP ROOM
Address:	25 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1704176 / 2017-07-31
Facility ID:	1704176
Facility Type:	ER
DER Facility ID:	337137
Site ID:	556399
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2017-07-26
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2017-07-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported

NYCTA (Continued) **U003080332**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-07-28
Spill Record Last Update:	2017-07-31
Spiller Name:	Not reported
Spiller Company:	NYCTA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MIKE MANDACK
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	DEC Piper- Small spill to pump room floor. Cleaned. Closed.
Remarks:	spill is contained and cleaned up

All Materials:

Site ID:	556399
Operable Unit ID:	1304437
Operable Unit:	01
Material ID:	2311025
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	COMMERCIAL
Address:	25 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2102025 / 2022-06-09
Facility ID:	2102025
Facility Type:	ER
DER Facility ID:	337137
Site ID:	619758
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2021-06-03
Investigator:	VXBREVDO
Referred To:	Not reported
Reported to Dept:	2021-06-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

NYCTA (Continued) **U003080332**

Remediation Phase:	0
Date Entered In Computer:	2021-06-03
Spill Record Last Update:	2022-06-09
Spiller Name:	DANIEL YU
Spiller Company:	NYC TRANSIT
Spiller Address:	25 JAMAICA AVE
Spiller Company:	999
Contact Name:	DANIEL YU
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	6/8/21-Zhune spoke to Daniel Yu from NYC Transit 646-879-6199. Daniel sent the following email Here are the details that I have so far regarding this spill for your assessment. Product was recently found in a sump associated with the fill lines for diesel tanks 7 and 8 at the depot . The tanks were taken out of service and tightness testing was performed yesterday 6/3. Both the primary and secondary lines fill lines failed, after which the incident was called into the DEC spill hotline. The facility has checked the last three months of reconciliation records and have no noted any issues. The people from the facility cleaned the sump. It was a little amount of diesel fuel. 6/9/21-Zhune-Michael Mandac from NYCT sent the following email NYCT was performing sump testing for the diesel USTs at East New York Bus Depot (25 Jamaica Avenue, Brooklyn, NY 11238). Our contractor overseeing the sump test discovered product in the tank sump for tanks 7 and 8. The remote fill line (from the fill port to the tanks) and secondary piping product line (from the tanks to the pump room) both failed the tightness test. Please note that the primary piping (containing the diesel) passed the tightness test. NYCT has locked out the remote fill port for tanks 7 and 8 (please note that the remote fill services both tanks) and locked out dispensing from the tanks 7 and 8. We are reviewing our options to determine if repairs can be made and how long it will take. 6/2/22 - Kim - Copies of AARCO Environmental Services Corp air tightness test results for tanks 7 and 8 were uploaded to DecDocs. Spill 2102025 reassigned to DEC Brevdo project manager for MTA-NYCT Spill 8807411. June 2, 2022 - Vadim Brevdo - As per discussion and consensus with Eric Kim of Spill Response Section, Spill case 2102025 is reassigned to DER Remediation Section B, Vadim Brevdo to manage, as Vadim Brevdo has been managing entire MTA-NYCT Order on Consent Portfolio, including spill 8807411 at the same site - East New York Bus Depot. One DEC project manager for two spill cases on the same site will make management of the project more effective. VB June 9, 2022 - Vadim Brevdo MTA-NYCT East New York Depot, 25 Jamaica Ave., Brooklyn (Spill Nos. 8807411 and 2102025) This site is an active bus depot and maintenance facility located in a

NYCTA (Continued) **U003080332**

commercial area. In 1991,
the diesel and gasoline USTs failed tightness testing. Site investigations identified petroleum
contamination in the diesel dispenser area but not in the gasoline UST area. Remedial activities in
the diesel dispenser area included the recovery of 124 gallons of free-product and in-situ chemical
oxidation. No free product had been detected since October 2016; however, in January 2021, a sheen
was observed in well W-07R. In May 2021, 0.5 foot of product was detected in well W-07R. An
absorbent sock was installed in the well. On June 3, 2021, free product was detected in the sump of
diesel USTs #7 and #8, which was reported to DEC and spill #2102025 was opened. The tanks primary
fill line and secondary suction lines failed tightness tests. However, review of diesel fuel
inventory records showed no issues. During a site visit on June 11, 2021, no measurable product was
detected in well W-07R or in other wells at the depot. It is unclear if the June 3, 2021 tightness
test failure resulted in a release of product into the environment. On October 5, 2021, MTA-NYCT
and AECOM submitted a Post-Remediation Confirmatory Sampling Work Plan. The plan proposed twelve
soil borings. Seven borings would assess the extent of soil and groundwater contamination remaining
at the site and would be advanced to the water table at 62 feet below grade. The other five borings
would be advanced adjacent to USTs #7 and #8 to determine if there was a release of diesel fuel
into the environment associated with the June 3, 2021 discovery of diesel fuel in the UST sump. Due
to difficult drilling conditions at the site, the borings would be advanced using Sonic drilling.
All soil samples would be inspected for evidence of staining and petroleum odors and screened with
a PID, and samples submitted to a laboratory would be analyzed for VOCs and SVOCs. DEC approved the
Post-Remedial Confirmatory Sampling Work Plan on October 12, 2021. NYCT-AECOM commenced the
fieldwork in November 2021 and completed it in January 2022. On June 1, 2022, NYCT-AECOM submitted
Post-Remediation Confirmatory Sampling Report to DEC which included petition for closure of spills
#8807411 and #2102025. A combined post-remedial confirmatory sampling program for spill #8807411
and an investigation for spill #2102025 were implemented in 2021 and 2022 to evaluate current
subsurface contaminant conditions and to determine if the June 2021 tightness testing failure
resulted in a diesel release into the subsurface. The findings of the investigation show that there
is no free phase petroleum product plume beneath the site. Petroleum impacts in soil, where
detected, were at levels just slightly exceeding 6NYCRR Part 375 Unrestricted Use or NYSDEC s CP-51

NYCTA (Continued) **U003080332**

Soil Cleanup Objectives (SCOs); all detections were below NYCRR Part 375 Commercial Use SCOs. Very low levels of VOCs and SVOCs in the groundwater indicate that the residual petroleum soil impacts are not significantly impacting groundwater at the site and/or off-site. Furthermore, groundwater data confirm that no groundwater impacts are migrating off site. Based on the previous remedial actions and investigations performed at the site, MTA-NYCT and AECOM concluded that the remaining low-level impacts do not pose a potential threat to human health or the environment, and petitioned for closure of two spill cases associated with the site. The site will continue to operate as bus depot for the foreseeable future. Based on review of the Post-Remedial Confirmatory Sampling Report, results of previous site investigations and remedial actions performed to date, the DEC concurred that the closure of spill cases is an appropriate course of action. DEC closed spills #8807411 and #2102025 on June 9, 2022. VB

Remarks: CLEANUP PENDING.

All Materials:

Site ID:	619758
Operable Unit ID:	1366939
Operable Unit:	01
Material ID:	2379635
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	EAST NY BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0109737 / 2002-07-30
Facility ID:	0109737
Facility Type:	ER
DER Facility ID:	137218
Site ID:	318237
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2002-01-07
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2002-01-08
CID:	390
Water Affected:	Not reported
Spill Source:	Unknown

NYCTA (Continued) **U003080332**

Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-08
Spill Record Last Update:	2002-07-30
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	UNK
Spiller Company:	999
Contact Name:	PASHKO CAMAJ
Latitude:	40.6774454
Longitude:	-73.8991844
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE PRODUCT WAS SAMPLED AND DETERMINED TO WASTE OIL. mONITORING WELL IS IN THE AREA WHERE THE DEPOT WASHES THE BUSES AND THE WELL IS USUALLY UNDER WATER. iT WAS DETERMINED THAT THE WELL, WHICH NEVER HAD PRODUCT IN IT BEFORE, WAS BEING IMPACTED BY A SURFACE SOURCE AND THERE WAS NO WAY TO PROTECT IT. tHE WELL WAS VACCED OUT AND CLOSED TO PREVENT FURTHER INTRODUCTION OF CONTAMINATION TO THE GROUNDWATER.
Remarks:	motor oil found in a monitoring well - unk where it came from - will keep monitoring and try to locate source

All Materials:

Site ID:	318237
Operable Unit ID:	846926
Operable Unit:	01
Material ID:	527387
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access
15 additional NY SPILL: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYD991290677
Country:	USA
Name:	Nycta
Address:	25 JAMAICA AVENUE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	25 JAMAICA AVENUE

NYCTA (Continued) **U003080332**

Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta
Mailing Contact:	Charles B Burrus
Mailing Address 1:	370 JAY ST - RM 819
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123308612

Manifest Data:

Document ID:	NJA1915866
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	12/01/1994
Trans1 Recv Date:	12/01/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/01/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

NYCTA (Continued) **U003080332**

Waste Code 6:	Not reported
Quantity:	00010
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00085
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NJA1915926
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	12/13/1994
Trans1 Recv Date:	12/13/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/13/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of

NYCTA (Continued) **U003080332**

	One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00598
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00265
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NJA1917013
Manifest Status:	Not reported
Trans1 State ID:	S5916
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/1994
Trans1 Recv Date:	08/17/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/17/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

NYCTA (Continued) **U003080332**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA1917014
Manifest Status:	Not reported
Trans1 State ID:	S5011
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	08/17/1994
Trans1 Recv Date:	08/17/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/17/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	NJD982281016

NYCTA (Continued) **U003080332**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

NYCTA (Continued) **U003080332**

Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00275
Units:	Gallons (liquids only)
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC1052998
Manifest Status:	Not reported
Trans1 State ID:	GF3013
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/1991
Trans1 Recv Date:	06/26/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/03/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980753784
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

NYCTA (Continued) **U003080332**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC3063216
Manifest Status:	Not reported
Trans1 State ID:	JE4550
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	06/08/1994
Trans1 Recv Date:	06/08/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/08/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn

NYCTA (Continued) **U003080332**

Specific Gravity: 01.00

Document ID: NYC3063240
Manifest Status: Not reported
Trans1 State ID: GF3013NY
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 06/23/1994
Trans1 Recv Date: 06/23/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/23/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD991290677
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980785760
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00036
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC3063508
Manifest Status: Not reported
Trans1 State ID: JE4550NY
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 06/15/1994
Trans1 Recv Date: 06/15/1994
Trans2 Recv Date: Not reported

NYCTA (Continued) **U003080332**

TSD Site Recv Date:	06/15/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA9214143
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	DL7754NY
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	881229
Trans1 Recv Date:	881229
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	881229
Part A Recv Date:	890131
Part B Recv Date:	890109
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

NYCTA (Continued) **U003080332**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02530
Units:	Pounds
Number of Containers:	036
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYC3142383
Manifest Status:	Not reported
Trans1 State ID:	AP6277
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/1994
Trans1 Recv Date:	07/14/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/14/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

NYCTA (Continued) **U003080332**

Quantity:	00060
Units:	Gallons (liquids only)
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYC1108124
Manifest Status:	Not reported
Trans1 State ID:	GF3013
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	07/25/1991
Trans1 Recv Date:	07/25/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/01/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD991290677
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980753784
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
964 additional NY MANIFEST: record(s) in the EDR Site Report.

S126 **EAST NEW YORK TRUCK SHOP** **NY UST** **U004062593**
NNE **1997 BROADWAY** **NY CBS** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.175 mi.
923 ft. **Site 3 of 11 in cluster S**

Relative:
Higher

Actual:
92 ft.

Client Plot

UST:

Name:	EAST NEW YORK TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-609105 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/16/2028
UTM X:	592777.77447
UTM Y:	4503625.69156
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	30951
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	27TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	EnvironmentalProtectionNYCT@nyct.com
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-10-18

Site Id:	30951
Affiliation Type:	Facility Operator
Company Name:	EAST NEW YORK TRUCK SHOP
Contact Type:	Not reported
Contact Name:	PETER CASSAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 566-3880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2023-06-06

Site Id:	30951
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, ENVIRONMENTAL PROTECTION
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY 27TH FLR.

EAST NEW YORK TRUCK SHOP (Continued) **U004062593**

Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2021-09-14

Site Id:	30951
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-11-22

Tank Info:

Tank Number:	W/O-1
Tank ID:	66444
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	03/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J00 - Dispenser - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

EAST NEW YORK TRUCK SHOP (Continued) **U004062593**

I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None

CBS:

Name:	EAST NEW YORK TRUCK SHOP
Address:	1997 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
CBS Number:	2-000445
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	592679.18231
UTMY:	4503688.09487

S127 **EAST NEW YORK BUS DEPOT** **NY UST** **U004062591**
NNE **25 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.175 mi.
923 ft. **Site 4 of 11 in cluster S**

Relative:
Higher

Actual:
92 ft.

Client Plot

UST:

Name:	EAST NEW YORK BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-190292 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/05/2027
UTM X:	592978.45466
UTM Y:	4503511.36944
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	5864
Affiliation Type:	Emergency Contact
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-12-09

Site Id: 5864

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Affiliation Type:	Facility Owner
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-06-09

Site Id:	5864
Affiliation Type:	Facility Operator
Company Name:	PETER CASSAR
Contact Type:	Not reported
Contact Name:	PETER CASSAR
Address1:	25 JAMAICA AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(646) 721-8295
EMail:	PETER.CASSAR@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Site Id:	5864
Affiliation Type:	Mail Contact
Company Name:	MTA New York City Transit
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY # 27
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	001
Tank ID:	6753
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	25000

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Install Date: 09/01/1947
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: ZZ
Date Test: 06/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 002
Tank ID: 6754
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 25000
Install Date: 09/01/1947
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: ZZ
Date Test: 06/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Tank Number:	DSL-1
Tank ID:	47327
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-10
Tank ID:	47336
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-2
Tank ID:	47328
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-3
Tank ID:	47329
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: DSL-4
Tank ID: 47330
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-5
Tank ID:	47331
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-6
Tank ID:	47332
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: DSL-7
Tank ID: 47333
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: DSL-8
Tank ID: 47334

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: DSL-9
Tank ID: 47335
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	ENY-1
Tank ID:	47325
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	20000
Install Date:	11/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	ENY-16
Tank ID:	49089
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: ENY-2
Tank ID: 47326
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 20000
Install Date: 11/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: ENY-20
Tank ID: 55448
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 1000
Install Date: 03/01/1999

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: GAS
Tank ID: 47337
Tank Status: Temporarily Out of Service
Material Name: Temporarily Out of Service
Capacity Gallons: 4000
Install Date: 12/01/1993
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	M/O-1
Tank ID:	47338
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2500
Install Date:	11/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	W/O
Tank ID:	47339
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	11/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd

EAST NEW YORK BUS DEPOT (Continued) **U004062591**

Last Modified: 01/27/2023

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J00 - Dispenser - None

S128 **MTA NYCT - EAST NY DEPOT** **RCRA-SQG** **1000136912**
NNE **25 JAMAICA AVE** **RAATS** **NYD991290677**
1/8-1/4 **BROOKLYN, NY 11207** **ICIS**
0.175 mi. **FINDS**
923 ft. **Site 5 of 11 in cluster S** **ECHO**
E MANIFEST
Relative: Higher **NJ MANIFEST**
RI MANIFEST
Actual: 92 ft.

Client Plot

RCRA Listings:

Date Form Received by Agency:		20220210
Handler Name:		Mta Nyct - East Ny Depot
Handler Address:		Jamaica Ave
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYD991290677
Contact Name:		ISABEL POTTER
Contact Address:		BROADWAY 27TH FL
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-5777
Contact Fax:		Not reported
Contact Email:		ENVIRONMENTALPROTECTIONNYCT@NYCT.COM
Contact Title:		SYSTEM SAFETY SPECIALIST
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2021
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		BROADWAY 27TH FL
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	Mta Nyc Transit	
Owner Type:		State
Operator Name:	Mta Nyc Transit	
Operator Type:		State
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220214
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years

Year: 2021

Click Here for Biennial Reporting System Data:

Year: 2011

Click Here for Biennial Reporting System Data:

Year: 2005

Click Here for Biennial Reporting System Data:

Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Waste Description: Corrosive Waste

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F004
Waste Description: The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MTA -NEW YORK CITY TARNSIT
Legal Status: State
Date Became Current: 19530101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27 FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYC TRANSIT
Legal Status: State
Date Became Current: 19530101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA NYC TRANSIT
Legal Status: State
Date Became Current: 19530101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: 20070906
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19530601
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA -NEW YORK CITY TARNSIT
Legal Status: State
Date Became Current: 19530101
Date Ended Current: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NYC TRANSIT
Legal Status: State
Date Became Current: 19530101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: 20070906
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY ROOM A27.64
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MTA NYC TRANSIT
Legal Status: State
Date Became Current: 19530101
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-5777
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19530601
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20120302

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Handler Name: NYCT-EAST NEW YORK DEPOT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20220210
Handler Name: MTA NYCT - EAST NY DEPOT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20060130
Handler Name: NYCT-ENY STORE ROOM 63
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070905
Handler Name: NYCT EAST NEW YORK DEPOT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19801216
Handler Name: NEW YORK CITY TRANSIT AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070906
Handler Name: NYCT EAST NEW YORK DEPOT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210819
Handler Name: MTA NYCT - EAST NY DEPOT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19900301
Handler Name: NEW YORK CITY TRANSIT AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920316
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Electronic Manifest Broker: Not reported

Receive Date: 19940330
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960320
Handler Name: EAST NEW YORK COMPLEX / NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980204
Handler Name: NYCTA - EAST NEW YORK COMPLEX
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: NYC TRANSIT AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020220
Handler Name: NYCTA-EAST NEW YORK DEPOT
Federal Waste Generator Description: Large Quantity Generator

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060131
Handler Name:	NYCT-ENY STORE ROOM 63
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	Mixed Mode Transit Systems

NAICS Code:	485999
NAICS Description:	All Other Transit And Ground Passenger Transportation

NAICS Code:	488119
NAICS Description:	Other Airport Operations

NAICS Code:	561599
NAICS Description:	All Other Travel Arrangement And Reservation Services

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20240430
Actual Return to Compliance Date:	20250207
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19840823
Actual Return to Compliance Date: 19840823
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20120830
Actual Return to Compliance Date:	20120830
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20120830
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20120830
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	R2STP
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19840823
Actual Return to Compliance Date:	19840823
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19870601
Actual Return to Compliance Date: 19870922
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19870909
Enforcement Identifier: 002
Date of Enforcement Action: 19870701
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19850321
Actual Return to Compliance Date:	19870922
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19870909
Enforcement Identifier:	002
Date of Enforcement Action:	19870701
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20020214
Actual Return to Compliance Date: 20020802
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20020429
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19850321
Actual Return to Compliance Date:	19870922
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19860919
Actual Return to Compliance Date:	19870922
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19861030
Enforcement Identifier:	001
Date of Enforcement Action:	19860930
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R2SRS
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 27664
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20020214
Actual Return to Compliance Date: 20020802
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20020701
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Evaluation Action Summary:

Evaluation Date:	20240430
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRMA
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20250207
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19840823
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19840823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20120830
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20120830
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19840823
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19840823
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19870601
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870922
Scheduled Compliance Date:	19870909
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850321
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870922
Scheduled Compliance Date:	19870909
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20161222
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020214
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20020802
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19850321
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870922
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19860919
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2SRS
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19870922
Scheduled Compliance Date:	19861030
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20020214
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20020802
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

RAATS:

Entry No:	1
Facility ID:	NYD991290677
Type:	Not reported
Docket No:	II RCRA-86-0219
Region:	02
Issue Date:	Not reported
Final Date:	09/30/1986
Status:	Complaint Issued
Additional:	Not reported
Action ID:	2070
Action:	3008 (A)

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Violation No: Not reported
Viol No Cited: 1 6 NYCRR 373-1.2 (C)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 7,700.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02
Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued
Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 2 6 NYCRR 373-3.9 (B)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 4,400.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02
Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued
Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 3 6 NYCRR 373-3.2 (G)(1)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 2,420.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02
Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 4 6 NYCRR 373-3.4 (C)(3)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 264.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02
Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued
Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 5 6 NYCRR 372.2 (C)(1)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 880.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02
Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued
Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 6 6 NYCRR 373-3.9 (F)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 6,500.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued
Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 7 6 NYCRR 373-3.3 (F)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 4,000.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

Entry No: 1
Facility ID: NYD991290677
Type: Not reported
Docket No: II RCRA-86-0219
Region: 02
Issue Date: Not reported
Final Date: 09/30/1986
Status: Complaint Issued
Additional: Not reported
Action ID: 2070
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 8 6 NYCRR 373-3.2 (H)(1)
Total No Cited: Not reported
Reg Type: State
Prop. Penalty: 1,500.00
Final Penalty: .00
Total Prop. Penalty: 27,664.00
Comments: Not reported

ICIS:
Enforcement Action ID: 02-1986-0303
FRS ID: 110009483497
Action Name: NYC TRANSIT AUTHORITY (JAMAICA AVE)
Facility Name: NEW YORK CITY TRANSIT AUTHORITY
Facility Address: 25 JAMAICA AVE
BROOKLYN, NY 11207
Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 3008A
Facility SIC Code: 4111
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.677393
Longitude in Decimal Degrees: -73.899088
Permit Type Desc: Not reported
Program System Acronym: 13473
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Facility Name: NEW YORK CITY TRANSIT AUTHORITY
Address: 25 JAMAICA AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4111

Facility Name: NEW YORK CITY TRANSIT AUTHORITY
Address: 25 JAMAICA AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4111

Facility Name: NEW YORK CITY TRANSIT AUTHORITY
Address: 25 JAMAICA AVENUE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4111

FINDS:
Registry ID: 110059735283

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
Registry ID: 110009483497

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
The Resource Conservation and Recovery Act Information System

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

(RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000136912
Registry ID:	110009483497

DFR URL:

Name:	NYCT-EAST NEW YORK DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207

E MANIFEST:

Manifest Tracking Number:	020509712JJK
Last Updated Date:	20190821
Shipped Date:	20190626
Received Date:	20190626
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (East New York Depot) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Rejection Indicator:	N
Manifest Tracking Number:	023617864JJK
Last Updated Date:	20211209
Shipped Date:	20211108
Received Date:	20211108
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYD991290677
Generator Name:	Mta Nyct - East Ny Depot
Generator Location Street Number:	25
Generator Location Street 1:	25 JAMAICA AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 27TH FL
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cyclechem,Inc.
Designated Facility Mail Street Number:	217
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETHPORT
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	217
Designated Facility Location Street 1:	SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETHPORT
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	023617950JJK
Last Updated Date:	20211216
Shipped Date:	20211117
Received Date:	20211117
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (East New York Depot) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	023618547JJK
Last Updated Date:	20230808
Shipped Date:	20211122
Received Date:	20211122
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (Eny Cmf) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	1720 BUSHWICK AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	023618601JJK
Last Updated Date:	20211230
Shipped Date:	20211201
Received Date:	20211201
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (East New York Depot) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	015548678FLE
Last Updated Date:	20210729
Shipped Date:	20210716
Received Date:	20210716
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nyct-East New York Depot

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Generator Location Street Number:	25
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 27FL
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	016637182FLE
Last Updated Date:	20230405
Shipped Date:	20230323
Received Date:	20230323
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Mta Nyct - East Ny Depot
Generator Location Street Number:	25
Generator Location Street 1:	25 JAMAICA AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 27TH FL
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020506504JJK
Last Updated Date:	20190821
Shipped Date:	20190802
Received Date:	20190803
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (East New York Depot) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020506966JJK
Last Updated Date:	20190927
Shipped Date:	20190910

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Received Date:	20190910
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (East New York Depot) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020509649JJK
Last Updated Date:	20190819
Shipped Date:	20190619
Received Date:	20190619
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (East New York Depot) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	25 JAMAICA AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	025926417JJK
Last Updated Date:	20240528
Shipped Date:	20240216
Received Date:	20240523
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD991290677
Generator Name:	Nycta (Storeroom 63) Haz
Generator Location Street Number:	25
Generator Location Street 1:	25 2059 BROADWAY
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	217
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	217
Designated Facility Location Street 1:	SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 025926992JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Service Inc.

Waste Line:
Manifest Tracking Number: 025926992JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3077
U.S. DOT Description: Rq, Na3077, Waste, Hazardous Waste, Solid, N.O.S., 9, Pgiii, D008, Erg#171
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 125
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.0625
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.0625
Waste Quantity, in Kilograms: 56.689377
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 56.689377
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

Click this hyperlink while viewing on your computer to access
28 additional US EManifest: record(s) in the EDR Site Report.

NJ MANIFEST:
EPA ID: NYD991290677
Name: NEW YORK TRANSIT AUTHORITY
Address: 25 JAMAICA AVE
City,State,Zip: BROOKLYN, NY 11207
County: Not reported
Mailing Address: Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Mailing City,State,Zip:	Not reported
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	NYT370011371
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYD991290677
Manifest Number:	NJA5210745
Date Shipped:	11/18/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/18/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/18/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12150435
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD991290677

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Manifest Number:	001031217JJK
Date Shipped:	05/23/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/23/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/23/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100
Unit:	P

EPA ID:	NYD991290677
Manifest Number:	001026711JJK
Date Shipped:	05/15/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/15/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/15/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H14
Quantity:	55
Unit:	G

EPA ID:	NYD991290677
Manifest Number:	003535288JJK
Date Shipped:	01/25/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/25/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/25/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	550
Unit:	G

EPA ID:	NYD991290677
Manifest Number:	015626096JJK
Date Shipped:	3/30/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
EPA ID:	NYD991290677
Manifest Number:	014162170JJK
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
EPA ID:	NYD991290677
Manifest Number:	NJA5075965
Date Shipped:	01/22/2004

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/22/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/22/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03100422
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD991290677
Manifest Number:	NJA5076984
Date Shipped:	05/04/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/04/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/04/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05180422
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD991290677
Manifest Number:	NJA5111457
Date Shipped:	11/30/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/30/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/30/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01040521
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported
EPA ID:	NYD991290677
Manifest Number:	003636253JJK
Date Shipped:	12/6/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	50.00
Unit:	Pounds
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	7.00

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Unit:	gallons
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	110.00
Unit:	gallons
Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	110.00
Unit:	gallons
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	4,000.00
Unit:	gallons
EPA ID:	NYD991290677
Manifest Number:	NJA5074353
Date Shipped:	03/05/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/05/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Manifest Discrepancy Type:	Not reported
Data Entry Number:	04010425
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Click this hyperlink while viewing on your computer to access
54 additional NJ MANIFEST: record(s) in the EDR Site Report.

RI MANIFEST:

Name:	NEW YORK CITY TRANSIT EAST NY DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207-0000
EPA Id:	NYD991290677
GEN Cert Date:	6/27/2008
Manifest Document Number:	000126743UIS
Waste Description:	PETROLEUM DISTILLATE, NOS
TSDF Id:	RID084802842
TSDF Name:	SAFETY-KLEEN SYSTEMS INC
Qty:	85
WT/Vol Units:	G
TSDF Date:	7/1/2008
Transporter 2 Id:	Not reported
Item Number:	a
Transporter 2 Name:	Not reported
Transporter Name 2:	SAFETY-KLEEN SYSTEMS, INC.
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	6/27/2008
Number Of Containers:	2
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	1/15/2008
Number Of Containers:	2

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000081078UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/15/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/17/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	5/29/2008
Number Of Containers:	2
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000126532UIS

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATE, NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS INC
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	5/29/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	6/2/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	6/27/2008
Number Of Containers:	2
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000126743UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATE, NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/27/2008
Facility Receipt Date:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	7/1/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	6/27/2008
Number Of Containers:	2
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000126743UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATE, NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/27/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	7/1/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	5/1/2008
Number Of Containers:	5
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000111677UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATE, NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS INC
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	5/1/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	5/5/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/7/2008
Number Of Containers:	2
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000081304UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/7/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/11/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	3/14/2008
Number Of Containers:	4
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000079506UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/13/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	3/20/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

Transporter Receipt Date:	3/13/2008
Number Of Containers:	4
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000079505UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	136
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/13/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	3/20/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	3/14/2008
Number Of Containers:	4
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

EPA ID:	NYD991290677
Manifest Docket Number:	000079506UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/13/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	3/20/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	3/13/2008
Number Of Containers:	4
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000079505UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	136
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported

MTA NYCT - EAST NY DEPOT (Continued) **1000136912**

GEN Cert Date:	3/13/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	3/20/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	4/3/2008
Number Of Containers:	5
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD991290677
Manifest Docket Number:	000066853UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	85
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS INC
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/3/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	4/9/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Click this hyperlink while viewing on your computer to access
24 additional RI_MANIFEST: record(s) in the EDR Site Report.

S129 **NYCT-40 CONWAY ST** **RCRA-LQG** **1001119495**
NNE **40 CONWAY ST** **FINDS** **NYR000027821**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.175 mi. **E MANIFEST**
923 ft. **Site 6 of 11 in cluster S** **NY MANIFEST**
NJ MANIFEST

Relative:
Higher

Actual:
92 ft.

Client Plot

RCRA Listings:

Date Form Received by Agency:		20080219
Handler Name:		Nyct-40 Conway St
Handler Address:		Conway St
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYR000027821
Contact Name:		JENNIFER WUOTINEN
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		646-252-5777
Contact Fax:		Not reported
Contact Email:		JENNIFER.WUOTINEN@NYCT.COM
Contact Title:		Not reported
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2007
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		BROADWAY 27TH FLOOR
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	New York City Transit	
Owner Type:		State
Operator Name:	New York City Transit	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No

NYCT-40 CONWAY ST (Continued) **1001119495**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211005
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents

NYCT-40 CONWAY ST (Continued) **1001119495**

Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYCT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST - RM 819
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYCT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST - ROOM 809
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-243-4581
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Owner/Operator Address: 2 BROADWAY 27TH FLOOR
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 370 JAY ST - ROOM 809
Owner/Operator City,State,Zip: BROOKLYN, NY 11201
Owner/Operator Telephone: 718-243-4581
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND
Legal Status: State
Date Became Current: 19530601
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960806
Handler Name: MTA NYCT - 40 CONWAY
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980204
Handler Name: NYCTA-40 CONWAY STREET
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Receive Date: 20040211
Handler Name: NYCT - 40 CONWAY STREET
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080219
Handler Name: NYCT-40 CONWAY ST
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990721
Handler Name: MTA NYCT - 40 CONWAY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYCT - 40 CONWAY STREET
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCT - 40 CONWAY STREET
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

NYCT-40 CONWAY ST (Continued) **1001119495**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	Mixed Mode Transit Systems
NAICS Code:	485119
NAICS Description:	Other Urban Transit Systems
NAICS Code:	561599
NAICS Description:	All Other Travel Arrangement And Reservation Services

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20090320
Actual Return to Compliance Date:	20090513
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090413
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20090519
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20090320
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090513
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20180424
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2STP

NYCT-40 CONWAY ST (Continued) **1001119495**

Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110009485324

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001119495
Registry ID:	110009485324

DFR URL:

Name:	NYCT-40 CONWAY ST
Address:	40 CONWAY STREET
City,State,Zip:	BROOKLYN, NY 11207

E MANIFEST:

Manifest Tracking Number:	020509687JJK
Last Updated Date:	20190819
Shipped Date:	20190625
Received Date:	20190625
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (40 Conway Street) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020507303JJK
Last Updated Date:	20190605
Shipped Date:	20190523
Received Date:	20190523
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (40 Conway Street) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY, ROOM A27.72
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	025926048JJK
Last Updated Date:	20231204
Shipped Date:	20230926
Received Date:	20230926
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000027821
Generator Name:	Nyct-40 Conway St
Generator Location Street Number:	40
Generator Location Street 1:	40 CONWAY ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 27TH FLOOR
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cyclechem Inc
Designated Facility Mail Street Number:	217
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	217
Designated Facility Location Street 1:	S 1ST ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	025926902JJK
Last Updated Date:	20240229
Shipped Date:	20231226
Received Date:	20231227
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (Conway Maintenance Shop) Haz
Generator Location Street Number:	40

NYCT-40 CONWAY ST (Continued) **1001119495**

Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	40 CONWAY STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	217
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	217
Designated Facility Location Street 1:	SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	024689907JJK
Last Updated Date:	20230721
Shipped Date:	20230120
Received Date:	20230120
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (Conway Maintenance Shop) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET

NYCT-40 CONWAY ST (Continued) **1001119495**

Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020071934JJK
Last Updated Date:	20200221
Shipped Date:	20190131
Received Date:	20190131
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000027821
Generator Name:	Nyct-40 Conway Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY 27TH FLOOR
Generator Mail Street 2:	Not reported
Generator Mail City:	BOWLING GREEN
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cyclechem,Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETHPORT
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETHPORT
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020072988JJK
Last Updated Date:	20190506
Shipped Date:	20190416
Received Date:	20190416

NYCT-40 CONWAY ST (Continued) **1001119495**

Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (40 Conway Street) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY, ROOM A27.72
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	020073290JJK
Last Updated Date:	20191223
Shipped Date:	20181218
Received Date:	20181218
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000027821
Generator Name:	Nyct-40 Conway Street
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY 27TH FLOOR
Generator Mail Street 2:	Not reported
Generator Mail City:	BOWLING GREEN
Generator Mail Zip:	10004
Generator Mail State:	NY

NYCT-40 CONWAY ST (Continued) **1001119495**

Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cyclechem,Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETHPORT
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETHPORT
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	025122807JJK
Last Updated Date:	20230719
Shipped Date:	20230622
Received Date:	20230622
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (Conway Maintenance Shop) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N

NYCT-40 CONWAY ST (Continued) **1001119495**

Rejection Indicator:	N
Manifest Tracking Number:	025123146JJK
Last Updated Date:	20230727
Shipped Date:	20230328
Received Date:	20230328
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (Conway Maintenance Shop) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	025891149JJK
Last Updated Date:	20241108
Shipped Date:	20241014
Received Date:	20241014
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000027821
Generator Name:	Nycta (Conway Maintenance Shop) Haz
Generator Location Street Number:	40
Generator Location Street 1:	40 CONWAY STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207

NYCT-40 CONWAY ST (Continued) **1001119495**

Generator Mail Street Number:	2
Generator Mail Street 1:	40 CONWAY STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	217
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	217
Designated Facility Location Street 1:	SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:		023908042JJK
Waste Line Number:		1
Federal Waste Code:		D008
Federal Waste:	LEAD	

Manifest Tracking Number:		023908042JJK
Waste Line Number:		2
Federal Waste Code:		D008
Federal Waste:	LEAD	

State Waste:

Manifest Tracking Number:	023908042JJK
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T
State Waste:	Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Manifest Tracking Number:	023908042JJK
Waste Line Number:	2
State Waste Code Owner:	NY
State Waste Code:	T
State Waste:	Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:

Manifest Tracking Number:	023908042JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services, Inc

NYCT-40 CONWAY ST (Continued) **1001119495**

Waste Line:

Manifest Tracking Number:	023908042JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Na3077, Hazardous Waste, Solid, N.O.S. (Lead), 9 , Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	95
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0475
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0475
Waste Quantity, in Kilograms:	43.083927
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	43.083927
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

Manifest Tracking Number:	023908042JJK
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Rq, Na3077, Hazardous Waste, Solid, N.O.S. (Lead), 9 , Iii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	78
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.039
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.039
Waste Quantity, in Kilograms:	35.374172
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	35.374172
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N

NYCT-40 CONWAY ST (Continued) **1001119495**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

Click this hyperlink while viewing on your computer to access
9 additional US EManifest: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYR000027821
Country:	USA
Name:	Mta Nyct - 40 Conway
Address:	40 CONWAY STREET
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	40 CONWAY STREET
Location Address 2:	BROOKLYN
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Mta Nyct - 40 Conway
Mailing Contact:	Howard Matza
Mailing Address 1:	370 JAY STREET
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182434581

Manifest Data:

Document ID:	NJA2784723
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/1998
Trans1 Recv Date:	06/25/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/25/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	NJ0000027193

NYCT-40 CONWAY ST (Continued) **1001119495**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00170
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA2567993
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES58

NYCT-40 CONWAY ST (Continued) **1001119495**

Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	09/12/1996
Trans1 Recv Date:	09/12/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/12/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00390
Units:	Gallons (liquids only)
Number of Containers:	006
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA2564779
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES58
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/1996
Trans1 Recv Date:	10/10/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/10/1996
Part A Recv Date:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00220
Units:	Gallons (liquids only)
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)

NYCT-40 CONWAY ST (Continued) **1001119495**

Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NJA4118237
Manifest Status: Not reported
Trans1 State ID: H10376
Year: 2003
Trans2 State ID: Not reported
Generator Ship Date: 05/23/2003
Trans1 Recv Date: 05/23/2003
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/28/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000027821
Trans1 EPA ID: NJD003812047
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00092
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NJA3180666
Manifest Status: Not reported
Trans1 State ID: H10376
Year: 2002
Trans2 State ID: 083165
Generator Ship Date: 03/15/2002
Trans1 Recv Date: 03/15/2002
Trans2 Recv Date: 03/18/2002
TSD Site Recv Date: 03/22/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Generator EPA ID:	NYR000027821
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	NJD003812047
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01385
Units:	Pounds
Number of Containers:	006
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NJA3205253
Manifest Status:	Not reported
Trans1 State ID:	H10376
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	01/11/2002
Trans1 Recv Date:	01/11/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/15/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00104
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NJA3205304
Manifest Status: Not reported
Trans1 State ID: H10376
Year: 2002
Trans2 State ID: Not reported
Generator Ship Date: 02/13/2002
Trans1 Recv Date: 02/13/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/14/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000027821
Trans1 EPA ID: NJD003812047
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00420
Units: Pounds
Number of Containers: 004
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: Not reported
Manifest Status: Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2013
Trans1 Recv Date:	03/06/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	000960236GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	327
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/30/2016
Trans1 Recv Date:	11/30/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/30/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821

NYCT-40 CONWAY ST (Continued) **1001119495**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	016114760JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	406
Units:	Pounds
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/18/2017
Trans1 Recv Date:	08/18/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014162567JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

NYCT-40 CONWAY ST (Continued) **1001119495**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Lead
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	328
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/03/2011
Trans1 Recv Date:	05/03/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/03/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000027821
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003534571JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	74
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
132 additional NY MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA ID:	NYR000027821
Name:	NYCTA
Address:	40 CONWAY ST
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	370 JAY ST ROOM 809
Mailing City,State,Zip:	BROOKLYN 11201
Telephone:	7182434581
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000027821
Manifest Number:	001028762JJK
Date Shipped:	12/19/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/19/2008

NYCT-40 CONWAY ST (Continued) **1001119495**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/19/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	446
Unit:	P

EPA ID:	NYR000027821
Manifest Number:	NJA5254900
Date Shipped:	07/19/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/19/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Date TSDF Received Waste:	07/19/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08260521
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYR000027821
Manifest Number:	003536157JJK
Date Shipped:	06/11/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/11/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/11/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	166
Unit:	P

EPA ID:	NYR000027821
Manifest Number:	000959827GBF
Date Shipped:	3/31/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

EPA ID:	NYR000027821
Manifest Number:	003531077JJK
Date Shipped:	02/01/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/01/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/01/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	642
Unit:	P

EPA ID:	NYR000027821
Manifest Number:	014162161JJK
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

EPA ID:	NYR000027821
Manifest Number:	003535530JJK
Date Shipped:	11/09/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/09/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/09/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported
EPA ID:	NYR000027821
Manifest Number:	003535841JJK
Date Shipped:	10/14/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/14/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/14/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	55
Unit:	G
Manifest Year:	Not reported
Waste Code:	D008

NYCT-40 CONWAY ST (Continued) **1001119495**

Hand Code:	H111
Quantity:	139
Unit:	P

EPA ID:	NYR000027821
Manifest Number:	001057569GBF
Date Shipped:	12/08/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/08/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/08/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	187
Unit:	P

EPA ID:	NYR000027821
Manifest Number:	001026842JJK
Date Shipped:	12/21/2007
TSDF EPA ID:	NJD002200046

NYCT-40 CONWAY ST (Continued) **1001119495**

Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/21/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/21/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYR000027821
Manifest Number:	010407124JJK
Date Shipped:	6/7/2013
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

NYCT-40 CONWAY ST (Continued) **1001119495**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	101.00
Unit:	Pounds

Click this hyperlink while viewing on your computer to access
66 additional NJ MANIFEST: record(s) in the EDR Site Report.

S130 **NYC-TA EAST NY BUS DEPOT & SHOPS** **NY LTANKS** **1004566769**
NNE **1 JAMAICA AVE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11207** **US AIRS**
0.175 mi. **NY AIRS**
923 ft. **Site 7 of 11 in cluster S**

Relative:
Higher

Actual:
92 ft.

Client Plot

LTANKS:

Name:	MTA BUS DEPOT - TTF
Address:	1 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0902562 / 2009-08-24
Facility ID:	0902562
Site ID:	414609
Spill Date:	2009-05-31
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2009-06-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-03
Spill Record Last Update:	2009-08-24
Spiller Name:	HAROON ASLAM
Spiller Company:	MTA BUS DEPOT
Spiller Address:	1 JAMAICA AVE
Spiller County:	999
Spiller Contact:	HAROON ASLAM
Spiller Phone:	(646) 252-3607
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	192989
Latitude:	40.6774570
Longitude:	-73.8991920
DEC Memo:	This spill event is BOTH a spill and a tank test failure. Spill was cleaned. TTF issue remains open 8/5/2009 TTF letter sent to: Ms. Jennifer Woutinen New York City Transit 2 Broadway 27th Flr New York, NY 10004 8/24/09. J.Krimgold interviewed the caller (HAROON ASLAM) form MTA over the phone. He stated that the failure was due to the leak from the fill line, not due to the t/test as originally stated. The fill line is double walled and sloped toward the tank sump, where the product was found. The pipe's secondary containment then was tested and found to be tight. This indicates that there was no release to the environment from this incident. The pipe was tagged (taken out of service). Tank is manifolded with other tanks and has another fill. NFA. JK.
Remarks:	CALLER STATES THAT THE TANK (UNK SIZE) FAILED A LEAK TEST, ABOUT 10 GALLONS WAS SPILLED. CALLER DID NOT HAVE THE PBS NUMBER. SPILL WAS CLEANED UP.

All Materials:

Site ID:	414609
Operable Unit ID:	1170993
Operable Unit:	01
Material ID:	2162776
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	EAST NY DEPOT
Address:	1 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0603788 / 2006-07-06
Facility ID:	0603788
Facility Type:	ER

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

DER Facility ID:	192989
Site ID:	366580
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-07-06
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-07-06
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-06
Spill Record Last Update:	2006-07-06
Spiller Name:	OLUCHI DUROHA
Spiller Company:	EAST NY DEPOT
Spiller Address:	1 JAMACIA AVE
Spiller Company:	001
Contact Name:	OLUCHI DUROHA
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	07/06/06-Hiralkumar Patel. spoke to Ms. Duroha. during tank test, due to wrong connection, oil spilled on concrete floor at fill port. no drain/soil affected. all cleaned up. case closed.
Remarks:	TESTING TANKS, AND WHILE DOING SO FILL LINE OVERFLOWED A LITTLE AND IS ALL CLEANED UP

All Materials:

Site ID:	366580
Operable Unit ID:	1124515
Operable Unit:	01
Material ID:	2114013
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NYC TRANSIT EAST NY SHOP
Address:	1 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0410136 / 2005-01-11
Facility ID:	0410136
Facility Type:	ER

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

DER Facility ID:	192989
Site ID:	334982
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	2401
Spill Date:	2004-12-12
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-12-12
CID:	38
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-13
Spill Record Last Update:	2005-01-11
Spiller Name:	BROWN,JOSEPHINE
Spiller Company:	NYC TRANSIT EAST NY SHOP
Spiller Address:	1 JAMAICA AV
Spiller Company:	001
Contact Name:	BROWN,JOSEPHINE
Latitude:	40.6774440
Longitude:	-73.8991800
DEC Memo:	01-11-05: 55 gallon drum discovered onn it’s side. Unkown how much was in drum. Drum was found empty so it is unknown how much was spilled and an undetermined amount entered a drain which lead to an OWS and eventually the sewer. NYC DEP was notified (977412). The remaining material was cleaned by NYCT.
Remarks:	55 GALLON BARREL OF ANTIFREEZE SPILLED OUT UNKNOWN QUANTITY OF ANTIFREEZE. SOME OF ANTIFREEZE WENT INTO A STORM DRAIN - UNKNOWN DESTINATION OF DRAIN. ANTIFREEZE HAS BEEN CLEANED UP BY NYC TRANSIT.

All Materials:

Site ID:	334982
Operable Unit ID:	1097091
Operable Unit:	01
Material ID:	577047
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	55.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	EAST NEW YORK DEPOT
Address:	1 JAMAICA AVE

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0007655 / 2001-04-19
Facility ID:	0007655
Facility Type:	ER
DER Facility ID:	192989
Site ID:	234264
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-09-29
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2000-09-29
CID:	396
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-09-29
Spill Record Last Update:	2001-04-19
Spiller Name:	JOE GAROFALO
Spiller Company:	RAD OIL
Spiller Address:	7 HAMPTON RD
Spiller Company:	001
Contact Name:	MIKE RYAN
Latitude:	40.6770042
Longitude:	-73.9001501
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE refer to 00-07658.
Remarks:	spill contained and cleaned up.

All Materials:

Site ID:	234264
Operable Unit ID:	830216
Operable Unit:	01
Material ID:	545185
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EAST NY DEPOT
Address:	1 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0311243 / 2004-01-09
Facility ID:	0311243

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Facility Type:	ER
DER Facility ID:	192989
Site ID:	234265
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-01-05
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-01-05
CID:	404
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-05
Spill Record Last Update:	2004-01-09
Spiller Name:	JOSEPHINE BROWN
Spiller Company:	NYCT
Spiller Address:	370 JAY STREET
Spiller Company:	001
Contact Name:	MR. BONSIENORI
Latitude:	40.6770042
Longitude:	-73.9001501
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Three drums fell from a broken pallet while being transfer from a truck to the sidewalk in front of the depot. Spill was contained and cleaned by NYCT.
Remarks:	BROKEN WOODEN SKID CAUSED A BARREL TO TIP AND SPILL. ALL CONTAINED AND IS CURRENTLY BEING CLEANED UP. NOTHING WENT INTO THE ENVIRONMENT.

All Materials:

Site ID:	234265
Operable Unit ID:	878940
Operable Unit:	01
Material ID:	500067
Material Code:	1045
Material Name:	gear/spindle oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EAST NY DEPOT
Address:	1 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9605587 / 2004-04-21

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Facility ID:	9605587
Facility Type:	ER
DER Facility ID:	192989
Site ID:	234266
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-07-31
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-07-31
CID:	233
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-31
Spill Record Last Update:	2004-04-21
Spiller Name:	JOSEPHINE BROWN
Spiller Company:	NEW YORK CITY TRANSIT AUT
Spiller Address:	370 JAY STREET, ROOM 809
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6770042
Longitude:	-73.9001501
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/3/03 - austin - transferred from hale to tibbe 04/21/04 - As per NYCT OSS, flooding due to rain caused the OWS to back up into the depot. Most of the product was contained and cleaned by NYCT but some was pushed through the separator into the sewer.
Remarks:	flood in area oil seperator was affected due to this oil has backed up into depot

All Materials:

Site ID:	234266
Operable Unit ID:	1036384
Operable Unit:	01
Material ID:	348331
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

US AIRS (AFS):
Region Code: 02
County Code: NY047
Programmatic ID: AIR NY0000002610500262
Facility Registry ID: 110001602533
D and B Number: Not reported
Facility Site Name: NYC-TA EAST NY BUS DEPOT & SHOPS
Primary SIC Code: 4111
NAICS Code: 485113
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: SMI
HPV Status: ADDRESSED HPV
Region Code: 02
County Code: NY047
Programmatic ID: AIR NY0000002610500262
Facility Registry ID: 110001602533
D and B Number: Not reported
Facility Site Name: NYC-TA EAST NY BUS DEPOT & SHOPS
Primary SIC Code: 4111
NAICS Code: 485113
Default Air Classification Code: SMI
Facility Type of Ownership Code: Not reported
Air CMS Category Code: TVM
HPV Status: ADDRESSED HPV

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002610500262
Facility Registry ID: 110001602533
Air Operating Status Code: OPR
Default Air Classification Code: SMI

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-05-26 00:00:00
Activity Status Date: 2016-06-09 07:01:20
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2016-05-26 00:00:00
Activity Status Date: 2016-06-09 07:01:20
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-05-26 00:00:00
Activity Status Date: 2016-06-09 07:01:20
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2016-03-21 00:00:00
Activity Status Date: 2016-05-02 13:12:17

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-03-21 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-03-21 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-02-05 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2015-02-05 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-02-05 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2014-02-08 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-02-08 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-02-08 00:00:00
Activity Status Date: 2016-05-02 13:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2013-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2012-08-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Operating Permits
Activity Date: 2012-08-15 00:00:00
Activity Status Date: 2012-09-18 11:43:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2012-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2012-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2011-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-09-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2011-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2011-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-07-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2011-04-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Date: 2011-04-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2011-04-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-04-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-08-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-08-11 00:00:00

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2010-08-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2010-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2010-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-08-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2009-08-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-08-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2009-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2009-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-04-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-03-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2009-03-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2009-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2009-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-02-02 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2009-02-02 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-02-02 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Air Program: Title V Permits
Activity Date: 2009-02-02 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-10-06 00:00:00
Activity Status Date: 2008-10-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Resolved

Air Program: New Source Performance Standards
Activity Date: 2008-08-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-08-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-08-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2008-08-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Date: 2008-08-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2008-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-31 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2008-07-31 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-31 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2008-07-31 00:00:00
Activity Status Date: 2016-05-02 13:12:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Performance Standards
Activity Date: 2008-07-31 00:00:00

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2007-06-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-06-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-06-12 00:00:00
Activity Status Date: 2008-10-06 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-06-12 00:00:00
Activity Status Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-06-12 00:00:00
Activity Status Date: 2007-06-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2007-05-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2007-05-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-05-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2007-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2006-12-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2006-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2006-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2006-06-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-08-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2005-08-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-08-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2005-08-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2005-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2005-07-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-04-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2005-04-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Date: 2005-04-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2005-04-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2005-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2005-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2004-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2004-08-03 00:00:00

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-08-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2004-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2004-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-03-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2003-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2003-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2003-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2003-08-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-08-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-08-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2003-08-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-02-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2003-02-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-02-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2003-02-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2003-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2003-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2002-09-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2002-09-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Air Program: Title V Permits
Activity Date: 2002-09-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-09-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2001-05-31 00:00:00
Activity Status Date: 2001-05-31 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Date: 2000-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 2000-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2000-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 2000-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-10-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Performance Standards
Activity Date: 1999-10-14 00:00:00

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-10-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 1999-10-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: Title V Permits
Activity Date: 1998-04-23 00:00:00
Activity Status Date: 1998-04-23 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Air Program: Title V Permits
Activity Date: 1998-03-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-09-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

AIRS:
Name: NYC-TA EAST NY BUS DEPOT & SHOPS
Address: 1 JAMAICA AVE
City,State,Zip: BROOKLYN, NY 11207
DECID: 2610500262
Process ID: Not reported
Latitude: 40.678269031
Longitude: 73.899585088
FIPS Code: Not reported
Auth Type Code: ATV

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 03/22/2002
Expired Date: 03/21/2007

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 05/16/2008
Expired Date: 11/19/2012
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 10/28/2005
Expired Date: 03/21/2007
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 11/19/2012
Expired Date: Not reported
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Issued
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 11/07/2016
Expired Date: 11/06/2026
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 11/20/2012
Expired Date: 11/06/2016
Emission Unit date: Not reported
Contamination: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.55776001
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	B00001
Contamination:	CO
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.05
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	B00001
Contamination:	7439921
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0001
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	B00001
Contamination:	50328
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.25
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	B00001
Contamination:	108883
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0013
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	B00001
Contamination:	85018
EPA Control Code:	Not reported
Control Eff:	Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Unit: LB

AIRS Detail:
DECID: 2610500262
Facility Name: NYC-TA EAST NY BUS DEPOT & SHOPS
Auth Type: ASF

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	VOC
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	LEAD
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	OXIDES OF NITROGEN
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	PARTICULATES
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	PM-10
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	TOTAL HAP
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Year:	Not reported
CAS #:	Not reported
Contaminant:	VOC
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	LEAD
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	OXIDES OF NITROGEN
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	PARTICULATES
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	PM-10
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	TOTAL HAP
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000115071
Contaminant: PROPYLENE
Amount(Lbs/Yr): 1.7543999999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 2.29489994606628E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 11535696.800000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 4.7816415543047502E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 1.1471469730331399E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.72028795954971E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 2.8722099325828501E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 1.16305936847683E-4

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 1.16319436847683E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 9313.4599999999991

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 1.9380000000000001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 4.7783915543047499E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 3.6315775812716097E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 2.4847636082384699E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.10512461419470399

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.20069244528079899

Issue Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Expiration Date: Not reported
Year: 2009
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 1.9113566217219002E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.42049845677881798

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 0.00114681397303314

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.10512461419470399

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.13379496352053299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 8.0276978112319708E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 8.1232656423180699E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.21980601149801801

Issue Date: Not reported
Expiration Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Year: 2009
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 2.77146710149675

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 114.81999999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 47.097819999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 2.2936279460662799E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 211.45959999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 7.7530291231788798E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 850.07011999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 6.5798769081000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 11526.42

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 182.75228461250001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 65.700000000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 4.8457234419867996

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 7.7543091231788806E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 7.7569891231788797E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 1.16409636847683E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.88574145365562995

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Contaminant: METHANE
Amount(Lbs/Yr): 221.07140000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 297.9658

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 103.37372164238499

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 0.000052156

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 1.72118695954971E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 1.1003449924503401E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 2.6957552704106599E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 3.9416997776159299E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Amount(Lbs/Yr):	2.2936279460662799E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000100414
Contaminant:	ETHYLBENZENE
Amount(Lbs/Yr):	7.5999999999999998E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	135.67800965563001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000106990
Contaminant:	1,3-BUTADIENE
Amount(Lbs/Yr):	2.6587999999999999E-6
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000107028
Contaminant:	ACROLEIN
Amount(Lbs/Yr):	6.2899999999999999E-6
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000108883
Contaminant:	TOLUENE
Amount(Lbs/Yr):	2.2496969704900698
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	167.98229766887599
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	118.891436847683
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	4.9076157899366402E-5

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000206440
Contaminant:	FLUORANTHENE
Amount(Lbs/Yr):	1.11572898409481E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000207089
Contaminant:	BENZO[K]FLUORANTHENE
Amount(Lbs/Yr):	3.3529921994392099E-5
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000218019
Contaminant:	CHRYSENE
Amount(Lbs/Yr):	3.4321921994392101E-5
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000540841
Contaminant:	PENTANE, 2,2,4-TRIMETHYL-
Amount(Lbs/Yr):	1.1000000000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	5035.9099999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	001330207
Contaminant:	XYLENE, M, O & P MIXT.
Amount(Lbs/Yr):	0.90114000000000005
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.0135221550882342
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	1.0276837867058001E-2
Issue Date:	Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Expiration Date: Not reported
Year: 2009
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 7.0315206458817598E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 2.9748741194115101E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 5.6793051370583499E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 5.4088620352936599E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.118994964776461

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 2.1917761221176201E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 2.9748741194115101E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 3.7862034247055601E-2

Issue Date: Not reported
Expiration Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Year:	2009
CAS #:	007440484
Contaminant:	COBALT
Amount(Lbs/Yr):	2.2717220548233402E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	2.2987663649998099E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440622
Contaminant:	VANADIUM
Amount(Lbs/Yr):	0.0622019134058771
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440666
Contaminant:	ZINC
Amount(Lbs/Yr):	0.78428499511758099
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007446095
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	21117.372200000002
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	368.99360000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	0.0175431794442352
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	108.74402000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 2.1939947996261401E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1130.1293194689499

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 870.48168627960001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 26031.353999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 832.71731396400003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 16.199999999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 20.2707017497663

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 2.26919479962614E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000053703

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 2.4271947996261402E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 3.9629921994392098E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.84212690899345799

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 273.73644999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 84.319999999999993

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 29.2532639950152

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 0.003068

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 5.4359752324175002E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000085018
Contaminant: PHENANTHRENE

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Amount(Lbs/Yr): 4.2841592994703699E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 1.9252394524814999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 0.1202

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 6.4906344423524003E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 1.1492006898099601E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 38.394908993457499

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 1.5640000000000001E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000107028
Contaminant: ACROLEIN
Amount(Lbs/Yr): 3.6999999999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 1.9637991859894099

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	47.536553991899702
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	35.309921994392099
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000115071
Contaminant:	PROPYLENE
Amount(Lbs/Yr):	1.0319999999999999E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	7.2386336530717499E-5
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	3354400
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	1.5434153070714699E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000191242
Contaminant:	BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr):	3.4409170147814202E-5
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2008
CAS #:	000206440
Contaminant:	FLUORANTHENE
Amount(Lbs/Yr):	3.2505503067397799E-4
Issue Date:	Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Expiration Date: Not reported
Year: 2008
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 226.06864400000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 11861180.800000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 331.187905

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 124.028886348285

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.10722190044889

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 0.00012012929979188

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 8.1878542160970201E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 1.1906612386200599E-4

Issue Date: Not reported
Expiration Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Year: 2008
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 7.9883144121927602E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 1.9494890990707201E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 4.4786054551023202

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 171.33362472530001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000115071
Contaminant: PROPYLENE
Amount(Lbs/Yr): 0.01106304

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.42888760179555802

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000107028
Contaminant: ACROLEIN
Amount(Lbs/Yr): 3.9664000000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 0.00122208

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 1.6766080000000001E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 3.9813796257947198E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 138.38485073966601

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.22419124639313301

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 2.1043572594424301E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 14.405283437845201

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 4.0561126662474301E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 303.91036000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000205992

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.7587893835673999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 0.00124632551551158

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 2.8267591936525398

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 2.4195724371674801E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 5.07868853294398E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 10722.16426

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 240.15761000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 435.72642163419999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY075025
Contaminant: PM 2.5

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Amount(Lbs/Yr): 1400.5024724257501

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 5321.9238074695004

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 24130.044999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 1.0795868918884901E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.20469635540242501

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 0.00018154303242274

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 7.9077057565523204E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.13646423693495

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 8.1576944121927603E-5

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 2.3393869188848599E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 1.2581939979187999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.10722190044889

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 2.5343358287919299E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 105.43607675403101

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 3.2888959999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 0.00011928019979188

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.0828532867105055

Issue Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Expiration Date: Not reported
Year: 2008
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 10990.8374

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 3.7040292882343701E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 0.14680000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 1.6891855547396699

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 5.4315481600094202E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.0110790695459442

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 1.10790695459442E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 3.9884690136443598E-5

Issue Date: Not reported
Expiration Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Year: 2007
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1055.77016

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 32.924994433465599

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.87745799350570997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 5.0963719911343498E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 6.6474417275665397E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 2.6964021320656701E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 4.7279319894854401

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 4.6532092092965799E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1130.86560109835

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.0179759962889771

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 5.7611161638909999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 465.98559299999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 1.8612836837186299E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 321.45231000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 2.5465994742717498E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 3.1021394728643899E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000050328

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 1.7975969401785902E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 2674284

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 5.3179533820532296E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 1.7975969401785902E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 8.4200928549176199E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007446119
Contaminant: SULFUR TRIOXIDE
Amount(Lbs/Yr): 341.29919999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 38.947991959450299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 2.6589766910266202E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440508
Contaminant: COPPER

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Amount(Lbs/Yr): 0.0188344182281052

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 33514.330000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 1.1234997680610701

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 3.9884690136443598E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1113.78443264

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 2.4373953001077302E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 2.6964021320656701E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 49.02854

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 0.2051

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 2.6964021320656701E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 2.4373953001077302E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 0.64258603366476597

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 5.3179533820532296E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 4716.1588000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 69.085669999999993

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 31.457993505709801

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 2.6589727139221799E-5

Issue Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Expiration Date: Not reported
Year: 2007
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 9.7495812004309304E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 6.2042829228332104E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 5.3179553706054498E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 4.4316278183776899E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 9.1377981135633297E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 23.9679950519694

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 26805.358619999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.14776374743712301

Issue Date: Not reported
Expiration Date: Not reported

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Year:	2006
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	4.7677442873640397E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440473
Contaminant:	CHROMIUM
Amount(Lbs/Yr):	4.7015737820902598E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	2.8545269391262298E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440622
Contaminant:	VANADIUM
Amount(Lbs/Yr):	7.7240140705768595E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440666
Contaminant:	ZINC
Amount(Lbs/Yr):	0.97389742629012499
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007446095
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	30370.280999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	532.04944
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	2.5292196076929799E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 145.18834000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 2.7244253070651699E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1345.5090990277599

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1261.6699868972

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 33663.178

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 913.22172499999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 0.21299999999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 383.76245

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000074840

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Contaminant: ETHANE
Amount(Lbs/Yr): 104.7056

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 36.325670760868903

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 1.3849161977581299E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 47.677442873640402

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 7.7192050366846399E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 59.029214986411901

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 40.8663796059775

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 4053120

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000630080
Contaminant: CARBON MONOXIDE

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

Amount(Lbs/Yr):	6059.0540000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.0167913349360366
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	1.2761414551387899E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	8.7314941667390508E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007439987
Contaminant:	MOLYBDENUM
Amount(Lbs/Yr):	3.6940936859280599E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440020
Contaminant:	NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr):	7.0523606731353897E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	6.7165339744146603E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000050000
Contaminant:	FORMALDEHYDE
Amount(Lbs/Yr):	29.088660816915699
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440439
Contaminant:	CADMIUM
Amount(Lbs/Yr):	3.6940936859280599E-2

NYC-TA EAST NY BUS DEPOT & SHOPS (Continued) **1004566769**

AIRS Emissions:

County:	KINGS
Municipality:	BROOKLYN (6105)
Facility ID:	2610500262
Facility Name:	NYC-TA EAST NY BUS DEPOT & SHOPS
SIC Code:	4111
Year:	2012
VOC(tons):	3.52
NOx(tons):	3.42
Co(tons):	2.77
Co2(tons):	3910.89
Particulates:	0.25
PM10(tons):	0.25
PM2.5(tons):	0.25
HAPS:	0
So2:	0.03
Year:	2011
VOC(tons):	2.35
NOx(tons):	4.41
Co(tons):	3.39
Co2(tons):	4710.53
Particulates:	0.33
PM10(tons):	0.32
PM2.5(tons):	0.3
HAPS:	0
So2:	0.18
Year:	2010
VOC(tons):	0.36
NOx(tons):	5.76
Co(tons):	4.66
Co2(tons):	6215.39
Particulates:	0.46
PM10(tons):	0.46
PM2.5(tons):	0.43
HAPS:	0
So2:	0.06

Click this hyperlink while viewing on your computer to access
133 additional NY AIRS: record(s) in the EDR Site Report.

S131 **NYCTA (ENY YARD) HAZ** **RCRA NonGen / NLR** **1000393172**
NNE **1700 BUSHWICK AVENUE** **ICIS** **NYD981140023**
1/8-1/4 **BROOKLYN, NY 11207** **US AIRS**
0.175 mi. **E MANIFEST**
923 ft. **Site 8 of 11 in cluster S** **RI MANIFEST**
NY MANIFEST
Relative: **NJ MANIFEST**
Higher

Actual: RCRA Listings:
92 ft.

Date Form Received by Agency:	20221116
Handler Name:	Nyct - East Ny Yard
Handler Address:	Bushwick Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYD981140023

Client Plot

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Contact Name:		ISABEL POTTER
Contact Address:		BROADWAY 27TH FL
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-5777
Contact Fax:		Not reported
Contact Email:		ENVIRONMENTALPROTECTIONNYCT@NYCT.COM
Contact Title:		SYSTEM SAFETY SPECIALIST
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		BROADWAY 27TH FL
Mailing City,State,Zip:		BOWLING GREEN, NY 10004
Owner Name:	Nyct	
Owner Type:		State
Operator Name:	Nyct	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20221116
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2007

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D008
Waste Description: Lead

Waste Code: D010
Waste Description: Selenium

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19530601
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: BOWLING GREEN, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NYCT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FL
Owner/Operator City,State,Zip:	BOWLING GREEN, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FLOOR
Owner/Operator City,State,Zip:	BOWLING GREEN, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NYCT	
Legal Status:	State
Date Became Current:	19530601
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FL
Owner/Operator City,State,Zip:	BOWLING GREEN, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT AUTHORITY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYCT
Legal Status: State
Date Became Current: 19530601
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: BOWLING GREEN, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20221116
Handler Name: NYCT - EAST NY YARD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990714
Handler Name: NYCTA - EAST NEW YORK BARN & YARD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYCTA - EAST NEW YORK BARN & YARD
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Receive Date: 20070101
Handler Name: NYCTA - EAST NEW YORK BARN & YARD
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19851105
Handler Name: NYCTA - EAST NEW YORK BARN & YARD
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210824
Handler Name: NYCT - EAST NY YARD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19920316
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080213
Handler Name: NYCT-EAST NEW YORK YARD
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485119
NAICS Description: Other Urban Transit Systems

NAICS Code: 485999
NAICS Description: All Other Transit And Ground Passenger Transportation

NAICS Code: 561599
NAICS Description: All Other Travel Arrangement And Reservation Services

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20120905
Actual Return to Compliance Date: 20120907
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20120905
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20120907
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2STP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20120905
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: R2STP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20120907
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

ICIS:
Enforcement Action ID: 02-2008-0852
FRS ID: 110001609778
Action Name: East New York Depot Central Maintenance Facility MTA
Facility Name: EAST NEW YORK CENTRAL MAINTENANCE FACILITY (MTA-NYCT)
Facility Address: 1700 BUSHWICK AVE.
BROOKLYN, NY 11207
Enforcement Action Type: RCRA 3008A AO For Comp And/Or Penalty
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 3008A
Facility SIC Code: 4111
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.679732
Longitude in Decimal Degrees: -73.900855
Permit Type Desc: Not reported
Program System Acronym: 600032762
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: EAST NEW YORK CENTRAL MAINTENANCE FACILITY (MTA-NYCT)
Address: 1700 BUSHWICK AVE.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4111

Facility Name: EAST NEW YORK CENTRAL MAINTENANCE FACILITY (MTA-NYCT)
Address: 1700 BUSHWICK AVE.
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4111

Facility Name: EAST NEW YORK CENTRAL MAINTENANCE FACILITY (MTA-NYCT)
Address: 1700 BUSHWICK AVE.
Tribal Indicator: N

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Fed Facility: No
NAIC Code: Not reported
SIC Code: 4111

US AIRS MINOR:
Envid: 1000393172
Region Code: 02
Programmatic ID: AIR 020000003604701049
Facility Registry ID: 110001609778
D and B Number: Not reported
Primary SIC Code: 4111
NAICS Code: 485119
Default Air Classification Code: MIN
Facility Type of Ownership Code: DIS
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR 020000003604701049
Facility Registry ID: 110001609778
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2003-12-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR 020000003604701049
Facility Registry ID: 110001609778
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: Stratospheric Ozone Protection
Activity Date: 1999-02-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

E MANIFEST:
Manifest Tracking Number: 015546580FLE
Last Updated Date: 20220211
Shipped Date: 20220125
Received Date: 20220125
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYD981140023
Generator Name: Nyct - East Ny Yard
Generator Location Street Number: Not reported
Generator Location Street 1: 1700 BUSHWICK AVE
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY 27TH FL
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015548499FLE
Last Updated Date:	20210429
Shipped Date:	20210412
Received Date:	20210413
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD981140023
Generator Name:	Nyct-East New York Yard
Generator Location Street Number:	1700
Generator Location Street 1:	1700 BUSHWICK AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 27TH FLOOR
Generator Mail Street 2:	Not reported
Generator Mail City:	BOWLING GREEN
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015548734FLE
Last Updated Date:	20210907
Shipped Date:	20210810
Received Date:	20210810
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD981140023
Generator Name:	Nyct-East New York Yard
Generator Location Street Number:	Not reported
Generator Location Street 1:	1700 BUSHWICK AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY RM A27.64
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	022175584JJK
Last Updated Date:	20201125
Shipped Date:	20201109
Received Date:	20201109
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Generator EPA ID:	NYD981140023
Generator Name:	Nycta (Eny Yard) Haz
Generator Location Street Number:	Not reported
Generator Location Street 1:	1700 BUSHWICK AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cycle Chem, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETH
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETH
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017573403FLE
Last Updated Date:	20241008
Shipped Date:	20220617
Received Date:	20220617
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD981140023
Generator Name:	Nyct - East Ny Yard
Generator Location Street Number:	1700
Generator Location Street 1:	1700 BUSHWICK AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	2
Generator Mail Street 1:	BROADWAY 27TH FL
Generator Mail Street 2:	Not reported
Generator Mail City:	BOWLING GREEN
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Designated Facility Mail Street Number: 105
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: JACOBUS AVE
Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 017573403FLE
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 017573403FLE
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 017573403FLE
Transporter Line Number: 1
Transporter EPA ID: NJR986628162
Transporter Name: Iwt Transport, Inc.

Waste Line:
Manifest Tracking Number: 017573403FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3077
U.S. DOT Description: Na3077, Waste Other Regulated Substances, Solid N.O.S, 9, Pg Iii, Rq (Contains Lead Compounds)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 50
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.025
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.025
Waste Quantity, in Kilograms: 22.67575
Acute Waste Quantity, in Kilograms: 0

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Non-Acute Waste Quantity, in Kilorgrams:	22.67575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

RI MANIFEST:

Name:	NEW YORK CITY TRANSIT CMF BASE
Address:	1700 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
EPA Id:	NYD981140023
GEN Cert Date:	3/8/2007
Manifest Document Number:	000007536UIS
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
TSDF Id:	RID084802842
TSDF Name:	United Oil Recovery Inc
Qty:	982
WT/Vol Units:	G
TSDF Date:	3/12/2007
Transporter 2 Id:	CTD021816889
Item Number:	a
Transporter 2 Name:	Not reported
Transporter Name 2:	UNITED INDUSTRIAL SERVICES
Transporter EPAID:	CTD021816889
Transporter Receipt Date:	3/8/2007
Number Of Containers:	16
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	UNITED INDUSTRIAL SERVICES
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	2/27/2008
Number Of Containers:	6
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000083882UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	350
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/27/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	3/3/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

Transporter Receipt Date:	1/21/2008
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000081094UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	965
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/21/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/21/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/27/2008
Number Of Containers:	6
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000083882UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	350
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/27/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	3/3/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/21/2008
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY-KLEEN SYSTEMS, INC.
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000081094UIS
Quarter:	Not reported
Waste Description:	RQ WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	965
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY-KLEEN SYSTEMS, INC.
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/21/2008
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/21/2008
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	8/23/2007

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000029846UIS
Quarter:	Not reported
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	8/23/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	8/27/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/8/2007
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	UNITED INDUSTRIAL SERVICES
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Manifest Docket Number:	000025116UIS
Quarter:	Not reported
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/8/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/12/2007
Transporter 2 ID:	CTD021816889
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/13/2007
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000079040UIS
Quarter:	Not reported
Waste Description:	PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	SAFETY-KLEEN SYSTEMS INC
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/13/2007

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	12/17/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	9/20/2007
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000060275UIS
Quarter:	Not reported
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	9/20/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	9/25/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/8/2007
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	UNITED INDUSTRIAL SERVICES
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000025116UIS
Quarter:	Not reported
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/8/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/12/2007
Transporter 2 ID:	CTD021816889
Manifest Updated Date:	Not reported
Transporter Receipt Date:	10/18/2007
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000051170UIS
Quarter:	Not reported
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/18/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	10/23/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	10/18/2007
Number Of Containers:	13
Container Type:	DM
Waste Code1:	R003
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	United Oil Recovery Inc
TSDF Id:	RID084802842
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981140023
Manifest Docket Number:	000051170UIS
Quarter:	Not reported
Waste Description:	WASTE PETROLEUM DISTILLATES NOS
Transporter Contact Name:	Not reported
Quantity:	982
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	a
Transporter Name:	UNITED INDUSTRIAL SERVICES
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/18/2007
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	10/23/2007
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Click this hyperlink while viewing on your computer to access
8 additional RI_MANIFEST: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYD981140023
Country:	USA
Name:	Nycta - East New York Barn & Yard
Address:	1700 BUSHWICK AVENUE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	1700 BUSHWICK AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta - East New York Barn & Yard
Mailing Contact:	N/S
Mailing Address 1:	370 JAY ST RM 809
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188524134

Manifest Data:

Document ID:	NJA0453611
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWAS300
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	881111
Trans1 Recv Date:	881111
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	881111
Part A Recv Date:	881125
Part B Recv Date:	881121
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Waste Code 7:	X721
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NJA0231724
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWAS300
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	860903
Trans1 Recv Date:	860903
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860903
Part A Recv Date:	860909
Part B Recv Date:	860909
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100
Document ID:	NJA2786578
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	04/02/1998
Trans1 Recv Date:	04/02/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/02/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00220
Units:	Gallons (liquids only)

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Number of Containers: 004
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NJA2565378
Manifest Status: Not reported
Trans1 State ID: NJDEPES58
Year: 1996
Trans2 State ID: Not reported
Generator Ship Date: 06/26/1996
Trans1 Recv Date: 06/26/1996
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/26/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981140023
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00085
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NJA4118310
Manifest Status: Not reported
Trans1 State ID: H10376
Year: 2003
Trans2 State ID: H10376
Generator Ship Date: 06/12/2003
Trans1 Recv Date: 06/12/2003
Trans2 Recv Date: 06/12/2003
TSD Site Recv Date: 06/16/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	NJD003812047
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00025
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NJA0157712
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NJSWAS300
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	860717
Trans1 Recv Date:	860717
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860717
Part A Recv Date:	860728
Part B Recv Date:	860829
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2010
Trans1 Recv Date:	04/15/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	002316600SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code a:	Tetrachloroethylene
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	4

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	1
Document ID:	NJA1241135
Manifest Status:	Not reported
Trans1 State ID:	NJDEPS581
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	10/08/1991
Trans1 Recv Date:	10/08/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Corrosive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00715
Units:	Gallons (liquids only)
Number of Containers:	013
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	CTF0901962

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Manifest Status:	Not reported
Trans1 State ID:	AE384L
Year:	2000
Trans2 State ID:	AB379S
Generator Ship Date:	07/19/2000
Trans1 Recv Date:	07/19/2000
Trans2 Recv Date:	07/27/2000
TSD Site Recv Date:	07/27/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	NJD003812047
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA0571137
Manifest Status:	C - Completed copy
Trans1 State ID:	NJSWAS300
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890419
Trans1 Recv Date:	890419
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890419
Part A Recv Date:	890425
Part B Recv Date:	890427
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100

Document ID:	NJA0293863
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NJSWAS300
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870821
Trans1 Recv Date:	870821
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870821
Part A Recv Date:	871014
Part B Recv Date:	870901
Generator EPA ID:	NYD981140023
Trans1 EPA ID:	NJD991291105
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
52 additional NY MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA ID:	NYD981140023
Name:	EAST NEW YORK BARN & YARD
Address:	1700 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYD981140023
Manifest Number:	009202905JJK
Date Shipped:	5/16/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: Not reported
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 87.00
Unit: gallons

Manifest Year: Not reported
Waste Code: D001
Hand Code: Not reported
Quantity: 14.00
Unit: gallons

EPA ID: NYD981140023
Manifest Number: 009202905JJK
Date Shipped: 5/16/2012
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	87.00
Unit:	gallons

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	14.00
Unit:	gallons

EPA ID:	NYD981140023
Manifest Number:	NJA5077066
Date Shipped:	05/12/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/12/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/12/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05270421
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD981140023
Manifest Number:	001031163JJK
Date Shipped:	05/23/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/23/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/23/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Quantity:	55
Unit:	G
Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	1500
Unit:	G
EPA ID:	NYD981140023
Manifest Number:	009205077JJK
Date Shipped:	5/17/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	19.00
Unit:	gallons

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported
Quantity:	8.00
Unit:	gallons

EPA ID:	NYD981140023
Manifest Number:	009205077JJK
Date Shipped:	5/17/2012
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	Not reported
Quantity:	19.00
Unit:	gallons

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Quantity:	8.00
Unit:	gallons
EPA ID:	NYD981140023
Manifest Number:	001026833JJK
Date Shipped:	12/21/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/21/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/21/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported
EPA ID:	NYD981140023
Manifest Number:	NJA5241540
Date Shipped:	12/08/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/08/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/08/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01240621
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD981140023
Manifest Number:	002316600SKS
Date Shipped:	04/15/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/15/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/19/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

NYCTA (ENY YARD) HAZ (Continued) **1000393172**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H020
Quantity:	100
Unit:	G

S132 **EAST NEW YORK BOILER PLANT** **NY UST U004046611**
NNE **1 JAMAICA AVENUE** **NY AST N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.175 mi.
923 ft. **Site 9 of 11 in cluster S**

Relative:
Higher

Actual:
92 ft.

Client Plot

UST:

Name:	EAST NEW YORK BOILER PLANT
Address:	1 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-609104 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/16/2028
UTM X:	592945.20001
UTM Y:	4503508.04494
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	30950
Affiliation Type:	Facility Operator
Company Name:	EAST NEW YORK BOILER PLANT
Contact Type:	Not reported
Contact Name:	NYC TRANSIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 927-7172
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-09-19

EAST NEW YORK BOILER PLANT (Continued) **U004046611**

Site Id:	30950
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	27TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	EnvironmentalProtectionNYCT@nyct.com
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-10-18

Site Id:	30950
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, ENVIRONMENTAL
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2023-02-16

Site Id:	30950
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	Not reported
Contact Name:	RAIL COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 712-4242
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-10-16

Tank Info:

Tank Number:	HTGOIL1
Tank ID:	66442
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use

EAST NEW YORK BOILER PLANT (Continued) **U004046611**

Capacity Gallons:	20000
Install Date:	10/01/1995
Date Tank Closed:	05/18/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXLIU
Last Modified:	02/16/2023

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H05 - Tank Leak Detection - In-Tank System (ATG)
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	HTGOIL2
Tank ID:	66443
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	20000
Install Date:	10/01/1995
Date Tank Closed:	05/18/2022
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXLIU
Last Modified:	02/16/2023

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H05 - Tank Leak Detection - In-Tank System (ATG)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J02 - Dispenser - Suction Dispenser

EAST NEW YORK BOILER PLANT (Continued) **U004046611**

F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)

AST:

Name:	EAST NEW YORK BOILER PLANT
Address:	1 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609104
Program Type:	PBS
UTM X:	592945.20001
UTM Y:	4503508.04494
Expiration Date:	07/16/2028
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	30950
Affiliation Type:	Facility Operator
Company Name:	EAST NEW YORK BOILER PLANT
Contact Type:	Not reported
Contact Name:	NYC TRANSIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 927-7172
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-09-19

Site Id:	30950
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	27TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	EnvironmentalProtectionNYCT@nyct.com
Fax Number:	Not reported

EAST NEW YORK BOILER PLANT (Continued) **U004046611**

Modified By:	nFormUpd
Date Last Modified:	2024-10-18
Site Id:	30950
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, ENVIRONMENTAL
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2023-02-16
Site Id:	30950
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	Not reported
Contact Name:	RAIL COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 712-4242
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-10-16

Tank Info:

Tank Number:	EGT-1
Tank Id:	244804
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

J00 - Dispenser - None
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I02 - Overfill - High Level Alarm
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

EAST NEW YORK BOILER PLANT (Continued) **U004046611**

	E00 - Piping Secondary Containment - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/05/1989
Capacity Gallons:	300
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXLIU
Last Modified:	06/09/2023
Material Name:	diesel
Tank Number:	EGT-2
Tank Id:	244805
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	J00 - Dispenser - None
	C01 - Pipe Location - Aboveground
	E01 - Piping Secondary Containment - Diking (AG only)
	L00 - Piping Leak Detection - None
	G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
	H00 - Tank Leak Detection - None
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F00 - Pipe External Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/09/2011
Capacity Gallons:	36
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel
Tank Number:	MSW/O-1
Tank Id:	289083

EAST NEW YORK BOILER PLANT (Continued) **U004046611**

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/03/2017
Capacity Gallons:	240
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

S133 **EAST NEW YORK DEPOT** **NY LTANKS** **S100177204**
NNE **25 JAMAICA AVE/NYCTA** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.175 mi.
923 ft. **Site 10 of 11 in cluster S**

Relative: **Higher**
Actual: **92 ft.**
Client Plot

LTANKS:

Name:	EAST NEW YORK DEPOT
Address:	25 JAMAICA AVE/NYCTA
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9102804 / 2000-12-27
Facility ID:	9102804
Site ID:	300659
Spill Date:	1991-06-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	8807411
Reported to Dept:	1991-06-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False

EAST NEW YORK DEPOT (Continued) **S100177204**

Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-06-11
Spill Record Last Update:	2010-12-24
Spiller Name:	Not reported
Spiller Company:	NYCTA
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	243189
Latitude:	40.6775870
Longitude:	-73.8988470
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 11/17/94: REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 11/17/94. transfered from Hale to Tibbe on 12/27/00. refer to 88-07411. tanks closed and replaced and invrstigation/remediation is ongoing.
Remarks:	2-500 GAL MANIFOLDED 0.48 CAP SUPPLY LINE, WILL PUMP OUT TANK

All TTF:

Facility ID:	9102804
Spill Number:	9102804
Spill Tank Test:	1538648
Site ID:	300659
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	300659
Operable Unit ID:	953625
Operable Unit:	01
Material ID:	425291
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

S134 **EAST NEW YORK CMF** **NY AST** **A100293853**
NNE **1730 BUSHWICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.175 mi.
923 ft. **Site 11 of 11 in cluster S**

Relative:
Higher

Actual:
92 ft.

Client Plot

AST:

Name:	EAST NEW YORK CMF
Address:	1730 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609106
Program Type:	PBS
UTM X:	592961.77908
UTM Y:	4503730.95787
Expiration Date:	07/16/2028
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	30952
Affiliation Type:	Facility Operator
Company Name:	EAST NEW YORK CMF
Contact Type:	Not reported
Contact Name:	PETER CASSAR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 566-3880
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2023-05-19

Site Id:	30952
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY TRANSIT AUTHORITY
Contact Type:	DIRECTOR, ENV. PROTECTION & INDUSTRIAL HYGIENE
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2023-05-19

Site Id:	30952
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	DIRECTOR, ENVIRONMENTAL PROTECTION
Contact Name:	DOREEN BOATSWAIN

EAST NEW YORK CMF (Continued) **A100293853**

Address1:	2 BROADWAY
Address2:	27TH FLR.
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2021-09-14

Site Id:	30952
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY TRANSIT
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-11-22

Tank Info:

Tank Number:	W/O-1
Tank Id:	66449
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
G01 - Tank Secondary Containment - Diking (Aboveground)
G12 - Tank Secondary Containment - Double-Walled (AG only)
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

EAST NEW YORK CMF (Continued) **A100293853**

Install Date:	02/01/1999
Capacity Gallons:	500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	W/O-2
Tank Id:	66450
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
G01 - Tank Secondary Containment - Diking (Aboveground)
G12 - Tank Secondary Containment - Double-Walled (AG only)
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/1999
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

N135
NNW
1/8-1/4
0.176 mi.
930 ft.

CON EDISON
BROADWAY & CONWAY STR
BROOKLYN, NY 11245

Site 6 of 8 in cluster N

E MANIFEST **1031628157**
N/A

Relative:
Higher

Actual:
88 ft.

E MANIFEST:

Manifest Tracking Number:	023096274JJK
Last Updated Date:	20211220
Shipped Date:	20211206
Received Date:	20211206
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	BROADWAY & CONWAY STR
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11245
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 BUTLER STREET
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	023096274JJK
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	023096274JJK
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T

CON EDISON (Continued) **1031628157**

State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 023096274JJK
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 023096274JJK
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 1000
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.5
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.5
- Waste Quantity, in Kilograms: 453.515
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 453.515
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

O136 **LOT 18,TAXBLOCK 1553** **NY E DESIGNATION** **S118704148**
WNW **2246 FULTON STREET** **NY NYC OER** **N/A**
1/8-1/4 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.178 mi.
939 ft. **Site 2 of 2 in cluster O**

Relative: **Higher**
Actual: **86 ft.**

E DESIGNATION:
- Name: LOT 18,TAXBLOCK 1553
- Address: 2246 FULTON STREET
- City,State,Zip: BROOKLYN, NY 11233
- Tax Lot(s): 18
- Tax Block: 1553

LOT 18,TAXBLOCK 1553 (Continued) **S118704148**

Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	2246 FULTON STREET
Address:	2246 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678061
Longitude:	-73.906988
OER Project Numbers:	22TMP0391K,22EHAN084K
BBL:	3015530018
OER Program:	E/RD (Review)
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	367
BIN:	3042287
NTA:	Ocean Hill

NYC LAND USE:

Name:	Not reported
Address:	2246 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6777860
Longitude:	-73.9063464
Type Of Ownership Code:	Not reported
Owner Name:	50 SACKMAN LLC
Borough:	BK
Tax Block:	1553
Tax Lot:	18
Community District:	316
Census Tract 2020:	3036700
Census Block 2020:	30367003005
Census Tract 2010:	367
Census Block 2010:	1004
School District:	23
City Council District:	37
Fire Company:	L176
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3

LOT 18,TAXBLOCK 1553 (Continued) **S118704148**

Sanitation District Number:	16
Sanitation Subsection:	2B
Zoning District 1:	M1-4/R7D: Mixed Manufacturing & Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	MX-16
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Y
Building Class:	F5: Factory And Industrial Buildings - Light Manufacturing
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	15000
Total Building Floor Area:	15000
Commercial Floor Area:	15000
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	15000
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	150.0000000
Lot Depth:	100.0000000
Building Frontage:	150.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	202500.00000
Assessed Total Value:	627750.00000
Exempt Total Value:	0.00000
Year Built:	1921
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.00000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015530018.00000000
Condominium Number:	Not reported
Census Tract 2:	0367
X Coordinate:	1010227

LOT 18,TAXBLOCK 1553 (Continued) **S118704148**

Y Coordinate:	186226
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 011
Tax Map #:	30603
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

T137 **20-50 POWELL STREET LLC** **NY AST** **A100414553**
SW **20-50 POWELL STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.180 mi.
951 ft. **Site 1 of 2 in cluster T**

Relative: **Lower**

Actual: **62 ft.**

AST:

Name:	20-50 POWELL STREET LLC
Address:	20-50 POWELL STREET
City,State,Zip:	BROOKLYN, NY 11212
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612527
Program Type:	PBS
UTM X:	592528.94507
UTM Y:	4503170.43843
Expiration Date:	01/04/2026
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	522599
Affiliation Type:	Mail Contact
Company Name:	20-50 POWELL STREET LLC
Contact Type:	Not reported
Contact Name:	MARK STEGMAN / PAT SGAMBATI
Address1:	97-14 ATLANTIC AVENUE
Address2:	Not reported
City:	OZONE PARK
State:	NY
Zip Code:	11416
Country Code:	001
Phone:	(718) 738-7373
EMail:	PSGAMBATI@LOGANBUS.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-04-02

Site Id:	522599
Affiliation Type:	Facility Owner
Company Name:	20-50 POWELL STREET LLC
Contact Type:	PRESIDENT
Contact Name:	LORINDA LOGAN
Address1:	97-14 ATLANTIC AVENUE

20-50 POWELL STREET LLC (Continued) **A100414553**

Address2:	Not reported
City:	OZONE PARK
State:	NY
Zip Code:	11416
Country Code:	001
Phone:	(718) 738-7373
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-02-11

Site Id:	522599
Affiliation Type:	Facility Operator
Company Name:	20-50 POWELL STREET LLC
Contact Type:	Not reported
Contact Name:	MARK STEGMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 475-7550
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-04-02

Site Id:	522599
Affiliation Type:	Emergency Contact
Company Name:	20-50 POWELL STREET LLC
Contact Type:	Not reported
Contact Name:	JOHN PISCIOTTA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 477-0352
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-02-25

Tank Info:

Tank Number:	01
Tank Id:	260541

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
G10 - Tank Secondary Containment - Impervious Underlayment
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)

20-50 POWELL STREET LLC (Continued) **A100414553**

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Galvanized Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/04/2016
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

N138 **SOLID GOLD TOWING INC.** **NY UST** **U002259356**
NNW **1960 BROADWAY** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.182 mi.
961 ft. **Site 7 of 8 in cluster N**

Relative: **Higher**
Actual: **88 ft.**

UST:

Name:	SOLID GOLD TOWING INC.
Address:	1960 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-482099 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592579.45137
UTM Y:	4503698.80840
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	21587
Affiliation Type:	Facility Owner
Company Name:	FRANK PETROSINO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2744 DEVON COURT
Address2:	Not reported
City:	DELRAY BEACH
State:	FL
Zip Code:	33445
Country Code:	001
Phone:	(561) 498-7835
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR

SOLID GOLD TOWING INC. (Continued) **U002259356**

Date Last Modified: 2009-07-09

Site Id: 21587
Affiliation Type: Mail Contact
Company Name: FRANK PETROSINO
Contact Type: Not reported
Contact Name: Not reported
Address1: 2744 DEVON COURT
Address2: Not reported
City: DELRAY BEACH
State: FL
Zip Code: 33445
Country Code: 001
Phone: (561) 498-7835
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-07-09

Site Id: 21587
Affiliation Type: Facility Operator
Company Name: SOLID GOLD TOWING INC.
Contact Type: Not reported
Contact Name: FLOYD BERMUDEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (718) 257-1556
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-05-21

Site Id: 21587
Affiliation Type: Emergency Contact
Company Name: SOLID GOLD TOWING INC.
Contact Type: Not reported
Contact Name: DANIEL DANNER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 763-4791
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-05-21

Tank Info:

Tank Number: 001
Tank ID: 39245

SOLID GOLD TOWING INC. (Continued) **U002259356**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3000
Install Date: 04/23/1994
Date Tank Closed: 12/07/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 09/01/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well

Tank Number: 002
Tank ID: 39246
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: 12/07/2011
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 09/01/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

SOLID GOLD TOWING INC. (Continued) **U002259356**

SPILLS:

Name:	TOWING COMPANY
Address:	1960 BROADWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1008292 / 2011-01-05
Facility ID:	1008292
Facility Type:	ER
DER Facility ID:	396791
Site ID:	441770
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2010-11-08
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2010-11-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-08
Spill Record Last Update:	2011-01-05
Spiller Name:	Not reported
Spiller Company:	SOLID GOLD TOWING
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JESSICA REALMUTO
Latitude:	40.6792300
Longitude:	-73.9042140
DEC Memo:	11/08/10- Zhune spoke to Jessica Realmuto 631-360-8901 from Windmill oil Tank Service. She said They are in the process to abandoned two UST 3000-gallons. They found contamination. She will ask someone to call back for more details. Lee- Windmill- 516- 330 -8170
Remarks:	company moving tank and noticed spill - cleanup pending

All Materials:

Site ID:	441770
Operable Unit ID:	1192314
Operable Unit:	01
Material ID:	2187596
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

N139 **SOLID GOLD TOWING INC.** **UST FINDER** **1028571379**
NNW **1960 BROADWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.182 mi.
961 ft. **Site 8 of 8 in cluster N**

Relative:
Higher

Actual:
88 ft.

UST FINDER:

Object ID:	295991
Facility ID:	NY21587
Name:	SOLID GOLD TOWING INC.
Address:	1960 BROADWAY
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	5773
Private Wells 1500ft:	3
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.904502
Y Coord:	40.6789810000001
Latitude:	40.678981
Longitude:	-73.904502

UST FINDER:

Object ID:	1216239
Facility ID:	NY21587
Tank ID:	NY28350
Tank Status:	Closed
Installation Date:	1994/04/23 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1216240
Facility ID:	NY21587
Tank ID:	NY29110
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

R140 **CON EDISON** **NY MANIFEST** **S117739760**
ESE **2569 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.186 mi.
982 ft. **Site 8 of 18 in cluster R**

Relative:
Lower

Actual:
60 ft.

NY MANIFEST:

EPA ID:	NYP004728978
Country:	USA
Name:	Con Edison
Address:	2569 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	2569 ATLANTIC AV
Location Address 2:	SB18037
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/09/2015
Trans1 Recv Date:	02/09/2015
Trans2 Recv Date:	02/13/2015
TSD Site Recv Date:	02/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004728978
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620946GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117739760**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

R141 **CON EDISON** **NJ MANIFEST** **S120667032**
ESE **2569 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.186 mi.
982 ft. **Site 9 of 18 in cluster R**

Relative: **Lower**

Actual: **60 ft.**

NJ MANIFEST:

EPA ID:	NYP004728978
Name:	CON EDISON
Address:	2569 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004728978
Manifest Number:	002620946GBF
Date Shipped:	2/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120667032**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

R142 **CON EDISON** **RCRA NonGen / NLR** **1018278142**
ESE **2569 ATLANTIC AVE** **FINDS** **NYP004728978**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.186 mi.
982 ft. **Site 10 of 18 in cluster R**

Relative: **Lower**
Actual: **60 ft.**

RCRA Listings:

Date Form Received by Agency:	20150209
Handler Name:	Con Edison
Handler Address:	Atlantic Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004728978
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON (Continued) **1018278142**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160502
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		20150209
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator

CON EDISON (Continued) **1018278142**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150209
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067700401

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278142
Registry ID: 110067700401

DFR URL:
Name: CON EDISON
Address: 2569 ATLANTIC AVE

CON EDISON (Continued) **1018278142**

City,State,Zip: BROOKLYN, NY 11207

P143 **CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031619674**
West **2361 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.187 mi.
987 ft. **Site 3 of 6 in cluster P**

Relative:
Higher

Actual:
77 ft.

E MANIFEST:

Manifest Tracking Number:	006872452GBF
Last Updated Date:	20220104
Shipped Date:	20211216
Received Date:	20211222
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2361 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	006872452GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	006872452GBF

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619674**

Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 006872452GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006872452GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

P144 **CON EDISON MANHOLE: 55769** **RCRA NonGen / NLR** **1017775165**
WSW **2356 ATLANTIC AVE** **FINDS** **NYP004529905**
1/8-1/4 **BROOKLYN, NY 11233**
0.194 mi.
1023 ft. **Site 4 of 6 in cluster P**

Relative:
Higher

Actual:
74 ft.

RCRA Listings:

Date Form Received by Agency:		20140613
Handler Name:		Con Edison Manhole: 55769
Handler Address:		Atlantic Ave
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004529905
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON MANHOLE: 55769 (Continued) **1017775165**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140513
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140513
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140613
Handler Name: CON EDISON MANHOLE: 55769	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON MANHOLE: 55769 (Continued) **1017775165**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063762290

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P145 **CON EDISON** **NY MANIFEST** **S117736546**
WSW **2356 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.194 mi.
1023 ft. **Site 5 of 6 in cluster P**

Relative:
Higher

Actual:
74 ft.

NY MANIFEST:

EPA ID:	NYP004529905
Country:	USA
Name:	Con Edison
Address:	2356 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	2356 ATLANTIC AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117736546**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/2014
Trans1 Recv Date:	05/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004529905
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002417995GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	300
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

U146 **CON EDISON** **RCRA NonGen / NLR** **1018279069**
SSE **LIBERTY AVE & SNEIDIKER** **FINDS** **NYP004738654**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.196 mi.
1033 ft. **Site 1 of 10 in cluster U**

Relative: **Lower**
Actual: **57 ft.**

RCRA Listings:

Date Form Received by Agency:		20150225
Handler Name:		Con Edison
Handler Address:		Liberty Ave & Sneidiker
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004738654
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON (Continued) **1018279069**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150225
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150225
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 5070
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny

CON EDISON (Continued) **1018279069**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150225
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	Electric Power Distribution

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110067685650

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and

CON EDISON (Continued) **1018279069**

Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279069
Registry ID:	110067685650

DFR URL:

Name:	CON EDISON
Address:	LIBERTY AVE & SNEIDIKER
City,State,Zip:	BROOKLYN, NY 11207

U147 **CON EDISON** **NJ MANIFEST** **S120667911**
SSE **LIBERTY & SNEIDIKER** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.196 mi.
1033 ft. **Site 2 of 10 in cluster U**

Relative:
Lower

Actual:
57 ft.

NJ MANIFEST:

EPA ID:	NYP004738654
Name:	CON EDISON
Address:	LIBERTY AVE & SNEIDIKER
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004738654
Manifest Number:	002621242GBF
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

CON EDISON (Continued) **S120667911**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

U148 **CON EDISON** **RCRA NonGen / NLR** **1014397187**
SSE **SNEDIKER AVE & LIBERTY AVE** **NJ MANIFEST** **NYP004195053**
1/8-1/4 **BROOKLYN, NY 11207** **NY MANIFEST**
0.196 mi.
1033 ft. **Site 3 of 10 in cluster U**

Relative: **Lower**

Actual: **57 ft.**

RCRA Listings:

Date Form Received by Agency:	20160601
Handler Name:	Con Edison
Handler Address:	Snediker Ave & Liberty Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004195053
Contact Name:	CAROLINE ISKANDER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CON EDISON (Continued) **1014397187**

Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160616
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		20090918
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:		Ny

CON EDISON (Continued) **1014397187**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA ID:	NYP004195053
Name:	CON EDISON
Address:	SNEDIKER AVE & LIBERTY AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:
EPA ID: NYP004195053

CON EDISON (Continued) **1014397187**

Manifest Number:	000893800GBF
Date Shipped:	10/05/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/05/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/07/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	200
Unit:	G

NY MANIFEST:

EPA ID:	NYP004195053
Country:	USA
Name:	Consolidated Edison
Address:	SNEDIKER AVE & LIBERTY AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported

CON EDISON (Continued) **1014397187**

Location Address 1: SNEDIKER AVE & LIBERTY AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/05/2009
Trans1 Recv Date: 10/05/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/07/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004195053
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000893800GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

CON EDISON (Continued) **1014397187**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

U149 **CON EDISON** **NY MANIFEST** **S117740686**
SSE **LIBERTY AVE & SNEIDIKER** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.196 mi.
1033 ft. **Site 4 of 10 in cluster U**

Relative:
Lower

Actual:
57 ft.

NY MANIFEST:

EPA ID:	NYP004738654
Country:	USA
Name:	Con Edison
Address:	LIBERTY AVE & SNEIDIKER
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	LIBERTY & SNEIDIKER
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2015
Trans1 Recv Date:	02/25/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105

CON EDISON (Continued) **S117740686**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002621242GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	5000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

U150 **CON EDISON** **RCRA NonGen / NLR** **1014397147**
SSE **SNEDIKER AVE & LIBERTY AVE** **NJ MANIFEST** **NYP004194650**
1/8-1/4 **BROOKLYN, NY 11207** **NY MANIFEST**
0.196 mi.
1033 ft. **Site 5 of 10 in cluster U**

Relative: **Lower**

Actual: **57 ft.**

RCRA Listings:

Date Form Received by Agency:	20160601
Handler Name:	Con Edison
Handler Address:	Snediker Ave & Liberty Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004194650
Contact Name:	CAROLINE ISKANDER
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CON EDISON (Continued) **1014397147**

Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160616
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		20090917
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:		Ny

CON EDISON (Continued) **1014397147**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA ID:	NYP004194650
Name:	CON EDISON
Address:	SNEDIKER AVE & LIBERTY AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:
EPA ID: NYP004194650

CON EDISON (Continued) **1014397147**

Manifest Number:	000893802GBF
Date Shipped:	10/05/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/05/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/07/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	200
Unit:	G

NY MANIFEST:

EPA ID:	NYP004194650
Country:	USA
Name:	Consolidated Edison
Address:	SNEDIKER AVE & LIBERTY AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported

CON EDISON (Continued) **1014397147**

Location Address 1: SNEDIKER AVE & LIBERTY AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Consolidated Edison
Mailing Contact: Franklyn Murray
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/05/2009
Trans1 Recv Date: 10/05/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/07/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004194650
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 000893802GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

CON EDISON (Continued) **1014397147**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Q151 **CON EDISON/ ATTN: BROOKLYN/QUEENS ENVIRONMENTAL OP** **E MANIFEST** **1031620560**
WSW **2363 PACIFIC STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.196 mi.
1036 ft. **Site 3 of 4 in cluster Q**

Relative: **Higher**

Actual: **70 ft.**

E MANIFEST:

Manifest Tracking Number:	024100766JJK
Last Updated Date:	20230411
Shipped Date:	20230330
Received Date:	20230330
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn/Queens Environmental Ops C/O Acv Enviro
Generator Location Street Number:	Not reported
Generator Location Street 1:	2363 PACIFIC STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

CON EDISON/ ATTN: BROOKLYN/QUEENS ENVIRONMENTAL OPS C/O ACV (Continued) **1031620560**

Federal Waste:
- Manifest Tracking Number: 024100766JJK
- Waste Line Number: 1
- Federal Waste Code: D008
- Federal Waste: LEAD

State Waste:
- Manifest Tracking Number: 024100766JJK
- Waste Line Number: 1
- State Waste Code Owner: NY
- State Waste Code: T
- State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 024100766JJK
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 024100766JJK
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S. (Lead), 9, Pg Iii, Rq
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 500
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.25
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.25
- Waste Quantity, in Kilograms: 226.7575
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 226.7575
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

V152 **CON EDISON - SERVICE BOX 53135** **NY LEAD** **S120958016**
SE **92 WILLIAMS AVE** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.197 mi.
1040 ft. **Site 1 of 5 in cluster V**

Relative: **Lower**
Actual: **56 ft.**

NYC LEAD:

Name:	Not reported
Address:	92 WILLIAMS AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	12333122
Building ID:	395984
Registration ID:	323042
Apartment:	3
Story:	3
Class:	Most Serious
Inspection Date:	04/04/2018
Approved Date:	04/12/2018
Original Certify By Date:	05/15/2018
Original Correct By Date:	05/10/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6063554
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st RADIATOR FROM NORTH AT EAST WALL, SOUTH WALL, WEST WALL IN THE 1st ROOM FROM EAST AT NORTH LOCATED AT APT 3, 3rd STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	04/12/2018
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	07/07/2020

Name:	Not reported
Address:	92 WILLIAMS AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	12333123
Building ID:	395984
Registration ID:	323042
Apartment:	3
Story:	3
Class:	Most Serious
Inspection Date:	04/04/2018
Approved Date:	04/12/2018
Original Certify By Date:	05/15/2018
Original Correct By Date:	05/10/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6063554
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st CLOSET FROM NORTH AT EAST WALL DOOR, 1st RADIATOR FROM SOUTH AT WEST WALL, WEST WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 2nd ROOM FROM

CON EDISON - SERVICE BOX 53135 (Continued) **S120958016**

	EAST AT NORTH LOCATED AT APT 3, 3rd STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	04/12/2018
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	07/07/2020
Name:	Not reported
Address:	92 WILLIAMS AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	12333124
Building ID:	395984
Registration ID:	323042
Apartment:	3
Story:	3
Class:	Most Serious
Inspection Date:	04/04/2018
Approved Date:	04/12/2018
Original Certify By Date:	05/15/2018
Original Correct By Date:	05/10/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6063554
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st RADIATOR FROM EAST AT SOUTH WALL IN THE KITCHEN LOCATED AT APT 3, 3rd STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	04/12/2018
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	07/07/2020
Name:	Not reported
Address:	92 WILLIAMS AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	12333125
Building ID:	395984
Registration ID:	323042
Apartment:	3
Story:	3
Class:	Most Serious
Inspection Date:	04/04/2018
Approved Date:	04/12/2018
Original Certify By Date:	05/15/2018
Original Correct By Date:	05/10/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6063554
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE BATHROOM LOCATED AT APT 3, 3rd STORY,

CON EDISON - SERVICE BOX 53135 (Continued) **S120958016**

	1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	04/12/2018
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	07/07/2020
Name:	Not reported
Address:	92 WILLIAMS AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	12333126
Building ID:	395984
Registration ID:	323042
Apartment:	3
Story:	3
Class:	Most Serious
Inspection Date:	04/04/2018
Approved Date:	04/12/2018
Original Certify By Date:	05/15/2018
Original Correct By Date:	05/10/2018
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	6063554
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM WEST AT NORTH WALL, 1st WINDOW FRAME FROM SOUTH AT WEST WALL IN THE 4th ROOM FROM EAST AT SOUTH LOCATED AT APT 3, 3rd STORY, 1st APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	04/12/2018
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	07/07/2020

NY MANIFEST:

EPA ID:	NYP004903884
Country:	USA
Name:	Con Edison - Service Box 53135
Address:	92 WILLIAMS AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	92 WILLIAMS AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison - Service Box 53135
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON - SERVICE BOX 53135 (Continued) **S120958016**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	92 WILLIAMS AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6741333
Longitude:	-73.9005546
Type Of Ownership Code:	Not reported
Owner Name:	MELONIK, JOHN
Borough:	BK
Tax Block:	3682
Tax Lot:	52
Community District:	305
Census Tract 2020:	3114400
Census Block 2020:	31144001005
Census Tract 2010:	1144
Census Block 2010:	1002
School District:	19
City Council District:	37
Fire Company:	L120
Police Precinct:	75
Health Center District:	33
Health Area:	5700
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	M1-4: Manufacturing Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C0: Walk Up Apartments - Three Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	1600
Total Building Floor Area:	3282
Commercial Floor Area:	0
Residential Floor Area:	3282
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000

CON EDISON - SERVICE BOX 53135 (Continued) **S120958016**

Residential Units:	3
Total Units:	3
Lot Frontage:	20.0000000
Lot Depth:	80.0000000
Building Frontage:	20.0000000
Building Depth:	52.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	19500.00000
Assessed Total Value:	63600.00000
Exempt Total Value:	0.00000
Year Built:	1901
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.05000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036820052.00000000
Condominium Number:	Not reported
Census Tract 2:	1144
X Coordinate:	1011835
Y Coordinate:	184897
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 009
Tax Map #:	31205
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

V153 **CONSOLIDATED EDISON-BROOKLYN/QUEENS** **E MANIFEST** **1031636795**
SE **92 WILLIAMS AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.197 mi.
1040 ft. **Site 2 of 5 in cluster V**

Relative: **Lower**
Actual: **56 ft.**

E MANIFEST:

Manifest Tracking Number:	012169190FLE
Last Updated Date:	20181113
Shipped Date:	20181019
Received Date:	20181102
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Consolidated Edison-Brooklyn/Queens

CONSOLIDATED EDISON-BROOKLYN/QUEENS (Continued) **1031636795**

Generator Location Street Number:	Not reported
Generator Location Street 1:	92 WILLIAMS AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	42-19 19th Avenue
Generator Mail Street 2:	Not reported
Generator Mail City:	ASTORIA
Generator Mail Zip:	11105
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	012169190FLE
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

Transporter:

Manifest Tracking Number:	012169190FLE
Transporter Line Number:	1
Transporter EPA ID:	MAC300016672
Transporter Name:	Triumvirate Environmental

Waste Line:

Manifest Tracking Number:	012169190FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082 Hazardous Waste, Liquid, N.O.S. (Lead) Iii 9 D008
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	100
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds

CONSOLIDATED EDISON-BROOKLYN/QUEENS (Continued) **1031636795**

Waste Quantity, in Tons:	0.05
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.05
Waste Quantity, in Kilograms:	45.3515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	45.3515
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

R154 **CON EDISON** **RCRA NonGen / NLR** **1019908747**
East **38 GEORGIA AVE** **NYP004876932**
1/8-1/4 **BROOKLYN, NY 11207**
0.197 mi.
1041 ft. **Site 11 of 18 in cluster R**

Relative: **Lower**
Actual: **61 ft.**

RCRA Listings:

Date Form Received by Agency:	20151207
Handler Name:	Con Edison
Handler Address:	Georgia Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004876932
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No

CON EDISON (Continued) **1019908747**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151207
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151207
Handler Name: CON EDISON	

CON EDISON (Continued) **1019908747**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

R155 **CON EDISON** **NJ MANIFEST** **S120677968**
East **38 GEORGIA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.197 mi.
1041 ft. **Site 12 of 18 in cluster R**

Relative: **Lower**

Actual: **61 ft.**

NJ MANIFEST:

EPA ID:	NYP004876932
Name:	CON EDISON
Address:	38 GEORGIA AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004876932
Manifest Number:	002613625GBF
Date Shipped:	12/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120677968**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

W156 **CON EDISON - MANHOLE 21022** **RCRA-LQG** **1014397496**
ENE **1 JAMAICA AVE AND BROADWAY** **NY MANIFEST** **NYP004198198**
1/8-1/4 **BROOKLYN, NY 11207**
0.198 mi.
1044 ft. **Site 1 of 11 in cluster W**

Relative: **Lower**
Actual: **68 ft.**

RCRA Listings:

Date Form Received by Agency:	20100416
Handler Name:	Con Edison - Manhole 21022
Handler Address:	Jamaica Ave And Broadway
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004198198
Contact Name:	THOMAS P TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	TEELINGT@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported

CON EDISON - MANHOLE 21022 (Continued) **1014397496**

Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Co. Of Ny Inc
Owner Type:	Private
Operator Name:	Consolidated Edison Co. Of Ny Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years

Year: 2009

Click Here for Biennial Reporting System Data:

CON EDISON - MANHOLE 21022 (Continued) **1014397496**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO. OF NY INC
Legal Status: Private
Date Became Current: 20091015
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NYC, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON CO. OF NY INC.
Legal Status: Private
Date Became Current: 20091015
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NYC, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100416
Handler Name: CON EDISON - MANHOLE 21022
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON - MANHOLE 21022 (Continued) **1014397496**

NY MANIFEST:

EPA ID:	NYP004198198
Country:	USA
Name:	Consolidated Edison
Address:	1 JAMAICA AVE AND BROADWAY
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	1 JAMAICA AVE AND BROADWAY
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklyn Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	NJD003812047
Generator Ship Date:	10/20/2009
Trans1 Recv Date:	10/20/2009
Trans2 Recv Date:	10/21/2009
TSD Site Recv Date:	10/23/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004198198
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000893752GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported

CON EDISON - MANHOLE 21022 (Continued) **1014397496**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

W157 **EAST NEW YORK BOILER PLANT** **UST FINDER** **1028574537**
ENE **1 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.198 mi.
1044 ft. **Site 2 of 11 in cluster W**

Relative: **Lower**
Actual: **68 ft.**

UST FINDER:

Object ID:	295898
Facility ID:	NY30950
Name:	EAST NEW YORK BOILER PLANT
Address:	1 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	2
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	3007
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.900203
Y Coord:	40.677222
Latitude:	40.677222
Longitude:	-73.900203

EAST NEW YORK BOILER PLANT (Continued) **1028574537**

UST FINDER:

Object ID:	1227084
Facility ID:	NY30950
Tank ID:	NY34842
Tank Status:	Open
Installation Date:	1995/10/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	20000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1227085
Facility ID:	NY30950
Tank ID:	NY37782
Tank Status:	Open
Installation Date:	1995/10/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	20000
Substances:	Not reported
Tank Wall Type:	Not reported

R158 **CON EDISON** **NJ MANIFEST** **S120675138**
East **44 GEORGIA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.200 mi.
1054 ft. **Site 13 of 18 in cluster R**

Relative:
Lower

Actual:
60 ft.

NJ MANIFEST:

EPA ID:	NYP004820326
Name:	CON EDISON
Address:	44 GEORGIA AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004820326
Manifest Number:	014472974JJK
Date Shipped:	8/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120675138**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

R159 **CON EDISON** **NY MANIFEST** **S119077087**
East **44 GEORGIA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.200 mi.
1054 ft. **Site 14 of 18 in cluster R**

Relative: NY MANIFEST:
Lower

Actual: EPA ID: NYP004820326
60 ft. Country: USA
Name: Con Edison
Address: 44 GEORGIA AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: OPP 44 GEORGIA AVE
Location Address 2: SB 26258
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:

CON EDISON (Continued) **S119077087**

Mailing Name: Con Edison
Mailing Contact: Dennis Huacon
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/07/2015
Trans1 Recv Date: 08/07/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/11/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004820326
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014472974JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 1500
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

R160 **CON EDISON** **RCRA NonGen / NLR** **1019906374**
East **44 GEORGIA AVE** **FINDS** **NYP004820326**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.200 mi.
1054 ft. **Site 15 of 18 in cluster R**

Relative: **Lower**

Actual: **60 ft.**

RCRA Listings:

Date Form Received by Agency:		20150807
Handler Name:		Con Edison
Handler Address:		Georgia Ave
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004820326
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON (Continued) **1019906374**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150807
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150807
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019906374**

FINDS:
Registry ID: 110069649278

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906374
Registry ID: 110069649278

DFR URL:
Name: CON EDISON
Address: 44 GEORGIA AVE
City,State,Zip: BROOKLYN, NY 11207

X161 **MILTON UNGER** **NY UST** **U004047600**
WNW **2234 FULTON STREET** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11213**
0.200 mi.
1056 ft. **Site 1 of 10 in cluster X**

Relative:
Higher

Actual:
89 ft.

UST:
Name: MILTON UNGER
Address: 2234 FULTON STREET
City,State,Zip: BROOKLYN, NY 11213
Id/Status: 2-607309 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 592334.94469
UTM Y: 4503590.65882
Site Type: Other

Affiliation Records:
Site Id: 29162
Affiliation Type: Facility Owner
Company Name: MILTON UNGER
Contact Type: Not reported
Contact Name: Not reported
Address1: 779 EAST NEW YORK AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11213
Country Code: 001
Phone: (718) 771-1270
EMail: Not reported
Fax Number: Not reported

MILTON UNGER (Continued) **U004047600**

Modified By: NRLOMBAR
Date Last Modified: 2009-11-12

Site Id: 29162
Affiliation Type: Mail Contact
Company Name: BAY REFRIGARATION
Contact Type: Not reported
Contact Name: MILTON UNGER
Address1: 779 EAST NEW YORK AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11213
Country Code: 001
Phone: (718) 771-1270
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 29162
Affiliation Type: Facility Operator
Company Name: MILTON UNGER
Contact Type: Not reported
Contact Name: MILTON UNGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 771-1270
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 29162
Affiliation Type: Emergency Contact
Company Name: MILTON UNGER
Contact Type: Not reported
Contact Name: ABE KLEIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 553-8363
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 01

MILTON UNGER (Continued) **U004047600**

Tank ID:	62718
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	12/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

AST:

Name:	MILTON UNGER
Address:	2234 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11213
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-607309
Program Type:	PBS
UTM X:	592334.94469
UTM Y:	4503590.65882
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	29162
Affiliation Type:	Facility Owner
Company Name:	MILTON UNGER
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	779 EAST NEW YORK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11213
Country Code:	001
Phone:	(718) 771-1270
EMail:	Not reported

MILTON UNGER (Continued) **U004047600**

Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-11-12

Site Id:	29162
Affiliation Type:	Mail Contact
Company Name:	BAY REFRIGARATION
Contact Type:	Not reported
Contact Name:	MILTON UNGER
Address1:	779 EAST NEW YORK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11213
Country Code:	001
Phone:	(718) 771-1270
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29162
Affiliation Type:	Facility Operator
Company Name:	MILTON UNGER
Contact Type:	Not reported
Contact Name:	MILTON UNGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 771-1270
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29162
Affiliation Type:	Emergency Contact
Company Name:	MILTON UNGER
Contact Type:	Not reported
Contact Name:	ABE KLEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 553-8363
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

MILTON UNGER (Continued) **U004047600**

Tank Number:	02
Tank Id:	62719
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B05 - Tank External Protection - Jacketed

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/2001
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

X162 **MILTON UNGER** **UST FINDER** **1028574090**
WNW **2234 FULTON STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11213**
0.200 mi.
1056 ft. **Site 2 of 10 in cluster X**

Relative: **Higher**

Actual: **89 ft.**

UST FINDER:

Object ID:	295948
Facility ID:	NY29162
Name:	MILTON UNGER
Address:	2234 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11213
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	9739
Private Wells 1500ft:	13
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No

MILTON UNGER (Continued) **1028574090**

WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.907411
Y Coord:	40.678034
Latitude:	40.678034
Longitude:	-73.907411

UST FINDER:

Object ID:	1226068
Facility ID:	NY29162
Tank ID:	NY112233
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

R163 **ACT TEAMS** **E MANIFEST** **1031530624**
ESE **2581 ATLANTIC AVE STE 227** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.201 mi.
1059 ft. **Site 16 of 18 in cluster R**

Relative: **Lower**

Actual: **59 ft.**

E MANIFEST:

Manifest Tracking Number:	200893008CLE
Last Updated Date:	20241211
Shipped Date:	20240806
Received Date:	20240902
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Act Teams
Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE STE 227
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 ATLANTIC AVE STE 227
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys (Pa) Llc
Designated Facility Mail Street Number:	Not reported

ACT TEAMS (Continued) **1031530624**

Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 SANDSTONE DRIVE
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 SANDSTONE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	HATFIELD
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	200893008CLE
Transporter Line Number:	1
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Env Sys (Trans Group), Llc

Waste Line:

Manifest Tracking Number:	200893008CLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3248
U.S. DOT Description:	Un3248, Waste Medicine, Liquid, Flammable, Toxic, N.O.S. (Alcohol, Phenol), 3 (6.1), Pg-Ii,Rq(D009 = 1 Lb)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	2
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	32
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.016
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.016
Waste Quantity, in Kilograms:	14.51248
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	14.51248
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported

ACT TEAMS (Continued) **1031530624**

EPA Waste Indicator: Y

R164 **EAST NEW YORK HEALTH HUB** **E MANIFEST** **1027790056**
ESE **2581 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.201 mi.
1059 ft. **Site 17 of 18 in cluster R**

Relative: E MANIFEST:
Lower

Actual: Manifest Tracking Number: 014429023FLE
59 ft. Last Updated Date: 20200904
Shipped Date: 20200828
Received Date: 20200902
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: CESQG
Generator Name: Act Teams
Generator Location Street Number: Not reported
Generator Location Street 1: 2581 ATLANTIC AVE
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY
Generator Location Zip: 11233
Generator Mail Street Number: Not reported
Generator Mail Street 1: 2581 Atlantic Ave
Generator Mail Street 2: Not reported
Generator Mail City: Brooklyn
Generator Mail Zip: 11233
Generator Mail State: NY
Generator Contact Company Name: Not reported
Designated Facility EPA ID: RID040098352
Designated Facility Name: Northland Environmental, Llc
Designated Facility Mail Street Number: Not reported
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: 275 Allens Avenue
Designated Facility Mail City: Providence
Designated Facility Mail Zip: 02905
Designated Facility Mail State: RI
Designated Facility Location Street Number: Not reported
Designated Facility Location Street 1: 275 Allens Avenue
Designated Facility Location Street 2: Not reported
Designated Facility Location City: Providence
Designated Facility Location Zip: 02905
Designated Facility Location State: RI
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Manifest Tracking Number: 200260881CLE
Last Updated Date: 20221014
Shipped Date: 20220926
Received Date: 20221004
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: CESQG
Generator Name: Act Teams

EAST NEW YORK HEALTH HUB (Continued) **1027790056**

Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 Atlantic Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	RID040098352
Designated Facility Name:	Northland Environmental, Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	275 Allens Avenue
Designated Facility Mail City:	Providence
Designated Facility Mail Zip:	02905
Designated Facility Mail State:	RI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	275 Allens Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Providence
Designated Facility Location Zip:	02905
Designated Facility Location State:	RI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	014952339FLE
Last Updated Date:	20210817
Shipped Date:	20210802
Received Date:	20210810
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Act Teams
Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 Atlantic Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	RID040098352
Designated Facility Name:	Northland Environmental, Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported

EAST NEW YORK HEALTH HUB (Continued) **1027790056**

Designated Facility Mail Street 2:	275 Allens Avenue
Designated Facility Mail City:	Providence
Designated Facility Mail Zip:	02905
Designated Facility Mail State:	RI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	275 Allens Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Providence
Designated Facility Location Zip:	02905
Designated Facility Location State:	RI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	014955194FLE
Last Updated Date:	20201109
Shipped Date:	20201028
Received Date:	20201104
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	East New York Health Hub
Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 Atlantic Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	RID040098352
Designated Facility Name:	Northland Environmental, Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	275 Allens Avenue
Designated Facility Mail City:	Providence
Designated Facility Mail Zip:	02905
Designated Facility Mail State:	RI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	275 Allens Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Providence
Designated Facility Location Zip:	02905
Designated Facility Location State:	RI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013398031FLE
Last Updated Date:	20200106
Shipped Date:	20191106

EAST NEW YORK HEALTH HUB (Continued) **1027790056**

Received Date:	20191119
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Act Teams
Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 Atlantic Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015993549FLE
Last Updated Date:	20211007
Shipped Date:	20210917
Received Date:	20210928
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Act Teams
Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 Atlantic Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11233

EAST NEW YORK HEALTH HUB (Continued) **1027790056**

Generator Mail State: NY
Generator Contact Company Name: Not reported
Designated Facility EPA ID: RID040098352
Designated Facility Name: Northland Environmental, Llc
Designated Facility Mail Street Number: Not reported
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: 275 Allens Avenue
Designated Facility Mail City: Providence
Designated Facility Mail Zip: 02905
Designated Facility Mail State: RI
Designated Facility Location Street Number: Not reported
Designated Facility Location Street 1: 275 Allens Avenue
Designated Facility Location Street 2: Not reported
Designated Facility Location City: Providence
Designated Facility Location Zip: 02905
Designated Facility Location State: RI
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
Federal Waste Code: D001
Federal Waste: IGNITABLE WASTE

Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
Federal Waste Code: D005
Federal Waste: BARIUM

Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
Federal Waste Code: D007
Federal Waste: CHROMIUM

Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
Federal Waste Code: D022
Federal Waste: CHLOROFORM

Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
Federal Waste Code: D024
Federal Waste: M-CRESOL

State Waste:
Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: B
State Waste: Incineration, heat recovery, burning. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 015993549FLE

EAST NEW YORK HEALTH HUB (Continued) **1027790056**

Transporter Line Number: 1
Transporter EPA ID: PAD982661381
Transporter Name: Republic Environmental Systems

Waste Line:
Manifest Tracking Number: 015993549FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3248
U.S. DOT Description: Un3248, Waste Medicine, Liquid, Flammable, Toxic, N.O.S. (Alcohol, Phenol), 3 (6.1), Pg Ii, (Ltd Qty), Erg#131
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 18
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.009
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.009
Waste Quantity, in Kilograms: 8.16327
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 8.16327
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

R165 **ACT TEAMS** **E MANIFEST** **1031530625**
ESE **2581 ATLANTIC AVE, STE 227** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.201 mi.
1059 ft. **Site 18 of 18 in cluster R**

Relative: **Lower**

Actual: **59 ft.**

E MANIFEST:
Manifest Tracking Number: 200594043CLE
Last Updated Date: 20231030
Shipped Date: 20231006
Received Date: 20231017
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: CESQG
Generator Name: Act Teams

ACT TEAMS (Continued) **1031530625**

Generator Location Street Number:	Not reported
Generator Location Street 1:	2581 ATLANTIC AVE, STE 227
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2581 Atlantic Ave, Ste 227
Generator Mail Street 2:	Not reported
Generator Mail City:	Brooklyn
Generator Mail Zip:	11233
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	RID040098352
Designated Facility Name:	Northland Environmental, Llc
Designated Facility Mail Street Number:	275
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	Allens Avenue
Designated Facility Mail City:	Providence
Designated Facility Mail Zip:	02905
Designated Facility Mail State:	RI
Designated Facility Location Street Number:	275
Designated Facility Location Street 1:	Allens Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Providence
Designated Facility Location Zip:	02905
Designated Facility Location State:	RI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	200594043CLE
Transporter Line Number:	1
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Environmental Systems

Waste Line:

Manifest Tracking Number:	200594043CLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3248
U.S. DOT Description:	Un3248, Waste Medicine, Liquid, Flammable, Toxic, N.O.S. (Alcohol, Phenol), 3 (6.1), Pg Ii, (Ltd Qty), Erg#131
Non-Hazardous Waste Description:	Not reported
Number of Containers:	4
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	46
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.023
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.023
Waste Quantity, in Kilograms:	20.86169
Acute Waste Quantity, in Kilograms:	0

ACT TEAMS (Continued) **1031530625**

Non-Acute Waste Quantity, in Kilorgrams:	20.86169
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

P166 **CON EDISON SERVICE BOX: 18018** **RCRA NonGen / NLR** **1016973388**
West **ATLANTIC AVE & SHERLOCK PL** **NY MANIFEST** **NYP004471892**
1/8-1/4 **BROOKLYN, NY 11217**
0.201 mi.
1061 ft. **Site 6 of 6 in cluster P**

Relative: **Higher**

Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20140419
Handler Name:	Con Edison Service Box: 18018
Handler Address:	Atlantic Ave & Sherlock Pl
Handler City,State,Zip:	BROOKLYN, NY 11217
EPA ID:	NYP004471892
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

CON EDISON SERVICE BOX: 18018 (Continued) **1016973388**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140319
Handler Name: CON EDISON SERVICE BOX:	18018
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140419
Handler Name: CON EDISON SERVICE BOX:	18018
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 18018 (Continued) **1016973388**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004471892
Country:	USA
Name:	Con Edison
Address:	ATLANTIC AVE & SHERLOCK PL
Address 2:	NW COR
City,State,Zip:	BROOKLYN, NY 11217
Zip 4:	Not reported
Location Address 1:	N/W/C ATLANTIC AVE & SHERLOCK PL
Location Address 2:	SERVICE BOX # 18018
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2014
Trans1 Recv Date:	03/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON SERVICE BOX: 18018 (Continued) **1016973388**

Generator EPA ID:	NYP004471892
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002359175GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Q167 **CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031619676**
WSW **2372 PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.202 mi.
1069 ft. **Site 4 of 4 in cluster Q**

Relative: E MANIFEST:
Lower

Actual:
68 ft.

Manifest Tracking Number:	007360360GBF
Last Updated Date:	20230531
Shipped Date:	20230505
Received Date:	20230512
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2372 PACIFIC ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619676**

Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	007360360GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007360360GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid N.O.S. (Lead), 9, Pg Iii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	300
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.15
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.15
Waste Quantity, in Kilograms:	136.0545
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	136.0545
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619676**

Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

Y168 **PARK AVENUE BUILDING & ROOFING SUPPLIES** **NY UST** **U004191956**
North **68 CONWAY STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.204 mi.
1079 ft. **Site 1 of 2 in cluster Y**

Relative:
Higher

Actual:
93 ft.

UST:

Name:	PARK AVENUE BUILDING & ROOFING SUPPLIES
Address:	68 CONWAY STREET
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-611887 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592688.73232
UTM Y:	4503804.46638
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	468811
Affiliation Type:	Facility Owner
Company Name:	A.L.B. ENTERPRISES LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	4 OLD WAGON LANE
Address2:	Not reported
City:	OLD WESTBURY
State:	NY
Zip Code:	11568
Country Code:	001
Phone:	(347) 236-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-10-05

Site Id:	468811
Affiliation Type:	Mail Contact
Company Name:	A.L.B. ENTERPRISES LLC
Contact Type:	Not reported
Contact Name:	TIM BEAUMONT
Address1:	4 OLD WAGON LANE
Address2:	Not reported
City:	OLD WESTBURY
State:	NY

PARK AVENUE BUILDING & ROOFING SUPPLIES (Continued) **U004191956**

Zip Code:	11568
Country Code:	001
Phone:	(347) 236-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-10-05

Site Id:	468811
Affiliation Type:	Facility Operator
Company Name:	PARK AVENUE BUILDING & ROOFING SUPPLIES
Contact Type:	Not reported
Contact Name:	TIM BEAUMONT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 236-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-10-05

Site Id:	468811
Affiliation Type:	Emergency Contact
Company Name:	A.L.B. ENTERPRISES LLC
Contact Type:	Not reported
Contact Name:	MIKE ROSATI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(631) 567-6545
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-10-05

Tank Info:

Tank Number:	001
Tank ID:	245556
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/14/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0021
Common Name of Substance:	Transmission Fluid

PARK AVENUE BUILDING & ROOFING SUPPLIES (Continued) **U004191956**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 245557
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/14/2012
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0015
Common Name of Substance: Motor Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 245558
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 09/14/2012
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0015
Common Name of Substance: Motor Oil

PARK AVENUE BUILDING & ROOFING SUPPLIES (Continued) **U004191956**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Y169 **PARK AVENUE BUILDING & ROOFING SUPPLIES** **UST FINDER** **1028590653**
North **68 CONWAY STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.204 mi.
1079 ft. **Site 2 of 2 in cluster Y**

Relative:
Higher

Actual:
93 ft.

UST FINDER:

Object ID:	296035
Facility ID:	NY468811
Name:	PARK AVENUE BUILDING & ROOFING SUPPLIES
Address:	68 CONWAY STREET
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	3
TOS USTs:	0
Population 1500ft:	3706
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.903194
Y Coord:	40.67992
Latitude:	40.67992
Longitude:	-73.903194

UST FINDER:

Object ID:	1284585
Facility ID:	NY468811
Tank ID:	NY102912

PARK AVENUE BUILDING & ROOFING SUPPLIES (Continued) **1028590653**

Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1284586
Facility ID:	NY468811
Tank ID:	NY102913
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1284587
Facility ID:	NY468811
Tank ID:	NY103165
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Z170 **CON EDISON - SERVICE BOX 18415** **RCRA-LQG** **1019325885**
SE **80 ALABAMA AVE** **NYP004868206**
1/8-1/4 **BROOKLYN, NY 11207**
0.205 mi.
1082 ft. **Site 1 of 2 in cluster Z**

Relative: **Lower**

Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:	20160205
Handler Name:	Con Edison - Service Box 18415
Handler Address:	Alabama Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004868206
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	HUACOND@CONED.COM
Contact Title:	SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON - SERVICE BOX 18415 (Continued) **1019325885**

Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner

CON EDISON - SERVICE BOX 18415 (Continued) **1019325885**

Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151111
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL 15TH FL NE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20151111
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL 15TH FL NE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - SERVICE BOX 18415
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Z171 **CON EDISON - SERVICE BOX 18415** **NJ MANIFEST** **S120677849**
SE **80 ALABAMA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.205 mi.
1082 ft. **Site 2 of 2 in cluster Z**

Relative:
Lower

Actual:
56 ft.

NJ MANIFEST:

EPA ID:	NYP004868206
Name:	CON EDISON - SERVICE BOX 18415
Address:	80 ALABAMA AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	DENNIS HUACON
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004868206
Manifest Number:	015319426JJK
Date Shipped:	11/11/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON - SERVICE BOX 18415 (Continued) **S120677849**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

X172 **CON EDISON - BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031609718**
WNW **1401 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.206 mi.
1086 ft. **Site 3 of 10 in cluster X**

Relative: **Higher**
Actual: **88 ft.**

E MANIFEST:

Manifest Tracking Number:	006873937GBF
Last Updated Date:	20210729
Shipped Date:	20210715
Received Date:	20210716
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	1401 HERKIMER ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 Rahway Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Avenel
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

CON EDISON - BROOKLYN ENVIRONMENTAL OPS (Continued) **1031609718**

Federal Waste:
- Manifest Tracking Number: 006873937GBF
- Waste Line Number: 1
- Federal Waste Code: D008
- Federal Waste: LEAD

State Waste:
- Manifest Tracking Number: 006873937GBF
- Waste Line Number: 1
- State Waste Code Owner: NY
- State Waste Code: T
- State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 006873937GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 006873937GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 1000
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.5
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.5
- Waste Quantity, in Kilograms: 453.515
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 453.515
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

X173 **CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031619316**
WNW **1401 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 10462**
0.206 mi.
1086 ft. **Site 4 of 10 in cluster X**

Relative:
Higher

Actual:
88 ft.

E MANIFEST:

Manifest Tracking Number:	006875154GBF
Last Updated Date:	20210709
Shipped Date:	20210701
Received Date:	20210701
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	1401 HERKIMER ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	10462
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	co/ACV Enviro 1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	006875154GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	006875154GBF
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619316**

State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 006875154GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006875154GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Rq, Na3082, Hazardous Waste, Liquid N.O.S.(Lead), 9, Pg Iii
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

AA174 **156-158 SOMERS ST LLC-EINAV GELBERG** **RCRA-VSQG** **1027222168**
NW **156-158 SOMERS ST** **E MANIFEST** **NYR000255042**
1/8-1/4 **BROOKLYN, NY 11233**
0.210 mi.
1111 ft. **Site 1 of 9 in cluster AA**

Relative: **Higher**
Actual: **92 ft.**

RCRA Listings:
Date Form Received by Agency: 20230717
Handler Name: 156-158 Somers St Llc-Einav Gelberg
Handler Address: Somers St
Handler City,State,Zip: BROOKLYN, NY 11233
EPA ID: NYR000255042

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Contact Name:		EINAV GELBERG
Contact Address:		PENNSYLVANIA AVE
Contact City,State,Zip:		BROOKLYN, NY 11207
Contact Telephone:		929-245-0972
Contact Fax:		Not reported
Contact Email:		EINAV.OGI@GMAIL.COM
Contact Title:		PRESIDENT
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2022
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		PENNSYLVANIA AVE
Mailing City,State,Zip:		BROOKLYN, NY 11207
Owner Name:	Einav Gelberg	
Owner Type:		Private
Operator Name:	Einav Gelberg	
Operator Type:		Private
Short-Term Generator Activity:		Yes
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20230717
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: EINAV GELBERG	
Legal Status:	Private
Date Became Current:	20191215
Date Ended Current:	Not reported
Owner/Operator Address:	122 PENNSYLVANIA AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11207
Owner/Operator Telephone:	929-245-0972
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	EINAV.OGI@GMAIL.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: EINAV GELBERG	
Legal Status:	Private
Date Became Current:	20191215
Date Ended Current:	Not reported
Owner/Operator Address:	122 PENNSYLVANIA AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11207
Owner/Operator Telephone:	929-245-0972
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	EINAV.OGI@GMAIL.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name: EINAV GELBERG	
Legal Status:	Private
Date Became Current:	20191215
Date Ended Current:	Not reported
Owner/Operator Address:	122 PENNSYLVANIA AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11207
Owner/Operator Telephone:	929-245-0972
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	EINAV.OGI@GMAIL.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: EINAV GELBERG	
Legal Status:	Private
Date Became Current:	20191215
Date Ended Current:	Not reported
Owner/Operator Address:	122 PENNSYLVANIA AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11207
Owner/Operator Telephone:	929-245-0972

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: EINAV.OGI@GMAIL.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: EINAV GELBERG
Legal Status: Private
Date Became Current: 20191215
Date Ended Current: Not reported
Owner/Operator Address: 122 PENNSYLVANIA AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11207
Owner/Operator Telephone: 929-245-0972
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: EINAV.OGI@GMAIL.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: EINAV GELBERG
Legal Status: Private
Date Became Current: 20191215
Date Ended Current: Not reported
Owner/Operator Address: 122 PENNSYLVANIA AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11207
Owner/Operator Telephone: 929-245-0972
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: EINAV.OGI@GMAIL.COM

Historic Generators:
Receive Date: 20230717
Handler Name: 156-158 SOMERS ST LLC-EINAV GELBERG
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20230519
Handler Name: 156-158 SOMERS ST LLC-EINAV GELBERG
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Receive Date: 20220413
Handler Name: EINAV GELBERG
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 623311
NAICS Description: Continuing Care Retirement Communities

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 017505410FLE
Last Updated Date: 20220505
Shipped Date: 20220502
Received Date: 20220502
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYR000255042
Generator Name: Einav Gelberg
Generator Location Street Number: Not reported
Generator Location Street 1: 156-158 SOMERS STREET
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY
Generator Location Zip: 11233
Generator Mail Street Number: Not reported
Generator Mail Street 1: 122 PENNSYLVANIA AVE
Generator Mail Street 2: Not reported
Generator Mail City: BROOKLYN
Generator Mail Zip: 11207
Generator Mail State: NY
Generator Contact Company Name: Not reported
Designated Facility EPA ID: PAD085690592
Designated Facility Name: Republic Env Sys Inc
Designated Facility Mail Street Number: Not reported
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: 2869 Sandstone Drive
Designated Facility Mail City: Hatfield
Designated Facility Mail Zip: 19440

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017505411FLE
Last Updated Date:	20230519
Shipped Date:	20220502
Received Date:	20220502
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000255042
Generator Name:	Einav Gelberg
Generator Location Street Number:	Not reported
Generator Location Street 1:	156-158 SOMERS STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	122 PENNSYLVANIA AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017505412FLE
Last Updated Date:	20220505
Shipped Date:	20220502
Received Date:	20220502
Manifest Status:	Signed
Submission Type:	DataImage5Copy

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Origin Type:	Service
Generator EPA ID:	NYR000255042
Generator Name:	Einav Gelberg
Generator Location Street Number:	Not reported
Generator Location Street 1:	156-158 SOMERS STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	122 PENNSYLVANIA AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	017505413FLE
Last Updated Date:	20230519
Shipped Date:	20220505
Received Date:	20220505
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000255042
Generator Name:	Einav Gelberg
Generator Location Street Number:	Not reported
Generator Location Street 1:	156-158 SOMERS STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	122 PENNSYLVANIA AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	017505414FLE
Last Updated Date:	20230519
Shipped Date:	20220505
Received Date:	20220505
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000255042
Generator Name:	Einav Gelberg
Generator Location Street Number:	Not reported
Generator Location Street 1:	156-158 SOMERS STREET
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	122 PENNSYLVANIA AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BROOKLYN
Generator Mail Zip:	11207
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

156-158 SOMERS ST LLC-EINAV GELBERG (Continued) **1027222168**

Federal Waste:
- Manifest Tracking Number: 017505414FLE
- Waste Line Number: 1
- Federal Waste Code: D008
- Federal Waste: LEAD

Transporter:
- Manifest Tracking Number: 017505414FLE
- Transporter Line Number: 1
- Transporter EPA ID: NJR986653780
- Transporter Name: Grid Logistics, Llc

Waste Line:
- Manifest Tracking Number: 017505414FLE
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: UN3077
- U.S. DOT Description: Un3077 Waste Environmentally Hazardous Substances, Solid, N.O.S. (Lead) Iii 9 D008=100#
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: DT
- Container Type Description: Dump truck
- Waste Quantity: 32060
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 16.03
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 16.03
- Waste Quantity, in Kilograms: 14539.692
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 14539.692
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

AA175
NW
1/8-1/4
0.210 mi.
1111 ft.

156 SOMERS STREET
BROOKLYN, NY 11233

Site 2 of 9 in cluster AA

NY VCP **S118704094**
NY E DESIGNATION **N/A**
NY NYC LAND USE
NY NYC OER

Relative:
Higher

Actual:
92 ft.

VCP NYC:

Project ID:	20TMP0986K,20EH-N203K,20CVCP076K
Name:	156-158 SOMERS STREET
Address:	156 - 158 SOMERS STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,154,400,153,015,400,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.679416
Longitude:	-73.905349
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	367
BIN:	3000000
NTA:	Ocean Hill

E DESIGNATION:

Name:	LOT 15,TAXBLOCK 1544
Address:	156 SOMERS STREET
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	15
Tax Block:	1544
Borough Code:	Not reported
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	156 SOMERS STREET
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6791659
Longitude:	-73.9055729
Type Of Ownership Code:	Not reported
Owner Name:	156 SOMERS ST LLC
Borough:	BK
Tax Block:	1544
Tax Lot:	15
Community District:	316
Census Tract 2020:	3036700
Census Block 2020:	30367003001
Census Tract 2010:	367
Census Block 2010:	2001

(Continued) **S118704094**

School District:	23
City Council District:	37
Fire Company:	E233
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	2B
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D3: Elevator Apartments - Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	2533
Total Building Floor Area:	8422
Commercial Floor Area:	0
Residential Floor Area:	8422
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	0
Number Of Floors:	6.0000000
Residential Units:	10
Total Units:	10
Lot Frontage:	25.3300000
Lot Depth:	100.0000000
Building Frontage:	25.0000000
Building Depth:	58.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	45450.00000
Assessed Total Value:	576900.00000
Exempt Total Value:	0.00000
Year Built:	2022
Year Altered 1:	2021
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	3.32000000000
Maximum Allowable Residential Far:	3.00000000000

(Continued) **S118704094**

Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015440015.00000000
Condominium Number:	Not reported
Census Tract 2:	0367
X Coordinate:	1010441
Y Coordinate:	186729
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	305 072
Tax Map #:	30603
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	156-158 SOMERS STREET
Address:	156 - 158 SOMERS STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.679416
Longitude:	-73.905349
OER Project Numbers:	20TMP0986K,20EH-N203K,20CVCP076K
BBL:	3.0154400153015398E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Construction

URL:

Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	367
BIN:	3000000
NTA:	Ocean Hill

AA176 **EINAV GELBERG** **NY MANIFEST** **S130582827**
NW **156-158 SOMERS ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.210 mi.
1111 ft. **Site 3 of 9 in cluster AA**

Relative:
Higher

Actual:
92 ft.

NY MANIFEST:

EPA ID:	NYR000255042
Country:	USA
Name:	Einav Gelberg
Address:	156-158 SOMERS ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	156-158 SOMERS ST
Location Address 2:	Not reported

EINAV GELBERG (Continued) **S130582827**

Location City,State,Zip: BROOKLYN, NY 11233
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Einav Gelberg
Mailing Contact: Einav Gelberg
Mailing Address 1: 122 PENNSYLVANIA AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11207
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9292450972

U177 **ROYAL LACE CORP.** **NY UST** **U001842052**
South **200 LIBERTY AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.212 mi.
1121 ft. **Site 6 of 10 in cluster U**

Relative:
Lower

Actual:
58 ft.

UST:
Name: ROYAL LACE CORP.
Address: 200 LIBERTY AVENUE
City,State,Zip: BROOKLYN, NY 11207
Id/Status: 2-601711 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 592762.87120
UTM Y: 4503085.09941
Site Type: Other

Affiliation Records:
Site Id: 23673
Affiliation Type: Facility Owner
Company Name: AARON GUTTMAN
Contact Type: Not reported
Contact Name: Not reported
Address1: 5323 13TH AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11219
Country Code: 001
Phone: (718) 871-2235
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23673
Affiliation Type: Mail Contact
Company Name: ROYAL LACE CORP.
Contact Type: Not reported
Contact Name: NATHAN GRAAN

ROYAL LACE CORP. (Continued) **U001842052**

Address1:	200 LIBERTY AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 495-9335
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23673
Affiliation Type:	Facility Operator
Company Name:	ROYAL LACE CORP.
Contact Type:	Not reported
Contact Name:	AARON GUTTMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 495-9327
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23673
Affiliation Type:	Emergency Contact
Company Name:	AARON GUTTMAN
Contact Type:	Not reported
Contact Name:	MOSES GUTTMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 633-2411
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	47551
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	01/01/1994
Registered:	True
Tank Location:	Underground

ROYAL LACE CORP. (Continued) **U001842052**

Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 002
Tank ID: 47552
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 10000
Install Date: Not reported
Date Tank Closed: 01/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

U178 **ROYAL LACE CORP.** **UST FINDER** **1028572455**
South **200 LIBERTY AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.212 mi.
1121 ft. **Site 7 of 10 in cluster U**

Relative:
Lower

Actual:
58 ft.

UST FINDER:

Object ID:	295695
Facility ID:	NY23673
Name:	ROYAL LACE CORP.
Address:	200 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	4984
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.902779
Y Coord:	40.67292
Latitude:	40.67292
Longitude:	-73.902779

UST FINDER:

Object ID:	1221055
Facility ID:	NY23673
Tank ID:	NY32151
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1221056
Facility ID:	NY23673
Tank ID:	NY111636
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

U179 **STAR POLY BAG INC** **PFAS ECHO** **1027423016**
SSE **N/A**
1/8-1/4 **BROOKLYN, NY**
0.213 mi.
1126 ft. **Site 8 of 10 in cluster U**

Relative:
Lower

Actual:
56 ft.

PFAS ECHO:

Name:	Star Poly Bag Inc
Address:	Not reported
City,State,Zip:	BROOKLYN, NY
Latitude:	40.67333
Longitude:	-73.902
Count:	1
County:	KINGS
Status:	Active
Region:	02
Industry:	Plastics and Resins

ECHO Facility Report:

Facility Percent Minority:	88.213
Facility Derived Tribes:	-
Facility Population:	37324.76
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36047
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	02030202
Facility Derived WBD:	020302020103
Facility Derived CD113:	08
Facility Derived CB2010:	360471144001007
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-

STAR POLY BAG INC (Continued) **1027423016**

NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	NYR000229955
RCRA Permit Types:	VSQG
RCRA NAICS:	326113 326111 326112
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y

EJSCREEN Report:

AA180 **1848 STEWART ST** **NY LTANKS** **S103238604**
NNW **1848 STEWART ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.220 mi.
1164 ft. **Site 4 of 9 in cluster AA**

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	1848 STEWART ST
Address:	1848 STEWART ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9510983 / 1995-12-01
Facility ID:	9510983
Site ID:	137876
Spill Date:	1995-12-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	LUCE
Referred To:	Not reported
Reported to Dept:	1995-12-01
CID:	349
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-01
Spill Record Last Update:	1995-12-04
Spiller Name:	ANDREW BASILE
Spiller Company:	Not reported
Spiller Address:	1848 STEWART ST
Spiller County:	001
Spiller Contact:	ANDREW BASILE

1848 STEWART ST (Continued) **S103238604**

Spiller Phone: (718) 376-2909
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 117898
Latitude: 40.6079092
Longitude: -73.9406809
DEC Memo: Not reported
Remarks: LEAKING TANK

All Materials:
Site ID: 137876
Operable Unit ID: 1021534
Operable Unit: 01
Material ID: 358338
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: 2.00
Resource Affected: Soil
Oxygenate: Not reported

V181 **NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN** **RCRA NonGen / NLR** **1004759513**
SE **275 LIBERTY AVE** **FINDS** **NYR000011957**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.222 mi. **NY MANIFEST**
1173 ft. **Site 3 of 5 in cluster V**

Relative: **Lower**
Actual: **54 ft.**

RCRA Listings:
Date Form Received by Agency: 20070101
Handler Name: Nyc Bd Of Ed - Public School 897 Bklyn
Handler Address: Liberty Ave
Handler City,State,Zip: BROOKLYN, NY 11207
EPA ID: NYR000011957
Contact Name: ROBERT GUASTA
Contact Address: LIBERTY AVE
Contact City,State,Zip: BROOKLYN, NY 11207
Contact Telephone: 718-349-5590
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Municipal
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: LIBERTY AVE
Mailing City,State,Zip: BROOKLYN, NY 11207
Owner Name: Nyc Board Of Education
Owner Type: Municipal
Operator Name: Nyc Board Of Education

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC BOARD OF EDUCATION
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

Receive Date: 19950822
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004517693

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004759513
Registry ID: 110004517693

DFR URL:
Name: NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN
Address: 275 LIBERTY AVE
City,State,Zip: BROOKLYN, NY 11207

NY MANIFEST:
EPA ID: NYR000011957
Country: USA
Name: Nyc Board Of Education
Address: 275 LIBERTY AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

Zip 4: Not reported
Location Address 1: 275 LIBERTY AVENUE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Nyc Board Of Education
Mailing Contact: Jack Brucculeri
Mailing Address 1: 28-11 QUEENS PLAZA NORTH
Mailing Address 2: Not reported
Mailing City,State,Zip: LONG ISLAND CITY, NY 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183916094

Manifest Data:
Document ID: NJA2182274
Manifest Status: Not reported
Trans1 State ID: 50082
Year: 1995
Trans2 State ID: S6993
Generator Ship Date: 08/22/1995
Trans1 Recv Date: 08/22/1995
Trans2 Recv Date: 10/26/1995
TSD Site Recv Date: 10/27/1995
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000011957
Trans1 EPA ID: NY0000551218
Trans2 EPA ID: NJD980772768
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00150
Units: Pounds
Number of Containers: 001

NYC BD OF ED - PUBLIC SCHOOL 897 BKLYN (Continued) **1004759513**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

AB182 **CON EDISON** **NY MANIFEST** **S117067485**
East **51 GEORGIA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.223 mi.
1175 ft. **Site 1 of 7 in cluster AB**

Relative: **Lower**
Actual: **60 ft.**

NY MANIFEST:

EPA ID:	NYP004603775
Country:	USA
Name:	Con Edison
Address:	51 GEORGIA AVE
Address 2:	SB 26258
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	51 GEORGIA AVE
Location Address 2:	SB 26258
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/2014
Trans1 Recv Date:	07/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004603775
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615101GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S117067485**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AC183 **CON EDISON SERVICE BOX: 19418** **RCRA NonGen / NLR** **1017779243**
WSW **2425 DEAN ST** **FINDS** **NYP004572301**
1/8-1/4 **BROOKLYN, NY 11233**
0.223 mi.
1178 ft. **Site 1 of 7 in cluster AC**

Relative: **Lower**

Actual: **67 ft.**

RCRA Listings:

Date Form Received by Agency:	20140721
Handler Name:	Con Edison Service Box: 19418
Handler Address:	Dean St
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004572301
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON SERVICE BOX: 19418 (Continued) **1017779243**

Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150211
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		20140621
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No

CON EDISON SERVICE BOX: 19418 (Continued) **1017779243**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140621
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140721
Handler Name: CON EDISON SERVICE BOX: 19418
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063834917

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AC184 **CON EDISON** **NY MANIFEST** **S117064728**
WSW **2425 DEAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.223 mi.
1178 ft. **Site 2 of 7 in cluster AC**

Relative:
Lower

Actual:
67 ft.

NY MANIFEST:

EPA ID:	NYP004572301
Country:	USA
Name:	Con Edison
Address:	2425 DEAN ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	2425 DEAN ST
Location Address 2:	SB 19418
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/21/2014
Trans1 Recv Date:	06/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004572301
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502097GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117064728**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

U185 **STAR POLY BAG INC** **RCRA-VSQG** **1023679016**
SSE **96 SNEDIKER AVE** **NYR000229955**
1/8-1/4 **BROOKLYN, NY 11207**
0.223 mi.
1179 ft. **Site 9 of 10 in cluster U**

Relative: **Lower**
Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:	20210913
Handler Name:	Star Poly Bag Inc
Handler Address:	Snediker Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYR000229955
Contact Name:	JOEL POSEN
Contact Address:	SNEDIKER AVE
Contact City,State,Zip:	BROOKLYN, NY 11207
Contact Telephone:	718-384-3130 x101
Contact Fax:	Not reported
Contact Email:	JOEL@STARPOLY.COM
Contact Title:	PROJECT MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	SNEDIKER AVE
Mailing City,State,Zip:	BROOKLYN, NY 11207
Owner Name:	Jacob Posen
Owner Type:	Private
Operator Name:	Joel Posen
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

STAR POLY BAG INC (Continued) **1023679016**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211013
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOEL POSEN	
Legal Status:	Private
Date Became Current:	20140301
Date Ended Current:	Not reported
Owner/Operator Address:	96 SNEDIKER AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11207
Owner/Operator Telephone:	718-384-3130
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JOEL@STARPOLY.COM

STAR POLY BAG INC (Continued) **1023679016**

Owner/Operator Indicator: Owner
Owner/Operator Name: LIBERTY BH LLC
Legal Status: Private
Date Became Current: 20140301
Date Ended Current: Not reported
Owner/Operator Address: 199 LEE AVE SUITE 656
Owner/Operator City,State,Zip: BROOKLYN, NY 11211
Owner/Operator Telephone: 347-623-7033
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: STAR POLY BAGS INC
Legal Status: Private
Date Became Current: 20140301
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JACOB POSEN
Legal Status: Private
Date Became Current: 20140301
Date Ended Current: Not reported
Owner/Operator Address: 219 HEWES ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11211
Owner/Operator Telephone: 718-218-8474
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: JACOB@STARPOLY.COM

Historic Generators:
Receive Date: 20161212
Handler Name: STAR POLY BAG INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210913
Handler Name: STAR POLY BAG INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

STAR POLY BAG INC (Continued) **1023679016**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 326111
NAICS Description: Plastics Bag And Pouch Manufacturing

NAICS Code: 326112
NAICS Description: Plastics Packaging Film And Sheet (Including Laminated) Manufacturing

NAICS Code: 326113
NAICS Description: Unlaminated Plastics Film And Sheet (Except Packaging) Manufacturing

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T186 **VACANT LOT** **NY LTANKS** **S107489258**
SW **170-180 SACKMAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.223 mi.
1180 ft. **Site 2 of 2 in cluster T**

Relative: LTANKS:
Lower
Actual: Name: VACANT LOT
61 ft. Address: 170-180 SACKMAN ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0510241 / 2006-04-25
Facility ID: 0510241
Site ID: 356181
Spill Date: 2005-11-29
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2005-11-29
CID: 406
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-11-30
Spill Record Last Update: 2006-04-25

VACANT LOT (Continued) **S107489258**

Spiller Name:	KAY ZIAS
Spiller Company:	VACANT LOT
Spiller Address:	170-180 SACKMAN ST
Spiller County:	001
Spiller Contact:	KAY ZIAS
Spiller Phone:	(212) 312-3752
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	306251
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	No CSL was sent to this owner. The consultant has already done most of the work necessary and they said they would send in the results when the end point sample results come back from the lab. 03/06/06 Sharif Rahman- I tried to call Nelson Abramas,(908)947-0274 and left messege to his voice mail to follow up about the status of the vacant lot. 04/06/06 Sharif Rahman- CSL was sent via mail and facsimile to NYC Economic Development Corp. 110 William Street New York, NY 10038 Attn: Kay Zias, Fax:(212)312-3989. 04/25/06 Sharif Rahman- Rec'd tank closure report from Metcalf & Eddy of New York,Inc. One 550 gallon #2 UST was removed from the site. Approx. 12 tons of petroleum contaminated soil was removed from the site.No VOC was detected above TAGM limit in the post excavation end point samples.Minor exceedances of SVOC are similiar to the fill material observed during the Phase II site assesment.NFA required.
Remarks:	While removing an underground tank found holes in the tank. The contaminated was stock piled and samples have been taken. More clean up will be done depending on the test results. Excavation was lined with plastic then filled in with clean soil.

All TTF:

Facility ID:	0510241
Spill Number:	0510241
Spill Tank Test:	1549554
Site ID:	356181
Tank Number:	Not reported
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	356181
Operable Unit ID:	1113495
Operable Unit:	01
Material ID:	2103553
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

VACANT LOT (Continued) **S107489258**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

W187 **NYCTA** **NY MANIFEST** **1009244579**
ENE **25 JAMAICA AVE NYD991290677** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.224 mi.
1183 ft. **Site 3 of 11 in cluster W**

Relative:
Lower

Actual:
67 ft.

NY MANIFEST:

EPA ID:	NYT370011371
Country:	USA
Name:	Nycta
Address:	25 JAMAICA AVE NYD991290677
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	25 JAMAICA AVE NYD991290677
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nycta
Mailing Contact:	Squitieri John Chemist
Mailing Address 1:	370 JAY ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11201
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123304782

Manifest Data:

Document ID:	NYO1685016
Manifest Status:	C - Completed copy
Trans1 State ID:	PA 060
Year:	1982
Trans2 State ID:	Not reported
Generator Ship Date:	820331
Trans1 Recv Date:	820331
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820401
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	PAD990753089
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD990753089
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

NYCTA (Continued) **1009244579**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	37392
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NYO1685061
Manifest Status:	C - Completed copy
Trans1 State ID:	PA 060
Year:	1982
Trans2 State ID:	Not reported
Generator Ship Date:	820608
Trans1 Recv Date:	820608
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820615
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	PAD061102356
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD990753089
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

NYCTA (Continued) **1009244579**

Waste Code 6:	Not reported
Quantity:	29520
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYO1685133
Manifest Status:	C - Completed copy
Trans1 State ID:	PA 060
Year:	1982
Trans2 State ID:	Not reported
Generator Ship Date:	820615
Trans1 Recv Date:	820615
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820622
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	PAD061102356
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD990753089
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	31488
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYO1685178
Manifest Status:	C - Completed copy
Trans1 State ID:	PA 060
Year:	1982
Trans2 State ID:	Not reported
Generator Ship Date:	821019
Trans1 Recv Date:	821019
Trans2 Recv Date:	Not reported

NYCTA (Continued) **1009244579**

TSD Site Recv Date:	821025
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	PAD061102356
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD990753089
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	19680
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NYO1685205
Manifest Status:	C - Completed copy
Trans1 State ID:	PA 060
Year:	1982
Trans2 State ID:	Not reported
Generator Ship Date:	821004
Trans1 Recv Date:	821004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	821011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	PAD061102356
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD990753089
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported

NYCTA (Continued) **1009244579**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	39360
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NYO1934442
Manifest Status:	C - Completed copy
Trans1 State ID:	S7728AJ
Year:	1982
Trans2 State ID:	Not reported
Generator Ship Date:	820830
Trans1 Recv Date:	820830
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	820903
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	NJD099264319
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

NYCTA (Continued) **1009244579**

Waste Code 6:	Not reported
Quantity:	02145
Units:	Gallons (liquids only)
Number of Containers:	039
Container Type:	Metal drums, barrels, kegs
Handling Method:	Not reported
Specific Gravity:	100
Document ID:	NYO1666647
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NYJA098
Year:	1980-1981
Trans2 State ID:	Not reported
Generator Ship Date:	810515
Trans1 Recv Date:	810515
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	810518
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	NJD000692160
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD049851892
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01600
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NJO0068580
Manifest Status:	B - TSDF copy
Trans1 State ID:	Not reported
Year:	1980-1981
Trans2 State ID:	Not reported
Generator Ship Date:	811030
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	Not reported

NYCTA (Continued) **1009244579**

TSD Site Recv Date:	811023
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	Not reported
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported

Document ID:	NYO1566135
Manifest Status:	B - TSDF copy
Trans1 State ID:	Not reported
Year:	1980-1981
Trans2 State ID:	Not reported
Generator Ship Date:	811030
Trans1 Recv Date:	Not reported
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	811023
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYT370011371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	Not reported
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported

W188 **EAST NEW YORK DEPOT** **UST FINDER RELEASE** **1029068155**
ENE **25 JAMAICA AVE/NYCTA** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.224 mi.
1183 ft. **Site 4 of 11 in cluster W**

Relative: **Lower**
Actual: **67 ft.**

UST FINDER RELEASE:

Object ID:	258894
Facility ID:	NY243189
Lust ID:	NY9102804
Name:	EAST NEW YORK DEPOT
Address:	25 JAMAICA AVE/NYCTA
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1991/06/10 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	3315
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.89885
Y Coord:	40.6775900000001
Latitude:	40.67759
Longitude:	-73.8988499999999

W189 **NEW YORK CITY TRANSIT AUTHORITY** **PA MANIFEST** **S123092787**
ENE **25 JAMAICA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.224 mi.
1183 ft. **Site 5 of 11 in cluster W**

Relative: **Lower**
Actual: **67 ft.**

PA MANIFEST:

Name:	NEW YORK CITY TRANSIT AUTHORITY
Address:	25 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY 11207
Year:	2017
Manifest Number:	015625193JJK
Manifest Type:	T
Generator EPA ID:	NYD991290677
Generator Date:	10/26/2017
Mailing Address:	Not reported

NEW YORK CITY TRANSIT AUTHORITY (Continued) **S123092787**

Contact Name:	Not reported
Contact Phone:	718-330-4891
TSD EPA ID:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	DF
Waste Quantity:	107
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	PAD067098822
Date TSP Sig:	Not reported

W190 **EAST NEW YORK BUS DEPOT** **NY AST** **A100520577**
ENE **25 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.224 mi.
1183 ft. **Site 6 of 11 in cluster W**

Relative:
Lower

Actual:
67 ft.

AST:

Name:	EAST NEW YORK BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-190292
Program Type:	PBS
UTM X:	592978.45466
UTM Y:	4503511.36944
Expiration Date:	06/05/2027
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	5864
Affiliation Type:	Emergency Contact
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-12-09

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Site Id:	5864
Affiliation Type:	Facility Owner
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-06-09

Site Id:	5864
Affiliation Type:	Facility Operator
Company Name:	PETER CASSAR
Contact Type:	Not reported
Contact Name:	PETER CASSAR
Address1:	25 JAMAICA AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(646) 721-8295
EMail:	PETER.CASSAR@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Site Id:	5864
Affiliation Type:	Mail Contact
Company Name:	MTA New York City Transit
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY # 27
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	003
Tank Id:	6755
Material Code:	0008
Common Name of Substance:	Diesel

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1949
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel
Tank Number:	004
Tank Id:	6756
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1949
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Material Name: diesel

Tank Number: 005
Tank Id: 6757
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1949
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/01/1992
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: diesel

Tank Number: 006
Tank Id: 6758
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1949

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	007
Tank Id:	6759
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1949
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	008
Tank Id:	6760
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

	I00 - Overfill - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1949
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	009
Tank Id:	6761
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	A01 - Tank Internal Protection - Epoxy Liner
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1949
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	010
Tank Id:	6762
Material Code:	0008
Common Name of Substance:	Diesel

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1949
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel
Tank Number:	011
Tank Id:	6763
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1949
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/1991
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Material Name: gasoline

Tank Number: 012
Tank Id: 6764
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1949
Capacity Gallons: 2000
Tightness Test Method: ZZ
Date Test: 06/01/1991
Next Test Date: Not reported
Date Tank Closed: 11/01/1993
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: gasoline

Tank Number: 013
Tank Id: 6765
Material Code: 9999
Common Name of Substance: Other

Equipment Records:
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1949

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Capacity Gallons:	1000
Tightness Test Method:	01
Date Test:	06/01/1991
Next Test Date:	Not reported
Date Tank Closed:	12/01/1993
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	014
Tank Id:	6766
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1949
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/01/1991
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	015
Tank Id:	6767
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1949
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1993
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: lube oil

Tank Number: 016
Tank Id: 6768
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1949
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/01/1993
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: lube oil

Tank Number: 017
Tank Id: 6769
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1949
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1993
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil
Tank Number:	018
Tank Id:	6770
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1949
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/1991
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other
Tank Number:	019

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Tank Id: 6771
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1949
Capacity Gallons: 550
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/01/1991
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: other

Tank Number: DAY TANK
Tank Id: 178477
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 12
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Date Tank Closed:	01/01/2005
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	EMGEN-1
Tank Id:	53478
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/2003
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	EMGEN-2
Tank Id:	66209
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	75
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	EMGEN-3
Tank Id:	66208
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	25
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	EMGEN-4
Tank Id:	280546

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Equipment Records:
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/02/2019
Capacity Gallons:	780
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Diesel (E-Gen)
Tank Number:	EMGEN-5
Tank Id:	298292

Equipment Records:
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/31/2022
Capacity Gallons:	200
Tightness Test Method:	Not reported
Date Test:	Not reported
Next Test Date:	Not reported

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Date Tank Closed:	Not reported
Register:	True
Modified By:	nFormUpd
Last Modified:	03/31/2023
Material Name:	Diesel (E-Gen)

Tank Number:	ENY-17
Tank Id:	50839
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	ENY-18
Tank Id:	50840
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
G01 - Tank Secondary Containment - Diking (Aboveground)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	ENY-21
Tank Id:	56208
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	03/01/1999
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	ENY-22
Tank Id:	58093
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	03/01/1999
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other
Tank Number:	GEN-23
Tank Id:	178476
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
G01 - Tank Secondary Containment - Diking (Aboveground)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
C01 - Pipe Location - Aboveground
J00 - Dispenser - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	70
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Tank Number: LUBE OIL
Tank Id: 178474
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 500
Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/01/2006
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: lube oil

Tank Number: W/O-2
Tank Id: 178475
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 500

EAST NEW YORK BUS DEPOT (Continued) **A100520577**

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

W191 **EAST NEW YORK BUS DEPOT** **UST FINDER** **1028599267**
ENE **25 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.224 mi.
1183 ft. **Site 7 of 11 in cluster W**

Relative:
Lower

Actual:
67 ft.

UST FINDER:

Object ID:	295865
Facility ID:	NY5864
Name:	EAST NEW YORK BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	13
Closed USTs:	6
TOS USTs:	0
Population 1500ft:	3369
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.899241
Y Coord:	40.6768230000001
Latitude:	40.676823
Longitude:	-73.899241

UST FINDER:

Object ID:	1316075
Facility ID:	NY5864
Tank ID:	NY8184
Tank Status:	Closed
Installation Date:	1947/09/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	25000
Substances:	Not reported

EAST NEW YORK BUS DEPOT (Continued) **1028599267**

Tank Wall Type: Not reported

Object ID: 1316076
Facility ID: NY5864
Tank ID: NY108525
Tank Status: Closed
Installation Date: 1947/09/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 25000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316298
Facility ID: NY5864
Tank ID: NY8185
Tank Status: Open
Installation Date: 1993/12/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316299
Facility ID: NY5864
Tank ID: NY8186
Tank Status: Open
Installation Date: 1993/12/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316300
Facility ID: NY5864
Tank ID: NY8291
Tank Status: Closed
Installation Date: 1993/11/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 20000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316301
Facility ID: NY5864
Tank ID: NY8292
Tank Status: Open
Installation Date: 1993/12/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316302
Facility ID: NY5864
Tank ID: NY8293
Tank Status: Open
Installation Date: 1993/12/01 15:59:59+00

EAST NEW YORK BUS DEPOT (Continued) **1028599267**

Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316303
Facility ID:	NY5864
Tank ID:	NY8294
Tank Status:	Open
Installation Date:	1993/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316304
Facility ID:	NY5864
Tank ID:	NY8462
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316305
Facility ID:	NY5864
Tank ID:	NY8463
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316306
Facility ID:	NY5864
Tank ID:	NY8464
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316307
Facility ID:	NY5864
Tank ID:	NY8677
Tank Status:	Closed
Installation Date:	1993/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	20000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316308
Facility ID:	NY5864

EAST NEW YORK BUS DEPOT (Continued) **1028599267**

Tank ID:	NY8678
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316309
Facility ID:	NY5864
Tank ID:	NY8679
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316310
Facility ID:	NY5864
Tank ID:	NY8680
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316311
Facility ID:	NY5864
Tank ID:	NY8681
Tank Status:	Open
Installation Date:	1993/11/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316312
Facility ID:	NY5864
Tank ID:	NY8710
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316313
Facility ID:	NY5864
Tank ID:	NY8711
Tank Status:	Closed
Installation Date:	1999/03/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

EAST NEW YORK BUS DEPOT (Continued) **1028599267**

Object ID:	1316314
Facility ID:	NY5864
Tank ID:	NY9592
Tank Status:	Open
Installation Date:	1993/12/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

W192 **EAST NEW YORK BUS DEPOT** **NY AST** **A100520418**
ENE **25 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.224 mi.
1183 ft. **Site 8 of 11 in cluster W**

Relative:
Lower

Actual:
67 ft.

AST:

Name:	EAST NEW YORK BUS DEPOT
Address:	25 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000284
Program Type:	CBS
UTM X:	592990.74775
UTM Y:	4503579.01980
Expiration Date:	N/A
Site Type:	Trucking/Transportation/Fleet Operation

Tank Info:

Tank Number:	1
Tank Id:	191632
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/1995
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	ANTI DEPOT
Tank Id:	194237
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place

EAST NEW YORK BUS DEPOT (Continued) **A100520418**

Pipe Model:	Not reported
Install Date:	03/01/2001
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/16/2015
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	ANTI TRASH
Tank Id:	194856
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	06/01/2001
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/19/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	CBS-ENY-1
Tank Id:	191807
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1995
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/01/2001
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	W ANTI TRAS
Tank Id:	195188
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use

EAST NEW YORK BUS DEPOT (Continued) **A100520418**

Pipe Model:	Not reported
Install Date:	06/01/2001
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/19/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

AD193 **CON EDISON** **NY LEAD** **S117316054**
WSW **2342 ATLANTIC AV** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.225 mi.
1190 ft. **Site 1 of 5 in cluster AD**

Relative:
Higher

Actual:
75 ft.

NYC LEAD:

Name:	Not reported
Address:	2342 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	11741768
Building ID:	185969
Registration ID:	381898
Apartment:	4B
Story:	4
Class:	Most Serious
Inspection Date:	04/13/2017
Approved Date:	04/18/2017
Original Certify By Date:	05/22/2017
Original Correct By Date:	05/17/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	5730858
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st WINDOW FRAME FROM NORTH AT EAST WALL IN THE 2nd ROOM FROM NORTH AT EAST LOCATED AT APT 4B, 4th STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	04/19/2017
Current Status ID:	19
Current Status:	VIOLATION CLOSED
Current Status Date:	05/03/2017

Name:	Not reported
Address:	2342 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	15189947
Building ID:	185969
Registration ID:	381898
Apartment:	5B
Story:	4
Class:	Most Serious
Inspection Date:	05/19/2022
Approved Date:	05/29/2022

CON EDISON (Continued) **S117316054**

Original Certify By Date:	06/29/2022
Original Correct By Date:	06/24/2022
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	7923478
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE FOYER LOCATED AT APT 5B, 4th STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	05/31/2022
Current Status ID:	11
Current Status:	VIOLATION WILL BE REINSPECTED
Current Status Date:	12/20/2022

Name:	Not reported
Address:	2342 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	15189946
Building ID:	185969
Registration ID:	381898
Apartment:	5B
Story:	4
Class:	Most Serious
Inspection Date:	05/19/2022
Approved Date:	05/29/2022
Original Certify By Date:	06/29/2022
Original Correct By Date:	06/24/2022
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	616
NOV ID:	7923478
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE BATHROOM LOCATED AT APT 5B, 4th STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date:	05/31/2022
Current Status ID:	11
Current Status:	VIOLATION WILL BE REINSPECTED
Current Status Date:	12/20/2022

Name:	Not reported
Address:	2342 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Violation ID:	15081542
Building ID:	185969
Registration ID:	381898
Apartment:	3A
Story:	3
Class:	Most Serious
Inspection Date:	03/21/2022
Approved Date:	03/26/2022
Original Certify By Date:	04/26/2022
Original Correct By Date:	04/21/2022

CON EDISON (Continued) **S117316054**

New Certify By Date: Not reported
New Correct By Date: Not reported
Certified Date: Not reported
Order Number: 616
NOV ID: 7855449
NOV Description: 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) CEILING IN THE 3rd ROOM FROM NORTH AT WEST LOCATED AT APT 3A, 3rd STORY, 1st APARTMENT FROM NORTH AT EAST
NOV Issued Date: 03/28/2022
Current Status ID: 19
Current Status: VIOLATION CLOSED
Current Status Date: 02/29/2024

NY MANIFEST:
EPA ID: NYP004632832
Country: USA
Name: Con Edison
Address: 2342 ATLANTIC AV
Address 2: SB55768
City,State,Zip: BROOKLYN, NY 11233
Zip 4: Not reported
Location Address 1: 2342 ATLANTIC AV
Location Address 2: SB55768
Location City,State,Zip: BROOKLYN, NY 11233
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/19/2014
Trans1 Recv Date: 08/19/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/30/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004632832
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON (Continued) **S117316054**

TSDF ID 2: Not reported
Manifest Tracking Number: 013254205JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 50
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

NYC LAND USE:
Name: Not reported
Address: 2342 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11233
Latitude: 40.6758574
Longitude: -73.9075604
Type Of Ownership Code: Not reported
Owner Name: 2342 ATLANTIC 22 LLC
Borough: BK
Tax Block: 1436
Tax Lot: 11
Community District: 316
Census Tract 2020: 3036502
Census Block 2020: 30365021003
Census Tract 2010: 365.02
Census Block 2010: 1002
School District: 23
City Council District: 37
Fire Company: L176
Police Precinct: 73
Health Center District: 34
Health Area: 3700
Sanitation District Boro: 3
Sanitation District Number: 16

CON EDISON (Continued) **S117316054**

Sanitation Subsection:	1B
Zoning District 1:	R6: Residential Districts
Zoning District 2:	R8A: Residential Districts
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	Y
Building Class:	D5: Elevator Apartments - Converted
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	4000
Total Building Floor Area:	16495
Commercial Floor Area:	2309
Residential Floor Area:	14186
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	2309
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	5.0000000
Residential Units:	24
Total Units:	24
Lot Frontage:	40.0000000
Lot Depth:	100.0000000
Building Frontage:	36.0000000
Building Depth:	98.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	63000.00000
Assessed Total Value:	1090350.00000
Exempt Total Value:	0.00000
Year Built:	1920
Year Altered 1:	2003
Year Altered 2:	2003
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.12000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014360011.00000000
Condominium Number:	Not reported
Census Tract 2:	036502
X Coordinate:	1009891
Y Coordinate:	185523

CON EDISON (Continued) **S117316054**

Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	307 011
Tax Map #:	30508
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AA194 **SACKMAN REALTY LLC** **NY AST** **A100343964**
NW **10 SACKMAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.227 mi.
1197 ft. **Site 5 of 9 in cluster AA**

Relative:
Higher

Actual:
91 ft.

AST:

Name:	SACKMAN REALTY LLC
Address:	10 SACKMAN ST
City,State,Zip:	BROOKLYN, NY 11233
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-611080
Program Type:	PBS
UTM X:	592422.71221
UTM Y:	4503714.28080
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	413672
Affiliation Type:	Emergency Contact
Company Name:	SACKMAN REALTY LLC
Contact Type:	Not reported
Contact Name:	SOL GOLD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 935-9624
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-05-11

Site Id:	413672
Affiliation Type:	Facility Operator
Company Name:	SACKMAN REALTY LLC
Contact Type:	Not reported
Contact Name:	MOSE NEW
Address1:	Not reported
Address2:	Not reported

SACKMAN REALTY LLC (Continued) **A100343964**

City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 935-9624
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-03-22

Site Id: 413672
Affiliation Type: Facility Owner
Company Name: SACKMAN REALTY LLC
Contact Type: MGR
Contact Name: MOSE NE
Address1: 199 LEE AVE .#233
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 935-9624
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-03-22

Site Id: 413672
Affiliation Type: Mail Contact
Company Name: SACKMAN REALTY LLC
Contact Type: MGR
Contact Name: MOSE NE
Address1: 199 LEE AVE .#233
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 935-9624
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-03-22

Tank Info:

Tank Number: 69428
Tank Id: 228368
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None

SACKMAN REALTY LLC (Continued) **A100343964**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/15/2003
Capacity Gallons:	2000
Tightness Test Method:	21
Date Test:	10/08/2013
Next Test Date:	Not reported
Date Tank Closed:	10/16/2013
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AD195 **CON EDISON** **NY MANIFEST** **S117062654**
WSW **2349 PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.227 mi.
1200 ft. **Site 2 of 5 in cluster AD**

Relative:
Higher

Actual:
73 ft.

NY MANIFEST:

EPA ID:	NYP004550240
Country:	USA
Name:	Con Edison
Address:	2349 PACIFIC ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	2349 PACIFIC ST
Location Address 2:	SB33412
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported

CON EDISON (Continued) **S117062654**

Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2014
Trans1 Recv Date:	06/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004550240
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002423620GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD196 **CON EDISON SERVICE BOX: 33412** **RCRA NonGen / NLR** **1017777137**
WSW **2349 PACIFIC ST** **FINDS** **NYP004550240**
1/8-1/4 **BROOKLYN, NY 11233**
0.227 mi.
1200 ft. **Site 3 of 5 in cluster AD**

Relative: **Higher**
Actual: **73 ft.**

RCRA Listings:

Date Form Received by Agency:	20140702
Handler Name:	Con Edison Service Box: 33412
Handler Address:	Pacific St
Handler City,State,Zip:	BROOKLYN, NY 11233

CON EDISON SERVICE BOX: 33412 (Continued) **1017777137**

EPA ID:		NYP004550240
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150211
Recognized Trader-Importer:		No

CON EDISON SERVICE BOX: 33412 (Continued) **1017777137**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140602
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140602
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140702
Handler Name: CON EDISON SERVICE BOX: 33412	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 33412 (Continued) **1017777137**

Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063813146

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AE197 **CON EDISON** **NJ MANIFEST** **S120672853**
ESE **74 GEORGIA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.228 mi.
1204 ft. **Site 1 of 6 in cluster AE**

Relative:
Lower

Actual:
56 ft.

NJ MANIFEST:

EPA ID:	NYP004794962
Name:	CON EDISON
Address:	74 GEORGIA AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004794962
Manifest Number:	002620036GBF
Date Shipped:	6/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON (Continued) **S120672853**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AE198 **CON EDISON** **NY MANIFEST** **S118256947**
ESE **74 GEORGIA AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.228 mi.
1204 ft. **Site 2 of 6 in cluster AE**

Relative:
Lower

Actual:
56 ft.

NY MANIFEST:

EPA ID:	NYP004794962
Country:	USA
Name:	Con Edison
Address:	74 GEORGIA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	74 GEORGIA AVE
Location Address 2:	SB 26263
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Dennis Huacon
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported

CON EDISON (Continued) **S118256947**

Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/16/2015
Trans1 Recv Date: 06/16/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/18/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004794962
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002620036GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 500
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

AE199 **CON EDISON** **RCRA NonGen / NLR** **1019904197**
ESE **74 GEORGIA AVE** **FINDS** **NYP004794962**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.228 mi.
1204 ft. **Site 3 of 6 in cluster AE**

Relative: **Lower**
Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:		20150616
Handler Name:		Con Edison
Handler Address:		Georgia Ave
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004794962
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON (Continued) **1019904197**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150616
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150616
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019904197**

FINDS:
Registry ID: 110069691989

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019904197
Registry ID: 110069691989

DFR URL:
Name: CON EDISON
Address: 74 GEORGIA AVE
City,State,Zip: BROOKLYN, NY 11207

X200 **CON EDISON** **RCRA NonGen / NLR** **1019901864**
WNW **1385 HERKIMER ST** **FINDS** **NYP004766895**
1/8-1/4 **BROOKLYN, NY 11233** **ECHO**
0.229 mi.
1208 ft. **Site 5 of 10 in cluster X**

Relative: **Higher**
Actual: **89 ft.**

RCRA Listings:
Date Form Received by Agency: 20150413
Handler Name: Con Edison
Handler Address: Herkimer St
Handler City,State,Zip: BROOKLYN, NY 11233
EPA ID: NYP004766895
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported

CON EDISON (Continued) **1019901864**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1019901864**

Receive Date:	20150413
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069662181

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019901864
Registry ID:	110069662181

DFR URL:

Name:	CON EDISON
Address:	1385 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233

X201 **CON EDISON** **NJ MANIFEST** **S120670391**
WNW **1385 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.229 mi.
1208 ft. **Site 6 of 10 in cluster X**

Relative:
Higher

Actual:
89 ft.

NJ MANIFEST:

EPA ID:	NYP004766895
Name:	CON EDISON
Address:	1385 HERKIMER ST
City,State,Zip:	BROOKLYN, NY 11233
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004766895
Manifest Number:	002619179GBF
Date Shipped:	4/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **S120670391**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

X202 **CON EDISON** **NY MANIFEST** **S118089097**
WNW **1385 HERKIMER ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.229 mi.
1208 ft. **Site 7 of 10 in cluster X**

Relative:
Higher

Actual:
89 ft.

NY MANIFEST:

EPA ID:	NYP004766895
Country:	USA
Name:	Con Edison
Address:	1385 HERKIMER ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	1385 HERKIMER ST
Location Address 2:	SB 22030
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/13/2015
Trans1 Recv Date:	04/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/16/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004766895
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S118089097**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619179GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AF203 **CON ED** **NY MANIFEST** **S119076948**
NE **1716 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.229 mi.
1209 ft. **Site 1 of 6 in cluster AF**

Relative: **Higher**
Actual: **91 ft.**

NY MANIFEST:

EPA ID:	NYP004817219
Country:	USA
Name:	Con Ed
Address:	1716 BUSHWICK AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	1761 BUSHWICK AVE
Location Address 2:	SB 35041
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Ed

CON ED (Continued) **S119076948**

Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/03/2015
Trans1 Recv Date: 08/03/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/06/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004817219
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014472959JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 1000
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

AF204
NE
1/8-1/4
0.229 mi.
1209 ft.

CON EDISON
1716 BUSHWICK AVE
BROOKLYN, NY 11207

Site 2 of 6 in cluster AF

NJ MANIFEST **S120674850**
N/A

Relative:
Higher

Actual:
91 ft.

NJ MANIFEST:

EPA ID:	NYP004817219
Name:	CON EDISON
Address:	1716 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004817219
Manifest Number:	014472959JJK
Date Shipped:	8/3/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **S120674850**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AF205 **CON EDISON** **RCRA NonGen / NLR** **1019906095**
NE **1716 BUSHWICK AVE** **FINDS** **NYP004817219**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.229 mi.
1209 ft. **Site 3 of 6 in cluster AF**

Relative: **Higher**
Actual: **91 ft.**

RCRA Listings:

Date Form Received by Agency:		20150803
Handler Name:		Con Edison
Handler Address:		Bushwick Ave
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004817219
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

CON EDISON (Continued) **1019906095**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150803
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150803
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1019906095**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069703592

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906095
Registry ID: 110069703592

DFR URL:
Name: CON EDISON
Address: 1716 BUSHWICK AVE
City,State,Zip: BROOKLYN, NY 11207

AF206 **NYCTA (NON-HAZ CONTRACT)** **E MANIFEST** **1027973546**
NE **1720 BUSHWICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.230 mi.
1212 ft. **Site 4 of 6 in cluster AF**

Relative:
Higher

Actual:
89 ft.

E MANIFEST:
Manifest Tracking Number: 020072675JJK
Last Updated Date: 20191107
Shipped Date: 20190227
Received Date: 20190227
Manifest Status: Corrected
Submission Type: DataImage5Copy
Origin Type: Web
Generator EPA ID: NOT REQUIRED
Generator Name: Nycta (Non-Haz Contract)
Generator Location Street Number: Not reported
Generator Location Street 1: 1720 BUSHWICK AVENUE
Generator Location Street 2: Not reported
Generator Location City: BROOKLYN
Generator Location State: NY
Generator Location Zip: 11207

NYCTA (NON-HAZ CONTRACT) (Continued) **1027973546**

Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2 BROADWAY RM#A18.61
Generator Mail Street 2:	Not reported
Generator Mail City:	New York
Generator Mail Zip:	10004
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002200046
Designated Facility Name:	Cyclechem,Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	217 SOUTH FIRST STREET
Designated Facility Mail City:	ELIZABETHPORT
Designated Facility Mail Zip:	07206
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	217 SOUTH FIRST STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	ELIZABETHPORT
Designated Facility Location Zip:	07206
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	020072675JJK
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Allstate Power Vac Inc

Waste Line:

Manifest Tracking Number:	020072675JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3161
U.S. DOT Description:	Un3161, Waste Liquefied Gas, Flammable, N.O.S. (Diethyl Ether), 2.1, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	5
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0025
Waste Quantity, in Kilograms:	2.267575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2.267575
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	Y
Waste Type Discrepancy Indicator:	N

NYCTA (NON-HAZ CONTRACT) (Continued) **1027973546**

Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N

AF207 **CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1027974209**
NNE **1700 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.230 mi.
1213 ft. **Site 5 of 6 in cluster AF**

Relative: **Higher**

Actual: **97 ft.**

E MANIFEST:

Manifest Tracking Number:	006872876GBF
Last Updated Date:	20220307
Shipped Date:	20220222
Received Date:	20220222
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	1700 BUSHWICK AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1027974209**

Federal Waste:
- Manifest Tracking Number: 006872876GBF
- Waste Line Number: 1
- Federal Waste Code: D008
- Federal Waste: LEAD

State Waste:
- Manifest Tracking Number: 006872876GBF
- Waste Line Number: 1
- State Waste Code Owner: NY
- State Waste Code: T
- State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 006872876GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 006872876GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 200
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.1
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.1
- Waste Quantity, in Kilograms: 90.703
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 90.703
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

W208 **BP #30129** **RCRA-SQG** **1000553872**
ENE **32 JAMAICA AVE** **US AIRS** **NYD986963064**
1/8-1/4 **BROOKLYN, NY 11207** **FINDS**
0.230 mi. **ECHO**
1214 ft. **Site 9 of 11 in cluster W** **E MANIFEST**
NY MANIFEST
Relative: **NJ MANIFEST**
Lower

Actual: RCRA Listings:
63 ft.

Date Form Received by Agency:		20240703
Handler Name:		Bp #30129
Handler Address:		Jamaica Ave
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYD986963064
Contact Name:		REMY WEINSTEIN
Contact Address:		E 85TH ST #1010
Contact City,State,Zip:		NEW YORK, NY 10028
Contact Telephone:		212-517-7760
Contact Fax:		Not reported
Contact Email:		REMY@REMICAGROUP.COM
Contact Title:		CHEIF OPERATING OFFICER
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		E 85TH ST #1010
Mailing City,State,Zip:		NEW YORK, NY 10028
Owner Name:	Merel Glaubiger	
Owner Type:		Private
Operator Name:	Remica Property Group Corp	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking

BP #30129 (Continued) **1000553872**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20240703
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	REMICA PROPERTY GROUP CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	229 E 85TH ST #1010
Owner/Operator City,State,Zip:	NEW YORK, NY 10028
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	A C A MANAGEMENT SERVICES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	728 BLACKHORSE PIKE
Owner/Operator City,State,Zip:	TURNERSVILLE, NJ 08012
Owner/Operator Telephone:	609-227-6111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BP #30129 (Continued) **1000553872**

Owner/Operator Indicator: Owner
Owner/Operator Name: A C A MANAGEMENT SERVICES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 728 BLACKHORSE PIKE
Owner/Operator City,State,Zip: TURNERSVILLE, NJ 08012
Owner/Operator Telephone: 609-227-6111
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: A C A MANAGEMENT SERVICES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 728 BLACKHORSE PIKE
Owner/Operator City,State,Zip: TURNERSVILLE, NJ 08012
Owner/Operator Telephone: 609-227-6111
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MEREL GLAUBIGER
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 32 JAMAICA AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11207
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JAMAICA ISLAND CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 32 JAMAICA AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11207
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: A C A AMOCO #578
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

BP #30129 (Continued) **1000553872**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: A C A AMOCO #578	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: A C A AMOCO #578	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19910627
Handler Name: A C A AMOCO #578	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20240703
Handler Name: BP #30129	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

BP #30129 (Continued) **1000553872**

List of NAICS Codes and Descriptions:
NAICS Code: 457110
NAICS Description: Gasoline Stations With Convenience Stores

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000553872
Region Code: 02
Programmatic ID: AIR NY0000002610500144
Facility Registry ID: 110001572405
D and B Number: Not reported
Primary SIC Code: 5541
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610500144
Facility Registry ID: 110001572405
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-04-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110001572405

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.

BP #30129 (Continued) **1000553872**

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Registry ID: 110064404121

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000553872
Registry ID:	110001572405

DFR URL:

Name:	BP #30129
Address:	32 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY 11207

E MANIFEST:

Manifest Tracking Number:	009986489FLE
Last Updated Date:	20240812
Shipped Date:	20240702
Received Date:	20240730
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Bp #30129
Generator Location Street Number:	Not reported
Generator Location Street 1:	32 JAMAICA AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207-1834
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	229 EAST 85TH STREET #1010,
Generator Mail Street 2:	Not reported

BP #30129 (Continued) **1000553872**

Generator Mail City:	NEW YORK
Generator Mail Zip:	10028
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys (Pa) Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 SANDSTONE DRIVE
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 SANDSTONE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	HATFIELD
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	009987006FLE
Last Updated Date:	20230123
Shipped Date:	20221225
Received Date:	20230117
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Bp #30129
Generator Location Street Number:	Not reported
Generator Location Street 1:	32 JAMAICA AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207-1834
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	229 EAST 85TH STREET #1010,
Generator Mail Street 2:	Not reported
Generator Mail City:	NEW YORK
Generator Mail Zip:	10028
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440

BP #30129 (Continued) **1000553872**

Designated Facility Location State: PA
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 009987006FLE
Waste Line Number: 1
Federal Waste Code: D001
Federal Waste: IGNITABLE WASTE

Manifest Tracking Number: 009987006FLE
Waste Line Number: 1
Federal Waste Code: D018
Federal Waste: BENZENE

State Waste:
Manifest Tracking Number: 009987006FLE
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: B
State Waste: Incineration, heat recovery, burning. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 009987006FLE
Transporter Line Number: 1
Transporter EPA ID: PAD982661381
Transporter Name: Republic Environmental Systems

Manifest Tracking Number: 009987006FLE
Transporter Line Number: 2
Transporter EPA ID: NYR000191726
Transporter Name: Island Pump & Tank Corp.

Waste Line:
Manifest Tracking Number: 009987006FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3175
U.S. DOT Description: Un3175 Waste Solids Containing Flammable Liquid, N.O.S. (Benzene) Ii 4.1 D001=100# D018=10#
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 215
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.1075
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.1075
Waste Quantity, in Kilograms: 97.50573
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 97.50573

BP #30129 (Continued) **1000553872**

Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

NY MANIFEST:

EPA ID:	NYD986963064
Country:	USA
Name:	A C A Amoco #578
Address:	32 JAMAICA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207-1834
Zip 4:	Not reported
Location Address 1:	32 JAMAICA AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	A C A Amoco #578
Mailing Contact:	A C A Amoco #578
Mailing Address 1:	32 JAMAICA AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11207
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9494605200

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000021036
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/2007
Trans1 Recv Date:	01/22/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/22/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986963064
Trans1 EPA ID:	Not reported

BP #30129 (Continued) **1000553872**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001274583JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Benzene
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000023036
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2008
Trans1 Recv Date:	10/23/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986963064
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001274849JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

BP #30129 (Continued) **1000553872**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Benzene
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

NJ MANIFEST:

EPA ID:	NYD986963064
Name:	A C A AMOCO #578
Address:	32 JAMAICA AVE
City,State,Zip:	BROOKLYN, NY 11207-1834
County:	Not reported
Mailing Address:	JAMAICA AVE
Mailing City,State,Zip:	BROOKLYN, NY 11207
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYD986963064
Manifest Number:	001274849JJK
Date Shipped:	10/23/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

BP #30129 (Continued) **1000553872**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/23/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/23/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	200
Unit:	P

EPA ID:	NYD986963064
Manifest Number:	001274583JJK
Date Shipped:	01/22/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/22/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

BP #30129 (Continued) **1000553872**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/22/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H14
Quantity:	200
Unit:	P

W209 **JAMAICA ISLAND CORP.** **NY UST** **U002034340**
ENE **32 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.230 mi.
1214 ft. **Site 10 of 11 in cluster W**

Relative:
Lower

Actual:
63 ft.

UST:

Name:	JAMAICA ISLAND CORP.
Address:	32 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-602003 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/21/2028
UTM X:	593078.15288
UTM Y:	4503509.73992
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23962
Affiliation Type:	Facility Operator
Company Name:	RAM JAN
Contact Type:	Not reported
Contact Name:	RAM JAN
Address1:	32 JAMAICA AVE
Address2:	Not reported

JAMAICA ISLAND CORP. (Continued) **U002034340**

City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 345-0885
EMail:	RAMJAN57@yahoo.com
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-09-13

Site Id:	23962
Affiliation Type:	Emergency Contact
Company Name:	MEREL GLAUBIGER, TRUSTEE
Contact Type:	Not reported
Contact Name:	REMY ROIZEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 355-8474
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-09-13

Site Id:	23962
Affiliation Type:	Facility Owner
Company Name:	MITCHELL JAY GOODSTEIN AS TRUSTEE
Contact Type:	CHIEF OPERATING OFFICER
Contact Name:	REMY ROIZEN
Address1:	3466 JACKSON ST
Address2:	Not reported
City:	SAN FRANCISCO
State:	CA
Zip Code:	94118
Country Code:	001
Phone:	(415) 563-3341
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2023-09-12

Site Id:	23962
Affiliation Type:	Mail Contact
Company Name:	REMICA PROPERTY GROUP CORP.
Contact Type:	Not reported
Contact Name:	REMY ROIZEN
Address1:	229 EAST 85TH STREET
Address2:	#1010
City:	NEW YORK
State:	NY
Zip Code:	10028
Country Code:	001
Phone:	(212) 517-7760
EMail:	REMY@REMICAGROUP.COM

JAMAICA ISLAND CORP. (Continued) **U002034340**

Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-09-13

Tank Info:

Tank Number:	05
Tank ID:	208456
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	08/01/2005
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	LABATIST
Last Modified:	03/28/2024

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
L99 - Piping Leak Detection - Other
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A00 - Tank Internal Protection - None

Tank Number:	06
Tank ID:	208457
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	08/01/2005
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	-

JAMAICA ISLAND CORP. (Continued) **U002034340**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: LABATIST
Last Modified: 03/28/2024

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L99 - Piping Leak Detection - Other
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass

Tank Number: 1
Tank ID: 48704
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 01/01/1972
Date Tank Closed: 08/01/2005
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 03/17/2005
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
B02 - Tank External Protection - Original Sacrificial Anode
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
H05 - Tank Leak Detection - In-Tank System (ATG)

JAMAICA ISLAND CORP. (Continued) **U002034340**

Tank Number:	2
Tank ID:	48705
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	01/01/1972
Date Tank Closed:	08/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	03/17/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	3
Tank ID:	48706
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	01/01/1972
Date Tank Closed:	08/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	03/17/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

JAMAICA ISLAND CORP. (Continued) **U002034340**

G00 - Tank Secondary Containment - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	4
Tank ID:	48707
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	01/01/1972
Date Tank Closed:	08/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	03/17/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H05 - Tank Leak Detection - In-Tank System (ATG)

W210 **JAMAICA ISLAND CORP.** **UST FINDER** **1028572615**
ENE **32 JAMAICA AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.230 mi.
1214 ft. **Site 11 of 11 in cluster W**

Relative:
Lower

Actual:
63 ft.

UST FINDER:

Object ID:	295897
Facility ID:	NY23962
Name:	JAMAICA ISLAND CORP.
Address:	32 JAMAICA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	2
Closed USTs:	4
TOS USTs:	0
Population 1500ft:	3617
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.89863
Y Coord:	40.677222
Latitude:	40.677222
Longitude:	-73.89863

UST FINDER:

Object ID:	1221385
Facility ID:	NY23962
Tank ID:	NY28254
Tank Status:	Closed
Installation Date:	1972/01/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1221386
Facility ID:	NY23962
Tank ID:	NY28255
Tank Status:	Closed
Installation Date:	1972/01/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

JAMAICA ISLAND CORP. (Continued) **1028572615**

Object ID:	1221387
Facility ID:	NY23962
Tank ID:	NY30117
Tank Status:	Closed
Installation Date:	1972/01/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1221388
Facility ID:	NY23962
Tank ID:	NY30118
Tank Status:	Closed
Installation Date:	1972/01/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1221389
Facility ID:	NY23962
Tank ID:	NY28256
Tank Status:	Open
Installation Date:	2005/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1221390
Facility ID:	NY23962
Tank ID:	NY30672
Tank Status:	Open
Installation Date:	2005/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported

AG211 **CON ED - MH 5143** **RCRA NonGen / NLR** **1007206488**
SSW **LIBERTY AVE & POWELL ST** **NY MANIFEST** **NYP004010690**
1/8-1/4 **BROOKLYN, NY 11212**
0.234 mi.
1235 ft. **Site 1 of 7 in cluster AG**

Relative: **Lower**
Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - Mh 5143
Handler Address:	Liberty Ave & Powell St
Handler City,State,Zip:	BROOKLYN, NY 11212-0000
EPA ID:	NYP004010690
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported

CON ED - MH 5143 (Continued) **1007206488**

Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		CONSOLIDATED EDISON INC
Mailing City,State,Zip:		NEW YORK, NY 10003-0000
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

CON ED - MH 5143 (Continued) **1007206488**

Historic Generators:

Receive Date:		19980227
Handler Name:	CON ED - MH 5143	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		19980228
Handler Name:	CON ED - MH 5143	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		19980226
Handler Name:	CON ED - MH 5143	
Federal Waste Generator Description:		Large Quantity Generator
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	Electric Power Generation, Transmission And Distribution

NAICS Code:	22111
NAICS Description:	Electric Power Generation

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON ED - MH 5143 (Continued) **1007206488**

NY MANIFEST:

EPA ID:	NYP004139515
Country:	USA
Name:	Consolidated Edison
Address:	LIBERTY AVE & POWELL ST
Address 2:	S OF & E OF POWELL ST
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	POWELL ST & LIBERTY AV MH5143
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/2006
Trans1 Recv Date:	01/24/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/25/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004139515
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	NYE1605771
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code a:	B007
Waste Code b:	Not reported

CON ED - MH 5143 (Continued) **1007206488**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

EPA ID:	NYP004010690
Country:	USA
Name:	Consolidated Edison
Address:	LIBERTY AVE & POWELL ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11212-0000
Zip 4:	Not reported
Location Address 1:	MH 5143 - LIBERTY AVE
Location Address 2:	Not reported
Location City,State,Zip:	QUEENS, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	NYG0903582
Manifest Status:	Not reported
Trans1 State ID:	80336AB
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004010690
Trans1 EPA ID:	NYD006982359

CON ED - MH 5143 (Continued) **1007206488**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Cubic Yards
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0904959
Manifest Status:	Not reported
Trans1 State ID:	20856AD
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004010690
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B003

CON ED - MH 5143 (Continued) **1007206488**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00455
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYG0905247
Manifest Status:	Not reported
Trans1 State ID:	20854AD
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1997
Trans1 Recv Date:	08/28/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/28/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004010690
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B003
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00341
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

AG212 **CON EDISON MANHOLE 5142** **RCRA NonGen / NLR** **1010787494**
SSW **POWELL ST & LIBERTY AVE** **NY MANIFEST** **NYP004150199**
1/8-1/4 **BROOKLYN, NY 11201**
0.234 mi.
1235 ft. **Site 2 of 7 in cluster AG**

Relative: **Lower**
Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:		20080315
Handler Name:		Con Edison Manhole 5142
Handler Address:		Powell St & Liberty Ave
Handler City,State,Zip:		BROOKLYN, NY 11201
EPA ID:		NYP004150199
Contact Name:		MICHAEL D'AGOSTINO
Contact Address:		4 IRVING PL, RM 828
Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		212-580-8383
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON MANHOLE 5142 (Continued) **1010787494**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20080314
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20080315
Handler Name: CON EDISON MANHOLE 5142	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON MANHOLE 5142 (Continued) **1010787494**

NY MANIFEST:

EPA ID:	NYP004150199
Country:	USA
Name:	Consolidated Edison
Address:	POWELL ST & LIBERTY AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	LIBERTY AVE & POWELL ST
Location Address 2:	MH 5142
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklyn Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/27/2007
Trans1 Recv Date:	04/27/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004150199
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001436047FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	B007
Waste Code b:	Lead

CON EDISON MANHOLE 5142 (Continued) **1010787494**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

AG213 **CONSOLIDATED EDISON** **NY MANIFEST** **S123252422**
SSW **LIBERTY AVE & POWELL ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.234 mi.
1235 ft. **Site 3 of 7 in cluster AG**

Relative:
Lower

Actual:
56 ft.

NY MANIFEST:

EPA ID:	NYP004147526
Country:	USA
Name:	Consolidated Edison
Address:	LIBERTY AVE & POWELL ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	LIBERTY AVE & POWELL ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Woo Dong Kim
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/25/2007
Trans1 Recv Date:	01/25/2007

CONSOLIDATED EDISON (Continued) **S123252422**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/29/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	000331309FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	B007
Waste Code b:	Lead
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/11/2007
Trans1 Recv Date:	01/11/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/12/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004147526
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	000331139FLE

CONSOLIDATED EDISON (Continued) **S123252422**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	B007
Waste Code b:	Lead
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

AG214 **CON EDISON MANHOLE 5143** **RCRA NonGen / NLR** **1010326780**
SSW **LIBERTY AVE & POWELL ST** **NYP004143012**
1/8-1/4 **BROOKLYN, NY 11201**
0.234 mi.
1235 ft. **Site 4 of 7 in cluster AG**

Relative: **Lower**

Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:	20061117
Handler Name:	Con Edison Manhole 5143
Handler Address:	Liberty Ave & Powell St
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004143012
Contact Name:	DANIEL PONTECORVO
Contact Address:	4 IRVING PL, RM 828
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-580-8383
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

CON EDISON MANHOLE 5143 (Continued) **1010326780**

State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:		20061115
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Not reported
State District Owner:		Not reported
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No

CON EDISON MANHOLE 5143 (Continued) **1010326780**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20061116
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20061117
Handler Name: CON EDISON MANHOLE 5143	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG215 **CON EDISON MANHOLE 5143** **RCRA NonGen / NLR** **1010326170**
SSW **LIBERTY AVE & POWELL ST** **NYP004139515**
1/8-1/4 **BROOKLYN, NY 11201**
0.234 mi.
1235 ft. **Site 5 of 7 in cluster AG**

Relative:
Lower

Actual:
56 ft.

RCRA Listings:

Date Form Received by Agency:	20060707
Handler Name:	Con Edison Manhole 5143
Handler Address:	Liberty Ave & Powell St
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYP004139515
Contact Name:	ANTONIO DELGADO
Contact Address:	4 IRVING PL, RM 828

CON EDISON MANHOLE 5143 (Continued) **1010326170**

Contact City,State,Zip:		NEW YORK, NY 10003
Contact Telephone:		718-204-4201
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No

CON EDISON MANHOLE 5143 (Continued) **1010326170**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20060705
Handler Name: CON EDISON
Federal Waste Generator Description: Not reported
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060706
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060707
Handler Name: CON EDISON MANHOLE 5143
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG216 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241813**
SSW **POWELL & LIBERTY AVE MH05142** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.235 mi.
1240 ft. **Site 6 of 7 in cluster AG**

Relative:
Lower

Actual:
56 ft.

NY MANIFEST:

EPA ID:	NYP004103420
Country:	USA
Name:	Consolidated Edison
Address:	POWELL & LIBERTY AVE MH05142
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	POWELL & LIBERTY AVE MH05142
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Consolidated Edison
Mailing Contact:	Franklin Murray
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	NYE0513315
Manifest Status:	Not reported
Trans1 State ID:	31877AJ
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	10/09/2002
Trans1 Recv Date:	10/09/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/10/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004103420
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CONSOLIDATED EDISON (Continued) **1009241813**

Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00273
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYE0460917
Manifest Status: Not reported
Trans1 State ID: SM1708
Year: 2002
Trans2 State ID: Not reported
Generator Ship Date: 10/10/2002
Trans1 Recv Date: 10/10/2002
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/11/2002
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004103420
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 01327
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYE0499239

CONSOLIDATED EDISON (Continued) **1009241813**

Manifest Status:	Not reported
Trans1 State ID:	28190AV
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2002
Trans1 Recv Date:	10/10/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/15/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004103420
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00268
Units:	Kilograms
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00
Waste Code 7:	B007
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00071
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

AA217 **BRADFORD SWETT** **NY UST** **U000396120**
NNW **2000 EASTERN PARKWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.235 mi.
1243 ft. **Site 6 of 9 in cluster AA**

Relative:
Higher

Actual:
96 ft.

UST:

Name:	BRADFORD SWETT
Address:	2000 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-145483 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592491.12258
UTM Y:	4503785.44793
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	4166
Affiliation Type:	Facility Owner
Company Name:	AMERICAN IAN CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	530 E 90 ST
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10128
Country Code:	001
Phone:	(212) 722-6775
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4166
Affiliation Type:	Mail Contact
Company Name:	BRADFORD SWETT
Contact Type:	Not reported
Contact Name:	SUPER/FACILITY MANAGER
Address1:	2000 EASTERN PARKWAY
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(212) 722-7550
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4166
Affiliation Type:	Facility Operator
Company Name:	BRADFORD SWETT
Contact Type:	Not reported
Contact Name:	BRADFORD SWETT
Address1:	Not reported

BRADFORD SWETT (Continued) **U000396120**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 772-7550
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4166
Affiliation Type:	Emergency Contact
Company Name:	AMERICAN IAN CORP
Contact Type:	Not reported
Contact Name:	IAN LESSER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(310) 578-6752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	5625
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	12/01/1954
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

BRADFORD SWETT (Continued) **U000396120**

D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)

AA218 **BRADFORD SWETT** **UST FINDER** **1028585491**
NNW **2000 EASTERN PARKWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.235 mi.
1243 ft. **Site 7 of 9 in cluster AA**

Relative:
Higher

Actual:
96 ft.

UST FINDER:

Object ID:	295992
Facility ID:	NY4166
Name:	BRADFORD SWETT
Address:	2000 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11233
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	8106
Private Wells 1500ft:	9
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.905962
Y Coord:	40.6789830000001
Latitude:	40.678983
Longitude:	-73.905962

UST FINDER:

Object ID:	1266874
Facility ID:	NY4166
Tank ID:	NY3372
Tank Status:	Closed
Installation Date:	1954/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

U219 **CON EDISON** **E MANIFEST** **1031622813**
SSE **103 SNEDIKER AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.236 mi.
1245 ft. **Site 10 of 10 in cluster U**

Relative: **Lower**

Actual: **54 ft.**

E MANIFEST:

Manifest Tracking Number:	006874683GBF
Last Updated Date:	20210825
Shipped Date:	20210804
Received Date:	20210805
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	103 SNEDIKER AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Federal Waste:

Manifest Tracking Number:	006874683GBF
Waste Line Number:	1
Federal Waste Code:	D008
Federal Waste:	LEAD

State Waste:

Manifest Tracking Number:	006874683GBF
Waste Line Number:	1
State Waste Code Owner:	NY
State Waste Code:	T

CON EDISON (Continued) **1031622813**

State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 006874683GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 006874683GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq (Lead)
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 1000
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.5
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.5
- Waste Quantity, in Kilograms: 453.515
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 453.515
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

AD220 **LOT 6,TAXBLOCK 1436** **NY VCP S120839002**
West **1860 EASTERN PARKWAY** **NY E DESIGNATION N/A**
1/8-1/4 **BROOKLYN, NY** **NY NYC OER**
0.237 mi.
1249 ft. **Site 4 of 5 in cluster AD**

Relative: **Higher**
Actual: **76 ft.**

VCP NYC:
- Project ID: 17TMP0413K,18EH-N003K,18CVCP020K
- Name: 1860 EASTERN PARKWAY
- Address: 1860 EASTERN PARKWAY
- City,State,Zip: NEW YORK CITY, NY
- Borough: Brooklyn

LOT 6,TAXBLOCK 1436 (Continued) **S120839002**

BBL:	3014360006
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.675822
Longitude:	-73.908126
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3337899
NTA:	Ocean Hill

E DESIGNATION:

Name:	LOT 6,TAXBLOCK 1436
Address:	1860 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	6
Tax Block:	1436
Borough Code:	Not reported
E-No:	E-400
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	17DCP068K
Ulurp Number:	N170143ZRK; C170142ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	1860 EASTERN PARKWAY
Address:	1860 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Latitude:	40.675822
Longitude:	-73.908126
OER Project Numbers:	17TMP0413K,18EH-N003K,18CVCP020K
BBL:	3014360006
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3337899
NTA:	Ocean Hill

AD221 **HARRY T NANCE APARTMENTS** **NY UST** **U004341940**
West **1860 EASTERN PARKWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.237 mi.
1249 ft. **Site 5 of 5 in cluster AD**

Relative:
Higher

Actual:
76 ft.

UST:

Name:	HARRY T NANCE APARTMENTS
Address:	1860 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11233
Id/Status:	2-613171 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Other

Affiliation Records:

Site Id:	609577
Affiliation Type:	Facility Owner
Company Name:	TRUE HOLY CHURCH OF GOD
Contact Type:	SR. PROJECT MANAGER
Contact Name:	DREW VANDERBURG
Address1:	1981 FULTON STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 366-3800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-06

Site Id:	609577
Affiliation Type:	Mail Contact
Company Name:	RISEBORO COMMUNITY PARTNERSHIP, INC.
Contact Type:	Not reported
Contact Name:	DREW VANDERBURG
Address1:	217 WYCKOFF AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 366-3800
EMail:	DVANDERBURG@RISEBORO.ORG
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-06

Site Id:	609577
Affiliation Type:	Facility Operator
Company Name:	HARRY T NANCE APARTMENTS
Contact Type:	Not reported
Contact Name:	HARRY T NANCE APARTMENTS, HDFC, INC.
Address1:	Not reported

HARRY T NANCE APARTMENTS (Continued) **U004341940**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-06

Site Id:	609577
Affiliation Type:	Emergency Contact
Company Name:	TRUE HOLY CHURCH OF GOD
Contact Type:	Not reported
Contact Name:	DREW VANDERBURG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 366-3800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-08-06

Tank Info:

Tank Number:	01
Tank ID:	287188
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	10/02/2018
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C01 - Pipe Location - Aboveground
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None

HARRY T NANCE APARTMENTS (Continued) **U004341940**

F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None

AA222 **AMERICAN TRUCK REPAIRS** **UST FINDER** **1028571725**
NNW **2020 EASTERN PARKWAY** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.238 mi.
1259 ft. **Site 8 of 9 in cluster AA**

Relative:
Higher

Actual:
96 ft.

UST FINDER:

Object ID:	296012
Facility ID:	NY22283
Name:	AMERICAN TRUCK REPAIRS
Address:	2020 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	8
TOS USTs:	0
Population 1500ft:	6864
Private Wells 1500ft:	6
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.905203
Y Coord:	40.6794810000001
Latitude:	40.679481
Longitude:	-73.905203

UST FINDER:

Object ID:	1217694
Facility ID:	NY22283
Tank ID:	NY26352
Tank Status:	Closed
Installation Date:	1963/08/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1217695
Facility ID:	NY22283
Tank ID:	NY26353

AMERICAN TRUCK REPAIRS (Continued) **1028571725**

Tank Status: Closed
Installation Date: 1963/08/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1217696
Facility ID: NY22283
Tank ID: NY26354
Tank Status: Closed
Installation Date: 1963/08/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1217697
Facility ID: NY22283
Tank ID: NY26765
Tank Status: Closed
Installation Date: 1963/08/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1217698
Facility ID: NY22283
Tank ID: NY29549
Tank Status: Closed
Installation Date: 1963/08/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1217699
Facility ID: NY22283
Tank ID: NY111231
Tank Status: Closed
Installation Date: 1963/08/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1217700
Facility ID: NY22283
Tank ID: NY111232
Tank Status: Closed
Installation Date: 1963/08/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

AMERICAN TRUCK REPAIRS (Continued) **1028571725**

Object ID:	1217701
Facility ID:	NY22283
Tank ID:	NY111233
Tank Status:	Closed
Installation Date:	1963/08/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

AA223 **AMERICAN TRUCK REPAIRS** **NY UST** **U001841386**
NNW **2020 EASTERN PARKWAY** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.238 mi.
1259 ft. **Site 9 of 9 in cluster AA**

Relative:
Higher

Actual:
96 ft.

UST:

Name:	AMERICAN TRUCK REPAIRS
Address:	2020 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-600300 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592543.04959
UTM Y:	4503833.95960
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	22283
Affiliation Type:	Facility Owner
Company Name:	MAZALIKO INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1143 E. 8TH ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11230
Country Code:	001
Phone:	(718) 338-8112
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22283
Affiliation Type:	Mail Contact
Company Name:	MAZALIKO INC.
Contact Type:	Not reported
Contact Name:	DAVID ISRAELI
Address1:	1143 EAST 8TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11230

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

Country Code:	001
Phone:	(718) 338-8112
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	22283
Affiliation Type:	Facility Operator
Company Name:	AMERICAN TRUCK REPAIRS
Contact Type:	Not reported
Contact Name:	AMERICAN TRUCK REPAIRS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 443-2323
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	22283
Affiliation Type:	Emergency Contact
Company Name:	MAZALIKO INC.
Contact Type:	Not reported
Contact Name:	DAVID ISRAELI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 879-5527
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	42065
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1963
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Concrete
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

Date Test: 03/01/1990
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle

Tank Number: 002
Tank ID: 42066
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1963
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: ZZ
Date Test: 03/01/1990
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle

Tank Number: 003
Tank ID: 42067
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1963
Date Tank Closed: 12/01/1999
Registered: True

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: ZZ
Date Test: 03/01/1990
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle

Tank Number: 004
Tank ID: 42068
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 08/01/1963
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Concrete
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: ZZ
Date Test: 03/01/1990
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle

Tank Number: 005
Tank ID: 42069

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1963
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Concrete
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	03/01/1990
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle

Tank Number:	006
Tank ID:	42070
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1963
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Concrete
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	03/01/1990
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number:	007
Tank ID:	42071
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1963
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Concrete
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	03/01/1990
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Number:	008
Tank ID:	42072
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	08/01/1963
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Concrete
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	03/01/1990
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
I05 - Overfill - Vent Whistle
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

SPILLS:

Name:	2020 EASTERN PARKWAY
Address:	2020 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0206799 / 2002-10-04
Facility ID:	0206799
Facility Type:	ER
DER Facility ID:	216093
Site ID:	265198
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-10-01
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-10-01
CID:	204
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-01
Spill Record Last Update:	2002-11-25
Spiller Name:	RUSS MAGLIO
Spiller Company:	2020 EASTERN PARKWAY
Spiller Address:	2020 EASTERN PARKWAY
Spiller Company:	001
Contact Name:	RUSS MAGLIO
Latitude:	40.6801417
Longitude:	-73.9051631
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 10/4/02 TJD Site inspected 10/3. Location is a former gas station now operated as a truck repair garage. Current business on site is A & N Brake and Clutch (owner:Alon Yemini 718-443-2323) which has been operating on site for one month. Several minor petroleum spills were noted both inside and ouside of building, owner immediately dispatched employees to clean up spills on concrete/aphalt using absorbents. Clean-up completed while inpection was conducted. Buried waste oil tank of unknown capacity was identified

AMERICAN TRUCK REPAIRS (Continued) **U001841386**

on site, owner was unable to produce a PBS registation for this tank and was directed to empty tank
and obtain registration from DEC. Database search revealed a total of (8) gasoline UST's exist on
site an are of unknown status. PBS records (2-600300) indicate registration expired 8/29/96. Last
tank tests were performed in 1990 on these tanks. Surface spill closed. Out of compliance tanks
referred to PBS for follow-up. FAX 443-2422.

Remarks: OLD GAS STATION - NOW DOING REPAIRS - POSSIBLY DUMPING USED OIL ETC *****NRC # 624474****** CALLER WANTED TO BE ANNOYMOUS NAME-HAYDEE IRIZARRI PHONE 718-9190566

All Materials:

Site ID:	265198
Operable Unit ID:	858563
Operable Unit:	01
Material ID:	517394
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AH224 **HESS#32507** **UST FINDER RELEASE** **1029064745**
North **1630 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.239 mi.
1260 ft. **Site 1 of 13 in cluster AH**

Relative: **Higher**
Actual: **100 ft.**

UST FINDER RELEASE:

Object ID:	258796
Facility ID:	NY201627
Lust ID:	NY405282
Name:	HESS#32507
Address:	1630 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2004/08/13 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2747
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported

HESS#32507 (Continued) **1029064745**

WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.9025999999999
Y Coord:	40.6805600000001
Latitude:	40.68056
Longitude:	-73.9026

AH225 **SPEEDWAY # 7812** **NY UST U001835741**
North **1630 BUSHWICK AVENUE** **NY AST N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.239 mi.
1260 ft. **Site 2 of 13 in cluster AH**

Relative:
Higher

Actual:
100 ft.

UST:

Name:	SPEEDWAY # 7812
Address:	1630 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Id/Status:	2-297739 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	592732.71498
UTM Y:	4503833.77018
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	13763
Affiliation Type:	Emergency Contact
Company Name:	HESS RETAIL STORES LLC
Contact Type:	Not reported
Contact Name:	SCOTT FLEMING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(937) 207-1832
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-07-17

Site Id:	13763
Affiliation Type:	Facility Owner
Company Name:	SPEEDWAY LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	500 SPEEDWAY DRIVE

SPEEDWAY # 7812 (Continued) **U001835741**

Address2:	Not reported
City:	ENON
State:	OH
Zip Code:	45323
Country Code:	001
Phone:	(732) 738-2925
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-11

Site Id:	13763
Affiliation Type:	Mail Contact
Company Name:	SPEEDWAY LLC
Contact Type:	Not reported
Contact Name:	MICHAEL MATRI
Address1:	500 SPEEDWAY DRIVE
Address2:	Not reported
City:	ENON
State:	OH
Zip Code:	45323
Country Code:	001
Phone:	(732) 738-2925
EMail:	MMATRI@SPEEDWAY.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-04-12

Site Id:	13763
Affiliation Type:	Facility Operator
Company Name:	SPEEDWAY # 7812
Contact Type:	Not reported
Contact Name:	SITE MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 443-1545
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-10-23

Tank Info:

Tank Number:	10
Tank ID:	46801
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	05/01/1990
Date Tank Closed:	09/01/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel

SPEEDWAY # 7812 (Continued) **U001835741**

Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 20
Date Test: 07/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 11
Tank ID: 46802
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: 05/01/1990
Date Tank Closed: 08/31/2015
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 20
Date Test: 07/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG

SPEEDWAY # 7812 (Continued) **U001835741**

G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 12
Tank ID: 46803
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: 05/01/1990
Date Tank Closed: 09/02/2015
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 20
Date Test: 07/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 13
Tank ID: 46804
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: 05/01/1990
Date Tank Closed: 09/02/2015
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 20
Date Test: 07/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

SPEEDWAY # 7812 (Continued) **U001835741**

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	14
Tank ID:	46805
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	05/01/1990
Date Tank Closed:	09/01/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	20
Date Test:	07/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number:	15
Tank ID:	16158
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1990
Date Tank Closed:	09/04/2015

SPEEDWAY # 7812 (Continued) **U001835741**

Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 20
Date Test: 07/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
K01 - Spill Prevention - Catch Basin
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J00 - Dispenser - None

Tank Number: 16
Tank ID: 261715
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1997
Date Tank Closed: 03/22/2016
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None

SPEEDWAY # 7812 (Continued) **U001835741**

Tank Number:	17
Tank ID:	261716
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1997
Date Tank Closed:	03/22/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None

Tank Number:	9
Tank ID:	16157
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	05/01/1990
Date Tank Closed:	08/31/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	20
Date Test:	07/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm

SPEEDWAY # 7812 (Continued) **U001835741**

K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

AST:

Name:	SPEEDWAY # 7812
Address:	1630 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-297739
Program Type:	PBS
UTM X:	592732.71498
UTM Y:	4503833.77018
Expiration Date:	N/A
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	13763
Affiliation Type:	Emergency Contact
Company Name:	HESS RETAIL STORES LLC
Contact Type:	Not reported
Contact Name:	SCOTT FLEMING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(937) 207-1832
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2018-07-17

Site Id:	13763
Affiliation Type:	Facility Owner
Company Name:	SPEEDWAY LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	500 SPEEDWAY DRIVE
Address2:	Not reported
City:	ENON
State:	OH
Zip Code:	45323
Country Code:	001
Phone:	(732) 738-2925
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-05-11

SPEEDWAY # 7812 (Continued) **U001835741**

Site Id:	13763
Affiliation Type:	Mail Contact
Company Name:	SPEEDWAY LLC
Contact Type:	Not reported
Contact Name:	MICHAEL MATRI
Address1:	500 SPEEDWAY DRIVE
Address2:	Not reported
City:	ENON
State:	OH
Zip Code:	45323
Country Code:	001
Phone:	(732) 738-2925
EMail:	MMATRI@SPEEDWAY.COM
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-04-12

Site Id:	13763
Affiliation Type:	Facility Operator
Company Name:	SPEEDWAY # 7812
Contact Type:	Not reported
Contact Name:	SITE MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 443-1545
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-10-23

Tank Info:

Tank Number:	0D6
Tank Id:	16154
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported

SPEEDWAY # 7812 (Continued) **U001835741**

Install Date:	11/01/1973
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1990
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	0F8
Tank Id:	16156
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1973
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1990
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	0P4
Tank Id:	16152
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

SPEEDWAY # 7812 (Continued) **U001835741**

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1973
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/01/1990
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: gasoline

Tank Number: 0P5
Tank Id: 16153
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1973
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/01/1990
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: gasoline

Tank Number: 0R1
Tank Id: 16149
Material Code: 0009
Common Name of Substance: Gasoline

SPEEDWAY # 7812 (Continued) **U001835741**

Equipment Records:
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1973
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1990
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	gasoline
Tank Number:	0U2
Tank Id:	16150
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1973
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1990
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

SPEEDWAY # 7812 (Continued) **U001835741**

Material Name: gasoline

Tank Number: 0U3
Tank Id: 16151
Material Code: 0009
Common Name of Substance: Gasoline

Equipment Records:
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1973
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/01/1990
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: gasoline

Tank Number: 0W7
Tank Id: 16155
Material Code: 9999
Common Name of Substance: Other

Equipment Records:
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 11/01/1973

SPEEDWAY # 7812 (Continued) **U001835741**

Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1990
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

AH226 **HESS #32507** **UST FINDER RELEASE** **1029064744**
North **1630 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.239 mi.
1260 ft. **Site 3 of 13 in cluster AH**

Relative:
Higher

Actual:
100 ft.

UST FINDER RELEASE:

Object ID:	258797
Facility ID:	NY201627
Lust ID:	NY405822
Name:	HESS #32507
Address:	1630 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2004/08/27 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2747
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.9025999999999
Y Coord:	40.6805600000001
Latitude:	40.68056
Longitude:	-73.9026

AH227 **HESS-MERIT STATION** **UST FINDER RELEASE** **1029076826**
North **1630-76 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.239 mi.
1260 ft. **Site 4 of 13 in cluster AH**

Relative: UST FINDER RELEASE:
Higher

Actual:
100 ft.

Object ID:	258798
Facility ID:	NY59940
Lust ID:	NY9704866
Name:	HESS-MERIT STATION
Address:	1630-76 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1997/07/23 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2743
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.9025999999999
Y Coord:	40.6805800000001
Latitude:	40.6805799999999
Longitude:	-73.9026

AH228 **SPEEDWAY # 7812** **UST FINDER** **1028568277**
North **1630 BUSHWICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.239 mi.
1260 ft. **Site 5 of 13 in cluster AH**

Relative: UST FINDER:
Higher

Actual:
100 ft.

Object ID:	296055
Facility ID:	NY13763
Name:	SPEEDWAY # 7812
Address:	1630 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	9
TOS USTs:	0

SPEEDWAY # 7812 (Continued) **1028568277**

Population 1500ft:	2418
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.9022439999999
Y Coord:	40.6803090000001
Latitude:	40.680309
Longitude:	-73.902244

UST FINDER:

Object ID:	1203265
Facility ID:	NY13763
Tank ID:	NY14464
Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203266
Facility ID:	NY13763
Tank ID:	NY15543
Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203267
Facility ID:	NY13763
Tank ID:	NY15544
Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203268
Facility ID:	NY13763
Tank ID:	NY15545

SPEEDWAY # 7812 (Continued) **1028568277**

Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203269
Facility ID:	NY13763
Tank ID:	NY15816
Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203270
Facility ID:	NY13763
Tank ID:	NY17643
Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203271
Facility ID:	NY13763
Tank ID:	NY109551
Tank Status:	Closed
Installation Date:	1990/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203272
Facility ID:	NY13763
Tank ID:	NY109552
Tank Status:	Closed
Installation Date:	1997/07/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1203273
Facility ID:	NY13763
Tank ID:	NY109553
Tank Status:	Closed
Installation Date:	1997/07/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

AH229 **HESS-MERIT GAS STATION** **NY LTANKS** **S104514567**
North **1630-76 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.239 mi.
1260 ft. **Site 6 of 13 in cluster AH**

Relative:
Higher

Actual:
100 ft.

LTANKS:

Name:	HESS-MERIT GAS STATION
Address:	1630-76 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9704864 / 2003-03-18
Facility ID:	9704864
Site ID:	290955
Spill Date:	1997-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1997-07-23
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-07-23
Spill Record Last Update:	2003-03-18
Spiller Name:	ANDY FORD
Spiller Company:	MERIT GAS STATION
Spiller Address:	1630-76 BUSHWICK AV
Spiller County:	001
Spiller Contact:	ANDY FORD
Spiller Phone:	(610) 527-7900
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	59940
Latitude:	40.6805768
Longitude:	-73.9026000
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND
Remarks:	LEAK AT MANWAY CAUSED TANK TO FAIL / NO REPAIR MADE

All TTF:

Facility ID:	9704864
Spill Number:	9704864
Spill Tank Test:	1545226
Site ID:	290955
Tank Number:	Not reported
Tank Size:	5000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20

HESS-MERIT GAS STATION (Continued) **S104514567**

Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	290955
Operable Unit ID:	1050730
Operable Unit:	01
Material ID:	334102
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HESS-MERIT STATION
Address:	1630-76 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9704866 / 2003-03-18
Facility ID:	9704866
Site ID:	61682
Spill Date:	1997-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1997-07-23
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-07-23
Spill Record Last Update:	2003-04-08
Spiller Name:	ANY FORD
Spiller Company:	MERIT STATION
Spiller Address:	1630-76 BUSHWICK AVE
Spiller County:	001
Spiller Contact:	ANDY FORD
Spiller Phone:	(610) 527-7900
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	59940
Latitude:	40.6805768

HESS-MERIT GAS STATION (Continued) **S104514567**

Longitude:	-73.9026000
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND
Remarks:	LEAKING GASKET ON MANWAY COVER

All Materials:

Site ID:	61682
Operable Unit ID:	1050734
Operable Unit:	01
Material ID:	334104
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AH230 **MERIT OIL CORP** **RCRA NonGen / NLR** **1000263765**
North **1630 BUSHWICK AVE** **US AIRS** **NYD982185589**
1/8-1/4 **BROOKLYN, NY 11207** **NY MANIFEST**
0.239 mi.
1260 ft. **Site 7 of 13 in cluster AH**

Relative:
Higher

Actual:
100 ft.

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Merit Oil Corp
Handler Address:		Bushwick Ave
Handler City,State,Zip:		BROOKLYN, NY 11207-1803
EPA ID:		NYD982185589
Contact Name:		Not reported
Contact Address:		W LANCASTER AVE
Contact City,State,Zip:		HAVERFORD, NY 19041
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		W LANCASTER AVE
Mailing City,State,Zip:		HAVERFORD, NY 19041
Owner Name:	Merit Oil Corp	
Owner Type:		Private
Operator Name:	Merit Oil Corp	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No

MERIT OIL CORP (Continued) **1000263765**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

MERIT OIL CORP (Continued) **1000263765**

Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MERIT OIL CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported

MERIT OIL CORP (Continued) **1000263765**

Electronic Manifest Broker: Not reported

Receive Date: 19870511
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000263765
Region Code: 02
Programmatic ID: AIR NY0000002610500194
Facility Registry ID: 110004415874
D and B Number: Not reported
Primary SIC Code: 5541
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610500194
Facility Registry ID: 110004415874
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NY MANIFEST:
EPA ID: NYD982185589
Country: USA

MERIT OIL CORP (Continued) **1000263765**

Name:	Amerada Hess Corporation
Address:	1630 BUSHWICK AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207-1803
Zip 4:	Not reported
Location Address 1:	1630 BUSWACK AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Amerada Hess Corporation
Mailing Contact:	Paul Marino
Mailing Address 1:	1 HESS PLAZA
Mailing Address 2:	Not reported
Mailing City,State,Zip:	WOODBRIDGE, NJ 07095
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7327506000

Manifest Data:

Document ID:	NJA3109362
Manifest Status:	Not reported
Trans1 State ID:	06815
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	04/09/2002
Trans1 Recv Date:	04/09/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/10/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982185589
Trans1 EPA ID:	PAD014146179
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

MERIT OIL CORP (Continued) **1000263765**

Waste Code 6:	Not reported
Quantity:	00300
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

AH231 **HESS-MERIT GAS STATION** **UST FINDER RELEASE** **1029076825**
North **1630-76 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.239 mi.
1260 ft. **Site 8 of 13 in cluster AH**

Relative:
Higher

Actual:
100 ft.

UST FINDER RELEASE:

Object ID:	258799
Facility ID:	NY59940
Lust ID:	NY9704864
Name:	HESS-MERIT GAS STATION
Address:	1630-76 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1997/07/23 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2743
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.9025999999999
Y Coord:	40.6805800000001
Latitude:	40.6805799999999
Longitude:	-73.9026

AH232 **HESS # 32507** **UST FINDER RELEASE** **1029064743**
North **1630 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.239 mi.
1260 ft. **Site 9 of 13 in cluster AH**

Relative: **Higher**
Actual: **100 ft.**

UST FINDER RELEASE:

Object ID:	258803
Facility ID:	NY201627
Lust ID:	NY612460
Name:	HESS # 32507
Address:	1630 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	PointAddress
Reported Date:	2007/02/14 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2606
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-73.9024699999999
Y Coord:	40.6805400000001
Latitude:	40.68054
Longitude:	-73.9024699999999

AC233 **CON EDISON** **NY MANIFEST** **S117315576**
WSW **FRONT OF 2413 DEAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.239 mi.
1262 ft. **Site 3 of 7 in cluster AC**

Relative: **Lower**
Actual: **68 ft.**

NY MANIFEST:

EPA ID:	NYP004627618
Country:	USA
Name:	Con Edison
Address:	FRONT OF 2413 DEAN ST
Address 2:	SB19418
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	FRONT OF 2413 DEAN ST
Location Address 2:	SB19418

CON EDISON (Continued) **S117315576**

Location City,State,Zip: BROOKLYN, NY 11233
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/14/2014
Trans1 Recv Date: 08/14/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/18/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004627618
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616376GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported

CON EDISON (Continued) **S117315576**

Quantity:	70
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

X234 **CON EDISON SERVICE BOX: 17845** **RCRA NonGen / NLR** **1017772055**
WNW **1910 EASTERN PKWY** **NYP004490033**
1/8-1/4 **BROOKLYN, NY 11233**
0.242 mi.
1276 ft. **Site 8 of 10 in cluster X**

Relative: **Higher**
Actual: **90 ft.**

RCRA Listings:

Date Form Received by Agency:		20140504
Handler Name:		Con Edison Service Box: 17845
Handler Address:		Eastern Pkwy
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004490033
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N

CON EDISON SERVICE BOX: 17845 (Continued) **1017772055**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140404
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140404
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140504
Handler Name: CON EDISON SERVICE BOX: 17845	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny

CON EDISON SERVICE BOX: 17845 (Continued) **1017772055**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

X235 **CON EDISON** **NY MANIFEST** **S116550610**
WNW **1910 EASTERN PKWY** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.242 mi.
1276 ft. **Site 9 of 10 in cluster X**

Relative:
Higher

Actual:
90 ft.

NY MANIFEST:

EPA ID:	NYP004490033
Country:	USA
Name:	Con Edison
Address:	1910 EASTERN PKWY
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	1918 EASTERN PKWY
Location Address 2:	SB 17845
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018

CON EDISON (Continued) **S116550610**

Trans2 State ID:	Not reported
Generator Ship Date:	04/04/2014
Trans1 Recv Date:	04/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004490033
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407761GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

X236 **CON EDISON/QUEENS ENVIRO OPS-C/O-ACV ENVIRO** **E MANIFEST** **1031622591**
WNW **281 2216 FULTON ST.** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.242 mi.
1277 ft. **Site 10 of 10 in cluster X**

Relative: E MANIFEST:
Higher

Manifest Tracking Number:	007352862GBF
Last Updated Date:	20231106
Shipped Date:	20231024
Received Date:	20231026
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service

Actual:
91 ft.

CON EDISON/QUEENS ENVIRO OPS-C/O-ACV ENVIRO (Continued) **1031622591**

Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/Queens Enviro Ops-C/O-Acv Enviro
Generator Location Street Number:	281
Generator Location Street 1:	281 2216 FULTON ST.
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	1610
Generator Mail Street 1:	1500 Rahway Ave.
Generator Mail Street 2:	Not reported
Generator Mail City:	Avenel
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	007352862GBF
Transporter Line Number:	1
Transporter EPA ID:	NJD003812047
Transporter Name:	Acv Environmental Services Inc.

Waste Line:

Manifest Tracking Number:	007352862GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Rq, Na3082, Hazardous Waste, Liquid N.O.S., (Lead), 9, Pg Iii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	TT
Container Type Description:	Cargo tanks (tank trucks)
Waste Quantity:	500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.25
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.25
Waste Quantity, in Kilograms:	226.7575

CON EDISON/QUEENS ENVIRO OPS-C/O-ACV ENVIRO (Continued) **1031622591**

Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	226.7575
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

237
South
1/8-1/4
0.242 mi.
1277 ft.

81-111 JUNIUS STREET
81 JUNIUS STREET
BROOKLYN, NY

NY VCP **S129932646**
NY NYC OER **N/A**

Relative:
Lower

Actual:
50 ft.

VCP NYC:

Project ID:	15TMP0582K,15CVCP118K,15CVCP118K
Name:	81-111 JUNIUS STREET
Address:	81 JUNIUS STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,369,600,013,036,900,000
OER Program:	VCP (Enrolled)
Phase:	Completed
Latitude:	40.673003
Longitude:	-73.903826
Postcode:	11212
Community Board:	16
Council District:	37
Census Tract:	908
BIN:	3425596
NTA:	Brownsville

NYC OER:

Name:	81-111 JUNIUS STREET
Address:	81 JUNIUS STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.673003
Longitude:	-73.903826
OER Project Numbers:	15TMP0582K,15CVCP118K,15CVCP118K
BBL:	3.03696000130369E+19
OER Program:	VCP (Enrolled)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	11212

81-111 JUNIUS STREET (Continued) **S129932646**

Community Board:	16
Council District:	37
Census Tract:	908
BIN:	3425596
NTA:	Brownsville

AI238 **MTA NYCT - NEW YARD** **RCRA NonGen / NLR** **1004761525**
NNW **1925 BROADWAY** **FINDS** **NYR000087759**
1/8-1/4 **BROOKLYN, NY 11207** **ECHO**
0.242 mi. **NY MANIFEST**
1278 ft. **Site 1 of 3 in cluster AI**

Relative: **Higher**
Actual: **98 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Mta Nyct - New Yard
Handler Address:		Broadway
Handler City,State,Zip:		BROOKLYN, NY 11207-1822
EPA ID:		NYR000087759
Contact Name:		DENNIS RAMDAHIN
Contact Address:		JAY ST ROOM 819
Contact City,State,Zip:		BROOKLYN, NY 11201
Contact Telephone:		718-243-4581
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		JAY ST ROOM 819
Mailing City,State,Zip:		BROOKLYN, NY 11201
Owner Name:	New York City Transit	
Owner Type:		Municipal
Operator Name:	New York City Transit	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline

MTA NYCT - NEW YARD (Continued) **1004761525**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 819
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-243-4581
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 819
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-243-4581
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NEW YORK CITY TRANSIT	
Legal Status:	Municipal

MTA NYCT - NEW YARD (Continued) **1004761525**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	370 JAY ST ROOM 819
Owner/Operator City,State,Zip:	BROOKLYN, NY 11201
Owner/Operator Telephone:	718-243-4581
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: MTA NYCT - NEW YARD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: MTA NYCT - NEW YARD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20000707
Handler Name: MTA NYCT - NEW YARD	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

MTA NYCT - NEW YARD (Continued) **1004761525**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004563259

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004761525
Registry ID: 110004563259

DFR URL:
Name: MTA NYCT - NEW YARD
Address: 1925 BROADWAY
City,State,Zip: BROOKLYN, NY 11207

NY MANIFEST:
EPA ID: NYR000087759
Country: USA
Name: Nycta
Address: 1925 BROADWAY
Address 2: BLOCK 3474 LOT 10
City,State,Zip: BROOKLYN, NY 11207-1822
Zip 4: Not reported
Location Address 1: 370 JAY ST-RM 819
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Nycta
Mailing Contact: Edward Hopkinson
Mailing Address 1: 370 JAY ST-RM 819
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11201
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7182434227

Manifest Data:
Document ID: NJA3180640

MTA NYCT - NEW YARD (Continued) **1004761525**

Manifest Status:	Not reported
Trans1 State ID:	H10376
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2000
Trans1 Recv Date:	08/24/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/24/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000087759
Trans1 EPA ID:	NJD003812047
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	13085
Units:	Pounds
Number of Containers:	026
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

AC239 **CON EDISON SERVICE BOX: 33415** **RCRA NonGen / NLR** **1017775147**
WSW **2346 PACIFIC ST** **NYP004529723**
1/8-1/4 **BROOKLYN, NY 11233**
0.243 mi.
1282 ft. **Site 4 of 7 in cluster AC**

Relative: **Higher**
Actual: **72 ft.**

RCRA Listings:

Date Form Received by Agency:	20140613
Handler Name:	Con Edison Service Box: 33415
Handler Address:	Pacific St
Handler City,State,Zip:	BROOKLYN, NY 11233
EPA ID:	NYP004529723
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported

CON EDISON SERVICE BOX: 33415 (Continued) **1017775147**

Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150211
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

CON EDISON SERVICE BOX: 33415 (Continued) **1017775147**

Historic Generators:

Receive Date:		20140513
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Small Quantity Generator
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140513
Handler Name:	CON EDISON	
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20140613
Handler Name:	CON EDISON SERVICE BOX:	33415
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AC240 **CON EDISON** **NY MANIFEST** **S117060732**
WSW **2346 PACIFIC ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.243 mi.
1282 ft. **Site 5 of 7 in cluster AC**

Relative:
Higher

Actual:
72 ft.

NY MANIFEST:

EPA ID:	NYP004529723
Country:	USA
Name:	Con Edison
Address:	2346 PACIFIC ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	2346 PACIFIC ST
Location Address 2:	SB33415
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Con Edison
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/2014
Trans1 Recv Date:	05/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004529723
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002422347GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117060732**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	80
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB241 **WARTBURG LUTHERAN HOME FOR THE AGING** **NY LTANKS** **S110045457**
East **50 SHEFFIELD AVENUE** **NY NYC LAND USE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.243 mi.
1285 ft. **Site 2 of 7 in cluster AB**

Relative: **Lower**
Actual: **59 ft.**

LTANKS:

Name:	WARTBURG LUTHERAN HOME FOR THE AGING
Address:	50 SHEFFIELD AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Spill Number/Closed Date:	0908501 / 2010-01-15
Facility ID:	0908501
Site ID:	421105
Spill Date:	2009-10-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	2009-10-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-10-28
Spill Record Last Update:	2010-06-30
Spiller Name:	Not reported
Spiller Company:	WARTBURG LUTHERAN HOME FOR THE AGING
Spiller Address:	Not reported
Spiller County:	999

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **S110045457**

Spiller Contact:	NICK CANONICO-= NOVA CONSULTING NORTHEAST
Spiller Phone:	(516) 352-3233
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	5331
Latitude:	40.6763830
Longitude:	-73.8981180
DEC Memo:	10/29/09-Vought-Primary off-hours responder. Vought called Nova Consulting (Nick Canonico 516-352-3233) and left message to return call to DEC. As per PBS #2-15884, site has one 1500-gallon diesel UST and site owner info is: Mr. Barry Frankenstein Wartburg Lutheran Home For the Aging 50 Sheffield Avenue Brooklyn, NY 11207 Ph: 718-345-2273 Fax: (718)485-9236 Vought sent TTF with cc to Canonico via email. Spill assigned to DEC Krimgold as site is PBS site. Vought received email reply from Canonico that two tanks failed (one wet and one dry leak). Vought required PBS registration to be updated and that tank with wet leak be emptied immediately to prevent release to soil and or groundwater. Requested confirmation from Canonico that UST will be emptied. 01/15/10. J. Krimgold reviewed the letter report submitted by Pro Test Env. dated Dec. 28, 2009. According to the report the tank failed due to the old abandoned fill line. The line was disconnected and tank retested and passed. During line and tank top excavation no contamination was found. Case closed.
Remarks:	underground tank test failure. removal- investigation will be done.

All Materials:

Site ID:	421105
Operable Unit ID:	1177040
Operable Unit:	01
Material ID:	2169782
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	50 SHEFFIELD AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6763766
Longitude:	-73.8983160
Type Of Ownership Code:	Not reported
Owner Name:	WART REALTY LLC
Borough:	BK
Tax Block:	3668
Tax Lot:	2
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198001005
Census Tract 2010:	1198
Census Block 2010:	1005

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **S110045457**

School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	C4-1: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	I6: Hospitals And Health - Nursing Home
Land Use Category:	Public Facilities & Institutions
Number Of Easements:	0
Lot Area:	19500
Total Building Floor Area:	39568
Commercial Floor Area:	39568
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	39568
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	4.0000000
Residential Units:	0
Total Units:	0
Lot Frontage:	166.5800000
Lot Depth:	200.0000000
Building Frontage:	193.6700000
Building Depth:	105.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	219600.00000
Assessed Total Value:	2712600.00000
Exempt Total Value:	0.00000
Year Built:	1971
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.03000000000
Maximum Allowable Residential Far:	1.25000000000

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **S110045457**

Maximum Allowable Commercial Far:	1.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036680002.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1012455
Y Coordinate:	185715
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 010
Tax Map #:	31205
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AB242 **WARTBURG LUTHERAN HOME FOR THE AGING** **UST FINDER** **1028596974**
East **50 SHEFFIELD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.243 mi.
1285 ft. **Site 3 of 7 in cluster AB**

Relative: **Lower**
Actual: **59 ft.**

UST FINDER:

Object ID:	295822
Facility ID:	NY5338
Name:	WARTBURG LUTHERAN HOME FOR THE AGING
Address:	50 SHEFFIELD AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	4486
Private Wells 1500ft:	1
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.897952
Y Coord:	40.6758320000001

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **1028596974**

Latitude: 40.675832
Longitude: -73.897952

UST FINDER:
Object ID: 1308756
Facility ID: NY5338
Tank ID: NY6762
Tank Status: Closed
Installation Date: 1972/02/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 1500
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1308757
Facility ID: NY5338
Tank ID: NY6763
Tank Status: Open
Installation Date: 1996/01/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 1000
Substances: Not reported
Tank Wall Type: Not reported

AB243 **WARTBURG LUTHERAN HOME FOR THE AGING** **NY UST** **U000396960**
East **50 SHEFFIELD AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.243 mi.
1285 ft. **Site 4 of 7 in cluster AB**

Relative: **Lower**

Actual: **59 ft.**

UST:
Name: WARTBURG LUTHERAN HOME FOR THE AGING
Address: 50 SHEFFIELD AVENUE
City,State,Zip: BROOKLYN, NY 11207
Id/Status: 2-158844 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 593137.40689
UTM Y: 4503356.20311
Site Type: Other

Affiliation Records:
Site Id: 5338
Affiliation Type: Facility Owner
Company Name: WARTBURG LUTHERAN HOME FOR THE AGING
Contact Type: DIRECTOR OF FACILITIES
Contact Name: BARRY FRANKENSTEIN
Address1: 50 SHEFFIELD AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11207
Country Code: 001
Phone: (718) 345-2273
EMail: Not reported
Fax Number: Not reported

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **U000396960**

Modified By:	NRLOMBAR
Date Last Modified:	2008-07-31
Site Id:	5338
Affiliation Type:	Mail Contact
Company Name:	WARTBURG LUTHERAN HOME FOR THE AGING
Contact Type:	DIRECTOR OF FACILITIES
Contact Name:	BARRY FRANKENSTEIN
Address1:	50 SHEFFIELD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 345-2273
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-31
Site Id:	5338
Affiliation Type:	Facility Operator
Company Name:	WARTBURG LUTHERAN HOME FOR THE AGING
Contact Type:	Not reported
Contact Name:	BARRY FRANKENSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 345-2273
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-31
Site Id:	5338
Affiliation Type:	Emergency Contact
Company Name:	WARTBURG LUTHERAN HOME FOR THE AGING
Contact Type:	Not reported
Contact Name:	BARRY FRANKENSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 345-2273
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2008-07-31

Tank Info:

Tank Number:	001

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **U000396960**

Tank ID: 8549
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1500
Install Date: 02/01/1972
Date Tank Closed: 12/08/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 02/12/2007
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H04 - Tank Leak Detection - Groundwater Well
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 002
Tank ID: 232199
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: 01/01/1996
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 12/23/2009
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F06 - Pipe External Protection - Wrapped

WARTBURG LUTHERAN HOME FOR THE AGING (Continued) **U000396960**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

AB244 **SHINY CAR WASH AND QUICK LUBE** **NY AST** **A100514994**
East **2591 ATLANTIC AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.244 mi.
1287 ft. **Site 5 of 7 in cluster AB**

Relative:
Lower

Actual:
58 ft.

AST:

Name:	SHINY CAR WASH AND QUICK LUBE
Address:	2591 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609840
Program Type:	PBS
UTM X:	593116.32870
UTM Y:	4503379.29692
Expiration Date:	04/30/2028
Site Type:	Other

Affiliation Records:

Site Id:	337283
Affiliation Type:	Mail Contact
Company Name:	SID REALTY HOLDINGS LLC
Contact Type:	MEMBER
Contact Name:	ANNA MARIA OPPEDISANO
Address1:	2591 ATLANTIC AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(917) 685-0643
EMail:	AMOGLOS@AOL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2023-03-23

Site Id:	337283
Affiliation Type:	Facility Owner
Company Name:	SID REALTY HOLDINGS LLC
Contact Type:	MEMBER
Contact Name:	ANNA MARIA OPPEDISANO
Address1:	2591 ATLANTIC AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(917) 685-0643
EMail:	AMOGLOS@AOL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2023-03-23

SHINY CAR WASH AND QUICK LUBE (Continued) **A100514994**

Site Id:	337283
Affiliation Type:	Emergency Contact
Company Name:	SID REALTY HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	PETER OPPEDISANO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 626-5882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-06-11

Site Id:	337283
Affiliation Type:	Facility Operator
Company Name:	SHINY CARWASH AND LUBE CTR INC
Contact Type:	Not reported
Contact Name:	SALVATORE DEVITO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 947-1169
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-05-17

Tank Info:

Tank Number:	1A
Tank Id:	181906
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on

SHINY CAR WASH AND QUICK LUBE (Continued) **A100514994**

impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2004
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JSMACRI
Last Modified: 03/23/2023
Material Name: lube oil

Tank Number: 1B
Tank Id: 181909
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2004
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JSMACRI
Last Modified: 03/23/2023
Material Name: waste oil/used oil

Tank Number: 2A
Tank Id: 181905
Material Code: 0012
Common Name of Substance: Kerosene [#1 Fuel Oil] (On-Site Consumption)

SHINY CAR WASH AND QUICK LUBE (Continued) **A100514994**

Equipment Records:

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2004
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	03/23/2023
Material Name:	lube oil

Tank Number:	2B
Tank Id:	181907
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2004

SHINY CAR WASH AND QUICK LUBE (Continued) **A100514994**

Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	03/23/2023
Material Name:	transmission fluid

Tank Number:	2C
Tank Id:	181908
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
F02 - Pipe External Protection - Original Sacrificial Anode
F06 - Pipe External Protection - Wrapped
G01 - Tank Secondary Containment - Diking (Aboveground)
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2004
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	03/23/2023
Material Name:	lube oil

Tank Number:	3
Tank Id:	253588

Equipment Records:

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
F02 - Pipe External Protection - Original Sacrificial Anode

SHINY CAR WASH AND QUICK LUBE (Continued) **A100514994**

F06 - Pipe External Protection - Wrapped
G01 - Tank Secondary Containment - Diking (Aboveground)
J03 - Dispenser - Gravity
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/23/2013
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	03/23/2023
Material Name:	lube oil

AB245 **SHINY CAR WASH & LUBE CTR. INC.** **NY CBS** **S109581137**
East **2591 ATLANTIC AVE** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207** **NY Spills**
0.244 mi.
1287 ft. **Site 6 of 7 in cluster AB**

Relative: **Lower**
Actual: **58 ft.**

CBS:

Name:	SHINY CAR WASH & LUBE CTR. INC.
Address:	2591 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
CBS Number:	2-000511
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	593116.32870
UTMY:	4503379.29692

AST:

Name:	SHINY CAR WASH & LUBE CTR. INC.
Address:	2591 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000511
Program Type:	CBS
UTM X:	593116.32870
UTM Y:	4503379.29692
Expiration Date:	N/A
Site Type:	Other

Tank Info:

Tank Number:	4
Tank Id:	252484

SHINY CAR WASH & LUBE CTR. INC. (Continued) **S109581137**

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/23/2013
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/29/2015
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

SPILLS:

Name:	SIDEWALK
Address:	2591 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0813719 / 2009-03-19
Facility ID:	0813719
Facility Type:	ER
DER Facility ID:	360633
Site ID:	411415
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	2401
Spill Date:	2009-03-19
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2009-03-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-03-19
Spill Record Last Update:	2009-03-19
Spiller Name:	NONE
Spiller Company:	UNKNOWN
Spiller Address:	2591 ATLANTIC AVE
Spiller Company:	999
Contact Name:	NONE
Latitude:	40.6757460
Longitude:	-73.8986200
DEC Memo:	Sanitation will sand it - spill is approx 1 pt.
Remarks:	Oil stain on sidewalk.

All Materials:

Site ID:	411415

SHINY CAR WASH & LUBE CTR. INC. (Continued) **S109581137**

Operable Unit ID:	1167889
Operable Unit:	01
Material ID:	2159514
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

246
SW
1/8-1/4
0.244 mi.
1287 ft.

GRAFTON REALTY CORP. **NY AST** **A100300594**
1660 EAST NEW YORK AVENUE **N/A**
BROOKLYN, NY 11212

Relative:
Lower

Actual:
61 ft.

AST:

Name:	GRAFTON REALTY CORP.
Address:	1660 EAST NEW YORK AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-082570
Program Type:	PBS
UTM X:	592402.05666
UTM Y:	4503142.73000
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	1796
Affiliation Type:	Facility Owner
Company Name:	RENE ZETRENNE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1478 PITKIN AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1796
Affiliation Type:	Mail Contact
Company Name:	RENE ZETRENNE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1478 PITKIN AVENUE

GRAFTON REALTY CORP. (Continued) **A100300594**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11212
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1796
Affiliation Type:	Facility Operator
Company Name:	GRAFTON REALTY CORP.
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1796
Affiliation Type:	Emergency Contact
Company Name:	RENE ZETRENNE
Contact Type:	Not reported
Contact Name:	N/AMJR HOLDING CORPORATION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	3008
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

GRAFTON REALTY CORP. (Continued) **A100300594**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AH247 **SLS CAR WASH, INC.** **NY AST** **A100300284**
North **1650 BUSHWICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.244 mi.
1289 ft. **Site 10 of 13 in cluster AH**

Relative:
Higher

Actual:
103 ft.

AST:

Name:	SLS CAR WASH, INC.
Address:	1650 BUSHWICK AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610338
Program Type:	PBS
UTM X:	592771.42844
UTM Y:	4503829.81242
Expiration Date:	11/01/2016
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	370439
Affiliation Type:	Emergency Contact
Company Name:	VALDEMIRO SANTOS
Contact Type:	Not reported
Contact Name:	VAL SANTOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 919-4100
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS

SLS CAR WASH, INC. (Continued) **A100300284**

Date Last Modified: 2011-09-07

Site Id: 370439
Affiliation Type: Facility Operator
Company Name: SLS CAR WASH, INC.
Contact Type: Not reported
Contact Name: DEXTER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 919-4100
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2011-09-07

Site Id: 370439
Affiliation Type: Mail Contact
Company Name: SLS CAR WASH, INC.
Contact Type: Not reported
Contact Name: VAL SANTOS
Address1: 1650 BUSHWICK AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11207
Country Code: 001
Phone: (718) 919-4100
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2011-09-08

Site Id: 370439
Affiliation Type: Facility Owner
Company Name: VALDEMIRO SANTOS
Contact Type: VICE PRESIDENT
Contact Name: VAL SANTOS
Address1: 4 PATTERSON RD
Address2: Not reported
City: POUND RIDGE
State: NY
Zip Code: 10576
Country Code: 001
Phone: (718) 919-4100
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2011-09-07

Tank Info:

Tank Number: 1
Tank Id: 213569

SLS CAR WASH, INC. (Continued) **A100300284**

Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 11/01/2001
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: 08/22/2006
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: waste oil/used oil

Tank Number: 2
Tank Id: 213570
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported

SLS CAR WASH, INC. (Continued) **A100300284**

Install Date:	11/01/2001
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	08/22/2006
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	3
Tank Id:	213571
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2001
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	08/22/2006
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	4
Tank Id:	213572
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G02 - Tank Secondary Containment - Vault (w/access)

SLS CAR WASH, INC. (Continued) **A100300284**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2001
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	08/22/2006
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil
Tank Number:	5
Tank Id:	213573
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B09 - Tank External Protection - Urethane
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2001
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	08/22/2006
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI

SLS CAR WASH, INC. (Continued) **A100300284**

Last Modified: 05/09/2022
Material Name: lube oil

V248 **METRO STRUCTURAL STEEL MR. RUSSO** **NY UST** **U001831595**
SE **282 LIBERTY AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.245 mi.
1294 ft. **Site 4 of 5 in cluster V**

Relative:
Lower

Actual:
53 ft.

UST:
Name: METRO STRUCTURAL STEEL MR. RUSSO
Address: 282 LIBERTY AVENUE
City,State,Zip: BROOKLYN, NY 11207
Id/Status: 2-054895 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 592991.99190
UTM Y: 4503132.64794
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 788
Affiliation Type: Facility Owner
Company Name: MR. LUCLANO RUSSO
Contact Type: Not reported
Contact Name: Not reported
Address1: 282 LIBERTY AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11234-2521
Country Code: 001
Phone: (718) 241-2501
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 788
Affiliation Type: Mail Contact
Company Name: TAKE PRIDE
Contact Type: Not reported
Contact Name: HAROLT PITTS
Address1: 76 RUNYON AVENUE
Address2: Not reported
City: YONKERS
State: NY
Zip Code: 10710
Country Code: 001
Phone: (914) 969-1006
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 788

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

Affiliation Type:	Facility Operator
Company Name:	METRO STRUCTURAL STEEL MR. RUSSO
Contact Type:	Not reported
Contact Name:	MR. RUSSO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 241-2501
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	788
Affiliation Type:	Emergency Contact
Company Name:	MR. LUCLANO RUSSO
Contact Type:	Not reported
Contact Name:	HALOID PITTS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 760-3705
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	1971
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	05/01/1972
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 66151
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Z
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 003
Tank ID: 66152
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 500
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Z
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **U001831595**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 1000UST
Tank ID: 66253
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2500
Install Date: 01/01/2003
Date Tank Closed: 01/01/2003
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

V249 **METRO STRUCTURAL STEEL MR. RUSSO** **UST FINDER** **1028600002**
SE **282 LIBERTY AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.245 mi.
1294 ft. **Site 5 of 5 in cluster V**

Relative: **Lower**
Actual: **53 ft.**

UST FINDER:
Object ID: 295716
Facility ID: NY788
Name: METRO STRUCTURAL STEEL MR. RUSSO
Address: 282 LIBERTY AVENUE
City,State,Zip: BROOKLYN, NY
Address Match Type: Not reported

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **1028600002**

Open USTs:	0
Closed USTs:	4
TOS USTs:	0
Population 1500ft:	3828
Private Wells 1500ft:	3
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-73.8996559999999
Y Coord:	40.673394
Latitude:	40.673394
Longitude:	-73.899656

UST FINDER:

Object ID:	1319224
Facility ID:	NY788
Tank ID:	NY1482
Tank Status:	Closed
Installation Date:	2003/01/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1319225
Facility ID:	NY788
Tank ID:	NY1434
Tank Status:	Closed
Installation Date:	1972/05/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1319226
Facility ID:	NY788
Tank ID:	NY1590
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

METRO STRUCTURAL STEEL MR. RUSSO (Continued) **1028600002**

Object ID:	1319227
Facility ID:	NY788
Tank ID:	NY1622
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	500
Substances:	Not reported
Tank Wall Type:	Not reported

AC250 **CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS** **E MANIFEST** **1031619691**
WSW **2409 DEAN ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.245 mi.
1294 ft. **Site 6 of 7 in cluster AC**

Relative: **Lower**
Actual: **68 ft.**

E MANIFEST:

Manifest Tracking Number:	006873275GBF
Last Updated Date:	20211220
Shipped Date:	20211202
Received Date:	20211206
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison/ Attn: Brooklyn Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	2409 DEAN ST
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11233
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

CON EDISON/ ATTN: BROOKLYN ENVIRONMENTAL OPS (Continued) **1031619691**

Federal Waste:
- Manifest Tracking Number: 006873275GBF
- Waste Line Number: 1
- Federal Waste Code: D008
- Federal Waste: LEAD

State Waste:
- Manifest Tracking Number: 006873275GBF
- Waste Line Number: 1
- State Waste Code Owner: NY
- State Waste Code: T
- State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 006873275GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 006873275GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 500
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.25
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.25
- Waste Quantity, in Kilograms: 226.7575
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 226.7575
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

AI251 **CON EDISON SERVICE BOX: 40752** **RCRA NonGen / NLR** **1017779088**
NNW **17 STEWART ST** **NYP004570578**
1/8-1/4 **BROOKLYN, NY 11207**
0.245 mi.
1295 ft. **Site 2 of 3 in cluster AI**

Relative: **Higher**

Actual: **99 ft.**

RCRA Listings:

Date Form Received by Agency:		20140719
Handler Name:		Con Edison Service Box: 40752
Handler Address:		Stewart St
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004570578
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		SENIOR SCIENTIST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL, 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

CON EDISON SERVICE BOX: 40752 (Continued) **1017779088**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140719
Handler Name: CON EDISON SERVICE BOX:	40752
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 40752 (Continued) **1017779088**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AI252 **CON EDISON** **NY MANIFEST** **S117064564**
NNW **17 STEWART ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.245 mi.
1295 ft. **Site 3 of 3 in cluster AI**

Relative:
Higher

Actual:
99 ft.

NY MANIFEST:

EPA ID:	NYP004570578
Country:	USA
Name:	Con Edison
Address:	17 STEWART ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	FO 17 STEWART ST
Location Address 2:	STRUCTURE 40752
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/19/2014
Trans1 Recv Date:	06/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004570578
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117064564**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002502776GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AH253 **CON EDISON** **NY MANIFEST** **S117314929**
NNE **FO 1654 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.246 mi.
1299 ft. **Site 11 of 13 in cluster AH**

Relative: **Higher**
Actual: **104 ft.**

NY MANIFEST:

EPA ID:	NYP004620266
Country:	USA
Name:	Con Edison
Address:	FO 1654 BUSHWICK AVE
Address 2:	STRUCTURE 19053
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	FO 1654 BUSHWICK AVE
Location Address 2:	STRUCTURE 19053
Location City,State,Zip:	BROOKLYN, NY 11207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

CON EDISON (Continued) **S117314929**

Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/06/2014
Trans1 Recv Date: 08/06/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004620266
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616153GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 150
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

AH254 **CON EDISON** **NY MANIFEST** **S117314933**
NNE **1652 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11213**
0.246 mi.
1301 ft. **Site 12 of 13 in cluster AH**

Relative:
Higher

Actual:
104 ft.

NY MANIFEST:

EPA ID:	NYP004620324
Country:	USA
Name:	Con Edison
Address:	1652 BUSHWICK AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11213
Zip 4:	Not reported
Location Address 1:	1652 BUSHWICK AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11213
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Tom Teeling
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/27/2014
Trans1 Recv Date:	08/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/02/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004620324
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616795GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117314933**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	60
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/06/2014
Trans1 Recv Date:	08/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004620324
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616154GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported

CON EDISON (Continued) **S117314933**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	350
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AH255 **CON EDISON - COMPANY OF NY** **E MANIFEST** **1031610816**
NNE **1652 BUSHWICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.246 mi.
1301 ft. **Site 13 of 13 in cluster AH**

Relative: **Higher**
Actual: **104 ft.**

E MANIFEST:

Manifest Tracking Number:	006853937GBF
Last Updated Date:	20210629
Shipped Date:	20210618
Received Date:	20210618
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Company Of Ny
Generator Location Street Number:	Not reported
Generator Location Street 1:	1652 BUSHWICK AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	36 Butler Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Elizabeth
Generator Mail Zip:	07206
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

CON EDISON - COMPANY OF NY (Continued) **1031610816**

Federal Waste:
- Manifest Tracking Number: 006853937GBF
- Waste Line Number: 1
- Federal Waste Code: D008
- Federal Waste: LEAD

State Waste:
- Manifest Tracking Number: 006853937GBF
- Waste Line Number: 1
- State Waste Code Owner: NY
- State Waste Code: T
- State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
- Manifest Tracking Number: 006853937GBF
- Transporter Line Number: 1
- Transporter EPA ID: NJD003812047
- Transporter Name: Acv Environmental Services Inc.

Waste Line:
- Manifest Tracking Number: 006853937GBF
- Waste Line Number: 1
- U.S. DOT Hazardous Indicator: Y
- U.S. DOT ID Number: NA3082
- U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
- Non-Hazardous Waste Description: Not reported
- Number of Containers: 1
- Container Type Code: TT
- Container Type Description: Cargo tanks (tank trucks)
- Waste Quantity: 800
- Quantity Unit of Measure Code: P
- Quantity Unit of Measure Description: Pounds
- Waste Quantity, in Tons: 0.4
- Acute Waste Quantity, in Tons: 0
- Non-Acute Waste Quantity, in Tons: 0.4
- Waste Quantity, in Kilograms: 362.812
- Acute Waste Quantity, in Kilograms: 0
- Non-Acute Waste Quantity, in Kilorgrams: 362.812
- Management Method Code: H110
- Management Method Description: STABILIZATION
- Waste Residue Indicator: N
- Quantity Discrepancy Indicator: N
- Waste Type Discrepancy Indicator: N
- Waste Density: Not reported
- Waste Density Unit of Measure Code: Not reported
- Waste Density Unit of Measure Description: Not reported
- Form Code: Not reported
- Form Code Description: Not reported
- Source Code: Not reported
- Source Code Description: Not reported
- Waste Minimization Code: Not reported
- Waste Minimization Code Description: Not reported
- Consent Number: Not reported
- EPA Waste Indicator: Y

AE256 **CON EDISON** **NJ MANIFEST** **S120675134**
ESE **2604 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.247 mi.
1302 ft. **Site 4 of 6 in cluster AE**

Relative:
Lower

Actual:
56 ft.

NJ MANIFEST:

EPA ID:	NYP004820276
Name:	CON EDISON
Address:	2604 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY 11207
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004820276
Manifest Number:	014472973JJK
Date Shipped:	8/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **S120675134**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AE257 **CON EDISON** **RCRA NonGen / NLR** **1019906370**
ESE **2604 ATLANTIC AVE** **NYP004820276**
1/8-1/4 **BROOKLYN, NY 11207**
0.247 mi.
1302 ft. **Site 5 of 6 in cluster AE**

Relative: **Lower**
Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:		20150807
Handler Name:		Con Edison
Handler Address:		Atlantic Ave
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYP004820276
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

CON EDISON (Continued) **1019906370**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150807
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150807
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1019906370**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AE258 **CON EDISON** **NY MANIFEST** **S119077084**
ESE **2604 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.247 mi.
1302 ft. **Site 6 of 6 in cluster AE**

Relative:
Lower

Actual:
56 ft.

NY MANIFEST:

EPA ID:	NYP004820276
Country:	USA
Name:	Con Edison
Address:	2604 ATLANTIC AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Zip 4:	Not reported
Location Address 1:	OPP 2604 ATLANTIC AVE
Location Address 2:	SB 18038
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Con Edison
Mailing Contact:	Dennis Huacon
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/07/2015
Trans1 Recv Date:	08/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004820276
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S119077084**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014472973JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AG259 **NYC ENVIRONMENTAL PROTECTION** **E MANIFEST** **1031541784**
SSW **127 LIBERTY AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11212**
0.247 mi.
1303 ft. **Site 7 of 7 in cluster AG**

Relative: E MANIFEST:
Lower

Actual: Manifest Tracking Number:	016038738FLE
57 ft. Last Updated Date:	20240925
Shipped Date:	20240802
Received Date:	20240829
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Nyc Environmental Protection
Generator Location Street Number:	Not reported
Generator Location Street 1:	127 LIBERTY AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11212
Generator Mail Street Number:	Not reported

NYC ENVIRONMENTAL PROTECTION (Continued) **1031541784**

Generator Mail Street 1:	96-05 HORACE HARDING EXPRESSWAY
Generator Mail Street 2:	Not reported
Generator Mail City:	CORONA
Generator Mail Zip:	11368
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys (Pa) Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 SANDSTONE DRIVE
Designated Facility Mail City:	HATFIELD
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 SANDSTONE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	HATFIELD
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	016038738FLE
Transporter Line Number:	1
Transporter EPA ID:	NYR000107326
Transporter Name:	Aarco Environmental Services Corp.

Manifest Tracking Number:	016038738FLE
Transporter Line Number:	2
Transporter EPA ID:	PAD982661381
Transporter Name:	Republic Env Sys (Trans Group), Llc

Waste Line:

Manifest Tracking Number:	016038738FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263, Waste Paint, 3, Pg-Ii,Rq(D001=100#)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	2
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	70
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.035
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.035
Waste Quantity, in Kilograms:	31.74605
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	31.74605
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE

NYC ENVIRONMENTAL PROTECTION (Continued) **1031541784**

Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

AB260 **CON EDISON** **E MANIFEST** **1031625025**
ESE **2599 ATLANTIC AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11207**
0.247 mi.
1304 ft. **Site 7 of 7 in cluster AB**

Relative: **Lower**

Actual: **57 ft.**

E MANIFEST:

Manifest Tracking Number:	007165023GBF
Last Updated Date:	20220525
Shipped Date:	20220511
Received Date:	20220513
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison
Generator Location Street Number:	Not reported
Generator Location Street 1:	2599 ATLANTIC AVE
Generator Location Street 2:	Not reported
Generator Location City:	BROOKLYN
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 RAHWAY AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	AVENEL
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE
Designated Facility Mail City:	KEARNY
Designated Facility Mail Zip:	07032
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	105
Designated Facility Location Street 1:	JACOBUS AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	KEARNY
Designated Facility Location Zip:	07032
Designated Facility Location State:	NJ

CON EDISON (Continued) **1031625025**

Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 007165023GBF
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 007165023GBF
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 007165023GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 007165023GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Waste Other Regulated Substances, Liquid N.O.S, 9, Pg Iii, Rq (Lead)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 1000
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.5
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.5
Waste Quantity, in Kilograms: 453.515
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 453.515
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported

CON EDISON (Continued) **1031625025**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

261
ENE
1/8-1/4
0.247 mi.
1304 ft.

MTA NYCT - BUS COMMAND CENTER **RCRA-SQG** **1026498363**
51 FANCHON PL **NYR000246785**
BROOKLYN, NY 11207

Relative:
Lower

Actual:
69 ft.

RCRA Listings:

Date Form Received by Agency:		20200721
Handler Name:		Mta Nyct - Bus Command Center
Handler Address:		Fanchon Pl
Handler City,State,Zip:		BROOKLYN, NY 11207
EPA ID:		NYR000246785
Contact Name:		LUMINITA MARINESCU
Contact Address:		BROADWAY, 5TH FL, MB 503
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		646-252-3506
Contact Fax:		Not reported
Contact Email:		LUMINITA.MARINESCU@NYCT.COM
Contact Title:		ADMIN STAFF ANALYST
EPA Region:		02
Land Type:		State
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		BROADWAY, 5TH FL MB 503
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:	Mta Nyct	
Owner Type:		State
Operator Name:	Mta Nyct	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline

MTA NYCT - BUS COMMAND CENTER (Continued) **1026498363**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200728
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY, 5TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3506
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	LUMINITA.MARINESCU@NYCT.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NYCT	
Legal Status:	State
Date Became Current:	19680301
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY, 5TH FL, MB 503
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3506
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	LUMINITA.MARINESCU@NYCT.COM

Historic Generators:

Receive Date:	20200721
Handler Name:	MTA NYCT - BUS COMMAND CENTER

MTA NYCT - BUS COMMAND CENTER (Continued) **1026498363**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	485111
NAICS Description:	Mixed Mode Transit Systems

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AF262 **CON EDISON - QUEENS ENVIRONMENTAL OPS** **E MANIFEST** **1031617329**
NE **9 HIGHLAND BLVD** **N/A**
1/8-1/4 **QUEENS, NY 11207**
0.248 mi.
1312 ft. **Site 6 of 6 in cluster AF**

Relative:
Higher

Actual:
99 ft.

E MANIFEST:

Manifest Tracking Number:	006871413GBF
Last Updated Date:	20211130
Shipped Date:	20211118
Received Date:	20211119
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000114579
Generator Name:	Con Edison - Queens Environmental Ops
Generator Location Street Number:	Not reported
Generator Location Street 1:	9 HIGHLAND BLVD
Generator Location Street 2:	Not reported
Generator Location City:	QUEENS
Generator Location State:	NY
Generator Location Zip:	11207
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1500 Rahway Ave
Generator Mail Street 2:	Not reported
Generator Mail City:	Avenel
Generator Mail Zip:	07001
Generator Mail State:	NJ
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD991291105
Designated Facility Name:	Clean Earth Of North Jersey
Designated Facility Mail Street Number:	105
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	JACOBUS AVE

CON EDISON - QUEENS ENVIRONMENTAL OPS (Continued) **1031617329**

Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Federal Waste:
Manifest Tracking Number: 006871413GBF
Waste Line Number: 1
Federal Waste Code: D008
Federal Waste: LEAD

State Waste:
Manifest Tracking Number: 006871413GBF
Waste Line Number: 1
State Waste Code Owner: NY
State Waste Code: T
State Waste: Chemical, physical or biological treatment. Waste management method code to be used on e-Manifest only

Transporter:
Manifest Tracking Number: 006871413GBF
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 006871413GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N

CON EDISON - QUEENS ENVIRONMENTAL OPS (Continued) **1031617329**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y

263
SE
1/8-1/4
0.250 mi.
1318 ft.

CON EDISON MANHOLE: 66421
ALABAMA AVE & LIBERTY AVE
BROOKLYN, NY 11207

RCRA NonGen / NLR **1016971192**
NY MANIFEST **NYP004449278**

Relative:
Lower

Actual:
53 ft.

RCRA Listings:

Date Form Received by Agency:	20140323
Handler Name:	Con Edison Manhole: 66421
Handler Address:	Alabama Ave & Liberty Ave
Handler City,State,Zip:	BROOKLYN, NY 11207
EPA ID:	NYP004449278
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON MANHOLE: 66421 (Continued) **1016971192**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140223
Handler Name:	CON EDISON MANHOLE: 66421
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140323
Handler Name:	CON EDISON MANHOLE: 66421
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

CON EDISON MANHOLE: 66421 (Continued) **1016971192**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004449278
Country: USA
Name: Con Edison
Address: ALABAMA AVE & LIBERTY AVE
Address 2: 48 FEET S OF
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: ALABAMA AVE & LIBERTY AVE
Location Address 2: SB66421‘
Location City,State,Zip: QUEENS, NY 11432
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 02/23/2014
Trans1 Recv Date: 02/23/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004449278
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105

CON EDISON MANHOLE: 66421 (Continued) **1016971192**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002358959GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AJ264 **50 PENN LLC** **NY VCP** **S118704070**
East **2618 FULTON ST** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11207** **NY MANIFEST**
0.264 mi. **NY NYC OER**
1395 ft. **Site 1 of 2 in cluster AJ**

Relative: **Lower**

Actual: **59 ft.**

VCP NYC:

Project ID:	18TMP1429K,18EHAN480K,19CVCP033K
Name:	2618 FULTON STREET
Address:	2618 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	303,669,001,330,366,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.677079
Longitude:	-73.898052
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3083272
NTA:	East New York

50 PENN LLC (Continued) **S118704070**

SPILLS:

Name:	SOIL
Address:	2618 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1901557 / 2021-11-05
Facility ID:	1901557
Facility Type:	ER
DER Facility ID:	539729
Site ID:	588446
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2019-05-14
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-05-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-05-14
Spill Record Last Update:	2021-11-05
Spiller Name:	STEWART KNOOP
Spiller Company:	50 PENN LLC
Spiller Address:	2618 FULTON STREET
Spiller Company:	999
Contact Name:	STEWART KNOOP
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	5/16/19-Lin-This site along with a few neighboring lots are currently under OER s cleanup program to redevelop the sites. They found a few underground tanks that were previously identified and underground tanks that were not found during the GPR survey. Langan suspect that they will encounter more tanks going forward. 9/10/19-Lin-Received call from langan that they found multiple tank near the site boundary that had soil contamination where the tank were. They made us aware that they would have trouble obtaining side wall samples due to the shoring put in place. Off site borings might be require to delineate the contaminated soil. The whole site is going to be excavated down to 15’ and 30 bottoms samples would be taken across the site. 11/5/21-Lin-A total of sixteen (16) underground storage tanks were removed. Contaminated soil was excavated. Groundwater was encountered around 50 bgs and the groundwater is inferred to flow to the southeast towards Jamaica Bay. One groundwater sample was collected and came back clean.

50 PENN LLC (Continued) **S118704070**

Groundwater is not expected
to be impacted at this site. The whole site was excavated to varies depth. A total of 18 endpoint
samples were collected from the base of the remedial excavation. The sample results confirmed that
a Track 4 residential cleanup was achieved. An engineered composite cover system consisting of 46
inch and 40 inch thick structural mat slabs in the partial cellar and in the ground floor garage
was constructed. A 12 inch thick concrete slab above a 20 mil vapor barrier and an active SSDS were
installed. Case closed Stewart from langan 212-479-5461
sknoop@langan.com
Remarks: clean up is done

All Materials:
Site ID: 588446
Operable Unit ID: 1336105
Operable Unit: 01
Material ID: 2345435
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: 2.00
Units: G
Recovered: Not reported
Resource Affected: Soil
Oxygenate: Not reported

NY MANIFEST:
EPA ID: NYR000242487
Country: USA
Name: 50 Penn Llc
Address: 2618 FULTON ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11207
Zip 4: Not reported
Location Address 1: 2618 FULTON ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11207
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: 50 Penn Llc
Mailing Contact: 50 Penn Llc
Mailing Address 1: 2618 FULTON ST
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11207
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

50 PENN LLC (Continued) **S118704070**

NYC OER:

Name:	2618 FULTON STREET
Address:	2618 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677079
Longitude:	-73.898052
OER Project Numbers:	18TMP1429K,18EHAN480K,19CVCP033K
BBL:	3.0366900133036599E+59
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3083272
NTA:	East New York

AC265 **DEAN STREET - HABITAT FOR HUMANITY** **NY VCP** **S129932714**
WSW **2396 DEAN STREET** **NY NYC OER** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.272 mi.
1436 ft. **Site 7 of 7 in cluster AC**

Relative:
Lower

Actual:
66 ft.

VCP NYC:

Project ID:	13TMP0569K,13CVCP135K,13CVCP135K
Name:	DEAN STREET - HABITAT FOR HUMANITY
Address:	2396 DEAN STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3,014,500,008,301,450,000,000,000,000,000,000,000,000
OER Program:	VCP (Enrolled)
Phase:	Closure
Latitude:	40.674571
Longitude:	-73.907807
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	Not reported
NTA:	Ocean Hill

NYC OER:

Name:	DEAN STREET - HABITAT FOR HUMANITY
Address:	2396 DEAN STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.674571
Longitude:	-73.907807
OER Project Numbers:	13TMP0569K,13CVCP135K,13CVCP135K
BBL:	3.0145000083014501E+39
OER Program:	VCP (Enrolled)
Class:	Active (A)
Phase:	Closure

DEAN STREET - HABITAT FOR HUMANITY (Continued) **S129932714**

URL:
Postcode: 11233
Community Board: 16
Council District: 37
Census Tract: 36502
BIN: Not reported
NTA: Ocean Hill

266
South
1/4-1/2
0.272 mi.
1438 ft.

Relative:
Lower

Actual:
52 ft.

114 SNEDIKER AVENUE
221-241 GLENMORE AVENUE
BROOKLYN, NY 11207

NY BROWNFIELDS **S129982648**
N/A

BROWNFIELDS:
Name: 114 SNEDIKER AVENUE
Address: 221-241 GLENMORE AVENUE
City,State,Zip: BROOKLYN, NY 11207
Program: BCP
Site Code: 647562
Acres: 0.777
HW Code: C224385
SWIS: 2401
Town: New York City
Record Added Date: 01/06/2023
Record Updated Date: 04/17/2024
Update By: CXMAYCOC
Site Description: Location: The site is located within a mixed-use neighborhood on the north side of Glenmore Avenue between Van Sinderen Avenue and Snediker Avenue in the New Lots sub-section of the East New York neighborhood in Brooklyn, NY. The site is abutted to the north by light manufacturing and a multi-family residential building; to the east by Snediker Avenue followed by a five-story office building occupied by the New York City Police Department and an asphalt-paved parking lot followed by commercial, industrial, and residential uses beyond; to the south by Glenmore Avenue followed by mixed-use industrial, residential, and commercial properties; and to the west by Van Sinderen Avenue and an elevated railway for the L-line of the NYC Metropolitan Transit Authority. An adjacent property (Lot 36) divides a portion of this site along Glenmore Avenue forming a U shape and includes a 1-story metal frame garage and driveway. Site Features: The site consists of a single tax parcel (Block 3697, Lot 1) and was previously occupied by three adjoining buildings consisting of a two-story building formerly utilized as storage and workshop spaces, and two single-story former manufacturing buildings. The three former buildings were recently demolished to facilitate the Interim Remedial Measures (IRM). Current Zoning and Land Use: The site is currently zoned as M1-4 (light manufacturing). The surrounding area includes predominately commercial and industrial properties with some residential development. Past Use of the Site: Former uses of the site that may have contributed to site contamination include a lumber yard, manufacture of plumbing supplies, lighting fixture manufacturing, auto repair shop, nail polish bottling, and an auto junkyard from 1983 to 1996. The lighting manufacturer was identified as a Resource Conservation Recovery Act (RCRA) Large Quantity Generator (LQG) in 1982 for the generation of F-coded wastes, which are defined as characteristic hazardous waste

114 SNEDIKER AVENUE (Continued) **S129982648**

and include such chemicals as halogenated solvents (F001: tetrachloroethylene [PCE], trichloroethylene [TCE], etc.) and nonhalogenated solvents (F005: toluene, carbon disulfide, benzene, etc.). Site Geology and Hydrogeology: On-site surface topography is generally flat, with the surrounding area topography sloping gently down to the south-southwest, toward Jamaica Bay. Based on the U.S. Geological Survey (Brooklyn, NY Quadrangle), the Site lies at an elevation of approximately 50 feet above the North American Vertical Datum of 1988 (NAVD 1988), an approximation of mean sea level. The site is underlain by unconsolidated fill comprised of a mixture of sand, gravel, silt, clay, brick, concrete, metal, and plastic to approximately 10.5 feet below ground surface (bgs). The fill is underlain by apparently native dense sand and silt with varying amounts of gravel and cobbles down to the maximum boring terminus of 75 feet bgs. Bedrock was not encountered during the RI; however, a cobble layer was encountered at varying depths throughout the site between approximately 10 and 30 feet bgs and was noted to act as a non-contiguous confining layer. Groundwater is found at a depth of approximately 41 to 43 feet below sidewalk grade and flows south-southeast towards Jamaica Bay, which is located approximately 2.5 miles southeast of the site.

Env Problem:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Based upon investigations conducted to date, the primary contaminants of concern for the site include VOCs, SVOCs, and metals in soil, VOCs in groundwater, and VOCs in soil vapor. Soil - Soil data were compared to Restricted Residential Use Soil Cleanup Objectives (RRUSCOs) and Protection of Groundwater Soil Cleanup Objectives (PGWSCOs). PCE was found mostly at the northeast end of the property in shallow soil (0 to 4 ft bgs) and in some areas up to 21 ft bgs. VOCs identified include PCE at a maximum concentration of 98 parts per million, or ppm (RRSCO of 19 ppm and PGWSCO of 1.3 ppm). TCE was detected at a maximum concentration of 8 ppm (PGWSCO of 0.47 ppm). SVOCs identified include benzo(a)anthracene at a maximum concentration of 15 ppm (RRSCO is 1 ppm), benzo(a)pyrene at a maximum concentration of 17 ppm (RRSCO is 1 ppm), and benzo(b)fluoranthene at a maximum concentration of 27 ppm (RRSCO is 1 ppm). Metals identified include lead at a maximum concentration of 1,360 ppm (RRSCO of 400 ppm), mercury at a maximum concentration of 3.71 ppm (RRSCO of 0.81 ppm), and barium at a maximum concentration of 814 ppm (RRSCO of 400 ppm). There were no exceedances of RRSCOs or PGWSCOs for PCBs or pesticides in soil samples. 1,4-dioxane was not detected above the reporting limit. Perfluorooctane sulfonic acid (PFOS) was detected at a maximum of 11.4 parts per billion (ppb), which exceeds the Protection of Groundwater Guidance Value (PGGV) of 1.1 ppb but does not exceed the Restricted Residential Use Guidance Value (RRUGV) of 44 ppb. Perfluorooctanoic acid (PFOA) was detected at a maximum of 3.08 ppb which exceeds the Protection of Groundwater Guidance Value (PGGV) of 0.8 ppb but does not exceed RRUGV of 33 ppb. Data does not indicate any off-site impacts in soil related to this site. Groundwater - PCE and its associated degradation products are also found in groundwater across the entire site. For VOCs, PCE, was detected at a maximum concentration of 19,000 ppb exceeding its Ambient Water Quality Standards and Guidance Values (AWQSGV) of 5 ppb, and TCE was detected at a maximum concentration of 30 ppb (AWQSGV of 5 ppb). The naturally

114 SNEDIKER AVENUE (Continued) **S129982648**

occurring metals iron, manganese, and sodium were detected at concentrations exceeding the AWQSGVs. These metals are not considered to be site-specific contaminants of concern. There were no exceedances of AWQSGVs for SVOCs, PCBs, and pesticides in groundwater samples. For PFAS, PFOA and PFOS were detected at concentrations of up to 105 and 23.8 parts per trillion (ppt), respectively, exceeding the respective AWQSGV of 6.7 ppt and 2.7 ppt respectively. 1,4-dioxane was detected at a maximum concentration of 0.82 ppb, exceeding the AWQSGV of 0.35 ppb. Data indicates there is potential for off-site impacts in groundwater related to this site. Soil Vapor - Elevated concentrations of VOCs were detected in all soil vapor samples collected from 12 soil vapor points, including PCE ranging from 200 micrograms per cubic meter (ug/m3) to 10,000,000 ug/m3, and TCE ranging from 23 ug/m3 to 250,000 ug/m3. Additionally, cis-1,2-dichloroethylene (DCE) was detected in multiple soil vapor samples at concentrations up to 5,800 ug/m3. Data indicates there is potential for off-site impacts in soil vapor related to this site.

Health Problem: Access to the site is restricted by a fence. However, people who enter the site may come into contact with contaminants in soil by walking on the site, digging, or otherwise disturbing the soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into structures and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion (SVI). The site is vacant so inhalation of site contaminants in indoor air on-site via the SVI pathway is not a current concern. However, the potential exists for inhalation of site contaminants due to SVI for any future on-site development. Environmental sampling indicates that SVI related to site-contamination is a potential concern for off-site structures.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2023-04-19 12:36:00
Record Upd: 2024-02-21 14:26:00
Updated By: JHOCONNE
Own Op: Document Repository
Sub Type: NNN
Owner Name: Paul Levy
Owner Company: Brooklyn Public Library, Brownsville Library
Owner Address: 61 Glenmore Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11212
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: Michael Bellovin
Owner Company: Legion Lighting Co.
Owner Address: 155 Marcus Boulevard

114 SNEDIKER AVENUE (Continued) **S129982648**

Owner Addr2:	Not reported
Owner City,St,Zip:	Hauppauge, NY 11788
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	JOSEPH RAMOS
Owner Company:	Glenmore Owner LLC
Owner Address:	116 E 27th St, 11th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Melinda Perkins
Owner Company:	Brooklyn Community Board 5
Owner Address:	127 Pennsylvania Avenue, 2nd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn,, NY 11207
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Thomas hameline
Owner Company:	HELP Glenmore WAC Housing Development Fund Corporation.
Owner Address:	115 East 13th St
Owner Addr2:	C/o H.E.L.P. USA, Inc.
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Thomas hameline
Owner Company:	HELP Glenmore WAC Housing Development Fund Corporation.
Owner Address:	115 East 13th St
Owner Addr2:	C/o H.E.L.P. USA, Inc.
Owner City,St,Zip:	New York, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	JOSEPH RAMOS
Owner Company:	Glenmore Owner LLC
Owner Address:	116 E 27th St, 11th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
HW Code:	C224385
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	benzo(a)pyrene

114 SNEDIKER AVENUE (Continued) **S129982648**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224385
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

267
NW
1/4-1/2
0.274 mi.
1449 ft.

228 HULL ST **NY LTANKS** **S102673365**
228 HULL ST **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
94 ft.

LTANKS:

Name:	228 HULL ST
Address:	228 HULL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9600752 / 2003-12-15
Facility ID:	9600752
Site ID:	207681
Spill Date:	1996-04-16
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1996-04-16
CID:	349
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

228 HULL ST (Continued) **S102673365**

Remediation Phase:	0
Date Entered In Computer:	1996-04-16
Spill Record Last Update:	2003-12-15
Spiller Name:	Not reported
Spiller Company:	HPD
Spiller Address:	230 HULL ST
Spiller County:	001
Spiller Contact:	ANNA CHAMBERS
Spiller Phone:	(718) 385-2076
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	172329
Latitude:	40.6799838
Longitude:	-73.9065620
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 12/15/03 - AUSTIN - UNCONFIRMED REPORT OF SURF. SPILL AT FILL BOX ALMOST 8 YRS. AGO - CLOSED - ORIG. ASSIGNED TO SIGONA - END
Remarks:	Caller states the oil co spills each week a delivery is made - also strong odor of oil

All Materials:

Site ID:	207681
Operable Unit ID:	1032194
Operable Unit:	01
Material ID:	354149
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AK268 **SUNOCO GAS STA** **NY LTANKS** **1001010572**
NE **35 HIGHLAND BLVD** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.284 mi.
1500 ft. **Site 1 of 2 in cluster AK**

Relative: **Higher**
Actual: **106 ft.**

LTANKS:

Name:	SUNOCO GAS STA
Address:	35 HIGHLAND BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9709845 / 2006-04-14
Facility ID:	9709845
Site ID:	267776
Spill Date:	1997-11-24
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SKCARLSO
Referred To:	NFA 4/14/06
Reported to Dept:	1997-11-24

SUNOCO GAS STA (Continued) **1001010572**

CID:	252
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-11-24
Spill Record Last Update:	2006-04-14
Spiller Name:	MARK MORIN
Spiller Company:	SUNOCO GAS STA
Spiller Address:	35 HIGHLAND BLVD
Spiller County:	001
Spiller Contact:	MARK MORIN
Spiller Phone:	(800) 777-6444
Spiller Extention:	8860
DEC Region:	2
DER Facility ID:	218140
Latitude:	40.6796516
Longitude:	-73.8990890
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SUN 12/10/2003 Reassigned from Tipple to Sun. 12/21/05: Case reassigned to Andersen. Emailed Russell Hammond and he said he will have EnviroTrac perform an investigation. 4/13/06: Received and reviewed environmental site assessment. Three soil borings conducted to 40 feet bgs. Soil tested clean. Groundwater was not encountered, it is suspected to be 90 feet bgs. 4/14/06: NFA issued 4/14/06.
Remarks:	UPON EXCAVATION AT SUNOCO CONTAMINATED SOIL WAS DISCOVERED-SOIL HAS BEEN STOCKPILED FOR CLEANUP AND FURTHER INVESTIGATION CONTINUES.

All Materials:

Site ID:	267776
Operable Unit ID:	1056219
Operable Unit:	01
Material ID:	328176
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	SUNOCO
Address:	35 HIGHLAND BLVD
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9709827 / 1998-01-30
Facility ID:	9709827
Facility Type:	ER
DER Facility ID:	218140
Site ID:	267775
DEC Region:	2

SUNOCO GAS STA (Continued) **1001010572**

Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1997-11-24
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-11-24
CID:	366
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-11-24
Spill Record Last Update:	1998-02-06
Spiller Name:	MARK MORAN
Spiller Company:	SUNOCO
Spiller Address:	35 HIGHLAND BLVD
Spiller Company:	001
Contact Name:	MARK MORAN
Latitude:	40.6796516
Longitude:	-73.8990890
DEC Memo:	Not reported
Remarks:	CALLER REPORTING A LEAK IN INNER WALL OF PIPE. PRODUCT IS CONTAAINED IN OUTER WALL.

All Materials:

Site ID:	267775
Operable Unit ID:	1056196
Operable Unit:	01
Material ID:	328159
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AK269 **SUNOCO GAS STA** **UST FINDER RELEASE** **1029066097**
NE **35 HIGHLAND BLVD** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.284 mi.
1500 ft. **Site 2 of 2 in cluster AK**

Relative: **Higher**

Actual: **106 ft.**

UST FINDER RELEASE:

Object ID:	258885
Facility ID:	NY218140
Lust ID:	NY9709845
Name:	SUNOCO GAS STA
Address:	35 HIGHLAND BLVD

SUNOCO GAS STA (Continued) **1029066097**

City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1997/11/24 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2609
Domestic Wells within 1500ft:	0
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8990899999999
Y Coord:	40.67965
Latitude:	40.67965
Longitude:	-73.89909

---

270 WNW 1/4-1/2 0.285 mi. 1504 ft.

33 TRUXTON STREET
33 TRUXTON STREET
BROOKLYN, NY

NY NYC OER **S129932325**
N/A

Relative: Higher

Actual: 94 ft.

NYC OER:

Name:	33 TRUXTON STREET
Address:	33 TRUXTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678378
Longitude:	-73.908065
OER Project Numbers:	18TMP1417K,18EH-N489K
BBL:	3.01543000130154E+19
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	369
BIN:	3330731
NTA:	Ocean Hill

271
SW
1/4-1/2
0.297 mi.
1568 ft.

CON EDISON SERVICE BOX: 29407
103 LIBERTY AVE
BROOKLYN, NY 11212

NY VCP **1016971087**
RCRA NonGen / NLR **NYP004448205**
NY MANIFEST
NY NYC OER

Relative:
Lower

Actual:
56 ft.

VCP NYC:

Project ID:	21TMP0374K,21EH-N087K,21CVCP060K
Name:	103 LIBERTY AVENUE
Address:	103 LIBERTY AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,367,500,253,036,700,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.672868
Longitude:	-73.906894
Postcode:	11212
Community Board:	16
Council District:	37
Census Tract:	908
BIN:	3414073
NTA:	Brownsville

RCRA Listings:

Date Form Received by Agency:	20140321
Handler Name:	Con Edison Service Box: 29407
Handler Address:	Liberty Ave
Handler City,State,Zip:	BROOKLYN, NY 11212
EPA ID:	NYP004448205
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

CON EDISON SERVICE BOX: 29407 (Continued) **1016971087**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140221
Handler Name: CON EDISON SERVICE BOX:	29407
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140321
Handler Name: CON EDISON SERVICE BOX:	29407
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 29407 (Continued) **1016971087**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004448205
Country: USA
Name: Con Edison
Address: 103 LIBERTY AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11212
Zip 4: Not reported
Location Address 1: 99 LIBERTY AVE
Location Address 2: SB29407
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 02/21/2014
Trans1 Recv Date: 02/21/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/21/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004448205

CON EDISON SERVICE BOX: 29407 (Continued) **1016971087**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002358881GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

NYC OER:

Name:	103 LIBERTY AVENUE
Address:	103 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.672868
Longitude:	-73.906894
OER Project Numbers:	21TMP0374K,21EH-N087K,21CVCP060K
BBL:	3.03675002530367E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	11212
Community Board:	16
Council District:	37
Census Tract:	908
BIN:	3414073
NTA:	Brownsville

272
West
1/4-1/2
0.299 mi.
1581 ft.

AKA 31-33 MONACO PLACE
2121 MONACO PLACE
BROOKLYN, NY

NY LTANKS **S106971540**
N/A

Relative:
Higher

Actual:
85 ft.

LTANKS:

Name:	AKA 31-33 MONACO PLACE
Address:	2121 MONACO PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0408751 / Not Reported
Facility ID:	0408751
Site ID:	333492
Spill Date:	2004-11-08
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	DELINEATION TO FOLLOW
Reported to Dept:	2004-11-08
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	1
Date Entered In Computer:	2004-11-08
Spill Record Last Update:	2024-08-20
Spiller Name:	MAURICE
Spiller Company:	Not reported
Spiller Address:	31-33 MONOCO PLACE
Spiller County:	001
Spiller Contact:	MAURICE
Spiller Phone:	(516) 482-0276
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	268724
Latitude:	40.6763620
Longitude:	-73.9090200
DEC Memo:	During excavation to re-develop the lot, two 550 gallon gasoline ust's were uncovered. DC Env. was retained to remove the tanks. A gas-water mix was pumped from the tanks and soil contamination was encountered. A contaminated soil letter was sent. New Owner Maurice Shami- #212-656-1338 Maurice called and stated that DC spilled the gas while conducting the pump out. Maurice requested and was given the names and numbers of 6 additional consultants upon his request. 11/17/04-Vought-Spoke to Reza Khanbilzardi who is a consultant (Indertech Consultants 914-329-3440) who is requesting DEC requirements. DEC requires: 1)collection of five endpoint soil samples and EPA Methods 8260/8270 2)collection of one groundwater sample 3)locations of fill ports and pump islands 4)copies of soil disposal manifests 5)site plan with sampling locations. 1/12/04 Bill Vardy left message 914-329-3440 requesting 10 day extension to submit report. Rommel 1/26/05-Vought-Spoke to Reza and he is requesting an additional ten days to submit report. Report will be submitted by

AKA 31-33 MONACO PLACE (Continued) **S106971540**

2/8/05. 02/08/05 Reza called 914-329-3440. He is the engineer representing the owner. He will overnight the report tomorrow. Rommel 2/11/04-Vought-Received message from Reza on 2/9/05. Vought returned call and he sent report via FedEx to Rommel. Vought told him to call Rommel on 2/14/05. 3/3/05 - Spoke to Reza Khanbilvardi, he is asking a quick review of the closure report. He stated that only minor contamination found with the soil boring and sampling. Need to find the report and get back to him for a determination. - KST 3/8/05 - Owner, Maurice, called and begging to review the closure report. I told him that we have not received the report. He will called his consultant to get a copy and hand deliver it to DEC. - KST 3/9/05-Vought-Spill transferred from Rommel to Vought as per Tang. Review of Subsurface Investigation Report submitted by InterTech Inc (Reza Khanbilvardi)dated 2/9/05 and received on 3/7/05. Owner of property is Maurice Shami. The site is vacant land... A small excavation (approximate size of 12 ft wide by 16 foot long and 7 ft deep were noticed on the southwest portion of the site. This is the location of the two empty oil tanks which resulted in above spill number to be issued . Five endpoint soil samples were collected on 12/7/05. One groundwater sample was also collected. Since all soil samples taken at the site meets recommended soil cleanup objective criteria and semi-volatile compounds in groundwater are not detected, the elevated volatile amount in groundwater could not have been due to any element on the property. It must be noted that an active commercial gas station is on the other corner of Monaco Place and Atlantic Avenue . Report recommends that we don't believe that any action with respect to soil cleanup is warranted for this site . Site plan shows three proposed two-story buildings onsite. Groundwater at depth of 12' below grade. Groundwater analyticals show 61ppb benzene, 300ppb toluene, 72ppb ethylbenzene, 200ppb xylene and 14ppb MTBE. DEC requires signing of Stipulation Agreement: 1)locations of fill ports and pump islands 2)notification to NYC agencies requesting no development of site 3)determination of groundwater flow direction via installation of three monitoring wells 4)installation of vapor barrier upon development of site 5)installation of passive venting system or performance of soil gas sampling as per NYSDOH guidance upon development of site 6)surrounding area site plan. Vought called Khanbilvardi and left message to return call to DEC. Vought sent Stipulation with above requirements with due date of 4/18/05. 3/10/05-Vought-Received message from Reza. Vought returned call and left message to return call to DEC. 3/14/05-Vought-Meeting at DEC with Reza and Maurice Shami. DEC will give approval to start construction once we receive and approve plan for vapor barrier and three onsite monitoring wells. No passive ventilation system or soil gas sampling will be required due to clean soil endpoints, lack of basement, relatively minor groundwater contamination and 6' depth to groundwater. 3/15/05-Vought-Received call from Maurice Shami (516-482-0276) and copy of bargain and sale deed which referred to previous owner as: Stephen Carter 679 East 98th Street Brooklyn, NY Vought called Shami and left message to return call to DEC. 3/22/05-Vought-Received fax from Inter Tech dated 3/16/05. .... we came to the decision to do the following: 1)the owner of the above referenced property will install a vapor barrier under the footings and basement floor slabs of the proposed construction on the site. This will be done after the excavation and prior to pouring the concrete of the foundation. The owner will install three monitoring wells...to determine groundwater flow direction with respect to the

AKA 31-33 MONACO PLACE (Continued) **S106971540**

above site . You will provide approval letter to install these wells on the sidewalk . I appreciate your acknowledgement of receiving this letter and also your consent to it and start of the construction at the site so Mr. Shami can proceed with the construction . Vought sent out sidewalk permit letter and called Inter Tech to explain that consent to begin construction will not be given until groundwater results are received and groundwater flow direction is determined. 3/29/05-Vought-Called Maurice Shami for update on site and left message to return call. 3/31/05-Vought-Received call from Reza that wells were scheduled to be installed tomorrow and whether sidewalk permit was needed due to DEC sidewalk permit letter. Vought explained that letter was to effectuate the obtaining of a permit and that the permit was still required from DOT. 4/5/05-Vought-Received message from Reza. Vought returned call and left message to return call to DEC. Vought spoke to Reza and he will install wells onsite as opposed to sidewalk so that sidewalk permits are not needed. 5/19/05-Vought-Reviewed Investigation Report (Inter Tech) dated 5/17/05 and received on 5/18/05. Installation of three 4-inch monitoring wells. Contractor who installed wells was American Environmental Assessment Corp. Report recommends ....we do not believe that any action with respect to cleanup is warranted for this site. We therefore, request your approval to start the construction project as the owner is patiently waiting for the last 6 months . Groundwater analyticals show: 13ppb ethylbenzene(MW2), 82ppb MTBE(MW2), 120ppb n-propylbenzene(MW2), 72ppb isopropylbenzene(MW2), 440ppb MTBE(MW3). Source of minor groundwater contamination may be from onsite UST excavation (despite clean endpoints) or from upgradient site(due to minor groundwater contamination in well MW2). DEC sent letter approving construction of residence with installation of vapor barrier as per 3/16/05 letter and requiring as per 3/9/05 STIP cover letter: 1)surrounding area site plan with possible upgradient sources 2)continued quarterly monitoring of groundwater 3)installation of well downgradient from former tankfield and Boring B1 on sidewalk of Atlantic Avenue 4)submission of PBS registration 5)locations of remote fill and dispenser islands. Vought called Maurice and left message. 5/27/05-Vought-Spoke with Maurice and five additional tanks discovered during excavation for building. Maurice is hiring American Environmental to remove the tanks. Maurice will call back with update on tank removal. Maurice returned call and American (631-586-2000 Danny Herzberger) will do tank removal on 6/6/05. 6/1/05-Vought-Received call from Herschberger. Vought returned call and left message to return call. 6/6/05-Vought-Received call from Herschberger(516-852-4713). Vought returned call and tanks registered with PBS. Five endpoint samples will be collected and sampled for 8021 plus MTBE and 8270. Dan will call DEC when excavation is complete so that site visit may be scheduled. Received call from Dan that tanks were removed and impacted soil was found. Vought required excavation of impacted soil and called Maurice to restate requirement. 6/7/05-Vought-Received call from Herschberger. Vought returned call and American will only be removing tanks and underlying pad. A sixth tank was discovered and Maurice's contractor will be removing contaminated soil. American will be collecting endpoint samples. Vought received call from Maurice and returned call and left message to return and stated requirement of disposal manifests. Vought received second message from Maurice and returned call. 6/8/05-Vought-Received third message from Maurice and returned call. Vought spoke to Maurice and stated requirement of disposal

AKA 31-33 MONACO PLACE (Continued) **S106971540**

manifests and site visit. Maurice will collect two soil samples and submit to laboratory for analyses to see if further excavation is warranted. Vought advised use of field screening device however due to possibility of saving further cost of excavation Maurice decided to collected samples. 6/10/05-Vought-Received call from Maurice. Vought returned call and arranged site visit for Wed 6/15. 6/15/05-Vought-Site visit by Vought with Maurice, Dan Herschberger and Reza. Contaminated soil at former UST location and DEC required 1)additional excavation to groundwater 2)collection of four sidewalls and one bottom groundwater endpoint sample 3)installation of vapor barrier(agreed to by Maurice) 4)well installation downgradient from tankfield along Atlantic Ave. Vought also suggested groundwater treatment when excavation was open and boring by Amoco to see if they are contributing source. Vought will send above requirements upon receiving endpoint analyticals. 7/26/05-Vought-Called Maurice for status update of site. No work has been performed as of yet due to unable to find contractor. 7/29/05-Vought-Spoke to Gerard Rutigliano (Rutigliano Environmental 516-314-1553) and he may be performing soil removal and vapor barrier installation. Vought approved installation of a 6.mil vapor barrier under building footprints. Four sidewall endpoint and one bottom groundwater sample will be collected. 8/8/05-Vought-Called El-Shami, Reza and Rutigliano and informed them of new project manager (DEC Zhitomirsky). Vought spoke to Maurice El-Shami and approved that he install vapor barrier provided that he sent letter in writing to DEC. Vought also stated that vapor mitigation system was not necessary as long as excavation was performed to groundwater (12' below grade). 8/8/2005 Zhitomirsky spoke with Maurice Shami and requested submittal of soil disposal manifest, drawings showing where the soil was excavated from, drawings and description of vapor barrier installation. Jeffry Voight informed me that he requested from the site owner a description of the vapor barrier. In this case Vought would not require a vapor mitigation system and allow RP to install the vapor barrier himself. AZ 8/10/2005 I discussed this site with K.Tang. I told him I am requiring environmental report describing soil excavation with pictures, drawings and disposal manifest. Also, RP should include specifications and drawings for vapor barrier. K.Tang concurred and stated that we can issue permission to start construction and install vapor barrier. K.Tang thinks that 6 mil thickness polyethylane sheeting may be not thick enough and RP consultant should suggest another one. I conveyed this information to Morris Yeroshalmi and provided him with K. Tang phone number upon his request. AZ 8/17/2004 KT visited the site on 8/12/2005. He noticed that the excavation could cave in because it is 11 feet deep. He said that there is not much to see in the excavation except gravels and dirt. No petroleum odor, no stained soil. They have put some soil back in the tank pit. He asked a soil sample at the center of the tank pit taken at the water table. He could smell a slight petro odor. Not bad though. Due to safety concern of the side walk on Atlantic Ave side of the excavation collapsing, he told Maurice to go ahead with his construction work and backfill the hole, with the condition that he put down the vapor barrier material (15 mil) below the foundation of the buildings he is putting up. He also told him to compile all the tank removal, soil excavation, wells installation, soil removal activities, soil samples, water samples and the soil disposal manifest in a report for you. He also told him to install 4 wells - 1 on Monaco Pl, 3 on Atlantic Ave. for GW monitor and/or remediation.

AKA 31-33 MONACO PLACE (Continued) **S106971540**

AZ 11/22/2005 I received an e-mail from K Tang. He asked me to issue a letter to Moris Shami (Mfund Company 516-482-0276). I called him and conveyed that as per K.Tang 4 wells should be installed one on Monaco Place and three on Atlantic Avenue. His address is: 1 Linden Place Suite#302 Great Neck, New York 11021.AZ 11/29/2005 I called Moris and informed him that he should install 3 wells on Atlantic Ave. and one well between his place and BP station. I confirmed this request with K. Tang. I sent him a letter so he can obtain a permission from DOT to install sidewalk wells. AZ 1/18/2006 The owner (Moris) has contacted me. He needed some kind of a letter for the City. I replied that we do not isuue such letters. He is going to proceed with the well installation. AZ 4/4/2006 I left a message for owner Moris (516-482-0276). He called me back. Hydro Tech installed wells and is working on the report for DEC. AZ 5-11-2006 Left a message for Rachel Ataman (Hydro Tech Environmental). AZ 5-16-2006 I contacted Sharissa Singh 718-636-0800(Hydro Tech Environmental). She informed me that Rachel Ataman is no longer handles this project. I conveyed to Ms. Singh that the plume should be delineated and once the delineation has been completed a remedial plan should be sumbitted. AZ 5-17-2006 Reviewed the Groundwater Investigation Report prepared by Hydro Tech Environmental Corp., dated April 4, 2006. The report states that VOCs were detected in the groundwater samples obtained from wells MW-1 through MW-4 at concentrations exceeding their respective TOGS standards. The total VOC concentrations at the site range from 1,111 ppb to 523 ppb in downgradient wells. Hydro Tech Environmental recommended groundwater monitoring. After consultation with Koon Tang, I requested delineation of the groundwater plume in the southern area of the site by installing two new wells. If contamination is encountered by these downgradient wells, additional wells should be installed to fully delineate the plume. Once the plume has been delineated, a remedial plan to address the contamination should be submitted to DEC. A letter was sent to the RP and the consultant. AZ 5-25-2006 I reiterated myc comments regarding the submitted report to the owner Maurice Shami over the phone. AZ 10-24-2006 Left a message for the owner Maurice @ 516-482-0276. AZ 10/25/2006 Contacted the owner Maurice @ 516-482-0276. He is hiring an environmental consultant American Environmental Co. He will get back to DEC when the consultants are hired. AZ 11-5-2007 Contacted the owner Maurice @ 516-482-0276 and requested about the site status. He stated that he thinks that no work should be done at this site. He will contact me with more information ASAP. AZ 11-7-2007 Spoke with Maurice Chami (M Fund 45 North Station Plaza Great Neck New York 11021). Mr. Shami is stating that he sold the property but he does not know whom he sold the property to, since the sale was handled by his broker. He will get back to me with this information ASAP. Mr. Shami contacted me later and informed that the buyer is Victor Inwang 31 Monaco Place, Brooklyn, New York 11221. He sold the property in May or June of 2006 (his guess).It is a private dwelling. AZ 11-14-2007 Case Initiation Form was signed by Vadim Brevdo and forwarded to John Urda. AZ 7-29-2008 J. Urda requested that CSL, STIP are send to RP. I sent drafts of CSL, STIP and CAP to John Urda and V. Brevdo for review. They approved the documents. CSL,STIP and CAP were sent to Maurice Chami- M Fund, 45 North Station Plaza, Great Neck, NY 11021 and Victor P. Inwang 1400 Bedford Avenue, Brooklyn, New York 11216. Copies were sent to V.B and John Urda. AZ 8-21-2011 The letter was returned to DEC stating: Return to Sender unclaimed unable to forward

AKA 31-33 MONACO PLACE (Continued) **S106971540**

AZ 3-17-2011 As per J. Urda request, STIP, CSL and CAP were resent to Victor P. Inwang 1400 Bedford Avenue, Brooklyn, New York 11216 and send to Victor P. Inwang 583 Eastern Parkway, Brooklyn, NY 11216. AZ 4-11-2011 Two letters were returned to DEC stating Return to sender unclaimed unable to forward. I informed J. Urda about the returned letters. AZ

Remarks: 2 550 gal tanks

All Materials:

Site ID:	333492
Operable Unit ID:	1095646
Operable Unit:	01
Material ID:	575767
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

273
WSW
1/4-1/2
0.301 mi.
1587 ft.

2175 BERGEN STREET **NY VCP S129932176**
217-221 MOTHER GASTON BOULEVARD **NY NYC OER N/A**
NEW YORK CITY, NY

Relative:
Lower

Actual:
63 ft.

VCP NYC:

Project ID:	19TMP0747K,19EHAN199K,19CVCP055K
Name:	2175 BERGEN STREET
Address:	217-221 MOTHER GASTON BOULEVARD
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	301,450,000,130,145,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.674093
Longitude:	-73.908345
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3000000
NTA:	Ocean Hill

NYC OER:

Name:	2175 BERGEN STREET
Address:	217-221 MOTHER GASTON BOULEVARD
City,State,Zip:	BROOKLYN, NY
Latitude:	40.674093
Longitude:	-73.908345
OER Project Numbers:	19TMP0747K,19EHAN199K,19CVCP055K
BBL:	3.0145000013014499E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)

2175 BERGEN STREET (Continued) **S129932176**

Phase:	Site Management
URL:	
Postcode:	11233
Community Board:	16
Council District:	37
Census Tract:	36502
BIN:	3000000
NTA:	Ocean Hill

AJ274 **UNKNOWN** **NY LTANKS** **S109371558**
East **2642 FULTON ST.** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.311 mi.
1640 ft. **Site 2 of 2 in cluster AJ**

Relative:
Lower

Actual:
58 ft.

LTANKS:

Name:	GULF
Address:	2642 FULTON ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1909031 / Not Reported
Facility ID:	1909031
Site ID:	599249
Spill Date:	2019-12-15
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-12-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2019-12-15
Spill Record Last Update:	2019-12-16
Spiller Name:	STEVE FARINO
Spiller Company:	GULF
Spiller Address:	2642 FULTON ST
Spiller County:	999
Spiller Contact:	STEVE FARINO
Spiller Phone:	(845) 661-2184
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	353391
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/16/19-Zhune spoke to Steve Farino 845-661-2184. Steve said the diesel tank failed the test with a ullage portion leak. 12/1619- A TTF letter was sent to: Efran Castro 2642 Fulton Street Brooklyn NY 11207
Remarks:	tank test failure- 200 gallon tank #04

UNKNOWN (Continued) **S109371558**

All Materials:

Site ID:	599249
Operable Unit ID:	1346754
Operable Unit:	01
Material ID:	2357124
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	UNKNOWN
Address:	2642 FULTON ST.
City,State,Zip:	BROOKLYN, NY 11207
Spill Number/Closed Date:	1909345 / 2019-12-30
Facility ID:	1909345
Facility Type:	ER
DER Facility ID:	548622
Site ID:	599939
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2019-12-27
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-12-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-12-28
Spill Record Last Update:	2019-12-30
Spiller Name:	Not reported
Spiller Company:	GULF GAS STATION
Spiller Address:	2642 FULTON ST.
Spiller Company:	999
Contact Name:	UNKNOWN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/30/19-Lin-Unknown report received through email. No contact information. Case closed.
Remarks:	Central received the below email: The following information was received through the DEC website "Report an Environmental

UNKNOWN (Continued) **S109371558**

Violation Online" or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: gulf gas station What Occurred: there is a petroleum spill. A leak in the gas tank. When Did It Occur: 12/27/2019 County: New York Municipality: brooklyn Location Or Address: 2642 Fulton St, Brooklyn, NY 11207 How Did It Occur: Complainants Name: Complainants Phone: Complainants Email: Date of Submittal: 12/28/2019

All Materials:

Site ID:	599939
Operable Unit ID:	1347086
Operable Unit:	01
Material ID:	2357488
Material Code:	9999
Material Name:	other - petroleum
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	GULF STATION
Address:	2642 FULTON ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0806851 / 2008-12-24
Facility ID:	0806851
Facility Type:	ER
DER Facility ID:	353391
Site ID:	404152
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-07-30
Investigator:	MXAJOKU
Referred To:	Not reported
Reported to Dept:	2008-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-17
Spill Record Last Update:	2008-12-24
Spiller Name:	DAN YAROM
Spiller Company:	GULF STATION
Spiller Address:	2642 FULTON ST
Spiller Company:	999
Contact Name:	DAN YAROM
Latitude:	40.6771450

UNKNOWN (Continued) **S109371558**

Longitude: -73.8971780
DEC Memo: 12/24/08: Spill has been removed from the sumps, and disposed off. by consultant (C.D.S.P Corp.) to the facility owner. Document to this effect was dated 11/17/08. Spill case is closed (MA).
Remarks: CALLER STATES THAT A TANK WAS OVER FILLED AND PRODUCT WENT INTO PUMP. NO PRODUCT WAS SPILLED.

All Materials:
Site ID: 404152
Operable Unit ID: 1160824
Operable Unit: 01
Material ID: 2152006
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: 1.00
Resource Affected: Not reported
Oxygenate: Not reported

---

275 South 1/4-1/2 0.336 mi. 1773 ft.

GERSHOW RECYCLING OF BROOKLYN **NY SWF/LF** **S128178159**
1885 PITKEN AVENUE **N/A**
BROOKLYN, NY 11212

Relative: Lower

Actual: 46 ft.

SWF/LF:
Name: GERSHOW RECYCLING OF BROOKLYN
Address: 1885 PITKEN AVENUE
City,State,Zip: BROOKLYN, NY 11212
Flag: ACTIVE
Region Code: 2
Phone Number: 7183452240
Owner Name: Gershow Recycling Corporation
Owner Type: Private
Owner Address: P.O. Box 526
Owner Addr2: Not reported
Owner City,St,Zip: Medford;, NY 11763
Owner Email: decinfo@gershow.com
Owner Phone: 6312896188
Contact Name: Ray Colon
Contact Address: P.O. Box 526
Contact Addr2: Not reported
Contact City,St,Zip: Medford, NY 11763
Contact Email: decinfo@gershow.com
Contact Phone: 6312896188
Activity Desc: Vehicle Dismantling Facility
Activity Number: [7090157]
Active: Yes
East Coordinate: 592695
North Coordinate: 4502800
Accuracy Code: 1 - No accuracy stated
Regulatory Status: Not reported
Waste Type: Not reported

GERSHOW RECYCLING OF BROOKLYN (Continued) **S128178159**

Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported
Name:	GERSHOW RECYCLING OF BROOKLYN
Address:	1885 PITKEN AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183452240
Owner Name:	Gershow Recycling Corporation
Owner Type:	Private
Owner Address:	P.O. Box 526
Owner Addr2:	Not reported
Owner City,St,Zip:	Medford;, NY 11763
Owner Email:	decinfo@gershow.com
Owner Phone:	6312896188
Contact Name:	Ray Colon
Contact Address:	P.O. Box 526
Contact Addr2:	Not reported
Contact City,St,Zip:	Medford, NY 11763
Contact Email:	decinfo@gershow.com
Contact Phone:	6312896188
Activity Desc:	Mobile Vehicle Crushers
Activity Number:	[24J]
Active:	No
East Coordinate:	592694
North Coordinate:	4502797
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

276
NW
1/4-1/2
0.344 mi.
1817 ft.

APARTMENT BUILDING
211 HULL STREET
BROOKLYN, NY

NY LTANKS **S108466382**
NY Spills **N/A**
NY NYC LAND USE

Relative:
Higher

Actual:
89 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0612788 / 2007-09-17
Facility ID:	0612788
Site ID:	377715
Spill Date:	2007-02-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4

APARTMENT BUILDING (Continued) **S108466382**

Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2007-02-26
CID:	408
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-02-26
Spill Record Last Update:	2007-09-17
Spiller Name:	Not reported
Spiller Company:	APARTMENT BUILDING
Spiller Address:	211 HULL ST
Spiller County:	999
Spiller Contact:	MEADOWS, RICHARD
Spiller Phone:	(347) 203-6886
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	327460
Latitude:	40.6799150
Longitude:	-73.9082060
DEC Memo:	02/26/07-Vought-DEC Patel performing site visit due to proximity to spill in field. DEC Ketani called FDNY and left message to return call to DEC. 02/27/06-Hiralkumar Patel. visited site on 02/26/07. met Ferdrnand Torres (917-568-3022), tenant at building. Mr. Torres lives on second floor. as per Mr. Torres, there was no heat yesterday (02/26/07) morning and he compalined to NYC HPD. oil delivered during day. lateron tenant found oil in basement and called FDNY. site has two 275 gal #2 oil ASTs on leg and FDNY found one of these tanks was leaking. they pumped out oil from leaking tank and put in drums and spread absorbent in basement. three 55 gal drums were out of building on sidewalk. second tank is still in use. as per Mr. Torres there is no super in building but Mr. Torres has keys to basement. at time of visit, heavy odors inside basement, free product around tank and odors upstairs also. Mr. Torres's mother and brother living on first floor. suggest Mr. Torres to get these people on second floor as there was no odors. this building ownes by NY City. Mr. Torres gave contact info for person managing property for city. Francis SynMoie 7A Admin. Bld #042 C/O NY Residential Works Inc. 347 Lenox Avenue New York, NY 10027 Ph. (212) 987-8088 Ext. 105 left message for emergency service at NY Residential Works at night. received call from Basil Marshall (646-294-0086). asked him to get cleanup crew to start cleanup for free product and odors in building. he spoke with Anthony Lara (646-772-7180). received call from Anthony. he was ready to send cleanup crew in night but he need approval from city and proposal signed by authorized person, which he hadn't got. tried to contact Mr. Marshall again regarding signing paperwork, but no contact was made. left message for Mr. Marshall. left message for Mr. SynMoie at NY Residential works last night. spoke with Mr. SynMoie this morning. they are still working on getting authorization from city agency for cleanup. asked Mr. SynMoie to start cleanup by end of today. 2/27/07 - Raphael Ketani. I contacted Mr. Francis Synmoie (sin-moy) at NY

APARTMENT BUILDING (Continued) **S108466382**

Residential Works, Inc. (212) 987-8088, ext 101. He said that he is still waiting for authorization to hire a contractor to do the cleanup, but someone already put down absorbent. He said that he contacted Debra Thomas of Unit 7A at HPD (212) 863-7392. He said she has the authority to authorize someone to cleanup the spill. I asked him how the odors are. He said that you notice a moderate odor of oil as you walk into the building, but no one lives on the first floor. I asked him about the odors on the second floor. He said there were none. He said that this building was owned by a private party, but they didn't keep it up. So the city took it over and they will refurbish it. I spoke to Ms. Thomas. She said the City doesn't own the building, but is managing it. I asked her what is happening now. She said that a call was made to the Emergency Repair Unit as there is no money in the budget to pay for the cleanup. She said she is waiting for a call back. I told her that this spill is now at least 24 hours old. She said she knows, but all she can do right now is to call the Emergency Repair people. I told her that certain things will have to be done to cleanup the spill. She asked me to e-mail her what these requirements are. The requirements are: (1) cleanup all of the free oil (2) pickup all of the spent absorbent (3) powerwash the affected areas and the concrete floor (4) take soil samples below the concrete floor and send them to a NYSDOH certified lab for 8260 and 8270 analysis (5) remove all contaminated soil (6) submit manifests for all soil and contaminated material that is removed and the soil analytical results (7) repair the tank system and send copies of the documentation verifying that the repairs were made (8) submit to DEC a short report with pictures (if possible) of the before and after conditions and all documentation Ms. Thomas' e-mail address is thomasd@hpd.nyc.gov 3/12/07 - Raphael Ketani. Spill case #0613303 came in today regarding a new spill at the site. I spoke to Patrick Fahey of Pacific Energy (718) 647-1400 about the spill. He said that it was a loose flare nut that allowed oil to drip onto the floor. About 1 gal. leaked out. The flare nut was tightened, but the earlier large spill hasn't been cleaned up yet. This later spill case was closed. I spoke to Ms. Thomas regarding the old big spill of 2 weeks ago. She said she just got back from vacation and had been told the old spill had been cleaned up. I told her that Pacific Energy had a mechanic on site about 1 hour ago and he said the old spill was not removed. She told me that she will look into the issue and call me back. 3/23/07 - Raphael Ketani. I tried to make a site visit. The front door was locked and there was no one around to let me in. I didn't see or smell any signs of an oil release. 3/27/07 - Raphael Ketani. I made a site visit at 9:45AM today and was shown the basement by a second floor resident of the building who goes by the name of Rio and serves as a helper for Mr. Synmoie. The vapors were light but noticeable in the first floor hallway. The vapor readings were: basement 1334 ppb, first floor 903 ppb, second floor 782 ppb, third floor 751 ppb. Rio explained to me that the tanks are still not sitting solidly on the floor and that there were 2 big spills - both due to the tanks moving and a line below them getting loose. There was a 12 by 6 wet spot below the oil line that connects the two tanks at the bottom. Rio showed me that one spill flowed 30 feet down the basement hallway and into the adjacent room. The floor was in very bad shape and was in pieces, many of which could be moved by hand exposing the soil below. The floor had dark staining all over and so did the floor of the adjacent room. Lastly, Rio showed me the boiler room. The floor there also had staining. 3/28/07 - Raphael Ketani. I

APARTMENT BUILDING (Continued) **S108466382**

spoke to Mr. Synmoie and told him about the floor, the high vapor readings, the oily wet spot, the oil staining, and the probability that the soil under the basement floor is contaminated. I told him that he has to hire a company to stabilize the tanks, fix the line at the bottom if it is still dripping, do a soil investigation and ventilate the building. He said he will do this. He said there is one tenant on the first floor and she will be moved to the second floor. He said that the building is scheduled for rehabilitation in the very near future. I told him that the soil investigation has to get started as soon as possible. He said he will call Ms. Thomas. I sent Ms. Thomas an e-mail with my notes from 3/27 and 3/28. 3/29/07 - Raphael Ketani. Chacko Thomas (cell (646) 865-4564) [supervisor (718) 857-5444] of NYC HPD called to say that 6 soil samples were taken in the floor of the building after the last oil spill. He said samples were taken in the tank room, the hallway, and the storage rooms. The analytical results should be available soon. He asked what else needed to be done at the site. I told him that the vapors are high so ventilation needs to be provided, the tanks need to be fixed to the floor so they don't move, the line at the bottom of the tanks needs to be fixed so it doesn't drip, and a soil boring needs to be taken in the boiler room floor. Mr. Chafeko said he will have this done. 4/4/07 - Raphael Ketani. Mr. Thomas of NYC HPD sent me a FAX for SVOC analysis for 4 of the 5 samples that were taken in the basement. He said he was expecting the VOC analysis today and will FAX them as soon as he gets them. There were only 2 very low exceedences of the TAGM RSCO limits. I told him these results looked fine. I received a FAX from Mr. Thomas with the VOC analyticals for soil samples 1,2,4,5. The samples were taken on 3/22/07. There were no RSCO exceedences, except 3200 ppb for total xylenes for soil sample #1. This is the tank room sample. Again, soil sample #3 was missing from the results. 4/5/07 - Raphael Ketani. I contacted Mr. Thomas and told him that the results seemed fine, except for total xylene in sample #1. I told him that soil will have to be removed in this area. Afterwards, Mr. Thomas called me up regarding which sample came from what location in the basement. Sample #1 was the tank room. Sample #2 was the storage room next to the tank room. Samples #3 (which he will check on why the results weren't received) to sample #5 were from the hallway. He said that the drip from the pipe at the bottom of the tanks is something new and will be taken care of shortly and that the tank feet were covered in cement to stabilize the tanks. Mr. Thomas said that the stain in the boiler room is only from routine servicing of the boiler. I told him that it seemed like more than routine servicing. He said the service techinician is sloppy and he will talk to him about being careful. However, he said, the building is privately owned and HPD is just overseeing the refurbishing of the building. 4/11/07 - Raphael Ketani. Mr. Thomas FAXed me the analytical results for samples 1,2,4,5. I spoke with him shortly after I received the FAX. He said that the contractor who did the sampling also took samples 3 and 6. However, the contractor threw out these samples as he felt he had enough samples for the site, according to Mr. Thomas. I told Mr. Thomas that either the soil has to be dug out in the tank room or soil treatment needs to be used. He said that he has to make a work order, in either case. I asked him to try and push the process forward. He said he would try. 5/18/07 - Raphael Ketani. Mr. Thomas of HPD (718) 857-5444 sent me a FAX with analytical results for 3 soil samples that were taken in the tank room after the contaminated soil was removed. All 3 sets of results

APARTMENT BUILDING (Continued) **S108466382**

were non-detect. I called up Mr. Thomas and asked him to send the manifests for the removed soil. He said he will send them. Mr. Thomas added that the 2 tanks have been emptied and will replaced with one tank. So that will take care of the leaking pipe. 7/13/07 - Raphael Ketani. I tried to contact Mr. Thomas regarding the documentation for the cleanup work and the tank replacement work, but could only leave a message. (Mr. Thomas is the person to contact regarding the project, NOT Mr. Synmoie or Ms. Thomas.) 7/16/07 - Raphael Ketani. I spoke to Mr. Thomas and he told me the two tanks were replaced with 2 new 275 gallon tanks. He added that the contaminated soil at boring location #1 was taken away and that I should be receiving the manifest soon. 9/17/07 - Raphael Ketani. I received the Oil Spill Site Assessment Report from Mr. Thomas. The report states that the floors of the basement, the tank room, and the boiler room were power washed and soil samples were taken. The report also states that the leaking tanks were emptied (a waste ticket is included), removed, and replaced with new tanks. On 5/11/07, soil from the tank room was excavated and removed. Based upon the above mentioned Oil Spill Site Assessment Report and the analytical results for the tank room soil that were FAXed on 5/18/07, I am closing the spill case.

Remarks: UNSURE IF SEWERS AND GROUNDWATERS EFFECTED; CLEAN UP IS IN PROCESS;

All Materials:

Site ID:	377715
Operable Unit ID:	1135237
Operable Unit:	01
Material ID:	2125131
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	ON SIDEWALK
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0612954 / 2007-03-14
Facility ID:	0612954
Facility Type:	ER
DER Facility ID:	327460
Site ID:	377908
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	2401
Spill Date:	2007-03-02
Investigator:	sfrahman
Referred To:	Not reported
Reported to Dept:	2007-03-02
CID:	444
Water Affected:	Not reported

APARTMENT BUILDING (Continued) **S108466382**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-02
Spill Record Last Update:	2007-03-14
Spiller Name:	MALLORY GILMORE
Spiller Company:	ON SIDEWALK
Spiller Address:	211 HULL STREET
Spiller Company:	001
Contact Name:	MALLORY GILMORE
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	added to the drum run. 03/14/07 Rahman- Drums were not found on 03/13/07.
Remarks:	3 - 55 gallon drums left on sidewalk: not leaking

All Materials:

Site ID:	377908
Operable Unit ID:	1135425
Operable Unit:	01
Material ID:	2125332
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	TORES HOME
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0613303 / 2007-03-12
Facility ID:	0613303
Facility Type:	ER
DER Facility ID:	327460
Site ID:	378311
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2007-03-12
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2007-03-12
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported

APARTMENT BUILDING (Continued) **S108466382**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-12
Spill Record Last Update:	2007-03-12
Spiller Name:	FERDIEAND TORES
Spiller Company:	TORES HOME
Spiller Address:	211 HULL STREET
Spiller Company:	001
Contact Name:	FERDIEAND TORES
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	10 days ago line under the oil tank broke. Tank was loose and when the tank is filled, the tank moves. Oil gushed onto the basement floor. FD Haz Mat cleaned the spill. Line broke again. 6 family building - Oil Company on site now - Pacific Energy 718-647-1400 3/12/07 - Raphael Ketani. I spoke to Patrick Fahey, manager at Pacific Energy. He said his mechanic was on site now. He said that a flare nut connecting two pipes came loose a little and dripped oil onto the floor. He said that about 1 gal. dripped out. The flare nut has been tightened and this problem is solved. He said that a big spill happened weeks ago (#0612788)and was caused by a rotten equalizer (pipe connecting the 2 tanks). He said this pipe was repaired back then. Mr. Fahey said that the tanks are full and are holding the oil. As there is an earlier open spill case, I am closing this later case.
Remarks:	BOILER MALFUNCTION:

All Materials:

Site ID:	378311
Operable Unit ID:	1135815
Operable Unit:	01
Material ID:	2125740
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	211 HULL STREET
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6800766
Longitude:	-73.9082144
Type Of Ownership Code:	Not reported

APARTMENT BUILDING (Continued) **S108466382**

Owner Name:	CYPRESS HILLS TPT HOUSING DEVELOPMENT FU ND CORPORA
Borough:	BK
Tax Block:	1535
Tax Lot:	56
Community District:	316
Census Tract 2020:	3036900
Census Block 2020:	30369001001
Census Tract 2010:	369
Census Block 2010:	1001
School District:	23
City Council District:	37
Fire Company:	E233
Police Precinct:	73
Health Center District:	34
Health Area:	3700
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	2B
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C2: Walk Up Apartments - Five To Six Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	3750
Commercial Floor Area:	0
Residential Floor Area:	3750
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	6
Total Units:	6
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	25.0000000
Building Depth:	50.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	90000.00000

APARTMENT BUILDING (Continued) **S108466382**

Assessed Total Value:	221850.00000
Exempt Total Value:	0.00000
Year Built:	1911
Year Altered 1:	2009
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.50000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015350056.00000000
Condominium Number:	Not reported
Census Tract 2:	0369
X Coordinate:	1009708
Y Coordinate:	187060
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	305 071
Tax Map #:	30602
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AL277 **117 GLENMORE AVENUE** **NY VCP** **S130679321**
SSW **117 GLENMORE AVENUE** **NY NYC OER** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.355 mi.
1874 ft. **Site 1 of 2 in cluster AL**

Relative:
Lower

Actual:
49 ft.

VCP NYC:

Project ID:	20TMP1262K,21CVCP030K
Name:	117 GLENMORE AVENUE
Address:	117 GLENMORE AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	403,692,000,130,369,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,
OER Program:	VCP (Enrolled)
Phase:	Construction
Latitude:	40.67163
Longitude:	-73.906568
Postcode:	11212
Community Board:	16
Council District:	37
Census Tract:	908
BIN:	3326760
NTA:	Brownsville

NYC OER:

Name:	117 GLENMORE AVENUE
Address:	117 GLENMORE AVENUE

117 GLENMORE AVENUE (Continued) **S130679321**

City,State,Zip:	BROOKLYN, NY
Latitude:	40.67163
Longitude:	-73.906568
OER Project Numbers:	20TMP1262K,21CVCP030K
BBL:	4.0369200013036897E+179
OER Program:	VCP (Enrolled)
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	11212
Community Board:	16
Council District:	37
Census Tract:	908
BIN:	3326760
NTA:	Brownsville

278
East
1/4-1/2
0.367 mi.
1938 ft.

2667 FULTON STREET **NY VCP** **S129932248**
2667 FULTON STREET **NY NYC OER** **N/A**
NEW YORK CITY, NY

Relative:
Lower

Actual:
58 ft.

VCP NYC:

Project ID:	22TMP1353K,22EHAN317K,22CVCP079K
Name:	2667 FULTON STREET
Address:	2667 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3036610001
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.677388
Longitude:	-73.896083
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1146
BIN:	3000000
NTA:	Cypress Hills-City Line

NYC OER:

Name:	2667 FULTON STREET
Address:	2667 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677388
Longitude:	-73.896083
OER Project Numbers:	22TMP1353K,22EHAN317K,22CVCP079K
BBL:	3036610001
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	11207
Community Board:	5
Council District:	37

2667 FULTON STREET (Continued) **S129932248**

Census Tract: 1146
BIN: 3000000
NTA: Cypress Hills-City Line

AL279 **GLENMORE PLAZA -NYCHA** **NY LTANKS** **S104073503**
SSW **108 CHRISTOPHER AVE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.375 mi.
1982 ft. **Site 2 of 2 in cluster AL**

Relative:
Lower

Actual:
48 ft.

LTANKS:

Name:	GLENMORE PLAZA
Address:	108 CHRISTOPHER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9602447 / 1996-07-24
Facility ID:	9602447
Site ID:	110612
Spill Date:	1996-05-21
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1996-05-21
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-21
Spill Record Last Update:	1996-07-24
Spiller Name:	FRANK OCELLO
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	WILLY NEGRON
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96846
Latitude:	40.6715052
Longitude:	-73.9063929
DEC Memo:	Not reported
Remarks:	old tank removed - contaminated soil found

All Materials:

Site ID:	110612
Operable Unit ID:	1033927
Operable Unit:	01
Material ID:	352269
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported

GLENMORE PLAZA -NYCHA (Continued) **S104073503**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NYC HOUSING AUTHORITY
Address:	108 CHRISTOPHER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9611221 / 1996-12-13
Facility ID:	9611221
Site ID:	120585
Spill Date:	1996-12-11
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1996-12-11
CID:	297
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-11
Spill Record Last Update:	1996-12-13
Spiller Name:	TINA HANSEN
Spiller Company:	CLASSIC OIL
Spiller Address:	9 WYTHE AV
Spiller County:	001
Spiller Contact:	RAY VELEZ
Spiller Phone:	(212) 306-3142
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96846
Latitude:	40.6715052
Longitude:	-73.9063929
DEC Memo:	Not reported
Remarks:	THE SUPVSR AT THE NYC HOUSING AUTHORITY ORDERED THE OIL BUT NEVER STUCK THE TANK FOR THE LEVEL - WHEN THE DRIVER FILLED THE TANK, IT OVERFILLED - THE OIL COMPANY IS REFUSING TO CLEAN THE SPILL

All Materials:

Site ID:	120585
Operable Unit ID:	1039245
Operable Unit:	01
Material ID:	343418
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

GLENMORE PLAZA -NYCHA (Continued) **S104073503**

Quantity:	100.00
Units:	G
Recovered:	100.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	GLENMORE PLAZA -NYCHA
Address:	108 CHRISTOPHER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9413245 / 2019-09-10
Facility ID:	9413245
Site ID:	272843
Spill Date:	1995-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AAOBLIGA
Referred To:	STIP SITE, SIR DUE 4/14/15
Reported to Dept:	1995-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-01-05
Spill Record Last Update:	2019-09-10
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96846
Latitude:	40.6715851
Longitude:	-73.9062614
DEC Memo:	02/09/07 - J.Kann - Spill reassigned from S.Kraszewski to J.Kann. 3/10/11: J.Kann - Investigative work plan submitte on 3/3/11. 8/26/14: J.Kann - Reviewed the file. Minimal contamination detected in 1995 ISRP. However, a second spill was called in during tank removal due to contaminated soils being encountered. It is not clear if and where endpoints were collected. Therefore, an investigation is warranted and an approval for the IWP prepared by Grant was emailed to NYCHA today. 12/30/14: J.Kann - part of multi site stip executed on 10/14/14. SIR due 4/14/15. 06/05/2017: J.Kann - Spill reassigned to Andre Obligado. 8/1/2019 - Obligado - I met American Environmental at the Site to observe implementation of the drilling work plan. At the time of my visit, the geoprobe rig had broken down and they had discontinued drilling. Only 1 boring to 30 ft had been advanced prior to break down. They will reschedule the drilling. 9/10/19 - Obligado

GLENMORE PLAZA -NYCHA (Continued) **S104073503**

- I reviewed a Subsurface Investigation Report submitted by American Environemntal. Three wells were installed to between 45 and 50 ft bgs. Groundwater was encountered between 37 and 39 ft bgs. One SVOC compound, Chrysene, was detected above CP51 clean up standards in soil at boring B7 from 25-30 ft with a level of 1.8 ppm, which is above its cp51 standard of 1ppm. No petroleum compounds were detected in groundwater above GWQS. This spill does not appear to be a threat to human health or the environment. This spill is closed.

Remarks: CONTRACTOR DOING BORINGS AT LOCATION FOUND CONTAMINATED SOIL.

All Materials:

Site ID:	272843
Operable Unit ID:	1010793
Operable Unit:	01
Material ID:	371991
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	GLENMORE HOUSES
Address:	108 CHRISTOPHER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9614301 / 1997-08-15
Facility ID:	9614301
Facility Type:	ER
DER Facility ID:	96846
Site ID:	110615
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-03-10
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1997-03-10
CID:	297
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-10
Spill Record Last Update:	2002-11-05
Spiller Name:	ED MALONE
Spiller Company:	NYC HOUSING

GLENMORE PLAZA -NYCHA (Continued) **S104073503**

Spiller Address:	250 BROADWAY
Spiller Company:	001
Contact Name:	ED MALONE
Latitude:	40.6715052
Longitude:	-73.9063929
DEC Memo:	Not reported
Remarks:	FUEL COMPANY DID NOT OPEN ALL THE COMPARTMENTS IN THE FUEL OIL TANK AND IT CREATED BACKPRESSURE WHICH PUSHED THE OIL BACK OUT THE TANK - DEC ON SITE - WINSTON CONTRACTING CALLED IN FOR THE CLEAN UP

All Materials:

Site ID:	110615
Operable Unit ID:	1045726
Operable Unit:	01
Material ID:	339403
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	GLENMORE PLAZA
Address:	108 CHRISTOPHER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9608161 / 1996-10-07
Facility ID:	9608161
Facility Type:	ER
DER Facility ID:	96846
Site ID:	110613
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1996-09-30
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1996-09-30
CID:	282
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-09-30
Spill Record Last Update:	1996-10-07
Spiller Name:	DECLAN POWER
Spiller Company:	KELLY TANK
Spiller Address:	Not reported
Spiller Company:	001

GLENMORE PLAZA -NYCHA (Continued) **S104073503**

Contact Name:	FRANCIS FIELDS
Latitude:	40.6715052
Longitude:	-73.9063929
DEC Memo:	Not reported
Remarks:	PIPING BROKE IN THE BOILER ROOM CAUSING THE SPILL SPILL IS BEING CLEANED UPS

All Materials:

Site ID:	110613
Operable Unit ID:	1036429
Operable Unit:	01
Material ID:	343901
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	GLENMORE PLAZA
Address:	108 CHRISTOPHER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9611220 / 1996-12-13
Facility ID:	9611220
Facility Type:	ER
DER Facility ID:	96846
Site ID:	110614
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-12-11
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1996-12-11
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-11
Spill Record Last Update:	2002-09-16
Spiller Name:	TINA
Spiller Company:	CLASSIC OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	WILLIE NEGRON
Latitude:	40.6715052
Longitude:	-73.9063929

GLENMORE PLAZA -NYCHA (Continued) **S104073503**

DEC Memo: Not reported
Remarks: PROBLEM WITH VENT CLEANUP CREW FINISHING CLEAN UP NOW

All Materials:
Site ID: 110614
Operable Unit ID: 1039243
Operable Unit: 01
Material ID: 561130
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: 100.00
Resource Affected: Soil
Oxygenate: Not reported

---

280 East 1/4-1/2 0.378 mi. 1998 ft.

157 NEW JERSEY AVENUE
157 NEW JERSEY AVENUE
BROOKLYN, NY

NY VCP S129932074
NY NYC OER N/A

Relative: Lower

Actual: 54 ft.

VCP NYC:
Project ID: 18TMP0088K,18EH-N061K,18CVCP043K
Name: 157 NEW JERSEY AVENUE
Address: 157 NEW JERSEY AVENUE
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 30,367,101,433,036,700,000
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Construction
Latitude: 40.676216
Longitude: -73.895915
Postcode: 11207
Community Board: 5
Council District: 37
Census Tract: 1198
BIN: 3000000
NTA: East New York

NYC OER:
Name: 157 NEW JERSEY AVENUE
Address: 157 NEW JERSEY AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.676216
Longitude: -73.895915
OER Project Numbers: 18TMP0088K,18EH-N061K,18CVCP043K
BBL: 3.0367101433036702E+19
OER Program: VCP (Enrolled), E/RD (Review)
Class: Active (A)
Phase: Construction

URL:
Postcode: 11207
Community Board: 5

157 NEW JERSEY AVENUE (Continued) **S129932074**

Council District:	37
Census Tract:	1198
BIN:	3000000
NTA:	East New York

AM281 **BIG APPLE AUTO INC** **NY SWF/LF** **S108145711**
SSE **1934 PITKIN AVE** **NY SPDES** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.383 mi.
2020 ft. **Site 1 of 2 in cluster AM**

Relative:
Lower

Actual:
40 ft.

SWF/LF:

Name:	BIG APPLE AUTO INC
Address:	1934 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11207
Flag:	INACTIVE
Region Code:	2
Phone Number:	7184951781
Owner Name:	Big Apple Auto Inc
Owner Type:	Private
Owner Address:	1934 Pitkin Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Email:	bigappleauto1@optimum.net
Owner Phone:	7184951781
Contact Name:	Joseph Spitaliere
Contact Address:	1934 Pilkin Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11207
Contact Email:	Bigappleauto1@optimum.net
Contact Phone:	7184951781
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7071149]
Active:	No
East Coordinate:	592856
North Coordinate:	4502761
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Big Apple Auto Inc
Operator Type:	Private
Laste Date:	Not reported

SPDES:

Name:	Big Apple Auto Inc
Address:	1934 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11207
Permit Number:	NYR00E015
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5015
State Water Body Name:	JAMAICA BAY

BIG APPLE AUTO INC (Continued) **S108145711**

Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.670 / -73.901
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TABS CONSULTING GROUP
Non-Gov Permit Street Address:	BIG APPLE AUTO INC
Non-Gov Permit Supplemental Location:	2 52ND ST, BOX B11
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11232
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BIG APPLE AUTO INC
Non-Gov Facility Street Address:	BIG APPLE AUTO INC
Non-Gov Facility Supplemental Location:	1934 PITKIN AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11207
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported
Name:	Big Apple Auto Inc
Address:	1934 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11207
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BIG APPLE AUTO INC
Non-Gov Permit Street Address:	1934 PITKIN AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11207
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BIG APPLE AUTO INC
Non-Gov Facility Street Address:	BIG APPLE AUTO INC
Non-Gov Facility Supplemental Location:	1934 PITKIN AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11207
State Water Body:	Not reported

BIG APPLE AUTO INC (Continued) **S108145711**

Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported
Name:	Big Apple Auto Inc
Address:	1934 PITKIN AVE
City,State,Zip:	BROOKLYN, NY 11207
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BIG APPLE AUTO INC
Non-Gov Facility Street Address:	BIG APPLE AUTO INC
Non-Gov Facility Supplemental Location:	1934 PITKIN AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11207
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported

AN282 **WOLF PETROLEUM CORP** **UST FINDER RELEASE** **1029057021**
NNW **1532 BUSHWICK AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.391 mi.
2066 ft. **Site 1 of 3 in cluster AN**

Relative: **Higher**
Actual: **102 ft.**

UST FINDER RELEASE:

Object ID:	258719
Facility ID:	NY106365
Lust ID:	NY212200
Name:	WOLF PETROLEUM CORP
Address:	1532 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2003/03/12 15:59:59+00
Status:	No Further Action
Substance:	Not reported

WOLF PETROLEUM CORP (Continued) **1029057021**

Population within 1500ft:	7225
Domestic Wells within 1500ft:	6
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.90579
Y Coord:	40.6823800000001
Latitude:	40.68238
Longitude:	-73.9057899999999

AN283 **WOLF PETROLEUM CORP** **NY LTANKS** **S105998357**
NNW **1532 BUSHWICK AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.391 mi.
2066 ft. **Site 2 of 3 in cluster AN**

Relative: **Higher**

Actual: **102 ft.**

LTANKS:

Name:	WOLF PETROLEUM CORP
Address:	1532 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0203277 / 2003-09-25
Facility ID:	0203277
Site ID:	122706
Spill Date:	2002-06-27
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-06-27
CID:	207
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-27

WOLF PETROLEUM CORP (Continued) **S105998357**

Spill Record Last Update:	2004-10-18
Spiller Name:	Not reported
Spiller Company:	STORAGE MAINTENANCE CORP
Spiller Address:	55 JERICHO TURNPIKE
Spiller County:	001
Spiller Contact:	BRUCE BECK
Spiller Phone:	(631) 226-9080
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	106365
Latitude:	40.6823818
Longitude:	-73.9057891
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 9/25/03 TJD Tank overfill. All impacts to concrete. Contained and cleaned using absorbants. Spill closed.
Remarks:	cleanup in progress

All Materials:

Site ID:	122706
Operable Unit ID:	854102
Operable Unit:	01
Material ID:	521107
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	WOLF PETROLEUM CORP
Address:	1532 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0212200 / 2004-10-21
Facility ID:	0212200
Site ID:	153386
Spill Date:	2003-03-12
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2003-03-12
CID:	297
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-03-12
Spill Record Last Update:	2004-10-21

WOLF PETROLEUM CORP (Continued) **S105998357**

Spiller Name:	ADAM WOLF
Spiller Company:	WOLF PETROLEUM
Spiller Address:	125 JERICHO TURNPIKE
Spiller County:	001
Spiller Contact:	ADAM WOLF
Spiller Phone:	(516) 997-9300
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	106365
Latitude:	40.6823818
Longitude:	-73.9057891
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 1/8/04 Reassigned from Vought to K Foley. 9/29/04 Met with B. Cohen(Certilman Balin Attorneys), B. Beck(Consultant, National Env.) with J. Rommel and L. Oliva. B. Beck to provide a response by 10/29/04. 10/20/04 B. Beck provided repair record of vent line performed by Tyree and 3/14/03 passing tank test results from Crompco. 10/21/04 Mailed NFA letter.
Remarks:	TANK FAILED TEST, NO CONTAIMINATION FOUND

All TTF:

Facility ID:	0212200
Spill Number:	0212200
Spill Tank Test:	1528074
Site ID:	153386
Tank Number:	1
Tank Size:	4000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	153386
Operable Unit ID:	863207
Operable Unit:	01
Material ID:	511939
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AN284 **FIVE STAR AUTO REBUILDERS INC** **NY SWF/LF** **S108145864**
NNW **1533 BUSHWICK AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.397 mi.
2096 ft. **Site 3 of 3 in cluster AN**

Relative: **Higher**
Actual: **108 ft.**

SWF/LF:

Name:	FIVE STAR AUTO REBUILDERS INC
Address:	1533 BUSHWICK AVE
City,State,Zip:	BROOKLYN, NY 11207
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	592513
North Coordinate:	4504043
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

---

285 **LOT 35,TAXBLOCK 3703** **NY VCP** **S118704314**
ESE **184 PENNSYLVANIA AVENUE** **NY E DESIGNATION** **N/A**
1/4-1/2 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.399 mi. **NY NYC OER**
2108 ft.

Relative: **Lower**
Actual: **47 ft.**

VCP NYC:

Project ID:	22TMP1653K,22EHAZ371K,23CVCP013K
Name:	184 PENNSYLVANIA AVENUE
Address:	184 PENNSYLVANIA AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	303,703,003,530,370,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.673405
Longitude:	-73.896266
Postcode:	11207
Community Board:	5

LOT 35,TAXBLOCK 3703 (Continued) **S118704314**

Council District: 37
Census Tract: 1144
BIN: 3000000
NTA: East New York (Pennsylvania Ave)

E DESIGNATION:
Name: LOT 35,TAXBLOCK 3703
Address: 184 PENNSYLVANIA AVENUE
City,State,Zip: BROOKLYN, NY 11207
Tax Lot(s): 35
Tax Block: 3703
Borough Code: BK
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date: Not reported

NYC LAND USE:
Name: Not reported
Address: 184 PENNSYLVANIA AVENUE
City,State,Zip: BROOKLYN, NY 11207
Latitude: 40.6732871
Longitude: -73.8965795
Type Of Ownership Code: Not reported
Owner Name: 180 PENNSYLVANIA LLC
Borough: BK
Tax Block: 3703
Tax Lot: 35
Community District: 305
Census Tract 2020: 3114400
Census Block 2020: 31144002003
Census Tract 2010: 1144
Census Block 2010: 2003
School District: 19
City Council District: 37
Fire Company: L175
Police Precinct: 75
Health Center District: 33
Health Area: 5700
Sanitation District Boro: 3
Sanitation District Number: 05
Sanitation Subsection: 1C
Zoning District 1: R7A: Residential Districts
Zoning District 2: Not reported
Zoning District 3: Not reported
Zoning District 4: Not reported
Commercial Overlay 1: C2-4
Commercial Overlay 2: Not reported
Special Purpose District 1: Not reported
Special Purpose District 2: Not reported
Special Purpose District 3: Not reported

LOT 35,TAXBLOCK 3703 (Continued) **S118704314**

Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V1: Vacant Land - Zoned Commercial Or Manhattan Residential
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	50850.00000
Assessed Total Value:	108000.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3037030035.00000000
Condominium Number:	Not reported
Census Tract 2:	1144
X Coordinate:	1012938
Y Coordinate:	184590
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 010
Tax Map #:	31205
E-designation Number:	E-366
Apportionment BBL:	3037030034.00000000
Apportionment Date:	07/19/2024
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported

LOT 35,TAXBLOCK 3703 (Continued) **S118704314**

Version Number: 24v3.1
Changed By DCP: Not reported

NYC OER:
Name: 184 PENNSYLVANIA AVENUE
Address: 184 PENNSYLVANIA AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.673405
Longitude: -73.896266
OER Project Numbers: 22TMP1653K,22EHAZ371K,23CVCP013K
BBL: 3.0370300353037001E+29
OER Program: VCP (Enrolled), E/RD (Review)
Class: Active (A)
Phase: Construction

URL:
Postcode: 11207
Community Board: 5
Council District: 37
Census Tract: 1144
BIN: 3000000
NTA: East New York (Pennsylvania Ave)

AM286 **NATIONWIDE SCRAP LLC SNEDIKER AVE** **NY SWRCY** **S118708711**
SSE **178-214 SNEDIKER AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.402 mi.
2123 ft. **Site 2 of 2 in cluster AM**

Relative:
Lower

Actual:
40 ft.

SWRCY:
Name: NATIONWIDE SCRAP LLC SNEDIKER AVE
Address: 178-214 SNEDIKER AVENUE
City,State,Zip: BROOKLYN, NY 11207
Region: 2
Facility Address 2: Not reported
Phone Number: 7186583311
Owner Type: Private
Owner Name: Rudulph C. Filiberto
Owner Address: 197 Snediker Avenue
Owner Address 2: Not reported
Owner City,St,Zip: Brooklyn, NY 11207
Owner Email: Not reported
Owner Phone: 7184565000
Contact Name: Not reported
Contact Address: Not reported
Contact Address 2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: RHRF - registration
Activity Number: [24MH0]
Active: No
East Coordinate: 592853
North Coordinate: 4502829
Accuracy Code: 4.1 - Address Matching
Regulatory Status: Registration
Permit #: 24MH0

NATIONWIDE SCRAP LLC SNEDIKER AVE (Continued) **S118708711**

Auth. Date:	5/20/2016
Expiration Date:	5/19/2021
Waste Types:	Commingled Paper;Newspaper;Container Glass;Paperboard/Boxboard;Commingled Containers;Other Aluminum Scrap Metal;Other Ferrous Scrap Metal;Other Non-Ferrous Scrap Metal;Wood (Unadulterated Pallets)
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	2/3/2017

287
SE
1/4-1/2
0.407 mi.
2151 ft.

F & S AUTO **NY SWF/LF** **S108145856**
202 SHEFFIELD AVE **N/A**
BROOKLYN, NY 11207

Relative:
Lower

Actual:
43 ft.

SWF/LF:

Name:	F & S AUTO
Address:	202 SHEFFIELD AVE
City,State,Zip:	BROOKLYN, NY 11207
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	593226
North Coordinate:	4502908
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AO288
East
1/4-1/2
0.425 mi.
2246 ft.

2701-2715 FULTON STREET
2701-2715 FULTON STREET
BROOKLYN, NY

Site 1 of 2 in cluster AO

NY VCP **S129932257**
NY NYC OER **N/A**

Relative:
Lower

Actual:
57 ft.

VCP NYC:

Project ID:	22TMP0913K,22EH-N211K,22CVCP068K
Name:	2701-2715 FULTON STREET
Address:	2701-2715 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	303,662,005,230,366,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.67756
Longitude:	-73.894943
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1146
BIN:	3083146
NTA:	Cypress Hills-City Line

NYC OER:

Name:	2701-2715 FULTON STREET
Address:	2701-2715 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.67756
Longitude:	-73.894943
OER Project Numbers:	22TMP0913K,22EH-N211K,22CVCP068K
BBL:	3.0366200523036599E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1146
BIN:	3083146
NTA:	Cypress Hills-City Line

289
NW
1/4-1/2
0.431 mi.
2274 ft.

OCEAN HILL HOUSES -NYCHA
24 STONE AVENUE
BROOKLYN, NY

NY LTANKS **S102149171**
NY Spills **N/A**

Relative:
Higher

Actual:
85 ft.

LTANKS:

Name:	OCEAN HILL -NYCHA
Address:	24 STONE AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9010234 / 2019-01-14
Facility ID:	9010234
Site ID:	171459
Spill Date:	1990-12-20
Spill Cause:	Tank Test Failure

OCEAN HILL HOUSES -NYCHA (Continued) **S102149171**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AAOBLIGA
Referred To:	CMTS SENT 10/14/16, 6 MNTH MONIT.[INVALID]DUE 5/1/
Reported to Dept:	1990-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-01-08
Spill Record Last Update:	2019-01-14
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	144292
Latitude:	40.6811900
Longitude:	-73.9087840
DEC Memo:	01/24/06: This spill transferred from J.Kolleeny to S.Kraszewski. - SK 03/14/06: This spill reassigned to K.Tang. - SK 01/15/08: spill reassigned to J.Kann. Consolidated with closed spill 0302414. J.Kann 4/10/13: J.Kann - IWP approved in an email (edoced). 4/26/13: J.Kann - revised IWP rcvd and edoced. 11/4/13: J.Kann - SAR is past due (due October 2013). stip sent to NYCHA today. Must be returned by December 4, 2013. 12/6/13: J.kann - signed stip rcvd from NYCHA on 12/4 and forwarded to legal for execution on 12/6/13 4/4/14: J.Kann - extention requests made by NYCHA's consultants due to poor weather and a damaged drill rig. Extension was approved on February 12 and then again on March 12. Report was submitted today, the approved extension date. Brief glance at the report shows some VOC and SVOC constituents in groundwater above CP-51 at one location. Closure request was made by NYCHA's consultant. Will need to further review the report before making a determination. 10/21/14: J.Kann - reviewing site. One well has elevated VOCs. Groundwater is at approx. 75 fbgs. Two wells were previously installed on site as part of another investigation. An email was sent to NYCHA on 10/21/14 requesting they try to locate the report related to the previous investigation. 10/30/14: J.Kann - spoke with NYCHA today. They never received information about the investigative work that Gannett Fleming had started at the site. Therefore, no additional info is available. 11/18/14: J.Kann - information from spill 0302414 indicates NYCHA CONTRACTOR GANNETT FLEMING DOING FOLLOW-UP SITE INVESTIGATION SINCE TANK CLOSURE FOUND SVOCs IN SOIL ABOVE TAGM. PUTTING IN WELL, SOIL CONTAMINATION ENCOUNTERED FROM 25 FEET DOWN TO WATER TABLE AT 75 FT., WITH PID=220 PPM AT 50 FT., THEN FIRST SPLIT SPOON BELOW WATER TABLE, PID=230 PPM. SOIL SAMPLES WERE COLLECTED FOR LAB ANALYSIS, AND GROUNDWATER SAMPLE WILL BE TAKEN AFTER WELL IS

OCEAN HILL HOUSES -NYCHA (Continued) **S102149171**

DEVELOPED. The tank closure report was reviewed (dated February 2000 and prepared by PT&L Contracting). Endpoints were not above CP-51. No VOCs were detected, some PAHs were detected below CP-51. The investigation performed by JCB is also under review. 12/10/14: J.Kann -email sent to Yelena today- I have read the Remedial Investigation Report (RIR) prepared by JC Broderick for the referenced site. Based on the review, the spill has not been closed and the Department has the following comments: -Based on the site file, JCB notified the Department of difficulty encountered during the field investigation, resulting in approved modifications to the original work plan. None of this information is discussed and presented in the RIR. These details must be discussed in the RIR since borings were not advanced to the depths proposed in the original work plan. -The conclusions and recommendations section indicates that JCB suspects the contamination in the on site groundwater monitoring well is from another source, but a potential source is not identified. The Gannett Fleming work plan for the site dated 2003 indicates that based on historic Sanborn Maps a gasoline tank was present on this property until around 1962, or when Ocean Hill Houses were built. Why is the source assumed to be off-site? Please clarify and further discuss this in the RIR. -An additional round of groundwater samples must be collected from the three wells, analyzed for VOCs/SVOCs, summarized and submitted to the Department. Once these comments are addressed, additional investigative work may be necessary at this site. 6/4/15: J.Kann - Additional round of sampling performed at MW-1 and MW-2 in February 2015. Product thickness of .02 ft found in MW-5. Based on new information, an email was sent to NYCHA requesting a fingerprint analysis and installation of two additional wells. 10/14/16: J.kann - Additional investigative work was done including the advancement of 5 more borings. All soil samples collected were below CP-51. Three wells were sampled and MW-5 had minor elevated concentrations. This was the well with a small amount of product previously. The recommendation is to install a sock in MW-6 and sample in 6 months. NYCHA was emailed today indicating that should be done. 06/05/2017: J.Kann - Spill reassigned to Andre Obligado. 1/14/19 - Obligado - I reviewed the 3Q18 monitoring report prepared by H2M. No product was observed in any of the wells since 2015. During the most recent sampling round, data submitted in December 2017, all petroleum VOCs were detected at or below GWQS. H2M recommends spill closure. After review of the report, the DEC concurs that this spill does not appear to be a threat to human health or the environment. This spill is closed based on: 1) 235 tons of contaminated soil removed from the Site during tank closure in 2000. 2) Soil samples collected during well installation were all below CP51 3) No LNAPL present for 3 years 4) No petroleum VOCs above TOGS GWQS. Spill closed. .

Remarks: 20K TANK SYSTEM FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL EXCAVATE, ISOLATE & RETEST.

All TTF:

Facility ID:	9010234
Spill Number:	9010234
Spill Tank Test:	1538069
Site ID:	171459
Tank Number:	001
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported

OCEAN HILL HOUSES -NYCHA (Continued) **S102149171**

Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	171459
Operable Unit ID:	947383
Operable Unit:	01
Material ID:	430396
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	OCEAN HILL HOUSES -NYCHA
Address:	24 STONE AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9412305 / 1994-12-15
Facility ID:	9412305
Facility Type:	ER
DER Facility ID:	144292
Site ID:	261115
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	1994-12-14
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1994-12-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-12-15
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-12-15
Spill Record Last Update:	2006-01-24
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY

OCEAN HILL HOUSES -NYCHA (Continued) **S102149171**

Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
Latitude: 40.6815459
Longitude: -73.9088439
DEC Memo: Not reported
Remarks: KNOCKED OVER FIVE GALLON BUCKET. ABSORBENT USED TO CLEAN UP.

All TTF:
Facility ID: 9412305
Spill Number: 9412305
Spill Tank Test: 1543451
Site ID: 261115
Tank Number: Not reported
Tank Size: 0
Material: 0002
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 261115
Operable Unit ID: 1005996
Operable Unit: 01
Material ID: 564283
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: 5.00
Resource Affected: Soil
Oxygenate: Not reported

Name: OCEAN HILL HOUSES -NYCHA
Address: 24 STONE AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0302414 / 2008-01-15
Facility ID: 0302414
Facility Type: ER
DER Facility ID: 144292
Site ID: 133799
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2003-06-06
Investigator: jkkann

OCEAN HILL HOUSES -NYCHA (Continued) **S102149171**

Referred To:	SPILL CONSOLIDATED WITH 9010234
Reported to Dept:	2003-06-06
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-06
Spill Record Last Update:	2008-01-15
Spiller Name:	CALLER
Spiller Company:	OCEAN HILL HOUSES
Spiller Address:	30 MOTHER GASTEN BLVD
Spiller Company:	001
Contact Name:	CALLER
Latitude:	40.6813745
Longitude:	-73.9088231
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY NYCHA CONTRACTOR GANNETT FLEMING DOING FOLLOW-UP SITE INVESTIGATION SINCE TANK CLOSURE FOUND SVOCs IN SOIL ABOVE TAGM. PUTTING IN WELL, SOIL CONTAMINATION ENCOUNTERED FROM 25 FEET DOWN TO WATER TABLE AT 75 FT., WITH PID=220 PPM AT 50 FT., THEN FIRST SPLIT SPOON BELOW WATER TABLE, PID=230 PPM. SOIL SAMPLES WERE COLLECTED FOR LAB ANALYSIS, AND GROUNDWATER SAMPLE WILL BE TAKEN AFTER WELL IS DEVELOPED. 3 MORE WELLS AND 4 SOIL BORINGS WILL BE INSTALLED. - J.KOLLEENY 6/6/03 11/03/05: This spill transferred from J.Kolleeny to S.Kraszewski. 07/07/06: NYCHA summary report states that no recovery system and no MWs on-site. The site assessment is available and NYCHA recommends that the Department review it. - SK 02/06/07 - J.Kann - site reassigned from S. Kraszewski to J.Kann. 01/15/08 - J.kann - spill closed and consolidated with 9011619.
Remarks:	site work found contaminated soil.

All Materials:

Site ID:	133799
Operable Unit ID:	869251
Operable Unit:	01
Material ID:	506891
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

290 South 1/4-1/2 0.432 mi. 2281 ft. | **SETH LOW HOUSES -NYCHA**
180 POWELL STREET
BROOKLYN, NY | **NY LTANKS**
NY Spills | **S101658382**
N/A

Relative: Lower

Actual: 44 ft.

LTANKS:

Name:	SETH LOW
Address:	180 POWELL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9104796 / 1995-06-28
Facility ID:	9104796
Site ID:	249121
Spill Date:	1991-08-02
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-06-28
SWIS:	2401
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1991-08-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-08-07
Spill Record Last Update:	2003-01-27
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	204278
Latitude:	40.6701868
Longitude:	-73.9041547
DEC Memo:	Not reported
Remarks:	20K TANK (#2) FAILED HORNER EZY CHECK,VISUAL GROSS LEAK,PLUMBING LEAK,SYSTEM TEST,WILL EXCAVATE,ISOLATE & RETEST. CLOSE OUT-SEE SPILL #9503722 (SUBSEQUENT TANK TEST FAILURE)

All TTF:

Facility ID:	9104796
Spill Number:	9104796
Spill Tank Test:	1538844
Site ID:	249121
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9104796
Spill Number:	9104796
Spill Tank Test:	1538845
Site ID:	249121
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	249121
Operable Unit ID:	958855
Operable Unit:	01
Material ID:	423855
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SETH LOW HOUSES -NYCHA
Address:	180 POWELL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9503722 / 2006-02-07
Facility ID:	9503722
Site ID:	249122
Spill Date:	1995-06-26
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SWKRASZE
Referred To:	Not reported
Reported to Dept:	1995-06-26
CID:	Not reported

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-06-28
Spill Record Last Update:	2006-02-07
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	204278
Latitude:	40.6701868
Longitude:	-73.9041547
DEC Memo:	11/29/05: This spill transferre from J.Kolleeny to S.Kraszewski. 02/07/06: This spill closed to consolidate with open spill #9906013. - SK
Remarks:	TANK #1 COULDN'T HOLD VACUUM. TANK #2 - LEAK RATE OF 3.5

All TTF:

Facility ID:	9503722
Spill Number:	9503722
Spill Tank Test:	1543949
Site ID:	249122
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	9503722
Spill Number:	9503722
Spill Tank Test:	1543950
Site ID:	249122
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 249122
Operable Unit ID: 1018188
Operable Unit: 01
Material ID: 365230
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

SPILLS:
Name: SETH LOW HOUSES -NYCHA
Address: 180 POWELL STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9407081 / 2006-02-07
Facility ID: 9407081
Facility Type: ER
DER Facility ID: 204278
Site ID: 146499
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 1994-08-25
Investigator: SWKRASZE
Referred To: Not reported
Reported to Dept: 1994-08-25
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1994-08-25
Spill Record Last Update: 2006-02-07
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
Latitude: 40.6701868
Longitude: -73.9041547

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

DEC Memo: 11/29/05: This spill transferred from J.Kolleeny to S.Kraszewski.
02/07/06: This spill closed to
consolidate with open spill #9906013. - SK

Remarks: FUEL LINE FAILURE - BLUE WATER ENVIRONMENTAL (TOM SPATAFORA 516-752-2145) AND NYCHA PERSONNEL DOING CLEANUP. APPROXIMATELY 30 TO 40 CUBIC YARDS OF CONTAMINATED SOIL.

All TTF:

Facility ID:	9407081
Spill Number:	9407081
Spill Tank Test:	1543080
Site ID:	146499
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	146499
Operable Unit ID:	1004507
Operable Unit:	01
Material ID:	380100
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NYC HOUSING AUTH
Address:	180 POWELL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0209860 / 2002-12-30
Facility ID:	0209860
Facility Type:	ER
DER Facility ID:	204278
Site ID:	250473
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2002-12-28
Investigator:	MXTIPPLE
Referred To:	Not reported

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Reported to Dept:	2002-12-28
CID:	398
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-28
Spill Record Last Update:	2002-12-30
Spiller Name:	Not reported
Spiller Company:	NYC HOUSING AUTH
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CHARLES MCINNIS
Latitude:	40.6701868
Longitude:	-73.9041547
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 12/30/2002 TIPPLE--THE EXISTING REMEDIATION SYSTEM LOCATED IN BOILER ROOM HAD A HIGH FLOAT ALARM FAILURE CAUSING AN OIL WATER MIX TO SPILL ONTO THE FLOOR. CLEAN VENTURES WERE CALLED AND CLEANED THE SPILL FROM THE FLOOR, THE SYSTEM HAS BEEN TURNED OFF UNTIL REPAIRS CAN BE MADE AND THE RETENTION TANK EMPTIED. THIS WORK IS SCHEDULED TO BE COMPLETED BY END OF BUSINESS DECEMBER 31.
Remarks:	oil and water changer failed. clean up crew enroute. oil and water mixture may of been 30-40 gals.

All Materials:

Site ID:	250473
Operable Unit ID:	861096
Operable Unit:	01
Material ID:	513280
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SETH LOW HOUSES -NYCHA
Address:	180 POWELL STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9906013 / Not Reported
Facility ID:	9906013
Facility Type:	ER
DER Facility ID:	204278
Site ID:	139972
DEC Region:	2
Spill Cause:	Equipment Failure

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

Spill Class:	C3
SWIS:	2401
Spill Date:	1999-08-19
Investigator:	MSHOQUE
Referred To:	PRS AND VEFR ONGOING, CMTS ON QRTLY SENT 2/5/15
Reported to Dept:	1999-08-19
CID:	389
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	1999-08-19
Spill Record Last Update:	2023-02-16
Spiller Name:	LEWIS PONCE
Spiller Company:	NYC HOUSING AUTHORITY
Spiller Address:	250 BROADWAY
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6688684
Longitude:	-73.9038213
DEC Memo:	11/29/05: This spill transferred from J.Kolleeny to S.Kraszewski. 9/22/06: Spill transferred from Kraszewski to Kann. 9/21/10: J.Kann - Quarterly Report recieved on 9/1/10. 3/7/11: J.Kann - Qrtly Rpt rcvd 1/6/11 5/10/12: J.Kann - Quarterly Report rcvd 5/9/12. 9/6/12: J.Kann - Quarterly Report recieved on 8/21/12 5/21/13: J.kann - QR rcvd 1/16/13 and edoced. 2/5/15: J.Kann - Site visit made in 2014 to observe pilot study method of gauging 6 oil. The following email was sent to Yelena Tkach of NYCHA today: The Department has reviewed the 2014 3rd and 4th Quarter Status Reports for the referenced site. Based on the review NYCHA should -continue operation of the PRS and VEFR monthly -continue to utilize the pilot study method of gauging the onsite wells monthly. After a year of proper gauging of the 6 oil (in June 2015), the 2nd Quarter 2015 Status Report must include a trend analysis of product in wells, and an evaluation made of the current recovery effort. Please let me know if you have any questions. 06/05/2017: J.Kann - Spill reassigned to Andre Obligado. Obligado - I received the 1Q17 update report. Operation of the PRS is on-going. The system was offline in March 2017 to repair the oil water separator. According to this report, approximately 447 gallons of oil was recovered during the 1st Quarter 2017. That includes an estimated 46 gallons during VEFR 4 VEFR events. LNAPL was present in multiple wells. Including MW 2 (.25 ft), MW2A (0.08 ft), MW3 (0.25 ft) RW1 (0.08 ft and RW4 (0.08 ft). A film was observed in MW7, RW2, and RW3. The

SETH LOW HOUSES -NYCHA (Continued) **S101658382**

report recommends continued operation of the product recovery system, as well as monthly VEFR events. 11/17/22 - Obligado - I reviewed the Biannual Report - 2022 - System is off-line. All wells were guaged January through June 2022. LNAPL present in MW2, MW2A,MW3, MW7, RW1, RW2, RW3, RW4. Maximum thickness was 1.33 ft in MW5 in January 2022. Monthly VEFRing is on-going. SYSTEM NEEDS REPAIR 12/12/2022-M. Hoque: Due to Andre Obligado's transfer from Spill Response Program to BCP/SSF Section, spill case manager reassigned from Andre Obligado to MD Hoque/ Spill Remediation Section B effective on 12/12/2022. (MDH) 1/30/2022-M. Hoque: Received a semi-annual (January- June) 2022 report and being reviewed. (MDH) 2/16/2023-M. Hoque: DEC reviewed a bi-annual (January-June) 2022 site status update report. Monitoring wells, MW-1, MW-2, MW-2A, MW-3, MW-4, MW-5, MW-6, MW-7, MW-8, MW-9, and recovery wells RW-1, RW-2, RW-3, and RW-4 were gauged during this period. Product thickness was observed ranging from 0.17 foot to 0.59 foot in wells. VEFR events took place on monitoring wells MW-2A, MW-2, MW-3, and MW-7 in January, February, April, May, and June 2022, recovery wells RW-1 in May 2022, RW-2 in February and April 2022, RW-3 in February, April, and May, and RW-4 in February, April, May, and June 2022. The PRS consists of four recovery wells with pneumatic pumps, but it has been offline since February 2019. The PRS need repairs. NYCHA will continue well gauging monthly, with annually reporting to DEC. (MDH)

Remarks: CALLER STATES THAT A MALFUNCTION IN THE TANK PIPING CAUSED AN UNKNOWN AMOUNT SPILL CLEAN UP IS IN THE PROCESS AND TANK WILL BE REPLACED NO CALLBACK NECESSARY

All Materials:

Site ID:	139972
Operable Unit ID:	1084451
Operable Unit:	01
Material ID:	302286
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

291
East
1/4-1/2
0.443 mi.
2340 ft.

2700 ATLANTIC AVENUE
2700 ATLANTIC AVENUE
BROOKLYN, NY

NY VCP **S129932256**
NY NYC OER **N/A**

Relative:
Lower

Actual:
51 ft.

VCP NYC:

Project ID:	19TMP0704K,19EHAN181K,22CVCP001K
Name:	2700 ATLANTIC AVENUE
Address:	2700 ATLANTIC AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3,036,890,012,303,680,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.675937
Longitude:	-73.894603
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3326746
NTA:	East New York

NYC OER:

Name:	2700 ATLANTIC AVENUE
Address:	2700 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.675937
Longitude:	-73.894603
OER Project Numbers:	19TMP0704K,19EHAN181K,22CVCP001K
BBL:	3.03689001230368E+69
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3326746
NTA:	East New York

292
East
1/4-1/2
0.448 mi.
2367 ft.

110 WYONA STREET
BROOKLYN, NY 11207

NY LTANKS **U003385703**
NY Spills **N/A**
NY LEAD
NY NYC LAND USE

Relative:
Lower

Actual:
53 ft.

LTANKS:

Name:	RESIDENCE
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0411597 / 2005-01-31
Facility ID:	0411597
Site ID:	336825
Spill Date:	2005-01-28
Spill Cause:	Tank Overfill

(Continued) **U003385703**

Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2005-01-28
CID:	409
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-28
Spill Record Last Update:	2005-01-31
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL CORP.
Spiller Address:	290 LOCUST AVE
Spiller County:	001
Spiller Contact:	DORIS ZAMBRUSKI
Spiller Phone:	(718) 647-0507
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	272158
Latitude:	40.6766040
Longitude:	-73.8942130
DEC Memo:	Duplicate spill is closed. Ref back to Spill #0411594
Remarks:	REMEDIATIONS ARE MOBILIZING TO THE SITE. SOME INSIDE SOME OUTSIDE.

All Materials:

Site ID:	336825
Operable Unit ID:	1098826
Operable Unit:	01
Material ID:	579005
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	RESIDENCE
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0411594 / 2006-09-06
Facility ID:	0411594
Facility Type:	ER
DER Facility ID:	272158
Site ID:	336822
DEC Region:	2

(Continued) **U003385703**

Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-01-28
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2005-01-28
CID:	409
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-28
Spill Record Last Update:	2006-09-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MS. UVILES
Latitude:	40.6766040
Longitude:	-73.8942130
DEC Memo:	CROSS REF WITH SPILL #0411597 9/6/2006 Rob Hill from Castle Oil called looking to close out this spill case. Spill #0411597 was closed out because it was a duplicate of this spill. Spill case came back from Albany and was reassigned to R. Piper. 9/6/06- DEC Piper received documentation of spill cleanup by Castle oil and PTC. See e-docs if warranted. Closed.
Remarks:	CAP OFF BOILER AND LARGE FUMES. LOCATED IN HER BASEMEN. SPILL OUTSIDE AND IN BASEMENT. RESPONSE ENVIR. HIRED FOR CLEANUP

All Materials:

Site ID:	336822
Operable Unit ID:	1098823
Operable Unit:	01
Material ID:	579002
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NYC LEAD:

Name:	Not reported
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	11682359

(Continued) **U003385703**

Building ID:	398578
Registration ID:	334921
Apartment:	17
Story:	3
Class:	Most Serious
Inspection Date:	03/07/2017
Approved Date:	03/08/2017
Original Certify By Date:	04/11/2017
Original Correct By Date:	04/06/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5700707
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) WEST WALL IN THE 4th ROOM FROM NORTH LOCATED AT APT 17, 3rd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	03/09/2017
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	08/24/2019
Name:	Not reported
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	11682358
Building ID:	398578
Registration ID:	334921
Apartment:	17
Story:	3
Class:	Most Serious
Inspection Date:	03/07/2017
Approved Date:	03/08/2017
Original Certify By Date:	04/11/2017
Original Correct By Date:	04/06/2017
New Certify By Date:	Not reported
New Correct By Date:	Not reported
Certified Date:	Not reported
Order Number:	617
NOV ID:	5700707
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) SOUTH WALL IN THE 1st ROOM FROM NORTH LOCATED AT APT 17, 3rd STORY, 2nd APARTMENT FROM SOUTH AT WEST
NOV Issued Date:	03/09/2017
Current Status ID:	20
Current Status:	DEFECT LETTER ISSUED
Current Status Date:	08/24/2019
Name:	Not reported
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	14656120
Building ID:	398578

(Continued) **U003385703**

Registration ID:	334921
Apartment:	20
Story:	4
Class:	Most Serious
Inspection Date:	10/26/2021
Approved Date:	10/28/2021
Original Certify By Date:	11/27/2021
Original Correct By Date:	11/22/2021
New Certify By Date:	12/11/2021
New Correct By Date:	12/06/2021
Certified Date:	Not reported
Order Number:	617
NOV ID:	7530131
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) NORTH WALL, SOUTH WALL IN THE FOYER LOCATED AT APT 20, 4th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date:	10/29/2021
Current Status ID:	28
Current Status:	INVALID CERTIFICATION
Current Status Date:	12/11/2021
Name:	Not reported
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	14656121
Building ID:	398578
Registration ID:	334921
Apartment:	20
Story:	4
Class:	Most Serious
Inspection Date:	10/26/2021
Approved Date:	10/28/2021
Original Certify By Date:	11/27/2021
Original Correct By Date:	11/22/2021
New Certify By Date:	12/11/2021
New Correct By Date:	12/06/2021
Certified Date:	Not reported
Order Number:	617
NOV ID:	7530131
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) EAST WALL IN THE PRIVATE HALLWAY LOCATED AT APT 20, 4th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date:	10/29/2021
Current Status ID:	28
Current Status:	INVALID CERTIFICATION
Current Status Date:	12/11/2021
Name:	Not reported
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY 11207
Violation ID:	14656118
Building ID:	398578
Registration ID:	334921

(Continued) **U003385703**

Apartment:	20
Story:	4
Class:	Most Serious
Inspection Date:	10/26/2021
Approved Date:	10/28/2021
Original Certify By Date:	11/27/2021
Original Correct By Date:	11/22/2021
New Certify By Date:	12/11/2021
New Correct By Date:	12/06/2021
Certified Date:	Not reported
Order Number:	617
NOV ID:	7530131
NOV Description:	SECTION 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY 11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st WINDOW FRAME FROM NORTH AT EAST WALL, 2nd WINDOW FRAME FROM NORTH AT EAST WALL IN THE 1st ROOM FROM NORTH LOCATED AT APT 20, 4th STORY, 2nd APARTMENT FROM NORTH AT EAST
NOV Issued Date:	10/29/2021
Current Status ID:	28
Current Status:	INVALID CERTIFICATION
Current Status Date:	12/11/2021

NYC LAND USE:

Name:	Not reported
Address:	110 WYONA STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6765734
Longitude:	-73.8943969
Type Of Ownership Code:	Not reported
Owner Name:	WYONA APARTMENTS LLC
Borough:	BK
Tax Block:	3672
Tax Lot:	37
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198002002
Census Tract 2010:	1198
Census Block 2010:	2002
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	R5B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported

(Continued) **U003385703**

Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	5767
Total Building Floor Area:	16144
Commercial Floor Area:	0
Residential Floor Area:	16144
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	4.0000000
Residential Units:	23
Total Units:	23
Lot Frontage:	57.6700000
Lot Depth:	100.0000000
Building Frontage:	57.6700000
Building Depth:	89.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	103950.00000
Assessed Total Value:	703800.00000
Exempt Total Value:	0.00000
Year Built:	1937
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.80000000000
Maximum Allowable Residential Far:	1.35000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036720037.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1013542
Y Coordinate:	185788
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 011
Tax Map #:	31205
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported

(Continued) **U003385703**

2015 Preliminary Flood Insurance Rate Map Indicator: Not reported
Version Number: 24v3.1
Changed By DCP: Not reported

AO293 **NY VCP** **S118704084**
East **2718 FULTON STREET** **NY E DESIGNATION** **N/A**
1/4-1/2 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.460 mi. **NY NYC OER**
2430 ft. **Site 2 of 2 in cluster AO**

Relative:
Lower

Actual:
55 ft.

VCP NYC:
Project ID: 17TMP0622K,18CVCP046K,18EH-N452K
Name: 2718 FULTON STREET
Address: 2718 FULTON STREET
City,State,Zip: NEW YORK CITY, NY
Borough: Brooklyn
BBL: 303,673,001,430,367,000,000,000,000,000
OER Program: VCP (Enrolled), E/RD (Review)
Phase: Site Management
Latitude: 40.677641
Longitude: -73.894251
Postcode: 11207
Community Board: 5
Council District: 37
Census Tract: 1198
BIN: 3000000
NTA: East New York

E DESIGNATION:
Name: LOT 14,TAXBLOCK 3673
Address: 2718 FULTON STREET
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 14
Tax Block: 3673
Borough Code: Not reported
E-No: E-366
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 15DCP102K
Ulurp Number: N160050ZRK; C160035ZMK
Zoning Map No: Not reported

Description: Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC LAND USE:
Name: Not reported
Address: 2718 FULTON STREET
City,State,Zip: BROOKLYN, NY 11207
Latitude: 40.6774432
Longitude: -73.8941143
Type Of Ownership Code: Not reported
Owner Name: 2722 FULTON LLC
Borough: BK
Tax Block: 3673
Tax Lot: 14

(Continued) **S118704084**

Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198002001
Census Tract 2010:	1198
Census Block 2010:	2001
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	C4-4L: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	H3: Hotels - Limited Service ? Many Affiliated With National Chain
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	7513
Total Building Floor Area:	36769
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	7.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	75.0000000
Lot Depth:	100.5000000
Building Frontage:	48.0000000
Building Depth:	100.0000000
Extension Code:	Not reported
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	270450.00000
Assessed Total Value:	2942550.00000
Exempt Total Value:	0.00000
Year Built:	2020
Year Altered 1:	0

(Continued) **S118704084**

Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	4.89000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	4.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036730014.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1013620
Y Coordinate:	186105
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 012
Tax Map #:	31205
E-designation Number:	E-366
Apportionment BBL:	3036730014.00000000
Apportionment Date:	11/09/2017
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	2718 FULTON STREET
Address:	2718 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677641
Longitude:	-73.894251
OER Project Numbers:	17TMP0622K,18CVCP046K,18EH-N452K
BBL:	3.0367300143036699E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3000000
NTA:	East New York

AP294 **EXXONMOBIL** **NY LTANKS** **S110045421**
SE **225 PENNSYLVANIA AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.464 mi.
2450 ft. **Site 1 of 4 in cluster AP**

Relative:
Lower

Actual:
41 ft.

LTANKS:

Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9213037 / 1994-08-25

EXXONMOBIL (Continued) **S110045421**

Facility ID:	9213037
Site ID:	173885
Spill Date:	1993-02-22
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1994-08-25
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1993-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-02-24
Spill Record Last Update:	2004-01-13
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	61415
Latitude:	40.6722071
Longitude:	-73.8958986
DEC Memo:	Not reported
Remarks:	DELIVERY JUDGED TANK TOO BIG-TANK OVERFLOWED TO PAVED AREA AND CONTAINED STORM DRAIN SYSTEM INTO HOLDING-ENVI PRODS AND SVCS CO.TO PUMP TANK & WILL DISPOSAL-NYCFD RESPONDED & FLUSHED SPILL.

All Materials:

Site ID:	173885
Operable Unit ID:	980202
Operable Unit:	01
Material ID:	402857
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CUMBERLAND FARMS 70227
Address:	225 PENNSYLVANIA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0907694 / 2009-11-20
Facility ID:	0907694

EXXONMOBIL (Continued) **S110045421**

Site ID:	420231
Spill Date:	2009-10-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2009-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-10-08
Spill Record Last Update:	2009-11-20
Spiller Name:	ANGELA PIMENTAL
Spiller Company:	CUMBERLAND FARMS 70227
Spiller Address:	225 PENNSYLVANIA AVENUE
Spiller County:	999
Spiller Contact:	GLIDDEN
Spiller Phone:	(800) 225-9702
Spiller Extention:	4494
DEC Region:	2
DER Facility ID:	341256
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	10/8/09 - Raphael Ketani (duty desk officer). The spill was discovered on 10/7/09 and called in on 10/8/09. Yesterday, staff from Tanknology (C.J. Schultz (800) 666-1215) discovered an interstitial leak and a ullage leak. In both instances, a vacuum could not be maintained. Mr. Schultz told me that they will come back today and do helium testing to try and pin point the location of the failure. The PBS is #2-217980. The corporate address is: Cumberland Farms, Inc., 100 Crossing Blvd., Framingham, MA, 01702, Attn: Angela Pimental. Cumberland's phone is: (800) 225-9702, ext 4494. A TTF letter was sent to Cumberland. 11/20/09. J.Krimgold reviewed the letter report submitted by ECS and dated 11/17/09. Based on the report subsequent tests were performed on the tank indicating the ullage and interstitial failure. The contents of thank was evacuated and tank is scheduled for in-place closure at the end of November 2009. Gaging of tank pad wells and groundwater monitoring wells throughout the site shows no change in the tank surrounding subsurface. Case closed.
Remarks:	Not reported

All TTF:

Facility ID:	0907694
Spill Number:	0907694
Spill Tank Test:	2488094
Site ID:	420231
Tank Number:	4
Tank Size:	4000
Material:	0009
EPA UST:	True

EXXONMOBIL (Continued) **S110045421**

UST:	True
Cause:	00
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	JMKRIMGO
Last Modified Date:	Not reported

All Materials:

Site ID:	420231
Operable Unit ID:	1176214
Operable Unit:	01
Material ID:	2168876
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8807901 / 1994-08-25
Facility ID:	8807901
Site ID:	63604
Spill Date:	1988-12-28
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	1994-08-25
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1988-12-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-12-30
Spill Record Last Update:	2004-01-13
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

EXXONMOBIL (Continued) **S110045421**

Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 61415
Latitude: 40.6722071
Longitude: -73.8958986
DEC Memo: Not reported
Remarks: (2) 4K TANKS MANIFOLDED TOGETHER, FAILED SYSTEM TEST WITH A LEAK RATE OF -.447GPH, WILL EXCAVATE, ISOLATE AND RETEST.

All TTF:
Facility ID: 8807901
Spill Number: 8807901
Spill Tank Test: 1535047
Site ID: 63604
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 63604
Operable Unit ID: 923381
Operable Unit: 01
Material ID: 452677
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

SPILLS:
Name: CUMBERLAND EXXON#70227
Address: 225 PENNSYLVANIA AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0701806 / 2010-08-20
Facility ID: 0701806
Facility Type: ER
DER Facility ID: 61415
Site ID: 381404
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401

EXXONMOBIL (Continued) **S110045421**

Spill Date:	2007-05-14
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2007-05-14
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-05-15
Spill Record Last Update:	2010-08-20
Spiller Name:	MELISSA GLIDEN
Spiller Company:	EXXON#70227
Spiller Address:	225 PENNSYLVANIA AVE
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Several spills have been called in today by Cumberland Exxon. All assigned to Piper. 08/20/10-HRAHMED-PBS#2-217980 As per the DEC PBS records Tank # 1, 2 & 3 was tested tight on 11/09/09 and Tank # 4 & 5 were tested tight on 2/9/10. This case is closed.
Remarks:	OFF 10 DAY AND WILL BE TESTING

All Materials:

Site ID:	381404
Operable Unit ID:	1138859
Operable Unit:	01
Material ID:	2128862
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9510716 / 1995-11-27
Facility ID:	9510716
Facility Type:	ER
DER Facility ID:	61415
Site ID:	72482
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3

EXXONMOBIL (Continued) **S110045421**

SWIS:	2401
Spill Date:	1995-11-27
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1995-11-27
CID:	270
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1995-11-27
Spill Record Last Update:	2004-01-13
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	UNKNOWN
Latitude:	40.6722071
Longitude:	-73.8958986
DEC Memo:	Not reported
Remarks:	CONTRACTOR DISCOVERED A LEAK IN THE AREA OF FILTER ON THE NUMBER 5 AND 6 DISPENSER. FIELD ENG MIKE MEOLA 516 8764697.

All Materials:

Site ID:	72482
Operable Unit ID:	1025177
Operable Unit:	01
Material ID:	358070
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9405913 / 1994-10-18
Facility ID:	9405913
Facility Type:	ER
DER Facility ID:	61415
Site ID:	63605
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1994-07-29
Investigator:	SIGONA

EXXONMOBIL (Continued) **S110045421**

Referred To:	Not reported
Reported to Dept:	1994-08-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-10-18
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1994-10-17
Spill Record Last Update:	2004-01-13
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6722071
Longitude:	-73.8958986
DEC Memo:	Not reported
Remarks:	O RING WAS BACK-FILTER LEAKING 18' INTO GROUND-REMOVE PEA GRAVEL. FIXED PROBLEM.

All Materials:

Site ID:	63605
Operable Unit ID:	1003285
Operable Unit:	01
Material ID:	382482
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CUMBERLAND FARMS # 70227
Address:	225 PENNSYLVANIA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0811834 / 2009-04-23
Facility ID:	0811834
Facility Type:	ER
DER Facility ID:	341256
Site ID:	409422
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-01-29
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2009-01-29
CID:	Not reported

EXXONMOBIL (Continued) **S110045421**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-29
Spill Record Last Update:	2009-04-23
Spiller Name:	MELISSA GLIDDEN
Spiller Company:	CUMBERLAND FARMS # 70227
Spiller Address:	225 PENNSYLVANIA AVE
Spiller Company:	999
Contact Name:	MELISSA GLIDDEN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	04/23/09-HRAHMED-Phoenix cleanedup the spill. See eDocs for cleanup documents. This case is closed.
Remarks:	WATER IN THE SUMP PUMP OUT WILL BE DONE BY TYREE.

All Materials:

Site ID:	409422
Operable Unit ID:	1165929
Operable Unit:	01
Material ID:	2157362
Material Code:	9999
Material Name:	other - WATER
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	CUMBERLAND FARMS # 70227
Address:	225 PENNSYLVANIA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0811933 / 2009-04-24
Facility ID:	0811933
Facility Type:	ER
DER Facility ID:	341256
Site ID:	409526
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-02-02
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2009-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other

EXXONMOBIL (Continued) **S110045421**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-02
Spill Record Last Update:	2009-04-24
Spiller Name:	MELISSA GLIDDEN
Spiller Company:	CUMBERLAND FARMS # 70227
Spiller Address:	225 PENNSYLVANIA AVE
Spiller Company:	999
Contact Name:	MELISSA GLIDDEN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	04/24/09-HRAHMED-Non-petroleum spill, weather related. As per discussion with DEC Austin and DEC Krimgold, this spill is closed.
Remarks:	LIQUID IN THE ANNUALAR SPACE, CLEAN UP WILL BE DONE BY PHOENIX ENVIRONMENTAL

All Materials:

Site ID:	409526
Operable Unit ID:	1166033
Operable Unit:	01
Material ID:	2157468
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9211872 / 2009-11-24
Facility ID:	9211872
Facility Type:	ER
DER Facility ID:	61415
Site ID:	173884
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1993-01-18
Investigator:	jamaison
Referred To:	NFA
Reported to Dept:	1993-01-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

EXXONMOBIL (Continued) **S110045421**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1993-01-28
Spill Record Last Update:	2009-11-25
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	40.6722071
Longitude:	-73.8958986
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill site has been consolidated under Spill No. 9211872. 6/14/05: This spill case transferred from Rommel to J. Kolleeny. - JK 6/13/06: This spill case transferred from J. Kolleeny to J.A. Maisonave - JAM 6/14/06: Reviewed Semi-annual Groundwater Monitoring Report for July through Dec 2005 submitted by ECS in Feb 2006 for monitoring wells MW-1 through 3. MW-1 and MW-2 show levels of ethylbenzene and xylene above AWQS (highest hit was 147 ppb xylene in MW-1). MW-1 which is located next to the fill ports seems to be on the decline and MW-2 which is down gradient of MW-1 is only slightly elevated. To date MW-3 has shown no contamination. Since the depth to water is in excess of 30 feet the contamination is a low risk. The Semi-annual report for January through June 2006 is expected at the end of July. I will review to see if the downward trend continues. JAM 10/20/06: Reviewed Semi-annual Groundwater Monitoring Report for Jan through June 2006 submitted by ECS dated Sept. 18, 2006 for monitoring wells MW-1 through MW-3. Mw-1 and MW-2 show levels of toluene, ethylbenzene and total zylene above AWQS (highest hit was 192ppb total xylene in MW-1). To date MW-3 has shown no contamination. There was a slight rise in total xylenes in both wells on the March sampling event, which then decreased in the June sampling event. Overall the contaminant concentration is low. The Semi-annual Monitoring Report for July through Dec 2006 is expected in January, 2007. - JAM 9/19/07 Reviewed Semi-annual Groundwater Monitoring Report for Jan-June 2007. Wells MW-1 through MW-03 were sampled and results showed some levels of BTEX that exceeded AWQS. Highest hit was in MW-1 on March 6, 2007 sampling event of total xylene at 303ug/L. I asked Bill Simmons to continue sampling groundwater and analyze for the full TAGM 4046 list of gasoline-related VOCs. - JAM 12/18/07 Reviewed Groundwater Monitoring Report & Closure Request for the period July-Sept 2007. Wells MW-1 through MW-3 were sampled. Results showed total VOCs

EXXONMOBIL (Continued) **S110045421**

in MW-1 and MW-2 to be
342ug/L and 176ug/L, respectively. MW-03 was ND. ECS requests closure of the spill. I sent an email
today requesting another round of samples be taken and sampled for the full TAGM 4046 list of
gasoline related VOCs. A copy of the mail is in the file. - JAM
11/04/08 Reviewed Groundwater
Monitoring Report & Closure Request for period October 2007 through May 2008. ECS collected
groundwater samples from 3 on-site monitoring wells. Results for the latest round collected in May
2008 were 575ug/L Total VOCs in MW-1, 58 ug/L Total VOCs in MW-2 and ND in MW-3. ECS requests spill
closure due to the relatively minor contamination observed. I reviewed a UST closure report
submitted by Unico Environmental, Inc. from 1993. The USTs removed were located on the corner of
Pitkin Ave. and Pennsylvania Ave. This area has not been adequately investgated. Also, groundwater
contamination has not been delineated downgradient of MW-1. I sent a letter today stating, The
NYSDEC cannot approve spill closure at this time. I requested three borings be advanced and soil
and groundwater samples be collected from each boring. A work plan should be submitted for NYSDEC
review and approval. This letter is uploaded to eDocs. - JAM 1/20/09 Reviewed the Groundwater
Monitoring Report & Subsurface Investigation Work Plan for period June 2008 through January 2009
submitted by ECS dated January 15, 2009. ECS collected groundwater samples from three monitoring
wells on-site on Sept 24, 2008 and January 2, 2009. Results from the Sept sampling event showed
total VOC concentrations of ND in MW-3, 210ug/L in MW-2 and 1,718ug/L in MW-1. Results from the Jan
sampling event showed total VOCs of ND in MW-3, 153ug/L in MW-2 and 1,170ug/L in MW-1. ECS proposed
advancing three soil borings (SB-7 through SB-9) and collecting soil and groundwater samples from
each to analyze for the full range of gasoline related VOCs. SB-7 is located at the corner of
Pitken Ave and Pennsylvania Ave, SB-8 is located near MW-2 and SB-9 is located near SB-1,
downgradient from MW-1. I sent an approval letter today requesting that SB-8 be moved further west,
mid-way between MW-2 and proposed soil boring SB-7. Both the report and my approval letter are
uploaded to eDocs. -JAM 11/24/09 Reviewed the On-site Subsurface Investigation Report submitted by
ECS dated August 5, 2009. The report summarizes results of 3 soil borings advanced on site and two
rounds groundwater monitoring results. On March 6 and 27, 2009 three soil borings (GP-7, SB-8 and
MW-4) were advanced and soil and groundwater samples were collected. On March 6, boring GP-7 was
advanced with a geoprobe and soil was continuously screened to 20fbg, at which point very dense

EXXONMOBIL (Continued) **S110045421**

soil was encountered and the sample tubes could not be advanced. The boring was then advanced to
34-36fbg to collect a groundwater grab sample. On March 27, a hollow stem auger was utilized to
advance borings SB-8 and MW-4. Soil at these locations was continuously screened to the water
table. A permanent monitoring well was installed at MW-4. Four soil samples from borings SB-8 and
MW-4 were analyzed by a lab and results idication no VOCs above TAGM RSCOs. Results from the
groundwater grab samples collected at GP-7 and SB-8 also indicated no VOCs above lab RDLs. On April
2 and June 29, 2009, ECS gauged and sampled four monitoring wells (MW-1 - MW-4. Results from April
ranged from ND in wells MW-3 to 678ug/L total VOCs in MW-1. In June, the results ranged from ND in
well MW-3 and MW-1 to 106ug/L total VOCs. The results from well MW-1 decreased from April to June
where they were ND. Based on the findings of this investigation and from the most recent
groundwater samples collected at the site, ECS requests spill closure. Report uploaded to eDocs.
According to the report, the former UST area on the southwest corner of the site has been
adequately investigated and the soil samples from GP-7 and SB-8 had VOC concentrations below lab
RDLs. The groundwater samples collected during the investigation and during the monitoring events
in April and June 2009, show a general continuing decreasing trend in dissolved phase VOC
concentrations. This site does not pose a threat to human health or the environment. This spill
case was closed and a No Further Action was issued. Letter uploaded to eDocs. - JAM

Remarks: REBUILDING STATION EXCAVATED SOILS & TEST PROVED IMPACTED BY H.C. SOIL STOCK PILED ON SITE COVERED W/ PLASTIC WILL DISPOSE OF THE SOIL

All Materials:

Site ID:	173884
Operable Unit ID:	978814
Operable Unit:	01
Material ID:	405255
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	CUMBERLAND FARM #70227
Address:	225 PENNSYLVANIA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0710383 / 2007-12-31
Facility ID:	0710383

EXXONMOBIL (Continued) **S110045421**

Facility Type:	ER
DER Facility ID:	341256
Site ID:	391656
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2007-12-31
Investigator:	jbvought
Referred To:	Not reported
Reported to Dept:	2007-12-31
CID:	408
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-12-31
Spill Record Last Update:	2007-12-31
Spiller Name:	MELLISSA GLIDDEN
Spiller Company:	CUMBERLAND FARM #70227
Spiller Address:	225 PENNSYLVANIA AVE
Spiller Company:	001
Contact Name:	MELLISSA GLIDDEN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/31/07-Vought-Duty desk officer. Non-petroleum spill closed as per PBS Jacob Krimgold. Spill closed by Vought.
Remarks:	WATER IN SUMP; possibly rain is factor; TYREE WILL BE PUMPING IT OUT;

All Materials:

Site ID:	391656
Operable Unit ID:	1148699
Operable Unit:	01
Material ID:	2139193
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CUMBERLAND FARMS 70227
Address:	225 PENNSYLVANIA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1000581 / 2010-04-20
Facility ID:	1000581
Facility Type:	ER
DER Facility ID:	341256

EXXONMOBIL (Continued) **S110045421**

Site ID:	431751
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-04-14
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2010-04-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-14
Spill Record Last Update:	2010-04-20
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WINSOME KELLY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	4/20/09-HRAHMED-Weather related. Non-petroleum spill. Case closed.
Remarks:	cleanup pending by Phoenix

All Materials:

Site ID:	431751
Operable Unit ID:	1183221
Operable Unit:	01
Material ID:	2177429
Material Code:	9999
Material Name:	other - water in sump
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0111691 / 2004-01-13
Facility ID:	0111691
Facility Type:	ER
DER Facility ID:	61415
Site ID:	173883
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3

EXXONMOBIL (Continued) **S110045421**

SWIS:	2401
Spill Date:	2002-03-11
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	2002-03-11
CID:	322
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2002-03-11
Spill Record Last Update:	2005-06-13
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller Company:	001
Contact Name:	STEVE QUATTRO
Latitude:	40.6722071
Longitude:	-73.8958986
DEC Memo:	Site relates to an Exxon gasoline station. Initial spill report was a gasoline spill. 3/16/2005 Sangesland received a report from Environemtnal Compliance Services, most of the report deals with MTBE levels. 3/16/2005 Koon Tang found that the same spill has been tracked under 9211872. Refer to 9211872 for additional details. - KST
Remarks:	While Tyree was replacing the fill buckets on tanks - soil around the old buckets was contaminated

All Materials:

Site ID:	173883
Operable Unit ID:	850335
Operable Unit:	01
Material ID:	571979
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	True

Site ID:	173883
Operable Unit ID:	850335
Operable Unit:	01
Material ID:	525710
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

EXXONMOBIL (Continued) **S110045421**

Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	True

AP295 **EXXONMOBIL** **UST FINDER RELEASE** **1029076943**
SE **225 PENNSYLVANIA AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.464 mi.
2450 ft. **Site 2 of 4 in cluster AP**

Relative: **Lower**
Actual: **41 ft.**

UST FINDER RELEASE:

Object ID:	258975
Facility ID:	NY61415
Lust ID:	NY8807901
Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1988/12/28 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8077
Domestic Wells within 1500ft:	4
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8959
Y Coord:	40.6722100000001
Latitude:	40.67221
Longitude:	-73.8958999999999

Object ID:	258976
Facility ID:	NY61415
Lust ID:	NY9211872
Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1993/01/18 15:59:59+00

EXXONMOBIL (Continued) **1029076943**

Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8077
Domestic Wells within 1500ft:	4
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8959
Y Coord:	40.6722100000001
Latitude:	40.67221
Longitude:	-73.8958999999999

Object ID:	258977
Facility ID:	NY61415
Lust ID:	NY9213037
Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1993/02/22 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8077
Domestic Wells within 1500ft:	4
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported

EXXONMOBIL (Continued) **1029076943**

NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8959
Y Coord:	40.6722100000001
Latitude:	40.67221
Longitude:	-73.8958999999999
Object ID:	258978
Facility ID:	NY61415
Lust ID:	NY9405913
Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1994/07/29 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8077
Domestic Wells within 1500ft:	4
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8959
Y Coord:	40.6722100000001
Latitude:	40.67221
Longitude:	-73.8958999999999
Object ID:	258979
Facility ID:	NY61415
Lust ID:	NY9510716
Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1995/11/27 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8077

EXXONMOBIL (Continued) **1029076943**

Domestic Wells within 1500ft:	4
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-73.8959
Y Coord:	40.6722100000001
Latitude:	40.67221
Longitude:	-73.8958999999999

Object ID:	258980
Facility ID:	NY61415
Lust ID:	NY111691
Name:	EXXONMOBIL
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2002/03/11 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8077
Domestic Wells within 1500ft:	4
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported

EXXONMOBIL (Continued) **1029076943**

Coordinate Source:	State
X Coord:	-73.8959
Y Coord:	40.6722100000001
Latitude:	40.67221
Longitude:	-73.8958999999999

AP296 **EXXON DIV OF CFI #70227** **RCRA NonGen / NLR** **1000335601**
SE **225 PENNSYLVANIA AVE** **FINDS** **NYD986894186**
1/4-1/2 **BROOKLYN, NY 11236** **ECHO**
0.464 mi. **NY MANIFEST**
2450 ft. **Site 3 of 4 in cluster AP** **NY NYC OER**

Relative: **Lower**
Actual: **41 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Exxon Div Of Cfi #70227
Handler Address:		Pennsylvania Ave
Handler City,State,Zip:		BROOKLYN, NY 11236
EPA ID:		NYD986894186
Contact Name:		MAUREEN JERNSTEDT
Contact Address:		DEDHAM ST
Contact City,State,Zip:		CANTON, MA 02021
Contact Telephone:		800-225-9702 x3378
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R2
Mailing Address:		DEDHAM ST
Mailing City,State,Zip:		CANTON, MA 02021
Owner Name:	Tosco	
Owner Type:		Private
Operator Name:	No Name Found	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline

EXXON DIV OF CFI #70227 (Continued) **1000335601**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CUMBERLAND FARMS INC	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CUMBERLAND FARMS INC	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Private
Date Became Current:	20030910
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: TOSCO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 52085
Owner/Operator City,State,Zip:	PHOENIX, AZ 85072-2085
Owner/Operator Telephone:	602-728-8000
Owner/Operator Telephone Ext:	Not reported

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: TOSCO #34780
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EXXON DIV OF CFI #70227
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EXXON DIV OF CFI #70227
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900404
Handler Name: TOSCO #34780
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010808

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Handler Name: TOSCO #34780
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20041001
Handler Name: EXXON DIV OF CFI #70227
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44711
NAICS Description: Gasoline Stations With Convenience Stores

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004444192

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000335601
Registry ID: 110004444192

EXXON DIV OF CFI #70227 (Continued) **1000335601**

DFR URL:
Name: EXXON DIV OF CFI #70227
Address: 225 PENNSYLVANIA AVE
City,State,Zip: BROOKLYN, NY 11236

NY MANIFEST:
EPA ID: NYD986894186
Country: USA
Name: Exxon Company Usa
Address: 225 PENNSYLVANIA AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11236
Zip 4: Not reported
Location Address 1: 225 PENNSYLVANIA AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 13775
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Exxon Company Usa
Mailing Contact: Christine Coluccio
Mailing Address 1: P O BOX 4415
Mailing Address 2: Not reported
Mailing City,State,Zip: HOUSTON, TX 77210
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 5168641772

Manifest Data:
Document ID: NYB2128320
Manifest Status: Not reported
Trans1 State ID: IL015
Year: 1990
Trans2 State ID: Not reported
Generator Ship Date: 10/11/1990
Trans1 Recv Date: 10/11/1990
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/12/1990
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986894186
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Carbon Tetrachloride
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00100
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB2445165
Manifest Status:	Not reported
Trans1 State ID:	HW6917
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	01/07/1992
Trans1 Recv Date:	01/07/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	NYD986910222
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00010
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Document ID:	MAF3182630
Manifest Status:	Not reported
Trans1 State ID:	50C143OH
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/1991
Trans1 Recv Date:	05/30/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/31/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD053452637
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA1565917
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES50
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	03/24/1993
Trans1 Recv Date:	03/24/1993
Trans2 Recv Date:	Not reported

EXXON DIV OF CFI #70227 (Continued) **1000335601**

TSD Site Recv Date:	03/24/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	CTF0180176
Manifest Status:	Not reported
Trans1 State ID:	PP1384
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1992
Trans1 Recv Date:	10/12/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986894186
Trans1 EPA ID:	NYD986910222
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported

EXXON DIV OF CFI #70227 (Continued) **1000335601**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00600
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	01.00

NYC OER:

Name:	225 PENNSYLVANIA AVENUE
Address:	225 PENNSYLVANIA AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.672274
Longitude:	-73.895954
OER Project Numbers:	17TMP0295K,17EH-N250K
BBL:	3037210001
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1144
BIN:	3426261
NTA:	East New York (Pennsylvania Ave)

297
ESE
1/4-1/2
0.471 mi.
2487 ft.

SOLCO PLUMBING SUPPLY
413 LIBERTY AVENUE
BROOKLYN, NY 11207

NY SWF/LF **S118406630**
NY NYC LAND USE **N/A**

Relative:
Lower

Actual:
49 ft.

SWF/LF:

Name:	SOLCO PLUMBING SUPPLY
Address:	413 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183451900
Owner Name:	New York City Department of Environmental Protection
Owner Type:	Municipal
Owner Address:	59-17 Junction Blvd; 11th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Flushing, NY 11373
Owner Email:	bhuff@dep.nyc.gov

SOLCO PLUMBING SUPPLY (Continued) **S118406630**

Owner Phone:	7185955522
Contact Name:	Ben Huff
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	NY
Contact Email:	bhuff@dep.nyc.gov
Contact Phone:	7185955522
Activity Desc:	Transfer station - registration
Activity Number:	[24RG8]
Active:	No
East Coordinate:	593465
North Coordinate:	4503257
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Not reported
Authorization #:	24RG8
Authorization Date:	12/23/2015
Expiration Date:	Not reported
Operator Name:	New York City Department of Environmental Protection
Operator Type:	Municipal
Laste Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	413 LIBERTY AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6750636
Longitude:	-73.8942118
Type Of Ownership Code:	X
Owner Name:	413 LIBERTY REALTY CORP
Borough:	BK
Tax Block:	3689
Tax Lot:	1
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198002005
Census Tract 2010:	1198
Census Block 2010:	2005
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1C
Zoning District 1:	M1-4: Manufacturing Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

SOLCO PLUMBING SUPPLY (Continued) **S118406630**

Spill Boundary Indicator:	N
Building Class:	E9: Warehouses - Miscellaneous
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	36050
Total Building Floor Area:	36050
Commercial Floor Area:	36050
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	10000
Garage Floor Area:	0
Storage Floor Area:	26050
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	206.0000000
Lot Depth:	175.6700000
Building Frontage:	206.0000000
Building Depth:	175.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	306900.00000
Assessed Total Value:	989100.00000
Exempt Total Value:	989100.00000
Year Built:	1955
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.00000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036890001.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1013594
Y Coordinate:	185238
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 011
Tax Map #:	31205
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1

SOLCO PLUMBING SUPPLY (Continued) **S118406630**

Changed By DCP: Not reported

298
NE
1/4-1/2
0.473 mi.
2500 ft.

20 INTERBOROUGH PKWY **NY LTANKS** **S102672131**
20 INTERBOROUGH PKWY **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
116 ft.

LTANKS:

Name:	20 INTERBOROUGH PKWY
Address:	20 INTERBOROUGH PKWY
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9213957 / 1993-03-20
Facility ID:	9213957
Site ID:	244192
Spill Date:	1993-03-20
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1993-03-20
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1993-03-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-03-30
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BAREANKLAU OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	200568
Latitude:	40.6812250
Longitude:	-73.8961130
DEC Memo:	Not reported
Remarks:	CUSTOMER ORDERED MORE THAN TANK CAN HOLD. APPLIED DRYSOL. NO CALLBACK. Not reported

All Materials:

Site ID:	244192
Operable Unit ID:	978011
Operable Unit:	01
Material ID:	403702
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

20 INTERBOROUGH PKWY (Continued) **S102672131**

Quantity:	2.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AP299 **CFI STATION #70227** **NY LTANKS** **S110045410**
SE **189 PENNSYLVANIA AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.479 mi.
2527 ft. **Site 4 of 4 in cluster AP**

Relative: **Lower**
Actual: **41 ft.**

LTANKS:

Name:	CFI STATION #70227
Address:	189 PENNSYLVANIA AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0907625 / 2015-12-09
Facility ID:	0907625
Site ID:	420161
Spill Date:	2009-10-07
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	AXDORONO
Referred To:	Not reported
Reported to Dept:	2009-10-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-10-07
Spill Record Last Update:	2015-12-09
Spiller Name:	Not reported
Spiller Company:	GULF
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MELISA GLIDDEN
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	369183
Latitude:	40.6731237
Longitude:	-73.8960915
DEC Memo:	10/27/11 - Austin - Transferring this case from Ahmed to Ketani - end 07/11/13 - Case is transferred from Ketani (Section C) to Brevdo (Section B) as per DER Region 2 decision. V. Brevdo 07/17/2013: This spill case was transferred to A. Doronova. - AD Put site priority as P0. AD This spill was opened as a result of a reported tank test failure. Looked in the ACRIS database for the property ownership. According to ACRIS, this site belongs to CUmberland Farms, Inc. Sent the following e-mail to Chris Johnson of CFI: Dear Mr. Johnson: The

CFI STATION #70227 (Continued) **S110045410**

NYSDEC has in its files open spill cases for the following properties: 1. NYSDEC Spill No. 0907625, Station #70227, 189 Pennsylvania Avenue, Brooklyn; 2. NYSDEC Spill No. 0905291, 90-02 Metropolitan Avenue, Queens; 3. NYSDEC Spill No. 0904510, 15411 Horace Harding Boulevard, Flushing; 4. NYSDEC Spill No. 0901625, Station #70220, 6743 Fourth Avenue, Brooklyn; 5. NYSDEC Spill No. 0901547, Station #70216, 3602 Snyder Avenue, Brooklyn. These spill cases were transferred to me. According to ACRIS database these properties belong to CFI, Inc. Please confirm the ownership of these sites by CFI, Inc., and if this is the case, please provide DEC with all information related to remediation and cleanup activities for these sites. Feel free to contact me if you have any questions. Thank you. Sincerely, Ainura Doronova AD 07/18/2013: Received the following e-mail from C. Johnson of CFI: Good morning, Bill Simmons of ECS will also be the consultant for these spills. We are working to gather information for these sites too. Thank you, Chris Christopher Johnson Senior Project Manager Office of the General Counsel Environmental Affairs Changed spill name to Cumberland Farms - CFI. AD 11/05/2013: Sent the following e-mail to Mr. Johnson of CFI: Dear Mr. Johnson: I am awaiting for the information regarding the following CFI sites: 1. NYSDEC Spill #1009352, CFI # 70223, 1938 Coney Island Avenue, Brooklyn; 2. NYSDEC Spill #0809132, CFI # 70224, 3031 Coney Island Avenue, Brooklyn; 3. NYSDEC Spill #0703743, 2338 31st Street, Astoria; 4. NYSDEC Spill #0702193, 115-05 Beach Channel Drive, Rockaway Park; 5. NYSDEC Spill #0701807, CFI #70225, 8779 Bay Parkway, Brooklyn; 6. NYSDEC Spill #9505634, 29-16 Francis Lewis Boulevard, Flushing. 7. NYSDEC Spill No. 0907625, Station #70227, 189 Pennsylvania Avenue, Brooklyn; 8. NYSDEC Spill No. 0905291, 90-02 Metropolitan Avenue, Queens; 9. NYSDEC Spill No. 0904510, 15411 Horace Harding Boulevard, Flushing; 10. NYSDEC Spill No. 0901625, Station #70220, 6743 Fourth Avenue, Brooklyn; 11. NYSDEC Spill No. 0901547, Station #70216, 3602 Snyder Avenue, Brooklyn. Any information regarding performed investigation and remediation actions related to these open spill cases, should be compiled into a summary report with conclusions and recommendations for further actions and submitted to the Department in a timely manner. If there is no such information, an investigation work plan should be submitted to DEC for its review and approval. Please feel free to contact me with your questions or comments. Sincerely, Ainura Doronova AD 02/19/2015: Sent the following e-mail to Mr. Johnson: Dear Mr. Johnson, DEC is awaiting for the information regarding NYSDEC spill cases for the following CFI sites: 1. NYSDEC Spill No.0809132, CFI # 70224, 3031 Coney Island Avenue, Brooklyn; 2. NYSDEC Spill No.0703743, 2338 31st Street, Astoria; 3. NYSDEC Spill No.0701807, CFI #70225, 8779 Bay Parkway, Brooklyn; 4. NYSDEC Spill No.9505634, 29-16 Francis Lewis Boulevard, Flushing. 5. NYSDEC Spill No.0907625, Station #70227, 189 Pennsylvania Avenue, Brooklyn; 6. NYSDEC Spill No.0904510, 15411 Horace Harding Boulevard, Flushing; 7. NYSDEC Spill No.0901625, Station #70220, 6743 Fourth Avenue, Brooklyn; 8. NYSDEC Spill No.0901547, Station #70216, 3602 Snyder Avenue, Brooklyn; 9. NYSDEC Spill No.9604417, 6743 Fourth Avenue, Brooklyn; An information regarding performed investigation and remediation actions, related to these open spill cases, should be compiled into a summary reports with conclusions and recommendations for further actions and submitted to the Department in a timely manner. If there is no such information, an investigation work plans should be prepared and submitted to DEC for review and approval. Please feel free to contact

CFI STATION #70227 (Continued) **S110045410**

me with your questions or comments. Sincerely, Ainura Doronova AD 11/16/2015: Sent the following e-mail to Mr. Johnson: Dear Mr. Johnson, DEC is awaiting for the information regarding open NYSDEC spill cases for the following CFI sites: 1. NYSDEC Spill No.0809132, CFI # 70224, 3031 Coney Island Avenue, Brooklyn; 2. NYSDEC Spill No.0703743, 2338 31st Street, Astoria; 3. NYSDEC Spill No.0701807, CFI #70225, 8779 Bay Parkway, Brooklyn; 4. NYSDEC Spill No.9505634, 29-16 Francis Lewis Boulevard, Flushing. 5. NYSDEC Spill No.0907625, Station #70227, 189 Pennsylvania Avenue, Brooklyn; 6. NYSDEC Spill No.0904510, 15411 Horace Harding Boulevard, Flushing; 7. NYSDEC Spill No.0901625, Station #70220, 6743 Fourth Avenue, Brooklyn; 8. NYSDEC Spill No.0901547, Station #70216, 3602 Snyder Avenue, Brooklyn; 9. NYSDEC Spill No.9602411, 137-21 Liberty Avenue, Queens; 10. NYSDEC Spill No.219-02 Horace Harding Boulevard, Queens; 11. NYSDEC Spill No.9604417, 6743 Fourth Avenue, Brooklyn; Any information regarding performed repair work, investigation and/or remediation actions related to these open spill cases, should be compiled into summary reports for each case with conclusions and recommendations for further actions and submitted to the Department in a timely manner by December 30, 2015. If there is no information on the performed actions, a suitable investigation work plans should be submitted to DEC for review and approval no later than January 30, 2016. Please feel free to contact me with your questions or comments. Sincerely, Ainura Doronova Response is due December 30, 2015. AD 11/19/2015: Received the following e-mail from B. Simmons; Hi Ainura, The following presents information regarding NYSDEC Spill No.0907625 - 225 Pennsylvania Avenue, Brooklyn: {we believe your address of 189 Pennsylvania is a mistake, as CFI s site was located at 225 Pennsylvania Avenue}. Spill No. 0907625 was assigned on October 7, 2009 for a tank test failure, resulting from an interstitial failure of the inner wall of the double-walled UST identified as T-4. On October 8, 2009, NYSDEC also assigned a 2nd Spill No. 09-07694 to the same tank failure issue - Attached is the NYSDEC letter Dated 10-9-2009 for the 2nd Spill No. 09-07694; Attached is the ECS Letter to NYSDEC dated November 17, 2009 that describes the testing and re-testing and actions to close the tank in place and indicate no release to the environment occurred and only references Spill No. 09-07694. The NYSDEC used this information to CLOSE Spill No. 09-07694 on November 20, 2009. Also attached, is the UST Closure Summary Report & Closure Request of Spill No. 13-00539, dated 6-4-2013 - documenting the removal of the entire UST system the NYSDEC Closed Spill No. 13-00539 on October 16, 2013. Also, several subsurface investigations and groundwater monitoring events were performed and reported to the NYSDEC under Spill No. 92-11872 during the period 2002-2009. The NYSDEC closed this Spill No. on November 24, 2009. Based on the fact that the circumstances regarding Spill No. 09-07625 assigned on October 7, 2009, is the 1st Spill No. assigned for the same tank failure issue that was assigned a 2nd Spill No. 09-07694 the very next day, and subsequent information was submitted to the NYSDEC who closed that Spill No. on November 17, 2009, ECS believes that Spill No. 09-07625 should also be closed. Please let me know if you have any additional questions or concerns. Thank you. William Simmons Will review. AD 12/04/2015: Reviewed the submitted documentation. According to ECS, spill No. 0907625 was assigned on October 7, 2009 for a tank test failure, resulting from an interstitial failure of the inner wall of the double-walled UST identified as T-4. On the next day, on October 8, 2009, NYSDEC also

CFI STATION #70227 (Continued) **S110045410**

assigned a 2nd Spill No. 09-07694 to the same tank failure issue. Based on the fact that the circumstances regarding Spill No. 09-07625 assigned on October 7, 2009, is the 1st Spill No. assigned for the same tank failure issue that was assigned a 2nd Spill No. 09-07694 the very next day, and subsequent information was submitted to the NYSDEC who closed that Spill No. on November 17, 2009, ECS believes that Spill No. 09-07625 should also be closed. Also, ECS submitted USTs closure report which states that all tanks with associated piping were removed off-site in 2013. End-point soil samples were ND for TVOCs. GW depth at the site greater than 30' bgs. No groundwater was encountered during tanks excavation at the final depth at 15' bgs. This report confirms that no release had occurred from the reported tank test failure. Based on the documentation provided, DEC will close this case. AD 12/09/2015: Issued and sent a spill closure letter to Mr. Johnson of CFI. Case closed. AD

Remarks: Not reported

All Materials:

Site ID:	420161
Operable Unit ID:	1176145
Operable Unit:	01
Material ID:	2168805
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

AQ300 **BUG, BELMONT WORKS** **NY HSWDS** **S105212102**
SSE **BELMONT & ALABAMA AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11207**
0.487 mi.
2569 ft. **Site 1 of 2 in cluster AQ**

Relative:
Lower

Actual:
37 ft.

HSWDS:

Facility ID:	HS2005
Region:	2
Facility Status:	Unknown
Owner Type:	Publ Utily
Owner:	(formerly) Brooklyn Union Gas
Owner Address:	195 Montague Street
Owner Phone:	(718)403-3053
Operator Type:	Unknown
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD980532097
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Brooklyn
Operator City State:	Not reported

BUG, BELMONT WORKS (Continued) **S105212102**

Quadrange:	Unknown
Latitude:	40 40 10 N
Longitude:	73 53 55 W
Acres:	0.00
Operator Date:	mid 1800
Close Date:	1900
Completed:	PA
Active:	Unknown
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	Unknown
Semi Volatile Organic Compounds Disposed:	Unknown
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Unknown
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	Not reported
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	Not reported
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported

BUG, BELMONT WORKS (Continued) **S105212102**

Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AQ301 **BKLYN UNION GAS /BELMONT WORKS** **SEMS-ARCHIVE** **1003863858**
SSE **BELMONT & ALABAMA AVE** **NYD980532097**
1/4-1/2 **BROOKLYN, NY 11207**
0.487 mi.
2569 ft. **Site 2 of 2 in cluster AQ**

Relative:
Lower

Actual:
37 ft.

SEMS Archive:

Site ID:	0201985
EPA ID:	NYD980532097
Name:	BKLYN UNION GAS /BELMONT WORKS
Address:	BELMONT & ALABAMA AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11207
Cong District:	16
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201985
EPA ID:	NYD980532097
Site Name:	BKLYN UNION GAS /BELMONT WORKS
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-24 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201985
EPA ID:	NYD980532097
Site Name:	BKLYN UNION GAS /BELMONT WORKS
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1981-06-01 04:00:00
Finish Date:	1981-06-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

BKLYN UNION GAS /BELMONT WORKS (Continued) **1003863858**

Region:	02
Site ID:	0201985
EPA ID:	NYD980532097
Site Name:	BKLYN UNION GAS /BELMONT WORKS
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-24 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

302
East
1/2-1
0.516 mi.
2726 ft.

LOT 15,TAXBLOCK 3690
2738 ATLANTIC AVENUE
BROOKLYN, NY 11207

NY VCP **S118704098**
NY E DESIGNATION **N/A**
NY NYC LAND USE
NY NYC OER

Relative:
Lower

Actual:
49 ft.

VCP NYC:

Project ID:	22TMP0839K,22EH-N233K,25CVCP004K
Name:	2738 ATLANTIC AVENUE
Address:	2738 ATLANTIC AVE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3036900015
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.676101
Longitude:	-73.89332
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3000000
NTA:	East New York

E DESIGNATION:

Name:	LOT 15,TAXBLOCK 3690
Address:	2738 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	15
Tax Block:	3690
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

LOT 15,TAXBLOCK 3690 (Continued) **S118704098**

NYC LAND USE:

Name:	Not reported
Address:	2738 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6758284
Longitude:	-73.8931435
Type Of Ownership Code:	Not reported
Owner Name:	2738 ATLANTIC AVENUE LLC
Borough:	BK
Tax Block:	3690
Tax Lot:	15
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198002006
Census Tract 2010:	1198
Census Block 2010:	2006
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	C4-4D: Commercial Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2513
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.5000000
Building Frontage:	0.0000000

LOT 15,TAXBLOCK 3690 (Continued) **S118704098**

Building Depth:	0.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	24750.00000
Assessed Total Value:	28755.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	3.40000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3036900015.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1013890
Y Coordinate:	185517
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 012
Tax Map #:	31205
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	2738 ATLANTIC AVENUE
Address:	2738 ATLANTIC AVE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676101
Longitude:	-73.89332
OER Project Numbers:	22TMP0839K,22EH-N233K,25CVCP004K
BBL:	3036900015
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Construction

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3000000
NTA:	East New York

303
SSE
1/2-1
0.523 mi.
2764 ft.

BELMONT STATION
BELMONT, WILLIAMS, ALABAMA AND SUTTER AVES.
BROOKLYN, NY 11207

EDR MGP **1008407879**
N/A

Relative:
Lower

Actual:
37 ft.

EDR MGP:

No additional information available

AR304
East
1/2-1
0.576 mi.
3040 ft.

LOT 18,TAXBLOCK 3946
2776 FULTON STREET
BROOKLYN, NY 11207

Site 1 of 2 in cluster AR

NY VCP **S118704153**
NY E DESIGNATION **N/A**
NY NYC LAND USE
NY NYC OER

Relative:
Lower

Actual:
50 ft.

VCP NYC:

Project ID:	19TMP1818K,19EH-N392K,20CVCP007K
Name:	2776 FULTON STREET
Address:	2776 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,394,600,183,039,400,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Construction
Latitude:	40.677955
Longitude:	-73.892152
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3000000
NTA:	East New York

E DESIGNATION:

Name:	LOT 18,TAXBLOCK 3946
Address:	2776 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	18
Tax Block:	3946
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2776 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6777542
Longitude:	-73.8920336

LOT 18,TAXBLOCK 3946 (Continued) **S118704153**

Type Of Ownership Code:	Not reported
Owner Name:	FULTON PROJECTS LLC
Borough:	BK
Tax Block:	3946
Tax Lot:	18
Community District:	305
Census Tract 2020:	3119800
Census Block 2020:	31198003003
Census Tract 2010:	1198
Census Block 2010:	3003
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	Z9: Miscellaneous - Other
Land Use Category:	Not reported
Number Of Easements:	0
Lot Area:	2500
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	25.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5

LOT 18,TAXBLOCK 3946 (Continued) **S118704153**

Assessed Land Value:	39150.00000
Assessed Total Value:	39150.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039460018.00000000
Condominium Number:	Not reported
Census Tract 2:	1198
X Coordinate:	1014197
Y Coordinate:	186219
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 012
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	2776 FULTON STREET
Address:	2776 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677955
Longitude:	-73.892152
OER Project Numbers:	19TMP1818K,19EH-N392K,20CVCP007K
BBL:	3.0394600183039402E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Construction

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1198
BIN:	3000000
NTA:	East New York

AR305 **LOT 55,TAXBLOCK 3933** **NY VCP** **S118704409**
East **2795 FULTON STREET** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY 11207** **NY NYC LAND USE**
0.612 mi. **NY NYC OER**
3230 ft. **Site 2 of 2 in cluster AR**

Relative:
Lower

Actual:
49 ft.

VCP NYC:

Project ID:	20TMP0836K,20EH-N258K
Name:	2795 FULTON STREET
Address:	2795 FULTON STREET
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3039330055
OER Program:	VCP (Withdrawn), E/RD (Review)
Phase:	Construction
Latitude:	40.678086
Longitude:	-73.89137
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1146
BIN:	3000000
NTA:	Cypress Hills-City Line

E DESIGNATION:

Name:	LOT 55,TAXBLOCK 3933
Address:	2795 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	55
Tax Block:	3933
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	2795 FULTON STREET
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6782861
Longitude:	-73.8914523
Type Of Ownership Code:	Not reported
Owner Name:	2795 FULTON ST LLC
Borough:	BK
Tax Block:	3933
Tax Lot:	55
Community District:	305
Census Tract 2020:	3114600
Census Block 2020:	31146001003
Census Tract 2010:	1146
Census Block 2010:	1003

LOT 55,TAXBLOCK 3933 (Continued) **S118704409**

School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R6A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-6
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V1: Vacant Land - Zoned Commercial Or Manhattan Residential
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	382950.00000
Assessed Total Value:	382950.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.00000000000

LOT 55,TAXBLOCK 3933 (Continued) **S118704409**

Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	3.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039330055.00000000
Condominium Number:	Not reported
Census Tract 2:	1146
X Coordinate:	1014358
Y Coordinate:	186413
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	316 005
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	3039330055.00000000
Apportionment Date:	04/03/2012
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	2795 FULTON STREET
Address:	2795 FULTON STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.678086
Longitude:	-73.89137
OER Project Numbers:	20TMP0836K,20EH-N258K
BBL:	3039330055
OER Program:	VCP (Withdrawn), E/RD (Review)
Class:	Active (A)
Phase:	Construction

URL:

Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1146
BIN:	3000000
NTA:	Cypress Hills-City Line

306
NW
1/2-1
0.637 mi.
3365 ft.

HENRY APARTMENTS SITE B **NY VCP** **S118091678**
8 ROCKAWAY AVENUE **NY MANIFEST** **N/A**
BROOKLYN, NY 11233 **NY NYC OER**

Relative:
Lower

Actual:
67 ft.

VCP NYC:

Project ID:	15TMP0587K,15CVCP120K,15CVCP120K
Name:	HENRY APARTMENTS SITE B - 8 ROCKAWAY AVENUE
Address:	8 ROCKAWAY AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,150,700,323,015,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,000,0
OER Program:	VCP (Enrolled)
Phase:	Completed
Latitude:	40.683362

HENRY APARTMENTS SITE B (Continued) **S118091678**

Longitude:	-73.911657
Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	373
BIN:	3414036
NTA:	Ocean Hill

NY MANIFEST:

EPA ID:	NYR000217901
Country:	USA
Name:	Henry Apartments Site B
Address:	8 ROCKAWAY AVENUE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11233
Zip 4:	Not reported
Location Address 1:	8 ROCKAWAY AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11233
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Henry Apartments Site B
Mailing Contact:	Broadway Decatur Owners Llc
Mailing Address 1:	11 HARPER SQUARE - SUITE 701
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10005
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3477825582

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014570915JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N

HENRY APARTMENTS SITE B (Continued) **S118091678**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	53320
Units:	Pounds
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014570916JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported

HENRY APARTMENTS SITE B (Continued) **S118091678**

Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	47820
Units:	Pounds
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014570917JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	43640
Units:	Pounds

HENRY APARTMENTS SITE B (Continued) **S118091678**

Number of Containers: 1
Container Type: Dump truck
Handling Method: Treat
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/06/2015
Trans1 Recv Date: 05/06/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/06/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000217901
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 014570918JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 44320
Units: Pounds
Number of Containers: 1
Container Type: Dump truck
Handling Method: Treat
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJR000029967
Year: 2018
Trans2 State ID: Not reported

HENRY APARTMENTS SITE B (Continued) **S118091678**

Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014570919JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	47720
Units:	Pounds
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105

HENRY APARTMENTS SITE B (Continued) **S118091678**

TSDF ID 2:	Not reported
Manifest Tracking Number:	014570920JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	48640
Units:	Pounds
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014570921JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

HENRY APARTMENTS SITE B (Continued) **S118091678**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	48900
Units:	Pounds
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/06/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000217901
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014570922JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported

HENRY APARTMENTS SITE B (Continued) **S118091678**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	51320
Units:	Pounds
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Treat
Specific Gravity:	1

NYC OER:

Name:	HENRY APARTMENTS SITE B - 8 ROCKAWAY AVENUE
Address:	8 ROCKAWAY AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.683362
Longitude:	-73.911657
OER Project Numbers:	15TMP0587K,15CVCP120K,15CVCP120K
BBL:	3.0150700323014997E+79
OER Program:	VCP (Enrolled)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	373
BIN:	3414036
NTA:	Ocean Hill

AS307 **LOT 56,TAXBLOCK 1468** **NY E DESIGNATION** **S122872774**
WSW **1900 PARK PLACE** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.668 mi.
3527 ft. **Site 1 of 2 in cluster AS**

Relative:
Lower

Actual:
63 ft.

E DESIGNATION:

Name:	LOT 56,TAXBLOCK 1468
Address:	1900 PARK PLACE
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	56
Tax Block:	1468
Borough Code:	BK
E-No:	E-41
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	89-112K
Ulurp Number:	C920693ZMK
Zoning Map No:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

LOT 56,TAXBLOCK 1468 (Continued) **S122872774**

NYC OER:

Name:	1900 PARK PLACE
Address:	1900 PARK PLACE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.671483
Longitude:	-73.914794
OER Project Numbers:	17TMP0154K,17ENOS093K,17TMP0471K
BBL:	3.0146800633014602E+49
OER Program:	E/RD (No Cleanup)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	363
BIN:	3000000
NTA:	Ocean Hill

NYC LAND USE:

Name:	Not reported
Address:	1900 PARK PLACE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6713010
Longitude:	-73.9145891
Type Of Ownership Code:	X
Owner Name:	THOMAS S. BOYLAND STREET PARK PLACE
Borough:	BK
Tax Block:	1468
Tax Lot:	56
Community District:	316
Census Tract 2020:	3036300
Census Block 2020:	30363003003
Census Tract 2010:	363
Census Block 2010:	3003
School District:	23
City Council District:	41
Fire Company:	L176
Police Precinct:	73
Health Center District:	32
Health Area:	5020
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N

LOT 56,TAXBLOCK 1468 (Continued) **S122872774**

Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	7853
Total Building Floor Area:	20255
Commercial Floor Area:	0
Residential Floor Area:	20255
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	4.0000000
Residential Units:	17
Total Units:	17
Lot Frontage:	158.3900000
Lot Depth:	93.7100000
Building Frontage:	153.5000000
Building Depth:	47.7100000
Extension Code:	Not reported
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	247500.00000
Assessed Total Value:	1728900.00000
Exempt Total Value:	1728900.00000
Year Built:	2017
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.58000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014680056.00000000
Condominium Number:	Not reported
Census Tract 2:	0363
X Coordinate:	1007943
Y Coordinate:	183861
Zoning Map #:	17a
Zoning Map Code:	Y
Sanborn Map #:	307 013
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	3014680063.00000000
Apportionment Date:	07/28/2017
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AS308 **416 THOMAS S. BOYLAND STREET** **NY NYC OER** **S129932420**
WSW **416 THOMAS S. BOYLAND STREET** **N/A**
1/2-1 **BROOKLYN, NY**
0.693 mi.
3659 ft. **Site 2 of 2 in cluster AS**

Relative:
Lower

Actual:
60 ft.

NYC OER:

Name:	416 THOMAS S. BOYLAND STREET
Address:	416 THOMAS S. BOYLAND STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.67101
Longitude:	-73.914128
OER Project Numbers:	17TMP0152K,17ENOS091K
BBL:	3014680063
OER Program:	E/RD (No Cleanup)
Class:	Active (A)
Phase:	Closure
URL:	
Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	363
BIN:	3000000
NTA:	Ocean Hill

---

309 **HENRY APARTMENTS - SITE A - 1676 BROADWAY** **NY VCP** **S129932730**
NW **1676 BROADWAY** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY**
0.710 mi.
3750 ft.

Relative:
Lower

Actual:
60 ft.

VCP NYC:

Project ID:	15TMP0592K,15CVCP148K,15CVCP148K
Name:	HENRY APARTMENTS - SITE A - 1676 BROADWAY
Address:	1676 BROADWAY
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,150,300,293,015,000,000,000,000,000,000,000,000,000,000,000,000
OER Program:	VCP (Enrolled)
Phase:	Completed
Latitude:	40.684159
Longitude:	-73.912683
Postcode:	11207
Community Board:	16
Council District:	41
Census Tract:	373
BIN:	3414048
NTA:	Ocean Hill

NYC OER:

Name:	HENRY APARTMENTS - SITE A - 1676 BROADWAY
Address:	1676 BROADWAY
City,State,Zip:	BROOKLYN, NY
Latitude:	40.684159
Longitude:	-73.912683
OER Project Numbers:	15TMP0592K,15CVCP148K,15CVCP148K
BBL:	3.0150300293015E+49
OER Program:	VCP (Enrolled)

HENRY APARTMENTS - SITE A - 1676 BROADWAY (Continued) **S129932730**

Class: Completed (C)
Phase: Completed

URL:
Postcode: 11207
Community Board: 16
Council District: 41
Census Tract: 373
BIN: 3414048
NTA: Ocean Hill

310
East
1/2-1
0.752 mi.
3972 ft.

2862 FULTON STREET **NY NYC OER** **S132179920**
2862 FULTON STREET **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
41 ft.

NYC OER:
Name: 2862 FULTON STREET
Address: 2862 FULTON STREET
City,State,Zip: BROOKLYN, NY
Latitude: 40.678605
Longitude: -73.888831
OER Project Numbers: 19TMP0585K,19EH-N180K
BBL: 3039500017
OER Program: E/RD (Review)
Class: Completed (C)
Phase: Completed

URL:
Postcode: 11207
Community Board: 5
Council District: 37
Census Tract: 1170
BIN: 3087843
NTA: East New York

311
WSW
1/2-1
0.761 mi.
4017 ft.

1846 PARK PLACE **NY E DESIGNATION** **S108077731**
BROOKLYN, NY 11233 **NY NYC OER** **N/A**
NY NYC LAND USE

Relative:
Higher

Actual:
72 ft.

E DESIGNATION:
Name: LOT 14,TAXBLOCK 1468
Address: 1846 PARK PLACE
City,State,Zip: BROOKLYN, NY
Tax Lot(s): 14
Tax Block: 1468
Borough Code: Not reported
E-No: E-41
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 89-112K
Ulurp Number: C920693ZMK
Zoning Map No: Not reported

(Continued) **S108077731**

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC OER:
Name: 1846 PARK PLACE
Address: 1846 PARK PLACE
City,State,Zip: BROOKLYN, NY
Latitude: 40.671566
Longitude: -73.916341
OER Project Numbers: 20TMP1015K,20ENOS210K
BBL: 3.0146800133014599E+29
OER Program: E/RD (No Cleanup)
Class: Completed (C)
Phase: Completed

URL:
Postcode: 11233
Community Board: 16
Council District: 41
Census Tract: 363
BIN: 3000000
NTA: Ocean Hill

NYC LAND USE:
Name: Not reported
Address: 1846 PARK PLACE
City,State,Zip: BROOKLYN, NY 11233
Latitude: 40.6714312
Longitude: -73.9162724
Type Of Ownership Code: Not reported
Owner Name: 1846 PARK PLACE LLC
Borough: BK
Tax Block: 1468
Tax Lot: 14
Community District: 316
Census Tract 2020: 3036300
Census Block 2020: 30363003002
Census Tract 2010: 363
Census Block 2010: 3004
School District: 23
City Council District: 41
Fire Company: L176
Police Precinct: 73
Health Center District: 32
Health Area: 5020
Sanitation District Boro: 3
Sanitation District Number: 16
Sanitation Subsection: 1B
Zoning District 1: R6: Residential Districts
Zoning District 2: Not reported
Zoning District 3: Not reported
Zoning District 4: Not reported
Commercial Overlay 1: C2-3
Commercial Overlay 2: Not reported
Special Purpose District 1: Not reported
Special Purpose District 2: Not reported

(Continued) **S108077731**

Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	2352
Total Building Floor Area:	5154
Commercial Floor Area:	0
Residential Floor Area:	5154
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	0
Number Of Floors:	4.0000000
Residential Units:	7
Total Units:	7
Lot Frontage:	64.2900000
Lot Depth:	42.7100000
Building Frontage:	64.0000000
Building Depth:	24.0000000
Extension Code:	Not reported
Proximity Code:	2
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	42300.00000
Assessed Total Value:	414450.00000
Exempt Total Value:	0.00000
Year Built:	2022
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.19000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014680014.00000000
Condominium Number:	Not reported
Census Tract 2:	0363
X Coordinate:	1007476
Y Coordinate:	183908
Zoning Map #:	17a
Zoning Map Code:	Not reported
Sanborn Map #:	307 013
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	3014680013.00000000
Apportionment Date:	11/12/2019
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported

(Continued) **S108077731**

2015 Preliminary Flood Insurance Rate Map Indicator: Not reported
Version Number: 24v3.1
Changed By DCP: Not reported

312
East
1/2-1
0.778 mi.
4108 ft.

LOT 11,TAXBLOCK 3965
2864 ATLANTIC AVENUE
BROOKLYN, NY 11207

NY BROWNFIELDS **S118704052**
NY E DESIGNATION **N/A**
NY NYC OER
NY NYC LAND USE

Relative:
Lower

Actual:
39 ft.

BROWNFIELDS:

Name:	2864 ATLANTIC AVENUE REDEVELOPMENT
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Program:	BCP
Site Code:	629738
Acres:	0.415
HW Code:	C224349
SWIS:	2401
Town:	New York City
Record Added Date:	11/24/2021
Record Updated Date:	12/28/2023
Update By:	MSBABICK
Site Description:	Site Location: The 0.415-acre site is located at 2864 Atlantic Avenue in the East New York neighborhood of Brooklyn, NY, and is designated as Brooklyn Tax Block 3965, Lot 11. The site is bounded to the north by Atlantic Avenue, to the east by Jerome Street, to the south by 2-story residential buildings, and to the west by Barbey Street followed by another BCP site (Site No. C224255). The Long Island Railroad (LIRR) is located approximately 40 feet to the north of the site, beneath Atlantic Avenue. Site Features: Construction for a new mixed-use residential/commercial, mixed-income building with a cellar is currently ongoing. Current Zoning and Land Use: The site is zoned R8-A for residential use and includes a commercial C2-4 overlay. The surrounding properties are currently used for commercial, residential, and warehousing/manufacturing purposes. The nearest residential buildings immediately adjoin the Site to the south. The proposed mixed-use commercial/residential development of this property is consistent with the current zoning. As a result of the CEQR process, Block 3965 Lot 11 was assigned an environmental E-Designation (E-366) - East New York Rezoning Action, for hazardous materials, noise (window wall attenuation & alternative means of ventilation), and air (HVAC fuel limited to natural gas) resulting from a City Environmental Quality Review (CEQR) effective 20 April 2016 (CEQR #15DCP102K). Satisfaction of the E-Designation requirements is subject to review and approval by the New York City Mayor’s Office of Environmental Remediation (NYCOER) to obtain a Notice to Proceed (NTP) or a Notice of No Objection (NNO) prior to obtaining building permits. Past Land Use: The site was first developed in the early 1950s with a garage and two gasoline tanks. By 1965, the entire site was occupied by a gas filling station that was developed with an overhead canopy and a one-story office building. The site remained unchanged until 2022 when all on-site fuel tanks were decommissioned and the gas station was demolished as part of the NYSDEC approved Interim Remedial Measures Work Plan (IRMWP). Records for historic bulk petroleum storage (PBS No. 2-297747) list a total of forty-three former underground storage tanks (USTs) for the site. Five additional unregistered USTs were discovered during the 2023

LOT 11,TAXBLOCK 3965 (Continued) **S118704052**

remedial activities and have since been removed. Site Geology and Hydrogeology: As of the 2023 remedial activities, nearly all urban fill has been excavated and removed from the site. The site has been backfilled with approximately 225 tons of 3/4 clean stone from the building foundation sub-base at 13 feet below ground surface (ft-bgs)up to 14 ft-bgs. This layer of clean stone is underlain by a native layer consisting of brown to orange-brown coarse to fine sand with varying amounts of silt and gravel and intermittent clay lenses. Bedrock underlying the site is present at depths greater than 100 ft-bgs and is part of the Raritan formation consisting of unconsolidated coastal plain deposits. Groundwater was encountered at approximately 25 to 35 ft-bgs and groundwater flows to the southeast.

Env Problem:

Remediation at the site is complete. Prior to the 2023 remediation, the primary contaminants of concern for the site were SVOCs and lead in soil, SVOCs and petroleum-related VOCs in groundwater, and petroleum-related VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for Unrestricted Use. Residual contamination remaining in groundwater and soil vapor is being managed under a Site Management Plan. Prior to the 2023 Remediation: Soil One VOC of concern, total xylene, was detected at a maximum concentration of 1.7 parts per million (ppm), exceeding the Unrestricted Use Soil Cleanup Objective (UUSCO) of 0.26 ppm and the Protection of Groundwater Soil Cleanup Objective (PGWSCO) of 1.6 ppm. Several SVOCs were detected at concentrations exceeding the UUSCOs and PGWSCOs, including benzo(a)anthracene (max. 7.1 ppm, UUSCO and PGWSCO is 1 ppm), benzo(b)fluoranthene (max. 8.3 ppm, UUSCO is 1 ppm, PGWSCO is 1.7 ppm), benzo(k)fluoranthene (max. 2.2 ppm, UUSCO is 0.8 ppm, PGWSCO is 1.7 ppm), and chrysene (max. 7.4 ppm, UUSCO and PGWSCO is 1 ppm). For metals in soil, lead was detected at a maximum concentration of 932 ppm (UUSCO is 64 ppm). For PFAS compounds, perfluorooctanesulfonic acid (PFOS) was detected at a maximum concentration of 1.25 parts per billion (ppb), exceeding the guidance value for unrestricted use of 0.88 ppb. Data did not indicate any off-site impacts in soil related to this site. Groundwater Several VOCs were identified in groundwater samples at concentrations above the Ambient Water Quality Standards (AWQSs), including 1,2,4-trimethylbenzene (max. 3,800 ppb, AWQS is 5 ppb), 1,3,5-trimethylbenzene (max. 760 ppb, AWQS is 5 ppb), ethylbenzene (max. 1,500 ppb, AWQS is 5 ppb), o-xylene (max. 1,300 ppb, AWQS is 5 ppb), p/m-xyelene (max. 5,200 ppb, AWQS is 5 ppb), and benzene (max. 22 ppb, AQWS is 1 ppb). Several SVOCs were identified at concentrations exceeding the AWQSs, including benzo(a)anthracene (max. 0.12 ppb, AWQS is 0.002 ppb), benzo(b)fluoranthene (max. 0.18 ppb, AWQS is 0.002 ppb), benzo(k)fluoranthene (max. 0.06 ppb, AWQS is 0.002 ppb), and chrysene (max. 0.13 ppb, AWQS is 0.002 ppb). Several dissolved metals were detected in groundwater, including iron, manganese, and sodium. These are naturally occurring metals and are not considered to be site-related contaminants. PFOS and perfluorooctanoic acid (PFOA) were detected in groundwater at maximum concentrations of 105 parts per trillion (ppt) and 92.1 ppt, respectively. These concentrations exceed the applicable Maximum Contaminant Level (drinking water standard) of 10 ppt each. Data did not indicate any off-site impacts in groundwater-related to this site. Soil Vapor Several petroleum-related VOCs were detected in soil vapor throughout the site, including benzene (max. 69.6 micrograms per cubic meter (ug/m3)), toluene (max. 288 ug/m3), ethylbenzene (max. 34 ug/m3), total xylenes (max. 29.4 ug/m3),

LOT 11,TAXBLOCK 3965 (Continued) **S118704052**

	2,2,4-trimethylpentane (max. 27,200 ug/m3), n-hexane (max. 9,060 ug/m3), 2-butanone (max. 2,140 ug/m3), heptane (max. 1,750 ug/m3), 1,2,4-trimethylbenzene (max. 29.6 ug/m3), and 1,3,5-trimethylbenzene (max. 7.18 ug/m3). Data did not indicate any off-site impacts in soil vapor related to this site.
Health Problem:	Remedial actions are complete and measures are in place to prevent people from coming in contact with remaining contamination at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2022-01-25 12:53:00
Record Upd:	2023-12-12 16:37:00
Updated By:	MSBABICK
Own Op:	6
Sub Type:	P03
Owner Name:	Jacob Kohn
Owner Company:	2864 Atlantic Realty LLC
Owner Address:	40 Oser Avenue, Suite 4
Owner Addr2:	Not reported
Owner City,St,Zip:	Hauppauge, NY 11788
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Jacob Kohn
Owner Company:	2864 Atlantic Realty LLC
Owner Address:	40 Oser Avenue, Suite 4
Owner Addr2:	Not reported
Owner City,St,Zip:	Hauppauge, NY 11788
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Melinda Perkins
Owner Company:	Brooklyn Community Board 5
Owner Address:	127 Pennsylvania Avenue, 2nd Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11207
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Rowshon A. Perveen
Owner Company:	Cypress Hills Library
Owner Address:	1197 Sutter Ave. at Crystal St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11208
Owner Country:	United States of America
HW Code:	C224349
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349

LOT 11,TAXBLOCK 3965 (Continued) **S118704052**

Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	benzene

LOT 11,TAXBLOCK 3965 (Continued) **S118704052**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224349
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	9830002
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2023-08-29 11:26:00
Record Updated:	2023-08-29 11:26:00
Updated By:	MSBABICK
Crossref ID:	C224349-03-22
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2023-08-29 11:24:00
Record Updated:	2023-08-29 11:24:00
Updated By:	MSBABICK
Crossref ID:	2023000304719
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2023-12-04 10:02:00
Record Updated:	2023-12-04 10:02:00
Updated By:	MSBABICK
Crossref ID:	2-297747
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2022-09-22 13:23:00
Record Updated:	2022-09-22 13:23:00
Updated By:	KXLIU

E DESIGNATION:

Name:	LOT 11,TAXBLOCK 3965
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	11
Tax Block:	3965
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Air Quality - HVAC fuel limited to natural gas;Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	2886 ATLANTIC AVENUE

LOT 11,TAXBLOCK 3965 (Continued) **S118704052**

Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.676977
Longitude:	-73.888458
OER Project Numbers:	22TMP0805K,22EHAN181K
BBL:	3039650011
OER Program:	E/RD (Review), State BCP
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1170
BIN:	3327107
NTA:	East New York

NYC LAND USE:

Name:	Not reported
Address:	2864 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6767760
Longitude:	-73.8880767
Type Of Ownership Code:	Not reported
Owner Name:	2864 ATLANTIC REALTY LLC
Borough:	BK
Tax Block:	3965
Tax Lot:	11
Community District:	305
Census Tract 2020:	3117000
Census Block 2020:	31170002006
Census Tract 2010:	1170
Census Block 2010:	2006
School District:	19
City Council District:	37
Fire Company:	L175
Police Precinct:	75
Health Center District:	34
Health Area:	3820
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	1D
Zoning District 1:	R8A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	EC-5
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D7: Elevator Apartments - Semi-Fireproof With Stores
Land Use Category:	Mixed Residential & Commercial Buildings
Number Of Easements:	0

LOT 11,TAXBLOCK 3965 (Continued) **S118704052**

Lot Area:	18111
Total Building Floor Area:	154888
Commercial Floor Area:	16043
Residential Floor Area:	138845
Office Floor Area:	0
Retail Floor Area:	5293
Garage Floor Area:	10750
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	10.0000000
Residential Units:	183
Total Units:	184
Lot Frontage:	200.9200000
Lot Depth:	99.9200000
Building Frontage:	190.0000000
Building Depth:	90.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	448200.00000
Assessed Total Value:	448200.00000
Exempt Total Value:	0.00000
Year Built:	2023
Year Altered 1:	2023
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	8.55000000000
Maximum Allowable Residential Far:	6.02000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3039650011.00000000
Condominium Number:	Not reported
Census Tract 2:	1170
X Coordinate:	1015295
Y Coordinate:	185864
Zoning Map #:	17c
Zoning Map Code:	Not reported
Sanborn Map #:	308 003
Tax Map #:	31302
E-designation Number:	E-366
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

313
SSE
1/2-1
0.801 mi.
4228 ft.

402 SNEDIKER AVENUE
402 SNEDIKER AVENUE
NEW YORK CITY, NY

NY VCP **S129932408**
NY NYC OER **N/A**

Relative:
Lower

Actual:
35 ft.

VCP NYC:

Project ID:	17TMP0373K,17CVCP062K
Name:	402 SNEDIKER AVENUE
Address:	402 SNEDIKER AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3037990026
OER Program:	VCP (Enrolled)
Phase:	Site Management
Latitude:	40.665053
Longitude:	-73.899901
Postcode:	11207
Community Board:	5
Council District:	42
Census Tract:	1132
BIN:	3327032
NTA:	East New York (Pennsylvania Ave)

NYC OER:

Name:	402 SNEDIKER AVENUE
Address:	402 SNEDIKER AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.665053
Longitude:	-73.899901
OER Project Numbers:	17TMP0373K,17CVCP062K
BBL:	3037990026
OER Program:	VCP (Enrolled)
Class:	Completed (C)
Phase:	Site Management

URL:

Postcode:	11207
Community Board:	5
Council District:	42
Census Tract:	1132
BIN:	3327032
NTA:	East New York (Pennsylvania Ave)

314
West
1/2-1
0.822 mi.
4338 ft.

2064 ATLANTIC AVENUE
BROOKLYN, NY 11233

NY E DESIGNATION **S108469629**
NY NYC OER **N/A**
NY NYC LAND USE

Relative:
Higher

Actual:
89 ft.

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 1432
Address:	2064 ATLANTIC AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	1432
Borough Code:	Not reported
E-No:	E-127
Effective Date:	Not reported

(Continued) **S108469629**

Satisfaction Date: Not reported
Ceqr Number: 03DME017K
Ulurp Number: C040124ZMK
Zoning Map No: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.
Lot Remediation Date: Not reported

NYC OER:
Name: 2066 ATLANTIC AVENUE
Address: 2064 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY
Latitude: 40.676797
Longitude: -73.919099
OER Project Numbers: 17TMP0072K,17EHAZ077K
BBL: 3014320001
OER Program: E/RD (Review)
Class: Completed (C)
Phase: Completed

URL:
Postcode: 11233
Community Board: 16
Council District: 41
Census Tract: 303
BIN: 3038523
NTA: Ocean Hill

NYC LAND USE:
Name: Not reported
Address: 2064 ATLANTIC AVENUE
City,State,Zip: BROOKLYN, NY 11233
Latitude: 40.6764726
Longitude: -73.9189628
Type Of Ownership Code: Not reported
Owner Name: BERMUDA REALTY NO 2 LLC
Borough: BK
Tax Block: 1432
Tax Lot: 1
Community District: 316
Census Tract 2020: 3030300
Census Block 2020: 30303003001
Census Tract 2010: 303
Census Block 2010: 3000
School District: 16
City Council District: 41
Fire Company: L176
Police Precinct: 73
Health Center District: 32
Health Area: 5200
Sanitation District Boro: 3
Sanitation District Number: 16
Sanitation Subsection: 1B
Zoning District 1: M1-1: Manufacturing Districts
Zoning District 2: Not reported
Zoning District 3: Not reported

(Continued) **S108469629**

Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	O1: Office Buildings - Office Only ? 1 Story
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	9025
Commercial Floor Area:	9025
Residential Floor Area:	0
Office Floor Area:	9025
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	98.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	157500.00000
Assessed Total Value:	1581300.00000
Exempt Total Value:	83714.00000
Year Built:	1975
Year Altered 1:	2017
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.90000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	1.00000000000
Maximum Allowable Community Facility Far:	2.40000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014320001.00000000
Condominium Number:	Not reported
Census Tract 2:	0303
X Coordinate:	1006728
Y Coordinate:	185744
Zoning Map #:	17a
Zoning Map Code:	Not reported
Sanborn Map #:	307 007
Tax Map #:	30508

(Continued) **S108469629**

E-designation Number:	E-127
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

---

315 WNW 1/2-1 0.903 mi. 4768 ft.

53 MACDOUGAL STREET
53 MACDOUGAL ST
NEW YORK CITY, NY

NY VCP S129932522
NY NYC OER N/A

Relative: Lower

Actual: 60 ft.

VCP NYC:

Project ID:	21TMP0395K,22CVCP065K
Name:	53 MACDOUGAL STREET
Address:	53 MACDOUGAL ST
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3015240043
OER Program:	VCP (Enrolled)
Phase:	Approved Remedial Plan
Latitude:	40.679232
Longitude:	-73.920178
Postcode:	11233
Community Board:	3
Council District:	41
Census Tract:	379
BIN:	3000000
NTA:	Stuyvesant Heights

NYC OER:

Name:	53 MACDOUGAL STREET
Address:	53 MACDOUGAL ST
City,State,Zip:	BROOKLYN, NY
Latitude:	40.679232
Longitude:	-73.920178
OER Project Numbers:	21TMP0395K,22CVCP065K
BBL:	3015240043
OER Program:	VCP (Enrolled)
Class:	Active (A)
Phase:	Approved Remedial Plan

URL:

Postcode:	11233
Community Board:	3
Council District:	41
Census Tract:	379
BIN:	3000000
NTA:	Stuyvesant Heights

316
ESE
1/2-1
0.906 mi.
4786 ft.

LOT 30,TAXBLOCK 3998
2337 PITKIN AVENUE
BROOKLYN, NY 11207

NY VCP **S118704284**
NY E DESIGNATION **N/A**
NY NYC OER

Relative:
Lower

Actual:
34 ft.

VCP NYC:

Project ID:	19TMP2102K,19EH-N449K,20CVCP019K
Name:	2337 PITKIN AVENUE
Address:	2337 PITKIN AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,399,800,303,039,900,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.673349
Longitude:	-73.8861
Postcode:	11207
Community Board:	5
Council District:	37
Census Tract:	1150
BIN:	3392571
NTA:	East New York

E DESIGNATION:

Name:	LOT 30,TAXBLOCK 3998
Address:	2337 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Tax Lot(s):	30
Tax Block:	3998
Borough Code:	BK
E-No:	E-366
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	15DCP102K
Ulurp Number:	N160050ZRK; C160035ZMK
Zoning Map No:	Not reported
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	2337 PITKIN AVENUE
Address:	2337 PITKIN AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.673349
Longitude:	-73.8861
OER Project Numbers:	19TMP2102K,19EH-N449K,20CVCP019K
BBL:	3.0399800303039902E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	
Postcode:	11207
Community Board:	5
Council District:	37

LOT 30,TAXBLOCK 3998 (Continued) **S118704284**

Census Tract: 1150
BIN: 3392571
NTA: East New York

AT317 **K - UNION STATION HOLDER** **NY SHWS** **S109580117**
East **ATLANTIC AVE, ASHFORD ST, LIBERTY AVE** **NY BROWNFIELDS** **N/A**
1/2-1 **BROOKLYN, NY 11207** **NY MGP**
0.910 mi.
4804 ft. **Site 1 of 2 in cluster AT**

Relative: **Lower**
Actual: **34 ft.**

SHWS:
Name: K - UNION STATION HOLDER
Address: ATLANTIC AVE, ASHFORD ST, LIBERTY AVE
City,State,Zip: BROOKLYN, NY 11207
Program: HW
Site Code: 378991
Classification: A
Region: 2
Acres: 1.300
HW Code: 224054
Record Add: 03/27/2007
Record Upd: 07/17/2024
Updated By: GHPRATT
Site Description: Location: The Union Station Holder site is located in an urban area at 2940 Atlantic Avenue in Brooklyn, Kings County. The site is 1.3 acres in size. Site Features: The main site feature is a two-story brick building located in the northeast corner of the site. The rest of the site is covered in asphalt. Current Zoning and Land Use: The site is currently an active Con Edison Service Center, and is zoned for commercial use. The surrounding parcels are currently used for a combination of residential, commercial and manufacturing/industrial. The closest residential area is within 150 feet, due west of the site. Past Use of the Site: The first two gas holders (north and center) were constructed in approximately 1887. The center gas holder was dismantled in 1906, and the north gas holder was dismantled in 1908. The southern holder was constructed in 1908 and operated until approximately 1928, then dismantled around 1950. The site was used as a distribution facility. The Con Edison facility removed two underground storage tanks (USTs) in 1998, and as a result of the impacts found in groundwater and soil, a spill number was assigned (98-06522), and remains open. Site Geology and Hydrogeology: The site is underlain by artificial fill and glacial deposits (outwash sands and gravel). The outwash sand and gravel beneath the site consists of coarse to fine gravel with sand, and ranges from 2 to 250 feet in thickness. The depth to groundwater is approximately 25 to 30 feet below ground surface (bgs), and general flow direction is to the east-southeast.
Env Problem: Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Based upon investigations completed to date, the primary contaminants of concern for the site are VOCs and SVOCs. There have been multiple spills at the site of petroleum products and one spill remains open, associated with the removal of two USTs in 1998. Soil - Total benzene, toluene, ethylbenzene, and xylene (BTEX) ranged from non-detect (ND) to 414 ppm. In addition to BTEX, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and naphthalene were detected at elevated levels, with Total VOC concentrations as high as

K - UNION STATION HOLDER (Continued) **S109580117**

2092 ppm. SVOCs, in the form of polycyclic aromatic hydrocarbons (PAHs), were detected from ND to 928 ppm. Groundwater - Total VOC concentrations were found as high as 1879 ppb, mostly downgradient of the holders. Total PAH concentrations ranged from non-detect to 601 ppb. In 2019, several monitoring wells were sampled for PFAS and 1,4-dioxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 99.5 and 38 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. There were no soil vapor samples collected as part of this investigation.

Health Problem:	The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-20 14:17:00
Record Upd:	2013-10-29 11:19:00
Updated By:	ldennist
Own Op:	1
Sub Type:	E
Owner Name:	Raphael rosenbaum
Owner Company:	Consolidated Edison Company of NY, Inc.
Owner Address:	31-01 20th Avenue - Bldg 136, 2nd Flr
Owner Addr2:	Not reported
Owner City,St,Zip:	long island city, NY 11105
Owner Country:	United States of America
HW Code:	224054
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	9806522
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2017-04-04 14:52:00
Record Updated:	2017-04-04 14:52:00
Updated By:	SXDEYETT

BROWNFIELDS:

Name:	K - UNION STATION HOLDER
Address:	ATLANTIC AVE, ASHFORD ST, LIBERTY AVE
City,State,Zip:	BROOKLYN, NY 11207
Program:	BCP
Site Code:	57390
Acres:	1.300
HW Code:	C224054
SWIS:	2401
Town:	New York City
Record Added Date:	04/30/2004
Record Updated Date:	12/07/2009

K - UNION STATION HOLDER (Continued) **S109580117**

Update By:	MOBARRIE
Site Description:	See Site 224054
Env Problem:	Not reported
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	KEYSPAN
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	Unknown
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

MGP:

Site ID:	224054
Name:	K - UNION STATION HOLDER
Address:	ATLANTIC AVE, ASHFORD ST, LIBERTY AVE
City,State,Zip:	BROOKLYN, NY 11207
Region:	2
Class:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Swis Code:	2401
Town:	New York City
Disp Start:	Not reported
Disp Term:	Not reported
Acres:	1.3
Fuse:	Commercial
Description:	Location: The Union Station Holder site is located in an urban area at 2940 Atlantic Avenue in Brooklyn, Kings County. The site is 1.3 acres in size. Site Features: The main site feature is a two-story brick building located in the northeast corner of the site. The rest

K - UNION STATION HOLDER (Continued) **S109580117**

of the site is covered in asphalt. Current Zoning and Land Use: The site is currently an active Con Edison Service Center, and is zoned for commercial use. The surrounding parcels are currently used for a combination of residential, commercial and manufacturing/industrial. The closest residential area is within 150 feet, due west of the site. Past Use of the Site: The first two gas holders (north and center) were constructed in approximately 1887. The center gas holder was dismantled in 1906, and the north gas holder was dismantled in 1908. The southern holder was constructed in 1908 and operated until approximately 1928, then dismantled around 1950. The site was used as a distribution facility. The Con Edison facility removed two underground storage tanks (USTs) in 1998, and as a result of the impacts found in groundwater and soil, a spill number was assigned (98-06522), and remains open. Site Geology and Hydrogeology: The site is underlain by artificial fill and glacial deposits (outwash sands and gravel). The outwash sand and gravel beneath the site consists of coarse to fine gravel with sand, and ranges from 2 to 250 feet in thickness. The depth to groundwater is approximately 25 to 30 feet below ground surface (bgs), and general flow direction is to the east-southeast.

Assess Env: Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Based upon investigations completed to date, the primary contaminants of concern for the site are VOCs and SVOCs. There have been multiple spills at the site of petroleum products and one spill remains open, associated with the removal of two USTs in 1998. Soil - Total benzene, toluene, ethylbenzene, and xylene (BTEX) ranged from non-detect (ND) to 414 ppm. In addition to BTEX, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and naphthalene were detected at elevated levels, with Total VOC concentrations as high as 2092 ppm. SVOCs, in the form of polycyclic aromatic hydrocarbons (PAHs), were detected from ND to 928 ppm. Groundwater - Total VOC concentrations were found as high as 1879 ppb, mostly downgradient of the holders. Total PAH concentrations ranged from non-detect to 601 ppb. In 2019, several monitoring wells were sampled for PFAS and 1,4-dioxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 99.5 and 38 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. There were no soil vapor samples collected as part of this investigation.

Assess Doh: The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.

Latitude: 40.677222222
Longitude: -73.885555556

318
SSW
1/2-1
0.911 mi.
4812 ft.

305 CHESTER STREET - BUILDING G
305 CHESTER STREET
BROOKLYN, NY

NY NYC OER **S132179930**
N/A

Relative:
Lower

Actual:
32 ft.

NYC OER:

Name:	305 CHESTER STREET - BUILDING G
Address:	305 CHESTER STREET
City,State,Zip:	BROOKLYN, NY
Latitude:	40.664368
Longitude:	-73.910337
OER Project Numbers:	21TMP1187K,21EHAN261K
BBL:	3035600001
OER Program:	E/RD (Review)
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	11212
Community Board:	16
Council District:	41
Census Tract:	924
BIN:	3000000
NTA:	Brownsville

AT319
East
1/2-1
0.912 mi.
4813 ft.

UNION STATION (CITIZENS BRANCH)
ATLANTIC AVE., ASHFORD ST., LIBERTY AVE.
BROOKLYN, NY 11207

Site 2 of 2 in cluster AT

EDR MGP **1008407901**
N/A

Relative:
Lower

Actual:
34 ft.

EDR MGP:

No additional information available

320
South
1/2-1
0.913 mi.
4819 ft.

368 LIVONIA AVENUE
BROOKLYN, NY 11212

NY VCP **S131093842**
NY NYC LAND USE **N/A**
NY NYC OER

Relative:
Lower

Actual:
31 ft.

VCP NYC:

Project ID:	23TMP1096K,25CVCP009K
Name:	368 LIVONIA AVENUE
Address:	368 LIVONIA AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,381,200,193,038,100,000,000,000,000,000,000,000,000,000,000,000,000
OER Program:	VCP (Enrolled)
Phase:	Approved Remedial Plan
Latitude:	40.663281
Longitude:	-73.903901
Postcode:	11212
Community Board:	16
Council District:	42
Census Tract:	918

(Continued) **S131093842**

BIN: 3084851
NTA: Brownsville

NYC LAND USE:

Name:	Not reported
Address:	368 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Latitude:	40.6631350
Longitude:	-73.9038510
Type Of Ownership Code:	C
Owner Name:	NYC HOUSING PRESERVATION AND DEVELOPMENT
Borough:	BK
Tax Block:	3812
Tax Lot:	21
Community District:	316
Census Tract 2020:	3091800
Census Block 2020:	30918002002
Census Tract 2010:	918
Census Block 2010:	2002
School District:	23
City Council District:	41
Fire Company:	E231
Police Precinct:	73
Health Center District:	33
Health Area:	6000
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1A
Zoning District 1:	R7-2: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V1: Vacant Land - Zoned Commercial Or Manhattan Residential
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	1391
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	1
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0

(Continued) **S131093842**

Lot Frontage:	27.0000000
Lot Depth:	51.5000000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	61200.00000
Assessed Total Value:	61200.00000
Exempt Total Value:	61200.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	3.44000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	6.50000000000
Boro Code:	3
Borough, Tax Block and Lot:	3038120021.00000000
Condominium Number:	Not reported
Census Tract 2:	0918
X Coordinate:	1010925
Y Coordinate:	180889
Zoning Map #:	17d
Zoning Map Code:	Not reported
Sanborn Map #:	316 028
Tax Map #:	31207
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	t

NYC OER:

Name:	368 LIVONIA AVENUE
Address:	368 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.663281
Longitude:	-73.903901
OER Project Numbers:	23TMP1096K,25CVCP009K
BBL:	3.0381200193038102E+49
OER Program:	VCP (Enrolled)
Class:	Active (A)
Phase:	Approved Remedial Plan

URL:

Postcode:	11212
Community Board:	16
Council District:	42
Census Tract:	918

(Continued) **S131093842**

BIN: 3084851
NTA: Brownsville

AU321 **19 PRESCOTT PLACE - MWBE SITE B** **NY NYC OER** **S129932127**
West **19 PRESCOTT PLACE** **N/A**
1/2-1 **BROOKLYN, NY**
0.917 mi.
4844 ft. **Site 1 of 3 in cluster AU**

Relative:
Higher

Actual:
75 ft.

NYC OER:
Name: 19 PRESCOTT PLACE - MWBE SITE B
Address: 19 PRESCOTT PLACE
City,State,Zip: BROOKLYN, NY
Latitude: 40.677443
Longitude: -73.920887
OER Project Numbers: 17TMP0331K,17JMPS004K,20EH-N041K
BBL: 3.0155700033015498E+149
OER Program: E/RD (Review), State BCP, Jumpstart
Class: Completed (C)
Phase: Completed

URL:
Postcode: 11233
Community Board: 3
Council District: 41
Census Tract: 301
BIN: 3000000
NTA: Ocean Hill

AV322 **LOT 14,TAXBLOCK 1471** **NY E DESIGNATION** **S108077732**
WSW **1790 STERLING PLACE** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.926 mi.
4889 ft. **Site 1 of 2 in cluster AV**

Relative:
Higher

Actual:
75 ft.

E DESIGNATION:
Name: LOT 14,TAXBLOCK 1471
Address: 1790 STERLING PLACE
City,State,Zip: BROOKLYN, NY 11233
Tax Lot(s): 14
Tax Block: 1471
Borough Code: BK
E-No: E-41
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 89-112K
Ulurp Number: C920693ZMK
Zoning Map No: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC OER:
Name: 1790 STERLING PLACE
Address: 1790 STERLING PLACE
City,State,Zip: BROOKLYN, NY

LOT 14,TAXBLOCK 1471 (Continued) **S108077732**

Latitude:	40.670846
Longitude:	-73.91951
OER Project Numbers:	24TMP0316K,24ENOS069K
BBL:	3.0147100143014699E+69
OER Program:	E/RD (No Cleanup)
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	361
BIN:	3393524
NTA:	Ocean Hill

NYC LAND USE:

Name:	Not reported
Address:	1790 STERLING PLACE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6706044
Longitude:	-73.9192835
Type Of Ownership Code:	O
Owner Name:	NYC PACT PRESERVATION PARTNERS LLC
Borough:	BK
Tax Block:	1471
Tax Lot:	14
Community District:	316
Census Tract 2020:	3036100
Census Block 2020:	30361001001
Census Tract 2010:	361
Census Block 2010:	1001
School District:	23
City Council District:	41
Fire Company:	L176
Police Precinct:	73
Health Center District:	32
Health Area:	5020
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C0: Walk Up Apartments - Three Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	2000
Total Building Floor Area:	1800

LOT 14,TAXBLOCK 1471 (Continued) **S108077732**

Commercial Floor Area:	0
Residential Floor Area:	1800
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	3
Total Units:	3
Lot Frontage:	20.0000000
Lot Depth:	100.0000000
Building Frontage:	20.0000000
Building Depth:	30.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	19860.00000
Assessed Total Value:	30540.00000
Exempt Total Value:	30540.00000
Year Built:	1992
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.90000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014710014.00000000
Condominium Number:	Not reported
Census Tract 2:	0361
X Coordinate:	1006641
Y Coordinate:	183606
Zoning Map #:	17b
Zoning Map Code:	Not reported
Sanborn Map #:	307 050
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AV323 **NY E DESIGNATION** **S108077724**
WSW **497 HOWARD AVENUE** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.938 mi.
4953 ft. **Site 2 of 2 in cluster AV**

Relative:
Higher

Actual:
76 ft.

E DESIGNATION:

Name:	LOT 11,TAXBLOCK 1471
Address:	497 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	11
Tax Block:	1471
Borough Code:	Not reported
E-No:	E-41
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	89-112K
Ulurp Number:	C920693ZMK
Zoning Map No:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	497 HOWARD AVENUE
Address:	497 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.670781
Longitude:	-73.919792
OER Project Numbers:	24TMP0289K,24ENOS070K
BBL:	3.0147100013014699E+89
OER Program:	E/RD (No Cleanup)
Class:	Active (A)
Phase:	Construction
URL:	
Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	361
BIN:	3392621
NTA:	Ocean Hill

NYC LAND USE:

Name:	Not reported
Address:	497 HOWARD AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6707144
Longitude:	-73.9194853
Type Of Ownership Code:	O
Owner Name:	NYC PACT PRESERVATION PARTNERS LLC
Borough:	BK
Tax Block:	1471
Tax Lot:	11
Community District:	316
Census Tract 2020:	3036100
Census Block 2020:	30361001001
Census Tract 2010:	361

(Continued) **S108077724**

Census Block 2010:	1001
School District:	23
City Council District:	41
Fire Company:	L176
Police Precinct:	73
Health Center District:	32
Health Area:	5020
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C0: Walk Up Apartments - Three Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	2775
Total Building Floor Area:	2499
Commercial Floor Area:	0
Residential Floor Area:	2499
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	3
Total Units:	3
Lot Frontage:	27.7500000
Lot Depth:	100.0000000
Building Frontage:	27.7500000
Building Depth:	30.0000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	5
Assessed Land Value:	17340.00000
Assessed Total Value:	48000.00000
Exempt Total Value:	48000.00000
Year Built:	1992
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.90000000000

(Continued) **S108077724**

Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014710011.00000000
Condominium Number:	Not reported
Census Tract 2:	0361
X Coordinate:	1006585
Y Coordinate:	183646
Zoning Map #:	17b
Zoning Map Code:	Not reported
Sanborn Map #:	307 050
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AU324 **LOT 25,TAXBLOCK 1556** **NY VCP** **S108984195**
West **20 PRESCOTT PLACE** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.939 mi. **NY NYC OER**
4958 ft. **Site 2 of 3 in cluster AU**

Relative:
Higher

Actual:
73 ft.

VCP NYC:

Project ID:	18TMP0304K,18EH-N124K,18CVCP064K
Name:	20 PRESCOTT PLACE
Address:	20 PRESCOTT PLACE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	301,556,002,530,155,000,000,000,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.677446
Longitude:	-73.920908
Postcode:	11233
Community Board:	3
Council District:	41
Census Tract:	301
BIN:	3042319
NTA:	Ocean Hill

E DESIGNATION:

Name:	LOT 25,TAXBLOCK 1556
Address:	20 PRESCOTT PLACE
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	25
Tax Block:	1556
Borough Code:	BK
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K

LOT 25,TAXBLOCK 1556 (Continued) **S108984195**

Ulurp Number: C070447ZMK
Zoning Map No: Not reported

Description: Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	20 PRESCOTT PLACE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6773222
Longitude:	-73.9211393
Type Of Ownership Code:	Not reported
Owner Name:	MOR ROSEN LLC
Borough:	BK
Tax Block:	1556
Tax Lot:	25
Community District:	303
Census Tract 2020:	3030100
Census Block 2020:	30301003005
Census Tract 2010:	301
Census Block 2010:	3005
School District:	16
City Council District:	41
Fire Company:	L176
Police Precinct:	81
Health Center District:	32
Health Area:	3600
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	5B
Zoning District 1:	M1-1/R7D: Mixed Manufacturing & Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	MX-10
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D1: Elevator Apartments - Semi-Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	8035
Total Building Floor Area:	43261
Commercial Floor Area:	0
Residential Floor Area:	43261
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2

LOT 25,TAXBLOCK 1556 (Continued) **S108984195**

Number Of Buildings:	1
Number Of Floors:	8.0000000
Residential Units:	49
Total Units:	49
Lot Frontage:	145.7500000
Lot Depth:	90.0000000
Building Frontage:	30.0000000
Building Depth:	145.9000000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	Y
Lot Type:	5
Basement Type/Grade:	0
Assessed Land Value:	361800.00000
Assessed Total Value:	2824200.00000
Exempt Total Value:	2607300.00000
Year Built:	2020
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	5.38000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	1.00000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015560025.00000000
Condominium Number:	Not reported
Census Tract 2:	0301
X Coordinate:	1006124
Y Coordinate:	186053
Zoning Map #:	17a
Zoning Map Code:	Not reported
Sanborn Map #:	307 006
Tax Map #:	30603
E-designation Number:	E-185
Apportionment BBL:	3015560025.00000000
Apportionment Date:	10/26/2017
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	20 PRESCOTT PLACE
Address:	20 PRESCOTT PLACE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677446
Longitude:	-73.920908
OER Project Numbers:	18TMP0304K,18EH-N124K,18CVCP064K
BBL:	3.01556002530155E+29
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

LOT 25,TAXBLOCK 1556 (Continued) **S108984195**

URL:
Postcode: 11233
Community Board: 3
Council District: 41
Census Tract: 301
BIN: 3042319
NTA: Ocean Hill

AW325 **LOT 65,TAXBLOCK 1474** **NY E DESIGNATION** **S108077855**
WSW **1717 LINCOLN PLACE** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.952 mi.
5027 ft. **Site 1 of 4 in cluster AW**

Relative:
Lower

Actual:
61 ft.

E DESIGNATION:
Name: LOT 65,TAXBLOCK 1474
Address: 1717 LINCOLN PLACE
City,State,Zip: BROOKLYN, NY 11233
Tax Lot(s): 65
Tax Block: 1474
Borough Code: BK
E-No: E-41
Effective Date: Not reported
Satisfaction Date: Not reported
Ceqr Number: 89-112K
Ulurp Number: C920693ZMK
Zoning Map No: Not reported

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC OER:
Name: 1717 LINCOLN PLACE
Address: 1717 LINCOLN PL
City,State,Zip: BROOKLYN, NY
Latitude: 40.669098
Longitude: -73.919112
OER Project Numbers: 23TMP0560K,23ENOS091K
BBL: 3014740065
OER Program: E/RD (No Cleanup)
Class: Active (A)
Phase: Closure

URL:
Postcode: 11233
Community Board: 16
Council District: 41
Census Tract: 361
BIN: 3000000
NTA: Ocean Hill

NYC LAND USE:
Name: Not reported
Address: 1717 LINCOLN PLACE
City,State,Zip: BROOKLYN, NY 11233
Latitude: 40.6692592

LOT 65,TAXBLOCK 1474 (Continued) **S108077855**

Longitude:	-73.9188706
Type Of Ownership Code:	Not reported
Owner Name:	HABITAT MOSAIC HOUSING DEVELOPMENT FUND CORP
Borough:	BK
Tax Block:	1474
Tax Lot:	65
Community District:	316
Census Tract 2020:	3036100
Census Block 2020:	30361002007
Census Tract 2010:	361
Census Block 2010:	2000
School District:	23
City Council District:	41
Fire Company:	L176
Police Precinct:	73
Health Center District:	32
Health Area:	5020
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	V0: Vacant Land - Zoned Residential; Not Manhattan
Land Use Category:	Vacant Land
Number Of Easements:	0
Lot Area:	1836
Total Building Floor Area:	0
Commercial Floor Area:	Not reported
Residential Floor Area:	Not reported
Office Floor Area:	Not reported
Retail Floor Area:	Not reported
Garage Floor Area:	Not reported
Storage Floor Area:	Not reported
Factory Floor Area:	Not reported
Other Floor Area:	Not reported
Total Building Floor Area Source Code:	7
Number Of Buildings:	0
Number Of Floors:	Not reported
Residential Units:	0
Total Units:	0
Lot Frontage:	18.0000000
Lot Depth:	106.7500000
Building Frontage:	0.0000000
Building Depth:	0.0000000
Extension Code:	Not reported
Proximity Code:	0
Irregular Lot Code:	Y
Lot Type:	5

LOT 65,TAXBLOCK 1474 (Continued) **S108077855**

Basement Type/Grade:	5
Assessed Land Value:	11820.00000
Assessed Total Value:	11820.00000
Exempt Total Value:	0.00000
Year Built:	0
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.00000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014740065.00000000
Condominium Number:	Not reported
Census Tract 2:	0361
X Coordinate:	1006756
Y Coordinate:	183116
Zoning Map #:	17b
Zoning Map Code:	Not reported
Sanborn Map #:	307 050
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

326
SE
1/2-1
0.960 mi.
5067 ft.

673 LIVONIA AVENUE
673 LIVONIA AVENUE
BROOKLYN, NY 11207

NY SHWS **S129982655**
NY NYC LAND USE **N/A**

Relative:
Lower

Actual:
29 ft.

SHWS:

Name:	673 LIVONIA AVENUE
Address:	673 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Program:	HW
Site Code:	631213
Classification:	P
Region:	2
Acres:	0.230
HW Code:	224352
Record Add:	01/24/2022
Record Upd:	07/16/2024
Updated By:	CXMAYCOC

Site Description: Location: The 0.23-acre site is located at 673 Livonia Avenue in Brooklyn, Kings County, NY in an urban area. Site Features: The site currently consists of a vacant, 8,300 square foot, one-story, slab-on-grade, concrete warehouse building with a concrete driveway to the north. A former UST below the northwest corner of the driveway was closed and removed sometime prior to 1991. Current Zoning and Land Use: The site is currently zoned as R6 (medium-density residence

673 LIVONIA AVENUE (Continued) **S129982655**

district) with a C2-3 (local retail/service district) overlay and is surrounded by other residential and retail commercial parcels. The site is bound to the north by Dumont Avenue, to the east by Wyona Street, to the south by Livonia Avenue as well as the MTA 2 and 3 aboveground subway lines, and to the west by Vermont Street. Past Use of the Site: The current building was constructed between 1954 1966 and was most recently occupied by Fleetwood Cabinet Co for furniture manufacturing and spray-painting operations from 1985 2017. Historical on-site uses include a knitting mill, textile processing, and dry-cleaning. Site reconnaissance during June 2021 observed a vent pipe reportedly connected to an out-of-service 2,500-gallon #2 fuel oil UST under the northern driveway. An empty 55-gallon drum and two active 250-gallon aboveground storage tanks were observed inside the building as well as evidence of spray-painting on the walls and floor slab in the southeast corner. Site Geology and Hydrogeology: Sub-surface samples collected in June 2021 identified soil consisting of red-brown sand and brown sandy silt. Groundwater was encountered at approximately 22.5 feet below grade and flows at a slight gradient (0.001 ft/ft) to the southeast.

Env Problem: Nature and Extent of Contamination: SOIL No VOCs were detected at concentrations exceeding the applicable protection of groundwater soil cleanup objectives (PGSCO). PCE was detected at a maximum concentration of 0.17 parts per million (ppm) compared to the PGSCO of 1.3 ppm, and TCE at a maximum concentration of 0.11 ppm (PGSCO is 0.47 ppm). One SVOC, benzo(a)pyrene, was identified as exceeding the restricted commercial (RC) SCO of 1 ppm at a maximum of 1.69 ppm. One RCRA metal, barium, was detected at a maximum concentration of 723 ppm (RCSCO is 400 ppm). GROUNDWATER PCE was detected at concentrations exceeding the applicable Ambient Water Quality Standard (AWQS) of 5 parts per billion (ppb) at a maximum concentration of 8.98 ppb. Chloroform was detected at a maximum of 28 ppb (AWQS is 7 ppb). Detected TCE concentrations did not exceed the AWQS of 5 ppb at a maximum of 0.95 ppb. PFOS was detected at a maximum concertation of 0.0747 ppb (AWQS is 0.01 ppb) and PFOA at a maximum of 0.0635 ppb (AWQS is 0.01 ppb). SOIL VAPOR PCE and TCE were detected at maximum concentrations of 180,000 micrograms per cubic meter (ug/m3) and 52,700 ug/m3, respectively. Additionally, the degradation compounds cis-1,2-dichloroethene and trans-1,2-dicholorethene were detected at maximum concentrations of 16,500 ug/m3 and 1,870 ug/m3. Several petroleum-related VOCs were also detected, including benzene (max. 94 ug/m3), toluene (max. 1,800 ug/m3), ethylbenzene (max. 170 ug/m3), and total xylene (max. 800 ug/m3). --- Significant Threat: No evaluation has been made thus far to determine if the contaminants represent a significant environmental threat.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

673 LIVONIA AVENUE (Continued) **S129982655**

Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	ElderServe Health, Inc.
Owner Address:	80 West 225th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Bronx, NY 10463
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	673 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11207
Latitude:	40.6653147
Longitude:	-73.8919023
Type Of Ownership Code:	X
Owner Name:	ELDERSERVE HEALTH, INC.
Borough:	BK
Tax Block:	3808
Tax Lot:	1
Community District:	305
Census Tract 2020:	3112600
Census Block 2020:	31126001001
Census Tract 2010:	1126
Census Block 2010:	1001
School District:	19
City Council District:	42
Fire Company:	L103
Police Precinct:	75
Health Center District:	33
Health Area:	6300
Sanitation District Boro:	3
Sanitation District Number:	05
Sanitation Subsection:	4D
Zoning District 1:	R6: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-3
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported

673 LIVONIA AVENUE (Continued) **S129982655**

Spill Boundary Indicator:	N
Building Class:	F5: Factory And Industrial Buildings - Light Manufacturing
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	10000
Total Building Floor Area:	8300
Commercial Floor Area:	8300
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	8300
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.0000000
Lot Depth:	100.0000000
Building Frontage:	83.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	81000.00000
Assessed Total Value:	403200.00000
Exempt Total Value:	403200.00000
Year Built:	1930
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.83000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3038080001.00000000
Condominium Number:	Not reported
Census Tract 2:	1126
X Coordinate:	1014239
Y Coordinate:	181687
Zoning Map #:	17d
Zoning Map Code:	Not reported
Sanborn Map #:	316 032
Tax Map #:	31207
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1

673 LIVONIA AVENUE (Continued) **S129982655**

Changed By DCP: Not reported

AU327 **LOT 3,TAXBLOCK 1556** **NY VCP** **S108984220**
West **335 RALPH AVENUE** **NY E DESIGNATION** **N/A**
1/2-1 **BROOKLYN, NY** **NY NYC LAND USE**
0.960 mi. **NY NYC OER**
5069 ft. **Site 3 of 3 in cluster AU**

Relative:
Higher

Actual:
70 ft.

VCP NYC:

Project ID:	17TMP0084K,17EH-N064K,21CVCP031K
Name:	335 RALPH AVENUE
Address:	335 RALPH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3015560003
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.677644
Longitude:	-73.921745
Postcode:	11233
Community Board:	3
Council District:	41
Census Tract:	301
BIN:	3000000
NTA:	Ocean Hill

E DESIGNATION:

Name:	LOT 3,TAXBLOCK 1556
Address:	335 RALPH AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	3
Tax Block:	1556
Borough Code:	Not reported
E-No:	E-185
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	07DCP070K
Ulurp Number:	C070447ZMK
Zoning Map No:	Not reported
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	335 RALPH AVENUE
City,State,Zip:	BROOKLYN, NY 11233
Latitude:	40.6774734
Longitude:	-73.9214924
Type Of Ownership Code:	X
Owner Name:	NYC PARTNERSHIP HOUSING DEVELOPMENT FUND COMPANY,
Borough:	BK
Tax Block:	1556
Tax Lot:	3
Community District:	303
Census Tract 2020:	3030100

LOT 3,TAXBLOCK 1556 (Continued) **S108984220**

Census Block 2020:	30301003005
Census Tract 2010:	301
Census Block 2010:	3005
School District:	16
City Council District:	41
Fire Company:	L176
Police Precinct:	81
Health Center District:	32
Health Area:	3600
Sanitation District Boro:	3
Sanitation District Number:	03
Sanitation Subsection:	5B
Zoning District 1:	M1-1/R7D: Mixed Manufacturing & Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	MX-10
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	D3: Elevator Apartments - Fireproof (Without Stores)
Land Use Category:	Multi-Family Elevator Buildings
Number Of Easements:	0
Lot Area:	3060
Total Building Floor Area:	13003
Commercial Floor Area:	0
Residential Floor Area:	13003
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	7.0000000
Residential Units:	13
Total Units:	13
Lot Frontage:	34.0000000
Lot Depth:	90.0000000
Building Frontage:	34.0000000
Building Depth:	58.3300000
Extension Code:	N
Proximity Code:	3
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	2
Assessed Land Value:	110250.00000
Assessed Total Value:	472950.00000
Exempt Total Value:	472950.00000
Year Built:	2022
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported

LOT 3,TAXBLOCK 1556 (Continued) **S108984220**

Landmark Status:	Not reported
Built Floor Area Ratio:	4.25000000000
Maximum Allowable Residential Far:	4.20000000000
Maximum Allowable Commercial Far:	1.00000000000
Maximum Allowable Community Facility Far:	4.20000000000
Boro Code:	3
Borough, Tax Block and Lot:	3015560003.00000000
Condominium Number:	Not reported
Census Tract 2:	0301
X Coordinate:	1006026
Y Coordinate:	186108
Zoning Map #:	17a
Zoning Map Code:	Not reported
Sanborn Map #:	307 006
Tax Map #:	30603
E-designation Number:	E-185
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

NYC OER:

Name:	335 RALPH AVENUE
Address:	335 RALPH AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.677644
Longitude:	-73.921745
OER Project Numbers:	17TMP0084K,17EH-N064K,21CVCP031K
BBL:	3015560003
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed

URL:

Postcode:	11233
Community Board:	3
Council District:	41
Census Tract:	301
BIN:	3000000
NTA:	Ocean Hill

AW328 **LOT 23,TAXBLOCK 1476** **NY E DESIGNATION** **S108077754**
WSW **1319 EAST NEW YORK AVENUE** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY 11212** **NY NYC LAND USE**
0.961 mi.
5074 ft. **Site 2 of 4 in cluster AW**

Relative:
Lower

Actual:
57 ft.

E DESIGNATION:

Name:	LOT 23,TAXBLOCK 1476
Address:	1319 EAST NEW YORK AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Tax Lot(s):	23
Tax Block:	1476
Borough Code:	BK

LOT 23,TAXBLOCK 1476 (Continued) **S108077754**

E-No:	E-41
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	89-112K
Ulurp Number:	C920693ZMK
Zoning Map No:	Not reported
Description:	Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

NYC OER:

Name:	1319 EAST NEW YORK AVENUE
Address:	1319 EAST NEW YORK AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.668796
Longitude:	-73.918878
OER Project Numbers:	22TMP1292K,22ENOS294K
BBL:	3014760023
OER Program:	E/RD (No Cleanup)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	11212
Community Board:	16
Council District:	41
Census Tract:	361
BIN:	3039582
NTA:	Ocean Hill

NYC LAND USE:

Name:	Not reported
Address:	1319 EAST NEW YORK AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Latitude:	40.6689710
Longitude:	-73.9188313
Type Of Ownership Code:	Not reported
Owner Name:	LINCOLN RESIDENCE NY LLC
Borough:	BK
Tax Block:	1476
Tax Lot:	23
Community District:	316
Census Tract 2020:	3036100
Census Block 2020:	30361002006
Census Tract 2010:	361
Census Block 2010:	2002
School District:	23
City Council District:	41
Fire Company:	L176
Police Precinct:	73
Health Center District:	32
Health Area:	5020
Sanitation District Boro:	3
Sanitation District Number:	16
Sanitation Subsection:	1B
Zoning District 1:	R6: Residential Districts

LOT 23,TAXBLOCK 1476 (Continued) **S108077754**

Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C1: Walk Up Apartments - Over Six Families Without Stores
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	3515
Total Building Floor Area:	8711
Commercial Floor Area:	0
Residential Floor Area:	8711
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	11
Total Units:	11
Lot Frontage:	102.1700000
Lot Depth:	68.6700000
Building Frontage:	67.0000000
Building Depth:	58.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	4
Basement Type/Grade:	2
Assessed Land Value:	55350.00000
Assessed Total Value:	116100.00000
Exempt Total Value:	0.00000
Year Built:	2022
Year Altered 1:	2022
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	2.48000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014760023.00000000
Condominium Number:	Not reported
Census Tract 2:	0361
X Coordinate:	1006767
Y Coordinate:	183011
Zoning Map #:	17b
Zoning Map Code:	Not reported

LOT 23,TAXBLOCK 1476 (Continued) **S108077754**

Sanborn Map #:	307 050
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	24v3.1
Changed By DCP:	Not reported

AW329 **1470 EASTERN PARKWAY** **NY NYC OER** **S129932052**
WSW **1470 EASTERN PARKWAY** **N/A**
1/2-1 **BROOKLYN, NY**
0.980 mi.
5175 ft. **Site 3 of 4 in cluster AW**

Relative:
Lower

Actual:
66 ft.

NYC OER:

Name:	1470 EASTERN PARKWAY
Address:	1470 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY
Latitude:	40.669625
Longitude:	-73.919577
OER Project Numbers:	19TMP1220K,19ENOS267K
BBL:	3014740007
OER Program:	E/RD (No Cleanup)
Class:	Completed (C)
Phase:	Completed
URL:	
Postcode:	11233
Community Board:	16
Council District:	41
Census Tract:	361
BIN:	Not reported
NTA:	Ocean Hill

AW330 **LOT 5,TAXBLOCK 1474** **NY E DESIGNATION** **S108470054**
WSW **1464 EASTERN PARKWAY** **NY NYC OER** **N/A**
1/2-1 **BROOKLYN, NY 11233** **NY NYC LAND USE**
0.986 mi.
5204 ft. **Site 4 of 4 in cluster AW**

Relative:
Lower

Actual:
65 ft.

E DESIGNATION:

Name:	LOT 5,TAXBLOCK 1474
Address:	1464 EASTERN PARKWAY
City,State,Zip:	BROOKLYN, NY 11233
Tax Lot(s):	5
Tax Block:	1474
Borough Code:	BK
E-No:	E-41
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	89-112K
Ulurp Number:	C920693ZMK
Zoning Map No:	Not reported

LOT 5,TAXBLOCK 1474 (Continued) **S108470054**

Description: Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date: Not reported

NYC OER:
Name: 1464 EASTERN PARKWAY - DOB JOB NO. A2 - 340344684
Address: 1464 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY
Latitude: 40.669579
Longitude: -73.919692
OER Project Numbers: 16TMP0047Q,16ENOS041K
BBL: 3014740005
OER Program: E/RD (No Cleanup)
Class: Active (A)
Phase: Closure

URL:
Postcode: 11233
Community Board: 16
Council District: 41
Census Tract: 361
BIN: 3039520
NTA: Ocean Hill

NYC LAND USE:
Name: Not reported
Address: 1464 EASTERN PARKWAY
City,State,Zip: BROOKLYN, NY 11233
Latitude: 40.6692982
Longitude: -73.9196348
Type Of Ownership Code: Not reported
Owner Name: SMITH, MONICA
Borough: BK
Tax Block: 1474
Tax Lot: 5
Community District: 316
Census Tract 2020: 3036100
Census Block 2020: 30361002000
Census Tract 2010: 361
Census Block 2010: 2000
School District: 23
City Council District: 41
Fire Company: L176
Police Precinct: 73
Health Center District: 32
Health Area: 5020
Sanitation District Boro: 3
Sanitation District Number: 16
Sanitation Subsection: 1B
Zoning District 1: R6: Residential Districts
Zoning District 2: Not reported
Zoning District 3: Not reported
Zoning District 4: Not reported
Commercial Overlay 1: Not reported
Commercial Overlay 2: Not reported
Special Purpose District 1: Not reported
Special Purpose District 2: Not reported

LOT 5,TAXBLOCK 1474 (Continued) **S108470054**

Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	B1: Two Family Dwellings - Brick
Land Use Category:	One & Two Family Buildings
Number Of Easements:	0
Lot Area:	1882
Total Building Floor Area:	3300
Commercial Floor Area:	0
Residential Floor Area:	3300
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	2
Number Of Floors:	3.0000000
Residential Units:	2
Total Units:	2
Lot Frontage:	22.0000000
Lot Depth:	86.1700000
Building Frontage:	22.0000000
Building Depth:	62.0000000
Extension Code:	G
Proximity Code:	3
Irregular Lot Code:	Y
Lot Type:	4
Basement Type/Grade:	2
Assessed Land Value:	20520.00000
Assessed Total Value:	79320.00000
Exempt Total Value:	0.00000
Year Built:	1899
Year Altered 1:	2016
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.75000000000
Maximum Allowable Residential Far:	2.43000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3014740005.00000000
Condominium Number:	Not reported
Census Tract 2:	0361
X Coordinate:	1006544
Y Coordinate:	183130
Zoning Map #:	17b
Zoning Map Code:	Not reported
Sanborn Map #:	307 050
Tax Map #:	30509
E-designation Number:	E-41
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported

LOT 5,TAXBLOCK 1474 (Continued) **S108470054**

2015 Preliminary Flood Insurance Rate Map Indicator: Not reported
Version Number: 24v3.1
Changed By DCP: Not reported

---

331 SSW 1/2-1 0.994 mi. 5250 ft. **FORMER SEP S CLEANERS** **NY SHWS** **S127478102**
242-288 LIVONIA AVENUE **NY ENG CONTROLS** **N/A**
BROOKLYN, NY 11212 **NY INST CONTROL**

Relative: Lower
Actual: 27 ft.

SHWS:
Name: FORMER SEP S CLEANERS
Address: 242-288 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11212
Program: HW
Site Code: 576845
Classification: P
Region: 2
Acres: 0.566
HW Code: 224283
Record Add: 09/06/2018
Record Upd: 03/11/2021
Updated By: JHOCONNE
Site Description: Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.
Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted

FORMER SEP S CLEANERS (Continued) **S127478102**

Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: christon harris
Owner Company: the community preservation corporation
Owner Address: 220 East 42nd Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

ENG CONTROLS:
Name: FORMER SEP S CLEANERS
Address: 242-288 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11212

FORMER SEP S CLEANERS (Continued) **S127478102**

Site Code:	576845
HW Code:	224283
Control Code:	15
Control Type:	ENG
Date Record Added:	10/10/2023
Date Rec Updated:	03/21/2024
Updated By:	MCSALAZA
Site Description:	Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.
Env Problem:	Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air

FORMER SEP S CLEANERS (Continued) **S127478102**

	sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	christon harris
Owner Company:	the community preservation corporation
Owner Address:	220 East 42nd Street, 16th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Name:	FORMER SEP S CLEANERS
Address:	242-288 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Site Code:	576845
HW Code:	224283
Control Code:	13
Control Type:	ENG
Date Record Added:	10/10/2023
Date Rec Updated:	03/21/2024
Updated By:	MCSALAZA
Site Description:	Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and

FORMER SEP S CLEANERS (Continued) **S127478102**

other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.

Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

FORMER SEP S CLEANERS (Continued) **S127478102**

Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	christon harris
Owner Company:	the community preservation corporation
Owner Address:	220 East 42nd Street, 16th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

INST CONTROL:

Name:	FORMER SEP S CLEANERS
Address:	242-288 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Site Code:	576845
Control Name:	O&M Plan
HW Code:	224283
Control Code:	33
Control Type:	INST
Dt record added:	10/10/2023
Dt rec updated:	03/21/2024
Updated By:	MCSALAZA
Site Code:	576845
Site Description:	Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt

FORMER SEP S CLEANERS (Continued) **S127478102**

and gravel. The water table is located some 20 feet below grade.

Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: christon harris
Owner Company: the community preservation corporation
Owner Address: 220 East 42nd Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported

FORMER SEP S CLEANERS (Continued) **S127478102**

Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: FORMER SEP S CLEANERS
Address: 242-288 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11212
Site Code: 576845
Control Name: Environmental Easement
HW Code: 224283
Control Code: J
Control Type: INST
Dt record added: 10/10/2023
Dt rec updated: 03/21/2024
Updated By: MCSALAZA
Site Code: 576845
Site Description: Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.
Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from

FORMER SEP S CLEANERS (Continued) **S127478102**

20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: christon harris
Owner Company: the community preservation corporation
Owner Address: 220 East 42nd Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: FORMER SEP S CLEANERS
Address: 242-288 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11212
Site Code: 576845
Control Name: Ground Water Use Restriction

FORMER SEP S CLEANERS (Continued) **S127478102**

HW Code: 224283
Control Code: 08
Control Type: INST
Dt record added: 10/10/2023
Dt rec updated: 03/21/2024
Updated By: MCSALAZA
Site Code: 576845
Site Description: Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.
Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air

FORMER SEP S CLEANERS (Continued) **S127478102**

	sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	christon harris
Owner Company:	the community preservation corporation
Owner Address:	220 East 42nd Street, 16th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Name:	FORMER SEP S CLEANERS
Address:	242-288 LIVONIA AVENUE
City,State,Zip:	BROOKLYN, NY 11212
Site Code:	576845
Control Name:	Monitoring Plan
HW Code:	224283
Control Code:	31
Control Type:	INST
Dt record added:	10/10/2023
Dt rec updated:	03/21/2024
Updated By:	MCSALAZA
Site Code:	576845
Site Description:	Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building

FORMER SEP S CLEANERS (Continued) **S127478102**

contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.

Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported

FORMER SEP S CLEANERS (Continued) **S127478102**

Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: christon harris
Owner Company: the community preservation corporation
Owner Address: 220 East 42nd Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: FORMER SEP S CLEANERS
Address: 242-288 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11212
Site Code: 576845
Control Name: Site Management Plan
HW Code: 224283
Control Code: 32
Control Type: INST
Dt record added: 10/10/2023
Dt rec updated: 03/21/2024
Updated By: MCSALAZA
Site Code: 576845
Site Description: Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone

FORMER SEP S CLEANERS (Continued) **S127478102**

generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.

Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: christon harris
Owner Company: the community preservation corporation
Owner Address: 220 East 42nd Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: Not reported

FORMER SEP S CLEANERS (Continued) **S127478102**

Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: FORMER SEP S CLEANERS
Address: 242-288 LIVONIA AVENUE
City,State,Zip: BROOKLYN, NY 11212
Site Code: 576845
Control Name: IC/EC Plan
HW Code: 224283
Control Code: 34
Control Type: INST
Dt record added: 10/10/2023
Dt rec updated: 03/21/2024
Updated By: MCSALAZA
Site Code: 576845
Site Description: Location: The 24,645 square feet (0.566 acre) site is located at 242-288 Livonia Avenue in the Borough of Brooklyn, Kings County, NY in an urban area. Site Features: The Site is occupied by a strip mall with several commercial tenants. The former dry cleaner tenant space is now occupied by a deli. The deli is the westernmost unit. Other tenants on the site include a Chinese take-out restaurant, a pizza restaurant, a check cashing business and a supermarket. The building contains a basement below the units. Current Zoning and Land Use: The site is currently zoned as R-6 and is surrounded by residential and other commercial parcels. The site is bounded on the north by Livonia Avenue, to the east by two high-rise residential buildings, to the south by the rear driveway for the strip mall and a parking lot, and to the west by Rockaway Avenue. Past Use of the Site: A portion of the site was previously occupied by Sep s Cleaners (250 Livonia Avenue) which performed dry cleaning operations and was listed as a Resource Conservation and Recovery Act Small Quantity Generator of spent halogenated wastes. Site Geology and Hydrogeology: The Site-specific vadose zone geology generally consists of brown to dark brown medium-grained sand with occasional silt, minor and sporadic clay, and, in the shallower soil, some fill materials including brick and wood fragments. The Site-specific geology in the saturated zone generally consists of brown medium-grained sand with occasional silt and gravel. The water table is located some 20 feet below grade.
Env Problem: Nature and Extent of Contamination: Soil Soil samples taken from 16 locations in the alleyway at the rear of the Site revealed elevated concentrations of tetrachloroethylene (PCE) in an area approximately 30 feet long by the width of the alleyway. The highest concentration of PCE was 370 ppm and concentrations ranged from 0.057 ppm to 2.8 ppm at depth (16-20 ft-bgs) and 0.3 to 370 ppm in the shallow sample (0-6 ft-bgs) compared to the Unrestricted Use SCO of 1.3 ppm. In addition, a second smaller hot spot area was delineated directly east of the primary hot spot where the maximum concentration of PCE was 4.2 ppm. The breakdown products of PCE were detected in the soil but not at significant concentrations. One sample was analyzed for SVOCs, PCBs and pesticides, but none were detected above the Unrestricted

FORMER SEP S CLEANERS (Continued) **S127478102**

Use SCOs. Groundwater Geoprobe groundwater samples were obtained from 20 locations. These locations were within the soil hot spot area, and up-, side- and down-gradient of the hot spots. The sampling results were grouped by depth as shallow (20-22 ft-bgs), intermediate (30-32 ft-bgs) and deep (40-42 ft-bgs). The analytical results showed that a groundwater plume, defined by concentrations of PCE combined with its breakdown products exceeding 100 parts per billion (ppb), emanates from the area of soil contamination mentioned above and advances in the downgradient direction. The highest concentration detected was 39,000 ppb in the shallow groundwater and 2,500 ppb at depth in the same location which corresponds with the area of soil contamination. Soil Vapor PCE and cis-1,2-dichloroethene were detected at up to 140,000 (PCE) and 14,678 g/m3 (DCE) in the sub-slab vapor of the basements in the on-site building. Remediation at the site is ongoing under a Stipulation Agreement (see spill no. 0712821). An air sparging/soil vapor extraction system has been operating on the site since July 2014 and has resulted in improvement to the contaminant concentrations. Site Management will be tracked under this site number.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: christon harris
Owner Company: the community preservation corporation
Owner Address: 220 East 42nd Street, 16th Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10017
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Count: 4 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S113922095	UNION STATION (CITIZENS BRANCH)	ATLANTIC AVE, ASHFORD ST, LIBE	11207	NY VCP
BROOKLYN	S113922098	BELMONT STATION	BELMONT, WILLIAMS, ALABAMA & S	11207	NY VCP
BROOKLYN	1015735576	PENNSYLAVANIA AVE MUNICIPAL LANDFI	PENNSYLVANIA AVE - SHORE PKWY	11207	SEMS-ARCHIVE, RCRA NonGen / NL
FLUSHING	S127586981	COMMERCIAL	59-20 VAN DOREN ST		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: EPA
Telephone: N/A
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/20/2024
Date Data Arrived at EDR: 12/18/2024
Date Made Active in Reports: 12/20/2024
Number of Days to Update: 2

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/18/2024
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 11/11/2024
Date Data Arrived at EDR: 11/25/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 85

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 03/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/15/2024
Date Made Active in Reports: 02/11/2025
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/18/2025
Next Scheduled EDR Contact: 12/02/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/15/2024
Date Made Active in Reports: 02/11/2025
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/18/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/03/2024
Date Data Arrived at EDR: 12/11/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 69

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/11/2024
Date Data Arrived at EDR: 12/17/2024
Date Made Active in Reports: 12/27/2024
Number of Days to Update: 10

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/17/2024
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/11/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 05/07/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 11/03/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 12/05/2024
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 08/12/2024
Date Data Arrived at EDR: 10/30/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 76

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 12/23/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/12/2024
Date Data Arrived at EDR: 12/12/2024
Date Made Active in Reports: 02/28/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/12/2024
Next Scheduled EDR Contact: 03/31/2025
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/12/2024
Date Data Arrived at EDR: 12/12/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/12/2024
Next Scheduled EDR Contact: 03/31/2025
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/12/2024
Date Data Arrived at EDR: 12/12/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/12/2024
Next Scheduled EDR Contact: 03/31/2025
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/12/2024
Date Data Arrived at EDR: 12/12/2024
Date Made Active in Reports: 02/28/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/12/2024
Next Scheduled EDR Contact: 03/31/2025
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/11/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 07/29/2024
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/28/2024
Number of Days to Update: 90

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/12/2024
Date Data Arrived at EDR: 12/12/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 12/12/2024
Next Scheduled EDR Contact: 03/31/2025
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 12/06/2024
Date Data Arrived at EDR: 12/11/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 82

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/13/2025
Next Scheduled EDR Contact: 06/23/2025
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 12/04/2024
Date Data Arrived at EDR: 12/09/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 84

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/11/2025
Next Scheduled EDR Contact: 06/23/2025
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/12/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 12/02/2024
Date Data Arrived at EDR: 12/04/2024
Date Made Active in Reports: 02/25/2025
Number of Days to Update: 83

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/04/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024
Date Data Arrived at EDR: 09/11/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/12/2025
Next Scheduled EDR Contact: 06/23/2025
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/11/2024
Date Data Arrived at EDR: 12/17/2024
Date Made Active in Reports: 12/27/2024
Number of Days to Update: 10

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/17/2024
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 02/26/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 12/09/2024
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/20/2024
Date Data Arrived at EDR: 08/19/2024
Date Made Active in Reports: 10/09/2024
Number of Days to Update: 51

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/20/2024
Date Data Arrived at EDR: 08/19/2024
Date Made Active in Reports: 10/09/2024
Number of Days to Update: 51

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 10/28/2024
Date Data Arrived at EDR: 10/29/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 85

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/10/2024
Date Data Arrived at EDR: 12/11/2024
Date Made Active in Reports: 02/27/2025
Number of Days to Update: 78

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 11/03/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 12/05/2024
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 10/01/2024
Date Data Arrived at EDR: 11/12/2024
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 70

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/11/2025
Next Scheduled EDR Contact: 05/26/2025
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/07/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 12/30/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/03/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 01/27/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 01/30/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/10/2025
Next Scheduled EDR Contact: 06/23/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/11/2025
Next Scheduled EDR Contact: 05/26/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/15/2024
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/15/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/29/2025
Date Data Arrived at EDR: 02/03/2025
Date Made Active in Reports: 02/27/2025
Number of Days to Update: 24

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 10/01/2024
Date Data Arrived at EDR: 10/23/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/09/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 09/19/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 10/19/2023
Number of Days to Update: 16

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 100

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/02/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/23/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/12/2024
Date Data Arrived at EDR: 10/17/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 33
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 01/09/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 02/24/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 02/24/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 01/30/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 12/17/2024
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 10/04/2024
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 51

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/22/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2024
Date Data Arrived at EDR: 10/09/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 93

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 12/30/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 12/30/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 02/12/2025
Date Data Arrived at EDR: 02/12/2025
Date Made Active in Reports: 02/27/2025
Number of Days to Update: 15

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/06/2025
Next Scheduled EDR Contact: 05/26/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/19/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/21/2025
Number of Days to Update: 19

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 03/03/2025
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/01/2024
Date Data Arrived at EDR: 11/18/2024
Date Made Active in Reports: 02/11/2025
Number of Days to Update: 85

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/18/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 10/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 10/09/2024
Number of Days to Update: 7

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 02/19/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/02/2024
Date Data Arrived at EDR: 08/20/2024
Date Made Active in Reports: 10/09/2024
Number of Days to Update: 50

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/10/2024
Date Data Arrived at EDR: 12/11/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 69

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/12/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/11/2024
Date Data Arrived at EDR: 11/20/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 90

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 02/25/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/13/2023
Date Made Active in Reports: 12/11/2023
Number of Days to Update: 89

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/06/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 12/21/2024
Date Data Arrived at EDR: 12/27/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 12/27/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/12/2025
Next Scheduled EDR Contact: 06/02/2025
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/08/2024
Date Data Arrived at EDR: 11/08/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 67

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/13/2025
Next Scheduled EDR Contact: 05/26/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 12/13/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/02/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/19/2023
Date Data Arrived at EDR: 04/05/2024
Date Made Active in Reports: 06/06/2024
Number of Days to Update: 62

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 03/06/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 12/30/2024
Date Data Arrived at EDR: 01/02/2025
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 12/23/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: No Update Planned

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/23/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data
The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 10/13/2024
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 10/23/2024
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 01/14/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Varies

UST FINDER: UST Finder Database
EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 02/06/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database
US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 02/06/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Semi-Annually

E MANIFEST: Hazardous Waste Electronic Manifest System
EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/14/2025
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 03/18/2025
Next Scheduled EDR Contact: 06/30/2025
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List
A list of records included in the Environmental Remediation database whose material is listed as Perfluorooctanoic Acid or Perfluorooctane Sulfonic Acid.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/06/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 08/10/2023
Date Made Active in Reports: 10/25/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 01/30/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 10/09/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 11/21/2024
Number of Days to Update: 16

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/09/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 12/18/2024
Date Data Arrived at EDR: 12/18/2024
Date Made Active in Reports: 03/10/2025
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/17/2024
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 11/27/2024
Date Data Arrived at EDR: 12/09/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 84

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 02/26/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 10/07/2024
Date Data Arrived at EDR: 12/19/2024
Date Made Active in Reports: 03/11/2025
Number of Days to Update: 82

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/11/2025
Next Scheduled EDR Contact: 06/23/2025
Data Release Frequency: Semi-Annually

FIN ASSURANCE 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 12/11/2024
Date Data Arrived at EDR: 12/18/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/17/2024
Next Scheduled EDR Contact: 04/07/2025
Data Release Frequency: Quarterly

FIN ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 08/30/2024
Date Data Arrived at EDR: 08/30/2024
Date Made Active in Reports: 09/13/2024
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 02/26/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 07/10/2024
Date Data Arrived at EDR: 07/30/2024
Date Made Active in Reports: 10/17/2024
Number of Days to Update: 79

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 01/28/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 10/28/2024
Date Data Arrived at EDR: 10/30/2024
Date Made Active in Reports: 01/22/2025
Number of Days to Update: 84

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 01/28/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/10/2024
Date Data Arrived at EDR: 11/08/2024
Date Made Active in Reports: 12/02/2024
Number of Days to Update: 24

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/09/2025
Next Scheduled EDR Contact: 04/28/2025
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/06/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 11/19/2024
Date Data Arrived at EDR: 11/20/2024
Date Made Active in Reports: 02/14/2025
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 02/25/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/01/2024
Date Data Arrived at EDR: 10/08/2024
Date Made Active in Reports: 12/23/2024
Number of Days to Update: 76

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/07/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Varies

NYC OER: OER Cleanup Sites Listing
Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Date of Government Version: 12/02/2024
Date Data Arrived at EDR: 12/04/2024
Date Made Active in Reports: 02/25/2025
Number of Days to Update: 83
Source: Office of Environmental Remediation
Telephone: 212-788-8841
Last EDR Contact: 03/04/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Varies

NYC LAND USE: New York City Land Use Information
Land use colors

Date of Government Version: 09/30/2024
Date Data Arrived at EDR: 12/09/2024
Date Made Active in Reports: 03/06/2025
Number of Days to Update: 87
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/11/2025
Next Scheduled EDR Contact: 06/23/2025
Data Release Frequency: Varies

ILI: New York State Inactive Landfill Initiative
A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

Date of Government Version: 05/16/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/26/2024
Number of Days to Update: 88
Source: Department of Environmental Conservation
Telephone: 518-402-8671
Last EDR Contact: 02/10/2025
Next Scheduled EDR Contact: 05/12/2025
Data Release Frequency: Varies

MGP: Manufactured Gas Plants Listing
From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

Date of Government Version: 12/02/2024
Date Data Arrived at EDR: 12/03/2024
Date Made Active in Reports: 02/25/2025
Number of Days to Update: 84
Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 02/26/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A
Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 02/12/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: No Update Planned

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 02/12/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/20/2025
Next Scheduled EDR Contact: 06/09/2025
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 11/13/2024
Date Data Arrived at EDR: 11/14/2024
Date Made Active in Reports: 02/07/2025
Number of Days to Update: 85

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 11/13/2024
Date Data Arrived at EDR: 11/14/2024
Date Made Active in Reports: 02/07/2025
Number of Days to Update: 85

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/23/2025
Next Scheduled EDR Contact: 05/05/2025
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/04/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/27/2025
Number of Days to Update: 83

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/04/2025
Next Scheduled EDR Contact: 05/19/2025
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 12/23/2024
Next Scheduled EDR Contact: 04/14/2025
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/06/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/06/2025
Next Scheduled EDR Contact: 05/26/2025
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/06/2025
Next Scheduled EDR Contact: 04/21/2025
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 02/26/2025
Next Scheduled EDR Contact: 06/16/2025
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BROADWAY JUNCTION PROPERTIES
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

TARGET PROPERTY COORDINATES

Latitude (North):	40.676539 - 40° 40' 35.54''
Longitude (West):	73.903116 - 73° 54' 11.22''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	592702.5
UTM Y (Meters):	4503218.0
Elevation:	70 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 70 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970065B	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
3604970208F	FEMA FIRM Flood data
3604970064B	FEMA Q3 Flood data
3604970074B	FEMA Q3 Flood data
3604970075C	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
2	USGS40000828399	1/8 - 1/4 Mile North
3	USGS40000828290	1/4 - 1/2 Mile East
4	USGS40000828169	1/4 - 1/2 Mile ESE
5	USGS40000828135	1/4 - 1/2 Mile SE
C10	USGS40000828104	1/2 - 1 Mile SW
C11	USGS40000828103	1/2 - 1 Mile SW
14	USGS40000828031	1/2 - 1 Mile SW
16	USGS40000828360	1/2 - 1 Mile ENE
18	USGS40000827849	1/2 - 1 Mile SE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYREG1200061424	1/8 - 1/4 Mile SSE
A6	NYREG1200061508	1/4 - 1/2 Mile SSE
A7	NYREG1200061361	1/2 - 1 Mile SSE
B8	NYREG1200061644	1/2 - 1 Mile SSE
B9	NYREG1200061645	1/2 - 1 Mile SSE
D12	NYREG1200061347	1/2 - 1 Mile East
D13	NYREG1200061346	1/2 - 1 Mile East
15	NYREG1200061405	1/2 - 1 Mile ESE
17	NYREG1200061475	1/2 - 1 Mile West

PHYSICAL SETTING SOURCE MAP - 7931531.2s



County Boundary
Major Roads
Contour Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

Groundwater Flow Direction
GI Indeterminate Groundwater Flow at Location
GV Groundwater Flow Varies at Location
HD Closest Hydrogeological Data
Oil, gas or related wells

SITE NAME:	Broadway Junction Properties	CLIENT:	P.W. Grosser Consulting
ADDRESS:	45 Van Sinderen Avenue Brooklyn NY 11207	CONTACT:	Michael Pecoraro
LAT/LONG:	40.676539 / 73.903116	INQUIRY #:	7931531.2s
		DATE:	March 19, 2025 3:33 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
SSE
1/8 - 1/4 Mile
Lower

NY WELLS **NYREG1200061424**

WELLS REG 1:

Well Number:	K003547	Well Type:	Commercial/Industrial Supply
Owner:	M And B Cement	Diameter (in):	4
Well Depth (ft):	75	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	45

2
North
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000828399**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 45. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	284	Well Hole Depth Units:	ft

3
East
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000828290**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1235. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	80
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	432	Level reading date:	1972-08-31
Feet below surface:	Not Reported	Feet to sea level:	7.12
Note:	Not Reported		
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	7.03	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	7.16	Note:	Not Reported
Level reading date:	1971-10-22	Feet below surface:	Not Reported
Feet to sea level:	7.07	Note:	Not Reported

Level reading date:	1971-09-23	Feet below surface:	Not Reported
Feet to sea level:	7.07	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	6.83	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	5.79	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	6.40	Note:	Not Reported
Level reading date:	1969-09-05	Feet below surface:	Not Reported
Feet to sea level:	6.06	Note:	Not Reported
Level reading date:	1969-08-04	Feet below surface:	Not Reported
Feet to sea level:	5.82	Note:	Not Reported
Level reading date:	1969-07-02	Feet below surface:	Not Reported
Feet to sea level:	5.77	Note:	Not Reported
Level reading date:	1969-05-28	Feet below surface:	Not Reported
Feet to sea level:	5.53	Note:	Not Reported
Level reading date:	1969-04-21	Feet below surface:	Not Reported
Feet to sea level:	5.52	Note:	Not Reported
Level reading date:	1969-04-01	Feet below surface:	Not Reported
Feet to sea level:	5.44	Note:	Not Reported
Level reading date:	1969-02-20	Feet below surface:	Not Reported
Feet to sea level:	5.57	Note:	Not Reported
Level reading date:	1969-01-08	Feet below surface:	Not Reported
Feet to sea level:	5.04	Note:	Not Reported
Level reading date:	1968-12-03	Feet below surface:	Not Reported
Feet to sea level:	4.77	Note:	Not Reported
Level reading date:	1968-11-05	Feet below surface:	Not Reported
Feet to sea level:	4.52	Note:	Not Reported
Level reading date:	1968-09-30	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1968-08-28	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1968-07-29	Feet below surface:	Not Reported
Feet to sea level:	4.64	Note:	Not Reported
Level reading date:	1968-06-26	Feet below surface:	Not Reported
Feet to sea level:	4.58	Note:	Not Reported
Level reading date:	1968-05-28	Feet below surface:	Not Reported
Feet to sea level:	4.47	Note:	Not Reported
Level reading date:	1968-04-23	Feet below surface:	Not Reported
Feet to sea level:	4.48	Note:	Not Reported
Level reading date:	1968-03-27	Feet below surface:	Not Reported
Feet to sea level:	4.45	Note:	Not Reported

Level reading date:	1968-02-29	Feet below surface:	Not Reported
Feet to sea level:	5.74	Note:	Not Reported
Level reading date:	1968-02-05	Feet below surface:	Not Reported
Feet to sea level:	8.43	Note:	Not Reported
Level reading date:	1968-01-02	Feet below surface:	Not Reported
Feet to sea level:	4.07	Note:	Not Reported
Level reading date:	1967-11-29	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1967-10-23	Feet below surface:	Not Reported
Feet to sea level:	3.91	Note:	Not Reported
Level reading date:	1967-09-26	Feet below surface:	Not Reported
Feet to sea level:	3.88	Note:	Not Reported
Level reading date:	1967-09-07	Feet below surface:	Not Reported
Feet to sea level:	3.75	Note:	Not Reported
Level reading date:	1967-07-28	Feet below surface:	Not Reported
Feet to sea level:	3.62	Note:	Not Reported
Level reading date:	1967-07-06	Feet below surface:	Not Reported
Feet to sea level:	3.54	Note:	Not Reported
Level reading date:	1967-05-31	Feet below surface:	Not Reported
Feet to sea level:	3.46	Note:	Not Reported
Level reading date:	1967-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.30	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.23	Note:	Not Reported
Level reading date:	1967-01-31	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1966-12-23	Feet below surface:	Not Reported
Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1966-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.93	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1966-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.83	Note:	Not Reported
Level reading date:	1966-08-29	Feet below surface:	Not Reported
Feet to sea level:	2.88	Note:	Not Reported
Level reading date:	1966-07-29	Feet below surface:	Not Reported
Feet to sea level:	2.97	Note:	Not Reported
Level reading date:	1966-06-27	Feet below surface:	Not Reported
Feet to sea level:	3.12	Note:	Not Reported
Level reading date:	1966-05-26	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported

Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported
Level reading date:	1966-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1966-02-02	Feet below surface:	Not Reported
Feet to sea level:	3.21	Note:	Not Reported
Level reading date:	1966-01-28	Feet below surface:	Not Reported
Feet to sea level:	3.23	Note:	Not Reported
Level reading date:	1965-12-30	Feet below surface:	Not Reported
Feet to sea level:	3.32	Note:	Not Reported
Level reading date:	1965-12-02	Feet below surface:	Not Reported
Feet to sea level:	3.38	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	3.49	Note:	Not Reported
Level reading date:	1965-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.52	Note:	Not Reported
Level reading date:	1965-09-09	Feet below surface:	Not Reported
Feet to sea level:	3.62	Note:	Not Reported
Level reading date:	1965-07-23	Feet below surface:	Not Reported
Feet to sea level:	3.71	Note:	Not Reported
Level reading date:	1965-06-24	Feet below surface:	Not Reported
Feet to sea level:	3.82	Note:	Not Reported
Level reading date:	1965-05-24	Feet below surface:	Not Reported
Feet to sea level:	3.86	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	3.87	Note:	Not Reported
Level reading date:	1965-03-25	Feet below surface:	Not Reported
Feet to sea level:	3.88	Note:	Not Reported
Level reading date:	1965-02-24	Feet below surface:	Not Reported
Feet to sea level:	3.88	Note:	Not Reported
Level reading date:	1965-02-10	Feet below surface:	Not Reported
Feet to sea level:	3.84	Note:	Not Reported
Level reading date:	1964-12-31	Feet below surface:	Not Reported
Feet to sea level:	3.90	Note:	Not Reported
Level reading date:	1964-11-25	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	3.77	Note:	Not Reported
Level reading date:	1964-10-01	Feet below surface:	Not Reported
Feet to sea level:	3.83	Note:	Not Reported
Level reading date:	1964-09-02	Feet below surface:	Not Reported
Feet to sea level:	3.82	Note:	Not Reported

Level reading date:	1964-07-27	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1964-07-06	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1964-05-28	Feet below surface:	Not Reported
Feet to sea level:	4.03	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1964-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1964-02-28	Feet below surface:	Not Reported
Feet to sea level:	3.83	Note:	Not Reported
Level reading date:	1964-01-28	Feet below surface:	Not Reported
Feet to sea level:	3.81	Note:	Not Reported
Level reading date:	1963-12-31	Feet below surface:	Not Reported
Feet to sea level:	3.67	Note:	Not Reported
Level reading date:	1963-12-05	Feet below surface:	Not Reported
Feet to sea level:	3.91	Note:	Not Reported
Level reading date:	1963-10-26	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1963-09-30	Feet below surface:	Not Reported
Feet to sea level:	4.21	Note:	Not Reported
Level reading date:	1963-09-03	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1963-07-30	Feet below surface:	Not Reported
Feet to sea level:	4.27	Note:	Not Reported
Level reading date:	1963-07-02	Feet below surface:	Not Reported
Feet to sea level:	4.25	Note:	Not Reported
Level reading date:	1963-06-03	Feet below surface:	Not Reported
Feet to sea level:	4.44	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	4.42	Note:	Not Reported
Level reading date:	1963-03-29	Feet below surface:	Not Reported
Feet to sea level:	4.49	Note:	Not Reported
Level reading date:	1963-02-28	Feet below surface:	Not Reported
Feet to sea level:	4.54	Note:	Not Reported
Level reading date:	1963-01-03	Feet below surface:	Not Reported
Feet to sea level:	4.64	Note:	Not Reported
Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	4.71	Note:	Not Reported
Level reading date:	1962-11-06	Feet below surface:	Not Reported
Feet to sea level:	4.77	Note:	Not Reported

Level reading date:	1962-10-03	Feet below surface:	Not Reported
Feet to sea level:	4.89	Note:	Not Reported
Level reading date:	1962-08-31	Feet below surface:	Not Reported
Feet to sea level:	4.97	Note:	Not Reported
Level reading date:	1962-07-30	Feet below surface:	Not Reported
Feet to sea level:	4.76	Note:	Not Reported
Level reading date:	1962-07-02	Feet below surface:	Not Reported
Feet to sea level:	4.58	Note:	Not Reported
Level reading date:	1962-05-29	Feet below surface:	Not Reported
Feet to sea level:	4.69	Note:	Not Reported
Level reading date:	1962-04-27	Feet below surface:	Not Reported
Feet to sea level:	4.65	Note:	Not Reported
Level reading date:	1962-03-27	Feet below surface:	Not Reported
Feet to sea level:	4.63	Note:	Not Reported
Level reading date:	1962-03-05	Feet below surface:	Not Reported
Feet to sea level:	4.55	Note:	Not Reported
Level reading date:	1962-01-31	Feet below surface:	Not Reported
Feet to sea level:	4.48	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	5.16	Note:	Not Reported
Level reading date:	1961-11-28	Feet below surface:	Not Reported
Feet to sea level:	4.68	Note:	Not Reported
Level reading date:	1961-10-31	Feet below surface:	Not Reported
Feet to sea level:	4.61	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	4.62	Note:	Not Reported
Level reading date:	1961-08-30	Feet below surface:	Not Reported
Feet to sea level:	4.72	Note:	Not Reported
Level reading date:	1961-08-01	Feet below surface:	Not Reported
Feet to sea level:	4.59	Note:	Not Reported
Level reading date:	1961-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.58	Note:	Not Reported
Level reading date:	1961-05-31	Feet below surface:	Not Reported
Feet to sea level:	4.50	Note:	Not Reported
Level reading date:	1961-04-26	Feet below surface:	Not Reported
Feet to sea level:	4.14	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	3.98	Note:	Not Reported
Level reading date:	1961-03-01	Feet below surface:	Not Reported
Feet to sea level:	4.12	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	3.94	Note:	Not Reported

Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.26	Note:	Not Reported
Level reading date:	1960-12-07	Feet below surface:	Not Reported
Feet to sea level:	3.72	Note:	Not Reported
Level reading date:	1960-11-02	Feet below surface:	Not Reported
Feet to sea level:	3.48	Note:	Not Reported
Level reading date:	1960-09-27	Feet below surface:	Not Reported
Feet to sea level:	3.37	Note:	Not Reported
Level reading date:	1960-08-30	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1960-07-18	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported
Level reading date:	1960-06-30	Feet below surface:	Not Reported
Feet to sea level:	3.06	Note:	Not Reported
Level reading date:	1960-06-02	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1960-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.14	Note:	Not Reported
Level reading date:	1960-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.04	Note:	Not Reported
Level reading date:	1960-01-27	Feet below surface:	Not Reported
Feet to sea level:	2.86	Note:	Not Reported
Level reading date:	1960-01-05	Feet below surface:	Not Reported
Feet to sea level:	2.92	Note:	Not Reported
Level reading date:	1959-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.85	Note:	Not Reported
Level reading date:	1959-11-02	Feet below surface:	Not Reported
Feet to sea level:	2.54	Note:	Not Reported
Level reading date:	1959-10-06	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1959-09-03	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1959-08-04	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1959-07-07	Feet below surface:	Not Reported
Feet to sea level:	2.62	Note:	Not Reported
Level reading date:	1959-06-02	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1959-05-06	Feet below surface:	Not Reported
Feet to sea level:	2.84	Note:	Not Reported
Level reading date:	1959-04-03	Feet below surface:	Not Reported
Feet to sea level:	2.94	Note:	Not Reported

Level reading date:	1959-03-02	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1959-01-29	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1959-01-07	Feet below surface:	Not Reported
Feet to sea level:	3.40	Note:	Not Reported
Level reading date:	1958-12-09	Feet below surface:	Not Reported
Feet to sea level:	3.32	Note:	Not Reported
Level reading date:	1958-10-30	Feet below surface:	Not Reported
Feet to sea level:	3.21	Note:	Not Reported
Level reading date:	1958-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1958-08-28	Feet below surface:	Not Reported
Feet to sea level:	3.01	Note:	Not Reported
Level reading date:	1958-07-29	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1958-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1958-05-29	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1958-05-01	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1958-04-02	Feet below surface:	Not Reported
Feet to sea level:	1.96	Note:	Not Reported
Level reading date:	1958-03-03	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported
Level reading date:	1958-01-28	Feet below surface:	Not Reported
Feet to sea level:	1.90	Note:	Not Reported
Level reading date:	1957-12-31	Feet below surface:	Not Reported
Feet to sea level:	1.85	Note:	Not Reported
Level reading date:	1957-11-22	Feet below surface:	Not Reported
Feet to sea level:	1.99	Note:	Not Reported
Level reading date:	1957-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.11	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	2.34	Note:	Not Reported
Level reading date:	1957-08-26	Feet below surface:	Not Reported
Feet to sea level:	2.51	Note:	Not Reported
Level reading date:	1957-07-24	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.67	Note:	Not Reported

Level reading date:	1957-05-28	Feet below surface:	Not Reported
Feet to sea level:	2.76	Note:	Not Reported
Level reading date:	1957-04-24	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	2.78	Note:	Not Reported
Level reading date:	1957-02-27	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1957-01-25	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	2.85	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	2.68	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	2.51	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	2.51	Note:	Not Reported
Level reading date:	1956-07-10	Feet below surface:	Not Reported
Feet to sea level:	2.53	Note:	Not Reported
Level reading date:	1956-06-04	Feet below surface:	Not Reported
Feet to sea level:	2.57	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	2.41	Note:	Not Reported
Level reading date:	1956-03-06	Feet below surface:	Not Reported
Feet to sea level:	2.39	Note:	Not Reported
Level reading date:	1956-02-07	Feet below surface:	Not Reported
Feet to sea level:	2.55	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	3.73	Note:	Not Reported
Level reading date:	1955-11-07	Feet below surface:	Not Reported
Feet to sea level:	2.59	Note:	Not Reported
Level reading date:	1955-10-05	Feet below surface:	Not Reported
Feet to sea level:	2.26	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1955-07-26	Feet below surface:	Not Reported
Feet to sea level:	1.67	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported

Level reading date:	1955-05-24	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	1.83	Note:	Not Reported
Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	1.73	Note:	Not Reported
Level reading date:	1955-02-21	Feet below surface:	Not Reported
Feet to sea level:	1.68	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	1.62	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1954-12-02	Feet below surface:	Not Reported
Feet to sea level:	1.26	Note:	Not Reported
Level reading date:	1954-11-29	Feet below surface:	Not Reported
Feet to sea level:	1.14	Note:	Not Reported
Level reading date:	1954-09-28	Feet below surface:	Not Reported
Feet to sea level:	0.96	Note:	Not Reported
Level reading date:	1954-08-23	Feet below surface:	Not Reported
Feet to sea level:	0.99	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.05	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.12	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.23	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.39	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.48	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.60	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	1.45	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	1.44	Note:	Not Reported
Level reading date:	1953-10-26	Feet below surface:	Not Reported
Feet to sea level:	1.48	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	1.32	Note:	Not Reported

Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	1.18	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	0.92	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	0.83	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	0.71	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	0.59	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	0.51	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	0.56	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	0.41	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	0.03	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	-0.22	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	-0.31	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-0.50	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	-0.93	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-1.07	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-1.06	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-1.67	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-1.74	Note:	Not Reported

Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-1.69	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-2.03	Note:	Not Reported
Level reading date:	1951-09-11	Feet below surface:	Not Reported
Feet to sea level:	-1.86	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.04	Note:	Not Reported
Level reading date:	1951-07-25	Feet below surface:	Not Reported
Feet to sea level:	-2.06	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	-1.89	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-2.24	Note:	Not Reported
Level reading date:	1951-04-26	Feet below surface:	Not Reported
Feet to sea level:	-1.72	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-2.59	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-2.55	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-2.51	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-2.75	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-2.92	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-2.37	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-2.96	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.91	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-2.76	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-2.55	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-2.33	Note:	Not Reported

Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-2.03	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-2.16	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-2.57	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-3.04	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.08	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	-3.17	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-4.11	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-4.17	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-4.26	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-4.82	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-4.41	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-4.26	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-4.98	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1948-07-23	Feet below surface:	Not Reported
Feet to sea level:	-6.25	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-6.45	Note:	Not Reported

Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-6.60	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-6.92	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-7.11	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-7.51	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-7.40	Note:	Not Reported
Level reading date:	1948-01-08	Feet below surface:	Not Reported
Feet to sea level:	-8.01	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-7.65	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-8.59	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-7.90	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-8.60	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-8.42	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-8.12	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-8.64	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-8.64	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-8.81	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-8.75	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-8.66	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-8.77	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-8.57	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported

Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-8.52	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-8.49	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1947-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.39	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-8.15	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-8.12	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1946-03-15	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-8.15	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-8.28	Note:	Not Reported

Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-8.31	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-8.39	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-8.35	Note:	Not Reported
Level reading date:	1945-08-07	Feet below surface:	Not Reported
Feet to sea level:	-8.30	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-8.19	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-8.24	Note:	Not Reported
Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1945-03-05	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported
Level reading date:	1945-01-02	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1944-11-03	Feet below surface:	Not Reported
Feet to sea level:	-8.47	Note:	Not Reported
Level reading date:	1944-10-05	Feet below surface:	Not Reported
Feet to sea level:	-8.50	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-8.79	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-8.63	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-8.58	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-8.63	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-8.64	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-8.78	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported

Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-8.78	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-8.93	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-9.26	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-9.16	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-9.08	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-9.15	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-9.31	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-9.49	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-9.66	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-9.70	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-9.70	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-9.72	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-9.78	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-9.83	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-9.85	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-9.90	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-9.95	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-10.01	Note:	Not Reported

Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-10.06	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-10.08	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-10.12	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-10.21	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-10.26	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-10.29	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-10.32	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-10.37	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-10.41	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-10.45	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-10.50	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-10.57	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-10.58	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-10.62	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-10.61	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-10.65	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-10.63	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-10.61	Note:	Not Reported

Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-10.59	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-10.52	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-10.51	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-10.48	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-10.46	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-10.42	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-10.42	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-10.39	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-10.36	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-10.40	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-10.38	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-10.33	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-10.31	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-10.27	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-10.23	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-10.19	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-10.15	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-10.13	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-10.13	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-10.10	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-10.06	Note:	Not Reported

Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-10.03	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-9.99	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-9.96	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-9.90	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-9.91	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-9.88	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-9.87	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-9.86	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-9.80	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-9.80	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-9.74	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-9.68	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-9.65	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-9.63	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-9.65	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-9.65	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-9.63	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-9.60	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-9.60	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-9.56	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-9.50	Note:	Not Reported

Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-9.45	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-9.42	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-9.38	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-9.35	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-9.33	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-9.18	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-9.14	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-9.06	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-9.06	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-9.01	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-8.95	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-8.89	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-8.84	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-8.84	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-8.89	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-8.87	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-8.91	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported

Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-9.03	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-9.07	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-9.12	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-9.15	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-9.17	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-9.19	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported

4
ESE **FED USGS** **USGS40000828169**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2622. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	105
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

5
SE **FED USGS** **USGS40000828135**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 136. 1	Type:	Well
Description:	5201	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A6
SSE **NY WELLS** **NYREG1200061508**
1/4 - 1/2 Mile
Lower

WELLS REG 1:

Well Number:	K003477	Well Type:	Multipurpose/Other
Owner:	Herrera Brothers Company	Diameter (in):	4
Well Depth (ft):	80	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	45

A7
SSE **NY WELLS** **NYREG1200061361**
1/2 - 1 Mile
Lower

WELLS REG 1:

Well Number:	K003608	Well Type:	Commercial/Industrial Supply
Owner:	North Eastern Precast	Diameter (in):	4
Well Depth (ft):	80	Casing Length (ft):	Not Reported
Screen Length (ft):	5	Pump Capacity (gpm):	25

B8
SSE **NY WELLS** **NYREG1200061644**
1/2 - 1 Mile
Lower

WELLS REG 1:

Well Number:	K001786	Well Type:	Cooling (Commercial/Industrial)
Owner:	Belmont Metals Incorporated	Diameter (in):	8
Well Depth (ft):	84	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	100

B9
SSE **NY WELLS** **NYREG1200061645**
1/2 - 1 Mile
Lower

WELLS REG 1:

Well Number:	K001786	Well Type:	Cooling (Commercial/Industrial)
Owner:	Belmont Metals Incorporated	Diameter (in):	8
Well Depth (ft):	84	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	100

C10
SW **FED USGS** **USGS40000828104**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3257. 2	Type:	Well
Description:	CHESTER AVE AND EAST NEW YORK AVE		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

HUC:	02030202	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	19980624	Well Depth:	55
Well Depth Units:	ft	Well Hole Depth:	55
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	73	Level reading date:	2005-02-15
Feet below surface:	Not Reported	Feet to sea level:	10.53
Note:	Not Reported		

Level reading date:	2005-01-21	Feet below surface:	Not Reported
Feet to sea level:	10.40	Note:	Not Reported
Level reading date:	2004-12-15	Feet below surface:	Not Reported
Feet to sea level:	10.44	Note:	Not Reported
Level reading date:	2004-11-23	Feet below surface:	Not Reported
Feet to sea level:	10.48	Note:	Not Reported
Level reading date:	2004-10-21	Feet below surface:	Not Reported
Feet to sea level:	10.43	Note:	Not Reported
Level reading date:	2004-09-21	Feet below surface:	Not Reported
Feet to sea level:	10.31	Note:	Not Reported
Level reading date:	2004-08-25	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	2004-07-19	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported
Level reading date:	2004-06-16	Feet below surface:	Not Reported
Feet to sea level:	10.01	Note:	Not Reported
Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	10.01	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	9.88	Note:	Not Reported
Level reading date:	2004-03-21	Feet below surface:	Not Reported
Feet to sea level:	9.86	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	10.03	Note:	Not Reported
Level reading date:	2003-12-18	Feet below surface:	Not Reported
Feet to sea level:	10.00	Note:	Not Reported
Level reading date:	2003-11-25	Feet below surface:	Not Reported
Feet to sea level:	9.89	Note:	Not Reported
Level reading date:	2003-10-29	Feet below surface:	Not Reported
Feet to sea level:	9.99	Note:	Not Reported
Level reading date:	2003-09-24	Feet below surface:	Not Reported
Feet to sea level:	10.07	Note:	Not Reported

Level reading date:	2003-08-25	Feet below surface:	Not Reported
Feet to sea level:	10.24	Note:	Not Reported
Level reading date:	2003-07-21	Feet below surface:	Not Reported
Feet to sea level:	10.83	Note:	Not Reported
Level reading date:	2003-06-25	Feet below surface:	Not Reported
Feet to sea level:	9.92	Note:	Not Reported
Level reading date:	2003-05-19	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	2003-04-28	Feet below surface:	Not Reported
Feet to sea level:	9.64	Note:	Not Reported
Level reading date:	2003-02-27	Feet below surface:	Not Reported
Feet to sea level:	9.37	Note:	Not Reported
Level reading date:	2002-12-27	Feet below surface:	Not Reported
Feet to sea level:	9.02	Note:	Not Reported
Level reading date:	2002-11-26	Feet below surface:	Not Reported
Feet to sea level:	9.01	Note:	Not Reported
Level reading date:	2002-10-21	Feet below surface:	Not Reported
Feet to sea level:	8.91	Note:	Not Reported
Level reading date:	2002-09-25	Feet below surface:	Not Reported
Feet to sea level:	8.78	Note:	Not Reported
Level reading date:	2002-08-27	Feet below surface:	Not Reported
Feet to sea level:	8.68	Note:	Not Reported
Level reading date:	2002-07-24	Feet below surface:	Not Reported
Feet to sea level:	8.82	Note:	Not Reported
Level reading date:	2002-07-22	Feet below surface:	Not Reported
Feet to sea level:	8.77	Note:	Not Reported
Level reading date:	2002-06-18	Feet below surface:	Not Reported
Feet to sea level:	8.74	Note:	Not Reported
Level reading date:	2002-05-29	Feet below surface:	Not Reported
Feet to sea level:	8.74	Note:	Not Reported
Level reading date:	2002-04-24	Feet below surface:	Not Reported
Feet to sea level:	8.67	Note:	Not Reported
Level reading date:	2002-03-21	Feet below surface:	Not Reported
Feet to sea level:	8.78	Note:	Not Reported
Level reading date:	2002-02-27	Feet below surface:	Not Reported
Feet to sea level:	8.91	Note:	Not Reported
Level reading date:	2002-01-28	Feet below surface:	Not Reported
Feet to sea level:	9.02	Note:	Not Reported
Level reading date:	2001-12-28	Feet below surface:	Not Reported
Feet to sea level:	9.15	Note:	Not Reported
Level reading date:	2001-09-25	Feet below surface:	Not Reported
Feet to sea level:	9.57	Note:	Not Reported

Level reading date:	2001-08-29	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	2001-07-24	Feet below surface:	Not Reported
Feet to sea level:	9.46	Note:	Not Reported
Level reading date:	2001-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.76	Note:	Not Reported
Level reading date:	2001-05-24	Feet below surface:	Not Reported
Feet to sea level:	9.82	Note:	Not Reported
Level reading date:	2001-04-25	Feet below surface:	Not Reported
Feet to sea level:	9.83	Note:	Not Reported
Level reading date:	2001-03-20	Feet below surface:	Not Reported
Feet to sea level:	9.34	Note:	Not Reported
Level reading date:	2001-02-22	Feet below surface:	Not Reported
Feet to sea level:	9.39	Note:	Not Reported
Level reading date:	2001-01-17	Feet below surface:	Not Reported
Feet to sea level:	9.28	Note:	Not Reported
Level reading date:	2000-12-19	Feet below surface:	Not Reported
Feet to sea level:	9.49	Note:	Not Reported
Level reading date:	2000-11-28	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported
Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	9.73	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	9.98	Note:	Not Reported
Level reading date:	2000-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.09	Note:	Not Reported
Level reading date:	2000-07-27	Feet below surface:	Not Reported
Feet to sea level:	9.94	Note:	Not Reported
Level reading date:	2000-06-28	Feet below surface:	Not Reported
Feet to sea level:	9.92	Note:	Not Reported
Level reading date:	2000-05-23	Feet below surface:	Not Reported
Feet to sea level:	9.78	Note:	Not Reported
Level reading date:	2000-04-27	Feet below surface:	Not Reported
Feet to sea level:	9.70	Note:	Not Reported
Level reading date:	2000-03-29	Feet below surface:	Not Reported
Feet to sea level:	9.69	Note:	Not Reported
Level reading date:	2000-02-29	Feet below surface:	Not Reported
Feet to sea level:	9.63	Note:	Not Reported
Level reading date:	1999-12-13	Feet below surface:	Not Reported
Feet to sea level:	9.62	Note:	Not Reported
Level reading date:	1999-11-23	Feet below surface:	Not Reported
Feet to sea level:	9.68	Note:	Not Reported

Level reading date:	1999-10-19	Feet below surface:	Not Reported
Feet to sea level:	9.79	Note:	Not Reported
Level reading date:	1999-09-23	Feet below surface:	Not Reported
Feet to sea level:	9.94	Note:	Not Reported
Level reading date:	1999-08-17	Feet below surface:	Not Reported
Feet to sea level:	10.00	Note:	Not Reported
Level reading date:	1999-06-23	Feet below surface:	Not Reported
Feet to sea level:	10.07	Note:	Not Reported
Level reading date:	1999-05-18	Feet below surface:	Not Reported
Feet to sea level:	10.12	Note:	Not Reported
Level reading date:	1999-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.13	Note:	Not Reported
Level reading date:	1999-03-23	Feet below surface:	Not Reported
Feet to sea level:	10.14	Note:	Not Reported
Level reading date:	1999-03-02	Feet below surface:	Not Reported
Feet to sea level:	10.22	Note:	Not Reported
Level reading date:	1999-01-27	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	1998-11-24	Feet below surface:	Not Reported
Feet to sea level:	10.47	Note:	Not Reported
Level reading date:	1998-10-29	Feet below surface:	Not Reported
Feet to sea level:	10.57	Note:	Not Reported
Level reading date:	1998-09-29	Feet below surface:	Not Reported
Feet to sea level:	10.72	Note:	Not Reported
Level reading date:	1998-09-01	Feet below surface:	Not Reported
Feet to sea level:	10.93	Note:	Not Reported
Level reading date:	1998-07-28	Feet below surface:	Not Reported
Feet to sea level:	11.22	Note:	Not Reported

C11
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828103**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3257. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	50
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	51	Level reading date:	1999-06-23
Feet below surface:	Not Reported	Feet to sea level:	11.12

Note:	Not Reported		
Level reading date:	1997-03-17	Feet below surface:	Not Reported
Feet to sea level:	9.75	Note:	Not Reported
Level reading date:	1996-07-05	Feet below surface:	Not Reported
Feet to sea level:	10.29	Note:	Not Reported
Level reading date:	1996-03-14	Feet below surface:	Not Reported
Feet to sea level:	10.11	Note:	Not Reported
Level reading date:	1995-09-29	Feet below surface:	Not Reported
Feet to sea level:	9.54	Note:	Not Reported
Level reading date:	1995-06-21	Feet below surface:	Not Reported
Feet to sea level:	9.72	Note:	Not Reported
Level reading date:	1995-03-14	Feet below surface:	Not Reported
Feet to sea level:	9.98	Note:	Not Reported
Level reading date:	1995-01-03	Feet below surface:	Not Reported
Feet to sea level:	10.11	Note:	Not Reported
Level reading date:	1994-06-29	Feet below surface:	Not Reported
Feet to sea level:	10.58	Note:	Not Reported
Level reading date:	1994-03-24	Feet below surface:	Not Reported
Feet to sea level:	10.42	Note:	Not Reported
Level reading date:	1993-11-22	Feet below surface:	Not Reported
Feet to sea level:	9.94	Note:	Not Reported
Level reading date:	1993-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.26	Note:	Not Reported
Level reading date:	1993-07-22	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1993-06-22	Feet below surface:	Not Reported
Feet to sea level:	10.57	Note:	Not Reported
Level reading date:	1993-05-24	Feet below surface:	Not Reported
Feet to sea level:	10.65	Note:	Not Reported
Level reading date:	1993-04-28	Feet below surface:	Not Reported
Feet to sea level:	10.65	Note:	Not Reported
Level reading date:	1993-03-22	Feet below surface:	Not Reported
Feet to sea level:	10.28	Note:	Not Reported
Level reading date:	1993-01-19	Feet below surface:	Not Reported
Feet to sea level:	10.23	Note:	Not Reported
Level reading date:	1992-12-28	Feet below surface:	Not Reported
Feet to sea level:	10.25	Note:	Not Reported
Level reading date:	1992-11-19	Feet below surface:	Not Reported
Feet to sea level:	10.12	Note:	Not Reported
Level reading date:	1992-11-10	Feet below surface:	Not Reported
Feet to sea level:	10.19	Note:	Not Reported

Level reading date:	1992-10-27	Feet below surface:	Not Reported
Feet to sea level:	10.29	Note:	Not Reported
Level reading date:	1992-09-18	Feet below surface:	Not Reported
Feet to sea level:	10.55	Note:	Not Reported
Level reading date:	1992-08-24	Feet below surface:	Not Reported
Feet to sea level:	10.43	Note:	Not Reported
Level reading date:	1992-07-16	Feet below surface:	Not Reported
Feet to sea level:	10.28	Note:	Not Reported
Level reading date:	1992-06-23	Feet below surface:	Not Reported
Feet to sea level:	10.24	Note:	Not Reported
Level reading date:	1992-06-12	Feet below surface:	Not Reported
Feet to sea level:	10.21	Note:	Not Reported
Level reading date:	1992-04-06	Feet below surface:	Not Reported
Feet to sea level:	10.39	Note:	Not Reported
Level reading date:	1985-12-04	Feet below surface:	Not Reported
Feet to sea level:	10.18	Note:	Not Reported
Level reading date:	1985-10-02	Feet below surface:	Not Reported
Feet to sea level:	10.22	Note:	Not Reported
Level reading date:	1985-05-18	Feet below surface:	Not Reported
Feet to sea level:	10.38	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	11.39	Note:	Not Reported
Level reading date:	1984-10-03	Feet below surface:	Not Reported
Feet to sea level:	12.16	Note:	Not Reported
Level reading date:	1984-06-28	Feet below surface:	Not Reported
Feet to sea level:	12.51	Note:	Not Reported
Level reading date:	1984-03-19	Feet below surface:	Not Reported
Feet to sea level:	11.45	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	11.19	Note:	Not Reported
Level reading date:	1983-09-28	Feet below surface:	Not Reported
Feet to sea level:	11.85	Note:	Not Reported
Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	11.07	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	12.07	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	11.37	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	11.21	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	11.35	Note:	Not Reported

Level reading date:	1982-03-24	Feet below surface:	Not Reported
Feet to sea level:	11.16	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	12.46	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	12.27	Note:	Not Reported
Level reading date:	1981-06-25	Feet below surface:	Not Reported
Feet to sea level:	11.94	Note:	Not Reported
Level reading date:	1981-03-19	Feet below surface:	Not Reported
Feet to sea level:	12.56	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	13.01	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	13.65	Note:	Not Reported
Level reading date:	1980-06-20	Feet below surface:	Not Reported
Feet to sea level:	13.96	Note:	Not Reported
Level reading date:	1980-06-10	Feet below surface:	Not Reported
Feet to sea level:	13.90	Note:	Not Reported

D12
East
1/2 - 1 Mile
Lower

NY WELLS **NYREG1200061347**

WELLS REG 1:

Well Number:	K003622	Well Type:	Geothermal - Ac Only
Owner:	Johns Funeral Home	Diameter (in):	6
Well Depth (ft):	65	Casing Length (ft):	55
Screen Length (ft):	10	Pump Capacity (gpm):	20

D13
East
1/2 - 1 Mile
Lower

NY WELLS **NYREG1200061346**

WELLS REG 1:

Well Number:	K003623D	Well Type:	Geothermal Diffusion
Owner:	Johns Funeral Home	Diameter (in):	6
Well Depth (ft):	45	Casing Length (ft):	35
Screen Length (ft):	10	Pump Capacity (gpm):	Not Reported

14
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000828031**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 910. 1	Type:	Well
Description:	4401	HUC:	02030202

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	182	Well Hole Depth Units:	ft

15
ESE
1/2 - 1 Mile
Lower

NY WELLS **NYREG1200061405**

WELLS REG 1:

Well Number:	K003566	Well Type:	Commercial/Industrial Supply
Owner:	Lee, Chin	Diameter (in):	6
Well Depth (ft):	160	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	40

16
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000828360**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1198. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	53
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	282	Level reading date:	1968-11-06
Feet below surface:	Not Reported	Feet to sea level:	3.51
Note:	Not Reported		
Level reading date:	1968-04-30	Feet below surface:	Not Reported
Feet to sea level:	3.43	Note:	Not Reported
Level reading date:	1967-11-09	Feet below surface:	Not Reported
Feet to sea level:	2.96	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	2.25	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	1.92	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	2.23	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	2.60	Note:	Not Reported
Level reading date:	1965-09-06	Feet below surface:	Not Reported

Feet to sea level:	2.74	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	3.08	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	2.97	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	3.25	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	3.78	Note:	Not Reported
Level reading date:	1962-04-27	Feet below surface:	Not Reported
Feet to sea level:	4.11	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.25	Note:	Not Reported
Level reading date:	1961-01-05	Feet below surface:	Not Reported
Feet to sea level:	3.29	Note:	Not Reported
Level reading date:	1960-07-18	Feet below surface:	Not Reported
Feet to sea level:	2.65	Note:	Not Reported
Level reading date:	1957-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.64	Note:	Not Reported
Level reading date:	1956-12-27	Feet below surface:	Not Reported
Feet to sea level:	2.86	Note:	Not Reported
Level reading date:	1956-01-20	Feet below surface:	Not Reported
Feet to sea level:	2.70	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.75	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.43	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.42	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.50	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.79	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	2.05	Note:	Not Reported
Level reading date:	1954-01-30	Feet below surface:	Not Reported
Feet to sea level:	2.13	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	2.16	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.06	Note:	Not Reported

Level reading date:	1953-10-10	Feet below surface:	Not Reported
Feet to sea level:	2.20	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	2.26	Note:	Not Reported
Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	2.10	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	1.96	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	2.01	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	1.72	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	1.55	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	1.59	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	1.47	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	1.58	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	1.61	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	1.60	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	1.53	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	1.29	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	0.91	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	0.70	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	0.42	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	0.24	Note:	Not Reported

Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	0.07	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	0.20	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	-0.28	Note:	Not Reported
Level reading date:	1951-11-01	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.50	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.48	Note:	Not Reported
Level reading date:	1951-07-25	Feet below surface:	Not Reported
Feet to sea level:	-0.62	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-0.60	Note:	Not Reported
Level reading date:	1951-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.82	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-1.08	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-1.22	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-1.33	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-1.23	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-1.16	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-1.12	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.98	Note:	Not Reported

Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.99	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-1.00	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-1.08	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-1.17	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-1.37	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-1.16	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-1.28	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-1.14	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-1.13	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-1.20	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-1.29	Note:	Not Reported
Level reading date:	1949-05-31	Feet below surface:	Not Reported
Feet to sea level:	-1.50	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-1.80	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-1.97	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-2.23	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-2.55	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-2.65	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-2.64	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-2.66	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-2.75	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-2.64	Note:	Not Reported

Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.46	Note:	Not Reported
Level reading date:	1948-06-01	Feet below surface:	Not Reported
Feet to sea level:	-3.67	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-4.02	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-4.32	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-4.50	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1948-01-08	Feet below surface:	Not Reported
Feet to sea level:	-4.88	Note:	Not Reported
Level reading date:	1947-12-16	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-5.10	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-5.19	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-5.34	Note:	Not Reported
Level reading date:	1947-10-06	Feet below surface:	Not Reported
Feet to sea level:	-5.37	Note:	Not Reported
Level reading date:	1947-09-29	Feet below surface:	Not Reported
Feet to sea level:	-5.30	Note:	Not Reported
Level reading date:	1947-09-15	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-5.24	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-5.13	Note:	Not Reported

Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-5.05	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.01	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1947-04-04	Feet below surface:	Not Reported
Feet to sea level:	-5.15	Note:	Not Reported
Level reading date:	1947-02-05	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-4.77	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-4.67	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-4.57	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-4.33	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-4.34	Note:	Not Reported
Level reading date:	1946-07-01	Feet below surface:	Not Reported
Feet to sea level:	-4.43	Note:	Not Reported
Level reading date:	1946-06-19	Feet below surface:	Not Reported
Feet to sea level:	-4.55	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1946-03-04	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1946-02-07	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported

Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.69	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-4.74	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-4.70	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-4.53	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-4.54	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-4.47	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-4.56	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-4.62	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-4.57	Note:	Not Reported
Level reading date:	1945-04-05	Feet below surface:	Not Reported
Feet to sea level:	-4.63	Note:	Not Reported
Level reading date:	1945-03-03	Feet below surface:	Not Reported
Feet to sea level:	-4.50	Note:	Not Reported
Level reading date:	1945-01-13	Feet below surface:	Not Reported
Feet to sea level:	-4.54	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1944-11-03	Feet below surface:	Not Reported
Feet to sea level:	-4.59	Note:	Not Reported
Level reading date:	1944-10-05	Feet below surface:	Not Reported
Feet to sea level:	-4.49	Note:	Not Reported
Level reading date:	1944-09-02	Feet below surface:	Not Reported
Feet to sea level:	-4.79	Note:	Not Reported
Level reading date:	1944-07-31	Feet below surface:	Not Reported
Feet to sea level:	-4.71	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-4.68	Note:	Not Reported
Level reading date:	1944-05-27	Feet below surface:	Not Reported
Feet to sea level:	-4.79	Note:	Not Reported
Level reading date:	1944-05-05	Feet below surface:	Not Reported
Feet to sea level:	-4.93	Note:	Not Reported
Level reading date:	1944-03-30	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported

Level reading date:	1944-02-26	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-5.16	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-5.17	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-5.22	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-5.35	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-5.40	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.30	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-5.35	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-5.39	Note:	Not Reported
Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.48	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-5.62	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-5.80	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-5.97	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-6.13	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-6.29	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-6.32	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-6.36	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-6.38	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-6.45	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-6.45	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-6.48	Note:	Not Reported

Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-6.52	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-6.61	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-6.70	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-6.83	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-6.88	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-6.94	Note:	Not Reported
Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-7.02	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-7.10	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-7.19	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-7.28	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-7.56	Note:	Not Reported
Level reading date:	1942-07-25	Feet below surface:	Not Reported
Feet to sea level:	-7.65	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-7.77	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-7.84	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported

Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-8.14	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-8.30	Note:	Not Reported
Level reading date:	1942-05-09	Feet below surface:	Not Reported
Feet to sea level:	-8.32	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-8.35	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-8.39	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1942-03-14	Feet below surface:	Not Reported
Feet to sea level:	-8.45	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-8.40	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-8.35	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-8.20	Note:	Not Reported
Level reading date:	1942-01-31	Feet below surface:	Not Reported
Feet to sea level:	-8.17	Note:	Not Reported

Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-8.11	Note:	Not Reported
Level reading date:	1942-01-10	Feet below surface:	Not Reported
Feet to sea level:	-8.05	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-7.97	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1941-12-13	Feet below surface:	Not Reported
Feet to sea level:	-7.81	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-7.75	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-7.66	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-7.60	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-7.55	Note:	Not Reported
Level reading date:	1941-11-01	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-7.44	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-7.40	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-7.35	Note:	Not Reported
Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-7.30	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-7.20	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-7.16	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-7.13	Note:	Not Reported

Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-7.06	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-7.11	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-7.04	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-6.99	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-6.93	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.86	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-6.78	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-6.72	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-6.49	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-6.40	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-6.21	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-6.14	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-6.03	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-5.93	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-5.86	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-5.79	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-5.68	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-5.63	Note:	Not Reported

Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported
Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.49	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-5.51	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-5.53	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-5.58	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-5.64	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-5.77	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-5.83	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-5.89	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-5.96	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-6.00	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-6.16	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-6.23	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-6.32	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-6.52	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-6.64	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-6.76	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-6.89	Note:	Not Reported

Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-7.03	Note:	Not Reported
Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported

17
West
1/2 - 1 Mile
Higher

NY WELLS **NYREG1200061475**

WELLS REG 1:

Well Number:	K003508	Well Type:	Multipurpose/Other
Owner:	Odessa Car Wash Incorporated	Diameter (in):	6
Well Depth (ft):	160	Casing Length (ft):	Not Reported
Screen Length (ft):	Not Reported	Pump Capacity (gpm):	45

18
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000827849**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1266. 1	Type:	Well
Description:	Not Reported	HUC:	02030202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	41
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	300	Level reading date:	1968-04-30
Feet below surface:	Not Reported	Feet to sea level:	4.51
Note:	Not Reported		
Level reading date:	1967-11-09	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported
Level reading date:	1967-03-29	Feet below surface:	Not Reported
Feet to sea level:	3.55	Note:	Not Reported
Level reading date:	1966-10-25	Feet below surface:	Not Reported
Feet to sea level:	3.09	Note:	Not Reported
Level reading date:	1966-05-04	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1965-10-27	Feet below surface:	Not Reported
Feet to sea level:	3.16	Note:	Not Reported
Level reading date:	1965-09-16	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1965-04-29	Feet below surface:	Not Reported
Feet to sea level:	3.70	Note:	Not Reported

Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	3.85	Note:	Not Reported
Level reading date:	1963-11-05	Feet below surface:	Not Reported
Feet to sea level:	3.15	Note:	Not Reported
Level reading date:	1963-04-25	Feet below surface:	Not Reported
Feet to sea level:	4.04	Note:	Not Reported
Level reading date:	1962-11-09	Feet below surface:	Not Reported
Feet to sea level:	3.86	Note:	Not Reported
Level reading date:	1962-04-03	Feet below surface:	Not Reported
Feet to sea level:	4.33	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	4.30	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	4.28	Note:	Not Reported
Level reading date:	1961-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.26	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	4.19	Note:	Not Reported
Level reading date:	1961-01-30	Feet below surface:	Not Reported
Feet to sea level:	3.77	Note:	Not Reported
Level reading date:	1960-09-27	Feet below surface:	Not Reported
Feet to sea level:	3.77	Note:	Not Reported
Level reading date:	1960-07-01	Feet below surface:	Not Reported
Feet to sea level:	3.22	Note:	Not Reported
Level reading date:	1960-03-30	Feet below surface:	Not Reported
Feet to sea level:	3.40	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	3.06	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	2.82	Note:	Not Reported
Level reading date:	1959-07-13	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1959-03-20	Feet below surface:	Not Reported
Feet to sea level:	2.89	Note:	Not Reported
Level reading date:	1957-12-30	Feet below surface:	Not Reported
Feet to sea level:	1.49	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	1.88	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	2.95	Note:	Not Reported
Level reading date:	1957-03-28	Feet below surface:	Not Reported
Feet to sea level:	3.00	Note:	Not Reported

Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	2.52	Note:	Not Reported
Level reading date:	1955-01-26	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1954-08-24	Feet below surface:	Not Reported
Feet to sea level:	1.78	Note:	Not Reported
Level reading date:	1954-07-29	Feet below surface:	Not Reported
Feet to sea level:	1.74	Note:	Not Reported
Level reading date:	1954-06-30	Feet below surface:	Not Reported
Feet to sea level:	1.90	Note:	Not Reported
Level reading date:	1954-05-26	Feet below surface:	Not Reported
Feet to sea level:	1.90	Note:	Not Reported
Level reading date:	1954-04-29	Feet below surface:	Not Reported
Feet to sea level:	1.85	Note:	Not Reported
Level reading date:	1954-03-27	Feet below surface:	Not Reported
Feet to sea level:	1.87	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	1.83	Note:	Not Reported
Level reading date:	1953-12-26	Feet below surface:	Not Reported
Feet to sea level:	1.84	Note:	Not Reported
Level reading date:	1953-12-21	Feet below surface:	Not Reported
Feet to sea level:	2.08	Note:	Not Reported
Level reading date:	1953-12-01	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1953-10-26	Feet below surface:	Not Reported
Feet to sea level:	2.50	Note:	Not Reported
Level reading date:	1953-09-30	Feet below surface:	Not Reported
Feet to sea level:	2.53	Note:	Not Reported
Level reading date:	1953-08-27	Feet below surface:	Not Reported
Feet to sea level:	2.75	Note:	Not Reported
Level reading date:	1953-07-31	Feet below surface:	Not Reported
Feet to sea level:	2.63	Note:	Not Reported
Level reading date:	1953-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.74	Note:	Not Reported
Level reading date:	1953-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.98	Note:	Not Reported
Level reading date:	1953-04-29	Feet below surface:	Not Reported
Feet to sea level:	3.07	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	2.42	Note:	Not Reported
Level reading date:	1953-02-26	Feet below surface:	Not Reported
Feet to sea level:	2.12	Note:	Not Reported

Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1952-12-23	Feet below surface:	Not Reported
Feet to sea level:	1.97	Note:	Not Reported
Level reading date:	1952-12-04	Feet below surface:	Not Reported
Feet to sea level:	2.02	Note:	Not Reported
Level reading date:	1952-11-04	Feet below surface:	Not Reported
Feet to sea level:	2.04	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	2.32	Note:	Not Reported
Level reading date:	1952-08-26	Feet below surface:	Not Reported
Feet to sea level:	2.47	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	2.49	Note:	Not Reported
Level reading date:	1952-06-23	Feet below surface:	Not Reported
Feet to sea level:	2.40	Note:	Not Reported
Level reading date:	1952-05-26	Feet below surface:	Not Reported
Feet to sea level:	2.01	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1952-03-20	Feet below surface:	Not Reported
Feet to sea level:	1.57	Note:	Not Reported
Level reading date:	1952-02-19	Feet below surface:	Not Reported
Feet to sea level:	1.48	Note:	Not Reported
Level reading date:	1952-01-28	Feet below surface:	Not Reported
Feet to sea level:	1.03	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	1.00	Note:	Not Reported
Level reading date:	1951-11-29	Feet below surface:	Not Reported
Feet to sea level:	0.84	Note:	Not Reported
Level reading date:	1951-10-03	Feet below surface:	Not Reported
Feet to sea level:	0.40	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	0.62	Note:	Not Reported
Level reading date:	1951-07-24	Feet below surface:	Not Reported
Feet to sea level:	0.52	Note:	Not Reported
Level reading date:	1951-06-26	Feet below surface:	Not Reported
Feet to sea level:	0.60	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	0.69	Note:	Not Reported

Level reading date:	1951-05-01	Feet below surface:	Not Reported
Feet to sea level:	0.54	Note:	Not Reported
Level reading date:	1951-03-26	Feet below surface:	Not Reported
Feet to sea level:	0.28	Note:	Not Reported
Level reading date:	1951-02-23	Feet below surface:	Not Reported
Feet to sea level:	-0.12	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	0.16	Note:	Not Reported
Level reading date:	1950-12-18	Feet below surface:	Not Reported
Feet to sea level:	0.22	Note:	Not Reported
Level reading date:	1950-11-27	Feet below surface:	Not Reported
Feet to sea level:	-0.30	Note:	Not Reported
Level reading date:	1950-10-30	Feet below surface:	Not Reported
Feet to sea level:	-0.32	Note:	Not Reported
Level reading date:	1950-09-26	Feet below surface:	Not Reported
Feet to sea level:	-0.51	Note:	Not Reported
Level reading date:	1950-08-28	Feet below surface:	Not Reported
Feet to sea level:	-0.33	Note:	Not Reported
Level reading date:	1950-07-26	Feet below surface:	Not Reported
Feet to sea level:	-0.35	Note:	Not Reported
Level reading date:	1950-06-28	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-0.36	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.20	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-0.52	Note:	Not Reported
Level reading date:	1950-02-28	Feet below surface:	Not Reported
Feet to sea level:	-0.40	Note:	Not Reported
Level reading date:	1950-01-25	Feet below surface:	Not Reported
Feet to sea level:	-0.49	Note:	Not Reported
Level reading date:	1949-12-27	Feet below surface:	Not Reported
Feet to sea level:	-0.76	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-0.65	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-0.89	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-0.58	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-0.59	Note:	Not Reported

Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-0.68	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-0.75	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-1.07	Note:	Not Reported
Level reading date:	1949-04-27	Feet below surface:	Not Reported
Feet to sea level:	-1.63	Note:	Not Reported
Level reading date:	1949-04-04	Feet below surface:	Not Reported
Feet to sea level:	-1.83	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-1.89	Note:	Not Reported
Level reading date:	1949-01-26	Feet below surface:	Not Reported
Feet to sea level:	-1.96	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-2.06	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	Not Reported
Feet to sea level:	-2.59	Note:	Not Reported
Level reading date:	1948-11-03	Feet below surface:	Not Reported
Feet to sea level:	-3.16	Note:	Not Reported
Level reading date:	1948-10-04	Feet below surface:	Not Reported
Feet to sea level:	-3.10	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-2.80	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-3.54	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1948-04-28	Feet below surface:	Not Reported
Feet to sea level:	-3.66	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-3.94	Note:	Not Reported
Level reading date:	1948-03-03	Feet below surface:	Not Reported
Feet to sea level:	-4.32	Note:	Not Reported
Level reading date:	1948-02-02	Feet below surface:	Not Reported
Feet to sea level:	-3.94	Note:	Not Reported
Level reading date:	1948-01-09	Feet below surface:	Not Reported
Feet to sea level:	-4.82	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported

Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-5.04	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-5.34	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-5.27	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-5.26	Note:	Not Reported
Level reading date:	1947-08-14	Feet below surface:	Not Reported
Feet to sea level:	-5.36	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-5.30	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-5.27	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-5.22	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-5.16	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-5.12	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-5.11	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-5.14	Note:	Not Reported
Level reading date:	1947-05-27	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1947-05-06	Feet below surface:	Not Reported
Feet to sea level:	-5.08	Note:	Not Reported
Level reading date:	1947-04-03	Feet below surface:	Not Reported
Feet to sea level:	-5.29	Note:	Not Reported
Level reading date:	1947-03-05	Feet below surface:	Not Reported
Feet to sea level:	-4.85	Note:	Not Reported
Level reading date:	1947-01-27	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported

Level reading date:	1946-12-30	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1946-11-26	Feet below surface:	Not Reported
Feet to sea level:	-4.96	Note:	Not Reported
Level reading date:	1946-10-22	Feet below surface:	Not Reported
Feet to sea level:	-4.90	Note:	Not Reported
Level reading date:	1946-09-27	Feet below surface:	Not Reported
Feet to sea level:	-4.83	Note:	Not Reported
Level reading date:	1946-08-29	Feet below surface:	Not Reported
Feet to sea level:	-4.65	Note:	Not Reported
Level reading date:	1946-07-26	Feet below surface:	Not Reported
Feet to sea level:	-4.45	Note:	Not Reported
Level reading date:	1946-07-05	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported
Level reading date:	1946-06-18	Feet below surface:	Not Reported
Feet to sea level:	-4.52	Note:	Not Reported
Level reading date:	1946-05-09	Feet below surface:	Not Reported
Feet to sea level:	-5.10	Note:	Not Reported
Level reading date:	1946-04-12	Feet below surface:	Not Reported
Feet to sea level:	-5.00	Note:	Not Reported
Level reading date:	1946-03-15	Feet below surface:	Not Reported
Feet to sea level:	-4.98	Note:	Not Reported
Level reading date:	1946-02-08	Feet below surface:	Not Reported
Feet to sea level:	-4.83	Note:	Not Reported
Level reading date:	1946-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.92	Note:	Not Reported
Level reading date:	1945-12-04	Feet below surface:	Not Reported
Feet to sea level:	-5.20	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-5.24	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-5.03	Note:	Not Reported
Level reading date:	1945-09-13	Feet below surface:	Not Reported
Feet to sea level:	-5.12	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-5.97	Note:	Not Reported
Level reading date:	1945-07-04	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1945-06-05	Feet below surface:	Not Reported
Feet to sea level:	-4.91	Note:	Not Reported
Level reading date:	1945-04-27	Feet below surface:	Not Reported
Feet to sea level:	-5.17	Note:	Not Reported

Level reading date:	1945-04-03	Feet below surface:	Not Reported
Feet to sea level:	-5.04	Note:	Not Reported
Level reading date:	1945-03-05	Feet below surface:	Not Reported
Feet to sea level:	-5.11	Note:	Not Reported
Level reading date:	1945-01-03	Feet below surface:	Not Reported
Feet to sea level:	-4.98	Note:	Not Reported
Level reading date:	1944-12-05	Feet below surface:	Not Reported
Feet to sea level:	-5.08	Note:	Not Reported
Level reading date:	1944-10-28	Feet below surface:	Not Reported
Feet to sea level:	-5.09	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	Not Reported
Feet to sea level:	-5.08	Note:	Not Reported
Level reading date:	1944-09-01	Feet below surface:	Not Reported
Feet to sea level:	-5.51	Note:	Not Reported
Level reading date:	1944-08-01	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1944-07-04	Feet below surface:	Not Reported
Feet to sea level:	-5.18	Note:	Not Reported
Level reading date:	1944-06-03	Feet below surface:	Not Reported
Feet to sea level:	-5.15	Note:	Not Reported
Level reading date:	1944-04-25	Feet below surface:	Not Reported
Feet to sea level:	-5.42	Note:	Not Reported
Level reading date:	1944-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.66	Note:	Not Reported
Level reading date:	1944-03-07	Feet below surface:	Not Reported
Feet to sea level:	-6.07	Note:	Not Reported
Level reading date:	1944-01-29	Feet below surface:	Not Reported
Feet to sea level:	-5.81	Note:	Not Reported
Level reading date:	1944-01-01	Feet below surface:	Not Reported
Feet to sea level:	-5.90	Note:	Not Reported
Level reading date:	1943-11-27	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1943-10-30	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1943-09-25	Feet below surface:	Not Reported
Feet to sea level:	-6.15	Note:	Not Reported
Level reading date:	1943-08-28	Feet below surface:	Not Reported
Feet to sea level:	-5.96	Note:	Not Reported
Level reading date:	1943-07-31	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1943-06-26	Feet below surface:	Not Reported
Feet to sea level:	-5.77	Note:	Not Reported

Level reading date:	1943-05-29	Feet below surface:	Not Reported
Feet to sea level:	-5.92	Note:	Not Reported
Level reading date:	1943-05-01	Feet below surface:	Not Reported
Feet to sea level:	-6.04	Note:	Not Reported
Level reading date:	1943-03-27	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1943-02-27	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported
Level reading date:	1943-01-30	Feet below surface:	Not Reported
Feet to sea level:	-6.39	Note:	Not Reported
Level reading date:	1943-01-02	Feet below surface:	Not Reported
Feet to sea level:	-6.64	Note:	Not Reported
Level reading date:	1942-12-26	Feet below surface:	Not Reported
Feet to sea level:	-6.55	Note:	Not Reported
Level reading date:	1942-12-19	Feet below surface:	Not Reported
Feet to sea level:	-6.31	Note:	Not Reported
Level reading date:	1942-12-12	Feet below surface:	Not Reported
Feet to sea level:	-6.59	Note:	Not Reported
Level reading date:	1942-12-05	Feet below surface:	Not Reported
Feet to sea level:	-6.70	Note:	Not Reported
Level reading date:	1942-11-28	Feet below surface:	Not Reported
Feet to sea level:	-6.81	Note:	Not Reported
Level reading date:	1942-11-21	Feet below surface:	Not Reported
Feet to sea level:	-6.81	Note:	Not Reported
Level reading date:	1942-11-14	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1942-11-07	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1942-10-31	Feet below surface:	Not Reported
Feet to sea level:	-6.83	Note:	Not Reported
Level reading date:	1942-10-24	Feet below surface:	Not Reported
Feet to sea level:	-6.86	Note:	Not Reported
Level reading date:	1942-10-17	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1942-10-10	Feet below surface:	Not Reported
Feet to sea level:	-6.88	Note:	Not Reported
Level reading date:	1942-10-03	Feet below surface:	Not Reported
Feet to sea level:	-6.90	Note:	Not Reported
Level reading date:	1942-09-26	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported
Level reading date:	1942-09-19	Feet below surface:	Not Reported
Feet to sea level:	-6.91	Note:	Not Reported

Level reading date:	1942-09-12	Feet below surface:	Not Reported
Feet to sea level:	-6.98	Note:	Not Reported
Level reading date:	1942-09-05	Feet below surface:	Not Reported
Feet to sea level:	-7.00	Note:	Not Reported
Level reading date:	1942-08-29	Feet below surface:	Not Reported
Feet to sea level:	-7.08	Note:	Not Reported
Level reading date:	1942-08-22	Feet below surface:	Not Reported
Feet to sea level:	-7.23	Note:	Not Reported
Level reading date:	1942-08-15	Feet below surface:	Not Reported
Feet to sea level:	-7.18	Note:	Not Reported
Level reading date:	1942-08-08	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1942-08-01	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1942-07-18	Feet below surface:	Not Reported
Feet to sea level:	-7.26	Note:	Not Reported
Level reading date:	1942-07-11	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1942-07-04	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1942-06-27	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-06-20	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-06-13	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-06-06	Feet below surface:	Not Reported
Feet to sea level:	-7.49	Note:	Not Reported
Level reading date:	1942-05-30	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-05-23	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1942-05-16	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1942-05-02	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1942-04-25	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1942-04-18	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1942-04-11	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported

Level reading date:	1942-04-04	Feet below surface:	Not Reported
Feet to sea level:	-7.42	Note:	Not Reported
Level reading date:	1942-03-28	Feet below surface:	Not Reported
Feet to sea level:	-7.19	Note:	Not Reported
Level reading date:	1942-03-21	Feet below surface:	Not Reported
Feet to sea level:	-7.27	Note:	Not Reported
Level reading date:	1942-03-07	Feet below surface:	Not Reported
Feet to sea level:	-7.22	Note:	Not Reported
Level reading date:	1942-02-28	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1942-02-21	Feet below surface:	Not Reported
Feet to sea level:	-7.37	Note:	Not Reported
Level reading date:	1942-02-14	Feet below surface:	Not Reported
Feet to sea level:	-7.15	Note:	Not Reported
Level reading date:	1942-02-07	Feet below surface:	Not Reported
Feet to sea level:	-7.10	Note:	Not Reported
Level reading date:	1942-01-24	Feet below surface:	Not Reported
Feet to sea level:	-7.21	Note:	Not Reported
Level reading date:	1942-01-17	Feet below surface:	Not Reported
Feet to sea level:	-6.77	Note:	Not Reported
Level reading date:	1942-01-03	Feet below surface:	Not Reported
Feet to sea level:	-6.77	Note:	Not Reported
Level reading date:	1941-12-27	Feet below surface:	Not Reported
Feet to sea level:	-6.84	Note:	Not Reported
Level reading date:	1941-12-20	Feet below surface:	Not Reported
Feet to sea level:	-6.57	Note:	Not Reported
Level reading date:	1941-12-06	Feet below surface:	Not Reported
Feet to sea level:	-6.85	Note:	Not Reported
Level reading date:	1941-11-29	Feet below surface:	Not Reported
Feet to sea level:	-6.74	Note:	Not Reported
Level reading date:	1941-11-22	Feet below surface:	Not Reported
Feet to sea level:	-6.71	Note:	Not Reported
Level reading date:	1941-11-15	Feet below surface:	Not Reported
Feet to sea level:	-6.11	Note:	Not Reported
Level reading date:	1941-11-08	Feet below surface:	Not Reported
Feet to sea level:	-6.48	Note:	Not Reported
Level reading date:	1941-10-25	Feet below surface:	Not Reported
Feet to sea level:	-6.65	Note:	Not Reported
Level reading date:	1941-10-18	Feet below surface:	Not Reported
Feet to sea level:	-6.55	Note:	Not Reported
Level reading date:	1941-10-11	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported

Level reading date:	1941-10-04	Feet below surface:	Not Reported
Feet to sea level:	-6.58	Note:	Not Reported
Level reading date:	1941-09-27	Feet below surface:	Not Reported
Feet to sea level:	-6.54	Note:	Not Reported
Level reading date:	1941-09-20	Feet below surface:	Not Reported
Feet to sea level:	-6.49	Note:	Not Reported
Level reading date:	1941-09-13	Feet below surface:	Not Reported
Feet to sea level:	-6.22	Note:	Not Reported
Level reading date:	1941-09-06	Feet below surface:	Not Reported
Feet to sea level:	-6.43	Note:	Not Reported
Level reading date:	1941-08-30	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported
Level reading date:	1941-08-23	Feet below surface:	Not Reported
Feet to sea level:	-6.28	Note:	Not Reported
Level reading date:	1941-08-16	Feet below surface:	Not Reported
Feet to sea level:	-6.40	Note:	Not Reported
Level reading date:	1941-08-09	Feet below surface:	Not Reported
Feet to sea level:	-6.29	Note:	Not Reported
Level reading date:	1941-08-02	Feet below surface:	Not Reported
Feet to sea level:	-6.19	Note:	Not Reported
Level reading date:	1941-07-26	Feet below surface:	Not Reported
Feet to sea level:	-6.17	Note:	Not Reported
Level reading date:	1941-07-19	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1941-07-12	Feet below surface:	Not Reported
Feet to sea level:	-6.10	Note:	Not Reported
Level reading date:	1941-07-05	Feet below surface:	Not Reported
Feet to sea level:	-6.02	Note:	Not Reported
Level reading date:	1941-06-28	Feet below surface:	Not Reported
Feet to sea level:	-6.01	Note:	Not Reported
Level reading date:	1941-06-21	Feet below surface:	Not Reported
Feet to sea level:	-5.86	Note:	Not Reported
Level reading date:	1941-06-14	Feet below surface:	Not Reported
Feet to sea level:	-5.92	Note:	Not Reported
Level reading date:	1941-06-07	Feet below surface:	Not Reported
Feet to sea level:	-5.82	Note:	Not Reported
Level reading date:	1941-05-31	Feet below surface:	Not Reported
Feet to sea level:	-5.76	Note:	Not Reported
Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-5.70	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-5.73	Note:	Not Reported

Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-5.19	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-5.68	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-5.41	Note:	Not Reported
Level reading date:	1937-06-15	Feet below surface:	Not Reported
Feet to sea level:	-4.28	Note:	Not Reported
Level reading date:	1937-03-23	Feet below surface:	Not Reported
Feet to sea level:	-3.77	Note:	Not Reported
Level reading date:	1937-02-02	Feet below surface:	Not Reported
Feet to sea level:	-3.97	Note:	Not Reported
Level reading date:	1936-12-29	Feet below surface:	Not Reported
Feet to sea level:	-3.70	Note:	Not Reported
Level reading date:	1936-09-24	Feet below surface:	Not Reported
Feet to sea level:	-4.70	Note:	Not Reported
Level reading date:	1936-07-21	Feet below surface:	Not Reported
Feet to sea level:	-4.14	Note:	Not Reported
Level reading date:	1936-06-11	Feet below surface:	Not Reported
Feet to sea level:	-4.04	Note:	Not Reported
Level reading date:	1936-04-20	Feet below surface:	Not Reported
Feet to sea level:	-3.68	Note:	Not Reported
Level reading date:	1936-03-16	Feet below surface:	Not Reported
Feet to sea level:	-3.75	Note:	Not Reported
Level reading date:	1935-12-11	Feet below surface:	Not Reported
Feet to sea level:	-4.31	Note:	Not Reported
Level reading date:	1935-10-24	Feet below surface:	Not Reported
Feet to sea level:	-4.37	Note:	Not Reported
Level reading date:	1935-09-13	Feet below surface:	Not Reported
Feet to sea level:	-4.42	Note:	Not Reported
Level reading date:	1935-07-01	Feet below surface:	Not Reported
Feet to sea level:	-3.73	Note:	Not Reported
Level reading date:	1935-05-28	Feet below surface:	Not Reported
Feet to sea level:	-3.51	Note:	Not Reported
Level reading date:	1935-04-01	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1935-03-04	Feet below surface:	Not Reported
Feet to sea level:	-2.99	Note:	Not Reported
Level reading date:	1935-01-02	Feet below surface:	Not Reported
Feet to sea level:	-3.14	Note:	Not Reported
Level reading date:	1934-12-07	Feet below surface:	Not Reported
Feet to sea level:	-3.07	Note:	Not Reported

Level reading date:	1934-11-09	Feet below surface:	Not Reported
Feet to sea level:	-2.58	Note:	Not Reported
Level reading date:	1934-10-18	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1934-09-20	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1934-08-21	Feet below surface:	Not Reported
Feet to sea level:	-3.47	Note:	Not Reported
Level reading date:	1934-08-01	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1934-07-09	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1934-06-13	Feet below surface:	Not Reported
Feet to sea level:	-3.32	Note:	Not Reported
Level reading date:	1934-04-11	Feet below surface:	Not Reported
Feet to sea level:	-2.82	Note:	Not Reported
Level reading date:	1934-03-22	Feet below surface:	Not Reported
Feet to sea level:	-2.41	Note:	Not Reported
Level reading date:	1934-01-09	Feet below surface:	Not Reported
Feet to sea level:	-2.90	Note:	Not Reported
Level reading date:	1933-12-11	Feet below surface:	Not Reported
Feet to sea level:	-2.67	Note:	Not Reported
Level reading date:	1933-11-22	Feet below surface:	Not Reported
Feet to sea level:	-2.73	Note:	Not Reported
Level reading date:	1933-11-02	Feet below surface:	Not Reported
Feet to sea level:	-2.37	Note:	Not Reported
Level reading date:	1933-09-28	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1933-08-29	Feet below surface:	Not Reported
Feet to sea level:	-2.85	Note:	Not Reported
Level reading date:	1933-07-25	Feet below surface:	Not Reported
Feet to sea level:	-2.60	Note:	Not Reported
Level reading date:	1933-06-28	Feet below surface:	Not Reported
Feet to sea level:	-2.43	Note:	Not Reported
Level reading date:	1933-05-29	Feet below surface:	Not Reported
Feet to sea level:	-2.44	Note:	Not Reported
Level reading date:	1933-04-21	Feet below surface:	Not Reported
Feet to sea level:	-2.02	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX H
VAPOR ENCROACHMENT SCREENING

Broadway Junction Properties
45 Van Sinderen Avenue
Brooklyn, NY 11207

Inquiry Number: 7931531.2s
April 10, 2025

EDR Vapor Encroachment Screen

Prepared using EDR's Vapor Encroachment Worksheet

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Primary Map	**2**
Secondary Map	**3**
Map Findings	**4**
Record Sources and Currency	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR Vapor Encroachment Worksheet enables EDR's customers to make certain online modifications that effects maps, text and calculations contained in this Report. As a result, maps, text and calculations contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. Environmental Data Resources shall not be responsible for any customer's decision to include or not include in any final report any records determined to be within the relevant minimum search distances.

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by EDR. The report was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property Involved in Real Estate Transactions (E 2600).

STANDARD ENVIRONMENTAL RECORDS	Default Area of Concern (Miles)*	property	1/10	> 1/10
Lists of Federal NPL (Superfund) sites	1.0	0	0	0
Lists of Federal Delisted NPL sites	1.0	0	0	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders	0.5	0	0	0
Lists of Federal CERCLA sites with NFRAP	0.5	0	0	0
Lists of Federal RCRA facilities undergoing Corrective Action	1.0	0	0	0
Lists of Federal RCRA TSD facilities	0.5	0	0	0
Lists of Federal RCRA generators	0.25	0	0	0
Federal institutional controls / engineering controls registries	0.5	0	0	0
Federal ERNS list	property	0	-	-
Lists of state- and tribal (Superfund) equivalent sites	not searched	-	-	-
Lists of state- and tribal hazardous waste facilities	1.0	0	0	0
Lists of state and tribal landfills and solid waste disposal facilities	0.5	0	0	0
Lists of state and tribal leaking storage tanks	0.5	0	0	0
Lists of state and tribal registered storage tanks	0.5	0	0	0
State and tribal institutional control / engineering control registries	0.5	0	0	0
Lists of state and tribal voluntary cleanup sites	0.5	0	0	0
Lists of state and tribal brownfield sites	0.5	0	0	0

ADDITIONAL ENVIRONMENTAL RECORDS				
Local Brownfield lists	0.5	0	0	0
Local Lists of Landfill / Solid Waste Disposal Sites	0.5	0	0	0
Local Lists of Hazardous waste / Contaminated Sites	1.0	0	0	0
Local Lists of Registered Storage Tanks	0.25	0	0	0
Local Land Records	property	0	-	-
Records of Emergency Release Reports	0.125	0	0	0
Other Ascertainable Records	1.0	0	0	0

EDR HIGH RISK HISTORICAL RECORDS				
EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	property	0	-	-

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	property	0	-	-

*The Default Area of Concern may be adjusted by the environmental professional using experience and professional judgement. Each category may include several databases, and each database may have a different distance. A list of individual databases is provided at the back of this report.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

BROADWAY JUNCTION PROPERTIES
45 VAN SINDEREN AVENUE
BROOKLYN, NY 11207

COORDINATES

Latitude (North):	40.676539 - 40° 40′ 35.54535″
Longitude (West):	73.903116 - 73° 54′ 11.211548″
Elevation:	70 ft. above sea level

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records.

EXECUTIVE SUMMARY

SEARCH RESULTS

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page

Not Reported

ADDITIONAL ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page

Not Reported

EDR HIGH RISK HISTORICAL RECORDS

Name	Address	Dist/Dir	Map ID	Page


Not Reported

EDR RECOVERED GOVERNMENT ARCHIVES

Name	Address	Dist/Dir	Map ID	Page

Not Reported

PRIMARY MAP - 7931531.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

Pipelines

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Broadway Junction Properties	CLIENT:	P.W. Grosser Consulting
ADDRESS:	45 Van Sinderen Avenue Brooklyn NY 11207	CONTACT:	Michael Pecoraro
LAT/LONG:	40.676539 / 73.903116	INQUIRY #:	7931531.2s
		DATE:	March 19, 2025 3:33 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

SECONDARY MAP - 7931531.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Broadway Junction Properties	CLIENT:	P.W. Grosser Consulting
ADDRESS:	45 Van Sinderen Avenue Brooklyn NY 11207	CONTACT:	Michael Pecoraro
LAT/LONG:	40.676539 / 73.903116	INQUIRY #:	7931531.2s
		DATE:	March 19, 2025 3:32 pm

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS

LEGEND

FACILITY NAME **FACILITY ADDRESS, CITY, ST, ZIP**			EDR SITE ID NUMBER
◆ **MAP ID#**	Direction Distance Range Relative Elevation	(Distance feet / miles) Feet Above Sea Level	ASTM 2600 Record Sources found in this report. Each database searched has been assigned to one or more categories. For detailed information about categorization, see the section of the report Records Searched and Currency.

Worksheet:

Comments:

Comments may be added on the online Vapor Encroachment Worksheet.

DATABASE ACRONYM: Applicable categories (A hoverbox with database description).

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
ENVIRONMENTAL RECORDS						
Federal NPL site list						
US	NPL	National Priority List	EPA	12/19/2024	01/02/2025	01/21/2025
US	Proposed NPL	Proposed National Priority List Sites	EPA	12/19/2024	01/02/2025	01/21/2025
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
Federal CERCLIS list						
US	SEMS	Superfund Enterprise Management System	EPA	12/19/2024	01/02/2025	01/21/2025
Federal RCRA CORRACTS facilities list						
US	CORRACTS	Corrective Action Report	EPA	02/17/2025	02/19/2025	03/06/2025
Federal RCRA TSD facilities list						
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	02/17/2025	02/19/2025	03/06/2025
Federal RCRA generators list						
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	02/17/2025	02/19/2025	03/06/2025
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	02/17/2025	02/19/2025	03/06/2025
US	RCRA-VSQG	RCRA - Very Small Quantity Generators (Formerly Conditionall	Environmental Protection Agency	02/17/2025	02/19/2025	03/06/2025
Federal institutional controls / engineering controls registries						
US	LUCIS	Land Use Control Information System	Department of the Navy	11/11/2024	11/25/2024	02/18/2025
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	11/04/2024	11/15/2024	02/11/2025
US	US INST CONTROLS	Institutional Controls Sites List	Environmental Protection Agency	11/04/2024	11/15/2024	02/11/2025
Federal ERNS list						
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	12/03/2024	12/11/2024	02/18/2025
State and tribal - equivalent CERCLIS						
NY	SHWS	Inactive Hazardous Waste Disposal Sites in New York State	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
State and tribal landfill / solid waste disposal						
NY	SWF/LF	Facility Register	Department of Environmental Conservation	12/11/2024	12/17/2024	12/27/2024
State and tribal leaking storage tank lists						
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	05/07/2024	05/30/2024	08/28/2024
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	05/07/2024	05/30/2024	08/28/2024
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	05/07/2024	05/30/2024	08/28/2024
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	05/07/2024	05/30/2024	08/28/2024
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	04/11/2024	05/30/2024	08/28/2024
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	05/07/2024	05/30/2024	08/28/2024
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	05/07/2024	05/30/2024	08/28/2024
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	05/07/2024	05/30/2024	08/28/2024
NY	LTANKS	Spills Information Database	Department of Environmental Conservation	11/03/2024	11/05/2024	12/05/2024
NY	HIST LTANKS	Listing of Leaking Storage Tanks	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
State and tribal registered storage tank lists						
NY	TANKS	Storage Tank Faciliy Listing	Department of Environmental Conservation	12/12/2024	12/12/2024	03/03/2025
NY	UST	Petroleum Bulk Storage (PBS) Database	Department of Environmental Conservation	12/12/2024	12/12/2024	02/28/2025
NY	CBS UST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF UST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	AST	Petroleum Bulk Storage	Department of Environmental Conservation	12/12/2024	12/12/2024	02/28/2025
NY	CBS AST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF AST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	CBS	Chemical Bulk Storage Site Listing	Department of Environmental Conservation	12/12/2024	12/12/2024	03/03/2025
NY	MOSF	Major Oil Storage Facility Site Listing	Department of Environmental Conservation	12/12/2024	12/12/2024	03/03/2025
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	05/14/2024	05/30/2024	08/28/2024
US	INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	05/14/2024	05/30/2024	08/28/2024
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	05/14/2024	05/30/2024	08/28/2024
US	INDIAN UST R7	Underground Storage Tanks on Indian Land	EPA Region 7	05/14/2024	05/30/2024	08/28/2024
US	INDIAN UST R6	Underground Storage Tanks on Indian Land	EPA Region 6	05/14/2024	05/30/2024	08/28/2024
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 5	04/11/2024	05/30/2024	08/28/2024
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	05/14/2024	05/30/2024	08/28/2024
US	INDIAN UST R8	Underground Storage Tanks on Indian Land	EPA Region 8	05/14/2024	05/30/2024	08/28/2024
US	FEMA UST	Underground Storage Tank Listing	FEMA	08/12/2024	10/30/2024	01/14/2025
State and tribal institutional control / engineering control registries						
NY	RES DECL	Restrictive Declarations Listing	NYC Department of City Planning	12/04/2024	12/09/2024	03/03/2025
NY	ENV RES DECL	Environmental Restrictive Declarations	New York City Department of City Planning	12/06/2024	12/11/2024	03/03/2025
NY	ENG CONTROLS	Registry of Engineering Controls	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
NY	INST CONTROL	Registry of Institutional Controls	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
State and tribal voluntary cleanup sites						
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008
NY	VCP NYC	Voluntary Cleanup Program Listing NYC	New York City Office of Environmental Protect	12/02/2024	12/04/2024	02/25/2025
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
NY	VCP	Voluntary Cleanup Agreements	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
State and tribal Brownfields sites						
NY	BROWNFIELDS	Brownfields Site List	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
NY	ERP	Environmental Restoration Program Listing	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
Other Records						
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	09/30/2024	10/09/2024	01/10/2025
US	ROD	Records Of Decision	EPA	01/29/2025	02/03/2025	02/27/2025
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	12/19/2024	01/02/2025	01/21/2025
NY	DEL SHWS	Delisted Registry Sites	Department of Environmental Conservation	11/04/2024	11/05/2024	01/22/2025
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
NY	SWRCY	Registered Recycling Facility List	Department of Environmental Conservation	12/11/2024	12/17/2024	12/27/2024
NY	SWTIRE	Registered Waste Tire Storage & Facility List	Department of Environmental Conservation	02/27/2018	04/06/2018	06/08/2018
NY	HIST UST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006
NY	HIST AST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	EPA WATCH LIST	EPA Watch List	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2023	10/16/2024	01/14/2025
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	02/17/2025	02/19/2025	03/06/2025
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	12/19/2024	01/02/2025	01/21/2025
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	03/03/2023	03/03/2023	06/09/2023
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	01/12/2017	03/05/2019	11/11/2019
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (	EPA	10/12/2016	10/26/2016	02/03/2017
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	09/13/2019	11/06/2019	02/10/2020
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	07/30/2021	02/03/2023	02/10/2023
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	05/20/2024	08/19/2024	10/09/2024
US	Delisted NPL	National Priority List Deletions	EPA	12/19/2024	01/02/2025	01/21/2025
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	12/19/2024	01/02/2025	01/21/2025
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	02/17/2025	02/19/2025	03/06/2025
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	12/10/2024	12/11/2024	02/27/2025
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	10/04/2024	10/16/2024	12/06/2024
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	05/20/2024	08/19/2024	10/09/2024
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	09/09/2024	09/11/2024	12/06/2024
US	DOD	Department of Defense Sites	USGS	06/07/2021	07/13/2021	03/09/2022
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	04/02/2018	04/11/2018	11/06/2019
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	10/01/2024	11/12/2024	01/21/2025
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	02/12/2025	02/12/2025	02/27/2025
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	11/01/2024	11/18/2024	02/11/2025
US	MINES VIOLATIONS	MSHA Violation Assessment Data	DOL, Mine Safety & Health Admi	10/01/2024	10/02/2024	10/09/2024
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	05/02/2024	08/20/2024	10/09/2024
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
US	PRP	Potentially Responsible Parties	EPA	09/19/2023	10/03/2023	10/19/2023
US	TRIS	Toxic Chemical Release Inventory System	EPA	12/31/2023	02/11/2025	02/18/2025
US	TSCA	Toxic Substances Control Act	EPA	12/31/2020	06/14/2022	03/24/2023
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	SSTS	Section 7 Tracking Systems	EPA	10/15/2024	10/16/2024	01/14/2025
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	PADS	PCB Activity Database System	EPA	07/01/2024	10/02/2024	01/10/2025
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	10/12/2024	10/17/2024	11/19/2024
US	RADINFO	Radiation Information Database	Environmental Protection Agency	07/01/2019	07/01/2019	09/23/2019
US	FINDS	Facility Index System/Facility Registry System	EPA	11/11/2024	11/20/2024	02/18/2025
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RMP	Risk Management Plans	Environmental Protection Agency	10/01/2024	10/23/2024	01/14/2025
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2023	02/19/2025	03/07/2025
US	PWS	Public Water System Data	EPA	12/17/2013	01/09/2014	10/15/2014
US	INDIAN RESERV	Indian Reservations	USGS	12/31/2014	07/14/2015	01/10/2017

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	02/07/2024	11/13/2024	11/19/2024
US	ABANDONED MINES	Abandoned Mines	Department of Interior	12/10/2024	12/11/2024	02/18/2025
NY	AIRS	Air Emissions Data	Department of Environmental Conservation	10/09/2024	11/05/2024	11/21/2024
NY	COAL ASH	Coal Ash Disposal Site Listing	Department of Environmental Conservation	12/18/2024	12/18/2024	03/10/2025
NY	PFAS 3	PFAS Environmental Site Remediation List	Department of Environmental Conservation	11/04/2024	11/06/2024	01/22/2025
NY	PFAS 2	New York State Inactive Landfill Initiative	Department of Environmental Conservation	12/12/2022	08/10/2023	10/25/2023
NY	DRYCLEANERS	Registered Drycleaners	Department of Environmental Conservation	11/27/2024	12/09/2024	03/03/2025
NY	E DESIGNATION	E DESIGNATION SITE LISTING	New York City Department of City Planning	10/07/2024	12/19/2024	03/11/2025
NY	FIN ASSURANCE 1	Financial Assurance Information Listing	Department of Environmental Conservation	12/11/2024	12/18/2024	01/22/2025
NY	FIN ASSURANCE 2	Financial Assurance Information Listing	Department of Environmental Conservation	08/30/2024	08/30/2024	09/13/2024
NY	HIST SPILLS	SPILLS Database	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005
NY	HSWDS	Hazardous Substance Waste Disposal Site Inventory	Department of Environmental Conservation	01/01/2003	10/20/2006	11/30/2006
NY	LIENS	Spill Liens Information	Office of the State Comptroller	10/28/2024	10/29/2024	01/22/2025
NY	NY MANIFEST	Facility and Manifest Data	Department of Environmental Conservation	12/31/2019	11/30/2023	12/01/2023
NY	SPDES	State Pollutant Discharge Elimination System	Department of Environmental Conservation	10/10/2024	11/08/2024	12/02/2024
NY	SPILLS	Spills Information Database	Department of Environmental Conservation	11/03/2024	11/05/2024	12/05/2024
NY	SPILLS 80	SPILLS80 data from FirstSearch	FirstSearch	11/02/2010	01/03/2013	03/07/2013
NY	SPILLS 90	SPILLS90 data from FirstSearch	FirstSearch	12/14/2012	01/03/2013	02/12/2013
NY	UIC	Underground Injection Control Wells	Department of Environmental Conservation	11/19/2024	11/20/2024	02/14/2025
NY	VAPOR REOPENED	Vapor Intrusion Legacy Site List	Department of Environmenal Conservation	01/01/2022	02/08/2022	05/06/2022
US	UXO	Unexploded Ordnance Sites	Department of Defense	09/06/2023	09/13/2023	12/11/2023
US	E MANIFEST	Hazardous Waste Electronic Manifest System	Environmental Protection Agency	02/17/2025	02/19/2025	03/14/2025
US	BIOSOLIDS	ICIS-NPDES Biosolids Facility Data	Environmental Protection Agency	10/13/2024	10/16/2024	10/23/2024
US	AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PCS	Permit Compliance System	EPA, Office of Water	12/16/2016	01/06/2017	03/10/2017
US	UST FINDER RELEASE	UST Finder Releases Database	Environmental Protecton Agency	06/08/2023	10/31/2023	01/18/2024
US	UST FINDER	UST Finder Database	Environmental Protection Agency	06/08/2023	10/04/2023	01/18/2024
US	PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PFAS TRIS	List of PFAS Added to the TRI	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PFAS NPL	Superfund Sites with PFAS Detections Information	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PFAS PROJECT	NORTHEASTERN UNIVERSITY PFAS PROJECT	Social Science Environmental Health Research	05/19/2023	04/05/2024	06/06/2024
NY	ILI	New York State Inactive Landfill Initiative	Department of Environmental Conservation	05/16/2024	05/30/2024	08/26/2024
NY	NYC LEAD 2	Recent Lead Paint Violations	New York City Department of Housing Preservat	10/28/2024	10/30/2024	01/22/2025
NY	NYC LAND USE	New York City Land Use Information	New York City Department of City Planning	09/30/2024	12/09/2024	03/06/2025
US	PFAS NPDES	Clean Water Act Discharge Monitoring Information	Environmental Protection Agency	12/30/2024	01/02/2025	01/14/2025
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	11/08/2024	11/08/2024	01/14/2025
US	PFAS FEDERAL SITES	Federal Sites PFAS Information	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PFAS ECHO FIRE TRAIN	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PFAS PT 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
NY	PFAS	PFAS Contamination Site Location Listing	Department of Environmental Conservation	01/16/2019	05/08/2019	06/24/2019
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	12/21/2024	12/27/2024	01/10/2025
US	PFAS WQP	Ambient Environmental Sampling for PFAS	Environmental Protection Agency	12/13/2024	01/02/2025	01/10/2025
US	PFAS TSCA	PFAS Manufacture and Imports Information	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
US	PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	12/30/2024	01/02/2025	01/10/2025
NY	COOLING TOWERS	Registered Cooling Towers	Department of Health	10/01/2024	10/08/2024	12/23/2024
US	MINES MRDS	Mineral Resources Data System	USGS	06/04/2024	11/22/2024	02/18/2025

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	11/20/2024	12/18/2024	12/20/2024
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/06/2021	05/21/2021	08/11/2021
US	PFAS ATSDR	PFAS Contamination Site Location Listing	Department of Health & Human Services	06/24/2020	03/17/2021	11/08/2022
NY	NYC LEAD	Lead-based Paint Testing Results	New York City Department of Education	07/10/2024	07/30/2024	10/17/2024
NY	MGP	Manufactured Gas Plants Listing	Department of Environmental Conservation	12/02/2024	12/03/2024	02/25/2025
NY	NYC OER	OER Cleanup Sites Listing	Office of Environmental Remediation	12/02/2024	12/04/2024	02/25/2025
HISTORICAL USE RECORDS						
US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
NY	RGA HWS	Recovered Government Archive State Hazardous Waste Facilitie	Department of Environmental Conservation		07/01/2013	12/30/2013
NY	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Environmental Conservation		07/01/2013	01/10/2014
COUNTY RECORDS						
NY	AST - CORTLAND	Cortland County Storage Tank Listing	Cortland County Health Department	08/20/2019	08/20/2019	10/16/2019
NY	UST - CORTLAND	Cortland County Storage Tank Listing	Cortland County Health Department	08/20/2019	08/20/2019	10/16/2019
NY	AST - NASSAU	Registered Tank Database	Nassau County Health Department	11/27/2023	11/28/2023	02/06/2024
NY	AST NCFM	Storage Tank Database	Nassau County Office of the Fire Marshal	02/15/2011	02/23/2011	03/29/2011
NY	TANKS NASSAU	Registered Tank Database in Nassau County	Nassau County Department of Health	11/27/2023	11/28/2023	02/06/2024
NY	UST - NASSAU	Registered Tank Database	Nassau County Health Department	11/27/2023	11/28/2023	02/06/2024
NY	UST NCFM	Storage Tank Database	Nassau County Office of the Fire Marshal	02/15/2011	02/23/2011	03/29/2011
NY	AST - ROCKLAND	Petroleum Bulk Storage Database	Rockland County Health Department	02/02/2017	03/17/2017	09/22/2017
NY	UST - ROCKLAND	Petroleum Bulk Storage Database	Rockland County Health Department	02/02/2017	03/17/2017	09/22/2017
NY	AST - SUFFOLK	Storage Tank Database	Suffolk County Department of Health Services	06/28/2018	12/06/2018	02/07/2019
NY	TANKS SUFFOLK	Storage Tank Database	Department of Health Services	06/28/2018	02/05/2019	03/08/2019
NY	UST - SUFFOLK	Storage Tank Database	Suffolk County Department of Health Services	06/28/2018	12/06/2018	02/07/2019
NY	AST - WESTCHESTER	Listing of Storage Tanks	Westchester County Department of Health	11/13/2024	11/14/2024	02/07/2025
NY	UST - WESTCHESTER	Listing of Storage Tanks	Westchester County Department of Health	11/13/2024	11/14/2024	02/07/2025

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX I
PUBLIC RECORDS

Property Report by PropertyShark.com, for:

45 Van Sinderen Ave, Brooklyn, NY 11207

General

1. Overview

Address

Property address	**45 Van Sinderen Ave**
Zip code	**11207**
Neighborhood	**Ocean Hill**
Borough	**Brooklyn**
Block & lot	**01576-0001**

Owner

Name	**2465 Atlantic LLC**
Address	**478 Albany Ave #110 Brooklyn, NY 11203**
Real Owners	
Purchase date	**01/24/2018**
Purchase price	**$3,300,000**
Special factors	**Multiple parcels**
Arm's length	**Yes**

Property Taxes

Tax class	**4**
Property tax	**$31,150**
Property tax tentative	**$32,137**

Lot

Lot sqft	**13,110**
Lot dimensions	**138 ft x 95 ft**
Ground elevation	**69 ft**
Corner lot	**No**

Zoning

Zoning districts	**M1-2**
Zoning map	**17c**
Qualified opportunity zone	**Yes (map)**

Building

Building class	**Fireproof Warehouse (E1)**
Square feet	**8,000**
Building dimensions	**55 ft x 85 ft**
Buildings on lot	**1**
Stories	**2**
Roof height	**25 ft**
Year built	**1921**
Structure type	**Miscellaneous factory**
Construction type	**Masonry**
Grade	**C**

Use

Commercial units	**1**
Storage sqft	**8,000**

Floor Area Ratio (FAR)

Commercial FAR	**2**
Facility FAR	**4.8**
FAR as built	**0.61**
Maximum usable floor area	**26,220**
Usable floor area as built	**7,997**
Unused FAR	**18,223**

Violations


DOB violations	**2**

2. Photos



Uploaded in May, 2012 by Christopher Bride

3. Maps



Community district	**5**	Closest police station	**0.63 Miles**
School district	**23**	Closest fire station	**0.45 Miles**
Census tract	**367**	Tax map	**30603**
Lat long	**40.67653, -73.90311**	Sanborn map	**307 013**

4. Web Mentions

Recorded	Publisher	Article
11/29/2023	www.brownstoner.com	Rezoning for Towers in Broadway Junction Area Inches Forward

Preview: ...neglect of resources, so already theres like OK whats really at play here. 45 Van Sinderen Avenue would be demolished The other factor is what Wilkins called the Manhattan-ization...

Units

1. Units & Related Parcels

This is the property report for the cooperative building located at **45 Van Sinderen Ave, Brooklyn, NY 11207**(1 unit). To view the report for an individual unit, select it from the list below.

All buildings and entrances:

Unit/Tax lot	Owner	Purchase date	Purchase price	Sqft	Price/sqft
Unit 15D					

Contacts

1. Real Owners

Access manually researched real owner contact info for all LLC-owned properties in NYC. We closely monitor all deeds, with new data extracted daily. We have manually researched phone contact information for the owner of this property.



Upgrade

Name

Phone

Address

E-mail

to unlock Real Owners and their phone numbers.

2. Registered Owner

2465 Atlantic LLC

478 Albany Ave #110
Brooklyn, NY 11203
Source: Assessment Roll
Last recorded: 12/15/2024

Add to address book

Ownership data is aggregated from governmental sources like deeds and the assessment roll. If the registered owner is an LLC or other form of company, use our Real Owners service to find the person behind the company.

Valuation

1. Last Sale

Purchase date	**01/24/2018**
Purchase price	**$3,300,000**
Special factors	**Multiple parcels**
Arm's length	**Yes**

2. Assessment History

Year	Building class	Market value	Assessed value	Taxable	Tax rate%	Base tax	Property tax
2024/25	E1	$731,000	$328,950	$289,440	10.762%	$31,150	$31,150
2023/24	E1	$687,000	$309,150	$278,640	10.592%	$29,514	$29,514
2022/23	E1	$637,000	$286,650	$267,030	10.646%	$28,428	$28,428
2021/22	E1	$530,000	$238,500	$238,500	10.755%	$25,651	$25,651
2020/21	E1	$631,000	$283,950	$244,980	10.694%	$26,198	$26,198
2019/20	E1	$611,000	$274,950	$225,000	10.537%	$23,708	$23,708
2018/19	E1	$558,000	$251,100	$206,910	10.514%	$21,755	$21,755
2017/18	E1	$492,000	$221,400	$188,917	10.514%	$19,863	$19,863
2016/17	E9	$430,000	$193,500	$175,055	10.574%	$18,510	$18,510
2015/16	E9	$409,000	$184,050	$166,775	10.656%	$17,772	$17,772
2014/15	E9	$410,000	$184,500	$155,705	10.684%	$16,636	$16,636
2013/14	E9	$358,060	$161,127	$144,815	10.323%	$14,949	$14,949
2012/13	E9	$338,000	$152,100	$138,510	10.228%	$14,167	$14,167
2011/12	E9	$338,000	$152,100	$126,450	10.152%	$12,837	$12,837
2010/11	E9	$286,000	$128,700	$110,340	10.312%	$11,378	$11,378

Documents

1. Deed Summary

Our dedicated team has manually researched over 500,000 documents to identify partial interest transfers, arm's length and non-arm's length transactions. We continue to verify transactions as they happen, so you can be sure that the sale accurately represents the fair market value of the property.

Contract date	Party 1	Party 2	Arm`s length	Transfer conditions	Amount	Doc image
11/28/2017	Apex Airtronics, INC. , C/O Richard H Rosenblum Esq Van Atlantic Management CORP, C/O Richard H Rosenblum Esq	2465 Atlantic LLC, Attn Yehuda Simpson	Yes	• Arm's Length Sale • Package Deal	$3,300,000 **(M)**	

2. Title Documents

Export to Excel (10 records)

Date	Type	Amount	Party 1	Party 2	Doc image
12/19/2018 - R	Initial UCC1 (2018121700583007) - **M**		2465 Atlantic LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203 Fulton Junction LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203	Metropolitan Commercial Bank 99 Park Avenue 4th Floor New York NY 10016	
12/05/2018 - D 12/19/2018 - R	Assignment of leases and rents (2018121700583006) - **M**	$3,100,000	2465 Atlantic LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203 Fulton Junction LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203	Metropolitan Commercial Bank 99 Park Avenue 4th Floor New York NY 10016	
12/05/2018 - D 12/19/2018 - R	Agreement (2018121700583005) - **M**	$3,100,000	2465 Atlantic LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203 Fulton Junction LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203	Metropolitan Commercial Bank 99 Park Avenue 4th Floor New York NY 10016	
12/05/2018 - D 12/19/2018 - R	Mortgage (2018121700583004) - **M**	$955,000	2465 Atlantic LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203 Fulton Junction LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203	Metropolitan Commercial Bank 99 Park Avenue 4th Floor New York NY 10016	
12/05/2018 - D 12/19/2018 - R	Assignment, mortgage (2018121700583003) - **M**		Arnav Industries INC Profit Sharing Plan Trust 441 West End Avenue Suite 1a New York NY 10024	Metropolitan Commercial Bank 99 Park Avenue 4th Floor New York NY 10016	
12/05/2018 - D 12/19/2018 - R	Termination of assign of L&R (2018121700583002) - **M**		Arnav Industries INC Profit Sharing Plan Trust 441 West End Avenue Suite 1a New York NY 10024	2465 Atlantic LLC NY	
01/24/2018 - D 01/31/2018 - R	Assignment of leases and rents (2018013000926003) - **M**	$2,145,000	2465 Atlantic LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203	Arnav Industries INC Profit Sharing Plan and Tru 441 West End Avenue Suite 1a New York NY 10024	
01/24/2018 - D 01/31/2018 - R	Mortgage (2018013000926002) - **M**	$2,145,000	2465 Atlantic LLC 478 Albany Avenue Suite 133 Brooklyn NY 11203	Arnav Industries INC Profit Sharing Plan and Tru 441 West End Avenue Suite	

Date	Type	Amount	Party 1	Party 2	Doc image
				1a New York NY 10024	
01/24/2018 - D 01/31/2018 - R	Deed (2018013000926001) - **M**	$3,300,000	Apex Airtronics INC C/O: Richard H Rosenblum Esq PO Box 1150 Briarcliff Manor NY 10510 Van Atlantic Management CORP C/O: Richard H Rosenblum Esq PO Box 1150 Briarcliff Manor NY 10510	2465 Atlantic LLC Attn: Yehuda Simpson 478 Albany Avenue Suite 133 Brooklyn NY 11203	
08/19/1983 - D 08/29/1983 - R	Deed (3730000975173)		Amthor Testing Instrumt	Van Atlantic Managemt Cp	

R: Record date
D: Document date

Financials

1. Debt Service Coverage Ratio

Get Platinum to unlock the property debt service coverage ratio.

2. Mortgage Summary

Origination date	Lender(s)	Amount	Loan type	Lien position	Maturity date	Doc image
🔒	🔒	🔒	🔒	🔒	🔒	🔒

to unlock the property's mortgage balance, maturity date, interest rate and much more.

3. Income and Expenses

Owners of income-producing properties that have an actual assessed value of more than $40,000 are required to file annual Real Property Income and Expense (RPIE) statements with the Department of Finance(DOF). The DOF uses the information from these statements, or data from comparables, to estimate the market value of a property for tax purposes.

Year	Residential units	Commercial units	Total units	Residential sqft	Commercial sqft	Total sqft	Capitalization rate	Estimated gross income	Estim expe
2026		1			8,000		14.313%	$143,547	$5
2025		1			8,000		14.236%	$137,224	$4
2024		1			8,000		14.261%	$123,844	$4
2021		1			8,000		14.492%	$101,153	$3
2020		1			8,000		14.222%	$108,080	$3
2018		1			8,000		14.771%	$88,880	$2
2017		1			5,900			$70,446	$1

Occupancy

Taxes

1. Tax Bill


Property tax bill for 7/1/2024 to 6/30/2025	**$31,150**
Estimated property tax bill for 7/1/2025 to 6/30/2026	**$32,137**

2. Key Values in Calculating the Bill

Tax class	**4**
Market value	**$731,000**
Assessed value	**$328,950**
Exemptions granted by city	**$0**
Transitional value	**$289,440**
Transitional exemption value	**$0**
Tax abatements	**$0**

3. Assessed Value Evolution

The state law requires to phase in any changes to the assessed value over a five-year period. In any given year, multiple transitions are being applied to the property, which result in different assessed and transitional values each year. The law requires the use of the lowest value between the two - assessed or transitional - to calculate the property tax bill.Please note that assessment changes due to physical alterations/renovations to the property are not phased in. Additionally, if a tax class change has occurred in the past two years, we are unable to estimate value increases for the next 5 years.



4. Assessment Reductions & Open Petitions

New York City's Tax Commission is responsible for reviewing and determining the annual applications for corrections of assessments. Owners and other parties with legal interest can claim that they are incorrectly assessed or improperly denied an exemption from real property tax. There are four types of assessment claims subject to review and corrective action: excessive assessment, misclassification, unequal assessment and unlawful assessment. More information can be found on New York City Tax Commission website.

Open Petitions

If relief from tax commission is not obtained, the owner or other party with legal interest can file a petition with the New York State Supreme Court to keep the appeal open for further review. The information shown here represents only open petitions. The ones that are invalid or abandoned are closed.

Petition year	Index number	Petitioner	Attorney	Description
2020	405235/2019	2465 Atlantic LLC	Brandt Steinberg Lewis & Blond LLP	Fifth-year extension under RPTL Â§718 agreed to with the Law Department

5. Property Tax Calculation

Market Value

The first step is for the City Assessor to determine the *market value* of the property. While the term *market value* would seemingly refer to how much the property would sell for on the open market, in reality the *market value* established by the City Assessor is almost always substantially lower.

		24/25		25/26
Land market value		$257,000		$257,000
Building market value	+	$474,000	+	$476,000
Market value	**=**	**$731,000**	**=**	**$733,000**

Assessed Value

Next, the market value is used to compute the assessed value, which is a percentage of the market value. The exact percentage is determined by the tax class of the property. Tax class 1 is assessed at 6% of the market value, and tax classes 2,3 and 4 are assessed at 45%.

		24/25		25/26
Market value		$731,000		$733,000
Assessment ratio	x	45%	x	45%
Maximum assessed value	**=**	**$328,950**	**=**	**$329,850**

Transitional Value

To protect property owners from sudden large increases in property tax, the state limits how quickly the city can increase the assessed value. Typically these limits are applied when the City Assessor makes a big increase to the market value. Without the limits the assessed value would increase by a similar percentage. Instead, the change to the assessed value is phased in over a number of years.

		24/25		25/26
Assessed value		$328,950		$329,850
Exemptions granted by city	-	$0	-	$0
Net assessed value	**=**	**$328,950**	**=**	**$329,850**

The market value of this property was increased in previous years and the assessed value is currently being phased in. Because this property is in **tax class 4**, the assessment cannot be raised more than 8% from the year before or 30% over five years. Assessed value cannot be raised more than 45% from market value.

		24/25		25/26
Transitional value		$289,440		$298,620
Transitional exemption value	-	$0	-	$0
Transitional net value	**=**	**$289,440**	**=**	**$298,620**

Taxable Value

The *taxable value*, for 24/25, is the smaller of the city's net assessed value and the transitional net assessed value.

		24/25		25/26
Taxable value	=	$289,440	=	$298,620


Property Tax

Current tax is calculated by multiplying the taxable value (the assessed value minus any exemptions) by the tax rate. The city also grants some properties incentives called tax abatements, which are subtracted directly from the current tax. This results in the property tax, the amount the current owner pays.

Tax description	Billable value 24/25		Tax rate 24/25		Tax bill 24/25
Current tax	$289,440	x	10.7620%	=	$31,150
Property tax				**=**	**$31,150**

Tax description	Billable value 25/26		Tax rate 24/25		Tax bill 25/26
Current tax estimated	$298,620	x	10.7620%	=	$32,137
Total abatements 24/25 Q3				-	$0
Property tax estimated				**=**	**$32,137**

For more information, you can view this property's assessment, tax bill, and account statements by clicking here and entering the Borough, Block, & Lot.



This map shows property tax in correlation with square footage of the property.

Above $10.00	$4.00 - $5.00
$9.00 - $10.00	$3.00 - $4.00
$8.00 - $9.00	$2.00 - $3.00
$7.00 - $8.00	$1.00 - $2.00
$6.00 - $7.00	Below $1.00
$5.00 - $6.00	No Data

Property tax	**$31,150**
Tax year	**2024-2025**
Square feet	**8,000**
Tax per sqft	**$4**

6. Tentative Values

Every year in January, the NYC Department of Finance Commissioner publishes the tentative property assessment roll for the current fiscal year. All properties are valued by law according to their condition on the taxable status date of January 5th. Owners who believe that the Department of Finance has used incorrect information to determine their market value may file forms providing corrections. After Finance verifies the complaints, the agency will make any corrections before the final assessment roll is published on May 25. The final roll will also include changes, based on the decisions made by the New York City Tax Commission, an independent City agency, as well as new information Finance gathers about abatements, exemptions and other adjustments. In June, Finance will use the final roll and new tax rates adopted by the City Council to generate property tax bills for the fiscal year beginning July 1st.

Tentative Transitional Values

Land value	**$115,650**
Total value	**$298,620**
Exemption value	**$0**

Tentative Actual Values

Land value	**$257,000**
Total value	**$733,000**
Exemption value	**$0**

Permits

1. Boiler Permits

Issue date	**12/08/1993**	Primary fuel	**Natural gas**
Expiration date	**12/15/2014**	Boiler model	**Peerless G-1361-SW1**
Request type	**Registration**	Burner model	**Integral**
Status	**Expired**	Link to permit	**CA340793**

Development

1. Zoning

New York City is divided into three basic *zoning districts:* residential (R), commercial (C) and manufacturing (M). These basic zoning districts are subdivided by the intensity of use. Development is governed by the use, bulk, and parking requirements of the zoning district.



Residence districts
- Low density residence
- Medium and high density residence

Commercial districts
- Neighborhood commercial
- General commercial
- Specialty commercial

Manufacturing districts
- Districts that permit residence
- Districts that do not permit residence

Parks
- Battery Park

Zoning overlays
- Special purpose
- Limited height d
- Commercial ove

Rezoning
- Rezoning propos
- Rezoning recent

Zoning Designation

Manufacturing	**M1-2**

Rezoning Projects

We have no information to indicate that there is a rezoning planned.

For more information about zoning district regulations, click here.

Parcel Vicinity

Frontage(s)	**District Boundary(narrow)**
Nearest wide street	**Fulton Street**
Distance to wide street	**352 ft**

Manufacturing M1-2



M1 districts range from the Garment District in Manhattan and Port Morris in the Bronx with multistory lofts, to parts of Red Hook or College Point with one- or two-story warehouses characterized by loading bays. M1 districts are often buffers between M2 or M3 districts and adjacent residential or commercial districts. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. M1-1, M1-2 and M1-3 districts are subject to parking requirements based on the type of use and size of an establishment. More info

Map Disclaimer: Our maps are not official zoning maps. The print version of the NYC Zoning Resolution, which includes the zoning maps, together with any amendments adopted by the City Council subsequent to the most recent update to the print version, remains the official version of the Zoning Resolution. All zoning descriptions have been taken from the NYC Planning official source.


2. Building Class

The *building class* specifies how a property is used or what type of building is present on that property. Building classes range from A to Z (excluding X). There are at most 10 different sub-classes within each building class (ranging from 0 to 10). These building classes cover all property uses from residential and commercial to government buildings and parks.

The full list of building classes can be found here.



Building class: **Fireproof Warehouse (E1)**



3. Floor Area Ratio & Air Rights

There are many rules that limit what you can build on a lot and how large it can be. But the most important is the Floor Area Ratio, or FAR. The FAR is expressed as a ratio of the size of the building in square feet to the size of the lot in square feet. For example, if a lot is 2,000 square feet and has an allowable FAR of 4.0, then you cannot build a building larger than 8,000 square feet. Max FAR depends on several factors including zoning, location and use.

The maximum usable floor area is calculated by multiplying the size of the lot by the larger of the residential or commercial FAR.

Lot sqft		**13,110**
FAR	x	**2**
Maximum usable floor area	=	**26,220**

Available Air Rights by Parcel

The building on this lot is smaller than the maximum set by the FAR. Thus it may be possible to add to the building (either more floors or an extension) or it may be possible to sell the "air rights" to a developer who owns a nearby lot. (Note: other factors may limit what you can do.)

Maximum usable floor area		**26,220**
Usable floor area as built	-	**7,997**
Unused FAR ("air rights")	=	**18,223**



Opportunity by parcel


- Above 250.000 sq. ft.
- 100.000 - 250.000 sq. ft.
- 60.000 - 100.000 sq. ft.

Very little opportunity

- 30.000 - 60.000 sq. ft.
- 10.000 - 30.000 sq. ft.
- Below 10.000 sq. ft.

Commercial FAR	**2**
Facility FAR	**4.8**
FAR as built	**0.61**

4. Urban Landscape Maps




Click on the map to expand.

Year built: **1921**

On this color-coded map, view the year each property was built.

- >2020
- 2011-2020
- 2001-2010
- 1981-2000
- 1961-1980
- 1941-1960
- 1900-1940
- <1900



Click on the map to expand.


Stories: **2**

On this map, view the number of stories per building.

- 10 & Up stories
- 7 to 9 Stories
- 5 to 6 Stories
- 4 Stories
- 3 Stories
- 2 Stories
- 1 Story
- No data

5. Planimetric Map

This planimetric map shows features such as retaining walls, sidewalks, medians, curbs, and roadbeds that have been digitized from aerial photography. These features must be taken into consideration when determining how a new building, or extensions to an existing building, are situated within the lot. They can also affect the maximum height that can be built.




- Sidewalk
- Curb
- Pavement edge
- Roadbed
- Median
- Retaining wall
- Plaza
- Swimming pool
- Building footprint
- Garage
- Sky bridge
- Under construction
- Piers/seawall
- Boardwalk
- Recreational area
- Park/greenstreets
- Transport structure

BIN	**3042806**
Type	**Building**
Status	**Constructed**
Roof height	**25 ft**
Ground elevation	**69 ft**

6. HPD Alternative Enforcement Program

The HPD Alternative Enforcement Program map is based on the current month's HPD violations in a building divided by the number of units in the building. It takes in consideration the open hazardous and immediately hazardous violations (I/B/C class) in the last 5 years.



Properties over the HPD-AEP threshold
- More than 600% over
- 300% to 600% over
- Up to 300% over

Properties below the HPD-AEP threshold
- 80% to 99%
- 60% to 80%
- 50% to 60%

HPD-AEP threshold for buildings having:
- 3 to 14 units = 5 violations/unit
- 15 units or more = 3 violations/unit

For more information, visit the HPD website.

Neighborhood

1. Area Overview


Walk Score
87 /100. Very Walkable

Transit Score
100 /100. Rider's Paradise

Bike Score
60 /100. Bikeable

2. Transportation

On this color-coded map, view the nearest subway station for each building.



1 2 3
4 5 6 6
7 7
A C E
B D F M
G
J Z
L S
N Q R W

Up to 1/4 mile
1/4 to 1/2 mile
1/2 to 3/4 mile
3/4 to 1 mile
Over 1 mile
Subway station
Metro Nord station
Metro Nord line
LIRR station
LIRR line
* distances are calculated as radius from station

Closest station	**Snediker Ave & New York Ave at SW Corner**
Station lines	**L**
Distance (miles)	**0.067**

On this map, view the closest local or express bus routes and stations.



Express bus stops
Express bus lines
Local bus stops
Local bus lines

Name	**Fulton St/Van Sinderen Av**
Line	**B25**
Distance (miles)	**0.091**

3. Distance to Schools



Elementary School Proximity

This map shows zoned Elementary School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Elementary schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **People's Elementary School**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
People's Elementary School	NR	No	Private	PK-8	435	0.06
Trey Whitfield School	NR	No	Private	PK, K-8	435	0.13
P.S. Is 155 Nicholas Herkimer	7	No	Public	PK, K-8	296	0.30
Leadership Preparatory Ocean Hill Charter School	6	No	Charter	K-12	1,202	0.33
Christopher Avenue Community School	8	No	Public	PK, K-5	225	0.33
Our Lady of Lourdes School	NR	No	Private	PK, K-8		0.37
P.S. 298 Dr Betty Shabazz	6	No	Public	PK, K-5	330	0.45
Brooklyn Landmark Elementary School	8	No	Public	PK, K-5	404	0.48
Ark Christian Academy	NR	No	Private	K-6	14	0.52
Ark Christian Academy	NR	No	Private	K-5	60	0.55
P.S. 150 Christopher	3	No	Public	PK, K-5	142	0.55
Achievement First Brownsville Charter School	6	No	Charter	K-12	1,057	0.56
P.S. 328 Phyllis Wheatley	6	No	Public	PK, K-5	243	0.65
Hyde Leadership Charter School-Brooklyn	4	No	Charter	K-8	476	0.65

Data provided by GreatSchools.org © 2025. All rights reserved.



Middle School Proximity

This map shows zoned Middle School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Middle schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **People's Elementary School**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
People's Elementary School	NR	No	Private	PK-8	435	0.06
Trey Whitfield School	NR	No	Private	PK, K-8	435	0.13
P.S. Is 155 Nicholas Herkimer	7	No	Public	PK, K-8	296	0.30
Leadership Preparatory Ocean Hill Charter School	6	No	Charter	K-12	1,202	0.33
Our Lady of Lourdes School	NR	No	Private	PK, K-8		0.37
Brownsville Collaborative Middle School	8	No	Public	6-8	279	0.45
Brooklyn Environmental Exploration	3	No	Public	6-8	165	0.48
Brownsville Collegiate Charter School	5	No	Charter	6-8	117	0.55
Charles Churn Christian Academy	NR	No	Private	PK-12	117	0.56
Achievement First Brownsville Charter School	6	No	Charter	K-12	1,057	0.56
Jhs 292 Margaret S Douglas	5	No	Public	6-8	351	0.62
Hyde Leadership Charter School-Brooklyn	4	No	Charter	K-8	476	0.65
P.S. 178 Saint Clair Mckelway	4	No	Public	PK, K-8	280	0.65
Eagle Academy for Young Men II	6	No	Public	6-12	599	0.71
Ocean Hill Collegiate Charter School	7	No	Charter	K-9	411	0.71

Data provided by GreatSchools.org © 2025. All rights reserved.



High School Proximity

This map shows zoned High School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

High schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Leadership Preparatory Ocean Hill Charter School**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Leadership Preparatory Ocean Hill Charter School	6	No	Charter	K-12	1,202	0.33
W H Maxwell Career and Technical Education High School	2	No	Public	9-12	408	0.42
Charles Churn Christian Academy	NR	No	Private	PK-12	117	0.56
Achievement First Brownsville Charter School	6	No	Charter	K-12	1,057	0.56
Brooklyn Collegiate A College Board School	3	No	Public	9-12	413	0.56
Eagle Academy for Young Men II	6	No	Public	6-12	599	0.71
High School For Civil Rights	2	No	Public	9-12	140	0.79
World Academy For Total Community Health	2	No	Public	9-12	132	0.79
Captain Vernon a Richards High School-Fire	3	No	Public	9-12	223	0.79
Performing Arts and Technology High School	6	No	Public	9-12	319	0.79
Teachers Preperatory High School	NR	No	Public	9-12	189	0.89
Frederick Douglas Academy Vii High School	5	No	Public	9-12	227	0.89
Achievement First East New York Charter School	7	No	Charter	K-12	1,144	1.02
Followers of Jesus School	NR	No	Private	1-12	36	1.13
Brooklyn High School Law And Tech	3	No	Public	9-12	549	1.24

Data provided by GreatSchools.org © 2025. All rights reserved.

4. Traffic Map



Estimated average daily traffic volume on a route segment at a particular count location.

Average daily traffic

- 75001 - 300000
- 25001 - 75000
- 10001 - 25000
- 4001 - 10000
- 1501 - 4000
- 1 - 1500

5. Demographics By Zip Code

Demographic data shown in this section was gathered from the 2023 American Community Survey and refers to zip code **11207**.

Population Demographics

Total population	**93,445**
Female population	**55.3%**
Male population	**44.7%**
Median age	**36**
Male median age	**35**
Female median age	**37**

Education

No highschool	**8.3%**
Some highschool or college	**64.1%**
Bachelors degree	**13.4%**

Other

Citizens	**88.4%**
Citizens born in US	**65.5%**
English speakers	**94.3%**

Journey to Work

Work in a metropolitan area	**99.8%**
Work in a micropolitan area	**0.1%**
Work at home	**10.5%**
Go to work by car	**27.8%**
Go to work after 10 am	**19.9%**

Economic/Employment

Average household income	**$74,315**
White collar	**82.9%**
Blue collar	**17.1%**

Housing

Family households	**58.3%**
Households with kids	**30.1%**
Housing units	**38,030**
Occupied housing units	**35,309**
Owner occupied units	**26.9%**
Average number of people per household	**2**
Median year structure built	**1955**
Houses with mortgages	**66.8%**

Wealth

Median value for units with a mortgage	**$673,300**
Median value for units without a mortgage	**$629,700**
Median gross rent	**$1,443**
Median mobile home values	**$0**
Median housing costs per month	**$1,549**
Population in poverty	**27.3%**

Violations

1. HPD Violations

When excessive violations are present, this can adversely affect the support given by The NYC Department of Housing Preservation and Development (HPD). These violations can result in building-wide inspections, fees, and the requirement of extensive repair work to correct underlying conditions. In some cases, outstanding violations may result in a lien being placed on the property. It is also substantially more difficult to mortgage a building with extensive violations.

We do not have any record of violations in our database. Status can be verified here.

2. DOB Violations

Violation ID	Issue date	Type	Status
V062023LBLVIO34669	06/20/2023	Lblvio-low pressure boiler boiler required	Active
Violation issued-failure to file 2019 external low pressure inspection			
V062023LBLVIO13539	06/20/2023	Lblvio-low pressure boiler boiler required	Active
Violation issued-failure to file 2018 external low pressure inspection			
V*030315LBLVIO13533	03/03/2015	Lblvio-low pressure boiler	Dismissed
Violation issued for failure to file annual boiler 2013 inspection report 10/28/2015 - Ciakst dismiss, $1000 PD inv#61593084			
V*091697LL6291221162	09/16/1997	Ll6291-local law 62/91 - boilers	Dismissed
11/25/1997 - Dismissed reduced penalty inv#60153603 MO#67470860068 $50. 00			

Please note: the NYC Department of Buildings is the only authoritative source for information on DOB violations. Verify the status of the violation on DOB website.

Records are obtained from DOB and updated daily.

3. Neighborhood Complaints

Created	Agency	Type	Descriptor	Disposition	Closed
05/11/2023	NYPD	Blocked driveway	No access	The Police Department responded and upon arrival those responsible for the condition were gone.	05/11/2023
02/03/2022	NYPD	Blocked driveway	No access	The Police Department reviewed your complaint and provided additional information below.	02/03/2022

Risk

1. FEMA Flood Zones

Use this map to determine if the property is in a flood zone.



Moderate to low risk areas
X
0.2% PCT
High risk areas
A
AE
High risk-coastal areas
VE

Floodway
COBRA **
** Coastal barrier resources system area

Link to the map for this property at **FEMA's Map Service Center** (may not be available in all locations).


FEMA Flood Zoning

FEMA flood zone(s)	**X**
Coastal barrier resources system area (COBRA)	**Out**
Floodway	**Out**
FEMA special flood hazard area	**Out**
Map panel ID	**3604970217F**
Map quaderant ID	**40073-F8**

Distance to...

Nearest distance to coastline (miles)	**1.942**
Compass direction to coastline	**309**
Nearest distance to 100 year flood zone area (ft)	**65**
Angle100	**26**

2. Hurricane Evacuation Zones



This map shows hurricane evacuation zones. In the case of coastal storms, the City may order the evacuation of neighborhoods in danger of flooding, the most critical being Zone 1.

- Zone 1
- Zone 2
- Zone 3
- Zone 4
- Zone 5
- Zone 6

Disclaimer

Copyright 2003-2025 by Property Research Partners LLC

All data comes from government sources. No attempt has been made to validate it. No attempt has been made to validate the accuracy of the programming of this web site. Do not rely on this report to support investment decisions. The only authoritative source for the information in this report is the government agencies from which the data was acquired.

U.S. Environmental Protection Agency

MyProperty

Environmental Databases Search

The search of EPA's Facility Registry System did not locate any records for the search criteria provided below:

Search Criteria:

Street Address:	45 Van Sinderen Avenue
City, State:	Brooklyn, NY
Query executed on:	04/10/2025 05:00:48 **EST**

Contact the appropriate state, tribal or local agencies if you seek additional information.

>Disclaimer

>The MyProperty reports are provided solely for informational purposes. They do not provide legal advice, have legally binding effect, or expressly or implicitly create, expand, or limit any legal rights, obligations, responsibilities, expectations, or benefits in regard to any person. EPA maintains the application to enhance public access to environmental information. This service has continual data updates, and we will correct errors brought to our attention, as appropriate.

DECinfo Locator

Base Map: Topographical | Help

Search

Search by Location

45 Van Sinderen Ave, Brooklyn, New York, 11207

search clear


- [x] Address
- [ ] Municipalities
- [ ] Place Names
- [ ] Counties

Search Help (Click to view/hide)

Tools

DEC Information Layers

Reference Layers



NEW YORK STATE OF OPPORTUNITY | Department of Environmental Conservation

Environmental Site Remediation Database Search Results

Record Count: 3 Rows: 1 to 3

Export XLS | Export CSV | Export KML

	Site Code	Site Name	Program	Site Class	County	City/town	Address
1	C224275	Jean's Place	BCP	A	Kings	Brooklyn	485 Van Sinderen Avenue
2	C224275A	Jean's Place - Off-site	BCP	A	Kings	Brooklyn	485 Van Sinderen Avenue
3	C224405	749 Van Sinderen Avenue, Brooklyn, NY	BCP	A	Kings	Brooklyn	723-753 Van Sinderen Avenue

Refine This Search

NEW YORK STATE OF OPPORTUNITY | Department of Environmental Conservation

Spill Incidents Database Search Results

Record Count: 7 Rows: 1 to 7

Export XLS | Export CSV

	Spill Number	Date Spill Reported	Spill Name	County	City/Town	Address
1.	0206144	09/13/2002	Spill Number 0206144	Kings	BROOKLYN	38 VAN SINDEREN AVE
2.	0601203	05/02/2006	MANHOLE #04264	Kings	BROOKLYN	FULTON STREET & VAN SINDEREN AVE
3.	1103525	06/29/2011	MANHOLE 3940	Kings	BROOKLYN	LIVONIA AVE @ VAN SINDEREN AVE
4.	1304283	07/19/2013	DRUM RUN	Kings	BROOKLYN	VAN SINDEREN AVE AND RIVERDALE AVE
5.	1310459	01/31/2014	DRUM RUN	Kings	BROOKLYN	DEWITT AVE AND VAN SINDEREN AVE
6.	1604150	07/26/2016	TO ROADWAY - DRUM RUN	Kings	BROOKLYN	VAN SINDEREN AVE AND BELMONT AVE
7.	1800995	04/27/2018	DRUM RUN	Kings	BROOKLYN	647 VAN SINDEREN AVE

Refine This Search

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Elevator violations for failure to file Periodic, Category 1, Category 5 and Affirmation of Correction issued in August 2023 or later are only available in DOB NOW: *Safety*. Search the DOB NOW public portal for these records.

Boiler violations for failure to file internal and external inspection reports and affirmation of correction issued in November 2023 or later are only available in DOB NOW: *Safety*. Search the DOB NOW public portal for these records.

Premises: 45 VAN SINDEREN AVENUE BROOKLYN **BIN: 3042806 Block: 1576 Lot: 1**

NUMBER		TYPE	FILE DATE
A 12563-101920		ALTERATION	00/00/1920
A 12563-111620		ALTERATION	00/00/1920
A 3971-041220		ALTERATION	00/00/1920
ALT 528-45-022057		ALTERATION	00/00/1957
BDO 301943-040943			00/00/1943
BN 105(INT)49-012643		BUILDING NOTICE	00/00/1943
BN 1008DENIEDINACTI-081144		BUILDING NOTICE	00/00/1944
BN 2197-45-100362		BUILDING NOTICE	00/00/1962
C -A6281-112662		CONSTRUCTION	00/00/1962
CERT IFICATEISSUED6292NB1	(PDF)	CERTIFICATE OF OCCUPANCY	00/00/0000
ELV 37-031457		ELEVATOR	00/00/1957
ELV 6-45-012257		ELEVATOR	00/00/1957
FO 2378-110543		OIL BURNER APPLICATION	00/00/1943
FO 1353-45-080662		OIL BURNER APPLICATION	00/00/1962
GRAN TEDONCONDITION			00/00/0000
NB 105061-1FSHED-082420		NEW BUILDING	00/00/1920
NB 1473-021320		NEW BUILDING	00/00/1920
NB 1590-030420		NEW BUILDING	00/00/1920
NB 8055-092220		NEW BUILDING	00/00/1920
PRS 1461-060540		PLUMBING REPAIR SLIP	00/00/1940
UNK 14+OL28EAL8543SAPPLICATI		UNKNOWN	00/00/0000
V* 4156FLANAGANFIRE-092145		DOB VIOLATION - CLOSED	00/00/0000
CLOSURE DATE: 09/28/2011			
V* -26		DOB VIOLATION - CLOSED	00/00/1926
CLOSURE DATE: 09/28/2011			
WORK 6-072020			00/00/1907
V* 091697LL6291221162		DOB VIOLATION - DISMISSED	09/16/1997

Next

Select Violation Type: Show All Violations Refresh

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

Outlook

[OpenRecords] Request FOIL-2025-057-03336 Submitted to New York City Fire Department (FDNY)

From donotreply@records.nyc.gov <donotreply@records.nyc.gov>
Date Thu 4/10/2025 5:12 PM
To Michael Pecoraro <mpecoraro@pwgrosser.com>

Your request FOIL-2025-057-03336 has been successfully submitted to the New York City Fire Department (FDNY). The details of your request are shown below.

Request Title: Records for 45 Van Sinderen Ave, Brooklyn, NY

Request Description: Other Request

Request Type: Other Request

Other Request
Submission Method: Online/At Home
Description of Records: Requesting records related to incidents occurring at 45 Van Sinderen Ave, Brooklyn, NY 11207, NYC Tax map block 1576 and lot 1, including whether Aqueous Fire Fighting Foam (AFFF) was utilized

Requester's Contact Information

Name:
Michael Pecoraro
Title:
Project Manager
Organization:
P.W. Grosser Consulting, Inc.
Email:
mpecoraro@pwgrosser.com
Phone Number:
(631) 589-6353
Fax Number:
Not provided
Street Address (line 1):
630 Johnson Ave, Suite #7
Street Address (line 2):
630 Johnson Ave, Suite #7
City:
Bohemia
State:
NY
Zip Code:
11716

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2025-057-03336.

Outlook

[OpenRecords] Request FOIL-2025-826-01767 Submitted to Department of Environmental Protection (DEP)

From donotreply@records.nyc.gov <donotreply@records.nyc.gov>
Date Thu 4/10/2025 5:09 PM
To Michael Pecoraro <mpecoraro@pwgrosser.com>

Your request FOIL-2025-826-01767 has been successfully submitted to the Department of Environmental Protection (DEP). The details of your request are shown below.

Request Title: Environmental Records or Permits for 45 Van Sinderen Ave

Request Description: Requesting environmental records pertaining to the address of 45 Van Sinderen Avenue, Brooklyn, NY 10207, NYC Tax map block 1576 and lot 1, including spill records, tank records, remediation records, etc.

Requester's Contact Information

Name:
Michael Pecoraro
Title:
Project Manager
Organization:
P.W. Grosser Consulting, Inc.
Email:
mpecoraro@pwgrosser.com
Phone Number:
(631) 589-6353
Fax Number:
Not provided
Street Address (line 1):
630 Johnson Ave
Street Address (line 2):
Not provided
City:
Bohemia
State:
NY
Zip Code:
11716

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2025-826-01767.

Outlook

[OpenRecords] Request FOIL-2025-002-00362 Submitted to Mayor's Office of Environmental Remediation (OER)

From donotreply@records.nyc.gov <donotreply@records.nyc.gov>
Date Thu 4/10/2025 5:10 PM
To Michael Pecoraro <mpecoraro@pwgrosser.com>

Your request FOIL-2025-002-00362 has been successfully submitted to the Mayor's Office of Environmental Remediation (OER). The details of your request are shown below.

Request Title: Environmental Records or Permits for 45 Van Sinderen Ave

Request Description: Requesting environmental records pertaining to the address of 45 Van Sinderen Avenue, Brooklyn, NY 10207, NYC Tax map block 1576 and lot 1, including spill records, tank records, remediation records, etc.

Requester's Contact Information

Name:
Michael Pecoraro
Title:
Project Manager
Organization:
P.W. Grosser Consulting, Inc.
Email:
mpecoraro@pwgrosser.com
Phone Number:
(631) 589-6353
Fax Number:
Not provided
Street Address (line 1):
630 Johnson Ave, Suite #7
Street Address (line 2):
Not provided
City:
Bohemia
State:
NY
Zip Code:
11716

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2025-002-00362.

APPENDIX J
SITE INSPECTION CHECKLIST

PHASE I ESA SITE INSPECTION CHECKLIST

Site Address:
45 Van Sinderen Avenue, Brooklyn, NY 11207

Inspector:	Date:
Danielle Dulligan	03/26/2025 & 4/8/2025

Site Contact (include phone #):

Weather Conditions:
Cloudy, 43-52F

Limiting Conditions:
Locked rooms on second floor. Trucks obscuring view in yard

Property Description – Include # of buildings, floors, basements, occupied vs. unoccupied, etc. Also try to identify potential former use based on visual evidence or discussions with site contact.
Two-floor building with basement and yard on north end of site. All occupied, three separate tenants: Outside yard- garbage company; First floor/basement- Great Goods (Amazon Distributor); Second floor- Rented art studio space. Alleyway on south side of building, seemed to belong to adjoining property (south) with a dumpster- cardboard waste. Broken vent pipe observed along front of building, near second door for first floor access.

Adjoining Property Description – General site use, evidence of tanks, monitoring wells, etc.

North:
Calvary church, two-floor building may have basement.

South:
Noble Signs, sign making company (use paint), three-story building with basement.

East:
Overhead trains

West:
Van Sinderen Avenue; Building space w/ garage doors, one-floor.

General Topographic Site Condition and Other Site Notes

Utilities – Visual Inspection and Discussion with Site Contact

Heating & Cooling System:
Radiators (both floors)

Water Supply:
NYC water supply

Sanitary System(s):
NYC sewer

Electric:
Yes- lighting and AC window units.

Emergency Generator? Yes / No (If Yes, location, size, type, description, fuel)
None observed.

Site Features – Visual Inspection and Discussion with Site Contact (If yes for any describe in detail)

Aboveground Storage Tanks (ASTs):
None observed.

Underground Storage Tanks (USTs):
None observed.

Hazardous and Non-Haz Chemical Storage:
None observed; Paint storage and glue second floor.

Waste Generation, Storage and Disposal:
None observed. Cardboard waste.

PCB Containing Equipment (transformers or hydraulic lifts present?):
None observed- jacks on first floor.

Interior Drains, Trenches or Sumps:

None observed.

Interior Stains or Corrosion:

Bathroom sinks on second-floor had paint stains. Carpet in first floor offices- could not see floor beneath.

Unusual Odors:

None observed

Interior Pools of Liquid:

None observed.

Stained Soils, Pavement or Stressed Vegetation:

Outside yard had stains on floor, beneath diesel garbage trucks.

Drums:

None observed.

Indications of Solid Waste Disposal:

None observed.

Exterior Ponds, Pits or Lagoons:

None observed.

Wastewater or Storm Water Discharge / Disposal:

None observed.

Oil/Water Separators:

None observed.

Septic Systems / Cesspools:

None observed.

Wells:

None observed.

Petroleum or Natural Gas Pipelines or Easements:

Old connections exposed, potentially for previous water lines for radiators.

Other General Observations:

North yard, full of waste (garbage truck storage) tires, wheels, pipes, dumpsters, etc.; Potential diesel stains on soil first-floor tenant noted fire occurred about two years ago in north yard, truck caught on fire.

Interview Information

Contact Name:	Stephen/Tom
Relationship to Site:	Employee of first floor tenant/Tenant second floor
Years Associated with Site:	Approximately 3 years/Approximately 5 years

Topics Discussed:

Fire on one of the garbage trucks occurred in northern yard

Other Observations

Asbestos Containing Material (List Major Potential ACM Identified):

None observed.

Lead Based Paint (If Built Before 1975, identify chipping paint):

None observed

Mold (note any evidence and location):

None observed.

General Notes or Additional Information

2 bathrooms first floor, one not in operation and in poor condition: cracked tile floor.
2 bathrooms second floor, paint observed in sink of second floor, tenant commented that he was unsure if other occupants poured anything down drain (i.e. paint or textile products).

Carpeted office/rooms on first floor, could not see floor.

Locked basement- did not access this or roof.

APPENDIX K
QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONAL

Michael Pecoraro .

PROJECT MANAGER



PROFESSIONAL EXPERIENCE
PWGC: 8 years

AREAS OF EXPERTISE
Environmental Due Diligence
Preparation of Investigative and Remedial Plans and Reports
Water, Soil, Air Sampling
Field Work (Protocol, Oversight, Documentation)
Site Investigation/Analysis
PFAS & Other Emerging Contaminants
Health & Safety Protocols
Air Monitoring Protocols
Public Well Installation & Development
Geotechnical Investigation
Electronic Data Deliverable Processing

EDUCATION & TRAINING/CERTIFICATION
MA, Geological and Environmental Sciences, CUNY Queens College
BA, Earth Science/Education, University of Delaware
AS, Liberal Sciences, Nassau Community College
40 Hour HAZWOPER Certification
30 Hour Construction Certification
10 Hour Construction Certification
NYC Site Safety Training Certification
NYSDEC Erosion and Sediment Control Training 4 Hour
Transportation Worker Identification Credential (TWIC)

PROFILE

Mr. Pecoraro is a member of PWGC's Environmental Team where he applies his skills as a Project Manager. His project experience is focused on projects that include groundwater remediation, soil sampling, air quality sampling, Phase I/II environmental site assessments, water supply well installation, and permitting for dredging projects. He has an excellent record in timely completion and maintenance of project coordination, monitoring, and document preparation, while successfully maintaining communication between clients, government regulatory agencies, and other interested parties.

NOTABLE PROJECTS

Glen Isle Waterfront Redevelopment, Glen Cove, NY

Mr. Pecoraro performed air monitoring during intrusive earth work to assure air quality was in accordance with the Community Air Monitoring Program approved by the NYSDEC and USEPA. He prepared Remedial Action Completion Reports and EDD data submittals to the NYSDEC. He conducted soil sampling in accordance with NYSDEC TOGS at Garvies Point. He was responsible for overseeing the on-site contracts perform drilling, impacted soil excavations, hazardous and non-hazardous soil trucking and the importation of acceptable materials to the site. Mr. Pecoraro collected confirmation endpoint samples within remedial excavations and prevented on-site contaminants from migrating off-site. Mr. Pecoraro was responsible for keeping a detailed field log and coordinating daily work on-site with the numerous contractors.

NYCOER E-Designation/VCP Sites

Mr. Pecoraro has provided management services for sites which are included in the NYCOER E-Designation Program. The services included on-site services performed in accordance with the NYCOER approved Remedial Action Work Plan (RAWP) and Health & Safety Plan (HASP), reporting to the NYCOER, coordinating field efforts, and coordinating with contractors and disposal facilities for the removal of impacted soils to obtain site specific cleanup objectives.

NYSDEC Brownfield Cleanup Program Services

Mr. Pecoraro has performed investigations and remediations for sites under the NYSDEC Brownfield Cleanup Program. He has performed Remedial Investigations that included soil, groundwater, and soil vapor sampling, geophysical surveys, and based on those findings assisted in developing an appropriate Remedial Action Plan for the site.

Phase I/II Environmental Site Assessments
Mr. Pecoraro has performed various aspects of Phase I/II ESA scopes of work for commercial and industrial properties, including: historical research; FOIL requests, EDR records, initial site inspections; field work; sampling of soil, groundwater and air; subcontractor oversight, coordinating with assigned laboratories, and general project coordination and management.

Residential/ Commercial Fuel Oil Spills Oversight and Reporting
Mr. Pecoraro has overseen fieldwork for projects such as petroleum spill remediation. He completes spill reports, and coordinates with contractors and the NYSDEC to ensure that the project stays on schedule, is compliant with regulatory guidelines, and meets the client's goals.

UIC Remediation Oversight
Mr. Pecoraro has overseen remediation activities of dry wells (Class V wells) at multiple sites for various clients throughout Suffolk County. He ensures proper soil and sediment removal during VacTruck operations, performs endpoint sampling of storm drains and sanitary systems, coordinates and performs sampling in conjunction with the SCDHS, and prepares reports documenting the remediation and endpoint sampling so a No Further Action letter can be obtained.

Drilling Oversight
Mr. Pecoraro has performed various aspects of the installation of monitoring and injection wells, including: completion of boring logs; USCS soil classification, soil screening, processing logs using Strater; soil and groundwater sampling, health and safety monitoring, conduction of NYSDEC static, pumping, and recovery tests using data loggers, subcontractor oversight, coordinating with assigned laboratories, and general project coordination and management.

Dredged Materials Management Implementation
Mr. Pecoraro has implemented Sediment Sampling and Analysis Plans (SSAPs) for proposed dredge sites to determine the appropriate dredge protocols and materials management. He oversees soil borings collected by the assigned subcontractors, completes boring logs with proper USCS soil classification, processes logs on Strater, and coordinates with the assigned analytical laboratories. He assists in the preparation of dredging permits from multiple regulatory agencies and maintains frequent communication to ensure they are processed in a timely manner.

Public Supply Well Installation – Ocean Beach, Sands Point, Franklinville
Mr. Pecoraro has overseen the installation of public supply wells, including test borings, well installation, well development, and water sampling for multiple supply wells across New York State. He has assisted with the selection of screen intervals using USCS soil classification, collection of groundwater parameters (pH, turbidity, depth to water) during development, and coordination and collection of groundwater samples for drinking water standards.

PFAS Remediation Sites – Suffolk County
Mr. Pecoraro has implemented Site Characterization and Soil Delineation Investigations for sites impacted with per-and poly-fluoroalkyl substances (PFAS) at properties in Suffolk County. Activities included collection of soil and groundwater samples, generation of contour maps to trace the sources of PFAS impact, coordination with NYSDEC and SCDHS, preparation of remedial costs to cure and feasibility studies, and preparation of investigation reports.

Jennifer Lewis, PG .

VICE PRESIDENT



PROFESSIONAL EXPERIENCE
PWGC: 17 years

AREAS OF EXPERTISE
NYSDEC Brownfield Cleanup Program Management
NYCOER Brownfield and "E" Designation Management
Work Plan/Report Preparation
Phase I & II Environmental Site Assessments
Underground Injection Structure Remediation
Underground Storage Tank Remediation
Water, Soil, Air Sampling
Data Management & Interpretation
Groundwater Remediation via Chemical Injection

EDUCATION & TRAINING/CERTIFICATION
MBA, CUNY Baruch, New York, NY
BS, Geology, SUNY Stony Brook, NY
AA, Liberal Arts, Suffolk County Community College, Selden, NY
Licensed Professional Geologist - NYS
OSHA Health & Safety 8-hr Supervisor, 40-hr HazWoper
Construction Management Certification
ASTM Training on Phase I and Phase II Environmental Site Assessments for Commercial Real Estate

PROFILE

As a Vice President, Ms. Lewis has assisted property buyers, sellers, and developers navigate potential environmental concerns, petroleum spills, the New York State (NYS) Brownfield Cleanup Program, the New York City (NYC) E-Designation Program/Voluntary Cleanup Program requirements during property transactions and site development. Ms. Lewis's roles on these projects has included planning, conducting, and reporting soil/groundwater investigations, air quality studies, and instituting remedial measures. Her clients, ranging from developers to attorneys to municipal agencies, benefit from her expertise in overseeing Phase I and II Environmental Site Assessments (ESAs), Remedial Investigations, cost to cure estimates for financial institutions, and Brownfields projects. Ms. Lewis coordinates with clients and attorneys to prepare plans for approval by federal, state, and local agencies (e.g., Remedial Action Plans, Health and Safety Plans, Investigation Work Plans, Interim Remedial Measures) and monitors each project's day-to-day progress to meet the client's objectives and regulatory requirements.

NOTABLE PROJECTS

Phase I & II Environmental Site Assessment

Ms. Lewis manages Phase I & II ESA preparation, implementation, and completion. For each project, she provides a customized scope of work and relevant documentation to provide clients with pertinent information. She performs Phase I & Phase II ESAs for private clients, environmental attorneys, municipalities, and lending institutions for use in property transactions according to ASTM Standards.

Brownfield Redevelopment

AvalonBay Communities, Inc. – Former Darby Drug Facility, Rockville Centre, NY – NYSDEC Brownfield Cleanup Program Implementation During Development

The Former Darby Drugs Distribution Center was a commercial warehouse formerly occupied by a textile company which was a source of PCE contamination to soil and groundwater beneath the site. The site was enrolled in the NYSDEC Brownfield Cleanup Program (BCP). Ms. Lewis implemented an Interim Remedial Measure which included a sophisticated soil excavation and dewatering program within a warehouse, chemical injections into the groundwater, and UIC remediation. Ms. Lewis then documented the Interim Remedial Measure effort and prepared an Alternatives Analysis and a Remedial Action Work Plan to provide a scope for additional remediation and a Final Engineering Report and a Site Management Plan to document the results of the remedial action and protective steps to follow for the future use of the site.

Brownfield Redevelopment

Coney Island Realty - NYSDEC BCP Site

During the Interim Remedial Measure Phase, Ms. Lewis coordinated the soil excavation, community air monitoring, and sampling activities. Ms. Lewis also prepared reports detailing the Supplemental Remedial Investigation and Interim Remedial Measure, as

well as the Remedial Action Work Plan to provide a scope for additional remediation and a Final Engineering Report and a Site Management Plan to document the results of the remedial action and protective steps to follow for the future use of the site. Ms. Lewis has continued overseeing the routine operation and maintenance of a soil vapor extraction system operating at the site.

Suffolk County Department of Public Works (SCDPW) - Suffolk County, NY
UIC Remediation
Ms. Lewis was responsible for maintaining a UIC structure database for SCDPW and conducting UIC investigations and remediations as part of the planned upgrade of SCDPW site sanitary upgrades. Ms. Lewis coordinated closely with SCPWS, SCDHS, and contractors to conduct this work efficiently and within budget.

Brookhaven National Laboratory - Upton, NY
OUIII Western South Boundary/OUI South Boundary Vertical Profiles and Monitoring Well Installation
Ms. Lewis provided sampling services and hydrogeologic oversight for multiple vertical profiles, as part of the on-site OUIII plume evaluation. Her responsibilities included the collection of groundwater samples during sampling. She was responsible for construction observation and documentation for 3 monitoring well installations. After installation, wells were developed by pumping and surging. Ms. Lewis documented field activities and verified the work that was performed in accordance with BNL's Standard Operating Procedures and Project Work Plans. She conducted daily tailgate safety meetings, completed BNL's daily field reports and reported to BNL's Project Manager at the completion of each day.

Pratt Institute – Brooklyn, NY
Well Installation
Ms. Lewis provided over-site for the installation of a geothermal test well. She generated boring logs, documented soil characteristics, and classified in accordance with USGS' Monthly/Quarterly Groundwater/Air Sampling.
Well Monitoring
Ms. Lewis performs routine monitoring and sampling of air and groundwater, and product removal if necessary, at various sites. In addition to the fieldwork at these sites, Ms. Lewis analyzes the data and prepares a site plan and a quarterly report detailing the results and future recommendations.

Brookhaven National Laboratory - Upton, NY
Environmental Protection Division: Groundwater Protection and Remediation
Ms. Lewis supervised the installation of multiple vertical profiles via geoprobe to monitor strontium-90, tritium, and volatile organic compound (VOC) plumes on site. Her responsibilities included the collection of groundwater samples during sampling. Ms. Lewis documented field activities and verified the work that was performed in accordance with BNL's Standard Operating Procedures and Project Work Plans. She conducted daily tailgate safety meetings, completed BNL's daily field reports and reported to BNL's Project Manager at the completion of each day.

Newark-Liberty International Airport
The Automotive Fueling Station at Newark-Liberty Airport is the site of a UST failure regulated by the NJDEP Site Remediation Program. Ms. Lewis performs routine groundwater monitoring and sampling as well as supplemental remedial activities at the site. Ms. Lewis is also responsible for coordinating field activities with regulators and assisting with preparation of periodic Status Reports. Field work and reporting is completed in accordance with NJDEP Technical Requirements for Site Investigation 7.26E.

New York City Housing Authority - New York City, NY
Sub-Surface Investigations
Ms. Lewis performs environmental assessments associated with site specific NYSDEC spill files in order to delineate petroleum and tetrachloroethene impacts. Specifically, collection of soil, groundwater, and sub-surface air samples, oversight of monitoring well installations, preparation and submittal of site assessment reports, and coordination with NYCHA staff and regulatory agencies.

NYCDEP/NYCOER "E" Designation Sites - New York City, NY
RAP & HASP enforcement, air monitoring for particulates and VOCs
Ms. Lewis's services focus on coordinating remedial investigations, preparation of Remedial Investigation Reports, preparing a Remedial Action Scope of Work that considers the contaminants identified at the site as well as the intended use and building design, coordinating the remediation, and documenting the results of the remediation. Ms. Lewis, with the assistance of the architect and mechanical engineer of record, has also prepared Remedial Action Work Plans and Installation Reports for Air and Noise "E"s.

Former Penetrex Remedial Investigation
Ms. Lewis oversaw a chemical injection at a former dry cleaning facility utilizing a Geoprobe® that drilled down to 50 feet below grade and pulled the rods up during the injection.

USEPA Superfund Site
Treatment System O&M
Ms. Lewis provided assistance with the remediation efforts of the down-gradient pond system and oversight of the down-gradient recovery well installation for the USEPA Superfund remediation project. Additional duties included sampling backfill material brought on-site and overseeing the backfilling and compaction of excavations. Allstate Insurance Company – NY Wide Residential/Commercial Fuel Oil Spills Oversight & Reporting - Ms. Lewis oversees fieldwork for projects such as petroleum spill remediation. She completes spill reports, and coordinates with contractors and the NYSDEC to ensure that the project stays on schedule, is compliant with regulatory guidelines, and meets the client's goals.

UIC Control Programs - Suffolk and Nassau Counties, NY
Remediation Oversight
Ms. Lewis has been overseeing the remediation activities of dry wells (Class V wells) at multiple sites for various clients throughout Suffolk and Nassau Counties. She performs endpoint sampling of storm drains and sanitary systems, coordinates and performs sampling in conjunction with the SCDHS and NCDH, and ensures proper soil and sediment removal during VacTruck operations.

Rechler Equity Partners - Melville, NY
250 Miller Place, Hicksville, NY
The subject site, a large commercial property and formerly used by a circuit board manufacturer and trucking company, had a history of chemical uses (i.e. chlorinated solvents, diesel fuel, and gasoline). To determine if subsurface soils had been impacted, PWGC conducted a Phase II investigation for a potential buyer. Ms. Lewis was present during the Phase II and oversaw the project's subsurface investigation-phase. She directed the Geoprobe® operator, and participated in the preparation of the Phase II investigation report. In addition, Ms. Lewis observed the follow-up investigation and remediation performed by the current property owner's consultant.

Franklin Hospital - Valley Stream, NY
Water Sampling
Ms. Lewis collected water samples from the dialysis treatment suite and from a sink in order to determine the source of a bacterial contamination.